

Available from

NRC/GPO Sales Program

Superintendent of Documents
Government Printing Office
Washington, D. C. 20402

A year's subscription consists of 12 issues for
this publication.

Single copies of this publication
are available from National Technical
Information Service, Springfield, VA 22161

Microfiche of single copies are
available from NRC/GPO Sales Program
Washington, D. C. 20555

Title List of Documents Made Publicly Available

June 1-30, 1983

Division of Technical Information and Document Control
Office of Administration
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555



CONTENTS

Preface	v
Arrangement of Items by Docket Number	ix
Alphabetic Arrangement of Docket Items by Facility Name	xvii
Docketed Items	
Low Level Radwaste Disposal Sites — Docket 27	1
Domestic Licensing of Source Material — Docket 40	1
Domestic Licensing of Production and Utilization Facilities — Docket 50	7
Domestic Licensing of Special Nuclear Material — Docket 70	374
Packaging of Radioactive Material for Transport and Transportation of Radioactive Material Under Certain Conditions — Docket 71	381
Licensing of Independent Spent Fuel Storage — Docket 72	388
Nondocketed Items	
10 CFR — Commission Meeting Records	389
ACRS — Advisory Committee on Reactor Safeguards	390
ADVCM — NRC Advisory Committees	391
COMMISSION — NRC Commissioners	392
CONTRACT — NRC Contracts and Modifications	394
FOIA — Freedom of Information Act Requests and Releases	400
GEN TECH IS — Generic Technical Issues	415
I&E — Inspection and Enforcement	419
MISC — Public Document Room Miscellaneous	421
NUREG — NUREG Reports and Related Correspondence	422
ORG — Correspondence with Other Organizations	441
PR — Proposed Rule	443
PRM — Petition for Rulemaking	445
PROJ — Projects - Predocket Licensing	445
PT 21 — Noncompliance Reports and Related Correspondence	446
QA999 — Quality Assurance Inspections	449
REGGD — Regulatory Guides	451
RES — Research and Technical Assistance Reports	452
REVIEW GROUP — NRC Research Review Groups	452
SECY — Position Papers Before the Commission	453
STATE PROG — State Programs	454
TOPREP — Vendor Reports and Related Correspondence	455
WASH — Regulatory Publications - Pre-Nureg Series	458
WASTE MGT — Nuclear Waste Management	458
XPORTLIC — Export and Import Licenses	460
Personal Author Index	465
Corporate Source Index	497
Report Number Index	527
Cross Reference of Enclosures to Principal Documents	529
Appendix A — Definitions of Docket 50 Categories	A-1
Appendix B — Definitions of Nondocketed Categories	B-1

PREFACE

The *Title List of Documents Made Publicly Available* is a monthly publication. It contains descriptions of the information received and generated by the U.S. Nuclear Regulatory Commission (NRC). This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. As used here, *docketed* does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index.

The docketed information contained in the *Title List* includes the information formerly issued through the Department of Energy publication *Power Reactor Docket Information*, last published in January 1979. Microfiche of the docketed information listed in the *Title List* is available for sale on a subscription basis from the National Technical Information Service (NTIS). See NOTES at the end of the Preface for the complete NTIS address.

We encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base. In so far as possible, we would like this document to be a valuable part of your reference material.

DOCKETED ITEMS

The listings within Docket 50 are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:

- A. Application/construction stage documents and correspondence
- B. Utility Preliminary Safety Analysis Report (PSAR), amendments
- C. Utility Environmental Report (ER), amendments and correspondence
- D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
- E. NRC Safety Evaluation Report (SER), supplements and correspondence
- F. Security, medical, emergency and fire-protection plans
- G. Adjudicatory correspondence
- H. General correspondence
- I. Financial information
- J. Insurance and indemnity information
- K. Utility Final Safety Analysis Report (FSAR) and amendments
- L. Limited work authorization and related correspondence
- M. Antitrust correspondence
- N. Antitrust hearing transcripts
- O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
- P. Operating license stage documents and correspondence
- Q. Inspection reports, IE Bulletins and correspondence
- R. Periodic operating reports and related correspondence
- S. Reportable occurrences. LERs and related correspondence
- T. Hearing transcripts on non-antitrust matters
- U. Congressional/executive correspondence
- V. Licensing operators and related correspondence

- W. Decommissioning stage documents and correspondence
- X. Onsite low-level wastes storage

Appendix A sets forth those categories and describes the materials available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the entries in the list are:

- ① P. Operating license stage documents & correspondence

② 8203090028 ③ Responds to 820201 ltr requesting documents re environ qualification of electrical equipment. All nonproprietary repts will be provided to Franklin Research Ctr by 820408. Proprietary repts will be provided to NRC by 820510.
 ④ MILLS, L.M. ⑤ Tennessee Valley Authority. ⑥ 82/03/04. ⑦ VASSALLO, D.B.
 Operating Reactors Branch 2. ⑧ 1p. 1216:254. 24XFiche: 50-259, 82/03/04, 8203090028.
 ⑨ ⑩ ⑪ ⑫

1. NRC/PDR Document category (see Appendix A).
2. NRC Accession Number (year, month, day, and sequence number of item).
3. Description of information contained in the document.
4. Personal author(s). An asterisk in this position indicates that there is no personal author.
5. Corporate, agency or nonindividual source.
6. Date of document described.
7. Recipient of document and NRC or corporate affiliation.
8. Pages in this document.
9. The NRC 48X microfiche designation for this document. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who have access to 48X microfiche files.
10. This three-digit portion of this entry is the number of the frame on which this document starts.
11. The 24X Fiche designation consists of the docket number followed by the date of the document and the accession number for the document. This designation provides the information needed by subscribers to the National Technical Information Service docket microfiche to locate the document fiche.
12. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or "Available at GPO."

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5.

NONDOCKETED ITEMS


The nondocketed items are divided into the categories used for filing and searching in the NRC Public Document Room. These categories and their symbols are;

10CFR — Commission Meeting Records
 ACRS — Advisory Committee on Reactor Safeguards
 COMMISSION — NRC Commissioners
 CONTRACT — NRC Contracts and Modifications
 DISCLOSURE — Financial Disclosure Information
 FOIA — Freedom of Information Act Requests and Releases
 GEN TECH IS — Generic Technical Issues

I&E — Inspection and Enforcement
 MISC — Public Document Room Miscellaneous
 NUREG — NUREG Reports and Related Correspondence
 ORG — Correspondence with Other Organizations
 PR — Proposed Rule
 PRM — Petition for Rulemaking
 PROJ — Projects—Predocket Licensing
 PT21 — Noncompliance Reports and Related Correspondence
 QA999 — Quality Assurance Inspections
 REGGD — Regulatory Guides
 RES — Research and Technical Assistance Reports
 REVIEW GRP — NRC Research Review Groups
 RM — Rulemakings
 SECY — Position Papers Before the Commission
 STATE PROG — State Programs
 TOPREP — Vendor Reports and Related Correspondence
 WASH — Regulatory Publications—Pre-NUREG Series
 WASTE MGT — Nuclear Waste Management
 XPORTLIC — Export and Import Licenses

Appendix B sets forth these categories and describes the material available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the nondocketed items are:



1. Nondocketed category
2. NRC Accession Number (year, month, day, and sequence number of item)
3. NRC Report Number
4. Title and description of information contained in the document
5. Personal author(s). An asterisk in this position indicates that there is no personal author.
6. Corporate, agency or other nonindividual source.
7. Contract or financial (FIN) number (if any). If the document has a secondary report number, it will appear following this entry.
8. Secondary report number assigned by originator.
9. Date of document described.
10. NRC organizational recipient.
11. Pages in document.
12. All NUREG-series documents are available for purchase at NRC. Information on ordering documents is given below. All NUREG-series documents are also available at NTIS. Information on ordering from NTIS is also given below.
13. Price for which NRC sells the document.

14. The NRC 48X microfiche designation for this document. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who have access to 48X microfiche files
15. This three-digit portion of this entry is the number of the frame on which this document starts.

The Nondocketed Items list is arranged sequentially by Accession Number within category. Indented items preceded by a dash are enclosures to unindented items.

NOTES:

1. The address for NRC is:

Director
Division of Technical Information and Document Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

To place orders, send check or money order, payable to the Superintendent of Documents. GPO Deposit Account holders may charge their orders by calling (301) 492-9530.

2. The address for NTIS is:

National Technical Information Service
Springfield, Virginia 22161

To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 557-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the chargecard number when placing your order.

3. The address for the PDR is:

1717 H Street, N.W.
Washington, D.C. 20555

To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation.

Paper copy and microfiche of the documents listed in this title list may be purchased. Reproduction charges for duplication are as follows: (1) paper to paper is \$0.05 per page except for oversized documents and engineering drawings, which vary from \$0.50 to \$1.00 per square foot; (2) microform to paper is \$0.05 a page for pages on microfiche and is \$0.20 a square foot for a full-size print or \$0.25 for a reduced-size print (18" x 24") of a drawing on an aperture card; and (3) microform to microform is \$0.10 per microfiche and \$0.20 per aperture card. Orders completed for mailing or for a special delivery service will have an additional fee for the actual mailing, shipping, or delivery service rate. Unless a user requests special packing materials, there is no additional charge by the contractor for handling and wrapping materials.

Please acknowledge a willingness to assume charges for all orders but do not send payments. Orders will be processed and mailed with a bill from Literature Research Company. An account may be established with the Literature Research Company by calling (703)-941-8018.

ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Docket	Name	Page	Docket	Name	Page
Low Level Disposal Sites — Docket 27			40-8452	Bear Creek Uranium Co., Casper, WY	4
27-039	Sheffield, IL, U.S. Ecology, Inc.	1	40-8502	Wyoming Mineral Corp., Lakewood, CO	4
27-047	Barnwell, SC, Chem-Nuclear Systems, Inc.		40-8584	Minerals Exploration Co., Los Angeles, CA	5
27-048	Richland, WA, U.S. Ecology, Inc.		40-8585	Wyoming Mineral Corp., Lakewood, CO	5
Domestic Licensing of Source Material — Docket 40			40-8586	Kerr-McGee Nuclear Corp., Oklahoma City, OK	5
40-0086	W. R. Grace & Co., Pompton Plains, NJ	1	40-8610	Stepan Chemical Co., Maywood, NJ	5
40-0299	Union Carbide Corp., Grand Junction, CO	1	40-8631	Army, Dept. of, Rock Island, IL	5
40-0672	Nuclear Metals, Inc., Concord, MA	2	40-8663	Nuclear Dynamics, Inc., Phoenix, AZ	5
40-1162	Western Nuclear, Inc., Jeffrey City, WY	2	40-8674	Plateau Resources, Ltd., Grand Junction, CO	5
40-1341	Tennessee Valley Authority, Chattanooga, TN	2	40-8681	Energy Fuels Nuclear, Inc., Denver, CO	5
40-2061	Kerr-McGee Chemical Corp., Oklahoma City, OK	2	40-8684	Western Nuclear, Inc., Lakewood, CO	6
40-2259	Pathfinder Mines Corp., Riverton, WY	2	40-8697	Rocky Mountain Energy Co., Denver, CO	6
40-3392	Allied Chemical Corp., Morristown, NJ	3	40-8698	Plateau Resources, Ltd., Grand Junction, CO	6
40-3453	Atlas Mineral, Inc., Denver, CO	3	40-8714	Cleveland-Cliffs Iron Co., Cleveland, OH	6
40-4492	Federal-American Partners, Riverton, WY	3	40-8722	Brush Wellman, Inc., Cleveland, OH	6
40-6264	Michigan Chemical Corp., St. Louis, MI	3	40-8728	Teton Exploration Drilling Co., Inc., Casper, WY	7
40-6500	Energy, Dept. of, Canonsburg, PA	3	40-8745	Ogle Petroleum, Inc., Casper, WY	7
40-6622	Pathfinder Mines Corp., Shirley Basin, WY	3	40-8768	Kerr-McGee Nuclear Corp., Oklahoma City, OK	7
40-6940	Kawecki Berylco Industries, Inc., Boyertown, PA	3	40-8783	Uranerz USA, Inc., Casper, WY	7
40-7580	Fansteel, Inc., North Chicago, IL	3	40-8786	Uranium Resources, Inc., Richardson, TX	7
40-7869	Plateau Resources, Ltd., Grand Junction, CO	3	40-8794	MolyCorp., Inc., Los Angeles, CA	7
40-8027	Kerr-McGee Nuclear Corp., Oklahoma City, OK	3	Domestic Licensing of Production and Utilization Facilities — Docket 50		
40-8035	Cotter Corp., Roswell, NM	4	50-2	Univ. of Michigan Research Reactor	7
40-8064	Exxon Minerals Co. USA, Houston, TX	4	50-3	Indian Point Station, Unit 1	7
40-8084	Rio Algom Corp., Moab, UT	4	50-5	Pennsylvania State Univ. Research Reactor	8
40-8348	Minerals Exploration Co., Los Angeles, CA	4	50-6	Battelle Memorial Institute Research Reactor	8
40-8380	Rocky Mountain Energy Co., Broomfield, CO	4	50-8	North Carolina State Univ. Research Reactor	8

Docket	Name	Page	Docket	Name	Page
50-10	Dresden Nuclear Power Station, Unit 1	8	50-186	Univ. of Missouri Research Reactor	22
50-14	Battelle Memorial Institute Critical Facility	9	50-188	Kansas State Univ. Research Reactor	22
50-16	Enrico Fermi Atomic Power Plant, Unit 1	9	50-192	Univ. of Texas Research Reactor	22
50-20	Massachusetts Institute of Technology Research Reactor	9	50-193	Rhode Island & Providence Plantations AEC	22
50-27	Washington State Univ. Research Reactor	9	50-199	Manhattan College Research Reactor	22
50-29	Yankee-Rowe Nuclear Power Station	9	50-201	West Valley Reprocessing Plant	22
50-54	Union Carbide Research Reactor	11	50-206	San Onofre Nuclear Station, Unit 1	23
50-57	State Univ. of New York Research Reactor	11	50-208	Columbia Univ. Research Reactor	25
50-62	Univ. of Virginia Research Reactor	11	50-213	Haddam Neck Plant	26
50-70	General Electric Test Reactor	12	50-219	Oyster Creek Nuclear Power Plant	28
50-72	Univ. of Utah Research Reactor	12	50-220	Nine Mile Point Nuclear Station, Unit 1	30
50-77	Catholic Univ. of America Research Reactor	12	50-223	Univ. of Lowell Research Reactor	32
50-89	General Atomic Co.	12	50-224	Univ. of California Research Reactor	32
50-97	Cornell Univ. Zero Power Reactor	12	50-225	RPI Critical Experiment	32
50-111	North Carolina State Univ. Research Reactor	13	50-237	Dresden Nuclear Power Station, Unit 2	32
50-112	Univ. of Oklahoma Research Reactor	13	50-243	Oregon State Univ. Research Reactor	35
50-116	Iowa State Univ. Research Reactor	13	50-244	Robert Emmet Ginna Nuclear Plant, Unit 1	35
50-128	Texas A&M Univ. Research Reactor	13	50-245	Millstone Nuclear Power Station, Unit 1	38
50-131	Omaha Veterans Administration Hospital Research Reactor	14	50-247	Indian Point Station, Unit 2	40
50-133	Humboldt Bay Power Plant, Unit 3	14	50-249	Dresden Nuclear Power Station, Unit 3	44
50-134	Worcester Polytechnic Institute Research Reactor	14	50-250	Turkey Point Plant, Unit 3	46
50-141	Stanford Univ. Research Reactor	14	50-251	Turkey Point Plant, Unit 4	48
50-142	UCLA Training Reactor	14	50-254	Quad-Cities Station, Unit 1	50
50-146	Saxton Nuclear Experimental Facility	16	50-255	Palisades Nuclear Plant	52
50-148	Univ. of Kansas Research Reactor	16	50-259	Browns Ferry Nuclear Power Station, Unit 1	54
50-151	Univ. of Illinois Research Reactor	16	50-260	Browns Ferry Nuclear Power Station, Unit 2	57
50-155	Big Rock Point Nuclear Plant	16	50-261	H. B. Robinson Plant, Unit 2	61
50-156	Univ. of Wisconsin Research Reactor	20	50-263	Monticello Nuclear Generating Plant	63
50-157	Cornell Univ. Research Reactor	21	50-265	Quad-Cities Station, Unit 2	64
50-163	General Atomic Co.	21	50-266	Point Beach Nuclear Plant, Unit 1	66
50-166	Univ. of Maryland Research Reactor	21	50-267	Fort St. Vrain Nuclear Generating Station	68
50-170	National Naval Medical Center	21	50-269	Oconee Nuclear Station, Unit 1	71
50-182	Purdue Univ. Research Reactor	22	50-270	Oconee Nuclear Station, Unit 2	72
50-184	National Bureau of Standards Reactor	22	50-271	Vermont Yankee Nuclear Power Station	74
			50-272	Salem Nuclear Generating Station, Unit 1	77

Docket	Name	Page	Docket	Name	Page
50-274	U S. Geological Survey Research Reactor	79	50-326	Univ. of California at Irvine Research Reactor	169
50-275	Diablo Canyon Nuclear Power Plant, Unit 1	80	50-327	Sequoyah Nuclear Plant, Unit 1	169
50-277	Peach Bottom Atomic Power Station, Unit 2	85	50-328	Sequoyah Nuclear Plant, Unit 2	171
50-278	Peach Bottom Atomic Power Station, Unit 3	88	50-329	Midland Plant, Unit 1	173
50-280	Surry Power Station, Unit 1	91	50-330	Midland Plant, Unit 2	177
50-281	Surry Power Station, Unit 2	92	50-331	Duane Arnold Energy Center	182
50-282	Prairie Island Nuclear Station, Unit 1	94	50-333	James A. Fitzpatrick Nuclear Power Plant	183
50-285	Fort Calhoun Station, Unit 1	96	50-334	Beaver Valley Power Station, Unit 1	185
50-286	Indian Point Station, Unit 3	98	50-335	St. Lucie Plant, Unit 1	188
50-287	Oconee Nuclear Station, Unit 3	102	50-336	Millstone Nuclear Power Station, Unit 2	190
50-289	Three Mile Island Nuclear Station, Unit 1	104	50-338	North Anna Power Station, Unit 1	193
50-293	Pilgrim Nuclear Power Station, Unit 1	109	50-339	North Anna Power Station, Unit 2	195
50-294	Michigan State Univ. Research Reactor	112	50-341	Enrico Fermi Atomic Power Plant, Unit 2	197
50-295	Zion Nuclear Power Station, Unit 1	112	50-344	Trojan Nuclear Plant	199
50-296	Browns Ferry Nuclear Power Station, Unit 3	113	50-346	Davis-Besse Nuclear Power Station, Unit 1	202
50-298	Cooper Nuclear Station	116	50-348	Joseph M. Farley Nuclear Plant, Unit 1	205
50-301	Point Beach Nuclear Plant, Unit 2	118	50-352	Limerick Generating Station, Unit 1	208
50-302	Crystal River Nuclear Plant, Unit 3	120	50-353	Limerick Generating Station, Unit 2	212
50-304	Zion Nuclear Power Station, Unit 2	122	50-354	Hope Creek Nuclear Station, Unit 1	217
50-305	Kewaunee Nuclear Power Plant	124	50-355	Hope Creek Nuclear Station, Unit 2	218
50-306	Prairie Island Nuclear Station, Unit 2	125	50-356	Univ. of Illinois LOPRA Research Reactor	218
50-309	Maine Yankee Atomic Power Plant	127	50-358	William H. Zimmer Nuclear Station, Unit 1	218
50-311	Salem Nuclear Generating Station, Unit 2	130	50-361	San Onofre Nuclear Station, Unit 2	222
50-312	Rancho Seco Nuclear Generating Station	132	50-362	San Onofre Nuclear Station, Unit 3	227
50-313	Arkansas Nuclear One, Unit 1	135	50-364	Joseph M. Farley Nuclear Plant, Unit 2	230
50-315	Donald C. Cook Nuclear Power Plant, Unit 1	138	50-366	Edwin I. Hatch Nuclear Plant, Unit 2	232
50-316	Donald C. Cook Nuclear Power Plant, Unit 2	140	50-367	Bailly Generating Station	236
50-317	Calvert Cliffs Nuclear Power Plant, Unit 1	142	50-368	Arkansas Nuclear One, Unit 2	236
50-318	Calvert Cliffs Nuclear Power Plant, Unit 2	145	50-369	William B. McGuire Nuclear Station, Unit 1	239
50-320	Three Mile Island Nuclear Station, Unit 2	147	50-370	William B. McGuire Nuclear Station, Unit 2	241
50-321	Edwin I. Hatch Nuclear Plant, Unit 1	150	50-373	LaSalle County Station, Unit 1	244
50-322	Shoreham Nuclear Power Station	153	50-374	LaSalle County Station, Unit 2	247
50-323	Diablo Canyon Nuclear Power Plant, Unit 2	160	50-382	Waterford Generating Station, Unit 3	250
50-324	Brunswick Steam Electric Plant, Unit 2	162	50-387	Susquehanna Steam Electric Station, Unit 1	252
50-325	Brunswick Steam Electric Plant, Unit 1	165	50-388	Susquehanna Steam Electric Station, Unit 2	256

Docket	Name	Page	Docket	Name	Page
50-389	St. Lucie Plant, Unit 2	257	STN-50-457	Braidwood Station, Unit 2	338
50-390	Watts Bar Nuclear Plant, Unit 1	261	50-458	River Bend Station, Unit 1	340
50-391	Watts Bar Nuclear Plant, Unit 2	265	50-459	River Bend Station, Unit 2	342
50-394	California State Polytech College Research Reactor	269	50-460	WPPSS Nuclear Project, Unit 1	343
50-395	Virgil C. Summer Nuclear Station, Unit 1	269	50-461	Clinton Power Station, Unit 1	345
50-396	Univ. of Virginia Cavalier Reactor	271	50-462	Clinton Power Station, Unit 2	346
50-397	WPPSS Nuclear Project, Unit 2	271	STN-50-470	CESSAR System 80	346
50-400	Shearon Harris Nuclear Power Plant, Unit 1	273	STN-50-482	Wolf Creek Generating Station	346
50-401	Shearon Harris Nuclear Power Plant, Unit 2	278	STN-50-483	Callaway Plant, Unit 1	349
50-404	North Anna Power Station, Unit 3	281	50-496	Montague Nuclear Power Station, Unit 1	351
50-407	Univ. of Utah Research Reactor	281	50-497	Montague Nuclear Power Station, Unit 2	352
50-409	La Crosse Boiling Water Reactor	281	STN-50-498	South Texas Project, Unit 1	352
50-410	Nine Mile Point Nuclear Station, Unit 2	284	STN-50-499	South Texas Project, Unit 2	354
50-412	Beaver Valley Power Station, Unit 2	286	STN-50-508	WPPSS Nuclear Project, Unit 3	356
50-413	Catawba Nuclear Station, Unit 1	287	STN-50-509	WPPSS Nuclear Project, Unit 5	357
50-414	Catawba Nuclear Station, Unit 2	290	50-513	WPPSS Nuclear Project, Unit 4	357
50-416	Grand Gulf Nuclear Station, Unit 1	293	50-514	Pebble Springs Nuclear Plant, Unit 1	357
50-417	Grand Gulf Nuclear Station, Unit 2	297	50-515	Pebble Springs Nuclear Plant, Unit 2	358
50-423	Millstone Nuclear Power Station, Unit 3	299	STN-50-517	Jamesport Nuclear Station, Unit 2	358
50-424	Alvin W. Vogtle Nuclear Plant, Unit 1	300	STN-50-518	Hartsville Nuclear Plant, Unit 1	358
50-425	Alvin W. Vogtle Nuclear Plant, Unit 2	302	STN-50-519	Hartsville Nuclear Plant, Unit 2	358
50-438	Bellefonte Nuclear Plant, Unit 1	303	STN-50-520	Hartsville Nuclear Plant, Unit 3	358
50-439	Bellefonte Nuclear Plant, Unit 2	306	STN-50-521	Hartsville Nuclear Plant, Unit 4	359
50-440	Perry Nuclear Power Plant, Unit 1	309	50-522	Skagit Nuclear Power Project, Unit 1	359
50-441	Perry Nuclear Power Plant, Unit 2	312	50-523	Skagit Nuclear Power Project, Unit 2	359
50-443	Seabrook Nuclear Station, Unit 1	315	STN-50-528	Palo Verde Nuclear Station, Unit 1	360
50-444	Seabrook Nuclear Station, Unit 2	318	STN-50-529	Palo Verde Nuclear Station, Unit 2	363
50-445	Comanche Peak Steam Electric Station, Unit 1	321	STN-50-530	Palo Verde Nuclear Station, Unit 3	366
50-446	Comanche Peak Steam Electric Station, Unit 2	325	50-537	Clinch River Breeder Reactor	369
STN-50-447	CESSAR-238	328	STN-50-546	Marble Hill Nuclear Station, Unit 1	370
STN-50-454	Byron Station, Unit 1	329	STN-50-547	Marble Hill Nuclear Station, Unit 2	372
STN-50-455	Byron Station, Unit 2	333	STN-50-553	Phipps Bend Nuclear Station, Unit 1	373
STN-50-456	Braidwood Station, Unit 1	337	STN-50-554	Phipps Bend Nuclear Station, Unit 2	373
			STN-50-556	Black Fox Station, Unit 1	373
			STN-50-557	Black Fox Station, Unit 2	374

Docket	Name	Page	Docket	Name	Page
Atomic Energy Commission Licensing of Special Nuclear Material — Docket 70			70-2548	Dover General Hospital, Dover, NJ	379
70-0008	Battelle Memorial Institute, Columbus, OH	374	70-2669	Robert Packer Hospital, Sayre, PA	379
70-0025	Rockwell International Corp., Canoga Park, CA	375	70-2838	Cincinnati Gas & Electric Co., Cincinnati, OH	379
70-0084	Iowa State Univ., Ames, IA	375	70-2850	Weber State College, Ogden, UT	380
70-0115	Washington, Univ. of, Seattle, WA	375	70-2892	Auxilio Muto Hospital, Hato Rey, PR	380
70-0121	Interior, Dept. of, Denver, CO	375	70-2910	Tennessee Valley Authority, Chattanooga, TN	380
70-0124	Teledyne Isotopes, Inc., Westwood, NJ	375	70-2926	Detroit Edison Co., Detroit, MI	380
70-0134	Wisconsin, Univ. of, Madison, WI	375	70-2929	Army, Dept. of, Ft. McClellan, AL	380
70-0135	Babcock & Wilcox Co., Apollo, PA	375	70-2945	Union Electric Co., St. Louis, MO	380
70-0143	Nuclear Fuel Services, Inc., Erwin, TN	375	70-2947	Illinois Power & Light Co., Decatur, IL	380
70-0258	Illinois, Univ. of, Urbana, IL	376	70-2950	Washington Public Power Supply System, Richland, WA	380
70-0267	New York, State Univ. of, Buffalo, NY	376	70-2953	Connecticut, Univ. of, Storrs, CT	380
70-0364	Babcock & Wilcox Co., Apollo, PA	376	70-2968	Cleveland Electric Illuminating Co., Cleveland, OH	380
70-0371	UNC Naval Products, Inc., Uncasville, CT	376	70-2982	Rochester, Univ. of, Rochester, NY	380
70-0498	Eastern Michigan Univ., Ypsilanti, MI	376	70-2984	Arizona Public Service Co., Phoenix, AZ	380
70-0687	Union Carbide Corp., Tuxedo, NY	376	70-2985	Duke Power Co., Charlotte, NC	381
70-0698	Westinghouse Electric Corp., Pittsburgh, PA	377	Packaging of Radioactive Material for Transport and Transportation of Radioactive Material under Certain Conditions — Docket 71		
70-0734	GA Technologies, Inc., San Diego, CA	377	71-0002	ATCOR Engineered Systems, Inc.	381
70-0754	General Electric Co., Pleasanton, CA	377	71-0086	Alpha-Omega Services, Inc.	381
70-0820	United Nuclear Corp., Wood River Junction, RI	377	71-0210	Gulf Nuclear, Inc.	381
70-0824	Babcock & Wilcox Co., Lynchburg, VA	377	71-0250	Transnuclear, Inc.	381
70-1113	General Electric Co., Wilmington, NC	377	71-0302	Associated Piping & Engineering Corp.	381
70-1143	Westinghouse Electric Corp., Pittsburgh, PA	378	71-0367	Navy, Dept. of	381
70-1151	Westinghouse Electric Corp., Pittsburgh, PA	378	71-0498	Gearhart-Owen Industries	381
70-1201	Babcock & Wilcox Co., Lynchburg, VA	378	71-4909	Model: GE 21PF-1, General Electric Co.	381
70-1207	Navy, Dept. of, Silver Spring, MD	378	71-4960	Model: LLD-1, Energy, Dept. of	381
70-1224	Teleflex, Inc., North Wales, PA	378	71-5026	Model: CNS 14-190, Chem-Nuclear Systems, Inc.	381
70-1257	Exxon Nuclear Co., Inc., Richland, WA	379	71-5097	Model: 44, Energy, Dept. of	382
70-1308	General Electric Co., San Jose, CA	379	71-5170	Model: Steel Ingot Skid & Box 37, Energy, Dept. of	382
70-1402	Abington Memorial Hospital, Abington, PA	379	71-5364	Model: NPI-67-0442, Neutron Products, Inc.	382
70-1549	Nuclear Fuel Services, Inc., Erwin, TN	379	71-5450	Model: RCC, -1, -2, -3, -4, Westinghouse Electric Corp.	382
70-1739	Tri-State Motor Transit Co., Joplin, MO	379			
70-1764	Nuclear Fuel Services, Inc., Erwin, TN	379			
70-2375	Pacific Gas & Electric Co., San Francisco, CA	379			

Docket	Name	Page	Docket	Name	Page
71-5467	Model. Mark VR, VE & Mark 15, Energy, Dept. of	382	71-6550	Model: 6-GS-1, Energy, Dept. of	384
71-5469	Model. HNPf Spent Fuel Shipping Cask, Energy, Dept. of	382	71-6553	Model: PADUCAH Tiger, Energy, Dept. of	384
71-5507	Model: HFIR Spent Fuel Element Shipping Cask, Energy, Dept. of	382	71-6574	Model: HN-200, Hittman Nuclear & Development Corp.	384
71-5552	Model: Gas Cylinder Fire Impact Shield, Energy, Dept. of	382	71-6601	Model: CNS 8-120, Chem-Nuclear Systems, Inc.	384
71-5595	Model: L&M ORNL Uranium Shielded Cask, Energy, Dept. of	382	71-6613	Model: 702, Technical Operations, Inc.	384
71-5597	Model: Tungsten Shielded Cask, Energy, Dept. of	382	71-6639	Model: MH-1A, Energy, Dept. of	384
71-5607	Model: T-2, Energy, Dept. of	382	71-6679	Model. 6679, U.S. Ecology	384
71-5608	Model: BR 63-0101, Energy, Dept. of	382	71-6698	Model: NFS-4, Nuclear Fuel Services, Inc.	384
71-5641	Model: UNC-2500, United Nuclear Corp.	382	71-6717	Model: 6717-B, Gamma Industries	384
71-5645	Model: AL-L 8, Energy, Dept. of	382	71-9006	Model: 500-SU, Automation Industries, Inc	385
71-5753	Model: ORNL Loop Transport Cask, Energy, Dept. of	382	71-9010	Model: NLI-1/2, NL Industries, Inc.	385
71-5795	Model: None, Energy, Dept. of	383	71-9015	Model: TN-8, -8L, No Users	385
71-5796	Model: 181375, 181361, Advanced Medical Systems, Inc.	383	71-9016	Model: TN-9, No Users	385
71-5828	Model: TREAT, Energy, Dept. of	383	71-9017	Model: SNAP-23A 1000, Navy, Dept. of	385
71-5885	Model: AL-L 11, Energy, Dept. of	383	71-9029	Model: 676 & 676E, Technical Operations, Inc.	385
71-5907	Model: ORNL in Pile Capsule, Energy, Dept. of	383	71-9032	Model: 650, Technical Operations, Inc.	385
71-5957	Model: BMI-1, Battelle Columbus Laboratory	383	71-9033	Model: 660 & 660E, Technical Operations, Inc.	385
71-5971	Model: GE-200, General Electric Co.	383	71-9035	Model: 680 & 680E, Technical Operations, Inc.	385
71-6003	Model: M-130, Energy, Dept. of	383	71-9039	Model: 715, Technical Operations, Inc.	385
71-6088	Model: D-38, Oak Ridge National Lab	383	71-9056	Model: SPEC 2-T, Source Production & Equipment Co.	385
71-6104	Model: ANL-390-SPM, Energy, Dept. of	383	71-9070	Model: N-55, Energy, Dept. of	386
71-6115	Model: R1010-0032, Energy, Dept. of	383	71-9080	Model: 9080, Hittman Nuclear & Development Corp.	386
71-6142	Model: Bettis Waste, Energy, Dept. of	383	71-9086	Model: HN-100, Series 1, Hittman Nuclear & Development Corp.	386
71-6244	Model: 6244, Chem-Nuclear Systems, Inc.	383	71-9089	Model: HN-100S, Hittman Nuclear & Development Corp.	386
71-6272	Model: 6272, U.S. Ecology	383	71-9096	Model: CNS 21-300, Chem-Nuclear Systems, Inc.	386
71-6345	Model: ANL-402-SPM & 403-SPM, E.I. du Pont de Nemours	383	71-9100	Model: KKP-20-4950, Kerr-McGee Nuclear Corp.	386
71-6346	Model: FSV-1, General Atomic Co.	384	71-9108	Model: CNS 6-75, Chem-Nuclear Systems, Inc.	386
71-6357	Model: NNFD-10, Babcock & Wilcox Co.	384	71-9110	Model: MX-IC-100, Magnaflux Corp.	386
71-6400	Model: 6400, Westinghouse Electric Corp.	384	71-9111	Model: CNS 6-80-2, Chem-Nuclear Systems, Inc.	386
71-6421	Model: CBE-14, Energy, Dept. of	384			

Docket	Name	Page	Docket	Name	Page
71-9132	Model T-3, Energy, Dept. of	387	71-9165	Model. 855, Technical Operations, Inc.	387
71-9133	Model. C-10, Gamma Industries	387	71-9174	Model: F-147, Atomic Energy of Canada, Ltd.	388
71-9134	Model: ETR, Exxon Nuclear Idaho Co	387	71-9176	Model NUPAC 14/210L & 14/210H, Nuclear Packaging, Inc	388
71-9135	Model: Century S & SA, Cen. Univ. S & SA, Gamma Industries	387	71-9178	Model NUPAC 7/100, Nuclear Packaging, Inc	388
71-9141	Model: 900, Technical Operations, Inc	387	71-9179	Model: NUPAC 6/100L & 6/100 H, Nuclear Packaging, Inc.	388
71-9142	Model: MRC-20WC, Monsanto Research Corp.	387	71-9182	Model: Husman Irradiator, Agriculture, Dept. of	388
71-9143	Model: 920, Technical Operations, Inc.	387	71-9508	Model: DOT Spec 6M, Energy, Dept. of	388
71-9147	Model: 850, Technical Operations, Inc.	387	71-9510	Model: GPHS, Energy, Dept. of	388
71-9151	Model: HN-100, Series 3, Hittman Nuclear & Development Corp.	387	71-9851	Model: Lithium Hydroxide Fire/Impact Shield, Energy, Dept. of	388
71-9152	Model: CNS 1-13CII, Chem-Nuclear Systems, Inc.	387	71-9852	Model: DT-14, Energy, Dept. of	388
71-9156	Model: IR-50, Industrial Nuclear Co.	387	Licensing of Independent Spent Fuel Storage — Docket 72		
71-9157	Model: IR-100, Industrial Nuclear Co.	387	72-0001	Morris Operations, General Electric Co.	388
71-9159	Model: NUPAC Series A, Nuclear Packing, Inc.	387			
71-9163	Model: GNG-20, Gulf Nuclear, Inc.	387			

ALPHABETIC ARRANGEMENT OF DOCKET ITEMS BY FACILITY NAME

Name	Docket	Page	Name	Docket	Page
Barnwell, SC, Chem-Nuclear Systems, Inc.	27-047	1	Pathfinder Mines Corp., Shirley Basin, WY	40-6622	3
Richland, WA, U S Ecology, Inc.	27-048	1	Plateau Resources, Ltd., Grand Junction, CO	40-7869	3
Sheffield, IL, U.S. Ecology, Inc.	27-039	1	Plateau Resources, Ltd., Grand Junction, CO	40-8674	5
Domestic Licensing of Source Material — Docket 40			Plateau Resources, Ltd., Grand Junction, CO	40-8698	6
Allied Chemical Corp., Morristown, NJ	40-3392	3	Rio Algom Corp., Moab, UT	40-8084	4
Army, Dept. of, Rock Island, IL	40-8631	5	Rocky Mountain Energy Co., Broomfield, CO	40-8380	4
Atlas Mineral, Inc., Denver, CO	40-3453	3	Rocky Mountain Energy Co., Denver, CO	40-8697	6
Bear Creek Uranium Co., Casper, WY	40-8452	4	Stepan Chemical Co., Maywood, NJ	40-8610	5
Brush Wellman, Inc., Cleveland, OH	40-8722	6	Tennessee Valley Authority, Chattanooga, TN	40-1341	2
Cleveland-Cliffs Iron Co., Cleveland, OH	40-8714	6	Teton Exploration Drilling Co., Inc., Casper, WY	40-8728	7
Cotter Corp., Roswell, NM	40-8035	4	Union Carbide Corp., Grand Junction, CO	40-0299	1
Energy Fuels Nuclear, Inc., Denver, CO	40-8681	5	Uranerz USA, Inc., Casper, WY	40-8783	7
Energy, Dept. of, Canonsburg, PA	40-6500	3	Uranium Resources, Inc., Richardson, TX	40-8786	7
Exxon Minerals Co. USA, Houston, TX	40-8064	4	W. R. Grace & Co., Pompton Plains, NJ	40-0086	1
Fansteel, Inc., North Chicago, IL	40-7580	3	Western Nuclear, Inc., Jeffrey City, WY	40-1162	2
Federal-American Partners, Riverton, WY	40-4492	3	Western Nuclear, Inc., Lakewood, CO	40-8684	6
Kawecki Berylo Industries, Inc., Boyertown, PA	40-6940	3	Wyoming Mineral Corp., Lakewood, CO	40-8502	4
Kerr-McGee Chemical Corp., Oklahoma City, OK	40-2061	2	Wyoming Mineral Corp., Lakewood, CO	40-8585	5
Kerr-McGee Nuclear Corp., Oklahoma City, OK	40-8027	3	Domestic Licensing of Production and Utilization Facilities — Docket 50		
Kerr-McGee Nuclear Corp., Oklahoma City, OK	40-8586	5	Alvin W. Vogtle Nuclear Plant, Unit 1	50-424	300
Kerr-McGee Nuclear Corp., Oklahoma City, OK	40-8768	7	Alvin W. Vogtle Nuclear Plant, Unit 2	50-425	302
Michigan Chemical Corp., St. Louis, MI	40-6264	3	Arkansas Nuclear One, Unit 1	50-313	135
Minerals Exploration Co., Los Angeles, CA	40-8348	4	Arkansas Nuclear One, Unit 2	50-368	236
Minerals Exploration Co., Los Angeles, CA	40-8584	5	Bailly Generating Station	50-367	236
MolyCorp., Inc., Los Angeles, CA	40-8794	7	Battelle Memorial Institute Critical Facility	50-14	9
Nuclear Dynamics, Inc., Phoenix, AZ	40-8663	5	Battelle Memorial Institute Research Reactor	50-6	8
Nuclear Metals, Inc., Concord, MA	40-0672	2	Beaver Valley Power Station, Unit 1	50-334	185
Ogle Petroleum, Inc., Casper, WY	40-8745	7	Beaver Valley Power Station, Unit 2	50-412	286
Pathfinder Mines Corp., Riverton, WY	40-2259	2	Bellefonte Nuclear Plant, Unit 1	50-438	303

Name	Docket	Page	Name	Docket	Page
Belleville Nuclear Plant, Unit 2	50-439	306	Donald C. Cook Nuclear Power Plant, Unit 2	50-316	140
Big Rock Point Nuclear Plant	50-155	16	Dresden Nuclear Power Station, Unit 1	50-10	8
Black Fox Station, Unit 1	STN-50-556	373	Dresden Nuclear Power Station, Unit 2	50-237	32
Black Fox Station, Unit 2	STN-50-557	374	Dresden Nuclear Power Station, Unit 3	50-249	44
Braidwood Station, Unit 1	STN-50-456	337	Duane Arnold Energy Center	50-331	182
Braidwood Station, Unit 2	STN-50-457	338	Edwin I. Hatch Nuclear Plant, Unit 1	50-321	150
Browns Ferry Nuclear Power Station, Unit 1	50-259	54	Edwin I. Hatch Nuclear Plant, Unit 2	50-366	232
Browns Ferry Nuclear Power Station, Unit 2	50-260	57	Enrico Fermi Atomic Power Plant, Unit 1	50-16	9
Browns Ferry Nuclear Power Station, Unit 3	50-296	113	Enrico Fermi Atomic Power Plant, Unit 2	50-341	197
Brunswick Steam Electric Plant, Unit 1	50-325	165	Fort Calhoun Station, Unit 1	50-285	96
Brunswick Steam Electric Plant, Unit 2	50-324	162	Fort St. Vrain Nuclear Generating Station	50-267	68
Byron Station, Unit 1	STN-50-454	329	General Atomic Co.	50-163	21
Byron Station, Unit 2	STN-50-455	333	General Atomic Co.	50-89	12
California State Polytechnic College Research Reactor	50-394	269	General Electric Test Reactor	50-70	12
Callaway Plant, Unit 1	STN-50-483	349	GESSAR-238	STN-50-447	328
Calvert Cliffs Nuclear Power Plant, Unit 1	50-317	142	Grand Gulf Nuclear Station, Unit 1	50-416	293
Calvert Cliffs Nuclear Power Plant, Unit 2	50-318	145	Grand Gulf Nuclear Station, Unit 2	50-417	297
Catawba Nuclear Station, Unit 1	50-413	287	H. B. Robinson Plant, Unit 2	50-261	61
Catawba Nuclear Station, Unit 2	50-414	290	Haddam Neck Plant	50-213	26
Catholic Univ. of America Research Reactor	50-77	12	Hartsville Nuclear Plant, Unit 1	STN-50-518	358
CESSAR System 80	STN-50-470	346	Hartsville Nuclear Plant, Unit 2	STN-50-519	358
Clinch River Breeder Reactor	50-537	369	Hartsville Nuclear Plant, Unit 3	STN-50-520	358
Clinton Power Station, Unit 1	50-461	345	Hartsville Nuclear Plant, Unit 4	STN-50-521	359
Clinton Power Station, Unit 2	50-462	346	Hope Creek Nuclear Station, Unit 1	50-354	217
Columbia Univ. Research Reactor	50-208	25	Hope Creek Nuclear Station, Unit 2	50-355	218
Comanche Peak Steam Electric Station, Unit 1	50-445	321	Humboldt Bay Power Plant, Unit 3	50-133	14
Comanche Peak Steam Electric Station, Unit 2	50-446	325	Indian Point Station, Unit 1	50-3	7
Cooper Nuclear Station	50-298	116	Indian Point Station, Unit 2	50-247	40
Cornell Univ. Research Reactor	50-157	21	Indian Point Station, Unit 3	50-286	98
Cornell Univ. Zero Power Reactor	50-97	12	Iowa State Univ. Research Reactor	50-116	13
Crystal River Nuclear Plant, Unit 3	50-302	120	James A. Fitzpatrick Nuclear Power Plant	50-333	183
Davis-Besse Nuclear Power Station, Unit 1	50-346	202	Jamesport Nuclear Station, Unit 2	STN-50-517	358
Diablo Canyon Nuclear Power Plant, Unit 1	50-275	80	Joseph M. Farley Nuclear Plant, Unit 1	50-348	205
Diablo Canyon Nuclear Power Plant, Unit 2	50-323	160	Joseph M. Farley Nuclear Plant, Unit 2	50-364	230
Donald C. Cook Nuclear Power Plant, Unit 1	50-315	138	Kansas State Univ. Research Reactor	50-188	22

Name	Docket	Page	Name	Docket	Page
Kewaunee Nuclear Power Plant	50-305	124	Oyster Creek Nuclear Power Plant	50-219	28
La Crosse Boiling Water Reactor	50-409	281	Palisades Nuclear Plant	50-255	52
LaSalle County Station, Unit 1	50-373	244	Palo Verde Nuclear Station, Unit 1	STN-50-528	360
LaSalle County Station, Unit 2	50-374	247	Palo Verde Nuclear Station, Unit 2	STN-50-529	363
Limerick Generating Station, Unit 1	50-352	208	Palo Verde Nuclear Station, Unit 3	STN-50-530	366
Limerick Generating Station, Unit 2	50-353	212	Peach Bottom Atomic Power Station, Unit 2	50-277	85
Maine Yankee Atomic Power Plant	50-309	127	Peach Bottom Atomic Power Station, Unit 3	50-278	88
Manhattan College Research Reactor	50-199	22	Pebble Springs Nuclear Plant, Unit 1	50-514	357
Marble Hill Nuclear Station, Unit 1	STN-50-546	370	Pebble Springs Nuclear Plant, Unit 2	50-515	358
Marble Hill Nuclear Station, Unit 2	STN-50-547	372	Pennsylvania State Univ. Research Reactor	50-5	8
Massachusetts Institute of Technology Res. Reactor	50-20	9	Perry Nuclear Power Plant, Unit 1	50-440	309
Michigan State Univ. Research Reactor	50-294	112	Perry Nuclear Power Plant, Unit 2	50-441	312
Midland Plant, Unit 1	50-329	173	Phipps Bend Nuclear Station, Unit 1	STN-50-553	373
Midland Plant, Unit 2	50-330	177	Phipps Bend Nuclear Station, Unit 2	STN-50-554	373
Millstone Nuclear Power Station, Unit 1	50-245	38	Pilgrim Nuclear Power Station, Unit 1	50-293	109
Millstone Nuclear Power Station, Unit 2	50-336	190	Point Beach Nuclear Plant, Unit 1	50-266	66
Millstone Nuclear Power Station, Unit 3	50-423	299	Point Beach Nuclear Plant, Unit 2	50-301	118
Montague Nuclear Power Station, Unit 1	50-496	351	Prairie Island Nuclear Station, Unit 1	50-282	94
Montague Nuclear Power Station, Unit 2	50-497	352	Prairie Island Nuclear Station, Unit 2	50-306	125
Monticello Nuclear Generating Plant	50-263	63	Purdue Univ. Research Reactor	50-182	22
National Bureau of Standards Reactor	50-184	22	Quad-Cities Station, Unit 1	50-254	50
National Naval Medical Center	50-170	21	Quad-Cities Station, Unit 2	50-265	64
Nine Mile Point Nuclear Station, Unit 1	50-220	30	Rancho Seco Nuclear Generating Station	50-312	132
Nine Mile Point Nuclear Station, Unit 2	50-410	284	Rhode Island & Providence Plantations AEC	50-193	22
North Anna Power Station, Unit 1	50-338	193	River Bend Station, Unit 1	50-458	340
North Anna Power Station, Unit 2	50-339	195	River Bend Station, Unit 2	50-459	342
North Anna Power Station, Unit 3	50-404	281	Robert Emmet Ginna Nuclear Plant, Unit 1	50-244	35
North Carolina State Univ. Research Reactor	50-8	8	RPI Critical Experiment	50-225	32
North Carolina State Univ. Research Reactor	50-111	13	Salem Nuclear Generating Station, Unit 1	50-272	77
Oconee Nuclear Station, Unit 1	50-269	71	Salem Nuclear Generating Station, Unit 2	50-311	130
Oconee Nuclear Station, Unit 2	50-270	72	San Onofre Nuclear Station, Unit 1	50-206	23
Oconee Nuclear Station, Unit 3	50-287	102	San Onofre Nuclear Station, Unit 2	50-361	222
Omaha Veterans Administration Hospital Research Reactor	50-131	14	San Onofre Nuclear Station, Unit 3	50-362	227
Oregon State Univ. Research Reactor	50-243	35	Saxton Nuclear Experimental Facility	50-146	16
			Seabrook Nuclear Station, Unit 1	50-443	315

Name	Docket	Page	Name	Docket	Page
Seabrook Nuclear Station, Unit 2	50-444	318	Univ. of Missouri Research Reactor	50-186	22
Sequoyah Nuclear Plant, Unit 1	50-327	169	Univ. of Oklahoma Research Reactor	50-112	13
Sequoyah Nuclear Plant, Unit 2	50-328	171	Univ. of Texas Research Reactor	50-192	22
Shearon Harris Nuclear Power Plant, Unit 1	50-400	273	Univ. of Utah Research Reactor	50-407	281
Shearon Harris Nuclear Power Plant, Unit 2	50-401	278	Univ. of Utah Research Reactor	50-72	12
Shoreham Nuclear Power Station	50-322	153	Univ. of Virginia Cavalier Reactor	50-396	271
Skagit Nuclear Power Project, Unit 1	50-522	359	Univ. of Virginia Research Reactor	50-62	11
Skagit Nuclear Power Project, Unit 2	50-523	359	Univ. of Wisconsin Research Reactor	50-156	20
South Texas Project, Unit 1	STN-50-498	352	Vermont Yankee Nuclear Power Station	50-271	74
South Texas Project, Unit 2	STN-50-499	354	Virgil C. Summer Nuclear Station, Unit 1	50-395	269
St. Lucie Plant, Unit 1	50-335	188	Washington State Univ. Research Reactor	50-27	9
St. Lucie Plant, Unit 2	50-389	257	Waterford Generating Station, Unit 3	50-382	250
Stanford Univ. Research Reactor	50-141	14	Watts Bar Nuclear Plant, Unit 1	50-390	261
State Univ. of New York Research Reactor	50-57	11	Watts Bar Nuclear Plant, Unit 2	50-391	265
Surry Power Station, Unit 1	50-280	91	West Valley Reprocessing Plant	50-201	22
Surry Power Station, Unit 2	50-281	92	William B. McGuire Nuclear Station, Unit 1	50-369	239
Susquehanna Steam Electric Station, Unit 1	50-387	252	William B. McGuire Nuclear Station, Unit 2	50-370	241
Susquehanna Steam Electric Station, Unit 2	50-388	256	William H. Zimmer Nuclear Station, Unit 1	50-358	218
Texas A&M Univ. Research Reactor	50-128	13	Wolf Creek Generating Station	STN-50-482	346
Three Mile Island Nuclear Station, Unit 1	50-289	104	Worcester Polytechnic Institute Research Reactor	50-134	14
Three Mile Island Nuclear Station, Unit 2	50-320	147	WPPSS Nuclear Project, Unit 1	50-460	343
Trojan Nuclear Plant	50-344	199	WPPSS Nuclear Project, Unit 2	50-397	271
Turkey Point Plant, Unit 3	50-250	46	WPPSS Nuclear Project, Unit 3	STN-50-508	356
Turkey Point Plant, Unit 4	50-251	48	WPPSS Nuclear Project, Unit 4	50-513	357
U.S. Geological Survey Research Reactor	50-274	79	WPPSS Nuclear Project, Unit 5	STN-50-509	357
UCLA Training Reactor	50-142	14	Yankee-Rowe Nuclear Power Station	50-29	9
Union Carbide Research Reactor	50-54	11	Zion Nuclear Power Station, Unit 1	50-295	112
Univ. of California at Irvine Res. Reactor	50-326	169	Zion Nuclear Power Station, Unit 2	50-304	122
Univ. of California Research Reactor	50-224	32	Domestic Licensing of Special Nuclear Material — Docket 70		
Univ. of Illinois LOPRA Research Reactor	50-356	218	Abington Memorial Hospital, Abington, PA	70-1402	379
Univ. of Illinois Research Reactor	50-151	16	Arizona Public Service Co., Phoenix, AZ	70-2984	380
Univ. of Kansas Research Reactor	50-148	16	Army, Dept. of, Ft. McClellan, AL	70-2929	380
Univ. of Lowell Research Reactor	50-223	32	Auxilio Muto Hospital, Hato Rey, PR	70-2892	380
Univ. of Maryland Research Reactor	50-166	21	Babcock & Wilcox Co., Apollo, PA	70-0135	375
Univ. of Michigan Research Reactor	50-2	7			

Name	Docket	Page	Name	Docket	Page
Babcock & Wilcox Co , Apollo, PA	70-0364	376	Union Electric Co., St. Louis, MO	70-2945	380
Babcock & Wilcox Co., Lynchburg, VA	70-1201	378	United Nuclear Corp , Wood River Junction, RI	70-0820	377
Babcock & Wilcox Co., Lynchburg, VA	70-0824	377	Washington Public Power Supply System, Richland, WA	70-2950	380
Battelle Memorial Institute, Columbus, OH	70-0008	374	Washington, Univ. of, Seattle, WA	70-0115	375
Cincinnati Gas & Electric Co., Cincinnati, OH	70-2838	379	Weber State College, Ogden, UT	70-2850	380
Cleveland Electric Illuminating Co., Cleveland, OH	70-2968	380	Westinghouse Electric Corp , Pittsburgh, PA	70-0698	377
Connecticut, Univ. of, Storrs, CT	70-2953	380	Westinghouse Electric Corp., Pittsburgh, PA	70-1143	378
Detroit Edison Co., Detroit, MI	70-2926	380	Westinghouse Electric Corp., Pittsburgh, PA	70-1151	378
Dover General Hospital, Dover, NJ	70-2548	379	Wisconsin, Univ. of, Madison, WI	70-0134	375
Duke Power Co., Charlotte, NC	70-2985	381	Packaging of Radioactive Material for Transport and Transportation of Radioactive Material Under Certain Conditions — Docket 71		
Eastern Michigan Univ., Ypsilanti, MI	70-0498	376	Alpha-Omega Services, Inc.	71-0086	381
Exxon Nuclear Co., Inc., Richland, WA	70-1257	379	Associated Piping & Engineering Corp.	71-0302	381
GA Technologies, Inc., San Diego, CA	70-0734	377	ATCOR Engineered Systems, Inc.	71-0002	381
General Electric Co., Pleasanton, CA	70-0754	377	Gearhart-Owen Industries	71-0498	381
General Electric Co., San Jose, CA	70-1308	379	Gulf Nuclear, Inc.	71-0210	381
General Electric Co., Wilmington, NC	70-1113	377	Model. 181375, 181361, Advanced Medical Systems, Inc.	71-5796	383
Illinois Power & Light Co., Decatur, IL	70-2947	380	Model: 44, Energy, Dept. of	71-5097	382
Illinois, Univ. of, Urbana, IL	70-0258	376	Model: 500-SU, Automation Industries, Inc.	71-9006	385
Interior, Dept. of, Denver, CO	70-0121	375	Model: 6-GS-1, Energy, Dept. of	71-6550	384
Iowa State Univ., Ames, IA	70-0084	375	Model: 6244, Chem-Nuclear Systems, Inc.	71-6244	383
Navy, Dept. of, Silver Spring, MD	70-1207	378	Model: 6272, U.S. Ecology	71-6272	383
New York, State Univ. of, Buffalo, NY	70-0267	376	Model: 6400, Westinghouse Electric Corp.	71-6400	384
Nuclear Fuel Services, Inc., Erwin, TN	70-0143	375	Model: 650, Technical Operations, Inc.	71-9032	385
Nuclear Fuel Services, Inc., Erwin, TN	70-1764	379	Model: 660 & 660E, Technical Operations, Inc.	71-9033	385
Nuclear Fuel Services, Inc., Erwin, TN	70-1549	379	Model: 6679, U.S. Ecology	71-6679	384
Pacific Gas & Electric Co., San Francisco, CA	70-2375	379	Model: 6717-B, Gamma Industries	71-6717	384
Robert Packer Hospital, Sayre, PA	70-2669	379	Model: 676 & 676E, Technical Operations, Inc.	71-9029	385
Rochester, Univ. of, Rochester, NY	70-2982	380	Model: 680 & 680E, Technical Operations, Inc.	71-9035	385
Rockwell International Corp., Canoga Park, CA	70-0025	375	Model: 702, Technical Operations, Inc.	71-6613	384
Teledyne Isotopes, Inc., Westwood, NJ	70-0124	375	Model: 715, Technical Operations, Inc.	71-9039	385
Teleflex, Inc., North Wales, PA	70-1224	378	Model: 850, Technical Operations, Inc.	71-9147	387
Tennessee Valley Authority, Chattanooga, TN	70-2910	380	Model: 855, Technical Operations, Inc.	71-9165	387
Tri-State Motor Transit Co., Joplin, MO	70-1739	379	Model: 900, Technical Operations, Inc.	71-9141	387
UNC Naval Products, Inc., Uncasville, CT	70-0371	376			
Union Carbide Corp., Tuxedo, NY	70-0687	376			

Name	Docket	Page	Name	Docket	Page
Model: 9080, Hittman Nuclear & Development Corp.	71-9080	386	Model: HN-100, Series 3, Hittman Nuclear & Development Corp.	71-9151	387
Model: 920, Technical Operations, Inc.	71-9143	387	Model: HN-100S, Hittman Nuclear & Development Corp.	71-9089	386
Model: AL-L 11, Energy, Dept. of	71-5885	383	Model: HN-200, Hittman Nuclear & Development Corp.	71-6574	384
Model: AL-L 8, Energy, Dept. of	71-5645	382	Model: HNPF Spent Fuel Shipping Cask, Energy, Dept. of	71-5469	382
Model: ANL-390-SPM, Energy, Dept. of	71-6104	383	Model: Husman Irradiator, Agriculture, Dept. of	71-9182	388
Model: ANL-402-SPM & 403-SPM, E.I. du Pont de Nemours	71-6345	383	Model: IR-100, Industrial Nuclear Co.	71-9157	387
Model: Bettis Waste, Energy, Dept. of	71-6142	383	Model: IR-50, Industrial Nuclear Co.	71-9156	387
Model: BMI-1, Battelle Columbus Laboratory	71-5957	383	Model: KKP-20-4950, Kerr-McGee Nuclear Corp.	71-9100	386
Model: BR 63-0101, Energy, Dept. of	71-5608	382	Model: L&M ORNL Uranium Shielded Cask, Energy, Dept. of	71-5595	382
Model: C-10, Gamma Industries	71-9133	387	Model: Lithium Hydroxide Fire/Impact Shield, Energy, Dept. of	71-9851	388
Model: CBE-14, Energy, Dept. of	71-6421	384	LLD-1, Energy, Dept. of	71-4960	381
Model: Century S & SA, Cen. Univ. S & SA Gamma Industries	71-9135	387	Model: M-130, Energy, Dept. of	71-6003	383
Model: CNS 1-13CII, Chem-Nuclear Systems, Inc.	71-9152	387	Model: Mark VR, VE & Mark 15, Energy Dept. of	71-5467	382
Model: CNS 14-190, Chem-Nuclear Systems, Inc.	71-5026	381	Model: MH-1A, Energy, Dept. of	71-6639	384
Model: CNS 21-300, Chem-Nuclear Systems, Inc.	71-9096	386	Model: MRC-20WC, Monsanto Research Corp.	71-9142	387
Model: CNS 6-75, Chem-Nuclear Systems, Inc.	71-9108	386	Model: MX-1C-100, Magnaflux Corp.	71-9110	386
Model: CNS 6-80-2, Chem-Nuclear Systems, Inc.	71-9111	386	Model: N-55, Energy, Dept. of	71-9070	386
Model: CNS 8-120, Chem-Nuclear Systems, Inc.	71-6601	384	Model: NFS-4, Nuclear Fuel Services, Inc.	71-6698	384
Model: D-38, Oak Ridge National Lab	71-6088	383	Model: NLI-1/2, NL Industries, Inc.	71-9010	385
Model: DOT Spec 6M, Energy, Dept. of	71-9508	388	Model: NNFD-10, Babcock & Wilcox Co	71-6357	384
Model: DT-14, Energy, Dept. of	71-9852	388	Model: None, Energy, Dept. of	71-5795	383
Model: ETR, Exxon Nuclear Idaho Co.	71-9134	387	Model: NPI-67-0442, Neutron Products, Inc.	71-5364	382
Model: F-147, Atomic Energy of Canada, Ltd.	71-9174	388	Model: NUPAC 14/210L & 14/210H, Nuclear Packaging, Inc.	71-9176	388
Model: FSV-1, General Atomic Co.	71-6346	384	Model: NUPAC 6/100L & 6/100H, Nuclear Packaging, Inc.	71-9179	388
Model: Gas Cylinder Fire Impact Shield, Energy, Dept. of	71-5552	382	Model: NUPAC 7/100, Nuclear Packaging, Inc.	71-9178	388
Model: GE 21PF-1, General Electric Co.	71-4909	381	Model: NUPAC Series A, Nuclear Packing, Inc.	71-9159	387
Model: GE-200, General Electric Co.	71-5971	383	Model: ORNL in Pile Capsule, Energy, Dept. of	71-5907	383
Model: GNG-20, Gulf Nuclear, Inc.	71-9163	387	Model: ORNL Loop Transport Cask, Energy, Dept. of	71-5753	382
Model: GPHS, Energy, Dept. of	71-9510	388	Model: PADUCAH Tiger, Energy, Dept. of	71-6553	384
Model: HFIR Spent Fuel Element Shipping Cask, Energy, Dept. of	71-5507	382	Model: R1010-0032, Energy, Dept. of	71-6115	383
Model: HN-100, Series 1, Hittman Nuclear & Development Corp.	71-9086	386			

Name	Docket	Page	Name	Docket	Page
Model RCC, -1, -2, -3, -4, Westinghouse Electric Corp	71-5450	382	Model TN-9, No Users	71-9016	385
Model: SNAP-23A 1000, Navy, Dept. of	71-9017	385	Model: TREAT, Energy, Dept. of	71-5828	383
Model: SPEC 2-T, Source Production & Equipment Co.	71-9056	385	Model: Tungsten Shielded Cask, Energy, Dept of	71-5597	382
Model. Steel Ingot Skid & Box 37, Energy, Dept. of	71-5170	382	Model: UNC-2500, United Nuclear Corp	71-5641	382
Model: T-2, Energy, Dept. of	71-5607	382	Navy, Dept. of	71-0367	381
Model: T-3, Energy, Dept. of	71-9132	387	Transnuclear, Inc.	71-0250	381
Model: TN-8, -8L, No Users	71-9015	385	Licensing of Independent Spent Fuel Storage — Docket 72		
			Morris Operations, General Electric Co.	72-0001	388

DOCKETED ITEMS

LOW LEVEL RADWASTE DISPOSAL SITES

DOCKET 27-039 SHEFFIELD, IL, U S ECOLOGY, INC

8306240391 Forwards results of Sheffield analysis & listing of samples collected in 1983 awaiting lab analysis Updated analysis rept will be submitted w/o encl
HAMEL, M A Illinois, State of, Dept Nuc Safety (formerly Dept Public Health), 83/06/13 BCHAFFNER, J NRC - No Detailed Affiliation Given ip 18987.347

DOCKET 27-047 BARNWELL, SC, CHEM-NUCLEAR SYSTEMS, INC.

8306210437 Trip rept of 830411-13 visit to Barnwell, SC & Columbia, SC to familiarize DA Widmayer w/facility personnel, components, layout & operations to assume NRC project manager role
PANGBURN, Q C, WIDMAYER, D A. Low Level Waste Licensing Branch 83/06/06 HAWKINS, E F Low Level Waste Licensing Branch 3pp 18936.267.

8306240394 Ack receipt of 830302 ltr re impact of 10CFR61 on rate changes Price increases only partially attributed to 10CFR61 implementation
EBENHACK, D O Chem-Nuclear Systems, Inc. 83/06/10 BROWNING, R E Division of Waste Management ip 18987.348

DOCKET 27-048 RICHLAND, WA, U S. ECOLOGY, INC

8306020225 Ack receipt of ltr re Amend 3 to License 16-19204-01. Change incomprehensible w/o adequate background Briefing requested
HEININCK, J Yakima Indian Nation. 83/04/27 HAWKINS, E F Low Level Waste Licensing Branch ip 18701.011

8306020222 Forwards monthly BNM receipt & burial rept for Apr 1983, per License Condition 6 & rept of isotopic activity required by State of WA w/o encls
WRIGHT, B V. US Ecology, Inc (formerly Nuclear Engineering) 83/05/11 HAWKINS, E. Low Level Waste Licensing Branch ip. 18701.014

8306210435 Forwards draft use application to determine if all requirements necessary to receive & bury high integrity container at facility addressed. Request for approval will not be submitted until meeting to discuss draft held.
HIPHER, W.M. US Ecology, Inc (formerly Nuclear Engineering) 83/05/17, KIRNER, N Washington, State of 27pp 18937.001.

8306240487 Forwards monthly BNM receipt & burial rept for May 1983, per License Condition 6 & rept of isotopic activity, per State of WA License WN-1019-2
WRIGHT, B V. US Ecology, Inc (formerly Nuclear Engineering). 83/06/13. HAWKINS, E Low Level Waste Licensing Branch. ip. 18998.066.

DOMESTIC LICENSING OF SOURCE MATERIAL

DOCKET 40-0086 W R. GRACE & CO , POMPTON PLAINS, NJ

8306010103 Responds to 830311 ltr & reaffirms 830218 position that DOE will not assume responsibility for remedial actions at Pompton Plains site. DOE plans no further action unless addl legislative authority provided.
BAUBLITT, J E Energy, Dept. of. 83/04/11 PAGE, R. Q. Uranium Fuel Licensing Branch 3pp 18686.351.

8306010263 Forwards RD Closeout Insp Rept 40-0086/74-01 on 740731, 0801 & 02 & 0720, per 830419 request.
KINNEMAN, J D Region 1, Office of Director 83/04/26. TONGUE, T. O. W. R Grace & Co ip 18672.255.

DOCKET 40-0299 UNION CARBIDE CORP , GRAND JUNCTION, CO

8306070467 Forwards application to amend License BUA-648, increasing capacity of A-9 pit tailings area Approval requested by 830515.
LYONS, P J. Union Carbide Corp. 83/03/28 PETTENGILL, H Uranium Recovery Licensing Branch ip. 18781.134.

--8306070470 Application for amend to License BUA-648, increasing capacity of A-9 pit tailings area
* Union Carbide Corp 83/03/31. 208pp 18781.135.

8306020314 Forwards corrected "40CFR190 Data Summary for 1982." Summary indicates that estimated dose commitment at JE Ranch is 0.
WONG, T. Union Carbide Corp 83/04/27. WOODBEY, R. Uranium Recovery Field Office ip. 18715.271

--8306020320 Corrected "40CFR190 Data Summary for 1982."
WONG, T Union Carbide Corp 83/04/27. 3pp. 18715.272.

8306080350 Forwards eight oversize figures for use in reviewing amend to License BUA-648 to increase capacity of A-9 pit tailings area Aperture cards are available in PDR
LUTKIN, M.H. Water, Waste & Land, Inc 83/04/27. PETTENGILL, H. Uranium Recovery Licensing Branch ip 18790.294

8306020198 Forwards corrected version of 830402 ltr re temporary closure of Gas Hills U Mill. Ltr should be dtd 830502.
LYONS, P J Union Carbide Corp. 83/05/09. PETTENGILL, H. Uranium Recovery Licensing Branch. ip. 18701.068.

--8306020201 Confirms 830429 telcon that milling of mine ore through Gas Hills U Mill will be curtailed on 830601. Amend to License BUA-648 needed to increase A-9 tailings pit capacity.
LYONS, P J. Union Carbide Corp. 83/05/02 PETTENGILL, H Uranium Recovery Licensing Branch. ip. 18701.069.

8306020259 Forwards R Williams observations re evaporation pond spill at Gas Hills, WY site Contaminated soils not removed & deposited in A-9 pit due to bad weather.
PETTENGILL, H.J. Uranium Recovery Field Office. 83/05/10. BROWN, Q.D. Division of Vendor & Technical Programs ip. 18700.326

--8306020269 Submits observations re evaporation pond spill at East Gas Hills, WY site. Spill discovered on 830403 in form of seepage at toe of embankment separating evaporation ponds from tailings disposal pit.
WILLIAMS, R.E. R.E. Williams & Associates, Inc. 83/04/16. PETTENGILL, H. Uranium Recovery Licensing Branch. 3pp. 18700.327.

8306020340 Rejects 830225 request for amend to License BUA-648 to postpone cleanup of contaminated soils resulting from windblown tailings. Cleanup should be completed by 830801.
PETTENGILL, H.J. Uranium Recovery Field Office. 83/05/11. BEVERLY, R. Q Union Carbide Corp. 3pp. 18715.317.

8306220116 Advises that plans & specs signed by State of WY engineer & addl copy of application required to process application to increase A-9 pit tailings area capacity.
LABARGE, F. Wyoming, State of. 83/05/12. LYONS, P. J. Union Carbide Corp. ip. 18937.362.

8306220118 Advises that plans & specs signed by State of WY engineer required to process application for A-9 pit collection sys.
LABARGE, F. Wyoming, State of. 83/05/13. LYONS, P. J. Union Carbide Corp. ip. 18937.361.

DOCKETED ITEMS

DOCKET 40-0672 NUCLEAR METALS, INC., CONCORD, MA

06060167 Forwards IE Insp Repts 40-0672/B1-03, 40-0672/B2-01 & 40-0672/B2-02 on B10115, B20419-20 & 0804 & notice of violation
 MARTIN, T. Division of Engineering & Technical Programs 83/03/23
 TUFFIN, W. B. Nuclear Metals, Inc. 2pp. 18728 118

-B306060169 Notice of violation from insps on B10115, B20419-20 & 0804
 * Region 1, Office of Director 83/05/23 1p 18728 120

-B306060172 IE Insp Rept 40-0672/B1-03 on B10115. Noncompliance noted: radioactive matl transported in inadequate packages & package w/dangerous quantity of flammable gas received.
 NICLOSI, J., KINNEHAN, J. Region 1, Office of Director. 83/04/29. 5pp 18728 121.

-B306060177 IE Insp Rept 40-0672/B2-01 on B20429 Noncompliance noted, containers of radioactive matl that evolved quantity of dangerous gas transported
 NICLOSI, J., KINNEHAN, J. Region 1, Office of Director 83/04/29 17pp. 18728 126

-B306060179 IE Insp Rept 40-0672/B2-02 on B20804 Noncompliance noted, radioactive matl transported in inadequate package
 NICLOSI, J., KINNEHAN, J. Region 1, Office of Director 83/04/29 21pp. 18728 143

DOCKET 40-1162 WESTERN NUCLEAR, INC., JEFFREY CITY, WY

060200074 Addendum to "Groundwater & Surface Water Monitoring Results, Fourth Quarter, 1982"
 BODDEN, G. Western Nuclear, Inc. (subs. of Phelps Dodge Corp.). 83/04/29 PETTENGILL, H. J. Uranium Recovery Licensing Branch 27pp. 18908. 179

060220136 Requests Western Nuclear rept, "Reclamation Plan, Mill Site & Tailings Disposal Area" & B20219.22 & 0302 ltrs re radiological & hydrologic issues
 BEIFFERT, S. O. Wyoming, State of 83/05/13 PETTENGILL, H. J. Uranium Recovery Field Office 1p 18937 352

DOCKET 40-1341 TENNESSEE VALLEY AUTHORITY, CHATTANOOGA, TN

060205903 Forwards revised License SUA-B16 License will not expire until NRC completes FES & BER re decommissioning of Edgemont U Mill.
 SMITH, R. D. Uranium Recovery Field Office. 83/04/06 Tennessee Valley Authority 1p 18715.154.

060205909 Revised License SUA-B16 extending license in entirety until NRC determines in FES & BER that decommissioning Edgemont U Mill tailings site is adequate.
 * NRC - No Detailed Affiliation Given 83/04/06 16pp. 18715.155.

06200155 Updates B21022 submittal re Edgemont Mill unresolved item from IE Insp Rept 40-1341/B2-01 on B20616. Deep in uninhabited area outside restricted site boundary isolated by fencing & restricting access.
 MILLS, L. M. Tennessee Valley Authority. 83/03/17. SMITH, D. Uranium Recovery Field Office 5pp. 18909.164.

06210307 Application for amend to License SUA-B16 to accommodate disposal of up to 12,000 cubic yards of residual radioactive matls. Const of repository scheduled to begin in Aug or Sept upon receipt of State of SD cooperative agreement.
 TUCKER, M. K. Energy, Dept. of. 83/06/01. SMITH, D. Uranium Recovery Field Office 2pp 18923.361

06210428 Discusses license amend & other documentation necessary to accommodate disposal of vicinity property matls.
 TUCKER, M. K. Energy, Dept. of. 83/06/01. SMITH, D. Uranium Recovery Field Office 2pp 18937.031.

DOCKET 40-2061 KERR-MCQUEE CHEMICAL CORP., OKLAHOMA CITY, OK

06080293 FOIA request for list of addressees receiving DEB re decommissioning of Rare Earths Facility, West Chicago, IL subsequent to May 1982
 SPELMAN, H. J. Harold J. Spelman & Associates. 83/03/23. Division of Rules and Records. 8pp. 18792.145.

8306080297 Responds to FOIA request for list of addressees receiving DEB re decommissioning of Rare Earths Facility, West Chicago, IL subsequent to May 1982 Forwards mailing list for DEB Addressees receiving DEB after May 1982 not identified
 FELTON, J. M. Division of Rules and Records 83/04/06 SPELMAN, H. J. Harold J. Spelman & Associates 1p 18792 147

--B306080302 "Distribution List, Kerr-McQuee West Chicago DEB"
 * NRC - No Detailed Affiliation Given 83/04/06 8pp 18792 148

8306010069 Forwards response to JL Grant ltr commenting on thorium plant closure rept Differences exist due to lack of access or possession of ref documents
 PORT, E. A. Radiation Safety Services, Inc. 83/04/08 FILMER, P. L. Harold J. Spelman & Associates. 8pp 18687.082

8306060362 Issues Amends 5 & 6 to License STA-583 authorizing dismantling of Bldgs 2, 10, 11, 14, 16 & 21 at West Chicago site.
 PAGE, R. O. Uranium Fuel Licensing Branch 83/05/27 SHELLEY, W. J. Kerr-McQuee Chemical Corp (subs of Kerr-McQuee Corp) 1p. 18731.282

--B306060367 Safety evaluation supporting Amends 5 & 6 to License STA-583, authorizing dismantling of Bldgs 2, 10, 11, 14, 16 & 21 at West Chicago site
 NIXON, W. A. Uranium Fuel Licensing Branch. 83/05/27 4pp 18731.283

8306080399 Forwards completed eligibility form for inorganic chemical mfg industries that may be subj to pretreatment regulations Facility shut down since 1970
 DENNY, I. L. Kerr-McQuee Chemical Corp (subs of Kerr-McQuee Corp.) 83/05/27 ROBICHAUD, R. R. Environmental Protection Agency 2pp 18789 346.

8306200042 Forwards Radiation Safety Svcs, Inc response to JL Grant ltr re assessment of Law Engineering Testing Co West Chicago thorium plant closure rept Delay in receipt of response due to omission of name from distribution list
 SPELMAN, H. J. Harold J. Spelman & Associates 83/05/28 NIXON, W. A. NRC - No Detailed Affiliation Given 8pp 18919 310

8306080146 FINAL ENVIRONMENTAL STATEMENT RELATED TO THE DECOMMISSIONING OF THE RARE EARTHS FACILITY, WEST CHICAGO, ILLINOIS, Docket No 40-2061
 * Division of Fuel Cycle & Material Safety NUREG-0904. 83/05/31 522pp Available at NRC \$10.00. 18788.001.

8306020343 Advises that time for Commission to review presiding officer decision expired Commission declined review Decision became final agency action on B30527
 CHILK, B. J. Office of the Secretary of the Commission 83/06/01. Kerr-McQuee Chemical Corp. (subs of Kerr-McQuee Corp) 1p. 18694.288.

8306070435 Forwards FR notice of availability of FES re decommissioning of Rare Earths facility.
 PAGE, R. O. Uranium Fuel Licensing Branch. 83/06/02. SHELLEY, W. J. Kerr-McQuee Chemical Corp. (subs of Kerr-McQuee Corp.) 1p 18776.349

--B306070442 Notice of opportunity for hearing & availability of FES for decommissioning of Rare Earths facility
 PAGE, R. O. Uranium Fuel Licensing Branch 83/05/27 4pp 18776.350

DOCKET 40-2239 PATHFINDER MINES CORP., RIVERTON, WY

8306130406 Comments on Fourth Quarter 1982 environ monitoring data for Pathfinder Mines Corp Lucky Mc Mill Radionuclide data for groundwater monitoring wells will be submitted in Apr 1983
 WOOLSEY, R. T., PETTENGILL, H. J. Uranium Recovery Field Office 83/03/11 Region 4, Office of Director 3pp. 18823.092.

8306160656 Submits waste matls disposal program. Wastes are monitored by radiation staff & classified according to contamination level
 POYBER, R. W. Pathfinder Mines Corp 83/03/24 WOOLSEY, R. T. Uranium Recovery Field Office 3pp 18876.273

8306020263 Updates status of pumpback sys & contaminated groundwater plume at Lucky Mc Mill site Surface expression of contaminated groundwater plume still exists.
 WILLIAMS, R. E. R. E. Williams & Associates, Inc 83/04/18. PETTENGILL, H. Uranium Recovery Licensing Branch 3pp 18700.323

DOCKETED ITEMS

3

8306160234 "Quarterly Effluent Monitoring Rept for Fourth Quarter 1982" W/830512 ltr
HARDGROVE, T W Pathfinder Mines Corp 83/05/12. WOOLSEY, R T
Uranium Recovery Field Office 3pp 18861 236.

8306220121 Forwards comments on renewal application re final reclamation plan & seepage control. Considerable upgrading of plan to assure long-term stabilization recommended.
FREUDENTHAL, N Wyoming, State of. 83/05/23 SMITH, D. NRC - No Detailed Affiliation Given 10pp 18977-034

DOCKET 40-3392 ALLIED CHEMICAL CORP., MORRISTOWN, NJ

8306080404 Forwards response to environ questions, per 830425 ltr re Source Mat'l License SUB-826
CIPOLLA, A J Allied Chemical Corp. 83/05/27 WYNWARDEN, S. Uranium Fuel Licensing Branch 28pp. 18791-219

DOCKET 40-3453 ATLAS MINERAL, INC., DENVER, CO

8306200437 Tabulates contract costs incurred & manhours expended in reviewing 821026 application for Amend 11 to License
SUA-917
OARCIA, P, PETTENGILL, H. Uranium Recovery Field Office 83/05/15 MILLER, W. O. License Fee Management Branch 1p. 18920.011.

8306200107 Informs that Moab Wash interim operation phase mode complete per revised Condition 16, dtd 830228
BLUBAUGH, R E Atlas Minerals. 83/05/17. SMITH, D. Uranium Recovery Licensing Branch. 1p. 18908-232.

8306170468 Informs of 821004 official opening of U recovery field ofc in Lakewood, Co. Future correspondence should be sent to Lakewood field ofc, effective 830601, Washington, DC ofc being phased out
SMITH, R D. Uranium Recovery Field Office. 83/05/23 BLUBAUGH, R Atlas Minerals 6pp. 18894 356

DOCKET 40-4492 FEDERAL-AMERICAN PARTNERS, RIVERTON, WY

8306200047 Confirms understanding per 830511 telcon that work can begin on Willow Springs Draw w/o completing design mods & requirements specified in Amend 14 to License SUA-667. Rerouting of draw may be delayed due to bad weather
ANDRUS, N. J. Federal American Partners 83/05/18. LINEHAN, J. Uranium Recovery Field Office. 2pp. 18908-171.

DOCKET 40-6264 MICHIGAN CHEMICAL CORP., ST. LOUIS, MI

8306210434 Discusses site evaluation & closeout of docket file. Consent judgement requirements & proposed notations on granite marker & in land deeds adequate to protect public from radioactive contaminants on site.
CROW, W. T., PAGE, R O Uranium Fuel Licensing Branch. 83/06/08. Uranium Fuel Licensing Branch. 3pp. 18936-357.

8306170479 Confirms 830601 telcon re Velsicol Chemical Corp site in St Louis, MI. Stabilization plan implementation imposed by 821227 consent judgement adequate to protect public & environ from radioactive contaminants
PAGE, R O Uranium Fuel Licensing Branch 83/06/09. RADEMACHER, J. H. Velsicol Chemical Corp 1p. 18894-321.

DOCKET 40-6500 ENERGY, DEPT OF, CANONSBURG, PA

8306030506 Summary of data from Mound radon program monitoring network in Canonsburg, PA area for 820129-0430. CAR designators in table to be used w/maps of Canonsburg area sent to NRC on 830415
RUDY, C R Monsanto Research Corp 83/04/22. CROW, W. T. Assistant Director for Fuel Cycle Safety & Licensing. 2pp. 18735-003.

8306010095 Summary of Canonsburg outdoor monitoring data, mound radon program for 820429-0729.
RUDY, C R. Monsanto Co. 83/04/29. CROW, W. T. Uranium Fuel Licensing Branch. 2pp. 18686-348.

8306030194 Summary of data from Mound/radon program radon monitoring network in Canonsburg, PA area for 821029-830128. Indoor radon monitoring commenced on 821119 at new site not marked on location map.
RUDY, C R. Monsanto Research Corp 83/05/10. CROW, W. T. Assistant Director for Fuel Cycle Safety & Licensing. 4pp. 18733-325.

8306010479 Comments on items of interest Amend issued to Licensee SUB-1010, authorizing disposal of treated liquid raffinate via injection in deep salt water aquifer.
PAGE, R O Uranium Fuel Licensing Branch 83/05/26. DAVIS, J. O. Office of Nuclear Material Safety & Safeguards, Director 1p. 18688, 358.

8306070430 Submits current items of interest re issuance of License BNM-1915 on 830531 & 830526 meeting w/DOE to discuss UNTRCA program
PAGE, R O Uranium Fuel Licensing Branch 83/06/02. DAVIS, J. O. Office of Nuclear Material Safety & Safeguards, Director. 3pp 18780-345

8306280030 Summary of 830609 meeting w/DOE in Albuquerque, NM re DES for remedial action at Canonsburg, PA site. NHSS meeting schedule encl
PAGE, R O Uranium Fuel Licensing Branch 83/06/16. DAVIS, J. O. Office of Nuclear Material Safety & Safeguards, Director. 2pp. 19042 359.

8306290101 Summary of 830617 meeting w/DOE on proposed remedial action plan for Canonsburg, PA site. DOE informed of add'l info required to continue technical review of plan. Notice of 830707 meeting w/EPA encl.
PAGE, R O. Uranium Fuel Licensing Branch 83/06/22 DAVIS, J. O. Office of Nuclear Material Safety & Safeguards, Director. 2pp. 19046 178.

DOCKET 40-6622 PATHFINDER MINES CORP., SHIRLEY BASIN, WY

8306140168 Requests add'l info or explanations on Questions 2(a), 2(b) & 3 re slope stabilization & PMF in order to respond completely to request for add'l info re application for licensing.
RUSSELL, J E. Pathfinder Mines Corp. 83/05/05. PETTENGILL, H. J. Uranium Recovery Licensing Branch. 1p 18844-185.

DOCKET 40-6940 KAMECKI BERYLCO IND., INC., BOYERTOWN, PA

8306280610 Discusses IE Insp Rept 40-6940/83-01 conducted on 830607 & 08 No noncompliance noted. Major areas inspected: radiation safety; procedures & representative records; interviews w/personnel & measurements taken by inspector
MARTIN, T. T. Division of Engineering & Technical Programs. 83/06/22. COYLE, F. KBI Corp 2p. 19015-359.

8306290611 Summary of 830607 & 08 site safety insps in Boyertown, Revere & Reading, PA.
COOL, D. A. Division of Fuel Cycle & Material Safety. 83/06/22. Division of Fuel Cycle & Material Safety. 2pp. 19047-083.

DOCKET 40-7580 FANSTEEL, INC., NORTH CHICAGO, IL

8306030469 Trip rept of 830505 meeting w/licensee & State of OK Water Resources Board at site in Muskogee, OK re application for add'l ponding capacity.
RHODES, M. J. Uranium Fuel Licensing Branch. 83/05/26. Uranium Fuel Licensing Branch. 1p. 18735-277.

DOCKET 40-7869 PLATEAU RESOURCES, LTD., GRAND JUNCTION, CO

8306130347 "Effluent Monitoring Rept" for Jul-Dec 1982 for Shooting Canyon leaching facility.
GERDEMAN, F. W. Plateau Resources, Ltd. 83/04/13. Region 4, Office of Director. 11pp. 18822-296.

DOCKET 40-8027 KERR-MCQUEE NUCLEAR CORP., OKLAHOMA CITY, OK

8306130344 Repts release of nuclides in effluents to unrestricted areas during Second Half 1982.
SHELLEY, W. J. Kerr-McQuee Chemical Corp. (subs. of Kerr-McQuee Corp.). 83/02/21 BROWN, O D. Region 4, Office of Director. 3pp. 18823-002.

8306080152 Forwards IE Insp Rept 40-8027/83-01 on 830214-18 & notice of violation
BROWN, O D. Region 4, Office of Director. 83/04/06 SHELLEY, W. J. Kerr-McQuee Nuclear Corp. 2pp. 18772-175.

--8306080156 Notice of violation from insp on 830214-18.
* Region 4, Office of Director. 83/04/06. 2pp. 18772-177.

DOCKETED ITEMS

--8306080165 IE Insp Rept 40-8027/83-01 on 830214-18 Noncompliances noted. Failure to perform direct radiation surveys & properly sample stack effluent. One unresolved item re location of air sampler heads & air flow rates identified.
SHOENEN, M. M., SPITZBERG, D. B., EVERETT, R. J. Region 4, Office of Director 83/03/24. 11pp 18772 179.

8306020213 Forwards list of formal site visit questions re EIA on license renewal. Written responses needed by 830613
RHODES, M. Uranium Fuel Licensing Branch 83/05/24 SHELLEY, W. J.
Kerr-McGee Nuclear Corp. 6pp. 18701 048.

8306030186 Trip rept of attendance at 830504 meeting w/Kerr-McGee Nuclear Corp in Core, OK re questions concerning environ review of vendor license renewal application
RHODES, M. J. Uranium Fuel Licensing Branch. 83/05/26. Uranium Fuel Licensing Branch. 1p 18733 320

8306140767 Forwards request for addl info re evaluation of 820924 renewal application for License BUA-1010 Comments on initial review encl. Formal response to comments expected by 830715. Meeting to discuss draft response suggested.
KOSLA, B. M. Uranium Fuel Licensing Branch 83/06/02. SHELLEY, W. J.
Kerr-McGee Nuclear Corp 5pp. 18845 333.

8306210343 Forwards leach test results of composite sample of lime fluoride sludge per request. Quantity of U leached w/water leach test negligible. Substantiating soundness of proposed onsite burial.
SHELLEY, W. J. Kerr-McGee Corp. 83/06/06 PAOE, R. O. Uranium Fuel Licensing Branch 2pp. 18999 181

DOCKET 40-8035 COTTER CORP., ROSWELL, NM

8306060416 Summary of 830503 meeting w/DOE, Bechtel & State of MO representatives in St Louis, MO re legislation on decontamination of former Cotter Corp site. List of attendees encl
CROW, W. T. Uranium Fuel Licensing Branch. 83/05/31. Uranium Fuel Licensing Branch 2pp 18748 357

DOCKET 40-8064 EXXON MINERALS CO USA, HOUSTON, TX

8306060318 Proposes mod to excursion parameters monitoring frequency from bimonthly to monthly. Mod would affect Conditions 30 & 31 of License BUA-1064 & portions of Tables 2 & 3 in 830917 submittal
OILCHIRIST, J. E. Exxon Corp. 83/04/19 LINEHAN, J. J. Uranium Recovery Field Office 7pp. 18751 354.

8306020294 Withdraws Comment 3 re expanded R&D pilot U solution mine. Licensee supplied adequate data to justify limited sampling suite currently being analyzed. Wells M-G, 4 & 5 should be included in post-restoration monitoring program
FREUDENTHAL, N. SMITH, M. Wyoming, State of 83/04/25. SMITH, R. D. Uranium Recovery Field Office. 7pp 18700 316

8306070456 Notifies of mod restoration program at Highland expanded R&D pilot U in situ mine. Use of reverse osmosis sys will be terminated. Sample groundwater sweep program will be implemented.
SHANNON, J. B. Exxon Corp. 83/05/03. LINEHAN, J. J. Uranium Recovery Field Office. 1p 18780 311.

8306210454 Forwards Land Quality Div & Water Quality Div reviews of Exxon 820917 matl re restoration of original pilot in situ U mine.
FREUDENTHAL, N. Wyoming, State of 83/05/06. SMITH, R. D. Uranium Recovery Field Office. 22pp. 18938 316.

8306200421 Reaffirms position that max practical restoration achieved & demonstrated for original pilot in situ U mine at Highland per 820929 & 830406 submittals.
OILCHIRIST, J. E. Exxon Corp. 83/05/17. LINEHAN, J. J. Uranium Recovery Field Office. 2pp. 18919 292.

DOCKET 40-8084 RIO ALGOM CORP., MOAB, UT

306090163 Forwards IE Insp Rept 40-8084/82-02 on 821214-16 & notice of violation.
BROWN, G. D. Region 4, Office of Director. 83/02/02 LAWTON, M. D. Rio Algom, Ltd 2pp. 18792 322

--8306090167 Notice of violation from insp on 821214-16.
* Region 4, Office of Director. 83/02/02 2pp 18792 324.

--8306090175 IE Insp Rept 40-8084/82-02 on 821214-16 Noncompliance noted occupational overexposure of one minor to airborne soluble U & to airborne U ore dust to two minors & failure to report overexposures to NRC & individuals
SPITZBERG, D. B., CAIN, C. L., EVERETT, R. J. Region 4, Office of Director 83/01/21 18pp 18792 326

8306200171 Forwards data derived from 1981 vegetation sampling under discontinued License Condition 18 Data should be inserted in 1981 environ monitoring rept Addendum to "Semiannual Environ Monitoring Rept, Jul-Dec 1982," encl
HARDY, B. L. Rio Algom, Ltd 83/05/04 WASTLER, S. Uranium Recovery Licensing Branch 1p 18909 315

--8306200175 Data derived from vegetation sampling during 1981
* Rio Algom, Ltd. 83/05/04 1p 18909 316

--8306200285 Addendum to "Semiannual Environ Monitoring Rept, Jul-Dec 1982"
LAWTON, M. D. Rio Algom, Ltd 83/05/09 38pp 18909 317

8306210431 Reviews licensee Jul-Dec 1982 environ monitoring rept submitted per 10CFR40.65 & License Conditions 36 & 49 Rept lacks sample analyses for Th-230, Pb-210 & Po-210 due to commercial lab delays
WASTLER, S. L., LINEHAN, J. J. Uranium Recovery Field Office 83/05/18 Uranium Recovery Field Office 3pp 18937 028

DOCKET 40-8348 MINERALS EXPLORATION CO, LOS ANGELES, CA

8306280106 Forwards memos discussed at 830511 meeting. Memos are internal & do not represent official final div decisions on restoration issues.
ENGELMANN, R. Wyoming, State of. 83/05/12 VOLK, B. Union Energy 1p 19042 302

DOCKET 40-8380 ROCKY MOUNTAIN ENERGY CO, BROOMFIELD, CO

8306160567 Forwards quarterly & monthly well data for Jan-Mar 1983. No further mining or restoration planned for Second Quarter 1983
SPIELER, P. R. Rocky Mountain Energy Co 83/04/30 SMITH, R. D. Uranium Recovery Field Office 3pp 18866 015

--8306160576 Quarterly & monthly well data for Jan-Mar 1983
* Rocky Mountain Energy Co 83/04/30 13pp. 18866 018.

8306200276 Advises that Patterns 1, 2 & 3 sufficiently restored so well closure of Nine Mile Lake R&D Project can be authorized. Vendor must secure surface owner release & advise well permit applicants in area of groundwater conditions.
SHAFFER, R., SUDIN, R. Wyoming, State of 83/05/20 OLDHAM, K. R. Rocky Mountain Energy Co 2pp 18909 357

8306200425 Advises that future applicants for well permits near Nine Mile Lake will be notified of deteriorated state of groundwater. Monitoring of plume movement suggested.
BEACH, O. Rocky Mountain Energy Co. 83/05/25. Rocky Mountain Energy Co. 1p. 18920 026

DOCKET 40-8452 BEAR CREEK URANIUM CO, CASPER, WY

8306090224 Concurs w/preferred tailings disposal alternative of expanding present area. Const of dam raise may not begin until dam stability review performed & license amend issued
SMITH, R. D. Uranium Recovery Field Office. 83/05/18 Bear Creek Uranium Co 4pp. 18909 205

--8306090228 Discusses Amend 20 to Source Matl License BUA-1310 re tailings mgmt alternative of expansion of disposal area.
PANOSBURN, O. C., PETTENGILL, H. J. Uranium Recovery Field Office 83/05/18. Uranium Recovery Field Office 16pp 18809 209.

DOCKET 40-8502 WYOMING MINERAL CORP, LAKEWOOD, CO

8306130245 "Irigaray Mine Site Semiannual Activity & Monitoring Rept for Jul-Dec 1982" w/830215 1tr
RUTLEDGE, C. Wyoming Mineral Corp. 82/12/31 BROWN, C. Region 4, Office of Director. 11pp 18824 300.

8306020338 Issues Amend 5 to Source Matl License BUA-1341 changing License Condition 10 to incorporate radiation protection organization chart submitted by licensee on 830308
SMITH, R. D. Uranium Recovery Field Office 83/05/05 Wyoming Mineral Corp. 1p. 18715 316.

DOCKETED ITEMS

5

8306200182 Requests instructions & guidelines for preparing & filing, w/fee application, renewal of License SUA-1341 under 10CFR170.31-2D
RUTLEDGE, C. Wyoming Mineral Corp. 83/05/16 ROSE, F. Uranium Recovery Field Office. 1p. 18909.182

8306160215 "Water Quality Data on Excursion Wells, Irigaray Mine Site, Jan-May 1983." W/830526 1tr
RUTLEDGE, C. Wyoming Mineral Corp. 83/05/26 SMITH, R. D. Uranium Recovery Field Office. 2pp. 18861.174

8306240436 Updates 821008 & 830127 status repts on Monitor Wells 9TB & 9T32, for Jan-May 1983, per 830526 telcon. Monitoring parameters for wells diminished to below NRC action level in four recent analyses
RUTLEDGE, C. Wyoming Mineral Corp. 83/05/26 SMITH, R. D. Uranium Recovery Field Office. 2pp. 18977.239

DOCKET 40-8584 MINERALS EXPLORATION CO., LOS ANGELES, CA

8306140687 Requests amend to License SUA-1330, modifying environ & plant monitoring programs & procedures placing mill & tailings in environmentally acceptable condition
SNYDER, H. L. Union 76 Minerals Exploration Co. 83/04/12. SMITH, R. D. NRC - No Detailed Affiliation Given. 7pp. 18843.356

8306040415 Advises that liner manufacturer or installer for tailings cell liner not yet selected. Specific installation details & plans unavailable. Installation specs will be provided prior to installation
SNYDER, H. L. Union Minerals. 83/04/22 GARCIA, P. Uranium Recovery Field Office. 1p. 18748.356

8306020500 Confirms 830428 telcon re possible reportable incident concerning disposal of low grade ore, mixed mill effluents & waste into internal mine pit waste dump. Attempt to locate mixed ore & effluents for removal planned.
DYKERS, L. O. Union 76 Minerals Exploration Co. 83/04/29 SMITH, R. D. Uranium Recovery Field Office. 1p. 18715.183

8306200179 Forwards insp rept on 830422 re interim stabilization & citizen O Beach complaint. Containment pond residue, drilling, sampling & analysis procedure outline & description of incidents surrounding complaint requested.
ENGELMANN, R. Wyoming, State of. 83/05/09. DYKERS, L. O. Union 76 Minerals Exploration Co. 13pp. 18909.169.

8306200111 Trip rept of attendance at 830510 meeting w/State of WY Dept of Environ Quality & Mineral Exploration Co in Cheyenne, WY re request for license to construct new tailings disposal facility at Sweetwater Hill in Red Desert
WILLIAMS, R. E. R.E. Williams & Associates, Inc. 83/05/11. GARCIA, P. Uranium Recovery Field Office. 3pp. 18908.233.

8306270177 Advises of administrative changes. CZ Hill will replace LQ Pykers as project manager of Sweetwater U Mine. TJ Klein will handle H.L. Snyder former responsibilities.
HOPKINS, J. M. Union 76 Minerals Exploration Co. 83/05/25. SMITH, R. D. Uranium Recovery Field Office. 1p. 18999.349.

8306220113 Responds to R Williams 830511 comments on meetings in Cheyenne, WY re modified tailings proposal. Response clarifies conclusions inconsistent w/Williams conclusions. Further evaluation of issue recommended
FREUDENTHAL, N. Wyoming, State of. 83/05/27. LINEHAN, J. Uranium Recovery Field Office. 2pp. 18977.338

8306200423 Responds to request for rept on 830519 visit to Sweetwater Hill. Six wells used to monitor groundwater at site. Bank erosion continuing problem w/pond. Leak detection sys checked daily
MITCHELL, D. H. Battelle Memorial Institute, Pacific Northwest Laboratory. 83/06/01. PETTENGILL, H. J. Uranium Recovery Field Office. 1p. 18919.294

DOCKET 40-8585 WYOMING MINERAL CORP., LAKEWOOD, CO

8306020515 Responds to 830308 request for amend to License SUA-1351 re appointment of corporate radiation protection officer. No amend required since new officer meets qualifications included in license. Case closed
SMITH, R. D. Uranium Recovery Field Office. 83/05/10. Wyoming Mineral Corp. 1p. 18715.145.

8306090495 Discusses review of semiannual effluent monitoring rept for Bingham Canyon Extraction Plant for Jul-Dec 1982. Rept adequate. No further licensing action required.
YOUNG, Y. PETTENGILL, H. J. Uranium Recovery Field Office. 83/05/18. Uranium Recovery Field Office. 1p. 18815.167.

DOCKET 40-8586 KERR-MCGEE NUCLEAR CORP., OKLAHOMA CITY, OK

8306020331 Issues Amend 1 to Source Mat'l License SUA-1330 revising Conditions 4 & 29 to extend expiration date of license & require submittal of rept on site decommissioning activities
SMITH, R. D. Uranium Recovery Field Office. 83/04/29. Kerr-McGee Corp. 2pp. 18715.307

--8306020334 Advises of 830429 issuance of amend to Source Mat'l License SUA-1330 extending expiration date of license. Amend initiated by NRC & is exempt from fees
JOHNSON, T. L., PETTENGILL, H. J. Uranium Recovery Field Office. 83/04/29. MILLER, W. O. License Fee Management Branch. 1p. 18715.309.

DOCKET 40-8610 STEPAN CHEMICAL CO., MAYWOOD, NJ

8306020238 Forwards application for renewal of License BTC-1333, authorizing burial of alkaline thorium phosphate tailings at listed locations
SWANSON, E. A. Stepan Chemical Co. 83/03/16. Division of Fuel Cycle & Material Safety. 1p. 18700.358.

--8306020243 Application for renewal of License BTC-1333, authorizing burial of alkaline thorium phosphate tailings at listed locations.
SWANSON, E. A. Stepan Chemical Co. 83/03/15. 4pp. 18700.359.

8306270238 Ack receipt of 830115 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 40-8610/80-01. Comprehensive environ rept required prior to NRC review of 830321 license renewal application.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/06/16. JACOBSON, R. L. Mayer, Brown & Platt. 2pp. 18988.260.

--8306270239 Responds to NRC 821215 ltr re violations noted in IE Insp Repts 40-8610/80-01. Stepan not legally liable for presence of thorium on property between fence & railroad tracks.
JACOBSON, R. L. Mayer, Brown & Platt. JACOBSON, R. L. Stepan Chemical Co. 83/01/15. MARTIN, T. T. Division of Engineering & Technical Programs. 7pp. 18988.262

DOCKET 40-8631 ARMY, DEPT. OF, ROCK ISLAND, IL

8306210148 PNO-III-83-046, on 830610, contaminated water from Weldon Spring Chemical Plant appeared to be draining into miss sewage sys due to dislodged mechanical plug. Cause unknown. Plug replaced
NICHOLSON, N., SCHUMACHER, M. Region 3, Office of Director. 83/06/15. 2pp. 18915.246

DOCKET 40-8663 NUCLEAR DYNAMICS, INC., PHOENIX, AZ

8306090172 Forwards IE Insp Rept 40-8663/83-01 on 830316. No noncompliance noted.
BROWN, O. D. Region 4, Office of Director. 83/04/15. BTOWICK, A. F. ND Resources, Inc. 2pp. 18792.281

--8306090179 IE Insp Rept 40-8663/83-01 on 830316. No noncompliance noted. Insp consisted of site visit to determine status, review of records re past operation & ongoing monitoring programs. Facility inactive since Sept 1979.
SPITZBERG, D. B., EVERETT, R. J. Region 4, Office of Director. 83/04/13. 3pp. 18792.283.

DOCKET 40-8674 PLATEAU RESOURCES, LTD., GRAND JUNCTION, CO

8306220311 Application for amend to License Conditions 10 & 19 of License SUA-1326, due to organizational changes
GERDEMAN, F. W. Plateau Resources, Ltd. 83/05/06. SMITH, R. D. Uranium Recovery Licensing Branch. 3pp. 18977.182.

DOCKET 40-8681 ENERGY FUELS NUCLEAR, INC., DENVER, CO

8306230027 Forwards final rept: "1981 Excavations on White Mesa Ben Juan County, UT." Excavations conducted to comply w/License Conditions 43 & 47. Rept should complete archeological work for current phase of tailings sys.
ROBERTS, H. R. Energy Fuels Nuclear, Inc. 83/06/01. GILLEN, D. Uranium Recovery Field Office. 1p. 18982.028.

DOCKETED ITEMS

--8306230030 "1981 Excavations on White Mesa, San Juan County, UT" final rept
DAVIS, W E Plano Archaeological Consultants 83/02/28 574pp
18933 106

8306090181 Forwards IE Insp Rept 40-8681/82-01 & IE Enforcement Conference Rept 40-8681/82-02 on 821102-04 & 1207, respectively
BROWN, G D Region 4, Office of Director 83/03/07 VINCELETTE, M D
Energy Fuels Nuclear, Inc 2pp. 18772 261.

--8306090190 IE Insp Rept 40-8681/82-01 on 821102-04 Noncompliance noted: failure to rept worker overexposure to airborne soluble U, to use source mat'l per license application & to post airborne radioactivity areas
CAIN, C L, EVERETT, R J Region 4, Office of Director 82/12/09, 11pp 18772 263.

--8306090193 IE Enforcement Conference Rept 40-8681/82-02 on 821207 Major areas discussed findings of NRC insp on 821102-04 Licensee will use approved respiratory protection program & expanded surveys in mill yellowcake areas
CAIN, C L, EVERETT, R J Region 4, Office of Director 82/12/13 2pp. 18772 274

8306220274 Ack receipt of 830407 payment of civil penalties proposed in NRC 830222 ltr. Corrective actions will be examined during subsequent insps
AXELRAD, J A Director's Office, Office of Inspection and Enforcement. 83/04/21 VINCELETTE, M D Energy Fuels Nuclear, Inc. 2pp. 18926 031.

8306020305 Forwards amend to memorandum of agreement between NRC & Advisory Council on Historic Preservation re mitigation of adverse effects of White Mesa U Mill project Signature requested.
SMITH, R D Uranium Recovery Field Office 83/05/03 SMITH, M T
Utah, State of. 1p 18715.275.

--8306020308 Amend to memorandum of agreement between NRC & Advisory Council on Historic Preservation re mitigation of adverse effects of White Mesa U Mill project
PETTENHILL, H J NRC - No Detailed Affiliation Given, * Advisory Council on Historic Preservation. 83/05/03 4pp 18715 276

8306020326 Issues Amend 21 to Source Mat'l License SUA-1358 revising Conditions 40.41, 45, 47 & Table A re archaeological sites affected by White Mesa Project Deadline for recovery of all "eligible" archaeological sites eliminated
SMITH, D. Uranium Recovery Field Office. 83/05/11. Energy Fuels Nuclear, Inc. 3pp. 18715 300

--8306020328 Recommends issuance of Amend 21 to License SUA-1358 revising Conditions 40.41, 45, 47 & Table A changing archaeological site designations from "eligible" to "contributing" & eliminating deadline for recovery
GILLEN, D M, LINEHAN, J J Uranium Recovery Field Office 83/05/11. Uranium Recovery Field Office. 4pp. 18715.303

8306090489 Presents NRC review of data in environ monitoring rept for Fourth Quarter 1982 Licensee has now reverted to semiannual reporting in Feb & Aug of each yr. No significant variations identified
GILLEN, D M, PETTENHILL, H J. Uranium Recovery Field Office 83/05/18 Uranium Recovery Field Office 3pp 18815.164.

DOCKET 40-8684 WESTERN NUCLEAR, INC., LAKEWOOD, CO

8306230032 Forwards design of multi-well pumping test planned for summer for R&D Site 2 to Christensen Ranch, for review
Proposed pumping test should be discussed at 830319 meeting.
BODDEN, O Western Nuclear, Inc (subs of Phelps Dodge Corp.) 83/05/11, LINEHAN, J C. Uranium Recovery Field Office. 22pp 18934:320

DOCKET 40-8497 ROCKY MOUNTAIN ENERGY CO., DENVER, CO

8306160329 "Quarterly Environ Monitoring Rept for First Quarter 1983." SPIELER, P R. Rocky Mountain Energy Co. 83/04/18 SMITH, R D. Uranium Recovery Field Office 18pp 18859.288

8306200160 Advises that restoration of groundwater within Pattern II well field meets applicable groundwater use classification stds per Permit 479. Decision based on company info & confirmation water samples collected on 830208-09
SUNDIN, R E Wyoming, State of 83/05/04 YELICH, J A Rocky Mountain Energy Co. 2pp 18909 126

8306070450 Responds to 830504 discussion w/NRC re extension to license to authorize decommissioning activities Ltr requesting license extension will be submitted at least 30 days prior to 830930 expiration date.
NEUMANN, M R Rocky Mountain Energy Co 83/05/05 LINEHAN, J
Uranium Recovery Licensing Branch 1p 18780 359

DOCKET 40-8698 PLATEAU RESOURCES, LTD., GRAND JUNCTION, CO

8306090129 Forwards IE Insp Rept 40-8698/82-02 & IE Enforcement Conference Rept 40-8698/83-01 on 821123 & 830111, respectively
BROWN, G D Region 4, Office of Director. 83/03/07 FISHER, B D
Plateau Resources, Ltd 2pp 18792 228

--8306090132 IE Insp Rept 40-8698/82-02 on 821123 Noncompliance noted: failure to rept worker overexposures to airborne soluble U & to maintain bioassay program in accordance w/license requirements
CAIN, C L, EVERETT, R J. Region 4, Office of Director 83/01/26 5pp 18792 230

--8306090138 IE Enforcement Conference Rept 40-8698/83-01 on 830111. Major areas discussed findings of NRC insp on 821123 Licensee will implement engineering controls, restrain personnel & modify procedures
CAIN, C L, EVERETT, R J Region 4, Office of Director 83/01/26 2pp 18792 235.

8306140356 Forwards revised surety estimates in response to License Condition 39, to better reflect costs of decommissioning & reclamation Discussion of proposed method of capping tailings impoundment also encl
GERDEMAN, F W Plateau Resources, Ltd 83/04/11 SMITH, R D. NRC - No Detailed Affiliation Given. 1p 18854.143.

--8306140367 "Interim Surety Estimates for Decommissioning & Reclamation," Shootaring Canyon processing facility.
* Plateau Resources, Ltd. 83/04/30 NRC - No Detailed Affiliation Given 8pp 18854.144

8306220271 Ack receipt of 830324 payment of civil penalties proposed in NRC 830222 ltr. Corrective actions will be examined during subsequent insps
AXELRAD, J A. Director's Office, Office of Inspection and Enforcement 83/04/21 FISHER, B D. Plateau Resources, Ltd. 2pp 18926 029.

DOCKET 40-8714 CLEVELAND-CLIFFS IRON CO., CLEVELAND, OH

8306170459 "Quarterly Rept, Jan-Mar 1983." W/one oversize figure. Aperture card is available in PDR. W/830427 ltr
WDEK, D J. Cleveland-Cliffs Iron Co. 83/04/27. LINEHAN, J Uranium Recovery Licensing Branch. 29pp 18894-273

8306200036 Forwards 830519 ltr to N Fraudenthal confirming 830511 meeting results re water quality restoration Cooperation & input appreciated.
SUNDAHL, J A. Godfrey & Sundahl. 83/05/23 LINEHAN, J. Uranium Recovery Field Office 5pp. 18908 357

DOCKET 40-8722 BRUSH WELLMAN, INC., CLEVELAND, OH

8306130243 "NRC Rept for Effluent Monitoring of Stack Emissions." Jul-Dec 1982 Stacks need not be monitored in future because baseline data now achieved; per license suppl W/830222 ltr.
ATHOOD, M D Brush Wellman, Inc 83/02/22 Region 4, Office of Director 51pp 18826.329

8306080119 Discusses IE insp of License SUA-1354 on 830131-0201 & forwards notice of violation
BROWN, G D Region 4, Office of Director 83/03/01 VALIQUETTE, J.
Brush Wellman, Inc 2pp. 18773.044

--8306080124 Notice of violation from insp on 830131-0201 Noncompliance noted: semiannual repts for First Quarters 1981 & 82 failed to identify pronounced increase in measured RN-222 levels at two offsite locations.
* Region 4, Office of Director 83/03/01 2pp 18773 046.

DOCKETED ITEMS

7

DOCKET 40-8728 TETON EXPLORATION DRILLING CO, INC, CASPER, WY

8306220126 Forwards P Pucel & C McCarty review of Teton Exploration Co M-zone restoration-stability repts Rept supercedes 830511 rough draft
FREUDENTHAL, N Wyoming, State of 83/05/16 SMITH, R. D Uranium
Recovery Licensing Branch 14pp 18977 137

DOCKET 40-8745 DOLE PETROLEUM, INC, CASPER, WY

8306130367 Presents info required in semiannual ALARA audit per License BUA-1396, Condition 17 Region IV license repts evaluation encl
BROWN, K. J Dole Petroleum, Inc 83/02/15 Region 4, Office of
Director 4pp 18822 320.

DOCKET 40-8768 KERR-MCQUEE NUCLEAR CORP, OKLAHOMA CITY, OK

8306240444 Forwards evaluation of Kerr-McQuee O sand in situ project R&D testing license application Application not acceptable.
Permit rev requested
FREUDENTHAL, N Wyoming, State of 83/05/26 SMITH, D NRC - No
Detailed Affiliation Given 15pp 18977 258

8306220140 "G-Band In Situ U Recovery R&D Project, Converse County, WY." First Quarter 1983, W/830531 ltr
SHELLEY, W. J Kerr-McQuee Corp 83/05/31 SMITH, R. D Uranium
Recovery Licensing Branch 53pp 18977 044

DOCKET 40-8783 URANERZ USA, INC., CASPER, WY

8306210353 "First Quarterly Rept, Jan-Mar 1983 " W/three oversize drawings Aperture cards are available in PDR
SOMERVILLE, K. Q Uranerz USA, Inc. 83/05/23 LINEHAN, J. J. Uranium
Recovery Licensing Branch, 100pp 18936 275

DOCKET 40-8786 URANIUM RESOURCES, INC, RICHARDSON, TX

8306210451 Informs of decommissioning of North Platte R&D Facility. Plant will be mothballed until commercial operations begin
Reverse osmosis unit to be returned to Aquatic Design Sys, Inc.
PELLIZZA, M. B. Uranium Resources, Inc. 83/04/27 Division of Fuel
Cycle & Material Safety 3pp. 18935 340

8306090028 Forwards Vol 2 to "North Platte Technical Rept, Restoration," including verification samples indicating return of groundwater to essentially baseline quality Final
verification samples will be obtained in Aug.
PELLIZZA, M. B. Uranium Resources, Inc. 83/04/28. LINEHAN, J. J.
Uranium Recovery Licensing Branch 1p. 18798 025.

--8306090035 Vol 2 to "North Platte Technical Rept, Restoration " * Uranium Resources, Inc. 83/04/30. 152pp 18798 026

8306020477 Accepts interim decommissioning plan for wellfield & process facility dtd 821014 Addl info needed includes location & depths of soil samples & means of stabilizing sand & sludge remaining in evaporation ponds.
LINEHAN, J. J. Uranium Recovery Field Office 83/04/29. Uranium
Resources, Inc 2pp. 18715 205.

8306220130 Confirms telcon re decommissioning reverse osmosis unit. Alpha probe calibr acceptable Unit will be released as scheduled
PELLIZZA, M. B. Uranium Resources, Inc 83/06/01. GARCIA, P Uranium
Recovery Field Office 1p 18937 360

8306210425 Forwards Uranium Resources, Inc second semiannual ALARA audit of radiation safety program per License Condition 35. Bioassay results within action levels in Table 1 of Reg
Guide B.22
PELLIZZA, M. B. Uranium Resources, Inc. 83/06/05. LINEHAN, J. J.
Uranium Recovery Field Office. 9pp. 18937 033.

DOCKET 40-8794 MOLYCORP., INC., LOS ANGELES, CA

8306020230 Application for amend to License BMB-1408, authorizing processing of 180,000 lbs yttrium-bearing ore currently located at York, PA & Louviers, CO facilities Process described
DOYLE, W. E. MolyCorp, Inc. 83/04/22. BOONQ, A. NRC - No Detailed
Affiliation Given 4pp. 18700 347

8306140442 Authorizes amend to Source Matl License BMB-1408 re processing of source matl for recovery of yttrium.
PAGE, R. Q Uranium Fuel Licensing Branch 83/06/06 WARHOL, W. N
MolyCorp, Inc 1p 18854 066

--8306140446 Discusses review of amend to Source Matl License BMB-1408 authorizing processing of source matl for recovery of yttrium Amend should be issued
BOONQ, A. CROW, W. T Uranium Fuel Licensing Branch. 83/06/06
Uranium Fuel Licensing Branch. 2pp 18854 067

DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

DOCKET 50-2 UNIV OF MICHIGAN RESEARCH REACTOR

G. Inspection reports, IE Bulletins & correspondence

8306270185 Forwards IE Insp Rept 50-002/83-02 on 830516-18. No noncompliance noted
PAPERIELLO, C. J. Region 3, Office of Director. 83/06/10 KERR, W
Michigan, Univ of 2pp 18991 332 24X Fiche: 50-002, 83/06/10, 8306270185

--8306270187 IE Insp Rept 50-002/83-02 on 830516-18 No noncompliance noted. Major areas inspected: radiation protection & radwaste programs, including qualifications, audits, training & radiation protection procedures
GRANT, W. B., BREGER, L. R. Region 3, Office of Director. 83/06/10. 7pp. 18991 334. 24X Fiche: 50-002, 83/06/10, 8306270185

DOCKET 50-3 INDIAN POINT STATION, UNIT 1

G. Inspection reports, IE Bulletins & correspondence

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Bvc list encl.
TAYLOR, J. M. Division of Safeguards & Inspection Programs (Post 830103) 83/05/26. Consolidated Edison Co. of New York, Inc. 128pp 18831 043 24X Fiche: 50-000, 83/05/26, 8305110458.

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet." Bvc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26. Consolidated Edison Co. of New York, Inc. 115pp. 18732 085. 24X Fiche: 50-000, 83/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs." Bvc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31. Consolidated Edison Co. of New York, Inc. 116pp 18732 208. 24X Fiche: 50-000, 83/05/31, 8305110461

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations." Bvc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09. Consolidated Edison Co. of New York, Inc. 119pp 18830 280. 24X Fiche: 50-000, 83/06/09, 8305110464.

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Electrically Induced Chatter in Relays Within Printed Circuit Cards." Bvc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13. Consolidated Edison Co. of New York, Inc. 118pp. 18920 225 24X Fiche: 50-000, 83/06/13, 8305110470.

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables." Bvc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13. Consolidated Edison Co. of New York, Inc. 243pp. 18921 001. 24X Fiche: 50-000, 83/06/13, 8306090010

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers." Bvc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22. Consolidated Edison Co. of New York, Inc. 115pp. 19021 179. 24X Fiche: 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment." Bvc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22. Consolidated Edison Co. of New York, Inc. 120pp 18997 007 24X Fiche: 50-000, 83/06/22, 8305110477.

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions." Bvc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23. Consolidated Edison Co. of New York, Inc. 116pp. 18996 242. 24X Fiche: 50-000, 83/06/23, 8305110479.

DOCKETED ITEMS

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/06/24 Consolidated Edison Co of New
York, Inc. 116pp. 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

R Periodic operating reports & related correspondence

8306270171 Forwards revised pages to semiannual effluent & waste disposal repts for Jan-June 1982 & Jul-Dec 1982, re "Radiological Impact on Man" sections
O'TOOLE, J. D. Consolidated Edison Co of New York, Inc. 83/06/16
ALLAN, J. M. Region 1, Office of Director 1p 18991 358 24X
Fiche 50-000, 83/06/16, 8306270171.

--8306270179 Revised pages to semiannual effluent & waste disposal rept. Jan-June 1982
* Consolidated Edison Co of New York, Inc. 83/06/16 3pp.
18991 359 24X Fiche 50-000, 83/06/16, 8306270171

--8306270184 Revised pages for semiannual effluent & waste disposal rept. Jul-Dec 1982
* Consolidated Edison Co of New York, Inc. 83/06/16 3pp.
18991 362 24X Fiche 50-000, 83/06/16, 8306270171

DOCKET 50-5 PENNSYLVANIA STATE UNIV RESEARCH REACTOR

P Operating license stage documents & correspondence

8306240157 Application for amend to License R-2, modifying 821018 amend request to eliminate use of non-TRIGA fuel elements All other conditions unchanged
CUNNINGHAM, R. O. Pennsylvania State Univ. 83/06/23 THOMAS, C.
Standardization & Special Projects Branch 2pp 18991:039 24X
Fiche 50-000, 83/06/23, 8306240157

V. Operator Examinations

8306140467 Extends invitation to attend 830627 meeting in King of Prussia, PA to discuss transfer of reactor operator licensing function from Bethesda, MD to Region 1 of STAROSTECKI, R. Division of Project & Resident Programs 83/06/09,
CUNNINGHAM, R. O. Pennsylvania State Univ. 2pp. 18834 318. 24X
Fiche 50-000, 83/06/09, 8306140467

DOCKET 50-6 BATTELLE MEMORIAL INST RESEARCH REACTOR

G Inspection reports, IE Bulletins & correspondence

8306230129 Responds to FOIA request for five categories of documents re spent fuel at facilities App A & B documents respond to Items 1, 2, 4 & 5 Forwards App B Documents 1 & 5-11. No documents located for Item 3
FELTON, J. M. Division of Rules and Records 83/04/13 AUDIN, L.
Affiliation Unknown 3pp 18982:047 24X Fiche: 50-014, 83/04/13, 8306230129

--8306230149 Forwards request for addl info re IE Insp Repts 70-0008/82-02, 30-03728/80-02 & 50-006/80-01 concerning problems w/NFB-4 (NAC-1E) casing per 810226 telcon.
CARLSON, R. T. Region 1, Philadelphia, Office of the Director 81/02/27, FISCHER, W. L. Region 3, Chicago, Office of the Director. 4pp 18982:071 24X Fiche: 50-006, 83/04/13, 8306230129.

DOCKET 50-8 NORTH CAROLINA STATE UNIV. RESEARCH REACTOR

J Insurance & indemnity information

8306220286 Unexecuted Amend 17 to Indemnity Agreement E-7, revising attachment, item 2.
SALTZMAN, J. Assistant Director for State & License Relations 83/06/14 1p 18940 350 24X Fiche: 50-008, 83/06/14, 8306220286

DOCKET 50-10 DRESDEN NUCLEAR POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8306210314 FOIA request for NRC records re security violations & safeguards events at nuclear facilities
GOLDENBERG, O. Scripps-Howard Newspapers. 83/04/22 FELTON, J. M.
Office of Administration. 2pp 18925 198 24X
Fiche 50-000, 83/04/22, 8306210314.

8306210306 Partial response to FOIA request for NRC records re security violations & safeguards events at nuclear facilities Repts listed on App A available in PDR Search for addl documents
suby to request continuing
FELTON, J. M. Division of Rules and Records 83/05/16 GOLDENBERG, O.
Scripps-Howard Newspapers 2pp. 18925 196 24X
Fiche 50-000, 83/05/16, 8306210306

8306090247 Confirms 830601 telcon re changes to exercise windows for Dresden & Byron Nuclear Power Stations Dresden partial exercise will be conducted during wk of 830912 w/Dygon
full-scale exercise beginning wk of 831114
JONES, E. E. Illinois, State of 83/06/01 KEPLER, J. Region 3,
Office of Director ANDERSON, J. Federal Emergency Management
Agency WAGNER, O. Commonwealth Edison Co 1p 18795 319 24X
Fiche 50-000, 83/06/01, 8306090247

8306210355 Releases public version of revised emergency plan implementing procedure
FELTON, J. M. Division of Rules and Records, 83/06/06 Document
Management Branch 1p 18935 293 24X Fiche 50-010, 83/06/06,
8306210355

--8306210357 Public version of Rev 1 to Emergency Plan Implementing Procedure EPIP 300-12, "Initiation of Environ Monitoring Activities by Rad/Chem Director" Receipt form encl.
W/830516 ltr
SCOTT, D. J. Commonwealth Edison Co 83/05/11 DENTON, H. R. Office
of Nuclear Reactor Regulation, Director 19pp 18935 294 24X
Fiche 50-010, 83/06/06, 8306210355

8306100218 Responds to IE Insp Repts 50-010/83-01, 50-237/83-01 & 50-249/83-01 Corrective action surveillance notification program developed for annual distribution of public info brochures on emergency planning
FARRAR, D. L. Commonwealth Edison Co 83/06/07 PAPERIELLO, C. J.
Region 3, Office of Director. 4pp 18805 113 24X
Fiche 50-010, 83/06/07, 8306100218

8306160214 Submits correction to 830601 ltr Date of reassessment will be made prior to 830801, not 831001
JONES, E. E. Illinois, State of 83/06/09 KEPLER, J. Region 3,
Office of Director, ANDERSON, J. Federal Emergency Management
Agency WAGNER, O. Commonwealth Edison Co. 1p. 18861 350 24X
Fiche 50-000, 83/06/09, 8306160214

J Insurance & indemnity information

8306140003 Forwards Endorsement 145 to NELIA Policy NF-43 & Endorsement 122 to MAELU Policy MF-36
OSTER, J. Commonwealth Edison Co 83/06/07 SALTZMAN, J. Assistant
Director for State & License Relations 3pp 18838:216 24X
Fiche: 50-010, 83/06/07, 8306140003

G Inspection reports, IE Bulletins & correspondence

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl
TAYLOR, J. M. Division of Safeguards & Inspection Programs (Post 830103). 83/05/26. Consolidated Edison Co of New York, Inc. 128pp. 18831:043 24X Fiche: 50-000, 83/05/26, 8305110458.

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co. of New
York, Inc. 115pp. 18732 085 24X Fiche: 50-000, 83/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BHRs" Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/31 Consolidated Edison Co. of New
York, Inc. 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461.

8306100218 Responds to IE Insp Repts 50-010/83-01, 50-237/83-01 & 50-249/83-01 Corrective action surveillance notification program developed for annual distribution of public info brochures on emergency planning
FARRAR, D. L. Commonwealth Edison Co. 83/06/07 PAPERIELLO, C. J.
Region 3, Office of Director. 4pp 18805 113. 24X
Fiche 50-010, 83/06/07, 8306100218

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Data Operations" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/09. Consolidated Edison Co of New
York, Inc. 119pp 18830:280 24X Fiche 50-000, 83/06/09, 8305110464

DOCKETED ITEMS

9

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010.

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 118pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475.

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 120pp 18977 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co. of New York, Inc 116pp 18996, 242, 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc 116pp 19046 297, 24X Fiche 50-000, 83/06/24, 8305110483.

R Periodic operating reports & related correspondence

8306130275 "Semiannual Rept of Radioactive Effluents 1982." W/830302 ltr.
SCOTT, D J Commonwealth Edison Co. 83/03/02 KEPLER, J O Region 3, Office of Director 20pp, 18823, 277, 24X Fiche 50-010, 83/03/02, 8306130275

8306130454 Forwards corrected "1981 Rept of Occupational Personnel Radiation Doses - Contract Workers," per Reg Guide 1.16
Number of people per manrem should be listed in maint not engineering category
WAGNER, O P Commonwealth Edison Co. 83/06/07, KEPLER, J O Region 3, Office of Director, ip 18821:179, 24X Fiche 50-010, 83/06/07, 8306130454

--8306130457 Forwards corrected "1981 Rept of Occupational Personnel Radiation Doses - Contract Workers," per Reg Guide 1.16.
Number of people per manrem should be listed in maint not engineering category
WAGNER, O P Commonwealth Edison Co. 83/06/06 KEPLER, J O Region 3, Office of Director, ip 18821:180 24X Fiche 50-010, 83/06/07, 8306130454.

--8306130460 Corrected "1981 Rept of Occupational Personnel Radiation Doses - Contract Workers "
" Commonwealth Edison Co. 83/06/06 9pp 18821:181, 24X Fiche 50-010, 83/06/07, 8306130454.

G Reportable occurrences, LERs & related correspondence

8306270282 Potential Part 21 rept re discrepancy in welding of turnbuckle assembly, turnbuckle-bolt interface & on top plate assembly variable springs, SA307 Grade B bolts not ASME Section IX metl investigation underway.
KARAOZIANIS, J.A. Elcen Metal Products Co 83/06/17, KEPLER, J. O. Region 3, Office of Director 2pp, 18996:207, 24X Fiche 50-000, 83/06/17, 8306270282.

DOCKET 50-14 BATTELLE MEMORIAL INST. CRITICAL FACILITY

P. Operating license stage documents & correspondence

8306230123 FOIA request for five categories of documents re spent fuel at facilities
AUDIN, L. Affiliation Unknown. 83/03/05, Office of Administration, 2pp 18982:045 24X Fiche 50-014, 83/03/05, 8306230123

8306230129 Responds to FOIA request for five categories of documents re spent fuel at facilities, App A & B documents respond to Items 1, 2, 4 & 5 Forwards App B Documents 1 & 5-11. No documents located for Item 3.
FELTON, J.M. Division of Rules and Records 83/04/13, AUDIN, L. Affiliation Unknown 3pp 18982 047, 24X Fiche 50-014, 83/04/13, 8306230129

DOCKET 50-16 ENRICO FERMI ATOMIC POWER PLANT, UNIT 1

J Insurance & indemnity information

8306090022 Unexecuted Amend 25 to Indemnity Agreement B-20, deleting Items 3 & 4 re license numbers & location, respectively.
SALTZMAN, J Assistant Director for State & License Relations, 83/05/31 ip. 18777 361 24X Fiche 50-016, 83/05/31, 8306090022.

8306090039 Unexecuted Amend 24 to Indemnity Agreement B-20, adding Wolverine Power Supply Cooperative as licensee.
SALTZMAN, J. Assistant Director for State & License Relations, 83/05/31 ip. 18777, 360 24X Fiche 50-016, 83/05/31, 8306090039.

DOCKET 50-20 MASSACHUSETTS INST OF TECH RES REACTOR

V Operator Examinations

8306140531 Extends invitation to attend 830627 meeting in King of Prussia, PA to discuss transfer of reactor operator licensing function from Bethesda, MD to Region 1 ofc
STAROSTECKI, R. Division of Project & Resident Programs 83/06/09, CLARK, L. Massachusetts Institute of Technology, 2pp, 18834:320, 24X Fiche 50-020, 83/06/09, 8306140531.

DOCKET 50-27 WASHINGTON STATE UNIV RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8306200154 Requests addl info within 30 days re review of 821027 WA State Univ reactor emergency plan, Plan reviewed against App E to 10CFR50, Rev 1 to Reg Guide 2.6 & ANSI/ANS 15.16-1982.
THOMAS, C.O. Standardization & Special Projects Branch, 83/06/10, WILSON, W.E. Washington State Univ, ip. 19046:132, 24X Fiche 50-027, 83/06/10, 8306200154.

--8306290018 "Emergency Plan Review,"
" Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/31, 3pp, 19046:134, 24X Fiche 50-027, 83/06/10, 8306200154

8306200151 Ack receipt of 830610 ltr requesting addl info re Oct 1982 WA State Univ reactor emergency plan, Submittal of requested info within 30 days impossible due to previous commitments
Extension of submittal for 90 days requested
WILSON, W.E. Washington State Univ, 83/06/14, THOMAS, C.O. Standardization & Special Projects Branch, ip. 18903:118 24X Fiche 50-027, 83/06/14, 8306200151.

--8306200154 Requests addl info within 30 days re review of 821027 WA State Univ reactor emergency plan Plan reviewed against App E to 10CFR50, Rev 1 to Reg Guide 2.6 & ANSI/ANS 15.16-1982.
THOMAS, C.O. Standardization & Special Projects Branch, 83/06/10 WILSON, W.E. Washington State Univ, ip. 19046:132 24X Fiche 50-027, 83/06/14, 8306200151.

DOCKET 50-29 YANKEE-ROWE NUCLEAR POWER STATION

F. Security, medical, emergency & fire protection plans

8306010096 Forwards IE Insp Rept 50-029/83-08 on 830503-04. No noncompliance noted.
MARTIN, T T. Division of Engineering & Technical Programs, 83/05/17, HEIDER, L.H. Yankee Atomic Electric Co. 2pp, 18674:103, 24X Fiche 50-029, 83/05/17, 8306010096.

--8306010100 IE Insp Rept 50-029/83-08 on 830503-04. No noncompliance noted. Major areas inspected: prompt public notification sys.
COHEN, I., GORDON, C., CRDCKER, H.W. Region 1, Office of Director, 83/05/16, 6pp, 18674:105, 24X Fiche 50-029, 83/05/17, 8306010096.

8306090289 Releases public version of change to emergency plan.
FELTON, J.M. Division of Rules and Records, 83/06/01, Document Management Branch, ip. 18810:015, 24X Fiche 50-029, 83/06/01, 8306090289.

DOCKETED ITEMS

--8306090291 Public version of Change 4 to emergency plan, consisting of agreement ltr between licensee & States of VT & MA & Rev 4 to App H re public notification sys. Receipt form encl.
HARRT, D. Yankee Atomic Electric Co. 83/05/18. 10pp. 18810:016
24X Fiche: 50-029, 83/06/01, 8306090289

J Insurance & indemnity information

8306150253 Forwards exemption approving 820688 request for relief from 10CFR50.54(w) property insurance requirement
CRUTCHFIELD, D. Operating Reactors Branch 5. 83/06/10. KAY, J. A. Yankee Atomic Electric Co. 2pp. 18649:196 24X
Fiche: 50-029, 83/06/10, 8306150253.

--8306150257 Exemption from requirements of 10CFR50.54(w) re excess property insurance supplied by Nuclear Electric Insurance Limited, EEL American Nuclear Insurers & Mutual Atomic Energy Reinsurance Pool.
PURPLE, R. A. Division of Licensing. 83/06/10. Yankee Atomic Electric Co. 3pp. 18849:198. 24X Fiche: 50-029, 83/06/10, 8306150253.

8306230283 Forwards Endorsement 105 to NELA Policy NF-76 & Endorsement 87 to MAELU Policy MF-26.
SINIBI, J. M. Marsh & McLennan, Inc. 83/06/16. BALTMAN, J. D. Assistant Director for State & Licensee Relations. 3pp. 18945:155 24X Fiche: 50-029, 83/06/16, 8306230283.

P Operating license stage documents & correspondence

8306170398 Submits addl info re capability of proposed integrated sys for plant shutdown. Results of preliminary analysis indicate shutdown could be accomplished within 150 h. Requests approval be granted prior to 830701.
KAY, J. A. Yankee Atomic Electric Co. 83/06/09. CRUTCHFIELD, D. Operating Reactors Branch 5. 1p. 18879:316 24X
Fiche: 50-029, 83/06/09, 8306170398.

8306210017 Forwards Cycle XVI "Yankee Nuclear Power Station Main Steam Line Break Analysis." Review & approval requested by 831001.
KAY, J. A. Yankee Atomic Electric Co. 83/06/10. CRUTCHFIELD, D. Operating Reactors Branch 5. 2pp. 18918:140. 24X
Fiche: 50-029, 83/06/10, 8306210017.

--8306210024 "Yankee Nuclear Power Station Main Steam Line Break Analysis."
FUJITA, N., KENDALL, J. M., GUIMOND, P. J. Yankee Atomic Electric Co. YAE-1361. 83/05/31. 114pp. 18918:142. 24X
Fiche: 50-029, 83/06/10, 8306210017.

8306200326 Notification of 830622 meeting w/uttl in Bethesda, MD to discuss seismic analysis for design of spent fuel pool racks. Agenda encl.
LYONS, J. E. Operating Reactors Branch 5. 83/06/17. CRUTCHFIELD, D. Operating Reactors Branch 5. 4pp. 18900:360. 24X
Fiche: 50-029, 83/06/17, 8306200326.

8306290311 Forwards final seismic input for BEP Topic III-b, "Seismic Design Considerations." NUREG-0825 conclusions valid based on conservative structural analysis methods & linear elastic analysis.
CRUTCHFIELD, D. Operating Reactors Branch 5. 83/06/22. KAY, J. A. Yankee Atomic Electric Co. 33pp. 19055:316. 24X
Fiche: 50-029, 83/06/22, 8306290311.

8306290241 Forwards safety evaluation conditionally approving licensee 830310 request from relief from Generic Ltr 82-28 & NUREG-0737, Item II.F.2 requirements to install reactor vessel level sys. Addl info needed within 30 days.
CRUTCHFIELD, D. Operating Reactors Branch 5. 83/06/27. KAY, J. A. Yankee Atomic Electric Co. 11pp. 19056:247. 24X
Fiche: 50-029, 83/06/27, 8306290241.

G. Inspection reports, IE Bulletins & correspondence

8306020337 Advises that IE Bulletin 83-03, required actions inapplicable. Emergency diesel generators do not use raw water for cooling nor does cooling sys contain check valves. Water treated w/anti-freeze. Generators air cooled.
HEIDER, L. H. Yankee Atomic Electric Co. 83/05/16. ALLAN, J. M. Region 1, Office of Director. 1p. 18674:287. 24X
Fiche: 50-029, 83/05/16, 8306020337.

8306010096 Forwards IE Insp Rept 50-029/83-08 on 830503-04. No noncompliance noted.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/05/17. HEIDER, L. H. Yankee Atomic Electric Co. 2pp. 18674:103 24X
Fiche: 50-029, 83/05/17, 8306010096

--8306010100 IE Insp Rept 50-029/83-08 on 830503-04. No noncompliance noted. Major areas inspected, prompt public notification sys. CONNEN, I., GORDON, C., CROCKER, H. W. Region 1, Office of Director. 83/05/16. 6pp. 18674:105. 24X Fiche: 50-029, 83/05/17, 8306010096

8306070302 Responds to IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers," per NRC 830511 request Surveillance test performed for each plant startup in accordance w/approved procedure.
HEIDER, L. H. Yankee Atomic Electric Co. 83/05/24. ALLAN, J. M. Region 1, Office of Director. 2pp. 18740:303 24X
Fiche: 50-029, 83/05/24, 8306070302

8306010160 Ack receipt of 820512 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-029/83-07.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/05/25. HEIDER, L. H. Yankee Atomic Electric Co. 2pp. 18673:039 24X
Fiche: 50-029, 83/05/25, 8306010160

--8306010165 Responds to NRC 830413 ltr re violations noted in IE Insp Rept 50-029/83-07. Corrective actions areas cleaned prior to placard placement, tape placed over corners & two addl steel restraining bands placed on drum tops.
HEIDER, L. H. Yankee Atomic Electric Co. 83/05/12. ALLAN, J. M. Region 1, Office of Director. 3pp. 18673:041 24X
Fiche: 50-029, 83/05/25, 8306010160

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device." Svc list encl.
TAYLOR, J. M. Division of Safeguards & Inspection Programs (Post 830103). 83/05/26. Consolidated Edison Co. of New York, Inc. 125pp. 18831:043. 24X Fiche: 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/26. Consolidated Edison Co. of New York, Inc. 115pp. 18732:083 24X Fiche: 50-000, 83/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/31. Consolidated Edison Co. of New York, Inc. 116pp. 18732:208. 24X Fiche: 50-000, 83/05/31, 8305110461

8306140067 Proposes visual exam of four inlet nozzles, respective inner radii & safe-ends & ultrasonic exam of four outlet nozzles, respective inner radii & safe-ends, per reactor vessel insp program.
KAY, J. A. Yankee Atomic Electric Co. 83/06/06. CRUTCHFIELD, D. Operating Reactors Branch 5. 3pp. 18838:264. 24X
Fiche: 50-029, 83/06/06, 8306140067.

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/09. Consolidated Edison Co. of New York, Inc. 117pp. 18830:280 24X Fiche: 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/13. Consolidated Edison Co. of New York, Inc. 118pp. 18920:225 24X Fiche: 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/13. Consolidated Edison Co. of New York, Inc. 243pp. 18921:001 24X Fiche: 50-000, 83/06/13, 8306090010

8306200361 Ack receipt of 830301 & 0429 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-029/82-15. Corrective actions re Items A 1 & B adequate. Contention that no violation exists re Item A 2 disputed.
STAROSTECKI, R. Division of Project & Resident Programs. 83/06/14. HEIDER, L. H. Yankee Atomic Electric Co. 2pp. 18901:032 24X
Fiche: 50-029, 83/06/14, 8306200361

--8306200365 Suppls 830301 response to NRC 830124 ltr re violations noted in IE Insp Rept 50-029/82-15. Corrective actions, safety class drawing issued showing in-core instrumentation flux thimble paths & defining safety class boundaries.
HEIDER, L. H. Yankee Atomic Electric Co. 83/04/29. ALLAN, J. M. Region 1, Office of Director. 4pp. 18901:034. 24X
Fiche: 50-029, 83/06/14, 8306200361

DOCKETED ITEMS

11

--8306200369 Responds to NRC 830124 ltr re violations noted in IE Insp Rept 50-029/82-15 Corrective actions personnel restructured re evaluation of design change & NRC operations ctr notified of gaseous radioactive release item A 2 disputed
HEIDER, L. H. Yankee Atomic Electric Co. 83/03/01. HAYNES, R. C. Region 1, Office of Director. 3pp. 18901 03B. 24X
Fiche 50-029, 83/06/14, 8306200361

8305110475 IE Info Notice 83-40. "Need to Environmentally Qualify Epoxy Grouts & Sealers." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 115pp. 19021 179. 24X Fiche. 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41. "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp. 18997.007. 24X Fiche. 50-000, 83/06/22, 8305110477.

8305110479 IE Info Notice 83-42. "Reactor Mode Switch Malfunctions." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co. of New York, Inc. 116pp. 18996.242. 24X Fiche. 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43. "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc. 116pp. 19046:277. 24X Fiche. 50-000, 83/06/24, 8305110483.

R Periodic operating reports & related correspondence

8306020137 Monthly operating rept for Mar 1983. W/830406 ltr.
BATTERSON, B., HEIDER, L. H. Yankee Atomic Electric Co. 83/04/06. Office of Resource Management, Director. 6pp. 18691 23B. 24X
Fiche 50-029, 83/04/06, 8306020137.

8306160382 Monthly operating rept for Apr 1983 W/830512 ltr
BATTERSON, B., HEIDER, L. H. Yankee Atomic Electric Co. 83/05/12. 6pp. 18860 117. 24X Fiche. 50-029, 83/05/12, 8306160382.

B Reportable occurrences, LERs & related correspondence

8306280144 LER 83-017/03L-0, on 830516, Hassonilan containment isolation valve TV-CI-401B isolated & disassembled to repair gasket leak. Caused by failure of bottom flange gasket. Gasket replaced & sys returned to svc. W/830615 ltr.
FRENCH, L. D., AUTIO, H. A. Yankee Atomic Electric Co. 83/05/16. ALLAN, J. M. Region 1, Office of Director. 2pp. 19018 185. 24X
Fiche 50-029, 83/05/16, 8306280144.

8306170033 LER 83-014/03L-0: on 830429, while performing functional test of control room ventilation fire dampers following mod to fire detection sys, one damper failed to close. Caused by failure of heating element. W/830527 ltr.
MAY, E. L., AUTIO, H. A. Yankee Atomic Electric Co. 83/05/27. ALLAN, J. M. Region 1, Office of Director. 2pp. 18882:227. 24X
Fiche. 50-029, 83/05/27, 8306170033.

8306170418 LER 83-015/03L-0: on 830506, during Mode 1 operation, V177, 115-kV line opened for routine maint, contrary to Tech Specs 3 B 1.1. Caused by scheduled maint insp of 115-kV transformers. No corrective action necessary. W/830603 ltr.
RICE, D. A., AUTIO, H. A. Yankee Atomic Electric Co. 83/06/03. ALLAN, J. M. Region 1, Office of Director. 2pp. 18879:007. 24X
Fiche. 50-029, 83/06/03, 8306170418.

8306170339 LER 83-016/03L-0, on 830511, containment isolation valve TV-CI-401B & steam generator 2 blowdown monitor isolated to repair gasket leak. Caused by bottom flange gasket failure. Gasket replaced W/830610 ltr.
FRENCH, L. D., AUTIO, H. A. Yankee Atomic Electric Co. 83/06/10. ALLAN, J. M. Region 1, Office of Director. 2pp. 18880:284. 24X
Fiche. 50-029, 83/06/10, 8306170339.

8306280107 Updated LER 82-041/03L-1: on 82116, loop 1 channel initiation setpoint found outside Tech Spec limit. Caused by main control board indicator drift. Indicator replaced & channel recalibr procedure to be revised. W/830614 ltr.
MAY, E. L., AUTIO, H. A. Yankee Atomic Electric Co. 83/06/14. ALLAN, J. M. Region 1, Office of Director. 2pp. 19018:182. 24X
Fiche 50-029, 83/06/14, 8306280107.

V Operator Examinations

8306140523 Extends invitation to attend 830627 meeting in King of Prussia, PA to discuss transfer of reactor operator licensing function from Bethesda, MD to Region 1 ofc
STAROSTECKI, R. Division of Project & Resident Programs. 83/06/09. HEIDER, L. H. Yankee Atomic Electric Co. 2pp. 18838:122. 24X
Fiche 50-029, 83/06/09, 8306140523

DOCKET 50-54 UNION CARBIDE RESEARCH REACTOR

P Operating license stage documents & correspondence

8306090364 Advises that fuel element cladding alloy changed to comply w/Tech Specs, requiring high purity aluminum cladding. B&W contracted to fabricate new fuel element.
RUZICKA, W. O. Union Carbide Corp. 83/06/02 THOMAS, C. O. Standardization & Special Projects Branch. 1p. 18795:067. 24X
Fiche: 50-054, 83/06/02, 8306090364.

V. Operator Examinations

8306140631 Extends invitation to attend 830627 meeting in King of Prussia, PA to discuss transfer of reactor operator licensing function from Bethesda, MD to Region 1 ofc
STAROSTECKI, R. Division of Project & Resident Programs. 83/06/09. MCQUVERN, J. J. Union Carbide Corp. 2pp. 18842:082. 24X
Fiche: 50-054, 83/06/09, 8306140631.

DOCKET 50-57 STATE UNIV. OF NEW YORK RESEARCH REACTOR

E. NRC Safety Evaluation Report (SER), supp's & correspondence

8306210317 SAFETY EVALUATION REPORT RELATED TO RENEWAL OF THE OPERATING LICENSE FOR THE RESEARCH REACTOR AT THE STATE UNIVERSITY OF NEW YORK AT BUFFALO. Docket No. 50-57.
* Division of Licensing NUREG-0982. 83/05/31. 88pp. Available at NRC \$4.50. 18924:282. 24X Fiche: 50-057, 83/05/31, 8306210317.

Q. Inspection reports, IE Bulletins & correspondence

8306170050 Ack receipt of 830511 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-057/82-01 & 70-0267/82-01
MARTIN, T. T. Division of Engineering & Technical Programs. 83/06/01. HENRY, L. O. New York, State Univ. of Buffalo. 2pp. 18882:210. 24X Fiche: 50-057, 83/06/01, 8306170050.

--8306170052 Responds to NRC 830427 ltr re violations noted in IE Insp Repts 50-057/82-01 & 70-0267/82-01. Corrective actions: new reactor engineer added to assume responsibility for accountability actions & records. Fuel burnup code modified.
HENRY, L. O. New York, State Univ. of Buffalo. 83/05/11. MARTIN, T. T. Division of Engineering & Technical Programs. 1p. 18882 212. 24X Fiche: 50-057, 83/06/01, 8306170050.

8306140741 Ack receipt of 830510 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-057/83-01. Met controls to improve nuclear safety committee performance noted.
STAROSTECKI, R. Division of Project & Resident Programs. 83/06/03. HENRY, L. O. New York, State Univ. of Buffalo. 1p. 18841:159. 24X
Fiche: 50-057, 83/06/03, 8306140741.

V. Operator Examinations

8306140531 Extends invitation to attend 830627 meeting at King of Prussia, PA to discuss transfer of reactor operator licensing function from Bethesda, MD to Region 1 ofc.
STAROSTECKI, R. Region 1, Office of Director. 83/06/09. HENRY, L. O. New York, State Univ. of Buffalo. 2pp. 18841:163. 24X
Fiche: 50-057, 83/06/09, 8306140531.

DOCKET 50-62 UNIV. OF VIRGINIA RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8306220228 Forwards request for addl info re Univ of VA research reactor 820827 emergency plan to continue review per 10CFR50, App E, Reg Guide 2.4, Rev 1 & ANSI/ANS-15.16-1982 requirements. Info requested within 30 days of ltr date.
THOMAS, C. O. Standardization & Special Projects Branch. 83/06/10. BRENNER, J. B. Virginia, Univ. of Charlottesville, VA. 5pp. 18977:355. 24X Fiche. 50-062, 83/06/10, 8306220228.

DOCKETED ITEMS

B Reportable occurrences, LERs & related correspondence

B306140005 RD on B30530 reactor shut down when shutdown margin during criticality violated Tech Specs Caused by difference in partial fuel element added on B30525 Reactor shut down
B30604 Control rods recalibr Procedures changed
BRENNER, J B Virginia, Univ. of, Charlottesville, VA 03/06/09
O'REILLY, J P. Region 2, Office of Director, 2pp 18938 242 24X
Fiche 50-062, B3/06/09, B306140005

DOCKET 50-70 GENERAL ELECTRIC TEST REACTOR

C Adjudicatory correspondence

B306040287 Order extending time until B30703 for Commission to act to review ALAB-720.
CHILK, S J. Office of the Secretary of the Commission. 03/06/02
Commissioners. 1p 18730, 017. 24X Fiche: 50-070, B3/06/02,
B306040287.

B Reportable occurrences, LERs & related correspondence

B306160470 Part 21 rept re broken spring-steel bands on 60 amp fuse clips. ILSCO Corp requested to determine cause of breakage.
OE metallurgically testing broken bands.
DWYER, P W. General Electric Co 03/05/10. DEYOUNG, R C Director's
Office, Office of Inspection and Enforcement 7pp 18862, 253. 24X
Fiche: 50-070, B3/05/10, B306160470

DOCKET 50-72 UNIV OF UTAH RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

B306160189 Releases public version of emergency plan.
FELTON, J. M. Division of Rules and Records 03/06/06. Document
Management Branch. 1p. 18893, 095. 24X Fiche 50-072, B3/06/06,
B306160189

--B306160194 Public version of "Emergency Plan for Training & Research
Reactors" W/B30512 ltr.
BANDQUIST, O M, BROPHY, J J. Utah, Univ of UTEC ME B2-100
B2/11/01. Office of Nuclear Reactor Regulation, Director 2pp
18893, 096 24X Fiche. 50-072, B3/06/06, B306160189

G. Inspection reports, IE Bulletins & correspondence

B306140226 Forwards IE Insp Rept 50-072/B3-01 on B30421-22 & notice
of violation.
BEIDLE, W. C. Region 4, Office of Director 03/05/11. JACOB, H R.
Utah, Univ of 2pp 18832, 280 24X Fiche: 50-072, B3/05/11,
B306140226.

--B306140232 Notice of violation from insp on B30421-22.
* Region 4, Office of Director, 03/05/11 1p. 18032, 290. 24X
Fiche: 50-072, B3/05/11, B306140226

--B306140236 IE Insp Rept 50-072/B3-01 on B30421-22 Noncompliance noted
failure to perform required reactor startup surveillance
tests.
MURPHY, M E, JOHNSEN, W D Region 4, Office of Director. 03/05/11.
5pp. 18832 291. 24X Fiche: 50-072, B3/05/11, B306140226.

DOCKET 50-77 CATHOLIC UNIV. OF AMERICA RESEARCH REACTOR

G. Inspection reports, IE Bulletins & correspondence

B306200343 Forwards IE Insp Rept 50-077/B3-02 on B30511-13 & notice of
violation.
STAROSTECKI, R Division of Project & Resident Programs 03/06/06.
WANG, Y. C. Catholic Univ. of America, Washington, DC 2pp.
18900, 264. 24X Fiche: 50-077, B3/06/06, B306200343

--B306200347 Notice of violation from insp on B30511-13.
* Region 1, Office of Director 03/06/06. 1p. 18900, 266 24X
Fiche 50-077, B3/06/06, B306200343.

--B306200353 IE Insp Rept 50-077/B3-02 on B30511-13. Noncompliance noted:
failure of reactor safety committee to meet at least twice
each yr in CY01 & CY02
KINNEY, W M. Region 1, Office of Director. 03/06/02 7pp
18900, 067. 24X Fiche: 50-077, B3/06/06, B306200343.

B306200347 Ack receipt of B30613 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-77/B3-02
STAROSTECKI, R Division of Project & Resident Programs 03/06/23
KELNHOFFER, W Catholic Univ of America, Washington, DC 1p
19001 267 24X Fiche 50-077, B3/06/23, B306200347

--B306200351 Responds to NRC B30606 ltr re violations noted in IE Insp
Rept 50-077/B3-02 Corrective actions reactor safety
committee will meet at least twice each yr
JORDAN, E D Catholic Univ of America, Washington, DC 03/06/13
STAROSTECKI, R Division of Project & Resident Programs 1p
19001 268 24X Fiche 50-077, B3/06/23, B306200347

V Operator Examinations

B306140443 Extends invitation to attend B30627 meeting in King of
Prussia, PA to discuss transfer of reactor operator licensing
function from Bethesda, MD to Region 1 ofc
STAROSTECKI, R Division of Project & Resident Programs 07/06/09
WANG, Y C Catholic Univ of America, Washington, DC 2pp
18938 023 24X Fiche 50-077, B3/06/09, B306140443

DOCKET 50 89 GENERAL ATOMIC CO

F Security, medical, emergency & fire protection plans

B306280171 Forwards IE Insp Repts 50-089/03 02 & 50-163/03 02 on
B30509-12 & notice of violation Present level of resources
allocated to radiation protection program inadequate Insp
frequency will be increased
BOOK, H C Region 5, Office of Director 03/05/27 PARKER, J W QA
Technologies, Inc./General Atomic Co 2pp 19014 136 24X
Fiche 50-089, B3/05/27, B306280171

--B306280185 IE Insp Repts 50 089/03 02 & 50-163/03 02 on B30509-12
Noncompliance noted failure to post notice of violation re
radiological working conditions, per 10CFR19.11(e)
YUNAB, O P, WENGLAWSKI, F A, BOOK, H C Region 5, Office of
Director 03/05/27 10pp 19014 139 24X Fiche 50-089, B3/05/27,
B306280171

B306220240 Forwards request for addl info re QA Technologies, Inc
research reactor B21102 emergency plan to continue review
per 10CFR50, App E, Reg Guide 2.6, Rev 1 & ANSI/ANS-15.1A-1902
requirements Info requested within 30 days of ltr date
THOMAS, C O Standardization & Special Projects Branch 03/06/10
HARRIS, W R QA Technologies, Inc./General Atomic Co 6pp
18977, 026 24X Fiche 50-089, B3/06/10, B306220240

G Inspection reports, IE Bulletins & correspondence

B306280171 Forwards IE Insp Repts 50 089/03 02 & 50-163/03 02 on
B30509-12 & notice of violation. Present level of resources
allocated to radiation protection program inadequate. Insp
frequency will be increased
BOOK, H C Region 5, Office of Director 03/05/27 PARKER, J. W. QA
Technologies, Inc./General Atomic Co 2pp 19014 136 24X
Fiche. 50-089, B3/05/27, B306280171.

--B306280177 Notice of violation from insp on B30509-12
WENGLAWSKI, F A Region 5, Office of Director. 03/05/27 1p
19014, 130 24X Fiche. 50-089, B3/05/27, B306280171

--B306280185 IE Insp Repts 50 089/03 02 & 50-163/03 02 on B30509-12
Noncompliance noted: failure to post notice of violation re
radiological working conditions, per 10CFR19.11(e)
YUNAB, O. P., WENGLAWSKI, F A, BOOK, H C Region 5, Office of
Director 03/05/27. 10pp 19014, 139 24X Fiche: 50-089, B3/05/27,
B306280171.

DOCKET 50-97 CORNELL UNIV. ZERO POWER REACTOR

F. Security, medical, emergency & fire protection plans

B306230238 Forwards proposed physical security plan Plan withheld
(ref 10CFR2790)
CLARK, D B. Cornell Univ 03/06/17 THOMAS, C. O Standardization &
Special Projects Branch 1p 18945, 253. 24X Fiche: 50-097, B3/06/17,
B306230238

G Inspection reports, IE Bulletins & correspondence

B306140240 Ack receipt of B30518 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-097/B3-01 &
50-157/B3-01.
STAROSTECKI, R Division of Project & Resident Programs 03/06/06
BRETHER, W. U. Cornell Univ 1p. 18933, 011 24X
Fiche: 50-097, B3/06/06, B306140240

DOCKETED ITEMS

13

--8306140253 Responds to NRC 830421 ltr re violations noted in IE Insp Rept 50-157/83-01 Corrective actions TRIQA operations audited, insp findings reviewed at safety committee meeting & annual audit of tickler file required
CLARK, D D Cornell Univ 83/05/18. STAROSTECKI, R. Division of Project & Resident Programs 2pp 18833 012 24X
Fiche 50-097, 83/06/06, 8306140248

V Operator Examinations

8306140553 Extends invitation to attend 830627 meeting in King of Prussia, PA to discuss transfer of reactor operator licensing function from Bethesda, MD to Region 1 ofc
STAROSTECKI, R Division of Project & Resident Programs 83/06/09
STREET, W R Cornell Univ. 2pp 18834 206 24X
Fiche 50-097, 83/06/09, 8306140553

DOCKET 50-111 NORTH CAROLINA STATE UNIV. RESEARCH REACTOR

J. Insurance & indemnity information

8306210424 Forwards FR notice of availability of order terminating License R-63, BER supporting order & Amend 17 to Indemnity Agreement E-7 for signature
CRUTCHFIELD, D Operating Reactors Branch 5 83/06/13
COCKRELL, R O North Carolina State Univ 2pp 18937 038 24X
Fiche 50-111, 83/06/13, 8306210424.

8306220280 Advises of elimination of annual fee for Amend 17 to Indemnity Agreement E-7, terminating License R-63
DINITZ, I Office of State Programs, Director 83/06/14
PUOLIGE, A B. Division of Accounting 1p 18940 355 24X
Fiche 50-111, 83/06/14, 8306220280

8306220284 Unexecuted Amend 17 to Indemnity Agreement E-7, revising attachment, Item 2
BALITMAN, J Assistant Director for State & License Relations. 83/06/14 1p 18940 350 24X Fiche: 50-008, 83/06/14, 8306220284

P Operating license stage documents & correspondence

8306210424 Forwards FR notice of availability of order terminating License R-63, BER supporting order & Amend 17 to Indemnity Agreement E-7 for signature.
CRUTCHFIELD, D. Operating Reactors Branch 5. 83/06/13
COCKRELL, R O North Carolina State Univ 2pp. 18937 038 24X
Fiche 50-111, 83/06/13, 8306210424.

--8306210424 Order terminating License R-63
PURPLE, R A Assistant Director for Licensing 83/06/13 2pp.
18937 040 24X Fiche: 50-111, 83/06/13, 8306210424

--8306210430 BER supporting order terminating License R-63 R-3 reactor dismantled & disposed of per license 800605 dismantling plan. All radioactive components & activated concrete shield matl shipped to Richland, WA
* Office of Nuclear Reactor Regulation, Director. 83/06/13. 3pp.
18937 042 24X Fiche 50-111, 83/06/13, 8306210424

DOCKET 50-112 UNIV OF OKLAHOMA RESEARCH REACTOR

P. Operating license stage documents & correspondence

8306280569 Forwards revised "SAR Update & Review," & Tech Specs for 20-yr renewal of License R-63.
TERRELL, C W Oklahoma, Univ of. 83/06/20 THOMAS, C O Standardization & Special Projects Branch 1p 19018 130. 24X
Fiche: 50-112, 83/06/20, 8306280569.

--8306280581 "SAR Update & Review for Univ of OK AGN-211P Reactor."
* Oklahoma, Univ. of. 83/05/18. 16pp. 19018 131. 24X
Fiche: 50-112, 83/06/20, 8306280569.

--8306280594 Tech Specs 1.0 through 6.0 re safety limits & limiting safety sys settings, limiting conditions for operation, surveillance requirements, design features & controls.
* Oklahoma, Univ of 83/05/18. 33pp. 19018 147. 24X
Fiche: 50-112, 83/06/20, 8306280569.

Q. Inspection reports, IE Bulletins & correspondence

8306060128 Forwards IE Insp Rept 50-112/83-01 on 830402-22 & notice of violation.
MADSEN, O L. Region 4, Office of Director. 83/05/17. EGLE, D M. Oklahoma, Univ of. 2pp. 18722.298 24X Fiche: 50-112, 83/05/17, 8306060128

--8306060131 Notice of violation from insp on 830420-22
* Region 4, Office of Director 83/05/17 1p 18722 300. 24X
Fiche 50-112, 83/05/17, 8306060128

--8306060133 IE Insp Rept 50-112/83-01 on 830420-22 Noncompliance noted- failure to plot flow rate data since Oct 1979 while performing water purification sys flow rate check procedure.
REDANO, R T, WEBSTERMAN, T F, CROSSMAN, W A Region 4, Office of Director 83/05/17 10pp 18722 301 24X Fiche 50-112, 83/05/17, 8306060128

DOCKET 50-116 IDWA STATE UNIV RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8306290258 Informs that emergency plan does not meet requirements of App E to 10CFR50, Reg Guide 2.4 & ANSI/ANS-15 74-1982.
"Emergency Planning for Research Reactors " Addl info requested must be submitted by 830801.
THOMAS, C O Standardization & Special Projects Branch. 83/06/20
HENDRICKSON, R Iowa State Univ 4pp 19046 118 24X
Fiche: 50-116, 83/06/20, 8306290258

Q Inspection reports, IE Bulletins & correspondence

8306100275 Submits corrected data for application to renew License R-59 & advises that computer printout records summarizing SNM inventory results for 1981 & 1982 corrected, in response to IE Insp Repts 50-116/83-01 & 70-0084/83-01
HENDRICKSON, R Iowa State Univ. 83/05/19. PIRLIE, O L. Region 3. Office of Director 2pp 18805 142 24X Fiche: 50-116, 83/05/19, 8306100275

DOCKET 50-128 TEXAS A&M UNIV RESEARCH REACTOR

H General correspondence

8306010296 Forwards Region IV organization chart & ofc directory in response to 830509 request, W/o encl.
MADSEN, O L Region 4, Office of Director. 83/05/27 FELTZ, D. E. Texas A&M Univ., College Station, TX. 1p. 18672:189. 24X
Fiche: 50-128, 83/05/27, 8306010296.

--8306010298 Requests copy of Region IV organization chart.
FELTZ, D E Texas A&M Univ., College Station, TX. 83/05/09
MADSEN, O L Region 4, Office of Director 1p. 18672.190. 24X
Fiche: 50-128, 83/05/27, 8306010296.

P Operating license stage documents & correspondence

8306010358 Forwards "Completion & Results of Phase I of Nuclear Science Ctr Reactor Post-Damage Pulse Test Program for Full FLIP TRIQA Core " Pulse test planned at Phase I level to study fuel characteristics
FELTZ, D E Texas A&M Univ., College Station, TX 83/04/29.
CROSSMAN, B Region 4, Office of Director 1p. 18682:121 24X
Fiche: 50-128, 83/04/29, 8306010358.

--8306010361 "Completion & Results of Phase I of Nuclear Science Ctr Reactor Post-Damage Pulse Test Program for Full FLIP TRIQA Core "
JENNINGS, F. Texas A&M Univ., College Station, TX 83/04/30.
16pp. 18682.122 24X Fiche: 50-128, 83/04/29, 8306010358.

8306020612 Forwards repts on univ TRIQA bowed fuel elements, proposed pulsing program, results of Phase I of. "Post-Damage Pulse Test Program for Full FLIP TRIQA Core: " & SER for license renewal application, W/o encl
THOMAS, C O. Standardization & Special Projects Branch. 83/05/25.
BERLINGER, C Core Performance Branch 1p 18715 046. 24X
Fiche: 50-128, 83/05/25, 8306020612.

8306060213 Forwards revised Page 29 of Tech Specs correcting error in Item 3.8 re primary coolant conditions.
FELTZ, D. E. Texas A&M Univ., College Station, TX. 83/05/30.
BERNARD, H Standardization & Special Projects Branch 2pp 18727.360 24X Fiche: 50-128, 83/05/30, 8306060213.

--8306060216 Revised Page 29 of Tech Specs correcting error in Item 3.8 re primary coolant conditions.
* Texas A&M Univ., College Station, TX. 83/05/30. 1p.
18727.362. 24X Fiche: 50-128, 83/05/30, 8306060213.

DOCKETED ITEMS

R. Periodic operating reports & related correspondence

8306010369 "Nineteenth Progress Rept of Texas A&M Univ Nuclear Ctr, 1982"
DELO, H. O.; HEAD, J. O.; LAND, R. J. Texas A&M Univ, College Station, TX. DRD-4207-15. 83/04/30. 83pp. 18674:154. 24X
Fiche: 50-128, 83/04/30, 8306010369.

DOCKET 50-131 OHAMA VET. ADMIN HOSP RESEARCH REACTORF. Security, medical, emergency & fire protection plans

8306220216 Forwards request for addl info re Omaha Veterans Administration Medical Ctr research reactor 821021 emergency plan to continue review per 10CFR50, App E, Guide 2 & Rev 1 & ANSI/ANSI-15-16-1982 requirements
THOMAS, C. D. Standardization & Special Projects Branch. 83/06/10. TURCOTTE, R. L. Vet Admin. Hosp Omaha, NE. 5pp. 18951:010. 24X
Fiche: 50-131, 83/06/10, 8306220216

DOCKET 50-133 HUMBOLDT BAY POWER PLANT, UNIT 3F. Security, medical, emergency & fire protection plans

8306150224 Advises that 830425 changes to security plan do not decrease effectiveness of plan & are acceptable
VASSALLO, D. D. Operating Reactors Branch 2. 83/06/06. CRANE, P. A. Pacific Gas & Electric Co. 2pp. 18870:066. 24X
Fiche: 50-133, 83/06/06, 8306150224

H. General correspondence

8306070036 Provides names & addresses for appropriate distribution of technical correspondence re facilities
SCHRYLER, J. D. Pacific Gas & Electric Co. 83/06/02. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. EISENHUT, D. Q. Division of Licensing. MARTIN, J. B. Region 5, Office of Director. 2pp. 18739:337. 24X
Fiche: 50-000, 83/06/02, 8306070036

G. Inspection reports; IE Bulletins & correspondence

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device." Svc list encl.
TAYLOR, J. M. Division of Safeguards & Inspection Programs (Post 830103). 83/05/26. Consolidated Edison Co. of New York, Inc. 12pp. 18831:043. 24X
Fiche: 50-000, 83/05/26, 8305110458.

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/26. Consolidated Edison Co. of New York, Inc. 115pp. 18732:085. 24X
Fiche: 50-000, 83/05/26, 8305110460.

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/31. Consolidated Edison Co. of New York, Inc. 116pp. 18732:208. 24X
Fiche: 50-000, 83/05/31, 8305110461.

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/09. Consolidated Edison Co. of New York, Inc. 119pp. 18830:280. 24X
Fiche: 50-000, 83/06/09, 8305110464.

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Mechanically Induced Chatter in Relays Within Printed Circuit Cards." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/13. Consolidated Edison Co. of New York, Inc. 118pp. 18920:225. 24X
Fiche: 50-000, 83/06/13, 8305110470.

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/13. Consolidated Edison Co. of New York, Inc. 243pp. 18921:001. 24X
Fiche: 50-000, 83/06/13, 8306090010.

8306210080 Responds to IE Bulletin 83-03 re check valve failure in raw water cooling sys of diesel generators. Plant utilizes emergency propane generator w/closed loop jacket cooling water sys. No check valves in engine jacket cooling sys.
BRAND, D. A. Pacific Gas & Electric Co. 83/06/15. MARTIN, J. B. Region 5, Office of Director. 2pp. 18911:232. 24X
Fiche: 50-133, 83/06/15, 8306210080

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/22. Consolidated Edison Co. of New York, Inc. 118pp. 19021:179. 24X
Fiche: 50-000, 83/06/22, 8305110475.

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/22. Consolidated Edison Co. of New York, Inc. 120pp. 18997:007. 24X
Fiche: 50-000, 83/06/22, 8305110477.

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/23. Consolidated Edison Co. of New York, Inc. 116pp. 18996:242. 24X
Fiche: 50-000, 83/06/23, 8305110479.

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/24. Consolidated Edison Co. of New York, Inc. 116pp. 19046:297. 24X
Fiche: 50-000, 83/06/24, 8305110483.

R. Periodic operating reports & related correspondence

8306020309 Monthly operating rept for Mar 1983. W/830404 1tr
DERKS, P. B.; WEEKS, E. D. Pacific Gas & Electric Co. 83/04/01. 6pp. 18694:276. 24X
Fiche: 50-133, 83/04/01, 8306020309

8306160461 Monthly operating rept for Apr 1983. W/830504 1tr
DERKS, P. B.; WEEKS, E. D. Pacific Gas & Electric Co. 83/05/04. Office of Resource Management, Director. 5pp. 18863:046. 24X
Fiche: 50-133, 83/05/04, 8306160461.

DOCKET 50-134 WORCESTER POLYTECH INST RESEARCH REACTORV. Operator Examinations

8306140630 Extends invitation to attend 830627 meeting in King of Prussia, PA to discuss transfer of reactor operator licensing function from Bethesda, MD to Region 1 ofc
STAROSTECKI, R. Division of Project & Resident Programs. 83/06/09. WILBUR, L. C. Worcester Polytechnic Inst. 2pp. 18833:178. 24X
Fiche: 50-134, 83/06/09, 8306140630

DOCKET 50-141 STANFORD UNIV RESEARCH REACTORW. Decommissioning Stage Documents & Correspondence

8306290068 Forwards safety evaluation & order terminating License R-60 W/o Amend 11 to Indemnity Agreement E-19
CRUTCHFIELD, D. Operating Reactors Branch 5. 83/06/21. FINSTON, R. A. Stanford Univ., Stanford, CA. 2pp. 19046:142. 24X
Fiche: 50-141, 83/06/21, 8306290068

--8306290073 Order terminating License R-60
EISENHUT, D. Q. Division of Licensing. 83/06/21. Stanford Univ., Stanford, CA. 2pp. 19046:144. 24X
Fiche: 50-141, 83/06/21, 8306290068.

--8306290077 Safety evaluation supporting termination of License R-60
Office of Nuclear Reactor Regulation, Director. 83/06/21. 3pp. 19046:146. 24X
Fiche: 50-141, 83/06/21, 8306290068

--8306290080 Forwards IE Insp Rept 50-141/B2-02 on 820916 & 1105. Plant not contaminated above Reg Guide 1.86 limits Util estimate for biological shield occupancy reasonable. W/o encl.
BOOKER, E. Region 5, Office of Director. 83/03/11. ERICKSON, P. R. Standardization & Special Projects Branch. 1p. 19046:149. 24X
Fiche: 50-141, 83/06/21, 8306290068.

DOCKET 50-142 UCLA TRAINING REACTORQ. Adjudicatory correspondence

8306020161 Forwards UCLA application for amend & amend to Feb 1980 renewal application for License R-71, in response to ASLB 830511 memorandum & order ASLB order directing NRC to inventory SNM forwarded to Region V for action
HODGHEAD, C. P. Hearing Branch 4. 83/03/31. FRYE, J. H.; BRIGHT, D. Q.; LUEBKE, E. A. Atomic Safety and Licensing Board Panel. 1p. 18691:056. 24X
Fiche: 50-142, 83/03/31, 8306020161.

8306070399 Forwards prof qualification statements for UCLA witnesses at upcoming safety hearing. Other statements will be sent when received. W/o encl.
CORMIER, W. H. California, Univ. of, Los Angeles. 83/06/01
FRYE, J. H., BRIGHT, G. D., LUEBKE, E. A. Atomic Safety and Licensing Board Panel. 2pp. 18742.001. 24X Fiche: 50-142, 83/06/01, 8306070399.

8306060282 Errata to ASLB 830511 memorandum & order ruling on NRC motion for summary disposition of Contention XX QL amend reduced BHM amount UCLA authorized to possess.
FRYE, J. H., Atomic Safety and Licensing Board Panel. 83/06/02.
Office of the Executive Legal Director. 2pp. 18729.036. 24X Fiche: 50-142, 83/06/02, 8306060282.

8306070416 Requests for clarification of ASLB 830513 order scope of upcoming hearing. UCLA must be allowed to present testimony on seismic questions to answer issue of worst case accident. Certificate of Svc encl.
CORMIER, W. H. California, Univ. of, Los Angeles. 83/06/02. Atomic Safety and Licensing Board Panel. 4pp. 18742.260. 24X Fiche: 50-142, 83/06/02, 8306070416.

8306150382 Response opposing UCLA 830602 motion, requesting leave to introduce testimony on seismic matters at safety hearings. deferred by ASLB in 830513 memorandum & order re Contention XVII Declaration of Svc encl.
HIRSCH, D. Committee to Bridge the Gap. 83/06/09. Atomic Safety and Licensing Board Panel. 9pp. 18847.248. 24X Fiche: 50-142, 83/06/09, 8306150382.

8306150392 Advises that prefiled testimony for upcoming inherent safety hearings should be received by parties before 830613.
HIRSCH, D. Committee to Bridge the Gap. 83/06/09. WOODHEAD, C. P. Hearing Branch 4. CORMIER, W. California, Univ. of, Los Angeles. 1p. 18847.151. 24X Fiche: 50-142, 83/06/09, 8306150392.

8306160616 Memorandum & order ruling on UCLA request for clarification of ASLB 830513 ruling on Contention XVII UCLA testimony on seismic questions deferred. Testimony will be relevant only if NRC analysis incorrect.
BRIGHT, G. D., LUEBKE, E. A., FRYE, J. H. Atomic Safety and Licensing Board Panel. 83/06/13. California, Univ. of, Los Angeles. 3pp. 18866.031. 24X Fiche: 50-142, 83/06/13, 8306160616.

8306210275 Confirms addl testimony sent by express mail on 830604.
WOODHEAD, C. P. Hearing Branch 4. 83/06/16. HIRSCH, D. Committee to Bridge the Gap. 1p. 18915.146. 24X Fiche: 50-142, 83/06/16, 8306210275.

8306210280 Lists NRC exhibits for Jul 1983 hearings & forwards two exhibits not previously served.
WOODHEAD, C. P. Hearing Branch 4. 83/06/17. FRYE, J. H., BRIGHT, G. D., LUEBKE, E. A. Atomic Safety and Licensing Board Panel. 23pp. 18914.245. 24X Fiche: 50-142, 83/06/17, 8306210280.

8306230303 Forwards corrected proposed findings of fact & conclusions of law re Contention II.
WOODHEAD, C. P. Hearing Branch 4. 83/06/20. LAURENSEN, J. A. Atomic Safety and Licensing Board Panel. 1p. 18942.175. 24X Fiche: 50-142, 83/06/20, 8306230303.

--8306230305 Proposed findings of fact & conclusions of law.
* Office of the Executive Legal Director. 83/06/21. 46pp. 18942.177. 24X Fiche: 50-142, 83/06/20, 8306230303.

8306230301 Forwards corrected NRC 830620 proposed findings of fact & conclusions of law.
WOODHEAD, C. P. Hearing Branch 4. 83/06/21. LAURENSEN, J. A. Atomic Safety and Licensing Board Panel. 1p. 18942.127. 24X Fiche: 50-142, 83/06/21, 8306230301.

8306280525 Forwards proposed findings of fact & conclusions of law re special proceeding on Contention III, W/o encl.
CORMIER, W. H. California, Univ. of, Los Angeles. 83/06/23.
LAURENSEN, J. A. Atomic Safety and Licensing Board Panel. 1p. 19019.289. 24X Fiche: 50-142, 83/06/23, 8306280525.

8306290546 Forwards proposed findings of fact & conclusions of law.
THOMPSON, D. Nuclear Law Center. THOMPSON, D. Committee to Bridge the Gap. 83/06/23. LAURENSEN, J. A. Atomic Safety and Licensing Board Panel. 1p. 19052.241. 24X Fiche: 50-142, 83/06/23, 8306290546.

--8306290552 Proposed findings of fact & conclusions of law.
* Committee to Bridge the Gap. 83/06/23. 32pp. 19052.242. 24X Fiche: 50-142, 83/06/23, 8306290546.

8306280086 Motion for extension until 830701 to file reply briefs to proposed findings of fact & conclusions of law. Certificate of Svc encl.
WOODHEAD, C. P. Hearing Branch 4. 83/06/24. Atomic Safety and Licensing Board Panel. 4pp. 19001.157. 24X Fiche: 50-142, 83/06/24, 8306280086.

8306280560 Forwards "Analysis of Self-Shutdown Behavior in SPERT I Reactor." AEC R&D rept dtd 590723.
WOODHEAD, C. P. Hearing Branch 4. 83/06/24. FRYE, J. H., BRIGHT, G. D., LUEBKE, E. A. Atomic Safety and Licensing Board Panel. 42pp. 19017.338. 24X Fiche: 50-142, 83/06/24, 8306280560.

R Periodic operating reports & related correspondence

8306280595 "Nuclear Energy Lab Annual Rept. 1982." W/830622 1tr.
WEGBT, W. F. California, Univ. of, Los Angeles. 82/12/31. BERNARD, H. Standardization & Special Projects Branch. 21pp. 19017.165. 24X Fiche: 50-142, 83/06/22, 8306280595.

T Hearing transcripts on non-antitrust matters

8306010013 Transcript of 830525 hearing in Los Angeles, CA re proposed renewal of facility license. Pp 181-470. Supporting documentation encl.
* Atomic Safety and Licensing Board Panel. 83/05/25. 300pp. 18664.191. 24X Fiche: 50-142, 83/05/25, 8306010013.

8306020115 Transcript of 830526 hearing in Los Angeles, CA re proposed license renewal. Pp 471-782.
* Atomic Safety and Licensing Board Panel. 83/05/26. 327pp. 18692.199. 24X Fiche: 50-142, 83/05/26, 8306020115.

8306130371 Forwards GE Cort & P Neogy testimony.
WOODHEAD, C. P. Hearing Branch 4. 83/06/09. FRYE, J. H., BRIGHT, G. D., LUEBKE, E. A. Atomic Safety and Licensing Board Panel. 1p. 18821.231. 24X Fiche: 50-142, 83/06/09, 8306130371.

--8306130377 Testimony of GE Cort clarifying underlying bases of "Fuel Tamps in Argonaut Reactor Core Following Hypothetical DBA." Fuel melt impossible in event of LOCA w/or w/o core crushing. Prof qualifications encl.
CORT, G. E. NRC - No Detailed Affiliation Given. CORT, G. E. Los Alamos Scientific Laboratory. 83/06/09. 17pp. 18821.232. 24X Fiche: 50-142, 83/06/09, 8306130371.

--8306130379 Testimony of P Neogy clarifying bases & methods used in "Transient Analysis of UCLA Argonaut." Prof qualifications encl.
NEGOY, P. NRC - No Detailed Affiliation Given. NEGOY, P. Brookhaven National Laboratory. 83/06/09. 19pp. 18821.249. 24X Fiche: 50-142, 83/06/09, 8306130371.

8306160009 Forwards B Hawley & H Bernard testimony, completing NRC testimony filing for Jul 1983 hearing.
WOODHEAD, C. P. Hearing Branch 4. 83/06/14. FRYE, J. H., BRIGHT, G. D., LUEBKE, E. A. Atomic Safety and Licensing Board Panel. 1p. 18861.176. 24X Fiche: 50-142, 83/06/14, 8306160009.

--8306160010 Testimony of SC Hawley explaining & clarifying analytical bases for conclusion in NUREG/CR-2079, "Analysis of Credible Accidents for Argonaut Reactors." Prof qualifications encl.
HAWLEY, B. C. NRC - No Detailed Affiliation Given. HAWLEY, B. C. Battelle Memorial Institute, Pacific Northwest Laboratory. 83/06/14. 20pp. 18861.177. 24X Fiche: 50-142, 83/06/14, 8306160009.

--8306160017 Testimony of H Bernard explaining & clarifying bases & assumptions used in BER, Section 14 re analysis of consequences of postulated accidents. Prof qualifications encl.
BERNARD, H. Standardization & Special Projects Branch. 83/06/14. 14pp. 18861.197. 24X Fiche: 50-142, 83/06/14, 8306160009.

8306170373 Forwards direct testimony.
HIRSCH, D. Committee to Bridge the Gap. 83/06/14. Atomic Safety and Licensing Board Panel. 1p. 18879.067. 24X Fiche: 50-142, 83/06/14, 8306170373.

--8306170379 Testimony of B Norton, L Wayne, M Kaku, R Finston, R Kohn, M Pulido, D DuPont, B Aftergood, L Foster, D Hirsch & B Plotkin, questioning inherent reactor safety.
NORTON, B., WAYNE, L., KAKU, M. Committee to Bridge the Gap. 83/06/14. 29pp. 18879.068. 24X Fiche: 50-142, 83/06/14, 8306170373.

--8306170390 Testimony of B Norton, M Kaku, R Kohn, D Hirsch, B Aftergood, M Pulido & D DuPont, as Panel I re concepts of inherent safety applied to reactor.
NORTON, B., KAKU, M., KOHN, R. Committee to Bridge the Gap. 83/06/14. 78pp. 18879.097. 24X Fiche: 50-142, 83/06/14, 8306170373.

--8306170417 Testimony of B Norton, M Kaku, R Kohn, M Pulido, B Plotkin, D Hirsch, B Aftergood & D DuPont, as Panel III re core disruption & related accidents. Reactor not inherently protected against mechanical damage.
NORTON, B., KAKU, M., KOHN, R. Committee to Bridge the Gap. 83/06/14. 23pp. 18879.218. 24X Fiche: 50-142, 83/06/14, 8306170373.

DOCKETED ITEMS

--B306170426 Testimony of L. Wayne, R. Finston, S. Aftergood, L. Foster, H. Kaku, B. Norton, R. Kohn, B. Plotkin, M. Pulido, D. Dupont & D. Hirsch, as Panel IV re radiation doses from accidental release of fission products. Declaration of BVC encl. WAYNE, L., FINSTON, R., AFTERGOOD, S. Committee to Bridge the Gap 83/06/14 52pp. 18879 241. 24X Fiche: 50-142, 83/06/14, B306170373

DOCKET 50-146 SEXTON NUCLEAR EXPERIMENTAL FACILITY

P. Operating license stage documents & correspondence

B306160030 FOIA request for four documents re Sexton Test Reactor GRABER, L. D. NUS Corp 83/04/12 Division of Rules and Records 1p. 18872:315 24X Fiche: 50-146, 83/04/12, B306160030.

B306160026 Responds to FOIA request for four documents re Sexton Test Reactor Requested ltrs available in PDR Sexton 741124 1tr to NRC not located.

FELTON, J. M. Division of Rules and Records. 83/04/20. GRABER, L. D. NUS Corp 1p. 18872:314. 24X Fiche: 50-146, 83/04/20, B306160026.

DOCKET 50-148 UNIV. OF KANSAS RESEARCH REACTOR

P. Operating license stage documents & correspondence

B306080309 FOIA request for three documents re Univ of KS Research Reactor BARNES, C. Affiliation Unknown 83/03/08. FELTON, J. M. Division of Rules and Records. 1p. 18790:303. 24X Fiche: 50-148, 83/03/08, B306080309.

B306080313 Responds to FOIA request for three documents re Univ of KS Research Reactor. Forwards documents responsive to Items 1 & 2 of request. Releaseability determination for Item 3 re insp rept under review FELTON, J. M. Division of Rules and Records. 83/04/06 BARNES, C. Affiliation Unknown. 1p. 18790:304 24X Fiche: 50-148, 83/04/06, B306080313

--B306080316 Forwards responses to 731106 questions, indicating specified locations on floor plan. SMITH, W. P. Kansas Univ. of. 73/12/06. ZIEHANN, D. L. Atomic Energy Commission. Directorate of Licensing 8pp. 18790:305 24X Fiche: 50-148, 83/04/06, B306080313.

G. Inspection reports, IE Bulletins & correspondence

B306030448 Addl response to FOIA request for three documents re Univ of KS Research Reactor (License R-78) Forwards CL. Haden B30324 1tr transmitting notice of violation & IE Insp Rept 50-148/83-01. FELTON, J. M. Division of Rules and Records. 83/04/19. BARNES, C. Affiliation Unknown 1p. 18735:329. 24X Fiche: 50-148, 83/04/19, B306030448

DOCKET 50-151 UNIV. OF ILLINOIS RESEARCH REACTOR

G. Inspection reports, IE Bulletins & correspondence

B306100217 Forwards IE Insp Repts 50-151/83-01 & 50-356/83-01 on B30504-05. No noncompliance noted. PAPERIELLO, C. J. Region 3, Office of Director. 83/05/25. MILEY, O. H. Illinois Univ. of. Urbana-Champaign 2pp. 18805:189. 24X Fiche: 50-151, 83/05/25, B306100217.

--B306100220 IE Insp Repts 50-151/83-01 & 50-356/83-01 on B30504-05. No noncompliance noted. Major areas inspected: radwaste mgmt & radiation protection program, audits, training, procedures & instruments & equipment. ORANT, H. B., GREGER, L. R. Region 3, Office of Director. 83/05/23. 6pp. 18805:191. 24X Fiche: 50-151, 83/05/23, B306100217.

B306090023 Responds to violation noted in IE insp rept. Forwards data showing that calibr checks performed on dosimeters on 830616. BECK, G. P. Illinois Univ. of. Urbana-Champaign. 83/05/31. ORANT, H. B. Region 3, Office of Director. 2pp. 18792:356. 24X Fiche: 50-151, 83/05/31, B306090023.

DOCKET 50-155 BIO ROCK POINT NUCLEAR PLANT

F. Security, medical, emergency & fire protection plans

B306090118 Advises of approval of emergency response plan for facility, subj to verification of adequacy of public alerting & notification sys MCLOUGHLIN, D. Federal Emergency Management Agency 83/05/16 DIRCKS, W. J. Office of the Executive Director for Operations 1p. 18793:329. 24X Fiche: 50-155, 83/05/16, B306090118

B306100055 Describes integrated assessment of open issues & schedule for issue resolution & documents util response to environ equipment qualification & Generic Ltr 82-33 re NUREG-0737 TONER, K. A. Consumers Power Co 83/06/01 CRUTCHFIELD, D. Operating Reactors Branch 5 113pp. 18804:048 24X Fiche: 50-155, 83/06/01, B306100055

B306090229 Approves State of MI emergency response plan & associated local plans w/condition that adequacy of public alerting & notification sys be verified per FEMA/NRC joint criteria listed in NUREG-0684/FEMA-REP-1, Rev 1, App 3 PAPERIELLO, C. J. Region 3, Office of Director 83/06/06 DEWITT, R. B. Consumers Power Co 2pp. 18796:235 24X Fiche: 50-155, 83/06/06, B306090229

B306100088 Forwards IE Safeguards Insp Rept 50-155/83-08 on B30502-05 No noncompliance noted MILLER, J. R. Region 3, Office of Director 83/06/06 DEWITT, R. B. Consumers Power Co 2pp. 18802:091 24X Fiche: 50-155, 83/06/06, B306100088

--B306100093 IE Safeguards Insp Rept 50-155/83-08 on B30502-05 No noncompliance noted Major areas inspected: review of security plan & implementing procedures, security organization & program. Details withheld (ref 10CFR73.21). CHRISTOFFER, O., STAPLETON, B. W., CREED, J. R. Region 3, Office of Director 83/06/06 2pp. 18802:093 24X Fiche: 50-155, 83/06/06, B306100088

B306140217 Releases public version of revised site emergency plan FELTON, J. M. Division of Rules and Records. 83/06/06 Document Management Branch. 1p. 18844:227 24X Fiche: 50-155, 83/06/06, B306140217

--B306140223 Forwards public version of Rev 6B to site emergency plan * Consumers Power Co 83/05/03 Office of Nuclear Reactor Regulation, Director 1p. 18844:228 24X Fiche: 50-155, 83/06/06, B306140217.

--B306140227 Public version of Rev 6B to site emergency plan * Consumers Power Co 83/05/03. 29pp. 18844:229. 24X Fiche: 50-155, 83/06/06, B306140217.

B306200014 Releases public version of revised emergency plan FELTON, J. M. Division of Rules and Records. 83/06/06 Document Management Branch. 1p. 18909:062 24X Fiche: 50-155, 83/06/06, B306200014

--B306200015 Public version of Rev 6B to emergency plan, consisting of corrections to rev record W/830526 1tr & receipt form. * Consumers Power Co 83/05/23 3pp. 18909:063 24X Fiche: 50-155, 83/06/06, B306200014.

B306170218 Forwards Rev 8 to security plan Rev withheld (ref 10CFR73.21). VANDEWALLE, D. J. Consumers Power Co 83/06/09 CRUTCHFIELD, D. Operating Reactors Branch 5 2pp. 18882:314 24X Fiche: 50-155, 83/06/09, B306170218

B306210173 Forwards detailed scenario for emergency plan exercise scheduled for 830725-26 BORDINE, T. C. Consumers Power Co. 83/06/13. KEPPLER, J. G. Region 3, Office of Director 16pp. 18915:171 24X Fiche: 50-155, 83/06/13, B306210173

B306220065 Forwards Region III B30606 1tr to util endorsing FEMA B30516 1tr to NRC approving State of MI & local emergency plans. GALLO, J. Isham, Lincoln & Beale GALLO, J. Consumers Power Co 83/06/20 BLOCH, F. B., PARIS, D. H., SHON, F. J. Atomic Safety and Licensing Board Panel. 4pp. 18930:150. 24X Fiche: 50-155, 83/06/20, B306220065

B306240285 Forwards response to NRC B30506 & 09 ltrs re security & suitability, training & qualification plans, respectively. Response withheld (10CFR73.21). VANDEWALLE, D. J. Consumers Power Co 83/06/20. CRUTCHFIELD, D. Operating Reactors Branch 5. 2pp. 18780:151. 24X Fiche: 50-000, 83/06/20, B306240285.

DOCKETED ITEMS

17

9 Adjudicatory correspondence

8306010450 Notice of withdrawal as counsel for intervenors & motion for extension to 830701 to submit outstanding documents until new counsel obtained Certificate of Svc encl
BEMMEL, H Christa-Maria 83/05/27 3pp 18674 312 24X
Fiche 50-155, 83/05/27, 8306010450

8306070372 Withdraws 830602 motion re criticality, provisionally filed by telex
O'NEILL, J O'Neill, J 83/05/30 Commissioners 1p 18741 299.
24X Fiche 50-155, 83/05/30, 8306070372

--8306070375 Motion for Commission review of ALAB-725 Exceptions listed Spent fuel pool presents unforgiving design unless geometric configuration safe
O'NEILL, J O'Neill, J 83/06/02 Commissioners 7pp
18741 300 24X Fiche 50-155, 83/05/30, 8306070372

8306020339 Motion for leave to respond to Christa-Maria, J Mills & J Bier 830317 reply to licensee 830121 response to 820914 order directing licensee to demonstrate deficiencies re emergency planning issues Certificate of Svc encl
COPELAND, V O Consumers Power Co COPELAND, V O Isham, Lincoln & Beale 83/06/01 Atomic Safety and Licensing Board Panel 5pp
18693 180 24X Fiche 50-155, 83/06/01, 8306020339.

8306070424 Agrees w/Bemmel 830524 ltr re outstanding emergency planning issues Issues of bus drivers & accuracy of BkW rept must be resolved
O'NEILL, J O'Neill, J, 83/06/01 BLOCH, P B, PARIS, D H, SHON, F. J. Atomic Safety and Licensing Board Panel. 2pp 18742 183 24X
Fiche 50-155, 83/06/01, 8306070424.

8306080232 Motion to reconsider ABLB 830427 Decision ALAB-725 Concerns include lack of safety-related equipment for spent fuel cooling, use of average temp in calculations, void fraction & fuel.
BIER, J. Christa-Maria 83/06/02. Atomic Safety and Licensing Appeal Panel. 2pp 18770 230 24X Fiche: 50-155, 83/06/02, 8306080232

--8306080235 Advises that motion to reconsider ABLB 830427 Decision ALAB-725 should be corrected to read motion for Commission review of ABLB 830427 Decision ALAB-725
BIER, J A. Christa-Maria, 83/06/06 PALLADINO, N. Commissioners 1p 18770. 233 24X Fiche 50-155, 83/06/02, 8306080232.

8306080081 Response to intervenors 830527 motion for extension until 830701 to file response No filings due from intervenors before 830701. Opposes intervenors filing of addl matl on emergency planning issues Certificate of Svc encl.
BACHMANN, R. O Hearing Branch 1. 83/06/06. Atomic Safety and Licensing Board Panel App. 18773 264. 24X Fiche. 50-155, 83/06/06, 8306080081.

8306150405 Reply opposing intervenor 830517 motion re util misrepresentations Allegations of misconduct wholly unfounded
GALLO, J. Consumers Power Co GALLO, J Isham, Lincoln & Beale 83/06/09 Atomic Safety and Licensing Board Panel 6pp
18847 045. 24X Fiche 50-155, 83/06/09, 8306150405.

--8306150409 Affidavit of DJ Vandewalle in response to intervenor allegations of misrepresentation re util request to expand spent fuel storage capacity
VANDEWALLE, D J. Consumers Power Co. 83/06/02 App. 18847 051.
24X Fiche 50-155, 83/06/09, 8306150405

--8306150413 Affidavit of JB Jandovitz justifying util plans to inspect reactor vessel w/fuel in vessel instead of w/fuel removed. Certificate of Svc encl.
JANDOVITZ, J B. Consumers Power Co. 83/06/02 20pp. 18847 055.
24X Fiche: 50-155, 83/06/09, 8306150405.

8306170363 Answer opposing Christa-Maria, Mills & Bier 830602 separate petitions for review of ALAB-725 vacating & remanding LBP-82-97. Petitions fail to satisfy Commission regulation requirements & stds for review w/Certificate of Svc.
BACHMANN, R O. Hearing Branch 1. GORDARD, R. J. Hearing Branch 3 83/06/16 Commissioners. 12pp 18880 181. 24X
Fiche 50-155, 83/06/16, 8306170363.

8306240405 Forwards Director's Decision DD-83-09, denying Christa-Maria, J Bier & J Mills 830516 petition requesting NRC revoke or suspend OL. Notice of issuance of Director's Decision also encl.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 83/06/16. CHRISTA-MARIA Christa-Maria App. 18998. 020. 24X
Fiche: 50-155, 83/06/16, 8306240405

--8306240410 Director's Decision DD-83-09 denying Christa-Maria, J Bier & J Mills 830516 petition requesting NRC revoke or suspend OL
DENTON, H R Office of Nuclear Reactor Regulation, Director. 83/06/16 3pp 18998 024. 24X Fiche. 50-155, 83/06/16, 8306240405

--8306240415 Notice of issuance of Director's Decision DD-83-09, denying Christa-Maria, J Bier & J Mills 830516 petition requesting NRC revoke or suspend OL
DENTON, H R Office of Nuclear Reactor Regulation, Director 83/06/16 2pp 18998 029 24X Fiche 50-155, 83/06/16, 8306240405.

--8306240419 Forwards Director's Decision DD-83-09, denying Christa-Maria, J Bier & J Mills 830516 petition under 10CFR2.206 requesting NRC revoke or suspend OL Notice of issuance of Director's Decision also encl
DENTON, H R. Office of Nuclear Reactor Regulation, Director 83/06/16 BIER, J Affiliation Unknown. App 18998. 031. 24X
Fiche 50-155, 83/06/16, 8306240405.

--8306240421 Forwards Director's Decision DD-83-09, denying Christa-Maria, J Bier & J Mills 830516 petition under 10CFR2.206 requesting NRC revoke or suspend OL. Notice of issuance of Director's Decision also encl
DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 83/06/16 MILLS, J E Affiliation Unknown App. 18998. 042. 24X
Fiche 50-155, 83/06/16, 8306240405

--8306240422 Discusses H Bemmel 830516 petition under 10CFR2.206 requesting revocation or suspension of OL based on alleged false statements made during ongoing spent fuel expansion proceedings Petition can be answered quickly
BURNBS, S O Regional Operations & Enforcement Division. 83/06/02. DENTON, H R Office of Nuclear Reactor Regulation, Director. 1p. 18998 053 24X Fiche 50-155, 83/06/16, 8306240405

--8306240423 Requests proceeding under 10CFR2.206 be instituted to revoke or suspend OL until 10-yr insp at plant conducted w/all fuel removed from reactor core.
BEMMEL, H Antioch School of Law, Washington, DC. BEMMEL, H. Christa-Maria. 83/05/16 Office of Nuclear Reactor Regulation, Director 2pp. 18998. 054. 24X Fiche: 50-155, 83/06/16, 8306240405.

8306220023 Submits schedule of target dates for filing documents & testimony prior to commencement of resumed hearings. Order of issue presentation listed.
GALLO, J. Isham, Lincoln & Beale. GALLO, J. Consumers Power Co. 83/06/17. BLOCH, P B, PARIS, D. H., SHON, F. J. Atomic Safety and Licensing Board Panel 2pp. 18930:209. 24X Fiche: 50-155, 83/06/17, 8306220023.

8306220105 Response opposing J O'Neill & JA Bier petition for Commission review of ALAB-725. No important question of law or policy raised, no error of fact demonstrated & no new issues raised. Certificate of Svc encl
THORNTON, P. Consumers Power Co. THORNTON, P. Isham, Lincoln & Beale. 83/06/17. Commissioners 7pp 18926:248. 24X
Fiche 50-155, 83/06/17, 8306220105.

8306220065 Forwards Region III 830606 ltr to util endorsing FEMA 830516 ltr to NRC approving State of MI & local emergency plans.
GALLO, J. Isham, Lincoln & Beale. GALLO, J. Consumers Power Co. 83/06/20 BLOCH, P. B., PARIS, D. H., SHON, F. J. Atomic Safety and Licensing Board Panel. App. 18930:150. 24X Fiche: 50-155, 83/06/20, 8306220065

8306220102 Forwards addl info re structural integrity of concrete in spent fuel pool at elevated temps & work papers, "Crack Spacing of Two-Way Slab"
GALLO, J. Isham, Lincoln & Beale. GALLO, J. Consumers Power Co. 83/06/20. BLOCH, P. B., PARIS, D. H., SHON, F. J. Atomic Safety and Licensing Board Panel. 15pp. 18927:019. 24X Fiche: 50-155, 83/06/20, 8306220102.

8306230007 Response opposing intervenor 830517 motion alleging util misrepresentation re need to remove fuel from reactor vessel prior to inservice insp. Allegations unsubstantiated.
GORDARD, R. J. Hearing Branch 3. 83/06/20. Atomic Safety and Licensing Board Panel. 20pp. 18947:092. 24X Fiche: 50-155, 83/06/20, 8306230007.

--8306230010 Affidavit of DJ Vandewalle re urgency of util request to expand fuel storage capability Further delays in licensing proceedings could jeopardize continued plant operation. Certificate of Svc encl
VANDEWALLE, D. J. Consumers Power Co. 83/05/05. 8pp. 18947:112. 24X Fiche: 50-155, 83/06/20, 8306230007.

DOCKETED ITEMS

8306270173 Advises of 830607 & 08 military fighter aircraft flying over or in vicinity of facility. Events may be pertinent to Contention II-B re risks associated w/aircraft flying in site vicinity.
COPELAND, V. Q. Isham, Lincoln & Beale. COPELAND, V. Q. Consumers Power Co. 83/06/20. BLOCH, P. B., PARIS, D. H., SHON, F. J. Atomic Safety and Licensing Board Panel. 2pp. 18991:247. 24X
Fiche: 50-155, 83/06/20, 8306270173

8306280552 Memorandum & order denying Christa-Maria 830517 motion re misrepresentation by licensee. No misrepresentations occurred. Parties must exercise restraint so no reputations will be unduly affected by filings.
BLOCH, P. B., PARIS, D. H., SHON, R. J. Atomic Safety and Licensing Board Panel. 83/06/24. Christa-Maria. 3pp. 19018:023. 24X
Fiche: 50-155, 83/06/24, 8306280552.

8306290506 Recommends mods to applicant proposed schedule of target dates.
GODDARD, R. J. Hearing Branch 3. 83/06/28. BLOCH, P. B., SHON, F. J., PARIS, D. H. Atomic Safety and Licensing Board Panel. 1p. 19052:215. 24X
Fiche: 50-155, 83/06/28, 8306290506.

P. Operating license stage documents & correspondence

8306010281 Forwards evaluation of BEP Topic V-5, "RCPB Leakage Detection Sys." Evaluation satisfies 830228 commitment to provide detailed description of plant leakage detection sys.
TONER, K. A. Consumers Power Co. 83/05/25. CRUTCHFIELD, D. Operating Reactors Branch 5. 36pp. 18672:200. 24X
Fiche: 50-155, 83/05/25, 8306010281.

8306010362 Provides explanation of circumstances surrounding containment integrated leak test repairs & justification for actions taken per 830518 telcon request.
BORDINE, T. Consumers Power Co. 83/05/23. CRUTCHFIELD, D. Operating Reactors Branch 5. 4pp. 18682:117. 24X
Fiche: 50-155, 83/05/23, 8306010362.

8306020283 Forwards rev to 801219 response to NUREG-0737, Item I.C.6, "Guidance on Procedures for Verifying Correct Performance of Operating Activities," per 821222 Tech Spec change re shift technical advisor.
BORDINE, T. C. Consumers Power Co. 83/05/25. CRUTCHFIELD, D. Operating Reactors Branch 5. 2pp. 18690:318. 24X
Fiche: 50-155, 83/05/25, 8306020283

8306030223 Application for amend to License DPR-6, changing Tech Specs to revise procedure for reactor startup if neutron source strength below currently specified min count rate on out-of-core nuclear instrumentation.
VANDEWALLE, D. J. Consumers Power Co. 83/05/27. CRUTCHFIELD, D. Operating Reactors Branch 5. 3pp. 18703:351. 24X
Fiche: 50-155, 83/05/27, 8306030223.

--8306030230 Proposed Tech Specs revising procedure for reactor startup if neutron source strength below currently specified min count rate on out-of-core nuclear instrumentation.
* Consumers Power Co. 83/05/27. 3pp. 18703:354. 24X
Fiche: 50-155, 83/05/27, 8306030230.

8306060119 Responds to NRC 830426 BER for environ qualification of safety-related electrical equipment requesting reaffirmation of justification for continued operation (JCO) & info for items in NRC Categories I, B, II, A & IV. Addl JCO not required.
TONER, K. A. Consumers Power Co. 83/05/31. CRUTCHFIELD, D. Operating Reactors Branch 5. 4pp. 18722:271. 24X
Fiche: 50-155, 83/05/31, 8306060119.

8306060144 Informs that incorporation of model Tech Spec definition of "operable-operability" inappropriate for plant. Existing administrative controls meet intent of model Tech Spec definition for auxiliary sys.
BORDINE, T. C. Consumers Power Co. 83/05/31. CRUTCHFIELD, D. Operating Reactors Branch 5. 2pp. 18719:231. 24X
Fiche: 50-155, 83/05/31, 8306060144.

8306080045 Forwards responses to BER on BEP Topics III-6 & III-11 re seismic design considerations & component integrity, respectively. Insp recommended to reduce seismic capacity uncertainty. Structural analysis adequate.
TONER, K. A. Consumers Power Co. 83/06/01. CRUTCHFIELD, D. Operating Reactors Branch 5. 243pp. 18774:233. 24X
Fiche: 50-155, 83/06/01, 8306080045

8306160625 Forwards "Review of Operating Experience History of Big Rock Point Through 1981 for NRC SEP" & responses to util 830114 comments on draft rept transmitted by NRC 820910 ltr. Rept will be included as app to integrated plant BAR.
CRUTCHFIELD, D. Operating Reactors Branch 5. 83/06/02. VANDEWALLE, D. J. Consumers Power Co. 2pp. 18864:223. 24X
Fiche: 50-155, 83/06/02, 8306160625.

--8306160631 "Review of Operating Experience History of Big Rock Point Through 1981 for NRC SEP."
GUYMON, R. H., MAYB, O. T. Oak Ridge National Laboratory. KUKIELKA, C. Science Applications, Inc. ORNL/NBIC-202. 83/04/30. Office of Nuclear Reactor Regulation. Director. 178pp. 18864:223. 24X
Fiche: 50-155, 83/06/02, 8306160625

8306100129 Requests analysis of thermal gradient temporal effects in spent fuel pool structure to demonstrate conservative assessment per 830602 meeting. Response needed prior to restart approval.
CRUTCHFIELD, D. Operating Reactors Branch 5. 83/06/06. VANDEWALLE, D. J. Consumers Power Co. 11pp. 18802:035. 24X
Fiche: 50-155, 83/06/06, 8306100129.

8306100222 Forwards Rev 1 to evaluation of BEP Topic V-5, "RCPB Leakage Detection," replacing 830525 submittal. Evaluation provides PRA cost/benefit data concluding that installation of addl leak detection instrumentation not cost-justified.
TONER, K. A. Consumers Power Co. 83/06/06. CRUTCHFIELD, D. Operating Reactors Branch 5. 37pp. 18805:146. 24X
Fiche: 50-155, 83/06/06, 8306100222.

8306130051 Forwards revised evaluation of RCPB leakage detection sys at facility per BEP Topic V-5. Summary comment re conformance of sys to recommendations of Reg Guide 1.45 either modified or eliminated w/o encl.
TONER, K. A. Consumers Power Co. 83/06/06. CRUTCHFIELD, D. Operating Reactors Branch 5. 2pp. 18824:245. 24X
Fiche: 50-155, 83/06/06, 8306130051.

8306100224 Summary of 830509-11 onsite meetings w/util re expanded BEP integrated assessment program.
EMCH, R. L. Operating Reactors Branch 5. 83/06/08. Operating Reactors Branch 5. 5pp. 18807:217. 24X
Fiche: 50-155, 83/06/08, 8306100224.

8306150003 Forwards responses to NRC concerns re 830110 Amend 6 to License DPR-6 covering spent fuel rack addition. On 830516, BER identified five remaining unresolved items, including shear key capacity & effects of cracking on length.
BORDINE, T. C. Consumers Power Co. 83/06/08. CRUTCHFIELD, D. Operating Reactors Branch 5. 79pp. 18852:087. 24X
Fiche: 50-155, 83/06/08, 8306150003

8306160380 Forwards response to NRC concerns on Amend 2 to License DPR-6 re spent fuel rack addition. Technical justification re orthotropic plate assumptions & transient time provided.
BORDINE, T. C. Consumers Power Co. 83/06/10. CRUTCHFIELD, D. Operating Reactors Branch 5. 29pp. 18859:231. 24X
Fiche: 50-155, 83/06/10, 8306160380

8306160349 Forwards final evaluation of BEP Topic V-5, "RCPB Leakage Detection," based on review of util 830525 submittal. Evaluation will be basic input to integrated safety assessment. Topic complete.
CRUTCHFIELD, D. Operating Reactors Branch 5. 83/06/13. VANDEWALLE, D. Consumers Power Co. 6pp. 18865:117. 24X
Fiche: 50-155, 83/06/13, 8306160349

8306150152 Summary of 830602 meeting w/util & NUS Corp in Bethesda, MD re thermal/structural analysis of spent fuel pool Effects of NRC concerns on analyses would be insignificant.
EMCH, R. L. Operating Reactors Branch 5. 83/06/14. Operating Reactors Branch 5. 4pp. 18846:324. 24X
Fiche: 50-155, 83/06/14, 8306150152.

8306200192 Forwards FR notice of consideration of issuance of amend to License DPR-6 & proposed no significant hazards consideration determination & opportunity for hearing. Amend permits operation w/Exxon H-3 fuel assemblies.
CRUTCHFIELD, D. Operating Reactors Branch 5. 83/06/14. VANDEWALLE, D. J. Consumers Power Co. 3pp. 18903:189. 24X
Fiche: 50-155, 83/06/14, 8306200192.

--8306200197 FR notice of consideration of issuance of amend to License DPR-6 & proposed no significant hazards consideration determination & opportunity for hearing. Amend permits operation w/Exxon H-3 fuel assemblies.
CRUTCHFIELD, D. Operating Reactors Branch 5. 83/06/14. 6pp. 18903:188. 24X
Fiche: 50-155, 83/06/14, 8306200192.

8306200230 Forwards evaluation of BEP Topic V-12 A, "Water Purity of BWR Primary Coolant." Evaluation addresses adequacy of condensate treatment sys administrative controls. Rev to existing Tech Specs unwarranted.
TONER, K. A. Consumers Power Co. 83/06/14. CRUTCHFIELD, D. Operating Reactors Branch 5. 8pp. 18902:322. 24X
Fiche: 50-155, 83/06/14, 8306200230

DOCKETED ITEMS

19

8306200367 Corrects NRC 821129 final BER of util BAR for SEP Topic III-4 B re turbine missiles, incorporating OE probabilistic analysis. Final BER should be revised to incorporate listed corrections.
TONER, K. A. Consumers Power Co. 83/06/14 CRUTCHFIELD, D. Operating Reactors Branch 5 2pp 18879 054 24X Fiche 50-155, 83/06/14, 8306200367

8306230278 Forwards evaluation of SEP Topic VI-1, "Organic Matls & Post-Accident Chemistry." Likelihood of significant stress corrosion cracking very low due to low concentrations of chlorides & acceptable pH level.
TONER, K. A. Consumers Power Co. 83/06/17, CRUTCHFIELD, D. Operating Reactors Branch 5, 8pp. 18745 142. 24X Fiche 50-155, 83/06/17, 8306230278

8306220102 Forwards addl info re structural integrity of concrete in spent fuel pool at elevated temps & work papers: "Crack Spacing of Two-Way Slab"
GALLO, J. Isham, Lincoln & Beale GALLO, J. Consumers Power Co 83/06/20 BLOCH, P. B., PARIS, D. H., SHON, F. J. Atomic Safety and Licensing Board Panel 15pp. 18927 019 24X Fiche 50-155, 83/06/20, 8306220102

8306240004 Forwards vendor info re: "Containment Water Level Monitoring," in response to 830415 request for addl info re NUREG-0737, Items II F 1.4 & II F 1.5, "Containment Pressure Monitor" & "Containment Water Level Monitor"
BORDINE, T. C. Consumers Power Co. 83/06/20, CRUTCHFIELD, D. Operating Reactors Branch 5 16pp 18781, 293. 24X Fiche 50-155, 83/06/20, 8306240004

8306240139 Requests relief from fulfilling 820730 review of seismic Category I structures per SEP Topic III 7.B to determine if differences between structural code utilized for original plant design & current criteria
TONER, K. A. Consumers Power Co. 83/06/20 CRUTCHFIELD, D. Operating Reactors Branch 5 2pp 18981, 087 24X Fiche 50-155, 83/06/20, 8306240139.

8306280559 Forwards documents to assist w/evaluation of 830601 submittal re integrated assessment of open issues Results of primary coolant sys safety relief valve test, in response to NUREG-0737, Item II D. 1, provided in util 811001 ltr w/o encl
BLANCHARD, D. P. Carolina Power & Light Co. 83/06/20 RUBIN, M. NRC - No Detailed Affiliation Given 4pp. 19017, 310 24X Fiche 50-155, 83/06/20, 8306280559

8306270125 Requests exemption from 10CFR50, App J, Section III.A. 6(b) requirements, re integrated leak rate testing per 830617 telcon.
BORDINE, T. C. Consumers Power Co 83/06/21 CRUTCHFIELD, D. Operating Reactors Branch 5, 1p 18980, 086 24X Fiche 50-155, 83/06/21, 8306270125.

8306270076 Discusses encl PRA evaluations re SEP Topic VI-4, "Containment Isolation Sys," per 830228 commitment Only periodic stroke testing of MSIV & periodic leak testing of svc airline check valves cost effective.
TONER, K. A. Consumers Power Co. 83/06/22 CRUTCHFIELD, D. Operating Reactors Branch 5, 2pp 19013 088. 24X Fiche 50-155, 83/06/22, 8306270076

--8306270079 "SEP Topic VI-4, Containment Isolation Sys - PRA Evaluations."
* Consumers Power Co. 83/06/22, 31pp 19013, 090. 24X Fiche 50-155, 83/06/22, 8306270076

8306270107 Discusses encl PRA re SEP Topic III.5 A, "Evaluation of High Energy Line Break Inside Containment for Big Rock Plant," identifying probability of core damage Pipe whip restraints &/or jet shields not cost effective, SEP topic complete.
TONER, K. A. Consumers Power Co. 83/06/22 CRUTCHFIELD, D. Operating Reactors Branch 5 2pp. 19013 308. 24X Fiche 50-155, 83/06/22, 8306270107

--8306270109 "SEP Topic III-5.A, High Energy Line Break Inside Containment - PRA."
* Consumers Power Co 83/06/22, 48pp. 19013, 310. 24X Fiche 50-155, 83/06/22, 8306270107.

8306290391 Forwards justification for SEP Topics II-3.A, II-3.B, II-3.B.1, II-3.C & III-3.A, per NRC request, Evaluations indicate min sys available to safely shut down plant & maintain safe shutdown condition. Topics considered complete.
TONER, K. A. Consumers Power Co. 83/06/23, CRUTCHFIELD, D. Operating Reactors Branch 5, 13pp. 19035, 279. 24X Fiche 50-155, 83/06/23, 8306290391.

8306290412 Forwards corrections to PRA evaluations submitted to NRC on 830331 re BER on SEP Topic IX-5, "Ventilation Sys." Evaluations address impact loss of ventilation would have on various rooms & present cost-benefit analysis of mods.
TONER, K. A. Consumers Power Co 83/06/23, CRUTCHFIELD, D. Operating Reactors Branch 5 20pp 19053, 150. 24X Fiche 50-155, 83/06/23, 8306290412

8306280442 Advises that, based on review of 801219 submittal re NUREG-0737, Item II K 3.21, "Restart of Core Spray & LPCI Sys," issue resolved.
CRUTCHFIELD, D. Operating Reactors Branch 5, 83/06/27 VANDEHALL, D. J. Consumers Power Co 4pp 19020 184 24X Fiche 50-155, 83/06/27, 8306280442

8306300027 Forwards safety evaluation of util responses to NRC 781129 ltr re Generic Item B-24, "Containment Purging/Venting During Normal Operations." Radiological consequences of LOCA during purging acceptable Item closed.
CRUTCHFIELD, D. Operating Reactors Branch 5 83/06/28, VANDEHALL, D. J. Consumers Power Co 5pp. 19120, 238 24X Fiche 50-155, 83/06/28, 8306300027

--8306300034 Safety evaluation of util responses to NRC 781129 ltr re Generic Item B-24, "Containment Purging/Venting During Normal Operations." Issue of purge & vent valve operability resolved except for two open items
* Office of Nuclear Reactor Regulation, Director. 83/06/28, 7pp 19120, 243. 24X Fiche 50-155, 83/06/28, 8306300027

Q Inspection reports, IE Bulletins & correspondence

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device." Svc list encl.
TAYLOR, J. M. Division of Safeguards & Inspection Programs (Post 830103) 83/05/26, Consolidated Edison Co. of New York, Inc. 125pp 18831, 043. 24X Fiche 50-000, 83/05/26, 8305110458.

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/26 Consolidated Edison Co. of New York, Inc. 115pp. 18732, 085. 24X Fiche 50-000, 83/05/26, 8305110460.

8306100226 Forwards IE Insp Rept 80-155/83-06 on 830425-28. No noncompliance noted.
PAPERIELLO, C. J. Region 3, Office of Director 83/05/26 DEWITT, R. B. Consumers Power Co. 2pp. 18805, 312. 24X Fiche 50-155, 83/05/26, 8306100226.

--8306100229 IE Insp Rept 80-155/83-06 on 830425-28. No noncompliance noted Major areas inspected: radiation protection program including qualifications, audits, training, radiation protection procedures, exposure control & TMI action items.
LOVENDALE, P. C., OREGON, L. R. Region 3, Office of Director. 83/05/24 7pp 18805, 314. 24X Fiche 50-155, 83/05/26, 8306100226

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/31, Consolidated Edison Co. of New York, Inc. 116pp 18732, 208. 24X Fiche 50-000, 83/05/31, 8305110461.

8306100088 Forwards IE Safeguards Insp Rept 80-155/83-08 on 830502-05. No noncompliance noted
MILLER, J. R. Region 3, Office of Director. 83/06/06, DEWITT, R. B. Consumers Power Co 2pp. 18802, 091 24X Fiche 50-155, 83/06/06, 8306100088

--8306100093 IE Safeguards Insp Rept 80-155/83-08 on 830502-05. No noncompliance noted Major areas inspected: review of security plan & implementing procedures, security organization & program. Details withheld (ref 10CFR73.21)
CHRISTOFFER, O., STAPLETON, B. W., CREED, J. R. Region 3, Office of Director 83/06/06, 2pp. 18802, 093. 24X Fiche 50-155, 83/06/06, 8306100088

8306230431 Forwards IE Insp Rept 80-155/83-10 on 830512-13 & 21-24. No noncompliance noted
LITTLE, W. S. Region 3, Office of Director. 83/06/08 DEWITT, R. B. Consumers Power Co 2pp 18943, 233 24X Fiche 50-155, 83/06/08, 8306230431.

--8306230440 IE Insp Rept 80-155/83-10 on 830512-13 & 21-24. No noncompliance noted Major areas inspected: review of inservice insp procedures, work activities, NDE, personnel certifications & data.
WARD, K. D., DANIELSON, D. H. Region 3, Office of Director. 83/06/09, 7pp. 18943, 235. 24X Fiche 50-155, 83/06/08, 8306230431

DOCKETED ITEMS

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/09 Consolidated Edison Co. of New
York, Inc 119pp 18630 280 24X Fiche 50-000, 83/06/09, 8305110464

8306170355 Responds to IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators " Bulletin not applicable to plant since check valve not used at facility.
JOHNSON, B. D. Consumers Power Co 83/06/09 KEPLER, J. O. Region 3, Office of Director 4pp 18881 001 24X Fiche 50-155, 83/06/09, 8306170355

8306150218 Discusses results of review of relief requests re inservice insp relief granted in part from requirements of Section XI of ASME Boiler & Pressure Vessel Code SER encl
CRUTCHFIELD, D. Operating Reactors Branch 5 83/06/10
VANDEWALLE, D. Consumers Power Co 4pp 18846 018 24X Fiche 50-155, 83/06/10, 8306150218

--8306150222 Safety evaluation granting in part requests for relief from inservice insp requirements
* Operating Reactors Branch 5 83/06/10, 16pp 18846 022 24X Fiche 50-155, 83/06/10, 8306150218

8306270169 Forwards IE Insp Rept 50-155/83-07 on 830509-12 No noncompliance noted
PAPERIELLO, C. J. Region 3, Office of Director 83/06/10
DEWITT, R. B. Consumers Power Co 2pp 18992 010 24X Fiche 50-155, 83/06/10, 8306270169

--8306270174 IE Insp Rept 50-155/83-07 on 830509-12 No noncompliance noted Major areas inspected: radiological environ monitoring program, analytical measurement QC, confirmatory measurements program & previous insp items.
JANUSKA, A. Q., DEBTHANN, M. J., SCHUMACHER, M. C. Region 3, Office of Director, 83/06/10, 6pp 18992 012 24X Fiche 50-155, 83/06/10, 8306270169

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13, Consolidated Edison Co. of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8306210095 Ack receipt of 830526 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-155/83-04
SHAFFER, W. D. Region 3, Office of Director 83/06/14, DEWITT, R. B. Consumers Power Co. 1p 18914:160 24X Fiche 50-155, 83/06/14, 8306210095

--8306210102 Responds to NRC 830427 ltr re violations noted in IE Insp Rept 50-155/83-04 Corrective actions: four pieces of 1/4-inch stainless steel tubing taped in per Procedure 13-3, Rev 35, "Hatt Control," & valve & HX openings taped closed
VANDEWALLE, D. J. Consumers Power Co 83/05/26, KEPLER, J. O. Region 3, Office of Director, 5pp, 18914:161 24X Fiche: 50-155, 83/06/14, 8306210095,

8306230512 Requests until remit Class III fee for 781222 application requesting relief from certain inservice insp requirements of 10CFR50.55a(g) since review involved consideration of single safety issue
D1008, R. M. License Fee Management Branch. 83/06/16
VANDEWALLE, D. J. Consumers Power Co 1p, 18982 044, 24X Fiche: 50-155, 83/06/16, 8306230512.

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22, Consolidated Edison Co. of New York, Inc. 115pp, 19021 179 24X Fiche: 50-000, 83/06/22, 8305110475,

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22, Consolidated Edison Co. of New York, Inc. 120pp, 18997.007, 24X Fiche: 50-000, 83/06/22, 8305110477,

8306270376 Submits addl info re Generic Ltr 81-03 concerning implementation of NUREG-0313, "Intergranular Stress Corrosion Cracking of Pressure Boundary Piping & Safe Ends " per 830415 request inservice insp program not appropriate
BORDINE, T. C. Consumers Power Co 83/06/22 CRUTCHFIELD, D. Operating Reactors Branch 5 5pp 18993 308 24X Fiche 50-155, 83/06/22, 8306270376

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions," Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co. of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc 116pp, 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

R Periodic operating reports & related correspondence

8306060095 Monthly operating rept for Mar 1983, W/830406 ltr
AMSTUTZ, B., HOFFMAN, D. P. Consumers Power Co 83/04/04 6pp 18719:348 24X Fiche 50-155, 83/04/04, 8306060095

8306160566 Monthly operating rept for Apr 1983 W/830503 ltr
HOFFMAN, D. P., AMSTUTZ, B. Consumers Power Co 83/05/05
Director's Office, Office of Inspection and Enforcement 5pp 18866:290, 24X Fiche 50-155, 83/05/02, 8306160566

8305260226 Revised Table R8D-E-06B listing high, low & average concentrations for environ monitoring rept for 1982
submitted 830329

BORDINE, T. C. Consumers Power Co 83/05/19 KEPLER, J. O. Region 3, Office of Director 2pp 18625, 041 24X Fiche 50-155, 83/05/19, 8305260226

8305260265 Corrected annual environ monitoring rept, 1982, replacing Table R8D-E-06B to correct high, low & average concentration for highest average sampling location
BORDINE, T. C. Consumers Power Co, 83/05/19 KEPLER, J. O. Region 3, Office of Director, 3pp 18626 321 24X Fiche 50-155, 83/05/19, 8305260265

S Reportable occurrences, LERs & related correspondence

8306230241 LER 83-001/03L-0 on 830520, one of two steam drum level switches in each protection channel operated below required set point of 8 inches below drum ctr line Caused by error in calibr techniques W/830617 ltr

BORDINE, T. C. Consumers Power Co 83/06/17 KEPLER, J. O. Region 3, Office of Director 2pp 18945, 233 24X Fiche 50-155, 83/06/17, 8306230241

8306230330 PNO-111-83-050 on 830617, w/circuit breakers for core spray valves closed, core spray valves opened Approx 600 gallons lake water injected into reactor vessel, raising chloride concentration Event not reported within 1 h
HOLZMER, M., JACKIH, I. Region 3, Office of Director 83/06/17 1p 18942 274, 24X Fiche 50-155, 83/06/17, 8306230330,

T. Hearing transcripts on non-antitrust matters

8306090005 Transcript of 830607 telephone conference in Bethesda, MD, Pp 2, 646-2, 685.
* Atomic Safety and Licensing Board Panel 83/06/07 41pp 18793 330, 24X Fiche 50-155, 83/06/07, 8306090005,

DOCKET 50-156 UNIV OF WISCONSIN RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8306060270 Ack receipt of 830509 ltr informing NRC of steps taken to correct violations noted in IE insp rept
MILLER, J. R. Region 3, Office of Director, 83/06/01 CASHWELL, R. J. Wisconsin, Univ. of, Madison 1p, 18730:018 24X Fiche 50-156, 83/06/01, 8306060270,

--8306060272 Responds to NRC 830504 ltr re violations noted in IE insp rept, Corrective actions, copies of current security plan retrieved & destroyed or stamped & stored per 10CFR73.21.
CASHWELL, R. J. Wisconsin, Univ. of, Madison, 83/05/09
MILLER, J. R. Region 3, Office of Director 1p, 18730 019 24X Fiche 50-156, 83/06/01, 8306060270,

DOCKETED ITEMS

21

Q Inspection reports, IE Bulletins & correspondence

8306060270 Ack receipt of 830509 ltr informing NRC of steps taken to correct violations noted in IE insp rept
MILLER, J R Region 3, Office of Director 83/06/01 CASHWELL, R J
Wisconsin, Univ of, Madison 1p 18730 018 24X
Fiche 50-156, 83/06/01, 8306060270

--8306060272 Responds to NRC 830504 ltr re violations noted in IE insp rept. Corrective actions copies of current security plan retrieved & destroyed or stamped & stored per 10CFR73.21
CASHWELL, R J Wisconsin, Univ of, Madison 83/05/09
MILLER, J R Region 3, Office of Director 1p 18730 019 24X
Fiche 50-156, 83/06/01, 8306060270

8306270162 Forwards IE Insp Repts 50-154/83-03 & 70-0134/83-01 on 830519-20 No noncompliance noted
PAPERIELLO, C J Region 3, Office of Director 83/06/08
CASHWELL, R J Wisconsin, Univ of, Madison 2pp 18992 026 24X
Fiche 50-156, 83/06/08, 8306270162

--8306270167 IE Insp Repts 50-154/83-03 & 70-0134/83-01 on 830519-20. No noncompliance noted Major areas inspected: radiation protection & radwaste mgmt program, including organization & qualifications & logs & records.
PAUL, R A, GREGER, L R Region 3, Office of Director 83/06/08
6pp. 18992 028 24X Fiche 50-156, 83/06/08, 8306270162

DOCKET 50-157 CORNELL UNIV RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8306230238 Forwards proposed physical security plan Plan withheld (ref 10CFR2 770)
CLARK, D D Cornell Univ 83/06/17 THOMAS, C D Standardization & Special Projects Branch 1p 18945 253 24X Fiche 50-097, 83/06/17, 8306230238

Q Inspection reports, IE Bulletins & correspondence

8306140248 Ack receipt of 830518 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-097/83-01 & 50-157/83-01.
STAROSTECKI, R Division of Project & Resident Programs 83/06/06.
STREET, W B Cornell Univ 1p. 18833 011 24X
Fiche 50-097, 83/06/06, 8306140248

--8306140253 Responds to NRC 830421 ltr re violations noted in IE Insp Rept 50-157/83-01 Corrective actions TRIQA operations audited, insp findings reviewed at safety committee meeting & annual audit of tickler file required
CLARK, D D Cornell Univ 83/05/18. STAROSTECKI, R. Division of Project & Resident Programs 2pp 18833 012 24X
Fiche 50-097, 83/06/06, 8306140248

V Operator Examinations

8306140553 Extends invitation to attend 830627 meeting in King of Prussia, PA to discuss transfer of reactor operator licensing function from Bethesda, MD to Region 1 ofc
STAROSTECKI, R Division of Project & Resident Programs 83/06/09.
STREET, W B Cornell Univ 2pp. 18834 004 24X
Fiche 50-097, 83/06/09, 8306140553

DOCKET 50-163 GENERAL ATOMIC CO

F Security, medical, emergency & fire protection plans

8306280171 Forwards IE Insp Repts 50-089/83-02 & 50-163/83-02 on 830509-12 & notice of violation. Present level of resources allocated to radiation protection program inadequate. Insp frequency will be increased.
BOOK, H E Region 5, Office of Director 83/05/27 PARKER, J. W. OA Technologies, Inc /General Atomic Co 2pp 19014 136 24X
Fiche 50-089, 83/05/27, 8306280171

--8306280177 Notice of violation from insp on 830509-12.
WENSLAWSKI, F. A. Region 5, Office of Director. 83/05/27 1p.
19014 138 24X Fiche 50-089, 83/05/27, 8306280171.

--8306280185 IE Insp Repts 50-089/83-02 & 50-163/83-02 on 830509-12 Noncompliance noted: failure to post notice of violation re radiological working conditions, per 10CFR19.11(e).
YUHAB, Q. P. Region 5, Office of Director. 83/05/27. 10pp
19014 139. 24X Fiche: 50-089, 83/05/27, 8306280171.

8306220240 Forwards request for addl info re OA Technologies, Inc research reactor 821102 emergency plan to continue review per 10CFR50, App E, Reg Guide 2.6, Rev 1 & ANSI/ANS-15.16-1982 requirements. Info requested within 30 days of ltr date
THOMAS, C D Standardization & Special Projects Branch 83/06/10
MOWRY, W R OA Technologies, Inc /General Atomic Co 6pp
18977 026 24X Fiche 50-089, 83/06/10, 8306220240

Q Inspection reports, IE Bulletins & correspondence

8306280171 Forwards IE Insp Repts 50-089/83-02 & 50-163/83-02 on 830509-12 & notice of violation. Present level of resources allocated to radiation protection program inadequate. Insp frequency will be increased
BOOK, H E Region 5, Office of Director 83/05/27 PARKER, J. W. OA Technologies, Inc /General Atomic Co 2pp 19014 136 24X
Fiche 50-089, 83/05/27, 8306280171

--8306280177 Notice of violation from insp on 830509-12.
WENSLAWSKI, F. A. Region 5, Office of Director. 83/05/27 1p.
19014 138 24X Fiche. 50-089, 83/05/27, 8306280171.

--8306280185 IE Insp Repts 50-089/83-02 & 50-163/83-02 on 830509-12. Noncompliance noted: failure to post notice of violation re radiological working conditions, per 10CFR19.11(e).
YUHAB, Q. P., WENSLAWSKI, F. A., BOOK, H E Region 5, Office of Director 83/05/27 10pp 19014 139 24X Fiche 50-089, 83/05/27, 8306280171.

DOCKET 50-166 UNIV OF MARYLAND RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8306210328 Forwards request for addl info re Univ of MD research reactor 821027 emergency plan to continue review per 10CFR50, App E, Reg Guide 2.6, Rev 1 & ANSI/ANS-15.16-1982 requirements. Info requested within 30 days of ltr date.
THOMAS, C D Standardization & Special Projects Branch 83/06/09
TOLL, J B. Maryland, Univ of 5pp 18921 340. 24X
Fiche 50-166, 83/06/09, 8306210328

DOCKET 50-170 NATIONAL NAVAL MEDICAL CENTER

E NRC Safety Evaluation Report (SER), supp's & correspondence

8306210378 SAFETY EVALUATION REPORT RELATED TO THE RENEWAL OF THE OPERATING LICENSE FOR THE RESEARCH REACTOR AT THE ARMED FORCES RADIOBIOLOGY RESEARCH INSTITUTE. Docket No. 50-170.
* Division of Licensing. NUREG-0882 601 83/05/31. 1pp.
Available at NRC. \$3.00 18937 261 24X Fiche 50-170, 83/05/31, 8306210378

Q Adjudicatory correspondence

8306060316 Advances of Citizens for Nuclear Reactor Safety/ licensee agreement to discontinue litigation of admissible contentions except emergency plan contention in TRIQA reactor proceeding.
ENTHLE, E B Citizens for Nuclear Reactor Safety, Inc. 83/05/23.
HOYT, H. Atomic Safety and Licensing Board Panel 9pp 18729 163.
24X Fiche. 50-170, 83/05/23, 8306060316

8306150391 Forwards supplemental SER, NUREG-0882 re NRC review of licensee emergency plan, W/O encl.
BACHMANN, R Q Hearing Branch 1. 83/06/10 HOYT, H., HILL, E. E., SCHINK, D R Atomic Safety and Licensing Board Panel. 1p.
18947 028 24X Fiche 50-170, 83/06/10, 8306150391

8306220056 Ack receipt of 830316 ltr re EIA & negotiations for relicensing of AFRR nuclear reactor & cobalt irradiation facility. Issues re monitoring results, oversight committee & emergency plan should be addressed.
SCULL, D L., OILCHRIST, C. W. Montgomery County, MD 83/06/14.
PALLADINO, N Commissioners. GRIFFITH, H. A. Defense, Dept. of, Defense Nuclear Agency. 2pp 18930 028. 24X Fiche: 50-000, 83/06/14, 8306220056.

--8306220063 Responds to 830215 ltr re ongoing license renewal proceedings NRC decision not to issue EIS will be reexamined
PLAINE, H. H. Office of the General Counsel. 83/03/16
OILCHRIST, C W., SCULL, D L. Montgomery County, MD 2pp
18930 027 24X Fiche. 50-000, 83/06/14, 8306220056

DOCKETED ITEMS

V. Operator Examinations

8306140628 Extends invitation to attend 830627 meeting in King of Prussia, PA to discuss transfer of reactor operator licensing function from Bethesda, MD to Region I ofc.
STAROSTECKI, R. Division of Project & Resident Programs. 83/06/09.
ADCOCK, B.R. Armed Forces Radiobiological Research Institute. Rpp. 18833:180 24X Fiche 50-170, 83/06/09, 8306140628

DOCKET 50-182 PURDUE UNIV. RESEARCH REACTOR

B Reportable occurrences, LERs & related correspondence

8306230282 RD on 830614, sealed source w/Ru-106 leak tested. Results showed 0.005 uCi activity removed by smear. Second test on 830617 showed 0.00016 uCi removed. Source removed from use.
BORN, Q.B. Purdue Univ. 83/06/17 SRENIANSKI, D. Region 3, Office of Director 2pp. 18945:217 24X Fiche 50-182, 83/06/17, 8306230282.

DOCKET 50-184 NATIONAL BUREAU OF STANDARDS REACTOR

V Operator Examinations

8306140152 Extends invitation to attend 830627 meeting in King of Prussia, PA to discuss transfer of reactor operator licensing function from Bethesda, MD to Region I ofc.
STAROSTECKI, R. Division of Project & Resident Programs 83/06/09
CARTER, R.B. Commerce, Dept. of, National Bureau of Standards 2pp 18839:074. 24X Fiche 50-184, 83/06/09, 8306140152.

8306140278 Extends invitation to attend 830627 meeting in King of Prussia, PA to discuss transfer of reactor operator licensing function from Bethesda, MD to Region I ofc.
STAROSTECKI, R. Division of Project & Resident Programs 83/06/09
KERR, F. Maryland, Univ. of 2pp 18832:234. 24X Fiche 50-184, 83/06/09, 8306140278.

DOCKET 50-186 UNIV. OF MISSOURI RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8306150163 Forwards physical security plan. Plan withheld (ref 10CFR2.790 & 10CFR73.21).
MCKIBBEN, J.C.; MCINTY, D.M.; BRUGGER, R. Missouri, Univ. of, Columbia 83/06/10. THOMPSON, C.D. Standardization & Special Projects Branch 2pp 18846:005. 24X Fiche 50-186, 83/06/10, 8306150163.

DOCKET 50-188 KANSAS STATE UNIV. RESEARCH REACTOR

H General correspondence

8306160229 Advises of appointment of J Higginbotham as reactor supervisor, effective 830601.
FAN, R.E. Kansas State Univ. 83/06/10 MILLER, J.R. Standardization & Special Projects Branch. 2pp. 18861:239. 24X Fiche 50-188, 83/06/10, 8306160229

DOCKET 50-192 UNIV. OF TEXAS RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

8306020702 Forwards request for info identified in encl emergency plan review by 830709. Plan does not currently meet requirements of App E to 10CFR50 & guidance criteria set forth in Rev 1 to Reg Guide 2.6 & ANSI/ANS-15.16-1982
THOMAS, C.D. Standardization & Special Projects Branch. 83/05/23.
KLEIN, D.E. Texas, Univ. of, Austin, TX. 7pp. 18716:349. 24X Fiche 50-192, 83/05/23, 8306020702.

8306290403 Forwards request for addl info re physical security plan. Requested info required by 830709. W/c encl
THOMAS, C.D. Standardization & Special Projects Branch. 83/06/24.
KLEIN, D.E. Texas, Univ. of, Austin, TX. 1p. 19053:126 24X Fiche 50-192, 83/06/24, 8306290403.

DOCKET 50-193 RHODE ISLAND & PROVIDENCE PLANTATIONS AEC

F Security, medical, emergency & fire protection plans

8306080329 Requests route approval for shipment of spent fuel from Narragansett, RI to Savannah River, SC. Mode to last routes made to avoid travel through downtown Westerly, RI
DIMEGLIO, A.F. Rhode Island, State of 83/05/27 HILLMAN, C. Division of Safeguards 2pp 18789:339 24X Fiche 50-193, 83/05/27, 8306080329

8306210348 Forwards approved route for transport of spent fuel from Narragansett, RI to Savannah River, SC, in response to 830327 request

SHERR, T.B. Material Transfer Safeguards Licensing Branch 83/06/08
DIMEGLIO, A.F. Rhode Island, State of 18pp 18921:345 24X Fiche 50-193, 83/06/08, 8306210348.

G Inspection reports, IE Bulletins & correspondence

8306160238 Forwards IE Insp Rept 50-193/83-01 on 830425-2B & notice of violation
STAROSTECKI, R. Division of Project & Resident Programs 83/05/27
DIMEGLIO, A.F. Rhode Island & Providence Plantation 2pp 18861:309 24X Fiche 50-193, 83/05/27, 8306160238

--8306160239 Notice of violation from insp on 830425-2B
* Region 1, Office of Director 83/05/27 1p 18861:311 24X Fiche 50-193, 83/05/27, 8306160238

--8306160246 IE Insp Rept 50-193/83-01 on 830425-2B Noncompliance noted failure to formally appoint alternate to position of health physicist upon temporary vacancy & to post outside door into HX room as high radiation area
KINNEY, H.W.; ELBASSER, T.C. Region 1, Office of Director 83/05/20 9pp 18861:312 24X Fiche 50-193, 83/05/27, 8306160238

V Operator Examinations

8306140098 Extends invitation to attend 830627 meeting in King of Prussia, PA to discuss transfer of reactor operator licensing function from Bethesda, MD to Region I ofc
STAROSTECKI, R. Division of Project & Resident Programs 83/06/09
DIMEGLIO, A.F. Rhode Island, State of 2pp 18839:107 24X Fiche 50-193, 83/06/09, 8306140098.

DOCKET 50-199 MANHATTAN COLLEGE RESEARCH REACTOR

H. General correspondence

8306280389 Notifies that G Kane appointed chief reactor supervisor, effective 830702. Appointment will be noted in license renewal application being prepared
KANE, R.B. Manhattan College. 83/06/21. BERNARD, H. Standardization & Special Projects Branch 1p 19001:361 24X Fiche 50-199, 83/06/21, 8306280389

V. Operator Examinations

8306140625 Extends invitation to attend 830627 meeting in King of Prussia, PA to discuss transfer of reactor operator licensing function from Bethesda, MD to Region I ofc.
STAROSTECKI, R. Division of Project & Resident Programs 83/06/09
KANE, R. Manhattan College 2pp. 18842:084 24X Fiche 50-199, 83/06/09, 8306140625

DOCKET 50-201 WEST VALLEY REPROCESSING PLANT

P. Operating license stage documents & correspondence

8306010094 GEOLOGIC AND HYDROLOGIC RESEARCH AT THE WESTERN NEW YORK NUCLEAR SERVICE CENTER, WEST VALLEY, NEW YORK. Annual Report. August 1981 - July 1982.
ALBANESE, J.R.; ANDERSON, S.L.; DUNNE, L.A. New York, State of. FIN 8-6390 NUREG/CR-3207. 83/03/31 Division of Health, Safety & Waste Management 41pp Available at NRC #B.50. 18687:304. 24X Fiche 50-201, 83/03/31, 8306010094.

8306150216 Trip rept of site visit to observe test equipment operation & discuss waste mgt techniques w/DOE personnel & Dupont Corp. List of participants encl.
BOYLE, R. High Level Waste Licensing Management Branch. CLARK, A.T. NRC - No Detailed Affiliation Given 83/05/25 ROUSE, L.C. NRC - No Detailed Affiliation Given. BELL, M.J. High Level Waste Licensing Management Branch. 9pp. 18870:036. 24X Fiche 50-201, 83/05/25, 8306150216.

DOCKETED ITEMS

23

8306290620 Forwards "Analysis of Terminal Waste Form Selection for West Valley Demonstration Project" Rept discusses basis for selection of borosilicate glass
COFFMAN, F E Energy, Dept of 83/06/14 DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director 2pp 19047, 055 24X
Fiche 50-201, 83/06/14, 8306290620

--8306290626 "Analysis of Terminal Waste Form Selection for West Valley Demonstration Project"
* Energy, Dept of WVPD-100 83/06/14 24pp 19047 057, 24X
Fiche 50-201, 83/06/14, 8306290620

8306290566 Advises that DOE has selected borosilicate glass as waste form for immobilizing West Valley high level wastes
Appropriate tests of wastes required
HANNUM, W H Energy, Dept of 83/06/17 CLARK, A T Advanced Fuel & Spent Fuel Licensing Branch 1p 19047 188, 24X
Fiche 50-201, 83/06/17, 8306290566

DOCKET 50-206 SAN ONOFRE NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8306070251 Forwards IE Insp Repts 50-206/83-10, 50-361/83-19 & 50-362/83-17 on 830411-27 & notice of violation
BISHOP, T M Region 5, Office of Director, 83/05/16. PAPAY, L T Southern California Edison Co 2pp 18746 088 24X
Fiche 50-206, 83/05/16, 8306070251

--8306070261 IE Insp Repts 50-206/83-10, 50-361/83-19 & 50-362/83-17 on 830411-27 Noncompliance noted failure to install fully 8-h emergency lighting units in access/egress routes
BOON, K M Region 5, Office of Director 83/05/11 11pp 18746 092 24X Fiche 50-206, 83/05/16, 8306070251

8306010142 Advises that addl fire protection Tech Spec changes will be submitted as separate amend applicant superseding Proposed Change 92 by 830901 Addl fire protection mods in progress
KRIEGER, R W Southern California Edison Co, 83/05/24 CRUTCHFIELD, D Operating Reactors Branch 5 1p 18674, 044, 24X
Fiche 50-206, 83/05/24, 8306010142

8306160011 Advises that 830323 Rev 9 to physical security plan consistent w/10CFR73 21 provisions & does not decrease plan effectiveness. Changes acceptable
KNIGHTON, G W Licensing Branch 3 83/06/06, DIETCH, R Southern California Edison Co HOLCOMBE, J C San Diego Gas & Electric Co 3pp, 18872 148 24X Fiche 50-206, 83/06/06, 8306160011

8306280076 Forwards IE Insp Rept 50-206/83-09 on 830323 No noncompliance noted.
NORDERHAUG, L Region 5, Office of Director 83/06/07 PAPAY, L T Southern California Edison Co 2pp, 19001 168 24X
Fiche 50-206, 83/06/07, 8306280076

--8306280081 IE Insp Rept 50-206/83-09 on 830323. No noncompliance noted Major areas inspected, emergency plan exercise & associated critiques
KUNIHARD, D M, SCHUBERT, M D Region 5, Office of Director 83/06/06 5pp 19001 170, 24X Fiche 50-206, 83/06/07, 8306280076

8306220291 Responds to 830406 ltr re changes to physical security plan. Changes consistent w/10CFR50.54(p) & do not decrease effectiveness of plan.
KNIGHTON, G W Licensing Branch 3 83/06/10 DIETCH, R Southern California Edison Co HOLCOMBE, J C San Diego Gas & Electric Co, 3pp 18940 344 24X Fiche 50-206, 83/06/10, 8306220291

8306220294 Responds to 830323 ltr re Rev 2 to guard training & qualification plan Changes consistent w/10CFR50.54(p) provisions & do not decrease effectiveness of plan.
KNIGHTON, G W Licensing Branch 3 83/06/10, DIETCH, R Southern California Edison Co HOLCOMBE, J C San Diego Gas & Electric Co, 3pp, 18940 312, 24X Fiche 50-206, 83/06/10, 8306220294

8306230520 Responds to 830427 ltr re temporary changes to physical security plan Changes consistent w/10CFR50.54(p) requirements & acceptable.
KNIGHTON, G W Licensing Branch 3, 83/06/10, DIETCH, R Southern California Edison Co HOLCOMBE, J C San Diego Gas & Electric Co, 2pp 18954 361, 24X Fiche 50-206, 83/06/10, 8306230520

8306230455 Ack receipt & provides evaluation of changes to emergency plan implementing procedures submitted in 821029 & 831103 ltrs. Changes do not decrease effectiveness of emergency response planning
NORDERHAUG, L R Division of Radiological Safety & Safeguards Program 83/06/20, BASKIN, K P Southern California Edison Co, 1p 18941 360 24X Fiche 50-206, 83/06/20, 8306230455

J Insurance & indemnity information

8306270172 Forwards Endorsements 95, 96 & 97 to NELIA Policy NF-146, & Endorsements 83, 84 & 85 to MAELU Policy MF-38 & Endorsement 38 to NELIA Policy NF-282
ROCCO, J Southern California Edison Co 83/06/13 DINITZ, I, Antitrust & Economic Analysis Branch (Utility Finance) 8pp 18991 349, 24X Fiche 50-206, 83/06/13, 8306270172

P Operating license stage documents & correspondence

8306070019 Final response to FOIA request for documents re current efforts by NRC to upgrade earthquake resistance at facility Forwards documents listed in app. Handwritten document withheld (ref FOIA Exemption 3)
FELTON, J M Division of Rules and Records 83/04/05, WHARTON, R J San Diego, Univ. of, San Diego, CA 2pp, 18781 343 24X
Fiche 50-206, 83/04/05, 8306070019

--8305170474 Forwards 820506 memo w/Systematic Evaluation Program Branch recommendations re seismic reanalysis program
DIRCKS, W J Office of the Executive Director for Operations, 82/05/07, PALLADINO, N J, OILINSKY, V, AHEARNE, J F, Commissioners 2pp 18781 332 24X Fiche 50-206, 83/04/05, 8306070019

--8208050024 Forwards response to 820618 request for comments on Director's Decision 81-19 denying 10CFR2 206 relief re restart & emergency planning
DIRCKS, W J Office of the Executive Director for Operations, 82/07/22, AHEARNE, J Commissioners 6pp 18781 354, 24X
Fiche 50-206, 83/04/05, 8306070019

--8306070021 Requests meeting to discuss encl questions on BECY-82-63 re Director's Decision denying 10CFR2 206 relief concerning interim seismic adequacy.
AHEARNE, J Commissioners 82/04/20 Office of Policy Evaluations 5pp, 18781 347, 24X Fiche 50-206, 83/04/05, 8306070019

--8306070028 Approves BECY-82-63 re Director's Decisions 81-19 & 81-20 denying request for 10CFR2 206 relief Comments on BECY-82-63 re misclassification of turbine bldg complex encl.
AHEARNE, J F Commissioners, 82/05/03, CHILK, S J, Office of the Secretary of the Commission 2pp 18782 008, 24X
Fiche 50-206, 83/04/05, 8306070019

8306080209 Summary of 830601 meeting w/util re plan for managing retrofit items License amend schedule, w/proposed safety-based integrated schedule, will be submitted on or about 831115 List of attendees & handouts encl
PAULSON, W A Operating Reactors Branch 5 83/06/03, Operating Reactors Branch 5, 3pp 18771 274, 24X Fiche 50-206, 83/06/03, 8306080209

--8306080210 "Plan for Managing Plant Retrofit,"
* Southern California Edison Co, 83/06/01, 23pp, 18771 277, 24X Fiche 50-206, 83/06/03, 8306080209

8306070049 Notification of 830617 meeting w/util in Bethesda, MD to discuss NRC 830402 request for addl info re seismic reanalysis vertical response spectrum.
PAULSON, W A Operating Reactors Branch 5, 83/06/06, CRUTCHFIELD, D, Operating Reactors Branch 5, 3pp, 18740 056, 24X
Fiche 50-206, 83/06/06, 8306070049

8306130386 Forwards Amend 6 to Topical Rept SCE-1-A, "QA Program," & miscellaneous documents per Final Rule 10CFR50.54(a). Rept supercedes program described in FSAR, App D.
BASKIN, K P Southern California Edison Co, 83/06/09, MARTIN, J B, Region 5, Office of Director, 3pp, 18921 271, 24X
Fiche 50-206, 83/06/09, 8306130386

--8306130392 Amend 6 to Topical Rept SCE-1-A, "QA Program,"
* Southern California Edison Co, SCE-1-A A06, 83/04/30, 200pp, 18921 274, 24X Fiche 50-206, 83/06/09, 8306130386

8306140019 Submits description & basic premise for "Plan for Early Return to Power" & "Plan for Managing Plant Retrofit" & discusses implementation of each plan.
DIETCH, R Southern California Edison Co 83/06/10, DENTON, H R, Office of Nuclear Reactor Regulation, Director, 3pp, 18838 327, 24X Fiche 50-206, 83/06/10, 8306140019

8306130303 Responds to 830402 request for addl info re vertical ground response spectrum used for BEP Topic III-6, "Seismic Design Considerations." Addl info requirements & actions will be determined following meetings w/NRC.
BASKIN, K P Southern California Edison Co, 83/06/13 CRUTCHFIELD, D, Operating Reactors Branch 5, 1p, 18849 203, 24X
Fiche 50-206, 83/06/13, 8306130303

DOCKETED ITEMS

8306200156 Delineates activities associated w/continuation of work to resolve differences resulting from SEP Proposed corrective actions to resolve open items will be provided in last Quarter of 1983
BASKIN, K. P. Southern California Edison Co. 83/06/13.
CRUTCHFIELD, D. Operating Reactors Branch 5 1p. 18903 112. 24X
Fiche: 50-206, 83/06/13, 8306200156.

8306220004 Forwards replacement Page 2 for R Dietch 830610 ltr re util plans for continuation of work at facility. Replacement page supplied to clarify possible problems of interpretation due to typographical errors
KRIEGER, R. W. Southern California Edison Co. 83/06/16
CRUTCHFIELD, D. Operating Reactors Branch 5 2pp 18928 001. 24X
Fiche: 50-206, 83/06/16, 8306220004.

8306220095 Forwards plan for managing plant retrofit to assist in reducing capital expenditures & to improve capacity factor. NRR concurrence requested.
DIETCH, R. Southern California Edison Co. 83/06/17 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 26pp 18926 222. 24X
Fiche: 50-206, 83/06/17, 8306220095.

8306240203 Forwards "Reactor Coolant Pump Rotor Seizure/Shaft Break Accident Analysis," in response to 820210 request for addl info re SEP Topic XV-7, Environ consequence analysis unnecessary.
KRIEGER, R. W. Southern California Edison Co. 83/06/17.
CRUTCHFIELD, D. Operating Reactors Branch 5. 1p 18980, 250 24X
Fiche: 50-206, 83/06/17, 8306240203

--8306240208 "Reactor Coolant Pump Rotor Seizure/Shaft Break Accident Analysis."
ELLENBERGER, B. & BLACKBURN, T. A. Southern California Edison Co. 82/03/11. 12pp. 18980 251. 24X
Fiche: 50-206, 83/06/17, 8306240203.

8306240175 Summary of 830617 meeting w/util & TERA in Bethesda, MD re NRC 830402 request for addl info re vertical reanalysis response spectrum
PAULSON, W. A. Operating Reactors Branch 5. 83/06/22. Operating Reactors Branch 5. 4pp 18980:158. 24X
Fiche: 50-206, 83/06/22, 8306240175.

8306290415 Submits addl info re SEP Topic IX-5 Temp profile analysis for 4,160 & 480-volt rooms w/new ventilation sys to be provided prior to startup Addl dc switchgear & inverter room ventilation analysis forthcoming
BASKIN, K. P. Southern California Edison Co. 83/06/24.
CRUTCHFIELD, D. Operating Reactors Branch 5. 2pp. 19053:171. 24X
Fiche: 50-206, 83/06/24, 8306290415.

8306280466 Forwards response to 820303 request for info re as-built facility differing from licensing bases assumed in assessment of SEP Topic VI-4, "Containment Isolation Sys."
KRIEGER, R. W. Southern California Edison Co. 83/06/28.
CRUTCHFIELD, D. Operating Reactors Branch 5. 17pp 19018:246 24X
Fiche: 50-206, 83/06/28, 8306280466

Q Inspection reports, IE Bulletins & correspondence

8306160046 FOIA request, on behalf of EE Kent, for records prepared by US govt employees re Alliance for Survival, T Carpenter &/or ongoing NRC investigation of facilities.
CARPENTER, T. Orange County Alliance for Survival. 83/03/14
Office of Administration. 1p. 18893:031. 24X
Fiche: 50-206, 83/03/14, 8306160046.

8306100009 Addl response to FOIA request for documents dtd 820101 or after re BALP. Forwards App A documents Documents also available in PDR.
FELTON, J. M. Division of Rules and Records. 83/04/11. CLARK, R. San Francisco Examiner. 3pp. 18815:252 24X
Fiche: 50-000, 83/04/11, 8306100009

--8306100014 Submits schedule for BALP Board meetings for or. 82/03/19.
regulation, Director 1p. 5100009.

nators for Reactor
nators will be
board members
18 Minor encl.
82/03/24. Region
IX

8306160052 Responds to FOIA request for records prepared by US govt employees re Alliance for Survival, T Carpenter &/or ongoing NRC investigation of facilities Forwards App A documents Search for addl documents in progress
FELTON, J. M. Division of Rules and Records 83/04/14 CARPENTER, T. Orange County Alliance for Survival 2pp 18893 032 24X
Fiche 50-206, 83/04/14, 8306160052

8306160197 Responds to FOIA request for documents re FOIA Request 82-618. Forwards App A documents Documents 1B & 19(d) partially deleted (ref FOIA Exemption 6)
FELTON, J. M. Division of Rules and Records 83/04/25 GARDE, B. P. Government Accountability Project 4pp 18893 125 24X
Fiche 50-206, 83/04/25, 8306160197

--8306160200 Forwards FOIA request Releasability determinations indicated in response ltrs to requester No action required
FELTON, J. M. Division of Rules and Records 83/03/24 DIETCH, R. Southern California Edison Co 1p 18893 129 24X
Fiche 50-206, 83/04/25, 8306160197

--8306160200 Forwards FOIA request Releasability determinations indicated in response ltrs to requester No action required
FELTON, J. M. Division of Rules and Records 83/03/24 DIETCH, R. Southern California Edison Co. 1p 18893 129 24X
Fiche 50-206, 83/04/25, 8306160197

--8306160209 Requests disclosure determination for listed documents subj to FOIA Request 82-618
GRIMLEY, D. H. Division of Rules and Records 83/02/07
ALEXANDER, I. Region 5, Office of Director 2pp 18893 148 24X
Fiche 50-206, 83/04/25, 8306160197

--8306160218 Forwards documents re B Garde FOIA request, on behalf of EE Kent, for documents regarding 821120 IE rept "Special NRC Insp of San Onofre 1, 2 & 3 (FOIA-82-618)" w/o encl
FORTUNA, R. A. Office of Investigation 83/01/24 CARR, J. C. Division of Rules and Records 3pp 18893 150 24X
Fiche 50-206, 83/04/25, 8306160197

--8306160223 Request disclosure determination for document originated by ofc re FOIA Request 82-618 by noon on 830119
CARR, J. C. Division of Rules and Records 83/01/12 WILSON, V. Office of Nuclear Reactor Regulation, Director 2pp 18893 157 24X
Fiche 50-206, 83/04/25, 8306160197

--8306160230 Submits list of Region V Ofc of Investigation File Serials 26-42, "SDNQB-Allegations Re: Welding of Piping by EE Kent," Case 5-82-021 Serials 1-25 previously provided in response to FOIA Request 82-528
SHACKLETON, D. C. Office of Investigation 83/01/03 FORTUNA, R. A. Office of Investigation 3pp 18893:159 24X
Fiche 50-206, 83/04/25, 8306160197

--8306160243 Forwards list of documents available at Region V re B Garde FOIA Request 82-618 on EE Kent behalf, for documents concerning 821130 IE rept "Special NRC Insp of San Onofre 1, 2 & 3"
ALEXANDER, I. Region 5, Office of Director. 83/12/28 REED, C. A. Division of Rules and Records 3pp. 18893 162 24X
Fiche 50-206, 83/04/25, 8306160197

--8306160253 Forwards OC Shackleton 821109 memo transmitting documents subj to FOIA Request 82-528 Review of Documents 1, R, 10 & 19 by Region V recommended Confidentiality not sought by EE Kent
FORTUNA, R. A. Office of Investigation 82/12/10. CARR, J. C. Division of Rules and Records. 1p 18893:165. 24X
Fiche: 50-206, 83/04/25, 8306160197

--8306160263 Forwards list of documents responsive to FOIA Request 82-528 re EE Kent allegations concerning facilities from Oct 1980 to present. Region V not aware of allegation until Oct 1982
SHACKLETON, D. C. Region 5, Office of Director. 82/11/09 FORTUNA, R. A. Office of Investigation 3pp. 18893 166 24X
Fiche 50-206, 83/04/25, 8306160197

--8306160276 Requests info responsive to FOIA Request 82-528 for documents re EE Kent allegation concerning facilities from Oct 1980 to present be forwarded to Div of Rules & Records by 821116.
CARR, J. C. Division of Rules and Records 82/11/04 KIME, C. Director's Office, Office of Inspection and Enforcement
ALEXANDER, I. Region 5, Office of Director BOWERS, H. Office of Inspector & Auditor. 1p 18893:171. 24X
Fiche: 50-206, 83/04/25, 8306160197.

--8306160281 Forwards list of documents responsive to FOIA Request 82-528 re EE Kent allegations concerning facilities from Oct 1980 to present, per 821104 memo. Related info encl.
ENDELKEN, R. H. Region 5, Office of Director. 82/11/17. CARR, J. C. Division of Rules and Records 3pp. 18893, 174. 24X
Fiche: 50-206, 83/04/25, 8306160197.

DOCKETED ITEMS

25

--8306160301 Forwards FOIA Request 82-618 for documents re 821130 IE rept "Special NRC Insp of San Onofre 1,2 & 3 " Documents responsive to request should be forwarded to Div of Rules & Records by 830104
CARR, J C Division of Rules and Records 82/12/22 FORTUNA, R
Office of Inspector & Auditor ALEXANDER, I Region 5, Office of Director 1p 18893 195 24X Fiche 50-206, 83/04/25, 8306160177

8306160070 Addl response to FOIA request for records prepared by US govt employees re Alliance for Survival, T Carpenter &/or ongoing NRC investigation of facilities IE Insp Repts 50-206/82-31, 50-361/82-31 & 50-362/82-27 available in PDR
FELTON, J M Division of Rules and Records 83/04/28 CARPENTER, T
Orange County Alliance for Survival 2pp 18892 338 24X
Fiche 50-206, 83/04/28, 8306160070

8306070240 Forwards IE Insp Repts 50-206/83-13, 50-361/83-21 & 50-362/83-19 on 830401-29 No noncompliance noted
BISHOP, T W Region 5, Office of Director 83/05/13 PAPAY, L T
Southern California Edison Co 2pp 18746 047 24X
Fiche 50-206, 83/05/13, 8306070240

--8306070244 IE Insp Repts 50-206/83-13, 50-361/83-21 & 50-362/83-19 on 830401-29 No noncompliance noted Major areas inspected plant operations during long-term shutdown, monthly maint & surveillance activities & LERS
MILLER, L, KIRSCH, D F Region 5, Office of Director 83/05/12
8pp 18746 049 24X Fiche 50-206, 83/05/13, 8306070240

8306070333 Forwards IE Insp Repts 50-206/83-08, 50-361/83-17 & 50-362/83-20 on 830329-0406 No noncompliance noted
BODK, H E Region 5, Office of Director 83/05/13 PAPAY, L T
Southern California Edison Co 2pp 18741 077 24X
Fiche 50-206, 83/05/13, 8306070333

--8306070339 IE Insp Repts 50-206/83-08, 50-361/83-17 & 50-362/83-20 on 830329-0406 No noncompliance noted Major areas inspected lab QA program, including independent confirmatory measurements re Region V mobile lab
HAMADA, O H, TCMPL, O M, GARCIA, E Region 5, Office of Director 83/05/12 10pp 18741 079 24X Fiche 50-206, 83/05/13, 8306070339

8306070251 Forwards IE Insp Repts 50-206/83-10, 50-361/83-19 & 50-362/83-17 on 830411-27 & notice of violation
BISHOP, T W Region 5, Office of Director 83/05/16 PAPAY, L T
Southern California Edison Co 2pp, 18746, 088 24X
Fiche 50-206, 83/05/16, 8306070251

--8306070255 Notice of violation from insp on 830411-27
KIRSCH, D F, Region 5, Office of Director 83/05/16 2pp
18746 090 24X Fiche 50-206, 83/05/16, 8306070251

--8306070261 IE Insp Repts 50-206/83-10, 50-361/83-19 & 50-362/83-17 on 830411-27 Noncompliance noted Failure to install fully B-h emergency lighting units in access/egress routes
BODK, H E, KIRSCH, D F Region 5, Office of Director 83/05/11
11pp 18746 092 24X Fiche 50-206, 83/05/16, 8306070251

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 128pp 18831 043, 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 118pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306100111 Responds to IE Bulletin 83-03 re testing of check valves in diesel generator cooling water sys Four check valves will be included in inservice testing program, W/two oversize drawings Aperture cards are available in PDR
HAYNES, J O Southern California Edison Co 83/06/07, MARTIN, J B Region 5, Office of Director 3pp, 18801 259 24X
Fiche 50-206, 83/06/07, 8306100111

8306280076 Forwards IE Insp Rept 50-206/83-09 on 830323, No noncompliance noted.
NORDEHAG, L, Region 5, Office of Director 83/06/07, PAPAY, L T, Southern California Edison Co, 2pp, 19001, 168 24X
Fiche 50-206, 83/06/07, 8306280076,

--8306280081 IE Insp Rept 50-206/83-09 on 830323 No noncompliance noted Major areas inspected emergency plan exercise & associated critiques
KUNIHIRO, D M, SCHUSTER, M D Region 5, Office of Director 83/06/06 5pp 19001 170 24X Fiche 50-206, 83/06/07, 8306280076

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464,

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards, " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470,

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables, " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8306280477 Forwards IE Insp Rept 50-206/83-15 on 830502-31, No noncompliance noted
BISHOP, T W Region 5, Office of Director 83/06/14 PAPAY, L T Southern California Edison Co 2pp 19020 119 24X
Fiche 50-206, 83/06/14, 8306280477

--8306280480 IE Insp Rept 50-206/83-15 on 830502-31, No noncompliance noted Major areas inspected, plant operations during long-term shutdown, monthly maint & surveillance activities, LERS & previous insp items
MILLER, L, KIRSCH, D F Region 5, Office of Director, 83/06/14 6pp 19020 121 24X Fiche 50-206, 83/06/14, 8306280477,

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 115pp 19021 179, 24X Fiche 50-000, 83/06/22, 8305110475,

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions, " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Bettings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

R Periodic operating reports & related correspondence

8306160455 Monthly operating rept for Apr 1983, W/830513 ltr
SPEER, M., RAY, H B Southern California Edison Co 83/05/13, 6pp, 18863 088, 24X Fiche 50-206, 83/05/13, 8306160455,

U Congressional/Executive Correspondence

821160565 Forwards Community Energy Action Network 821018 ltr & Los Angeles Times article re potential problem w/welds at facilities
CRANSTON, A Senate 82/10/29 KRAMMERER, C Office of Congressional Affairs, 3pp 18893 056, 24X Fiche 50-206, 83/04/14, 8306160052

DOCKET 50-208 COLUMBIA UNIV RESEARCH REACTOR

G Inspection reports, IE Bulletins & correspondence

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc, 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010,

DOCKETED ITEMS

DOCKET 50-213 HADDAM NECK PLANT

F Security, medical, emergency & fire protection plans

8306160053 Rev 5 to Emergency Plan Implementing Procedure EPIP 1 5-B "Emergency Operations Facility (EOF), Emergency Radiological Surveys." CLOBIUS, O J. Connecticut Yankee Atomic Power Co 83/04/20 16pp. 18861, 284. 24X Fiche 50-213, 83/04/20, 8306160053

830610303 Forwards IE Insp Rept 50-213/83-11 on 830422-24 No noncompliance noted. MARTIN, T T Division of Engineering & Technical Programs 83/05/17 COUNCIL, W O Connecticut Yankee Atomic Power Co 2pp 18672 332 24X Fiche 50-213, 83/05/17, 830610303

830610306 IE Insp Rept 50-213/83-11 on 830422-24 No noncompliance noted Major areas inspected licensee annual emergency full-scale exercise performed on 830423 SMITH, R H Region 1, Office of Director CROCKER, H W Division of Engineering & Technical Programs 83/05/12 6pp 18672, 334 24X Fiche 50-213, 83/05/17, 830610303

8306150334 Releases public version of revised emergency plan implementing procedures FELTON, J M Division of Rules and Records. 83/06/06. Document Management Branch 1p 18868 280 24X Fiche 50-213, 83/06/06, 8306150334

8306150338 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP 1 5-10 re offsite emergency radiological surveys, EPIP 1 5-20 re reentry & recovery & EPIP 1 5-30 re chemistry technician. COUNCIL, W O Connecticut Yankee Atomic Power Co 83/04/22 EISENHUT, D O Division of Licensing. 1p 18868 281. 24X Fiche 50-213, 83/06/06, 8306150338

8306150341 Public version of revised emergency plan implementing procedures, including Procedures EPIP 1 5-10 re offsite emergency radiological surveys, EPIP 1 5-20 re reentry & recovery & EPIP 1 5-30 re chemistry technician. * Connecticut Yankee Atomic Power Co 83/04/08 EISENHUT, D O Division of Licensing. 6pp 18868 282. 24X Fiche 50-213, 83/06/06, 8306150341

8306230092 Releases public version of revised emergency plan implementing procedures. FELTON, J M Division of Rules and Records. 83/06/06 Document Management Branch 1p. 18931:135. 24X Fiche 50-213, 83/06/06, 8306230092

8306230100 Forwards emergency plan implementing procedures, including Procedures EPIP 1 5-4 re alert, EPIP 1 5-5 re site area emergency & EPIP 1 5-6 re general emergency. COUNCIL, W O Connecticut Yankee Atomic Power Co. 83/05/09 Division of Licensing. 2p 18931, 136. 24X Fiche 50-213, 83/06/06, 8306230092

8306230102 Public version of revised emergency plan implementing procedures, including Procedures EPIP 1 5-4 re alert, EPIP 1 5-5 re site area emergency & EPIP 1 5-6 re general emergency. * Connecticut Yankee Atomic Power Co. 83/04/20. 177pp. 18931:138 24X Fiche 50-213, 83/06/06, 8306230092

8306230426 Forwards safeguards contingency plan, Plan withheld. COUNCIL, W O Connecticut Yankee Atomic Power Co. 83/06/08 Office of Nuclear Reactor Regulation, Director 2pp. 18943, 209 24X Fiche 50-213, 83/06/08, 8306230426

8306280204 Forwards IE Insp Rept 50-213/83-10 on 830411-15 & 19-21. No noncompliance noted. MARTIN, T T Division of Engineering & Technical Programs. 83/06/13. COUNCIL, W O Connecticut Yankee Atomic Power Co. 2pp. 19014:166 24X Fiche 50-213, 83/06/13, 8306280204

8306280210 IE Insp Rept 50-213/83-10 on 830411-15 & 19-21. No noncompliance noted, Major areas inspected; follow up of emergency preparedness items from prior appraisal performed 81107-20 detailed in IE Insp Rept 50-213/81-14. SMITH, R H, CROCKER, H W Region 1, Office of Director. 83/06/09. 10pp 19014:168. 24X Fiche 50-213, 83/06/13, 8306280204

H General correspondence

8306060090 Requests rev to "cc" distribution list for NRR correspondence reflecting position & title changes within utility COUNCIL, W O Connecticut Yankee Atomic Power Co COUNCIL, W O Northeast Utilities COUNCIL, W O Northeast Nuclear Energy Co. (subs of Northeast Utilities) 83/05/31 CLARK, R A Operating Reactors Branch 3 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 18719 360 24X Fiche 50-000, 83/05/31, 8306060090

O Advisory Committee on Reactor Safeguards reports & correspondence

8306200153 Minutes of ACRS Subcommittee on SEP on Haddam Neck Nuclear Plant 830407 meeting in Washington, DC re integrated plant safety assessment Proposed agenda & attendance list encl * ACRS - Advisory Committee on Reactor Safeguards 83/05/14 ACRS - Advisory Committee on Reactor Safeguards 14pp 18909 150. 24X Fiche 50-213, 83/05/14, 8306200153

8306020095 Discusses ACRS 277th meeting on 830512-14 re results of Phase II of SEP as applied to Facility Issue re protection against extreme external events requires resolution EBERSOLE, J C ACRS - Advisory Committee on Reactor Safeguards 83/05/17 PALLADINO, N J Commissioners 3pp 18701:283 24X Fiche 50-213, 83/05/17, 8306020095

8306150490 Advises that NRC will revise draft integrated plant SAR reflecting addl info provided by licensee, responding to recommendations & comments made by NRC consultants & incorporating licensee scheduler commitments DIRCKB, W J Office of the Executive Director for Operations 83/06/08 EBERSOLE, J C ACRS - Advisory Committee on Reactor Safeguards 4pp 18954 158. 24X Fiche 50-213, 83/06/08, 8306150490

8306010208 Summarizes ACRS 277th meeting on 830512-14 re SEP review of plant Several issues re protection against extreme external events unresolved EBERSOLE, J C ACRS - Advisory Committee on Reactor Safeguards 83/05/17 PALLADINO, N J, Commissioners 3pp 18854 161 24X Fiche 50-213, 83/06/08, 8306150490

P. Operating license stage documents & correspondence

8306010340 Forwards Rev 13 to corporate organization for nuclear incidents procedures manual table of contents & Rev 3 to CONI A 02, "On-Call Manager of Radiological Consequence Assessment, Responsibilities & General Guidelines" W/O encl COUNCIL, W O, BEARS, C F Connecticut Yankee Atomic Power Co. COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities). 83/05/18 EISENHUT, D O Division of Licensing 1p 18682, 271. 24X Fiche 50-000, 83/05/18, 8306010340

8306060243 Forwards "Environ Qualification of Safety-Related Electrical Equipment," per 10CFR50.49 info responds to 821213 SER items re identification of equipment & preventive maint programs & 830404 ltr COUNCIL, W O, BEARS, C F Connecticut Yankee Atomic Power Co 83/05/20 EISENHUT, D O Division of Licensing 86pp 18718 045 24X Fiche 50-213, 83/05/20, 8306060243

8306060207 Notifies that Apr 1983 rept, "Shaking-Table Testing for Seismic Evaluation of Electrical Raceway Sys," applicable to facilities for SEP Topic III-6 re seismic design NUREG-0824 & NUREG-0826 commitments partially satisfied. COUNCIL, W O Northeast Nuclear Energy Co (subs. of Northeast Utilities) COUNCIL, W O Connecticut Yankee Atomic Power Co. COUNCIL, W O Northeast Utilities. 83/05/26 CRUTCHFIELD, D Operating Reactors Branch 5. 1p 18727 295 24X Fiche 50-000, 83/05/26, 8306060207

8306100114 Forwards listing of scheduled completion dates for SEP integrated assessment open issues requiring addl action by util. Each issue resolution documented in draft NUREG-0826 Topic VI-7 C.1 resolution outlined COUNCIL, W O Connecticut Yankee Atomic Power Co. 83/06/02, CRUTCHFIELD, D Operating Reactors Branch 5. 15pp 18802, 186 24X Fiche 50-213, 83/06/02, 8306100114

8306170231 Confirms applicability of Rev 2 to Westinghouse WCAP-9558, "Mechanistic Fracture Evaluation of Reactor Coolant Pipe Containing Postulated Circumferential Through Wall Crack" Results still valid since loads below values used in rept COUNCIL, W O Connecticut Yankee Atomic Power Co. 83/06/08, CRUTCHFIELD, D Operating Reactors Branch 5. 1p 18882:325. 24X Fiche 50-213, 83/06/08, 8306170231

8306160412 Forwards draft Rev 5 to "QA Program Topical Rept" COUNCIL, W O Northeast Utilities Service Co. COUNCIL, W O Northeast Utilities 83/06/09. MURLEY, T E Region 1, Office of Director. 6pp. 18859 090. 24X Fiche 50-000, 83/06/09, 8306160412

DOCKETED ITEMS

27

--8306160424 Draft Rev 5 to "QA Program Topical Rept"
* Northeast Utilities 83/06/09 135pp 18859.096 24X
Fiche 50-000,83/06/09,8306160412

8306240200 Forwards listed revs to Corporate Organization for Nuclear
Incidents procedure manual, per Section V of App E to
LOCFR50, W/o encl
COUNCIL, W Q Connecticut Yankee Atomic Power Co COUNCIL, W Q
Northeast Nuclear Energy Co (subs of Northeast Utilities)
COUNCIL, W Q Northeast Utilities 83/06/17 EISENHUT, D Q
Division of Licensing 2pp 18980 263 24X Fiche 50-000,83/06/17,
8306240200

8306270318 Notification of 830707 meeting w/utiles in Bethesda, MD to
discuss NULAP-5 & FRAPCON-2 computer programs used in
licensee small break LOCA analyses
ERICKSON, P Operating Reactors Branch 5 83/06/24, CRUTCHFIELD, D
Operating Reactors Branch 5 2pp 18994 039 24X
Fiche 50-213,83/06/24,8306270318

G Inspection reports, IE Bulletins & correspondence

8306010303 Forwards IE Insp Rept 50-213/83-11 on 830422-24 No
noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/05/17
COUNCIL, W Q Connecticut Yankee Atomic Power Co. 2pp 18672 332
24X Fiche: 50-213,83/05/17,8306010303

--8306010306 IE Insp Rept 50-213/83-11 on 830422-24 No noncompliance
noted Major areas inspected licensee annual emergency
full-scale exercise performed on 830423
SMITH, R H Region 1, Office of Director CROCKER, H W, Division
of Engineering & Technical Programs 83/05/12 6pp 18672 334
24X Fiche 50-213,83/05/17,8306010303

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in
Well Logging Device" Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post
830103) 83/05/26 Consolidated Edison Co. of New York, Inc
125pp 18831 043 24X Fiche 50-000,83/05/26,8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet,"
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co. of New
York, Inc 115pp, 18732 085 24X Fiche 50-000,83/05/26,8305110460.

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods
Withdrawn at DWRs" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/31 Consolidated Edison Co. of New
York, Inc 116pp 18732 208 24X Fiche: 50-000,83/05/31,8305110461

8306170391 Responds to IE Bulletin 83-03, "Check Valve Failures in Raw
Water Cooling Bys of Diesel Generators" No check valves
installed in loop of piping to diesel generators from svc
water piping.
COUNCIL, W Q Northeast Nuclear Energy Co (subs of Northeast
Utilities), COUNCIL, W Q Connecticut Yankee Atomic Power Co.
COUNCIL, W Q Northeast Utilities 83/05/31 MURLEY, T E Region 1,
Office of Director 3pp, 18880,240, 24X Fiche: 50-000,83/05/31,
8306170391.

8306210098 Forwards IE Insp Rept 50-213/83-14 on 830509-13, No
noncompliance noted.
MARTIN, T T Division of Engineering & Technical Programs 83/06/07,
COUNCIL, W Q Connecticut Yankee Atomic Power Co 2pp, 18914 140
24X Fiche: 50-213,83/06/07,8306210098

--8306210103 IE Insp Rept 50-213/83-14 on 830509-13, No noncompliance
noted, Major areas inspected post-refueling startup testing
including control rod drop times, critical boron
concentration, control rod worth & boron worth.
PETRONI, C D, BETTENHAUSEN, L, Region 1, Office of Director,
83/06/02, 8pp, 18914:142, 24X Fiche 50-213,83/06/07,8306210098.

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe
Operations" Svc list encl,
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103), 83/06/09, Consolidated Edison Co. of New
York, Inc 119pp, 18830:280, 24X Fiche, 50-000,83/06/09,8305110464.

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive &
Seismically Induced Chatter in Relays Within Printed
Circuit Cards," Svc list encl,
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13, Consolidated Edison Co. of New
York, Inc, 118pp, 18920:225, 24X Fiche: 50-000,83/06/13,8305110470.

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From
Degraded Internal Connection Cables," Svc list encl,
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co. of New
York, Inc, 243pp 18921 001 24X Fiche: 50-000,83/06/13,8306090010

8306280204 Forwards IE Insp Rept 50-213/83-10 on 830411-15 & 19-21 No
noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/06/13
COUNCIL, W Q Connecticut Yankee Atomic Power Co. 2pp 19014:166,
24X Fiche 50-213,83/06/13,8306280204

--8306280210 IE Insp Rept 50-213/83-10 on 830411-15 & 19-21 No
noncompliance noted Major areas inspected, follow up of
emergency preparedness items from prior appraisal performed
81109-20 detailed in IE Insp Rept 50-213/81-14
SMITH, R H, CROCKER, H W Region 1, Office of Director, 83/06/09,
10pp 19014 168, 24X Fiche: 50-213,83/06/13,8306280204.

8306200387 Ack receipt of 830408 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-213/83-03, Rev 4
to 830324 Surveillance Procedure BUR 5 1-104 satisfies Tech
Spec 4.2, Notice of violation withdrawn.
MARTIN, T T Division of Engineering & Technical Programs, 83/06/15,
COUNCIL, W Q, Connecticut Yankee Atomic Power Co 2pp, 18899:047,
24X Fiche, 50-213,83/06/15,8306200387.

--8306200391 Responds to NRC 830309 ltr re violations noted in IE Insp
Rept 50-213/83-03 Surveillance Procedure BUR 5 1-104 meets
intent of Tech Spec 4.2, Table 4.2-2 re min equipment checks.
No violation exists.
COUNCIL, W Q Connecticut Yankee Atomic Power Co, 83/04/08
MARTIN, T T Division of Engineering & Technical Programs, 3pp,
18899,049, 24X Fiche, 50-213,83/06/15,8306200387

8306270001 Forwards "Connecticut Yankee 1983 Outage Inservice Insp
Rept."
GRAVES, R H Connecticut Yankee Atomic Power Co 83/06/17,
ALLAN, J M Region 1, Office of Director, 1p, 18988:160 24X
Fiche 50-213,83/06/17,8306270001

--8306270004 "Connecticut Yankee 1983 Outage Inservice Insp Rept,"
DELAWARE, J L Connecticut Yankee Atomic Power Co, 83/06/17,
83pp, 18988:161 24X Fiche: 50-213,83/06/17,8306270001.

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
Epoxy Grouts & Sealers," Svc list encl,
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co. of New
York, Inc 119pp, 19021:179, 24X Fiche: 50-000,83/06/22,8305110475.

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Bys
Causing Inoperability of Safety-Related Equipment" Svc list
encl
JORDAN, E L, Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22, Consolidated Edison Co. of New
York, Inc, 120pp 18997:007, 24X Fiche: 50-000,83/06/22,8305110477.

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions,"
Svc list encl
JORDAN, E L, Division of Emergency Preparedness & Engineering
Response (Post 830103), 83/06/23, Consolidated Edison Co. of New
York, Inc 116pp, 18996:242, 24X Fiche: 50-000,83/06/23,8305110479.

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate
Range (IR) High Flux Trip Setpoints," Svc list encl
JORDAN, E L, Division of Emergency Preparedness & Engineering
Response (Post 830103), 83/06/24, Consolidated Edison Co. of New
York, Inc, 116pp, 19046:297, 24X Fiche: 50-000,83/06/24,8305110483.

R. Periodic operating reports & related correspondence

8306020268 Monthly operating rept for Mar 1983, W/830514 ltr.
ELMS, A, GRAVES, R H, Connecticut Yankee Atomic Power Co, 83/04/14,
11pp, 18690:279, 24X Fiche: 50-213,83/04/14,8306020268.

8306160459 Monthly Operating Rept 83-4 for Apr 1983, W/830514 ltr.
ELMS, A, GRAVES, R H, Connecticut Yankee Atomic Power Co, 83/04/30,
Office of Resource Management, Director, 10pp, 18863:058, 24X
Fiche: 50-213,83/04/30,8306160459

S Reportable occurrences, LERs & related correspondence

8306170051 LER 83-011/03L-0 on 830504, during surveillance testing, HPB1
pump A failed to reach shutoff head of 1,400 psi, per
Procedure BUR 5.1-4 Caused by incorrect acceptance criteria.
Procedure revised, W/830531 ltr.
CLOBIUS, O J, GRAVES, R H, Connecticut Yankee Atomic Power Co,
83/05/31, ALLAN, J M, Region 1, Office of Director, 3pp,
18878:298, 24X Fiche: 50-213,83/05/31,8306170051.

DOCKETED ITEMS

8306170301 LER 83-010/03L-O on 830507, following svc water low flow alarm, svc water filters indicated 0 psi Caused by Filter B plugging up w/river silt due to rain & high river conditions. Filter A cleaned W/830531 ltr.
CLOBIUS, G J., GRAVES, R M Connecticut Yankee Atomic Power Co
83/05/31 ALLAN, J M Region 1, Office of Director 3pp
18878 194 24X Fiche 50-213, 83/05/31, 8306170301

8306170347 LER 83-009/03L-O on 830505, charging pump A could not be manually rotated for routine surveillance test Caused by binding due to solidified boric acid. Pump uncoupled from motor & turned over. W/830531 ltr.
CLOBIUS, G J., GRAVES, R M Connecticut Yankee Atomic Power Co
83/05/31 ALLAN, J M Region 1, Office of Director 3pp
18881 022 24X Fiche 50-213, 83/05/31, 8306170347

8306270361 LER 83-012/03L-O on 830517, following removal of diesel generator EG2A for normal preventative maint. generator load unable to increase above 2,800 kW. Caused by diesel generator governor voltage setting drift W/830614 ltr.
CLOBIUS, G J., GRAVES, R M Connecticut Yankee Atomic Power Co 83/06/14.
ALLAN, J M Region 1, Office of Director 2pp 18993 186 24X
Fiche 50-213, 83/06/14, 8306270361

8306270228 Part 21 rept re improper latching between control rod drive shafts & control rod cluster assemblies in reactor vessel Initially reported on 830620 Insp underway
COUNSILL, M G Northeast Nuclear Energy Co (subs of Northeast Utilities), 83/06/22 DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 2pp 18988 237, 24X
Fiche 50-213, 83/06/22, 8306270228

V Operator Examinations

8306140104 Extends invitation to attend 830627 meeting in King of Prussia, PA to discuss transfer of reactor operator licensing function from Bethesda, MD to Region 1 of STARDSTECH, R Division of Project & Resident Programs, 83/06/09.
COUNSILL, M G Connecticut Yankee Atomic Power Co 2pp 18839 080, 24X Fiche 50-213, 83/06/09, 8306140104

DOCKET 50-219 OYSTER CREEK NUCLEAR POWER PLANT

F Security, medical, emergency & fire protection plans

8306200340 Forwards draft objectives for annual NRC/FEMA observed exercise to be conducted on 830624 Exercise will address deficiencies identified in 830316 exercise & will test integrated capability for emergency response
FIEDLER, P B General Public Utilities - GPU Service Corp. 83/02/14
MARTIN, T T Division of Engineering & Technical Programs 7pp.
18900 201 24X Fiche 50-219, 83/02/14, 8306200340

8306040217 Forwards IE Insp Rept 50-219/83-11 on 830405-0502 No noncompliance noted
STARDSTECH, R Division of Project & Resident Programs 83/05/23
FIEDLER, P B General Public Utilities - GPU Service Corp 2pp.
18732, 335 24X Fiche 50-219, 83/05/23, 8306040217.

--8306040220 IE Insp Rept 50-219/83-11 on 830405-0502 No noncompliance noted Major areas inspected: followup of previous insp findings, review of plant operations, log & record review, plant tours, physical security & radiation protection
COWILL, C J THOMAS, J., REINHOLD, R R Region 1, Office of Director, 83/05/17 9pp, 18732, 337, 24X Fiche 50-219, 83/05/23, 8306040217.

8306090041 Forwards IE Enforcement Conference Rept 50-219/83-12 on 830418 Meeting approved until understanding of NRC concerns re violations noted in IE Insp Rept 50-219/83-07
ALLAN, J M Region 1, Office of Director, 83/05/26 FIEDLER, P B General Public Utilities - GPU Service Corp 2pp, 18793 280, 24X
Fiche 50-219, 83/05/26, 8306090041.

--8306090044 IE Enforcement Conference Rept 50-219/83-12 on 830418 Major areas discussed: NRC concerns re recent insp findings concerning licensee implementation & reg of physical security program, Safeguards info deleted (ref 10CFR73.21)
BAILLEY, R J., GDDY, A T Region 1, Office of Director, 83/05/18, 3pp 18793 282, 24X Fiche 50-219, 83/05/26, 8306090041.

8306210145 Discusses IE insp on 830314-17 & forwards notice of violation & proposed imposition of civil penalty. Violation involves failure to control access to protected area from outside protected area
ALLAN, J M Region 1, Office of Director, 83/06/01, FIEDLER, P B, General Public Utilities - GPU Service Corp. 3pp, 18914:197, 24X
Fiche 50-219, 83/06/01, 8306210145

--8306210149 Notice of violation & proposed imposition of civil penalty in amount of \$40,000 Noncompliance noted degradation of portions of protected area barrier Safeguards info deleted (ref 10CFR73.21)
ALLAN, J M Region 1, Office of Director 83/06/01 4pp
18914 200 24X Fiche 50-219, 83/06/01, 8306210145

8306090024 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/06/06 Document
Management Branch 1p 18797 114 24X Fiche 50-219, 83/06/06, 8306090024.

--8306090027 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP-5 re general emergency, EPIP-1 re classification of emergency conditions & EPIP-3 re alert
FIEDLER, P B General Public Utilities - GPU Service Corp 83/05/17
Region 1, Office of Director 1p 18797 115, 24X
Fiche 50-219, 83/06/06, 8306090024

--8306090031 Public version of revised emergency plan implementing procedures, including Procedures EPIP-5 re general emergency, EPIP-1 re classification of emergency conditions & EPIP-3 re alert
General Public Utilities - GPU Service Corp 83/05/09 832pp
18797 116 24X Fiche 50-219, 83/06/06, 8306090024

8306170204 Ack receipt of operational QA plan for TH1-1 & Oyster Creek under review by QA Branch, per 10CFR50.54, Future revs/changes to program will be reviewed by Engineering Programs Branch, Region 1
MARTIN, T T Division of Engineering & Technical Programs 83/06/13
HUKILL, H D General Public Utilities - GPU Service Corp 2pp
18882, 304 24X Fiche 50-000, 83/06/13, 8306170204

H General correspondence

8306150174 Responds to 830323 ltr addressed to WJ Dircks & forwards "Priority Concerns of Licensed Nuclear Operators at TH1 & Oyster Creek & Suggested Action Steps" & "Review of Current & Projected Expenditures & Manpower Utilization for GPU"
CUNNINGHAM, G H Office of the Executive Legal Director 83/06/13
LEWIS, M I Lewis, M 2pp 18851 001 24X Fiche 50-000, 83/06/13, 8306150174

--8306150179 "Priority Concerns of Licensed Nuclear Operators at TH1 & Oyster Creek & Suggested Action Steps," final rept
D'ARCY, P F., BAUER, J R Affiliation Unknown 83/03/15, 56pp.
18851, 003 24X Fiche 50-000, 83/06/13, 8306150174

--8306150185 "Review of Current & Projected Expenditures & Manpower Utilization for GPU Nuclear Corp"
Basic Energy Technology Associates 83/02/28 161pp
18851, 059 24X Fiche 50-000, 83/06/13, 8306150174

I. Financial information

8305020461 Forwards Annual Financial Rept 1982
FIEDLER, P B General Public Utilities - GPU Service Corp 83/04/27
Office of Nuclear Reactor Regulation, Director 1p 18281, 071
24X Fiche 50-219, 83/04/27, 8305020461

P. Operating license stage documents & correspondence

8306010404 Forwards operational QA plan for TH1-1 & Oyster Creek Nuclear Stations, per 10CFR50.54(a)(2), W/o and
HUKILL, H D General Public Utilities - GPU Service Corp 83/05/23
Region 1, Office of Director 1p, 18679:314 24X
Fiche 50-000, 83/05/23, 8306010404.

8306140642 Forwards evaluation of BWR Owners Group generic response to NUREG-0737, Item II K 3.18, "Automatic Depressurization Sys Logic Mode." Two of seven BWR Owners Group alternatives acceptable Selection of option within 45 days requested
CRUTCHFIELD, D Operating Reactors Branch 5 83/06/03 FIEDLER, P B General Public Utilities - GPU Service Corp 2pp, 18833 264 24X
Fiche 50-219, 83/06/03, 8306140642

8306130384 Submits findings re integrated assessment of SEP Topic III, 3.C, "Flooding Potential & Protection Requirements"
Bill & entry floor elevations not susceptible to flooding
FIEDLER, P B General Public Utilities - GPU Service Corp. 83/06/06
CRUTCHFIELD, D, Operating Reactors Branch 5, 2pp 18822 342 24X
Fiche 50-219, 83/06/06, 8306130384.

8306200157 Advises that 821210 Tech Spec Change Request 100 for snubber surveillance not fee exempt. Remittance requested
D'OGG, R M License Fee Management Branch 83/06/13, FIEDLER, P B General Public Utilities - GPU Service Corp. 1p 18908 270 24X
Fiche 50-219, 83/06/13, 8306200157

DOCKETED ITEMS

29

8306280406 Estimates that dilution pump sys renovation program will be completed by Nov 1983 based on anticipated receipt date of diffusers & required installation time
FIEDLER, P B General Public Utilities - GPU Service Corp 83/06/15
ORIER, B H Region 1, Office of Director 2pp 19014 057 24X
Fiche 50-219, 83/06/15, 8306280406

8306210158 Forwards order confirming commitment to implement post-TMI-related items II B 3, "Post-Accident Sampling" & II E 4 2 7, "Isolate Purge & Vent Valves on Radiation Signal"
CRUTCHFIELD, D Operating Reactors Branch 5 83/06/17 FIEDLER, P B
General Public Utilities - GPU Service Corp 3pp 18916 352 24X
Fiche 50-219, 83/06/17, 8306210158

--8306210166 Order confirming licensee commitments on post-TMI-related items II B 3, "Post Accident Sampling" & II E 4 2, "Isolate Purge & Vent Valves on Radiation Signal"
EISENHUT, D G Division of Licensing 83/06/17 General Public Utilities - GPU Service Corp 6pp 18916 355 24X
Fiche 50-219, 83/06/17, 8306210158

8306220074 Forwards safety evaluation & technical evaluation rept re util response to 801222 generic ltr, "Control of Heavy Loads" Guidelines in NUREG-0612 satisfied & Phase acceptable
CRUTCHFIELD, D Operating Reactors Branch 5 83/06/21 FIEDLER, P B
General Public Utilities - GPU Service Corp 2pp 18926 060 24X
Fiche 50-219, 83/06/21, 8306220074

--8306220083 Safety evaluation re util response to Generic Technical Issue A-36, "Control of Heavy Loads" NUREG-0612 guidelines satisfied Phase 1 acceptable
* Office of Nuclear Reactor Regulation, Director 83/06/21 2pp
18926 062 24X Fiche 50-219, 83/06/21, 8306220074

--8306140424 "Control of Heavy Loads (C-10), JCP&L Oyster Creek Nuclear Power Plant," technical evaluation rept
BOMBERGER, C Franklin Institute/Franklin Research Center
NRC-03-81-130 TER-C5806-377 83/06/10 BINGH, A NRC - No Detailed Affiliation Given 32pp 18926 064 24X
Fiche 50-219, 83/06/21, 8306220074

8306240254 Advises that proposed schedule & interim resolution re monitoring & annunciation of dc power sys acceptable, Verification of interim resolution & long-term mod will be referred to IE Description of battery integrity requested
CRUTCHFIELD, D Operating Reactors Branch 5 83/06/22 FIEDLER, P B
General Public Utilities - GPU Service Corp 4pp 18981 319 24X
Fiche 50-219, 83/06/22, 8306240254

8306280155 Informs that 830606 response to open item in integrated plant BAR (NUREG-0822) re flooding elevation acceptably resolves item Corrective actions re diesel generator bldg entrances also acceptable.
CRUTCHFIELD, D Operating Reactors Branch 5 83/06/23 FIEDLER, P B
General Public Utilities - GPU Service Corp 2pp 19014 316 24X
Fiche 50-219, 83/06/23, 8306280155

8306280176 Forwards order confirming 811224 commitment to install permanent scram discharge sys mods prior to operation in Cycle 10 Proposed model Tech Specs also encl
CRUTCHFIELD, D Operating Reactors Branch 5 83/06/24 FIEDLER, P B
General Public Utilities - GPU Service Corp. 2pp 19014 239 24X
Fiche 50-219, 83/06/24, 8306280176

--8306280181 Order confirming util 811224 commitments to install long-term BWR scram discharge sys mods in conformance w/NRC generic SER before operation in Cycle 10
EISENHUT, D Division of Licensing 83/06/24 General Public Utilities - GPU Service Corp 33pp 19014 241 24X
Fiche 50-219, 83/06/24, 8306280176

8306290538 Requests methodology & acceptance criteria to be used in evaluating anchorage of 4,160-volt switchgear panels by 831130. Review will be included in integrated plant BAR suppl
CRUTCHFIELD, D Operating Reactors Branch 5, 83/06/24, FIEDLER, P B
General Public Utilities - GPU Service Corp 2pp 19053 029 24X
Fiche 50-219, 83/06/24, 8306290538

G. Inspection reports, IE Bulletins & correspondence

8306210450 Ack receipt of 830322 payment of civil penalties imposed by 830215 order Corrective actions described in 821230 correspondence will be examined during future insps
AXELRAD, J A Enforcement Staff, 83/03/24 FIEDLER, P B General Public Utilities - GPU Service Corp 2pp 18938 343 24X
Fiche 50-219, 83/03/24, 8306210450

8306020445 Forwards IE Insp Rept 50-219/83-10 on 830406-08 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/05/20
FIEDLER, P B General Public Utilities - GPU Service Corp 2pp
18694 080 24X Fiche 50-219, 83/05/20, 8306020445

--8306020447 IE Insp Rept 50-219/83-10 on 830406-08 No noncompliance noted Major areas inspected implementation of radiation protection program during outage, including procedure implementation & exposure control
WHITE, J R, MCBRIDE, M H, SHANBAKY, M M Region 1, Office of Director 83/05/13 6pp 18694 082 24X Fiche 50-219, 83/05/20, 8306020445

8306060217 Forwards IE Insp Rept 50-219/83-11 on 830405-0502 No noncompliance noted
STARDSTECKI, R Division of Project & Resident Programs 83/05/23
FIEDLER, P B General Public Utilities - GPU Service Corp 2pp
18732 335 24X Fiche 50-219, 83/05/23, 8306060217.

--8306060220 IE Insp Rept 50-219/83-11 on 830405-0502 No noncompliance noted Major areas inspected, followup of previous insp findings, review of plant operations, log & record review, plant tours, physical security & radiation protection
COWGILL, C, THOMAS, J, KEIMIG, R R Region 1, Office of Director 83/05/17 9pp 18732 337 24X Fiche 50-219, 83/05/23, 8306060217

8306020341 Forwards supplemental response to IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter Stainless Steel Recirculation Piping at BWR Plants"
FIEDLER, P B General Public Utilities - GPU Service Corp. 83/05/25, Region 1, Office of Director 29pp 18694 291 24X
Fiche 50-219, 83/05/25, 8306020341

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl.
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc. 12pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458.

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet," Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 11pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460.

8306010066 EN-83-037 on 830601, notice of violation & proposed imposition of civil penalty in amount of \$40,000 to be issued. Action based on failure to control access into protected area & to properly handle intrusion alarms.
ROBANO, R, AXELRAD, J Director's Office, Office of Inspection and Enforcement 83/05/26 1p 18674 088 24X Fiche 50-219, 83/05/26, 8306010066

8306090041 Forwards IE Enforcement Conference Rept 50-219/83-12 on 830418, Meeting improved util understanding of NRC concerns re violations noted in IE Insp Rept 50-219/83-07
ALLAN, J M Region 1, Office of Director 83/05/26 FIEDLER, P B General Public Utilities - GPU Service Corp 2pp 18993 280 24X
Fiche 50-219, 83/05/26, 8306090041

--8306090044 IE Enforcement Conference Rept 50-219/83-12 on 830418, Major areas discussed, NRC concerns re recent insp findings concerning licensee implementation & mgt of physical security program Safeguards info deleted (ref 10CFR 73.21).
BAILEY, R J, GODY, A T Region 1, Office of Director. 83/05/18, 3pp 18793 282 24X Fiche 50-219, 83/05/26, 8306090041.

8306210085 Responds to IE Bulletin 83-03 re check valve failures in raw water cooling sys of diesel generators No check valves in closed loop diesel engine cooling sys for either diesel generator at plant, Bulletin not applicable.
FIEDLER, P B General Public Utilities - GPU Service Corp 83/05/27, Region 1, Office of Director. 2pp 18914 126 24X
Fiche 50-219, 83/05/27, 8306210085.

8305110461 IE Info Notice 83-35, "Fuel Movement w/Control Rods Withdrawn at BWRs," Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc. 11pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461.

8306210145 Discusses IE insp on 830314-17 & forwards notice of violation & proposed imposition of civil penalty. Violation involves failure to control access to protected area from outside protected area
ALLAN, J M Region 1, Office of Director 83/06/01 FIEDLER, P B General Public Utilities - GPU Service Corp. 3pp 18914 197 24X
Fiche 50-219, 83/06/01, 8306210145

DOCKETED ITEMS

--8306210149 Notice of violation & proposed imposition of civil penalty in amount of \$40,000 Noncompliance noted degradation of portions of protected area barrier Safeguards info deleted (ref 10CFR73.21)
ALLAN, J. M. Region 1, Office of Director 83/06/01 App
18914, 200 24X Fiche 50-219, 83/06/01, 8306210145

8306090320 Forwards request for addl info re IE Bulletin 80-11, "Masonry Wall Design" Info requested within 30 days of ltr receipt
CRUTCHFIELD, D. Operating Reactors Branch 5 83/06/08 FIEDLER, P. B. General Public Utilities - GPU Service Corp 5pp 18793 170 24X
Fiche 50-219, 83/06/08, 8306090320

8306160250 Ack receipt of 830506 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-219/83-04
STAROSTECKI, R. Division of Project & Resident Programs 83/06/08 FIEDLER, P. B. General Public Utilities - GPU Service Corp 2pp
18861 252 24X Fiche 50-219, 83/06/08, 8306160250

--8306160258 Response to NRC 830406 ltr re violations noted in IE Insp Rept 50-219/83-04 Corrective actions, addl authorized escort provided for visitor & watchman re-instructed on proper package search techniques
FIEDLER, P. B. General Public Utilities - GPU Service Corp 83/05/05 STAROSTECKI, R. Division of Project & Resident Programs 4pp 18861 254 24X Fiche 50-219, 83/06/08, 8306160250

8305110444 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110444.

8305110470 IE Info Notice 83-30, "Defective Heat Sink Adhesive & Schematically Induced Chatter in Relays Within Printed Circuit Cards" Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8305110475 IE Info Notice 83-40, "Need to Environmentally Quality Epoxy Grouts & Sealers" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 119pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment" Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 120pp 18997-007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co. of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479.

8305110482 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

R. Periodic operating reports & related correspondence

8306020090 Monthly operating rept for Mar 1983 W/830418 ltr
FIEDLER, P. B., BARAN, R. General Public Utilities - GPU Service Corp. 83/04/07 11pp 18691-187 24X Fiche 50-219, 83/04/07, 8306020090.

8306060252 "Annual Rept for Dec 1981 - Nov 1982 on Study of Woodborer Populations in Relation to Oyster Creek Generating Station" W/830523 ltr
HILLMAN, R. E., BELMORE, C. I., MCGRATH, R. A. Battelle New England Marine Research Laboratory. 83/05/15 150pp 18727, 044. 24X
Fiche 50-219, 83/05/25, 8306060252

8306090235 "Study of Woodborer Populations in Relation to Oyster Creek Generating Station." progress rept for 32nd quarter ending 830420 W/830601 ltr
HILLMAN, R. E., BELMORE, C. I. Battelle New England Marine Research Laboratory. FIEDLER, P. B. General Public Utilities - GPU Service Corp 19183. 83/05/31 Region 1, Office of Director 25pp
18797, 019 24X Fiche 50-219, 83/05/31, 8306090235.

S Reportable occurrences, LERs & related correspondence

8306020378 LER 83-007/03L-0 on 830418, during monthly 10 h operability test of standby gas treatment sys 11, high differential pressure across both HEPA filters observed. Caused by plugging of Filters. Filters replaced W/830520 ltr
HAGER, C., FIEDLER, P. B. General Public Utilities - GPU Service Corp 83/05/20 Region 1, Office of Director 4pp 18695 007 24X
Fiche 50-219, 83/05/20, 8306020378

8306020353 Updated LER 82-055/01X-1 on 821115, stack gas sample pump B thermal overload protector tripped. Pump failed to produce normal flow when restarted. Caused by impeller vanes Pump B rebuilt W/830525 ltr
CHARTERINA, J., FIEDLER, P. B. General Public Utilities - GPU Service Corp. 83/05/25 Region 1, Office of Director 4pp 18694 324 24X Fiche 50-219, 83/05/25, 8306020353

8306030269 LER 82-062 has been canceled.
* Jersey Central Power & Light Co 83/05/31 Region 1, Office of Director 1p 18703 343. 24X Fiche 50-219, 83/05/31, 8306030269

8306140022 PNO-I-83-056 on 830606, chlorine gas released into atmosphere for approx 15 minutes. Caused by leak in 3/4-inch plastic pipe on outlet of chlorination evaporator. All fuel removed from vessel & vessel drained.
CONGILL, CONNER Region 1, Office of Director. 83/06/07 1p 18838 234 24X Fiche 50-219, 83/06/07, 8306140022

V Operator Examinations

8306140371 Extends invitation to attend 830627 meeting in King of Prussia, PA to discuss transfer of reactor operator licensing function from Bethesda, MD to Region 1 ofc
STAROSTECKI, R. Division of Project & Resident Programs 83/06/09 FIEDLER, P. B. General Public Utilities - GPU Service Corp. 2pp 18832 121 24X Fiche 50-219, 83/06/09, 8306140371

DOCKET 50-220 NINE MILE POINT NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8306060223 Forwards IE Insp Rept 50-220/83-08 on 830401-30 & notice of violation
STAROSTECKI, R. Division of Project & Resident Programs 83/05/23 RHODE, Q. K. Niagara Mohawk Power Corp 2pp 18728 014 24X
Fiche 50-220, 83/05/23, 8306060223

--8306060224 Notice of violation from insp on 830401-30
* Region 1, Office of Director 83/05/23 1p 18728 014 24X
Fiche 50-220, 83/05/23, 8306060223.

--8306060227 IE Insp Rept 50-220/83-08 on 830401-30. Noncompliance noted: failure to control use of jumpers.
HUDSON, S. D., DOERFLEIN, L. T., MCBREARTY, R. A. Region 1, Office of Director 83/05/18 9pp 18728 015. 24X Fiche 50-220, 83/05/23, 8306060223

8306010360 Submits alternative solutions to alleviate potential spurious operation of valves listed in 821203 suppl to 821001 App R submittal Requirements for valves 40-30, 40-31 & 38-02 not required.
MANQAN, C. V. Niagara Mohawk Power Corp 83/05/26, VASSALLO, D. B. Operating Reactors Branch 2. 2pp 18681 361. 24X
Fiche 50-220, 83/05/26, 8306010360.

8306010258 Informs that recent App R-related mod resulted in loss of independence of two remote shutdown panels. Change to panels does not alter conclusions re safe shutdown capability per fire area or subarea
LEMPQES, T. E. Niagara Mohawk Power Corp 83/05/27 VASSALLO, D. B. Operating Reactors Branch 2. 1p. 18672, 291. 24X
Fiche 50-220, 83/05/27, 8306010258.

8306030352 Advises that backup meteorological instrumentation will not be installed at facility, per NUREG-0737, Suppl 1. Software problems w/meteorological dispersion modeling unresolved.
Interim sys described in 820401 ltr utilized.
LEMPQES, T. E. Niagara Mohawk Power Corp. 83/05/27, VASSALLO, D. B. Operating Reactors Branch 2. 1p 18706 126. 24X
Fiche 50-220, 83/05/27, 8306030352.

8306150626 Forwards exemption from scheduler requirements of 10CFR50, App E, Section IV, F re annual emergency preparedness exercise, per 830309 request. Exemption permits exercise to be conducted during wk of 830928
VASSALLO, D. B. Operating Reactors Branch 2. 83/05/27. RHODE, Q. K. Niagara Mohawk Power Corp. 2pp. 18867, 273. 24X
Fiche 50-220, 83/05/27, 8306150626.

DOCKETED ITEMS

31

--B306150628 Exemption from scheduler requirements of 10CFR50, App E, Section IV F re annual emergency preparedness exercise
PURPLE, R A Division of Licensing 83/05/27 Niagara Mohawk Power Corp 4pp 18867 275 24X Fiche 50-220, 83/05/27, 8306150626

B306300241 Forwards diagram depicting proposed location of new training ctr per Suppl 1 to NUREG-0737. Ctr will house new emergency operations facility & is tentatively scheduled for completion in Spring 1984
MANOAN, C V Niagara Mohawk Power Corp 83/06/24 VASSALLO, D B Operating Reactors Branch 2 2pp 19122 309 24X Fiche 50-220, 83/06/24, 8306300241

J Insurance & indemnity information

B306020158 Forwards Endorsement 82 to NELIA Policy NF-161
RUSHMORE, J W Niagara Mohawk Power Corp 83/05/27 SALTZMAN, J Assistant Director for State & License Relations 2pp 18690 354, 24X Fiche 50-220, 83/05/27, 8306020158.

B306020189 Forwards Endorsement 68 to MAELU Policy MF-46
RUSHMORE, J W Niagara Mohawk Power Corp. 83/05/27. SALTZMAN, J Office of State Programs, Director. 2pp 18690 292 24X Fiche 50-220, 83/05/27, 8306020189

P. Operating license stage documents & correspondence

B306010063 Submits clarification to B30425 response to Item 7 of Generic Ltr 83-02 re NUREG-0737 Tech Specs Failures of valves to close & challenges to valves to be reported per Tech Spec 6.9.2 & 6.9.16, respectively
MANOAN, C V. Niagara Mohawk Power Corp. 83/05/26 VASSALLO, D. B. Operating Reactors Branch 2 1p 18674 087 24X Fiche 50-220, 83/05/26, 8306010063.

B306090430 Informs that review of submittals re stress reanalysis of replaced primary sys piping completed. Reanalysis results acceptable.
VASSALLO, D B Operating Reactors Branch 2 83/05/27. RHODE, O K Niagara Mohawk Power Corp 2pp 18815 240. 24X Fiche 50-220, 83/05/27, 8306090430

--B306090432 Safety evaluation supporting results of stress reanalysis of primary sys piping replacement
* Office of Nuclear Reactor Regulation, Director. 83/05/27. 10pp 18815 242 24X Fiche 50-220, 83/05/27, 8306090430

B306070034 Notifies that Tech Specs for installation of Class IE protection packages on reactor protection motor generator sets will be submitted within 60 days of NRC concurrence w/proposed mod submitted on 821201.
MANOAN, C V. Niagara Mohawk Power Corp 83/06/01. VASSALLO, D B. Operating Reactors Branch 2 1p 18739 336 24X Fiche 50-220, 83/06/01, 8306070034.

B306150631 Forwards request for addl info re 821201 response to Multi-Plant Action Item C-11 on BWR reactor protection sys, in order to complete review. Info must be received within 45 days of ltr receipt.
VASSALLO, D B Operating Reactors Branch 2 83/06/03 RHODE, O K. Niagara Mohawk Power Corp. App. 18867.343 24X Fiche 50-220, 83/06/03, 8306150631

B306100143 Requests addl time to complete control room habitability study per IMI Item III, D.3.4 Assumptions used performing control room dose assessment reexamined. Study completion expected by Dec 1983.
MANOAN, C V. Niagara Mohawk Power Corp 83/06/06. VASSALLO, D B. Operating Reactors Branch 2. 2pp. 18801:209. 24X Fiche: 50-220, 83/06/06, 8306100143.

B306280509 Suppl to 780321 application to amend License DPR-63, revising Tech Spec Sections 5.5 & 5.6 re spent fuel pool. Also clarifies info in 781220 & 21 ltrs & forwards spent fuel pool structural analysis.
MANOAN, C V. Niagara Mohawk Power Corp. 83/06/24. VASSALLO, D B. Operating Reactors Branch 2 31pp. 19017 241. 24X Fiche: 50-220, 83/06/24, 8306280509.

--B306280513 Proposed Tech Spec Sections 5.5 & 5.6 re spent fuel pool
* Niagara Mohawk Power Corp. 83/06/24. 16pp. 19017:272. 24X Fiche 50-220, 83/06/24, 8306280509.

Q. Inspection reports, IE Bulletins & correspondence

B306060223 Forwards IE Insp Rept 50-220/83-08 on B30401-30 & notice of violation
STAROSTECKI, R. Division of Project & Resident Programs. 83/05/23 RHODE, O K Niagara Mohawk Power Corp. 2pp. 18728:014. 24X Fiche: 50-220, 83/05/23, 8306060223

--B306060224 Notice of violation from insp on B30401-30
* Region 1, Office of Director. 83/05/23 1p 18728:014 24X Fiche 50-220, 83/05/23, 8306060223

--B306060227 IE Insp Rept 50-220/83-08 on B30401-30 Noncompliance noted: Failure to control use of jumpers
HUDSON, S D, DOERFLEIN, L T., MCBREARTY, R A Region 1, Office of Director 83/05/18 9pp 18728,015 24X Fiche 50-220, 83/05/23, 8306060223

B306010402 Ack receipt of B30513 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-220/83-03
MARTIN, T T Division of Engineering & Technical Programs. 83/05/25. RHODE, O K Niagara Mohawk Power Corp. 2pp. 18677.330 24X Fiche 50-220, 83/05/25, 8306010402

--B306010412 Responds to NRC B30407 ltr re violations noted in IE Insp Rept 50-220/83-03 Corrective actions source storage cabinets received source inventory & Procedure 8-RTP-35A & 35B training completed & Tech Spec amend submitted on 830503.
LEMPGEB, T E Niagara Mohawk Power Corp 83/05/13. MARTIN, T T. Division of Engineering & Technical Programs. 5pp 18679:332. 24X Fiche 50-220, 83/05/25, 8306010402

B305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl.
TAYLOR, J M. Division of Safeguards & Inspection Programs (Post B30103) 83/05/26. Consolidated Edison Co. of New York, Inc 12pp 18831:043. 24X Fiche 50-000, 83/05/26, 8305110458.

B305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl.
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post B30103). 83/05/26 Consolidated Edison Co. of New York, Inc 11pp 18732.085 24X Fiche 50-000, 83/05/26, 8305110460.

B305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post B30103). 83/05/31 Consolidated Edison Co. of New York, Inc. 11pp 18732.208 24X Fiche: 50-000, 83/05/31, 8305110461.

B306160341 Forwards IE Insp Rept 50-220/83-09 on B30412-15 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs 83/06/01. RHODE, O K Niagara Mohawk Power Corp 2pp. 18861:158. 24X Fiche. 50-220, 83/06/01, 8306160341

--B306160344 Notice of violation from insp on B30412-15.
* Region 1, Office of Director 83/06/01 1p. 18861.160. 24X Fiche. 50-220, 83/06/01, 8306160341.

--B306160348 IE Insp Rept 50-220/83-09 on B30412-15 Noncompliance noted. Failure to inventory matl within reactor cavity railing, per Tech Specs
NIMITZ, R L, SHANBAKY, M M. Region 1, Office of Director. 83/05/27. 10pp. 18861.161 24X Fiche. 50-220, 83/06/01, 8306160341.

B305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl.
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post B30103). 83/06/09. Consolidated Edison Co. of New York, Inc 11pp. 18830:280 24X Fiche: 50-000, 83/06/09, 8305110464

B305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards." Svc list encl.
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post B30103). 83/06/13. Consolidated Edison Co. of New York, Inc 11pp 18920:225. 24X Fiche. 50-000, 83/06/13, 8305110470.

B306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables." Svc list encl.
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post B30103). 83/06/13. Consolidated Edison Co. of New York, Inc. 24pp. 18921:001. 24X Fiche: 50-000, 83/06/13, 8306090010.

B305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers." Svc list encl.
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post B30103). 83/06/22. Consolidated Edison Co. of New York, Inc. 11pp. 19021:179. 24X Fiche: 50-000, 83/06/22, 8305110475.

B305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Bys Causing Inoperability of Safety-Related Equipment " Svc list encl.
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post B30103). 83/06/22 Consolidated Edison Co. of New York, Inc. 12pp. 18997 007. 24X Fiche: 50-000, 83/06/22, 8305110477.

DOCKETED ITEMS

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Bvc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/06/23 Consolidated Edison Co of New York, Inc. 116pp. 18976 242. 24X Fiche 50-000, 83/06/23, 8305110479.

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Bvc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/06/24. Consolidated Edison Co of New York, Inc. 116pp. 19046 277. 24X Fiche 50-000, 83/06/24, 8305110483

8306280422 Forwards "Design Criteria for Reanalysis of Safety-Related Masonry Walls," per NRC 830513 request for addl info.
MANGAN, C. V. Niagara Mohawk Power Corp. 83/06/24 VASSALLO, D. B. Operating Reactors Branch 2. 1p. 19020 302. 24X Fiche 50-220, 83/06/24, 8306280422

--8306280424 "Design Criteria for Reanalysis of Safety-Related Masonry Walls, Nine Mile Point Unit 1,"
* Niagara Mohawk Power Corp. 83/06/30 2pp. 19020:303 24X Fiche: 50-220, 83/06/24, 8306280422

R Periodic operating reports & related correspondence

8306020094 Monthly operating rept for Mar 1983 W/830408 ltr
ROMAN, T. W., LEMPOEB, T. E. Niagara Mohawk Power Corp. 83/04/01, Director's Office, Office of Inspection and Enforcement. 7pp. 18991 170. 24X Fiche 50-220, 83/04/01, 8306020094.

8306200214 Monthly operating rept for May 1983 W/830613 ltr
ROMAN, T. W., MANGAN, C. V. Niagara Mohawk Power Corp. 83/06/02. 18pp. 18993 218 24X Fiche 50-220, 83/06/02, 8306200214.

B. Reportable occurrences, LERs & related correspondence

8306060199 LER 83-009/03L-0: on 830426, control room ventilation sys removed from svc for mods to control room wall, per LER 83-06 Temporary flexible ducting in place during mods. Mode completed. Ventilation sys returned to svc. W/830526 ltr
RABY, J., LEMPOEB, T. E. Niagara Mohawk Power Corp. 83/05/24.
ALLAN, J. H. Region 1, Office of Director. 2pp. 18727 291. 24X Fiche: 50-220, 83/05/24, 8306060199.

V. Operator Examinations

8306140697 Extends invitation to attend 830627 meeting in King of Prussia, PA to discuss transfer of reactor operator licensing function from Bethesda, MD to Region I ofc.
STAROSTECKI, R. Division of Project & Resident Programs. 83/06/09.
RHODE, S. K. Niagara Mohawk Power Corp. Rpp. 18841:349. 24X Fiche: 50-220, 83/06/09, 8306140697.

DOCKET 50-223 UNIV. OF LOWELL RESEARCH REACTOR

V. Operator Examinations

8306140635 Extends invitation to attend 830627 meeting in King of Prussia, PA to discuss transfer of reactor operator licensing function from Bethesda, MD to Region I ofc.
STAROSTECKI, R. Division of Project & Resident Programs. 83/06/09.
BECHIAN, L. E. Lowell, Univ. of. 2pp. 18843:048. 24X Fiche: 50-223, 83/06/09, 8306140635.

DOCKET 50-224 UNIV OF CALIFORNIA RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

8306280296 Forwards request for addl info re Univ of CA research reactor 821023 emergency plan to continue review per App E to 10CFR50, Rev 1 to Reg Guide 2.6 & ANSI/ANS-15.1d-1982 requirements. Info requested within 90 days of ltr date.
THOMAS, C. O. Standardization & Special Projects Branch. 83/06/09.
KAPLAN, S. N. California, Univ. of. Berkeley. App. 18940:306. 24X Fiche: 50-224, 83/06/09, 8306280296.

DOCKET 50-225 RPI CRITICAL EXPERIMENT

V. Operator Examinations

8306140255 Requests attendance at 830627 meeting in King of Prussia, PA to discuss transfer of reactor operator licensing function from Bethesda, MD to Region I ofc.
STAROSTECKI, R. Division of Project & Resident Programs. 83/06/09.
LANEY, R. T. Rensselaer Polytechnic Inst. 2pp. 18833:017. 24X Fiche: 50-225, 83/06/09, 8306140255.

DOCKET 50-237 DRESDEN NUCLEAR POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8306210314 FOIA request for NRC records re security violations & safeguards events at nuclear facilities.
OLDENDERO, G. Scripps-Howard Newspapers. 83/04/22 FELTON, J. M. Office of Administration. 2pp. 18925 198 24X Fiche 50-000, 83/04/22, 8306210314

8306210306 Partial response to FOIA request for NRC records re security violations & safeguards events at nuclear facilities Repts listed on App A available in PDR Search for addl documents suby to request continuing
FELTON, J. M. Division of Rules and Records. 83/05/16 OLDENDERO, G. Scripps-Howard Newspapers. 2pp. 18925 196 24X Fiche 50-000, 83/05/16, 8306210306

8306090247 Confirms 830401 telcon re changes to exercise windows for Dresden & Byron Nuclear Power Stations Dresden partial exercise will be conducted during wk of 830912 w/Byron full-scale exercise beginning wk of 831114
JONES, E. E. Illinois, State of. 83/06/01 KEPLER, J. Region 3, Office of Director. ANDERSON, J. Federal Emergency Management Agency WADNER, G. Commonwealth Edison Co. 1p. 18793 319 24X Fiche: 50-000, 83/06/01, 8306090247

8306210355 Releases public version of revised emergency plan implementing procedure
FELTON, J. M. Division of Rules and Records. 83/06/06 Document Management Branch. 1p. 18935 293 24X Fiche 50-010, 83/06/06, 8306210355.

--8306210357 Public version of Rev 1 to Emergency Plan Implementing Procedure EPIP 300-12, "Initiation of Environ Monitoring Activities by Rad/Chem Director " Receipt form encl
W/830516 ltr
BCOTT, D. J. Commonwealth Edison Co. 83/05/11 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 19pp. 18935 294 24X Fiche 50-010, 83/06/06, 8306210355

8306100218 Responds to IE Insp Repts 50-010/83-01, 50-237/83-01 & 50-249/83-01. Corrective action surveillance notification program developed for annual distribution of public info brochures on emergency planning
FARRAR, D. L. Commonwealth Edison Co. 83/06/07 PAPERIELLO, C. J. Region 3, Office of Director. 4pp. 18809 113 24X Fiche 50-010, 83/06/07, 8306100218

8306140214 Submits correction to 830401 ltr Date of reassessment will be made prior to 830801, not 831001.
JONES, E. E. Illinois, State of. 83/06/09, KEPLER, J. Region 3, Office of Director. ANDERSON, J. Federal Emergency Management Agency WADNER, G. Commonwealth Edison Co. 1p. 18861 358 24X Fiche: 50-000, 83/06/09, 8306140214

P Operating license stage documents & correspondence

8306100308 Advises that maint procedures & schedules described in SER for SER Topic III-4-B, "Turbine Machines" & Section 4.6 of integrated plant BAR constitute adequate interim assurance of low probability of missile generation
CRUTCHFIELD, D. Operating Reactors Branch 5. 83/05/31. FARRAR, D. L. Commonwealth Edison Co. 2pp. 18672 319 24X Fiche 50-237, 83/05/31, 8306100308.

8306090194 Discusses util interpretation of 10CFR50.49, "Environ Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants." Intent of rulemaking is to require upgrade program for replacement equipment not parts
FARRAR, D. L. Commonwealth Edison Co. 83/06/03. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 3pp. 18796 090 24X Fiche: 50-000, 83/06/03, 8306090194

8306140408 Forwards evaluation of BWR Owners Group generic response to NUREG-0737, Item II, K 3 1B, "Mod of Automatic Depressurization Sys Logic-Feasibility for Increased Diversity for Some Event Sequences." Two options listed.
CRUTCHFIELD, D. Operating Reactors Branch 5. 83/06/03. FARRAR, D. L. Commonwealth Edison Co. 2pp. 18837 354. 24X Fiche: 50-237, 83/06/03, 8306140408.

8306090227 Informs that response to Generic Ltr 83-08 will be submitted by 830713 Info will include stress repts to determine mod to vacuum breakers on Mark I containments
RYBAK, J. Commonwealth Edison Co. 83/06/06. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 18796 234 24X Fiche: 50-000, 83/06/06, 8306090227.

8306130425 Provides overview of plan for checking for clamp interferences on main steam line snubbers Sargent & Lundy reviewing add'l snubber test data Results expected by 830622
RYBAK, B Commonwealth Edison Co 83/06/06 KEPLER, J O Region 3, Office of Director 2pp 18823 145 24X Fiche 50-237, 83/06/06, 8306130425

8306160233 Advises that manufacturers whose repts were used in technical evaluation repts re environ qualification of electrical equipment have been contacted List of proprietary pages detailed in util 830513 ltr W/OE affidavit
RYBAK, B Commonwealth Edison Co 83/06/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 18861 304 24X Fiche 50-000, 83/06/06, 8306160233

8306100128 Forwards safety evaluation & technical evaluation repts, "Monitoring of Electric Power to Reactor Protection Sys for Dresden Nuclear Power Station Units 2 & 3" Proposed mods acceptable
CRUTCHFIELD, D Operating Reactors Branch 5 83/06/09 FARRAR, D L Commonwealth Edison Co 3pp 18801 181 24X Fiche 50-237, 83/06/09, 8306100128

--8306100131 Safety evaluation re monitoring of electric power to reactor protection sys Proposed mods providing automatic protection of sys components from sustained abnormal power supply acceptable
* Office of Nuclear Reactor Regulation, Director 83/06/09 2pp 18801 184 24X Fiche 50-237, 83/06/09, 8306100128

--8306100135 "Monitoring of Electric Power to Reactor Protection Sys for Dresden Nuclear Power Station Units 2 & 3." technical evaluation repts
SELAN, J C Lawrence Livermore Laboratory FIN A-0250 UCID-17705 83/05/18 NRC - No Detailed Affiliation Given, 7pp 18801 186 24X Fiche 50-237, 83/06/09, 8306100128

8306200265 Forwards "Dresden Nuclear Power Station Unit 2 Reactor Vessel Irradiation Surveillance Program Analysis of Capsule Number B" Results support 820331 amend request that existing pressure temp curves be effective through 10 EFPPY
RYBAK, B Commonwealth Edison Co 83/06/10 SCHNEIDER, A Licensing Branch 2 2pp 19021 308 24X Fiche 50-237, 83/06/10, 8306200265.

--8306270003 "Dresden Nuclear Power Station Unit 2 Reactor Vessel Irradiation Surveillance Program Analysis of Capsule Number B"
NORRIS, E B, LINDHOLM, U B Southwest Research Institute, SWRI-4901-002 83/03/31 57pp, 19021 310, 24X Fiche 50-237, 83/06/10, 8306200265.

8306240030 Application to amend Licenses DPR-19 & DPR-25, extending time limits for inoperability of ECCB ring header snubbers Also updates Unit 3 Tables 3 & 1 a & b to reflect changes in type of snubbers installed.
RYBAK, B Commonwealth Edison Co 83/06/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp, 18981:095, 24X Fiche 50-237, 83/06/13, 8306240030

--8306240035 Proposed Tech Specs extending time limits for inoperability of ECCB ring header snubbers & updating Unit 3 Tables 3 & 1 a & b to reflect type of snubbers installed
* Commonwealth Edison Co, 83/06/13 20pp, 18981 097, 24X Fiche 50-237, 83/06/13, 8306240030

8306270247 Requests extension of Mark I containment completion date. All work on ECCB suction head snubbers will be completed by 830928. Description of remaining work, current status & reasons for delay encl
RYBAK, B Commonwealth Edison Co 83/06/16, DENTON, H R, Office of Nuclear Reactor Regulation, Director 4pp, 18988, 278, 24X Fiche 50-237, 83/06/16, 8306270247.

8306280564 Forwards confirmatory order re 820316 commitment to install permanent scram discharge sys mods by 850101 or prior to operation in Cycle 10. Proposed model Tech Specs provided for guidance also encl
CRUTCHFIELD, D, Operating Reactors Branch 5, 83/06/24, FARRAR, D L, Commonwealth Edison Co 2pp 19018, 029, 24X Fiche 50-237, 83/06/24, 8306280564

--8306280570 Confirmatory order re util 820316 commitment to install permanent scram discharge sys mods by 850101 or prior to operation in Cycle 10
EISENHUT, D O Division of Licensing 83/06/24, Commonwealth Edison Co 5pp, 19018 031, 24X Fiche 50-237, 83/06/24, 8306280564.

--8306280575 Proposed model Tech Specs for installation of permanent scram discharge sys mods.
* NRC - No Detailed Affiliation Given, 83/06/24 30pp, 19018, 036 24X Fiche 50-237, 83/06/24, 8306280564.

G Inspection reports, IE Bulletins & correspondence

8306220144 Ack receipt of payment of civil penalty & 830317 response to 830216 notice of violation & proposed imposition of civil penalty
AXELRAD, J A Director's Office, Office of Inspection and Enforcement 83/03/31 O'CONNOR, J J Commonwealth Edison Co 2pp 18937 348 24X Fiche 50-237, 83/03/31, 8306220144.

8306220218 Ack receipt of 830414 payment of proposed civil penalties Response to notice of violation & proposed imposition of civil penalties will be evaluated & corrective actions examined during future insps
AXELRAD, J A Enforcement Staff 83/04/21, REED, C Commonwealth Edison Co 2pp 18950 357 24X Fiche 50-000, 83/04/21, 8306220218

8305260238 Responds to violations noted in IE Insp Repts 50-237/83-08 & 50-249/83-07 Corrective actions radiation protection mgt personnel increased surveillance of respiratory devices & add'l radiation control technician added.
FARRAR, D L Commonwealth Edison Co, 83/05/20 KEPLER, J O, Region 3, Office of Director 5pp 18999 355, 24X Fiche 50-237, 83/05/20, 8305260238

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc. 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26, Consolidated Edison Co. of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460.

8306100101 Forwards IE Insp Repts 50-237/83-13 & 50-249/83-11 on 830426 No noncompliance noted.
LITTLE, W B Region 3, Office of Director, 83/05/27, REED, C, Commonwealth Edison Co 2pp 18802:332, 24X Fiche 50-237, 83/05/27, 8306100101

--8306100105 IE Insp Repts 50-237/83-13 & 50-249/83-11 on 830426. No noncompliance noted Major areas inspected: licensee action re IE Bulletin 80-11, "Masonry Wall Design,"
NORTON, J F., WILLIAMS, C C Region 3, Office of Director, 83/05/27, 4pp, 18802, 334, 24X Fiche 50-237, 83/05/27, 8306100101.

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs" Svc list encl
JORDAN, E L, Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc. 116pp, 18732 208 24X Fiche 50-000, 83/05/31, 8305110461.

8306130338 Confirms plan discussed on 830601 for 830620 enforcement conference to discuss post-maint problems & significance of missing snubber on torus.
NORELIOB, C E Division of Project & Resident Programs, 83/06/03, REED, C Commonwealth Edison Co 1p 18823 001 24X Fiche 50-237, 83/06/03, 8306130338

8306100149 Forwards Rev 3 to "180-Day Rept in Response to IE Bulletin 80-11 for Dresden 2 & 3 & Quad Cities 1 & 2."
RYBAK, B Commonwealth Edison Co 83/06/06 KEPLER, J O, Region 3, Office of Director 2pp 18804, 161 24X Fiche 50-000, 83/06/06, 8306100149

--8306100156 Rev 3 to "180-Day Rept in Response to IE Bulletin 80-11 for Dresden 2 & 3 & Quad Cities 1 & 2."
* Commonwealth Edison Co, 83/05/09, 129pp, 18804:163, 24X Fiche 50-000, 83/06/06, 8306100149.

8306100074 Forwards response to IE Bulletin 83-03 re diesel generator cooling water check valves. Plants utilize Mission Duo-Check valves employing hinge-to-pin design for protection against vibration-induced failures.
BARNES, P L, Commonwealth Edison Co 83/06/07, KEPLER, J O, Region 3, Office of Director, 7pp, 18802:238, 24X Fiche 50-000, 83/06/07, 8306100074.

8306100218 Responds to IE Insp Repts 50-010/83-01, 50-237/83-01 & 50-249/83-01. Corrective action surveillance notification program developed for annual distribution of public info brochures on emergency planning.
FARRAR, D L, Commonwealth Edison Co, 83/06/07, PAPERIELLO, C J, Region 3, Office of Director, 4pp, 18803:113, 24X Fiche 50-010, 83/06/07, 8306100218

DOCKETED ITEMS

8306170380 Forwards response to IE Bulletin 83-03 re diesel generator cooling water check valves. Valves at Dresden & LaSalle acceptable w/o further insp Rept on valve failures at Quad Cities will be submitted within 90 days of insp completion. BARNES, P. L. Commonwealth Edison Co. 83/06/07. KEPPLER, J. Q. Region 3, Office of Director 7pp 18880-211. 24X Fiche: 50-000, 83/06/07, 8306170380

8306270387 Forwards inservice insp rept for Jan 1983 insp of B&W reactor pressure vessel & GE primary sys piping. SCOTT, D. J. Commonwealth Edison Co. 83/06/08. KEPPLER, J. Q. Region 3, Office of Director 1p. 18993-252. 24X Fiche: 50-237, 83/06/08, 8306270387

--8306270392 Inservice insp rept on 830110-0329, B&W reactor pressure vessel & GE primary sys piping inspected. * Commonwealth Edison Co. 83/06/08 38pp. 18993-253 24X Fiche: 50-237, 83/06/08, 8306270387.

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations." Bvc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/09. Consolidated Edison Co. of New York, Inc. 119pp 18830-280 24X Fiche: 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards." Bvc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/13. Consolidated Edison Co. of New York, Inc. 118pp. 18920-225 24X Fiche: 50-000, 83/06/13, 8305110470.

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables." Bvc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/13. Consolidated Edison Co. of New York, Inc. 243pp. 18921-001. 24X Fiche: 50-000, 83/06/13, 8306090010

8306300235 Forwards IE Insp Repts 50-237/83-12, 50-249/83-10, 50-254/83-13 & 50-265/83-11 on 830412-14 & 0506 & 16 & notice of violation. LITTLE, W. B. Region 3, Office of Director 83/06/16. REED, C. Commonwealth Edison Co. 2pp. 19122-279 24X Fiche: 50-000, 83/06/16, 8306300235.

--8306300238 Notice of violation from insp on 830412-14 & 0506 & 16. LITTLE, W. B. Region 3, Office of Director. 83/06/16. 2pp 19122-281 24X Fiche: 50-000, 83/06/16, 8306300235.

--8306300246 IE Insp Repts 50-237/83-12, 50-249/83-10, 50-254/83-13 & 50-265/83-11 on 830412-14 & 0506 & 16 Noncompliance noted as-built configuration (for pipe anchor R133 in pressure suppression sys) differed from original design. YIN, I. Y., DANIELSON, D. H. Region 3, Office of Director. 83/06/15. 9pp. 19122-283 24X Fiche: 50-000, 83/06/16, 8306300235.

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers." Bvc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/22. Consolidated Edison Co. of New York, Inc. 115pp 19021-179. 24X Fiche: 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment." Bvc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/22. Consolidated Edison Co. of New York, Inc. 120pp. 18997-007. 24X Fiche: 50-000, 83/06/22, 8305110477.

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions." Bvc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/23. Consolidated Edison Co. of New York, Inc. 116pp. 18996-242. 24X Fiche: 50-000, 83/06/23, 8305110479.

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints." Bvc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/24. Consolidated Edison Co. of New York, Inc. 116pp 19046-297 24X Fiche: 50-000, 83/06/24, 8305110483.

R. Periodic operating reports & related correspondence

8306130275 "Semiannual Rept of Radioactive Effluents 1982" W/830302 ltr. SCOTT, D. J. Commonwealth Edison Co. 83/03/02. KEPPLER, J. Q. Region 3, Office of Director. 20pp. 18823-277. 24X Fiche: 50-010, 83/03/02, 8306130275.

8306140086 Monthly operating repts for May 1983 W/830601 ltr. SCHROEDER, B. A., SCOTT, D. J. Commonwealth Edison Co. 83/06/01. Director's Office, Office of Inspection and Enforcement 18pp 18838-347 24X Fiche: 50-237, 83/06/01, 8306140086

8306130454 Forwards corrected "1981 Rept of Occupational Personnel Radiation Doses - Contract Workers," per Reg Guide 1 16 Number of people per manrem should be listed in maint not engineering category. WAGNER, O. P. Commonwealth Edison Co. 83/06/07. KEPPLER, J. Q. Region 3, Office of Director 1p 18821-179 24X Fiche: 50-010, 83/06/07, 8306130454

--8306130457 Forwards corrected "1981 Rept of Occupational Personnel Radiation Doses - Contract Workers," per Reg Guide 1 16 Number of people per manrem should be listed in maint not engineering category. WAGNER, O. P. Commonwealth Edison Co. 83/06/06. KEPPLER, J. Q. Region 3, Office of Director 1p 18821-180 24X Fiche: 50-010, 83/06/07, 8306130454

--8306130460 Corrected "1981 Rept of Occupational Personnel Radiation Doses - Contract Workers." * Commonwealth Edison Co. 83/06/06 9pp 18821-181 24X Fiche: 50-010, 83/06/07, 8306130454

8306220086 Advises that V Biron farm will provide milk samples for radiological monitoring program. Herd totals 130 cows, including 50 milking cows. Addl info re Biron farm will be provided in annual environ rept. GOLDEN, J. C. Commonwealth Edison Co. 83/06/15. KEPPLER, J. Q. Region 3, Office of Director 1p 18927-187 24X Fiche: 50-237, 83/06/15, 8306220086

B Reportable occurrences, LERs & related correspondence

8306060232 Updated LER 83-013/03X-1 on 830211, power lead from welding machine became disconnected & grounded to torus base metal causing arc strike which fused copper/brass into metal. Cause considered accident W/830523 ltr. TANQ WEE, D., SCOTT, D. J. Commonwealth Edison Co. 83/05/23. KEPPLER, J. Q. Region 3, Office of Director 3pp 18728-288 24X Fiche: 50-237, 83/05/23, 8306060232

8306030218 LER 83-034/03L-0 on 830427, drywell floor drain sump pumped at interval exceeding Tech Spec limit caused by personnel failure to follow Operating Order 26-83 ensuring compliance w/Tech Spec requiring pumping at 4 h interval W/830525 ltr. SCOTT, D. J., COEN, R. Commonwealth Edison Co. 83/05/25. KEPPLER, J. Q. Region 3, Office of Director 3pp 18704-025 24X Fiche: 50-237, 83/05/25, 8306030218

8306060040 LER 83-035/03L-0 on 830427, low pressure coolant injection HX discharge valve M02-1501-3B failed to open. Cause undetermined. Control circuitry inspected by electrical & instrument maint & found satisfactory W/830525 ltr. COYLE, L. M., SCOTT, D. J. Commonwealth Edison Co. 83/05/25. KEPPLER, J. Q. Region 3, Office of Director. 3pp 18719-128 24X Fiche: 50-237, 83/05/25, 8306060040

8306070246 LER 83-036/03L-0 on 830502, drywell floor drain leakage exceeded Tech Spec limits due to bonnet leakage on feedwater check valve 2-220-98B. Caused by failed bonnet seal ring. Seal ring replaced. Leakage to be monitored W/830531 ltr. CHRISTEL, S., SCOTT, D. J. Commonwealth Edison Co. 83/05/31. KEPPLER, J. Q. Region 3, Office of Director 3pp 18744-213. 24X Fiche: 50-237, 83/05/31, 8306070246.

8306130382 LER 83-037/03L-0 on 830504, average power range Monitor 4 rod block setpoint exceeded Tech Spec limit of 12% caused by instrument drift. Monitor adjusted & tested satisfactorily W/830531 ltr. BEVERLY, K. F., SCOTT, D. J. Commonwealth Edison Co. 83/05/31. KEPPLER, J. Q. Region 3, Office of Director 3pp 18822-349 24X Fiche: 50-237, 83/05/31, 8306130382

8306130348 LER 83-039/03L-0 on 830505, during normal operation, unidentified leak from drywell discovered. Caused by packing leak on recirculation discharge bypass valve 2-202-7A causing overflow of equipment drain sump W/830601 ltr. TURNQUEST, L., SCOTT, D. J. Commonwealth Edison Co. 83/06/01. KEPPLER, J. Q. Region 3, Office of Director 3pp 18823-005 24X Fiche: 50-237, 83/06/01, 8306130348

8306130439 LER 83-040/03L-0 on 830507, during MBIV 10X closure test Procedure D08 250-1, N80 received half-scream signal on RPB channel A. Caused by ground on IC limit switch relay 570-102E circuit. Ground will be corrected W/830601 ltr. MAXWELL, J. Q., SCOTT, D. J. Commonwealth Edison Co. 83/06/01. KEPPLER, J. Q. Region 3, Office of Director 3pp 18821-212 24X Fiche: 50-237, 83/06/01, 8306130439.

DOCKETED ITEMS

36

8306130374 LER 83-042/03L-0 on 830512, condenser low vacuum scram switch 503D tripped at vacuum of 22.8 inches while performing DIS 500-6 Caused by instrument drift Barksdale switch DIT-H1888 adjusted & exercised W/830603 ltr BEVERLY, K P, SCOTT, D J Commonwealth Edison Co 83/06/03 KEPLER, J Q Region 3, Office of Director 3pp 1882R 344 24X Fiche 50-237, 83/06/03, 8306130374

8306270282 Potential Part 21 rept re discrepancy in welding of turnbuckle assembly, turnbuckle-bolt interface & on top plate assembly variable springs BA307 Grade B bolts not ASME Section IX matl investigation underway KARAGIANIS, J A Elcen Metal Products Co 83/06/17 KEPLER, J Q Region 3, Office of Director 2pp 18996 207 24X Fiche 50-000, 83/06/17, 8306270282

8306270279 PNO-111-83-052 on 830620, electrical fire occurred in generator exciter, forcing shutdown of unit for 2-3 wks. Storing process caused short in rings/brush manifold assembly Damage extensive TONGUE, T, SHAFER, W Region 3, Office of Director 83/06/21 ip 18996 172 24X Fiche 50-237, 83/06/21, 8306270279

DOCKET 50-243 OREGON STATE UNIV RESEARCH REACTOR

Q Inspection reports, IE Bulletins & correspondence

8306070285 Forwards IE Insp Rept 50-243/83-01 on 830511-12 No noncompliance noted BODK, H E Region 5, Office of Director 83/05/20 PARSONS, T D Oregon State Univ 3pp 18741 166 24X Fiche 50-243, 83/05/20, 8306070285

--8306070287 IE Insp Rept 50-243/83-01 on 830511-12 No noncompliance noted Major areas inspected radiation control program, environ protection, transportation activities & processing of IE info notices GARCIA, E M, WENBLAWSKI, F, BODK, H E Region 5, Office of Director 83/05/20 5pp 18741 168 24X Fiche 50-243, 83/05/20, 8306070285

B Reportable occurrences, LCRs & related correspondence

8306070044 RO on 830523, discovered insp of transient control rod not conducted since 810317 Caused by misinterpretation of Tech Specs Surveillance time intervals will be modified per ANSI/ANS 15.1-1982 guidelines WANG, C H Oregon State Univ 83/05/25 Region 5, Office of Director 2pp 18740 001 24X Fiche 50-243, 83/05/25, 8306070044

DOCKET 50-244 ROBERT EMMET GINNA NUCLEAR PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8306070258 Forwards Rev 18 to security plan, delineating frequency for testing emergency power annunciator sys Rev withheld (ref 10CFR73.21) MAIER, J E Rochester Gas & Electric Corp 83/05/19 ALLAN, J M Region 1, Office of Director 1p 18740 339 24X Fiche 50-244, 83/05/19, 8306070258

8306020381 Forwards IE Insp Rept 50-244/83-08 on 830418-22 No noncompliance noted MARTIN, T T Division of Engineering & Technical Programs 83/05/20 MAIER, J E Rochester Gas & Electric Corp. 2pp 18695 142 24X Fiche 50-244, 83/05/20, 8306020381

--8306020389 IE Insp Rept 50-244/83-08 on 830418-22 No noncompliance noted Major areas inspected: emergency preparedness items from prior appraisal performed on 81102-13. TERC, N M, COHEN, I, CROCKER, H M Region 1, Office of Director, 83/05/19 14pp 18695 144, 24X Fiche 50-244, 83/05/20, 8306020389

8306020400 Forwards IE Insp Rept 50-244/83-09 on 830419-22 No noncompliance noted MARTIN, T T Division of Engineering & Technical Programs 83/05/20 MAIER, J E Rochester Gas & Electric Corp. 2pp 18695 033 24X Fiche 50-244, 83/05/20, 8306020400

--8306020403 IE Insp Rept 50-244/83-09 on 830419-22 No noncompliance noted Major areas inspected: security plan & implementing procedures, security organization & program audit, records & repts, testing & maint & locks, keys & combinations DUNLAP, J M, ODDY, A T Region 1, Office of Director 83/05/18, 3pp, 18695 035, 24X Fiche 50-244, 83/05/20, 8306020400

8306060174 Summary of 830518 meeting w/Westinghouse re review of Westinghouse generic safety parameter display sys concerning WCAP-10170, "Emergency Response Facility Design & V&V Process" Vendor will append man-in-the loop results DICK, Q F Operating Reactors Branch 5 83/06/02 CRUTCHFIELD, D, Operating Reactors Branch 5 17pp 18728 164 24X Fiche 50-244, 83/06/02, 8306060174

8306170008 Advises that LABL vital area analysis program personnel will revisit plant site to gather addl info due to major mods & redirection of program by NRC ALLAN, J M Region 1, Office of Director 83/06/13 MAIER, J E Rochester Gas & Electric Corp 2pp 18882 275 24X Fiche 50-244, 83/06/13, 8306170008

Q Adjudicatory correspondence

8306160571 Order requesting party status repts by 830715 re expected issuances, suggested procedure re discovery, prehearing conference & hearings, proposed agenda if prehearing conference suggested & renouncing of procedure. GROSSMAN, H Atomic Safety and Licensing Board Panel. 83/06/15, 2pp 18866 283 24X Fiche 50-244, 83/06/15, 8306160571

J Insurance & indemnity information

8306020128 Forwards Endorsements 73 & 74 to MAELU Policy MF-47 & Endorsements 87 & 88 to NELIA Policy MF-170. SINISI, J M Marsh & McLennan, Inc 83/05/26, SALTZMAN, J Assistant Director for Stats & License Relations 5pp 18691, 222, 24X Fiche 50-244, 83/05/26, 8306020128

P Operating license stage documents & correspondence

8306020079 Forwards visual aids used at 830512 & 20 meetings re steam generator sleeving & B&W proprietary "Ginna Sleeving Repair - Spring 1983 Steam Generator Rapid Sleeving Program." Rept withheld (ref 10CFR2.790) MAIER, J E Rochester Gas & Electric Corp. 83/05/24, CRUTCHFIELD, D, Operating Reactors Branch 5 33pp 18691 135, 24X Fiche 50-244, 83/05/24, 8306020079

8306060057 Forwards info & rept re SEP Topic III-7.8, "Design Codes, Design Criteria & Load Combinations" As result of review, util has identified two commitments re scupper installation & diesel generator bldg concrete walls. MAIER, J E Rochester Gas & Electric Corp 83/05/27, CRUTCHFIELD, D, Operating Reactors Branch 5 11pp 18719 271, 24X Fiche 50-244, 83/05/27, 8306060057

--8306060059 "Evaluation of Concrete Code Changes, 'Design Codes, Design Criteria & Load Combinations' Portion of USNRC SEP Topic III-7.8" ADAMETZ, J M, MOORE, T L Gilbert/Commonwealth Cos. 83/05/23, 34pp 18719 282 24X Fiche 50-244, 83/05/27, 8306060057

8306060296 Requests clarification of 830201 response to 821213 safety evaluation on environ qualification of safety-related electrical equipment. Proprietary info should be identified per encl guidelines within 30 days of receipt of ltr CRUTCHFIELD, D Operating Reactors Branch 5. 83/05/31, MAIER, J E, Rochester Gas & Electric Corp. 8pp, 18726 347, 24X Fiche 50-244, 83/05/31, 8306060296

8306060255 Summary of 830520 meeting w/util & B&W re steam generator tube sleeving program. Agenda & viewgraphs encl. Safety evaluation will be issued prior to permitting criticality. DICK, Q F, Operating Reactors Branch 5 83/06/02 Operating Reactors Branch 5, 17pp 18727 207, 24X Fiche 50-244, 83/06/02, 8306060255

8306140595 Forwards Rev O to proprietary "Steam Generator Evaluation, Spring 1983 Outage, Strength Testing of Sealable Sleeves Explosively Expanded Into Locked Tubes - RE Ginna Station." Rept withheld (ref 10CFR2.790). MAIER, J E Rochester Gas & Electric Corp. 83/06/09, CRUTCHFIELD, D, Operating Reactors Branch 5, 1p, 18833 059, 24X Fiche 50-244, 83/06/09, 8306140595

8306170032 Discusses NRC 830428 ltr re blocking of safety injection signal during cooldown Tech Specs will be submitted to reflect clarification of permissible bypass conditions. No Tech Spec mod required for steam line isolation MAIER, J E, Rochester Gas & Electric Corp 83/06/09, CRUTCHFIELD, D, Operating Reactors Branch 5, 1p, 18882 232 24X Fiche 50-244, 83/06/09, 8306170032

DOCKETED ITEMS

8306200314 Forwards "RE Ginna Nuclear Power Station Containment Vessel Tendons, Response to NRC Review Comments on Tendon Evaluation," supporting until conclusion that stress relaxation of tendon major cause of large force losses. MAIER, J. E. Rochester Gas & Electric Corp. 83/06/13 CRUTCHFIELD, D. Operating Reactors Branch 5. 1p. 18899 24X 24X
Fiche: 50-244, 83/06/13, 8306200314

--8306200316 "RE Ginna Nuclear Power Station Containment Vessel Tendons, Response to NRC Review Comments on Tendon Evaluation" FULTON, J. F., HERR, J. C., CHEN, C. Gilbert/Commonwealth Cos. 83/06/09 56pp 18899 244. 24X Fiche 50-244, 83/06/13, 8306200314

8306200235 Forwards proprietary version of safety evaluation finding pretensioning mod to previously approved sleeving process acceptable for locked up tubes in steam generators. Safety evaluation withheld. CRUTCHFIELD, D. D. Operating Reactors Branch 5. 83/06/16 MAIER, J. E. Rochester Gas & Electric Corp. 3pp 18902. 151 24X
Fiche 50-244, 83/06/16, 8306200235

8306240177 Responds to SEP Topic III-5 B. "Pipe Break Outside Containment" Installation of jet impingement shields to protect main steam safety & relief valves not needed. Item resolved. MAIER, J. E. Rochester Gas & Electric Corp. 83/06/16 CRUTCHFIELD, D. Operating Reactors Branch 5. 3pp 18981 030. 24X
Fiche 50-244, 83/06/16, 8306240177

8306240311 Discusses analysis used to meet current SRP seismic criteria for refueling water storage tank (RWST), per SEP Topic III-6. Preliminary results w/ input & acceptance parameters encl. Final analysis will be available by 830715. MAIER, J. E. Rochester Gas & Electric Corp. 83/06/16. CRUTCHFIELD, D. Operating Reactors Branch 5. 24pp 18979. 148 24X
Fiche: 50-244, 83/06/16, 8306240311.

--8306240312 "Design Input Document Index for Evaluation of Sodium Hydroxide Tank." CAMPBELL, D. R. Gilbert/Commonwealth Cos. 3572. 82/10/25. 17pp 18979. 172 24X Fiche. 50-244, 83/06/16, 8306240311

8306210157 Forwards environ evaluation & notice of availability re conversion of provisional OL DPR-18 to full-term OL. Evaluation determined no substantial changes in proposed actions relevant to environ concerns. MIRALIA, F. J. Assistant Director for Safety Assessment. 83/06/17 MAIER, J. E. Rochester Gas & Electric Corp. 5pp. 18915 193 24X
Fiche: 50-244, 83/06/17, 8306210157

--8306210163 Environ evaluation re conversion of provisional OL DPR-18 to full-term OL. * Office of Nuclear Reactor Regulation, Director 83/06/17 18pp. 18915:198 24X Fiche: 50-244, 83/06/17, 8306210157.

--8306210168 Notice of availability of environ evaluation re conversion of provisional OL DPR-18 to full-term OL. PAULSON, W. A. Operating Reactors Branch 5. 83/06/17 2pp 18915:216. 24X Fiche: 50-244, 83/06/17, 8306210157.

8306240298 Forwards Rev 3A to App C to GA manual describing inservice pump & valve testing program for Jan 1981 - Dec 1990. Rev includes commitments to test valves performing pressure isolation function from RCPB. MAIER, J. E. Rochester Gas & Electric Corp. 83/06/20 CRUTCHFIELD, D. Operating Reactors Branch 5. 1p. 18979 189. 24X
Fiche: 50-244, 83/06/20, 8306240298.

--8306240302 Rev 3A to App C to GA manual re inservice pump & valve testing program for Jan 1981 - Dec 1990. ANDERSON, C. R. Rochester Gas & Electric Corp. 83/06/15 37pp. 18979:190. 24X Fiche 50-244, 83/06/20, 8306240298

8306270360 Forwards addl info requested 830407 re containment pressure monitor, containment water level monitor & containment hydrogen monitors installed per requirements of TH1 Items II F.1.4, II F.1.5 & II F.1.6 respectively. MAIER, J. E. Rochester Gas & Electric Corp. 83/06/20. CRUTCHFIELD, D. Operating Reactors Branch 5. 10pp. 18993:176. 24X
Fiche: 50-244, 83/06/20, 8306270360.

8306270257 Forwards JH Taylor affidavit supporting 830609 request to withhold retest summarizing testing performed to support pretensioning of steam generator tubes for sleeving from public disclosure. MAIER, J. E. Rochester Gas & Electric Corp. 83/06/21. CRUTCHFIELD, D. Operating Reactors Branch 5. 4pp. 18988:270. 24X
Fiche: 50-244, 83/06/21, 8306270257

0 Inspection reports, IE Bulletins & correspondence

8306020381 Forwards IE Insp Rept 50-244/83-08 on 830418-22 No noncompliance noted. MARTIN, T. T. Division of Engineering & Technical Programs. 83/05/20 MAIER, J. E. Rochester Gas & Electric Corp. 2pp 18695 142 24X
Fiche 50-244, 83/05/20, 8306020381

--8306020389 IE Insp Rept 50-244/83-08 on 830418-22 No noncompliance noted. Major areas inspected emergency preparedness items from prior appraisal performed on 81102-13. TERC, N. M., COHEN, I., CROCKER, H. W. Region 1, Office of Director. 83/05/19 14pp 18695 144 24X Fiche 50-244, 83/05/20, 8306020389

8306020400 Forwards IE Insp Rept 50-244/83-09 on 830419-22 No noncompliance noted. MARTIN, T. T. Division of Engineering & Technical Programs. 83/05/20 MAIER, J. E. Rochester Gas & Electric Corp. 2pp 18695 033 24X
Fiche 50-244, 83/05/20, 8306020400

--8306020403 IE Insp Rept 50-244/83-09 on 830419-22 No noncompliance noted. Major areas inspected security plan & implementing procedures, security organization & program audit, records & reports, testing & maint & locks, keys & combinations. DUNLAP, J. M., GDDY, A. T. Region 1, Office of Director. 83/05/18 3pp. 18695 035 24X Fiche 50-244, 83/05/20, 8306020400

8306020427 Forwards IE Insp Rept 50-244/83-06 on 830331-0401 No noncompliance noted. MARTIN, T. T. Division of Engineering & Technical Programs. 83/05/20 MAIER, J. E. Rochester Gas & Electric Corp. 2pp 18694 113 24X
Fiche 50-244, 83/05/20, 8306020427

--8306020434 IE Insp Rept 50-244/83-06 on 830331-0401 No noncompliance noted. Major areas inspected 830331 personnel injury event, including personnel exposure, notifications, high radiation area control, individual work hours & training. NIMITZ, R. L., SHANBAKY, M. M. Region 1, Office of Director. 83/05/13 8pp 18694 115 24X Fiche 50-244, 83/05/20, 8306020427

8306020458 Forwards IE Insp Rept 50-244/83-07 on 830411-15 No noncompliance noted. MARTIN, T. T. Division of Engineering & Technical Programs. 83/05/20 MAIER, J. E. Rochester Gas & Electric Corp. 2pp. 18693 278 24X
Fiche: 50-244, 83/05/20, 8306020458

--8306020460 IE Insp Rept 50-244/83-07 on 830411-15 No noncompliance noted. Major areas inspected radiation protection program, including status of previously identified items, personnel selection, qualification & training & exposure controls. COLLINS, D. J., SHANBAKY, M. M. Region 1, Office of Director. 83/05/18 9pp 18693 280 24X Fiche 50-244, 83/05/20, 8306020458

8306020079 Forwards visual aids used at 830512 & 20 meetings re steam generator sleeving & B&W proprietary "Ginna Sleeving Repair - Spring 1983 Steam Generator Rapid Sleeving Program" Rept withheld (ref 10CFR2.790). MAIER, J. E. Rochester Gas & Electric Corp. 83/05/24 CRUTCHFIELD, D. Operating Reactors Branch 5. 35pp 18691 135. 24X
Fiche: 50-244, 83/05/24, 8306020079

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl. TAYLOR, J. M. Division of Safeguards & Inspection Programs (Post 830103) 83/05/26. Consolidated Edison Co. of New York, Inc. 128pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc. 118pp. 18732:085 24X Fiche 50-000, 83/05/26, 8305110460

8306020074 Notification of 830601 significant licensee meeting in King of Prussia, PA to discuss enforcement issues. KESTER, H. B. Region 1, Office of Director. 83/05/26. Region 1, Office of Director. 1p 18701:336 24X Fiche. 50-244, 83/05/26, 8306020074

8306060036 Specifies provisions incorporated into procedures re NRC positions for SEP Topic III-3 C, "Inservice Insp of Water-Control Structures" Topic detailed in final integrated plant BAR, NUREG-0821. MAIER, J. E. Rochester Gas & Electric Corp. 83/05/26 CRUTCHFIELD, D. Operating Reactors Branch 5. 2pp. 18723 298. 24X
Fiche: 50-244, 83/05/26, 8306060036.

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31. Consolidated Edison Co. of New York, Inc. 116pp. 18732:208 24X Fiche 50-000, 83/05/31, 8305110461

DOCKETED ITEMS

37

8306160361 Forwards IE Insp Rept 90-244/83-10 on 830408-0507 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 83/05/31
MAIER, J E Rochester Gas & Electric Corp 2pp 18860 076 24X
Fiche 90-244, 83/05/31, 8306160361

--8306160369 Notice of violation from insp on 830408-0507
* Region 1, Office of Director 83/05/31 1p 18860 078 24X
Fiche 90-244, 83/05/31, 8306160361

--8306160372 IE Insp Rept 90-244/83-10 on 830408-0507 Noncompliance noted failure to perform surveillance testing specified in inservice pump & valve test program
ZIMMERMAN, R P Region 1, Office of Director KISTER, H B Division of Project & Resident Programs 83/05/25 11pp 18860 079 24X Fiche 90-244, 83/05/31, 8306160361

8306140025 Responds to IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators " Backflow test performed on 830420 No leakage indicated integrity of valve internals confirmed
MAIER, J E Rochester Gas & Electric Corp 83/06/08 ALLAN, J M Region 1, Office of Director 3pp 18838 231 24X
Fiche 90-244, 83/06/08, 8306140025

8306210015 Responds to IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators " Inservice test program will be modified to include leak testing to confirm integrity of valve internals during each refueling shutdown
MAIER, J E Rochester Gas & Electric Corp 83/06/08 ALLAN, J M Region 1, Office of Director 3pp 18912 280 24X
Fiche: 90-244, 83/06/08, 8306210015

8306230195 Forwards IE Insp Rept 90-244/83-11 on 830502-06 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/06/08 MAIER, J E Rochester Gas & Electric Corp 2pp 18946 352 24X
Fiche 90-244, 83/06/08, 8306230195

--8306230197 IE Insp Rept 90-244/83-11 on 830502-06 No noncompliance noted Major areas inspected, actions taken to comply w/ NUREG-0737, Item II B 2 re design review of plant shielding
BAUNACK, W H , EAPEN, P K Region 1, Office of Director KISTER, H B Division of Project & Resident Programs 83/06/07 7pp 18946 354 24X Fiche 90-244, 83/06/08, 8306230195

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Bvc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 117pp 18830 280 24X Fiche 90-000, 83/06/09, 8305110464

8306140410 Documents tube R34C54 removal from D steam generator 2 hot leg Results of BMJ analyses will be submitted in Fall 1983. Sequence of events & eddy current insp results encl
MAIER, J E Rochester Gas & Electric Corp. 83/06/10 CRUTCHFIELD, D Operating Reactors Branch 5 10pp 18838, 081 24X
Fiche 90-244, 83/06/10, 8306140410

8306150309 Responds to IE Bulletin 83-05, "ASME Nuclear Code Pumps & Spare Parts Mfg by Hayward Tyler Pump Co " Subj pumps not used at facility.
MAIER, J E Rochester Gas & Electric Corp 83/06/10 ALLAN, J M Region 1, Office of Director. 1p. 10049:204 24X
Fiche 90-244, 83/06/10, 8306150309

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Bvc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 110pp. 18920 225 24X Fiche 90-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Bvc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001, 24X Fiche 90-000, 83/06/13, 8306090010.

8306150013 Advises that tubesheet sleeving of no more than 30 tubes acceptable repair technique per inservice insp program Safety evaluation encl
CRUTCHFIELD, D Operating Reactors Branch 5 83/06/13 MAIER, J E Rochester Gas & Electric Corp. 2pp. 18846, 328 24X
Fiche 90-244, 83/06/13, 8306150013

--8306150014 Safety evaluation accepting tubesheet sleeving of no more than 30 tubes as repair technique per inservice insp program
* Office of Nuclear Reactor Regulation, Director. 83/06/13 4pp 18846, 330 24X Fiche 90-244, 83/06/13, 8306150013

8306220022 Discusses steam generator sleeving eddy current exam. Util pursuing improvements in techniques w/goal of improving sensitivity by mixing frequencies for unwanted signal suppression & alternate probe designs
MAIER, J E Rochester Gas & Electric Corp 83/06/14. CRUTCHFIELD, D Operating Reactors Branch 5 1p 18930 211 24X
Fiche 90-244, 83/06/14, 8306220022

8306230317 Forwards IE Enforcement Conference Rept 90-244/83-16 on 830601 & notice of violation re improper post-maint test for containment personnel hatch, noted in IE Insp Rept 90-244/83-05 W/o notice of violation
STAROSTECKI, R Division of Project & Resident Programs 83/06/21 MAIER, J E Rochester Gas & Electric Corp 2pp 18944 166 24X
Fiche 90-244, 83/06/21, 8306230317

--8306230322 IE Enforcement Conference Rept 90-244/83-16 on 830601 Major areas discussed failure to perform proper post-maint testing on containment personnel hatch.
ZIMMERMAN, R P Region 1, Office of Director KISTER, H B Division of Project & Resident Programs 83/06/16 3pp. 18944, 168 24X Fiche 90-244, 83/06/21, 8306230317.

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers." Bvc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 115pp 19021 179 24X Fiche 90-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment." Bvc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 120pp. 18997, 007 24X Fiche 90-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Bvc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242, 24X Fiche. 90-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints." Bvc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc 116pp 19046, 297 24X Fiche 90-000, 83/06/24, 8305110483

R Periodic operating reports & related correspondence

8306020274 Monthly operating rept for Mar 1983 W/830404 ltr.
MCNAMARA, A E , SNOW, B A Rochester Gas & Electric Corp. 83/04/04 7pp 18690 298 24X Fiche. 90-244, 83/04/04, 8306020274.

8306160485 Monthly operating rept for Apr 1983 W/830506 ltr
SNOW, B A , MCNAMARA, A E Rochester Gas & Electric Corp 83/05/06 Office of Management and Program Analysis. 6pp 18864 128, 24X
Fiche 90-244, 83/05/06, 8306160485

8306020451 "Annual Rept of Facility Changes, Tests & Experiments Conducted W/o Prior Approval & Challenges to Primary & Secondary Sys PDRVs & Safety Valves, 1981 "
MAIER, J E Rochester Gas & Electric Corp. 83/05/20 ALLAN, J M Region 1, Office of Director 22pp. 18693 348 24X
Fiche 90-244, 83/05/20, 8306020451.

8306020453 "Annual Rept of Facility Changes, Tests & Experiments Conducted W/o Prior Approval & Challenges to Primary & Secondary Sys PDRVs & Safety Valves, 1982."
MAIER, J E Rochester Gas & Electric Corp 83/05/20 ALLAN, J M Region 1, Office of Director 32pp 10693, 306 24X
Fiche 90-244, 83/05/20, 8306020453.

S Reportable occurrences, LERs & related correspondence

8306170201 LER 83-018/03L-0 on 820126, RCB average temp reduced to less than 350 F & both reactor coolant pumps inoperable. Caused by personnel failure to incorporate Tech Spec. W/830527 ltr.
MEYER, T A , MAIER, J E Rochester Gas & Electric Corp. 83/05/27, ALLAN, J M Region 1, Office of Director 4pp. 18877, 020, 24X
Fiche 90-244, 83/05/27, 8306170201

8306210034 LER 83-017/03L-0 on 830501, RHR pumps A & B took suction from refueling water storage tank (RUWT) for filling reactor refueling cavity RHR pump stopped & flow dropped to zero Caused by power failure to MCC D circuit W/830531 ltr.
LARIZZA, G F , MAIER, J E Rochester Gas & Electric Corp. 83/05/31, ALLAN, J M Region 1, Office of Director. 3pp 18912, 288, 24X
Fiche 90-244, 83/05/31, 8306210034.

DOCKETED ITEMS

V Operator Examinations

8306140243 Requests attendance at 830627 meeting in King of Prussia, PA to discuss transfer of reactor operator licensing function from Bethesda, MD to Region I ofc
STAROSTECKI, R. Division of Project & Resident Programs 83/06/09
MAIER, J E Rochester Gas & Electric Corp 2pp 18833 003 24X
Fiche 50-244, 83/06/09, 8306140243

DOCKET 50-245 MILLSTONE NUCLEAR POWER STATION, UNIT 1F Security, medical, emergency & fire protection plans

8306070136 Forwards Rev 16 to modified amended security plan, Rev withheld (ref 10CFR2 790 & 10CFR73 21)
COUNSIL, W O Northeast Nuclear Energy Co. (subs. of Northeast Utilities) COUNSIL, W O, Northeast Utilities 83/05/12
ALLAN, J H Region I, Office of Director, ip 18739, 215 24X
Fiche 50-245, 83/05/12, 8306070136

8306090238 Forwards IE Insp Repts 50-245/83-11 & 50-336/83-13 on 830417-0507 No noncompliance noted
STAROSTECKI, R. Division of Project & Resident Programs 83/05/27
COUNSIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities), 2pp. 18795 299. 24X Fiche: 50-245, 83/05/27, 8306090238

--8306090241 IE Insp Repts 50-245/83-11 & 50-336/83-13 on 830417-0507 No noncompliance noted. Major areas inspected evaluations of plant operations, startup testing, equipment alignments & readiness, radiation protection & physical security
SHELDON, J T, LIPINSKI, D R. Region I, Office of Director
ELSAESSER, J C. Division of Project & Resident Programs 83/05/20, 17pp. 18795:301. 24X Fiche: 50-245, 83/05/27, 8306090238

8306200307 Ack receipt of 830225 & 0415 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts
50-245/83-01 & 50-336/83-01 Confirms understanding that uninterrupted power supply sys was operable by 830501.
MARTIN, T T. Division of Engineering & Technical Programs 83/06/15.
COUNSIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 18900 164 24X Fiche: 50-245, 83/06/15, 8306200307

--8306200313 Responds to NRC ltr re violations noted in IE Insp Repts 50-245/83-01 & 50-336/83-01 Forwards info requested during IE security insp info withheld (ref 10CFR73.21 & 10CFR2.790).
COUNSIL, W O. Northeast Nuclear Energy Co. (subs of Northeast Utilities). COUNSIL, W O. Northeast Utilities. 83/02/25.
HAYNES, R C Region I, Office of Director, ip 18900:166 24X
Fiche: 50-245, 83/06/15, 8306200307.

--8306200322 Responds to NRC ltr re violation noted in IE Insp Repts 50-245/83-01 & 50-336/83-01. Forwards info requested during IE security insp info withheld (ref 10CFR73.21 & 10CFR2.790).
COUNSIL, W O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, W O. Northeast Utilities 83/04/15
ALLAN, J H Region I, Office of Director, ip. 18900 167. 24X
Fiche: 50-245, 83/06/15, 8306200307.

H General correspondence

8306060090 Requests rev to "cc" distribution list for NHR correspondence reflecting position & title changes within units.
COUNSIL, W O. Connecticut Yankee Atomic Power Co. COUNSIL, W O. Northeast Utilities COUNSIL, W O. Northeast Nuclear Energy Co (subs. of Northeast Utilities). 83/05/31 CLARK, R A Operating Reactors Branch 3. CRUTCHFIELD, D Operating Reactors Branch 5 3pp. 18719:360. 24X Fiche: 50-000, 83/05/31, 8306060090

I Financial information

8304110936 Forwards financial info for Connecticut Light & Power Co & Western Massachusetts Electric Co for 1982. Rept for Northeast Nuclear Energy Co will be available on or about 830415.
BIBBOP, R M. Northeast Utilities. 83/04/05. Office of Nuclear Reactor Regulation, Director. 71pp. 17916:248. 24X
Fiche: 50-245, 83/04/05, 8304110936

P. Operating license stage documents & correspondence

8306060031 Addl response to FOIA request for three categories of documents re PRA of reactor safety study methodology application program repts & interim reliability evaluation program repts. Forwards App A documents. Search continuing.
FELTON, J M. Division of Rules and Records. 83/04/07. SHOLLY, B C. Union of Concerned Scientists. 3pp 18782:001. 24X
Fiche: 50-000, 83/04/07, 8306060031.

--8211220332 Forwards "Effect of Resolution of Millstone Unit 1 SEP Issues on Probabilistic Calculations of Risk" & risk-based perspective of selected SEP issues
ERNST, M L. Assistant Director for Technology Review 82/11/15
MIRAGLIA, F. Assistant Director for Safety Assessment 12pp
18752 079. 24X Fiche 50-000, 83/04/07, 8306060031

--8211220337 "Effect of Resolution of Millstone Unit 1 SEP Issues on Probabilistic Calculations of Risk"
SPULAK, R O. STACK, D. AHIC, P. Science Applications, Inc
BAND82-2429 82/11/15 NRC - No Detailed Affiliation Given
108pp 18752 091 24X Fiche 50-000, 83/04/07, 8306060031

--8306060061 Statement on background, issues, current status & future action re interim & natl reliability evaluation programs
* NRC - No Detailed Affiliation Given 82/12/31 2pp
18752 039 24X Fiche 50-000, 83/04/07, 8306060031

8305310226 INTERIM RELIABILITY EVALUATION PROGRAM ANALYSIS OF THE MILLSTONE POINT UNIT 1 NUCLEAR POWER PLANT Docket No 50-245 (Northeast Utilities)
CURRY, J J, GALLAGHER, D W, MODARRES, M Sandia Laboratories FIN A-1241 NUREG/CR-3083 Vol. 83/04/30 Division of Risk Analysis 201pp 18682 277 24X Fiche 50-245, 83/04/30, 8305310226

8306010340 Forwards Rev 13 to corporate organization for nuclear incidents procedures manual table of contents & Rev 3 to CONI 4 02. "On-Call Manager of Radiological Consequence Assessment, Responsibilities & General Guidelines" W/O encl
COUNSIL, W O, BEARS, C F Connecticut Yankee Atomic Power Co
COUNSIL, W O. Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/05/18 EISENHUT, D O Division of Licensing 1p
18682 271 24X Fiche 50-000, 83/05/18, 8306010340

8306080058 Forwards info re environ qualification of electrical equipment, including in-containment environ svc conditions, methods used to identify equipment per 10CFR50 49(b)(2) & preventative maint program
COUNSIL, W O, BEARS, C F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W O Northeast Utilities 83/05/20
EISENHUT, D O Division of Licensing 419pp 18775 116 24X
Fiche 50-245, 83/05/20, 8306080058

8306060207 Notifies that Apr 1983 rept. "Shaking-Table Testing for Seismic Evaluation of Electrical Raceway Bys." applicable to facilities for SEP Topic 11-6 re seismic design NUREG-0824 & NUREG-0826 commitments partially satisfied
COUNSIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W O Connecticut Yankee Atomic Power Co
COUNSIL, W O Northeast Utilities 83/05/26 CRUTCHFIELD, D Operating Reactors Branch 5 1p 18727 295 24X
Fiche 50-000, 83/05/26, 8306060207

8306090232 Advises that NUREG-0824, Section 4 1.6 concerns resolved, based on util 830113 response, per SEP Topic 11-3 D 1. "Capability of Operating Plant to Cope W/Design Basis Flooding Conditions" Procedure OP 514A revised by 830729
COUNSIL, W O Northeast Nuclear Energy Co (subs. of Northeast Utilities) COUNSIL, W O Northeast Utilities 83/06/03
CRUTCHFIELD, D Operating Reactors Branch 5 2pp 18795 344 24X
Fiche 50-245, 83/06/03, 8306090232

8306160283 Notice of consideration of issuance of amendments to Licenses DPR-21 & DPR-65 & proposed no significant hazards consideration determination & opportunity for hearing
CLARK, R A Operating Reactors Branch 3 83/06/03 10pp
18993:010 24X Fiche 50-245, 83/06/03, 8306160283

8306080198 Informs that requirements of TMI Item II B 2.2, "Design Review of Plant Shielding & Environ Qualification of Equipment for Spaces/Bys Which May Be Used in Post-Accident Operations," met
CRUTCHFIELD, D. Operating Reactors Branch 5 83/06/07 COUNSIL, W O Northeast Nuclear Energy Co. (subs of Northeast Utilities) 6pp
18772 233 24X Fiche 50-245, 83/06/07, 8306080198

8306090267 Forwards safety evaluation of BWR Owners Group response to NUREG-0737, Item II K 3 1B, "Mod of Automatic Depressurization Sys Logic..." Acceptable options include elimination of high drywell pressure permissive
CRUTCHFIELD, D Operating Reactors Branch 5 83/06/08 COUNSIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp.
18795 280 24X Fiche 50-245, 83/06/08, 8306090267

--8306090272 Safety evaluation of BWR Owners Group response to NUREG-0737, Item II K 3 1B, "Mod of Automatic Depressurization Sys Logic..." Acceptable options include elimination of high drywell pressure permissive.
* Office of Nuclear Reactor Regulation, Director 83/06/08 5pp
18795:282 24X Fiche 50-245, 83/06/08, 8306090267

8306130356 Forwards safety evaluation supporting util decision not to reroute reactor water cleanup sys return line per NUREG-0619 Decision based on value-impact analysis & sleeve leakage measurements
SHEA, J J Operating Reactors Branch 5 83/06/09 COUNCIL, W O
Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp
18822 153 24X Fiche 50-245, 83/06/09, 8306130356

--8306130358 Safety evaluation supporting util decision not to reroute reactor water cleanup sys return line per NUREG-0619 Decision based on value-impact analysis & sleeve leakage measurements
* Office of Nuclear Reactor Regulation, Director 83/06/09 2pp
18822 155 24X Fiche 50-245, 83/06/09, 8306130356

8306160412 Forwards draft Rev 5 to "QA Program Topical Rept."
COUNCIL, W O Northeast Utilities Service Co COUNCIL, W O
Northeast Utilities 83/06/09 MURLEY, T E Region I, Office of
Director 6pp 18859 090 24X Fiche 50-000, 83/06/09, 8306160412

--8306160424 Draft Rev 5 to "QA Program Topical Rept."
* Northeast Utilities 83/06/09 135pp 18859 096 24X
Fiche 50-000, 83/06/09, 8306160412

8306230289 Forwards addl info per TMI Item II K 3 28 re qualification of automatic depressurization sys accumulators, in response to NRC 830218 request W/two oversize drawings Aperture cards are available in PDR
COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/06/15 CRUTCHFIELD, D Operating Reactors Branch 5
19pp 18942 108 24X Fiche 50-245, 83/06/15, 8306230289

8306240200 Forwards listed revs to Corporate Organization for Nuclear Incidents procedure manual, per Section V of App E to 10CFR50 W/o encl
COUNCIL, W O Connecticut Yankee Atomic Power Co COUNCIL, W O
Northeast Nuclear Energy Co (subs of Northeast Utilities)
COUNCIL, W O Northeast Utilities 83/06/17 EIGENHUT, D O
Division of Licensing 2pp 18980 263 24X Fiche 50-000, 83/06/17, 8306240200

8306280534 Forwards proprietary Suppl 7 to "STR Bundle Submittal Millstone-1, Segmented Test Rod Bundle," updating 741003 reprinter Release 2 license amend 00 Sherwood Affidavit encl Rept withheld (ref 10CFR2 790).
COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W O Northeast Utilities 83/06/17,
CRUTCHFIELD, D Operating Reactors Branch 5 5pp 19016, 292, 24X
Fiche 50-245, 83/06/17, 8306280534

8306280412 Forwards response to 830422 request for addl info re Rev 1 to NUREG-0313 concerning leakage detection sys
COUNCIL, W O Northeast Nuclear Energy Co (subs. of Northeast Utilities) COUNCIL, W O Northeast Utilities 83/06/21
CRUTCHFIELD, D Operating Reactors Branch 5 95pp 19020 188 24X
Fiche 50-245, 83/06/21, 8306280412

8306280321 Discusses impact of NUREG-0824, SEP Topic III-4 B, "Turbine Missiles," on control valve surveillance testing program No changes to current testing program warranted. Item closed.
COUNCIL, W O Northeast Nuclear Energy Co (subs. of Northeast Utilities) COUNCIL, W O Northeast Utilities 83/06/22
CRUTCHFIELD, D Operating Reactors Branch 5 2pp 19001 312, 24X
Fiche 50-245, 83/06/22, 8306280321

8306280478 Provides info re SEP Topic VI-4, "Containment Isolation Sys," to resolve concern raised by NUREG-0824, "Integrated Plant Safety Assessment," for which NRC unable to determine adequacy of penetrations X-211A & X-204
COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W O Northeast Utilities 83/06/22,
CRUTCHFIELD, D Operating Reactors Branch 5 2pp 19018 313, 24X
Fiche 50-245, 83/06/22, 8306280478

8306300140 Informs that addl nondegree personnel will be assigned to shift technical advisor position per NUREG-0737, Item I A 1 1 Info re experience, college educ & current operator licenses encl
COUNCIL, W O Northeast Nuclear Energy Co (subs. of Northeast Utilities) COUNCIL, W O Northeast Utilities 83/06/22,
CRUTCHFIELD, D Operating Reactors Branch 5 CLARK, R A Operating Reactors Branch 3, 3pp, 19122 320, 24X Fiche 50-245, 83/06/22, 8306300140.

8306290406 Forwards safety evaluation of license compliance w/ NUREG-0737, Item II B.1, "RCB Vents," based on review of encl LLL technical evaluation rept. High point vents on primary coolant side of isolation condenser not required.
CRUTCHFIELD, D Operating Reactors Branch 5, 83/06/27 COUNCIL, W O
Northeast Nuclear Energy Co (subs. of Northeast Utilities) 6pp,
19053: 140 24X Fiche 50-245, 83/06/27, 8306290406.

--8306290413 "Selected Operating Reactor Issues Program II RCB Vents (NUREG-0737, Item II B.1)," final technical evaluation rept
HELD, J Y Energy Incorporated * Laurence Livermore Laboratory
FIN A-0250 TF-382/0823A 83/04/06 ALBERTHAL, O Division of
Licensing 4pp 19053 146 24X Fiche 50-245, 83/06/27, 8306290406

G Inspection reports, IE Bulletins & correspondence

8306060160 Forwards IE Insp Repts 50-245/83-06 & 50-336/83-08 on 830227-0416 & notice of violation
STAROSTECKI, R Region I, Office of Director 83/05/23
COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 18719 205, 24X Fiche 50-245, 83/05/23, 8306060160

--8306060165 Notice of violation from Insp on 830227-0416
* Region I, Office of Director 83/05/23, 1p 18719 207, 24X
Fiche 50-245, 83/05/23, 8306060160

--8306060171 IE Insp Repts 50-245/83-06 & 50-336/83-08 on 830227-0416 Noncompliance noted failure to maintain reactor power below 89% while monitoring core linear heat rate w/ex-core detector monitoring sys
SHEDLOSKEY, J T, LIPINSKI, D.R., ELBASSER, T C Region I, Office of
Director 83/05/21 19pp, 18719, 208, 24X Fiche 50-245, 83/05/23, 8306060160

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device," Svc list encl.
TAYLOR, M Division of Safeguards & Inspection Programs (Post 830103), 83/05/26 Consolidated Edison Co. of New York, Inc.
125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458.

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co. of New
York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8306090238 Forwards IE Insp Repts 50-245/83-11 & 50-336/83-13 on 830417-0507, No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/05/27
COUNCIL, W O Northeast Nuclear Energy Co (subs. of Northeast Utilities) 2pp, 18795, 299, 24X Fiche 50-245, 83/05/27, 8306090238.

--8306090241 IE Insp Repts 50-245/83-11 & 50-336/83-13 on 830417-0507, No noncompliance noted Major areas inspected: evaluations of plant operations, startup testing, equipment alignments & readiness, radiation protection & physical security.
SHEDLOSKEY, J T, LIPINSKI, D.R. Region I, Office of Director,
ELBASSER, T C Division of Project & Resident Programs 83/05/20,
17pp 18795 301 24X Fiche 50-245, 83/05/27, 8306090238.

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawal at BWRs" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103), 83/05/31 Consolidated Edison Co. of New
York, Inc. 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306170391 Responds to IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators." No check valves installed in loop of piping to diesel generators from svc water piping
COUNCIL, W O Northeast Nuclear Energy Co (subs. of Northeast Utilities) COUNCIL, W O Connecticut Yankee Atomic Power Co
COUNCIL, W O Northeast Utilities 83/05/31, MURLEY, T.E. Region I,
Office of Director 3pp 18880 240, 24X Fiche 50-000, 83/05/31, 8306170391

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations," Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/09 Consolidated Edison Co. of New
York, Inc. 117pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464.

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Mechanically Induced Chatter in Relays Within Printed Circuit Cards," Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103), 83/06/13 Consolidated Edison Co. of New
York, Inc 118pp, 18920, 225, 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co. of New
York, Inc. 243pp, 18921, 001, 24X Fiche 50-000, 83/06/13, 8306090010.

DOCKETED ITEMS

8306200307 Ack receipt of 830225 & 0415 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-245/83-01 & 50-336/83-01. Confirms understanding that uninterrupted power supply sys was operable by 830501. MARTIN, T. T. Division of Engineering & Technical Programs 83/06/15. COUNCIL, W. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 2pp 18900 164 24X Fiche 50-245, 83/06/15, 8306200307

--8306200313 Responds to NRC ltr re violations noted in IE Insp Repts 50-245/83-01 & 50-336/83-01. Forwards info requested during IE security insp. Info withheld (ref 10CFR73 21 & 10CFR2 790). COUNCIL, W. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) COUNCIL, W. O. Northeast Utilities 83/02/25 HAYNES, R. C. Region 1, Office of Director 1p 18900 165, 24X Fiche 50-245, 83/06/15, 8306200307.

--8306200322 Responds to NRC ltr re violation noted in IE Insp Repts 50-245/83-01 & 50-336/83-01. Forwards info requested during IE security insp. Info withheld (ref 10CFR73 21 & 10CFR2 790). COUNCIL, W. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) COUNCIL, W. O. Northeast Utilities 83/04/15. ALLAN, J. M. Region 1, Office of Director 1p 18900 167, 24X Fiche 50-245, 83/06/15, 8306200307

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Gaskets & Sealers." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/22 Consolidated Edison Co. of New York, Inc. 115pp. 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18977 007, 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/23 Consolidated Edison Co. of New York, Inc. 116pp. 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/24 Consolidated Edison Co. of New York, Inc. 116pp. 19046 277 24X Fiche 50-000, 83/06/24, 8305110483.

R. Periodic operating reports & related correspondence

8306020084 Monthly operating rept for Mar 1983 W/830415 ltr. HARRAN, O., MROCKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) MROCKA, E. J. Northeast Utilities 83/04/02 Office of Resource Management, Director 6pp 18691 210, 24X Fiche 50-245, 83/04/02, 8306020084.

8306160388 Monthly operating rept for Apr 1983 W/830512 ltr. HARRAN, O., MROCKA, E. J. Northeast Utilities. MROCKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 83/05/03. 6pp. 18861 132, 24X Fiche 50-245, 83/05/03, 8306160388.

8306060263 Documents understanding that 30-day extension for submittal of semiannual mail balance rept for Oct 1982 - Mar 1983 acceptable per 830427 & 0503 discussions. Extension necessary due to computer problems at OE. COUNCIL, W. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNCIL, W. O. Northeast Utilities 83/05/04. BURNETT, R. F. NRC - No Detailed Affiliation Given. 1p 18727 025, 24X Fiche 50-245, 83/05/04, 8306060263.

S. Reportable occurrences, LERs & related correspondence

8306010434 Updated LER 83-012/03X-1 on 830326, during repair of containment leakage. LPCI/CB valve permissive interlock switch valved out of svc. Caused by switch not restored to proper lineup after testing. W/830523 ltr. THULL, T. B., HERBERT, R. J., MROCKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 83/05/23. MURLEY, T. E. Region 1, Office of Director 3pp. 18674 131, 24X Fiche 50-245, 83/05/23, 8306010434.

8306020397 RO 83-02, on 830223, excessive levels of activity observed in sample of aerosols. Dose consequences evaluated for First Quarter 1983 by using effluent transport models. No operational corrective actions necessary. MROCKA, E. J., HERBERT, R. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). MROCKA, E. J. Northeast Utilities 83/05/24 MURLEY, T. E. Region 1, Office of Director 3pp. 18693 100 24X Fiche 50-245, 83/05/24, 8306020397.

8306030319 LER 83-017/03L-0 on 830502, during reactor low pressure pumpstart functional & calibr test, pressure switch 263-54A tripped at 379 psig. Caused by setpoint drift. Switch adjusted & tested satisfactorily W/830527 ltr. THULL, T. B., MROCKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) MROCKA, E. J. Northeast Utilities 83/05/27 MURLEY, T. E. Region 1, Office of Director 3pp. 18708 265 24X Fiche 50-245, 83/05/27, 8306030319

8306030326 LER 83-016/03L-0 on 830502, pressure switch 263-53A tripped at 1,109 psig, exceeding Tech Spec requirements of less than or equal to 1,085 psig. Caused by setpoint drift. Switch recalibr W/830527 ltr. THULL, T. B., MROCKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) MROCKA, E. J. Northeast Utilities 83/05/27 MURLEY, T. E. Region 1, Office of Director 3pp. 18708 268 24X Fiche 50-245, 83/05/27, 8306030326

8306170046 LER 83-019/03L-0 on 830503, during reactor low pressure valve permissive functional & calibr test, pressure switch 263-52A tripped at 364 psig. Caused by setpoint drift. Pressure switch adjusted to proper setpoint & tested W/830602 ltr. THULL, T. B., MROCKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) MROCKA, E. J. Northeast Utilities 83/06/02 MURLEY, T. E. Region 1, Office of Director 3pp. 18878 295 24X Fiche 50-245, 83/06/02, 8306170046

8306170300 RO 83-20/1P on 830607, crack indication identified on 1 x 6 inch weldolet weld. Weldolet supports nipple & flange to relief valve 1-CU-73. Investigation & encapsulation of weld for repair in progress. MROCKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) MROCKA, E. J. Northeast Utilities 83/06/08 MURLEY, T. E. Region 1, Office of Director 1p 18877 014, 24X Fiche 50-245, 83/06/08, 8306170300

8306270129 LER 83-021/031-0 on 830517, time delay relays 590-125A & B tripped at limits exceeding Tech Specs. Caused by tolerance established on surveillance data sheets less than setpoint accuracy of relays. Setpoints decreased W/830616 ltr. THULL, T. B., MROCKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) MROCKA, E. J. Northeast Utilities 83/06/16 MURLEY, T. E. Region 1, Office of Director 4pp. 18988 014 24X Fiche 50-245, 83/06/16, 8306270129

8306230001 PNS-I-83-015 on 830616, unannounced narcotics search of site initiated & one marijuana cigarette found in pocketbook belonging to contract security watchperson. Individuals employment terminated. MADDEN, H., ODDY, A., JOYNER, J. Region 1, Office of Director 83/06/17, 1p 18947 077 24X Fiche 50-245, 83/06/17, 8306230001

V. Operator Examinations

8306140453 Extends invitation to attend 830627 meeting in King of Prussia, PA to discuss transfer of reactor operator licensing function from Bethesda, MD to Region 1 ofc. BYAROSTECKI, R. Division of Project & Resident Programs 83/06/09 COUNCIL, W. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 2pp 18834 311 24X Fiche 50-245, 83/06/09, 8306140453

DOCKET 50-247 INDIAN POINT STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8306010365 Forwards IE Insp Rept 50-247/83-11 on 830405-0502 & notice of violation. BYAROSTECKI, R. Division of Project & Resident Programs 83/05/16 O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 3pp. 18682 073 24X Fiche 50-247, 83/05/16, 8306010365

--8306010370 Notice of violation from insp on 830405-0502 Safeguards info deleted (ref 10CFR73 21). * Region 1, Office of Director 83/05/16 1p 18682 076 24X Fiche 50-247, 83/05/16, 8306010365

--8306010378 IE Insp Rept 50-247/83-11 on 830405-0502 Noncompliance noted: failure to follow procedures Safeguards info deleted (ref 10CFR73 21). FOLEY, T., MOLTA, P. Region 1, Office of Director KISTER, H. B. Division of Project & Resident Programs 83/05/11, 14pp. 18682 077 24X Fiche 50-247, 83/05/16, 8306010365

8306090299 Confirms by ltr of intent, contract to make buses available during evacuation caused by radiological emergency. VHAAD, E. R. Consolidated Edison Co. of New York, Inc. * Power Authority of the State of New York. CORWIN, S. Affiliation Unknown 83/06/01. CORWIN, S. Affiliation Unknown 1p 18795 238 24X Fiche 50-247, 83/06/01, 8306090299

DOCKETED ITEMS

41

8306090317 Confirms, by ltr of intent, contract to make buses available during evacuation caused by radiological emergency
VHAAD, E R Consolidated Edison Co of New York, Inc BAYNE, J P
Power Authority of the State of New York * Affiliation Unknown
83/06/01 SILVANI, J Affiliation Unknown 1p 18793 230 24X
Fiche 50-247, 83/06/01, 8306090317

8306090325 Confirms, by ltr of intent, contract to make buses available during evacuation caused by radiological emergency
* Consolidated Edison Co of New York, Inc BAYNE, J P Power
Authority of the State of New York MURPHY, J Liberty Lines
Transit, Inc 83/06/02 MURPHY, J Liberty Lines Transit, Inc 1p
18795 069 24X Fiche 50-247, 83/06/02, 8306090325

8306090340 Confirms, by ltr of intent, contract to make buses available during evacuation caused by radiological emergency
* Consolidated Edison Co of New York, Inc BAYNE, J P Power
Authority of the State of New York * Riverdale Transit Corp
83/06/02 MURPHY, J Riverdale Transit Corp 1p 18794 321 24X
Fiche 50-247, 83/06/02, 8306090340

8306150206 Staff requirements memo re 830526 oral presentations in Bethesda, MD re emergency planning & preparedness at Indian
Point List of participants encl
CHILK, B J Office of the Secretary of the Commission 83/06/07
Office of the Secretary of the Commission 2pp 18870 045 24X
Fiche 50-247, 83/06/07, 8306150206

8306170396 Forwards FEMA 830608 ltr to NRC, providing current evaluation of plant offsite emergency planning
HASSELL, D F Hearing Branch 2 83/06/09 OLEASON, J P, SHON, F J,
PARIS, O H Atomic Safety and Licensing Board Panel 46pp
18879 333 24X Fiche 50-247, 83/06/09, 8306170396

8306200030 Staff requirements memo re 830607 discussion & vote in Washington, DC on continued operation of Indian Point
Commission agreed by vote of 3-2 to allow continued
operation
CHILK, B J Office of the Secretary of the Commission 83/06/14
Office of the Secretary of the Commission 1p 18908 356 24X
Fiche 50-247, 83/06/14, 8306200030

G Adjudicatory correspondence

8305160024 Forwards I Levi affidavit clarifying 830211 testimony on suggested method of making sensible probability judgments described in Section 5
HARTZMAN, R M Friends of the Earth 83/05/10 OLEASON, J P Atomic
Safety and Licensing Board Panel 1p 18452 353 24X
Fiche 50-247, 83/05/10, 8305160024

8306010451 Supports continued operation of facility Impact of shutdown would be devastating
O'SHAUGHNESSY Affiliation Unknown 83/05/20 PALLADINO, N J
Commissioners 2pp 18674 352 24X Fiche 50-247, 83/05/20,
8306010451

8306060180 Response opposing util 830509 motion for reconsideration Deposition inadmissible as evidence under federal rules
POBNER, P Parents Concerned About Indian Point 83/05/20 Atomic
Safety and Licensing Board Panel 3pp 18728 181 24X
Fiche 50-247, 83/05/20, 8306060180

8306010458 Requests extension of 830409 deadline for planners to provide adequate emergency evacuation Util acting in good faith in expressing concern for quality of life of community residents
BARNETT, T Affiliation Unknown 83/05/24 PALLADINO, N J
Commissioners 1p 18674 327 24X Fiche 50-247, 83/05/24,
8306010458

8306010348 Response supporting licensee 830509 motion for reconsideration of ruling on admissibility of DP McGuire disposition Admission of testimony would not prejudice parties w/ Certificate of Svc
HASSELL, D F Hearing Branch 1 83/05/31 Atomic Safety and
Licensing Board Panel 11pp, 18681 336 24X Fiche 50-247, 83/05/31,
8306010348

8306020443 Order requesting comments on encl rept re PRA by 830620.
OLEASON, J P Atomic Safety and Licensing Board Panel 83/05/31
Consolidated Edison Co of New York, Inc 1p, 18694 011 24X
Fiche 50-247, 83/05/31, 8306020443

--8306020448 Forwards final rept, "Analysis of PRA Testimony" Indian Point ASLB Hearings, Commission Question 1 " Rept conclusions coincide w/ conclusions in 830502 ltr
AMICO, P J Applied Risk Technology Corp 83/06/01 OLEASON, J P,
SHON, F J, PARIS, O H Atomic Safety and Licensing Board Panel,
1p 18694 012 24X Fiche 50-247, 83/05/31, 8306020443

--8306020452 "Analysis of PRA Testimony Indian Point ASLB Hearings, Commission Question 1," final rept
AMICO, P J Applied Risk Technology Corp ARTECH-83-001
83/06/01 NRC - No Detailed Affiliation Given 67pp
18694 013 24X Fiche 50-247, 83/05/31, 8306020443

8306200290 Affidavit of RA Rosen on Commission Question 6 3 EBR0 model underestimated average 1982 saltwater PHR capacity by 9.5X
Value of model should be assessed based on ability to track experience over period of time
ROSEN, R A Greater New York Council on Energy 83/05/31 5pp
18901 055 24X Fiche 50-247, 83/05/31, 8306200290

8306070414 Response opposing Friends of the Earth/New York City Audubon Soc request to file I Levi affidavit. Testimony by affidavit improper since no cross-examination possible Certificate of Svc encl
BRANDENBURG, B Consolidated Edison Co of New York, Inc.
COLARULLI, P F Power Authority of the State of New York
COLARULLI, P F Morgan Associates 83/06/03 Atomic Safety and
Licensing Board Panel 7pp 18742 244 24X Fiche 50-247, 83/06/03,
8306070414

8306070421 Expresses views on plant emergency preparedness in light of newly submitted state of NY interim plan Conceptual problems & inaccuracies identified in plan for implementing compensating measures for Rockland County
HOLT, J Public Interest Research Group, New York 83/06/03,
PALLADINO, N J, AHEARNE, J F, OILINSKY, V Commissioners 4pp,
18742 198 24X Fiche 50-247, 83/06/03, 8306070421

8306080200 Comments on "Governors Plan" prepared by NY State Disaster Commission Evaluation of wheelchair & bedridden patients & shelter for 1,200 mentally retarded patients overlooked
FLEISHER, Z S West Branch Conservation Association 83/06/06
PALLADINO, N, OILINSKY, V, AHEARNE, J F, Commissioners. 16pp,
18770 235 24X Fiche 50-247, 83/06/06, 8306080200

8306090359 Responds to Commission 830526 meeting questions & updates miscellaneous responses Record justifies continued plant operation Commission would be fully justified in suspending further enforcement action
CONWAY, J T Consolidated Edison Co of New York, Inc. BAYNE, J P,
Power Authority of the State of New York 83/06/07, PALLADINO, N J,
OILINSKY, V, AHEARNE, J F Commissioners. 3pp 18793 036 24X
Fiche 50-247, 83/06/07, 8306090359

8306090300 Recommendations for emergency planning process. Plans should originate at local govt level & should be supported & enforced at state & federal govt levels
* Public Interest Research Group, New York * Parents Concerned
About Indian Point 83/06/08, 2pp 18793 239, 24X
Fiche 50-247, 83/06/08, 8306090300

8306090308 Statement on role of federal, state & local govts & utils in planning, testing & executing emergency response procedures
HOLT, J Public Interest Research Group, New York 83/06/08, 3pp
18793 119 24X Fiche 50-247, 83/06/08, 8306090308

8306100086 Forwards evaluation of offsite emergency planning, providing factual basis for use in Commission 830609 licensing decision
BRAOQ, J S Federal Emergency Management Agency. 83/06/08
PALLADINO, N J Commissioners. 45pp, 18802 046 24X
Fiche 50-247, 83/06/08, 8306100086

8306100209 Memorandum & order denying licensee 830509 motion for reconsideration of ASLB 830429 ruling disallowing admission into evidence of DP McGuire deposition Federal rule inapplicable & no exceptional circumstances shown.
OLEASON, J P Atomic Safety and Licensing Board Panel 83/06/08,
Consolidated Edison Co of New York, Inc. 4pp 18809 202, 24X
Fiche 50-247, 83/06/08, 8306100209

8306130434 Order ruling I Levi affidavit, filed by Friends of the Earth & New York City Audubon Soc on 830510, inadmissible Affidavit provides add substantive testimony & will not be admitted unless witness available for cross-examination.
OLEASON, J P Atomic Safety and Licensing Board Panel, 83/06/09,
Friends of the Earth 2pp 18821 192 24X Fiche 50-247, 83/06/09,
8306130434

8306170372 Advises that NRC will file comments on Amico final rept. Separate comments on interim ltr rept will not be filed.
MOORE, J E Hearing Branch 1, 83/06/09, OLEASON, J P, SHON, F J,
PARIS, O H Atomic Safety and Licensing Board Panel, 1p 18880 210,
24X Fiche 50-247, 83/06/09, 8306170372

8306170396 Forwards FEMA 830608 ltr to NRC, providing current evaluation of plant offsite emergency planning.
HASSELL, D F Hearing Branch 2 83/06/09, OLEASON, J P, SHON, F J,
PARIS, O H Atomic Safety and Licensing Board Panel 46pp,
18879 333 24X Fiche 50-247, 83/06/09, 8306170396

DOCKETED ITEMS

8306150389 Response to ASLB consultant, PJ Amico, 830502 ltr re issues on accident probability requiring addl testimony. New York City Audubon Soc/Friends of the Earth comments endorsed Certificate of Bvc encl. WEISS, E R Union of Concerned Scientists WEISS, E R Public Interest Research Group, New York WEISS, E R. Harman & Weiss 83/06/10 7pp 18847.152 24X Fiche: 50-247, 83/06/10, 8306150389

8306150429 Advises that utils will respond to PJ Amico summary ltr rept & final rept on 830620.
BRANDENBURG, B Consolidated Edison Co. of New York, Inc.
COLARULLI, P F Morgan Associates. COLARULLI, P F Power Authority of the State of New York 83/06/10 QLEASON, J P, PARIS, O H, SHON, F J Atomic Safety and Licensing Board Panel 1p. 18847 089 24X Fiche 50-247, 83/06/10, 8306150429.

8306200324 Responds to P Amico 830502 ltr rept re recommendations for addl testimony on PRA Responing record on PRA would unduly prolong proceeding
HARTZMAN, R M. Friends of the Earth HARTZMAN, R M New York City Audubon Society. 83/06/10 QLEASON, J P, SHON, F J, PARIS, O H Atomic Safety and Licensing Board Panel. 2pp. 18901:018 24X Fiche 50-247, 83/06/10, 8306200324

8306230376 Response to PJ Amico 830502 ltr to ASLB & analysis of PRA testimony. Areas in which addl testimony recommended do not present issues materially affecting record & are too costly w/Certificate of Bvc
BRANDENBURG, B Consolidated Edison Co of New York, Inc
COLARULLI, P F Power Authority of the State of New York
COLARULLI, P F. Morgan Associates. 83/06/20 19pp 18943 258. 24X Fiche: 50-247, 83/06/20, 8306230376

8306240290 Response to ASLB consultant P Amico rept re addl testimony on Commission Question 1 No addl testimony necessary for complete record.
MOORE, J., MCQUARRIN, M. J Hearing Branch 1 83/06/20 15pp 18979:241. 24X Fiche. 50-247, 83/06/20, 8306240290

--8306240295 Affidavit of JF Meyer & RM Bernero re ASLB consultant P Amico 830601 rept. MARCH 1.1 Code used to assess core-melt accident progression & containment loading characteristics w/Prof qualifications
MEYER, J F Reactor Systems Branch BERNERD, R M Accident Source Term Program Office. 83/06/17 12pp 18979 256 24X Fiche 50-247, 83/06/20, 8306240290.

--8306240301 Affidavit of QB Varnado re ASLB consultant PJ Amico recommendation to provide expert testimony on risk significance of sabotage NRC studies & PRA do not estimate risk of sabotage Prof qualifications encl
VARNADO, Q B. Sandia Laboratories 83/06/07. 4pp. 18979 268. 24X Fiche. 50-247, 83/06/20, 8306240290.

--8306240305 Affidavit of HW Woods re ASLB consultant PJ Amico 830601 rept. Testimony on conditional probability of core melt & release due to pressurized thermal shock event unavailable. w/Prof qualifications & Certificate of Bvc
WOODS, H. W. NRC - No Detailed Affiliation Given 83/06/16. 7pp. 18979. 272. 24X Fiche 50-247, 83/06/20, 8306240290

8306230350 Motion for extension until 830711 to file proposed findings of fact. Time needed since intervenors filing consolidated findings & one Atty suffered death in family. Certificate of Bvc encl
WEISS, E. R. Union of Concerned Scientists. WEISS, E R. Harman & Weiss. 83/06/21 Atomic Safety and Licensing Board Panel 6pp. 18943.281. 24X Fiche: 50-247, 83/06/21, 8306230350.

8306230346 Motion for immediate reconsideration of Commission 830610 Order CLI-83-16 permitting continued plant operation
Commission did not consider current status of emergency planning in decision Certificate of Bvc encl
HOLT, V. Public Interest Research Group, New York 83/06/22 Commissioners. 12pp 18942:284 24X Fiche 50-247, 83/06/22, 8306230346.

8306270140 Order granting intervenor 830621 motion for extension of deadline until 830711 to file proposed findings Extension applies to all parties. Consolidation effort constructive
QLEASON, J P. Atomic Safety and Licensing Board Panel. 83/06/22 Union of Concerned Scientists. 2pp 19013 360 24X Fiche: 50-247, 83/06/22, 8306270140.

8306270160 Answer opposing intervenor motion for extension of time to submit proposed findings. Motion is attempt to delay hearings. If intervenor motion granted, exemption should apply to all parties. Certificate of Bvc encl.
BRANDENBURG, B. Consolidated Edison Co of New York, Inc.
COLARULLI, P F. Power Authority of the State of New York
COLARULLI, P F. Morgan Associates. 83/06/22. Atomic Safety and Licensing Board Panel. 6pp. 18992:037. 24X Fiche: 50-247, 83/06/22, 8306270160.

8306290550 Request 2-wk extension to file findings of fact for Commission Questions 3 & 4 Atty familiar w/case resigned
MILLER, F O Westchester County, NY 83/06/22 QLEASON, J P Atomic Safety and Licensing Board Panel 1p 17082 216 24X Fiche 50-247, 83/06/22, 8306290550

8306270159 Response supporting PIRG of NY motion for reconsideration of Commission 830609 decision, permitting facility operation w/o restriction despite continued noncompliance w/emergency planning requirements Certificate of Bvc encl
WEISS, E R Union of Concerned Scientists 83/06/23 Commissioners 6pp 18992 043 24X Fiche 50-247, 83/06/23, 8306270159

8306270267 Memorandum advising that ASLB will not reopen record to receive further testimony on Commission Question 1. ASLB consultant PJ Amico recommended addl testimony immaterial & covers topic sufficiently addressed or is unavailable
QLEASON, J P Atomic Safety and Licensing Board Panel 83/06/24 2pp 18990 202 24X Fiche 50-247, 83/06/24, 8306270267

H General correspondence

8306080171 Opposes facility shutdown
FRENCH, J F Affiliation Unknown 83/06/02 PALLADINO, N J Commissioners 1p 18770 234 24X Fiche 50-247, 83/06/02, 8306080171

8306200098 Requests NRC 830609 determination re facility DLs be reversed, per encl Rockland County Resolution 302 Request based on inability of FEMA to assure that public health & safety can be protected within 10-mile zone w/o stated encl
THOMSEN, E O, SCHOENDERGER, I Rockland County, NY 83/06/13 Office of Nuclear Reactor Regulation, Director 1p 18903 336 24X Fiche 50-247, 83/06/13, 8306200098

J Insurance & indemnity information

8306020318 Forwards Endorsements 134 & 118 to NELIA Policy NF-100 & MAELU Policy NF-29, respectively
DUJMAL, A Marsh & McLennan, Inc 83/05/26 BALTZMAN, J Assistant Director for State & License Relations 3pp 18694 273 24X Fiche 50-247, 83/05/26, 8306020318

P Operating license stage documents & correspondence

8306070343 Responds to Generic Ltr 82-16 re NUREG-0737 Tech Specs for listed TMI items Some Tech Specs incorporated, some not applicable & some unnecessary
O'TOOLE, J D Consolidated Edison Co of New York, Inc 83/05/31 EISENHUT, D Q Division of Licensing 6pp 18742 031 24X Fiche: 50-247, 83/05/31, 8306070343

8306200257 Forwards addl info in support of 830504 application for amend to License DPR-26, requesting changes to Tech Specs re reactor cavity level monitoring instrumentation info submitted in response to 830506 telcon
O'TOOLE, J D Consolidated Edison Co of New York, Inc 83/06/14 VARGA, B A Operating Reactors Branch 1 5pp 18901 179 24X Fiche 50-247, 83/06/14, 8306200257

Q Inspection reports, IE Bulletins & correspondence

8306010365 Forwards IE Insp Rept 50-247/83-11 on 830405-0502 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 83/05/16 O'TOOLE, J D. Consolidated Edison Co of New York, Inc 3pp 18682 073 24X Fiche 50-247, 83/05/16, 8306010365

--8306010370 Notice of violation from insp on 830405-0502 Safeguards info deleted (ref 10CFR73.21).
* Region 1, Office of Director 83/05/16 1p 18682 076 24X Fiche 50-247, 83/05/16, 8306010365

--8306010378 IE Insp Rept 50-247/83-11 on 830405-0502 Noncompliance noted failure to follow procedures Safeguards info deleted (ref 10CFR73.21)
FOLEY, T, KOLTAY, P Region 1, Office of Director. KIBTER, H B Division of Project & Resident Programs 83/05/11 14pp. 18682 077 24X Fiche 50-247, 83/05/16, 8306010365

8306010115 Ack receipt of 830416 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-247/83-05
HARYIN, T J Division of Engineering & Technical Programs. 83/05/25 O'TOOLE, J D. Consolidated Edison Co of New York, Inc 2pp 18673.342 24X Fiche. 50-247, 83/05/25, 8306010115

--8306010126 Responds to NRC 830317 ltr re violations noted in IE Insp Rept 50-247/83-03 Corrective actions cask handling procedure reviewed, approved & implemented & advance transport notification sent to governor Disputes Violation D
O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 83/04/16
MARTIN, T. T. Division of Engineering & Technical Programs 12pp
18673 344 24X Fiche 50-247, 83/05/25, 8306010115

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl
TAYLOR, J. M. Division of Safeguards & Inspection Programs (Post Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc. 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc. 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at DHRs" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc. 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc. 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8306170226 Ack receipt of 830525 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-247/83-10
STAROSTECKI, R. Division of Project & Resident Programs 83/06/10, O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 2pp 18882 290 24X Fiche 50-247, 83/06/10, 8306170226

--8306170230 Responds to NRC 830425 ltr re violations noted in IE Insp Rept 50-247/83-10 Corrective actions continuous fire watch established until investigation of alternate mats & feasibility of repairing penetration seals complete
O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 83/05/25
STAROSTECKI, R. Division of Project & Resident Programs 8pp 18882 292 24X Fiche 50-247, 83/06/10, 8306170226

8306230203 Forwards IE Insp Rept 50-247/83-12 on 830503-31, No noncompliance noted
STAROSTECKI, R. Division of Project & Resident Programs 83/06/10, O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 2pp 18945 283 24X Fiche 50-247, 83/06/10, 8306230203

--8306230212 IE Insp Rept 50-247/83-12 on 830503-31 No noncompliance noted Major areas inspected licensee action on previously identified insp findings, facility operations review, plant trips, TMI action items & surveillance
FOLEY, T. KOLTAI, P. Region I, Office of Director, COLLINS, B. Division of Project & Resident Programs, 83/06/07 14pp 18945 285 24X Fiche 50-247, 83/06/10, 8306230203

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc. 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc. 243pp 18921 001, 24X Fiche 50-000, 83/06/13, 8306090010

8306240225 Responds to IE Bulletin 83-03, "Check Valve Failure in Raw Water Cooling Sys of Diesel Generators" No check valves in svc water sys leading to or exiting from diesel generators Bulletin not applicable
O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 83/06/17, DEYOUNG, R. Director's Office, Office of Inspection and Enforcement 1p 18980 236 24X Fiche 50-247, 83/06/17, 8306240225

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18997 007, 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co. of New York, Inc. 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc. 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

R Periodic operating reports & related correspondence

8306020276 Monthly operating rept for Mar 1983 W/830415 ltr
EICH, E., O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 83/04/04 8pp 18690 290 24X Fiche 50-247, 83/04/04, 8306020276

8306160462 Monthly operating rept for Apr 1983 W/830315 ltr
EICH, E., O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 83/05/04 MCDONALD, W. Q. Office of Resource Management, Director, 12pp 18863 096 24X Fiche 50-247, 83/05/04, 8306160462

8306270171 Forwards revised pages to semiannual effluent & waste disposal repts for Jan-June 1982 & Jul-Dec 1982, re "Radiological Impact on Man" sections
O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 83/06/16
ALLAN, J. M. Region I, Office of Director, 1p 18991 358 24X Fiche 50-003, 83/06/16, 8306270171

--8306270179 Revised pages to semiannual effluent & waste disposal rept, Jan-June 1982
* Consolidated Edison Co. of New York, Inc. 83/06/16, 3pp 18991 359 24X Fiche 50-003, 83/06/16, 8306270171

--8306270184 Revised pages for semiannual effluent & waste disposal rept, Jul-Dec 1982
* Consolidated Edison Co. of New York, Inc. 83/06/16, 3pp 18991 362 24X Fiche 50-003, 83/06/16, 8306270171

S Reportable occurrences, LERs & related correspondence

8306170415 LER 83-012/03L-0 on 830419, reactor cavity continuous sump level monitor LI-3302 indicated above 20-Ft but independent cavity level alarm did not annunciate Reactor cavity found dry Caused by instrument drift W/830519 ltr.
MOONEY, J. P., O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 83/05/19 HURLEY, T. E. Region I, Office of Director, 3pp 18879 004 24X Fiche 50-247, 83/05/19, 8306170415

8306170323 LER 83-020/03L-0 on 830420, high steam flow bistable FC449A setpoint found higher than Tech Spec limit Caused by defective internal dc power supply board. Board replaced & bistable reset
MOONEY, J. P., O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 83/05/20 ALLAN, J. M. Region I, Office of Director, 2pp 18878 244 24X Fiche 50-247, 83/05/20, 8306170323

8306170405 LER 83-013/03L-0 on 830420, during surveillance testing of containment isolation valves, valve 1702 did not fully close Cause not stated Shaft & inside of actuator cleaned Air motor diaphragm replaced as preventive measure W/830520 ltr.
HINRICH, G., O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 83/05/20 HURLEY, T. E. Region I, Office of Director, 2pp 18879 318 24X Fiche 50-247, 83/05/20, 8306170405

8306170044 LER 83-014/03L-0 on 830421, charging pump R1 developed leak & declared inoperable Caused by defective head gasket on cylinder head 4. Gasket replaced
HINRICH, G., O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 83/05/21 ALLAN, J. M. Region I, Office of Director, 2pp 18878 293 24X Fiche 50-247, 83/05/21, 8306170044

8306170189 LER 83-017/03L-0 on 830422, leak observed in isolation valve seal water sys. Caused by damage to 3/8-inch stainless steel weld connection FW10016, Weld repaired W/830522 ltr.
HINRICH, G., O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 83/05/22 ALLAN, J. M. Region I, Office of Director, 2pp 18878 327 24X Fiche 50-247, 83/05/22, 8306170189

8306170197 LER 83-021/03L-0 on 830422, analysis revealed adsorption efficiency for methyl iodine of 82 %. Cause under investigation. Charcoal filters replaced W/830522 ltr.
HINRICH, G., O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 83/05/22 ALLAN, J. M. Region I, Office of Director, 3pp 18878 321 24X Fiche 50-247, 83/05/22, 8306170197

DOCKETED ITEMS

8306170271 LER 83-019/03L-0 on 830422, valve 743, nonautomatic containment isolation valves in RHR pump miniflow line would not operate Cause not stated Reach rods disconnected & valve stem & universal joints cleaned & lubricated. W/830522 ltr. HENRICH, D., O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 83/05/22 ALLAN, J. M. Region I, Office of Director 3pp 18978 252. 24X Fiche 50-247, 83/05/22, 8306170271

8306170397 LER 83-016/03L-0 on 830422, boron injection tank level channel 944F became inoperable Caused by erroneous level indication due to boric acid solidification in instrument impulse line Affected impulse line cleaned. W/830522 ltr. MOONEY, J. P., O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 83/05/22 ALLAN, J. M. Region I, Office of Director 2pp 18979 017. 24X Fiche 50-247, 83/05/22, 8306170397.

8306170410 LER 83-018/03L-0 on 830422, plant shutdown commenced when binding of valve 1870 could not be corrected within Tech Spec time period. Cause not stated. Binding alleviated by lubricating valve stem & universal joints. W/830522 ltr. HENRICH, D., O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 83/05/22 ALLAN, J. M. Region I, Office of Director 2pp 18979 025. 24X Fiche 50-247, 83/05/22, 8306170410.

8306170200 LER 83-015/03L-0 on 830427, shutdown initiated when containment spray pump 21 did not meet operability criteria Repairs not completed within allowable time period Caused by high vibrations. Pump replaced W/830527 ltr. HENRICH, D., O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 83/05/27 ALLAN, J. M. Region I, Office of Director 3pp 18978 224. 24X Fiche 50-247, 83/05/27, 8306170200.

8306230349 PNO-I-83-065 on 830617, contract between util & Util Workers of America Local 1-2 expired Union/agt turnover conducted w/o incident Reverification of sys linups & insp of equipment completed Media attention evident. GREENMAN, E. O. Region I, Office of Director. 83/06/20 1p 18973 280. 24X Fiche 50-247, 83/06/20, 8306230349

T Hearing transcripts on non-antitrust matters

8306020709 Transcript of Commission 830525 meeting in Washington, DC, re emergency planning & preparedness Pp 1-117. Supporting documentation encl. * Commissioners 83/05/26 236pp. 18716:001. 24X Fiche 50-247, 83/05/26, 8306020709

8306090347 Statement before House of Representatives Subcommittee on Energy Conservation & Power re emergency planning Public must be involved in planning & testing process. * Parents Concerned About Indian Point 83/06/08, 4pp. 18794 336. 24X Fiche 50-247, 83/06/08, 8306090347

8306090350 Testimony of J Holt, K Toscani & P Posner before House of Representatives Subcommittee on Energy Conservation & Power re public role in planning, testing & implementing emergency response procedures. HOLT, J. Public Interest Research Group, New York. TOSCANI, K., POSNER, P. Parents Concerned About Indian Point. 83/06/08 24pp. 18794 340. 24X Fiche 50-247, 83/06/08, 8306090350

8306180300 Transcript of 830609 Commission discussion & vote on emergency planning deficiencies at Indian Point in Washington, DC Pp 1-24. * Commissioners 83/06/09 30pp 18868:249. 24X Fiche 50-247, 83/06/09, 8306180300

8306200342 Forwards corrections to special proceeding transcripts. BRANDENBURG, B. Power Authority of the State of New York. COLARULLI, P. F. Consolidated Edison Co. of New York, Inc. COLARULLI, P. F. Morgan Associates 83/06/15 GLEASON, J. P., PARIS, D. H., SHON, F. J. Atomic Safety and Licensing Board Panel 1p. 18900:211. 24X Fiche 50-247, 83/06/15, 8306200342

8306200346 Corrections to special proceeding transcripts. * Power Authority of the State of New York * Consolidated Edison Co. of New York, Inc. 83/06/15. 52pp 18900 212. 24X Fiche 50-247, 83/06/15, 8306200346

8306240018 Transcript of Commission 830617 briefing on Indian Point leak issues in Washington, DC, Pp 1-44. * Commissioners 83/06/17 47pp. 18987:293. 24X Fiche 50-247, 83/06/17, 8306240018

U Congressional/Executive Correspondence

8306030156 Responds to 830506 request for clarification of 830513 order re consideration of views of public & parties to special proceeding in 830609 decision Comments from Licenses.govt agencies & public invited. PALLADINO, N. J. Commissioners 83/05/12 OTTINGER, H. L. House of Rep., Energy & Commerce 2pp 18733 324. 24X Fiche 50 247, 83/05/12, 8306030156

8306030158 Requests Commission 830505 order be revised to address Pats for parties to safety investigation views on shutdown New requested by 830511 OTTINGER, R. L. House of Rep., Energy & Commerce 11/05/14 PALLADINO, N. Commissioners. 2pp 18733 320. 24X Fiche 50-247, 83/05/12, 8306030158

V. Operator Examinations

8306140370 Extends invitation to attend 830627 meeting in King of Prussia, PA to discuss transfer of reactor operator licensing function from Bethesda, MD to Region I of STAROBTECH, N. Division of Project & Resident Programs 830614 O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 2pp 18932 112. 24X Fiche 50-247, 83/06/09, 8306140370

DOCKET 50-249 DRESDEN NUCLEAR POWER PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8306210314 FOIA request for NRC records re security violations & safeguards events at nuclear facilities. GOLDENBERG, O. Scripps-Howard Newspapers 01/04/22 18716:001. 24X Office of Administration 2pp 18725 176. 24X Fiche 50-000, 83/04/22, 8306210314

8306210306 Partial response to FOIA request for NRC records re security violations & safeguards events at nuclear facilities Repts listed on App A available in PDF Search for addl documents subj to request continuing. FELTON, J. M. Division of Rules and Records 83/05/16. 018742822 5. Scripps-Howard Newspapers. 2pp 18725 176. 24X Fiche 50-000, 83/05/16, 8306210306

8306090247 Confirms 830601 telcon re changes to exercise windows for Dresden & Byron Nuclear Power Stations Dresden partial exercise will be conducted during wk of 830712 w/Byron full-scale exercise beginning wk of 831114 JONES, E. E. Illinois, State of. 83/06/01 KEPLER, J. Region 3, Office of Director. ANDERSON, J. Federal Emergency Management Agency. WAGNER, O. Commonwealth Edison Co. 1p 18795 314. 24X Fiche 50-000, 83/06/01, 8306090247.

8306210355 Releases public version of revised emergency plan implementing procedure. FELTON, J. M. Division of Rules and Records. 83/06/06. Document Management Branch. 1p 18935 293. 24X Fiche 50-010, 83/06/06, 8306210355

8306210357 Public version of Rev 1 to Emergency Plan Implementing Procedure EPIP 300-12, "Initiation of Environ Monitoring Activities by Rad/Chem Director." Receipt form encl. W/830516 ltr. SCOTT, D. J. Commonwealth Edison Co. 83/05/11 DENTON, H. H. Office of Nuclear Reactor Regulation, Director 19pp 18935 294. 24X Fiche 50-010, 83/06/06, 8306210357

8306100218 Responds to IE Insp Repts 50-010/83-01, 50-237/83-01 & 50-249/83-01. Corrective action surveillance notification program developed for annual distribution of public info brochures on emergency planning. FARRAR, D. L. Commonwealth Edison Co. 83/06/07. PAPERIELLO, C. J. Region 3, Office of Director. 4pp. 18005 110. 24X Fiche 50-010, 83/06/07, 8306100218.

8306160214 Submits correction to 830601 ltr Date of reassessment will be made prior to 830801, not 831001. JONES, E. E. Illinois, State of. 83/06/09 KEPLER, J. Region 3, Office of Director. ANDERSON, J. Federal Emergency Management Agency. WAGNER, O. Commonwealth Edison Co. 1p 18861 350. 24X Fiche 50-000, 83/06/09, 8306160214.

P. Operating license stage documents & correspondence

8306090194 Discusses util interpretation of 10CFR80.49, "Environ Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants." Intent of rulemaking is to require upgrade program for replacement equipment not parts. FARRAR, D. L. Commonwealth Edison Co. 83/06/03. DENTON, H. H. Office of Nuclear Reactor Regulation, Director. 3pp 18796 090. 24X Fiche 50-000, 83/06/03, 8306090194.

DOCKETED ITEMS

45

8306140108 Forwards evaluation of BWR Owners Group generic response to NUREG-0737, Item 11 K 3 18, "Mod of Automatic Depressurization Sys Logic-Feasibility for Increased Diversity for Some Event Sequences " Two options listed CRUTCHFIELD, D. Operating Reactors Branch 5 83/06/03 FARRAR, D L Commonwealth Edison Co 2pp 18837 354 24X Fiche 50-237, 83/06/03, 8306140108

8306090227 Informs that response to Generic Ltr 83-08 will be submitted by 830713 Info will include stress repts to determine mod to vacuum breakers on Mark I containments RYBAK, B Commonwealth Edison Co 83/06/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18796 234 24X Fiche 50-000, 83/06/06, 8306090227

8306160233 Advises that manufacturers whose repts were used in technical evaluation repts re environ qualification of electrical equipment have been contacted List of proprietary pages detailed in util 830513 ltr W/OC affidavit RYBAK, B Commonwealth Edison Co 83/06/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 18861 304 24X Fiche 50-000, 83/06/06, 8306160233

8306130226 Application for amend to License DPR-25, proposing changes to Tech Spec Tables 3.6.1.a & b re safety-related hydraulic & mechanical snubbers, respectively Changes have no effect on piping stresses Amend fee encl RYBAK, B Commonwealth Edison Co 83/06/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18824 311 24X Fiche 50-249, 83/06/07, 8306130226

--8306130230 Proposed Tech Spec Tables 3.6.1.a & b re safety-related hydraulic & mechanical snubbers, respectively * Commonwealth Edison Co 83/06/07 2pp 18824 312 24X Fiche 50-249, 83/06/07, 8306130226

8306130254 Confirms 830610 meeting in Glen Ellyn, IL to discuss design data supporting analysis indicating that missing snubber on torus was not significant item NORELUB, C E Division of Project & Resident Programs 83/06/07 REED, C Commonwealth Edison Co 1p 18823 319 24X Fiche 50-249, 83/06/07, 8306130254

8306100128 Forwards safety evaluation & technical evaluation repts, "Monitoring of Electric Power to Reactor Protection Sys for Dresden Nuclear Power Station Units 2 & 3 " Proposed mods acceptable CRUTCHFIELD, D. Operating Reactors Branch 5 83/06/09 FARRAR, D L Commonwealth Edison Co 3pp 18801 181 24X Fiche 50-237, 83/06/09, 8306100128

--8306100131 Safety evaluation re monitoring of electric power to reactor protection sys Proposed mods providing automatic protection of sys components from sustained abnormal power supply acceptable * Office of Nuclear Reactor Regulation, Director, 83/06/09 2pp. 18801, 184 24X Fiche 50-237, 83/06/09, 8306100128

--8306100135 "Monitoring of Electric Power to Reactor Protection Sys for Dresden Nuclear Power Station Units 2 & 3," technical evaluation repts BELAN, J C Lawrence Livermore Laboratory FIN A-0250 UCID-17708 83/05/18 NRC - No Detailed Affiliation Given 9pp 18801 184 24X Fiche 50-237, 83/06/09, 8306100128

8306240030 Application to amend License DPR-19 & DPR-25, extending time limits for inoperability of ECCB ring header snubbers Also updates Unit 3 Tables 3.6.1.2 & b to reflect changes in type of snubbers installed RYBAK, B Commonwealth Edison Co, 83/06/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18981 095, 24X Fiche 50-237, 83/06/13, 8306240030

--8306240035 Proposed Tech Specs extending time limits for inoperability of ECCB ring header snubbers & updating Unit 3 Tables 3.6.1.a & b to reflect type of snubbers installed. * Commonwealth Edison Co, 83/06/13 20pp 18981 097 24X Fiche 50-237, 83/06/13, 8306240030

Q Inspection reports, IE Bulletins & correspondence

8306220218 Ack receipt of 830414 payment of proposed civil penalties. Response to notice of violation & proposed imposition of civil penalties will be evaluated & corrective actions examined during future insps. AXELRAD, J A Enforcement Staff 83/04/21, REED, C Commonwealth Edison Co 2pp. 18950 357 24X Fiche 50-000, 83/04/21, 8306220218

8305260238 Responds to violations noted in IE Insp Repts 50-237/83-08 & 50-249/83-07 Corrective actions radiation protection mgt personnel increased surveillance of respiratory devices & addl radiation control technician added FARRAR, D L Commonwealth Edison Co 83/05/20 KEPPLER, J O Region 3, Office of Director 5pp 18977 355 24X Fiche 50-237, 83/05/20, 8305260238

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet." Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8306100101 Forwards IE Insp Repts 50-237/83-13 & 50-249/83-11 on 830426 No noncompliance noted LITTLE, W S Region 3, Office of Director 83/05/27 REED, C Commonwealth Edison Co 2pp 18802 332 24X Fiche 50-237, 83/05/27, 8306100101

--8306100105 IE Insp Repts 50-237/83-13 & 50-249/83-11 on 830426, No noncompliance noted Major areas inspected, licensee action re IE Bulletin 80-11, "Masonry Wall Design " NORTON, J F, WILLIAMS, C C Region 3, Office of Director 83/05/27, 4pp 18802 334 24X Fiche 50-237, 83/05/27, 8306100101

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl. JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31, Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306130338 Confirms plan discussed on 830601 for 830620 enforcement conference to discuss post-maint problems & significance of missing snubber on torus NORELUB, C E Division of Project & Resident Programs, 83/06/03, REED, C, Commonwealth Edison Co, 1p 18823 001 24X Fiche 50-237, 83/06/03, 8306130338

8306100149 Forwards Rev 3 to "180-Day Rept in Response to IE Bulletin 80-11 for Dresden 2 & 3 & Quad Cities 1 & 2." RYBAK, B Commonwealth Edison Co 83/06/06, KEPPLER, J O, Region 3, Office of Director 2pp 18804, 141 24X Fiche 50-000, 83/06/06, 8306100149

--8306100156 Rev 3 to "180-Day Rept in Response to IE Bulletin 80-11 for Dresden 2 & 3 & Quad Cities 1 & 2 " * Commonwealth Edison Co, 83/05/09, 129pp, 18804:143, 24X Fiche 50-000, 83/06/06, 8306100149

8306100094 Forwards response to IE Bulletin 83-03 re diesel generator cooling water check valves. Plants utilize Mission Duo-Check valves employing hinge-to-pin design for protection against vibration-induced failure. BARNES, P. L. Commonwealth Edison Co 83/06/07, KEPPLER, J O Region 3, Office of Director 7pp 18802 238 24X Fiche 50-000, 83/06/07, 8306100094

8306100218 Responds to IE Insp Repts 50-010/83-01, 50-237/83-01 & 50-249/83-01 Corrective action: surveillance notification program developed for annual distribution of public info brochures on emergency planning FARRAR, D L. Commonwealth Edison Co 83/06/07, PAPERIELLO, C J, Region 3, Office of Director 4pp. 18805, 113 24X Fiche 50-010, 83/06/07, 8306100218

8306170380 Forwards response to IE Bulletin 83-03 re diesel generator cooling water check valves Valves at Dresden & LaBelle acceptable w/o further insp. Rept on valve failures at Quad Cities will be submitted within 90 days of insp completion. BARNES, P. L. Commonwealth Edison Co, 83/06/07, KEPPLER, J O, Region 3, Office of Director 7pp. 18880 211, 24X Fiche 50-000, 83/06/07, 8306170380

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations." Svc list encl. JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09, Consolidated Edison Co. of New York, Inc 117pp. 18830, 280, 24X Fiche 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Electrically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13, Consolidated Edison Co of New York, Inc 118pp. 18920:225 24X Fiche 50-000, 83/06/13, 8305110470

DOCKETED ITEMS

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/06/13 Consolidated Edison Co. of New York, Inc. 24pp. 18921 001. 24X Fiche 50-000, 83/06/13, 8306090010

8306300235 Forwards IE Insp Repts 50-237/83-12, 50-249/83-10, 50-254/83-13 & 50-263/83-11 on 820412-14 & 0506 & 16 & notice of violation.
LITTLE, W.B. Region 3, Office of Director 83/06/16 REED, C
Commonwealth Edison Co 2pp 19122.279 24X Fiche 50-000, 83/06/16, 8306300235.

--8306300238 Notice of violation from insp on 830412-14 & 0506 & 16
LITTLE, W.B. Region 3, Office of Director, 83/06/16 2pp.
19122.281 24X Fiche 50-000, 83/06/16, 8306300238

--8306300246 IE Insp Repts 50-237/83-12, 50-249/83-10, 50-254/83-13 & 50-263/83-11 on 830412-14 & 0506 & 16. Noncompliance noted: as-built configuration (for pipe anchor R133 in pressure suppression sys) differed from original design.
YIM, I.T., DANIELSON, D.H. Region 3, Office of Director, 83/06/15 9pp 19122.283 24X Fiche 50-000, 83/06/16, 8306300235

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Gaskets & Sealers." Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/06/22 Consolidated Edison Co. of New York, Inc. 115pp. 19021 179. 24X Fiche: 50-000, 83/06/22, 8305110475.

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp. 18997.007. 24X Fiche. 50-000, 83/06/22, 8305110477.

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/06/23 Consolidated Edison Co. of New York, Inc. 116pp. 18996.242. 24X Fiche. 50-000, 83/06/23, 8305110479.

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/06/24 Consolidated Edison Co. of New York, Inc. 116pp 19046.297. 24X Fiche. 50-000, 83/06/24, 8305110483

R. Periodic operating reports & related correspondence

8306130275 "Semiannual Rept of Radioactive Effluents 1982 " W/830302 ltr.
SCOTT, D.J. Commonwealth Edison Co 83/03/02 KEPLER, J.Q. Region 3, Office of Director. 20pp. 18923.277 24X Fiche 50-010, 83/03/02, 8306130275.

8306140086 Monthly operating repts for May 1983 W/830601 ltr.
SCHROEDER, B.A., SCOTT, D.J. Commonwealth Edison Co. 83/06/01.
Director's Office, Office of Inspection and Enforcement 18pp. 18838.347. 24X Fiche. 50-237, 83/06/01, 8306140086.

8306130434 Forwards corrected "1981 Rept of Occupational Personnel Radiation Doses - Contract Workers," per Reg Guide 1.14
Number of people per manrem should be listed in maint not engineering category.
WAGNER, O.P. Commonwealth Edison Co. 83/06/07. KEPLER, J.Q. Region 3, Office of Director 1p. 18921.179. 24X Fiche: 50-010, 83/06/07, 8306130434

--8306130457 Forwards corrected "1981 Rept of Occupational Personnel Radiation Doses - Contract Workers," per Reg Guide 1.14
Number of people per manrem should be listed in maint not engineering category.
WAGNER, O.P. Commonwealth Edison Co. 83/06/06. KEPLER, J.Q. Region 3, Office of Director. 1p. 18921.180. 24X Fiche: 50-010, 83/06/07, 8306130454

--8306130460 Corrected "1981 Rept of Occupational Personnel Radiation Doses - Contract Workers." *
Commonwealth Edison Co 83/06/06. 9pp. 18921.181 24X Fiche: 50-010, 83/06/07, 8306130454.

S. Reportable occurrences, LERs & related correspondence

8306070234 Updated LER 81-033/01X-1 on 811023, Unit 2/3 diesel generator (D/O) tripped due to high cooling water temp & Unit 3 D/O manually tripped during testing. Caused by failure of cooling water pump discharge valve W/830523 ltr
HOLLAND, P., SCOTT, D.J. Commonwealth Edison Co 83/05/23
KEPLER, J.Q. Region 3, Office of Director 4pp 18746 142 24X Fiche 50-249, 83/05/23, 8306070234

8306070279 LER 83-018/03L-0 on 830502, LPCI core spray pump pressure alarm annunciator & cleared after close signal sent to core spray valve MD 1402-25A, tripping indicating lights & breaker. Caused by incorrect trip setting W/830531 ltr
ANANDAPPA, A., SCOTT, D.J. Commonwealth Edison Co 83/05/31
KEPLER, J.Q. Region 3, Office of Director 3pp 18744 083 24X Fiche 50-249, 83/05/31, 8306070279

8306130346 LER 83-017/03L-0 on 830504, after actuation of HPCI deluge sys, weight releasing lever of deluge valve tripped. Probably caused by misaligned trip linkage. Solenoid & valve linkage disassembled/assembled w/no anomalies noted W/830531 ltr
MERRITT, B., SCOTT, D.J. Commonwealth Edison Co 83/05/31
KEPLER, J.Q. Region 3, Office of Director 3pp 18822 212 24X Fiche 50-249, 83/05/31, 8306130346

8306130325 LER 83-021/01T-0 on 830523, differential pressure switches PS 1349A & B actuated above Tech Spec limit. Caused by instrument drift. Switches reset. Trip point repeatability verified W/830601 ltr
CHRISTEL, B., SCOTT, D.J. Commonwealth Edison Co 83/06/01
KEPLER, J.Q. Region 3, Office of Director 4pp 18822 193 24X Fiche 50-249, 83/06/01, 8306130325

8306170409 LER 83-019/03L-0 on 830521, MSIV 203-1B found w/closure time of 2.7 s exceeding Tech Spec limit of 3 to 5 s. Caused by misadjustment to timing mechanism on MSIV-203-1B MSIV adjusted within Tech Spec limits W/830608 ltr
MAXWELL, D.C. Commonwealth Edison Co 83/06/01 KEPLER, J.Q. Region 3, Office of Director 3pp 18879 320 24X Fiche 50-249, 83/06/01, 8306170409

8306270111 Updated LER 83-003/03X-1 on 830105, pinhole leak found on connecting pipe weld between 3-1201-10 inch A & 3-1292-2 inch line A of water cleanup sys. Probably caused by intergranular stress corrosion cracking W/830603 ltr
MERRITT, B., SCOTT, D.J. Commonwealth Edison Co 83/06/03
KEPLER, J.Q. Region 3, Office of Director 3pp 18988 094 24X Fiche. 50-249, 83/06/03, 8306270111

8306270083 LER 83-020/03L-0 on 830521, when control rod drive (CRD) 0-6 pulled from core after scram & addl withdrawal signal applied, overtravel alarm came up & position indication lost. Caused by detached CRD inner filter W/830613 ltr
WHALEN, R.J., SCOTT, D.J. Consolidated Edison Co. of New York, Inc 83/06/13 KEPLER, J.Q. Region 3, Office of Director 3pp 19012 122 24X Fiche 50-249, 83/06/13, 8306270083

8306270282 Potential Part 21 rept re discrepancy in welding of turnbuckle assembly, turnbuckle-belt interfaces & on top plate assembly variable springs 8A307 Grade B bolts not ASME Section IX matl investigation underway.
KARAIANIS, J.A. Elcon Metal Products Co 83/06/17 KEPLER, J.Q. Region 3, Office of Director 2pp 18996.207 24X Fiche 50-000, 83/06/17, 8306270282

DOCKET 50-250 TURKEY POINT PLANT, UNIT 3

F. Security, medical, emergency & fire protection plans

8306070050 Forwards IE Safeguards Insp Repts 50-250/83-17 & 50-251/83-17 on 830420-22, 0502-05 & 10-12 No noncompliance noted
DANCE, H.C. Division of Project & Resident Programs 83/06/01.
UHRIG, R.E. Florida Power & Light Co 2pp 18740 053 24X Fiche 50-250, 83/06/01, 8306070050

--8306070061 IE Safeguards Insp Repts 50-250/83-17 & 50-251/83-17 on 830420-22, 0502-05 & 10-12 No noncompliance noted. Major areas inspected, licensee investigation of two closed valves in auxiliary feedwater sys. Details withheld (ref IOCFR73.21)
TOBIN, W. Region 2, Office of Director MCGUIRE, D.R. Division of Emergency Preparedness & Materials Safety 83/05/31 1p. 18740.055 24X Fiche 50-250, 83/06/01, 8306070050

8306130435 Forwards, for review, Rev 1 to 830408 fire protection rept. Rev provides specific info & justification for IOCFR50, App R, exemption requests. Exemptions unnecessary for Fire Areas/ Zones D, E, G2, B7, 91 & 92
UHRIG, R.E. Florida Power & Light Co 83/06/06 EISENHUT, D.Q. Division of Licensing 1p 18821.036 24X Fiche 50-250, 83/06/06, 8306130435

DOCKETED ITEMS

47

--B306130441 Rev 1 to "Fire Protection Rept "
 * Florida Power & Light Co 83/06/30 14pp 18821 037 24X
 Fiche 50-250,83/06/06,8306130435

B306230371 Confirms recent conversations w/util re control of access
 into containment during shutdown Security plan changes
 requested within 60 days of ltr receipt Safeguards info
 withheld (ref 10CFR73 21)
 VARQA,B A Operating Reactors Branch 1 83/06/20 UHRIO,R E
 Florida Power & Light Co 1p 18744 135 24X Fiche 50-250,
 83/06/20,8306230371

J Insurance & indemnity information

B306010398 Forwards Endorsement 65 to NELIA Policy NF-185 & Endorsement
 55 to MAELU Policy NF-55
 DUCK,J R Marsh & McLennan, Inc 83/05/20 SALTZMAN,J Assistant
 Director for State & License Relations 3pp 18682 237 24X
 Fiche 50-250,83/05/20,8306010398

B306230125 Forwards Endorsement 66 to NELIA Policy NF-185 & Endorsement
 56 to MAELU Policy NF-55
 DUCK,J R Marsh & McLennan, Inc 83/06/16, SALTZMAN,J Assistant
 Director for State & License Relations 3pp 18947 054 24X
 Fiche 50-250,83/06/16,8306230125

P Operating license stage documents & correspondence

B306030056 Ack receipt of B21027 application & B30307 rev re proposed
 revised pump & valve inservice test program Remittance of
 Class III & I fees requested
 D1008,R M License Fee Management Branch 83/05/27 UHRIO,R.E.
 Florida Power & Light Co 1p 18733 203 24X Fiche 50-250,
 83/05/27,8306030056

B306090352 Application for amend to Licenses DPR-31 & DPR-41, revising
 Tech Specs to support fuel design change from Westinghouse
 low parasitic fuel assembly to optimized fuel assembly & use
 of new Westinghouse wet annular burnable absorber rods
 UHRIO,R.E. Florida Power & Light Co 83/06/03 EISENHUT,D O
 Division of Licensing 3pp 18795 003 24X Fiche 50-250,83/06/03,
 8306090352

--B306090355 Proposed Tech Specs supporting fuel design change from
 Westinghouse low parasitic fuel assembly to optimized fuel
 assembly & use of new Westinghouse wet annular burnable
 absorber rods
 * Florida Power & Light Co. 83/06/03, 21pp, 18795 004, 24X
 Fiche 50-250,83/06/03,8306090352

B306160335 Forwards response to B30422 request for addl info re
 Criteria 2,10 & 11 of NUREG-0737, Item II B 3, "Post-Accident
 Sampling." Interim core damage estimate guidelines will be
 submitted by B30630
 UHRIO,R E Florida Power & Light Co 83/06/10 VARQA,B A
 Operating Reactors Branch 1 3pp, 18861 171, 24X
 Fiche 50-250,83/06/10,8306160335

Q Inspection reports, IE Bulletins & correspondence

B306140577 Confirms mgt meeting on B30316 at Region II ofc to discuss
 recent insp findings re failure to properly evaluate
 radiation exposures at facility. Proposed meeting agenda
 encl
 O'REILLY,J P. Region 2, Office of Director 83/03/15, UHRIO,R.E.
 Florida Power & Light Co. 2pp 18844:160 24X
 Fiche:50-250,83/03/15,8306140577.

B306140393 Confirms B30428 enforcement meeting at Region II ofcs to
 discuss recent incident of unavailability of auxiliary
 feedwater w/Unit 3 operating at full power, per B30422
 telcon. Proposed agenda encl
 O'REILLY,J P Region 2, Office of Director. 83/04/26. UHRIO,R E
 Florida Power & Light Co. 2pp, 18832:096, 24X
 Fiche:50-250,83/04/26,8306140393.

B305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in
 Well Logging Device " Svc list encl.
 TAYLOR,J.M Division of Safeguards & Inspection Programs (Post
 B30103), 83/05/26, Consolidated Edison Co. of New York, Inc.
 125pp 18831.043. 24X Fiche:50-000,83/05/26,8305110458.

B305110460 IE Info Notice 83-34, "Event Notification Info Worksheet."
 Svc list encl.
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post B30103), 83/05/26 Consolidated Edison Co. of New
 York, Inc 115pp, 18732:085 24X Fiche.50-000,83/05/26,8305110460.

B305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods
 Withdrawn at UMRs " Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) 83/05/31 Consolidated Edison Co. of New
 York, Inc 116pp 18732 208 24X Fiche 50-000,83/05/31,8305110461.

B306290204 Forwards IE Insp Repts 50-250/83-13 & 50-251/83-13 on
 B30503-06 No noncompliance noted
 DANCE,H C Region 2, Office of Director 83/05/31 UHRIO,R.E.
 Florida Power & Light Co 2pp 19056:229 24X
 Fiche 50-250,83/05/31,8306290204

--B306290212 IE Insp Repts 50-250/83-13 & 50-251/83-13 on B30503-06 No
 noncompliance noted Major areas inspected:containment
 integrated leakage rate testing
 BROOKS,E., JAPE,F Region 2, Office of Director 83/05/24, App
 19056 231 24X Fiche 50-250,83/05/31,8306290204

B306070050 Forwards IE Safeguards Insp Repts 50-250/83-17 &
 50-251/83-17 on B30420-22,0502-05 & 10-12 No noncompliance
 noted
 DANCE,H C Division of Project & Resident Programs 83/06/01.
 UHRIO,R E Florida Power & Light Co 2pp 18740:053 24X
 Fiche 50-250,83/06/01,8306070050

--B306070061 IE Safeguards Insp Repts 50-250/83-17 & 50-251/83-17 on
 B30420-22,0502-05 & 10-12 No noncompliance noted. Major areas
 inspected licensee investigation of two closed valves in
 auxiliary feedwater sys Details withheld (ref 10CFR73.21)
 TOBIN,W. Region 2, Office of Director MCQUIRE,D R. Division of
 Emergency Preparedness & Materials Safety. 83/05/31 1p.
 18740 055 24X Fiche 50-250,83/06/01,8306070050

B306080003 Forwards util response to Enforcement Action B3-31 & payment
 of proposed civil penalty
 O'REILLY,J.P Region 2, Office of Director. 83/06/03 DEYOUNG,R C
 Director's Office, Office of Inspection and Enforcement 1p.
 18772 354 24X Fiche 50-250,83/06/03,8306080003

--B306080004 Responds to NRC proposed civil penalty re violations noted
 in IE Insp Repts 50-250/83-06 & 50-251/83-06 Corrective
 actions:operating instructions revised detailing duties
 during outage & nonoutage conditions for technicians
 UHRIO,R E Florida Power & Light Co 83/06/01, O'REILLY,J.P.
 Region 2, Office of Director. 8pp, 18772:355, 24X
 Fiche 50-250,83/06/03,8306080003.

B306290398 Responds to IE Bulletin 83-03, "Check Valve Failures in Raw
 Water Cooling Sys of Diesel Generators " Closed cooling
 radiator sys contains no check valves. Bulletin not
 applicable.
 UHRIO,R.E. Florida Power & Light Co. 83/06/08 O'REILLY,J P
 Region 2, Office of Director 2pp, 19052:183, 24X
 Fiche.50-000,83/06/08,8306290398

B305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe
 Operations " Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) 83/06/09 Consolidated Edison Co. of New
 York, Inc. 119pp, 18830:280, 24X Fiche.50-000,83/06/09,8305110464.

B305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive &
 Mechanically Induced Chatter in Relays Within Printed
 Circuit Cards " Svc list encl
 JORDAN,E.L. Division of Emergency Preparedness & Engineering
 Response (Post B30103) 83/06/13, Consolidated Edison Co. of New
 York, Inc 118pp 18920:225, 24X Fiche: 50-000,83/06/13,8305110470.

B306090010 IE Info Notice 83-37, "Transformer Failure Resulting From
 Degraded Internal Connection Cables " Svc list encl.
 JORDAN,E.L. Division of Emergency Preparedness & Engineering
 Response (Post B30103) 83/06/13, Consolidated Edison Co. of New
 York, Inc. 243pp, 18921.001, 24X Fiche:50-000,83/06/13,8306090010.

B306290341 Ack receipt of B30512 ltr informing NRC of steps taken to
 correct violations noted in IE Insp Repts 50-250/83-07 &
 50-251/83-07.
 LEWIS,R C. Division of Project & Resident Programs. 83/06/16.
 UHRIO,R.E. Florida Power & Light Co 1p 19055:245, 24X
 Fiche.50-250,83/06/16,8306290341

--B306290345 Responds to NRC B30411 ltr re violations noted in IE Insp
 Repts 50-250/83-07 & 50-251/83-07 Corrective actions
 requests for relief from ASME Code requirements will be
 documented prior to insp. Disputes noncompliance for Unit 4.
 UHRIO,R.E. Florida Power & Light Co 83/05/12, O'REILLY,J.P.
 Region 2, Office of Director. 4pp, 19055.246, 24X
 Fiche.50-250,83/06/16,8306290341.

DOCKETED ITEMS

--B306290349 Forwards IE Insp Repts 50-250/83-07 & 50-251/83-07 on B30315-18 & notice of violation
DANCE, H. C. Division of Project & Resident Programs B3/04/11
UHRIG, R. E. Florida Power & Light Co 2pp 19055 250 24X
Fiche: 50-250, 83/06/16, B306290341

--B306290354 Notice of violation from insp on B30315-18
* Region 2, Office of Director B3/04/11, 2pp 19055 252 24X
Fiche 50-250, 83/06/16, B306290341

--B306290357 IE Insp Repts 50-250/83-07 & 50-251/83-07 on B30315-18
Noncompliance noted pump & valve inservice testing &
component inservice insp not performed per ASME Boiler &
Pressure Vessel Code, Section XI.
KLEINBORGE, W. P., BLAKE, J. J. Region 2, Office of Director
B3/04/07 9pp 19055-254 24X Fiche: 50-250, 83/06/16, B306290341.

B305110475 IE Info Notice B3-40, "Need to Environmentally Qualify
Epoxy Grouts & Sealers." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post B301031) B3/06/22 Consolidated Edison Co. of New
York, Inc 11pp 19021 179 24X Fiche: 50-000, 83/06/22, B305110475

B305110477 IE Info Notice B3-41, "Actuation of Fire Suppression Sys
Causing Inoperability of Safety-Related Equipment." Svc list
encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post B301031) B3/06/22 Consolidated Edison Co. of New
York, Inc 12pp 18997-007 24X Fiche: 50-000, 83/06/22, B305110477.

B305110479 IE Info Notice B3-42, "Reactor Mode Switch Malfunctions"
Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post B301031) B3/06/23 Consolidated Edison Co. of New
York, Inc 11pp 18996-242 24X Fiche: 50-000, 83/06/23, B305110479.

B305110483 IE Info Notice B3-43, "Improper Settings of Intermediate
Range (IR) High Flux Trip Setpoints." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post B301031) B3/06/24 Consolidated Edison Co. of New
York, Inc 11pp 19046-297 24X Fiche: 50-000, 83/06/24, B305110483

R Periodic operating reports & related correspondence

B306020216 Monthly operating repts for Mar 1983, W/B30415 1tr.
PACE, P. L., WILLIAMS, J. W. Florida Power & Light Co B3/04/15,
Office of Resource Management, Director 13pp. 18690 256 24X
Fiche 50-000, 83/04/15, B306020216

B306160638 Monthly operating repts for Apr 1983, W/B30516 1tr
PACE, P. L., WILLIAMS, J. W. Florida Power & Light Co B3/05/16,
Office of Resource Management, Director 17pp. 18866.105 24X
Fiche 50-000, 83/05/16, B306160638

S Reportable occurrences, LERs & related correspondence

B306210071 RD on B30516, several fire barrier penetrations breached for
longer than 7 days. Caused by implementation of design
changes, including new computer room & auxiliary power
upgrade. Hourly fire watch established
UHRIG, R. E. Florida Power & Light Co B3/06/16, DENTON, H. R. Office
of Nuclear Reactor Regulation, Director 1p 18912-309. 24X
Fiche: 50-250, 83/06/16, B306210071

B306280168 Updated LER B3-006/01x-1 on B30405, notified that some
masonry walls in control bldg do not comply w/original
designs. Insp within control bldg completed & expanded to
include outside walls. Repairs scheduled W/B30620 1tr
ARIAS, J., WILLIAMS, J. W. Florida Power & Light Co. B3/06/20,
O'REILLY, J. P. Region 2, Office of Director. 3pp. 19015.105 24X
Fiche: 50-250, 83/06/20, B306280168.

V Operator Examinations

B306140127 Requests approved ref matl re operator exams by B30314.
Missing deadline will result in delay in administering
exams. Applications should be submitted at least 60 days
prior to first exam scheduled for w/ of B30502
DANCE, H. C. Division of Project & Resident Programs B3/02/17,
WILLIAMS, J. L. Florida Power & Light Co. 4pp 18839:143. 24X
Fiche: 50-250, 83/02/17, B306140127.

DOCKET 50-251 TURKEY POINT PLANT, UNIT 4

F Security, medical, emergency & fire protection plans

B306070050 Forwards IE Safeguards Insp Repts 50-250/83-17 &
50-251/83-17 on B30420-22, 0502-05 & 10-12 No noncompliance
noted
DANCE, H. C. Division of Project & Resident Programs B3/06/01
UHRIG, R. E. Florida Power & Light Co 2pp 18740 053 24X
Fiche 50-250, 83/06/01, B306070050

--B306070061 IE Safeguards Insp Repts 50-250/83-17 & 50-251/83-17 on
B30420-22, 0502-05 & 10-12 No noncompliance noted Major areas
inspected licensee investigation of two closed valves in
auxiliary feedwater sys Details withheld (ref 10CFR73 21)
TODIN, W. Region 2, Office of Director B3/05/31 1p 18740-055
24X Fiche 50-250, 83/06/01, B306070050

B306130435 Forwards, for review, Rev 1 to B30408 fire protection rpt Rev
provides specific info & justification for 10CFR50, App R,
exemption requests Exemptions unnecessary for Fire Areas/
Zones D, E, G2, G7, V1 & V2
UHRIG, R. E. Florida Power & Light Co B3/06/06 EIBENHUT, D. G.
Division of Licensing 1p 18821 036 24X Fiche 50-250, 83/06/06,
B306130435

--B306130441 Rev 1 to "Fire Protection Rept"
* Florida Power & Light Co B3/06/30 141pp 18821 037 24X
Fiche 50-250, 83/06/06, B306130435

B306230371 Confirms recent conversations w/util re control of access
into containment during shutdown Security plan changes
requested within 60 days of 1tr receipt Safeguards info
withheld (ref 10CFR73 21)
VARQA, B. A. Operating Reactors Branch 1 B3/06/20 UHRIG, R. E.
Florida Power & Light Co 1p 18944 135. 24X Fiche: 50-250,
83/06/20, B306230371

J Insurance & indemnity information

B306010398 Forwards Endorsement 65 to NELIA Policy NF-185 & Endorsement
55 to HAEU Policy NF-55
DUCK, J. R. Marsh & McLennan, Inc. B3/05/20 SALTZMAN, J. Assistant
Director for State & License Relations 3pp. 18682.237 24X
Fiche: 50-250, 83/05/20, B306010398

B306230125 Forwards Endorsement 66 to NELIA Policy NF-185 & Endorsement
55 to HAEU Policy NF-55
DUCK, J. R. Marsh & McLennan, Inc B3/06/16 SALTZMAN, J. Assistant
Director for State & License Relations 3pp 18947 054. 24X
Fiche: 50-250, 83/06/16, B306230125

P Operating license stage documents & correspondence

B306030036 Act receipt of B21027 application & B30307 rev re proposed
revised pump & valve inservice test program Remittance of
Class III & I fees requested
DIOGB, R. M. License Fee Management Branch. B3/05/27 UHRIG, R. E.
Florida Power & Light Co 1p 18733.203 24X Fiche 50-250,
83/05/27, B306030036

B306090352 Application for amend to Licensee DPR-31 & DPR-41, revising
Tech Specs to support fuel design change from Westinghouse
low parasitic fuel assembly to optimized fuel assembly & use
of new Westinghouse wet annular burnable absorber rods
UHRIG, R. E. Florida Power & Light Co. B3/06/03, EIBENHUT, D. G.
Division of Licensing 3pp 18795.003. 24X Fiche: 50-250, 83/06/03,
B306090352.

--B306090355 Proposed Tech Specs supporting fuel design change from
Westinghouse low parasitic fuel assembly to optimized fuel
assembly & use of new Westinghouse wet annular burnable
absorber rods
* Florida Power & Light Co. B3/06/03 21pp. 18795 006. 24X
Fiche: 50-250, 83/06/03, B306090352.

B306160335 Forwards response to B30422 request for addl info re
Criteria 2, 10 & 11 of NUREG-0737, Item II B.3, "Post-Accident
Sampling." Interim core damage estimate guidelines will be
submitted by B30630.
UHRIG, R. E. Florida Power & Light Co. B3/06/10 VARQA, B. A.
Operating Reactors Branch 1. 3pp. 18861-171. 24X
Fiche: 50-250, 83/06/10, B306160335.

Q Inspection reports, IE Bulletins & correspondence

8306140577 Confirms mgt meeting on 830316 at Region II ofc to discuss recent insp findings re failure to properly evaluate radiation exposures at facility Proposed meeting agenda encl

O'REILLY, J.P. Region 2, Office of Director 83/03/15 UHRIQ, R.E. Florida Power & Light Co 2pp 18844 160 24X Fiche 50-250, 83/03/15, 8306140577

8306140393 Confirms 830428 enforcement meeting at Region II ofcs to discuss recent incident of unavailability of auxiliary feedwater w/Unit 3 operating at full power, per 830422 telcon Proposed agenda encl

O'REILLY, J.P. Region 2, Office of Director 83/04/26 UHRIQ, R.E. Florida Power & Light Co 2pp 18832 096 24X Fiche 50-250, 83/04/26, 8306140393

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl
TAYLOR, J.H. Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 119pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8306290204 Forwards IE Insp Repts 50-250/83-13 & 50-251/83-13 on 830503-06 No noncompliance noted
DANCE, H.C. Region 2, Office of Director 83/05/31 UHRIQ, R.E. Florida Power & Light Co 2pp 19056 229 24X Fiche 50-250, 83/05/31, 8306290204

--8306290212 IE Insp Repts 50-250/83-13 & 50-251/83-13 on 830503-06 No noncompliance noted Major areas inspected containment integrated leakage rate testing
BROOKS, E., JAFFE, P. Region 2, Office of Director. 83/05/24 4pp. 19056 231 24X Fiche 50-250, 83/05/31, 8306290204

8306070050 Forwards IE Safeguards Insp Repts 50-250/83-17 & 50-251/83-17 on 830420-22, 0502-05 & 10-12 No noncompliance noted
DANCE, H.C. Division of Project & Resident Programs 83/06/01. UHRIQ, R.E. Florida Power & Light Co. 2pp 18740 053 24X Fiche 50-250, 83/06/01, 8306070050

--8306070061 IE Safeguards Insp Repts 50-250/83-17 & 50-251/83-17 on 830420-22, 0502-05 & 10-12 No noncompliance noted Major areas inspected, license investigation of two closed valves in auxiliary feedwater sys Details withheld (ref 10CFR73 21)
TOBIN, W. Region 2, Office of Director MCQUIRE, D.R. Division of Emergency Preparedness & Materials Safety. 83/05/31 1p 18740 055, 24X Fiche 50-250, 83/06/01, 8306070050

8306080003 Forwards util response to Enforcement Action 83-31 & payment of proposed civil penalty
O'REILLY, J.P. Region 2, Office of Director. 83/06/03 DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement 1p 18772 354 24X Fiche 50-250, 83/06/03, 8306080003

--8306080004 Responds to NRC proposed civil penalty re violations noted in IE Insp Repts 50-250/83-06 & 50-251/83-06 Corrective actions, operating instructions revised detailing duties during outage & nonoutage conditions for technicians
UHRIQ, R.E. Florida Power & Light Co 83/06/01 O'REILLY, J.P. Region 2, Office of Director 8pp 18772 355 24X Fiche 50-250, 83/06/03, 8306080003

8306290398 Responds to IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators " Closed cooling radiator sys contains no check valves Bulletin not applicable
UHRIQ, R.E. Florida Power & Light Co 83/06/08 O'REILLY, J.P. Region 2, Office of Director. 2pp 19052 183 24X Fiche 50-000, 83/06/08, 8306290398

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Electrically Induced Chatter in Relays Within Printed Circuit Cards." Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc. 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306290341 Ack receipt of 830512 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/83-07 & 50-251/83-07
LEWIS, R.C. Division of Project & Resident Programs. 83/06/16 UHRIQ, R.E. Florida Power & Light Co 1p 19055 245 24X Fiche 50-250, 83/06/16, 8306290341

--8306290345 Responds to NRC 830411 ltr re violations noted in IE Insp Repts 50-250/83-07 & 50-251/83-07 Corrective actions requests for relief from ASME Code requirements will be documented prior to insp Disputes noncompliance for Unit 4
UHRIQ, R.E. Florida Power & Light Co 83/05/12 O'REILLY, J.P. Region 2, Office of Director 4pp 19055 246 24X Fiche 50-250, 83/06/16, 8306290341

--8306290349 Forwards IE Insp Repts 50-250/83-07 & 50-251/83-07 on 830315-18 & notice of violation
DANCE, H.C. Division of Project & Resident Programs 83/04/11. UHRIQ, R.E. Florida Power & Light Co 2pp 19055 250 24X Fiche 50-250, 83/06/16, 8306290341

--8306290354 Notice of violation from insp on 830315-18
* Region 2, Office of Director 83/04/11 2pp. 19055 252, 24X Fiche 50-250, 83/06/16, 8306290341

--8306290357 IE Insp Repts 50-250/83-07 & 50-251/83-07 on 830315-18 Noncompliance noted pump & valve inservice testing & component inservice insp not performed per ASME Boiler & Pressure Vessel Code, Section XI.
KLEINSORGE, W.P., BLAKE, J.J. Region 2, Office of Director. 83/04/07 9pp 19055 254 24X Fiche 50-250, 83/06/16, 8306290341

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers." Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 115pp. 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 120pp 18997 007, 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co. of New York, Inc. 116pp. 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Bettings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc 116pp. 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

R Periodic operating reports & related correspondence

8306160638 Monthly operating repts for Apr 1983 W/830516 ltr.
PACE, P.L., WILLIAMS, J.W. Florida Power & Light Co. 83/05/16, Office of Resource Management, Director 17pp 18866 105, 24X Fiche 50-000, 83/05/16, 8306160638

S Reportable occurrences, LERs & related correspondence

8306210197 Updated LER 83-001/01X-1: on 830331, while in refueling shutdown, discrepancies identified in bolting of platform framing steel to containment liner embedments, Bolts improperly installed, Deficiencies corrected, W/830610 ltr.
ARIAS, J., WILLIAMS, J.W. Florida Power & Light Co. 83/06/10, O'REILLY, J.P. Region 2, Office of Director 3pp. 18914 155, 24X Fiche 50-251, 83/06/10, 8306210197

8306270200 LER 83-005/01T-0: on 830601, mechanical maint supervisor determined that safety-related snubber inoperable due to incomplete mod to attachment, Caused by personnel error & procedure deficiencies, Mod completed W/830615 ltr.
ARIAS, J., WILLIAMS, J.W. Florida Power & Light Co. 83/06/15 O'REILLY, J.P. Region 2, Office of Director. 3pp. 18991 280, 24X Fiche 50-251, 83/06/15, 8306270200

8306210071 RO on 830516, several fire barrier penetrations breached for longer than 7 days Caused by implementation of design changes, including new computer room & auxiliary power upgrades, Hourly fire watch established
UHRIQ, R.E. Florida Power & Light Co 83/06/16 DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p 18912 309, 24X Fiche 50-250, 83/06/16, 8306210071

DOCKETED ITEMS

V Operator Examinations

8306140127 Requests approved ref mail re operator exams by 830314
Missing deadline will result in delay in administering
exams Applications should be submitted at least 60 days
prior to first exam scheduled for wk of 830502
DANCE, H C Division of Project & Resident Programs 83/02/17
WILLIAMS, J L Florida Power & Light Co 4pp 18839 163 24X
Fiche: 50-254, 83/02/17, 8306140127

DOCKET 50-254 QUAD-CITIES STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8306130405 Forwards IE Insp Repts 50-254/83-15 & 50-265/83-13 on
830510-13 No noncompliance noted
PAPERIELLO, C J Region 3, Office of Director 83/05/27 REED, C
Commonwealth Edison Co 2pp 18823 064 24X Fiche 50-254, 83/05/27,
8306130405

--8306130412 IE Insp Repts 50-254/83-15 & 50-265/83-13 on 830510-13 No
noncompliance noted Major areas inspected emergency
preparedness exercise
PHILLIPS, H, PLOSKI, T, OLOERSEN, N W Region 3, Office of
Director 83/05/27 26pp 18823 066 24X Fiche 50-254, 83/05/27,
8306130405

8306160071 Releases public version of revised emergency plan
implementing procedures
FELTON, J M Division of Rules and Records 83/06/07 Document
Management Branch 1p 18972 349 24X Fiche 50-254, 83/06/07,
8306160071

--8306160077 Public version of Rev 11 to Emergency Plan Implementing
Procedure GEP 550-O, "Emergency Equipment & Supplies" & Rev
5 to GEP 550-T1, "Environ Sampling Supplies." Receipt
form encl
* Commonwealth Edison Co 83/05/04 Office of Nuclear Reactor
Regulation, Director 6pp 18872 350 24X Fiche: 50-254, 83/06/07,
8306160071

P Operating license stage documents & correspondence

8306090194 Discusses util interpretation of 10CFR50.49, "Environ
Qualification of Electrical Equipment Important to Safety
for Nuclear Power Plants." Intent of rulemaking is to
require upgrade program for replacement equipment not parts
FARRAR, D L Commonwealth Edison Co 83/06/03 DENTON, H R Office
of Nuclear Reactor Regulation, Director 3pp 18796 090 24X
Fiche 50-000, 83/06/03, 8306090194

8306090227 Informs that response to Generic Ltr 83-08 will be submitted by
830713 Info will include stress repts to determine mod to
vacuum breakers on Mark I containments
RYBAK, B Commonwealth Edison Co 83/06/06 DENTON, H R Office of
Nuclear Reactor Regulation, Director 1p 18796 234 24X
Fiche: 50-000, 83/06/06, 8306090227

8306160233 Advises that manufacturers whose repts were used in
technical evaluation repts re environ qualification of
electrical equipment have been contacted List of proprietary
pages detailed in util 830513 ltr W/OE affidavit
RYBAK, B Commonwealth Edison Co 83/06/06 DENTON, H R Office of
Nuclear Reactor Regulation, Director 5pp 18861 304 24X
Fiche 50-000, 83/06/06, 8306160233

8306270108 Discusses final mods to be installed per NRC B10113 & B20119
orders & extension of exemptions for Mark I containment
work Completion of minor mods expected during next outage,
scheduled for Spring 1984
RYBAK, B Commonwealth Edison Co 83/06/15 DENTON, H R Office of
Nuclear Reactor Regulation, Director 2pp 18788 115 24X
Fiche 50-254, 83/06/15, 8306270108

8306270324 Advises that beta spectra measurements will be conducted
at facilities on 830628-29 for NRC project, "Beta Particle
Measurement & Dosimetry Requirements at NRC-Licensed
Facilities"
RATHBUN, L A Battelle Memorial Institute, Pacific Northwest
Laboratory FIN B-2448 83/06/17, KEPLER, J O Region 3, Office
of Director 1p 18794 074 24X Fiche 50-254, 83/06/17, 8306270324,

8306300237 Advises that listed mods will be complete by Spring 1984
outage, per 830615 request for extension of Mark I
containment program
RYBAK, B Commonwealth Edison Co 83/06/22 DENTON, H R Office of
Nuclear Reactor Regulation, Director 2pp 19119 339 24X
Fiche: 50-254, 83/06/22, 8306300237.

Q Inspection reports, IE Bulletins & correspondence

8306220218 Ack receipt of 830414 payment of proposed civil penalties
Response to notice of violation & proposed imposition of
civil penalties will be evaluated & corrective actions
examined during future insps
AXELRAD, J A Enforcement Staff 83/04/21 REED, C Commonwealth
Edison Co 2pp 18950 357 24X Fiche 50-000, 83/04/21, 8306220218

8306030139 Forwards IE Insp Repts 50-254/82-14 & 50-265/82-12 on
830419-20 No noncompliance noted
LITTLE, W S Region 3, Office of Director 83/05/17 REED, C
Commonwealth Edison Co 2pp 18704 291 24X Fiche 50-254, 83/05/17,
8306030139

--8306030143 IE Insp Repts 50-254/82-14 & 50-265/83-12 on 830419-20 No
noncompliance noted Major areas inspected action re IE
Bulletin 80-11, "Masonry Wall Design"
NORTON, J F, WILLIAMS, C C Region 3, Office of Director
83/05/16 4pp 18704 293 24X Fiche 50-254, 83/05/17, 8306030143

8306010179 Informs of results of NRC review of relief requests from
inservice insp requirements Relief granted in part, per encl
safety evaluation
VASSALLO, D J Operating Reactors Branch 2 03/05/19 FARRAR, D L
Commonwealth Edison Co 3pp 18696 010 24X Fiche 50-254, 83/05/19,
8306010179

--8306010182 Safety evaluation supporting, in part & denying in part,
requests for relief from inservice insp requirements
* Office of Nuclear Reactor Regulation, Director 83/05/19 7pp
18696 013 24X Fiche 50-254, 83/05/19, 8306010179

--8209200365 "Quad Cities Nuclear Power Station Units 1 & 2 Inservice
Insp Program," technical evaluation rept
* Science Applications, Inc NRC-03-82-096, SA1-184-028-30
82/09/17 NRC - No Detailed Affiliation Given 45pp
18696 023 24X Fiche 50-254, 83/05/19, 8306010179

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in
Well Logging Device" Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post
830103) 83/05/26 Consolidated Edison Co of New York, Inc
125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458,

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet."
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New
York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8306130405 Forwards IE Insp Repts 50-254/83-15 & 50-265/83-13 on
830510-13 No noncompliance noted
PAPERIELLO, C J Region 3, Office of Director 83/05/27 REED, C
Commonwealth Edison Co 2pp 18823 064 24X Fiche: 50-254, 83/05/27,
8306130405

--8306130412 IE Insp Repts 50-254/83-15 & 50-265/83-13 on 830510-13 No
noncompliance noted Major areas inspected emergency
preparedness exercise
PHILLIPS, H, PLOSKI, T, OLOERSEN, N W Region 3, Office of
Director 83/05/27 26pp 18823 066 24X Fiche: 50-254, 83/05/27,
8306130405

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods
Withdrawn at BWRs" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/31 Consolidated Edison Co of New
York, Inc 116pp 18732 208 24X Fiche: 50-000, 83/05/31, 8305110461

8306060208 Ack receipt of 830405 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-254/82-24 &
50-265/82-28
SPESBARD, R L Division of Engineering 83/05/31 REED, C
Commonwealth Edison Co 1p 18727 351 24X Fiche: 50-254, 83/05/31,
8306060208

--8306060212 Response to NRC 830309 ltr re violations noted in IE Insp
Repts 50-254/82-24 & 50-265/82-28 Corrective actions, onsite
review conducted on 830228 documenting computer program used
for integrated leak rate test
RYBAK, B Commonwealth Edison Co 83/04/05 KEPLER, J O Region
3, Office of Director 6pp 18727 352 24X Fiche: 50-254,
83/05/31, 8306060208

8306070175 Forwards corrected Page 1 to IE Insp Repts 50-254/83-14 &
50-265/83-12 on 830419-20, No noncompliance noted
LITTLE, W S Region 3, Office of Director 83/06/03 REED, C
Commonwealth Edison Co 1p 18736 331 24X Fiche: 50-254, 83/06/03,
8306070175.

DOCKETED ITEMS

51

--8306070190 Corrected Page 1 to IE Insp Repts 80-254/83-14 & 80-245/83-12 on 830419-20 No noncompliance noted Major areas inspected licensee action re IE Bulletin 80-11, "Masonry Wall Design"
NORTON, J. F., WILLIAMS, C. C. Region 3, Office of Director 83/06/02 1p 18736 332 24X Fiche 50-254, 83/06/03, 8306070195

8306100149 Forwards Rev 3 to "180-Day Rept in Response to IE Bulletin 80-11 for Dresden 2 & 3 & Quad Cities 1 & 2"
RYBAK, B. Commonwealth Edison Co 83/06/06 KEPLER, J. Q. Region 3, Office of Director 2pp 18804 161 24X Fiche 50-000, 83/06/06, 8306100149

--8306100156 Rev 3 to "180-Day Rept in Response to IE Bulletin 80-11 for Dresden 2 & 3 & Quad Cities 1 & 2"
* Commonwealth Edison Co 83/05/07 129pp 18804 163 24X Fiche 50-000, 83/06/06, 8306100149

8306100094 Forwards response to IE Bulletin 83-03 re diesel generator cooling water check valves Plants utilize Mission Duo-Check valves employing hinge-to-pin design for protection against vibration-induced failure
BARNES, P. L. Commonwealth Edison Co 83/06/07 KEPLER, J. Q. Region 3, Office of Director 7pp 18802 238 24X Fiche 50-000, 83/06/07, 8306100094

8306170380 Forwards response to IE Bulletin 83-03 re diesel generator cooling water check valves Valves at Dresden & LaSalle acceptable w/o further insp Rept on valve failures at Quad Cities will be submitted within 90 days of insp completion
BARNES, P. L. Commonwealth Edison Co 83/06/07 KEPLER, J. Q. Region 3, Office of Director 7pp 18880 211 24X Fiche 50-000, 83/06/07, 8306170380

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc 117pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8306220067 Summarizes revised schedule for util review of automated analytical instrumentation sys multiple analysis capability per IE Insp Repts 80-254/82-13 & 80-245/82-15
RYBAK, B. Commonwealth Edison Co 83/06/13, PAPERIELLO, C. J. Region 3, Office of Director 2pp 18928 180 24X Fiche 80-254, 83/06/13, 8306220067

8306200149 EN-83-043, on 830621, notice of violation & proposed imposition of civil penalties in amount of \$190,000 will be issued re Security Level III violations concerning shutting down reactor by inserting control rods in reverse order
BARBER, O., AXELRAD, J. Director's Office, Office of Inspection and Enforcement 83/06/16, 1p. 18903 120, 24X Fiche 50-254, 83/06/16, 8306200149

8306300235 Forwards IE Insp Repts 50-237/83-12, 50-249/83-10, 50-254/83-13 & 50-245/83-11 on 820412-14 & 0506 & 16 & notice of violation
LITTLE, W. B. Region 3, Office of Director 83/06/16 REED, C. Commonwealth Edison Co 2pp 19122 279 24X Fiche 50-000, 83/06/16, 8306300235

--8306300238 Notice of Violation from insp on 830412-14 & 0506 & 16.
LITTLE, W. B. Region 3, Office of Director 83/06/16 2pp 19122 281 24X Fiche 50-000, 83/06/16, 8306300235

--8306300246 IE Insp Repts 80-237/83-12, 50-249/83-10, 50-254/83-13 & 50-245/83-11 on 830412-14 & 0506 & 16. Noncompliance noted, as-built configuration (for pipe anchor R133 in pressure suppression sys) differed from original design
YIN, I. T., DANIELSON, D. H. Region 3, Office of Director 83/06/15 9pp 19122 283, 24X Fiche 50-000, 83/06/16, 8306300235

8306220028 Act receipt of 830509 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-254/82-26 & 80-245/82-26
KEPLER, J. Q. Region 3, Office of Director 83/06/17 REED, C. Commonwealth Edison Co. 1p. 18930 036, 24X Fiche 50-254, 83/06/17, 8306220028

--8306220034 Responds to NRC 830411 ltr re violations noted in IE Insp Repts 50-254/82-26 & 80-245/82-26 Corrective actions startup procedures revised to include sign-off space verifying alarm has cleared
REED, C. Commonwealth Edison Co 83/05/09 Director's Office, Office of Inspection and Enforcement 7pp 18930 037 24X Fiche 50-254, 83/06/17, 8306220028

8306270293 Forwards notice of violation & proposed imposition of civil penalties to be issued to licensee Action based on improper manipulation of control rods which occurred during IE safety insp on 830310-11
KEPLER, J. Q. Region 3, Office of Director 83/06/21 O'CONNOR, J. J. Commonwealth Edison Co 4pp 18990 141 24X Fiche 50-254, 83/06/21, 8306270293

--8306270298 Notice of violation & proposed imposition of civil penalties in amount of \$190,000 based on improper manipulation of control rods which occurred during IE safety insp on 830310-11
KEPLER, J. Q. Region 3, Office of Director 83/06/21 5pp 18990 145 24X Fiche 50-254, 83/06/21, 8306270293

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co. of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

R Periodic operating reports & related correspondence

8306170314 Monthly operating repts for May 1983, W/830606 ltr.
WEINFURTER, E., MIBAK, A., KALIVIANAKIS, N. Commonwealth Edison Co 83/06/06, Director's Office, Office of Inspection and Enforcement 22pp 18977 042 24X Fiche 50-254, 83/06/06, 8306170314

B Reportable occurrences, LERs & related correspondence

8306130337 LER 83-020/03L-0 on 830510, while performing monthly Exercise GDS 1400-1, Div 11 indicating lights for vacuum breaker 1-1601-23F did not operate when valve exercised. Caused by slight binding in vacuum breaker main shaft W/830526 ltr.
*, KALIVIANAKIS, N. Commonwealth Edison Co 83/05/26, KEPLER, J. Q. Region 3, Office of Director 4pp 18822 273 24X Fiche 50-254, 83/05/26, 8306130337

8306130329 LER 83-021/01T-0 on 830520, pinhole leak discovered on reactor continuous head vent line. Caused by slag entrapment within weld during initial installation. Indication removed & rewelded W/830601 ltr
TIETZ, G., KALIVIANAKIS, N. Commonwealth Edison Co 83/06/01, KEPLER, J. Q. Region 3, Office of Director 5pp 18822 356 24X Fiche 50-254, 83/06/01, 8306130329

8306300043 LER 83-023/03L-0 on 830522, electromagnetic relief valve opened for no obvious reason at approx 60 psig. Caused by electromagnetic relief pilot valve assembly stuck in open position. Pilot Valve replaced, W/830608 ltr.
COOK, D., KALIVIANAKIS, N. Commonwealth Edison Co 83/06/08, KEPLER, J. Q. Region 3, Office of Director 4pp 19120 223 24X Fiche 50-254, 83/06/08, 8306300043

8306270252 LER 83-022/03L-0 on 830523, RCIC steam supply valve MD-1-1301-16 did not give open position indication when operated from control room. Valve found open. Caused by loose wire on open limit switch W/830616 ltr.
RUSTICK, R., KALIVIANAKIS, N. Commonwealth Edison Co 83/06/16, KEPLER, J. Q. Region 3, Office of Director 2pp 18990 225 24X Fiche 50-254, 83/06/16, 8306270252

DOCKETED ITEMS

8306270282 Potential Part 21 rept re discrepancy in welding of turnbuckle assembly, turnbuckle-bolt interface & on top plate assembly variable springs SA307 Grade B bolts not ASME Section IX matl investigation underway
KARAOJIANIS, J A Eichen Metal Products Co 83/06/17 KEPLER, J O Region 3, Office of Director 2pp 18996 207 24X
Fiche: 50-000, 83/06/17, 8306270282

DOCKET 50-255 PALISADES NUCLEAR PLANT

F. Security, medical, emergency & fire protection plans

8306090201 Releases public version of Rev 0 to Emergency Plan Implementing Procedure EI 7 I, "Post-Accident Sampling"
FELTON, J M Division of Rules and Records 83/06/01 Document Management Branch 1p 18809 236 24X Fiche 50-255, 83/06/01, 8306090201

--8306090203 Public version of Rev 0 to Emergency Plan Implementing Procedure EI 7 I, "Post-Accident Sampling" W/830519 ltr & receipt form
EMBREY, B Consumers Power Co 83/05/19 14pp 18809 237 24X Fiche 50-255, 83/06/01, 8306090201.

8306090285 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/06/01 Document Management Branch 1p 18810 026 24X Fiche 50-255, 83/06/01, 8306090285

--8306090287 Public version of Rev 0 to Emergency Plan Implementing Procedure EI-7 B, "Baron-Mannitol Titration Method Post-Accident" W/830520 ltr & receipt form
EMBREY, B Consumers Power Co 83/05/19 9pp 18810 027 24X Fiche: 50-255, 83/06/01, 8306090285

8306140828 Releases public version of revised emergency plan implementing procedure.
FELTON, J M Division of Rules and Records 83/06/01 Document Management Branch 1p 18853 206 24X Fiche 50-255, 83/06/01, 8306140828

--8306140831 Public version of Rev 0 to Emergency Plan Implementing Procedure EI-7 B, "Quantitative Analysis of Chloride in Post-Accident Solution" W/830520 ltr & receipt form.
EMBREY, B Consumers Power Co 83/05/18 7pp 18853 208 24X Fiche 50-255, 83/06/01, 8306140828

8306150088 Advises that 830505 changes to security plan do not decrease effectiveness of plan & are consistent w/10CFR30 54(p) & are acceptable
CRUTCHFIELD, D Operating Reactors Branch 5 83/06/06 VANDEWALLE, D J Consumers Power Co. 2pp 18872 123 24X Fiche 50-255, 83/06/06, 8306150088

8306130334 Forwards "Suppl 1 to NUREG-0737, Milestone Activity - Submittal of Updated Detailed Control Room Design Review Program Plan"
TONER, K A Consumers Power Co 83/06/07 CRUTCHFIELD, D, Operating Reactors Branch 5, 1p 18822:197, 24X Fiche: 50-255, 83/06/07, 8306130334

--8306130335 "Suppl 1 to NUREG-0737, Milestone Activities - Submittal of Updated Detailed Control Room Design Review Program Plan"
* Consumers Power Co 83/06/07, 12pp 18822, 198 24X Fiche: 50-255, 83/06/07, 8306130334

8306220025 Confirms 830623 security enforcement meeting in Glen Ellyn, IL to review breach of security event on 830523, corrective actions & to discuss enforcement actions.
KEPLER, J O Region 3, Office of Director. 83/06/16 SELBY, J D Consumers Power Co 1p 18928 215 24X Fiche: 50-255, 83/06/16, 8306220025

8306300014 Forwards IE Insp Rept 50-255/83-13 on 830501-31. No noncompliance noted
SHAFFER, M D, Region 3, Office of Director 83/06/16, DEWITT, R B, Consumers Power Co 2pp 19120 255 24X Fiche 50-255, 83/06/16, 8306300014.

--8306300021 IE Insp Rept 50-255/83-13 on 830501-31. No noncompliance noted. Major areas inspected: LERs, operational safety, surveillance, maint, reactor trip & miscellaneous items
JORGENSEN, S L, HELLER, J K, BOYD, D C, Region 3, Office of Director. 83/06/16, 7pp, 19120:257 24X Fiche: 50-255, 83/06/16, 8306300014.

8306240285 Forwards response to NRC 830506 & 09 ltrs re security & suitability, training & qualification plans, respectively
Response withheld (10CFR73 21)
VANDEWALLE, D J Consumers Power Co 83/06/20 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 18980 151 24X
Fiche 50-000, 83/06/20, 8306240285

J Insurance & indemnity information

8306210151 Forwards Endorsements 74 & 68 to NELIA Policy NF-179 & MAELV Policy NF-50, respectively
FRONFELKER, R Consumers Power Co 83/06/14 SALTZMAN, J Antitrust & Economic Analysis Branch (Utility Finance) 4pp 18915 243 24X Fiche 50-255, 83/06/14, 8306210151

P Operating license stage documents & correspondence

8306030362 Forwards revs to "Environ Qualification of Safety-Related Electrical Equipment," in response to SER open items per NRC request Rev affects Encls 1, 2, 4 & 5 re schedule of equipment qualification for Items I B, II A, II B & IV
TONER, K A Consumers Power Co. 83/05/20 CRUTCHFIELD, D Operating Reactors Branch 5 279pp 18703 001 24X Fiche 50-255, 83/05/20, 8306030362

8306060145 Forwards Engineering Analysis EA-83-BRD-005, "Addl Resistive Isolation Devices for RPS/F&P Computer Interconnections," per util 820216 commitment re SEP Topic VIII-1 A
TONER, K A Consumers Power Co 83/05/27 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 18719 131 24X Fiche 50-255, 83/05/27, 8306060145

--8306060149 "Addl Resistive Isolation Devices for RPS/F&P Computer Interconnections"
* Consumers Power Co EA-83-BRD-005 83/04/18 28pp 18719 134 24X Fiche 50-255, 83/05/27, 8306060145

8306060044 Responds to 830505 amend application Forwards FR notice of consideration of issuance of amend re intervals between testing certain components & sys
CRUTCHFIELD, D Operating Reactors Branch 5 83/05/31 VANDEWALLE, D J Consumers Power Co 2pp 18719 233 24X
Fiche 50-255, 83/05/31, 8306060044

--8306060047 Notice of consideration of issuance of amend to provisional OL & proposed no significant hazards consideration determination & opportunity for hearing re surveillance test frequency
CRUTCHFIELD, D Operating Reactors Branch 5 83/05/31 /pp 18719 235 24X Fiche 50-255, 83/05/31, 8306060044

8306070042 Forwards safety evaluation of proposed resolution of integrated plant SAR Section 4 27 re svc & cooling water sys. Mods acceptable.
HAMBACH, T V, Operating Reactors Branch 5 83/05/31, VANDEWALLE, D J Consumers Power Co 2pp 18740 100 24X
Fiche 50-255, 83/05/31, 8306070042

--8306070043 Safety evaluation on integrated plant SAR Section 4 27 re svc & cooling water sys
* Operating Reactors Branch 5 83/05/31 3pp 18740 102 24X
Fiche 50-255, 83/05/31, 8306070042

8306070247 Forwards SER of 821101 response to integrated plant safety assessment rept, Section 4 28 re ventilation sys Proposed mods acceptable
HAMBACH, T V, Operating Reactors Branch 5 83/06/03 VANDEWALLE, D J Consumers Power Co 2pp 18740 314 24X
Fiche: 50-255, 83/06/03, 8306070247

--8306070250 SER of util 821101 response to integrated plant safety analysis rept, Section 4 28 re ventilation sys Issues resolved
* Office of Nuclear Reactor Regulation, Director 83/06/03 3pp 18740 316 24X Fiche: 50-255, 83/06/03, 8306070247

8306160396 Advises that design of electrical penetrations similar to other SEP plants Probability of electrical failure low & any leakage path due to penetration failure would be small
Issue completed No further action required
HAMBACH, T V, Operating Reactors Branch 5, 83/06/10 VANDEWALLE, D J, Consumers Power Co 4pp 18860 191 24X
Fiche 50-255, 83/06/10, 8306160396.

8306220020 Provides util action plan to close SEP Topic III-6, "Seismic Design Considerations."
TONER, K A Consumers Power Co 83/06/15 CRUTCHFIELD, D Operating Reactors Branch 5, 3pp, 18928 216, 24X Fiche 50-255, 83/06/15, 8306220020

DOCKETED ITEMS

53

8306230374 Withdraws 810505 Tech Spec change request re steam generator insp program & 810602 & 0702 supply to change request
JOHNSON, B D Consumers Power Co 83/06/15 CRUTCHFIELD, D
Operating Reactors Branch 5 1p 18942 346 24X
Fiche 50-255, 83/06/15, 8306230374

8306230413 Supplements 830202 ltr discussing alternative to automatic isolation of V-79 exhaust sys when radiation detected, per NUREG-0737, Item II F 1.1 Explanation of why alternatives to proposed mod investigated discussed
JOHNSON, B D Consumers Power Co 83/06/17 KEPLER, J O Region 3, Office of Director 3pp 18941 340 24X Fiche 50-255, 83/06/17, 8306230413

8306280439 Forwards evaluation of integrated plant SAR, Sections 4 9 & 4 15 re pipe break inside containment & RCBP leakage detection requirements Section 4 9 complete Corrective measures required for Section 4 15 within 90 days
HAMBACH, T V Operating Reactors Branch 5 83/06/22 VANDEWALLE, D J Consumers Power Co 8pp 19018 329 24X
Fiche 50-255, 83/06/22, 8306280439

8306290323 Forwards safety evaluation of proposed resolution of classification of structures, sys & components issue in Section 4 5 of integrated plant safety assessment rept (NUREG-0820) Info acceptable to resolve open items
HAMBACH, T V Operating Reactors Branch 5 83/06/27 VANDEWALLE, D J Consumers Power Co 7pp 19055 306 24X Fiche 50-255, 83/06/27, 8306290323

Q Inspection reports, IE Bulletins & correspondence

8309110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Mail Logging Device " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8309110458

8309110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 089 24X Fiche 50-000, 83/05/26, 8309110460

8309110461 IE Info Notice 83-35, "Fuel Movement W/Control Rds Withdrawn at BWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8309110461

8306070068 Responds to 830310 IE Bulletin 83-03, "Check Valve Failure in Raw Water Cooling Sys of Diesel Generators " Design of cooling water flow path to diesel generators does not utilize check valves IE Bulletin 83-03 not applicable
JOHNSON, B D Consumers Power Co 83/05/31 KEPLER, J O Region 3, Office of Director 2pp 18740 093 24X Fiche 50-255, 83/05/31, 8306070068

8309110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8309110464

8306130396 Forwards addendum Table II, confirmatory measurements program data sheets to be included in IE Insp Rept 50-255/82-22 transmitted 821028
PAPERFIELD, C J Region 3, Office of Director 83/06/10 DEWITT, R B Consumers Power Co 2pp 18823 273 24X
Fiche 50-255, 83/06/10, 8306130396

8309110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards, " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8309110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8306230374 Withdraws 810505 Tech Spec change request re steam generator insp program & 810602 & 0702 supply to change request
JOHNSON, B D Consumers Power Co 83/06/15 CRUTCHFIELD, D
Operating Reactors Branch 5 1p 18942 346 24X
Fiche 50-255, 83/06/15, 8306230374

8306300014 Forwards IE Insp Rept 50-255/83-13 on 830501-31, No noncompliance noted
SHAFFER, W D Region 3, Office of Director 83/06/16 DEWITT, R B Consumers Power Co 2pp 19120 255 24X Fiche 50-255, 83/06/16, 8306300014

--8306300021 IE Insp Rept 50-255/83-13 on 830501-31 No noncompliance noted Major areas inspected LERs, operational safety, surveillance, maint, reactor trip & miscellaneous items
JORGENSEN, B L, HELLER, J K, BOYD, D C Region 3, Office of Director 83/06/16 7pp 19120 257 24X Fiche 50-255, 83/06/16, 8306300014

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions, " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

R Periodic operating reports & related correspondence

8306100179 Forwards revised Tables RSD-E-03A & RSD-E-03D to 1982 radiological environ monitoring rept, Rev reflects review of rept on unit of measure for air sample.
JOHNSON, B D Consumers Power Co 83/05/18 KEPLER, J O Region 3, Office of Director 1p 18805 253 24X Fiche 50-255, 83/05/18, 8306100179

--8306100181 Revised Tables RSD-E-03A & RSD-E-03D for 1982 radiological environ monitoring rept.
* Consumers Power Co 83/05/18 3pp 18805 254 24X
Fiche 50-255, 83/05/18, 8306100179

8306130310 Monthly operating rept for May 1983 W/830608 ltr.
PETERSON, D A, KENNEDY, D M Consumers Power Co 83/06/08 NRC - No Detailed Affiliation Given 3pp 18823 323 24X
Fiche 50-255, 83/06/08, 8306130310

8306230287 Corrects statement in environ operating rept for 1982 re use of herbicides Small quantity of herbicides sprayed on site property during 1982
JOHNSON, B D Consumers Power Co 83/06/16 KEPLER, J O Region 3, Office of Director 1p 18945 164 24X Fiche 50-255, 83/06/16, 8306230287

S Reportable occurrences, LERs & related correspondence

8112090561 RO on 730812, MBIV CVO510 failed to close following shutdown & cooldown at plant Caused by hardening of valve packing. Packing will be removed & components cleaned
SEWELL, R B Consumers Power Co 73/08/22 O'LEARY, J F Atomic Energy Commission, Directorate of Licensing 1p 65760 206 24X
Fiche 50-255, 73/08/22, 8112090561

8306070236 LER 83-034/01T-0 on 830516, D safety injection tank T-82D level fell below Tech Spec limit during routine sampling. Caused by delay in fill operations due to failure of relief valve RV-3161 to reset within 1 h, W/830531 ltr
JOHNSON, B D Consumers Power Co 83/05/31 KEPLER, J O Region 3, Office of Director 2pp 18741 157 24X Fiche 50-255, 83/05/31, 8306070236

8306070248 LER 83-032/03L-0 on 830429, declaration of operability signature found incomplete for maint order on fire barrier penetration Caused by personnel oversight re new maint order closeout procedures, W/830531 ltr
JOHNSON, B D Consumers Power Co 83/05/31 KEPLER, J O Region 3, Office of Director 2pp 18740 328 24X Fiche 50-255, 83/05/31, 8306070248

DOCKETED ITEMS

8306070282 LER 83-033/03L-0 on 830428, D safety injection tank T-B2D sampling indicated boron concentration below Tech Spec limit. Caused by minor leakage past loop check valve & SIT check valve or fill & drain valve W/830531 ltr. JOHNSON, B D Consumers Power Co 83/05/31 KEPLER, J O Region 3, Office of Director 2pp 18741 212 24X Fiche 50-255, 83/05/31, 8306070282

8306130394 LER 83-035/03L-0 on 830505, safety injection tank (SIT) C reached Tech Spec limit of 198 inches. Caused by minor leakage past loop check valve & SIT check valve or fill & drain valve. Leak rate being monitored W/830603 ltr. JOHNSON, B D Consumers Power Co 83/06/03 KEPLER, J O Region 3, Office of Director 2pp 18823 016 24X Fiche 50-255, 83/06/03, 8306130394

8306220013 LER 83-036/03L-0 on 830515, during normal power operation, safety injection tank (SIT) D level reached Tech Spec limit. Caused by minor leakage past loop check valve & SIT check valve or fill & drain valve. Leak monitored W/830610 ltr. JOHNSON, B D Consumers Power Co 83/06/10 KEPLER, J O Region 3, Office of Director 2pp 18927 342 24X Fiche 50-255, 83/06/10, 8306220013

8306220029 Telecopy RD on 830610, safety injection tank C (T-B2C) became inoperable due to low level resulting from sampling. Caused by lifting of relief valve. Low level switch cleared. KRICH, R M Consumers Power Co, 83/06/13 Region 3, Office of Director 1p 18930 044 24X Fiche 50-255, 83/06/13, 8306220029

8306270063 LER 83-039/01T-0 on 830603, hydrogen recombiners simultaneously loaded to respective MCC for surveillance testing, contrary to standing order. Caused by inadequate surveillance procedure. W/830617 ltr. JOHNSON, B D Consumers Power Co 83/06/13 KEPLER, J O Region 3, Office of Director 2pp. 18995 219 24X Fiche 50-255, 83/06/13, 8306270063

8306220256 LER 83-037/01T-0 on 830601, rack mounted circuit board replaced w/one from stock resulting in total loss of valve control during restoration of automatic control of CV-0737A. Caused by faulty rack mounted circuit board W/830615 ltr. JOHNSON, B D Consumers Power Co 83/06/15 KEPLER, J O Region 3, Office of Director 3pp 18926 026 24X Fiche 50-255, 83/06/15, 8306220256

8306270432 LER 83-038/01T-0 on 830603, W/T-B2C (safety injection tank C) inoperable due to routine evolution & tank T-B2D became inoperable due to low level. Caused by leakage past fill & drain valve. Valves to be inspected W/830617 ltr. JOHNSON, B D Consumers Power Co 83/06/17 KEPLER, J O Region 3, Office of Director 2pp. 18993 043 24X Fiche 50-255, 83/06/17, 8306270432

8306270435 LER 83-040/01T-0 on 830607, safety injection tank D sample showed boron concentration below Tech Spec limit of 1.720 ppm. Caused by minor leakage past loop check valve. Valves will be checked during next outage W/830620 ltr. JOHNSON, B D Consumers Power Co 83/06/20 KEPLER, J O Region 3, Office of Director 2pp. 18993 067 24X Fiche 50-255, 83/06/20, 8306270435

DOCKET 50-257 JULICH TESTING REACTOR

0 Inspection reports, IE Bulletins & correspondence

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs" Svc list encl. JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461.

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list encl. JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/15 Consolidated Edison Co. of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/15, 8306090010

R Periodic operating reports & related correspondence

8306020216 Monthly operating reports for Mar 1983 W/830415 ltr. PAGE, P L., WILLIAMS, J W. Florida Power & Light Co 83/04/15 Office of Resource Management, Director 13pp. 18690:256 24X Fiche 50-000, 83/04/15, 8306020216

DOCKET 50-259 BROWNS FERRY NUCLEAR POWER STATION, UNIT 1
F Security, medical, emergency & fire protection plans

8306140107 Forwards summary of 830315 meeting at Region II of re proposed security mods for future const activities at Facilities List of attendees encl. LEWIS, R C Division of Project & Resident Programs 83/03/25 PARRIS, H Q Tennessee Valley Authority 4pp 18859 082 24X Fiche 50-259, 83/03/25, 8306140107

8306270007 Forwards revised physical security plan, reflecting NRC 830412 comments. Rev withheld (ref 10CFR73.21). MILLS, L M Tennessee Valley Authority 83/06/03 O'REILLY, J P Region 2, Office of Director 1p 18908 153 24X Fiche 50-259, 83/06/03, 8306270007

8306210010 Forwards "Program Plan for Control Room Design Reviews for all TVA Nuclear Plants," in response to Generic Ltr 82-33 re upgrade of emergency plans. KAMMER, D B Tennessee Valley Authority, 83/06/09 ADENBAM, C Licensing Branch 4 3pp 18913 001 24X Fiche 50-000, 83/06/09, 8306210010

--8306210016 Procedure 862209 10, "Program Plan for Control Room Design Reviews for all TVA Nuclear Plants" * Tennessee Valley Authority 83/06/09 200pp 18913 004 24X Fiche 50-000, 83/06/09, 8306210010

8306230201 Notification of 830621 meeting w/util in Bethesda, MD to discuss potential rev to App R submittal based on revised criteria w/respect to analyses on loss of offsite power & availability of other onsite units & condensate pumps. CLARK, D Operating Reactors Branch 2 83/06/16 VASSALLO, D B Operating Reactors Branch 2 1p 18954 357 24X Fiche 50-259, 83/06/16, 8306230201

8306210194 Ack receipt of 830603 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-259/83-10, 50-260/83-10 & 50-296/83-10. LEWIS, R C Division of Project & Resident Programs 83/06/17 PARRIS, H Q Tennessee Valley Authority 1p 18919 030 24X Fiche 50-259, 83/06/17, 8306210194

--8306210203 Forwards response to NRC 830429 ltr re violations noted in IE Safeguards Insp Repts 50-259/83-10, 50-260/83-10 & 50-296/83-10. Corrective actions withheld (ref 10CFR73.21). MILLS, L M Tennessee Valley Authority 83/06/03 O'REILLY, J P Region 2, Office of Director 1p 18919 031 24X Fiche 50-259, 83/06/17, 8306210194

--8306210213 Forwards IE Safeguards Insp Repts 50-259/83-10, 50-260/83-10 & 50-296/83-10 on 830404-08 & notice of violation. Notice of violation withheld (ref 10CFR73.21). LEWIS, R C Division of Project & Resident Programs 83/04/29 PARRIS, H Q Tennessee Valley Authority 2pp 18919 032 24X Fiche 50-259, 83/06/17, 8306210194

--8306210224 IE Safeguards Insp Repts 50-259/83-10, 50-260/83-10 & 50-296/83-10 on 830404-08 Noncompliance noted. Failure to follow access control procedures. Details withheld (ref 10CFR73.21). MOORE, D E Region 2, Office of Director 83/04/27 1p 18919 034 24X Fiche 50-259, 83/06/17, 8306210194

P Operating license stage documents & correspondence

8306060051 Addl response to FOIA request for three categories of documents re PRA of reactor safety study methodology, application program repts & interim reliability evaluation program repts. Forwards App A documents. Search continuing. FELTON, J M Division of Rules and Records 83/04/07 SHOLLY, B C Union of Concerned Scientists 3pp 18792 001 24X Fiche 50-000, 83/04/07, 8306060051

--8306060061 Statement on background, issues, current status & future action re interim & natl reliability evaluation programs * NRC - No Detailed Affiliation Given 82/12/31 2pp. 18792 059 24X Fiche 50-000, 83/04/07, 8306060051

8306020180 Forwards safety evaluation re valve operability for 10, 18 & 20-inch butterfly valves used for purge or vent of containments. Info submitted fails to demonstrate valve ability to close against pressure buildup during LOCA. VASSALLO, D B Operating Reactors Branch 2 83/05/19 PARRIS, H Q Tennessee Valley Authority 3pp 18701 113 24X Fiche 50-259, 83/05/19, 8306020180

--8306020187 Safety evaluation re valve operability for 10, 18 & 20-inch butterfly valves used for purge or vent of containments info submitted fails to demonstrate valve ability to close against pressure buildup during LOCA
* Office of Nuclear Reactor Regulation, Director 83/05/19 App
18701 116 24X Fiche 50-259, 83/05/19, 8306020180

8306150260 Forwards "Control of Heavy Loads (C-10), TVA, Browns Ferry Nuclear Power Station, Units 1, 2 & 3," draft technical evaluation rept Conference call requested within 4 to 5 wks to discuss review results
VASSALLO, D B Operating Reactors Branch 2 83/05/26 PARRIS, H O
Tennessee Valley Authority 2pp 18869 322 24X
Fiche 50-259, 83/05/26, 8306150260

--8306150266 "Control of Heavy Loads (C-10), TVA, Browns Ferry Nuclear Power Station, Units 1, 2 & 3," draft technical evaluation rept
BOMBERGER, C, AHMED, N, SARGENT, I M Franklin Institute/Franklin Research Center NRC-03-B1-130 TER-C5504-337/33B/33 83/04/03, CLEMENSON, F NRC - No Detailed Affiliation Given 25pp
18869 324 24X Fiche 50-259, 83/05/26, 8306150260

--8306150272 "Synopsis of Issues Associated w/NUREG-0612"
* Operating Reactors Branch 2 83/05/26 11pp 18869 349 24X
Fiche 50-259, 83/05/26, 8306150260

8306150243 Suppl 6 to 820914 application for amend to Licenses DPR-33, DPR-52 & DPR-68, changing Tech Specs 3 10 C & 4 10 C re min depth of water required over single irradiated fuel assemblies during handling
MILLS, L M Tennessee Valley Authority 83/06/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 18846 127
24X Fiche 50-259, 83/06/03, 8306150243

--8306150248 Proposed changes to Tech Specs 3 10 C & 4 10 C re min depth of water required over single irradiated fuel assemblies during handling
* Tennessee Valley Authority 83/06/03 10pp 18846 129 24X
Fiche 50-259, 83/06/03, 8306150243

8306140654 Forwards response to 830519 request for info re BER, Section 4 O, on containment purge & vent valves operability of valves justified under LOCA conditions
MILLS, L M Tennessee Valley Authority 83/06/07 DENTON, H R
Office of Nuclear Reactor Regulation, Director 7pp 18834 008
24X Fiche 50-259, 83/06/07, 8306140654

8306160507 Application for emergency amend to Licenses DPR-33, DPR-52 & DPR-68, changing Tech Spec standby gas treatment sys required surveillance interval to once per operating cycle
MILLS, L M Tennessee Valley Authority 83/06/13 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 18844 157
24X Fiche 50-259, 83/06/13, 8306160507

--8306160523 Proposed Tech Specs changing standby gas treatment sys required surveillance interval to once per operating cycle
Justification for emergency nature of proposed Tech Spec change encl
* Tennessee Valley Authority 83/06/13, 9pp, 18844 159 24X
Fiche 50-259, 83/06/13, 8306160507

8306210014 Confirms agreement w/NRC re interpretation of Tech Spec 4 7 B 3 a requirements Spec satisfied by commitment to activate annually standby gas treatment blowers in primary containment isolation sys logic, Tech Spec 189 needed
MILLS, L M Tennessee Valley Authority, 83/06/16, DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 18911 387
24X Fiche 50-259, 83/06/16, 8306210014

8306290400 Application to amend Licenses DPR-33, DPR-52 & DPR-68, changing Tech Specs to require annual rept of main steam safety/relief valve actuations, in response to NUREG-0737, Item II K 3 3 & Generic Ltr 83-02
MILLS, L M Tennessee Valley Authority 83/06/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 19053 133
24X Fiche 50-259, 83/06/20, 8306290400

--8306290408 Proposed Tech Spec revs, requiring annual rept of main/steam safety/relief valve actuations, in response to NUREG-0737, Item II K 3 3 & Generic Ltr 83-02
* Tennessee Valley Authority 83/06/20 5pp, 19053 135 24X
Fiche 50-259, 83/06/20, 8306290400

8306240354 Notification of 830629 meeting w/util in Bethesda, MD to discuss util analysis on intervening combustibles & separation of circuits
CLARK, D. Operating Reactors Branch 2 83/06/22 VASSALLO, D B
Operating Reactors Branch 2 2pp, 18999 137 24X
Fiche 50-259, 83/06/22, 8306240354

8306280415 Suppl 821220 response to NUREG-0313 request for addl info Ferrite content of cast austenitic stainless steel ranges from 15 to 20% Valves highly resistant to intergranular stress corrosion cracking
MILLS, L M Tennessee Valley Authority 83/06/22 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 19018 331
24X Fiche 50-259, 83/06/22, 8306280415

8306280567 Advises that GE equipment items discussed in 830520 ltr re environ qualification reclassified as nonproprietary.
MILLS, L M Tennessee Valley Authority 83/06/23 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p, 19018 028, 24X
Fiche 50-259, 83/06/23, 8306280567

8306300177 Discusses continuing problem re extreme length of time required for approval & resulting backlog of pending requests for Tech Spec changes Majority of changes administrative & require minimal review time
MILLS, L M Tennessee Valley Authority, 83/06/27 DENTON, H R
Office of Nuclear Reactor Regulation, Director, 3pp 19122 044, 24X Fiche 50-259, 83/06/27, 8306300177

8306280080 LOSS OF DHR SEQUENCES AT BROWNS FERRY UNIT ONE - ACCIDENT SEQUENCE ANALYSIS
COOK, D H, GREENE, S R, HARRINGTON, R M Oak Ridge National Laboratory T1N D-0452 NUREG/CR-2973 83/06/30 Division of Accident Evaluation 180pp 1906B 295 24X Fiche 50-259, 83/06/30, 8306280080

G Inspection reports, IE Bulletins & correspondence

8306290218 Forwards IE Insp Repts 50-259/83-03, 50-260/83-03 & 50-296/83-03 on 830110-14 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/03/21
PARRIS, H O Tennessee Valley Authority 2pp 19056 135, 24X
Fiche 50-259, 83/03/21, 8306290218

--8306290224 Notice of violation from insp on 830110-14
* Region 2, Office of Director 83/03/21 9pp 19056 137 24X
Fiche 50-259, 83/03/21, 8306290218

--8306290228 IE Insp Repts 50-259/83-03, 50-260/83-03 & 50-296/83-03 on 830110-14 Noncompliance noted failure to perform evaluation of radiation hazards to personnel & employee failure to wear gloves in contaminated zone
DEBB, B T, BARR, K P, Region 2, Office of Director 83/03/03 9pp 19056 139, 24X Fiche 50-259, 83/03/21, 8306290218

8306140543 Confirms mgt meeting on 830421 in Chattanooga, TN to review results of first phase of annual appraisal of regulatory performance, per 830328 telcon
LEWIS, R C Division of Project & Resident Programs 83/04/12
PARRIS, H O Tennessee Valley Authority, 3pp, 18834 176, 24X
Fiche 50-000, 83/04/12, 8306140543

8306140422 Confirms 830601 mgt meeting at site to discuss mgt controls for refueling operations, per 830519 telcon
LEWIS, R C Division of Project & Resident Programs 83/05/23
PARRIS, H O Tennessee Valley Authority 3pp 18838 049 24X
Fiche 50-259, 83/05/23, 8306140422

8306140685 Forwards IE Insp Repts 50-259/83-17, 50-260/83-17 & 50-296/83-17 on 830509-12 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/05/25, PARRIS, H O Tennessee Valley Authority 2pp 18841 336 24X
Fiche 50-259, 83/05/25, 8306140685

--8306140692 IE Insp Repts 50-259/83-17, 50-260/83-17 & 50-296/83-17 on 830509-12 No noncompliance noted Major areas inspected followup on IE Bulletin 80-11, "Masonry Wall Design,"
LENAHAN, J J, CONLON, T E Region 2, Office of Director, 83/05/25, 5pp, 18841 338 24X Fiche 50-259, 83/05/25, 8306140685

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl.
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp, 18831 043, 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet," Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8306150625 Requests approval for M Tokar to visit site on 830613 in order to observe exam of fuel removed from reactors, Specific info for discussion listed.
VASSALLO, D B Operating Reactors Branch 2 83/05/27, PARRIS, H O Tennessee Valley Authority 3pp 18847 285 24X
Fiche 50-259, 83/05/27, 8306150625

DOCKETED ITEMS

5110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods withdrawn at BWRs" Bvc list encl
DRAHAN, E. L. Division of Emergency Preparedness & Engineering
response (Post 830103). 83/05/31 Consolidated Edison Co. of New
ark, Inc 116pp 18732:208. 24X Fiche 50-000,83/05/31,8305110461.

6140291 Ack receipt of 830525 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-259/83-09,
0-260/83-09 & 50-296/83-09.
LEWIS, R. C. Division of Project & Resident Programs. 83/06/02
PARRIS, H. O. Tennessee Valley Authority 1p 18832 236 24X
Fiche 50-259,83/06/02,8306140291

306140266 Responds to NRC 830418 ltr re violations noted in IE Insp
Repts 50-259/83-09, 50-260/83-09 & 50-296/83-09 Corrective
actions all conduit supports for safety-related equipment
corrected by work plan or maint request.
KAHMER, D. B. Tennessee Valley Authority 83/05/25. O'REILLY, J. P.
Region 2, Office of Director 6pp 18832 237 24X
Fiche: 50-259,83/06/02,8306140266

306140276 Forwards IE Insp Repts 50-259/83-09, 50-260/83-09 &
50-296/83-09 on 830226-0325 & notice of violation
LEWIS, R. C. Division of Project & Resident Programs 83/04/18
PARRIS, H. O. Tennessee Valley Authority. 2pp 18832 243 24X
Fiche: 50-259,83/06/02,8306140276

106140284 Notice of violation from insp on 830226-0325.
* Region 2, Office of Director 83/04/18 2pp 18832 245 24X
Fiche: 50-259,83/06/02,8306140284.

06140297 IE Insp Repts 50-259/83-09, 50-260/83-09 & 50-296/83-09 on
830226-0325. Noncompliance noted. Failure to meet design flow
requirements & failure to have QA review & insp on maint
requests
PAULK, O. L. Region 2, Office of Director. CANTRELL, F. B. Division
of Project & Resident Programs. 83/04/13 14pp 18832,247. 24X
Fiche: 50-259,83/06/02,8306140297

090331 Forwards response to IE Bulletin 80-11 re masonry wall
sign wall displacement analysis. Masonry walls will remain
stable under max differential bldg displacement & other
ids caused by DBE
LEWIS, R. C. Tennessee Valley Authority. 83/06/03 DENTON, H. R.
Fiche of Nuclear Reactor Regulation, Director. 3pp 18795-078
(Fiche: 50-259,83/06/03,8306090331

10464 IE Info Notice 83-36, "Impact of Security Practices on Safe
Operations." Bvc list encl
DRAHAN, E. L. Division of Emergency Preparedness & Engineering
ponse (Post 830103). 83/06/09. Consolidated Edison Co. of New
ark, Inc 119pp. 18830:280 24X Fiche 50-000,83/06/09,8305110464

90195 Ack receipt of 830425 ltr informing NRC of steps taken to
rect violations noted in IE Insp Repts 50-259/83-03,
260/83-03 & 50-296/83-03.
LEWIS, R. C. Division of Project & Resident Programs. 83/06/09.
PARRIS, H. O. Tennessee Valley Authority. 1p. 19056:221. 24X
he: 50-259,83/06/09,8306290195.

6290203 Forwards response to NRC 830321 ltr re violations noted in
IE Insp Repts 50-259/83-03, 50-260/83-03 & 50-296/83-03
olation re Failure to perform radiation hazards evaluation
nied. Personnel counseled on radiological control
KAHMER, D. B. Tennessee Valley Authority 83/04/25 O'REILLY, J. P.
Region 2, Office of Director. 3pp 19056,222. 24X
iche: 50-259,83/06/09,8306290195.

10470 IE Info Notice 83-38, "Defective Heat Sink Adhesive &
imically Induced Chatter in Relays Within Printed
uit Cards." Bvc list encl.
DRAHAN, E. L. Division of Emergency Preparedness & Engineering
onse (Post 830103). 83/06/13 Consolidated Edison Co. of New
ark, Inc 118pp 18920:225 24X Fiche: 50-000,83/06/13,8305110470

0010 IE Info Notice 83-37, "Transformer Failure Resulting From
aded Internal Connection Cables" Bvc list encl.
DRAHAN, E. L. Division of Emergency Preparedness & Engineering
onse (Post 830103). 83/06/13 Consolidated Edison Co. of New
ark, Inc. 243pp. 18921:001. 24X Fiche 50-000,83/06/13,8306090010.

0077 Ack receipt of 830523 ltr informing NRC of steps taken to
ect violations noted in IE Insp Repts 50-259/83-12,
40/83-12 & 50-296/83-12.
LEWIS, R. C. Division of Project & Resident Programs 83/06/14.
PARRIS, H. O. Tennessee Valley Authority. 1p. 19056:038 24X
e: 50-259,83/06/14,8306290277

--8306290283 Responds to NRC 830422 ltr re violations noted in IE Insp
Repts 50-259/83-12, 50-260/83-12 & 50-296/83-12 Corrective
actions radiological incident repts issued for each instance
cited
MILLS, L. M. Tennessee Valley Authority 83/05/23 O'REILLY, J. P.
Region 2, Office of Director 5pp 19056 039 24X
Fiche 50-259,83/06/14,8306290277

--8306290288 Forwards IE Insp Repts 50-259/83-12, 50-260/83-12 &
50-296/83-12 on 830321-25 & notice of violation
LEWIS, R. C. Division of Project & Resident Programs 83/04/22
PARRIS, H. O. Tennessee Valley Authority 2pp 19056 044 24X
Fiche 50-259,83/06/14,8306290277

--8306290292 Notice of violation from insp on 830321-25
* Region 2, Office of Director 83/04/22 2pp 19056 046 24X
Fiche 50-259,83/06/14,8306290277

--8306290297 IE Insp Repts 50-259/83-12, 50-260/83-12 & 50-296/83-12 on
830321-25 Noncompliance noted radioactive waste operator
inside contamination zone w/o protective clothing or
radiation monitors
DEBB, D. T., BARR, K. P. Region 2, Office of Director 83/04/20
6pp 19056 048 24X Fiche 50-259,83/06/14,8306290277

8306290250 Forwards response to IE Bulletin 83-03 re check valve
failures in raw water cooling sys of diesel generators
Current test program sufficient to verify integrity of check
valves
MILLS, L. M. Tennessee Valley Authority 83/06/15 O'REILLY, J. P.
Region 2, Office of Director 3pp 19056 081 24X
Fiche 50-259,83/06/15,8306290250

8306290272 Ack receipt of supplemental 830610 ltr informing NRC of
steps taken to correct violations noted in IE Insp Repts
50-259/81-28, 50-260/81-28 & 50-296/81-20
LEWIS, R. C. Division of Project & Resident Programs. 83/06/16
PARRIS, H. O. Tennessee Valley Authority 1p. 19056 054 24X
Fiche 50-259,83/06/16,8306290272

--8306290275 Supplemental response to NRC 81031 ltr re violations noted
in IE Insp Repts 50-259/81-28, 50-260/81-28 & 50-296/81-20
Corrective actions five pump air vent valves removed &
replaced w/stronger & improved upper float guides
MILLS, L. M. Tennessee Valley Authority 83/06/10 O'REILLY, J. P.
Region 2, Office of Director 3pp 19056,055 24X
Fiche: 50-259,83/06/16,8306290272

8306210194 Ack receipt of 830603 ltr informing NRC of steps taken to
correct violations noted in IE Safeguards Insp Repts
50-259/83-10, 50-260/83-10 & 50-296/83-10.
LEWIS, R. C. Division of Project & Resident Programs 83/06/17
PARRIS, H. O. Tennessee Valley Authority 1p. 18919 030 24X
Fiche 50-259,83/06/17,8306210194

--8306210203 Forwards response to NRC 830429 ltr re violations noted in
IE Safeguards Insp Repts 50-259/83-10, 50-260/83-10 &
50-296/83-10 Corrective actions withheld (ref 10CFR73.21)
MILLS, L. M. Tennessee Valley Authority 83/06/03 O'REILLY, J. P.
Region 2, Office of Director. 1p 18919 031 24X
Fiche 50-259,83/06/17,8306210194

--8306210213 Forwards IE Safeguards Insp Repts 50-259/83-10, 50-260/83-10
& 50-296/83-10 on 830404-08 & notice of violation Notice
of violation withheld (ref 10CFR73.21)
LEWIS, R. C. Division of Project & Resident Programs 83/04/29
PARRIS, H. O. Tennessee Valley Authority 2pp 18919 032 24X
Fiche 50-259,83/06/17,8306210194

--8306210224 IE Safeguards Insp Repts 50-259/83-10, 50-260/83-10 &
50-296/83-10 on 830404-08 Noncompliance noted failure to
follow access control procedures Details withheld
(ref 10CFR73.21)
MOORE, D. E., MCQUIRE, D. R. Region 2, Office of Director 83/04/27
1p 18919 034. 24X Fiche 50-259,83/06/17,8306210194

8306290483 Approves issuance of SALP Repts 50-259/83-04, 50-260/83-04,
50-296/83-04, 50-327/83-04, 50-328/83-04, 50-390/83-07,
50-391/83-06, 50-438/83-06 & 50-439/83-06 for Jul 1981 - Dec
1982. No reply required
O'REILLY, J. P. Region 2, Office of Director 83/06/17. PARRIS, H. O.
Tennessee Valley Authority 3pp 19050,212 24X
Fiche 50-000,83/06/17,8306290483.

--8306290490 Forwards SALP Repts 50-259/83-04, 50-260/83-04,
50-296/83-04, 50-327/83-04, 50-328/83-04, 50-390/83-07,
50-391/83-06, 50-438/83-06 & 50-439/83-06 for Jul 1981 - Dec
1982
LEWIS, R. C. Division of Project & Resident Programs. 83/04/13
PARRIS, H. O. Tennessee Valley Authority. 3pp 19050 215 24X
Fiche 50-000,83/06/17,8306290483.

DOCKETED ITEMS

57

--8306290503 SALP Repts 50-259/83-04, 50-260/83-04, 50-296/83-04, 50-327/83-04, 50-328/83-04, 50-390/83 07, 50-391/83-04, 50-438/83-06 & 50-439/83-06 for Jul 1981 - Dec 1982
* Region 2, Office of Director 8/3/04/13 92pp 19050 210 24X
Fiche 50-000, 83/06/17, 8306290481

--8306290510 Comments on SALP Repts 50-259/83-04, 50-260/83-04, 50-296/83-04, 50-327/83-04, 50-328/83-04, 50-390/83 07, 50-391/83-06, 50-438/83-06 & 50-439/83-06 for Jul 1981 - Dec 1982
MILLS, L M Tennessee Valley Authority 83/05/10 O'REILLY, J P
Region 2, Office of Director 2pp 19050 310 24X
Fiche 50-259, 83/06/17, 8306290483

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 119pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Activation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

R Periodic operating reports & related correspondence

8306160482 Monthly operating repts for Apr 1983 W/830511 ltr
THOM, T, COFFEY, J A Tennessee Valley Authority 83/05/01
Office of Management and Program Analysis 39pp 18064 005 24X
Fiche 50-259, 83/05/01, 8306160482

B Reportable occurrences, LERs & related correspondence

8306010267 Deficiency rept re inability of prompt notification sys mobile sirens to complete routes in required time Initially reported on 830502 Addl sirens will be procured & mobile routes modified Full compliance expected by 830901
MILLS, L M Tennessee Valley Authority 83/05/23 O'REILLY, J P
Region 2, Office of Director 2pp 10674 324 24X
Fiche 50-259, 83/05/23, 8306010267

8306070092 LER 83-023/01T-0 on 830513, while performing insp per IE Bulletin 83-02, crack-like indications detected & confirmed by ultrasonic insp in weld KR-1-37 Cause not stated Weld will be repaired before startup W/830515 ltr
HOLDER, E I, GREEN, H J Tennessee Valley Authority 83/05/25
O'REILLY, J P Region 2, Office of Director 3pp 18739 155 24X
Fiche 50-259, 83/05/25, 8306070092

8306070087 LER 83-024/01T-0 on 830517, design review of diesel generator room ventilation indicated sys may not keep electrical components below design max temp limits Dissipated heat loads underestimated Ducting being installed W/830527 ltr
ELY, J O, GREEN, H J Tennessee Valley Authority 83/05/27
O'REILLY, J P Region 2, Office of Director 3pp 18737 347 24X
Fiche 50-259, 83/05/27, 8306070087

8306070241 LER 83-022/03L-0 on 830427, downstream HEPA filters in standby gas treatment sys trains A & B exceeded Tech Spec 18-month test frequency Caused by personnel error Procedure 81 4 7 B-4 review rescheduled.
ELY, J O, GREEN, H J Tennessee Valley Authority 83/05/27
O'REILLY, J P Region 2, Office of Director 3pp 18746 044 24X
Fiche 50-259, 83/05/27, 8306070241

8306090159 LER 83-025/03L-0 on 830502, standby gas treatment sys circuitry switch 1-P418-64-15 found set above max Tech Spec limit Caused by incorrect switch setting Setpoint corrected Caution tags placed on panel W/830601 ltr
BASS, G W, GREEN, H J Tennessee Valley Authority 83/06/01
O'REILLY, J P Region 2, Office of Director 3pp 18809 202 24X
Fiche 50-259, 83/06/01, 8306090159

8306070043 PND-11-83-044 until announced scheduling of enforcement conference w/NRC for 830601 to discuss offloading of 130 fuel bundles into high density fuel rack not verified for boral content
BUTCHER, R C, CANTRELL, F S Region 2, Office of Director 83/06/02
2pp 18739 361 24X Fiche 50-259, 83/06/02, 8306070043

8306210270 Updated LER 82-053/01X-1 on 820730, secondary containment integrity could not be confirmed Caused by displaced relief panel allowing leakage from turbine bldg into containment Panel replaced & leakage paths sealed W/830615 ltr
WILLIAMSON, B, GREEN, H J Tennessee Valley Authority 83/06/15
O'REILLY, J P Region 2, Office of Director 4pp 18913 037 24X
Fiche 50-259, 83/06/15, 8306210270

8306300139 LER 83-027/03L-0 on 830526, discovered that Surveillance Instruction 4 B 3 4-3 for reactor bldg vent monitoring sys calibr not performed within required interval Caused by personnel error Calibr performed W/830621 ltr
CAMPBELL, G D, GREEN, H J Tennessee Valley Authority 83/06/21
O'REILLY, J P Region 2, Office of Director 3pp 19122 317 24X
Fiche 50-259, 83/06/21, 8306300139

8306300208 LER 83-026/03L-0 on 830525, containment atmosphere dilution tank B level transmitter LT-84-13A indicated above Tech Spec limit Caused by transmitter zero drift Transmitter recalibr W/830622 ltr
IRBY, D J, GREEN, H J Tennessee Valley Authority 83/06/22
O'REILLY, J P Region 2, Office of Director 3pp 19122 118 24X
Fiche 50-259, 83/06/22, 8306300208

8306300066 Updated LER 83-009/01X-0 on 830223, design review of emergency diesel generator engine coolers showed coolers may not be able to maintain cooling water below hot setpoint Caused by design error Setpoint raised W/830623 ltr
ELY, J O, GREEN, H J Tennessee Valley Authority 83/06/23
O'REILLY, J P Region 2, Office of Director 3pp 19120 269 24X
Fiche 50-259, 83/06/23, 8306300066

V Operator Examinations

8306140687 Discusses operator & senior operator licensing exams & schedule to facilitate written & oral exams to be administered during wk of 830627 Approved ref matl listed in encl requested by 830427
VERRELLI, D M Division of Project & Resident Programs 83/03/30,
GREEN, H J Tennessee Valley Authority 3pp 18041 346 24X
Fiche 50-259, 83/03/30, 8306140687

8306140626 Responds to 830330 request for renewal of OT McChristian Senior Operator License SOP-293B-2 License expired McChristian should reapply for license NRC will consider request for waiver of exams
VERRELLI, D M Division of Project & Resident Programs 83/05/12
GREEN, H J Tennessee Valley Authority 1p 18842 006 24X
Fiche 50-259, 83/05/12, 8306140626

X Onsite Storage of Low Level Waste

8306060102 Responds to 830422 ltr re determination of fees for low level radwaste amend applications Fee determination acceptable
MILLS, L M Tennessee Valley Authority 83/06/01 MILLER, W O
License Fee Management Branch 1p 18719 339 24X
Fiche 50-000, 83/06/01, 8306060102

DOCKET 50-260 BROWNS FERRY NUCLEAR POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8306140107 Forwards summary of 830315 meeting at Region II of re proposed security mnds for future const activities at facilities list of attendees encl
LEWIS, R C Division of Project & Resident Programs 83/03/25
PARRIS, H O Tennessee Valley Authority 4pp 18839 082 24X
Fiche 50-259, 83/03/25, 8306140107

8306270007 Forwards revised physical security plan, reflecting NRC 830412 comments Rev withheld (ref 10CFR73.21)
MILLS, L M Tennessee Valley Authority 83/06/03, O'REILLY, J P,
Region 2, Office of Director 1p 18988 133 24X
Fiche 50-259, 83/06/03, 8306270007

8306210010 Forwards "Program Plan for Control Room Design Reviews for all TVA Nuclear Plants," in response to Generic Ltr 82-33 re upgrade of emergency plans
KAMMER, D B Tennessee Valley Authority 83/06/09 ADENBAM, E
Licensing Branch 4 3pp 18913 001 24X Fiche 50-000, 83/06/09, 8306210010

DOCKETED ITEMS

--8306210016 Procedure B42207 10, "Program Plan for Control Room Design Reviews for all TVA Nuclear Plants"
* Tennessee Valley Authority 83/06/09 200pp 18913 004 24X
Fiche: 50-000, 83/06/09, 8306210016

8306230201 Notification of 830621 meeting w/util in Bethesda, MD to discuss potential rev to App R submittal based on revised criteria w/respect to analyses on loss of offsite power & availability of other onsite units & condensate pumps
CLARK, D Operating Reactors Branch 2 83/06/16 VASSALLO, D B
Operating Reactors Branch 2 1p 18954 357 24X
Fiche: 50-259, 83/06/16, 8306230201

8306210194 Ack receipt of 830603 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts
50-259/83-10, 50-260/83-10 & 50-296/83-10.
LEWIS, R C Division of Project & Resident Programs. 83/06/17
PARRIS, H O Tennessee Valley Authority 1p 18919 030 24X
Fiche: 50-259, 83/06/17, 8306210194

--8306210203 Forwards response to NRC 830429 ltr re violations noted in IE Safeguards Insp Repts 50-259/83-10, 50-260/83-10 & 50-296/83-10 Corrective actions withheld (ref 10CFR73 21)
MILLS, L M Tennessee Valley Authority. 83/06/03 O'REILLY, J P
Region 2, Office of Director 1p 18919 031 24X
Fiche: 50-259, 83/06/17, 8306210194

--8306210213 Forwards IE Safeguards Insp Repts 50-259/83-10, 50-260/83-10 & 50-296/83-10 on 830404-08 & notice of violation Notice of violation withheld (ref 10CFR73 21)
LEWIS, R C Division of Project & Resident Programs 83/04/29
PARRIS, H O Tennessee Valley Authority 2pp 18919 032 24X
Fiche: 50-259, 83/06/17, 8306210194

--8306210224 IE Safeguards Insp Repts 50-259/83-10, 50-260/83-10 & 50-296/83-10 on 830404-08 Noncompliance noted: failure to follow access control procedures Details withheld (ref 10CFR73 21)
MOORE, D E Region 2, Office of Director 83/04/27 1p
18919 034 24X Fiche: 50-259, 83/06/17, 8306210194

Operating license stage documents & correspondence

830620180 Forwards safety evaluation re valve operability for 10, 18 & 20-inch butterfly valves used for purge or vent of containments Info submitted fails to demonstrate valve ability to close against pressure buildup during LOCA
VASSALLO, D B Operating Reactors Branch 2 83/05/19 PARRIS, H O
Tennessee Valley Authority 3pp 18701 113 24X
Fiche: 50-259, 83/05/19, 830620180

--8306202187 Safety evaluation re valve operability for 10, 18 & 20-inch butterfly valves used for purge or vent of containments Info submitted fails to demonstrate valve ability to close against pressure buildup during LOCA
* Office of Nuclear Reactor Regulation, Director 83/05/19 4pp
18701:116 24X Fiche: 50-259, 83/05/19, 830620180

8306150260 Forwards "Control of Heavy Loads (C-10), TVA, Browns Ferry Nuclear Power Station, Units 1, 2 & 3," draft technical evaluation re: Conference call requested within 4 to 5 wks to discuss review results
VASSALLO, D B Operating Reactors Branch 2 83/05/26 PARRIS, H O
Tennessee Valley Authority 2pp 18869:322 24X
Fiche: 50-259, 83/05/26, 8306150260

8306150266 "Control of Heavy Loads (C-10), TVA, Browns Ferry Nuclear Power Station, Units 1, 2 & 3," draft technical evaluation re: pt.
BOMBERGER, C., AHMED, N., BARGENT, I H Franklin Institute/Franklin Research Center NRC-03-B1-130, TER-C9306-337/338/33 83/04/05
CLEMONSON, F. NRC - No Detailed Affiliation Given 25pp
18869:324 24X Fiche: 50-259, 83/05/26, 8306150260

8306160453 Application for amend to Licenses DPR-52 & DPR-6B, changing Tech Spec to allow operation w/increased core flow
MILLS, L M Tennessee Valley Authority 83/06/02 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 18863:312 24X
Fiche: 50-260, 83/06/02, 8306160453

8306160456 Proposed Tech Spec changes allowing operation w/increased core flow
* Tennessee Valley Authority. 83/06/02 14pp 18863:314 24X
Fiche: 50-260, 83/06/02, 8306160453.

8306150243 Suppl 6 to 820914 application for amend to Licenses DPR-33, DPR-52 & DPR-6B, changing Tech Specs 3.10.C & 4.10.C re min depth of water required over single irradiated fuel assemblies during handling.
MILLS, L M Tennessee Valley Authority. 83/06/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 18846:127 24X
Fiche: 50-259, 83/06/03, 8306150243

--8306150248 Proposed changes to Tech Specs 3.10.C & 4.10.C re min depth of water required over single irradiated fuel assemblies during handling
* Tennessee Valley Authority 83/06/03 10pp 18846:129 24X
Fiche: 50-259, 83/06/03, 8306150243

8306140656 Forwards response to 830519 request for info re SCR, Section 4.0 on containment purge & vent valves Operability of valves justified under LOCA conditions
MILLS, L M Tennessee Valley Authority 83/06/07 DENTON, H R
Office of Nuclear Reactor Regulation, Director 7pp 18834:008 24X
Fiche: 50-259, 83/06/07, 8306140656

8306160507 Application for emergency amend to Licenses DPR-33, DPR-52 & DPR-6B, changing Tech Spec standby gas treatment sys required surveillance interval to once per operating cycle
MILLS, L M Tennessee Valley Authority 83/06/13 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 18864:157 24X
Fiche: 50-259, 83/06/13, 8306160507

--8306160523 Proposed Tech Specs changing standby gas treatment sys required surveillance interval to once per operating cycle Justification for emergency nature of proposed Tech Spec change encl
* Tennessee Valley Authority 83/06/13 5pp 18864:159 24X
Fiche: 50-259, 83/06/13, 8306160507

8306210014 Confirms agreement w/NRC re interpretation of Tech Spec 4.7.B.3 a requirements Spec satisfied by commitment to actuate annually standby gas treatment blowers in primary containment isolation sys logic Tech Spec 189 needed
MILLS, L M Tennessee Valley Authority 83/06/16 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 18911:357 24X
Fiche: 50-259, 83/06/16, 8306210014

8306290400 Application to amend Licenses DPR-33, DPR-52 & DPR-6B, changing Tech Specs to require annual rept of main steam safety/relief valve actuations, in response to NUREG-0737, Item 11 K.3.3 & Generic Ltr 83-02
MILLS, L M Tennessee Valley Authority 83/06/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 19053:133 24X
Fiche: 50-259, 83/06/20, 8306290400.

--8306290408 Proposed Tech Spec revs. requiring annual rept of main/steam safety/relief valve actuations, in response to NUREG-0737, Item 11 K.3.3 & Generic Ltr 83-02
* Tennessee Valley Authority 83/06/20 5pp 19053:135 24X
Fiche: 50-259, 83/06/20, 8306290400

8306240354 Notification of 830629 meeting w/util in Bethesda, MD to discuss util analysis on intervening combustibles & separation of circuits
CLARK, D Operating Reactors Branch 2 83/06/22 VASSALLO, D B
Operating Reactors Branch 2 2pp 18999:157 24X
Fiche: 50-259, 83/06/22, 8306240354

8306280415 Suppl 821220 response to NUREC-0313 request for addl info Ferrite content of cast austenitic stainless steel ranges from 15 to 20% Valves highly resistant to intergranular stress corrosion cracking.
MILLS, L M Tennessee Valley Authority 83/06/22 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 19018:351 24X
Fiche: 50-259, 83/06/22, 8306280415

8306280567 Advises that GE equipment items discussed in 830520 ltr re environ qualification reclassified as nonproprietary
MILLS, L M Tennessee Valley Authority 83/06/23 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 19018:028 24X
Fiche: 50-259, 83/06/23, 8306280567

8306300177 Discusses continuing problem re extreme length of time required for approval & resulting backlog of pending requests for Tech Spec changes, Majority of changes administrative & require minimal review time
MILLS, L M Tennessee Valley Authority 83/06/27 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 19122:044 24X
Fiche: 50-259, 83/06/27, 8306300177

Q Inspection reports, IE Bulletins & correspondence

8306290218 Forwards IE Insp Repts 50-259/83-03, 50-260/83-03 & 50-296/83-03 on 830110-14 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/03/21
PARRIS, H O Tennessee Valley Authority 2pp 19056:135 24X
Fiche: 50-259, 83/03/21, 8306290218

--8306290224 Notice of violation from insp on 830110-14
* Region 2, Office of Director 83/03/21 9pp 19056:137 24X
Fiche: 50-259, 83/03/21, 8306290218

DOCKETED ITEMS

59

--8306290228 IE Insp Repts 50-259/83-03, 50-260/83-03 & 50-296/83-03 on 830110-14 Noncompliance noted failure to perform evaluation of radiation hazards to personnel & employee failure to wear gloves in contaminated zone
DEBB, B T, BARR, K P Region 2, Office of Director 83/03/03
9pp 19056 139 24X Fiche 50-259, 83/03/21, 8306290210

8306140543 Confirms mgt meeting on 830421 in Chattanooga, TN to review results of first phase of annual appraisal of regulatory performance, per 830328 telcon
LEWIS, R C Division of Project & Resident Programs 83/04/12
PARRIS, H O Tennessee Valley Authority 3pp 18834 176 24X
Fiche 50-000, 83/04/12, 8306140543

8306140041 Forwards results of testing required by IE Bulletin 80-04, "Engineered Safety Feature (ESF) Reset Controls " Two valves each in HPCI sys & RCIC sys do not remain closed on reset of sys line isolation signal
KAMMER, D S Tennessee Valley Authority 83/05/12 O'REILLY, J P, Region 2, Office of Director 2pp 18838 231 24X
Fiche 50-260, 83/05/12, 8306140041

8306140422 Confirms 830601 mgt meeting at site to discuss mgt controls for refueling operations, per 830519 telcon
LEWIS, R C Division of Project & Resident Programs 83/05/23
PARRIS, H O Tennessee Valley Authority 3pp 18838 049 24X
Fiche 50-259, 83/05/23, 8306140422

8306140685 Forwards IE Insp Repts 50-259/83-17, 50-260/83-17 & 50-296/83-17 on 830509-12 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/05/25
PARRIS, H O Tennessee Valley Authority 2pp 18841 336 24X
Fiche 50-259, 83/05/25, 8306140685

--8306140692 IE Insp Repts 50-259/83-17, 50-260/83-17 & 50-296/83-17 on 830509-12 No noncompliance noted Major areas inspected followup on IE Bulletin 80-11, "Masonry Wall Design "
LENAHAN, J J, CONLON, T E Region 2, Office of Director 83/05/25
5pp, 18841 338 24X Fiche 50-259, 83/05/25, 8306140685

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc
123pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 119pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8306150625 Requests approval for M Tokar to visit site on 830613 in order to observe exam of fuel removed from reactors
Specific info for discussion listed
VABBALLO, D B Operating Reactors Branch 2 83/05/27 PARRIS, H O Tennessee Valley Authority, 3pp 18847 285 24X
Fiche 50-259, 83/05/27, 8306150625

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31, Consolidated Edison Co. of New York, Inc 116pp 18732 208 24X Fiche, 50-000, 83/05/31, 8305110461.

8306140251 Ack receipt of 830525 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-09, 50-260/83-09 & 50-296/83-09
LEWIS, R C Division of Project & Resident Programs 83/06/02
PARRIS, H O Tennessee Valley Authority 1p 18832, 236 24X
Fiche, 50-259, 83/06/02, 8306140251

--8306140266 Responds to NRC 830418 ltr re violations noted in IE Insp Repts 50-259/83-09, 50-260/83-09 & 50-296/83-09 Corrective actions: all conduit supports for safety-related equipment corrected by work plan or maint request
KAMMER, D S Tennessee Valley Authority 83/05/25 O'REILLY, J P Region 2, Office of Director 6pp 18832 237 24X
Fiche 50-259, 83/06/02, 8306140251

--8306140276 Forwards IE Insp Repts 50-259/83-09, 50-260/83-09 & 50-296/83-09 on 830226-0325 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/04/18
PARRIS, H O Tennessee Valley Authority 2pp, 18832 243 24X
Fiche, 50-259, 83/06/02, 8306140251

--8306140284 Notice of violation from insp on 830226-0325.
* Region 2, Office of Director 83/04/18 2pp, 18832 245 24X
Fiche 50-259, 83/06/02, 8306140251

--8306140297 IE Insp Repts 50-259/83-09, 50-260/83-09 & 50-296/83-09 on 830226-0325 Noncompliance noted failure to meet design flow requirements & failure to have QA review & insp on maint requests
PAULK, G L Region 2, Office of Director CANTRELL, F B Division of Project & Resident Programs 83/04/13 14pp 18832 247 24X
Fiche 50-259, 83/06/02, 8306140251

8306090331 Forwards response to IE Bulletin 80-11 re masonry wall design wall displacement analysis Masonry walls will remain stable under max differential bldg displacement & other loads caused by DBE
MILLS, L M Tennessee Valley Authority 83/06/03 DENTON, H R, Office of Nuclear Reactor Regulation, Director 3pp 18795 078 24X Fiche 50-259, 83/06/03, 8306090331

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc 119pp 18830 280, 24X Fiche 50-000, 83/06/09, 8305110464.

8306290195 Ack receipt of 830425 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-03, 50-260/83-03 & 50-296/83-03
LEWIS, R C Division of Project & Resident Programs, 83/06/09
PARRIS, H O Tennessee Valley Authority 1p 19056, 221 24X
Fiche 50-259, 83/06/09, 8306290195

--8306290203 Forwards response to NRC 830321 ltr re violations noted in IE Insp Repts 50-259/83-03, 50-260/83-03 & 50-296/83-03
Violation re failure to perform radiation hazards evaluation denied Personnel counseled on radiological control.
KAMMER, D S Tennessee Valley Authority 83/04/25, O'REILLY, J P, Region 2, Office of Director 5pp, 19056, 222 24X
Fiche 50-259, 83/06/09, 8306290195

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 118pp 18920 225 24X Fiche, 50-000, 83/06/13, 8305110470.

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 243pp 18921 001 24X Fiche, 50-000, 83/06/13, 8306090010.

8306290277 Ack receipt of 830523 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-12, 50-260/83-12 & 50-296/83-12.
LEWIS, R C Division of Project & Resident Programs, 83/06/14
PARRIS, H O Tennessee Valley Authority 1p 19056, 038 24X
Fiche 50-259, 83/06/14, 8306290277

--8306290283 Responds to NRC 830422 ltr re violations noted in IE Insp Repts 50-259/83-12, 50-260/83-12 & 50-296/83-12 Corrective actions radiological incident repts issued for each instance cited
MILLS, L M Tennessee Valley Authority, 83/05/23 O'REILLY, J P, Region 2, Office of Director 5pp 19056 039 24X
Fiche 50-259, 83/06/14, 8306290277.

--8306290288 Forwards IE Insp Repts 50-259/83-12, 50-260/83-12 & 50-296/83-12 on 830321-25 & notice of violation.
LEWIS, R C Division of Project & Resident Programs, 83/04/22.
PARRIS, H O Tennessee Valley Authority 2pp 19056, 044, 24X
Fiche 50-259, 83/06/14, 8306290277.

--8306290292 Notice of violation from insp on 830321-25
* Region 2, Office of Director 83/04/22, 2pp 19056, 046, 24X
Fiche 50-259, 83/06/14, 8306290277

--8306290297 IE Insp Repts 50-259/83-12, 50-260/83-12 & 50-296/83-12 on 830321-25 Noncompliance noted radioactive waste operator inside contamination zone w/o protective clothing or radiation monitors
DEBB, D T, BARR, K P, Region 2, Office of Director, 83/04/20, 6pp 19056 048 24X Fiche 50-259, 83/06/14, 8306290277

8306290250 Forwards response to IE Bulletin 83-03 re check valve failures in raw water cooling sys of diesel generators.
Current test program sufficient to verify integrity of check valves
MILLS, L M Tennessee Valley Authority 83/06/15, O'REILLY, J P, Region 2, Office of Director, 3pp 19056 081, 24X
Fiche 50-259, 83/06/15, 8306290250.

DOCKETED ITEMS

6290272 Ack receipt of supplemental 830610 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 0-259/81-28, 50-260/81-28 & 50-296/81-28
 LEWIS, R C Division of Project & Resident Programs 83/06/16
 FARRIS, H O Tennessee Valley Authority. 1p 19056 054 24X
 Fiche 50-259, 83/06/16, 8306290272

306290275 Supplemental response to NRC B11031 ltr re violations noted in IE Insp Repts 50-259/81-28, 50-260/81-28 & 50-296/81-28
 Corrective actions: five pump air vent valves removed & replaced w/stronger & improved upper float guides
 MILLER, L M Tennessee Valley Authority 83/06/10 O'REILLY, J P
 Region 2, Office of Director 3pp 19056:035 24X
 Fiche 50-259, 83/06/16, 8306290272

6210194 Ack receipt of 830603 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 0-259/83-10, 50-260/83-10 & 50-296/83-10
 LEWIS, R C Division of Project & Resident Programs 83/06/17
 FARRIS, H O Tennessee Valley Authority. 1p 18919, 030 24X
 Fiche 50-259, 83/06/17, 8306210194

306210203 Forwards response to NRC 830429 ltr re violations noted in IE Safeguards Insp Repts 50-259/83-10, 50-260/83-10 & 50-296/83-10
 Corrective actions withheld (ref 10CFR73.21)
 MILLER, L M Tennessee Valley Authority 83/06/03 O'REILLY, J P
 Region 2, Office of Director 1p 18919:031 24X
 Fiche 50-259, 83/06/17, 8306210194

306210213 Forwards IE Safeguards Insp Repts 50-259/83-10, 50-260/83-10 & 50-296/83-10 on 830404-08 & notice of violation, Notice of Violation Withheld (ref 10CFR73.21)
 LEWIS, R C Division of Project & Resident Programs. 83/04/29
 FARRIS, H O Tennessee Valley Authority 2pp 18919:032 24X
 Fiche 50-259, 83/06/17, 8306210194

306210224 IE Safeguards Insp Repts 50-259/83-10, 50-260/83-10 & 50-296/83-10 on 830404-08 Noncompliance noted: Failure to follow access control procedures. Details withheld (ref 10CFR73.21).
 MOORE, D E; MCQUIRE, D R. Region 2, Office of Director 83/04/27
 1p. 18919:034 24X Fiche 50-259, 83/06/17, 8306210194

6290483 Approves issuance of BALP Repts 50-259/83-04, 50-260/83-04, 50-296/83-04, 50-327/83-04, 50-328/83-04, 50-390/83-07, 50-391/83-06, 50-438/83-06 & 50-439/83-06 for Jul 1981 - Dec 1982
 No reply required
 O'REILLY, J P. Region 2, Office of Director. 83/06/17. FARRIS, H O. Tennessee Valley Authority 3pp. 19050 212 24X
 Fiche 50-000, 83/06/17, 8306290483

306290490 Forwards BALP Repts 50-259/83-04, 50-260/83-04, 50-296/83-04, 50-327/83-04, 50-328/83-04, 50-390/83-07, 50-391/83-06, 50-438/83-06 & 50-439/83-06 for Jul 1981 - Dec 1982.
 LEWIS, R C Division of Project & Resident Programs. 83/04/13.
 FARRIS, H O Tennessee Valley Authority. 3pp 19050, 215 24X
 Fiche 50-000, 83/06/17, 8306290483

306290503 BALP Repts 50-259/83-04, 50-260/83-04, 50-296/83-04, 50-327/83-04, 50-328/83-04, 50-390/83-07, 50-391/83-06, 50-438/83-06 & 50-439/83-06 for Jul 1981 - Dec 1982
 * Region 2, Office of Director 83/04/13 92pp. 19050 218 24X
 Fiche: 50-000, 83/06/17, 8306290483

306290510 Comments on BALP Repts 50-259/83-04, 50-260/83-04, 50-296/83-04, 50-327/83-04, 50-328/83-04, 50-390/83-07, 50-391/83-06, 50-438/83-06 & 50-439/83-06 for Jul 1981 - Dec 1982.
 MILLER, L M Tennessee Valley Authority. 83/06/10 O'REILLY, J P.
 Region 2, Office of Director 2pp. 19050:010 24X
 Fiche: 50-259, 83/06/17, 8306290483

35110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers." Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 116pp. 19021:179 24X Fiche 50-000, 83/06/22, 8305110475

05110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/22. Consolidated Edison Co. of New York, Inc. 120pp. 18997:007 24X Fiche 50-000, 83/06/22, 8305110477

05110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions." Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/23. Consolidated Edison Co. of New York, Inc. 116pp. 18996:242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

R Periodic operating reports & related correspondence

8306160482 Monthly operating repts for Apr 1983 W/830511 ltr
 THOM, T. C. DUFFEY, J A Tennessee Valley Authority 83/05/01
 Office of Management and Program Analysis 39pp 18864 085 24X
 Fiche 50-259, 83/05/01, 8306160482

S Reportable occurrences, LERs & related correspondence

8306010269 Deficiency re rpt re inability of prompt notification sys mobile sirens to complete routes in required time Initially reported on 830502 Addl sirens will be procured & mobile routes modified Full compliance expected by 830901
 MILLER, L M Tennessee Valley Authority 83/05/23 O'REILLY, J P
 Region 2, Office of Director 2pp 18674 324 24X
 Fiche 50-259, 83/05/23, 8306010269

8306010237 Updated LER 81-050/03X-4 on 811003, containment atmosphere torus hydrogen analyzer 2-H2M-76-104 removed from svc for corrective maint Caused by water in sensing lines Design Change Request P-2493 evaluated W/830524 ltr
 GREEN, H J BURNS, R Tennessee Valley Authority 83/05/24
 O'REILLY, J P. Region 2, Office of Director 2pp 18672 300 24X
 Fiche 50-260, 83/05/24, 8306010237

8306070084 LER 83-023/03L-0 on 830602, while performing BT 4 1.A-6 drywell pressure switch found operating above Tech Spec trip setting, initiating drywell high pressure half scram Caused by setpoint drift W/830527 ltr
 CHAMBERS, O T GREEN, H J Tennessee Valley Authority 83/05/27
 O'REILLY, J P. Region 2, Office of Director 4pp 18739 202 24X
 Fiche 50-260, 83/05/27, 8306070084

8306070099 LER 83-022/03L-0 on 830503, scram discharge val scram switch failed to operate Reactor protection sys logic switch tripped upon actuation Caused by Magnetrol model switch drift outside operating band Switch adjusted W/830527 ltr
 OODWIN, D C GREEN, H J Tennessee Valley Authority 83/05/27
 O'REILLY, J P. Region 2, Office of Director 3pp. 18737:361 24X
 Fiche 50-260, 83/05/27, 8306070099

8306210226 LER 83-025/03L-0 on 830520, pressure switch PB-3-22B as-found setpoint set above Tech Spec limits during performance of BI 4 1.A-5 Caused by calibr drift Barksdale B2T-A126B pressure switch recalibr W/830614 ltr
 OODWIN, D C GREEN, H J Tennessee Valley Authority. 83/06/14
 O'REILLY, J P. Region 2, Office of Director 4pp 18916 031 24X
 Fiche: 50-260, 83/06/14, 8306210226

8306270090 LER 83-024/03L-0 on 830515, recirculation pump 2A tripped after isolation valve 2-24-744 failed closed Caused by sheared coupling pins Crane Model XP-3600 valve repaired & pump returned to svc W/830614 ltr
 LOCHBAUM, D GREEN, H J Tennessee Valley Authority 83/06/14
 O'REILLY, J P. Region 2, Office of Director 3pp 18988 082 24X
 Fiche: 50-260, 83/06/14, 8306270090

8306170294 PND-II-83-047 on 830613, standby gas treatment sys train B declared inoperable due to problems w/filter heaters Cause not stated Event involved no equipment damage, no personnel error or injury & no radioactive releases
 BUTCHER, R C VERRELLI, D M Region 2, Office of Director 83/06/15
 2pp 18879 048 24X Fiche 50-260, 83/06/15, 8306170294

8306210136 LER 83-027/03L-0 on 830520, differential pressure switch for pressure suppression chamber-reactor bldg vacuum breakers found operating above Tech Spec limits Caused by switch drift Switch 2-PD1B-64-20 recalibr W/830613 ltr
 CHAMBERS, O T GREEN, H J Tennessee Valley Authority. 83/06/15
 O'REILLY, J P. Region 2, Office of Director 3pp 18914:189 24X
 Fiche 50-260, 83/06/15, 8306210136

8306270327 Updated LER 83-014/03X-1 on 830330, air operator of main steam relief valve PCV-1-180 found assembled incorrectly. Caused by personnel failure to follow procedure Valve repaired & insp procedure revised W/830616 ltr
 HOLDER, E T GREEN, H J Tennessee Valley Authority 83/06/16
 O'REILLY, J P. Region 2, Office of Director 3p 18973 051 24X
 Fiche: 50-260, 83/06/16, 8306270327

8306280375 LER 83-026/03L-0 on 830521, during rod sequence exchange, calculated R factor less than R setpoint Caused by R factor calculated out during power shaping rod moves Rod pattern adjusted & verified W/830617 ltr
 MINGO, M D GREEN, H J Tennessee Valley Authority 83/06/17
 O'REILLY, J P. Region 2, Office of Director 3pp 19014:067 24X
 Fiche 50-260, 83/06/17, 8306280375

DOCKETED ITEMS

61

8304300224 LER 83-028/03L-0 on 830526, during normal operation, HPCI sys declared inoperable due to blown inverter fuse Fuse replaced HPCI turbine control valve failed to open due to misadjusted rod Rod adjusted W/830422 ltr.
CARTER, S., GREEN, H J Tennessee Valley Authority 83/06/22
O'REILLY, J P Region 2, Office of Director 3pp 19119 203 24X
Fiche 50-260, 83/06/22, 8304300224

8306300181 LER 83-029/03L-0 on 830528, during normal operation, drywell radiation monitor RE-90-256 sample pump tripped Caused by blown Fuse Fuse replaced & drywell air sampling sys returned to svc W/830624 ltr
CARTER, S., GREEN, H J Tennessee Valley Authority 83/06/24
O'REILLY, J P Region 2, Office of Director 3pp 19122 196 24X
Fiche 50-260, 83/06/24, 8306300181

V Operator Examinations

8306140687 Discusses operator & senior operator licensing exam & schedule to facilitate written & oral exams to be administered during wk of 830627 Approved ref matl listed in encl requested by 830427
VERRELLI, D M Division of Project & Resident Programs 83/03/30
GREEN, H J Tennessee Valley Authority 3pp 18841 346 24X
Fiche 50-259, 83/03/30, 8306140687

8306140626 Responds to 830330 request for renewal of QT McChristian Senior Operator License 80P-2938-2 License expired McChristian should reapply for license NRC will consider request for waiver of exam
VERRELLI, D M Division of Project & Resident Programs 83/05/12
GREEN, H J Tennessee Valley Authority 1p 18842 086 24X
Fiche 50-259, 83/05/12, 8306140626

X Onsite Storage of Low Level Waste

8306060102 Responds to 830422 ltr re determination of fees for low level radwaste amend applications Fee determination acceptable
MILLER, L M Tennessee Valley Authority 83/06/01 MILLER, W O
License Fee Management Branch 1p 18719 359 24X
Fiche 50-000, 83/06/01, 8306060102

DOCKET 50-261 H B ROBINSON PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8306140698 Ack receipt of 830131 ltr informing NRC of corrective actions taken in response to 821101 confirmation of action ltr re emergency preparedness program
LEWIS, R C Division of Project & Resident Programs 83/03/31
FURR, B J Carolina Power & Light Co 1p 18841 268 24X
Fiche 50-000, 83/03/31, 8306140698

--8306140708 Submits status of corrective actions for deficiencies noted in 821101 confirmation of action ltr re emergency preparedness program
UTLEY, E E Carolina Power & Light Co 83/01/31 O'REILLY, J P
Region 2, Office of Director 2pp 18841 269 24X
Fiche 50-000, 83/03/31, 8306140698

8306090391 Releases public version of revised emergency response plan
FELTON, J M Division of Rules and Records 83/06/01, Document
Management Branch 1p 18814 084, 24X Fiche 50-261, 83/06/01,
8306090391

--8306090394 Public version of Rev 13 to emergency response plan
ZIMMERMAN, B R Carolina Power & Light Co, 83/05/16 312pp
18814 085 24X Fiche 50-261, 83/06/01, 8306090391

8306080122 Forwards addl info re App R exemption requests for pipe alloy, component cooling water pump room & reactor coolant pump bay areas Exemption request for pipe alloy withdrawn W/2002 drawings Aperture cards are available in PDR.
EURY, L W Carolina Power & Light Co 83/06/07 VARQA, B A
Operating Reactors Branch 1, 102pp, 10770 257 24X
Fiche 50-261, 83/06/07, 8306080122

8306290420 Forwards IE Insp Rept 50-261/83-13 on 830502-06 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs, 83/06/08
UTLEY, E E Carolina Power & Light Co 2pp 19053 181 24X
Fiche 50-261, 83/06/08, 8306290420

--8306290426 IE Insp Rept 50-261/83-13 on 830502-06 No noncompliance noted, Major areas inspected emergency preparedness
CLINE, W E., DECKER, T R, Region 2, Office of Director,
JENKINS, O R, Division of Emergency Preparedness & Materials
Safety, 83/06/07 7pp 19053 183 24X Fiche 50-261, 83/06/08,
8306290420

8306220273 Confirms telcon w/IE re acceptability of emergency response facilities Locations of alternate locations for offsite personnel to assemble to communicate w/emergency operations facilities acceptable
HURFORD, W J Carolina Power & Light Co 83/06/17 DENTON, H R
Office of Nuclear Reactor Regulation, Director, 1p 18926 033 24X
Fiche 50-000, 83/06/17, 8306220273

O Adjudicatory correspondence

8306160007 Advises that NRC will prepare EIS for steam generators ASLB will be informed of projected issuance date
KARMAN, M Hearing Branch 1, 83/06/14, MARQUILIES, M B,
HETRICK, D L, KLINE, J R Atomic Safety and Licensing Board Panel
1p 18861 356 24X Fiche 50-261, 83/06/14, 8306160007

P Operating license stage documents & correspondence

8306070193 Responds to 821013 ltr finding util position on NURE0-0737, Item II K 3 25 re power on pump seals acceptable Addl info re component cooling water pumps B & C clarified Both pumps automatically tripped by containment spray sys
ZIMMERMAN, B R Carolina Power & Light Co 83/05/31 VARQA, B A
Operating Reactors Branch 1, 2pp 18736 241 24X
Fiche 50-261, 83/05/31, 8306070193

8306070101 Responds to 821001 ltr re util 801231 response to NURE0-0737, Item III, D 3 4, "Control Room Habitability," Control room HVAC sys modified to reduce unfiltered leakage Evaluations & recommendations re NUS-3696 encl.
EURY, L W Carolina Power & Light Co 83/06/02 VARQA, B A
Operating Reactors Branch 1, 17pp 18738 347 24X
Fiche 50-261, 83/06/02, 8306070101

8306100260 Forwards updated response to 830321 & 23 requests for addl info re final steam generator repair rept.
ZIMMERMAN, B R Carolina Power & Light Co, 83/06/03 VARQA, B A
Operating Reactors Branch 1, 22pp 18807 013 24X
Fiche 50-261, 83/06/03, 8306100260

8306170460 Notification of 830628 meeting w/util in Bethesda, MD to discuss plans for repair/replacement of steam generators Agenda encl.
REQUA, O Operating Reactors Branch 1, 83/06/14, VARQA, B A
Operating Reactors Branch 1, 4pp 18706 355, 24X
Fiche 50-261, 83/06/14, 8306170460

8306200018 Notification of 830624 meeting w/util in Bethesda, MD to discuss & schedule multi-plant actions, NURE0-0737 & plant-specific open items.
REQUA, O Operating Reactors Branch 1, 83/06/14, VARQA, B A
Operating Reactors Branch 1, 3pp 18709 121 24X
Fiche 50-261, 83/06/14, 8306200018

8306220005 Documents 830606 telcon re util 830209 response to NURE0-0737, Item II, E 1 2, "Auxiliary Feedwater Sys Automatic Initiation & Flow Indication" Bypass signals do not block indicators, annunciator or reactor trip signals
ZIMMERMAN, B R Carolina Power & Light Co, 83/06/17 VARQA, B A,
Operating Reactors Branch 1, 2pp, 18927 360 24X
Fiche 50-261, 83/06/17, 8306220005

8306280003 Informs of progress made since 820719 meeting re Unresolved Safety Issue A-47, "Safety Implications of Control Sys." Task Action Plan for A-47 completed Sept 1982 & EQ&O contracted for plant design review List of info needed encl.
EISENHUT, D O, Division of Licensing 83/06/20 UTLEY, E E
Carolina Power & Light Co 34pp, 19044 043, 24X
Fiche 50-261, 83/06/20, 8306280003

G Inspection reports, IE Bulletins & correspondence

8306140078 Confirms 830328 enforcement meeting at Region II ofc to discuss recent events at Brunswick 1 re standby gas treatment deluge sys & violation involving radwaste shipments from Robinson 2 per 830322 telcon Agenda encl
O'REILLY, J P, Region 2, Office of Director, 83/03/25 UTLEY, E E,
Carolina Power & Light Co 2pp, 18838 342 24X
Fiche 50-000, 83/03/25, 8306140078

8306140698 Ack receipt of 830131 ltr informing NRC of corrective actions taken in response to 821101 confirmation of action ltr re emergency preparedness program
LEWIS, R C, Division of Project & Resident Programs, 83/03/31,
FURR, B J Carolina Power & Light Co 1p, 18841 268 24X
Fiche 50-000, 83/03/31, 8306140698

DOCKETED ITEMS

--B30614070B Submits status of corrective actions for deficiencies noted in B21101 confirmation of action ltr re emergency preparedness program
UTLEY, E.E. Carolina Power & Light Co. 83/01/31. O'REILLY, J.P.
Region 2, Office of Director. 2pp. 18841 269 24X
Fiche 50-000, 83/03/31, B306140898

B306140264 Suppl's B10119 response to IE Bulletin 80-15, describing relocation of emergency notification sys (ENS) power supply to emergency power source ENS to be relocated in new technical support ctr presently under const.
FURR, B.J. Carolina Power & Light Co. 83/04/29. O'REILLY, J.P.
Region 2, Office of Director. 2pp. 18832:219 24X
Fiche 50-261, 83/04/29, B306140264.

B306140399 Confirms B30510 mgt meeting in Raleigh, NC to review BALP program (first phase) results, per B30412 telcon Proposed agenda encl.
LEWIS, R.C. Division of Project & Resident Programs. 83/04/29
UTLEY, E.E. Carolina Power & Light Co. 3pp. 18832 093 24X
Fiche: 50-000, 83/04/29, B306140399

B305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device." Svc list encl
TAYLOR, J.M. Division of Safeguards & Inspection Programs (Post B30103). 83/05/26. Consolidated Edison Co. of New York, Inc. 125pp. 18831:043 24X Fiche: 50-000, 83/05/26, B305110458

B305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post B30103). 83/05/26. Consolidated Edison Co. of New York, Inc. 115pp. 18732:085 24X Fiche: 50-000, 83/05/26, B305110460

B305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs." Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post B30103). 83/05/31. Consolidated Edison Co. of New York, Inc. 116pp. 18732 208 24X Fiche 50-000, 83/05/31, B305110461.

B306070172 Ack receipt of B30426 ltr requesting TLD data collected during steam generator insp for independent analysis of beta dose data will be provided as soon as available.
ZIMMERMAN, B.R. Carolina Power & Light Co. 83/05/31. VARQA, S.A. Operating Reactors Branch 1. 1p. 18736:279. 24X
Fiche: 50-261, 83/05/31, B306070172.

B306290247 Responds to IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators." No check valves installed in branch connection piping from main svc water headers to diesel generator components
FURR, B.J. Carolina Power & Light Co. 83/06/08. O'REILLY, J.P. Region 2, Office of Director. 1p. 19036:084. 24X
Fiche: 80-261, 83/06/08, B306290247

B306290420 Forwards IE Insp Rept 50-261/83-13 on B30502-06. No noncompliance noted.
VERRELLI, D.M. Division of Project & Resident Programs. 83/06/08. UTLEY, E.E. Carolina Power & Light Co. 2pp. 19053:181 24X
Fiche: 50-261, 83/06/08, B306290420.

--B306290426 IE Insp Rept 50-261/83-13 on B30502-06. No noncompliance noted Major areas inspected: emergency preparedness.
CLINE, W.E., DECKER, T.R. Region 2, Office of Director.
JENKINS, Q.R. Division of Emergency Preparedness & Materials Safety. 83/06/07. 7pp. 19053 183. 24X Fiche: 50-261, 83/06/08, B306290420.

B305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post B30103). 83/06/09. Consolidated Edison Co. of New York, Inc. 117pp. 18830 280. 24X Fiche 50-000, 83/06/09, B305110464.

B305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Biometrically Induced Chatter in Relays Within Printed Circuit Cards." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post B30103). 83/06/13. Consolidated Edison Co. of New York, Inc. 118pp. 18920:225 24X Fiche: 50-000, 83/06/13, B305110470.

B306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post B30103). 83/06/13. Consolidated Edison Co. of New York, Inc. 243pp. 18921:001 24X Fiche: 50-000, 83/06/13, B306090010.

B306290524 Approves issuance of BALP rept Notes improvement in safety-related activities, emergency preparedness & security & safeguards Weaknesses in QA program will be monitored
O'REILLY, J.P. Region 2, Office of Director. 83/06/14. UTLEY, E.E. Carolina Power & Light Co. 5pp. 19049 282 24X
Fiche 50-000, 83/06/14, B306290524

--B306290531 Forwards BALP Repts 50-325/83-09, 50-324/83-09, 50-261/83-07, 50-400/83-10 & 50-401/83-10 for Jan 1982 - Jan 1983
Evaluation will be discussed in Raleigh, NC on B30510
LEWIS, R.C. Division of Project & Resident Programs. 83/05/03.
UTLEY, E.E. Carolina Power & Light Co. 2pp. 19049 287 24X
Fiche 50-000, 83/06/14, B306290524

--B306290537 BALP rept for Jan 1982 - Jan 1983
* Region 2, Office of Director. 83/05/03. 64pp. 19049 289 24X
Fiche 50-000, 83/06/14, B306290524

--B306290553 Responds to B30503 BALP rept for Jan 1982 - Jan 1983 Reduced NRC attention may be appropriate for Category 1 re fire protection NRC attention should be maintained at normal levels for emergency preparedness
UTLEY, E.E. Carolina Power & Light Co. 83/05/20. O'REILLY, J.P. Region 2, Office of Director. 16pp. 19049 384 24X
Fiche 50-000, 83/06/14, B306290524

--B306290555 Forwards replacement Page 2 to Attachment 2 of B30520 ltr which commented on BALP rept
EURY, L.W. Carolina Power & Light Co. 83/05/27. O'REILLY, J.P. Region 2, Office of Director. 2pp. 19050:009 24X
Fiche 50-000, 83/06/14, B306290524

B306240470 Forwards request for addl info needed for Franklin Research Ctr review of B30204 response to IE Bulletin 80-11 on masonry wall design info should be submitted by B30725
VARQA, S.A. Operating Reactors Branch 1. 83/06/17. UTLEY, E.E. Carolina Power & Light Co. 3pp. 18998 082 24X
Fiche: 50-261, 83/06/17, B306240470

B305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers." Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post B30103). 83/06/22. Consolidated Edison Co. of New York, Inc. 115pp. 19021:179. 24X Fiche: 50-000, 83/06/22, B305110475

B305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety Related Equipment." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post B30103). 83/06/22. Consolidated Edison Co. of New York, Inc. 120pp. 18997:007 24X Fiche: 50-000, 83/06/22, B305110477

B305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions." Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post B30103). 83/06/23. Consolidated Edison Co. of New York, Inc. 116pp. 18996:242 24X Fiche 50-000, 83/06/23, B305110479

B305110483 IE Info Notice 83-43, "Improper Bettings of Intermediate Range (IR) High Flux Trip Setpoints." Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post B30103). 83/06/24. Consolidated Edison Co. of New York, Inc. 116pp. 19046:297. 24X Fiche 50-000, 83/06/24, B305110483

R. Periodic operating reports & related correspondence

B306160420 Monthly operating rept for Apr 1983 W/B30510 ltr
NORRIS, H.R., STARKEY, R.B. Carolina Power & Light Co. 83/05/02.
DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement. 4pp. 18860:033. 24X Fiche: 50-261, 83/05/02, B306160420

B306140405 Monthly operating rept for May 1983 W/B30610 ltr.
NORRIS, H.R., STARKEY, R.B. Carolina Power & Light Co. 83/06/02
DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement. 5pp. 18838:091. 24X Fiche: 50-261, 83/06/02, B306140405.

B Reportable occurrences, LERs & related correspondence

B306070161 LER B3-004/03L-0: on B30427, during testing of spare pump installed to replace svc water pump A pump tripped on overcurrent Apparently caused by internal binding of shaft as result of debris in impeller assembly. W/B30526 ltr.
COX, H.T., STARKEY, R.B. Carolina Power & Light Co. 83/05/26
O'REILLY, J.P. Region 2, Office of Director. 4pp. 18736:284. 24X
Fiche: 50-261, 83/05/26, B306070161.

DOCKETED ITEMS

63

B306070182 LER 83-007/03L-0 on B30429, PORV RC-455C failed to meet required cycle time & failed to open fully on subsequent attempt Caused by galling of valve plug to cage due to rubbing of stainless steel in dry condition W/B30527 ltr COX, H T, STARKEY, R B Carolina Power & Light Co 83/05/27
O'REILLY, J P Region 2, Office of Director App 18736 321 24X
Fiche 50-261, 83/05/27, B306070182

B306200002 LER 83-008/03L-0 on B30506, safety injection accumulator level transmitters found out of calibr Caused by instrument drift Transmitters recalibr & replacement mod developed W/B30606 ltr COX, H T, STARKEY, R B Carolina Power & Light Co 83/06/06
O'REILLY, J P Region 2, Office of Director App 18904 022 24X
Fiche 50-261, 83/06/06, B306200002

B306200188 LER 83-009/03L-0 on B30507, w/unit shut down for steam generator insp outage, flow transmitter FT-495, loop C steam flow found out of calibr Caused by instrument drift Transmitter recalibr & returned to svc W/B30607 ltr COX, H T, STARKEY, R B Carolina Power & Light Co 83/06/07
O'REILLY, J P Region 2, Office of Director App 18903 180 24X
Fiche 50-261, 83/06/07, B306200188

B306200109 LER 83-010/01T-0 on B30525, review of eddy current data revealed 137 & 206 defective tubes identified in steam generators B & C, respectively All defective tubes taken out of svc W/B30608 ltr COX, H T, STARKEY, R B Carolina Power & Light Co 83/06/08
O'REILLY, J P Region 2, Office of Director App 18903 255 24X
Fiche 50-261, 83/06/08, B306200109

DOCKET 50-263 MONTICELLO NUCLEAR GENERATING PLANT

F Security, medical, emergency & fire protection plans

B306060247 Forwards IE Insp Rept 50-263/83-07 on B30402-0501 No noncompliance noted
SHAFFER, W D Region 3, Office of Director 83/05/19 LARSON, C E
Northern States Power Co 2pp 18727 235 24X
Fiche 50-263, 83/05/19, B306060247

--B306060251 IE Insp Rept 50-263/83-07 on B30402-0501, No noncompliance noted Major areas inspected operational safety verification, including physical security plan implementation, onsite review committee & personnel changes
BROWN, C H, WALKER, R D Region 3, Office of Director 83/05/19
3pp 18727 237 24X Fiche 50-263, 83/05/19, B306060247

B306100095 Forwards finalized rept re emergency preparedness insp followup on B30516-20 Procedures for containment air sampling completed & implemented
MARTIN, J B THOMAS, W V Battelle Memorial Institute, Pacific Northwest Laboratory 83/05/25 PATTERSON, J Region 3, Office of Director 17pp 18802 245 24X Fiche 50-263, 83/05/25, B306100095

B306160430 Submits addl info to close out open items identified in B10212 Fire protection BER per App R, Section III, Q 2 requirements Cable tray penetrations & supply ducting verified for 3 h resistance
MUSOLF, D Northern States Power Co 83/06/07 Office of Nuclear
Reactor Regulation, Director App 18860 226 24X
Fiche 50-263, 83/06/07, B306160430

B306200108 Informs of change in design of control room ventilation sys smoke detection & isolation sys to upgrade control room ventilation sys to satisfy NUREG-0737, Item III D 3.4 requirements
MUSOLF, D Northern States Power Co 83/06/13 Office of Nuclear
Reactor Regulation, Director App 18903 258 24X
Fiche 50-263, 83/06/13, B306200108

B306210094 Forwards Rev 13 pages to security plan Pages withheld (ref 10CFR73 21).
MUSOLF, D Northern States Power Co 83/06/14 Office of Nuclear
Reactor Regulation, Director App 18914 150 24X
Fiche 50-263, 83/06/14, B306210094

B306210072 Forwards IE Safeguards Insp Rept 50-263/83-08 on B30510-13 & notice of violation Notice of violation withheld (ref 10CFR73 21)
MILLER, J R Region 3, Office of Director 83/06/15 LARSON, C E
Northern States Power Co 2pp 18914 220 24X
Fiche 50-263, 83/06/15, B306210072

--B306210075 IE Safeguards Insp Rept 50-263/83-08 on B30510-13, Noncompliance noted portions of protected area intrusion alarm sys failed to function as described, Details withheld (ref 10CFR73 21)
MCINCELEY, J R, STARLEYTON, B W, CREED, J R Region 3, Office of Director 83/06/14 App 18914 222 24X Fiche 50-263, 83/06/15, B306210072

B306280459 Informs that operational data for completion of HEPA filtration sys extended to B31001 due to difficulty in adopting ventilation sys to accommodate demands of HEPA filtration per Suppl 1 to NUREG-0737
MUSOLF, D Northern States Power Co 83/06/20 Office of Nuclear
Reactor Regulation, Director App 19018 328 24X
Fiche 50-000, 83/06/20, B306280459

P Operating license stage documents & correspondence

B306010441 Submits response to 10CFR50 49, "Environmental Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants" Master list of safety-related electrical equipment and
MUSOLF, D Northern States Power Co 83/05/19 Office of Nuclear
Reactor Regulation, Director App 18674 272 24X
Fiche 50-263, 83/05/19, B306010441

B306150576 Forwards safety evaluation of util submittals re NUREG-0737, Item II B 2 on plant shielding mode Item resolved.
VASSALLO, D B Operating Reactors Branch 2, 83/05/23 MUSOLF, D M
Northern States Power Co App 18867 034 24X
Fiche 50-263, 83/05/23, B306150576

B306020523 Notification of B30616 meeting w/util, Bechtel & OE in Bethesda, MD to discuss pipe cracks in recirculation sys piping
NICOLARAS, H Operating Reactors Branch 2, 83/05/25 VASSALLO, D B
Operating Reactors Branch 2 App 18715 143 24X
Fiche 50-263, 83/05/25, B306020523

B306230034 Notification of B30616 meeting w/util, OE & Bechtel in Bethesda, MD to discuss preliminary plans for modifying recirculation sys piping
NICOLARAS, H Operating Reactors Branch 2, 83/05/25 VASSALLO, D B
Operating Reactors Branch 2 App 18754 342 24X
Fiche 50-263, 83/05/25, B306230034

B306130466 Forwards safety evaluation of util submittals on NUREG-0737 Items 1 A, 2 1.4, "Upgrading Reactor Operator & Senior Reactor Operator Training" & 11. B 4, "Training for Mitigating Core Damage" Items resolved
VASSALLO, D B Operating Reactors Branch 2 83/06/03 MUSOLF, D M
Northern States Power Co App 18867 214 24X
Fiche 50-263, 83/06/03, B306130466

B306170353 Forwards Rev 1 to "Sys Description Safety Relief Valve Blowdown Control Sys for Monticello Nuclear Generating Plant" Rept describes control sys mods to be implemented during 1984 refueling outage
MUSOLF, D Northern States Power Co 83/06/13 Office of Nuclear
Reactor Regulation, Director App 18880 163 24X
Fiche 50-263, 83/06/13, B306170353

--B306170354 Rev 1 to "Sys Description Safety Relief Valve Blowdown Control Sys for Monticello Nuclear Generating Plant."
REIMERB, O A BETKA, O E, NAF, D E NUTECH Engineers, Inc.
NSP-4B-1103 R01, 83/05/18 14pp 18880 164 24X
Fiche 50-263, 83/06/13, B306170353

Q Inspection reports, IE Bulletins & correspondence

B305060453 Informs that revised process as stated in response to violation noted in IE Insp Rept 50-263/82-11 will not be in full effect until B30601, Rev involved substantial changes in areas not originally anticipated
LARSON, C E Northern States Power Co 83/04/26 NORELIUS, C E
Division of Engineering App 18343 144 24X Fiche 50-263, 83/04/26, B305060453

B306060247 Forwards IE Insp Rept 50-263/83-07 on B30402-0501, No noncompliance noted.
SHAFFER, W D Region 3, Office of Director 83/05/19 LARSON, C E
Northern States Power Co 2pp 18727 235 24X
Fiche 50-263, 83/05/19, B306060247

--B306060251 IE Insp Rept 50-263/83-07 on B30402-0501, No noncompliance noted Major areas inspected operational safety verification, including physical security plan implementation, onsite review committee & personnel changes
BROWN, C H, WALKER, R D Region 3, Office of Director 83/05/19
3pp 18727 237 24X Fiche 50-263, 83/05/19, B306060247

B306100095 Forwards finalized rept re emergency preparedness insp followup on B30516-20, Procedures for containment air sampling completed & implemented
MARTIN, J B THOMAS, W V Battelle Memorial Institute, Pacific Northwest Laboratory 83/05/25 PATTERSON, J Region 3, Office of Director 17pp 18802 245 24X Fiche 50-263, 83/05/25, B306100095

DOCKETED ITEMS

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device." Svc list encl.
TAYLOR, J.M. Division of Safeguards & Inspection Programs (Post 830103). 83/05/26 Consolidated Edison Co. of New York, Inc. 125pp. 18831.043 24X Fiche: 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/26 Consolidated Edison Co. of New York, Inc. 115pp. 18732.085. 24X Fiche: 50-000, 83/05/26, 8305110460

8306060084 Comments NRC re results of piping insp at BWRs. Leak-before-break concept continues to sustain validity of technical bases. Utils giving consideration to more permanent measures.
NEILB, G.H. Northern States Power Co. 83/05/26 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp. 18719.335. 24X Fiche 50-000, 83/05/26, 8306060084

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/31. Consolidated Edison Co. of New York, Inc. 116pp. 18732.208 24X Fiche 50-000, 83/05/31, 8305110461

8306170134 Responds to IE Bulletin 83-03. All applicable check valves will be tested in accordance w/bulletin following revs to surveillance test procedures & installation of described rods during 1984 refueling outage.
LARBON, C.E. Northern States Power Co. 83/06/08. KEPPLER, J.O. Region 3, Office of Director. 2pp. 18078.347 24X Fiche: 50-263, 83/06/08, 8306170134

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/09 Consolidated Edison Co. of New York, Inc. 119pp. 18830.280 24X Fiche: 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/13 Consolidated Edison Co. of New York, Inc. 118pp. 18920.225 24X Fiche: 50-000, 83/06/13, 8305110470.

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/13 Consolidated Edison Co. of New York, Inc. 243pp. 18921.001. 24X Fiche: 50-000, 83/06/13, 8306090010

8306210072 Forwards IE Safeguards Insp Rept 50-263/83-08 on 830510-13 & notice of violation. Notice of violation withheld (ref 10CFR73.21).
MILLER, J.R. Region 3, Office of Director. 83/06/15 LARBON, C.E. Northern States Power Co. 2pp. 18914.220 24X Fiche: 50-263, 83/06/15, 8306210072.

--8306210075 IE Safeguards Insp Rept 50-263/83-08 on 830510-13. Noncompliance noted, portions of protected area intrusion alarm sys failed to function as described Details withheld (ref 10CFR73.21).
KNICELEY, J.R., STAPLETON, B.W., CREED, J.R. Region 3, Office of Director. 83/06/14 2pp. 18914.222 24X Fiche: 50-263, 83/06/15, 8306210072.

8306210177 Ack receipt of 830511 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-263/83-01.
KEPPLER, J.O. Region 3, Office of Director. 83/06/15 LARBON, C.E. Northern States Power Co. 1p. 18915.168 24X Fiche: 50-263, 83/06/15, 8306210177.

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/22 Consolidated Edison Co. of New York, Inc. 115pp. 19021.179. 24X Fiche: 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp. 18997.007. 24X Fiche: 50-000, 83/06/22, 8305110477.

Notice 83-42, "Reactor Mode Switch Malfunctions."

Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/23 Consolidated Edison Co. of New York, Inc. 18996.242. 24X Fiche: 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Bettings of Intermediate Range (IR) High Flux Trip Setpoints." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/24 Consolidated Edison Co. of New York, Inc. 116pp. 19046.297 24X Fiche 50-000, 83/06/24, 8305110483

R Periodic operating reports & related correspondence

8306020088 Monthly operating rept for Mar 1983 W/830412 ltr.
MYRABD, A.L., MUBOLF, D. Northern States Power Co. 83/04/05 Office of Resource Management, Director 5pp. 18691.198 24X Fiche 50-263, 83/04/05, 8306020088

8306200105 Monthly operating rept for May 1983 W/830610 ltr.
MYRABD, A.L., MUBOLF, D. Northern States Power Co. 83/06/02 Office of Resource Management, Director 5pp. 18903.269 24X Fiche 50-263, 83/06/02, 8306200105.

B. Reportable occurrences, LERs & related correspondence

8306130438 LER 83-010/03L-0 on 830226, during surveillance testing, outboard MSIV AD-2-B6B closed faster than value stated in Tech Spec Table 3.7.1 Caused by oil leak from needle valve assembly on bottom dashpot cylinder head W/830601 ltr.
RUBBY, G.T., MUBOLF, D. Northern States Power Co. 83/06/01 Region 3, Office of Director 2pp. 18821.190 24X Fiche 50-263, 83/06/01, 8306130438

DOCKET 50-265 QUAD-CITIES STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8306130405 Forwards IE Insp Repts 50-254/83-15 & 50-265/83-13 on 830510-13 No noncompliance noted.
PAPERIELLO, C.J. Region 3, Office of Director. 83/05/27 REED, C. Commonwealth Edison Co. 2pp. 18823.064 24X Fiche: 50-254, 83/05/27, 8306130405

--8306130412 IE Insp Repts 50-254/83-15 & 50-265/83-13 on 830510-13 No noncompliance noted. Major areas inspected: emergency preparedness exercise.
PHILLIPS, H., SMITH, M., AXELSON, W.L. Region 3, Office of Director. 83/05/27 26pp. 18823.066. 24X Fiche: 50-254, 83/05/27, 8306130405.

8306160071 Releases public version of revised emergency plan implementing procedures.
FELTON, J.M. Division of Rules and Records. 83/06/07 Document Management Branch 1p. 18872.349. 24X Fiche: 50-254, 83/06/07, 8306160071.

--8306160077 Public version of Rev 11 to Emergency Plan Implementing Procedure GEP 550-0, "Emergency Equipment & Supplies" & Rev 5 to GEP 550-11, "Environ Sampling Supplies." Receipt form encl.
* Commonwealth Edison Co. 83/05/04 Office of Nuclear Reactor Regulation, Director. 5pp. 18872.350. 24X Fiche: 50-254, 83/06/07, 8306160071

P Operating license stage documents & correspondence

8306090194 Discusses util interpretation of 10CFR50.49, "Environ Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants." Intent of rulemaking is to require upgrade program for replacement equipment not parts.
FARRAR, D.L. Commonwealth Edison Co. 83/06/03 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 3pp. 18796.090 24X Fiche: 50-000, 83/06/03, 8306090194

8306090227 Informs that response to Generic Ltr 83-08 will be submitted by 830713 Info will include stress tests to determine mod to vacuum breakers on Mark I containments.
RYBAK, B. Commonwealth Edison Co. 83/06/06 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 1p. 18796.234 24X Fiche: 50-000, 83/06/06, 8306090227

8306160233 Advises that manufacturers whose repts were used in technical evaluation re environ qualification of electrical equipment have been contacted List of proprietary pages detailed in util 830513 ltr W/830601 affidavit.
RYBAK, B. Commonwealth Edison Co. 83/06/06 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 5pp. 18861.304. 24X Fiche: 50-000, 83/06/06, 8306160233

8306270324 Advises that beta spectra measurements will be conducted at facilities on 830628-29 for NRC project, "Beta Particle Measurement & Dosimetry Requirements at NRC-Licensed Facilities."
RATHBUN, L.A. Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2448 83/06/17 KEPPLER, J.O. Region 3, Office of Director 1p. 18994.074. 24X Fiche: 50-254, 83/06/17, 8306270324.

DOCKETED ITEMS

65

G Inspection reports, IE Bulletins & correspondence

8306220218 Ack receipt of 830414 payment of proposed civil penalties
Response to notice of violation & proposed imposition of
civil penalties will be evaluated & corrective actions
examined during future insps
AXELRAD, J A Enforcement Staff 83/04/21 REED, C Commonwealth
Edison Co 2pp 18750 357 24X Fiche 50-000, 83/04/21, 8306220218

8306030139 Forwards IE Insp Repts 50-254/82-14 & 50-265/82-12 on
830419-20 No noncompliance noted
LITTLE, W S Region 3, Office of Director 83/05/17 REED, C
Commonwealth Edison Co 2pp 18704 291 24X Fiche 50-254, 83/05/17,
8306030139

--8306030149 IE Insp Repts 50-254/82-14 & 50-265/83-12 on 830419-20 No
noncompliance noted Major areas inspected action re IE
Bulletin 80-11, "Hassonry Wall Design"
NORTON, J F, WILLIAMS, C C Region 3, Office of Director
83/05/16 4pp 18704 293 24X Fiche 50-254, 83/05/17, 8306030139

8306010179 Informs of results of NRC review of relief requests from
inservice insp requirements Relief granted in part, per encl
safety evaluation
VASSALLO, D B Operating Reactors Branch 2 83/05/19 FARRAR, D L
Commonwealth Edison Co 3pp 18696 010 24X Fiche 50-254, 83/05/19,
8306010179

--8306010182 Safety evaluation supporting, in part & denying in part,
requests for relief from inservice insp requirements
* Office of Nuclear Reactor Regulation, Director 83/05/19 7pp
18696 013 24X Fiche 50-254, 83/05/19, 8306010179

--8309200365 "Quad Cities Nuclear Power Station Units 1 & 2 Inservice
Insp Program," technical evaluation rept
* Science Applications, Inc NRC-03-82-096 SAI-186-028-30
82/09/17 NRC - No Detailed Affiliation Given 43pp
18696 023 24X Fiche 50-254, 83/05/19, 8306010179

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in
Well Logging Device" Svc list encl
TAYLOR, J H Division of Safeguards & Inspection Programs (Post
830103) 83/05/26 Consolidated Edison Co of New York, Inc.
123pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Lvent Notification Info Worksheet,"
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New
York, Inc 118pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460.

8306130405 Forwards IE Insp Repts 50-254/83-15 & 50-265/83-13 on
830510-13 No noncompliance noted
PAPERIELLO, C J Region 3, Office of Director 83/05/27 REED, C
Commonwealth Edison Co 2pp 18823 064 24X Fiche 50-254, 83/05/27,
8306130405

--8306130412 IE Insp Repts 50-254/83-15 & 50-265/83-13 on 830510-13 No
noncompliance noted Major areas inspected emergency
preparedness exercise
PHILLIPS, M, PLOSKI, T, GLDERSEN, N W Region 3, Office of
Director 83/05/27 26pp 18823 066 24X Fiche 50-254, 83/05/27,
8306130405

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods
Withdrawn at BWRs" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/31 Consolidated Edison Co of New
York, Inc. 116pp 18732 208, 24X Fiche 50-000, 83/05/31, 8305110461

8306060208 Ack receipt of 830405 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-254/82-24 &
50-265/82-28
SPESSARD, R L Division of Engineering 83/05/31 REED, C
Commonwealth Edison Co 1p 18727 351 24X Fiche 50-254, 83/05/31,
8306060208.

--8306060212 Response to NRC 830309 ltr re violations noted in IE Insp
Repts 50-254/82-24 & 50-265/82-28. Corrective actions onsite
review conducted on 830228 documenting computer program used
for integrated leak rate test.
RYBAK, B Commonwealth Edison Co 83/04/05 KEPLER, J O Region 3,
Office of Director 6pp. 18727 352 24X Fiche 50-254,
83/05/31, 8306060208

8306070175 Forwards corrected Page 1 to IE Insp Repts 50-254/83-14 &
50-265/83-12 on 830419-20 No noncompliance noted
LITTLE, W S Region 3, Office of Director 83/06/03 REED, C
Commonwealth Edison Co 1p 18736 331 24X Fiche 50-254, 83/06/03,
8306070175

--8306070190 Corrected Page 1 to IE Insp Repts 50-254/83-14 &
50-265/83-12 on 830419-20 No noncompliance noted Major
areas inspected licensee action re IE Bulletin 80-11,
"Hassonry Wall Design"
NORTON, J F, WILLIAMS, C C Region 3, Office of Director
83/06/02 1p 18736 332 24X Fiche 50-254, 83/06/03, 8306070175.

8306100149 Forwards Rev 3 to "180-Day Rept in Response to IE Bulletin
80-11 for Dresden 2 & 3 & Quad Cities 1 & 2"
RYBAK, B Commonwealth Edison Co 83/06/06, KEPLER, J O Region 3,
Office of Director 2pp 18804 161 24X Fiche 50-000, 83/06/06,
8306100149

--8306100156 Rev 3 to "180-Day Rept in Response to IE Bulletin 80-11 for
Dresden 2 & 3 & Quad Cities 1 & 2"
* Commonwealth Edison Co 83/05/09. 127pp 18804 163, 24X
Fiche 50-000, 83/06/06, 8306100149

8306100094 Forwards response to IE Bulletin 83-03 re diesel generator
cooling water check valves Plants utilize Mission Duo-Check
valves employing hinge-to-pin design for protection against
vibration-induced failure
BARNES, P L Commonwealth Edison Co 83/06/07, KEPLER, J O Region 3,
Office of Director 7pp 18802 238 24X Fiche 50-000, 83/06/07,
8306100094

8306170380 Forwards response to IE Bulletin 83-03 re diesel generator
cooling water check valves Valves at Dresden & LaBelle
acceptable w/o further insp Rept on valve failures at Quad
Cities will be submitted within 90 days of insp completion.
BARNES, P L Commonwealth Edison Co 83/06/07, KEPLER, J O Region 3,
Office of Director 7pp 18802 211 24X Fiche 50-000, 83/06/07,
8306170380

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe
Operations" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/09 Consolidated Edison Co of New
York, Inc 119pp, 18830 280 24X Fiche 50-000, 83/06/09, 8305110464.

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive &
Seismically Induced Chatter in Relays Within Printed
Circuit Cards" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New
York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470.

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From
Degraded Internal Connection Cables" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New
York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8306220067 Summarizes revised schedule for util review of automated
analytical instrumentation sys multiplst analysis
capability per IE Insp Repts 50-254/82-13 & 50-265/82-15
RYBAK, B Commonwealth Edison Co 83/06/13, PAPERIELLO, C J, Region 3,
Office of Director, 2pp. 18928 180, 24X Fiche 50-254, 83/06/13,
8306220067

8306300235 Forwards IE Insp Repts 50-237/83-12, 50-249/83-10,
50-254/83-13 & 50-265/83-11 on 820412-14 & 0506 & 16 &
notice of violation
LITTLE, W S Region 3, Office of Director 83/06/16 REED, C,
Commonwealth Edison Co 2pp 19122 279 24X Fiche 50-000, 83/06/16,
8306300235

--8306300238 Notice of violation from insp on 830412-14 & 0506 & 16,
LITTLE, W S Region 3, Office of Director. 83/06/16, 2pp.
19122 281, 24X Fiche 50-000, 83/06/16, 8306300235.

--8306300246 IE Insp Repts 50-237/83-12, 50-249/83-10, 50-254/83-13 &
50-265/83-11 on 830412-14 & 0506 & 16 Noncompliance noted
as-built configuration (for pipe anchor R133 in pressure
suppression sys) differed from original design.
VINI, T, Region 3, Office of Director. 83/06/16, 9pp.
19122 283, 24X Fiche 50-000, 83/06/16, 8306300235.

8306220028 Ack receipt of 830509 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-234/82-26 &
50-265/82-26
KEPLER, J O Region 3, Office of Director 83/06/17, REED, C,
Commonwealth Edison Co 1p 18930 036, 24X Fiche 50-254, 83/06/17,
8306220028.

--8306220034 Response to NRC 830411 ltr re violations noted in IE Insp
Repts 50-254/82-26 & 50-265/82-26 Corrective actions, startup
procedure revised to include sign-off space verifying alarm
has cleared
REED, C Commonwealth Edison Co 83/05/09, Director's Office,
Office of Inspection and Enforcement. 7pp. 18930:037, 24X
Fiche 50-254, 83/06/17, 8306220028.

DOCKETED ITEMS

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 115pp, 19021:179 24X Fiche: 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Byx Causing Inoperability of Safety-Related Equipment." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co. of New York, Inc. 116pp 18996:242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc 116pp, 19046:297, 24X Fiche: 50-000, 83/06/24, 8305110483.

R. Periodic operating reports & related correspondence

8306170314 Monthly operating repts for May 1983. W/830606 ltr
HEINFURTER, E., MISAK, A., KALIVIANAKIS, N. Commonwealth Edison Co.
83/06/06, Director's Office, Office of Inspection and Enforcement
22pp, 18977:042, 24X Fiche 50-254, 83/06/06, 8306170314.

S. Reportable occurrences, LERs & related correspondence

8306170344 LER 83-008/03L-0 on 830520, RHR pump 28 room watertight door could not be shut tightly. Caused by bent pivot arm. Arm repaired & RHR B loop declared operable. W/830607 ltr.
EAGLE, J., KALIVIANAKIS, N. Commonwealth Edison Co. 83/06/07
KEPPLER, J. Region 3, Office of Director 2pp, 18880:291, 24X Fiche: 50-265, 83/06/07, 8306170344.

8306270282 Potential Part 21 rept re discrepancy in welding of turnbuckle assembly, turnbuckle-bolt interface & on top plate assembly variable springs. 8A307 Grade B bolts not ASME Section IX matl. Investigation underway
KARAGIANIS, J. A., Elcon Metal Products Co 83/06/17 KEPPLER, J. O
Region 3, Office of Director 2pp, 18996:207, 24X Fiche: 50-000, 83/06/17, 8306270282.

DOCKET 50-266 POINT BEACH NUCLEAR PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

8306020199 Requests route approval for irradiated fuel shipments from GE Morris facility at Morris, IL to reactor site in Two Rivers, WI. Safeguards info withheld (ref 10CFR73.21).
DANESE, F. L. Nuclear Assurance Corp 83/05/10 HILLMAN, C. Division of Safeguards 3pp 18701:064 24X Fiche: 50-266, 83/05/10, 8306020199.

8306060156 Provides update to 830428 ltr re mods proposed to support App R exemption requests, based on 830523 insp of Unit 2 A05 & A06 switchgear cabinets.
FAY, C. W. Wisconsin Electric Power Co. 83/05/31, DENTON, H. R
Office of Nuclear Reactor Regulation, Director, CLARK, R. A
Operating Reactors Branch 3 2pp, 18728 103, 24X Fiche: 50-266, 83/05/31, 8306060156.

8306140218 Responds to 830510 request for approval for shipment of spent reactor fuel from Morris, IL to facility. Route approved per 10CFR73.37. Sanitized data re arrangements & approved route encl.
SHERR, T. B. Material Transfer Safeguards Licensing Branch, 83/06/02.
DANESE, F. L. Nuclear Assurance Corp. 7pp, 18844:315, 24X Fiche: 50-266, 83/06/02, 8306140218.

8306090177 Ack receipt of 830408 & 0523 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-266/83-01 & 50-301/83-01.
PAPERIELLO, C. J. Region 3, Office of Director, 83/06/06
BURSTEIN, S. Wisconsin Electric Power Co. 1p, 18796:081, 24X Fiche: 50-266, 83/06/06, 8306090177.

--8306090185 Responds to NRC 830308 ltr re violations noted in IE Insp Repts 50-266/83-01 & 50-301/83-01 Notice of violation inappropriately based on implementation of listed items. Fifteen-minute notifications inconsistent w/minor events
FAY, C. W. Wisconsin Electric Power Co. 83/04/08, KEPPLER, J. O
Region 3, Office of Director, 3pp 18796:082, 24X Fiche: 50-266, 83/06/06, 8306090177.

8306130447 Notifies that LABL vital area analysis program personnel will reanalyze original sites visited during early stages of program. Revisit necessary to gather addl info due to major mods & redirection by NRC
HIND, J. A. Division of Radiological & Materials Safety Programs
83/06/08 BURSTEIN, S. Wisconsin Electric Power Co 2pp 18821 209 24X Fiche 50-266, 83/06/08, 8306130447

8306130431 Forwards SER re compliance w/NUREG-0737, Item III A 1 2, "Min Staffing Levels for Emergency Situations." Provisions for onshift staffing & augmentation acceptable
HIND, J. A. Division of Radiological & Materials Safety Programs
83/06/10, BURSTEIN, S. Wisconsin Electric Power Co 8pp 18821 215 24X Fiche 50-266, 83/06/10, 8306130431

8306210100 Responds to 830603 ltr advising of status of util request to locate emergency operations facility at corporate headquarters in Milwaukee, WI. New communication apparatus & revised procedures enhance emergency capabilities
FAY, C. W. Wisconsin Electric Power Co 83/06/16 DEYOUNG, R. C
Director's Office, Office of Inspection and Enforcement 2pp 18914 138 24X Fiche 50-266, 83/06/16, 8306210100

8306230356 Ack receipt of NRC 830603 ltr re status of util request to locate emergency operations facility (EOF) at corporate headquarters in Milwaukee, WI. Past communication difficulties unrelated to divided EOF concept
FAY, C. W. Wisconsin Electric Power Co 83/06/16 DEYOUNG, R. C
Director's Office, Office of Inspection and Enforcement 2pp 18943 317 24X Fiche 50-266, 83/06/16, 8306230356

Q. Adjudicatory correspondence

8306090298 Order extending time until 830708 for Commission to act to review ALAB-719
CHILK, S. J. Office of the Secretary of the Commission, 83/06/07
Commissioners 1p, 18795 237 24X Fiche: 50-266, 83/06/07, 8306090298

J Insurance & indemnity information

8306070404 Forwards Endorsement 71 to NELIA Policy NF-178 & Endorsement 58 to MAELU Policy MF-53
DUNDAS, W. J. Wisconsin Electric Power Co 83/05/18 Antitrust & Economic Analysis Branch (Utility Finance), 3pp 18741 352, 24X Fiche 50-266, 83/05/18, 8306070404

P Operating license stage documents & correspondence

8306010428 Advises of failure to complete installation & place in operation portions of radioactive monitoring equipment for compliance w/NUREG-0737, Item II.F 1 i, "Noble Gas Monitoring." Completion expected by 830630
FAY, C. W. Wisconsin Electric Power Co. 83/05/25 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director, CLARK, R. A
Operating Reactors Branch 3 3pp 18679 321 24X Fiche 50-266, 83/05/25, 8306010428.

8306100018 Requests route approval for irradiated fuel shipments from West Valley, NY to Two Rivers, WI.
DANESE, F. L. Nuclear Assurance Corp 83/05/26 HILLMAN, C. Division of Safeguards 3pp 18815, 306 24X Fiche: 50-266, 83/05/26, 8306100018

8306070086 Provides results of chlorine, boron & pH analyses performed for chemical test matrix, per NUREG-0737, Item II B 3, Criterion 10, to demonstrate analytical capabilities in presence of interfering ion concentrations
FAY, C. W. Wisconsin Electric Power Co 83/06/03 DENTON, H. R
Office of Nuclear Reactor Regulation, Director 2pp 18737 350 24X Fiche: 50-266, 83/06/03, 8306070086

8306200267 Forwards latest rev of FSAR Section 1 B, describing QA program, per 10CFR50.54(a)(2). Changes do not reduce QA program commitments previously accepted by NRC. Substantive changes summarized.
FAY, C. W. Wisconsin Electric Power Co 83/06/10, KEPPLER, J. O
Region 3, Office of Director, 36pp 18901, 063 24X Fiche 50-266, 83/06/10, 8306200267

8306200260 Informs of further delay in implementing post-THI-related issues due to delay in shipment of auxiliary safety instrumentation panels from vendor, in response to 830314 order
FAY, C. W. Wisconsin Electric Power Co 83/06/16 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director CLARK, R. A
Operating Reactors Branch 3 4pp 18901 173 24X Fiche: 50-266, 83/06/16, 8306200260.

DOCKETED ITEMS

67

8306210091 Requests mod to WPDES Permit W1-0000957-2, removing pH limitations on sewage treatment plant & retention pond effluents Mod will allow operation of plant & pond w/reduced additions of dissolved solids to environ
LINGLE, J W Wisconsin Electric Power Co 83/06/16 Wisconsin, State of 3pp 18914 088 24X Fiche 50-266, 83/06/16, 8306210091

8306270275 Requests mod to WPDES Permit W1-0000957-2 to remove pH limitations on sewage treatment plant & retention pond effluents Removal of limits will allow operation w/reduced additions of dissolved solids to environ
LINGLE, J W Wisconsin Electric Power Co 83/06/16 Wisconsin, State of 2pp 18996 170 24X Fiche 50-266, 83/06/16, 8306270275

8306280443 Proposes hardware mod to ensure automatic initiation of auxiliary feedwater flow to affected operating unit w/o operator action Mod only affects motor driven auxiliary feedwater pumps & motor-operated isolation valves
FAY, C W Wisconsin Electric Power Co 83/06/20 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 3pp 19019 174 24X Fiche 50-266, 83/06/20, 8306280443

8306290146 Informs that util response to NUREQ-0737, Items II F 1 4, II F 1 5 & II F 1 6 acceptable re installation of containment pressure, water level & hydrogen monitoring sys.
SER encl
CLARK, R A Operating Reactors Branch 3 83/06/21 FAY, C W Wisconsin Electric Power Co 8pp 19046 258 24X Fiche 50-266, 83/06/21, 8306290146

8306280397 Requests extension of deadline for certain environ qualification items, listed in SER in Categories II A & II C, until 3 months after meeting held to resolve deficiencies
BURSTEIN, B Wisconsin Electric Power Co 83/06/22 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 2pp 19001 359 24X Fiche 50-266, 83/06/22, 8306280397

G Inspection reports, IE Bulletins & correspondence

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26, Consolidated Edison Co of New York, Inc. 12pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 11pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 11pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306070324 Confirms 830616 meeting w/util at Region III sfc to discuss BALP interested parties should submit advance notification by 830613
NORELIUS, C E Division of Project & Resident Programs 83/06/01 BURSTEIN, B Wisconsin Electric Power Co 1p 10746 080 24X Fiche 50-266, 83/06/01, 8306070324

8306090177 Ack receipt of 830408 & 0523 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-266/83-01 & 50-301/83-01
PAPERIELLO, C J Region 3, Office of Director, 83/06/06 BURSTEIN, B Wisconsin Electric Power Co 1p, 18796 081 24X Fiche 50-266, 83/06/06, 8306090177

--8306090185 Responds to NRC 830308 ltr re violations noted in IE Insp Repts 50-266/83-01 & 50-301/83-01, Notice of violation inappropriately based on implementation of listed items Fifteen-minute notifications inconsistent w/minor events.
FAY, C W Wisconsin Electric Power Co 83/06/08 KEPLER, J O Region 3, Office of Director 3pp, 18796 082, 24X Fiche 50-266, 83/06/08, 8306090177

8306130146 Advises that no check valves installed in flow path of cooling water for diesel generators, in response to IE Bulletin 83-03 re check valve failures in raw water cooling sys of diesel generators
BURSTEIN, B Wisconsin Electric Power Co, 83/06/06, KEPLER, J O Region 3, Office of Director, 1p 18824:277 24X Fiche 50-266, 83/06/06, 8306130146

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 11pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8306230274 Forwards IE Insp Repts 50-266/83-10 & 50-301/83-10 on 830523-26 No noncompliance noted
STREETER, J F Region 3, Office of Director 83/06/10 BURSTEIN, B Wisconsin Electric Power Co 2pp 18945 129 24X Fiche 50-266, 83/06/10, 8306230274

--8306230279 IE Insp Repts 50-266/83-10 & 50-301/83-10 on 830523-26 No noncompliance noted Major areas inspected nonlicensed personnel training & licensed personnel requalification programs
HASBE, R A, HAWKINS, F C Region 3, Office of Director 83/06/10, 4pp 18945 131 24X Fiche 50-266, 83/06/10, 8306230274

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 11pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 24pp 18921 001, 24X Fiche 50-000, 83/06/13, 8306090010

8306230260 Ack receipt of 830525 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-266/83-04 & 50-301/83-04
NORELIUS, C E Division of Project & Resident Programs, 83/06/20, BURSTEIN, B Wisconsin Electric Power Co 1p 18945:072 24X Fiche 50-266, 83/06/20, 8306230260

--8306230261 Responds to NRC 830425 ltr re violations noted in IE Insp Repts 50-266/83-04 & 50-301/83-04, Corrective actions: Procedure HF 2 4 re containment entry check-in/check-out sys deleted on 830520
FAY, C W Wisconsin Electric Power Co 83/05/25 KEPLER, J O Region 3, Office of Director 2pp 18945:073, 24X Fiche 50-266, 83/06/20, 8306230260

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 11pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007, 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 11pp, 18996, 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Bettings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24, Consolidated Edison Co of New York, Inc 11pp 19046:297 24X Fiche 50-000, 83/06/24, 8305110483

R. Periodic operating reports & related correspondence

8306200137 Monthly operating repts for May 1983 W/830613 ltr.
FAY, C W Wisconsin Electric Power Co 83/06/06 7pp, 18901:046, 24X Fiche 50-266, 83/06/06, 8306200137

S Reportable occurrences, LERs & related correspondence

8305020208 Forwards LER 83-003/01T-0.
BURSTEIN, B Wisconsin Electric Power Co, 83/04/19 KEPLER, J O Region 3, Office of Director 1p 18277, 271, 24X Fiche 50-266, 83/04/19, 8305020208

DOCKETED ITEMS

--8305020231 LER 83-003/OIT-0 on 830406, critical control power failure alarm received. Caused by breakers accidentally opened by contractor personnel setting up to pull wires for control board mode breakers closed.
FAV, C. W. Wisconsin Electric Power Co. 83/04/19 Region 3,
Office of Director. 2pp 18277 272 24X Fiche 50-267, 83/04/19,
8305020208

8306060078 NPDES noncompliance on 830525, daily max pH effluent limit exceeded. Util commenced investigation of incident. Ltr to be sent to Dept of Natural Resources outlining results & corrective action.
FAV, C. W. Wisconsin Electric Power Co. 83/05/27 Wisconsin, State
of 1p 18723 022 24X Fiche 50-266, 83/05/27, 8306060078

8306300058 NPDES noncompliance notification on 830525, pH of retention pond discharge exceeded limits. Caused by leaks in retaining board used to siphon sludge from pond to discharge. Leaks repaired on 830526.
FAV, C. W. Wisconsin Electric Power Co. 83/06/23 Wisconsin, State
of 1p 19120 237 24X Fiche 50-266, 83/06/23, 8306300058

DOCKET 50-267 FORT ST. VRAIN NUCLEAR GENERATING STATION

F Security, medical, emergency & fire protection plans

8306300104 Forwards exclusion area boundary, emergency planning zone survey team inventory, listed in Health Physics Procedure HPP-37 & Surveillance Procedure SR-HE-3-BA, in response to NRC 821102 ltr & IE Insp Rept 50-267/82-14.
LEE, O. R. Public Service Co. of Colorado 82/11/17, MADSEN, O. L.,
Region 4, Office of Director. 4pp 19048:222 24X
Fiche 50-267, 82/11/17, 8306300104.

--8306300107 Rev 15 to Health Physics Procedure HPP-37, "Radiological Emergency Respiratory Protection Inventory List."
* Public Service Co. of Colorado 82/10/01 14pp. 19048, 226
24X Fiche 50-267, 82/11/17, 8306300104

--8306300111 Rev 1 to Surveillance Procedure SR-HE-3-BA, "Radiation Protection Dept - On/Offsite Emergency Monitoring Exercise."
* Public Service Co. of Colorado 82/09/30 7pp 19048, 240.
24X Fiche 50-267, 82/11/17, 8306300104

8306010293 Extends invitation to attend 830617 meeting in Denver, CO to discuss various emergency planning & preparedness topics including NRC, FEMA, State of CO & Weld County roles in emergency response & evaluation.
COLLINS, J. T. Region 4, Office of Director. 83/05/25, LEE, O. R.,
Public Service Co. of Colorado. 2pp 18672, 198 24X
Fiche 50-267, 83/05/25, 8306010293

8306070199 Forwards responses to open items in IE Emergency Preparedness Appraisal Rept 50-267/83-03 HEPA & charcoal filter equipment installed on technical support ctr ventilation sys.
WAREMBOURG, D. W. Public Service Co. of Colorado, 83/05/27,
COLLINS, J. T. Region 4, Office of Director. 21pp. 18747-095, 24X
Fiche 50-267, 83/05/27, 8306070199

8306140279 Requests remittance of Class II fees for review of 820420, 0914 & 830407 applications re review committee, shift staffing & fire protection. Basis for fee determination discussed.
MILLER, W. D. License Fee Management Branch. 83/05/31 LEE, O. R.,
Public Service Co. of Colorado. 2pp 18844, 306, 24X
Fiche 50-267, 83/05/31, 8306140279.

8306130459 Recommends License DPR-34 be amended incorporating 830328 revs to security plan. Copy of response to licensee requested.
EISENHUT, D. O. Division of Licensing. 83/06/06, CAOLARDO, J. E.
Division of Resident, Reactor Project & Engineering Programs. 2pp
18830:174, 24X Fiche 50-267, 83/06/06, 8306130459.

8306210368 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records. 83/06/06 Document
Management Branch. 1p. 18937:090, 24X Fiche 50-267, 83/06/06,
8306210368

--8306210373 Forwards public version of revised emergency plan implementing procedures, including Procedures RERP Phone List re issue 17, RERP-CR-UE re issue 18 & RERP-CR-ALERT re issue 18 w/o encls.
WAREMBOURG, D. W. Public Service Co. of Colorado. 83/05/03,
COLLINS, J. T. Region 4, Office of Director. 3pp 18937:091, 24X
Fiche 50-267, 83/06/06, 8306210368

8306300130 Ack receipt of 830504 ltr re 830331 notice of deviation contained in IE Insp Rept 50-267/83-03 Implementation of corrective actions will be reviewed during future insp. Emergency plan procedures must be clarified.
MADSEN, O. L. Region 4, Office of Director. 83/06/06 LEE, O. R.,
Public Service Co. of Colorado. 2pp 19122 329 24X
Fiche 50-267, 83/06/06, 8306300130

8306300059 Forwards corrected pages to radiological emergency exercise scheduled for 830615.
WAREMBOURG, D. W. Public Service Co. of Colorado. 83/06/07
MONTGOMERY, J. T. COLLINS, J. T. Region 4, Office of Director. 11pp
19120 279, 24X Fiche 50-267, 83/06/07, 8306300059

P Operating license stage documents & correspondence

8306010335 Responds to NRC 830413 order re environ qualification of safety-related electrical equipment, per 10CFR90.49 Environ qualification records audit will be completed by 831231.
LEE, O. R. Public Service Co. of Colorado. 83/05/17 COLLINS, J. T.
Region 4, Office of Director. 8pp 18681 279 24X
Fiche 50-267, 83/05/17, 8306010335

8306070103 Forwards "Results of PQX Graphite Surveillance, Fort St Vrain," per Tech Spec BR5 2 2P.
BREV, H. L. Public Service Co. of Colorado. 83/05/19 COLLINS, J. T.
Region 4, Office of Director. 2pp 18738 284 24X
Fiche 50-267, 83/05/19, 8306070103

--8306070106 "Results of PQX Graphite Surveillance, Fort St Vrain."
BEAVAN, L. A. Public Service Co. of Colorado. 706624 82/10/21
59pp 18738 286 24X Fiche 50-267, 83/05/19, 8306070103

8306010343 Forwards application for amend to License DPR-34, revising App A Tech Specs re inservice surveillance requirements for snubbers in secondary RCS.
LEE, O. R. Public Service Co. of Colorado. 83/05/20 COLLINS, J. T.,
Region 4, Office of Director. 2pp 18681 293 24X
Fiche 50-267, 83/05/20, 8306010343

--8306010344 Application for amend to License DPR-34, revising App A Tech Specs 4.3 & 5.3 re inservice surveillance requirements for snubbers in secondary RCS.
LEE, O. R. Public Service Co. of Colorado. 83/05/20 2pp
18681-295 24X Fiche 50-267, 83/05/20, 8306010343

--8306010345 Proposed Tech Specs 4.3 & 5.3 re inservice surveillance requirements for snubbers in secondary RCS.
* Public Service Co. of Colorado. 83/05/20 39pp 18681, 297,
24X Fiche 50-267, 83/05/20, 8306010343

8306010411 Forwards application to amend License DPR-34, revising App B, environ protection plan (nonradiological), Tech Specs.
LEE, O. R. Public Service Co. of Colorado. 83/05/20, COLLINS, J. T.
Region 4, Office of Director. 3pp 18679 341 24X
Fiche 50-267, 83/05/20, 8306010411

--8306010416 Application to amend License DPR-34, revising App B, environ protection plan (nonradiological), Tech Specs.
LEE, O. R. Public Service Co. of Colorado. 83/05/20 2pp
18679 344 24X Fiche 50-267, 83/05/20, 8306010411

--8306010419 App B Tech Specs re environ protection plan (nonradiological).
* Public Service Co. of Colorado. 83/05/20 12pp 18679, 346
24X Fiche 50-267, 83/05/20, 8306010411

8306060130 Forwards payment of fees for review of amend to License DPR-34, changing Tech Spec Section 4.4.1.
WAREMBOURG, D. W. Public Service Co. of Colorado. 83/05/24
COLLINS, J. T. Region 4, Office of Director. 2pp 18719, 007 24X
Fiche 50-267, 83/05/24, 8306060130

8306070319 Advises that addl requirements incorporated in Tech Specs w/Amend 2B issued on 821015, assuring acceptable percent region peaking factor surveillance. Further changes not necessary.
MADSEN, O. L. Region 4, Office of Director. 83/05/26 LEE, O. R.,
Public Service Co. of Colorado. 2pp 18746 061 24X
Fiche 50-267, 83/05/26, 8306070319

8306140279 Requests remittance of Class II fees for review of 820420, 0914 & 830407 applications re review committee, shift staffing & fire protection. Basis for fee determination discussed.
MILLER, W. D. License Fee Management Branch. 83/05/31, LEE, O. R.,
Public Service Co. of Colorado. 2pp. 18844, 306, 24X
Fiche 50-267, 83/05/31, 8306140279.

DOCKETED ITEMS

69

8306060137 Requests FR publication of notice of consideration amending License DPR-34 re radiological effluents & proposed no significant hazards consideration determination & opportunity for hearing
MADSEN, O L Region 4, Office of Director 83/06/01 CLARK, R A
Operating Reactors Branch 3 3pp 18719 019 24X
Fiche 50-267, 83/06/01, 8306060137

8306160286 Outlines plan to complete review & update Tech Spec requirements for inservice insp & testing pertaining to other reactor auxiliary & support sys that perform safety function for postulated design basis events
BREV, H L Public Service Co of Colorado 83/06/01 COLLINS, J T
Region 4, Office of Director 2pp 18861 011, 24X
Fiche 50-267, 83/06/01, 8306160286

8306160541 Forwards QA Co Repts 906505, 906577 & QA-A16829 describing results of exams on fuel elements w/cracked webs Repts convey belief that cracks in fuel block graphite webbing do not intersect fuel holes
BREV, H L Public Service Co of Colorado 83/06/02 COLLINS, J T
Region 4, Office of Director 1p 18865 148 24X
Fiche 50-267, 83/06/02, 8306160541

--8306160545 "NDE of Fort St Vrain Fuel Element 1-2415 "
SAURWEIN, J J QA Technologies, Inc /General Atomic Co. 906505
82/10/31 7pp 18863 149 24X Fiche 50-267, 83/06/02, 8306160541

--8306160560 "Visual Exam Results of Segment 2, Fort St Vrain Fuel Elements 1-2415, 1-0172, 2-2693, 1-0108 & 3-0801 "
KETTEVER, J W QA Technologies, Inc /General Atomic Co. 906577
83/04/04, 21pp 18865 158 24X Fiche: 50-267, 83/06/02, 8306160541

--8306160564 "NDE of 54 Fuel & Reflector Elements From Fort St Vrain Core Segment 2 "
SAURWEIN, J J QA Technologies, Inc /General Atomic Co QA-A16829
82/10/31 19pp 18865 179 24X Fiche 50-267, 83/06/02, 8306160541

8306280354 Submits list of NRC & in-house project electrical commitments
BREV, H L Public Service Co of Colorado 83/06/03 WAGNER, P
Region 4, Office of Director 3pp 19001 269 24X
Fiche 50-267, 83/06/03, 8306280354

8306090344 Ack receipt of 830520 application to change Tech Specs re hydraulic snubber testing & surveillance requirements for mechanical snubbers Payment of Class III Fee requested.
DUGG, R M License Fee Management Branch, 83/06/06 LEE, O R
Public Service Co of Colorado 1p 18797, 109, 24X
Fiche 50-267, 83/06/06, 8306090344

8306280343 Forwards description of changes incorporated in updated FBAR, QA program through Amend 32 & of changes to updated FBAR QA program since 830311 Changes since 830311 will be included in Jul 1983 FBAR rev
LEE, O R Public Service Co of Colorado, 83/06/09, COLLINS, J T
Region 4, Office of Director 20pp 19001, 240 24X
Fiche 50-267, 83/06/09, 8306280343

8306140733 Forwards amend fees re 830407 & 19 applications for license amends
WAREMBOURG, D W Public Service Co of Colorado, 83/06/10
MILLER, W O License Fee Management Branch, 1p 18841, 091 24X
Fiche 50-267, 83/06/10, 8306140733

8306160220 Requests publication in monthly FR of notice of consideration of issuance of amend to License DPR-34 & proposed no significant hazards consideration determination & opportunity for hearing
MADSEN, O L Region 4, Office of Director 83/06/10 CLARK, R A
Operating Reactors Branch 3 2pp 18861, 300, 24X
Fiche 50-267, 83/06/10, 8306160220,

G Inspection reports, IE Bulletins & correspondence

8306300104 Forwards exclusion area boundary, emergency planning zone survey team inventory, listed in Health Physics Procedure HPP-37 & Surveillance Procedure SR-HE-3-SA, in response to NRC 821102 ltr & IE Insp Rept 50-267/82-14
LEE, O R Public Service Co of Colorado, 82/11/17 MADSEN, O L
Region 4, Office of Director 4pp 19048, 222, 24X
Fiche 50-267, 82/11/17, 8306300104

--8306300107 Rev 15 to Health Physics Procedure HPP-37, "Radiological Emergency Respiratory Protection Inventory List "
* Public Service Co of Colorado, 82/10/01, 14pp, 19048, 226, 24X Fiche: 50-267, 82/11/17, 8306300104

--8306300111 Rev 1 to Surveillance Procedure SR-HE-3-SA, "Radiation Protection Dept - On/Offsite Emergency Monitoring Exercise,"
* Public Service Co of Colorado 82/07/30 7pp 19048, 240 24X Fiche 50-267, 82/11/17, 8306300104

8306080042 Forwards IE Insp Rept 50-267/82-29 on 821213-17 No noncompliance noted
MADSEN, O L Region 4, Office of Director 83/03/21 LEE, O R
Public Service Co of Colorado 3pp 18773 151, 24X
Fiche 50-267, 83/03/21, 8306080042

--8306080046 IE Insp Rept 50-267/82-29 on 821213-17 No noncompliance noted Major areas inspected radiochemistry program including staffing, training program, sample collection, sample treatment & analysis & lab instrument calibr
NICHOLAS, J B, WIBE, R, MURRAY, B, Region 4, Office of Director 83/02/24 20pp, 18773 155, 24X Fiche: 50-267, 83/03/21, 8306080042

8306010132 Forwards IE Insp Rept 50-267/83-09 on 830411-15 & notice of violation
MADSEN, O L Region 4, Office of Director 83/05/14 LEE, O R
Public Service Co of Colorado 2pp 18674 025 24X
Fiche: 50-267, 83/05/14, 8306010132

--8306010135 Notice of violation from insp on 830411-15
* Region 4, Office of Director 83/05/14 2pp, 18674 027, 24X
Fiche 50-267, 83/05/14, 8306010132

--8306010141 IE Insp Rept 50-267/83-09 on 830411-15 Noncompliance noted: failure to follow Procedures GCIM-1 & Q12 re QC/QA dept measuring & test equipment program & results.
REDANO, R T, WESTERMAN, T F, Region 4, Office of Director 83/05/13 12pp 18674 029 24X Fiche 50-267, 83/05/14, 8306010132

8306010335 Responds to NRC 830413 order re environ qualification of safety-related electrical equipment, per 10CFR50.49 Environ qualification records audit will be completed by 831231
LEE, O R Public Service Co of Colorado 83/05/17, COLLINS, J T
Region 4, Office of Director, 8pp 18681, 279, 24X
Fiche 50-267, 83/05/17, 8306010335

8306060125 Forwards IE Insp Rept 50-267/83-10 on 830401-30 No noncompliance noted
MADSEN, O L Region 4, Office of Director 83/05/20, LEE, O R
Public Service Co of Colorado 2pp, 18722, 289, 24X
Fiche 50-267, 83/05/20, 8306060125,

--8306060126 IE Insp Rept 50-267/83-10 on 830401-30 No noncompliance noted Major areas inspected operational safety verification, surveillance, maint, bulletin followup, followup of previous insp findings & review of periodic & special repts.
DICKERSON, M W, PLUNLEE, O L, WESTERMAN, T F Region 4, Office of Director 83/05/19 7pp, 18722, 291 24X Fiche: 50-267, 83/05/20, 8306060125

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl.
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc. 125pp, 18831, 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet, " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche: 50-000, 83/05/26, 8305110460,

8306070199 Forwards responses to open items in IE Emergency Preparedness Appraisal Rept 50-267/83-03, HEPA & charcoal filter equipment installed on technical support ctr ventilation sys.
WAREMBOURG, D W Public Service Co of Colorado 83/05/27, COLLINS, J T Region 4, Office of Director, 21pp, 18747, 095 24X
Fiche: 50-267, 83/05/27, 8306070199,

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs, " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31, Consolidated Edison Co. of New York, Inc 116pp, 18732, 208, 24X Fiche: 50-000, 83/05/31, 8305110461,

8306160286 Outlines plan to complete review & update Tech Spec requirements for inservice insp & testing pertaining to other reactor auxiliary & support sys that perform safety function for postulated design basis events.
BREV, H L Public Service Co. of Colorado, 83/06/01, COLLINS, J T
Region 4, Office of Director 2pp, 18861, 011, 24X
Fiche: 50-267, 83/06/01, 8306160286,

DOCKETED ITEMS

8306300130 Ack receipt of 830506 ltr re 830331 notice of deviation contained in IE Insp Rept 50-267/83-03 Implementation of corrective actions will be reviewed during future Insp Emergency plan procedures must be clarified
MADSEN, O L Region 4, Office of Director 83/06/06 LEE, O R
Public Service Co of Colorado 2pp. 19122 329 24X
Fiche 50-267,83/06/06, 8306300130

8306210253 Responds to NRC 830514 ltr re violations noted in IE Insp Rept 50-267/83-09 Corrective actions measuring & test equipment maint/history cards reviewed & calibrs updated
Procedure GC-1 revised to include quarterly review
WAREHOUR, D W. Public Service Co of Colorado 83/06/07
COLLINS, J T Region 4, Office of Director 5pp 18914 001 24X
Fiche 50-267,83/06/07, 8306210253

8306210011 Clarifies proposed solution to Open Item 3 re radwaste sys identified in IE Insp Repts 50-267/78-15 & 50-267/83-06
Resolution will be included in next PSAR rev. scheduled for 830722.
BREV, H L Public Service Co of Colorado 83/06/08 COLLINS, J T
Region 4, Office of Director 2pp 18910 335 24X
Fiche 50-267,83/06/08, 8306210011

8305110444 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 260 24X Fiche 50-000,83/06/09, 8305110444

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Electrically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 118pp 18920 228 24X Fiche 50-000,83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000,83/06/13, 8306090010

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 115pp 19021 179 24X Fiche 50-000,83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp. 18997 007 24X Fiche 50-000,83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000,83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp. 19046 297 24X Fiche 50-000,83/06/24, 8305110483

R. Periodic operating reports & related correspondence

8306160434 Monthly operating rept for May 1983 W/830614 ltr
FULLER, C.H., WAREHOUR, D Public Service Co of Colorado.
83/06/09 Director's Office, Office of Inspection and Enforcement
10pp. 18861 131 24X Fiche 50-267,83/06/09, 8306160434

S. Reportable occurrences, LERs & related correspondence

8306060134 LER 83-017/01T-0; on 830512, insp performed per IE Bulletin 83-03 identified six of eight check valves frozen in mid-position. Caused by corrosion & rusting valve internal parts. Valves cleaned & internal components replaced
WAREHOUR, D. Public Service Co of Colorado 83/05/26
COLLINS, J T Region 4, Office of Director. 7pp. 18719 009 24X
Fiche 50-267,83/05/26, 8306060134.

8306280217 Forwards updated LERs 78-027/03X-6, 79-032/03X-2 & 79-056/03X-1, et al.
WAREHOUR, D. Public Service Co. of Colorado 83/06/06
COLLINS, J T. Region 4, Office of Director 2pp. 19001 063 24X
Fiche: 50-267,83/06/06, 8306280217

--8306280228 Updated LER 78-027/03X-6 on 780706, numerous failures of ITT Barton Model 209 pressure differential switches reported
Caused by dirt accumulation & oxidation on contact surfaces
Switches replaced w/Model 752 pressure transmitters
* Public Service Co of Colorado 83/06/06 Region 4, Office of Director 5pp 19001 063 24X Fiche 50-267,83/06/06, 8306280217

--8306280236 Updated LER 79-032/03X-2 on 790913, during testing, four of 12 helium circulator seal malfunction pressure differential switch units would not trip Caused by dirt accumulation in electrical switches Switches replaced
* Public Service Co of Colorado 83/06/06 Region 4, Office of Director 5pp 19001 068 24X Fiche 50-267,83/06/06, 8306280217

--8306280246 Updated LER 79-056/03X-1 on 791030, during testing, seven of 12 helium circulator seal malfunction pressure differential switch units tripped outside limits Caused by dirt accumulation in electrical switches Switches replaced
* Public Service Co of Colorado 83/06/06 Region 4, Office of Director 5pp 19001 073 24X Fiche 50-267,83/06/06, 8306280217

--8306280260 Updated LER 80-007/03X-1 on 800219, during testing, two of 12 helium circulator seal malfunction pressure differential switch units tripped outside limits Caused by dirt accumulation in electrical switches Switches replaced
* Public Service Co of Colorado 83/06/06 Region 4, Office of Director 5pp 19001 078 24X Fiche 50-267,83/06/06, 8306280217

--8306280262 Updated LER 80-016/03X-1 on 800322, during testing, four of 12 helium circulator seal malfunction pressure differential switch units tripped outside limits Caused by dirt accumulation in electrical switches Switches replaced
* Public Service Co of Colorado 83/06/06 Region 4, Office of Director 5pp 19001 083 24X Fiche 50-267,83/06/06, 8306280217

--8306280266 Updated LER 80-020/03X-1 on 800418, during testing, two of 12 helium circulator seal malfunction pressure differential switch units tripped outside limits Caused by dirt accumulation in electrical switches Switches replaced
* Public Service Co of Colorado 83/06/06 Region 4, Office of Director 5pp 19001 088 24X Fiche 50-267,83/06/06, 8306280217

--8306280272 Updated LER 80-026/03X-1 on 800524, during testing, eight of 12 helium circulator seal malfunction pressure differential switch units tripped outside limits Caused by dirt accumulation in electrical switches Switches replaced
* Public Service Co of Colorado 83/06/06 Region 4, Office of Director 5pp 19001 093 24X Fiche 50-267,83/06/06, 8306280217

--8306280278 Updated LER 80-034/03X-1 on 800619, during testing, two of 12 helium circulator seal malfunction pressure differential switch units tripped outside limits. Caused by dirt accumulation in electrical switches Switches replaced
* Public Service Co of Colorado 83/06/06 Region 4, Office of Director 5pp 19001 098 24X Fiche 50-267,83/06/06, 8306280217

--8306280283 Updated LER 80-041/03X-1 on 800721, during testing, one of 12 helium circulator seal malfunction pressure differential switch units tripped outside limits Caused by dirt accumulation in electrical switches Switches replaced
* Public Service Co of Colorado 83/06/06 Region 4, Office of Director 4pp 19001 103 24X Fiche 50-267,83/06/06, 8306280217

--8306280288 Updated LER 80-051/03X-1 on 800922, during testing, five of 12 helium circulator seal malfunction pressure differential switch units tripped outside limits. Caused by dirt accumulation in electrical switches Switches replaced
* Public Service Co of Colorado 83/06/06 Region 4, Office of Director 5pp 19001 109 24X Fiche 50-267,83/06/06, 8306280217

--8306280293 Updated LER 80-072/03X-1 on 801117, during testing, three of 12 helium circulator seal malfunction pressure differential switch units tripped outside limits. Caused by dirt accumulation in electrical switches Switches replaced
* Public Service Co of Colorado 83/06/06 Region 4, Office of Director 5pp 19001 114 24X Fiche 50-267,83/06/06, 8306280217.

--8306280298 Updated LER 81-006/03X-1 on 810107, during annual testing & calibr, six of 12 helium circulator seal malfunction pressure differential switch units tripped outside limits. Caused by dirt accumulation in electrical switches Switches replaced.
* Public Service Co of Colorado 83/06/06 Region 4, Office of Director 5pp. 19001 180 24X Fiche 50-267,83/06/06, 8306280217

DOCKETED ITEMS

71

--B306280302 Updated LER 81-016/03X-1 on B10213, during testing, three of 12 helium circulator seal malfunction pressure differential switch units tripped outside limits Caused by dirt accumulation in electrical switches Switches replaced
* Public Service Co of Colorado B3/06/06 Region 4, Office of Director 5pp 19001 185 24X Fiche 50-267, B3/06/06, B306280217

--B306280309 Updated LER 81-024/03X-1 on B10317, during testing, five of 12 helium circulator seal malfunction pressure differential switch units tripped outside limits Caused by dirt accumulation in electrical switches Switches replaced
* Public Service Co of Colorado B3/06/06 Region 4, Office of Director 5pp 19001 190 24X Fiche 50-267, B3/06/06, B306280217

--B306280313 Updated LER 81-047/03X-1 on B10807, during testing, one of 12 helium circulator seal malfunction pressure differential switch units tripped outside limits Caused by dirt accumulation in electrical switch Switch replaced
* Public Service Co of Colorado B3/06/06 Region 4, Office of Director 5pp 19001 195 24X Fiche 50-267, B3/06/06, B306280217

B306300187 LER 83-018/03L-0 on B30517, w/reactor shutdown, all outside power lost due to high winds & snow Emergency diesel generator load shedding & sequencing relays failed to operate Caused by coil failures Relays tested W/B30616 ltr WAREMBOURG, D Public Service Co of Colorado B3/06/16 COLLINS, J T Region 4, Office of Director 7pp 19119 256 24X Fiche 50-267, B3/06/16, B306300187

B306300098 LER 83-019/01T-0 on B30606, discovered that reactor operated between 5% power & shutdown w/o operable analytical moisture monitors on B30603 Caused by accidental isolation of sample paths to monitors NOVACHEK, F WAREMBOURG, D Public Service Co of Colorado B3/06/17 COLLINS, J T Region 4, Office of Director 8pp 19122 001 24X Fiche 50-267, B3/06/17, B306300098

DOCKET 50-269 OCONEE NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

B306090361 Forwards request for exemption from emergency operations facility (EOP) location requirements per Generic Ltr 82-33 Proposed EOP to be located 125 air miles from facility, w/ joint news ctr remaining in Oconee, NC
TUCKER, H B Duke Power Co B3/06/03 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 28pp 18795 039 24X Fiche 50-269, B3/06/03, B306090361

B306170283 Forwards IE Safeguards Insp Repts 50-269/B3-14 50-270/B3-14 & 50-287/B3-14 on B30509-13 No noncompliance noted
DANCE, H C Division of Project & Resident Programs B3/06/15 TUCKER, H B Duke Power Co 2pp 18877, 233, 24X Fiche 50-269, B3/06/15, B306170283

--B306170307 IE Safeguards Insp Repts 50-269/B3-14, 50-270/B3-14 & 50-287/B3-14 on B30509-13 No noncompliance noted Major areas inspected security plan & implementing procedures & security organization mgt Safeguards info deleted (ref 10CFR73.21).
TILLMAN, A Region 2, Office of Director B3/06/15 2pp, 18877, 235 24X Fiche 50-269, B3/06/15, B306170285

B306240038 Advises that preliminary fee review of B30603 request for exemption from location requirements of emergency operations facility determined that Class III appropriate
DUGGINS, R M License Fee Management Branch B3/06/15 TUCKER, H B Duke Power Co 1p 18987, 229 24X Fiche 50-269, B3/06/15, B306240038

P Operating license stage documents & correspondence

B306060051 Addl response to FOIA request for three categories of documents re PRA of reactor safety study methodology application program repts & interim reliability evaluation program repts, Forwards App A documents, Search continuing
FELTON, J M Division of Rules and Records B3/04/07, SHOLLY, S C Office of Concerned Scientists 3pp 18752, 001 24X Fiche 50-000, B3/04/07, B306060051

--B306060076 Discusses interim actions taken to reduce impact of turbine bldg flooding Doors between turbine & auxiliary bldgs at basement level sealed shut; component cooling water crossover valves closed & condensate cooler isolated
TUCKER, H B Duke Power Co B2/12/01 O'REILLY, J P Region 2, Office of Director 2pp 18752, 198, 24X Fiche 50-000, B3/04/07, B306060051

--B306060085 Provides info on boron precipitation clogging HP1 lines & failure of operator to switch to hot leg injection in order to flush out boron residue from core during recirculation
Info obtained from PRAs
DAVIS, S NRC - No Detailed Affiliation Given B3/02/24
THADANI, A NRC - No Detailed Affiliation Given 6pp 18752 206 24X Fiche 50-000, B3/04/07, B306060051

B306020103 Proposes B30608 meeting in Bethesda, MD to discuss Suppl & to SER for McGuire & SER for standby shutdown facility for Oconee
STOLZ, J F Operating Reactors Branch 4 B3/05/17 TUCKER, H B Duke Power Co 1p 18701 279 24X Fiche 50-000, B3/05/17, B306020103

B306070051 Forwards summary of B30512 meeting w/util & B&W, in response to B30327 request for addl info re reactor vessel surveillance capsule dosimetry results contained in BAW-1697 & 1699
TUCKER, H B Duke Power Co B3/05/27 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 4pp 18740 039 24X Fiche 50-269, B3/05/27, B306070051

B306030122 Forwards addl info to aid in completion of review re NUREG-0737, Items II F 1 4, II F 1 5 & II F 1 6, per B30110 ltr request & justification concerning Item II, F 1 5 Amend to B30318 confirmatory order requested
TUCKER, H B Duke Power Co B3/05/31 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 15pp 18704 302 24X Fiche 50-269, B3/05/31, B306030122

B306070272 Forwards BAW-1784, "B&W Owners Group Bolting Task Force Summary Rept of NRC/B&W Owners Group B30506 Meeting on Reactor Vessel Internals Bolting " Agrees w/overall findings, w/exception re neutron noise surveillance
TUCKER, H B Duke Power Co B3/05/31 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 2pp 18744 086 24X Fiche 50-269, B3/05/31, B306070272

--B306070280 Forwards BAW-1784, "B&W Owners Group Bolting Task Force Summary Rept of NRC/B&W Owners Group B30506 Meeting on Reactor Vessel Internals Bolting."
TAYLOR, J H Babcock & Wilcox Operating Plants Owners Group, TAYLOR, J H Babcock & Wilcox Co B3/05/20 MINER, S NRC - No Detailed Affiliation Given 1p 18744 088 24X Fiche 50-269, B3/05/31, B306070272

--B306070286 "B&W Owners Group Bolting Task Force Summary Rept of NRC/B&W Owners Group B30506 Meeting on Reactor Vessel Internals Bolting "
* Babcock & Wilcox Co BAW-1784, B3/05/31 124pp, 18744-089, 24X Fiche 50-269, B3/05/31, B306070272

B306140738 Forwards topical repts, "Boundary Analytical Assessment of NUREG-0630 on LOCA & Operating kW/Ft Limits," per B30602 request
TUCKER, H B Duke Power Co B3/06/26 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 1p 18845 001 24X Fiche 50-269, B3/06/06, B306140738

--B306140746 "Boundary Analytical Assessment of NUREG-0630 on LOCA & Operating kW/Ft Limits "
* Babcock & Wilcox Co 77-1141256-00, B3/06/06 29pp, 18845, 002 24X Fiche 50-269, B3/06/06, B306140738

--B306140752 "Boundary Analytical Assessment of NUREG-0630 on LOCA & Operating kW/Ft Limits "
* Babcock & Wilcox Co 77-1140895-00 B3/06/06 29pp 18845 032 24X Fiche 50-269, B3/06/06, B306140738

B306200185 Summary of B30512 meeting w/util & B&W in Bethesda, MD re neutron dosimetry & upper shelf matl properties provided in Topical Repts BAW-1697 & BAW-1699, List of attendees, agenda & viewpoints encl.
SUERMANN, J F Operating Reactors Branch 4 B3/06/06 Operating Reactors Branch 4 39pp 18909 183 24X Fiche 50-269, B3/06/06, B306200185

B306140377 Forwards revised Table D-1, "Preliminary Stress Level Comparison," showing value of stress concentration factor & higher calculated peak stresses Higher peak stresses do not affect conclusions from B30506 meeting Meeting summary encl.
TAYLOR, J H Babcock & Wilcox Co B3/06/07, MINER, S NRC - No Detailed Affiliation Given 2pp 18845 067, 24X Fiche 50-000, B3/06/07, B306140377

B306220275 Informs that B30310 proposed wide-range hot leg level/ reactor vessel head monitoring satisfactory Evaluation & addl info request re conformance of addl inadequate core cooling instrumentation sys components to NUREG-0737, encl.
STOLZ, J F Operating Reactors Branch 4 B3/06/06 TUCKER, H B Duke Power Co 10pp 18977 155 24X Fiche 50-269, B3/06/06, B306220275

DOCKETED ITEMS

Q Inspection reports, IE Bulletins & correspondence

8306080402 Confirms 830513 telcon re proposed site/corporate visit on 830529-27 to review masonry wall const. drawings & calculations re review of IE Bulletin 80-11 response Agenda encl
STOLZ, J F Operating Reactors Branch 4 83/05/20 TUCKER, H B Duke Power Co 4pp. 18789 342. 24X Fiche 50-000, 83/05/20, 8306080402

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 120pp 18831 043. 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732-085 24X Fiche 50-000, 83/05/26, 8305110460

8306010310 EN-83-038 notice of violation & proposed imposition of civil penalties in amount of \$180,000 to be issued on 830602 Action based on three Severity Level III violations re failure to maintain primary containment integrity.
BARBER, O, AXELRAD, J Director's Office, Office of Inspection and Enforcement 83/05/27 1p 18672 317 24X Fiche 50-269, 83/05/27, 8306010310

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732-208 24X Fiche 50-000, 83/05/31, 8305110461.

8306220171 Discusses IE insp on 830317-28 & forwards notice of violation & proposed imposition of civil penalty
O'REILLY, J P. Region 2, Office of Director. 83/06/02, TUCKER, H B, Duke Power Co 4pp 18937 281 24X Fiche 50-269, 83/06/02, 8306220171

--8306220175 Notice of violation & proposed imposition of civil penalty in amount of \$180,000 Noncompliance noted inadequate procedures to ensure that air lock sys restored to operability after maint
O'REILLY, J P. Director's Office, Office of Inspection and Enforcement. 83/06/02 4pp 18937 285 24X Fiche 50-269, 83/06/02, 8306220171

8306220245 Informs that response to IE Bulletin 83-03, Item 4 re failures of check valves used in diesel generator water cooling sys. will be submitted by 830622
TUCKER, H B Duke Power Co. 83/06/08 O'REILLY, J P Region 2, Office of Director 1p 19056-085 24X Fiche 50-269, 83/06/08, 8306220245

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp. 18830-280 24X Fiche 50-000, 83/06/09, 8305110464.

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 118pp. 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp. 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8306170285 Forwards IE Safeguards Insp Repts 50-269/83-14 50-270/83-14 & 50-287/83-14 on 830509-13 No noncompliance noted.
DANCE, H C Division of Project & Resident Programs 83/06/15 TUCKER, H B Duke Power Co. 2pp. 18877 233. 24X Fiche: 50-269, 83/06/15, 8306170285

--8306170307 IE Safeguards Insp Repts 50-269/83-14, 50-270/83-14 & 50-287/83-14 on 830509-13 No noncompliance noted. Major areas inspected security plan & implementing procedures & security organization mgt. Safeguards info deleted (ref 10CFR73 21).
TILLMAN, A, ENNIS, J Region 2, Office of Director MCQUIRE, D R Division of Emergency Preparedness & Materials Safety 83/06/15 2pp. 18877, 235. 24X Fiche: 50-269, 83/06/15, 8306170285

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 115pp 19021 177 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

R Periodic operating reports & related correspondence

8306170297 Monthly operating repts for May 1983 W/830615 1br
REAVIS, J A, TUCKER, H B Duke Power Co 83/06/15 17pp 18878 177 24X Fiche 50-269, 83/06/15, 8306170297

S Reportable occurrences, LCRs & related correspondence

8306300220 Part 21 rept re loose locking clips used to secure terminal boards to rear terminal panels of safety-related instrument cabinets. Initially reported on 821203 All B&W plants notified
TAYLOR, J H Babcock & Wilcox Co 82/12/03 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 4pp 19121 356 24X Fiche 50-269, 82/12/03, 8306300220

DOCKET 50-270 OCONEE NUCLEAR STATION, UNIT 2F Security, medical, emergency & fire protection plans

8306090361 Forwards request for exemption from emergency operations facility (EOF) location requirements per Generic Ltr 82-33 Proposed EOF to be located 12 1/2 air miles from facility, w/ joint news ctr remaining in Oconee, NC
TUCKER, H B Duke Power Co 83/06/03 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 28pp. 18795 039 24X Fiche. 50-269, 83/06/03, 8306090361

8306170285 Forwards IE Safeguards Insp Repts 50-269/83-14 50-270/83-14 & 50-287/83-14 on 830509-13 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/06/15 TUCKER, H B Duke Power Co 2pp 18877 233 24X Fiche 50-269, 83/06/15, 8306170285

--8306170307 IE Safeguards Insp Repts 50-269/83-14, 50-270/83-14 & 50-287/83-14 on 830509-13 No noncompliance noted. Major areas inspected security plan & implementing procedures & security organization mgt. Safeguards info deleted (ref 10CFR73 21)
TILLMAN, A Region 2, Office of Director 83/06/15 2pp 18877 235 24X Fiche 50-269, 83/06/15, 8306170285

8306240038 Advises that preliminary fee review of 830603 request for exemption from location requirements of emergency operations facility determined that Class III appropriate
DIQOS, R M License Fee Management Branch 83/06/15 TUCKER, H B Duke Power Co 1p 18987 229 24X Fiche 50-269, 83/06/15, 8306240038

P Operating license stage documents & correspondence

8306060051 Addl response to FOIA request for three categories of documents re PRA of reactor safety study methodology application program repts & interim reliability evaluation program repts. Forwards App A documents Search continuing
FELTON, J M Division of Rules and Records 83/04/07 SHOLLY, B C Union of Concerned Scientists 3pp 18732, 001. 24X Fiche 50-000, 83/04/07, 8306060051.

--B306060076 Discusses interim actions taken to reduce impact of turbine bldg flooding. Doors between turbine & auxiliary bldgs at basement level sealed shut; component cooling water crossover valves closed & condensate cooler isolated.
TUCKER, H B Duke Power Co 82/12/01 O'REILLY, J P Region 2, Office of Director 2pp 18/52 19B 24X Fiche 50-000, 83/04/07, B306060051

--B306060085 Provides info on boron precipitation clogging HPI lines & failure of operator to switch to hot leg injection in order to flush out boron residue from core during recirculation. Info obtained from PRAs.
DAVIS, B NRC - No Detailed Affiliation Given 83/02/24
THADANI, A NRC - No Detailed Affiliation Given 4pp 18/52 20B 24X Fiche 50-000, 83/04/07, B306060051

B306020103 Proposes B3060B meeting in Bethesda, MD to discuss Suppl A to SER for McGuire & SER for standby shutdown facility for Oconee.
STOLZ, J F Operating Reactors Branch 4 83/05/17 TUCKER, H B Duke Power Co 1p 18/01 279 24X Fiche 50-000, 83/05/17, B306020103

B306070051 Forwards summary of B30512 meeting w/util & B&W in response to B30327 request for addl info re reactor vessel surveillance capsule dosimetry results contained in BAW-1697 & 1699.
TUCKER, H B Duke Power Co 83/05/27 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 4pp 18/40 059 24X Fiche 50-269, 83/05/27, B306070051

B306030122 Forwards addl info to aid in completion of review re NUREG-0737, Items II F 1.4, II F 1.5 & II F 1.6, per B30110 ltr request & justification concerning Item II F 1.5 Amend to B30318 confirmatory order requested.
TUCKER, H B Duke Power Co 83/05/31 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 15pp 18/04 302 24X Fiche 50-269, 83/05/31, B306030122

B306070272 Forwards BAW-1784, "B&W Owners Group Bolting Task Force Summary Rept of NRC/B&W Owners Group B30506 Meeting on Reactor Vessel Internals Bolting." Agrees w/overall findings, w/exception re neutron noise surveillance.
TUCKER, H B Duke Power Co 83/05/31 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 2pp 18/44 086 24X Fiche 50-269, 83/05/31, B306070272

--B306070280 Forwards BAW-1784, "B&W Owners Group Bolting Task Force Summary Rept of NRC/B&W Owners Group B30506 Meeting on Reactor Vessel Internals Bolting."
TAYLOR, J H Babcock & Wilcox Operating Plants Owners Group
TAYLOR, J H Babcock & Wilcox Co 83/05/20 MINER, S NRC - No Detailed Affiliation Given 1p 18/44 088 24X Fiche 50-269, 83/05/31, B306070272

--B306070286 "B&W Owners Group Bolting Task Force Summary Rept of NRC/B&W Owners Group B30506 Meeting on Reactor Vessel Internals Bolting."
* Babcock & Wilcox Co BAW-1784 83/05/31 124pp, 18/44 089 24X Fiche 50-269, 83/05/31, B306070272

B306140738 Forwards topical repts, "Boundary Analytical Assessment of NUREG-0630 on LOCA & Operating kW/Ft Limits," per B30602 request.
TUCKER, H B Duke Power Co 83/06/26, DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 1p, 18/45 001 24X Fiche 50-269, 83/06/06, B306140738.

--B306140752 "Bounding Analytical Assessment of NUREG-0630 on LOCA & Operating kW/Ft Limits."
* Babcock & Wilcox Co 77-1140895-00 83/06/06 29pp, 18/45 032 24X Fiche 50-269, 83/06/06, B306140738.

B306200185 Summary of B30512 meeting w/util & B&W in Bethesda, MD re neutron dosimetry & upper half matl properties provided in Topical Repts BAW-1697 & BAW-1699 List of attendees, agenda & viewpoints encl.
SVERMANN, J F Operating Reactors Branch 4 83/06/06 Operating Reactors Branch 4 35pp 18/09 183 24X Fiche 50-269, 83/06/06, B306200185

B306140377 Forwards revised Table D-1, "Preliminary Stress Level Comparison," showing value of stress concentration factor & higher calculated peak stresses. Higher peak stresses do not affect conclusions from B30506 meeting. Meeting summary encl.
TAYLOR, J H Babcock & Wilcox Co 83/06/07 MINER, S NRC - No Detailed Affiliation Given 2pp, 18/43 067 24X Fiche 50-000, 83/06/07, B306140377

B306220275 Informs that B30310 proposed wide-range hot leg level/ reactor vessel head monitoring satisfactory. Evaluation & addl info request re conformance of addl inadequate core cooling instrumentation sys components to NUREG-0737, encl.
STOLZ, J F Operating Reactors Branch 4 83/06/08 TUCKER, H B Duke Power Co 10pp 18/77 155 24X Fiche 50-269, 83/06/08, B306220275

G Inspection reports, IE Bulletins & correspondence

B306080402 Confirms B30513 telcon re proposed site/corporate visit on B30525-27 to review masonry wall const, drawings & calculations re review of IE Bulletin 80-11 response Agenda encl.
STOLZ, J F Operating Reactors Branch 4 83/05/20, TUCKER, H B Duke Power Co 4pp 18/89 342 24X Fiche 50-269, 83/05/20, B306080402

B305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device." Svc list encl.
TAYLOR, J M Division of Safeguards & Inspection Programs (Post B30103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18/31 043 24X Fiche 50-000, 83/05/26, B305110458

B305110460 IE Info Notice 83-34, "Event Notification Info Worksheet." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/05/26 Consolidated Edison Co. of New York, Inc 115pp 18/32 085 24X Fiche 50-000, 83/05/26, B305110460.

B305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/05/31 Consolidated Edison Co. of New York, Inc 116pp 18/32 208 24X Fiche 50-000, 83/05/31, B305110461

B306220171 Discusses IE insp on B30317-28 & forwards notice of violation & proposed imposition of civil penalty.
O'REILLY, J P Region 2, Office of Director 83/06/02 TUCKER, H B, Duke Power Co. 4pp 18/37 281 24X Fiche 50-269, 83/06/02, B306220171

--B306220175 Notice of violation & proposed imposition of civil penalty in amount of \$180,000 Noncompliance noted. Inadequate procedures to ensure that air lock sys restored to operability after maint.
O'REILLY, J P Director's Office, Office of Inspection and Enforcement 83/06/02 4pp 18/37 285 24X Fiche 50-269, 83/06/02, B306220171

B306290245 Informs that response to IE Bulletin 83-03, Item 4 re failures of check valves used in diesel generator water cooling sys, will be submitted by B30622.
TUCKER, H B Duke Power Co 83/06/08 O'REILLY, J P Region 2, Office of Director, 1p, 19/06 085, 24X Fiche 50-269, 83/06/08, B306290245

B305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/06/09 Consolidated Edison Co. of New York, Inc 119pp 18/30 280 24X Fiche 50-000, 83/06/09, B305110464

B305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Electrically Induced Chatter in Relays Within Printed Circuit Cards." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/06/13 Consolidated Edison Co. of New York, Inc 118pp, 18/20 225 24X Fiche 50-000, 83/06/13, B305110470.

B306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/06/13 Consolidated Edison Co. of New York, Inc 243pp 18/21 001 24X Fiche 50-000, 83/06/13, B306090010.

B306170285 Forwards IE Safeguards Insp Repts 50-269/83-14 50-270/83-14 & 50-287/83-14 on B30509-13. No noncompliance noted.
DANCE, H C Division of Project & Resident Programs 83/06/15 TUCKER, H B, Duke Power Co 2pp 18/77 233 24X Fiche 50-269, 83/06/15, B306170285

--B306170307 IE Safeguards Insp Repts 50-269/83-14, 50-270/83-14 & 50-287/83-14 on B30509-13. No noncompliance noted. Major areas inspected, security plan & implementing procedures & security organization mgt. Safeguards info deleted (ref 10CFR73.21).
TILLMAN, A J ENNIS, J Region 2, Office of Director McGuire, D R, Division of Emergency Preparedness & Materials Safety 83/06/15 2pp 18/77 235, 24X Fiche 50-269, 83/06/15, B306170285.

DOCKETED ITEMS

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Gaskets & Sealers." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 118pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18994 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

R. Periodic operating reports & related correspondence

8306170297 Monthly operating repts for May 1983 W/830615 11r
REAVIS, J A, TUCKER, H B Duke Power Co 83/06/15 17pp
18878 177 24X Fiche 50-269, 83/06/15, 8306170297.

DOCKET 50-271 VERMONT YANKEE NUCLEAR POWER STATION

F. Security, medical, emergency & fire protection plans

8306010301 Forwards IE Insp Rept 50-271/83-12 on 830503-04 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/05/17
MURPHY, W P Vermont Yankee Nuclear Power Corp 2pp 18672 303
24X Fiche 50-271, 83/05/17, 8306010301

--8306010304 IE Insp Rept 50-271/83-12 on 830503-04 No noncompliance noted
Major areas inspected public prompt notification sys
COHEN, I, GORDON, C, CRDCHER, H W Region I, Office of Director
83/05/16 3pp 18672 305 24X Fiche 50-271, 83/05/17, 8306010301

8306070344 Forwards IE Insp Rept 50-271/83-01 on 830104-31 & notice of violation.
STAROSTECKI, R Division of Project & Resident Programs 83/05/24
MURPHY, W P Vermont Yankee Nuclear Power Corp 2pp 18742 037
24X Fiche 50-271, 83/05/24, 8306070344

--8306070353 IE Insp Rept 50-271/83-01 on 830104-0131 Noncompliance noted
Failure to follow health physics survey procedure & failure to maintain valve lineups per approved procedures
RAYMOND, W J, WIGGINS, J T, QALLOR, H Region I, Office of Director
83/05/19 24pp 18742 041 24X Fiche 50-271, 83/05/24, 8306070344

8306010435 Proposed Change 110 to License DPR-28, deleting Tech Spec provision for annual site evacuation drill. Tech Spec requirement duplicated by 10CFR50, App E
HEIDER, L H Vermont Yankee Nuclear Power Corp 83/05/26
EISENHUT, D G Division of Licensing 3pp 18674 268 24X Fiche 50-271, 83/05/26, 8306010435

--8306010436 Proposed Tech Spec change, deleting provision for annual site evacuation drill
* Vermont Yankee Nuclear Power Corp 83/05/26 1p 18674 271
24X Fiche 50-271, 83/05/26, 8306010435

8306150290 Releases public version of revised emergency plan implementing procedures
FELTON, J H Division of Rules and Records 83/06/06 Document Management Branch 1p 18869 276 24X Fiche 50-271, 83/06/06, 8306150290

--8306150293 Forwards public version of revised emergency plan implementing procedures, including Procedures OP 3500 re unusual events, OP 3501 re alert & OP 3502 re site area emergency
MARKT, D Yankee Atomic Electric Co 83/05/03 NRC - No Detailed Affiliation Given 1p 18869 277 24X Fiche 50-271, 83/06/06, 8306150290.

--8306150299 Public version of revised emergency plan implementing procedures, including Procedures OP 3500 re unusual events, OP 3501 re alert & OP 3502 re site area emergency
MARKT, D Yankee Atomic Electric Co 83/05/03 Office of Nuclear Reactor Regulation, Director 40pp 18869 278 24X Fiche 50-271, 83/06/06, 8306150290

8306280112 Forwards Temporary Change 83-1 to physical security plan Change withheld
MURPHY, W P Vermont Yankee Nuclear Power Corp 83/06/14
VASSALLO, D B Operating Reactors Branch 2 1p 19001 130 24X Fiche 50-271, 83/06/14, 8306280112

H. General correspondence

8306210029 Opposes facility restart Unresolved safety issues re inadequate pipe supports & cracked feedwater nozzle preclude safe operation Petition to follow
RICHARDSON, C Vermont Yankee Decommissioning Alliance 83/06/16
ROONEY, V, VASSALLO, D Operating Reactors Branch 2 1p 18912 296 24X Fiche 50-271, 83/06/16, 8306210029

I. Financial information

8306200073 Forwards annual financial statements for 1980, 1981 & 1982, per 10CFR50 71(b)
SINGLAIR, J B Vermont Yankee Nuclear Power Corp 83/06/15
DENTON, H R Office of Nuclear Reactor Regulation, Director 10pp 18904 001 24X Fiche 50-271, 83/06/15, 8306200073

P. Operating license stage documents & correspondence

8306010246 Application to amend License DPR-28, consisting of Proposed Change 107, revising Tech Spec Figure 3 & 1 re reactor vessel pressure temp limitations to permit reactor operation to power output of 1 330EB MMH(t)
HEIDER, L H Vermont Yankee Nuclear Power Corp 83/05/26
EISENHUT, D G Division of Licensing 4pp 18673 026 24X Fiche 50-271, 83/05/26, 8306010246

--8306010248 Proposed Change 107 revising Tech Spec Figure 3 & 1 re reactor vessel pressure temp limitations for operation through 1 330EB MMH(t)
* Vermont Yankee Nuclear Power Corp 83/05/26 3pp 18673 030 24X Fiche 50-271, 83/05/26, 8306010246

8306010379 Application to amend License DPR-28, modifying App A Tech Specs to reflect new limiting conditions for operation & surveillance requirements for RCS leakage monitoring sys
HEIDER, L H Vermont Yankee Nuclear Power Corp 83/05/26
EISENHUT, D G Division of Licensing 3pp 18682 193 24X Fiche 50-271, 83/05/26, 8306010379

--8306010383 Proposed Tech Specs re limiting conditions for operation & surveillance requirements for RCS leakage monitoring sys
* Vermont Yankee Nuclear Power Corp 83/05/26 4pp 18682 156 24X Fiche 50-271, 83/05/26, 8306010379

8306010435 Proposed Change 110 to License DPR-28, deleting Tech Spec provision for annual site evacuation drill Tech Spec requirement duplicated by 10CFR50, App L
HEIDER, L H Vermont Yankee Nuclear Power Corp 83/05/26
EISENHUT, D G Division of Licensing 3pp 18674 268 24X Fiche 50-271, 83/05/26, 8306010435

--8306010436 Proposed Tech Spec change, deleting provision for annual site evacuation drill
* Vermont Yankee Nuclear Power Corp 83/05/26 1p 18674 271
24X Fiche 50-271, 83/05/26, 8306010435

8306020174 Forwards response to 820912 commitment to perform feedwater nozzle integrity evaluation during 1983 outage Post-outage results of NDT exams per NRC 830126 request & affidavit for withholding proprietary info (ref 10CFR2 /90) also encl
SINGLAIR, J B Vermont Yankee Nuclear Power Corp 83/05/26
VASSALLO, D B Operating Reactors Branch 2 3pp 18695 031 24X Fiche 50-271, 83/05/26, 8306020174

--8306020178 "Insp Program Summary"
* Nuclear Energy Service, Inc 83/05/26 6pp 18695 054 24X Fiche 50-271, 83/05/26, 8306020174

--8306020184 Rev 1 to Procedure 80A7616, "Ultrasonic Exam Procedure for Reactor Vessel Feedwater Nozzle Inner Radius"
ALLING, M E Nuclear Energy Service, Inc 83/01/28 33pp 18695 060 24X Fiche 50-271, 83/05/26, 8306020174

- 8306130495 Forwards synopsis of resolutions to open items re control of heavy loads at nuclear power plants, per NUREG-0612 guidelines Draft final technical evaluation rept & request for addl info encl
VASSALLO, D B Operating Reactors Branch 2 83/05/26 SINCLAIR, J B Vermont Yankee Nuclear Power Corp 13pp 18830 107 24X
Fiche 50-271, 83/05/26, 8306130495
- 8306030112 Provides updated list of qualified electrical equipment important to safety per 830411 request List includes equipment scheduled to be qualified or replaced Diagrams of locations of control equipment encl
SINCLAIR, J B Vermont Yankee Nuclear Power Corp 83/05/31 EISENHUT, D G Division of Licensing 6pp 18704 352 24X
Fiche 50-271, 83/05/31, 8306030112
- 8306070303 Responds to 801001 ltr re mods to scram discharge sys Scram discharge voils, new instrument voils, instrumentations & associated piping & valves installed seismically Operation justified during mods
HEIDER, L H Vermont Yankee Nuclear Power Corp 83/06/06 VASSALLO, D B Operating Reactors Branch 2 2pp 18795 177 24X
Fiche 50-271, 83/06/06, 8306070303
- 8306140285 Forwards justification for continued operation re 830411 request for addl info concerning environ qualification of safety-related electrical equipment Similarity of isolation valves in containment sys verified by Target Rock
SINCLAIR, J B Vermont Yankee Nuclear Power Corp 83/06/09 EISENHUT, D G Division of Licensing 7pp 18832 227 24X
Fiche 50-271, 83/06/09, 8306140285
- 8306150161 Requests extension of implementation date for torus mods to 90 days following startup from current refueling outage All internal mods & all torus-related mods complete Extension applies only to torus-attached piping
HEIDER, L H Vermont Yankee Nuclear Power Corp 83/06/13 EISENHUT, D G Division of Licensing 2pp 18846 317 24X
Fiche 50-271, 83/06/13, 8306150161
- 8306220044 Forwards response to 830414 request for addl info re Mark 1 containment long-term program
SINCLAIR, J B Vermont Yankee Nuclear Power Corp 83/06/17 VASSALLO, D B Operating Reactors Branch 2 1p 18932 243 24X
Fiche 50-271, 83/06/17, 8306220044
- 8306220053 Procedure 5960-3 "Responses to NRC Request for Info, Mark 1 Torus Program Plant Unique Rept"
* Teledyne Engineering Services 83/06/10 31pp 18932 244, 24X Fiche 50-271, 83/06/17, 8306220044
- 8306240170 Forwards list of proposed amends submitted prior to 830506 effective date of Interim final Rule 40FRJ4864, per Generic Ltr 83-19 Copies of amend proposals to be prenotified & provided to designated state official
SINCLAIR, J B Vermont Yankee Nuclear Power Corp 83/06/17 VASSALLO, D B Operating Reactors Branch 2 3pp 18981 036 24X
Fiche 50-271, 83/06/17, 8306240170
- Q Inspection reports, IE Bulletins & correspondence
- 8306010301 Forwards IE Insp Rept 50-271/83-12 on 830503-04 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/05/17 MURPHY, W P Vermont Yankee Nuclear Power Corp. 2pp 18672 303 24X Fiche 50-271, 83/05/17, 8306010301
- 8306010304 IE Insp Rept 50-271/83-12 on 830503-04 No noncompliance noted Major areas inspected public prompt notification sys
COHEN, I, GORDON, C., CROCKER, H W Region 1, Office of Director 83/05/16 5pp 18672 305 24X Fiche 50-271, 83/05/17, 8306010301
- 8306070344 Forwards IE Insp Rept 50-271/83-01 on 830104-31 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs. 83/05/24 MURPHY, W P Vermont Yankee Nuclear Power Corp. 2pp 18742 037 24X Fiche 50-271, 83/05/24, 8306070344
- 8306070346 Notice of violation from insp on 830104-31
* Region 1, Office of Director. 83/05/24 2pp. 18742 039 24X Fiche 50-271, 83/05/24, 8306070344
- 8306070353 IE Insp Rept 50-271/83-01 on 830104-0131 Noncompliance noted Failure to follow health physics survey procedure & failure to maintain valve lineups per approved procedures
RAYMOND, W J, WIGGINS, J T, GALLOR, R M Region 1, Office of Director 83/05/19 24pp 18742 041 24X Fiche 50-271, 83/05/24, 8306070344
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 115pp 18732 095 24X Fiche 50-000, 83/05/26, 8305110460
- 8306020174 Forwards response to 820912 commitment to perform feedwater nozzle integrity evaluation during 1983 outage Post-outage results of NDT exams per NRC 830126 request & affidavit for withholding proprietary info (ref 10CFR2 790) also encl.
SINCLAIR, J B Vermont Yankee Nuclear Power Corp. 83/05/26 VASSALLO, D B Operating Reactors Branch 2 3pp 18695 051 24X
Fiche 50-271, 83/05/26, 8306020174
- 8306020178 "Insp Program Summary"
* Nuclear Energy Service, Inc 83/05/26 6pp 18695 054 24X
Fiche 50-271, 83/05/26, 8306020174,
- 8306070358 Forwards IE Insp Rept 50-271/83-13 on 830502-05 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 83/05/26 MURPHY, W P Vermont Yankee Nuclear Power Corp. 2pp 18795 027, 24X Fiche 50-271, 83/05/26, 8306070358
- 8306070360 Notice of violation from insp on 830502-05
* Region 1, Office of Director 83/05/26 1p 18795 029 24X
Fiche 50-271, 83/05/26, 8306070358
- 8306070366 IE Insp Rept 50-271/83-13 on 830502-05 Noncompliance noted failure to follow established documentation & review procedure for implementation of engineering design change to cables C1845HRA2 & C1844CRB1
WIGGINS, J T, GALLOR, R M Region 1, Office of Director 83/05/20, 6pp 18795 030 24X Fiche 50-271, 83/05/26, 8306070358
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461.
- 8306160003 Forwards IE Insp Rept 50-271/83-02 on 830201-0411 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs. 83/06/01. MURPHY, W P Vermont Yankee Nuclear Power Corp. 2pp. 18861 325, 24X Fiche 50-271, 83/06/01, 8306160003.
- 8306160005 Notice of violation from insp on 830201-0411
* Region 1, Office of Director 83/06/01 1p 18861 327 24X
Fiche 50-271, 83/06/01, 8306160003
- 8306160006 IE Insp Rept 50-271/83-02 on 830201-0411 Noncompliance noted failure to post contaminated area & to control work in contaminated area
RAYMOND, W J, COLLINS, S J, EICHENHOLZ, H Region 1, Office of Director 83/05/20 28pp. 18861 328 24X Fiche 50-271, 83/06/01, 8306160003
- 8306080076 Forwards response to IE Bulletin 83-02 re use of ultrasonic exam techniques for service insp program to assure integrity of recirculation sys piping for continued operation. Criteria selected & insp results encl
MURPHY, W P Vermont Yankee Nuclear Power Corp 83/06/03 VASSALLO, D B Operating Reactors Branch 2 174pp 18773 268 24X
Fiche 50-271, 83/06/03, 8306080076
- 8306200174 Forwards IE Insp Rept 50-271/83-09 on 830412-0502 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs. 83/06/06 MURPHY, W P Vermont Yankee Nuclear Power Corp 2pp. 18903 126, 24X Fiche 50-271, 83/06/06, 8306200174
- 8306200177 Notice of violation from insp on 830412-0502
* Region 1, Office of Director 83/06/06 1p 18903 128 24X
Fiche 50-271, 83/06/06, 8306200174
- 8306200181 IE Insp Rept 50-271/83-09 on 830412-0502 Noncompliance noted. Installation & Test Procedure SPN-70115-770 re torus internal mods not followed for gusset plates.
RAYMOND, W J, HOLDEN, C F, GALLOR, R M Region 1, Office of Director 83/06/03, 14pp 18903 129 24X Fiche 50-271, 83/06/06, 8306200174

DOCKETED ITEMS

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc 119pp 18930 280 24X Fiche 50-000,83/06/09,8305110464

8306140489 Forwards updated into re results of post-overlay weld joint insp. in response to IE Bulletin 83-02, "Stress Corrosion Cracking in Large Diameter, Stainless Steel Recirculation Sys Piping at BWR Plants."
MURPHY, W. P. Vermont Yankee Nuclear Power Corp. 83/06/09
VASSALLO, D. B. Operating Reactors Branch 2 3pp 18843 074 24X Fiche 50-271, 83/06/09, 8306140489

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 118pp 18920 225 24X Fiche 50-000,83/06/13,8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 243pp 18921 001 24X Fiche 50-000,83/06/13,8306090010

8306280472 Forwards IE Insp Rept 50-271/83-11 on 830503-06 No noncompliance noted
MARTIN, T. T. Division of Engineering & Technical Programs 83/06/13
MURPHY, W. P. Vermont Yankee Nuclear Power Corp. 2pp. 19018 315 24X Fiche 50-271,83/06/13,8306280472

--8306280474 IE Insp Rept 50-271/83-11 on 830503-06. No noncompliance noted. Major areas inspected, licensee radiation protection program, personnel training & internal & external exposure control.
MCBRIDE, M. H., SJANDAKY, M. Region I, Office of Director 83/06/08 6pp 19018 317 24X Fiche 50-271,83/06/13,8306280472

8306200388 Responds to IE Bulletin 83-02 re commitment to implement revised leakage monitoring provisions Insp &/or mod of recirculation & other RCPB piping sys for next refueling outage planned
MURPHY, W. P. Vermont Yankee Nuclear Power Corp. 83/06/15
VASSALLO, D. B. Operating Reactors Branch 2 3pp 18899 034. 24X Fiche 50-271,83/06/15,8306200388

8306210223 Responds to notice of violation & proposed imposition of civil penalty from IE Insp Rept 50-271/83-04. Corrective actions movement of fuel within spent fuel pool terminated & automatic features of standby gas treatment sys restored
MURPHY, W. P. Vermont Yankee Nuclear Power Corp. 83/06/16
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 6pp 18916 035 24X Fiche 50-271,83/06/16,8306210223

8306210118 Responds to NRC 830510 ltr re proposed civil penalty & IE Insp Rept 50-271/83-04. Amount of penalty should be reduced due to shorter length of time secondary containment was compromised & prompt corrective action
MURPHY, W. P. Vermont Yankee Nuclear Power Corp. 83/06/17
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 3pp. 18918 114. 24X Fiche. 50-271,83/06/17,8306210118

8306230075 Confirmatory Action Ltr 83-04 re error in spacing table for thermal & dead weight stresses w/ANSI B31.1 for installation of piping supports in svc water sys. Safety analysis to be performed & documented.
STAROSTECKI, R. Division of Project & Resident Programs 83/06/17
MURPHY, W. P. Vermont Yankee Nuclear Power Corp. 2pp 18947, 173 24X Fiche. 50-271,83/06/17,8306230075

8306280164 Forwards BALP rept on 830613 for assessment period May 1982 - Apr 1983 Meeting scheduled for 830628 to discuss assessment
STAROSTECKI, R. Division of Project & Resident Programs. 83/06/21
MURPHY, W. P. Vermont Yankee Nuclear Power Corp. 2pp. 19014 278. 24X Fiche: 50-271,83/06/21,8306280164.

--8306280166 BALP rept on 830613
a Region I, Office of Director, 83/06/13. 34pp. 19014 280. 24X Fiche: 50-271, 83/06/21, 8306280166.

8306280170 Ack receipt of 830414 ltr responding to human factors review forwarded in NRC 830211 ltr. Agrees that level of technical training provided to nuclear safety engineer did not affect responses to 830424 loss of feedwater transient.
STAROSTECKI, R. Division of Project & Resident Programs 83/06/21.
MURPHY, W. P. Vermont Yankee Nuclear Power Corp. 2pp 19014 355. 24X Fiche: 50-271,83/06/21,8306280170

--8306280173 Responds to NRC 830211 ltr forwarding human factors review evaluating shift technical advisor/control room design Lists salient features of program to enhance & redefine existing program
MURPHY, W. P. Vermont Yankee Nuclear Power Corp. 83/04/14
STAROSTECKI, R. Division of Project & Resident Programs 2pp 19014 357 24X Fiche 50-271,83/06/21,8306280170

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy GROUTS & Sealers " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 115pp 19021 179 24X Fiche 50-000,83/06/22,8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 120pp 18997 007 24X Fiche 50-000,83/06/22,8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co. of New York, Inc 116pp 18996 242 24X Fiche 50-000,83/06/23,8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc 116pp 19046 297 24X Fiche 50-000,83/06/24,8305110483

R Periodic operating reports & related correspondence

8306170068 Monthly Operating Rept 83-05 for May 1983 W/830609 ltr
BURGER, F. J., MURPHY, W. P. Vermont Yankee Nuclear Power Corp. 83/06/09 Office of Resource Management, Director 7pp 18882 203 24X Fiche: 50-271,83/06/09,8306170068

S Reportable occurrences, LERs & related correspondence

8306170264 LER 83-013/03L-O on 830413, while reactor shutdown, weekly environ air sample for 830405-12 at Station AT1 3 not obtained. Caused by technician failure to test for sys vacuum Technician reinstructed in procedure W/830513 ltr
PELLETIER, J. P. Vermont Yankee Nuclear Power Corp. 83/05/13
ALLAN, J. M. Region I, Office of Director 2pp 18878 161. 24X Fiche 50-271,83/05/13,8306170264

8306140154 PNO-I-83-054, on 830604, ECCS actuation signal caused HPCI & RCIC sys to activate, but sys failed due to lack of steam (reactor temp at 185 F) Open RCIC & HPCI lines created depressurization
HOLDEN, GALLO, KEIMIO Region I, Office of Director 83/06/06. 2pp 18839 029 24X Fiche 50-271,83/06/06,8306140154.

8306170039 LER 83-014/03L-O on 830510, discovered surveillance frequency for svc water process monitor exceeded Tech Specs Caused by schedule error Analysis immediately performed Applicable personnel reinstructed W/830607 ltr
PELLETIER, J. P. Vermont Yankee Nuclear Power Corp. 83/06/07
MURLEY, T. E. Region I, Office of Director 2pp 18882 225. 24X Fiche. 50-271,83/06/07,8306170039

8306140476 PNO-I-83-058: on 830608, Yankee Atomic Electric Corp notified licensee of two support problems w/ECCS suction piping attached to torus & svc water piping for cooling water to uninterruptible power supplies
HOLDEN, KISTER Region I, Office of Director 83/06/09 1p 18834 335 24X Fiche: 50-271,83/06/09,8306140476

8306170332 PNO-I-83-061: on 830615, while conducting mod to reactor water level sensing lines, false low reactor water & low-low reactor water level signals generated, initiating ECCS & starting emergency diesel generators
GALLO, KISTER Region I, Office of Director 83/06/15. 1p 18880 362 24X Fiche. 50-271,83/06/15,8306170332.

V Operator Examinations

8306140032 Requests attendance at 830627 meeting w/Region I in King of Prussia, PA to discuss transfer of reactor operator licensing function from Bethesda, MD to Region I of STAROSTECKI, R. Division of Project & Resident Programs. 83/06/09.
MURPHY, W. P. Vermont Yankee Nuclear Power Corp. 2pp 18838 333 24X Fiche. 50-271,83/06/09,8306140032.

DOCKET 50-272 SALEM NUCLEAR GENERATING STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8306070150 Forwards Submittal 3 to security training & qualification plan Submittal withheld (ref 10CFR73.21)
LIDEN, E A Public Service Electric & Gas Co. of New Jersey
83/05/02 Region 1, Office of Director 2pp 18736 291 24X
Fiche 50-272, 83/05/02, 8306070150

8306070164 Requests that revocation of Chapter 9 be taken into account during review of Rev 8 to security plan & that approval of plan not be delayed by review of Chapter 9 Notice withdrawing Chapter 9 & Procedure SP7 encl
LIDEN, E A Public Service Electric & Gas Co. of New Jersey
83/05/12 Region 1, Office of Director 3pp 18736 281 24X
Fiche 50-272, 83/05/12, 8306070164

8306020232 Forwards Rev 0 to Salem Generating Station Emergency Operating Procedures Generation Package, per Suppl 1 to NUREG-0737 (Generic Ltr 82-33)
LIDEN, E A Public Service Electric & Gas Co. of New Jersey
83/05/20 VARQA, B A Operating Reactors Branch 1 1p 18689 001 24X
Fiche 50-272, 83/05/20, 8306020232

--8306020240 Rev 0 to "Salem Generating Station Emergency Operating Procedures Generation Package"
GUELLER, J. FRY, L., BERKLEY, J. Public Service Electric & Gas Co. of New Jersey 83/04/20 16pp 18689 002 24X
Fiche 50-272, 83/05/20, 8306020232

8306170481 Forwards safety evaluation of util submittals re fire protection rule, incorporating BNL technical input facilities in compliance w/App R to 10CFR50. Items III G & III L re safe shutdown in relay cable spreading or control room
VARQA, B A Operating Reactors Branch 1 83/05/31 UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey 2pp 18894 307 24X
Fiche 50-272, 83/05/31, 8306170481

--8306170483 Safety evaluation of util compliance w/App R to 10CFR50. Items III G & III L Facility design provides train of sys necessary to achieve & maintain safe shutdown conditions
* Office of Nuclear Reactor Regulation, Director 83/05/31 8pp 18894 309 24X
Fiche 50-272, 83/05/31, 8306170481

8306090049 Forwards Rev 8 Amend 1 to security plan Rev withheld (ref 10CFR73.21)
LIDEN, E A Public Service Electric & Gas Co. of New Jersey
83/06/03 Region 1, Office of Director 2pp 18793 311 24X
Fiche 50-272, 83/06/03, 8306090049

8306230471 Forwards IE Safeguards Insp Repts 50-272/83-17 & 50-311/83-14 on 830516-20 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/06/08 UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey 2pp 18941 302 24X
Fiche 50-272, 83/06/08, 8306230471

--8306230475 IE Safeguards Insp Repts 50-272/83-17 & 50-311/83-14 on 830516-20 No noncompliance noted Major areas inspected security plan, contingency plan & previously identified items
SMITH, G C., GODY, A T Region 1, Office of Director, 83/06/06 3pp 18941 304 24X
Fiche 50-272, 83/06/08, 8306230471

H General correspondence

8306140043 Requests JM Zupko & A Nassman be added to svc list for all correspondence re facilities HJ Midura should be deleted
LIDEN, E A Public Service Electric & Gas Co. of New Jersey
83/06/06 VARQA, B A Operating Reactors Branch 1 1p 18838 319 24X
Fiche 50-272, 83/06/06, 8306140043

8306140604 Comments on recent near melt-down at facility NRC should begin to enforce regulations as required by law & shut down obviously accident-prone plants
BATY, D. Affiliation Unknown 83/06/08 NRC - No Detailed Affiliation Given 2pp 18833 060 24X
Fiche 50-272, 83/06/08, 8306140604

P Operating license stage documents & correspondence

8306020562 Clarifies 830219 & 21 environ qualification BERs Upon completion of plant-specific review of all plants, cross-ref of nonqualified equipment will be conducted to determine if same equipment in other plants determined qualified
VARQA, B A Operating Reactors Branch 1 83/05/23 UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey 3pp 18715 120 24X
Fiche 50-272, 83/05/23, 8306020562

8306030141 Submits long-term operational verification program for Westinghouse DB-30 reactor trip breakers Data will be used to assess reliability of undervoltage trip attachments
Results of program expected in Oct 1983
UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey
83/05/31 EISENHUT, D O Division of Licensing 8pp 18704 283 24X
Fiche 50-272, 83/05/31, 8306030141

8306150064 COPPER IN THE INTAKE AND DISCHARGE ZONES OF THE SURRY AND SALEM NUCLEAR POWER STATIONS
HARRISON, F. L., BISHOP, D. J., RICE, D. W. Lawrence Livermore Laboratory
FIN A-0119 NUREG/CR-2965 83/05/31 Division of Health, Safety & Waste Management 3pp Available at NRC \$4.00 18869 221 24X
Fiche 50-000, 83/05/31, 8306150064

8306220198 Forwards Vol 5, Number 4 to NUREG-0090, "Rept to Congress on ADS" for Fourth Quarter CY82 One AD reported at NRC licensees re inoperability of containment spray sys Agreement states reported no ADS
AHEARNE, J. F. Commissioners 83/06/02 O'NEILL, T. P. House of Rep
BUSH, G. H. W. Senate 2pp 18940 024 24X
Fiche 50-000, 83/06/02, 8306220198

8306140059 Forwards "Analysis of Valve/Operator Interface Hardware for Containment Pressure & Vacuum Relief Valves 1 & 2 VC 5," in response to NRC 830517 request
LIDEN, E A Public Service Electric & Gas Co. of New Jersey, 83/06/07, VARQA, B A Operating Reactors Branch 1 3pp 18838 267 24X
Fiche 50-272, 83/06/07, 8306140059

--8306140063 "Analysis of Valve/Operator Interface Hardware for Containment Pressure & Vacuum Relief Valves 1 & 2 VC 5"
FOLEY, J. M., WOOD, J. C., KRAMER, E. H. Public Service Electric & Gas Co. of New Jersey 83/06/03 16pp 18838 270 24X
Fiche 50-272, 83/06/07, 8306140059

8306160438 Forwards RA Uderitz affidavit per 830607 response to NRC 830519 ltr re valve operability reviews for 10-inch pressure/vacuum relief valves used for purge or vent of containments
LIDEN, E A Public Service Electric & Gas Co. of New Jersey
83/06/08 VARQA, B A Operating Reactors Branch 1 2pp 18860 074 24X
Fiche 50-272, 83/06/08, 8306160438

8306270299 Application for amend to Licenses DPR-70 & DPR-75, revising Amend Requests 79-01 & 81-19 re radiological effluent & administrative controls & Tech Specs re surveillance testing & reporting requirements for reactor trip breakers
LIDEN, E A Public Service Electric & Gas Co. of New Jersey, 83/06/17, VARQA, B A Operating Reactors Branch 1 3pp 18994 278 24X
Fiche 50-272, 83/06/17, 8306270299

--8306270304 Proposed Tech Specs revising radiological effluent & administrative controls & surveillance testing & reporting requirements for reactor trip breakers
* Public Service Electric & Gas Co. of New Jersey, 83/06/17 249pp 18994 281 24X
Fiche 50-272, 83/06/17, 8306270299

8306290313 Responds to 830523 clarification of BERs re environ qualification of safety-related electrical equipment requesting review of equipment in Categories IV, I, B & II, A
LIDEN, E A Public Service Electric & Gas Co. of New Jersey
83/06/21 VARQA, B A Operating Reactors Branch 1 3pp 19055 313 24X
Fiche 50-272, 83/06/21, 8306290313

8306300190 Forwards Offsite Dose Calculation Manual per NRC 790118 ltr
LIDEN, E A. Public Service Electric & Gas Co. of New Jersey
83/06/24 VARQA, B A Operating Reactors Branch 1, 1p 19122 199 24X
Fiche 50-272, 83/06/24, 8306300190

--8306300194 Offsite Dose Calculation Manual
* Public Service Electric & Gas Co. of New Jersey 83/03/31, 75pp, 19122 200 24X
Fiche 50-272, 83/06/24, 8306300190

Q Inspection reports, IE Bulletins & correspondence

8306240046 Discusses IE insp on 830302-06 & forwards notice of violation & proposed imposition of civil penalty.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement, 83/05/05 SMITH, R. Public Service Electric & Gas Co. of New Jersey 4pp 18987 217 24X
Fiche 50-272, 83/05/05, 8306240046

--8306240049 Notice of violation & proposed imposition of civil penalty in amount of \$850,000 Noncompliance noted reactor trip breaker failed to automatically open following receipt of valid trip signal.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/05/05 8pp 18987 221 24X
Fiche 50-272, 83/05/05, 8306240046

DOCKETED ITEMS

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device." Svc list encl
TAYLOR, J.M. Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 115pp 18732 005 24X Fiche 50-000, 83/05/26, 8305110460.

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc. 116pp 18732 208, 24X Fiche 50-000, 83/05/31, 8305110461

8306140256 Act receipt of 830317 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/82-36 & 50-311/82-33
STAROSTECKI, R. Division of Project & Resident Programs 83/05/31 UDERITZ, R.A. Public Service Electric & Gas Co. of New Jersey. 1p 18933 019. 24X Fiche: 50-272, 83/05/31, 8306140256

--8306140261 Responds to NRC 830215 ltr re violations noted in IE Insp Repts 50-272/82-36 & 50-311/82-33 Corrective actions Operations Directive 12, Tech Spec Interpretations, expanded to include encl Guide-11 & footnotes added to logs
UDERITZ, R.A. Public Service Electric & Gas Co. of New Jersey. 83/05/31. HAYNES, R.C. Region 1, Office of Director
STAROSTECKI, R. Division of Project & Resident Programs 3pp. 18933-020 24X Fiche 50-272, 83/05/31, 8306140256

8306140130 Forwards IE Insp Repts 50-272/83-12 & 50-311/83-13 on 830326-0510 & notice of violation
STAROSTECKI, R. Division of Project & Resident Programs 83/05/31 UDERITZ, R.A. Public Service Electric & Gas Co. of New Jersey 2pp 18862 005. 24X Fiche 50-272, 83/05/31, 8306140130

--8306140137 Notice of violation from insp on 830326-0510
* Region 1, Office of Director 83/05/31 1p 18862 007 24X Fiche 50-272, 83/05/31, 8306140130

--8306140144 IE Insp Repts 50-272/83-12 & 50-311/83-13 on 830326-0510 Noncompliance noted failure to submit timely LERs
NORRHOLOM, L.J., SUMMERS, R.J., TRIPP, L.E. Region 1, Office of Director, 83/05/27. 17pp 18862:008. 24X Fiche: 50-272, 83/05/31, 8306140130.

8306070177 Requests 30-day extension for response to 830509 notice of violation & proposed imposition of civil penalties delay due to complexity of issues & consideration of available options
UDERITZ, R.A. Public Service Electric & Gas Co. of New Jersey 83/06/01. DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement 2pp 18736.329 24X Fiche 50-272, 83/06/01, 8306070177.

8306140440 Ack receipt of 830415 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/83-01 & 50-311/83-01
MARTIN, T.T. Division of Engineering & Technical Programs 83/06/07 UDERITZ, R.A. Public Service Electric & Gas Co. of New Jersey. 1p 18864-214 24X Fiche. 50-272, 83/06/07, 8306140440

--8306140448 Responds to NRC 830304 ltr requesting addl info re violations noted in IE Insp Repts 50-272/83-01 & 50-311/83-01. Corrective actions: Meter M-137 returned to vendor for repair cost estimate.
UDERITZ, R.A. Public Service Electric & Gas Co. of New Jersey. 83/04/15. MARTIN, T.T. Division of Engineering & Technical Programs. 3pp. 18864 215. 24X Fiche 50-272, 83/06/07, 8306140440

8306210176 Responds to IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators " Affected check valves associated w/each diesel generator listed
LIDEN, E.A. Public Service Electric & Gas Co. of New Jersey 83/06/07 ALLAN, J.M. Region 1, Office of Director 3pp 18915 239. 24X Fiche. 50-272, 83/06/07, 8306210176.

8306230471 Forwards IE Safeguards Insp Repts 50-272/83-17 & 50-311/83-16 on 830516-20. No noncompliance noted.
MARTIN, T.T. Division of Engineering & Technical Programs. 83/06/08. UDERITZ, R.A. Public Service Electric & Gas Co. of New Jersey 2pp 18941-302. 24X Fiche 50-272, 83/06/08, 8306230471.

--8306230475 IE Safeguards Insp Repts 50-272/83-17 & 50-311/83-16 on 830516-20. No noncompliance noted Major areas inspected: security plan; contingency plan & previously identified items.
SMITH, O.C., OODY, A.T. Region 1, Office of Director. 83/06/06. 3pp. 18941-304 24X Fiche: 50-272, 83/06/08, 8306230471.

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 120pp. 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co. of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

R Periodic operating reports & related correspondence

8306150267 Forwards annual radiological rept for 1982, "Artificial Island Radiological Environ Monitoring Program "
LIDEN, E.A. Public Service Electric & Gas Co. of New Jersey 83/06/02 ALLAN, J.M. Region 1, Office of Director 1p 18849 263 24X Fiche 50-272, 83/06/02, 8306150267

--8306150270 "Artificial Island Radiological Environ Monitoring Program," annual radiological rept for 1982
LIDEN, E.A. Public Service Electric & Gas Co. of New Jersey RMC-TR-83-03 83/04/20 134pp 18849 264 24X Fiche: 50-272, 83/06/02, 8306150267

8306280542 "NPDES Discharge Monitoring Repts for May 1983 " W/830606 ltr
MILLER, L.K. Public Service Electric & Gas Co. of New Jersey 83/06/06 21pp 19019 343 24X Fiche. 50-272, 83/06/06, 8306280542

8306200240 "Annual Environ Operating Rept (Nonradiological), 1982 " W/830608 ltr
LIDEN, E.A. Public Service Electric & Gas Co. of New Jersey 83/06/08 ALLAN, J.M., BORER, R.J. Region 1, Office of Director 19pp 18902 127 24X Fiche 50-272, 83/06/08, 8306200240

8306200226 Monthly operating repts for May 1983, W/830610 ltr
MILLER, L.K., ZUPKO, J.M. Public Service Electric & Gas Co. of New Jersey 83/06/10 Director's Office, Office of Inspection and Enforcement 14pp. 18902 308 24X Fiche 50-272, 83/06/10, 8306200226

S. Reportable occurrences, LERs & related correspondence

8306070461 Forwards draft rept, "AEOD Study on Implications of ATWS Events at Salem Nuclear Power Plant on NRC Program for Collection & Analysis of Operational Experience." Review & comments requested by 830610
HELTENES, C.J. Director's Office 83/05/26. DENTON, H.R. Office of Nuclear Reactor Regulation, Director DAVIS, J.G. Office of Nuclear Material Safety & Safeguards, Director MINOQUE, R.B. Office of Nuclear Regulatory Research, Director 106pp 18782:356 24X Fiche 50-272, 83/05/26, 8306070461

DOCKETED ITEMS

79

8306030197 Staff requirements memo informing of Commission 830513 briefing in Washington, DC on NUREG-1000, "Generic Implications of ATWS Events at Salem Nuclear Power Plant" Operating criteria requested
CHILK, S J Office of the Secretary of the Commission 83/05/27
DIRCKS, W J Office of the Executive Director for Operations 1p
18733 313 24X Fiche 50-272, 83/05/27, 8306030197

8306030349 Forwards "Review of PSE&G Corrective Action Program re Reactor Trip Breaker Failures at Salem Generation Station, Unit 1"
UDERTZ, R A Public Service Electric & Gas Co of New Jersey
83/05/31 EISENHUT, D G Division of Licensing 1p 18706 127
24X Fiche 50-272, 83/05/31, 8306030349

--8306030351 "Review of PSE&G Corrective Action Program re Reactor Trip Breaker Failures at Salem Generating Station, Unit 1"
* Basic Energy Technology Associates 83/05/27 31pp
18706 128 24X Fiche 50-272, 83/05/31, 8306030349

8306170144 LER 83-020/03L-0 on 830506, pins found installed in two spring hangers supporting resistance temp device bypass lines Hanger pins removed & tested & procedure developed for lead shielding installation W/830602 ltr
FRAHM, R, ZUPKO, J M Public Service Electric & Gas Co of New Jersey 83/06/01 ALLAN, J Region 1, Office of Director 4pp
18878 351 24X Fiche 50-272, 83/06/01, 8306170144

8306170338 LER 83-022/04L-0 on 830513, estimated 131 uCi of activity released when 350 gallons low level radioactive water pumped into ground Caused by contaminated piping penetration area Control measures implemented W/830607 ltr
FRAHM, R, ZUPKO, J M Public Service Electric & Gas Co of New Jersey 83/06/01 ALLAN, J Region 1, Office of Director 5pp
18880 279 24X Fiche 50-272, 83/06/01, 8306170338

8306170381 LER 83-021/03L-0 on 830507, emergency diesel generator 1A tagged out due to broken differential current relay Caused by personnel accidentally breaking glass relay cover Relay cleaned W/830602 ltr
FRAHM, R, ZUPKO, J M Public Service Electric & Gas Co of New Jersey 83/06/01 ALLAN, J Region 1, Office of Director 4pp
18880 049 24X Fiche 50-272, 83/06/01, 8306170381

8306210189 Supplemental LER 82-035/99X-1 on 820526, fire pump 2 failed to start Caused by damaged fire pump electrical sys voltage regulator/alternator, due to faulty wiring harness Damaged components replaced W/830606 ltr
FRAHM, R, ZUPKO, J M Public Service Electric & Gas Co of New Jersey 83/06/01 ALLAN, J Region 1, Office of Director 4pp
18916 018 24X Fiche 50-272, 83/06/01, 8306210189

8306280488 Supplemental LER 82-083/03X-1 on 821102, control room operator observed temp recorder for air temp-delta T channels not printing Caused by failure of pinion gear on chart drive motor Motor replaced W/830606 ltr
FRAHM, R, ZUPKO, J M Public Service Electric & Gas Co of New Jersey 83/06/01 ALLAN, J Region 1, Office of Director 4pp
19018 298 24X Fiche 50-272, 83/06/01, 8306280488

8306130455 Forwards NRR comments on draft AD rept to Congress for First Quarter 1983
DENTON, H R Office of Nuclear Reactor Regulation, Director
83/06/07 HELTEHES, C J Director's Office 3pp 18830 176 24X
Fiche 50-000, 83/06/07, 8306130455

8306280256 Supplemental LER 82-091/01X-1 on 821130, operator discovered leakage from weld of svc water piping to component cooling HX 12 Caused by extensive biofouling & corrosion of circumferential welds W/830614 ltr
FRAHM, R, ZUPKO, J M Public Service Electric & Gas Co of New Jersey 83/06/08 ALLAN, J Region 1, Office of Director 5pp
19014 106 24X Fiche 50-272, 83/06/08, 8306280256

8306240452 Comments on AEOD study re implications of Salem ATWS events on NRC program for collection & analysis of operational experience, per 830526 request Summary of trip breaker failures at Farley 1 & 2 encl.
DENTON, H R Office of Nuclear Reactor Regulation, Director
83/06/10 HELTEHES, C J Director's Office 6pp 18998 117 24X
Fiche 50-272, 83/06/10, 8306240452

8306270269 LER 83-025/03L-0 on 830525, containment air particulate monitor indicated alarm condition w/o receiving purge/pressure relief isolation function, Caused by channel output alarm relay wire ball out of place, W/830614 ltr.
FRAHM, R, ZUPKO, J M Public Service Electric & Gas Co. of New Jersey 83/06/14, ALLAN, J M Region 1, Office of Director 5pp.
18990 204 24X Fiche 50-272, 83/06/14, 8306270269.

8306270343 LER 83-023/01T-0 on 830602, notification received from Westinghouse re potential increased power peaking in bottom of core Procedures will be implemented to insure operation within Tech Spec limits W/830615 ltr
FRAHM, R, ZUPKO, J M Public Service Electric & Gas Co of New Jersey 83/06/15 ALLAN, J Region 1, Office of Director 4pp
18993 129 24X Fiche 50-272, 83/06/15, 8306270343

U Congressional/Executive Correspondence

8306060388 Responds to 830407 ltr re ATWS events & reactor trip breaker malfunctions Language used in IE bulletins revised to ensure specific & general responses
PALLADINO, N J Commissioners 83/05/16 MARKEY, E J House of Rep, Interior & Insular Affairs 24pp 18732 347 24X
Fiche 50-272, 83/05/16, 8306060388

--8306060392 Requests info re unreported breaker failures, reporting requirements & reliability of 25 cycle pre-startup testing to better understand LER sys.
MARKEY, E J House of Rep, Interior & Insular Affairs 83/04/07.
PALLADINO, N J Commissioners 2pp 18733 018 24X
Fiche 50-272, 83/05/16, 8306060388

8306150533 Responds to 830304 ltr requesting info & responses to questions re 830222 & 25 events Failures of safety sys & broader implications for nuclear power industry discussed
PALLADINO, N J Commissioners 83/06/02 BIDEN, J R Senate 27pp
18866 334 24X Fiche 50-272, 83/06/02, 8306150533

--8306150543 Expresses concern re 830222 & 25 events when manual shutdown of reactor required following failures of automatic safety sys Investigation by NRC requested prior to restart Questions encl for NRC response
BIDEN, J R Senate 83/03/04 PALLADINO, N J Commissioners.
3pp 18867 023 24X Fiche 50-272, 83/06/02, 8306150533

V Operator Examinations

8306140036 Requests NRC concurrence in special requalification training program for JD Driscoll Failure of reactor trip breakers in late Feb & ensuing investigation & corrective action development prevented attendance w/scheduled shift.
LIDEN, E A Public Service Electric & Gas Co of New Jersey 83/06/08 VARQA, S A Operating Reactors Branch 1 2pp. 18838 209.
24X Fiche 50-272, 83/06/08, 8306140036

8306140403 Extends invitation to attend 830627 meeting in King of Prussia, PA to discuss transfer of reactor operator licensing function from Bethesda, MD to Region 1 ofc.
STAROSTECKI, R Division of Project & Resident Programs 83/06/09.
UDERTZ, R A Public Service Electric & Gas Co of New Jersey. 2pp.
18838 001 24X Fiche 50-272, 83/06/09, 8306140403

DOCKET 50-274 U. S. GEOLOGICAL SURVEY RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8306240140 Forwards IE Safeguards Insp Repts 50-274/83-02 & 70-0121/83-02 on 830418-20 No noncompliance noted.
HADSEN, O L Region 4, Office of Director 83/06/20 HILLARD, H Interior, Dept of, Geological Survey 2pp. 18980 162 24X
Fiche 50-274, 83/06/20, 8306240140

--8306240148 IE Safeguards Insp Repts 50-274/83-02 & 70-0121/83-02 on 830418-20, No noncompliance noted Major areas inspected, nuclear matl control & accountability, including facility organization & operations Details withheld (ref 10CFR2 790).
CALDWELL, R A, KELLY, J A F, WEBSTERMAN, T F Region 4, Office of Director 83/06/15 1p 18980 164 24X Fiche 50-274, 83/06/20, 8306240140.

G Inspection reports, IE Bulletins & correspondence

8306240140 Forwards IE Safeguards Insp Repts 50-274/83-02 & 70-0121/83-02 on 830418-20 No noncompliance noted
HADSEN, O L Region 4, Office of Director 83/06/20 HILLARD, H Interior, Dept of, Geological Survey. 2pp 18980 162. 24X
Fiche 50-274, 83/06/20, 8306240140

--8306240148 IE Safeguards Insp Repts 50-274/83-02 & 70-0121/83-02 on 830418-20, No noncompliance noted Major areas inspected: nuclear matl control & accountability, including facility organization & operations Details withheld (ref 10CFR2 790).
CALDWELL, R A, KELLY, J A F, WEBSTERMAN, T F Region 4, Office of Director 83/06/15 1p. 18980 164 24X Fiche 50-274, 83/06/20, 8306240140

DOCKETED ITEMS

DOCKET 50-275 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 1
 F Security, medical, emergency & fire protection plans

8306060155 Notifies that 830418 response to Generic Ltr 82-33 re emergency response capability indicating schedule for implementation of Reg Guide 1.97, Rev 2, would be provided by 830815, superseded 811022 commitment
 SCHUYLER, J O Pacific Gas & Electric Co 83/05/31 KNIGHT, G W
 Licensing Branch 3 2pp 18728 101 24X Fiche 50-275, 83/05/31, 8306060155

8306170196 Ack receipt & provides evaluation of various changes to emergency plan & corporate emergency plan implementing procedures. Changes do not decrease effectiveness of emergency response planning
 NORDERHAUO, L R Region 5, Office of Director 83/06/13 CRANE, P A
 Pacific Gas & Electric Co 2pp 18892 302 24X
 Fiche 50-275, 83/06/13, 8306170196

8306170305 Ack receipt of Dec 1982, Rev 1 to San Luis Obispo County emergency response plan FEMA will provide NRC w/written confirmation of results of evaluations
 NORDERHAUO, L R Region 5, Office of Director 83/06/13 CRANE, P A
 Pacific Gas & Electric Co 1p 18877 145 24X
 Fiche 50-275, 83/06/13, 8306170305

O Adjudicatory correspondence

8305040415 Responds to 830421 ltr requesting that meeting be arranged between NRC & person alleging improprieties in P&E/Bechtel revalidation program. Individual not inclined to meet w/NRC, fearing P&E/Bechtel reprisals
 FLEISCHAKER, D Fleischaker, D 83/04/28 EISENHUT, D O
 Division of Licensing 4pp 18319 327 24X Fiche 50-275, 83/04/28, 8305040415

8306060182 Response supporting Governor Deukmejian 830518 motion to reopen record in licensing proceeding re const GA. Further evidence needed re const GA/QC Certificate of Svc encl.
 REYNOLDS, J R Joint Intervenor-Diablo Canyon REYNOLDS, J R
 Center for Law in the Public Interest 83/05/31 Atomic Safety
 and Licensing Appeal Panel 6pp 18728 186 24X
 Fiche 50-275, 83/05/31, 8306060182

8306060275 Response opposing Joint Intervenor 830510 & Governor Deukmejian 830517 motions to reopen record on const GA. Const GA program vigorous, thorough & in full compliance w/NRC regulations. Certificate of Svc encl.
 NORTON, B Pacific Gas & Electric Co NORTON, B Norton, Burke,
 Berry & French 83/05/31 Atomic Safety and Licensing Appeal
 Panel 430pp 18730 031 24X Fiche 50-275, 83/05/31, 8306060275

8306070406 Response supporting Governor Deukmejian 830518 motion to reopen record on const GA. Disclosure of thousands of deficiencies warrants reopening Certificate of Svc encl.
 REYNOLDS, J R Joint Intervenor-Diablo Canyon 83/05/31 Atomic
 Safety and Licensing Appeal Panel 5pp 18742 275 24X
 Fiche 50-275, 83/05/31, 8306070406

8306150314 Notice of appearance in proceeding Certificate of Svc encl.
 HAVIAN, E Joint Intervenor-Diablo Canyon HAVIAN, E Center for
 Law in the Public Interest 83/06/02 5pp 18849 132 24X
 Fiche 50-275, 83/06/02, 8306150314

8306150230 Response opposing Joint Intervenor 830510 & Governor Deukmejian 830518 motions to reopen record on const GA. Movants fail to establish significance of info to GA findings in ASLB 810717 decision. Certificate of Svc encl.
 CHANDLER, L J Hearing Branch 2 83/06/06 Atomic Safety and
 Licensing Appeal Panel 196pp 18830 044 24X Fiche 50-275, 83/06/06, 8306150230

8306090309 Order allowing Joint Intervenor & Governor Deukmejian to reply to responses to motions to reopen record on const GA by 830620
 SHOEMAKER, C J Atomic Safety and Licensing Appeal Panel 83/06/07,
 Joint Intervenor-Diablo Canyon 2pp 18795 191 24X
 Fiche 50-275, 83/06/07, 8306090309

8306150435 Petition for review of ASLB 830518 Decision ALAB-728, to establish schedule for briefing on issues raised & to reverse ASLB rulings in ALAB-728 Certificate of Svc encl.
 REYNOLDS, J R Joint Intervenor-Diablo Canyon REYNOLDS, J R
 Center for Law in the Public Interest 83/06/08 Commissioners,
 15pp 18847 030 24X Fiche 50-275, 83/06/08, 8306150435

8306160579 First document production request. Related correspondence
 NORTON, B Pacific Gas & Electric Co NORTON, B Norton, Burke,
 Berry & French 83/06/10 Joint Intervenor-Diablo Canyon, 6pp,
 18866 161 24X Fiche 50-275, 83/06/10, 8306160579

--8306160584 First set of interrogatories Related correspondence
 NORTON, B Pacific Gas & Electric Co NORTON, B Norton, Burke,
 Berry & French 83/06/10 California, State of 17pp
 18866 167 24X Fiche 50-275, 83/06/10, 8306160579

--8306160595 First set of interrogatories Certificate of Svc encl Related correspondence
 NORTON, B Pacific Gas & Electric Co NORTON, B Norton, Burke,
 Berry & French 83/06/10 Joint Intervenor-Diablo Canyon
 19pp 18866 184 24X Fiche 50-275, 83/06/10, 8306160579

8306140702 Notice of withdrawal of appearance in proceeding Certificate of Svc encl
 GOLDBERG, J R Hearing Branch 2 83/06/13 3pp 18841 271 24X
 Fiche 50-275, 83/06/13, 8306140702

8306220038 Response opposing util & NRC responses to intervenor motions to reopen issue on const GA. NRC ignored util improper & rampant disregard of GA requirement & obscursion w/hearing speed & scheduling. Certificate of Svc encl
 REYNOLDS, J R Joint Intervenor-Diablo Canyon REYNOLDS, J R
 Center for Law in the Public Interest 83/06/17 Atomic Safety
 and Licensing Appeal Panel 11pp 18930 180 24X
 Fiche 50-275, 83/06/17, 8306220038

8306220045 Reply to response of NRC & util to Governor Deukmejian motion to reopen record on const GA. Submits new evidence of safety regulation violations & contends NRC & util response unacceptable
 KAUFMAN, P H, California, State of 83/06/17 Atomic Safety and
 Licensing Appeal Panel 45pp 18927 259 24X Fiche 50-275, 83/06/17, 8306220045

--8306220052 Affidavit of R Hubbard re breakdowns in design & const GA/QC program & implementation. Util & NRC did not include significant items in const GA review. Implementation of GA/QC measures unacceptable. Certificate of Svc encl
 HUBBARD, R B California, State of 83/06/15 14pp 18927 305
 24X Fiche 50-275, 83/06/17, 8306220045

8306240275 Response opposing Joint Intervenor 830608 petition for review of ALAB-728. No important safety, procedural, common defense, antitrust or public policy issues raised. Certificate of Svc encl
 CHANDLER, L J Hearing Branch 2 83/06/23 Commissioners 14pp
 18980 080 24X Fiche 50-275, 83/06/23, 8306240275

8306280522 Answer opposing Joint Intervenor 830608 petition for review of ALAB-728. Joint Intervenor fails to respond to rationale of ASLB decision. Certificate of Svc encl
 CRANE, P A Pacific Gas & Electric Co 83/06/23 Commissioners,
 7pp 19019 317 24X Fiche 50-275, 83/06/23, 8306280522

8306290535 Advises of concerns re evidence presented at 830614 independent design verification program meeting w/util/Bechtel licensing team. Util fails to appreciate meaning/necessity of program. Related correspondence.
 REYNOLDS, J R Center for Law in the Public Interest REYNOLDS, J R
 Joint Intervenor-Diablo Canyon 83/06/23 DENTON, H R Office of
 Nuclear Reactor Regulation, Director 6pp 19032 318 24X
 Fiche 50-275, 83/06/23, 8306290535

8306280520 Proposes schedule for reopened hearings on design GA
 NORTON, B Pacific Gas & Electric Co 83/06/24 Atomic Safety and
 Licensing Appeal Panel 3pp 19017 106 24X Fiche 50-275, 83/06/24, 8306280520

8306300052 Order scheduling 830719 hearing on Governor Deukmejian & Joint Intervenor motions to reopen record on const GA issue. NRC to provide ASLB & parties w/NRC insps repts on const GA by 830708
 SHOEMAKER, C J Atomic Safety and Licensing Appeal Panel 83/06/28
 Office of the Executive Legal Director 4pp 19120 189 24X
 Fiche 50-275, 83/06/28, 8306300052

8306300064 Requests that arrangements be made for removal & storage of security mats in NRC storage room. Room requires repair & is needed for other purposes
 CHANDLER, L J Hearing Branch 2 83/06/29 BTRUMWASSER, M,
 California, State of 1p 19121 011 24X Fiche 50-275, 83/06/29, 8306300064

H General correspondence

8306010336 Expresses alarm re recent news rept that P&E officials had seen preliminary drafts of NRC investigation rept concerning GA violations. NRC investigation requested.
 REYNOLDS, J R Joint Intervenor-Diablo Canyon REYNOLDS, J R
 Center for Law in the Public Interest 83/05/25 EISENHUT, D O,
 Division of Licensing 4pp 18680 072 24X Fiche 50-275, 83/05/25, 8306010336

DOCKETED ITEMS

81

B306070036 Provides names & addresses for appropriate distribution of technical correspondence re facilities
SCHUYLER, J. O. Pacific Gas & Electric Co. 83/06/02 DENTON, H. R. Office of Nuclear Reactor Regulation, Director EISENHUT, D. O. Division of Licensing MARTIN, J. B. Region 5, Office of Director 2pp 18739 337 24X Fiche 50-000, 83/06/02, B306070036

P Operating license stage documents & correspondence

B306020619 Notification of B30520 meeting w/util & Westinghouse in Monroeville, PA to discuss seismic qualification of main control board
SCHIERLING, H. Licensing Branch 3 83/05/18 KNIGHTON, O. W. Licensing Branch 3 4pp 18702 359 24X Fiche 50-275, 83/05/18, B306020619

B305110468 Board Notification 83-76 forwards info items for design verification program, including verification of effects of high energy line cracks & semimonthly status rept w/o encl
EISENHUT, D. O. Division of Licensing 83/05/27 PALLADINO, N. J., GILINSKY, V., AHEARNE, J. F. Commissioners 3pp 24X Fiche 50-275, 83/05/27, B305110468

B306070270 Forwards application for amend to License DPR-76 changing level of reporting of manager & QA to executive vice president of facilities & electric resources development
SCHUYLER, J. O. Pacific Gas & Electric Co. 83/05/27 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 1p 18740 296 24X Fiche 50-275, 83/05/27, B306070270

--B306070275 Application for amend to License DPR-76 changing level of reporting of manager & QA to executive vice president of facilities & electric resources development
SCHUYLER, J. O. Pacific Gas & Electric Co. 83/05/27 2pp 18740 297 24X Fiche 50-275, 83/05/27, B306070275

--B306070278 Proposed Tech Specs changing reporting level of manager & QA to executive vice president of facilities & electric resources development
* Pacific Gas & Electric Co. 83/05/27 2pp 18740 297 24X Fiche 50-275, 83/05/27, B306070278

B306030162 Forwards response to Generic ltr 83-10C re plans & schedules for resolution of TMI Action Item 11 K 3 B, "Automatic Trip of Reactor Coolant Pumps." Util not required to submit analyses supporting selection of pump trip criteria
SCHUYLER, J. O. Pacific Gas & Electric Co. 83/05/31 EISENHUT, D. O. Division of Licensing 7pp 18703 344 24X Fiche 50-275, 83/05/31, B306030162

B306070463 Forwards design verification program status summary as of B30506 Engineering effort & mod const required to be completed prior to fuel load
DIRCKS, W. J. Office of the Executive Director for Operations 83/05/31 PALLADINO, N. J., GILINSKY, V., AHEARNE, J. F. Commissioners 12pp 18780 318 24X Fiche 50-275, 83/05/31, B306070463

B306240473 Summary of B30520 meeting w/Westinghouse & util in Monroeville, PA re seismic qualification of main control board
SCHIERLING, H. Licensing Branch 3 83/05/31 KNIGHTON, O. W. Licensing Branch 3 4pp 18997 357 24X Fiche 50-275, 83/05/31, B306240473

B306080068 Describes independent design verification program position on seismic reevaluation of turbine bldg & intake structure
Corrective action reviewed from standpoint of both licensing & technical considerations
WRAY, R. Teledyne Engineering Services, 83/06/03 DENTON, H. R. Office of Nuclear Reactor Regulation, Director MARTIN, J. B. Region 5, Office of Director MANEATIS, G. A. Pacific Gas & Electric Co. 2pp 18773 191 24X Fiche 50-275, 83/06/03, B306080068

B306080199 Board Notification BN-83-77 forwards JR Reynolds B30525 & DQ Eisenhut B30603 ltrs addressing allegation re prerelease of NRC rept on alleged deficiencies in QA program implementation at Facility
EISENHUT, D. O. Division of Licensing, 83/06/03 PALLADINO, N. J., GILINSKY, V., AHEARNE, J. F. Commissioners, 7pp. 18772 223 24X Fiche 50-275, 83/06/03, B306080199

--B306080201 Ack receipt of B30525 ltr re potential prerelease of NRC rept, Ofc of Inspector & Auditor requested to investigate matter Commission & ASLAB will be informed
EISENHUT, D. O. Division of Licensing, 83/06/03, REYNOLDS, J. R. Center for Law in the Public Interest 2pp 18772 231 24X Fiche, 50-275, 83/06/03, B306080199

B306240474 Ack receipt of B30525 ltr re potential prerelease of NRC rept re independence of design verification program Ofc of Inspector & Auditor requested to investigate Commission & ASLAB being informed via board notification
EISENHUT, D. O. Division of Licensing 83/06/03 REYNOLDS, J. R. Center for Law in the Public Interest 4pp. 18778 071 24X Fiche 50-275, 83/06/03, B306240474

B306240464 Forwards request for addl info needed to complete review of safety-related masonry walls & necessary corrective actions based on review of B10701 submittal info requested within 60 days of ltr receipt
KNIGHTON, O. W. Licensing Branch 3 83/06/07, CRANE, P. Pacific Gas & Electric Co. 5pp 18998 103 24X Fiche 50-275, 83/06/07, B306240464

B306140031 Forwards background for two articles published in Telegram-Tribune re welding deficiencies info confirms misunderstanding between util & reporter At no time did util review NRC drafts of subj rept
SCHUYLER, J. O. Pacific Gas & Electric Co. 83/06/07 EISENHUT, D. O. Division of Licensing 2pp 18838 331 24X Fiche 50-275, 83/06/07, B306140031

B306280451 Forwards ltr from project info specialist giving background for two articles in San Luis Obispo Telegram-Tribune No one from util reviewed any NRC draft repts
SCHUYLER, J. O. Pacific Gas & Electric Co. 83/06/07, EISENHUT, D. O. Division of Licensing 2pp 19018 295 24X Fiche 50-275, 83/06/07, B306280451

B305110471 Board Notification 83-78 forwards matls re independent design verification program by participating organizations info relevant to safety issue on design adequacy of plant
EISENHUT, D. O. Division of Licensing 83/06/10 PALLADINO, N. J., GILINSKY, V., AHEARNE, J. F. Commissioners 3pp 18847 313 24X Fiche 50-275, 83/06/10, B305110471

--B305230345 Trip rept of B30406-07 visit to site & Bechtel ofc in San Francisco, CA re insp of technical calculations supporting Diablo Canyon project internal technical program
POLK, H. Structural & Geotechnical Engineering Branch, 83/05/13, LEAR, O. Structural & Geotechnical Engineering Branch, 5pp 18848 023 24X Fiche 50-275, 83/06/10, B305110471

--B305230135 Trip rept of B30329-30 site meetings w/independent design verification program personnel & licensee re progress on analysis of turbine bldg & containment annulus steel structure & auxiliary/fuel handling bldg
POLK, H. C. Structural & Geotechnical Engineering Branch 83/05/16, LEAR, O. Structural & Geotechnical Engineering Branch, 5pp. 18848 030 24X Fiche 50-275, 83/06/10, B305110471

--B306150276 Transcript of B30520 meeting in Monroeville, PA re seismic qualification of panel on main control board. Pp 1-125 Supporting documentation encl
* Commissioners 83/05/20 182pp. 18848 052 24X Fiche 50-275, 83/06/10, B305110471

--B306150281 Transcript of NRC independent design verification program B30521 meeting in Boston, MA Pp 1-90
* Commissioners 83/05/21, 92pp 18848 234, 24X Fiche 50-275, 83/06/10, B305110471

B306210111 Comments on util 790914 & 1828 submittals re moderate energy line breaks, info responds to NRC request to evaluate plant design for effects of line breaks on equipment required for safe shutdown Shield barrier requirements eliminated.
SCHUYLER, J. O. Pacific Gas & Electric Co. 83/06/15 KNIGHTON, O. W. Licensing Branch 3 1p 18914 178 24X Fiche 50-275, 83/06/15, B306210111

B305110481 Board Notification 83-81: forwards B30609 ltr from JO Schuyler providing info on allegation that util received preliminary NRC rept prior to official release
EISENHUT, D. O. Division of Licensing 83/06/17, PALLADINO, N. J., GILINSKY, V., AHEARNE, J. F. Commissioners, 2pp 18926 034, 24X Fiche, 50-275, 83/06/17, B305110481

B306170313 Advises of B30614 meeting w/util & consultants in San Francisco, CA to discuss status of Phase I engineering open item & Phase I programs
COOPER, W. E., CRAQIN, J. G., Teledyne Engineering Services, 83/06/17, DENTON, H. R., MARTIN, J. B. NRC - No Detailed Affiliation Given, MANEATIS, G. A. Affiliation Unknown 1p. 18877 068 24X Fiche, 50-275, 83/06/17, B306170313

B306170328 Announces B30615 meeting w/NRC in San Francisco, CA to discuss auxiliary bldg structures & polar crane/rail efforts as part of independent design verification program.
COOPER, W. E., CRAQIN, J. G., Teledyne Engineering Services, 83/06/17 DENTON, H. R., MARTIN, J. B., SCHIERLING, H. E. NRC - No Detailed Affiliation Given, 1p. 18878 251, 24X Fiche, 50-275, 83/06/17, B306170328

DOCKETED ITEMS

8305110487 Board Notification 83-080 Forwards ltrs & repts re status of activities performed as part of design verification efforts Encls include M Reich 830517 ltr, TW Bishop 830519 ltr & "Semi-monthly Status Rpt for May 1983" w/o encl. EISENHUT, D O Division of Licensing 83/06/20 PALLADINO, N J, QILINSKY, V., AHEARNE, J F Commissioners 3pp 18993:038 24X Fiche 50-275, 83/06/20, 8305110489

8306280332 Forwards revised schedule for completion of activities required for fuel loading, low power testing & full power operation Target schedule for licensing milestones encl Const will be completed by 830902 w/fuel loaded by 830930 SCHUYLER, J O, Pacific Gas & Electric Co. 83/06/23 EISENHUT, D O, Division of Licensing 3pp 19001:318 24X Fiche 50-275, 83/06/23, 8306280332

8306280388 Forwards application to amend License DPR-76, changing Tech Specs re containment spray timing Class III amend fee encl SCHUYLER, J O, Pacific Gas & Electric Co. 83/06/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 19014:001 24X Fiche 50-275, 83/06/23, 8306280388

8306280394 Application for amend to License DPR-76, changing Tech Specs re containment spray timing SCHUYLER, J O, Pacific Gas & Electric Co 83/06/23 3pp 19014:002 24X Fiche 50-275, 83/06/23, 8306280394

8306280396 Proposed Tech Spec changes re containment spray timing * Pacific Gas & Electric Co. 83/06/23 52pp 19014:005 24X Fiche 50-275, 83/06/23, 8306280396

8306280565 Expresses concern re util failure to rept that auxiliary bldg slabs not qualified for in-plane loadings, per independent design verification program 830614 meeting re status of error open items. REYNOLDS, J R, Joint Intervenor-Diablo Canyon, REYNOLDS, J R Center for Law in the Public Interest. 83/06/23 DENTON, H Office of Nuclear Reactor Regulation, Director 4pp 19017:332 24X Fiche 50-275, 83/06/23, 8306280565

8306300211 Forwards Rev O to "Suppl for As-Built" SCHUYLER, J O Pacific Gas & Electric Co. 83/06/24 EISENHUT, D O Division of Licensing, 1p. 19119:184 24X Fiche 50-275, 83/06/24, 8306300211

8306300217 Rev O to "Suppl for As-Built" * Pacific Gas & Electric Co. 83/06/24 18pp. 19119:185 24X Fiche 50-275, 83/06/24, 8306300217

8305110497 Board Notification 83-87 forwards info item re design verification program EISENHUT, D O Division of Licensing 83/06/27 PALLADINO, N J, QILINSKY, V., ROBERTS, T M Commissioners, 2pp 19053:035 24X Fiche 50-275, 83/06/27, 8305110497

8306290475 Notification of 830617 meeting w/BNL, RL Cloud Assoc, TEB, Bechtel & util in Bethesda, MD to discuss seismic analysis of buried tanks SCHIERLING, H, Licensing Branch 3. 83/06/15 KNIGHTON, O W, Licensing Branch 3 20pp. 24X Fiche 50-275, 83/06/27, 8305110499

8305110500 Board Notification 83-089: forwards PND-V-83-22A dtd 830623 re addl potential violations of min wall thickness of RCS piping. EISENHUT, D O, Division of Licensing 83/06/29 PALLADINO, N J, QILINSKY, V., AHEARNE, J F, Commissioners, 3pp. 19122:040, 24X Fiche 50-275, 83/06/29, 8305110500

Inspection reports, IE Bulletins & correspondence

8306100009 Addl response to FOIA request for documents dtd 820101 or after re BALP, Forwards App A documents, Documents also available in PDR. FELTON, J M Division of Rules and Records. 83/04/11, CLARK, R, San Francisco Examiner. 3pp. 18819:252 24X Fiche 50-000, 83/04/11, 8306100009

8306100014 Submits schedule for Region V BALP Board meetings for 820928-830523 ENGELKEN, R H, Region 5, Office of Director. 82/03/19, DENTON, H R, Office of Nuclear Reactor Regulation, Director, DAVIS, J O, Office of Nuclear Material Safety & Safeguards, Director MICHELSON, C, Director's Office. 1p. 18819:255 24X Fiche 50-000, 83/04/11, 8306100009

8306100036 Discusses assignment of BALP coordinators for Reactor Operations Projects Branch Facilities, Coordinators will be responsible for preparing input data used by board members in analyzing functional areas, Draft note from B Minor encl STERNBERG, D M, Region 5, Office of Director. 82/03/24, Region 5, Office of Director 11pp. 18815:257, 24X Fiche 50-000, 83/04/11, 8306100009

8306070360 Forwards IE Insp Repts 50-275/83-15 & 50-323/83-12 on 830418-22 No noncompliance noted BISHOP, T W Region 5, Office of Director 83/05/03 CRANE, P A Pacific Gas & Electric Co 2pp 18742:116 24X Fiche 50-275, 83/05/03, 8306070360

8306070369 IE Insp Repts 50-275/83-15 & 50-323/83-12 on 830418-22 No noncompliance noted Major areas inspected const activities & mods to annulus structural steel, ventilation duct supports, containment spray piping supports & circuit breakers BURDOIN, J F, ZMETZIG, G B Region 5, Office of Director 83/04/29, 5pp 18742:118 24X Fiche 50-275, 83/05/03, 8306070360

8306070093 Forwards IE Insp Repts 50-275/83-14 & 50-323/83-11 on 830301-02 & 31 No noncompliance noted BISHOP, T W Region 5, Office of Director 83/05/11 CRANE, P A Pacific Gas & Electric Co 2pp 18739:135 24X Fiche 50-275, 83/05/11, 8306070093

8306070098 IE Insp Repts 50-275/83-14 & 50-323/83-11 on 830301-02 & 31 No noncompliance noted Major areas inspected IE bulletins & circulars, Followup on previous licensee commitments & independent insp. MORRILL, P J, KIRSCH, D F Region 5, Office of Director 83/05/09 4pp 18739:137 24X Fiche 50-275, 83/05/11, 8306070093

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl TAYLOR, J M, Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 125pp 18831:043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Svc list encl. JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 115pp 18732:085 24X Fiche 50-000, 83/05/26, 8305110460

8306280189 Forwards IE Insp Repts 50-275/83-17 & 50-323/83-13 on 830403-30 & notice of violation w/o notice of violation BISHOP, T W Region 5, Office of Director 83/05/26 CRANE, P A Pacific Gas & Electric Co 2pp 19014:124 24X Fiche 50-275, 83/05/26, 8306280189

8306280194 IE Insp Repts 50-275/83-17 & 50-323/83-13 on 830403-30 Noncompliance noted failure of general const personnel to inform plant manager of observed damage to RCB piping CARLSON, J D, MENDONCA, H M, KIRSCH, D F Region 5, Office of Director 83/05/25 10pp 19014:176 24X Fiche 50-275, 83/05/26, 8306280189

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc 116pp 18732:208 24X Fiche 50-000, 83/05/31, 8305110461

8306300041 Responds to IE Bulletin re check valve failures in raw water cooling sys of diesel generators Check valves not used in closed-loop jacket cooling water sys. SCHUYLER, J O, CRANE, P A Pacific Gas & Electric Co 83/06/06 MARTIN, J B Region 5, Office of Director 2pp 19168:129 24X Fiche 50-275, 83/06/06, 8306300041

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc 117pp 18830:280 24X Fiche 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 118pp 18920:225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 243pp. 18921:001 24X Fiche 50-000, 83/06/13, 8306090010

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 115pp. 19021:179 24X Fiche 50-000, 83/06/22, 8305110475

DOCKETED ITEMS

83

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Bys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co. of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Bettings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

8305110492 Board Notification 83-83 Forwards info re violations of NRC Reporting requirements re min wall thickness on RCB piping
EISENHUT, D. O. Division of Licensing 83/06/24 FALLADINO, N. J., OILINSKY, V., AHEARNE, J. F. Commissioners 3pp 18996 228 24X Fiche 50-275, 83/06/24, 8305110492

--8306270342 Forwards IE Insp Rept 50-275/83-20 on 830523-0606 & notice of violation. W/o notice of violation
BISHOP, T. W. Region 5, Office of Director 83/06/17
SCHUYLER, J. O. Pacific Gas & Electric Co. 2pp 19046 104. 24X Fiche 50-275, 83/06/24, 8305110492

--8306270344 Notice of violation from insp on 830523-0606
KIRSCH, D. F. Region 5, Office of Director 83/06/17. 2pp 18996, 233 24X Fiche 50-275, 83/06/24, 8305110492

--8306270350 IE Insp Rept 50-275/83-20 on 830523-0606 Noncompliance noted licensee failed to promptly notify NRC of materially reportable conditions re min wall thickness on RCB piping
HERNANDEZ, G. H., MENDONCA, M. M., KIRSCH, D. F. Region 5, Office of Director, 83/06/17 6pp. 18996, 236 24X Fiche 50-275, 83/06/24, 8305110492

8306300083 Ack receipt of 830519 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-275/83-08
BISHOP, T. W. Region 5, Office of Director, 83/06/24 SCHUYLER, J. O. Pacific Gas & Electric Co. 1p. 19048 335 24X Fiche 50-275, 83/06/24, 8306300083.

--8306300089 Supplemental response to NRC 830329 ltr re violations noted in IE Insp Rept 50-275/83-08 Corrective actions: reinsp of 10% of fillet welded connections complete. Insufficient training of new welders & inspectors cause of deficiencies
CRANE, P. A. Pacific Gas & Electric Co. 83/05/19 MARTIN, J. B. Region 5, Office of Director, 5pp 19048, 336. 24X Fiche 50-275, 83/06/24, 8306300083

--8306300093 Responds to NRC 830329 ltr re violations noted in IE Insp Rept 50-275/83-08. Corrective actions: HP Foley Procedure GCP-5A will be revised to clarify requirements for stamping welds by welders & inspectors
CRANE, P. A. Pacific Gas & Electric Co. 83/04/25 MARTIN, J. B. Region 5, Office of Director 4pp. 19048, 341. 24X Fiche 50-275, 83/06/24, 8306300093

R Periodic operating reports & related correspondence

8306020214 Monthly operating rept for Mar 1983 W/830411 ltr.
KELLY, W. J., THORNBERRY, R. C. Pacific Gas & Electric Co. 83/04/11. Office of Resource Management, Director. 9pp. 18691, 120 24X Fiche 50-275, 83/04/11, 8306020214

8306160535 Monthly operating rept for Apr 1983 W/830503 ltr
KELLY, W. J., THORNBERRY, R. C. Pacific Gas & Electric Co. 83/05/03 Office of Management and Program Analysis. 5pp. 18864, 044 24X Fiche 50-275, 83/05/03, 8306160535

8306010347 Forwards updated sections of Phase I final rept for design verification program covering fuel handling & turbine bldgs. large-bore & small-bore piping & HVAC equipment results.
CRANE, P. A. Pacific Gas & Electric Co. 83/05/18. EISENHUT, D. O. Division of Licensing 262pp. 18680, 151 24X Fiche 50-275, 83/05/18, 8306010347

8306010317 Forwards "Diablo Canyon Nuclear Power Plant Independent Design Verification Program," semimonthly rept for May 1983
COOPER, W. E. Teledyne Engineering Services 83/05/27. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. MANEATIS, G. A. Pacific Gas & Electric Co. MARTIN, J. B. Region 5, Office of Director 1p. 18680 001 24X Fiche 50-275, 83/05/27, 8306010317

--8306010319 "Diablo Canyon Nuclear Power Plant Independent Design Verification Program," semimonthly rept for May 1983
* Teledyne Engineering Services 83/05/27 69pp 18680 002. 24X Fiche 50-275, 83/05/27, 8306010317

8306070292 Forwards design verification program, semimonthly Rept 38 for 830510-23 per Commission Order CLI-81-30
SCHUYLER, J. O. Pacific Gas & Electric Co. 83/05/27 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 1p 18741, 217 24X Fiche 50-275, 83/05/27, 8306070292

--8306070297 "Diablo Canyon Verification Program," semimonthly Rept 38 for 830510-23
* Pacific Gas & Electric Co. 83/05/27 64pp 18741 218. 24X Fiche 50-275, 83/05/27, 8306070292

8306170293 Discusses preliminary draft of revised interim technical repts re latest revs concerning independent design verification program Documents provided for info & not comment W/o encl
COOPER, W. E. Teledyne Engineering Services 83/05/27. SCHIERLING, M. E. Office of Nuclear Reactor Regulation, Director FRAY, R. R. Bechtel Corp BISHOP, T. E. Region 5, Office of Director 3pp 18878 171 24X Fiche 50-275, 83/05/27, 8306170293.

8306100130 Forwards "Diablo Canyon Nuclear Power Plant Unit 1 Independent Design Verification Program," third text submittal of final rept Next submittal scheduled for 830615 & final submittal scheduled for 830630
COOPER, W. E. Teledyne Engineering Services. 83/05/31 DENTON, H. R. Office of Nuclear Reactor Regulation, Director MARTIN, J. B. Region 5, Office of Director. MANEATIS, G. A. Pacific Gas & Electric Co. 2pp 18806 069. 24X Fiche 50-275, 83/05/31, 8306100130

--8306100134 "Diablo Canyon Nuclear Power Plant Unit 1 Independent Design Verification Program," third text submittal of final rept.
* Teledyne Engineering Services. 83/05/31. 183pp 18806, 071. 24X Fiche 50-275, 83/05/31, 8306100130

8306100168 Forwards Rev 1 to "Verification of High Energy Line Break & Internally Generated Missile Review Outside Containment for Auxiliary Feedwater Bys & Control Room Ventilation & Pressurization Bys." Interim Technical Rept 23
KRECHTING, J. E. Stone & Webster, Inc 83/06/02. DENTON, H. R. Office of Nuclear Reactor Regulation, Director MARTIN, J. B. Region 5, Office of Director MANEATIS, G. A. Pacific Gas & Electric Co. 1p. 18806, 035 24X Fiche 50-275, 83/06/02, 8306100168

--8306100171 Rev 1 to "Verification of High Energy Line Break & Internally Generated Missile Review Outside Containment for Auxiliary Feedwater Bys & Control Room Ventilation & Pressurization Bys." Interim Technical Rept 23.
BESTAK, F. Stone & Webster, Inc 83/05/27. 32pp 18806, 036 24X Fiche 50-275, 83/06/02, 8306100168

8306160526 Forwards "Diablo Canyon Verification Program, Semimonthly Rept 39."
SCHUYLER, J. O. Pacific Gas & Electric Co. 83/06/10 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. MARTIN, J. B. Region 5, Office of Director 1p. 18863 328 24X Fiche 50-275, 83/06/10, 8306160526

--8306160527 "Diablo Canyon Verification Program, Semimonthly Rept 39,"
* Pacific Gas & Electric Co. 83/06/10. 66pp. 18863, 329 24X Fiche 50-275, 83/06/10, 8306160526

8306170308 Forwards Open Item Repts 1123-1132 for independent design verification program semimonthly repts Conflict of interest statements for individuals assigned to program completed
DENISON, E. Robert L. Cloud Associates, Inc. 83/06/10 DENTON, H. R. Office of Nuclear Reactor Regulation, Director MARTIN, J. B. Region 5, Office of Director MANEATIS, G. A. Pacific Gas & Electric Co. 12pp. 18877 133 24X Fiche 50-275, 83/06/10, 8306170308.

8306170312 Forwards "Diablo Canyon Nuclear Power Plant Independent Design Verification Program June Second Friday Semimonthly Rept."
COOPER, W. E. Teledyne Engineering Services. 83/06/10. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. MARTIN, J. B. Region 5, Office of Director MANEATIS, G. A. Pacific Gas & Electric Co. 1p 18877 069. 24X Fiche 50-275, 83/06/10, 8306170312.

--8306170315 "Diablo Canyon Nuclear Power Plant Independent Design Verification Program June Second Friday Semimonthly Rept."
* Teledyne Engineering Services. 83/06/10 35pp 18877, 070. 24X Fiche 50-275, 83/06/10, 8306170312.

8306170350 Forwards June 1983 semimonthly open item rept.
KRECHTING, J. E. Stone & Webster Engineering Corp 83/06/10 DENTON, H. R. Office of Nuclear Reactor Regulation, Director MARTIN, J. B. Region 5, Office of Director MANEATIS, G. A. Pacific Gas & Electric Co. 13pp 18879, 027 24X Fiche 50-275, 83/06/10, 8306170350

DOCKETED ITEMS

8306170270 Forwards corrected pages to Apps 01 & 02 to draft Interim Technical Repts 3A & 3B W/o encls
COOPER, W E. Teledyne Engineering Services. 83/06/13 MOORE, T S
Atomic Safety and Licensing Board Panel 1p 18978:154 24X
Fiche: 50-275, 83/06/13, 8306170270

8306210162 Forwards "Phase II Final Rept, Design Verification Program," per 831119 ltr specifying requirements for addl info
BRAND, D A. Pacific Gas & Electric Co. 83/06/13 DENTON, H R.
Office of Nuclear Reactor Regulation, Director. 1p 18915 290 24X
Fiche: 50-275, 83/06/13, 8306210162

--8306210171 "Phase II Final Rept, Design Verification Program"
* Pacific Gas & Electric Co. 83/06/30 100pp 18915 291 24X
Fiche: 50-275, 83/06/13, 8306210162.

8306200249 Forwards "Diablo Canyon Nuclear Power Plant - Unit 1 Independent Design Verification Program Final Rept," fourth text submittal Final text submittal scheduled for 830630
COOPER, W E. Teledyne Engineering Services. 83/06/15. DENTON, H R.
Office of Nuclear Reactor Regulation, Director. MARTIN, J B. Region 5, Office of Director. MANEATIS, G A. Pacific Gas & Electric Co. 2pp 18901 111. 24X Fiche: 50-275, 83/06/15, 8306200249.

--8306200252 "Diablo Canyon Nuclear Power Plant - Unit 1 Independent Design Verification Program Final Rept," fourth text submittal
* Teledyne Engineering Services. 83/05/16. 59pp 18901 113
24X Fiche: 50-275, 83/06/15, 8306200249

8305110489 Board Notification 83-080, forwards ltrs & repts re status of activities performed as part of design verification efforts
Encls include M Reich 830517 ltr, TH Bishop 830519 ltr & "Semimonthly Status Rept for May 1983" W/o encl
EISENHUT, D. G. Division of Licensing. 83/06/20. PALLADINO, N. J., GILINSKY, V., AHEARNE, J. F. Commissioners. 3pp 18993 03B. 24X
Fiche: 50-275, 83/06/20, 8305110489

8306280483 Forwards Errata 2 to Rev 0 to "Independent Design Verification Program Final Rept"
COOPER, W E. Teledyne Engineering Services. 83/06/20 DENTON, H R.
Office of Nuclear Reactor Regulation, Director. MARTIN, J B. Region 5, Office of Director. MANEATIS, G A. Pacific Gas & Electric Co. 24pp. 19018 263 24X Fiche: 50-275, 83/06/20, 8306280483.

8306270416 Forwards Rev 3 to "Independent Design Verification Program, Final Rept."
COOPER, W E. Teledyne Engineering Services. 83/06/22 DENTON, H R.
Office of Nuclear Reactor Regulation, Director. MARTIN, J B. Region 5, Office of Director. MANEATIS, G A. Pacific Gas & Electric Co. 2pp 18992:152 24X Fiche: 50-275, 83/06/22, 8306270416

--8306270477 Rev 3 to "Independent Design Verification Program, Final Rept"
* Teledyne Engineering Services. 83/06/21. 180pp. 18992:156
24X Fiche: 50-275, 83/06/22, 8306270416.

8305110495 Board Notification 83-086 forwards 8MW "June Semimonthly Rept," RL Cloud Assoc "June Open Items Repts," & Teledyne Engineering Svcs "Independent Design Verification Program TEB June Semimonthly Rept"
EISENHUT, D. G. Division of Licensing. 83/06/24 PALLADINO, N. J., GILINSKY, V., AHEARNE, J. F. Commissioners. 3pp. 0 18992.336 24X
Fiche: 50-275, 83/06/24, 8305110495.

8305110498 Board Notification 83-85 forwards Teledyne Engineering Svcs "Independent Design Verification Program Final Rept - Fourth Test Submittal." Info will be considered in formulating recommendation re reinstatement of low power license
EISENHUT, D. G. Division of Licensing. 83/06/24. PALLADINO, N. J., GILINSKY, V., AHEARNE, J. F. Commissioners. 3pp. 19013 10B. 24X
Fiche: 50-275, 83/06/24, 8305110498.

8306280469 Forwards "Diablo Canyon Nuclear Plant Independent Design Verification Program," semimonthly status rept for June 1983
COOPER, W E. Teledyne Engineering Services. 83/06/24. DENTON, H R.
Office of Nuclear Reactor Regulation, Director. MARTIN, J B. Region 5, Office of Director. MANEATIS, G A. Pacific Gas & Electric Co. 1p. 19020:044 24X Fiche: 50-275, 83/06/24, 8306280469.

--8306280470 "Diablo Canyon Nuclear Power Plant Independent Design Verification Program," semimonthly rept for June 1983
* Teledyne Engineering Services. 83/06/24 71pp 19020:045.
24X Fiche: 50-275, 83/06/24, 8306280469.

8306290397 Forwards Rev 1 to "Final Rept on Const QA Evaluation of GF Atkinson Co." Interim Technical Rept 36 & Rev 2 to "Final Rept on Const QA Evaluation of Wismer & Becker," Interim Technical Rept 3B W/o Interim Rept 3B
SESTAK, F. Stone & Webster Engineering Corp. 83/06/24 DENTON, H R.
Office of Nuclear Reactor Regulation, Director. MANEATIS, G A.
Pacific Gas & Electric Co. MARTIN, J B. Region 5, Office of Director. 1p 19055 041 24X Fiche: 50-275, 83/06/24, 8306290397

--8306290401 Rev 1 to "Final Rept on Const QA Evaluation of GF Atkinson Co." Interim Technical Rept 36
SESTAK, F. Stone & Webster Engineering Corp. 83/06/20 149pp
19055 043 24X Fiche: 50-275, 83/06/24, 8306290397

--8306290545 Rev 2 to "Independent Design Verification Program, Final Rept on Const QA Evaluation of Wismer & Becker" Interim Technical Rept 3B
SESTAK, F. Stone & Webster Engineering Corp. 83/06/20 226pp
19049 051 24X Fiche: 50-275, 83/06/24, 8306290397

8 Reportable occurrences, LERs & related correspondence

8306090174 PNO-V-83-020 on 830504, 100 uCi Cs-137 check source found missing from gas decay tank discharge monitor RE-22 Licensee believes source stolen On 830415, 9 uCi Cs-137 source found missing All sources removed from monitors
GARCIA, E., WENSLAWSKI, F. Region 5, Office of Director. 83/05/04 1p 18792.270 24X Fiche: 50-275, 83/05/04, 8306090174

8306100067 LER 83-007/01T-0 on 830509, water leaked from weld area of reinforcement pad on branch connection to non-vital loop C component cooling water sys. Caused by flaw in root pass of shop weld Repairs to be made W/830523 ltr
KELLY, W J., SHIFFER, J D. Pacific Gas & Electric Co. 83/05/23
MARTIN, J B. Region 5, Office of Director. 3pp 18802 175 24X
Fiche: 50-275, 83/05/23, 8306100067

8306100082 LER 83-006/01T-0 on 830510, possible undersize condition found on weld WID-RC 2-17 Cause under investigation Below min wall thickness welds to be analyzed or repaired per ASME
Section XI W/830523 ltr
KELLY, W J., SHIFFER, J D. Pacific Gas & Electric Co. 83/05/23
MARTIN, J B. Region 5, Office of Director. 3pp 18802 229 24X
Fiche: 50-275, 83/05/23, 8306100082

8306230422 LER 83-005/04X-0 on 830502, prior to fuel load & following Coolings earthquake, unusual event declared based on earthquake motion felt at plant w/ 5 g full upscale indication Caused by faulty reset switch W/830601 ltr
KELLY, W J., SHIFFER, J D. Pacific Gas & Electric Co. 83/06/01
MARTIN, J B. Region 5, Office of Director. 3pp 18943 211 24X
Fiche: 50-275, 83/06/01, 8306230422

8306230365 LER 83-009/03L-0 on 830505, power switch to plant vent iodine sampler (RE-24) found in off position Power switch inadvertently moved to off position during const Const personnel cautioned W/830606 ltr
KELLY, W J., SHIFFER, J D. Pacific Gas & Electric Co. 83/06/06
MARTIN, J B. Region 5, Office of Director. 2pp 18944 126 24X
Fiche: 50-275, 83/06/06, 8306230365

8306210164 LER 83-008/03L-0 on 830510, const electrician inadvertently deenergized new fuel storage area monitor (RM-5) & oily water separator effluent line monitor (RM-3), resulting in loss of bus 1-1A Caused by lifting wrong wire W/830607 ltr
KELLY, W J., SHIFFER, J D. Pacific Gas & Electric Co. 83/06/07
MARTIN, J B. Region 5, Office of Director. 2pp 18918 097 24X
Fiche: 50-275, 83/06/07, 8306210164

8306210044 LER 83-014/01T-0 on 830526, during adjustment of Limitorque operator, binding of torque switch observed. Cause under investigation Torque switch mounting bolts substituted for original bolts. W/830609 ltr
KELLY, W J., SHIFFER, J D. Pacific Gas & Electric Co. 83/06/09
MARTIN, J B. Region 5, Office of Director. 2pp 18912:297 24X
Fiche: 50-275, 83/06/09, 8306210044

8306210078 LER 83-010/03L-0 on 830514, prior to fuel load, power to all main control room annunciators lost during const in annunciator cabinets Caused by electrician touching hot wire to ground, short circuiting panel W/830613 ltr
KELLY, W J., SHIFFER, J D. Pacific Gas & Electric Co. 83/06/13
MARTIN, J B. Region 5, Office of Director. 3pp 18911 229. 24X
Fiche: 50-275, 83/06/13, 8306210078

8306280421 LER 83-013/03L-0 on 830518, prior to fuel load, air sample pumps for plant vent radiation monitors RM-14A & B inoperable Caused by removal of control & instrument fuses for work inside RM2B A & B cabinet. W/830617 ltr
KELLY, W J., SHIFFER, J D. Pacific Gas & Electric Co. 83/06/17.
MARTIN, J B. Region 5, Office of Director. 3pp 19018 303 24X
Fiche: 50-275, 83/06/17, 8306280421.

DOCKETED ITEMS

85

8306280523 LER 83-012/03L-0 on 830518, prior to fuel load, air sample pumps for plant vent radiation monitors found tripped. Caused by excessive debris clogging radiation monitor filter paper due to const activities W/830617 ltr
KELLY, W J, SHIFFER, J D Pacific Gas & Electric Co 83/06/17
MARTIN, J B Region 5, Office of Director 3pp 19019 313 24X
Fiche 50-275, 83/06/17, 8306280523

8306280526 LER 83-011/03L-0 on 830518, prior to fuel load, discovered source check of oily water separator effluent line monitor not performed monthly. Caused by administrative error during procedure rev W/830617 ltr
KELLY, W J, SHIFFER, J D Pacific Gas & Electric Co 83/06/17
MARTIN, J B Region 5, Office of Director 3pp 19019 286 24X
Fiche 50-275, 83/06/17, 8306280526

8305110486 Board Notification 83-72 forwards info item re potential violation of min wall thickness on RCS pipe at facility
Region V currently examining licensee response to incident
EISENHUT, D O Division of Licensing 83/06/20 PALLADINO, N, GILINSKY, V, AHEARNE, J Commissioners 3pp 18980 146 24X
Fiche 50-275, 83/06/20, 8305110486

--8306240318 Confirms 830510 telcon re potential for one weld in reactor coolant loop 2 below min wall thickness. Ultrasonic thickness testing indicates that pipe to pipe weld in reactor coolant pump less than design min wall thickness
SHAFFER, J D Pacific Gas & Electric Co 83/05/11 MARTIN, J E Region 5, Office of Director 1p 18980 149 24X
Fiche 50-275, 83/06/20, 8305110486

8305110488 Board Notification 83-73 forwards 830509 ltr & PNO-V-83-021 re potential for inadequate welds in component cooling water piping sys
EISENHUT, D O Division of Licensing 83/06/20 PALLADINO, N J, GILINSKY, V, AHEARNE, J F Commissioners 4pp 18978 003 24X
Fiche 50-275, 83/06/20, 8305110488

8306280017 PNO-V-83-022A on 830622, personnel determined that RCS piping in areas of welds other than reported on 830510 may be less than min wall thickness. Reduction in wall thickness occurred during original preservice exam
KIRSCH, D F Region 5, Office of Director 83/06/23 1p 19001 119 24X
Fiche 50-275, 83/06/23, 8306280017

Y Hearing transcripts on non-antitrust matters

8305110471 Board Notification 83-78 forwards matls re independent design verification program by participating organizations
Info relevant to safety issue on design adequacy of plant
EISENHUT, D O Division of Licensing 83/06/10 PALLADINO, N, GILINSKY, V, AHEARNE, J Commissioners 3pp, 18847 313 24X
Fiche 50-275, 83/06/10, 8305110471

--8306190276 Transcript of 830520 meeting in Monroeville, PA re seismic qualification of panel on main control board Pp 1-125
Supporting documentation encl
* Commissioners 83/06/20 182pp 18848 052 24X
Fiche 50-275, 83/06/10, 8305110471

--8306190281 Transcript of NRC independent design verification program 830521 meeting in Boston, MA Pp 1-90,
* Commissioners 83/05/21 92pp 18848 234 24X
Fiche 50-275, 83/06/10, 8305110471

8305110499 Board Notification 83-87 forwards info item re design verification program
EISENHUT, D O Division of Licensing 83/06/27 PALLADINO, N J, GILINSKY, V, ROBERTS, T M Commissioners 2pp 19053 035 24X
Fiche 50-275, 83/06/27, 8305110499

--8306290470 Transcript of 830617 public meeting in Bethesda, MD re design verification program, Pp 1-45
* Commissioners 83/06/17 48pp 24X
Fiche 50-275, 83/06/27, 8305110499

--8306290476 Notification of 830617 meeting w/BNL, RL Cloud Assoc, TEB, Bechtel & util in Bethesda, MD to discuss seismic analysis of buried tanks
SCHIERLING, H Licensing Branch 3 83/06/15 KNIIGHTON, G W Licensing Branch 3 20pp, 24X
Fiche 50-275, 83/06/27, 8305110499

V Operator Examinations

8306240465 Approves 830315 request for variance in std cold license certification on program, allowing abbreviated 5 wk version of Phase II program for 11 on-shift operators.
KNIIGHTON, G W, Licensing Branch 3 83/06/13 CRANE, F A, Pacific Gas & Electric Co 2pp 18978 101 24X
Fiche 50-275, 83/06/13, 8306240465

DOCKET 50-277 PEACH BOTTOM ATOMIC POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8306030096 Informs that NUREG-0737, Item III A 2 i, "Emergency Preparedness, Upgrade Emergency Plans to App E:10CFR50," complete item closed
STOLZ, J F Operating Reactors Branch 4 83/05/18 BAUER, E O, Philadelphia Electric Co 3pp 18733 293 24X
Fiche 50-277, 83/05/18, 8306030096

8306070223 Forwards IE Insp Repts 50-277/83-09 & 50-278/83-09 on 830402-0512 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/05/24, DALTROFF, S L Philadelphia Electric Co 2pp, 18746 112 24X
Fiche 50-277, 83/05/24, 8306070223

--8306070226 IE Insp Repts 50-277/83-09 & 50-278/83-09 on 830402-0512 No noncompliance noted. Major areas inspected, accessible portions of facilities, operational safety, radiation protection, physical security & control room activities.
BLOUGH, A R, WILLIAMS, J H, MCBREARTY, R A Region 1, Office of Director 83/05/23 16pp 18746, 114 24X
Fiche 50-277, 83/05/24, 8306070223

8306060157 Forwards "Fire Protection Mod Progress Rept," per 830223 ltr, Request for exemptions re smoke detection & penetration seals & description of addl administrative controls dealing w/transient combustibles also encl
BOYER, V B Philadelphia Electric Co 83/05/27 EISENHUT, D O, Division of Licensing 8pp, 18732 059, 24X
Fiche 50-277, 83/05/27, 8306060157

--8306060158 "Fire Protection Mod Progress Rept" W/four oversize drawings. Aperture cards are available in PDR
* Philadelphia Electric Co 83/05/27 9pp 18732 067, 24X
Fiche 50-277, 83/05/27, 8306060157

8306140381 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/06/06 Document Management Branch 1p 18853 216 24X
Fiche 50-277, 83/06/06, 8306140381

--8306140391 Forwards public version of revised emergency plan implementing procedures, including Procedures EP-201 re technical support ctr activation, EP-205 re radiation protection team activation & EP-207C re first aid
DALTROFF, S L Philadelphia Electric Co 83/05/24, ALLAN, J H, Region 1, Office of Director 2pp 18853 217 24X
Fiche 50-277, 83/06/06, 8306140381

--8306140398 Public version of revised emergency plan implementing procedures, including Procedures EP-201 re technical support ctr activation, EP-205 re radiation protection team activation & EP-207C re first aid.
* Philadelphia Electric Co 83/04/25 145pp, 18853 219, 24X
Fiche 50-277, 83/06/06, 8306140381

8306200159 Ack receipt of 830504 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/83-04 & 50-278/83-04,
MARTIN, T T Division of Engineering & Technical Programs, 83/06/14 DALTROFF, S L Philadelphia Electric Co, 2pp, 18902 357, 24X
Fiche 50-277, 83/06/14, 8306200159

--8306200165 Responds to NRC 830404 ltr re violations noted in IE Insp Repts 50-277/83-04 & 50-278/83-04 Corrective actions withheld (ref 10CFR2 790 & 73.21)
DALTROFF, S L Philadelphia Electric Co 83/05/04, MARTIN, T T, Division of Engineering & Technical Programs, 1p, 18902 359, 24X
Fiche 50-277, 83/06/14, 8306200159

P Operating license stage documents & correspondence

8306030110 Forwards safety evaluation re BWR Owners Group 801230 response to NUREG-0737, Item II K.3.45, "Depressurization W/Other Than Automatic Depressurization Sys" No mod to plant design or operation required
STOLZ, J F Operating Reactors Branch 4, 83/05/18 BAUER, E O, Philadelphia Electric Co 2pp 18733 297, 24X
Fiche 50-277, 83/05/18, 8306030110

8306020299 Forwards responses to NRC questions addressed at 830520 meeting & provides description of augmented leak detection sys & interim surveillance requirements
DALTROFF, S L Philadelphia Electric Co 83/05/23, EISENHUT, D O Division of Licensing 8pp, 18694 158, 24X
Fiche 50-277, 83/05/23, 8306020299

DOCKETED ITEMS

--8306020303 Rev 4 to Procedure PB 83-1, "Ultrasonic Exam of Welds in Pipe,"
 * General Electric Co 83/04/03 53pp 18694 166 24X
 Fiche: 50-277, 83/05/23, 8306020299

8306020325 Informs that lead responsibility transferred from Region I to NRR for review of pipe crack indications, evaluation of response to IE Bulletin 83-02, approval of Unit 3 restart & acceptability of continued operation of Unit 2
 STOLZ, J F Operating Reactors Branch 4 83/05/23 DAUER, E O
 Philadelphia Electric Co 2pp 18715 299 24X
 Fiche: 50-277, 83/05/23, 8306020325

8306020378 Forwards "Crack Growth Analysis of Peach Bottom Unit 2 RHR Flaw," providing addl info to support continued operation of facility, per util 830523 ltr
 DALTROFF, B L Philadelphia Electric Co 83/05/26 EISENHUT, D O
 Division of Licensing 1p 18695 122 24X Fiche: 50-277, 83/05/26, 8306020378

--8306020379 "Crack Growth Analysis of Peach Bottom Unit 2 RHR Flaw"
 RANANATH, B. General Electric Co 83/05/25 19pp. 18695 123
 24X Fiche: 50-277, 83/05/26, 8306020378

8306070363 Responds to 830202 request for addl info re NUREG-0737, Item 11 K 3 B, "Verify Qualification of Accumulators on Automatic Depressurization Sys Valves." w/one oversize drawing. Aperture card is available in PDR
 DALTROFF, B L Philadelphia Electric Co 83/06/02 STOLZ, J F
 Operating Reactors Branch 4 11pp 18743 075 24X
 Fiche: 50-277, 83/06/02, 8306070363

--8306070374 Rev 0 to "Surveillance Test: ST 2 1 23A, Calibr of PT/PR 8102A & PT/PI/PB/DPS 8143A."
 * Philadelphia Electric Co 82/06/07 16pp 18743 087 24X
 Fiche: 50-277, 83/06/02, 8306070363

--8306070376 Rev 0 to "Surveillance Test: ST 2 1 23B, Calibr of PT/PR 8102B & PT/PI/PB/DPS 8143B."
 * Philadelphia Electric Co 82/07/15 16pp 18743 103 24X
 Fiche: 50-277, 83/06/02, 8306070363

--8306070379 Rev 0 to "Surveillance Test: ST 2 5 30A, Calibr of FT-8130A, F8-8130A."
 * Philadelphia Electric Co 82/08/23 6pp 18743 119 24X
 Fiche: 50-277, 83/06/02, 8306070363

--8306070383 Rev 5 to "Surveillance Test: ST 7 9 2, Daily Check of Seismic Gas Supply Bottle Pressures."
 * Philadelphia Electric Co 83/03/17 11pp 18743 125 24X
 Fiche: 50-277, 83/06/02, 8306070363

--8306070387 Rev 0 to "Surveillance Test: ST 20 129, LLRT ADS Back-Up Supply Penetrations N-47 & N-102B."
 * Philadelphia Electric Co 82/05/23 15pp 18743 136 24X
 Fiche: 50-277, 83/06/02, 8306070363

--8306070391 Rev 0 to "Surveillance Test: ST 30 131, ADS Accumulator Check Valve & Solenoid Valve LLRT."
 * Philadelphia Electric Co 81/10/14 11pp 18743 151 24X
 Fiche: 50-277, 83/06/02, 8306070363

--8306070395 Rev 3 to "Surveillance Test: ST 13 28, ADS Relief Valve Solenoid Valve Functional."
 * Philadelphia Electric Co 83/03/17 5pp 18743 162 24X
 Fiche: 50-277, 83/06/02, 8306070363

--8306070398 Rev 1 to "Surveillance Test: ST 2 & 3A, Calibr Check of PT-9202A & PR-9102A (Green Pen)."
 * Philadelphia Electric Co 83/03/11 16pp 18743 167 24X
 Fiche: 50-277, 83/06/02, 8306070363

--8306070403 Rev 1 to "Surveillance Test: ST 2 & 23B, Calibr Check of PT 9102B & PR 9102 (Green Pen)."
 * Philadelphia Electric Co 83/03/10 18pp. 18743 183 24X
 Fiche: 50-277, 83/06/02, 8306070363

8306090219 Forwards revised Tech Spec Pages 36 & 36a to limiting condition of operation to make B11223 application for amend to Tech Specs re reactor protection sys consistent w/model Tech Spec, per NRC 830511 telcon request
 DALTROFF, B L Philadelphia Electric Co 83/06/02, STOLZ, J F
 Operating Reactors Branch 4 2pp 18796 115 24X
 Fiche: 50-277, 83/06/02, 8306090219

--8306090226 Revised Tech Spec Pages 36 & 36a changing limiting condition of operation to be consistent w/model Tech Spec re reactor protection sys.
 * Philadelphia Electric Co. 83/06/02. 2pp 18796 117 24X
 Fiche: 50-277, 83/06/02, 8306090219

8306170471 Forwards evaluation of BWR Owners Group generic response to NUREG-0737, Item 11 K 3 B "Automatic Depressurization Sys Logic Mods." Two of seven alternatives acceptable. One alternative should be chosen for facility mod
 STOLZ, J F Operating Reactors Branch 4 83/06/03 BAUER, E O
 Philadelphia Electric Co 9pp 18894 338 24X
 Fiche: 50-277, 83/06/03, 8306170471

8306280138 Forwards "Control of Heavy Loads, Philadelphia Electric Co, Peach Bottom Atomic Power Station, Units 2 & 3," draft technical evaluation rept
 STOLZ, J F Operating Reactors Branch 4 83/06/14 BAUER, E O
 Philadelphia Electric Co 2pp 19043 359 24X
 Fiche: 50-277, 83/06/14, 8306280138

--8306060329 "Control of Heavy Loads, Peach Bottom Atomic Power Station, Units 2 & 3," draft technical evaluation rept
 BOMBERGER, C R Franklin Institute/Franklin Research Center
 NRC-03-81-130 TER-C5306-374/380 83/05/17 NRC - No Detailed
 Affiliation Given 45pp 19043 361 24X Fiche: 50-277, 83/06/14, 8306280138

8306280156 Forwards revised safety evaluation re degraded grid voltage protection for Class IE power sys, based on review of util 820512, 0722 & 1029 submittals & LLL technical evaluation rept
 Class IE adequately protected
 STOLZ, J F Operating Reactors Branch 4 83/06/14 BAUER, E O
 Philadelphia Electric Co 3pp 19046 072 24X
 Fiche: 50-277, 83/06/14, 8306280156

--8306280162 Revised safety evaluation re degraded grid voltage protection for Class IE sys Proposed electrical design mods acceptable
 * Office of Nuclear Reactor Regulation, Director 83/06/08 7pp
 19046 075 24X Fiche: 50-277, 83/06/14, 8306280156

--8306280167 Supplementary safety evaluation re proposed testing frequency for degraded grid protection sys Request for 6-month test should be denied Testing should be performed monthly
 * Office of Nuclear Reactor Regulation, Director 83/06/14 5pp
 19046 079 24X Fiche: 50-277, 83/06/14, 8306280156

--8304070100 Rev 1 to "Proposed Design Mods & Tech Spec Changes on Grid Voltage Degradation for Peach Bottom Atomic Power Station, Units 2 & 3," technical evaluation rept
 BELAN, J C Lawrence Livermore Laboratory FIN A-0250 UCID-19115
 R01 83/03/11 NRC - No Detailed Affiliation Given 10pp
 19046 084 24X Fiche: 50-277, 83/06/14, 8306280156

8306270261 Forwards application for amend to Licenses DPR-44 & DPR-56 revising list of shock suppressors to reflect mods made since last amend to B10324 application
 BRADLEY, E J Philadelphia Electric Co 83/06/22 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 1p 18990 181 24X
 Fiche: 50-277, 83/06/22, 8306270261

--8306270264 Application for amend to Licenses DPR-44 & DPR-56, revising list of shock suppressors to reflect mods made since last amend to B10324 application
 BAUER, E O, BRADLEY, E J Philadelphia Electric Co 83/06/22
 5pp 18990 182 24X Fiche: 50-277, 83/06/22, 8306270261

--8306270268 Proposed Tech Spec Table 3 11 D 1 revising list of shock suppressors to reflect mods made since last amend to B10324 application
 * Philadelphia Electric Co 83/06/22 3pp 18990 187 24X
 Fiche: 50-277, 83/06/22, 8306270261

Q Inspection reports, IE Bulletins & correspondence

8306220181 Discusses IE insps on B10113-820915 & forwards notice of violation & proposed imposition of civil penalty
 HAYNES, R C Region 1, Office of Director 83/03/29 BOYER, V
 Philadelphia Electric Co 6pp 18977 318 24X
 Fiche: 50-277, 83/03/29, 8306220181

--8306220191 Notice of violation & proposed imposition of civil penalty in amount of \$140,000 Noncompliance noted improper valve lineup, inadequate valve lineup verifications, improper use of test procedures & inadequate monitoring of parameters
 HAYNES, R C Region 1, Office of Director 83/03/29 8pp
 18977 324 24X Fiche: 50-277, 83/03/29, 8306220181

8306030291 Forwards IE Enforcement Conference Repts 50-277/83-13 & 50-278/83-13 on 830306 No noncompliance noted
 STAROSTECKI, R Division of Project & Resident Programs. 83/05/20,
 DALTROFF, B L Philadelphia Electric Co 2pp 18708 336 24X
 Fiche: 50-277, 83/05/20, 8306030291

DOCKETED ITEMS

87

--8306030312 IE Enforcement Conference Repts 50-277/83-13 & 50-278/83-13 on 830906 No noncompliance noted Major topics discussed violations of procedural controls & Tech Spec requirements
BLOUGH, A R, WILLIAMS, J H, MCCABE, E C Region 1, Office of Director 83/05/13 4pp 18708 337 24X Fiche 50-277, 83/05/20, 8306030271

8306020299 Forwards responses to NRC questions addressed at 830520 meeting & provides description of augmented leak detection sys & interim surveillance requirements
DALTROFF, S L Philadelphia Electric Co 83/05/23 EISENHUT, D G Division of Licensing 81pp 18694 158 24X Fiche 50-277, 83/05/23, 8306020299

--8306020303 Rev 4 to Procedure PD 83-1, "Ultrasonic Exam of Welds in Pipe"
* General Electric Co 83/04/05 50pp 18694 166 24X Fiche 50-277, 83/05/23, 8306020299

8306020325 Informs that lead responsibility transferred from Region 1 to NRR for review of pipe crack indications, evaluation of response to IE Bulletin 83-02, approval of Unit 3 restart & acceptability of continued operation of Unit 2
STOLZ, J F Operating Reactors Branch 4 83/05/23 DAUER, C G Philadelphia Electric Co 2pp 18715 299 24X Fiche 50-277, 83/05/23, 8306020325

8306060162 Forwards IE Insp Repts 50-277/83-12 & 50-278/83-12 on 830418-22 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs 83/05/23 DALTROFF, S L Philadelphia Electric Co 2pp 18719 197 24X Fiche 50-277, 83/05/23, 8306060162

--8306060166 Notice of violation from insp on 830418-22
* Region 1, Office of Director 83/05/23 1p 18719 199 24X Fiche 50-277, 83/05/23, 8306060162

--8306060170 IE Insp Repts 50-277/83-12 & 50-278/83-12 on 830418-22 Noncompliance noted failure to follow jumper log procedures & QA plan
RICHARDS, B, ANDERSON, C Region 1, Office of Director 83/05/16, 5pp 18719 200 24X Fiche 50-277, 83/05/23, 8306060162

8306070223 Forwards IE Insp Repts 50-277/83-09 & 50-278/83-09 on 830402-0512 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs, 83/05/24 DALTROFF, S L Philadelphia Electric Co 2pp 18746 112 24X Fiche 50-277, 83/05/24, 8306070223

--8306070226 IE Insp Repts 50-277/83-09 & 50-278/83-09 on 830402-0512 No noncompliance noted Major areas inspected accessible portions of facilities, operational safety, radiation protection, physical security & control room activities
BLOUGH, A R, WILLIAMS, J H, MCCREARY, R A, Region 1, Office of Director 83/05/23 16pp 18746 114 24X Fiche 50-277, 83/05/24, 8306070223

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device." Svc list encl
TAYLOR, J M, Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc. 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Svc list encl.
JORDAN, E L, Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc. 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs." Svc list encl.
JORDAN, E L, Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc. 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306160054 Notification of 830616 significant licensee meeting in Delta, PA to discuss BALP
TRIPP, L E, Region 1, Office of Director, 83/06/02, DIRCKS, W J, Office of the Executive Director for Operations STELLD, V, Regional Operations & Generic Requirements DEYOUNG, R C, Director's Office, Office of Inspection and Enforcement 1p 18892 327 24X Fiche 50-277, 83/06/02, 8306160054

8306200125 Forwards IE Insp Repts 50-277/83-11 & 50-278/83-11 on 830419-22 No noncompliance noted
MARTIN, T T, Division of Engineering & Technical Programs 83/06/06, DALTROFF, S L Philadelphia Electric Co 2pp 18903 291 24X Fiche 50-277, 83/06/06, 8306200125

--8306200130 IE Insp Repts 50-277/83-11 & 50-278/83-11 on 830419-22, No noncompliance noted Major areas inspected inservice testing of pumps & valves, local leak rate testing, integrated leak rate testing & facility tours
PULLANI, S V, BETTENHAUSEN, L, Region 1, Office of Director 83/06/01 10pp 18903 293 24X Fiche 50-277, 83/06/06, 8306200125

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations" Svc list encl
JORDAN, E L, Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc. 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8306140258 Ack receipt of 830526 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/83-07 & 50-278/83-07
MARTIN, T T, Division of Engineering & Technical Programs 83/06/09 DALTROFF, S L Philadelphia Electric Co 1p 18833 027 24X Fiche 50-277, 83/06/09, 8306140258

--8306140262 Responds to NRC 830429 ltr re violations noted in IE Insp Repts 50-277/83-07 & 50-278/83-07 Corrective action, radiation area immediately reposted & health physicist assigned to monitor reactor bldg
GALLAGHER, J W Philadelphia Electric Co 83/05/26 MARTIN, T T, Division of Engineering & Technical Programs 2pp 18833 028 24X Fiche 50-277, 83/06/09, 8306140258

8306160483 Ack receipt of 830517 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/82-10, 50-278/82-10, 50-277/82-14 & 50-278/82-14
STAROSTECKI, R, Division of Engineering & Technical Programs 83/06/10 DALTROFF, S L Philadelphia Electric Co 1p 18864 124 24X Fiche 50-277, 83/06/10, 8306160483

--8306160486 Responds to NRC 830418 ltr re violations noted in IE Insp Repts 50-277/82-10, 50-278/82-10, 50-277/82-14 & 50-278/82-14 Corrective actions personnel restructured re procedural controls governing operation
DALTROFF, S L Philadelphia Electric Co 83/05/17, STAROSTECKI, R, Division of Project & Resident Programs 3pp 18864 125 24X Fiche 50-277, 83/06/10, 8306160483

8306280235 Responds to IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators." Two check valves identified which could fail & possibly prevent coolant from reaching diesel generators
GALLAGHER, J W Philadelphia Electric Co 83/06/10 ALLAN, J M Region 1, Office of Director 8pp 19015 030 24X Fiche 50-277, 83/06/10, 8306280235

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards" Svc list encl
JORDAN, E L, Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list encl.
JORDAN, E L, Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8306200159 Ack receipt of 830504 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/83-04 & 50-278/83-04
MARTIN, T T, Division of Engineering & Technical Programs 83/06/14, DALTROFF, S L Philadelphia Electric Co 2pp 18902 357 24X Fiche 50-277, 83/06/14, 8306200159

--8306200165 Responds to NRC 830404 ltr re violations noted in IE Insp Repts 50-277/83-04 & 50-278/83-04, Corrective actions withheld (ref 10CFR2.790 & 73.21)
DALTROFF, S L Philadelphia Electric Co 83/05/04, MARTIN, T T, Division of Engineering & Technical Programs 1p 18902 359 24X Fiche 50-277, 83/06/14, 8306200159

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Outputs & Sealers" Svc list encl.
JORDAN, E L, Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc. 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment" Svc list encl
JORDAN, E L, Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc. 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

DOCKETED ITEMS

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions"
Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co of New
York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate
Range (IR) High Flux Trip Setpoints" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co of New
York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483.

R. Periodic operating reports & related correspondence

8306170163 Rev 1 to "Peach Bottom Atomic Power Station Units 2 & 3
Semiannual Effluent Release Rept 14, Jul-Dec 1982." W/830606
ltr
FLEISCHMANN, R, ALDEN, W M Philadelphia Electric Co. 82/12/31
ALLAN, J M Region 1, Office of Director 11pp, 18878-332 24X
Fiche 50-277, 82/12/31, 8306170163

8306160379 Monthly operating repts for Apr 1983 W/830512 ltr
ALDEN, W M, COONEY, M J Philadelphia Electric Co 83/05/09 10pp,
18860 092 24X Fiche 50-277, 83/05/09, 8306160379.

8306210076 Monthly operating repts for May 1983 W/830615 ltr
ALDEN, W M, COONEY, M J Philadelphia Electric Co 83/06/10
Director's Office, Office of Inspection and Enforcement 12pp,
18913-350, 24X Fiche 50-277, 83/06/10, 8306210076

S. Reportable occurrences, LERs & related correspondence

8306020277 LER 83-011/01T-0 on 830506, during forced outage, indications
found in heat affected zone of 20-inch RHR shutdown cooling
suction line weld. Caused by intergranular stress corrosion
cracking. Water sensitive tape applied to welds. W/830520 ltr
COONEY, M J Philadelphia Electric Co. 83/05/20, ALLAN, J M Region
1, Office of Director, 7pp 18690-329 24X Fiche 50-277, 83/05/20,
8306020277

8306020299 Forwards responses to NRC questions addressed at 830520
meeting & provides description of augmented leak detection
sys & interim surveillance requirements
DALTROFF, S L Philadelphia Electric Co. 83/05/23, EISENHUT, D O,
Division of Licensing 81pp, 18694 158, 24X Fiche 50-277, 83/05/23,
8306020299

8306020396 LER 83-004/03L-0 on 830424, refueling floor ventilation
radiation monitor RE2-17-432D experienced downscale spike
Caused by defective Gieger/Mueller tube. Tube replaced &
faulty connector rebuilt.
COONEY, M J Philadelphia Electric Co. 83/05/24, ALLAN, J M Region
1, Office of Director, 1p 18694 361, 24X Fiche 50-277, 83/05/24,
8306020396.

8306170017 LER 83-012/01T-0 on 830511, inadequacies found in fire walls
& penetration seals in eight emergency switchgear rooms &
four emergency battery rooms, caused by const or design
error. W/830525 ltr.
COONEY, M J Philadelphia Electric Co 83/05/25, ALLAN, J M Region
1, Office of Director, 5pp 18882-247 24X Fiche 50-277, 83/05/25,
8306170017

8306170278 LER 83-010/03L-0 on 830427, sample line flow meter indicated
no flow & 3-way selector valve BV-2524 found stuck. Caused by
dirt buildup inside solenoid valve, (ABCO Model B-26-734).
Valve tapped & flow returned.
COONEY, M J Philadelphia Electric Co. 83/05/26, ALLAN, J M Region
1, Office of Director, 1p 18878-057 24X Fiche 50-277, 83/05/26,
8306170278

8306200144 LER 83-013/03L-0 on 830503, fluctuating readings observed on
iodine monitor & downscale reading found on gas monitor.
Caused by poor connections in drywell air sampling radiation
detector circuitry due to oxidation buildup on connectors.
COONEY, M J Philadelphia Electric Co 83/06/01, ALLAN, J M Region
1, Office of Director, 1p, 18903-246 24X Fiche 50-277, 83/06/01,
8306200144.

V. Operator Examinations

8306140536 Extends invitation to attend 830627 meeting in King of
Prussia, PA to discuss transfer of reactor operator licensing
function from Bethesda, MD to Region 1 ofc
STAROSTECKI, R. Division of Project & Resident Programs 83/06/09,
DALTROFF, S L Philadelphia Electric Co. 2pp, 18834-336, 24X
Fiche 50-277, 83/06/09, 8306140536.

DOCKET 50-278 PEACH BOTTOM ATOMIC POWER STATION, UNIT 3

F Security, medical, emergency & fire protection plans

8306030096 Informs that NUREG-0737, Item 111 A 2 i, "Emergency
Preparedness, Upgrade Emergency Plans to App E.10CFR50,"
complete item closed
STOLZ, J F Operating Reactors Branch 4 83/05/18 BAUER, E O
Philadelphia Electric Co 3pp 18733-293 24X
Fiche 50-277, 83/05/18, 8306030096

8306070223 Forwards IE Insp Repts 50-277/83-09 & 50-278/83-09 on
830402-0512 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/05/24
DALTROFF, S L Philadelphia Electric Co 2pp 18746 112 24X
Fiche 50-277, 83/05/24, 8306070223

--8306070226 IE Insp Repts 50-277/83-09 & 50-278/83-09 on 830402-0512 No
noncompliance noted. Major areas inspected accessible
portions of facilities, operational safety, radiation
protection, physical security & control room activities
BLOUGH, A R, TRIPP, L E Region 1, Office of Director 83/05/23
10pp 18746 114 24X Fiche 50-277, 83/05/24, 8306070223

8306060157 Forwards "Fire Protection Mod Progress Rept," per 830225
ltr Request for exemptions re smoke detection & penetration
seals & description of addl administrative controls dealing
w/transient combustibles also encl
BOYER, V S Philadelphia Electric Co 83/05/27 EISENHUT, D O
Division of Licensing 8pp 18732-059 24X Fiche 50-277, 83/05/27,
8306060157

--8306060158 "Fire Protection Mod Progress Rept" W/four oversize
drawings. Aperture cards are available in PDR
* Philadelphia Electric Co 83/05/27 9pp 18732 067 24X
Fiche 50-277, 83/05/27, 8306060157

8306140381 Releases public version of revised emergency plan
implementing procedures
FELTON, J M Division of Rules and Records 83/06/06 Document
Management Branch 1p 18853-216 24X Fiche 50-277, 83/06/06,
8306140381.

--8306140391 Forwards public version of revised emergency plan
implementing procedures, including Procedures EP-201 re
technical support ctr activation, EP-205 re radiation
protection team activation & EP-207C re first aid
DALTROFF, S L Philadelphia Electric Co 83/05/24, ALLAN, J M
Region 1, Office of Director 2pp 18853 217 24X
Fiche 50-277, 83/06/06, 8306140381

--8306140398 Public version of revised emergency plan implementing
procedures, including Procedures EP-201 re technical support
ctr activation, EP-205 re radiation protection team
activation & EP-207C re first aid
* Philadelphia Electric Co 83/04/25 149pp 18853 219 24X
Fiche 50-277, 83/06/06, 8306140381

8306200159 Ack receipt of 830504 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-277/83-04 &
50-278/83-04
MARTIN, T T Division of Engineering & Technical Programs 83/06/14
DALTROFF, S L Philadelphia Electric Co. 2pp, 18902-357 24X
Fiche 50-277, 83/06/14, 8306200159

--8306200165 Responds to NRC 830404 ltr re violations noted in IE Insp
Repts 50-277/83-04 & 50-278/83-04. Corrective actions
withheld (ref 10CFR2, 790 & 73 21)
DALTROFF, S L Philadelphia Electric Co 83/05/04 MARTIN, T T
Division of Engineering & Technical Programs, 1p 18902 359, 24X
Fiche 50-277, 83/06/14, 8306200159

P Operating license stage documents & correspondence

8306030110 Forwards safety evaluation re BWR Owners Group 801230
response to NUREG-0737, Item II K 3 45, "Depressurization
W/Other Than Automatic Depressurization Sys" No mod to
plant design or operation required.
STOLZ, J F Operating Reactors Branch 4, 83/05/18 BAUER, E O,
Philadelphia Electric Co 2pp, 18733-297, 24X
Fiche 50-277, 83/05/18, 8306030110.

8306020360 Forwards missing Tech Spec Page 142e of Amend 92 to License
DPR-56, issued 830504, Amend changed Tech Specs to permit
reactor operation w/Reload 5 core (Cycle 6).
GEARS, Q, Operating Reactors Branch 4 83/05/19, BAUER, E O,
Philadelphia Electric Co. 2pp, 18716-346 24X
Fiche 50-278, 83/05/19, 8306020360.

DOCKETED ITEMS

89

--B306020572 Page 142s to Amend 92 to License DPR-56, issued B30504, changing Tech Specs to permit operation w/Reload 5 Core (Cycle 6)
* NRC - No Detailed Affiliation Given 83/05/19 1p 18716 348
24X Fiche 50-277, 83/05/19, B306020360

B306020325 Informs that lead responsibility transferred from Region 1 to NRR for review of pipe crack indications, evaluation of response to IE Bulletin 83-02, approval of Unit 3 restart & acceptability of continued operation of Unit 2
STOLZ, J F Operating Reactors Branch 4 83/05/23 BAUER, E O
Philadelphia Electric Co 2pp 18715 299 24X
Fiche 50-277, 83/05/23, B306020325

B306070363 Responds to B30202 request for addl info re NUREG-0737, Item II K 3 2B, "Verify Qualification of Accumulators on Automatic Depressurization Sys Valves" w/one oversize drawing Aperture card is available in PDR
DALTROFF, B L Philadelphia Electric Co 83/06/02 STOLZ, J F
Operating Reactors Branch 4 11pp 18743 075 24X
Fiche 50-277, 83/06/02, B306070363

--B306070381 Rev 5 to "Surveillance Test ST 7 9 2, Daily Check of Seismic Gas Supply Bottle Pressures"
* Philadelphia Electric Co 83/03/17 11pp 18743 125 24X
Fiche 50-277, 83/06/02, B306070363

--B306070391 Rev 0 to "Surveillance Test ST 30 131, ADG Accumulator Check Valve & Solenoid Valve L1R1"
* Philadelphia Electric Co 81/10/14 11pp 18743 151 24X
Fiche 50-277, 83/06/02, B306070363

--B306070395 Rev 3 to "Surveillance Test ST 13 2B, ADS Relief Valve Solenoid Valve Functional"
* Philadelphia Electric Co 83/03/17 5pp 18743 162 24X
Fiche 50-277, 83/06/02, B306070363

--B306070398 Rev 1 to "Surveillance Test ST 2 & 3A, Calibr Check of PT-9202A & PR-9102A (Green Pen)"
* Philadelphia Electric Co 83/03/11 16pp 18743 167 24X
Fiche 50-277, 83/06/02, B306070363

--B306070403 Rev 1 to "Surveillance Test ST 2 & 23B, Calibr Check of PT 9102W & PR 9102 (Green Pen)"
* Philadelphia Electric Co 83/03/10 18pp 18743 183 24X
Fiche 50-277, 83/06/02, B306070363

B306090219 Forwards revised Tech Spec Pages 34 & 36a to limiting condition of operation to make B11223 application for amend to Tech Specs re reactor protection sys consistent w/model
Tech Spec per NRC B30511 telcon request
DALTROFF, B L Philadelphia Electric Co 83/06/02 STOLZ, J F
Operating Reactors Branch 4 2pp 18796 119 24X
Fiche 50-277, 83/06/02, B306090219

--B306090226 Revised Tech Spec Pages 36 & 36a changing limiting condition of operation to be consistent w/model Tech Spec re reactor protection sys
* Philadelphia Electric Co 83/06/02 2pp 18796 117 24X
Fiche 50-277, 83/06/02, B306090219

B306170471 Forwards evaluation of BWR Owners Group generic response to NUREG-0737, Item II K 3 1B "Automatic Depressurization Sys Logic Mode" two of seven alternatives acceptable. One alternative should be chosen for facility mod.
STOLZ, J F Operating Reactors Branch 4 83/06/03 BAUER, E O
Philadelphia Electric Co 9pp 18094 038 24X
Fiche 50-277, 83/06/03, B306170471

B306240476 Informs of OE B30520 request for generic approval of Type I Hybrid 1 control rods during Refuel B. Charges will not be attributed to util docket or util organization
STOLZ, J F Operating Reactors Branch 4 83/06/14 BAUER, E O
Philadelphia Electric Co 2pp 18797 355 24X
Fiche 50-278, 83/06/14, B306240476

B306280138 Forwards "Control of Heavy Loads, Philadelphia Electric Co, Peach Bottom Atomic Power Station, Units 2 & 3," draft technical evaluation rept
STOLZ, J F Operating Reactors Branch 4 83/06/14 BAUER, E O
Philadelphia Electric Co 2pp 19043 059 24X
Fiche 50-277, 83/06/14, B306280138

--B306040329 "Control of Heavy Loads, Peach Bottom Atomic Power Station, Units 2 & 3," draft technical evaluation rept.
BOMBERGER, C R Franklin Institute/Franklin Research Center, NRC-02-B1-130 TER-C5506-379780, 83/05/17 NRC - No Detailed Affiliation Given 45pp, 19043 361, 24X Fiche 50-277, 83/06/14, B306280138.

B306280156 Forwards revised safety evaluation re degraded grid voltage protection for Class IE power sys, based on review of util B20512, 0722 & 1029 submittals & LLL technical evaluation rept Class IE adequately protected
STOLZ, J F Operating Reactors Branch 4 83/06/14 BAUER, E O
Philadelphia Electric Co 3pp 19046 072 24X
Fiche 50-277, 83/06/14, B306280156

--B306280162 Revised safety evaluation re degraded grid voltage protection for Class IE sys Proposed electrical design mods acceptable
* Office of Nuclear Reactor Regulation, Director 83/06/08 7pp 19046 075 24X Fiche 50-277, 83/06/14, B306280156

--B306280167 Supplementary safety evaluation re proposed testing frequency for degraded grid protection sys Request for 6-month test should be denied Testing should be performed monthly
* Office of Nuclear Reactor Regulation, Director 83/06/14, 5pp 19046 079 24X Fiche 50-277, 83/06/14, B306280156

--B304070100 Rev 1 to "Proposed Design Mods & Tech Spec Changes on Grid Voltage Degradation for Peach Bottom Atomic Power Station, Units 2 & 3," technical evaluation rept
SELAN, J C Lawrence Livermore Laboratory FIN A-0250, UCID-19115 R01 83/03/11, NRC - No Detailed Affiliation Given 10pp 19046 084 24X Fiche 50-277, 83/06/14, B306280156

B306270261 Forwards application for amend to Licenses DPR-44 & DPR-56 revising list of shock suppressors to reflect mods made since last amend to B10324 application
BRADLEY, E J Philadelphia Electric Co 83/06/22, DENTON, H. R. Office of Nuclear Reactor Regulation, Director, 1p 18990 181 24X
Fiche 50-277, 83/06/22, B306270261

--B306270264 Application for amend to Licenses DPR-44 & DPR-56, revising list of shock suppressors to reflect mods made since last amend to B10324 application
BAUER, E O, BRADLEY, E J Philadelphia Electric Co, 83/06/22 5pp 18990 182 24X Fiche 50-277, 83/06/22, B306270261

--B306270268 Proposed Tech Spec Table 3.11 D 1 revising list of shock suppressors to reflect mods made since last amend to B10324 application
* Philadelphia Electric Co 83/06/22 3pp 18990 187, 24X
Fiche 50-277, 83/06/22, B306270261

0 Inspection reports, IE Bulletins & correspondence

B306220181 Discusses IE insps on B11013-B20915 & forwards notice of violation & proposed imposition of civil penalty
HAYNES, R C Region 1, Office of Director 83/03/29 BOYER, V
Philadelphia Electric Co 5pp 18777 318, 24X
Fiche 50-277, 83/03/29, B306220181

--B306220191 Notice of violation & proposed imposition of civil penalty in amount of \$140,000 Noncompliance noted: improper valve lineup, inadequate valve lineup verifications, improper use of test procedures & inadequate monitoring of parameters
HAYNES, R C Region 1, Office of Director 83/03/29 8pp 18777 324 24X Fiche 50-277, 83/03/29, B306220181

B306030291 Forwards IE Enforcement Conference Repts 50-277/83-13 & 50-278/83-13 on B30506 No noncompliance noted.
STAROSTECKI, R. Division of Project & Resident Programs 83/05/20 DALTROFF, B L Philadelphia Electric Co. 2pp, 18708 336 24X
Fiche 50-277, 83/05/20, B306030291

--B306030312 IE Enforcement Conference Repts 50-277/83-13 & 50-278/83-13 on B30506 No noncompliance noted Major topics discussed: violations of procedural controls & Tech Spec requirements.
BLUQUH, A R, WILLIAMS, J H, MCCABE, E C, Region 1, Office of Director 83/05/13 4pp, 18708 337, 24X Fiche 50-277, 83/05/20, B306030291

B306020325 Informs that lead responsibility transferred from Region 1 to NRR for review of pipe crack indications, evaluation of response to IE Bulletin 83-02, approval of Unit 3 restart & acceptability of continued operation of Unit 2.
STOLZ, J F Operating Reactors Branch 4 83/05/23, BAUER, E O. Philadelphia Electric Co 2pp 18715 299, 24X
Fiche 50-277, 83/05/23, B306020325

B306060162 Forwards IE Insp Repts 50-277/83-12 & 50-278/83-12 on B30418-22 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs, 83/05/23 DALTROFF, B L Philadelphia Electric Co 2pp, 18719 197, 24X
Fiche 50-277, 83/05/23, B306060162.

--B306060166 Notice of violation from insp on B30418-22.
* Region 1, Office of Director 83/05/23, 1p 18719 199 24X
Fiche 50-277, 83/05/23, B306060162

DOCKETED ITEMS

--8306060170 IE Insp Repts 50-277/83-12 & 50-278/83-12 on 830418-22
Noncompliance noted Failure to follow jumper log procedures
& QA plan
RICHARDS, B. ANDERSON, C. Region I, Office of Director 83/05/16
5pp. 18719 200 24X Fiche 50-277, 83/05/23, 8306060162

8306070223 Forwards IE Insp Repts 50-277/83-09 & 50-278/83-09 on
830402-0512 No noncompliance noted
STAROSTECKI, R. Division of Project & Resident Programs. 83/05/24
DALTROFF, S. L. Philadelphia Electric Co 2pp 18746, 112 24X
Fiche: 50-277, 83/05/24, 8306070223

--8306070226 IE Insp Repts 50-277/83-09 & 50-278/83-09 on 830402-0512 No
noncompliance noted Major areas inspected: accessible
portions of facilities, operational safety, radiation
protection, physical security & control room activities
BLOUGH, A. R., WILLIAMS, J. H., MCBREARTY, R. A. Region I, Office of
Director 83/05/23 16pp 18746 114 24X Fiche 50-277, 83/05/24,
8306070223

8305110438 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in
Well Logging Device " Svc list encl
TAYLOR, J. H. Division of Safeguards & Inspection Programs (Post
830103) 83/05/26. Consolidated Edison Co. of New York, Inc
125pp 18931 043 24X Fiche 50-000, 83/05/26, 8305110438.

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet "
Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26. Consolidated Edison Co. of New
York, Inc. 115pp. 18732, 085 24X Fiche 50-000, 83/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods
Withdrawn at BHRs " Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/31. Consolidated Edison Co. of New
York, Inc 116pp 18732, 208 24X Fiche 50-000, 83/05/31, 8305110461

8306160054 Notification of 830616 significant licensee meeting in
Delta, PA to discuss BALP
TRIPP, L. E. Region I, Office of Director 83/06/02. DIRCKS, W. J.
Office of the Executive Director for Operations STELLD, V. Regional
Operations & Generic Requirements DEYOUNG, R. C. Director's Office,
Office of Inspection and Enforcement 1p. 18892 327 24X
Fiche, 50-277, 83/06/02, 8306160054

8306200125 Forwards IE Insp Repts 50-277/83-11 & 50-278/83-11 on
830419-22, No noncompliance noted
MARTIN, T. T. Division of Engineering & Technical Programs 83/06/06
DALTROFF, S. L. Philadelphia Electric Co 2pp. 18903 291 24X
Fiche 50-277, 83/06/06, 8306200125

--8306200130 IE Insp Repts 50-277/83-11 & 50-278/83-11 on 830419-22 No
noncompliance noted. Major areas inspected, inservice testing
of pumps & valves, local leak rate testing, integrated leak
rate testing & facility tours.
PULLANI, B. V., BETTENHAUSEN, L. Region I, Office of Director
83/06/01. 10pp 18903, 293. 24X Fiche 50-277, 83/06/06, 8306200125

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe
Operations." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/09. Consolidated Edison Co. of New
York, Inc. 119pp. 18830 260. 24X Fiche: 50-000, 83/06/09, 8305110464

8306140298 Act receipt of 830526 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-277/83-07 &
50-278/83-07
MARTIN, T. T. Division of Engineering & Technical Programs 83/06/09.
DALTROFF, S. L. Philadelphia Electric Co. 1p. 18833 027 24X
Fiche, 50-277, 83/06/09, 8306140298.

--8306140262 Responds to NRC 830429 ltr re violations noted in IE Insp
Repts 50-277/83-07 & 50-278/83-07, Corrective action,
radiation area immediately reposted & health physicist
assigned to monitor reactor bldg.
O'ALLAGHER, J. W. Philadelphia Electric Co. 83/05/26. MARTIN, T. T.
Division of Engineering & Technical Programs. 2pp. 18833 028.
24X Fiche: 50-277, 83/06/09, 8306140258

8306160483 Ack receipt of 830517 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-277/82-10,
50-278/82-10, 50-277/82-14 & 50-278/82-14
STAROSTECKI, R. Division of Engineering & Technical Programs
83/06/10. DALTROFF, S. L. Philadelphia Electric Co 1p 18864: 124
24X Fiche: 50-277, 83/06/10, 8306160483.

--8306160486 Responds to NRC 830418 ltr re violations noted in IE Insp
Repts 50-277/82-10, 50-278/82-10, 50-277/82-14 & 50-278/82-14
Corrective actions personnel restructured re procedural
controls governing operation
DALTROFF, S. L. Philadelphia Electric Co 83/05/17 STAROSTECKI, R.
Division of Project & Resident Programs 3pp 18864 125 24X
Fiche 50-277, 83/06/10, 8306160483

8306280235 Responds to IE Bulletin 83-03, "Check Valve Failures in Raw
Water Cooling Sys of Diesel Generators " Two check valves
identified which could fail & possibly prevent coolant from
reaching diesel generators
O'ALLAGHER, J. W. Philadelphia Electric Co 83/06/10 ALLAN, J. H.
Region I, Office of Director 8pp 19015 030 24X
Fiche 50-277, 83/06/10, 8306280235

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive &
Seismically Induced Chatter in Relays Within Printed
Circuit Cards " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13. Consolidated Edison Co. of New
York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From
Degraded Internal Connection Cables " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13. Consolidated Edison Co. of New
York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8306200159 Ack receipt of 830504 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-277/83-04 &
50-278/83-04
MARTIN, T. T. Division of Engineering & Technical Programs 83/06/14
DALTROFF, S. L. Philadelphia Electric Co 2pp 18902 357 24X
Fiche, 50-277, 83/06/14, 8306200159

--8306200165 Responds to NRC 830404 ltr re violations noted in IE Insp
Repts 50-277/83-04 & 50-278/83-04 Corrective actions
withheld (ref 10CFR2 790 & 79 21)
DALTROFF, S. L. Philadelphia Electric Co 83/05/04 MARTIN, T. T.
Division of Engineering & Technical Programs 1p 18902 359 24X
Fiche: 50-277, 83/06/14, 8306200159

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
Epoxy Grouts & Sealers " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22. Consolidated Edison Co. of New
York, Inc 119pp. 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys
Causing Inoperability of Safety-Related Equipment " Svc list
encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22. Consolidated Edison Co. of New
York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions "
Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23. Consolidated Edison Co. of New
York, Inc. 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate
Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24. Consolidated Edison Co. of New
York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

R Periodic operating reports & related correspondence

8306170163 Rev 1 to "Peach Bottom Atomic Power Station Units 2 & 3
Semiannual Effluent Release Rept 14, Jul-Dec 1982 " W/830606
1p
FLEISCHMANN, R., ALDEN, W. M. Philadelphia Electric Co 82/12/31
ALLAN, J. M. Region I, Office of Director 11pp 18878 332 24X
Fiche 50-277, 82/12/31, 8306170163

8306160379 Monthly operating repts for Apr 1983 W/830512 ltr
ALDEN, W. M., COONEY, M. J. Philadelphia Electric Co 83/05/09 10pp
18860: 092 24X Fiche 50-277, 83/05/09, 8306160379

8306210076 Monthly operating repts for May 1983 W/830615 ltr
ALDEN, W. M., COONEY, M. J. Philadelphia Electric Co 83/06/10
Director's Office, Office of Inspection and Enforcement 12pp
18913 350 24X Fiche 50-277, 83/06/10, 8306210076

DOCKETED ITEMS

91

B Reportable occurrences, LERs & related correspondence

B306010438 Forwards LER B3-012/01T-0 Detailed event analysis encl
COONEY, M J Philadelphia Electric Co B3/05/09 ALLAN, J M Region
1, Office of Director 3pp 18679 316 24X Fiche 50-278, B3/05/09,
B306010438

--B306010445 LER B3-012/01T-0 on B30425, during refueling outage, while
performing NDE, intergranular stress corrosion cracking
indications found in heat affected zone of 12 welds Caused
by stress corrosion Weld insp increased
COONEY, M J Philadelphia Electric Co B3/05/09 Region 1,
Office of Director 1p 18679 315 24X Fiche 50-278, B3/05/09,
B306010438

/ Operator Examinations

B306140536 Extends invitation to attend B30627 meeting in King of
Prussia, PA to discuss transfer of reactor operator licensing
function from Bethesda, MD to Region 1 ofc
STAROSTECKI, R Division of Project & Resident Programs B3/06/09
DALTROFF, S L Philadelphia Electric Co 2pp 18834 336 24X
Fiche 50-277, B3/06/09, B306140536

BUCKET 50-280 SURRY POWER STATION, UNIT 1

Security, medical, emergency & fire protection plans

B306140621 Forwards IE Insp Repts 50-280/B2-31 & 50-281/B2-31 on
B21004-31 Enforcement action addressed in JP O'Reilly
B30324 ltr
DANCE, H C Division of Project & Resident Programs B3/03/25
STEWART, W L Virginia Electric & Power Co 2pp 18843 009 24X
Fiche 50-280, B3/03/25, B306140621

--B306140627 IE Insp Repts 50-280/B2-31 & 50-281/B2-31 on B21004-31
Inoperable containment spray chemical addition tank
identified following Unit 1 startup
BURKE, D J, DAVIS, M J Region 2, Office of Director, JULIAN, C
Division of Project & Resident Programs B3/03/24 8pp
18843 011 24X Fiche 50-280, B3/03/25, B306140621

B306140950 Confirms IE enforcement conference on B30405 at Region II
ofc to discuss mgt of health physics operations Proposed
agenda encl
O'REILLY, J P Region 2, Office of Director B3/04/01, STEWART, W L
Virginia Electric & Power Co 2pp 18834 204 24X
Fiche 50-280, B3/04/01, B306140950

B306170327 Application supplementing B10921 & B20415 proposed changes
to Tech Specs re fire protection sys, by deleting reporting
requirements from Spec 3 21
STEWART, W L Virginia Electric & Power Co B3/06/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director, VARQA, B A,
Operating Reactors Branch 1, 3pp 18877 001 24X
Fiche 50-280, B3/06/14, B306170327

--B306170331 Suppl to proposed Tech Specs re fire protection sys,
* Virginia Electric & Power Co B3/06/14 10pp 18877 004 24X
Fiche 50-280, B3/06/14, B306170327

Insurance & indemnity information

B306300113 Endorsement 44 to NELA Policy NF-240
* Nuclear Energy Liability Insurance Association B3/06/01 1p,
19121 069 24X Fiche 50-280, B3/06/01, B306300113

Utility Final Safety Analysis Report (FSAR) & amends

B306300149 Forwards Rev 1 to updated FSAR Rev current as of B30101,
STEWART, W L Virginia Electric & Power Co B3/06/22 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p, 19115, 135, 24X
Fiche 50-280, B3/06/22, B306300149

B306300151 Rev 1 to updated FSAR
* Virginia Electric & Power Co B3/06/22 646pp, 19115, 136
24X Fiche 50-280, B3/06/22, B306300149

Operating license stage documents & correspondence

B4060051 Addl response to FDA request for three categories of
documents re PRA of reactor safety study methodology
application program repts & interim reliability evaluation
program repts Forwards App A documents Search continuing,
ELTON, J M Division of Rules and Records, B3/04/07 SHOLLY, B C,
Union of Concerned Scientists 3pp 18752 001, 24X
Fiche 50-000, B3/04/07, B306060051

--B306060089 Provides info on boron precipitation clogging MPI lines &
failure of operator to switch to hot leg injection in order
to flush out boron residue from core during recirculation
Info obtained from PRA
DAVIS, B NRC - No Detailed Affiliation Given B3/02/24
THADANI, A NRC - No Detailed Affiliation Given 8pp 18752 206
24X Fiche 50-000, B3/04/07, B306060051

B306030441 Forwards "Control of Heavy Loads (C-10), Surry Power Station
Units 1 & 2," draft technical evaluation rept & summary of
addl info required to complete review Response requested
within 60 days
VARQA, S A Operating Reactors Branch 1 B3/05/16 STEWART, W L
Virginia Electric & Power Co 2pp 18735 287 24X
Fiche 50-280, B3/05/16, B306030441

--B306030446 "Control of Heavy Loads (C-10), Surry Power Station Units 1 &
2," draft technical evaluation rept
VOGBURY, F W, BAROENT, I H Franklin Institute/Franklin Research
Center NRC-03-B1-130 YER-C5506-395/396 DR, B3/01/14 NRC -
No Detailed Affiliation Given, 40pp 18735 289, 24X
Fiche 50-280, B3/05/16, B306030441

B306150064 COPPER IN THE INTAKE AND DISCHARGE ZONES OF THE SURRY
AND SALEM NUCLEAR POWER STATIONS
HARRISON, F L, BISHOP, D J, RICE, D W Lawrence Livermore Laboratory,
FIN A-0119 NUREG/CR-2965 B3/05/31 Division of Health, Biting
& Waste Management 3pp Available at NRC \$4 00 18849 221
24X Fiche 50-000, B3/05/31, B306150064

B306100170 Updates B21112 ltr providing info on schedule for submitting
results of motor-operated valve studies & replacement of
valves w/unsatisfactory starting capabilities Permanent
schedule will be provided by B31215.
STEWART, W L Virginia Electric & Power Co B3/06/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director VARQA, B A,
Operating Reactors Branch 1 2pp 18805 263 24X
Fiche 50-280, B3/06/03, B306100170

B306170281 Advises that B21227 commitment to complete installation &
testing of post-accident sampling sys per NUREG-0737, Item
II B 3 by B30601 has been met Final procedures for sys will
be complete by B30701
STEWART, W L Virginia Electric & Power Co B3/06/14 DENTON, H R,
Office of Nuclear Reactor Regulation, Director EISENHUT, D G,
Division of Licensing 2pp 18877 025 24X Fiche 50-280, B3/06/14,
B306170281

B306170327 Application supplementing B10921 & B20415 proposed changes
to Tech Specs re fire protection sys, by deleting reporting
requirements from Spec 3 21
STEWART, W L Virginia Electric & Power Co, B3/06/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director VARQA, B A,
Operating Reactors Branch 1 3pp 18877 001, 24X
Fiche 50-280, B3/06/14, B306170327

--B306170331 Suppl to proposed Tech Specs re fire protection sys,
* Virginia Electric & Power Co B3/06/14, 10pp 18877 004, 24X
Fiche 50-280, B3/06/14, B306170327

B306220033 Application to amend Licenses DPR-32 & DPR-37, changing Tech
Specs by adding addl accident monitoring instrumentation &
reactor vessel head vents per NUREG-0737, Items II F 1 &
II B 1, respectively
STEWART, W L Virginia Electric & Power Co B3/06/16 DENTON, H R,
Office of Nuclear Reactor Regulation, Director VARQA, B A,
Operating Reactors Branch 1 3pp, 18927 233 24X
Fiche 50-280, B3/06/16, B306220033

--B306220047 Proposed Tech Specs adding addl accident monitoring
instrumentation & reactor vessel head vents, per NUREG-0737,
Items II F 1 & II B 1, respectively,
* Virginia Electric & Power Co B3/06/16, 23pp, 18927 237, 24X
Fiche 50-280, B3/06/16, B306220033

Q Inspection reports, IE Bulletins & correspondence

B306140556 Confirms mgt meeting on B30217 in Richmond, VA to review
results of first phase of annual appraisal of regulatory
performance, Proposed meeting agenda encl,
LEWIS, R C, Division of Project & Resident Programs, B3/02/08,
STEWART, W L Virginia Electric & Power Co 3pp, 18834 217 24X
Fiche 50-000, B3/02/08, B306140556

B306140328 Confirms B30309 enforcement conference w/util to discuss
Unit 1 B21016 incident re containment spray sys chemical
addition tank being valved out when required to be operable
by Tech Specs Proposed meeting agenda encl
O'REILLY, J P Region 2, Office of Director B3/03/04 STEWART, J L
Virginia Electric & Power Co 2pp 18832 215, 24X
Fiche 50-280, B3/03/04, B306140328

DOCKETED ITEMS

8306140621 Forwards IE Insp Repts 50-280/82-31 & 50-281/82-31 on 821004-31 Enforcement action addressed in JP O'Reilly
830324 ltr
DANCE, H. C. Division of Project & Resident Programs 83/03/25
STEWART, W. L. Virginia Electric & Power Co. 2pp. 18843 009 24X
Fiche 50-280, 83/03/25, 8306140621

--8306140627 IE Insp Repts 50-280/82-31 & 50-281/82-31 on 821004-31 Inoperable containment spray chemical addition tank identified following Unit 1 startup
BURKE, D. J., DAVIS, M. J. Region 2, Office of Director JULIAN, C
Division of Project & Resident Programs 83/03/24 8pp.
18843:011. 24X Fiche. 50-280, 83/03/25, 8306140621.

8306140710 Submits confirmation of action ltr re 830408 & 11 telcons & 830405 enforcement meeting in Atlanta, GA re util failure to perform adequate radiological air sampling & to monitor personnel radiation exposure
O'REILLY, J. P. Region 2, Office of Director. 83/04/11 STEWART, W. L.
Virginia Electric & Power Co. 2pp 18841:290 24X
Fiche: 50-280, 83/04/11, 8306140710

8306140397 Forwards IE Insp Repts 50-280/83-12 & 50-281/83-12 on 830415-21, No Noncompliance noted
DANCE, H. C. Region 2, Office of Director 83/05/17 STEWART, W. L.
Virginia Electric & Power Co. 2pp 18832 084 24X
Fiche: 50-280, 83/05/17, 8306140397.

--8306140400 IE Insp Repts 50-280/83-12 & 50-281/83-12 on 830415-21 No noncompliance noted. Major areas inspected containment integrated leakage rate testing & pipe supports & restraints
BROOKS, E. H., JAPPE, F. Region 2, Office of Director. 83/05/12
3pp 18832:086. 24X Fiche 50-280, 83/05/17, 8306140397

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl
TAYLOR, J. M. Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc.
123pp 18831:043 24X Fiche. 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/26 Consolidated Edison Co. of New York, Inc. 115pp. 18732 085. 24X Fiche 50-000, 83/05/26, 8305110460.

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/31 Consolidated Edison Co. of New York, Inc. 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306290331 Forwards response to IE Bulletin 83-08, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators " Surry has no valves in emergency diesel generator cooling sys. Raw cooling water sys not used at North Anna.
STEWART, W. L. Virginia Electric & Power Co. 83/06/08 O'REILLY, J. P.
Region 2, Office of Director 3pp 19055 303 24X
Fiche. 50-000, 83/06/08, 8306290331.

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc. 119pp 18830:280. 24X Fiche 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/13 Consolidated Edison Co. of New York, Inc. 118pp 18920,225. 24X Fiche. 50-000, 83/06/13, 8305110470.

8306200219 Revises 830603 response to Enforcement Action 83-36 contained in IE Insp rept re whole body counts & other outage-related requirements Corrected Page 3 encl.
STEWART, W. L. Virginia Electric & Power Co. 83/06/15 DEYOUNG, R. C.
Director's Office, Office of Inspection and Enforcement 2pp 18902, 286. 24X Fiche: 50-280, 83/06/15, 8306200219.

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/22 Consolidated Edison Co. of New York, Inc. 115pp. 19021,179. 24X Fiche. 50-000, 83/06/22, 8305110475.

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18997:007 24X Fiche: 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co. of New York, Inc. 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (1R) High Flux Trip Setpoints " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc. 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

R Periodic operating reports & related correspondence

8306020159 Forwards monthly operating repts for Mar 1983 & corrected pages to health physics rept for monthly operating repts for Jan & Feb 1983
STEWART, W. L. Virginia Electric & Power Co. 83/04/14 HALICR, N. H.
Office of Resource Management, Director 1p 18691 006 24X
Fiche 50-280, 83/04/14, 8306020159

--8306020162 Monthly operating repts for Mar 1983
JONES, V. Virginia Electric & Power Co. 83/04/19 47pp
18691 007 24X Fiche 50-280, 83/04/14, 8306020159

--8306020168 Correct page to health physics rept for monthly operating rept for Jan 1983
* Virginia Electric & Power Co. 83/04/14 1p 18691 054 24X
Fiche 50-280, 83/04/14, 8306020159

--8306020173 Corrected page to health physics rept for monthly operating rept for Feb 1983
* Virginia Electric & Power Co. 83/04/14 1p 18691 085 24X
Fiche 50-280, 83/04/14, 8306020159

8306160375 Monthly operating repts for Apr 1983 W/830513 ltr
JONES, V., STEWART, W. L. Virginia Electric & Power Co. 83/05/13
48pp 18861 074 24X Fiche 50-280, 83/05/13, 8306160375

S Reportable occurrences, LERs & related correspondence

8306070220 LER 83-021/03L-0 on 830427, Periodic Tests 1B 15 & 1B 16 re degraded protection function H train & J train, revealed emergency bus separation & diesel start time delay setpoint tolerance exceeded Delays reset W/830519 ltr
WILSON, J. L. Virginia Electric & Power Co. 83/05/19 O'REILLY, J. P.
Region 2, Office of Director App 18744 146 24X
Fiche 50-280, 83/05/19, 8306070220

8306210285 LER 83-023/03L-0 on 830513, steam generator blowdown released to discharge canal w/o monitor Caused by procedures not requiring flow verification in radiation monitor
Blowdown checklist will be modified W/830610 ltr
WILSON, J. L., WILSON, J. L. Virginia Electric & Power Co. 83/06/10
O'REILLY, J. P. Region 2, Office of Director 3pp 18715 019 24X
Fiche 50-280, 83/06/10, 8306210285.

8306270005 LER 83-024/03L-0 on 830517, RHR pump B removed from svc, rendering RHR loops inoperable Caused by pump cavitation due to inaccurate standpipe level indication RCS level increased RHR pump vented & returned to svc W/830616 ltr
WILSON, J. L. Virginia Electric & Power Co. 83/06/16 O'REILLY, J. P.
Region 2, Office of Director 3pp 18988 154 24X
Fiche 50-280, 83/06/16, 8306270005.

DOCKET 50-281 SURRY POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8306140621 Forwards IE Insp Repts 50-280/82-31 & 50-281/82-31 on 821004-31 Enforcement action addressed in JP O'Reilly
830324 ltr
DANCE, H. C. Division of Project & Resident Programs 83/03/25
STEWART, W. L. Virginia Electric & Power Co. 2pp 18843:009 24X
Fiche 50-280, 83/03/25, 8306140621

--8306140627 IE Insp Repts 50-280/82-31 & 50-281/82-31 on 821004-31 Inoperable containment spray chemical addition tank identified following Unit 1 startup
BURKE, D. J. Region 2, Office of Director 83/03/24 8pp
18843:011 24X Fiche 50-280, 83/03/25, 8306140621

8306140550 Confirms IE enforcement conference on 830405 at Region 11 w/pc to discuss mgt of health physics operations Proposed agenda encl.
O'REILLY, J. P. Region 2, Office of Director. 83/04/01 STEWART, W. L.
Virginia Electric & Power Co. 2pp 18834:204 24X
Fiche. 50-280, 83/04/01, 8306140550

DOCKETED ITEMS

8306170327 Application supplementing 810921 & 820415 proposed changes to Tech Specs re fire protection sys. by deleting reporting requirements from Spec 3 21
STEWART, W. L. Virginia Electric & Power Co 83/06/14 DENION, H. R.
Office of Nuclear Reactor Regulation, Director 3pp 18877 001 24X
Fiche 50-280, 83/06/14, 8306170327

--8306170331 Suppl to proposed Tech Specs re fire protection sys
* Virginia Electric & Power Co 83/06/14 10pp 18877 004 24X
Fiche 50-280, 83/06/14, 8306170327

J Insurance & indemnity information

8306300113 Endorsement 44 to NCLIA Policy NF-240
* Nuclear Energy Liability Insurance Association 83/06/01 1p
19121 049 24X Fiche 50-280, 83/06/01, 8306300113

K Utility Final Safety Analysis Report (FSAR) & amends

8306300149 Forwards Rev 1 to updated FSAR Rev current as of 830101
STEWART, W. L. Virginia Electric & Power Co 83/06/22 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director 1p 19115 135 24X
Fiche 50-280, 83/06/22, 8306300149

--8306300151 Rev 1 to updated FSAR
* Virginia Electric & Power Co 83/06/22 64pp 19115 136
24X Fiche 50-280, 83/06/22, 8306300149

P Operating license stage documents & correspondence

8306060051 Addl response to FOIA request for three categories of documents re PRA of reactor safety study methodology application program repts & interim reliability evaluation program repts Forwards App A documents Search continuing
FELTON, J. M. Division of Rules and Records 83/04/07 SHOLLY, S. C.
Unit of Concerned Scientists 3pp 18752 001 24X
Fiche 50-000, 83/04/07, 8306060051

--8306060085 Provides info on boron precipitation clogging HP1 lines & failure of operator to switch to hot leg injection in order to flush out boron residue from core during recirculation
Info obtained from PRAs
DAVIS, B. NRC - No Detailed Affiliation Given 83/02/24
THADANI, A. NRC - No Detailed Affiliation Given 6pp 18752 206
24X Fiche 50-000, 83/04/07, 8306060051

8306030441 Forwards "Control of Heavy Loads (C-10), Surry Power Station Units 1 & 2," draft technical evaluation rept & summary of addl info required to complete review Response requested within 60 days
VARQA, B. A. Operating Reactors Branch 1 83/05/16 STEWART, W. L.
Virginia Electric & Power Co 2pp 18735 287 24X
Fiche 50-280, 83/05/16, 8306030441

--8306030444 "Control of Heavy Loads (C-10), Surry Power Station Units 1 & 2," draft technical evaluation rept
VOGBURY, F. W., KNEZOVICH, J. P. Franklin Institute/Franklin Research Center NRC-03-B1-130 TER-C5506-375/396 DR 83/01/14 NRC --
No Detailed Affiliation Given 40pp 18735 284 24X
Fiche 50-280, 83/05/16, 8306030441

8306150064 COPPER IN THE INTAKE AND DISCHARGE ZONES OF THE SURRY AND SALEM NUCLEAR POWER STATIONS
HARRISON, F. L., KNEZOVICH, J. P. Lawrence Livermore Laboratory FIN A-0119, NUREG/CR-2969 83/05/31 Division of Health, Siting & Waste Management 31pp Available at NRC \$4.00 18869 221 24X
Fiche 50-000, 83/05/31, 8306150064

8306100170 Updates 82112 ltr providing info on schedule for submitting results of motor-operated valve studies & replacement of valves w/unsatisfactory starting capabilities Permanent schedule will be provided by 831215
STEWART, W. L. Virginia Electric & Power Co 83/06/03 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director, VARQA, B. A.
Operating Reactors Branch 1 2pp 18805 263 24X
Fiche 50-280, 83/06/03, 8306100170

8306170281 Advises that 821227 commitment to complete installation & testing of post-accident sampling sys per NUREG-0737, Item II B 3 by 830601 has been met Final procedures for sys will be complete by 830701
STEWART, W. L. Virginia Electric & Power Co. 83/06/14, DENTON, H. R.
Office of Nuclear Reactor Regulation, Director EISENHUT, D. O.
Division of Licensing 2pp 18877 025 24X Fiche: 50-280, 83/06/14, 8306170281

8306170327 Application supplementing 810921 & 820415 proposed changes to Tech Specs re fire protection sys. by deleting reporting requirements from Spec 3 21
STEWART, W. L. Virginia Electric & Power Co 83/06/14 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director VARQA, B. A.
Operating Reactors Branch 1 3pp 18877 001 24X
Fiche 50-280, 83/06/14, 8306170327

--8306170331 Suppl to proposed Tech Specs re fire protection sys
* Virginia Electric & Power Co 83/06/14 10pp, 18877 004 24
Fiche 50-280, 83/06/14, 8306170327

8306220033 Application to amend Licenses DPR-32 & DPR-37, changing Tech Specs by adding addl accident monitoring instrumentation & reactor vessel head vents per NUREG-0737, Items II F 1 & II B 1, respectively
STEWART, W. L. Virginia Electric & Power Co 83/06/16 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director VARQA, B. A.
Operating Reactors Branch 1 3pp 18927 233 24X
Fiche 50-280, 83/06/16, 8306220033

--8306220047 Proposed Tech Specs adding addl accident monitoring instrumentation & reactor vessel head vents, per NUREG-0737, Items II F 1 & II B 1, respectively
* Virginia Electric & Power Co 83/06/16 23pp 18927 237 24X
Fiche 50-280, 83/06/16, 8306220033

G Inspection reports, IE Bulletins & correspondence

8306140556 Confirms mgt meeting on 830217 in Richmond, VA to review results of first phase of annual appraisal of regulatory performance Proposed meeting agenda encl
LCWIS, R. C. Division of Project & Resident Programs 83/02/08.
STEWART, W. L. Virginia Electric & Power Co 3pp 18834 217 24X
Fiche 50-000, 83/02/08, 8306140556

8306140328 Confirms 830309 enforcement conference w/util to discuss Unit 1 821016 incident re containment spray sys chemical addition tank being valved out when required to be operable by Tech Specs Proposed meeting agenda encl
O'REILLY, J. P. Region 2, Office of Director 83/03/04 STEWART, J. L.
Virginia Electric & Power Co 2pp 18832 215 24X
Fiche 50-280, 83/03/04, 8306140328

8306140621 Forwards IE Insp Repts 50-280/82-31 & 50-281/82-31 on 821004-31 Enforcement action addressed in JP O'Reilly 830324 ltr
DANCE, H. C. Division of Project & Resident Programs 83/03/25.
STEWART, W. L. Virginia Electric & Power Co 2pp 18843 009 24X
Fiche 50-280, 83/03/25, 8306140621

--8306140627 IE Insp Repts 50-280/82-31 & 50-281/82-31 on 821004-31 Inoperable containment spray chemical addition tank identified following Unit 1 startup
BURNKE, D. J., DAVIS, M. J. Region 2, Office of Director JULIAN, C.
Division of Project & Resident Programs 83/03/24, 8pp, 18843 011 24X Fiche 50-280, 83/03/25, 8306140621.

8306140710 Submits confirmation of action ltr re 830408 & 11 telcons & 830405 enforcement meeting in Atlanta, GA re util failure to perform adequate radiological air sampling & to monitor personnel radiation exposure
O'REILLY, J. P. Region 2, Office of Director, 83/04/11. STEWART, W. L.
Virginia Electric & Power Co 2pp 18841 290 24X
Fiche 50-280, 83/04/11, 8306140710

8306140397 Forwards IE Insp Repts 50-280/83-12 & 50-281/83-12 on 830415-21 No noncompliance noted
DANCE, H. C. Region 2, Office of Director, 83/05/17 STEWART, W. L.
Virginia Electric & Power Co 2pp 18832 084, 24X
Fiche 50-280, 83/05/17, 8306140397

--8306140400 IE Insp Repts 50-280/83-12 & 50-281/83-12 on 830415-21 No noncompliance noted Major areas inspected: containment integrated leakage rate testing & pipe supports & restraints.
BRDOKS, E. H., JARPE, F. Region 2, Office of Director, 83/05/12, 3pp 18832 086 24X Fiche 50-280, 83/05/17, 8306140397

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Wall Logging Device," Svc list encl
TAYLOR, J. M. Division of Safeguards & Inspection Programs (Post 830103) 83/05/26, Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet," Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/26 Consolidated Edison Co of New York, Inc 115pp, 18732 085, 24X Fiche 50-000, 83/05/26, 8305110460.

DOCKETED ITEMS

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc 116pp 18732 208. 24X Fiche 50-000, 83/05/31, 8305110461

8306290331 Forwards response to IE Bulletin 83-08, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators " Surry has no valves in emergency diesel generator cooling sys Raw cooling water sys not used at North Anna
STEWART, W. L. Virginia Electric & Power Co 83/06/08 O'REILLY, J. P. Region 2, Office of Director 3pp 19055 303 24X Fiche 50-000, 83/06/08, 8306290331

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc 119pp. 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Mechanically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 118pp. 18920:225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc. 243pp 18921 001. 24X Fiche 50-000, 83/06/13, 8306090010

8306170138 Withdraws 830503 extension request for first 10-yr ASME Section XI inservice insp program Relief requested from code requirements re insp tolerance band for completion of interval insp requirements limited to 1 yr
STEWART, W. L. Virginia Electric & Power Co 83/06/14 DENTON, H. R. Office of Nuclear Reactor Regulation, Director VAROAN, S. A. Operating Reactors Branch 1 3pp 18878 355 24X Fiche 50-281, 83/06/14, 8306170138

8306200219 Revises 830603 response to Enforcement Action 83-36 contained in IE insp rept re whole body counts & other outage-related requirements Corrected Page 3 encl
STEWART, W. L. Virginia Electric & Power Co 83/06/15 DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 2pp 18902 286 24X Fiche 50-280, 83/06/15, 8306200219

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions. " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co. of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

R Periodic operating reports & related correspondence

8306020159 Forwards monthly operating repts for Mar 1983 & corrected pages to health physics rept for monthly operating repts for Jan & Feb 1983.
STEWART, W. L. Virginia Electric & Power Co. 83/04/14. HALLER, N. M. Office of Resource Management, Director 1p. 18691 006. 24X Fiche 50-280, 83/04/14, 8306020159

--8306020162 Monthly operating repts for Mar 1983.
JONES, V. Virginia Electric & Power Co 83/04/19 47pp 18691:007 24X Fiche 50-280, 83/04/19, 8306020159

--8306020168 Correct page to health physics rept for monthly operating rept for Jan 1983.
* Virginia Electric & Power Co. 83/04/14. 1p 18691.054. 24X Fiche 50-280, 83/04/14, 8306020159.

--8306020173 Corrected page to health physics rept for monthly operating rept for Feb 1983
* Virginia Electric & Power Co 83/04/14 1p 18691 055 24X Fiche 50-280, 83/04/14, 8306020159

8306160375 Monthly operating repts for Apr 1983 W/830513 ltr
JONES, V., STEWART, W. L. Virginia Electric & Power Co 83/05/13 48pp 18851 074 24X Fiche 50-280, 83/05/13, 8306160375

S Reportable occurrences, LERs & related correspondence

8306070238 Forwards LERs 83-022/03L-0 & 83-023/03L-0
WILSON, J. L. Virginia Electric & Power Co 83/05/27 O'REILLY, J. P. Region 2, Office of Director 1p 18744 222 24X Fiche 50-281, 83/05/27, 8306070238

--8306070243 LER 83-022/03L-0 on 830430, PT-27 revealed amp readings for heat tracing panel B, circuits 5A & 22A, below acceptance criteria Caused by excessive heat Defective heat tracing replaced & tested Design change prepared
WILSON, J. L. Virginia Electric & Power Co 83/05/27 Region 2, Office of Director 2pp 18744 223 24X Fiche 50-281, 83/05/27, 8306070238

--8306070245 LER 83-023/03L-0 on 830511, PT 2/B revealed amp readings for heat tracing panel 9, circuit 28A, below acceptance criteria Caused by basic acid buildup on heat tape, corroding terminals & resulting in open circuit Heat tracing replaced
WILSON, J. L. Virginia Electric & Power Co 83/05/27 Region 2, Office of Director 2pp 18744 225 24X Fiche 50-281, 83/05/27, 8306070238

8306100186 LER 83-024/03L-0 on 830517, PT-27D revealed that ampere readings for heat tracing Panel B, Circuit 13C below acceptance criteria in PT-27D Caused by excessive heat Defective heat tracing replaced W/830503 ltr
WILSON, J. L. Virginia Electric & Power Co 83/06/03 O'REILLY, J. P. Region 2, Office of Director 3pp 18806 021 24X Fiche 50-281, 83/06/03, 8306100186

8306270351 Forwards LERs 83-025/03L-0 & 83-026/03L-0
WILSON, J. L. Virginia Electric & Power Co 83/06/13 O'REILLY, J. P. Region 2, Office of Director 1p 18993 143 24X Fiche 50-281, 83/06/13, 8306270351

--8306270357 LER 83-025/03L-0 on 830518, w/unit at 100% power, MOV-SW-202B failed to close electrically from control room Caused by rust buildup between clutch & motor operator housing Rust removed
WILSON, J. L. Virginia Electric & Power Co 83/06/13 Region 2, Office of Director 2pp 18993 144. 24X Fiche 50-281, 83/06/13, 8306270351

--8306270364 LER 83-026/03L-0 on 830516, w/unit at 100% power, breaker for MOV-SW-202B found open & motor grounded Cause unknown Breaker could have been accidentally bumped Motor dried due to moisture & breaker closed
WILSON, J. L. Virginia Electric & Power Co 83/06/13 Region 2, Office of Director 3pp 18993.146 24X Fiche 50-281, 83/06/13, 8306270351.

8306300199 LER 83-027/03L-0 on 830523, PT-27C revealed that amp reading for heat tracing panel B, circuit 28A below Tech Spec limit. Caused by excessive heat Heat tracing replaced Design change initiated W/830620
WILSON, J. L. Virginia Electric & Power Co. 83/06/20 O'REILLY, J. P. Region 2, Office of Director. 3pp 19122 177 24X Fiche 50-281, 83/06/20, 8306300199.

DOCKET 50-282 PRAIRIE ISLAND NUCLEAR STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8306100059 "Control Room Design Review Plan, Prairie Island Nuclear Generating Plant," response to Generic Ltr 82-33, Suppl 1 to NUREG-0737 W/830527 ltr
MUSOLF, D. Northern States Power Co 83/05/27 47pp 18802 123 24X Fiche 50-282, 83/05/27, 8306100059

8306090237 Forwards "Emergency Operating Procedures Generation Package," in response to Generic Ltr 82-33, Suppl 1 to NUREG-0737.
MUSOLF, D. Northern States Power Co. 83/05/31. Office of Nuclear Reactor Regulation, Director 1p 18797 001 24X Fiche 50-282, 83/05/31, 8306090237

--8306090239 "Emergency Operating Procedures Generation Package " * Northern States Power Co 83/05/31. 16pp. 18797.002 24X Fiche 50-282, 83/05/31, 8306090237.

DOCKETED ITEMS

95

8306090254 Releases public version of revised emergency plan implementing procedures
FELTON, J. M. Division of Rules and Records 83/06/01 Document Management Branch 1p 18809 261 24X Fiche 50-282, 83/06/01, 8306090254

--8306090257 Forwards public version of revised emergency plan implementing procedures, including Procedures A 2-301 re emergency evacuation, A 2-3-2 re assembly point activation & A 2-303 re search & rescue
WARD, E. C. Northern States Power Co 83/05/17 Region 3, Office of Director 1p 18809 262 24X Fiche 50-282, 83/06/01, 8306090254

--8306090261 Public version of revised emergency plan implementing procedures, including Procedures A 2-301 re emergency evacuation, A 2-302 re assembly point activation & A 2-303 re search & rescue
FEY, F. L. Northern States Power Co 83/05/09 112pp 18809 263 24X Fiche 50-282, 83/06/01, 8306090254

8306090263 Forwards Rev 9 pages for security plan Pages withheld (ref 10CFR73)
MUSOLF, D. Northern States Power Co 83/06/06 Office of Nuclear Reactor Regulation, Director 1p 10795 279 24X Fiche 50-282, 83/06/06, 8306090263

8306230073 Releases public version of revised emergency plan implementing procedures
FELTON, J. M. Division of Rules and Records 83/06/06 Document Management Branch 1p 18782 186 24X Fiche 50-282, 83/06/06, 8306230073

--8306230079 Forwards public version of revised emergency plan implementing procedures, including Procedures F3-3 re responsibilities during notification of unusual event & F3-13 re offsite dose calculation
WARD, E. C. Northern States Power Co 83/05/16 Region 3, Office of Director 1p 18782 187 24X Fiche 50-282, 83/06/06, 8306230073

--8306230087 Public version of revised emergency plan implementing procedures, including Procedures F3-3 re responsibilities during notification of unusual event, F3-13 re offsite dose calculation & F3-14 2 re operations emergency surveys
SCHUELKKE, D. A. Northern States Power Co 83/04/26 Region 3, Office of Director 91pp 18782 188 24X Fiche 50-282, 83/06/06, 8306230073

8306280459 Informs that operational data for completion of HEPA filtration sys extended to 831001 due to difficulty in adopting ventilation sys to accommodate demands of HEPA filtration per Suppl 1 to NUREG-0737
MUSOLF, D. M. Northern States Power Co 83/06/20 Office of Nuclear Reactor Regulation, Director 1p 19018 328 24X Fiche 50-000, 83/06/20, 8306280459

P Operating license stage documents & correspondence

8306010349 Forwards updated equipment lists reflecting plant mods, current NRC views & licensee continuing review, in response to 10CFR90.49, "Environ Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants"
MUSOLF, D. M. Northern States Power Co 83/05/19 Office of Nuclear Reactor Regulation, Director 60pp. 18680 091 24X Fiche 50-282, 83/05/19, 8306010349

8306090230 Submits 30-day response to NRC 830425 safety evaluation of environ qualification of safety-related electrical equipment. Facility can operate safely while environ qualification deficiencies being resolved
MUSOLF, D. Northern States Power Co. 83/05/27, Office of Nuclear Reactor Regulation, Director 2pp 18795 346 24X Fiche 50-282, 83/05/27, 8306090230

8306200281 Advises that justification for continued operation re environ qualification of safety-related electrical equipment acceptable Rosemount transmitters 1152 Series D reclassified from NRC Category II B to II C.
CLARK, R. A. Operating Reactors Branch 3 83/06/03, MUSOLF, D. M. Northern States Power Co 2pp 18919, 264, 24X Fiche 50-282, 83/06/03, 8306200281

--8306200283 Safety evaluation supporting justification for continued operation w/safety-related equipment unqualified
* Office of Nuclear Reactor Regulation, Director 83/06/06 2pp. 18919, 266 24X Fiche 50-282, 83/06/03, 8306200281

8306170053 Concurs w/findings contained in technical evaluation rept, "Control of Heavy Loads." Guidelines in NUREG-0612, Section 5.1.1 satisfied, per util 810402, 0715, 0831 & 1209, 820203 & 1108 & 830408 submittals
CLARK, R. A. Operating Reactors Branch 3 83/06/06 MUSOLF, D. M. Northern States Power Co 2pp 18906 314 24X Fiche 50-282, 83/06/06, 8306170053

--8306170058 Safety evaluation supporting util Phase 1 actions re control of heavy loads NUREG-0612, Section 5.1.1 guidelines satisfied
* Office of Nuclear Reactor Regulation, Director 83/06/06, 1p. 18906 316 24X Fiche 50-282, 83/06/06, 8306170053

--8305230021 "Control of Heavy Loads (C-10), Prairie Island Nuclear Generating Plant, Units 1 & 2," technical evaluation rept VOSBURY, F. W. Franklin Institute/Franklin Research Center, NRC-03-81-130 TER-C5306-384/385 83/05/17 NRC - No Detailed Affiliation Given 31pp. 66794 188 24X Fiche 50-282, 83/06/06, 8306170053

8306200390 Forwards safety & licensing portion of Westinghouse Apr 1982 rept, providing addl info re fuel assembly failure effect on insertion of control rods or core cooling geometry
MUSOLF, D. Northern States Power Co 83/06/07, Office of Nuclear Reactor Regulation, Director 2pp 18899 032 24X Fiche 50-282, 83/06/07, 8306200390.

Q Inspection reports, IE Bulletins & correspondence

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device." Svc list encl
TAYLOR, J. M. Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458.

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 115pp. 18732 085, 24X Fiche 50-000, 83/05/26, 8305110460.

8306060084 Commends NRC re results of piping insp at BWRs. Leak-before-break concept continues to sustain validity of technical bases Utilis giving consideration to more permanent measures
NEILS, O. H. Northern States Power Co 83/05/26 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 18719 335 24X Fiche 50-000, 83/05/26, 8306060084.

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461.

8306170232 Submits list of affected valves, test method & test schedule in response to IE Bulletin 83-03. Inservice insp program will be revised to include testing of listed valves
LARSON, C. E. Northern States Power Co 83/06/08 KEPPNER, J. O. Region 3, Office of Director 2pp 18878 284, 24X Fiche 50-282, 83/06/08, 8306170232.

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc 119pp 18830 280, 24X Fiche 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc. 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470.

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 243pp 18921 001, 24X Fiche 50-000, 83/06/13, 8306090010.

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 115pp. 19021 177, 24X Fiche 50-000, 83/06/22, 8305110475.

DOCKETED ITEMS

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co. of New
York, Inc. 120pp. 18997 007 24X Fiche 50-000, 83/06/22, 8305110477.

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co. of New
York, Inc. 116pp. 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co. of New
York, Inc. 116pp. 19046:297 24X Fiche 50-000, 83/06/24, 8305110483

8306280340 Requests relief from requirement re 10-yr inservice insp of reactor coolant pump casing welds of ASME Boiler & Pressure Vessel Code, Section XI, "Inservice Insp" Request submitted as Rev 9 to inservice insp & testing program
HUSOLF, D Northern States Power Co. 83/06/24 Office of Nuclear
Reactor Regulation, Director. 3pp 19014 070 24X
Fiche 50-285, 83/06/24, 8306280340

--8306280345 Rev 9 to "ASME Code Section XI Inservice Insp & Testing Program"
Northern States Power Co. 83/06/24 9pp 19014 073. 24X
Fiche 50-285, 83/06/24, 8306280345

R. Periodic operating reports & related correspondence

8306020167 Monthly operating repts for Mar 1983 W/830411 ltr
HUSOLF, D, DUOSTAD, D Northern States Power Co 83/04/05 9pp.
18691:075. 24X Fiche 50-285, 83/04/05, 8306020167.

8306140002 Monthly operating repts for May 1983 W/830607 ltr.
DUOSTAD, D, HUSOLF, D Northern States Power Co 83/06/07 Office
of Resource Management, Director 9pp. 18938:219 24X
Fiche 50-285, 83/06/07, 8306140002

DOCKET 50-285 FORT CALHOUN STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8306090029 Releases public version of changes to radiological emergency response plan.
FELTON, J M Division of Rules and Records. 83/06/01 Document
Management Branch 1p 18798:022 24X Fiche 50-285, 83/06/01,
8306090029

--8306090032 Forwards public version of changes to radiological emergency response plan w/o encl
JONES, W C Omaha Public Power District. 83/05/11, COLLINS, J T.
Region 4, Office of Director 1p 18798:023 24X
Fiche 50-285, 83/06/01, 8306090032.

8306160346 Releases public version of changes to emergency plan implementing procedures.
FELTON, J M. Division of Rules and Records. 83/06/06 Document
Management Branch. 1p. 18872:168. 24X Fiche 50-285, 83/06/06,
8306160346

--8306160354 Forwards public version of changes to emergency plan implementing procedures, w/o encl.
JONES, W C. Omaha Public Power District 83/05/25 COLLINS, J. T.
Region 4, Office of Director 1p. 18872:169 24X
Fiche 50-285, 83/06/06, 8306160354

8306210359 Releases public version of changes to emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/06/06. Document
Management Branch 1p. 18935:242. 24X Fiche 50-285, 83/06/06,

version of changes to emergency plan
encl
for District. 83/04/27. COLLINS, J. T.
1p. 18935:241 24X
0359.

P Operating license stage documents & correspondence

8306300069 Forwards status of evaluation for sampling waste decay tanks & data from RCB gas sampling program, in response to NRC 830329 ltr
JONES, W C Omaha Public Power District 83/04/28 SEIDL, W C
Region 4, Office of Director 96pp 1904B 001 24X
Fiche 50-285, 83/04/28, 8306300069

8306040193 Forwards list of revised alternate shutdown panel (AI-185) drawings as of 830420 Drawing 13007 42-ESK-11D canceled
JONES, W C. Omaha Public Power District 83/05/02 SEIDL, W C
Region 4, Office of Director 4pp 18719 162 24X
Fiche 50-285, 83/05/02, 8306040193

8306010003 Notice of consideration of issuance of amend to OL & proposed no significant hazards consideration determination & opportunity for hearing re RCB pressure-temp limit curves Encl determination available in Central Files only
CLARK, R A Operating Reactors Branch 3 83/05/12 9pp 18483 232
24X Fiche 50-285, 83/05/12, 8306010003

8306080247 Advises that proposal to bypass certain reactor protection sys channels for more than 48 h, per 810782 application & 820615 & 1027 ltrs, unacceptable for listed reasons Addl info requested within 30 days of receipt of ltr
CLARK, R A Operating Reactors Branch 3 83/05/23 JONES, W C
Omaha Public Power District 18pp 18785 331 24X
Fiche 50-285, 83/05/23, 8306080247

8306160159 Discusses 830412 meeting w/utilis re damage to reactor thermal shield support lugs at St Lucie 1 Safety evaluation concluding that continued operation justified encl
CLARK, R A Operating Reactors Branch 3 83/06/01 JONES, W C
Omaha Public Power District 2pp 18892 355 24X
Fiche 50-285, 83/06/01, 8306160159

--8306160164 Safety evaluation supporting continued operation of facility based on until familiarity w/thermal shield concerns
* NRC - No Detailed Affiliation Given. 83/06/01 4pp
18892 357 24X Fiche 50-285, 83/06/01, 8306160159

8306100102 Application to amend License DPR-40, changing Tech Specs re proposed spent fuel storage rack mod
JONES, W C Omaha Public Power District 83/06/04 CLARK, R A
Operating Reactors Branch 3. 1p 18802 211 24X
Fiche 50-285, 83/06/04, 8306100102

--8306100106 Proposed Tech Specs re spent fuel storage rack mod
* Omaha Public Power District 83/06/06 15pp 18802:212 24X
Fiche 50-285, 83/06/06, 8306100102

8306130260 Comments on NUREG/CR-2337, Vols 1 & 4, "Aquatic Impacts From Operation of Three Midwestern Nuclear Power Stations"
Author evaluation & conclusions differ from util understanding gained in studies Supporting info encl
JONES, W C Omaha Public Power District 83/06/06 VOLLMER, R H
Division of Engineering 40pp 18824 194 24X
Fiche 50-285, 83/06/06, 8306130260

8306160491 Forwards in-process OL amend requests currently being evaluated by NRC, in response to final rules, effective 830506, specifying that when licensee request amend to OL, licensee must notify appropriate State designer
TOURIGNY, E Q Operating Reactors Branch 3 83/06/06 SIMMONS, H E
North Dakota, State of 2pp 18876 288 24X Fiche 50-285, 83/06/06,
8306160491

8306200065 Monthly notice of amends to OLs involving no significant hazards consideration, notice of consideration of issuance of amend to License DPR-40 & proposed no significant hazards determination & opportunity for hearing
CLARK, R A Operating Reactors Branch 3 83/06/07 16pp
18908 311. 24X Fiche 50-285, 83/06/07, 8306200065

8306290081 Requests FR notice of consideration of issuance of amend to License DPR-34 & proposed no significant hazards consideration determination re addl assurance that objectives of App 1 met
CLARK, R A Operating Reactors Branch 3 83/06/13 KREUTZER, P M.
Operating Reactors Branch 3 2pp. 19046.165. 24X
Fiche 50-285, 83/06/13, 8306290081.

8306270105 Forwards results of C-E analysis of effects of dropped thermal shield, per 830601 request Results do not differ significantly from NRC preliminary assessment.
JONES, W C Omaha Public Power District. 83/06/17. CLARK, R. A.
Operating Reactors Branch 3 2pp. 18988.113 24X
Fiche 50-285, 83/06/17, 8306270105.

8306290198 Forwards safety evaluation concluding that requirements of TMI Items II F 1 4, II F 1 5 & II F 1 6 re containment pressure, water level & hydrogen monitors met items resolved
CLARK, R A Operating Reactors Branch 3 83/06/17 JONES, W C
Omaha Public Power District 7pp 19046 271 24X
Fiche 50-285, 83/06/17, 8306290198

8306240347 Requests publication of FR notice re issuance of Amend 74 to License DPR-40 concerning RCS pressure-temp limits for operation to 7 0 effective full power yrs
CLARK, R A Operating Reactors Branch 3 83/06/20 KREUTZER, P M
Operating Reactors Branch J 1p 18777 170 24X
Fiche 50-285, 83/06/20, 8306240347

8306280073 Forwards Amend 74 to License DPR-40 & safety evaluation Amend revises Tech Specs for RCS pressure-temp limits for operation to 7 0 effective full power yrs
TOURIGNY, E O Operating Reactors Branch 3 83/06/20 JONES, W C
Omaha Public Power District 2pp 19042 321 24X
Fiche 50-285, 83/06/20, 8306280073

--8306280075 Amend 74 to License DPR-40, revising Tech Specs for RCS pressure-temp limits for operation to 7 0 effective full power yrs
CLARK, R A Operating Reactors Branch 3 83/06/20 18pp
19042 323 24X Fiche 50-285, 83/06/20, 8306280075

--8306280078 Safety evaluation supporting Amend 74 to License DPR-40
* Office of Nuclear Reactor Regulation, Director 83/06/20 3pp
19042 341 24X Fiche 50-285, 83/06/20, 8306280078

8306280233 Forwards correct version of App A, "Mechanical Errors From NUREG/CR-2337, Vol 1, Aquatic Impacts From Operation of Three Midwestern Nuclear Power Plants" Draft version inadvertently attached to 830606 submittal
JONES, W C Omaha Public Power District 83/06/22 VOLLMEYER, R H
Division of Engineering 10pp 19015 088 24X
Fiche 50-285, 83/06/22, 8306280233

8306280487 Discusses problems w/post-accident sampling sys (PASS) microprocessor, on-line pH meter sample flow & ion chromatograph Proposed PASS completion per NUREG-0737, Item II D 3, scheduled for 830930
JONES, W C Omaha Public Power District 83/06/23 CLARK, R A
Operating Reactors Branch 3 3pp 19019 186 24X
Fiche 50-285, 83/06/23, 8306280487

8306280464 Responds to 830523 ltr re Tech Spec amend application concerning inoperability of reactor protection sys (RPS) channels Meeting requested to resolve differences between util & NRC Tech Spec amend proposals
JONES, W C Omaha Public Power District 83/06/24 CLARK, R A
Operating Reactors Branch 3 2pp 19020 133 24X
Fiche 50-285, 83/06/24, 8306280464

G Inspection reports, IE Bulletins & correspondence

8306080231 Ack receipt of 830223 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-285/82-21 Addl info re sampling equipment & techniques, especially for games, requested within 30 days of ltr date
SEIDLE, W C Region 4, Office of Director 83/03/29 JONES, W C
Omaha Public Power District 2pp 18771 001 24X
Fiche 50-285, 83/03/29, 8306080231

--8306080236 Responds to NRC 830117 ltr re violations noted in IE Insp Rept 50-285/82-21. Corrective actions program implemented to cross-calibr Canberra & TN-J1 gamma spectrometer sys Program expected to be completed by 830401
JONES, W C Omaha Public Power District, 83/02/23 SEIDLE, W C
Region 4, Office of Director 1p, 10771 003 24X
Fiche 50-285, 83/03/29, 8306080231

8306080109 Forwards IE Insp Rept 50-285/83-03 on 830117-21 & notices of violation & deviation
SEIDLE, W C Region 4, Office of Director 83/04/13 JONES, W C
Omaha Public Power District 2pp 18771 253 24X
Fiche 50-285, 83/04/13, 8306080109

--8306080129 Notice of violation from insp on 830117-21
* Region 4, Office of Director 83/04/13 1p 18771 255 24X
Fiche 50-285, 83/04/13, 8306080109

--8306080134 Notice of deviation from insp on 830117-21.
* Region 4, Office of Director 83/04/13 1p 18771 256 24X
Fiche 50-285, 83/04/13, 8306080109

--8306080211 IE Insp Rept 50-285/83-03 on 830117-21 Noncompliance noted bag containing radioactive matl observed in noncompactible waste bin & w/o hot spot sticker attached
WILBORN, L, MURRAY, B, JOHNSON, W D Region 4, Office of Director
83/03/29 12pp 18771 257 24X Fiche 50-285, 83/04/13, 8306080109

8306090349 Forwards IE Insp Rept 50-285/83-06 on 830307-11 No noncompliance noted
SEIDLE, W C Region 4, Office of Director 83/04/13 JONES, W C
Omaha Public Power District 3pp 18795 150 24X
Fiche 50-285, 83/04/13, 8306090349

--8306090354 IE Insp Rept 50-285/83-06 on 830307-11 No noncompliance noted Major areas inspected radwaste sys & qualification criteria for supervisor of chemical radiation protection
CHANEY, H D, MURRAY, B, JOHNSON, W D Region 4, Office of Director,
83/04/12 17pp 18795 153 24X Fiche 50-285, 83/04/13, 8306090349

8306130364 Responds to IE Bulletin 83-03 re check valve failures in diesel generator raw water cooling sys. Check valves not used at facility
JONES, W C Omaha Public Power District 83/05/20 COLLINS, J T,
Region 4, Office of Director 3pp 18822 161 24X
Fiche 50-285, 83/05/20, 8306130364

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post
830103) 83/05/26, Consolidated Edison Co. of New York, Inc.
129pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co. of New
York, Inc 119pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at DHRs" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/31 Consolidated Edison Co. of New
York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306160159 Discusses 830412 meeting w/util re damage to reactor thermal shield support lugs at St Lucie 1 Safety evaluation concluding that continued operation justified encl.
CLARK, R A Operating Reactors Branch 3 83/06/01 JONES, W C
Omaha Public Power District, 2pp 18872 353 24X
Fiche 50-285, 83/06/01, 8306160159

--8306160164 Safety evaluation supporting continued operation of facility based on until familiarity w/thermal shield concerns
* NRC - No Detailed Affiliation Given 83/06/01 4pp.
18892 357 24X Fiche 50-285, 83/06/01, 8306160159

8306130117 Ack receipt of 830520 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-285/83-09.
SEIDLE, W C Region 4, Office of Director, 83/06/06 JONES, W C
Omaha Public Power District 1p 18824 295 24X
Fiche 50-285, 83/06/06, 8306130117

--8306130130 Responds to NRC 830422 ltr re violations noted in IE Insp Rept 50-285/83-09 Corrective actions, change to Standing Order Q-30 to require that spot changes be specifically noted within text of procedures initiated
JONES, W C Omaha Public Power District 83/05/20, SEIDLE, W C,
Region 4, Office of Director, 2pp 18824 296 24X
Fiche 50-285, 83/06/06, 8306130117

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/09 Consolidated Edison Co. of New
York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Electrically Induced Chatter in Relays Within Printed Circuit Cards" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co. of New
York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co. of New
York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

DOCKETED ITEMS

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 115pp 1902i 177 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18997 007. 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co. of New York, Inc. 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc. 116pp 19046, 297 24X Fiche 50-000, 83/06/24, 8305110483

R. Periodic operating reports & related correspondence

8306200358 Monthly operating rpt for May 1983, W/830614 ltr.
MATTHEWS, T. P., JONES, W. C. Omaha Public Power District 83/06/14
DEVOUNG, R. C. Director's Office, Office of Inspection and Enforcement 11pp. 18901 020 24X Fiche: 50-285, 83/06/14, 8306200358.

S Reportable occurrences, LERs & related correspondence

8306060299 Corrected LER 82-017/03L-i on 820830, valve position indication not noticed for inboard containment isolation valves HCV-820B & 821B, associated w/hydrogen monitor VA-81A Caused by failure of Conax environ seals. W/830525 ltr
CORE, M. R., JONES, W. C. Omaha Public Power District. 82/09/29
BEIDLE, H. C. Region 4, Office of Director, 6pp. 18729, 043. 24X Fiche: 50-285, 82/09/29, 8306060299

DOCKET 50-286 INDIAN POINT STATION, UNIT 3

F Security, medical, emergency & fire protection plans

8306200403 Forwards exercise objectives & scenario outline for small-scale emergency preparedness exercise scheduled for 830602, in response to NRC 811026 exercise guidelines
BRONK, J. C. Power Authority of the State of New York. 83/03/17
HAYNES, R. C. Region 1, Office of Director, 6pp 18899, 304 24X Fiche: 50-286, 83/03/17, 8306200403

--8306200411 Forwards small-scale emergency preparedness exercise scenario per guidelines established in NRC 811026 ltr. Scenario outline & expected time frame for events also encl.
BRONK, J. C. Power Authority of the State of New York 83/04/22.
ALLAN, J. A. Region 1, Office of Director, 195pp. 18899: 311. 24X Fiche: 50-286, 83/03/17, 8306200403

8306030343 Ack receipt of 830128 ltr in response to NRC 821104 ltr re IE Insp Rpt 50-286/82-09, Effective coverage by radial-type nozzles not addressed in safety evaluation. Addl info requested 830228 not received
MARTIN, T. T. Division of Engineering & Technical Programs. 83/05/23.
BRONK, J. C. Power Authority of the State of New York. 5pp. 18703: 012. 24X Fiche: 50-286, 83/05/23, 8306030343

--8306030345 Forwards addl info re installation of radial pattern sprinkler nozzles in lieu of previously committed closed head, horizontal side-wall type, per IE Insp Rpt 50-286/82-09.
BRONK, J. C. Power Authority of the State of New York 83/01/28.
MARTIN, T. T. Division of Engineering & Technical Programs. 5pp 18705: 014. 24X Fiche: 50-286, 83/05/23, 8306030343

8306220243 Forwards SERs on seismic qualification of auxiliary feedwater sys & fire protection interim measures re restart. Plant provides sufficient electrical redundancy & reliability for interim operation.
VARQA, S. A. Operating Reactors Branch 1. 83/05/27. BAYNE, J. P. Power Authority of the State of New York. 5pp. 18955: 116. 24X Fiche: 50-286, 83/05/27, 8306220243

--8306220251 Safety evaluation re seismic qualification of auxiliary feedwater sys. Sys capable of withstanding SSE since open items re turbine automatic speed control & instrument air piping, identified in encl technical rpt, resolved
* Office of Nuclear Reactor Regulation, Director. 83/05/27. 12pp. 18951: 121. 24X Fiche: 50-286, 83/05/27, 8306220243.

--8306220261 Safety evaluation re fire protection interim measures
Licensee actions demonstrate that interim alternate power supplies will be available until long-term 10CFR50, App R, requirements satisfied
* Office of Nuclear Reactor Regulation, Director 83/05/27 2pp 18951 133 24X Fiche 50-286, 83/05/27, 8306220243

8306090299 Confirms by ltr of intent, contract to make buses available during evacuation caused by radiological emergency.
VHAAD, E. R. Consolidated Edison Co. of New York, Inc. * Power Authority of the State of New York. CORWIN, S. Affiliation Unknown 83/06/01 CORWIN, S. Affiliation Unknown 1p 18795 238 24X Fiche 50-247, 83/06/01, 8306090299

8306090317 Confirms, by ltr of intent, contract to make buses available during evacuation caused by radiological emergency
VHAAD, E. R. Consolidated Edison Co. of New York, Inc. BAYNE, J. P. Power Authority of the State of New York * Affiliation Unknown 83/06/01 SILVANO, J. Affiliation Unknown 1p 18795 230 24X Fiche 50-247, 83/06/01, 8306090317

8306090325 Confirms, by ltr of intent, contract to make buses available during evacuation caused by radiological emergency
* Consolidated Edison Co. of New York, Inc. BAYON, J. P. Power Authority of the State of New York MURPHY, J. Liberty Lines Transit, Inc. 83/06/02 MURPHY, J. Liberty Lines Transit, Inc. 1p 18795 069 24X Fiche 50-247, 83/06/02, 8306090325

8306090340 Confirms, by ltr of intent, contract to make buses available during evacuation caused by radiological emergency
* Consolidated Edison Co. of New York, Inc. BAYON, J. P. Power Authority of the State of New York * Riverdale Transit Corp 83/06/02 MURPHY, J. Riverdale Transit Corp 1p 18794 321 24X Fiche: 50-247, 83/06/02, 8306090340

8306090302 Forwards application for amend to License DPR-64, changing Tech Specs re fire protection mods, in response to SA Varga 830421 ltr Procedures re alternate electrical feed sys operation will be at site prior to startup
BAYNE, J. P. Power Authority of the State of New York 83/06/03 VARQA, S. A. Operating Reactors Branch 1 2pp 18795 242 24X Fiche: 50-286, 83/06/03, 8306090302

--8306090304 Application to amend License DPR-64, changing Tech Spec Sections 3.3.3, 14 & 4.12 re fire protection mods, in response to SA Varga 830421 ltr
BAYNE, J. P. Power Authority of the State of New York 83/06/03 1p. 18795 244 24X Fiche 50-286, 83/06/03, 8306090302

--8306090307 Proposed Tech Specs re fire protection mods.
* Power Authority of the State of New York 83/06/30 11pp 18795 245 24X Fiche 50-286, 83/06/03, 8306090302

8306150206 Staff requirements memo re 830526 oral presentations in Bethesda, MD re emergency planning & preparedness at Indian Point. List of participants encl
CHILK, B. J. Office of the Secretary of the Commission 83/06/07
Office of the Secretary of the Commission 2pp 18870 045. 24X Fiche 50-247, 83/06/07, 8306150206

8306170396 Forwards FEMA 830608 ltr to NRC, providing current evaluation of plant offsite emergency planning
HABSELL, D. F. Hearing Branch 2 83/06/09 GLEASON, J. P. Atomic Safety and Licensing Board Panel 46pp 18879 333 24X Fiche 50-247, 83/06/09, 8306170396

8306200030 Staff requirements memo re 830609 discussion & vote in Washington, DC on continued operation of Indian Point Commission agreed by vote of 3-2 to allow continued operation.
CHILK, B. J. Office of the Secretary of the Commission. 83/06/14
Office of the Secretary of the Commission 1p 18908 356 24X Fiche: 50-247, 83/06/14, 8306200030.

8306210138 Requests clarification of NRC position re approval of security plan reys Util will adhere to revised security plan until NRC authorization received to commence 2-yr implementation period.
BAYNE, J. P. Power Authority of the State of New York. 83/06/15 VARQA, S. A. Operating Reactors Branch 1 2pp 18916 347 24X Fiche: 50-286, 83/06/15, 8306210138.

G Adjudicatory correspondence

8306010451 Supports continued operation of facility. Impact of shutdown would be devastating.
O'SHAUGHNESSY Affiliation Unknown 83/05/20. PALLADINO, N. J. Commissioners 2pp. 18674: 352 24X Fiche 50-247, 83/05/20, 8306010451

DOCKETED ITEMS

99

8306040180 Response opposing util 830809 motion for reconsideration
Deposition inadmissible as evidence under federal rules
POSENER, P Parents Concerned About Indian Point 83/05/20 Atomic
Safety and Licensing Board Panel 3pp 18728 181 24X
Fiche 50-247, 83/05/20, 8306040180

8306010458 Requests extension of 830609 deadline for planners to
provide adequate emergency evacuation Util acting in good
faith in expressing concern for quality of life of
community residents
BARNETT, T Affiliation Unknown 83/05/24 PALLADINO, N J
Commissioners 1p 18674 327 24X Fiche 50-247, 83/05/24,
8306010458

8306010348 Response supporting licensee 830509 motion for
reconsideration of ruling on admissibility of DP McGuire
disposition Admission of testimony would not prejudice
parties W/Certificate of Svc
HASSELL, D F Hearing Branch 1 83/05/31 Atomic Safety and
Licensing Board Panel 11pp 18681 336 24X Fiche 50-247, 83/05/31,
8306010348

8306020443 Order requesting comments on encl rept re PRA by 830620
GLEASON, J P Atomic Safety and Licensing Board Panel 83/05/31
Consolidated Edison Co of New York, Inc 1p 18694 011 24X
Fiche 50-247, 83/05/31, 8306020443

--8306020448 Forwards final rept, "Analysis of PRA Testimony Indian Point
ASLB Hearings, Commission Question 1 " Rept conclusions
coincide w/conclusions in 830502 ltr
AMICO, P J Applied Risk Technology Corp 83/06/01 GLEASON, J P,
SHON, F J, PARIB, O H Atomic Safety and Licensing Board Panel
1p. 18694 012, 24X Fiche 50-247, 83/05/31, 8306020443

--8306020452 "Analysis of PRA Testimony Indian Point ASLB Hearings,
Commission Question 1," final rept
AMICO, P J Applied Risk Technology Corp ARTECH-83-001
83/06/01 NRC - No Detailed Affiliation Given 67pp,
18694 013 24X Fiche 50-247, 83/05/31, 8306020443

8306200290 Affidavit of RA Rosen on Commission Question 6 3 EBR0 model
underestimated average 1982 saltwater PWR capacity by 9 %
Value of model should be assessed based on ability to track
experiences over period of time
ROSEN, R A Greater New York Council on Energy 83/05/31, 5pp
18701 055 24X Fiche 50-247, 83/05/31, 8306200290

8306070414 Response opposing Friends of the Earth/New York City Audubon
Soc request to file I Levi affidavit Testimony by affidavit
improper since no cross-examination possible Certificate of
Svc encl
BRANDENBURG, B Consolidated Edison Co. of New York, Inc.
COLARULLI, P F Power Authority of the State of New York
COLARULLI, P F Morgan Associates 83/06/03 Atomic Safety and
Licensing Board Panel 7pp 18742 264 24X Fiche 50-247, 83/06/03,
8306070414

8306070421 Expresses views on plant emergency preparedness in light of
newly submitted state of NY interim plan. Conceptual problems
& inaccuracies identified in plan for implementing
compensating measures for Rockland County
HOLT, J Public Interest Research Group, New York 83/06/03
PALLADINO, N J, AHEARNE, J F, OILINSKY, V Commissioners 4pp
18742 198 24X Fiche 50-247, 83/06/03, 8306070421

8306080200 Comments on "Governors Plan" prepared by NY State Disaster
Commission Evacuation of wheelchair & bedridden patients
& shelter for 1,200 mentally retarded patients overlooked
FLEISHNER, Z B West Branch Conservation Association 83/06/06
PALLADINO, N J, OILINSKY, V, AHEARNE, J F Commissioners 16pp
18770, 235, 24X Fiche 50-247, 83/06/06, 8306080200

8306090359 Responds to Commission 830526 meeting questions & updates
miscellaneous responses Record justifies continued plant
operation Commission would be fully justified in suspending
further enforcement action.
CONWAY, J T Consolidated Edison Co of New York, Inc BAYNE, J P,
Power Authority of the State of New York 83/06/07 PALLADINO, N J,
OILINSKY, V, AHEARNE, J F Commissioners 3pp, 18795 036 24X
Fiche 50-247, 83/06/07, 8306090359

8306090300 Recommendations for emergency planning process Plans should
originate at local govt level & should be supported &
enforced at state & federal govt levels
* Public Interest Research Group, New York, * Parents Concerned
About Indian Point, 83/06/08 2pp, 18795:239, 24X
Fiche: 50-247, 83/06/08, 8306090300

8306090308 Statement on role of federal, state & local govts & utils in
planning, testing & executing emergency response procedures.
HOLT, J, Public Interest Research Group, New York, 83/06/08, 3pp,
18795:119 24X Fiche 50-247, 83/06/08, 8306090308

8306100086 Forwards evaluation of offsite emergency planning, providing
factual basis for use in Commission 830609 licensing
decision
BRAGG, J B Federal Emergency Management Agency 83/06/08
PALLADINO, N J Commissioners 45pp 18802:046 24X
Fiche 50-247, 83/06/08, 8306100086

8306100209 Memorandum & order denying licensee 830509 motion for
reconsideration of ASLB 830429 ruling disallowing admission
into evidence of DP McGuire deposition Federal rule
inapplicable & no exceptional circumstances shown.
GLEASON, J P Atomic Safety and Licensing Board Panel 83/06/08
Consolidated Edison Co of New York, Inc 4pp 18805:202, 24X
Fiche: 50-247, 83/06/08, 8306100209

8306130434 Order ruling I Levi affidavit, filed by Friends of the Earth
& New York City Audubon Soc on 830510, inadmissible. Affidavit
provides addl substantive testimony & will not be admitted
unless witness available for cross-examination
GLEASON, J P Atomic Safety and Licensing Board Panel 83/06/09
Friends of the Earth 2pp 18821 192 24X Fiche 50-247, 83/06/09,
8306130434

8306170372 Advises that NRC will file comments on Amico final rept
Separate comments on interim ltr rept will not be filed
MOORE, J E Hearing Branch 1 83/06/09, GLEASON, J P, SHON, F J,
PARIB, O H Atomic Safety and Licensing Board Panel 1p 18880:210,
24X Fiche 50-247, 83/06/09, 8306170372

8306170396 Forwards FEMA 830608 ltr to NRC, providing current evaluation
of plant offsite emergency planning
HASSELL, D F Hearing Branch 2 83/06/09 GLEASON, J P, SHON, F J,
PARIB, O H Atomic Safety and Licensing Board Panel. 46pp,
18879:333 24X Fiche 50-247, 83/06/09, 8306170396

8306150389 Response to ASLB consultant, PJ Amico, 830502 ltr re issues on
accident probability requiring addl testimony New York City
Audubon Soc/Friends of the Earth comments endorsed
Certificate of Svc encl
WEISS, E R Union of Concerned Scientists, WEISS, E R Public
Interest Research Group, New York, WEISS, E R Harmon & Weiss,
83/06/10 7pp 18847 152, 24X Fiche 50-247, 83/06/10, 8306150389

8306150427 Advises that utils will respond to PJ Amico summary ltr rept
& final rept on 830620
BRANDENBURG, B Consolidated Edison Co. of New York, Inc
COLARULLI, P F Morgan Associates, COLARULLI, P F, Power Authority
of the State of New York 83/06/10, GLEASON, J P, PARIB, O H,
SHON, F J Atomic Safety and Licensing Board Panel 1p, 18847:089,
24X Fiche 50-247, 83/06/10, 8306150427

8306200324 Responds to P Amico 830502 ltr rept re recommendations for
addl testimony on PRA Reopening record on PRA would unduly
prolong proceeding
HARTZMAN, R M Friends of the Earth, HARTZMAN, R M, New York City
Audubon Society, 83/06/10, GLEASON, J P, SHON, F J, PARIB, O H,
Atomic Safety and Licensing Board Panel 2pp, 18701 018, 24X
Fiche 50-247, 83/06/10, 8306200324

8306230376 Response to PJ Amico 830502 ltr to ASLB & analysis of PRA
testimony. Areas in which addl testimony recommended do not
present issues materially affecting record & are too
costly W/Certificate of Svc.
BRANDENBURG, B Consolidated Edison Co. of New York, Inc.
COLARULLI, P F Power Authority of the State of New York,
COLARULLI, P F, Morgan Associates, 83/06/20 19pp 18943:238, 24X
Fiche 50-247, 83/06/20, 8306230376

8306240290 Response to ASLB consultant P Amico rept re addl testimony
on Commission Question 1. No addl testimony necessary for
complete record.
MOORE, J, MCOURRAN, H J Hearing Branch 1 83/06/20, 15pp,
18779:241, 24X Fiche 50-247, 83/06/20, 8306240290

--8306240295 Affidavit of JF Meyer & RM Bernero re ASLB consultant
P Amico 830601 rept MARCH 1 i Code used to assess core-melt
accident progression & containment loading characteristics.
W/prof qualifications
MEYER, J F Reactor Systems Branch BERNERO, R M, Accident Source
Term Program Office, 83/06/17, 12pp, 18779:286 24X
Fiche: 50-247, 83/06/20, 8306240290

--8306240301 Affidavit of QB Varnado re ASLB consultant PJ Amico
recommendation to provide expert testimony on risk
significance of sabotage. NRC studies & PRA do not estimate
risk of sabotage. Prof qualifications encl.
VARNADO, Q B Sandia Laboratories, 83/06/07 4pp, 18779, 268,
24X Fiche 50-247, 83/06/20, 8306240290

DOCKETED ITEMS

--8306240305 Affidavit of HW Woods re ASLB consultant PJ Amico 830601
rept Testimony on conditional probability of core melt &
release due to pressurized thermal shock event unavailable
w/prof qualifications & Certificate of Svc
WOODS, H. W. NRC - No Detailed Affiliation Given 83/06/16 7pp
18979, 272 24X Fiche 50-247, 83/06/20, 8306240290

8306230346 Motion for immediate reconsideration of Commission 830610
Order CLI-83-16 permitting continued plant operation
Commission did not consider current status of emergency
planning in decision. Certificate of Svc encl
HOLT, J. Public Interest Research Group, New York 83/06/22
Commissioners. 12pp. 18942 284, 24X Fiche 50-247, 83/06/22,
8306230346

8306270140 Order granting intervenor 830621 motion for extension of
deadline until 830711 to file proposed findings. Extension
applies to all parties Consolidation effort constructive
GLEASON, J. P. Atomic Safety and Licensing Board Panel 83/06/22.
Union of Concerned Scientists. 2pp. 19013 360 24X
Fiche 50-247, 83/06/22, 8306270140

8306270160 Answer opposing intervenor motion for extension of time to
submit proposed findings. Motion is attempt to delay
hearings if intervenor motion granted; exemption should apply
to all parties Certificate of Svc encl.
BRANDENBURG, B. Consolidated Edison Co. of New York, Inc.
COLARULLI, P. F. Power Authority of the State of New York.
COLARULLI, P. F. Morgan Associates. 83/06/22 Atomic Safety and
Licensing Board Panel. 6pp. 18992:037, 24X Fiche 50-247, 83/06/22,
8306270160.

8306290550 Request 2-wk extension to file findings of fact for
Commission Questions 3 & 4 Atty familiar w/case resigned.
MILLER, F. O. Westchester County, NY 83/06/22 GLEASON, J. P. Atomic
Safety and Licensing Board Panel 1p 19052, 216 24X
Fiche 50-247, 83/06/22, 8306290550.

8306270159 Response supporting PIRG of NY motion for reconsideration of
Commission 830609 decision, permitting facility operation w/o
restriction despite continued noncompliance w/emergency
planning requirements. Certificate of Svc encl.
WEISS, E. R. Union of Concerned Scientists 83/06/23.
Commissioners 6pp. 18992:043 24X Fiche 50-247, 83/06/23,
8306270159

8306270267 Memorandum advising that ASLB will not reopen record to
receive further testimony on Commission Question 1 ASLB
consultant PJ Amico recommended addl testimony immaterial &
covers topic sufficiently addressed or is unavailable.
GLEASON, J. P. Atomic Safety and Licensing Board Panel 83/06/24
2pp 18990:202 24X Fiche 50-247, 83/06/24, 8306270267

H General correspondence

8306080191 Opposes facility shutdown.
FRENCH, J. F. Affiliation Unknown 83/06/02. PALLADINO, N. J.
Commissioners 1p. 18770 234, 24X Fiche: 50-247, 83/06/02,
8306080191

8306200098 Requests NRC 830609 determination re facility OLRs be
reversed, per encl Rockland County Resolution 302. Request
based on inability of FEMA to assure that public health &
safety can be protected within 10-mile zone w/o stated encl.
THORSEN, E. O., SCHENBERGER, I. Rockland County, NY. 83/06/13.
Office of Nuclear Reactor Regulation, Director 1p. 18903 336 24X
Fiche: 50-247, 83/06/13, 8306200098

I. Financial information

8306130111 "Annual Financial Rept 1982." W/830607 ltr.
DYSON, J. B., BAYNE, J. P. Power Authority of the State of New York
83/06/07. Office of Nuclear Reactor Regulation, Director. 41pp.
18827, 224 24X Fiche: 50-000, 83/06/07, 8306130111

P. Operating license stage documents & correspondence

8306140598 "Reland Safety Evaluation, Indian Point Nuclear Plant Unit 3,
Cycle 4" W/830609 ltr.
SKARITKA, J., ARLOTTI, M. Q., BAYNE, J. P. Power Authority of the State
of New York. 82/02/28, 34pp. 18833:141, 24X Fiche: 50-286,
82/02/28, 8306140598.

8306030224 Notifies that util name changed from Power Authority of
State of NY to New York Power Authority New name does not
reflect change in status, but clarifies public identity.
BAYNE, J. P. Power Authority of the State of New York. 83/05/27.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp.
18703:332, 24X Fiche: 50-000, 83/05/27, 8306030224.

8306150627 Forwards Amend 47 to License DPR-64, safety evaluation, EIA &
notice of issuance & availability Amends modify license to
reflect repairs & mods to steam generator tubes & girth
welds
VARQA, S. A. Operating Reactors Branch 1 83/05/27 BAYNE, J. P.
Power Authority of the State of New York App 18867 288 24X
Fiche: 50-286, 83/05/27, 8306150627

--8306150630 Amend 47 to License DPR-64, modifying license to reflect
repairs & mods to steam generator tubes & girth welds
VARQA, S. A. Operating Reactors Branch 1 83/05/27 13pp
18867 292 24X Fiche 50-286, 83/05/27, 8306150627

--8306150634 Safety evaluation supporting Amend 47 to License DPR-64.
* Office of Nuclear Reactor Regulation, Director 83/04/27
22pp 18867 305 24X Fiche 50-286, 83/05/27, 8306150627

--8306150637 EIA supporting Amend 47 to License DPR-64
* Office of Nuclear Reactor Regulation, Director 83/05/27
10pp 18867 327 24X Fiche 50-286, 83/05/27, 8306150627

--8306150638 Notice of issuance & availability of Amend 47 to License
DPR-64
VARQA, S. A. Operating Reactors Branch 1 83/05/27 6pp
18867 337 24X Fiche 50-286, 83/05/27, 8306150627

8306070185 Forwards application to amend License DPR-64 to conform
requirements of QL-B2-16 concerning NUREG-0737 Tech Specs
BAYNE, J. P. Power Authority of the State of New York 83/06/01
EISENHUT, D. O. Division of Licensing 2pp 18736 304 24X
Fiche 50-286, 83/06/01, 8306070185

--8306070197 Application to amend License DPR-64 changing Tech Specs in
accordance w/requirements of Generic Ltr B2-16 re
NUREG-0737 items
BAYNE, J. P. Power Authority of the State of New York 83/06/01
12pp 18736 306 24X Fiche: 50-286, 83/06/01, 8306070185

8306080034 Forwards 30-day response to 821230 ltr & 830428
clarification of SER for environ qualification of safety-
related electrical equipment. NRC Category II B & IV
equipment not in use at facility
BAYNE, J. P. Power Authority of the State of New York 83/06/01
VARQA, S. A. Operating Reactors Branch 1 55pp 18773 090 24X
Fiche 50-286, 83/06/01, 8306080034

8306200211 Summary of 830408 meeting w/util in Bethesda, MD re steam
generator girth weld & secondary water chemistry List of
attendees & viewgraphs describing girth weld repair effort
encl
NEIGHBOR, D. Operating Reactors Branch 1. 83/06/02. Operating
Reactors Branch 1 19pp 18909 218 24X Fiche 50-286, 83/06/02,
8306200211

8306090302 Forwards application for amend to License DPR-64, changing
Tech Specs re fire protection mods, in response to SA Varga
830421 ltr Procedures re alternate electrical feed sys
operation will be at site prior to startup
BAYNE, J. P. Power Authority of the State of New York 83/06/03
VARQA, S. A. Operating Reactors Branch 1 2pp 18795:242 24X
Fiche: 50-286, 83/06/03, 8306090302

--8306090304 Application to amend License DPR-64, changing Tech Spec
Sections 3.3.3 14 & 4.12 re fire protection mods, in response
to SA Varga 830421 ltr
BAYNE, J. P. Power Authority of the State of New York 83/06/03
1p 18795 244, 24X Fiche 50-286, 83/06/03, 8306090302

--8306090307 Proposed Tech Specs re fire protection mods
* Power Authority of the State of New York 83/06/30 11pp
18795:245 24X Fiche 50-286, 83/06/03, 8306090302.

8306100113 Forwards addl info re time frame for providing access to
hydrogen recombiner panel area per 830215 commitment to
NUREG-0737, Item II B.2, "Plant Shielding." Hydrogen
recombiner panel access time of 5 days appropriate.
BAYNE, J. P. Power Authority of the State of New York. 83/06/03
EISENHUT, D. O. Division of Licensing 5pp 18802 018 24X
Fiche: 50-286, 83/06/03, 8306100113

8306100253 Forwards draft std radiological effluent Tech Specs, for
technical review & comments Formal amend application will
be submitted by 830930
BAYNE, J. P. Power Authority of the State of New York 83/06/06
VARQA, S. A. Operating Reactors Branch 1 1p 18807, 065 24X
Fiche: 50-286, 83/06/06, 8306100253

--8306100256 Draft std radiological effluent Tech Specs.
* Power Authority of the State of New York 83/04/30 60pp,
18807, 066, 24X Fiche 50-286, 83/06/06, 8306100253

DOCKETED ITEMS

101

B306140277 Informs that analysis of inlet & discharge piping for relief & safety valves refined to reflect more realistic conditions, per B30215 ltr & TMI Action Item 11 D 1 Listed options will be considered if overstress condition revealed
BAYNE, J P Power Authority of the State of New York 83/06/08
VARQA, S A Operating Reactors Branch 1 2pp 18832 225 24X
Fiche 50-286, 83/06/08, B306140277

B306160450 Forwards results of steam generator tube insp & tube repair programs implemented during 1982/83 maint & refueling outage, per B21018 submittal info satisfies Tech Spec 4 9 2 requirements
BAYNE, J P Power Authority of the State of New York 83/06/10
VARQA, S A Operating Reactors Branch 1 34pp 18864 049 24X
Fiche 50-286, 83/06/10, B306160450

B306170249 Advises that schedule for unavailability analysis of ATWS mitigating sys actuation circuitry sys will be submitted after final designs & equipment selection completion, in accordance w/schedule requirements of ATWS final rule
BAYNE, J P Power Authority of the State of New York 83/06/13
VARQA, S A Operating Reactors Branch 2 2pp 18078 274 24X
Fiche 50-286, 83/06/13, B306170249

B306200401 Forwards Rev 1 to "Reload Safety Evaluation, Indian Point Nuclear Plant Unit 3, Cycle 4 " Proposed Tech Spec changes reflecting steam generator equivalent tube plugging level of 24% submitted via util B30505 ltr
BAYNE, J P Power Authority of the State of New York 83/06/15
VARQA, S A Operating Reactors Branch 1 2pp 18899 016 24X
Fiche 50-286, 83/06/15, B306200401

--B306200402 Rev 1 to "Reload Safety Evaluation, Indian Point Nuclear Plant Unit 3, Cycle 4 "
SMARITKA, J, ARLOTTI, M Q Westinghouse Electric Corp 82/03/31
16pp 18899 018 24X Fiche 50-286, 83/06/15, B306200401

B306210144 Suppls B21012 & B30510 responses to NUREG-0737, Item 11 D 3, "Post-Accident Sampling Sys " Commitment to Criterion 9(b) re background radiation levels Fulfills item requirement
BAYNE, J P Power Authority of the State of New York 83/06/17
EISENHUT, D G Division of Licensing 4pp 18914 092 24X
Fiche 50-286, 83/06/17, B306210144

B306210178 Forwards "Offsite Dose Calculation Manual," for B30606 radiological effluent Tech Specs
BAYNE, J P Power Authority of the State of New York 83/06/17
VARQA, S A Operating Reactors Branch 1 1p 18918 257 24X
Fiche 50-286, 83/06/17, B306210178

--B306210188 "Offsite Dose Calculation Manual "
* Power Authority of the State of New York 83/06/30 93pp
18918 258 24X Fiche 50-286, 83/06/17, B306210178

B306240413 INVESTIGATION OF THE SHELL CRACKING ON THE STEAM GENERATORS OF INDIAN POINT NO 3 Docket No 50-286 (Consolidated Edison Company)
CAZAJKOWSKI, C Brookhaven National Laboratory FIN A-3400
NUREG/CR-3281 83/06/30 Division of Engineering 51pp
Available at NRC \$4 00 18998 273 24X Fiche 50-286, 83/06/30, B306240413

0 Inspection reports, IE Bulletins & correspondence

B306030343 Ack receipt of B30128 ltr in response to NRC B21104 ltr re IE Insp Rept 50-286/82-09 Effective coverage by radial-type nozzle not addressed in safety evaluation Addl info requested B30228 not received
MARTIN, T T Division of Engineering & Technical Programs 83/05/23
BRONS, J C Power Authority of the State of New York 2pp
18705 012 24X Fiche 50-286, 83/05/23, B306030343

--B306030345 Forwards addl info re installation of radial pattern sprinkler nozzles in lieu of previously committed closed head, horizontal side-wall type, per II Insp Rept 50-286/82-09
BRONS, J C Power Authority of the State of New York 83/01/28
MARTIN, T T Division of Engineering & Technical Programs 5pp
18705 014 24X Fiche 50-286, 83/05/23, B306030343

B306060264 Forwards IE Insp Rept 50-286/83-08 on B30412-15 No noncompliance noted Corrective actions re violations noted in B30117 & 0217 ltrs verified
MARTIN, T T Division of Engineering & Technical Programs 83/05/23
BRONS, J C Power Authority of the State of New York 2pp
18727 026 24X Fiche 50-286, 83/05/23, B306060264

--B306060267 IE Insp Rept 50-286/83-08 on B30412-15 No noncompliance noted Major areas inspected status of previously identified items, package selection, procedures, training, audits, transuranic determinations & girth weld ALARA consideration
CLEMONS, P, MCBRIDE, M, SHANDAKY, M Region 1, Office of Director 83/05/20 5pp 18727 028 24X Fiche 50-286, 83/05/23, B306060264

B306070046 Forwards IE Insp Rept 50-286/83-11 on B30416-0515 No noncompliance noted
STARDSTECKI, R Division of Project & Resident Programs 83/05/24
BRONS, J C Power Authority of the State of New York 2pp
18740 068 24X Fiche 50-286, 83/05/24, B306070046

--B306070052 IE Insp Rept 50-286/83-11 on B30416-0515 No noncompliance noted Major areas inspected shift logs, plant tour, surveillance, maint, review of monthly operating rept & damage to chemical & vol control sys holdup tank
KENNY, T J, ROBBACH, L W, RISTER, H Region 1, Office of Director 83/05/19 9pp 18740 070 24X Fiche 50-286, 83/05/24, B306070046

B305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post B30103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000, 83/05/26, B305110458

B305110460 IE Info Notice 83-34, "Event Notification Info Worksheet, " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, B305110460

B305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, B305110461

B306210068 Responds to IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators " No check valves in piping boundary at facility
BRONS, J C Power Authority of the State of New York 83/06/07
ALLAN, J M Region 1, Office of Director 1p 18912 361 24X
Fiche 50-286, 83/06/07, B306210068

B305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/06/09 Consolidated Edison Co of New York, Inc 117pp 18830 280 24X Fiche 50-000, 83/06/09, B305110464

B306160450 Forwards results of steam generator tube insp & tube repair programs implemented during 1982/83 maint & refueling outage, per B21018 submittal info satisfies Tech Spec 4 9 2 requirements
BAYNE, J P Power Authority of the State of New York 83/06/10
VARQA, S A Operating Reactors Branch 1 34pp 18864 049 24X
Fiche 50-286, 83/06/10, B306160450

B305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, B305110470

B306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables, " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/06/13 Consolidated Edison Co of New York, Inc 242pp 18921 001 24X Fiche 50-000, 83/06/13, B306090010

B305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/06/22 Consolidated Edison Co of New York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, B305110475

B305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, B305110477

B305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions, " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, B305110479

B305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, B305110483

DOCKETED ITEMS

R Periodic operating reports & related correspondence

8306160385 Monthly operating rept for Apr 1983 W/830509 ltr
KELLY, L., BRONB, J. C. Power Authority of the State of New York
83/05/01 Office of Resource Management, Director 7pp
18680 067, 24X Fiche 50-286, 83/05/01, 8306160385

B Reportable occurrences, LERs & related correspondence

8306010346 LER 83-001/03L-0 on 830422, during processing of water from
chemical & vol control sys holdup tank 33 to waste
sys, partial deformation of tank occurred due to low
pressure. Caused by vacuum due to closed vent W/830513 ltr
OUMBLE, F. W., BRONB, J. C. Power Authority of the State of New York
83/05/13, ALLAN, J. M. Region 1, Office of Director 3pp
18680 076 24X Fiche 50-286, 83/05/13, 8306010346

8306020450 LER 83-002/03L-0 on 830512, during refueling outage, small
leak identified on RHR miniflow line at weld joint between
valve 1870 & line 337 Cause not stated Leak isolated, section
of pipe repaired & downstream reducer replaced W/830524 ltr
OUMBLE, F. W., BRONB, J. C. Power Authority of the State of New York
83/05/24 ALLAN, J. M. Region 1, Office of Director 3pp
18694 008 24X Fiche 50-286, 83/05/24, 8306020450

8306140690 PNO-I-83-059 on 830608, several trips experienced during
startup Caused by feedwater flow inconsistency w/steam
generator level demand Secondary boron soak performed
KENNY, T., COLLINS, B. Region 1, Office of Director 83/06/09 1p.
18841 343 24X Fiche 50-286, 83/06/09, 8306140690

8306230002 PNO-I-83-064 on 830618, electrical generator/turbine trip
caused reactor to trip Investigation revealed fault
originated within main generator End turns on some windings
melted & portions of internals covered w/carbon
GREENMAN, E. O. Region 1, Office of Director 83/06/20 1p
18947 078 24X Fiche 50-286, 83/06/20, 8306230002

T Hearing transcripts on non-antitrust matters

8306020709 Transcript of Commission 830526 meeting in Washington, DC,
re emergency planning & preparedness Pp 1-117 Supporting
documentation encl
* Commissioners 83/05/26 236pp. 18716 001 24X
Fiche 50-247, 83/05/26, 8306020709

8306090347 Statement before House of Representatives Subcommittee on
Energy Conservation & Power re emergency planning Public
must be involved in planning & testing process
* Parents Concerned About Indian Point 83/06/08 4pp 18794-336
24X Fiche 50-247, 83/06/08, 8306090347

8306090350 Testimony of J. Holt, K. Toscani & P. Posner before House of
Representatives Subcommittee on Energy Conservation & Power
re public role in planning, testing & implementing emergency
response procedures
HOLT, J. Public Interest Research Group, New York TOSCANI, K.
POSNER, P. Parents Concerned About Indian Point 83/06/08 24pp
18794 340, 24X Fiche 50-247, 83/06/08, 8306090350

8306150500 Transcript of 830609 Commission discussion & vote on
emergency planning deficiencies at Indian Point in
Washington, DC Pp 1-24
* Commissioners 83/06/09 30pp 18868 249 24X
Fiche 50-247, 83/06/09, 8306150500

8306200342 Forwards corrections to special proceeding transcripts
BRANDENBURG, B. Power Authority of the State of New York
COLARULLI, P. F. Consolidated Edison Co. of New York, Inc.
COLARULLI, P. F. Morgan Associates 83/06/15 GLEASON, J. P.,
PARIB, O. H., SHON, F. J. Atomic Safety and Licensing Board Panel. 1p.
18900 211, 24X Fiche 50-247, 83/06/15, 8306200342

--8306200346 Corrections to special proceeding transcripts
* Power Authority of the State of New York * Consolidated
Edison Co. of New York, Inc. 83/06/15 52pp 18900 212 24X
Fiche 50-247, 83/06/15, 8306200346

8306240018 Transcript of Commission 830617 briefing on Indian Point
labor issues in Washington, DC Pp 1-44,
* Commissioners 83/06/17, 47pp 18987 293 24X
Fiche 50-247, 83/06/17, 8306240018

U Congressional/Executive Correspondence

8306030156 Responds to 830506 request for clarification of 830505 order
re consideration of views of public & parties to special
proceeding in 830609 decision Comments from licensees, govt
agencies & public invited
PALLADINO, N. J. Commissioners 83/05/12 OTTINGER, R. L. House of
Rep., Energy & Commerce 2pp 18733 326 24X Fiche 50-247,
83/05/12, 8306030156

--8306030158 Requests Commission 830505 order be revised to stress need
for parties to safety investigation views on shutdown Rev
requested by 830511
OTTINGER, R. L. House of Rep., Energy & Commerce 83/05/06
PALLADINO, N. Commissioners 2pp 18733 328 24X
Fiche 50-247, 83/05/12, 8306030158

V Operator Examinations

8306140291 Extends invitation to attend 830627 meeting in King of
Prussia, PA to discuss transfer of reactor operator licensing
function from Bethesda, MD to Region 1 ofc
STAROBTECKI, R. Division of Project & Resident Programs 83/06/09
BRONB, J. C. Power Authority of the State of New York 2pp
18832 217 24X Fiche 50-286, 83/06/09, 8306140291

DOCKET 50-287 CONNEX NUCLEAR STATION, UNIT 3

F Security, medical, emergency & fire protection plans

8306090361 Forwards request for exemption from emergency operations
facility (EOF) location requirements per Generic Ltr 82-33
Proposed EOF to be located 125 air miles from facility, w/
joint news ctr remaining in Uconnee, NC
TUCKER, H. B. Duke Power Co 83/06/03 BLNTON, H. R. Office of
Nuclear Reactor Regulation, Director STULZ, J. F. Operating Reactors
Branch 4 28pp 18795 039 24X Fiche 50-269, 83/06/03, 8306090361

8306170285 Forwards IE Safeguards Insp Repts 50-269/83-14
50-270/83-14 & 50-287/83-14 on 830509-13 No noncompliance
noted
DANCE, H. C. Division of Project & Resident Programs 83/06/15
TUCKER, H. B. Duke Power Co 2pp 18877 233 24X
Fiche 50-269, 83/06/15, 8306170285

--8306170307 IE Safeguards Insp Repts 50-269/83-14, 50-270/83-14 &
50-287/83-14 on 830509-13 No noncompliance noted Major areas
inspected security plan & implementing procedures & security
organization mgt Safeguards info deleted (ref 10CFR73 21)
TILLMAN, A. Region 2, Office of Director 83/06/15 2pp
18877 233 24X Fiche 50-269, 83/06/15, 8306170285

8306240038 Advises that preliminary fee review of 830603 request for
exemption from location requirements of emergency operations
facility determined that Class III appropriate
DIGGS, R. M. License Fee Management Branch 83/06/15 TUCKER, H. B.
Duke Power Co 1p 18987 229 24X Fiche 50-269, 83/06/15,
8306240038

P Operating license stage documents & correspondence

8306060051 Addl response to FOIA request for three categories of
documents re PRA of reactor safety study methodology
application program repts & interim reliability evaluation
program repts Forwards App A documents Search continuing
FELTON, J. M. Division of Rules and Records 83/04/07 SHOLLY, S. C.
Union of Concerned Scientists 3pp 18752 001 24X
Fiche 50-000, 83/04/07, 8306060051

--8109210318 Responds to 810820 memo re transmittal of NUREG/CR-1659,
Vol 2, to licensee for comments Util comments on rept already
requested
BERNERD, R. M. Division of Risk Analysis 81/08/20 NOVAK, T. M.
Assistant Director for Operating Reactors 2pp 18752 018 24X
Fiche 50-000, 83/04/07, 8306060051

--8306060080 Forwards background info re PRA studies Review of Sandia
Natl Labs interim reliability evaluation program studies
discussed W/o encl
STULZ, J. Operating Reactors Branch 4 83/01/19 LAINAB, G. C.
Assistant Director for Operating Reactors 2pp 18752 200 24X
Fiche 50-000, 83/04/07, 8306060051

--8306060085 Provides info on boron precipitation clogging HP1 lines &
failure of operator to switch to hot leg injection in order
to flush out boron residue from core during recirculation
Info obtained from PRAs
DAVIS, S. NRC - No Detailed Affiliation Given 83/02/24
THADANI, A. NRC - No Detailed Affiliation Given 6pp 18752 206
24X Fiche 50-000, 83/04/07, 8306060051

DOCKETED ITEMS

103

8306020103 Proposes 830608 meeting in Bethesda, MD to discuss Suppl 6 to SER for McGuire & SER for standby shutdown facility for Oconee
STOLZ, J F Operating Reactors Branch 4 83/05/17 TUCKER, H B
Duke Power Co 1p 18701 277 24X Fiche 50-000, 83/05/17,
8306020103

8306150504 Forwards request for addl info re 830310 proposed amend to License DPR-55 & proposed rev to Tech Spec on expansion of storage capacity of spent fuel pool info requested within 30 days of ltr receipt
STOLZ, J F Operating Reactors Branch 4 83/05/23 TUCKER, H B
Duke Power Co 3pp 18854 356 24X Fiche 50-287, 83/05/23,
8306150504

8306070051 Forwards summary of 830512 meeting w/util & B&W, in response to 830327 request for addl info re reactor vessel surveillance capsule dosimetry results contained in BAW-1697 & 1699
TUCKER, H B Duke Power Co 83/05/27 DENTON, H R Office of
Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors
Branch 4 4pp 18740 059 24X Fiche 50-269, 83/05/27, 8306070051

8306030122 Forwards addl info to aid in completion of review re NUREG-0737, Items II F 1 4, II F 1 5 & II F 1 6, per 830110 ltr request & justification concerning Item II F 1 5 Amend to 830318 confirmatory order requested
TUCKER, H B Duke Power Co 83/05/31 DENTON, H R Office of
Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors
Branch 4 15pp 18704 302 24X Fiche 50-269, 83/05/31, 8306030122

8306070272 Forwards BAW-1784, "B&W Owners Group Bolting Task Force Summary Rept of NRC/B&W Owners Group 830506 Meeting on Reactor Vessel Internals Bolting " Agrees w/overall findings w/exception re neutron noise surveillance
TUCKER, H B Duke Power Co 83/05/31 DENTON, H R Office of
Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors
Branch 4 2pp 18744 086 24X Fiche 50-269, 83/05/31, 8306070272

--8306070280 Forwards BAW-1784, "B&W Owners Group Bolting Task Force Summary Rept of NRC/B&W Owners Group 830506 Meeting on Reactor Vessel Internals Bolting "
TAYLOR, J H Babcock & Wilcox Operating Plants Owners Group
TAYLOR, J H Babcock & Wilcox Co 83/05/20 MINER, S NRC - No
Detailed Affiliation Given 1p 18744 008 24X
Fiche 50-269, 83/05/31, 8306070272

--8306070286 "B&W Owners Group Bolting Task Force Summary Rept of NRC/B&W Owners Group 830506 Meeting on Reactor Vessel Internals Bolting "
* Babcock & Wilcox Co BAW-1784 83/05/31 124pp 18744 089
24X Fiche 50-269, 83/05/31, 8306070272

8306080375 Forwards review of "Reactor Safety Study Methodology Applications Program Oconee 3 PWR Power Plant (NUREG/CR-1659, 2 of 4) " Review identified dominant core melt sequences & required licensing actions.
STOLZ, J F Operating Reactors Branch 4 83/06/01, TUCKER, H B,
Duke Power Co 14pp 18787 277 24X Fiche 50-287, 83/06/01,
8306080375

8306200185 Summary of 830512 meeting w/util & B&W in Bethesda, MD re neutron dosimetry & upper shelf matl properties provided in Topical Repts BAW-1697 & BAW-1699 List of attendees, agenda & viewgraphs encl
BUERMANN, J F Operating Reactors Branch 4 83/06/06 Operating
Reactors Branch 4 35pp 18909, 183 24X Fiche 50-269, 83/06/06,
8306200185

8306220275 Informs that 830310 proposed wide-range hot leg level/ reactor vessel head monitoring satisfactory. Evaluation & addl info request re conformance of addl inadequate core cooling instrumentation sys components to NUREG-0737, encl
STOLZ, J F Operating Reactors Branch 4 83/06/08, TUCKER, H B,
Duke Power Co 10pp 18977 155 24X Fiche 50-269, 83/06/08,
8306220275

8306300174 Forwards responses to 830523 request for addl info re spent fuel pool info suppls 830310 ltr
TUCKER, H B Duke Power Co 83/06/24, DENTON, H R Office of
Nuclear Reactor Regulation, Director STOLZ, J F, Operating Reactors
Branch 4 9pp 19122 047 24X Fiche 50-287, 83/06/24, 8306300174

0 Inspection reports, IE Bulletins & correspondence

8306080402 Confirms 830513 telcon re proposed site/corporate visit on 830525-27 to review masonry wall const, drawings & calculations re review of IE Bulletin 80-11 response Agenda encl
STOLZ, J F Operating Reactors Branch 4 83/05/20, TUCKER, H B,
Duke Power Co 4pp, 18789-342 24X Fiche 50-269, 83/05/20,
8306080402

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc.
125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458.

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8306010310 EN-83-038 notice of violation & proposed imposition of civil penalties in amount of \$180,000 to be issued on 830602 Action based on three Severity Level III violations re failure to maintain primary containment integrity
BARBER, G, AXELRAD, J Director's Office, Office of Inspection and Enforcement 83/05/27 1p 18672 317 24X Fiche 50-269, 83/05/27, 8306010310

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at DWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306220171 Discusses IE insp on 830317-28 & forwards notice of violation & proposed imposition of civil penalty
O'REILLY, J P Region 2, Office of Director 83/06/02 TUCKER, H B,
Duke Power Co 4pp 18937 281 24X Fiche 50-269, 83/06/02,
8306220171

--8306220175 Notice of violation & proposed imposition of civil penalty in amount of \$180,000 Noncompliance noted. Inadequate procedures to ensure that air lock sys restored to operability after maint
O'REILLY, J P Director's Office, Office of Inspection and Enforcement 83/06/02 4pp 18937 285, 24X
Fiche 50-269, 83/06/02, 8306220171

8306290245 Informs that response to IE Bulletin 83-03, Item 4 re failures of check valves used in diesel generator water cooling sys, will be submitted by 830622
TUCKER, H B Duke Power Co 83/06/08 O'REILLY, J P, Region 2,
Office of Director 1p 19056 085 24X Fiche 50-269, 83/06/08,
8306290245

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464.

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920, 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921, 001 24X Fiche 50-000, 83/06/13, 8306090010.

8306170285 Forwards IE Safeguards Insp Repts 50-269/83-14 50-270/83-14 & 50-287/83-14 on 830509-13 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/06/15,
TUCKER, H B Duke Power Co 2pp 18877-233 24X
Fiche 50-269, 83/06/15, 8306170285

--8306170307 IE Safeguards Insp Repts 50-269/83-14, 50-270/83-14 & 50-287/83-14 on 830509-13. No noncompliance noted. Major areas inspected, security plan & implementing procedures & security organization mgt Safeguards info deleted (ref 10CFR73.21)
TILLMAN, A, ENNIS, J, Region 2, Office of Director, HOGUIRE, D. R,
Division of Emergency Preparedness & Materials Safety 83/06/15,
2pp 18877-235, 24X Fiche 50-269, 83/06/15, 8306170285

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475.

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 120pp 18977-007 24X Fiche 50-000, 83/06/22, 8305110477.

DOCKETED ITEMS

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions" Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co. of New York, Inc. 11pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints" Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc. 11pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

R Periodic operating reports & related correspondence

8306170297 Monthly operating repts for May 1983 W/830615 ltr
REAVIS, J.A.; TUCKER, H.B. Duke Power Co. 83/06/15 17pp
18878 177 24X Fiche 50-289, 83/06/15, 8306170297

B Reportable occurrences, LERs & related correspondence

8306210190 LER 83-006/03L-0 on 830513, during attempt to replace cell in battery 3PB, power lost from emergency feedwater pump turbine auxiliary oil pump. Caused by personnel failure to follow procedure. Personnel counseled W/830610 ltr.
PETTY, J.C.; TUCKER, H.B. Duke Power Co. 83/06/10 O'REILLY, J.P. Region 2, Office of Director, 3pp. 18914 119, 24X Fiche 50-287, 83/06/10, 8306210190

8306220007 Part 21 re: re adequacy of fittings supplied by Tube-Line Corp through Capitol Pipe & Steel Products Co for use on new auxiliary feedwater headers of steam generators. Flanges not heat-treated as required by matl specs.
TAYLOR, J.H. Babcock & Wilcox Co. 83/06/17 DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement 4pp 18927 354, 24X Fiche 50-000, 83/06/17, 8306220007

8306300015 RD on 830527, certain containment isolation valves may have failed in non-ES position due to loss of dc power. Investigation & re: rpt will be completed & reviewed by 830708
TUCKER, H.B. Duke Power Co. 83/06/24 O'REILLY, J.P. Region 2, Office of Director, 1p. 19168 128, 24X Fiche 50-287, 83/06/24, 8306300015

DOCKET 50-289 THREE MILE ISLAND NUCLEAR STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8306240319 Ack receipt of 830504 ltr re emergency info brochures. Util proposes to effect distribution primarily by direct mail to agricultural community within plume exposure pathway emergency planning zone.
ROGAN, R.E. General Public Utilities - GPU Service Corp. 83/05/31, HALLOWELL, P. Pennsylvania, Commonwealth of, 1p. 18980 153 24X Fiche 50-289, 83/05/31, 8306240319

8306090268 Releases public version of revised emergency plan
FELTON, J.M. Division of Rules and Records, 83/06/01 Document Management Branch, 1p. 18798 259, 24X Fiche 50-289, 83/06/01, 8306090268

--8306090271 Public version of Rev 4 to emergency plan Receipt form encl.
CLARK, P.R. General Public Utilities - GPU Service Corp. 83/04/21, 301pp. 18798 260 24X Fiche 50-289, 83/06/01, 8306090268

8306100120 Forwards Rev 17 to security plan. Rev withheld (ref 10CFR73.21) Rev completes replacement of existing plan except for exhibits following Exhibit 1 2 TMI-2 addendum should be retained.
HUKILL, H.D. General Public Utilities - GPU Service Corp. 83/06/03 DENTON, H.R. Office of Nuclear Reactor Regulation, Director, 1p. 18802 030, 24X Fiche 50-289, 83/06/03, 8306100120

8306220293 Releases public version of revised emergency plan implementing procedure.
FELTON, J.M. Division of Rules and Records, 83/06/06, Document Management Branch, 1p. 18940 315 24X Fiche 50-289, 83/06/06, 8306220293

--8306220298 Public version of Rev 6 to Emergency Plan Implementing Procedure 1004.31: "Airborne Radioactivity Sampling & Analysis." Receipt form encl.
BRADY, J.A. General Public Utilities - GPU Service Corp. 83/05/24 28pp. 18940 316, 24X Fiche 50-289, 83/06/06, 8306220293

8306150025 Releases public version of revised administrative procedures & revised emergency plan implementing procedure
FELTON, J.M. Division of Rules and Records, 83/06/07 Document Management Branch, 1p. 18872 004 24X Fiche 50-289, 83/06/07, 8306150025

--8306150030 Public version of revised Administrative Procedures 1053 re emergency equipment readiness & 1055 re maintaining emergency preparedness & revised Emergency Plan Implementing Procedure 1004.33 re reactor coolant
NELSON, M.A.; TOOLE, R. General Public Utilities - GPU Service Corp. 83/05/02 43pp 18872 005 24X Fiche 50-289, 83/06/07, 8306150025

8306140732 Forwards Rev 0 to "Fire Protection Mods to TMI Unit 1 (Since Browns Ferry Incident)"
HUKILL, H.D. General Public Utilities - GPU Service Corp. 83/06/09 EISENHUT, D. Division of Licensing, 3pp 18840 210 24X Fiche 50-289, 83/06/09, 8306140732

--8306140737 Rev 0 to "Fire Protection Mods to TMI Unit 1 (Since Browns Ferry Incident)" W/one oversize chart Aperture card is available in PDR
HAFFER, D.L.; BOUTROS, F.O.; BRANNEN, W.A. Gilbert/Commonwealth Cos. 2469 R00, 83/06/01, 155pp 18840 213 24X Fiche 50-289, 83/06/09, 8306140732

8306170204 Ack receipt of operational GA plan for TMI-1 & Oyster Creek under review by QA Branch, per 10CFR80.94 Future revs/changes to program will be reviewed by Engineering Programs Branch, Region 1
MARTIN, T.T. Division of Engineering & Technical Programs, 83/06/13 HUKILL, H.D. General Public Utilities - GPU Service Corp. 2pp 18882 304 24X Fiche 50-000, 83/06/13, 8306170204

O Adjudicatory correspondence

8306010351 Comments on 830524 Commission meeting & on IE Insp Rept 50-289/83-10 Continued ref to Hartman allegations clouded purpose & results of revalidation effort Safe operation assured
DIECKAMP, H. General Public Utilities - GPU Service Corp. 83/05/27 PALLADINO, N.J. Commissioners 4pp 18682 141 24X Fiche 50-289, 83/05/27, 8306010351

8306010454 Forwards H Dieckamp comments on IE Insp Rept 50-289/83-10 & related Commission 830524 meeting Certificate of Svc encl W/o comments
BLAKE, E.L. Shaw, Pittman, Potts & Trowbridge, BLAKE, E.L. Metropolitan Edison Co. 83/05/31 CHILK, S.J. Office of the Secretary of the Commission, 4pp 18674 318 24X Fiche 50-289, 83/05/31, 8306010454

8306020441 Order extending time until 830624 for Commission to act to review ALAB-724
CHILK, S.J. Office of the Secretary of the Commission, 83/05/31 Commissioners 1p 18693 240 24X Fiche 50-289, 83/05/31, 8306020441

8306060190 Motion for extension of time to file comments re IE Insp Rept 50-289/83-10 in response to 830523 order
AAMODT, M.M. Aamodts, The, 83/05/31 Commissioners 1p 18728 280 24X Fiche 50-289, 83/05/31, 8306060190

8306070420 Comments on IE Insp Rept 50-289/83-10 & Commission 830524 briefing Insp rpt does not address issue of mgt integrity. Significant number of TMI-1 & GPU mgt personnel could have been involved in events surrounding Hartman allegations
AAMODT, N.D.; AAMODT, M.M. Aamodts, The, 83/05/31 42pp 18742 202 24X Fiche 50-289, 83/05/31, 8306070420

8306090339 Requests NRC documents re Hartman allegations & memoranda on whether NRC attys or senior staff aware of T Martin views re record falsification & whether Martin views reported to ABL or Commission
OILINSKY, V. Commissioners, 83/05/31, DIRCKS, W.J. Office of the Executive Director for Operations, 2pp 18795 110 24X Fiche 50-289, 83/05/31, 8306090339

8306020355 Advises of inability to meet 830601 deadline for commenting on B&W trial record. Physical exhaustion will not be risked & substandard work based on sloppy research will not be submitted to meet arbitrary deadline W/Certificate of Svc
BOROSHOW, J. Three Mile Island Alert, 83/06/01 PALLADINO, N.J., OILINSKY, V., AHEARNE, J.F. Commissioners 4pp 18694 288 24X Fiche 50-289, 83/06/01, 8306020355

DOCKETED ITEMS

105

8306030329 Requests available evidence & conclusions re falsification of THI-2 records per H Hartman Mar 1980 allegations Info should include NRC analyses & repts, mgt review records & specific citations supporting NRC statement
BLAKE, E L Shaw, Pittman, Potts & Trowbridge 83/06/01
PLAINE, H H Office of the General Counsel 3pp 18708 350 24X
Fiche 50-289, 83/06/01, 8306030329

8306070271 Forwards PA Governor Thornburgh 830602 ltr & supplemental comments on immediate effectiveness of partial initial decisions re mgt issues Filings constitute Commonwealth of PA comments on Commission 830524 meeting
ADLER, R W Pennsylvania, Commonwealth of, 83/06/02 CHILK, S J
Office of the Secretary of the Commission 1p 18742 130 24X
Fiche 50-289, 83/06/02, 8306070271

--8306070277 Urges postponement of restart decision until issues re operator cheating, THI-2 cleanup & operator competence & integrity resolved
THORNBURGH, D Pennsylvania, Commonwealth of, 83/06/02
PALLADINO, N J Commissioners 2pp 18742 131 24X
Fiche 50-289, 83/06/02, 8306070277

--8306070407 Supplemental comments on immediate effectiveness of partial initial decisions re mgt issues, in response to Commission 830523 order soliciting comments on Commission 830524 briefing issues must be investigated W/Certificate of Svc
ADLER, R W Pennsylvania, Commonwealth of, 83/06/02 12pp
18742 133 24X Fiche 50-289, 83/06/02, 8306070271

8306060279 Comments on NRC 830524 Commission briefing on revalidation of NRC position supporting licensee mgt NRC briefing violates due process rights Mgt issues not addressed sufficiently Certificate of Svc encl
DOROSHOW, J Three Mile Island Alert 83/06/03 10pp 18729 026
24X Fiche 50-289, 83/06/03, 8306060279

8306070390 Order extending time until 830603 for Aamodts to file comments on IC Insp Rept 50-289/83-10
CHILK, S J Office of the Secretary of the Commission 83/06/03
Aamodts, The 1p 18742 018 24X Fiche 50-289, 83/06/03, 8306070390

8306070418 Comments on Commission 830524 briefing on leak rate falsification & objection to ex parte communication Briefing violates due process since intervenors not given reasonable opportunity to confront evidence Certificate of Svc encl
WEISS, E R Union of Concerned Scientists 83/06/03 11pp
18742 259 24X Fiche 50-289, 83/06/03, 8306070418

8306080173 Response opposing THI Alert 830519 request for adjudicatory hearing on steam generator repair amend Request should be denied w/o prejudice re THI Alert ability to file subsequent request for hearing per recent notice W/Certificate of Svc
RAMSON, R J Hearing Branch 4 83/06/03 Commissioners 15pp
18771 331 24X Fiche 50-289, 83/06/03, 8306080173

8306150324 Corrected FR notice, originally issued 830531, extending date by which licensees may request hearing & parties may file written petition for leave to intervene to 830630 re 830507 application for amend to License DPR-50
STOLZ, J F Operating Reactors Branch 4 83/06/03 3pp 18067 359
24X Fiche 50-289, 83/06/03, 8306150324

8306090297 Errata to Aamodt comments re IC Insp Rept 50-289/83-10 & Commission 830524 briefing re Hartman matter Certificate of Svc encl
AAMODT, M Aamodts, The 83/06/06 4pp 18795 233 24X
Fiche 50-289, 83/06/06, 8306090297

8306090211 Response opposing THI Alert 830523 motion to reopen record re licensee mgt competence & integrity Certificate of Svc encl
BLAKE, E L Metropolitan Edison Co BLAKE, E L Shaw, Pittman, Potts & Trowbridge 83/06/07 Atomic Safety and Licensing Appeal Panel.
4pp 18776 031 24X Fiche 50-289, 83/06/07, 8306090211

8306090343 Advises that 830531 memo to W Dircks re Hartman allegations & NRC reply to memo should be served on parties
PLAINE, H H Office of the General Counsel 83/06/07 GILINSKY, V
Commissioners 1p 18794 334 24X Fiche 50-289, 83/06/07, 8306090343

8306130408 Response to util 830523 reply opposing NRC 830421 brief on review of ALAB-69B & response to util 830523 motion for leave to file affidavit Util should be required to staff emergency operations facility W/Certificate of Svc
GRAY, J R Hearing Branch 4 83/06/07 Commissioners 12pp
18823 095 24X Fiche 50-289, 83/06/07, 8306130408

8306090338 Forwards WJ Dircks 830607 memo to Commissioners re NRC recommendations for completion of restart review
GOLDBERG, J R Hearing Branch 2 83/06/08 EDLES, O J, KOHL, C N, BUCK, J H Atomic Safety and Licensing Appeal Panel 14pp
18795 096 24X Fiche 50-289, 83/06/08, 8306090338

8306150427 Errata to Aamodt comments re IE Insp Rept 50-289/83-10 & Commission 830524 briefing re Hartman matter Certificate of Svc encl
AAMODT, M Aamodts, The 83/06/08 4p 18847 085 24X
Fiche 50-289, 83/06/08, 8306150427

8306130390 Forwards util 830610 ltr to Commission re mgt integrity issues
BLAKE, E L Shaw, Pittman, Potts & Trowbridge 83/06/10 CHILK, S J
Office of the Secretary of the Commission 1p 18821 023 24X
Fiche 50-289, 83/06/10, 8306130390

--8306130395 Discusses mgt integrity issues Util confident in capability & integrity of mgt organization & personnel Certificate of Svc encl
DIECKAMP, H General Public Utilities - GPU Service Corp
83/06/10 PALLADINO, N J Commissioners 9pp 18821 024 24X
Fiche 50-289, 83/06/10, 8306130390

8306150410 Forwards corrected Page 4 to GPU 830610 ltr to NRC re assignment of personnel to provide overview assessment, analysis or audit of plant activities
BLAKE, E L Shaw, Pittman, Potts & Trowbridge BLAKE, E L
Metropolitan Edison Co 83/06/10 CHILK, S J Office of the
Secretary of the Commission 5pp 18847 121 24X
Fiche 50-289, 83/06/10, 8306150410

8306150245 Answer to THI Alert 830523 motion to reopen record on issue of util mgt competence & integrity Moves to defer ruling on motion pending further development of open issues W/Certificate of Svc
GOLDBERG, J R Hearing Branch 2 WAGNER, M E Hearing Branch 4
83/06/13 Atomic Safety and Licensing Appeal Panel 18pp
18846 110 24X Fiche 50-289, 83/06/13, 8306150245

8306160600 Opposes separation of util mgt from actions of util employees Issues re restart concern individual & local community control in determining std & quality of life
HUGHENDONER, L Dauphin County, PA 83/06/13 PALLADINO, N J
Commissioners 2pp 18866 095 24X Fiche 50-289, 83/06/13, 8306160600

8306160604 Petition for review of ASLAB 830526 Decision, ALAB-729. Issues re adequacy of DHR not resolved Certificate of Svc encl
WEISS, E R Union of Concerned Scientists WEISS, E R Harmon & Weiss 83/06/13 Commissioners 10pp 18865 086 24X
Fiche 50-289, 83/06/13, 8306160604

8306160008 Forwards WJ Dircks 830610 memo to Commission in response to Commissioner Gilinsky 830531 memo re Hartman allegations, W/o encl
WAGNER, M E Hearing Branch 4 83/06/14 EDLES, O J, KOHL, C N, BUCK, J H Atomic Safety and Licensing Appeal Panel 1p 18861 357.
24X Fiche 50-289, 83/06/14, 8306160008

8306160297 Comments on EDD 830607 proposal re THI-1 restart Restart w/o addressing questions re operator cheating & util response to cheating & util competence & integrity, unacceptable.
Certificate of Svc encl
WEISS, E Union of Concerned Scientists 83/06/14 7pp. 18860 060
24X Fiche 50-289, 83/06/14, 8306160297.

8306160594 Urges restart deferral until significant issues resolved.
GAPE, K National Lawyers Guild, Houston Chapter 83/06/14,
PALLADINO, N J, GILINSKY, V, ROBERTS, T M Commissioners, 1p.
18866 101 24X Fiche 50-289, 83/06/14, 8306160594

8306200328 Order scheduling 830720 oral argument on MM Aamodt 820903, N & M Aamodt 830416 & THI Alert 830523 motions to reopen record in Bethesda, MD Parties must inform ASLAB of participation by 830630
TOMPKINS, B A Atomic Safety and Licensing Appeal Panel 83/06/16.
7pp 18900 353 24X Fiche, 50-289, 83/06/16, 8306200328

8306220042 Notice of withdrawal of appearance in proceeding Certificate of Svc encl
STRAUBE, M Affiliation Unknown 83/06/16 4pp. 18930 175 24X
Fiche 50-289, 83/06/16, 8306220042.

8306220046 Notice of withdrawal of appearance in proceeding Certificate of Svc encl
ADLER, R W Pennsylvania, Commonwealth of, 83/06/17 4pp.
18928 204 24X Fiche, 50-289, 83/06/17, 8306220046

DOCKETED ITEMS

8306220142 Comments on H Dieckamp 830527 & 0610 ltr re immediate effectiveness of restart Dieckamp concealment of info detrimental to mgt evidences util policy of expediency Certificate of Svc encl
AAMODT, M. D., AAMODT, M. M. Aamodts, The 83/06/18 8pp 18926 166
24X Fiche 50-289, 83/06/18, 8306220142

8306220147 Comments re NRC 830615 briefing of Commission on util compliance w/open items & 830616 briefing of Commission re plant staffing to avoid employment of personnel involved in falsification of leak rates Certificate of Svc encl
AAMODT, M. M. Aamodts, The 83/06/18 6pp 18926 190 24X
Fiche 50-289, 83/06/18, 8306220147

8306220068 Motions to provide info & to lift order of confidentiality of reopened hearing Order of confidentiality should be lifted to permit discussion of staffing per Dircks & Dieckamp ltr Certificate of Svc encl
AAMODT, M. M. Aamodts, The 83/06/20 Atomic Safety and Licensing Appeal Panel 5pp 18930 100 24X Fiche 50-289, 83/06/20, 8306220068

8306220071 Forwards INPO 830610 draft rpt on restart evaluation & INPO May 1983 rpt re corp assistance visit Svc list encl.
BLAKE, E. L. Shaw, Pittman, Potts & Trowbridge BLAKE, E. L. Metropolitan Edison Co 83/06/20. EDLES, O. J., BUCK, J. W., KOHL, C. N. Atomic Safety and Licensing Appeal Panel 46pp 18927 188 24X
Fiche 50-289, 83/06/20, 8306220071

8306220367 Order extending time until 830715 for Commission to act to review ALAB-724
CHILK, B. J. Office of the Secretary of the Commission. 83/06/21. Commissioners 1p 18944 128 24X Fiche 50-289, 83/06/21, 8306220367

8306280532 Supports restart Four yrs more than sufficient time to reactivate TMI-1
SPANO, J. R. American Society of Utility Investors 83/06/21
PALLADINO, N. J. NRC - No Detailed Affiliation Given 1p 19019 007.
24X Fiche 50-289, 83/06/21, 8306280532

8306280538 Provides Borough of Highspire, Dauphin County, PA Resolution 4-83, supporting Governor of Pennsylvania position on TMI-1 restart, in 830602 ltr TMI-2 should be decontaminated & defueled TMI should be closed permanently
PORTHEMERE, W. Dauphin County, PA 83/06/21 PALLADINO, N. J. Commissioners 1p 19020.001 24X Fiche 50-289, 83/06/21, 8306280538

8306300076 Request for hearing re util request for Tech Spec rev to address steam generator tube repair techniques other than plugging. Public perceives significant hazards considerations
OODOLINO, B. House of Rep 83/06/21 CHILK, B. Office of the Secretary of the Commission. 2pp 19122 093. 24X
Fiche 50-289, 83/06/21, 8306300076

8306220360 Responds to 830601 ltr requesting evidence on NRC staff member statement at Commission 830524 meeting re falsification of leak rate testing record Statement that NRC aware records falsified does not reflect NRC views
PLAINE, H. W. Office of the General Counsel. 83/06/22 BLAKE, E. L. Shaw, Pittman, Potts & Trowbridge. 1p. 18943.331. 24X
Fiche 50-289, 83/06/22, 8306220360

8306240279 Forwards DELD 830614 memo to HR Denton re util untimely submittal of Basic Energy Technology Assoc, Inc & Rohrer-Hibler-Replogle, Inc repts Matter to be referred to Ofc of Investigations
DIRCKS, W. J. Office of the Executive Director for Operations. 83/06/22 PALLADINO, N. J., GILINKEY, V., AHEARNE, J. Commissioners 1p. 18980.134 24X Fiche 50-289, 83/06/22, 8306240279.

--8306240281 Advises that licensee failed to meet duty to make Board notifications & obligations under Section 186 by failing to provide Rohrer-Hibler-Replogle, Inc & Basic Energy Technology Assoc, Inc repts in timely manner
CUNNINGHAM, G. H. Office of the Executive Legal Director 83/06/14. DENTON, W. R. Office of Nuclear Reactor Regulation, Director 9pp. 18980.135 24X Fiche 50-289, 83/06/22, 8306240279.

8306270388 Expresses concern re NRC proposal to waive exam of OPU corp mgt policies & to focus on allegations of individual misconduct. OPU established mgt policies & practices should be investigated.
BHEDELEY, R. Three Mile Island Alert 83/06/22. Commissioners. 1p. 18993.303. 24X Fiche 50-289, 83/06/22, 8306270388.

8306270265 Forwards Chairman Palladino statement on Commissioner Gilinsky 830622 tentative conclusions re restart.
CHILK, B. J. Office of the Secretary of the Commission 83/06/23. Office of the Executive Legal Director. 1p. 18990.210 24X
Fiche 50-289, 83/06/23, 8306270265.

--8306270270 Chairman Palladino statement on Commissioner Gilinsky tentative conclusions on restart Comments premature since relevant info unavailable
PALLADINO, N. J. Commissioners 83/06/23 1p 18990.211 24X
Fiche 50-289, 83/06/23, 8306270265

8306270273 Forwards Commissioner Ahearne & Asselstine statements on Commissioner Gilinsky 830622 tentative conclusions re restart
CHILK, B. J. Office of the Secretary of the Commission 83/06/23
Office of the Executive Legal Director 1p 18996.190 24X
Fiche 50-289, 83/06/23, 8306270273

--8306270278 Commissioner Asselstine statement re Commissioner Gilinsky tentative conclusions on restart Agrees w/Chairman Palladino that immediate Commission decision premature since relevant info currently unavailable
ASSELSTINE, Commissioners 83/06/23 1p 18996.191 24X
Fiche 50-289, 83/06/23, 8306270273

--8306270281 Commissioner Ahearne statement re Commissioner Gilinsky tentative conclusions on restart Agrees w/Chairman Palladino statement
AHEARNE, J. Commissioners 83/06/23 1p 18996.192 24X
Fiche 50-289, 83/06/23, 8306270273

8306270286 Order directing that party answers to MM Aamodt 8306P1 motion for provision of info & to lift order of confidentiality of reopened hearing, be filed by 830627
SHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel 83/06/23 2pp 18994.176 24X Fiche 50-289, 83/06/23, 8306270286

8306270320 Forwards Commissioner Gilinsky 830622 memo re restart
CHILK, B. J. Office of the Secretary of the Commission 83/06/23
Office of the Executive Legal Director 1p 18994.041 24X
Fiche 50-289, 83/06/23, 8306270320

--8306270323 Presents tentative conclusions re restart Continued shortcomings in util performance show conditions that led to accident have not been corrected Top mgt must be replaced to resolve problems
GILINKEY, V. Commissioners 83/06/22 Office of the Executive Legal Director 3pp 18994.042 24X Fiche 50-289, 83/06/23, 8306270320

8306300095 Submits comments opposing Commission 830331 proposed no significant hazards determination re util proposed Tech Spec amend addressing steam generator tube repairs utilizing methods other than plugging
BOROSHIKH, J. Three Mile Island Alert 83/06/23 Office of the Secretary of the Commission 2pp 19120.013 24X
Fiche 50-289, 83/06/23, 8306300095

--8306300097 Affidavit of PL Lujanac that TMI Alert planning council officially endorsed TMI Alert 830519 request for hearing on proposed license amend re steam generator tube repair, on 830607
LUJANAC, P. L. Three Mile Island Alert 83/06/16 1p. 19120.016 24X Fiche 50-289, 83/06/23, 8306300095

8306280527 Response of Ltr-Designated Individuals O, VV & W, opposing Aamodt 830620 motion for provision of info to lift order of confidentiality of reopened hearing No substantial change in circumstances shown
VOIGT, M. H. Affiliation Unknown VOIGT, M. H. LeBoeuf, Lamb, Leiby & MacRae 83/06/27 Atomic Safety and Licensing Appeal Panel 3pp 19019.266 24X Fiche 50-289, 83/06/27, 8306280527

--8306280530 Response of individuals employed at TMI on 790328, opposing Aamodt 830620 request for matls from federal grand jury NRC lacks jurisdiction since grand jury matls can be disclosed only by court order Certificate of Svc encl
VOIGT, M. H. Affiliation Unknown 83/06/27 Atomic Safety and Licensing Appeal Panel 6pp 19017.280 24X
Fiche 50-289, 83/06/27, 8306280527

8306290399 Answer opposing Aamodt 830621 motion for provision of info & to lift order of confidentiality of reopened procedure Request for resumes of all new employees excessively burdensome W/Certificate of Svc
BAUSER, D. B. Metropolitan Edison Co BAUSER, D. B. Shaw, Pittman, Potts & Trowbridge 83/06/27 Atomic Safety and Licensing Appeal Panel 9pp 19053.106 24X Fiche 50-289, 83/06/27, 8306290399

8306290558 Answer opposing Aamodt 830601 motions for provision of info & to lift order of confidentiality Motion premature & overly broad in scope. Motion requesting info treated as discovery request for production of documents W/Certificate of Svc
WAGNER, M. E. Hearing Branch 4 83/06/27 Atomic Safety and Licensing Appeal Panel 495pp. 19050.313 24X
Fiche 50-289, 83/06/27, 8306290558

8306300039 Response supporting Aamodt 830621 motion for provision of info re mgt competence & integrity issues Info directly relevant Certificate of Svc encl
WEISS, E R Union of Concerned Scientists 83/06/27 Atomic Safety and Licensing Appeal Panel 4pp 19120 35B 24X
Fiche 50-289, 83/06/27, 8306300039

8306290372 Answer opposing UCS 830613 petition for Commission review of ALAB-729 No question of fact, law or policy affecting public health & safety presented for review Certificate of Svc encl
CUTCHIN, J M Hearing Branch 4 83/06/28 Commissioners 12pp 19055 202 24X Fiche 50-289, 83/06/28, 8306290372

8306300050 Answer opposing UCS 830613 petition for review of ALAB-729 Petition does not clearly identify issues needing review Four factors not addressed Certificate of Svc encl
BAXTER, T A Metropolitan Edison Co 83/06/28 Commissioners 12pp 19121 019 24X Fiche 50-289, 83/06/28, 8306300050

8306300087 Forwards util & Pickard, Lowe & Garrick correspondence re investigation of potential safety issues
BLAKE, E L Shaw, Pittman, Potts & Trowbridge BLAKE, E L Metropolitan Edison Co 83/06/28 EDLES, O J, BUCK, J H, KOHL, C N Atomic Safety and Licensing Appeal Panel 147pp 19120 042 24X Fiche 50-289, 83/06/28, 8306300087

H General correspondence

8306060142 Supports restart NRC incompetence & ineptitude displayed in encl 830525 news article
WILLIAMS, J O American Group Co 83/05/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 18727 249 24X Fiche 50-289, 83/05/27, 8306060142

8306130389 Discusses restart issues
LEE, J Affiliation Unknown 83/06/04 Commissioners 5pp 18823 017 24X Fiche 50-289, 83/06/04, 8306130389

8306100237 Ack receipt of 830602 ltr opposing restart of Unit 1 Ltr will be placed in docket file
GILINSKY, V Commissioners 83/06/08 HURST, A Affiliation Unknown 1p 18805 135 24X Fiche 50-289, 83/06/08, 8306100237

--8306100311 Opposes restart of Unit 1
HURST, A Affiliation Unknown 83/06/02 NRC - No Detailed Affiliation Given 3pp 18805 136 24X Fiche 50-289, 83/06/08, 8306100311

8306150174 Responds to 830523 ltr addressed to WJ Dircks & forwards "Priority Concerns of Licensed Nuclear Operators at TMI & Oyster Creek & Suggested Action Steps" & "Review of Current & Projected Expenditures & Manpower Utilization for GPU"
CUNNINGHAM, O H Office of the Executive Legal Director 83/06/13 LEWIS, M I Lewis, M 2pp 18851 001 24X Fiche 50-000, 83/06/13, 8306150174

--8306150179 "Priority Concerns of Licensed Nuclear Operators at TMI & Oyster Creek & Suggested Action Steps," final rpt
D'ARCY, P F, SAUER, J R Affiliation Unknown 83/03/15 56pp, 18851 003 24X Fiche 50-000, 83/06/13, 8306150174

--8306150185 "Review of Current & Projected Expenditures & Manpower Utilization for GPU Nuclear Corp."
* Basic Energy Technology Associates 83/02/28 161pp 18851 059 24X Fiche 50-000, 83/06/13, 8306150174

8306170377 Lists L. Brown comments on restart
GOLDSMITH, R Commissioners 83/06/13 Commissioners, 1p 18880 278 24X Fiche 50-289, 83/06/13, 8306170377

8306170385 Opines that NRC approach to separate corporate institution from corporate employees legally presumptuous & solidifies contention that NRC in collusion w/utills.
LEE, J Affiliation Unknown, 83/06/13 Commissioners 4pp 18880 066 24X Fiche 50-289, 83/06/13, 8306170385

8306270370 Opposes decision to allow restart before serious questions re integrity & competence of TMI mgt & staff resolved.
FINAMORE, B A, COCHRAN, T B. Natural Resources Defense Council 83/06/23, PALLADINO, N J, GILINSKY, V., ROBERTS, T. M. Commissioners 1p. 18793 314 24X Fiche 50-289, 83/06/23, 8306270370.

8306270303 Disagrees w/Commissioner Gilinsky attack on NRC chairman, president of GPU & president of GPU Nuclear GPU effort to recover from Mar 1979 accident commended
HALBKE, C. Atomic Industrial Forum 83/06/24, PALLADINO, N J Commissioners, 1p. 18795 287 24X Fiche 50-289, 83/06/24, 8306270303

P Operating license stage documents & correspondence

8305060487 Provides addl info per 830413 verbal request re emergency feedwater seismic qualification
HUKILL, H D General Public Utilities - GPU Service Corp 83/05/02 STOLZ, J F Operating Reactors Branch 4 2pp 18348 139 24X Fiche 50-289, 83/05/02, 8305060487

8306010404 Forwards operational QA plan for TMI-1 & Oyster Creek Nuclear Stations, per 10CFR50.54(a)(2) w/o encl
HUKILL, H D General Public Utilities - GPU Service Corp 83/05/23 Region 1, Office of Director 1p 18679 314 24X Fiche 50-000, 83/05/23, 8306010404

8306150297 Notice of consideration of issuance of amend to License DPR-50 & proposed no significant hazards consideration determination & opportunity for hearing Amend revises Tech Specs to recognize steam generator tube repair techniques
STOLZ, J F Operating Reactors Branch 4 83/05/24 9pp. 18870:017 24X Fiche 50-289, 83/05/24, 8306150297

8306060181 Forwards revised list of fees paid & fees due indicating over payment by util re amend applications Agree w/Items 1-4 in NRC 830425 ltr but takes exception w/Item 5 re steam generator repairs Refund requested
HUKILL, H D General Public Utilities - GPU Service Corp 83/06/01 MILLER, W O License Fee Management Branch 2pp 18728 184 24X Fiche 50-289, 83/06/01, 8306060181

8306200246 Forwards list of procedures reviewed, changed if appropriate & typical examples of controls that exist to assure equipment returned to svc, per NUREG-0608, Suppl 1
HUKILL, H D General Public Utilities - GPU Service Corp 83/06/01 Region 1, Office of Director 15pp 18901 187 24X Fiche 50-289, 83/06/01, 8306200246

8306220198 Forwards Vol 5, Number 4 to NUREG-0090, "Rpt to Congress on AOs," for Fourth Quarter CY82 One AO reported at NRC licensees re inoperability of containment spray sys Agreement states reported no AOs
AHEARNE, J F Commissioners 83/06/02 O'NEILL, T P House of Rep. BUSH, O H W Senate 2pp. 18940, 024 24X Fiche 50-000, 83/06/02, 8306220198

--8306220268 Discusses importance of carefully analyzing 830222 record of hearing on util/B&W litigation to determine whether record contains info bearing on questions of competence & character requirements of OL holder Questions per TMI-2 accident encl.
UDALL, M K House of Rep Interior & Insular Affairs 83/02/25, PALLADINO, N Commissioners 2pp 18940, 112 24X Fiche 50-000, 83/06/02, 8306220198

8306160606 Requests that NRR review listed B&W-GPU lawsuit documents re facility restart Conclusions & recommendations will be integrated into overall NRC conclusions on mgt integrity
DIRCKS, W J Office of the Executive Director for Operations 83/06/07 PALLADINO, N J, GILINSKY, V., AHEARNE, J F Commissioners 13pp 18884 315 24X Fiche 50-289, 83/06/07, 8306160606.

8306220207 Advises of NRC actions initiated to reach current position re impact of mgt integrity on restart Review should focus on past performance of individuals identified by various allegations, reviews & investigations
DIRCKS, W J Office of the Executive Director for Operations, 83/06/07 PALLADINO, N J, GILINSKY, V., AHEARNE, J Commissioners 13pp 18951:023 24X Fiche 50-289, 83/06/07, 8306220207.

8306090338 Forwards WJ Dircks 830607 memo to Commissioners re NRC recommendations for completion of restart review.
GOLDBERG, J R Hearing Branch 2 83/06/08 EDLES, O J, KOHL, C N, BUCK, J H Atomic Safety and Licensing Appeal Panel. 14pp. 18795 096 24X Fiche 50-289, 83/06/08, 8306090338

8306140014 Forwards amend fee & steam generator repair program review fee, per 830509 Tech Spec Change Request 125 & request for approval of steam generator repair
HUKILL, H D General Public Utilities - GPU Service Corp 83/06/08, STOLZ, J F Operating Reactors Branch 4 1p. 18838:326. 24X Fiche 50-289, 83/06/08, 8306140014.

8306140480 Forwards revised schedule for post-accident instrumentation transmitted by 830520 ltr re environ qualification of electrical equipment (10CFR50.49). Date of referenced ltr corrected. Original encl should be replaced
HUKILL, H D General Public Utilities - GPU Service Corp 83/06/08, DENTON, H A Office of Nuclear Reactor Regulation, Director 2pp. 18843, 279 24X Fiche 50-289, 83/06/08, 8306140480

DOCKETED ITEMS

8306140623 Advises that util will join other B&W owners in performing supplemental generic analyses to quantify reactor coolant pump trip subcooling margins, per 830518 discussion. Schedule will be submitted in Jul 1983.
HUKILL, H. D. General Public Utilities - GPU Service Corp. 83/06/08
STOLZ, J. F. Operating Reactors Branch 4. 1p. 18833 359 24X
Fiche 50-289, 83/06/08, 8306140623

8306170475 Requests current schedules on hot functional testing & plant readiness for criticality & power escalation testing. Identification of schedules of items controlling restart & any updated info requested by 830613.
EISENHUT, D. O. Division of Licensing. 83/06/08 HUKILL, H. D. General Public Utilities - GPU Service Corp. 3pp. 18894 332. 24X
Fiche 50-289, 83/06/08, 8306170475.

8306220224 Forwards draft tables reflecting status of NUREG-0752, NUREG-0737, NUREG-0480 & NUREG-0746 restart certification items. Meeting proposed for 830614 to discuss status of items listed in encl.
STOLZ, J. F. Operating Reactors Branch 4. 83/06/09 HUKILL, H. D. General Public Utilities - GPU Service Corp. 35pp. 18930 312 24X
Fiche 50-289, 83/06/09, 8306220224.

8306140586 Forwards restart milestone schedule, including hot functional testing & zero physics testing, in response to NRC 830608 request. W/ four oversize charts. Aperture cards are available in PDR.
HUKILL, H. D. General Public Utilities - GPU Service Corp. 83/06/10
EISENHUT, D. O. Division of Licensing. 2pp. 18841 294 24X
Fiche 50-289, 83/06/10, 8306140586

8306170256 Informs of post-repair testing results of repaired once-through steam generators & plans to proceed w/ remainder of test program. Drip, bubble & eddy current testing exams conducted. Add'l plugging repairs will be made.
HUKILL, H. D. General Public Utilities - GPU Service Corp. 83/06/13
STOLZ, J. F. Operating Reactors Branch 4. 3pp. 18878 165 24X
Fiche 50-289, 83/06/13, 8306170256.

8306220318 Requests FR publication of notice of consideration of issuance of amend to License DPR-50 & proposed no significant hazards consideration determination re steam generator repair techniques.
STOLZ, J. F. Operating Reactors Branch 4. 83/06/14 CLARK, R. A. Operating Reactors Branch 3. 2pp. 18977 130 24X
Fiche 50-289, 83/06/14, 8306220318.

8306280036 Forwards evaluation & request for add'l info on responses to 821210 order re NUREG-0737, item 11.F.2. "Detection of Inadequate Core Cooling." Clarification requested within 30 days. Digital indicators acceptable.
STOLZ, J. F. Operating Reactors Branch 4. 83/06/14. HUKILL, H. D. General Public Utilities - GPU Service Corp. 8pp. 19042 348. 24X
Fiche 50-289, 83/06/14, 8306280036.

8306210361 Notification of 830620 meeting w/util in Bethesda, MD to discuss actions taken to reinforce confidence in capability & integrity of util organization & personnel associated w/ facility.
VAN ULIE, J. Operating Reactors Branch 4. 83/06/17 STOLZ, J. F. Operating Reactors Branch 4. 2pp. 18937 226. 24X
Fiche 50-289, 83/06/17, 8306210361.

8306220071 Forwards INPD 830610 draft rept on restart evaluation & INPD May 1983 rept re corp assistance visit. Svc list encl.
BLAKE, E. L. Shaw, Pittman, Potts & Trowbridge. BLAKE, E. L. Metropolitan Edison Co. 83/06/20. EDLES, G. J., BUCK, J. H., KOHL, G. N. Atomic Safety and Licensing Appeal Panel. 46pp. 18927 188. 24X
Fiche 50-289, 83/06/20, 8306220071.

8306270231 Forwards application to amend License DPR-50, consisting of Tech Spec Change Request 127 re centerline fuel melt limit, flux to pump trip setpoint & quadrant tilt.
HUKILL, H. D. General Public Utilities - GPU Service Corp. 83/06/20.
STOLZ, J. F. Operating Reactors Branch 4. 1pp. 18988 240. 24X
Fiche 50-289, 83/06/20, 8306270231.

8306270233 Application to amend License DPR-50, consisting of Tech Spec Change Request 127 re centerline fuel melt limit, flux to pump trip setpoint & quadrant tilt.
HUKILL, H. D. General Public Utilities - GPU Service Corp. 83/06/20. 3pp. 18988 241 24X
Fiche 50-289, 83/06/20, 8306270233.

8306270234 Proposed Tech Specs re analyses of significant hazards considerations.
General Public Utilities - GPU Service Corp. 83/06/20. 4pp. 18988 246. 24X
Fiche 50-289, 83/06/20, 8306270234.

8306300087 Forwards util & Pickard, Lowe & Garrick correspondence re investigation of potential safety issues.
BLAKE, E. L. Shaw, Pittman, Potts & Trowbridge. BLAKE, E. L. Metropolitan Edison Co. 83/06/28. EDLES, G. J., BUCK, J. H., KOHL, G. N. Atomic Safety and Licensing Appeal Panel. 147pp. 19120 042. 24X
Fiche 50-289, 83/06/28, 8306300087.

0 Inspection reports, IE Bulletins & correspondence

8306200438 FOIA request for NRC Investigation Rept 1-83-003 re facilities.
KILCOYNE, J. J. Kilcoyne, J. J. 83/03/28 FELTON, J. Division of Rules and Records. 1p. 18920 018. 24X
Fiche 50-289, 83/03/28, 8306200438.

8306200434 Responds to FOIA request for NRC Investigation Rept 1-83-003 re facilities Rept withheld (ref FOIA Exemptions 5 & 7).
FELTON, J. M. Division of Rules and Records. 83/05/02. KILCOYNE, J. J. Kilcoyne, J. J. 1p. 18920 017. 24X
Fiche 50-289, 83/05/02, 8306200434.

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device." Svc list encl.
TAYLOR, J. M. Division of Safeguards & Inspection Programs (Post 830103). 83/05/26 Consolidated Edison Co. of New York, Inc. 125pp. 18831 043. 24X
Fiche 50-000, 83/05/26, 8305110458.

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/26 Consolidated Edison Co. of New York, Inc. 115pp. 18732 085. 24X
Fiche 50-000, 83/05/26, 8305110460.

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/31 Consolidated Edison Co. of New York, Inc. 114pp. 18732 208. 24X
Fiche 50-000, 83/05/31, 8305110461.

8306150005 Forwards IE Insp Rept 50-289/83-11 on 830329-0512 No noncompliance noted.
STAROSTECKI, R. Division of Project & Resident Programs. 83/06/02 HUKILL, H. D. General Public Utilities - GPU Service Corp. 2pp. 18846 348. 24X
Fiche 50-289, 83/06/02, 8306150005.

8306150008 IE Insp Rept 50-289/83-11 on 830329-0512 No noncompliance noted. Major areas inspected licensee action on previous insp findings, plant operation (shutdown), including steam generator repairs, restart mode & small break analysis.
YOUNG, F., BARR, K., CONTE, R. Region I, Office of Director. 83/06/02. 9pp. 18846 330. 24X
Fiche 50-289, 83/06/02, 8306150008.

8306280366 Responds to IE Bulletin 83-03 Emergency diesel generators at facility differ from those described in bulletin. Problems not experienced w/emergency diesel generator check valves.
HUKILL, H. D. General Public Utilities - GPU Service Corp. 83/06/08
Region I, Office of Director. 3pp. 19018 187. 24X
Fiche 50-289, 83/06/08, 8306280366.

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/09 Consolidated Edison Co. of New York, Inc. 119pp. 18830 280. 24X
Fiche 50-000, 83/06/09, 8305110464.

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/13 Consolidated Edison Co. of New York, Inc. 118pp. 18920 225. 24X
Fiche 50-000, 83/06/13, 8305110470.

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/13 Consolidated Edison Co. of New York, Inc. 243pp. 18921 001. 24X
Fiche 50-000, 83/06/13, 8306090010.

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/22 Consolidated Edison Co. of New York, Inc. 115pp. 19021 179. 24X
Fiche 50-000, 83/06/22, 8305110475.

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp. 18997 007. 24X
Fiche 50-000, 83/06/22, 8305110477.

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co. of New
York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8306300078 Forwards revised page to 820920 summary of stresses in
block wall elements per 830427 telcon. in response to
IE Bulletin 80-11 Rev reflects stresses following
reinforcement repairs of reactor bldg elevator shaft
HUKILL, H. D. General Public Utilities - GPU Service Corp 83/06/23
STOLZ, J. F. Operating Reactors Branch 1 2pp 19048 330 24X
Fiche 50-289, 83/06/23, 8306300078

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate
Range (IR) High Flux Trip Setpoints" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co. of New
York, Inc 116pp 19046 277 24X Fiche 50-000, 83/06/24, 8305110483

R Periodic operating reports & related correspondence

8306010407 Correction to annual operating rept 1981 containing info on
total aircraft movements at Harrisburg Intl Airport.
HUKILL, H. D. General Public Utilities - GPU Service Corp 83/05/11.
Region 1, Office of Director 2pp 18679 312 24X
Fiche: 50-289, 83/05/11, 8306010407

8306070215 Forwards "THI Aquatic Study, Apr 1983"
RESSLER, H. C. General Public Utilities - GPU Service Corp 83/06/01
HICKEY, C. NRC - No Detailed Affiliation Given 1p 18747 021
24X Fiche 50-289, 83/06/01, 8306070215

--8306070219 "THI Aquatic Study, Apr 1983"
NARDACCI, G. A. Ichthyological Associates, Inc 83/04/30 19pp
18747.022 24X Fiche 50-289, 83/06/01, 8306070219

8306300162 Forwards "THI Aquatic Study, Monthly Rept for May 1983,"
prepared by Ichthyological Assoc. Inc
RESSLER, H. C. General Public Utilities - GPU Service Corp 83/06/27
HICKEY, C. NRC - No Detailed Affiliation Given 1p 19119 280.
24X Fiche 50-289, 83/06/27, 8306300162

--8306300164 "THI Aquatic Study, Monthly Rept for May 1983"
NARDACCI, G. A. Ichthyological Associates, Inc 83/05/31 23pp
19119.281 24X Fiche 50-289, 83/06/27, 8306300162

S Reportable occurrences, LERs & related correspondence

8306010353 LER 83-013/03L-0 on 830419, while in cold shutdown, relay
room carbon dioxide fire protection sys pressure fell below
Tech Specs Caused by seat leakage through bleeder valve Fire
watch posted New valve installed. W/830518 ltr
STEPHENSON, C. J., HUKILL, H. D. General Public Utilities - GPU Service
Corp. 83/05/18 Region 1, Office of Director 4pp 18681 357
24X Fiche 50-289, 83/05/18, 8306010353

8306200127 Updated LER 82-002/03L-1 on 820128, during long-term cold
shutdown, leakage deposits observed on 2-inch nipple which
connects auxiliary bldg side of valve WDO-V4. Caused by
stress corrosion cracking Pipe replaced W/830606 ltr
STEPHENSON, C. J., HUKILL, H. D. General Public Utilities - GPU Service
Corp. 83/06/06 Region 1, Office of Director 8pp 18903 315
24X Fiche 50-289, 83/06/06, 8306200127

8306210247 Forwards updated LERs 83-003/01T-1 & 82-011/99X-1.
HUKILL, H. D. General Public Utilities - GPU Service Corp 83/06/06
Region 1, Office of Director 1p 18915 061 24X
Fiche 50-289, 83/06/06, 8306210247

--8306210254 Updated LER 82-011/99X-1 on 820831, notification received
from Hyle Labs that PORV severely corroded Caused by use of
acid sulfur compounds Spare valve installed
STEPHENSON, C. J., General Public Utilities - GPU Service Corp.
83/06/06 Region 1, Office of Director 1p 18915 062 24X
Fiche 50-289, 83/06/06, 8306210247

--8306210258 Updated LER 83-003/01T-1 on 830211, PORV special insp
revealed corrosion Caused by use of acid sulfur compounds
PORV internals replaced & leak tested & pressurizer steam
space inspected
STEPHENSON, C. J. General Public Utilities - GPU Service Corp.
83/06/06 Region 1, Office of Director 10pp 18915 063 24X
Fiche: 50-289, 83/06/06, 8306210247

8306210040 LER 83-015 on 830611, oxygen concentration in miscellaneous
waste storage tank gas space exceeded Tech Spec limits
Nitrogen used to purge oxygen from sys & reduce
concentration
TOOLE, R. J. General Public Utilities - GPU Service Corp 83/06/14.
MURLEY, T. E. Region 1, Office of Director 1p 18912 336 24X
Fiche 50-289, 83/06/14, 8306210040

8306280365 LER 83-014/03L-0 on 830518, while in long-term cold shutdown,
liquid radioactive effluent monitor RM-L6 found inoperable
RM-L6 functioned properly after monitor switch turned off &
on RMB recorder charts will be monitored W/830617 ltr
STEPHENSON, C. J., HUKILL, H. D. General Public Utilities - GPU Service
Corp 83/06/17 MURLEY, T. E. Region 1, Office of Director 4pp.
19001 200 24X Fiche 50-289, 83/06/17, 8306280365

T Hearing transcripts on non-antitrust matters

8306170450 Transcript of Commission 830615 briefing in Washington, DC
re status of certification in TMI-1 restart proceeding Pp
1-36 Supporting documentation encl
* Commissioners 83/06/15 80pp. 18906 234 24X
Fiche 50-289, 83/06/15, 8306170450

V Operator Examinations

8306140170 Extends invitation to attend 830627 meeting in King of
Prussia, PA to discuss transfer of reactor operator
licensing function from Bathesda, MD to Region 1 ofc.
STAROSTECKI, R. Division of Project & Resident Programs 83/06/09.
HUKILL, H. D. General Public Utilities - GPU Service Corp. 2pp
18839 036 24X Fiche 50-289, 83/06/09, 8306140170

DOCKET 50-293 PILGRIM NUCLEAR POWER STATION, UNIT 1

P Operating license stage documents & correspondence

8305240436 Forwards addl info on implementation of Rev 1 to NUREG-0313,
in response to NRC 830408 request W/two oversize drawings
Aperture cards are available in PDR
HARRINGTON, W. D. Boston Edison Co 83/05/20 VASSALLO, D. B.
Operating Reactors Branch 2 8pp 18573 224 24X
Fiche 50-293, 83/05/20, 8305240436

--8305240443 Rev 4 to Procedure 22 A 16, "Ultrasonic Exam of Piping
Welds"
DEEDS, P. E. Peabody International Corp 80/02/22 24pp
18573 232 24X Fiche 50-293, 83/05/20, 8305240436

--8305240448 Rev 53 to Procedure 58W1-NDT-600-3, "Manual Ultrasonic Exam
of Pressure Piping Welds"
* Southwest Research Institute 79/07/31 41pp 18573 256 24X
Fiche: 50-293, 83/05/20, 8305240436

--8305240455 Rev 3 to Procedure 58W1-NDT-700-3, "Mechanized Exam of
Vessel Components, Vessel Welds & Piping Welds."
* Southwest Research Institute 79/09/30 20pp. 18573 297 24X
Fiche: 50-293, 83/05/20, 8305240436

--8305240461 Rev 4 to Procedure 58W1-NDT-700-5, "Mechanized Ultrasonic
Exam of Vessel Components, Vessel Welds & Piping Welds."
* Southwest Research Institute 81/02/28 28pp. 18573 317 24X
Fiche: 50-293, 83/05/20, 8305240436

8306010334 Submits response to Generic Ltr 83-02 re implementation
of NUREG-0737 items No Tech Spec changes required for
Items I A 1 1.3, I A 1 3, II E 4, 1, II E 4, 2 5, II E 4 2 6,
II E 4 2 7, II K 3 3, II K 3 13, II K 3 22 & II K 3 15.
HARRINGTON, W. D. Boston Edison Co 83/05/24 EISENBAUM, D. G.
Division of Licensing 2pp 18672 315 24X Fiche 50-293, 83/05/24,
8306010334

8306070167 Application to amend License DPR-35, revising Tech Specs to
expand operating region of power/flow map & provide
associated changes in average power range monitor flux
scram & rod block trip settings. (Proposed Change 83-05.)
HARRINGTON, W. D. Boston Edison Co 83/05/31 VASSALLO, D. B.
Operating Reactors Branch 2 1p. 18739 004 24X
Fiche: 50-293, 83/05/31, 8306070167

--8306070170 Proposed Tech Specs expanding operating region of power/flow
map & providing associated changes in average power range
monitor flux scram & rod block trip settings
* Boston Edison Co 83/05/31 11pp. 18739 005 24X
Fiche: 50-293, 83/05/31, 8306070167

--8306070174 "OE BWR Extended Load Line Limit Analysis for Pilgrim
Nuclear Power Station Unit 1 Cycle 6."
STAROSTECKI, R. J. General Electric Co NFDQ-22198

DOCKETED ITEMS

- 8306070045 Clarifies misconception in 830513 safety evaluation submitted in response to NUREG-0737, Item II F 1-3 re containment high-range radiation monitors High-range drywell radiation monitors & procedures in place when response sent HARRINGTON, W D Boston Edison Co 83/06/01 VASSALLO, D B Operating Reactors Branch 2 1p 18739:243 24X Fiche 50-293, 83/06/01, 8306070045
- 8306070348 Forwards fee for 830405 proposed changes to Tech Spec Sections 2.2, 2 B & Table 3 11, per 10CFR170 HARRINGTON, W D Boston Edison Co 83/06/01 VASSALLO, D B Operating Reactors Branch 2 1p 18742:152 24X Fiche 50-293, 83/06/01, 8306070348
- 8306140613 Forwards Rev 1 to TR-5310-1, "Mark I Containment Program Plant Unique Analysis Rept of Torus Suppression Chamber for Pilgrim Station, Unit 1" HARRINGTON, W D Boston Edison Co 83/06/07 VASSALLO, D B Operating Reactors Branch 2 1p 18837:001 24X Fiche 50-293, 83/06/07, 8306140613
- 8306140616 "Mark I Containment Program Plant Unique Analysis Rept of Torus Suppression Chamber for Pilgrim Station, Unit 1" * Teledyne Engineering Services TR-5310-1 R01 83/04/21. 12pp 18837:002 24X Fiche 50-293, 83/06/07, 8306140613
- 8306220196 Advises that 830426 submittal of addl info re deletion of annual aerial photography acceptable Confirmation of commitment to implement modified breakeater monitoring program within 30 days requested VASSALLO, D B Operating Reactors Branch 2 83/06/07 HARRINGTON, W D Boston Edison Co 3pp. 18751:040. 24X Fiche 50-293, 83/06/07, 8306220196
- 8306150011 Forwards detailed design description of implementation of NUREG-0737, Item II F 1.6, "Containment Atmospheric Monitor," per 830411 request Task to be completed by 840601 HARRINGTON, W D Boston Edison Co 83/06/09 VASSALLO, D B Operating Reactors Branch 2 1pp 18846:334. 24X Fiche 50-293, 83/06/09, 8306150011
- 8306220003 Forwards "Offsite Dose Calculation Manual," per 830415 commitment re radiological effluent & environ monitoring Tech Specs. HARRINGTON, W D Boston Edison Co 83/06/16 VASSALLO, D B Operating Reactors Branch 2 1p 18928:078 24X Fiche 50-293, 83/06/16, 8306220003
- 8306220009 "Offsite Dose Calculation Manual," * Boston Edison Co 83/06/10 88pp 18928:079 24X Fiche 50-293, 83/06/16, 8306220003
- 8306280331 Forwards addl Class III fee for proposed Tech Spec Change 83-8 re max critical power ratio limits & safety relief valve simmer margin, per 830620 request. HARRINGTON, W D Boston Edison Co 83/06/23 VASSALLO, D B Operating Reactors Branch 2 1p 19001:222. 24X Fiche 50-293, 83/06/23, 8306280331
- G. Inspection reports, IE Bulletins & correspondence**
- 8306020409 Forwards IE Insp Rept 50-293/83-12 on 830426-29 & notice of violation. MARTIN, T T Division of Engineering & Technical Programs. 83/05/18 HARRINGTON, W D Boston Edison Co 2pp 18943:208 24X Fiche 50-293, 83/05/18, 8306020409
- 8306020413 Notice of violation from insp on 830426-29, * Region 1, Office of Director 83/05/18 2pp 18943:210 24X Fiche 50-293, 83/05/18, 8306020409
- 8306020416 IE Insp Rept 50-293/83-12 on 830426-29, Noncompliance noted, failure to control high radiation areas per Tech Spec 6.13 & failure to post airborne radioactivity areas per 10CFR20.203 WHITE, J R, SHANBAKY, M M Region 1, Office of Director. 83/05/16 9pp 18943:212 24X Fiche 50-293, 83/05/18, 8306020409
- 8306030119 Grants relief, in part, from inservice insp requirements of ASME Boiler & Pressure Vessel Code, per 790724 request Safety evaluation, technical evaluation rept & notice of granting of relief encl. VASSALLO, D B Operating Reactors Branch 2. 83/05/19, HARRINGTON, W D Boston Edison Co 3pp. 18734:239. 24X Fiche 50-293, 83/05/19, 8306030119.
- 8306030130 Safety evaluation, supporting in part, requests for relief from inservice insp requirements of ASME Boiler & Pressure Vessel Code, * Office of Nuclear Reactor Regulation, Director. 83/05/19. 18pp 18734:240 24X Fiche 50-293, 83/05/19, 8306030119
- 8209200370 "Pilgrim Nuclear Power Station Unit 1 Inservice Insp Program," technical evaluation rept * Science Applications, Inc NRC-03-02-076 BA1-186-02H-317 82/07/17 NRC - No Detailed Affiliation Given 34pp 18734:252 24X Fiche 50-293, 83/05/19, 8306030119
- 8306030134 Notice of granting relief, in part, from ASME Code Section XI inservice insp requirements VASSALLO, D B Operating Reactors Branch 2 83/05/19 2pp 18734:288 24X Fiche 50-293, 83/05/19, 8306030119
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103). 83/05/26 Consolidated Edison Co of New York, Inc. 125pp 18801:043 24X Fiche 50-000, 83/05/26, 8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732:085 24X Fiche 50-000, 83/05/26, 8305110460
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BHRs" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732:208 24X Fiche 50-000, 83/05/31, 8305110461
- 8306200158 Forwards IE Insp Rept 50-293/83-09 on 830404-0503 & notices of violation & deviation STAROSTECKI, R Division of Project & Resident Programs 83/06/06 HARRINGTON, W D Boston Edison Co 2pp 18903:004 24X Fiche 50-293, 83/06/06, 8306200158
- 8306200161 Notice of violation from insp on 830404-0503 * Region 1, Office of Director 83/06/06 2pp 18903:004 24X Fiche 50-293, 83/06/06, 8306200158
- 8306200162 Notice of deviation from insp on 830404-0503 * Region 1, Office of Director. 83/06/06 1p 18903:006 24X Fiche 50-293, 83/06/06, 8306200158
- 8306200166 IE Insp Rept 50-293/83-09 on 830404-0503, Noncompliance noted failure to maintain Q-list update FBAR & perform preventive maint. per Procedure 3 M 3-6 during last refueling cycle JOHNSON, J, EICHENHOLZ, H, ELASBER, T Region 1, Office of Director 83/05/23 23pp 24X Fiche 50-293, 83/06/06, 8306200158
- 8306170325 Forwards summary of 830510 mgt meeting w/util in Boston, MA re status of performance improvement program Apr 1983 milestones complete STAROSTECKI, R Division of Project & Resident Programs 83/06/07 HARRINGTON, W D Boston Edison Co 5pp 18878:246 24X Fiche 50-293, 83/06/07, 8306170325
- 8306140632 Advises that 830228 response, Rev 2 to performance improvement program to 820118 order, acceptable & incorporates 820927 comments Effectiveness of program implementation should be stressed at future meetings ALLAN, J M Region 1, Office of Director 83/06/08 HARRINGTON, W D Boston Edison Co 2pp 18043:060 24X Fiche 50-293, 83/06/08, 8306140632
- 8306230389 Forwards IE Insp Rept 50-293/83-13 on 830510-13 & notice of violation. MARTIN, T T Division of Engineering & Technical Programs 83/06/08 HARRINGTON, W D Boston Edison Co 2pp 18943:112 24X Fiche 50-293, 83/06/08, 8306230389
- 8306230392 Notice of violation from insp on 830510-13 * Region 1, Office of Director 83/06/08 1p 18943:114 24X Fiche 50-293, 83/06/08, 8306230389.
- 8306230397 IE Insp Rept 50-293/83-13 on 830510-13, Noncompliance noted, failure to follow procedures for chloride analysis mixed indicator solution & to review vendor lab procedures for strontium & tritium analyses of effluent samples. KOTTAN, J J, PASCIAK, W Region 1, Office of Director 83/06/02 7pp. 18943:115. 24X Fiche 50-293, 83/06/08, 8306230389
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations," Svc list encl. JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp. 18830:280. 24X Fiche 50-000, 83/06/09, 8305110464

DOCKETED ITEMS

111

8306140657 Ack receipt of 830531 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-293/83-07 STAROSTECKI, R Division of Project & Resident Programs 83/06/09 HARRINGTON, W D Boston Edison Co 1p 18834 005 24X Fiche 50-293, 83/06/09, 8306140657

--8306140662 Responds to NRC 830502 ltr re violations noted in IE Insp Rept 50-293/83-07 Corrective actions personnel counseled for failing to implement requirements of Procedure TP 82-43 re standby gas treatment sys HARRINGTON, W D Boston Edison Co 83/05/31 STAROSTECKI, R Division of Project & Resident Programs 2pp 18834 006 24X Fiche 50-293, 83/06/09, 8306140662

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting from Degraded Internal Connection Cables " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8306280357 Forwards IE Insp Rept 50-293/83-08 on 830509-13 & notice of violation MARTIN, T T Division of Engineering & Technical Programs 83/06/13 HARRINGTON, W D Boston Edison Co 2pp 19020 283 24X Fiche 50-293, 83/06/13, 8306280357

--8306280363 Notice of violation from insp on 830509-13 * Region 1, Office of Director 83/06/13 1p 19020 285 24X Fiche 50-293, 83/06/13, 8306280363

--8306280484 IE Insp Rept 50-293/83-08 on 830509-13 Noncompliance noted failure to conduct radiological environ monitoring program audit at required frequency & failure to submit 1982 radiological environ monitoring program rept on time JACKSON, T J, STRUCKMAYER, R, PASCIAK, W Region 1, Office of Director 83/06/09, 7pp 19020 286 24X Fiche 50-293, 83/06/13, 8306280357

8306240172 Informs that Rev 1 to ASME testing program for pumps & valves will be sent by 830715 Rev concerns second 10-yr insp interval for period 821208-921207 Submittal will also contain relief requests HARRINGTON, W D Boston Edison Co 83/06/17 VASSALLO, D D Operating Reactors Branch 2 1p 18901 035 24X Fiche 50-293, 83/06/17, 8306240172

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions." Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints." Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

R Periodic operating reports & related correspondence

8306020154 Monthly operating rept for Mar 1983, W/830413 ltr. HARRINGTON, W D, WHITNEY, G O Boston Edison Co 83/04/13 7pp. 18690 347 24X Fiche 50-293, 83/04/13, 8306020154

S Reportable occurrences, LLRs & related correspondence

8306010386 Updated LER 81-059/03L-1 on 811002, acceptance criteria for Test 8 7 3, "Secondary Containment Leak Rate Test," not met Caused by damper alignment reducing capability Engineering evaluations added to procedure W/830509 ltr HARRINGTON, W D, VENDER, J Boston Edison Co 83/05/09 Region 1, Office of Director 2pp 18682 171 24X Fiche 50-293, 83/05/09, 8306010386

8306010393 LER 83-020/01T-0 on 830429, Tech Spec Sections 3 11 D & 4 11 D not incorporated Sections issued w/Amend 39 & inadvertently deleted by Amend 42 Caused by personnel error Procedural change initiated W/830512 ltr WHITNEY, G O, HARRINGTON, W D Boston Edison Co 83/05/12 Region 1, Office of Director 3pp 18682 231 24X Fiche 50-293, 83/05/12, 8306010393

8306010157 LER 83-023/03L-0 on 830420 & D504, diesel generator fuel pump belt A broke Caused by improper installation Detailed instructions written & belt replaced W/830513 ltr WHITNEY, G O, HARRINGTON, W D Boston Edison Co 83/05/13 Region 1, Office of Director 2pp 18673 336 24X Fiche 50-293, 83/05/13, 8306010157

8306010322 LER 83-019/03L-0 on 830410, sprinkler head supply pipe on top of turbine stop valves found severed w/water running from pipe Probably caused by pipe fatigue due to vibration Pipe threaded, installed & visually inspected W/830513 ltr ORAHAM, E T, HARRINGTON, W D Boston Edison Co 83/05/13 Region 1, Office of Director 2pp 18682 275 24X Fiche 50-293, 83/05/13, 8306010322

8306010060 LER 83-024/03L-0 on 830421, drywell airborne leak detection sys (C-19) particulate channel found inoperable Caused by failure of heat tracing on sensing line to particulate detector Heat tracing repaired W/830516 ltr WHITNEY, G O, HARRINGTON, W D Boston Edison Co 83/05/16 Region 1, Office of Director 2pp 18674 084 24X Fiche 50-293, 83/05/16, 8306010060

8306010275 Updated LER 82-047/03X-1 on 821008, water leak observed on 74-ft elevation of reactor bldg in reactor water cleanup holding pump room Caused by socket weld cracks in vent assembly New assembly installed W/830516 ltr VENDER, J, HARRINGTON, W D Boston Edison Co 83/05/16 Region 1, Office of Director 2pp 18672 241 24X Fiche 50-293, 83/05/16, 8306010275

8306020419 LER 83-025/03L-0 on 830423, during fire protection surveillance, sliding door in switchgear room did not fully close, Caused by interference between knot in counterweight rope & security barrier Knot removed, W/830524 ltr HARRINGTON, W D, WHITNEY, G O Boston Edison Co 83/05/24, Region 1, Office of Director 2pp 18694 125 24X Fiche 50-293, 83/05/24, 8306020419

8306020456 Updated LER 82-034/03X-2 on 820826, both HPCI area smoke detector sys made inoperable to perform corrective maint due to moisture inside detectors Caused by condensation from steam leak Detectors replaced W/830524 ltr VENDER, J, HARRINGTON, W D Boston Edison Co 83/05/24, Region 1, Office of Director 2pp 18693 304 24X Fiche 50-293, 83/05/24, 8306020456

8306210206 Updated LER 83-005/01X-1 on 830216, util operated w/o 0.25X delta K shutdown margin required per Tech Spec 3 3 A 1 Caused by inappropriate cold critical eigenvalue used in QE calculations W/830831 ltr VARNER, D M, HARRINGTON, W D Boston Edison Co 83/05/31 Region 1, Office of Director 5pp 18919 022 24X Fiche 50-293, 83/05/31, 8306210206

8306210184 Updated LER 81-058/01X-1 on 811026, during refuel outage, cable spreading room carbon dioxide sys declared inoperative following abort of special operability test, Caused by design deficiency Halon 1301 flooding sys installed W/830608 ltr VERRELLI, D M, HARRINGTON, W D Boston Edison Co 83/06/08 Region 1, Office of Director 3pp 18915 154 24X Fiche 50-293, 83/06/08, 8306210184

8306280072 LER 83-026/03L-0 on 830515, during insp of control rod drive piping, number of vent valve plugs discovered missing No leaks observed, Caused by inadequate procedures Missing plugs replaced, Procedures modified W/830613 ltr WHITNEY, G O, HARRINGTON, W D Boston Edison Co 83/06/13 Region 1, Office of Director 2pp 19001 175 24X Fiche 50-293, 83/06/13, 8306280072

DOCKETED ITEMS

B306280358 LER 83-028/03L-0 on 830518, diesel generator fuel booster pump belt B parted Caused by broken belt clip & conditions not allowing immediate replacement of belt D when belt A broken Belt B replaced w/830613 ltr
WHITNEY, C O, HARRINGTON, W D Boston Edison Co 83/06/13
Region 1, Office of Director 2pp. 19001 274 24X
Fiche 50-293, 83/06/13, B306280358

V Operator Examinations

B306140055 Extends invitation to attend 830627 meeting in King of Prussia, PA to discuss transfer of reactor operator licensing function from Bethesda, MD to Region 1 ofc STAROSTECKI, R Division of Project & Resident Programs 83/06/09
HARRINGTON, W D Boston Edison Co 2pp 18838 337 24X
Fiche 50-293, 83/06/09, B306140055

DOCKET 50-294 MICHIGAN STATE UNIV RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

B306210333 Forwards request for addl info re MI State Univ research reactor B21006 emergency plan to continue review per requirements 10CFR50, App E, Reg Guide 2.6, Rev 1 & ANSI/ANS-15.16-1982 Info requested within 30 days of ltr date.
THOMAS, C O Standardization & Special Projects Branch 83/06/10
WILKINSON, B W Michigan State Univ 6pp 18921 334 24X
Fiche 50-294, 83/06/10, B306210333

DOCKET 50-295 ZION NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

B306210314 FOIA request for NRC records re security violations & safeguards events at nuclear facilities
GOLDENBERG, G Scripps-Howard Newspapers 83/04/22 FELTON, J M
Office of Administration 2pp 18925 198, 24X
Fiche 50-000, 83/04/22, B306210314

B306210306 Partial response to FOIA request for NRC records re security violations & safeguards events at nuclear facilities Repts listed on App A available in PDR. Search for addl documents subj to request continuing
FELTON, J M Division of Rules and Records 83/05/16, GOLDENBERG, G
Scripps-Howard Newspapers 2pp 18925 198, 24X
Fiche 50-000, 83/05/16, B306210306

B306130294 Forwards FEMA final exercise evaluations of offsite emergency preparedness exercise conducted on 810729, 1007 & B306110 No major exercise deficiencies noted
HIND, J A Region 3, Office of Director 83/06/09, REED, C
Commonwealth Edison Co 2pp 18823 334 24X Fiche: 50-295, 83/06/09, B306130294

P Operating license stage documents & correspondence

B306030508 Forwards draft "Control of Heavy Loads (C-10), Zion Station Units 1 & 2," per responses to NRC B00731 request for review of provisions for handling & control of heavy loads in conformance w/NUREG-0412 Addl guidance encl
VARQA, S A Operating Reactors Branch 1 83/05/19, FARRAR, D L
Commonwealth Edison Co, 15pp 18735 006 24X Fiche: 50-295, 83/05/19, B306030508

--B306030512 Draft "Control of Heavy Loads (C-10), Zion Station Units 1 & 2," technical evaluation rept.
SARGENT, I H, VITO, D J Franklin Institute/Franklin Research Center NRC-03-81-130 TCR-C5506-403/404 DR. 82/11/30
CLEMENSEN, F NRC - No Detailed Affiliation Given 30pp
18735 021 24X Fiche 50-295, 83/05/19, B306030508

B306090194 Discusses util interpretation of 10CFR50.49, "Environment Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants" Intent of rulemaking is to require upgrade program for replacement equipment not parts
FARRAR, D L Commonwealth Edison Co, 83/06/03, DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp. 18796 090, 24X
Fiche: 50-000, 83/06/03, B306090194

B306210073 Suppl 830513 ltr re NUREG-0737, Item II.F.1.5, "Containment Water Level Monitoring Sys" Lower value of transmitter error should be used for calculating of overall loop uncertainties
LENTINE, F O, Commonwealth Edison Co 83/06/13, DENTON, H R Office of Nuclear Reactor Regulation, Director. 1p. 18912 291, 24X
Fiche: 50-295, 83/06/13, B306210073.

B306230219 Forwards addl info on control room human factors items re nuisance alarms, prioritization of multiple alarms & communications w/breathing apparatus, in response to B30511 telcon
LENTINE, F O Commonwealth Edison Co 83/06/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 19pp 18945 264 24X
Fiche 50-295, 83/06/16, B306230219

G Inspection reports, IE Bulletins & correspondence

B306060218 Forwards IE Insp Repts 50-295/83-04 & 50-304/83-04 on B30305-0429 & notice of violation
SHAHER, W D Region 3, Office of Director 83/05/19 REED, C
Commonwealth Edison Co 2pp 18727 306 24X Fiche 50-295, 83/05/19, B306060218

--B306060219 Notice of violation from insp on B30305-0429
SHAHER, W D Region 3, Office of Director 83/05/19 2pp
18727 308 24X Fiche 50-295, 83/05/19, B306060218

--B306060221 IE Insp Repts 50-295/83-04 & 50-304/83-04 on B30305-0429 Noncompliance noted failure to provide procedures to account for plant condition changes after instrument calibr & failure to keep high radiation door locked
WATERS, J R, DUNAWAY, F R, HARTMANN, F L Region 3, Office of Director 83/05/18 12pp 18727 310 24X Fiche 50-295, 83/05/19, B306060218

B305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post B30103) 83/05/26 Consolidated Edison Co of New York, Inc
125pp 18831 043 24X Fiche 50-000, 83/05/26, B305110458

B305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 089 24X Fiche 50-000, 83/05/26, B305110460

B305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at DWRs" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, B305110461

B306090125 Confirms B30602 telcon request for 1-wk extension to reply to notice of violation & proposed imposition of civil penalty Request granted
KEPPLER, J O Region 3, Office of Director 83/06/06 O'CONNOR, J J
Commonwealth Edison Co 1p 18795 290 24X Fiche 50-295, 83/06/06, B306090125

B306100094 Forwards response to IE Bulletin 83-03 re diesel generator cooling water check valves Plants utilize Mission Duo-Check valves employing hinge-to-pin design for protection against vibration-induced failure
BARNES, P L Commonwealth Edison Co 83/06/07 KEPPLER, J O Region 3, Office of Director 7pp 18802 230 24X Fiche 50-000, 83/06/07, B306100094

B306170380 Forwards response to IE Bulletin 83-03 re diesel generator cooling water check valves Valves at Dresden & LaBolle acceptable w/o further insp Rept on valve failures at Quad Cities will be submitted within 90 days of insp completion
BARNES, P L Commonwealth Edison Co 83/06/07 KEPPLER, J O Region 3, Office of Director 7pp 18880 211 24X Fiche 50-000, 83/06/07, B306170380

B305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fiche: 50-000, 83/06/09, B305110464

B305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225, 24X Fiche 50-000, 83/06/13, B305110470

B306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp, 18921 001 24X Fiche 50-000, 83/06/13, B306090010

DOCKETED ITEMS

113

8306170277 Forwards addendum consisting of confirmatory measurements program data sheet for IE Insp Repts 50-295/83-30 & 50-304/82-27 re St-89 & St-90 Info will close Open Items 295/82-30-0 & 304/82-27-01
PAPERIELLO, C J Region 3, Office of Director 83/06/14 REED, C Commonwealth Edison Co 3pp 18078 268 24X Fiche 50-295, 83/06/14, 8306170277

8306220026 Ack receipt of 830524 ltr informing NRC of steps taken to correct violations noted in IL Insp Repts 50-295/83-07 & 50-304/83-06
PAPERIELLO, C J Region 3, Office of Director 83/06/17 REED, C Commonwealth Edison Co 1p 18928 210 24X Fiche 50-295, 83/06/17, 8306220026

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 115pp 19021 174 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Activation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 742 24X Fiche 50-000, 83/06/23, 8305110479

8306300197 Ack receipt of 830616 ltr informing NRC of steps taken to correct violations noted in IL Insp Repts 50-295/83-04 & 50-304/83-04
SHAFER, W D Region 3, Office of Director 83/06/23 REED, C Commonwealth Edison Co 1p 19122 174 24X Fiche 50-295, 83/06/23, 8306300197

--8306300216 Responds to NRC 830519 ltr re violations noted in IE Insp Repts 50-295/83-04 & 50-304/83-04 Corrective actions entire Radiological Protection Procedure 1190-1 will be kept at work site w/calibr sheet
FARRAR, D L Commonwealth Edison Co 83/06/16 KEPLER, J G Region 3, Office of Director 3pp 19122 184 24X Fiche 50-295, 83/06/23, 8306300197

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

8306290329 Forwards "Inservice Insp & Test Program, Second Interval, Zion Nuclear Power Station " Programs applicable for 120-month interval beginning 031231 for Unit 1 & 840919 for Unit 2
LENTINE, F G Consolidated Edison Co of New York, Inc 83/06/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 19054 027 24X Fiche 50-295, 83/06/27, 8306290329

--8306290335 "Inservice Insp & Test Program, Second Interval, Zion Nuclear Power Station "
* Consolidated Edison Co of New York, Inc 83/06/27 358pp, 19054 028 24X Fiche 50-295, 83/06/27, 8306290329

R Periodic operating reports & related correspondence

8306070233 "Zion Nuclear Generating Station," second evaluation, * Institute of Nuclear Power Operations 83/04/30 38pp 18741.117 24X Fiche 50-295, 83/04/30, 8306070233

8306140412 Monthly operating repts for May 1983 W/830608 ltr
AUSTIN, G, GRAEBER, K L Commonwealth Edison Co 83/06/08 Director's Office, Office of Inspection and Enforcement 12pp, 18838, 049 24X Fiche 50-295, 83/06/08, 8306140412

S Reportable occurrences, LCRs & related correspondence

8306100064 LER 83-013/03L-0 on 830430 gas cubicle radiation monitor QRTPRO28 failed & would not respond to check source Caused by stuck check source due to accumulated grime Tube, through which check source travels, cleaned W/830608 ltr
WILLIAMS, V S, GRAEBER, K L Commonwealth Edison Co 83/06/02, KEPLER, J G Region 3, Office of Director 2pp, 18803 067 24X Fiche 50-295, 83/06/02, 8306100064

8306130307 Updated 83-012/03X-1 on 830413, Class 1 pipe tunnel iodine monitor IRTPRO7B failed low Caused by personnel incorrectly adjusting high voltage setting on 830412 High voltage readjusted W/830603 ltr
WILLIAMS, V S, GRAEBER, K L Commonwealth Edison Co 83/06/03 KEPLER, J G Region 3, Office of Director 2pp 18823 297 24X Fiche 50-295, 83/06/03, 8306130307

8306130351 LER 83-014/01T-0 on 830521, during prolonged forced reduction in power, routine extended cycle analysis revealed original final acceptance criteria analysis not still bounding Caused by inaccurate core depletion models W/830603 ltr
CHIN, R Y, GRAEBER, K L Commonwealth Edison Co 83/06/03 KEPLER, J G Region 3, Office of Director 2pp 18822 324 24X Fiche 50-295, 83/06/03, 8306130351

8306220060 PND-III-83-044 on 830614, radiation chemistry lab foreman exiting plant Employee instructed to proceed to radiation protection ofc located in vital area for decontamination
BOYD, D, SHAFER, W Region 3, Office of Director 83/06/15 1p, 18930 174 24X Fiche 50-295, 83/06/15, 8306220060

8306230438 PND-III-83-048 on 830615, contractor employee reentered plant unescorted after triggering contamination monitor on existing plant Employee instructed to proceed to radiation protection ofc located in vital area for decontamination
CREED, J, MILLER, J, HIND, J Region 3, Office of Director 83/06/17 1p 18942 078 24X Fiche 50-295, 83/06/17, 8306230438

8306270168 LER 83-015/03L-0 on 830425, reactor coolant wide-range pressure indicator IPI-403 found reading low Caused by degradation of two dc u709 amplifiers & gain factor switch on summator IPI-403 Summator replaced W/830617 ltr
CANTWELL, P F, GRAEBER, K L Commonwealth Edison Co 83/06/17 KEPLER, J G Region 3, Office of Director 2pp 18992 018 24X Fiche 50-295, 83/06/17, 8306270168

DOCKET 50-296 BROWN'S FERRY NUCLEAR POWER STATION, UNIT 3

F Security, medical, emergency & fire protection plans

8306140107 Forwards summary of 830315 meeting at Region 11 ofc re proposed security mods for future const activities at facilities list of attendees encl
LEWIS, R C Division of Project & Resident Programs 83/03/25, PARRIS, H G Tennessee Valley Authority 4pp 18839, 082 24X Fiche 50-259, 83/03/25, 8306140107

8306270007 Forwards revised physical security plan, reflecting NRC 830412 comments, Rev withheld (ref 10CFR73.21)
MILLS, L M Tennessee Valley Authority 83/06/03, O'REILLY, J P Region 2, Office of Director 1p 18988 153 24X Fiche 50-259, 83/06/03, 8306270007

8306210010 Forwards "Program Plan for Control Room Design Reviews for all TVA Nuclear Plants," in response to Generic Ltr 82-33 re upgrade of emergency plans
KAMMER, D S Tennessee Valley Authority 83/06/09, ADENBAM, E, Licensing Branch 4 3pp 18913 001 24X Fiche 50-000, 83/06/09, 8306210010

--8306210016 Procedure 842209 10, "Program Plan for Control Room Design Reviews for all TVA Nuclear Plants "
* Tennessee Valley Authority 83/06/09, 200pp 18913 004 24X Fiche 50-000, 83/06/09, 8306210010

8306230201 Notification of 830621 meeting w/util in Bethesda, MD to discuss potential rev to App R submittal based on revised criteria w/respect to analyses on loss of offsite power & availability of other onsite units & condensate pumps.
CLARK, D Operating Reactors Branch 2 83/06/16 VASSALLO, D B, Operating Reactors Branch 2 1p 18954 357 24X Fiche 50-259, 83/06/16, 8306230201

8306210194 Ack receipt of 830603 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-299/83-10, 50-260/83-10 & 50-296/83-10
LEWIS, R C Division of Project & Resident Programs, 83/06/17 PARRIS, H G Tennessee Valley Authority 1p 18919, 030 24X Fiche 50-259, 83/06/17, 8306210194

--8306210203 Forwards response to NRC 830429 ltr re violations noted in IE Safeguards Insp Repts 50-259/83-10, 50-260/83-10 & 50-296/83-10, Corrective actions withheld (ref 10CFR73.21).
MILLS, L M Tennessee Valley Authority, 83/06/03 O'REILLY, J P Region 2, Office of Director 1p 18919 031, 24X Fiche 50-259, 83/06/17, 8306210194

DOCKETED ITEMS

--8306210213 Forwards IE Safeguards Insp Repts 50-259/83-10, 50-260/83-10 & 50-296/83-10 on 830404-08 Noncompliance noted Failure to follow access control procedures Details withheld (ref 10CFR73 21).
LEWIS, R C Division of Project & Resident Programs 83/04/29
PARRIS, H G Tennessee Valley Authority 2pp 18919 032 24X
Fiche 50-259, 83/06/17, 8306210194

--8306210224 IE Safeguards Insp Repts 50-259/83-10, 50-260/83-10 & 50-296/83-10 on 830404-08 Noncompliance noted Failure to follow access control procedures Details withheld (ref 10CFR73 21).
MOORE, D E Region 2, Office of Director 83/04/27 1p
18919 034 24X Fiche 50-259, 83/06/17, 8306210194

G Adjudicatory correspondence

8306230350 Motion for extension until 830711 to file proposed findings of fact Time needed since intervenors filing consolidated findings & one atty suffered death in family Certificate of Svc encl
WEISS, E R Union of Concerned Scientists WEISS, E R Harmon & Weiss 83/06/21 Atomic Safety and Licensing Board Panel 6pp
18943 291 24X Fiche 50-247, 83/06/21, 8306230350

P. Operating license stage documents & correspondence

8306020180 Forwards safety evaluation re valve operability for 10.18 & 20-inch butterfly valves used for purge or vent of containments info submitted fails to demonstrate valve ability to close against pressure buildup during LOCA
VASSALLO, D B Operating Reactors Branch 2 83/05/19 PARRIS, H G
Tennessee Valley Authority 3pp 18701 113 24X
Fiche 50-259, 83/05/19, 8306020180

--8306020187 Safety evaluation re valve operability for 10.18 & 20-inch butterfly valves used for purge or vent of containments info submitted fails to demonstrate valve ability to close against pressure buildup during LOCA
* Office of Nuclear Reactor Regulation, Director 83/05/19 4pp
18701 116 24X Fiche 50-259, 83/05/19, 8306020180

8306150260 Forwards "Control of Heavy Loads (C-10), TVA, Browns Ferry Nuclear Power Station, Units 1, 2 & 3," draft technical evaluation re Conference call requested within 4 to 5 wks to discuss review results
VASSALLO, D B Operating Reactors Branch 2 83/05/26 PARRIS, H G
Tennessee Valley Authority 2pp 18869 322 24X
Fiche 50-259, 83/05/26, 8306150260

--8306150266 "Control of Heavy Loads (C-10), TVA, Browns Ferry Nuclear Power Station, Units 1, 2 & 3," draft technical evaluation re
BOMBERGER, C, AHMED, N, SARGENT, I H Franklin Institute/Franklin Research Center NRC-03-81-130 TER-C5506-337/338/33 83/04/05
CLEMONSON, F NRC - No Detailed Affiliation Given, 25pp
18869 324 24X Fiche 50-259, 83/05/26, 8306150260

8306160453 Application for amend to Licenses DPR-52 & DPR-6B, changing Tech Specs to allow operation w/increased core flow
MILLS, L M Tennessee Valley Authority 83/06/02 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 18863 312
24X Fiche 50-260, 83/06/02, 8306160453

--8306160456 Proposed Tech Spec changes allowing operation w/increased core flow.
* Tennessee Valley Authority 83/06/02 14pp. 18863 314 24X
Fiche 50-260, 83/06/02, 8306160453.

8306150243 Suppl 6 to 820914 application for amend to Licenses DPR-33, DPR-52 & DPR-6B, changing Tech Specs 3 10 C & 4.10 C re min depth of water required over single irradiated fuel assemblies during handling.
MILLS, L M Tennessee Valley Authority 83/06/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director, 2pp 18946 127
24X Fiche: 50-259, 83/06/03, 8306150243

--8306150248 Proposed changes to Tech Specs 3 10 C & 4.10 C re min depth of water required over single irradiated fuel assemblies during handling
* Tennessee Valley Authority 83/06/03 10pp. 18846 129 24X
Fiche 50-259, 83/06/03, 8306150243

8306140656 Forwards response to 830519 request for info re BCR, Section 4.0 on containment purge & vent valves, operability of valves justified under LOCA conditions
MILLS, L M Tennessee Valley Authority 83/06/07 DENTON, H R
Office of Nuclear Reactor Regulation, Director, 9pp 18834:008
24X Fiche 50-259, 83/06/07, 8306140656

8306160507 Application for emergency amend to Licenses DPR-33, DPR-52 & DPR-6B, changing Tech Spec standby gas treatment sys required surveillance interval to once per operating cycle
MILLS, L M Tennessee Valley Authority 83/06/13 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 18864 157
24X Fiche 50-259, 83/06/13, 8306160507

--8306160523 Proposed Tech Specs changing standby gas treatment sys required surveillance interval to once per operating cycle
Justification for emergency nature of proposed Tech Spec change encl
* Tennessee Valley Authority 83/06/13 5pp 18864 159 24X
Fiche 50-259, 83/06/13, 8306160507

8306210014 Confirms agreement w/NRC re interpretation of Tech Spec 4 7 B 3 a requirements Spec satisfied by commitment to activate annually standby gas treatment blowers in primary containment isolation sys logic Tech Spec 189 needed
MILLS, L M Tennessee Valley Authority 83/06/16 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 18911 357
24X Fiche 50-259, 83/06/16, 8306210014

8306290400 Application to amend Licenses DPR-33, DPR-52 & DPR 6B, changing Tech Specs to require annual rept of main steam safety/relief valve actuations, in response to NUREG-0737, Item II K 3 3 & Generic Ltr 83-02
MILLS, L M Tennessee Valley Authority 83/06/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 19053 133
24X Fiche 50-259, 83/06/20, 8306290400

--8306290408 Proposed Tech Spec revs, requiring annual rept of main/steam safety/relief valve actuations, in response to NUREG-0737, Item II K 3 3 & Generic Ltr 83 02
* Tennessee Valley Authority 83/06/20 5pp 19053 135 24X
Fiche 50-259, 83/06/20, 8306290400

8306240394 Notification of 830627 meeting w/util in Bethesda, MD to discuss util analysis on intervening combustibles & separation of circuits
CLARK, D Operating Reactors Branch 2 83/06/22 VASSALLO, D B
Operating Reactors Branch 2 2pp 18779 15/ 24X
Fiche 50-259, 83/06/22, 8306240394

8306280415 Suppl 821220 response to NUREG-0313 request for addl info Ferrite content of cast austenitic stainless steel ranges from 15 to 20% Valves highly resistant to intergranular stress corrosion cracking
MILLS, L M Tennessee Valley Authority 83/06/22 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 19018 351
24X Fiche 50-259, 83/06/22, 8306280415

8306280567 Advises that OE equipment items discussed in 830520 ltr re environ qualification reclassified as nonproprietary
MILLS, L M Tennessee Valley Authority 83/06/23 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 19010 028 24X
Fiche 50-259, 83/06/23, 8306280567

8306300177 Discusses continuing problem re extreme length of time required for approval & resulting backlog of pending requests for tech Spec changes Majority of changes administrative & require minimal review time
MILLS, L M Tennessee Valley Authority 83/06/27 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 19122 044
24X Fiche 50-259, 83/06/27, 8306300177

0 Inspection reports, IE Bulletins & correspondence

8306290218 Forwards IE Insp Repts 50-259/83-03, 50-260/83-03 & 50-296/83-03 on 830110-14 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/03/21
PARRIS, H G Tennessee Valley Authority 2pp 19056 135 24X
Fiche 50-259, 83/03/21, 8306290218

--8306290224 Notice of violation from insp on 830110-14
* Region 2, Office of Director 83/03/21 9pp 19056 137 24X
Fiche 50-259, 83/03/21, 8306290218

--8306290228 IE Insp Repts 50-259/83-03, 50-260/83-03 & 50-296/83-03 on 830110-14 Noncompliance noted failure to perform evaluation of radiation hazards to personnel & employee failure to wear gloves in contaminated zone
DEBB, B T, BARR, K P Region 2, Office of Director, 83/03/03
9pp 19056 139 24X Fiche 50-259, 83/03/21, 8306290218

8306140543 Confirms mgt meeting on 830421 in Chattanooga, TN to review results of first phase of annual appraisal of regulatory performance, per 830328 telcon.
LEWIS, R C Division of Project & Resident Programs 83/04/12
PARRIS, H G Tennessee Valley Authority 3pp 18834.176 24X
Fiche 50-000, 83/04/12, 8306140543

8306140041 Forwards results of testing required by IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls." Two valves each in HPCI sys & RCIC sys do not remain closed on reset of sys line isolation signal
KAMMER, D S Tennessee Valley Authority 83/05/12 O'REILLY, J P
Region 2, Office of Director 2pp 18038 251 24X
Fiche 50-260, 83/05/12, 8306140041

8306140422 Confirms 830601 mgt meeting at site to discuss mgt controls for refueling operations, per 830519 telcon
LEWIS, R C Division of Project & Resident Programs 83/05/23
PARRIS, H O Tennessee Valley Authority 3pp 18838 049 24X
Fiche 50-259, 83/05/23, 8306140422

8306140685 Forwards IE Insp Repts 50-259/83-17, 50-260/83-17 & 50-276/83-17 on 830509-12 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/05/25
PARRIS, H O Tennessee Valley Authority 2pp 18841 336 24X
Fiche 50-259, 83/05/25, 8306140685

--8306140692 IE Insp Repts 50-259/83-17, 50-260/83-17 & 50-276/83-17 on 830509-12 No noncompliance noted Major areas inspected followup on IE Bulletin 80-11, "Masonry Wall Design"
LENAHAN, J J, CONLON, T L Region 2, Office of Director 83/05/25
5pp 18841 338 24X Fiche 50-259, 83/05/25, 8306140685

8305110458 IE Info Notice 83-32, "Ruptured Am-P41 Sources Contained in Well Logging Device" Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc
125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306140251 Ack receipt of 830525 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-09, 50-260/83-09 & 50-276/83-09
LEWIS, R C Division of Project & Resident Programs 83/06/02
PARRIS, H O Tennessee Valley Authority 1p 18832 236 24X
Fiche 50-259, 83/06/02, 8306140251

--8306140266 Responds to NRC 830418 ltr re violations noted in IE Insp Repts 50-259/83-09, 50-260/83-09 & 50-276/83-09 Corrective actions all conduit supports for safety-related equipment corrected by work plan or maint request
KAMMER, D S Tennessee Valley Authority 83/05/25, O'REILLY, J P
Region 2, Office of Director 4pp 18832 237 24X
Fiche 50-259, 83/06/02, 8306140251

--8306140276 Forwards IE Insp Repts 50-259/83-09, 50-260/83-09 & 50-276/83-09 on 830226-0325 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/04/18
PARRIS, H O Tennessee Valley Authority 2pp 18832 243 24X
Fiche 50-259, 83/06/02, 8306140251

--8306140284 Notice of violation from insp on 830226-0325
* Region 2, Office of Director 83/04/18 2pp 18832 245 24X
Fiche 50-259, 83/06/02, 8306140251

--8306140297 IE Insp Repts 50-259/83-09, 50-260/83-09 & 50-276/83-09 on 830226-0325 Noncompliance noted Failure to meet design flow requirements & failure to have QA review & insp on maint requests
PAULK, G L Region 2, Office of Director CANTRELL, F S Division of Project & Resident Programs 83/04/13 14pp 18832 247 24X
Fiche 50-259, 83/06/02, 8306140251

8306090331 Forwards response to IE Bulletin 80-11 re masonry wall design wall displacement analysis Masonry walls will remain stable under max differential bldg displacement & other loads caused by DBE.
MILLS, L M Tennessee Valley Authority 83/06/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 18793 078 24X Fiche 50-259, 83/06/03, 8306090331

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8306290195 Ack receipt of 830425 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-03, 50-260/83-03 & 50-276/83-03
LEWIS, R C Division of Project & Resident Programs 83/06/09
PARRIS, H O Tennessee Valley Authority 1p 19056 221 24X
Fiche 50-259, 83/06/09, 8306290195

--8306290203 Forwards response to NRC 830321 ltr re violations noted in IE Insp Repts 50-259/83-03, 50-260/83-03 & 50-276/83-03
Violation re failure to perform radiation hazards evaluation denied Personnel counseled on radiological control
KAMMER, D S Tennessee Valley Authority 83/04/25 O'REILLY, J P
Region 2, Office of Director 5pp 19056 222 24X
Fiche 50-259, 83/06/09, 8306290195

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8306290277 Ack receipt of 830523 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-12, 50-260/83-12 & 50-276/83-12
LEWIS, R C Division of Project & Resident Programs 83/06/14
PARRIS, H O Tennessee Valley Authority 1p 19056 038 24X
Fiche 50-259, 83/06/14, 8306290277

--8306290283 Responds to NRC 830422 ltr re violations noted in IE Insp Repts 50-259/83-12, 50-260/83-12 & 50-276/83-12 Corrective actions radiological incident repts issued for each instance cited
MILLS, L M Tennessee Valley Authority 83/05/23 O'REILLY, J P
Region 2, Office of Director 5pp 19056 039 24X
Fiche 50-259, 83/06/14, 8306290277

--8306290288 Forwards IE Insp Repts 50-259/83-12, 50-260/83-12 & 50-276/83-12 on 830321-25 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/04/22
PARRIS, H O Tennessee Valley Authority 2pp 19056 044 24X
Fiche 50-259, 83/06/14, 8306290277

--8306290292 Notice of violation from insp on 830321-25
* Region 2, Office of Director 83/04/22 2pp 19056 046 24X
Fiche 50-259, 83/06/14, 8306290277

--8306290297 IE Insp Repts 50-259/83-12, 50-260/83-12 & 50-276/83-12 on 830321-25, Noncompliance noted radioactive waste operator inside contamination zone w/o protective clothing or radiation monitors
DEBB, B T, BARR, K P Region 2, Office of Director 83/04/20
6pp 19056 048 24X Fiche 50-259, 83/06/14, 8306290277

8306290290 Forwards response to IE Bulletin 83-03 re check valve failures in raw water cooling sys of diesel generators. Current test program sufficient to verify integrity of check valves
MILLS, L M Tennessee Valley Authority 83/06/15 O'REILLY, J P
Region 2, Office of Director 3pp 19056 081 24X
Fiche 50-259, 83/06/15, 8306290250

8306290272 Ack receipt of supplemental 830610 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/81-28, 50-260/81-28 & 50-276/81-28
LEWIS, R C Division of Project & Resident Programs 83/06/16
PARRIS, H O Tennessee Valley Authority 1p 19056 054 24X
Fiche 50-259, 83/06/16, 8306290272

--8306290275 Supplemental response to NRC 81031 ltr re violations noted in IE Insp Repts 50-259/81-28, 50-260/81-28 & 50-276/81-28
Corrective actions: five pump air vent valves removed & replaced w/stronger & improved upper float guides
MILLS, L M Tennessee Valley Authority 83/06/10 O'REILLY, J P
Region 2, Office of Director 3pp 19056 095 24X
Fiche 50-259, 83/06/16, 8306290272

8306210194 Ack receipt of 830603 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-259/83-10, 50-260/83-10 & 50-276/83-10
LEWIS, R C Division of Project & Resident Programs 83/06/17
PARRIS, H O Tennessee Valley Authority 1p 18919 030 24X
Fiche 50-259, 83/06/17, 8306210194

DOCKETED ITEMS

- B306210203 Forwards response to NRC B30429 ltr re violations noted in IE Safeguards Insp Repts 50-259/83-10, 50-260/83-10 & 50-296/83-10 Corrective actions withheld (ref 10CFR73 21) MILLS, L M Tennessee Valley Authority 83/06/03 O'REILLY, J P Region 2, Office of Director 1p 18919 031 24X Fiche 50-259, 83/06/17, B306210194
- B306210213 Forwards IE Safeguards Insp Repts 50-259/83-10, 50-260/83-10 & 50-296/83-10 on B30404-08 & notice of violation Notice of violation withheld (ref 10CFR73 21) LEWIS, R C Division of Project & Resident Programs 83/04/29 PARRIS, H O Tennessee Valley Authority 2pp 18919 032 24X Fiche 50-259, 83/06/17, B306210194
- B306210224 IE Safeguards Insp Repts 50-259/83-10, 50-260/83-10 & 50-296/83-10 on B30404-08 Noncompliance noted failure to follow access control procedures Details withheld (ref 10CFR73 21) MOORE, D E J, MCQUIRE, D R Region 2, Office of Director 83/04/27 1p 18919 034 24X Fiche 50-259, 83/06/17, B306210194
- B306290483 Approves issuance of SAMP Repts 50-259/83-04, 50-260/83-04, 50-296/83-04, 50-327/83-04, 50-328/83-04, 50-390/83-07, 50-391/83-06, 50-438/83-06 & 50-439/83-06 for Jul 1981 - Dec 1982 No reply required O'REILLY, J P Region 2, Office of Director 83/06/17 PARRIS, H O Tennessee Valley Authority 3pp 19050 212 24X Fiche 50-000, 83/06/17, B306290483
- B306290490 Forwards SAMP Repts 50-259/83-04, 50-260/83-04, 50-296/83-04, 50-327/83-04, 50-328/83-04, 50-390/83-07, 50-391/83-06, 50-438/83-06 & 50-439/83-06 for Jul 1981 - Dec 1982 LEWIS, R C Division of Project & Resident Programs 83/04/13 PARRIS, H O Tennessee Valley Authority 3pp 19050 215 24X Fiche 50-000, 83/06/17, B306290483
- B306290503 SAMP Repts 50-259/83-04, 50-260/83-04, 50-296/83-04, 50-327/83-04, 50-328/83-04, 50-390/83-07, 50-438/83-06 & 50-439/83-06 for Jul 1981 - Dec 1982 e Region 2, Office of Director 83/04/13 92pp 19050 218 24X Fiche 50-000, 83/06/17, B306290483
- B306290510 Comments on SAMP Repts 50-259/83-04, 50-260/83-04, 50-296/83-04, 50-327/83-04, 50-328/83-04, 50-390/83-07, 50-391/83-06, 50-438/83-06 & 50-439/83-06 for Jul 1981 - Dec 1982 MILLS, L M Tennessee Valley Authority 83/05/10 O'REILLY, J P Region 2, Office of Director 2pp 19050 310 24X Fiche 50-259, 83/06/17, B306290483
- B305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers - Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/06/22 Consolidated Edison Co. of New York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, B305110475
- B305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment - Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/06/22 Consolidated Edison Co. of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, B305110477
- B305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions." Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/06/23 Consolidated Edison Co. of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, B305110479
- B305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints - Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/06/24 Consolidated Edison Co. of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, B305110483
- R Periodic operating reports & related correspondence
- B306160482 Monthly operating repts for Apr 1983 W/B30511 ltr THOM, T J, COFFEY, J A Tennessee Valley Authority 83/05/01 Office of Management and Program Analysis 39pp 18864 085 24X Fiche 50-259, 83/05/01, B306160482
- B Reportable occurrences, LERs & related correspondence
- B306010267 Deficiency re inability of prompt notification sys mobile sirens to complete routes in required time Initially reported on B30502 Addl sirens will be procured & mobile routes modified Full compliance expected by B30901, MILLS, L M Tennessee Valley Authority 83/05/23 O'REILLY, J P Region 2, Office of Director 2pp 18874 324 24X Fiche 50-259, 83/05/23, B306010267
- B306070059 Telecopy RD 50-286/B331 on B30520, reactor low pressure switches PS-3-74B & PS-6B-96, switch 2 found below Tech Spec limits Caused by setpoint drift Setpoints reset & Design Change Request DCR 1378 initiated to replace switches COFFEY, J A Tennessee Valley Authority 83/05/24 Region 2, Office of Director 1p 18740 079 24X Fiche 50-296, 83/05/24, B306070059
- B306070266 LER B3-02B/03L-0 on B30429, while investigating blown fuse in annunciation, relay 16A-K79 failed Caused by coil over heating melting spool matl & stuck armature in energized position Relay replaced W/B30527 ltr CHRISTOPHER, W, GREEN, H J Tennessee Valley Authority 83/05/27 O'REILLY, J P Region 2, Office of Director 3pp 18740 331 24X Fiche 50-296, 83/05/27, B306070266
- B306170423 LER B3-029/03L-0 on B30504, during insp of 3EA 480-volt reactor motor operated valve board motor generator set, generator side flywheel bearing found damaged Caused by mispositioning of row balls bearing replaced W/B30601 ltr AARON, J, GREEN, H J Tennessee Valley Authority 83/06/01 O'REILLY, J P Region 2, Office of Director 3pp 18879 062 24X Fiche 50-296, 83/06/01, B306170423
- B306100192 LER B3-031/01T-0 on B30520, while performing SI 4 D B-7, pressure switches 3-PB-3-74B switches 1 & 2 & 3-PS-6B-96 switch 2 had as-found calibr values below Tech Spec limits Caused by setpoint drift Switches recalibr W/B30602 ltr CHAMBERS, O T, GREEN, H J Tennessee Valley Authority 83/06/02 O'REILLY, J P Region 2, Office of Director 4pp 18807 252 24X Fiche 50-296, 83/06/02, B306100192
- B306130163 LER B3-030/03L-0 on B30504, hydrogen analyzer B removed from svc to replace defective hydrogen sample inlet pump motor Caused by worn end ball pump & motor assembly replaced & SI 4 7 H successfully completed W/B30602 ltr CARTER, S, GREEN, H J Tennessee Valley Authority 83/06/02 O'REILLY, J P Region 2, Office of Director 3pp 18824 263 24X Fiche 50-296, 83/06/02, B306130163
- B306170294 PNO-II-B3-047 on B30613, standby gas treatment sys train B declared inoperable due to problems w/filter heaters Cause not stated Event involved no equipment damage, no personnel error or injury & no radioactive releases BUTCHER, R C, VERRELLI, D M Region 2, Office of Director 83/06/15 2pp 18879 048, 24X Fiche 50-260, 83/06/15, B306170294
- B306270274 Updated LER B3-026/03X-1, on B30411, during attempt to establish EECW flow rate to 3 emergency diesel (ED) generator coolers, head on HX found cracked Caused by mfg defect apparently due to inservice stresses W/B30616 ltr HOLDER, E T, GREEN, H J Tennessee Valley Authority 83/06/16 O'REILLY, J P Region 2, Office of Director 3pp 18796 193 24X Fiche 50-296, 83/06/16, B306270274
- B306270371 Updated LER B2-064/03X-1 on B20215, radiochemical lab personnel discovered inlet sample hose on 3-90-250 turbine & reactor zone exhaust CAM disconnected Cause Unknown Hose reconnected W/B30616 ltr THORPE, D, GREEN, H J Tennessee Valley Authority 83/06/16 O'REILLY, J P Region 2, Office of Director 3pp 18993 103 24X Fiche 50-296, 83/06/16, B306270371
- V Operator Examinations
- B306140687 Discusses operator & senior operator licensing exams & schedule to facilitate written & oral exams to be administered during wk of B30627 Approved ref matl listed in encl requested by B30427 VERRELLI, D M Division of Project & Resident Programs 83/03/30 GREEN, H J Tennessee Valley Authority 3pp 18841 346 24X Fiche 50-259, 83/03/30, B306140687
- B306140626 Responds to B30330 request for renewal of OT McChristian Senior Operator License BOP-2938-2 License expired McChristian should reapply for license, NRC will consider request for waiver of exams VERRELLI, D M Division of Project & Resident Programs 83/05/12 GREEN, H J Tennessee Valley Authority 1p 18842 086 24X Fiche 50-259, 83/05/12, B306140626
- DOCKET 50-298 COOPER NUCLEAR STATION
- F. Security, medical, emergency & fire protection plans
- B306140716 Submits followup response to 16 of 19 open items identified in NRC B20217 ltr re IE Emergency Preparedness Appraisal Rept 50-298/B2-34 on B21206-10, PILANT, J M Nebraska Public Power District 83/05/13 MADSEN, G L Region 4, Office of Director, 9pp 18841 323 24X Fiche 50-298, 83/05/13, B306140716

8304080061 Forwards addl info re alternative shutdown capability, clarifying 830318 documentation of 830303 meeting concerning until 820628 request for exemption from Section III D of 10CFR50, App A Approval of exemption requested
 PILANT, J M Nebraska Public Power District 83/06/02
 VASSALLO, D B Operating Reactors Branch 2 33pp 18774 082 24X
 Fiche: 50-298, 83/06/02, 8306080061

8306200106 Forwards rept of change to Rev 3 to safeguards plan Description of changes withheld (ref 10CFR2 790 & 10CFR23 21)
 PILANT, J M Nebraska Public Power District 83/06/08 Office of Nuclear Reactor Regulation, Director 1p 18903 265 24X
 Fiche: 50-298, 83/06/08, 8306200106

8306160351 Forwards IE Safeguards Insp Rept 50-298/83-08 on 830405-07 No noncompliance noted
 MADSEN, Q L Region 4, Office of Director 83/06/10 PILANT, J M Nebraska Public Power District 2pp 18859 241 24X
 Fiche: 50-298, 83/06/10, 8306160351

--8306160362 IE Safeguards Insp Rept 50-298/83-08 on 830405-07 No noncompliance noted Major areas inspected safeguards contingency plan & response to emergency drill Details withheld (10CFR23 21)
 KELLY, J A, BROWN, Q D, WESTERMAN, T F Region 4, Office of Director 82/03/08 1p 18859 243 24X Fiche: 50-298, 83/06/10, 8306160351

J Insurance & indemnity information

8306060261 Forwards Endorsement 60 to NELA Policy NF-200 & Endorsement 47 to MAELU Policy NF-70
 PILANT, J M Nebraska Public Power District 83/05/31 Office of Nuclear Reactor Regulation, Director 3pp 18727 174 24X
 Fiche: 50-298, 83/05/31, 8306060261

P Operating license stage documents & correspondence

8306160466 Forwards revised P&IDs Updated index encl w/o P&IDs
 PILANT, J M Nebraska Public Power District 83/03/07, COLLINS, J T Region 4, Office of Director 7pp 18862 310 24X
 Fiche: 50-298, 83/03/07, 8306160466

8306160464 Forwards addl QA program App D info in response to NRC 830415 request Next formal rev to updated SAR scheduled for Jul 1983
 PILANT, J M Nebraska Public Power District 83/04/25 COLLINS, J T Region 4, Office of Director 72pp 18863, 239, 24X
 Fiche: 50-298, 83/04/25, 8306160464

8306090386 Forwards request for addl info re response to encl "Control of Heavy Loads at Nuclear Power Plants, Phase I, Nebraska Public Power District, Cooper Nuclear Station" draft technical evaluation rept encl info requested in 60 days
 VASSALLO, D B Operating Reactors Branch 2 83/05/26 PILANT, J M Nebraska Public Power District 13pp 18814 042 24X
 Fiche: 50-298, 83/05/26, 8306090386

--8306090388 "Control of Heavy Loads (C-10), Nebraska Public Power District, Cooper Nuclear Station," draft technical evaluation rept.
 VOBBURY, F, VITO, D., SARGENT, I H Franklin Institute/Franklin Research Center NRC-03-81-130 TER-C5506-346 DRFT 82/12/30
 CLEMENSON, F NRC - No Detailed Affiliation Given 29pp 18814 055 24X Fiche: 50-298, 83/05/26, 8306090386

8306100133 Forwards responses to Apr 1983 request for info re Mark I containment long-term program - plant-unique analysis rept leads evaluation (NEDE-24840)
 PILANT, J M Nebraska Public Power District 83/06/02
 VASSALLO, D B Operating Reactors Branch 2 36pp 18801 212 24X
 Fiche: 50-298, 83/06/02, 8306100133

8306210315 Advises that addl sum required to complete fees for 821124 application for Tech Spec changes, Item 2 re scram discharge val & Item 3 concerning reactor protection sys each involved separate safety issues
 D1008, R M License Fee Management Branch 83/06/15 PILANT, J M Nebraska Public Power District, 1p 18922, 357 24X
 Fiche: 50-298, 83/06/15, 8306210315

8306270208 Ack receipt of 830609 response to 820809 order modifying license. Submittal of analysis of recommendations in LRS Consultant, Inc rept can be extended to 830815
 COLLINS, J T Region 4, Office of Director, 83/06/21 JONES, C R Nebraska Public Power District, 2pp 18991 258 24X
 Fiche: 50-298, 83/06/21, 8306270208

8306280386 Clarifies 830422 response to request for addl info re NUREG-0737, Item II B 3, "Post-Accident Sampling Sys," per NRC 830831 telcon In-core temp indicators not in use at plant per Reg Guide 1.97 & Generic Ltr 82-33
 PILANT, J M Nebraska Public Power District 83/06/21
 VASSALLO, D B Operating Reactors Branch 2 2pp, 19014 085 24X
 Fiche: 50-298, 83/06/21, 8306280386

8306280444 Requests 60-day extension for responding to 830511 request for addl info re NUREG-0737, Item II K.3 2B, "Qualification of Automatic Depressurization Sys Accumulators" Extension due to personnel changes & addl time needed by AE
 PILANT, J M Nebraska Public Power District 83/06/21
 VASSALLO, D B Operating Reactors Branch 2 2pp 19020 176 24X
 Fiche: 50-298, 83/06/21, 8306280444

G Inspection reports, IE Bulletins & correspondence

8306220135 Ack receipt of 830316 ltr & payment of civil penalties imposed by NRC 830218 ltr IE will address issue of matl false statements
 AXELRAD, J A Director's Office, Office of Inspection and Enforcement 83/03/29 JONES, C R Nebraska Public Power District 2pp 18937 353 24X Fiche: 50-298, 83/03/29, 8306220135

8306270236 Forwards IE Insp Rept 50-298/83-04 on 830314-17 No noncompliance noted
 MADSEN, Q L Region 4, Office of Director 83/05/03 PILANT, J M Nebraska Public Power District 2pp 18988 251 24X
 Fiche: 50-298, 83/05/03, 8306270236

--8306270237 IE Insp Rept 50-298/83-04 on 830314-17 No noncompliance noted Major areas inspected environ protection program, including organization & administration, audits, radiological environ monitoring & nonradiological environ monitoring
 WILBORN, L, MURRAY, B, WESTERMAN, T F Region 4, Office of Director 83/04/29 7pp 18988 253, 24X Fiche: 50-298, 83/05/03, 8306270236

8306140716 Submits followup response to 16 of 19 open items identified in NRC 830217 ltr re IE Emergency Preparedness Appraisal Rept 50-298/82-34 on 821206-10
 PILANT, J M Nebraska Public Power District, 83/05/13, MADSEN, Q L, Region 4, Office of Director 7pp 18941 323 24X
 Fiche: 50-298, 83/05/13, 8306140716

8306020568 Forwards safety evaluation & notice of granting relief from ASME Code Section XI inservice insp requirements Program required to be revised in 120-month intervals.
 VASSALLO, D B Operating Reactors Branch 2 83/05/19 PILANT, J M Nebraska Public Power District 3pp 18715 068 24X
 Fiche: 50-298, 83/05/19, 8306020568

--8306020574 Safety evaluation granting in part & denying in part, requests for relief from inservice insp requirements.
 * Office of Nuclear Reactor Regulation, Director 83/05/19, 7pp 18715, 071, 24X Fiche: 50-298, 83/05/19, 8306020568

--8306020583 "Cooper Nuclear Station Inservice Insp Program," technical evaluation rept.
 * Science Applications, Inc NRC-03-82-096, 186-028-04 82/09/02 NRC - No Detailed Affiliation Given 36pp 18715 080 24X Fiche: 50-298, 83/05/19, 8306020568

--8306020587 Notice of granting in part & denying in part, relief from ASME Code Section XI inservice insp requirements.
 VASSALLO, D B Operating Reactors Branch 2 83/05/19 2pp 18715, 118 24X Fiche: 50-298, 83/05/19, 8306020568

8306080217 Ack receipt of 830411 ltr informing NRC of steps taken to correct violation & deviation noted in IE Insp Rept 50-298/82-32
 MADSEN, Q L Region 4, Office of Director, 83/05/19 PILANT, J M Nebraska Public Power District 1p 18771, 156, 24X
 Fiche: 50-298, 83/05/19, 8306080217

--8306080219 Responds to NRC 830307 ltr re violation & deviation noted in IE Insp Rept 50-298/82-32 Corrective actions, employee completed medical physicals & monitoring program of physicals established
 PILANT, J M Nebraska Public Power District 83/04/11, MADSEN, Q L, Region 4, Office of Director 4pp, 18771, 157, 24X
 Fiche: 50-298, 83/05/19, 8306080217

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl.
 TAYLOR, J M, Division of Safeguards & Inspection Programs (Post 830103), 83/03/26 Consolidated Edison Co. of New York, Inc, 125pp 18831, 043 24X Fiche: 50-000, 83/03/26, 8305110458

DOCKETED ITEMS

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet"
SVC list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co. of New
York, Inc 115pp. 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods
Withdrawn at BWRs" SVC list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/31 Consolidated Edison Co. of New
York, Inc 116pp 18732 208. 24X Fiche: 50-000, 83/05/31, 8305110461

8306210009 Forwards IE Insp Rept 50-298/83-09 on 830502-06 No
noncompliance noted
MADSEN, O. L. Region 4, Office of Director 83/05/31 PILANT, J. M.
Nebraska Public Power District 2pp 18912 273 24X
Fiche: 50-298, 83/05/31, 8306210009

--8306210012 IE Insp Rept 50-298/83-09 on 830502-06 No noncompliance
noted Major areas inspected: QA/QC administration & design
change programs. Two open items re operator exams & design
change identified
REDANO, R. T., WESTERMAN, T. F. Region 4, Office of Director
83/05/25 5pp 18912 275 24X Fiche 50-298, 83/05/31, 8306210009

8306210114 Forwards IE Insp Rept 50-298/83-06 on 830301-0430 No
noncompliance noted.
MADSEN, O. L. Region 4, Office of Director 83/05/31 PILANT, J. M.
Nebraska Public Power District 2pp 18914 074. 24X
Fiche: 50-298, 83/05/31, 8306210114.

--8306210129 IE Insp Rept 50-298/83-06 on 830301-0430 No noncompliance
noted Major areas inspected: operational safety
verifications, monthly surveillance & maint observations, IF
bulletin followup & independent insp effort
DUBOIS, D. L., WESTERMAN, T. F. Region 4, Office of Director
83/05/26 12pp 18914 076 24X Fiche 50-298, 83/05/31, 8306210114

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe
Operations" SVC list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/09. Consolidated Edison Co. of New
York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8306160351 Forwards IE Safeguards Insp Rept 50-298/83-08 on 830405-07
No noncompliance noted
MADSEN, O. L. Region 4, Office of Director 83/06/10. PILANT, J. M.
Nebraska Public Power District 2pp 18859 241 24X
Fiche: 50-298, 83/06/10, 8306160351

--8306160362 IE Safeguards Insp Rept 50-298/83-08 on 830405-07 No
noncompliance noted Major areas inspected: safeguards
contingency plan & response to emergency drill Details
withheld (10CFR73.21)
KELLY, J. A., BROWN, O. D., WESTERMAN, T. F. Region 4, Office of
Director 82/03/08 1p. 18859 243 24X Fiche: 50-298, 83/06/10,
8306160351.

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive &
Beisimically Induced Chatter in Relays Within Printed
Circuit Cards." SVC list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co. of New
York, Inc. 118pp. 18920 225. 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From
Degraded Internal Connection Cables" SVC list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co. of New
York, Inc 243pp. 18921 001. 24X Fiche: 50-000, 83/06/13, 8306090010.

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
Epoxy Grouts & Sealers" SVC list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22. Consolidated Edison Co. of New
York, Inc. 115pp 19021 179 24X Fiche: 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Activation of Fire Suppression Sys
Causing Inoperability of Safety-Related Equipment." SVC list
encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co. of New
York, Inc 120pp. 18997 007. 24X Fiche: 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions."
SVC list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co. of New
York, Inc. 116pp 18996 242 24X Fiche: 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate
Range (IR) High Flux Trip Setpoints" SVC list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co. of New
York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

R Periodic operating reports & related correspondence

8306020148 Monthly operating rept for Mar 1983 W/830405 1tr
BALLINGER, P. L., LESSOR, L. C. Nebraska Public Power District
83/04/05 5pp 18690 356 24X Fiche 50-298, 83/04/05, 8306020148

8306160477 Monthly operating rept for Apr 1983 W/830502 1tr
BALLINGER, P. L., THOMASON, P. V. Nebraska Public Power District
83/05/02 Office of Resource Management, Director 5pp
18862 232 24X Fiche 50-298, 83/05/02, 8306160477

8306160488 Monthly operating rept for Apr 1983 W/830510 1tr
BALLINGER, P. L., THOMASON, P. V. Nebraska Public Power District
83/05/10 Office of Management and Program Analysis 2pp
18864 134 24X Fiche 50-298, 83/05/10, 8306160488

S Reportable occurrences, IERs & related correspondence

8306010262 PNO-IV-83-019A on 830517, licensee committed to perform insp
of recirculation sys piping welds, including RHR sys inlet
& outlet T connections Four welds in need of repair, due to
intergranular stress corrosion cracking
DUBOIS, D. L., WESTERMAN, T. F. Region 4, Office of Director 83/05/27
1p 18672 288 24X Fiche 50-298, 83/05/27, 8306010262

8306130337 LER 83-005/03L-0 on 830505, steam discharge vol drain valve
CRD-CV-ADV33 failed to close per Tech Specs Caused by
graffiti packing working between valve stem & body Valve
repacked W/830604 1tr
THOMASON, P. V., BALLINGER, P. L. Nebraska Public Power District
83/06/04 COLLINS, J. T. Region 4, Office of Director 3pp
18822 277 24X Fiche 50-298, 83/06/04, 8306130339

8306160494 LER 83-006/03L-0 on 830509, during performance of
Surveillance Procedure 6.3.10.9.1, four RHR mechanical
snubbers frozen Caused by RHR shutdown cooling creating
water hammer & overloading snubbers W/830608 1tr
BALLINGER, P. L., THOMASON, P. V. Nebraska Public Power District
83/06/08 COLLINS, J. T. Region 4, Office of Director 3pp
18864 133 24X Fiche 50-298, 83/06/08, 8306160494

8306270163 LER 83-007/03L-0 on 830518, during refueling, both standby gas
treatment sys diesel generators found inoperable Caused by
personnel failure to follow Tech Spec requirements
Requirements reviewed & clarified W/830616 1tr
WIRE, K. R., THOMASON, P. V. Nebraska Public Power District 83/06/16
COLLINS, J. T. Region 4, Office of Director 3pp 18992 023 24X
Fiche 50-298, 83/06/16, 8306270163

DOCKET 50-301 POINT BEACH NUCLEAR PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8306060156 Provides update to 830428 1tr re mods proposed to support
App R exemption requests, based on 830523 insp of Unit 2 A05
& A06 switchgear cabinets
FAY, C. W. Wisconsin Electric Power Co 83/05/31 DENFON, H. R.
Office of Nuclear Reactor Regulation, Director CLARK, R. A.
Operating Reactors Branch 3 2pp 18728 103 24X
Fiche 50-266, 83/05/31, 8306060156

8306090177 Ack receipt of 830408 & 0523 1tr informing NRC of steps
taken to correct violations noted in IE Insp Repts
50-266/83-01 & 50-301/83-01
PAPERIELLO, C. J. Region 3, Office of Director 83/06/06
BURSTEIN, S. Wisconsin Electric Power Co 1p 18796 081 24X
Fiche: 50-266, 83/06/06, 8306090177

--8306090185 Responds to NRC 830308 1tr re violations noted in IE Insp
Repts 50-266/83-01 & 50-301/83-01 Notice of violation
inappropriately based on implementation of listed items
Fifteen-minute notifications inconsistent w/minor events
FAY, C. W. Wisconsin Electric Power Co 83/04/08, KEPPLER, J. O.
Region 3, Office of Director 3pp 18796 082 24X
Fiche 50-266, 83/06/06, 8306090177

8306130447 Notifies that LABEL vital area analysis program personnel
will reanalyze original sites visited during early stages of
program Revisit necessary to gather addl info due to major
mods & redirection by NRC
HIND, J. A. Division of Radiological & Materials Safety Programs.
83/06/08, BURSTEIN, S. Wisconsin Electric Power Co 2pp
18821 209 24X Fiche: 50-266, 83/06/08, 8306130447

DOCKETED ITEMS

119

8306130431 Forwards GER re compliance w/NUREG-0737, Item II A 1 2, "Min Staffing Levels for Emergency Situations " Provisions for onshift staffing & augmentation acceptable
HIND, J A Division of Radiological & Materials Safety Programs
83/06/10 BURSTEIN, S Wisconsin Electric Power Co 8pp
18821 215 24X Fiche 50-266, 83/06/10, 8306130431

8306210100 Responds to 830603 ltr advising of status of util request to locate emergency operations facility at corporate headquarters in Milwaukee, WI New communication apparatus & revised procedures enhance emergency capabilities
FAY, C W Wisconsin Electric Power Co 83/06/16 DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement 2pp
18714 138 24X Fiche 50-266, 83/06/16, 8306210100

8306230356 Ack receipt of NRC 830603 ltr re status of util request to locate emergency operations facility (EUF) at corporate headquarters in Milwaukee, WI Past communication difficulties unrelated to divided EDF concept
FAY, C W Wisconsin Electric Power Co 83/06/16 DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement 2pp
18743 317 24X Fiche 50-266, 83/06/16, 8306230356

J Insurance & indemnity information

8306070404 Forwards Endorsement 71 to NELA Policy NF-17B & Endorsement 59 to MAELU Policy MF-53
BUNDAG, W J Wisconsin Electric Power Co 83/05/18 Antitrust & Economic Analysis Branch (Utility Finance) 3pp 18741 352 24X
Fiche 50-266, 83/05/18, 8306070404

P Operating license stage documents & correspondence

8306010428 Advises of failure to complete installation & place in operation portions of radioactive monitoring equipment for compliance w/NUREG-0737, Item II F 1 1, "Noble Gas Monitoring " Completion expected by 830630
FAY, C W Wisconsin Electric Power Co 83/05/25 DENTON, H R
Office of Nuclear Reactor Regulation, Director CLARK, R A
Operating Reactors Branch 3 3pp 18679 321 24X
Fiche 50-266, 83/05/25, 8306010428

8306070086 Provides results of chlorine, boron & pH analyses performed for chemical test matrix, per NUREG-0737, Item II B 3, Criterion 10, to demonstrate analytical capabilities in presence of interfering ion concentrations
FAY, C W Wisconsin Electric Power Co 83/06/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 18737 350
24X Fiche 50-266, 83/06/03, 8306070086

8306200267 Forwards latest rev of FSAR Section 1 B, describing QA program, per 10CFR50 54(a)(2) Changes do not reduce QA program commitments previously accepted by NRC Substantive changes summarized
FAY, C W Wisconsin Electric Power Co 83/06/10 KEPLER, J Q
Region 3, Office of Director. 36pp 18901 063 24X
Fiche 50-266, 83/06/10, 8306200267

8306200260 Informs of further delay in implementing post-TMI-related issues due to delay in shipment of auxiliary safety instrumentation panels from vendor, in response to 830314 order
FAY, C W Wisconsin Electric Power Co 83/06/16 DENTON, H R
Office of Nuclear Reactor Regulation, Director CLARK, R A
Operating Reactors Branch 3 4pp 18901 173 24X
Fiche 50-266, 83/06/16, 8306200260

8306210091 Requests mod to WPDES Permit WI-0000957-2, removing pH limitations on sewage treatment plant & retention pond effluents Mod will allow operation of plant & pond w/reduced additions of dissolved solids to environ
LINGLE, J W Wisconsin Electric Power Co 83/06/16 Wisconsin, State of 3pp 18914 088 24X Fiche 50-266, 83/06/16, 8306210091

8306270275 Requests mod to WPDES Permit WI-0000957-2 to remove pH limitations on sewage treatment plant & retention pond effluents Removal of limits will allow operation w/reduced additions of dissolved solids to environ
LINGLE, J W Wisconsin Electric Power Co 83/06/16 Wisconsin, State of 2pp 18996 170 24X Fiche 50-266, 83/06/16, 8306270275

8306280443 Proposes hardware mod to ensure automatic initiation of auxiliary feedwater flow to affected operating unit w/o operator action Mod only affects motor driven auxiliary feedwater pumps & motor-operated isolation valves
FAY, C W Wisconsin Electric Power Co 83/06/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director CLARK, R A
Operating Reactors Branch 3 3pp 19019 174 24X
Fiche 50-266, 83/06/20, 8306280443

8306290146 Informs that util response to NUREG-0737, Items II F 1 4, II F 1 5 & II F 1 6 acceptable re installation of containment pressure, water level & hydrogen monitoring sys
SER encl
CLARK, R A Operating Reactors Branch 3 83/06/21 FAY, C W
Wisconsin Electric Power Co 8pp 19046 298 24X
Fiche 50-266, 83/06/21, 8306290146

8306280397 Requests extension of deadline for certain environ qualification items, listed in SER in Categories II A & II C, until 3 months after meeting held to resolve deficiencies
BURSTEIN, S Wisconsin Electric Power Co 83/06/22 DENTON, H R
Office of Nuclear Reactor Regulation, Director CLARK, R A
Operating Reactors Branch 3 2pp 19001 359 24X
Fiche 50-266, 83/06/22, 8306280397

G Inspection reports, IE Bulletins & correspondence

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at DHRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306070324 Confirms 830616 meeting w/util at Region III ofc to discuss SALP interested parties should submit advance notification by 830613
NORELIUS, C E Division of Project & Resident Programs 83/06/01
BURSTEIN, S Wisconsin Electric Power Co 1p 18746 080 24X
Fiche 50-266, 83/06/01, 8306070324

8306170013 Grants relief from requirement to perform volumetric insp of reactor coolant pump (RCP) casing welds & visual exam of interior surface of RCP casing, providing alternate exam described in safety evaluation performed, per 830113 ltr.
CLARK, R A Operating Reactors Branch 3 83/06/01 FAY, C E
Wisconsin Electric Power Co 4pp 18907 335 24X
Fiche 50-301, 83/06/01, 8306170013

--8306170016 Safety evaluation supporting request for exemption from requirement to perform volumetric insp of reactor coolant pump (RCP) casing provided proposed alternative exams substituted
* NRC - No Detailed Affiliation Given 83/06/01 7pp
18907 339 24X Fiche 50-301, 83/06/01, 8306170013

--8306170019 Notice of granting of relief from certain requirements of ASME Code Section XI inservice insp requirements.
CLARK, R A Operating Reactors Branch 3 83/06/01 2pp
18907 346 24X Fiche 50-301, 83/06/01, 8306170013

8306090177 Ack receipt of 830408 & 0523 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts
50-266/83-01 & 50-301/83-01
PAPERIELLO, C J Region 3, Office of Director. 83/06/06
BURSTEIN, S Wisconsin Electric Power Co 1p 18796 081 24X
Fiche 50-266, 83/06/06, 8306090177

--8306090185 Responds to NRC 830308 ltr re violations noted in IE Insp Repts 50-266/83-01 & 50-301/83-01, Notice of violation inappropriately based on implementation of listed items. Fifteen-minute notifications inconsistent w/minor events.
FAY, C W Wisconsin Electric Power Co 83/06/08 KEPLER, J Q
Region 3, Office of Director 3pp 18796 082 24X
Fiche 50-266, 83/06/08, 8306090177

8306130146 Advises that no check valves installed in flow path of cooling water for diesel generators, in response to IE Bulletin 83-03 re check valve failures in raw water cooling sys of diesel generators
BURSTEIN, S Wisconsin Electric Power Co 83/06/06 KEPLER, J Q
Region 3, Office of Director 1p 18824 277 24X
Fiche 50-266, 83/06/06, 8306130146

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 117pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

DOCKETED ITEMS

8306230274 Forwards IE Insp Repts 50-266/83-10 & 50-301/83-10 on 830523-26 No noncompliance noted
STREETER, J F Region 3, Office of Director 83/06/10 BURSTEIN, S
Wisconsin Electric Power Co 2pp. 18945 129. 24X
Fiche 50-266, 83/06/10, 8306230274

--8306230279 IE Insp Repts 50-266/83-10 & 50-301/83-10 on 830523-26 No noncompliance noted. Major areas inspected nonlicensed personnel training & licensed personnel requalification programs
HASSE, R A, HAWKINS, F C Region 3, Office of Director 83/06/10
4pp 18945:131 24X Fiche 50-266, 83/06/10, 8306230279

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Bvc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 118pp. 18920 225. 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Bvc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 243pp. 18921 001. 24X Fiche 50-000, 83/06/13, 8306090010

8306230260 Ack receipt of 830525 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-266/83-04 & 50-301/83-04.
NORELIUS, C. E. Division of Project & Resident Programs. 83/06/20, BURSTEIN, S. Wisconsin Electric Power Co 1p 18945 072 24X
Fiche 50-266, 83/06/20, 8306230260

--8306230261 Responds to NRC 830423 ltr re violations noted in IE Insp Repts 50-266/83-04 & 50-301/83-04. Corrective actions.
Procedure HP 2 4 re containment entry check-in/check-out sys deleted on 830520
FAY, C. W. Wisconsin Electric Power Co 83/05/25 KEPLER, J. O
Region 3, Office of Director 2pp 18945:073 24X
Fiche 50-266, 83/06/20, 8306230260

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Bvc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 118pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475.

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment." Bvc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp. 18997 007. 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions." Bvc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co. of New York, Inc. 116pp 18996.242 24X Fiche 50-000, 83/06/23, 8305110479.

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Bvc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc. 116pp. 19046.297 24X Fiche 50-000, 83/06/24, 8305110483.

R Periodic operating reports & related correspondence

8306200137 Monthly operating reports for May 1983. W/830613 ltr.
FAY, C. W. Wisconsin Electric Power Co 83/06/06 9pp 18901.046
24X Fiche: 50-266, 83/06/06, 8306200137

B. Reportable occurrences, LERs & related correspondence

8306060078 NPDES noncompliance on 830525, daily max pH effluent limit exceeded. Util commenced investigation of incident Ltr to be sent to Dept of Natural Resources outlining results & corrective action
FAY, C. W. Wisconsin Electric Power Co 83/05/27. Wisconsin, State of 1p. 18723:022 24X Fiche: 50-266, 83/05/27, 8306060078

8306210207 LER 83-007/017-0, on 830523, higher than normal levels of I-131 in primary coolant prompted investigation of fuel assemblies. Probably caused by fretting at bottom spring clip grid elevation optimized fuel assemblies. ZDS. W/830606 ltr.
FAY, C. W., BURSTEIN, S Wisconsin Electric Power Co. 83/06/06, KEPLER, J. O Region 3, Office of Director. 5pp. 18918:122 24X
Fiche: 50-301, 83/06/06, 8306210207.

8306300098 NPDES noncompliance notification on 830525, pH of retention pond discharge exceeded limits caused by leaks in retaining board used to siphon sludge from pond to discharge. Leaks repaired on 830526
FAY, C. W Wisconsin Electric Power Co 83/06/23 Wisconsin, State of 1p 19120 237 24X Fiche 50-266, 83/06/23, 8306300098

DOCKET 50-302 CRYSTAL RIVER NUCLEAR PLANT, UNIT 3

F Security, medical, emergency & fire protection plans

8306140040 Confirms 830124 enforcement meeting at Region II ofc to discuss apparent violations associated w/changing operational mode boron injection flow path, surveillance testing & fire barriers Agenda encl W/o encl
O'REILLY, J P Region 2, Office of Director 83/01/19 HANCOCK, J A Florida Power Corp 2pp 18938 335 24X Fiche 50-302, 83/01/19, 8306140040

8306030132 Ack receipt of 830325 ltr requesting waiver of 3 month hiatus between submittal of procedures generation package & initiation of training on upgraded emergency procedures. Waiver granted
STOLZ, J F Operating Reactors Branch 4 83/05/17 WILGUS, W S Florida Power Corp 2pp 18733 306 24X Fiche 50-302, 83/05/17, 8306030132

8306030253 Informs that NUREG-0737, Item III A 2 i. "Emergency Preparedness, Upgrade Emergency Plans to App E, 10CFR150," completed Item closed
STOLZ, J F. Operating Reactors Branch 4 83/05/17 WILGUS, W S Florida Power Corp 3pp 18734 067 24X Fiche 50-302, 83/05/17, 8306030253

8306140447 Ack receipt of 830428 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-302/83-07
DANCE, H C Division of Project & Resident Programs 83/05/27 WILGUS, W S Florida Power Corp 1p 18836 349 24X
Fiche 50-302, 83/05/27, 8306140447

--8306140469 IE Insp Rept 50-302/83-07 on 830129-0228 Noncompliance noted failure to follow Procedure OP-401 when pressurizing core flood tank A on 830625
STETKA, T F Region 2, Office of Director BROWNLEE, V L Division of Project & Resident Programs 83/03/28 7pp 18836 355 24X
Fiche 50-302, 83/05/27, 8306140447

8306070300 Forwards proposed schedule for completing requirements of NUREG-0737, Suppl 1, "Emergency Response Capability," per 830510 meeting commitments from 830415 ltr remain unchanged
WILGUS, W S Florida Power Corp 83/05/31 STOLZ, J F. Operating Reactors Branch 4 5pp 18740 305 24X Fiche 50-302, 83/05/31, 8306070300

8306300223 Application to amend License DPR-72, consisting of Request 109, allowing compensatory action other than establishment of continuous fire watch when penetration fire barrier found nonfunctional
WESTAFER, O R Florida Power Corp 83/06/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp. 19119 165 24X
Fiche 50-302, 83/06/24, 8306300223

--8306300229 Proposed Tech Specs 3/4 7 12 re fire barrier penetrations
W Florida Power Corp 83/06/24 2pp 19119 171 24X
Fiche 50-302, 83/06/24, 8306300223

H General correspondence

8306010049 Advises that R Hernan is operating reactor project manager for facility, effective 830516
FAIRTILE, H B Operating Reactors Branch 4 83/05/19 WILGUS, W S Florida Power & Light Co 2pp 18686 359 24X
Fiche 50-302, 83/05/19, 8306010049

I. Financial information

8306030320 Forwards Annual Financial Repts for 1982 for Florida Progress Corp & Cities of Tallahassee, Ocala, Kissimmee & Leesburg, FL Comprehensive financial info also encl
WESTAFER, O R Florida Power Corp 83/05/26 DENTON, H R Office of Nuclear Reactor Regulation, Director 321pp. 18706.185 24X
Fiche 50-302, 83/05/26, 8306030320

--8306030322 Annual Financial Rept, 1982
W Florida Power Corp 83/02/18 3pp 18706 332 24X
Fiche 50-302, 83/05/26, 8306030320.

--8306030323 Annual Financial Rept for FY ending 820930.
W Tallahassee, FL 83/03/26 139pp 18707 011. 24X
Fiche 50-302, 83/05/26, 8306030320.

DOCKETED ITEMS

121

--8306030325 Annual Financial Rpt for FY ending 820930
* Ocala, FL 83/05/26 153pp 19707 146 24X
Fiche 50-302, 83/05/26, 8306030320

--8306030327 Annual Financial Rpt for FY ending 820930
* Kissimmee, FL 83/01/03 160pp 18707 304 24X
Fiche 50-302, 83/05/26, 8306030320

--8306030328 Annual Financial Rpt for FY ending 820930
* Leesburg, FL 83/05/26 161pp 18708 104 24X
Fiche 50-302, 83/05/26, 8306030320

P Operating license stage documents & correspondence

8306060051 Addl response to FOIA request for three categories of documents re PRA of reactor safety study methodology application program repts & interim reliability evaluation program repts Forwards App A documents Search continuing FELTON, J M. Division of Rules and Records 83/04/07 8HOLLY, B C Union of Concerned Scientists 3pp 18752 001 24X
Fiche: 50-000, 83/04/07, 8306060051

--8306060061 Statement on background, issues, current status & future action re interim & natl reliability evaluation programs
* NRC - No Detailed Affiliation Given 82/12/31 2pp 18752 059 24X Fiche 50-000, 83/04/07, 8306060051

--8306060080 Forwards background info re PRA studies, Review of Sandia Natl Labs interim reliability evaluation program studies discussed W/o encl
STOLZ, J Operating Reactors Branch 4 83/01/19 LAINAS, O C Assistant Director for Operating Reactors 2pp 18752 200 24X
Fiche 50-000, 83/04/07, 8306060051

--8306060085 Provides info on boron precipitation clogging HPI lines & failure of operator to switch to hot leg injection in order to flush out boron residue from core during recirculation
Info obtained from PRA's
DAVID, B NRC - No Detailed Affiliation Given 83/02/24
THADANI, A NRC - No Detailed Affiliation Given 6pp 18752 206 24X Fiche 50-000, 83/04/07, 8306060051

8306020543 Requests responses to 12 open items in encl 830301 & 02 meeting minutes re inservice testing program
STOLZ, J F Operating Reactors Branch 4 83/05/17 WILGUS, W S Florida Power Corp 20pp 18715 123 24X Fiche 50-302, 83/05/17, 8306020543

8306020188 Forwards Franklin Research Ctr draft technical evaluation reft. "Control of Heavy Loads (C-10), Florida Power Co, Crystal River Unit 3" Guidance document, "Synopsis of Issues Associated w/NUREG-0612," also encl
STOLZ, J F Operating Reactors Branch 4 83/05/17 WILGUS, W S Florida Power Corp 2pp 18701 072 24X Fiche 50-302, 83/05/17, 8306020188

--8306020196 "Control of Heavy Loads (C-10), Florida Power Co, Crystal River Unit 3," draft technical evaluation reft.
BOMBARDIER, C, VOBBURY, F W Franklin Institute/Franklin Research Center NRC-03-B1-130 TER-C580A-347 DRFT 83/01/28
CLEMENSON, F NRC - No Detailed Affiliation Given 39pp 18701 074 24X Fiche 50-302, 83/05/17, 8306020188

8306150621 Forwards request for addl info re B10505 Generic Ltr B1-21, "Natural Circulation Cutdown," Info must be received by 830801 in order to complete review by 830930
STOLZ, J F Operating Reactors Branch 4 83/05/20 WILGUS, W S Florida Power Corp 6pp 18867 279 24X Fiche 50-302, 83/05/20, 8306150621

8306150282 Forwards notice of consideration of issuance of amend to License DPR-72 & proposed no significant hazards consideration determination & opportunity for hearing on 830331 amend application re Cycle 5 reload
HERNAN, R Operating Reactors Branch 4 83/05/27 WILGUS, W S Florida Power Corp 2pp 18870 026 24X Fiche 50-302, 83/05/27, 8306150282

--8306150286 Notice of consideration of issuance of amend to License DPR-72 & proposed no significant hazards consideration determination & opportunity for hearing re Cycle 5 reload.
STOLZ, J F Operating Reactors Branch 4 83/05/31 8pp 18870 028 24X Fiche 50-302, 83/05/27, 8306150282

8306140377 Forwards revised Table D-1, "Preliminary Stress Level Comparison," showing value of stress concentration factor & higher calculated peak stresses. Higher peak stresses do not affect conclusions from 830506 meeting Meeting summary encl
TAYLOR, J M Babcock & Wilcox Co 83/06/07 MINER, B NRC - No Detailed Affiliation Given 3pp 18844 001 24X
Fiche 50-000, 83/06/07, 8306140377

8306230429 Forwards analysis re fuel failures at facility resulting from combination of iodine spiking & overly stringent Tech Specs, in response to 811210 ltr Tech Spec change proposed for RCS iodine activity level
WESTAFER, O R Florida Power Corp 83/06/10 STOLZ, J F Licensing Branch 4 16pp 18941 343 24X Fiche 50-302, 83/06/10, 8306230429

8306200033 Advises that final submittal of pump & valve program will be forwarded within 90 days following receipt of SER Final submittal will include additions due to mods accomplished during Refuel IV Rev 4 to program encl
WESTAFER, O R Florida Power Corp 83/06/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 19121 081 24X
Fiche 50-302, 83/06/14, 8306200033

--8306300062 Rev 4 to pump & valve program
* Florida Power Corp 83/06/14 274pp 19121 082 24X
Fiche 50-302, 83/06/14, 8306200033

8306220049 Forwards Vols 3 & 4 to "Environ Qualification of Class 1E Equipment" Data combined w/830520 response to NRC 830111 SER, provides complete response to NUREG-0388, IE Bulletin 79-018 & recently published rule 10CFR50.49.
WESTAFER, O R Florida Power Corp 83/06/15 STOLZ, J F Operating Reactors Branch 4 2pp 18928 231 24X Fiche: 50-302, 83/06/15, 8306220049

--8306220055 Vols 3 & 4 to "Environ Qualification of Class 1E Equipment,"
* Olibert/Commonwealth Cos 83/06/15 307pp 18928 233 24X
Fiche 50-302, 83/06/15, 8306220049

8306230465 Submits addl info supporting 830331 Tech Spec Change Request 82 re Cycle 5 operation w/reactor coolant pump power monitors Response time for pump status based on reactor coolant power pump monitor trip should be 1.44 s
WESTAFER, O R Florida Power Corp 83/06/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18941 334 24X
Fiche 50-302, 83/06/17, 8306230465

8306240259 Updates status of DAW-1784 re internals bolting repair activities B&W stress analysis plus margins afforded by util repair plans, assure safety of reactor internals for return to full power.
WESTAFER, O R Florida Power Corp 83/06/20 STOLZ, J F Operating Reactors Branch 4 5pp 18981 310 24X Fiche: 50-302, 83/06/20, 8306240259

8306300225 Application to amend License DPR-72, consisting of Request 109, allowing compensatory action other than establishment of continuous fire watch when penetration fire barrier found nonfunctional.
WESTAFER, O R Florida Power Corp 83/06/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp 19119 165 24X
Fiche 50-302, 83/06/24, 8306300225

--8306300229 Proposed Tech Specs 3/4 7 12 re fire barrier penetrations
* Florida Power Corp 83/06/24 2pp 19119 171 24X
Fiche 50-302, 83/06/24, 8306300225

G Inspection reports, IE Bulletins & correspondence

8306140040 Confirms 830124 enforcement meeting at Region II ofc to discuss apparent violations associated w/changing operational mode boron injection flow path, surveillance testing & fire barriers Agenda encl W/o encl.
O'REILLY, J F Region 2, Office of Director 83/01/19 HANCOCK, J A Florida Power Corp 2pp 18838 335 24X Fiche 50-302, 83/01/19, 8306140040

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc. 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet," Svc list encl
JORDAN, C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8306140447 Ack receipt of 830428 ltr informing NRC of steps taken to correct violations noted in IE Insp Rpt 50-302/83-07
DANCE, H C Division of Project & Resident Programs 83/05/27 WILGUS, W S Florida Power Corp 1p 18836 349 24X
Fiche 50-302, 83/05/27, 8306140447

DOCKETED ITEMS

--B306140451 Responds to NRC B30329 ltr re violations noted in IE Insp Rept 50-302/B3-07 Corrective actions operations personnel instructed on importance of using procedures involving ECCB
WESTAFER, G R Florida Power Corp 83/04/28 O'REILLY, J P
Region 2, Office of Director 2pp 18836 350 24X
Fiche 50-302, 83/05/27, B306140447

--B306140495 Forwards IE Insp Rept 50-302/B3-07 on B30129-0228 & notice of violation
DANCE, H C Division of Project & Resident Programs 83/03/29
HANCOCK, J A Florida Power Corp 2pp 18836 352 24X
Fiche 50-302, 83/05/27, B306140447

--B306140462 Notice of violation from insp on B30129-0228
* Region 2, Office of Director 83/03/29 1p 18836 354. 24X
Fiche 50-302, 83/05/27, B306140447

--B306140469 IE Insp Rept 50-302/B3-07 on B30129-0228, Noncompliance noted failure to follow Procedure OP-401 when pressurizing core flood tank A on B30225
STETKA, T F Region 2, Office of Director BROWNLEE, V L Division of Project & Resident Programs 83/03/28 7pp 18836 355 24X
Fiche 50-302, 83/05/27, B306140447

B306290377 Forwards IE Insp Rept 50-302/B3-15 on B30502-04 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/05/27,
WILGUS, W S Florida Power Corp 2pp 19055 192 24X
Fiche 50-302, 83/05/27, B306290377

--B306290380 IE Insp Rept 50-302/B3-15 on B30502-06 No noncompliance noted. Major areas inspected refueling outage radiation protection organization, procedures, advanced planning (ALARA), exposure control & respiratory protection program
KAHLE, J B Region 2, Office of Director BARR, K P, Division of Engineering & Radiological Safety Programs 83/05/26 8pp 19055 194. 24X Fiche 50-302, 83/05/27, B306290377

B305110461 IE Info Notice B3-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, B305110461

B306140437 Responds to IE Bulletin B3-03, "Check Valve Failure in Raw Water Cooling Sys of Diesel Generators " Check valve insp will be performed during B30319 refueling outage
WILGUS, W S Florida Power Corp 83/05/31 O'REILLY, J P Region 2, Office of Director 3pp 18838 032 24X Fiche 50-302, 83/05/31, B306140437

B305110464 IE Info Notice B3-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/06/09 Consolidated Edison Co of New York, Inc 117pp 18830 280 24X Fiche 50-000, 83/06/09, B305110464

B305110470 IE Info Notice B3-38, "Defective Heat Sink Adhesive & Electrically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, B305110470

B306090010 IE Info Notice B3-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921-001 24X Fiche 50-000, 83/06/13, B306090010

B306220049 Forwards Vols 3 & 4 to "Environ Qualification of Class IE Equipment " Data combined w/B30520 response to NRC B30111 SER, provides complete response to NUREG-0588, IE Bulletin 79-018 & recently published rule 10CFR50.49.
WESTAFER, G R Florida Power Corp 83/06/15 STOLZ, J F Operating Reactors Branch 4, 2pp 18928 231 24X Fiche 50-302, 83/06/15, B306220049

--B306220055 Vols 3 & 4 to "Environ Qualification of Class IE Equipment." * Gilbert/Commonwealth Cox 83/06/15 307pp 18928 233 24X Fiche 50-302, 83/06/15, B306220049

B305110475 IE Info Notice B3-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/06/22 Consolidated Edison Co. of New York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, B305110475

B305110477 IE Info Notice B3-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, B305110477

B305110479 IE Info Notice B3-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, B305110479

B305110483 IE Info Notice B3-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, B305110483

R Periodic operating reports & related correspondence

B306170221 Suppl to "Annual Environ Operating Rept Radiological for 1982 " W/B30613 ltr
MCKEE, P F, REUSCHAEFER, E, WESTAFER, G R Florida Power Corp 83/06/07 O'REILLY, J P Region 2, Office of Director 108pp 18883 299 24X Fiche 50-302, 83/06/07, B306170221

B304230449 Monthly operating rept for May 1983 W/B30613
BQART, D S, WESTAFER, G R Florida Power Corp 83/06/13 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 5pp 18942 093 24X Fiche 50-302, 83/06/13, B304230449

S Reportable occurrences, LERs & related correspondence

B306070273 LER B3-022/OIT-O on B30516, two pinhole leaks found in piping on downstream side of two Nuclear Svc HX discharge isolation valves Caused by insufficient surveillance & design inadequacy on inner PVC liner W/B30527 ltr
BUFE, J L, WESTAFER, G R Florida Power Corp 83/05/27 O'REILLY, J P Region 2, Office of Director 4pp 18744 078 24X Fiche 50-302, 83/05/27, B306070273

B306090165 LER B3-021/O3L-O on B30504, three hydraulic snubbers failed functional test during Dec outage & 107 snubbers failed test during Refuel IV Caused by seal failure & valve assembly contamination All snubbers modified W/B30531 ltr
TAYLOR, B C, WESTAFER, G R Florida Power Corp 83/06/01 O'REILLY, J P Region 2, Office of Director 13pp 18809 186 24X Fiche 50-302, 83/06/01, B306090165

V Operator Examinations

B306140353 Responds to B21217 request for renewal of MP Holmes license which expired on B21214 Written exam will be waived upon request Only oral exam required since Mr Holmes passed annual written requalification exam
DANCE, H C Division of Project & Resident Programs 83/03/30 HANCOCK, J A Florida Power Corp 1p 18832 181 24X Fiche 50-302, 83/03/30, B306140353

B306140347 Advises that written & oral operator licensing exams scheduled for wk of B30725 Approved ref matl, as agreed in telcon, must be furnished by B30531 Administration of operator licensing written exam procedures encl
DANCE, H C Division of Project & Resident Programs 83/05/24 WILGUS, W S Florida Power Corp 3pp 18832 183 24X Fiche 50-302, 83/05/24, B306140347

DOCKET 50-304 ZION NUCLEAR POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

B306210314 FOIA request for NRC records re security violations & safeguards events at nuclear facilities
GOLDENBERG, G Scripps-Howard Newspapers 83/04/22 FELTON, J M Office of Administration 2pp 18925 198 24X Fiche 50-000, 83/04/22, B306210314

B306210306 Partial response to FOIA request for NRC records re security violations & safeguards events at nuclear facilities Repts listed on App A available in PDR Search for addl documents subj to request continuing
FELTON, J M Division of Rules and Records 83/05/16 GOLDENBERG, G Scripps-Howard Newspapers 2pp 18925 196 24X Fiche 50-000, 83/05/16, B306210306

8306130294 Forwards FEMA final exercise evaluations of offsite emergency preparedness exercise conducted on 8/07/29, 1007 & 830118 No major exercise deficiencies noted
HIND, J A Region 3, Office of Director 83/06/09 REED, C
Commonwealth Edison Co 2pp 18823 3J4 24X Fiche 50-295, 83/06/09, 8306130294

P Operating license stage documents & correspondence

8306030508 Forwards draft "Control of Heavy Loads (C-10), Zion Station Units 1 & 2," per responses to NRC 800731 request for review of provisions for handling & control of heavy loads in conformance w/NUREG-0612 Addl guidance encl
VAROA, S A Operating Reactors Branch 1 83/05/19 FARRAR, D L
Commonwealth Edison Co 15pp 18735 006 24X Fiche 50-295, 83/05/19, 8306030508

--8306030512 Draft "Control of Heavy Loads (C-10), Zion Station Units 1 & 2," technical evaluation rept
BARGENT, I H, VITO, D J Franklin Institute/Franklin Research Center NRC-03-B1-130 TLK-C5506-403/404 DR 82/11/30
CLEMENSON, F NRC - No Detailed Affiliation Given 30pp 18735 021 24X Fiche 50-295, 83/05/19, 8306030508

8306090194 Discusses util interpretation of 10CFR50.49, "Environment Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants" Intent of rulemaking is to require upgrade program for replacement equipment not parts
FARRAR, D L Commonwealth Edison Co 83/06/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 18796 090 24X Fiche 50-000, 83/06/03, 8306090194

8306210073 Suppl 830513 ltr re NUREG-0737, Item II F 1 5, "Containment Water Level Monitoring Sys" Lower value of transmitter error should be used for calculating of overall loop uncertainties
LENTINE, F O Commonwealth Edison Co 83/06/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18912 291 24X Fiche 50-295, 83/06/15, 8306210073

8306230219 Forwards addl info on control room human factors items re nuisance alarms, prioritization of multiple alarms & communications w/breathing apparatus, in response to 830511 telcon
LENTINE, F O Commonwealth Edison Co 83/06/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 1pp 18945 264 24X Fiche 50-295, 83/06/16, 8306230219

Q Inspection reports: IE Bulletins & correspondence

8306060218 Forwards IE Insp Repts 50-295/83-04 & 50-304/83-04 on 830305-0429 & notice of violation
SHAFFER, W D Region 3, Office of Director 83/05/19 REED, C
Commonwealth Edison Co 2pp 18727 306 24X Fiche 50-295, 83/05/19, 8306060218

--8306060219 Notice of violation from insp on 830305-0429
SHAFFER, W D Region 3, Office of Director 83/05/19 2pp 18727 308 24X Fiche 50-295, 83/05/19, 8306060218

--8306060221 IE Insp Repts 50-295/83-04 & 50-304/83-04 on 830305-0429
Noncompliance noted failure to provide procedures to account for plant condition changes after instrument calibr & failure to keep high radiation door locked
WATERS, J R, DUNAWAY, F R, HARTMANN, P L Region 3, Office of Director 83/05/18 12pp 18727 310 24X Fiche 50-295, 83/05/19, 8306060218

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 12pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 11pp 18732 08b 24X Fiche 50-000, 83/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 11pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306090125 Confirms 830602 telcon request for 1-wk extension to reply to notice of violation & proposed imposition of civil penalty Request granted
KEPPLER, J Q Region 3, Office of Director 83/06/06 O'CUNNOR, J J Commonwealth Edison Co 1p 18795 290 24X Fiche 50-295, 83/06/06, 8306090125

8306100094 Forwards response to IE Bulletin 83-03 re diesel generator cooling water check valves Plants utilize Mission Duo-Check valves employing hinge-to-pin design for protection against vibration-induced failure
BARNES, P L Commonwealth Edison Co 83/06/07 KEPPLER, J Q Region 3, Office of Director 7pp 18802 23B 24X Fiche 50-000, 83/06/07, 8306100094

8306170380 Forwards response to IE Bulletin 83-03 re diesel generator cooling water check valves Valves at Dresden & LaSalle acceptable w/o further insp Rept on valve failures at Quad Cities will be submitted within 90 days of insp completion
BARNES, P L Commonwealth Edison Co 83/06/07 KEPPLER, J Q Region 3, Office of Director 7pp 18880 211 24X Fiche 50-000, 83/06/07, 8306170380

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8306170277 Forwards addendum consisting of confirmatory measurements program data sheet for IE Insp Repts 50-295/82-30 & 50-304/82-27 re 8r-89 & 8r-90 info will close Open Items 295/82-30-0 & 304/82-27-01
PAPERIELLO, C J Region 3, Office of Director 83/06/14 REED, C Commonwealth Edison Co 3pp 18878 26B 24X Fiche 50-295, 83/06/14, 8306170277

8306220026 Ack receipt of 830525 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-295/83-07 & 50-304/83-06
PAPERIELLO, C J Region 3, Office of Director 83/06/17 REED, C Commonwealth Edison Co 1p 18928 210 24X Fiche 50-295, 83/06/17, 8306220026

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8306300197 Ack receipt of 830616 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-295/83-04 & 50-304/83-04
SHAFFER, W D Region 3, Office of Director 83/06/23 REED, C Commonwealth Edison Co 1p 19122 183 24X Fiche 50-295, 83/06/23, 8306300197

--8306300216 Responds to NRC 830519 ltr re violations noted in IE Insp Repts 50-295/83-04 & 50-304/83-04 Corrective actions, entire Radiological Protection Procedure 1190-1 will be kept at work site w/calibr sheet
FARRAR, D L Commonwealth Edison Co 83/06/16 KEPPLER, J Q Region 3, Office of Director 3pp 19122 184 24X Fiche 50-295, 83/06/23, 8306300197

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

DOCKETED ITEMS

8306280377 Forwards response to Item 4 of IE Bulletin 82-02, "Degradation of Threaded Fasteners in RCPB of FWR Plants" Insp requirements included in all appropriate maint procedures

BARNES, P L Commonwealth Edison Co 83/06/24 KEPLER, J O Region 3, Office of Director 4pp 19014 087 24X Fiche: 50-304, 83/06/24, 8306280377

8306290329 Forwards "Inservice Insp & Test Program, Second Interval, Zion Nuclear Power Station" Programs applicable for 120-month interval beginning 831231 for Unit 1 & 840919 for Unit 2

LENTINE, F O Consolidated Edison Co of New York, Inc 83/06/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 19054:027 24X Fiche 50-295, 83/06/27, 8306290329

--8306290335 "Inservice Insp & Test Program, Second Interval, Zion Nuclear Power Station"

* Consolidated Edison Co of New York, Inc. 83/06/27 358pp 19054:028 24X Fiche 50-295, 83/06/27, 8306290329

R Periodic operating reports & related correspondence

8306070233 "Zion Nuclear Generating Station," second evaluation, * Institute of Nuclear Power Operations 83/04/30 38pp 18741.117, 24X Fiche 50-295, 83/04/30, 8306070233

8306140412 Monthly operating repts for May 1983 W/830608 1tr AUSTIN, O, GRAEBER, K L Commonwealth Edison Co 83/06/08 Director's Office, Office of Inspection and Enforcement 12pp 18838 069 24X Fiche: 50-295, 83/06/08, 8306140412

B Reportable occurrences, LERs & related correspondence

8306060250 LER 83-013/017-0 on 830512, during air pressure test of one cooling bant on 2C reactor containment fan cooler, six leaking tubes verified. Caused by internal pitting. Two tubes removed for visual & metallurgical exam W/830526 ltr. WOODS, J., GRAEBER, K L Commonwealth Edison Co 83/05/26 KEPLER, J O Region 3, Office of Director 3pp 18727 229 24X Fiche: 50-304, 83/05/26, 8306060250

8306060148 LER 83-014/03L-0 on 830427, during visual insp, snubbers MSRB 150-2, MSRB 150-11 & BIRB 2135 failed to lock up in tension &/or compression. Caused by hydraulic fluid leak due to poor seal condition W/830527 ltr. GRAEBER, K L, PETROWSKI, S E Commonwealth Edison Co 83/05/27 KEPLER, J O Region 3, Office of Director 3pp 18719 228 24X Fiche: 50-304, 83/05/27, 8306060148

8306210234 LER 83-015/03L-0 on 830516 & 1D, pressurizer level channels 2L-460 & 2L-461 found out of tolerance. Caused by transmitter (Barton Model 386) drift. Transmitters recalibr & will be environmentally qualified W/830613 ltr. CANTWELL, P F, GRAEBER, K L Commonwealth Edison Co 83/06/13 KEPLER, J O Region 3, Office of Director 2pp 18717 001 24X Fiche: 50-304, 83/06/13, 8306210234

8306220060 PNO-III-83-044, on 830614, radiation chemistry lab foreman found shot twice. No known connection exists between apparent murder & employment. BOYD, D., SHAFFER, W Region 3, Office of Director 83/06/15 1p 18930, 174 24X Fiche: 50-295, 83/06/15, 8306220060

8306230438 PNO-III-83-048, on 830615, contractor employee reentered plant unescorted after triggering contamination monitor on exiting plant. Employee instructed to proceed to radiation protection ofc located in vital area for decontamination. CREED, J., MILLER, J., HIND, J Region 3, Office of Director 83/06/17, 1p 18942, 078 24X Fiche 50-295, 83/06/17, 8306230438

8306270221 LER 83-016/03L-0 on 830615, while at 89% power, 2B MSIV continuity lights for train A & B would not light. Caused by loose fuse clips due to repeated use. Clips tightened. Clip clamps will be installed W/830620 ltr. OAJIC, Z, GRAEBER, K L Commonwealth Edison Co 83/06/20 KEPLER, J O Region 3, Office of Director 2pp 18990 219 24X Fiche: 50-304, 83/06/20, 8306270221

--8306160048 Public version of revised Radiological Emergency Response Plan Implementing Procedures EP-ENV 5A, "LCS-1 Operation," & EP-ENV-5B, "MS-3 Operation" W/830429 1tr Revised index encl. LUONIA, C K, QIESLER, C W Washington Public Power Supply System 83/04/29 DENTON, H R Office of Nuclear Reactor Regulation, Director 17pp 18892 310 24X Fiche 50-305, 83/06/06, 8306160048

8306130306 Advises that Rev 1 to emergency plan meets planning stds of 10CFR50 47(h) & requirements of App C to 10CFR50. Any proposed changes to plan should be provided to NRC per 10CFR50 54(q). PAPERIELLO, C J Region 3, Office of Director 83/06/10 QIESLER, C W Wisconsin Public Service Corp 1p 18823 328 24X Fiche 50-305, 83/06/10, 8306130306

J Insurance & indemnity information

8306070070 Forwards Endorsements 61 & 48 to NELIA Policy NF-204 & MAELU Policy MF-71, respectively. QIESLER, C W Wisconsin Public Service Corp 83/06/01 DINI, T J Antitrust & Economic Analysis Branch (Utility Finance) 3pp 18740 090 24X Fiche 50-305, 83/06/01, 8306070070

P Operating license stage documents & correspondence

8306010065 Forwards "Control of Heavy Loads (C-10), Kewaunee Nuclear Power Plant," draft technical evaluation rept for review & comment. Conference call to discuss rept scheduled for wk of 830610. VAROA, S A Operating Reactors Branch 1 83/05/16 QIESLER, C W Wisconsin Public Service Corp 2pp 18695 332 24X Fiche 50-305, 83/05/16, 8306010065

--8305200714 "Control of Heavy Loads (C-10), Kewaunee Nuclear Power Plant," draft technical evaluation rept. VOSBURV, F W, BOHNERGER, C Franklin Institute/Franklin Research Center NRC-03-81-130 TCR-C5806-363 DRAFT 83/04/29 SARGENT, I H NRC - No Detailed Affiliation Given 38pp 18696 001 24X Fiche 50-305, 83/05/16, 8306010065

8306020648 Forwards list of outstanding amends under License DPR-43, per telcon. Subsequent amend requests to be sent directly from util W/O encl. GROTHENHUIS, M Operating Reactors Branch 1 83/05/19 RIEDERER, C Wisconsin Public Service Corp 2pp 18716 275 24X Fiche 50-305, 83/05/19, 8306020648

8306020395 Forwards Rev 1 to 830506 proposed change to Tech Specs correcting potential deficiency re containment cooling sys operability. QIESLER, C W Wisconsin Public Service Corp 83/05/27 VAROA, S A Operating Reactors Branch 1 4pp 18695 167 24X Fiche 50-305, 83/05/27, 8306020395

8306100189 Restates previous commitment to install redundant radiation monitor in control room HVAC sys, per NUREG-0737, Item III D 3 A, "Control Room Habitability," in response to 830401 request. QIESLER, C W Wisconsin Public Service Corp 83/06/06 VAROA, S A Operating Reactors Branch 1 5pp 18805 257 24X Fiche 50-305, 83/06/06, 8306100189

8306140048 Forwards revised pages to Cycle IX reload safety evaluation. Pages reflect redesigned core pattern. QIESLER, C W Wisconsin Public Service Corp 83/06/10 VAROA, S A Operating Reactors Branch 1 10pp 18838, 290 24X Fiche 50-305, 83/06/10, 8306140048

8306200102 Submits schedule for resolution of TMI Action Plan Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps," in response to Generic Ltr 83-10D Pump trip setpoint procedures will be implemented by end of 1985 refuel outage. QIESLER, C W Wisconsin Public Service Corp 83/06/15 EISENHUT, D O Division of Licensing 4pp 18903 330 24X Fiche 50-305, 83/06/15, 8306200102

8306280373 Rev to application for Amend 54 to License DPR-43, changing Tech Specs re offsite organization for plant mgt & technical support. Revised figure encl. QIESLER, C W Wisconsin Public Service Corp 83/06/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 19001 278 24X Fiche: 50-305, 83/06/24, 8306280373

--8306280378 Revised Tech Spec 6 2 1 re offsite organization for plant mgt & technical support. * Wisconsin Public Service Corp 83/06/24 1p 19001, 280 24X Fiche 50-305, 83/06/24, 8306280373

Q Inspection reports, IE Bulletins & correspondence

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl
TAYLOR, J. M. Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8306130330 Forwards IE Insp Rept 50-305/83-06 on 830418-22 No noncompliance noted
PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support 83/05/27 QIESLER, C. W. Wisconsin Public Service Corp 2pp 18822 262 24X Fiche 50-305, 83/05/27, 8306130330

--8306130332 IE Insp Rept 50-305/83-06 on 830418-22 No noncompliance noted Major areas inspected ALARA, exposure controls, posting & controls, transportation activities, TMI action items & effluent control instrumentation
PAUL, R. A., GRANT, W. B., GREGOR, L. R. Region 3, Office of Director 83/05/24 9pp 18822 264 24X Fiche 50-305, 83/05/27, 8306130330

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at DWRs" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306170056 Advises that no check valves installed in steam generator cooling water piping flow path, in response to IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators"
QIESLER, C. W. Wisconsin Public Service Corp 83/06/07 KEPLER, J. O. Region 3, Office of Director, Ip. 18878 301 24X Fiche 50-305, 83/06/07, 8306170056

8306160619 Forwards response to two items of noncompliance identified in IE Insp Rept 50-305/83-03 & update on status of commitments to ensure quality of radiological measurement program
QIESLER, C. W. Wisconsin Public Service Corp 83/06/08 HIND, J. A. Division of Emergency Preparedness & Operational Support 5pp 18866 126 24X Fiche 50-305, 83/06/08, 8306160619

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8306210037 Ack receipt of 830511 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-305/83-01, Noncompliance Item 1 a warranted & assigned appropriate severity level Item 2 recategorized as Severity Level V.
NORELIUS, C. E. Division of Project & Resident Programs 83/06/14 QIESLER, C. W. Wisconsin Public Service Corp 2pp 18912 339 24X Fiche 50-305, 83/06/14, 8306210037

--8306210041 Responds to NRC 830411 ltr re violations noted in IE Insp Rept 50-305/83-01 Corrective actions: personnel restructured in tagging requirements. Contends that Item 1 a warrants no noncompliance action & Item 2 should be Severity Level V.
QIESLER, C. W. Wisconsin Public Service Corp 83/06/11 NORELIUS, C. E. Division of Project & Resident Programs 14pp 18912 341 24X Fiche 50-305, 83/06/14, 8306210037

8306270329 Forwards IE Insp Rept 50-305/83-04 on 830303-0429 & notice of violation.
NORELIUS, C. E. Division of Project & Resident Programs 83/06/17 QIESLER, C. W. Wisconsin Public Service Corp 2pp 18993 054 24X Fiche 50-305, 83/06/17, 8306270329

--8306270335 Notice of violation from insp on 830303-0429
NORELIUS, C. E. Division of Project & Resident Programs 83/06/17 2pp 18993 056 24X Fiche 50-305, 83/06/17, 8306270329

--8306270341 IE Insp Rept 50-305/83-04 on 830303-0429 Noncompliance noted limiting condition for operation exceeded for RCS leakage detection
NELSON, R. L., JACKIWI, I. N. Region 3, Office of Director 83/06/17 9pp 18993 058 24X Fiche 50-305, 83/06/17, 8306270329

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co. of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc 116pp 19046 277 24X Fiche 50-000, 83/06/24, 8305110483

R Periodic operating reports & related correspondence

8306140001 Monthly operating rept for May 1983, W/830610 ltr.
RUITER, G. H., QIESLER, C. W. Wisconsin Public Service Corp 83/06/01. Director's Office, Office of Inspection and Enforcement 6pp 18840 201 24X Fiche 50-305, 83/06/01, 8306140001

S Reportable occurrences, LERs & related correspondence

8306270110 LER 83-013/03L-0 on 830520, App J Type B & C local leak rate testing identified six containment isolation valves w/ unacceptable as-found leakage Cause not stated. Valves repaired & tested satisfactorily W/830617 ltr
BERNHOF, S., HILTUNEN, E., QIESLER, C. W. Wisconsin Public Service Corp 83/06/17 KEPLER, J. O. Region 3, Office of Director 3pp 18988 060 24X Fiche 50-305, 83/06/17, 8306270110

DOCKET 50-306 PRAIRIE ISLAND NUCLEAR STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8306100059 "Control Room Design Review Plan, Prairie Island Nuclear Generating Plant," response to Generic Ltr 82-33, Suppl 1 to NUREG-0737 W/830527 ltr
MUSOLF, D. Northern States Power Co 83/05/27 47pp 18802 123 24X Fiche 50-282, 83/05/27, 8306100059

8306090237 Forwards "Emergency Operating Procedures Generation Package," in response to Generic Ltr 82-33, Suppl 1 to NUREG-0737.
MUSOLF, D. Northern States Power Co 83/05/31. Office of Nuclear Reactor Regulation, Director, Ip 18797 001 24X Fiche 50-282, 83/05/31, 8306090237

--8306090239 "Emergency Operating Procedures Generation Package," * Northern States Power Co 83/05/31 16pp 18797 002 24X Fiche 50-282, 83/05/31, 8306090237

8306090263 Forwards Rev 9 pages for security plan. Pages withheld (ref 10CFR73).
MUSOLF, D. Northern States Power Co 83/06/06 Office of Nuclear Reactor Regulation, Director, Ip 18795 279 24X Fiche 50-282, 83/06/06, 8306090263

8306230073 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records 83/06/06 Document Management Branch Ip 18982 186 24X Fiche 50-282, 83/06/06, 8306230073

DOCKETED ITEMS

--8306230079 Forwards public version of revised emergency plan implementing procedures, including Procedures F3-3 re responsibilities during notification of unusual event & F3-13 re offsite dose calculation
WARD, E C Northern States Power Co 83/05/16 Region 3, Office of Director 1p 18982 187 24X Fiche 50-282, 83/06/06, 8306230073

--8306230087 Public version of revised emergency plan implementing procedures, including Procedures F3-3 re responsibilities during notification of unusual event, F3-13 re offsite dose calculation & F3-14 2 re operations emergency surveys
SCHUELKE, D A Northern States Power Co 83/04/26 Region 3, Office of Director 9pp 18982 188 24X Fiche 50-282, 83/06/06, 8306230073

8306280459 Informs that operational data for completion of HEPA filtration sys extended to 831001 due to difficulty in adopting ventilation sys to accommodate demands of HEPA filtration per Suppl 1 to NUREG-0707
MUSOLF, D Northern States Power Co 83/06/20 Office of Nuclear Reactor Regulation, Director 1p 19018 328 24X Fiche 50-000, 83/06/20, 8306280459

P. Operating license stage documents & correspondence

8306010349 Forwards updated equipment lists reflecting plant mode, current NRC views & licensee continuing review in response to 10CFR50.49, "Environ Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants."
MUSOLF, D M Northern States Power Co. 83/05/19, Office of Nuclear Reactor Regulation, Director 40pp, 18680 091 24X Fiche 50-282, 83/05/19, 8306010349

8306090230 Submits 30-day response to NRC 830425 safety evaluation of environ qualification of safety-related electrical equipment Facility can operate safely while environ qualification deficiencies being resolved
MUSOLF, D Northern States Power Co 83/05/27 Office of Nuclear Reactor Regulation, Director 2pp 18795 346, 24X Fiche 50-282, 83/05/27, 8306090230

8306200281 Advises that justification for continued operation re environ qualification of safety-related electrical equipment acceptable. Rosemount transmitters 1152 Series D reclassified from NRC Category II B to II C.
CLARK, R A Operating Reactors Branch 3 83/06/03 MUSOLF, D M Northern States Power Co 2pp, 18919 264 24X Fiche 50-282, 83/06/03, 8306200281

--8306200283 Safety evaluation supporting justification for continued operation w/safety-related equipment unqualified
* Office of Nuclear Reactor Regulation, Director 83/06/06 2pp 18919 266 24X Fiche 50-282, 83/06/03, 8306200281

8306170053 Concurs w/findings contained in technical evaluation rept, "Control of Heavy Loads." Guidelines in NUREG-0612, Section 5.1.1 satisfied, per util 810402, 0715, 0831 & 1209, 820203 & 1108 & 830408 submittals
CLARK, R A Operating Reactors Branch 3 83/06/06 MUSOLF, D M Northern States Power Co 2pp, 18906 314 24X Fiche 50-282, 83/06/06, 8306170053

--8306170058 Safety evaluation supporting util Phase I actions re control of heavy loads NUREG-0612, Section 5.1.1 guidelines satisfied.
* Office of Nuclear Reactor Regulation, Director 83/06/06 1p 18906 316 24X Fiche 50-282, 83/06/06, 8306170053

--8305230021 "Control of Heavy Loads (C-10), Prairie Island Nuclear Generating Plant, Units 1 & 2," technical evaluation rept
VOSEBURY, F W Franklin Institute/Franklin Research Center NRC-03-B1-130 TER-C5506-384/385 83/05/17 NRC - No Detailed Affiliation Given 31pp 66794 188 24X Fiche 50-282, 83/06/06, 8306170053

8306200390 Forwards safety & licensing portion of Westinghouse Apr 1982 rept providing addl info re fuel assembly failure effect on insertion of control rods or core cooling geometry
MUSOLF, D Northern States Power Co 83/06/07 Office of Nuclear Reactor Regulation, Director 2pp, 18899 052, 24X Fiche 50-282, 83/06/07, 8306200390

Q Inspection reports, IE Bulletins & correspondence

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl.
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103), 83/05/26, Consolidated Edison Co. of New York, Inc 12pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8306060084 Comments NRC re results of piping insp at BWRs Leak-before-break concept continues to sustain validity of technical bases Utilis giving consideration to more permanent measures
NEILS, O H Northern States Power Co 83/05/26 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18719 335 24X Fiche 50-000, 83/05/26, 8306060084

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306170232 Submits list of affected valves, test method & test schedule in response to IE Bulletin 83-03 Inservice insp program will be revised to include testing of listed valves
LARSON, C E Northern States Power Co 83/06/08 KEPPLER, J G Region 3, Office of Director 2pp 18078 284 24X Fiche 50-282, 83/06/08, 8306170232

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 118pp 18920 225, 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 120pp 18997 007, 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co. of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

8306280340 Requests relief from requirement re 10-yr inservice insp of reactor coolant pump casing welds of ASME Boiler & Pressure Vessel Code, Section XI, "Inservice Insp." Request submitted as Rev 9 to inservice insp & testing program
MUSOLF, D Northern States Power Co 83/06/24 Office of Nuclear Reactor Regulation, Director 3pp 19014 070 24X Fiche 50-282, 83/06/24, 8306280340

--8306280345 Rev 9 to "ASME Code Section XI Inservice Insp & Testing Program"
* Northern States Power Co 83/06/24, 9pp 19014 073 24X Fiche 50-282, 83/06/24, 8306280340

R Periodic operating reports & related correspondence

8306020167 Monthly operating repts for Mar 1983 W/830411 ltr
MUSOLF, D DUGSTAD, D Northern States Power Co 83/04/05 9pp 18691 075, 24X Fiche 50-282, 83/04/05, 8306020167

DOCKETED ITEMS

127

8306140002 Monthly operating repts for May 1983 W/830607 ltr
DUGSTAD, D., MURDOLF, D Northern States Power Co 83/06/07 Office
of Resource Management, Director 9pp 18838 219 24X
Fiche 50-309,83/06/07,8306140002

9 Reportable occurrences, LERs & related correspondence

8306160264 PND-III-83-042 on 830608 unit shut down to investigate
source of RCS leakage Source of leakage determined to be
from four steam generator manways Repairs expected to take
3 to 5 days
JACKIWI, I., SHAFER, W Region 3, Office of Director 83/06/10 1p
18861 266 24X Fiche 50-309,83/06/10,8306160264

DOCKET 50-309 MAINE YANKEE ATOMIC POWER PLANT

F Security, medical, emergency & fire protection plans

8306030089 Informs that onsite & offsite emergency preparedness
adequate & emergency plans upgraded per NUREG-0737, Item
III A 2.1 Item complete
CLARK, R. A Operating Reactors Branch 3 83/05/20 GARRITY, J H
Maine Yankee Atomic Power Co 3pp 18733 280 24X
Fiche 50-309,83/05/20,8306030089

8306170166 Forwards "Summary of Public Emergency Alerting Sys (PEAS)
Siren Testing, Apr & May 1983 " Plans to correct deficiencies
in PEAS submitted in 830331 ltr
GARRITY, J H Maine Yankee Atomic Power Co 83/06/02 ALLAN, J H
Region 1, Office of Director 2pp 18803 263 24X
Fiche 50-309,83/06/02,8306170166

--8306170177 "Summary of Public Emergency Alerting Sys (PEAS) Siren
Testing, Apr & May 1983 "
* Maine Yankee Atomic Power Co 83/05/31 29pp 18883, 265 24X
Fiche 50-309,83/06/02,8306170166

8306140265 Releases public version of revised oversize Figure 2 50.0-1
FELTON, J M Division of Rules and Records 83/06/06, Document
Management Branch 1p 18844 335 24X Fiche 50-309,83/06/06,
8306140265

--8306140273 Forwards public version of oversize Figure 2 50.0-1,
emergency condition classification table Table replaces
Pages 5A through 17C of Rev 4 to Procedure 2 50.0 Aperture
card available in PDR
* Maine Yankee Atomic Power Co 83/04/27 NRC - No Detailed
Affiliation Given 3pp 18844 336, 24X Fiche 50-309,83/06/06,
8306140265

8306150263 Forwards State of ME plans to correct emergency preparedness
deficiencies identified by FEMA, per 830511 site meeting
Add info on radiological exposure control will be submitted
to FEMA within 1 wk
GARRITY, J H Maine Yankee Atomic Power Co 83/06/06 ALLAN, J H
Region 1, Office of Director 15pp 18849 176 24X
Fiche: 50-309,83/06/06,8306150263,

8306170260 Notifies that representative from LASL will be contacting
site in near future to establish schedule for revisit as
part of CY83 & 84 reanalysis of original 10 sites visited
during vital area analysis program
ALLAN, J M Region 1, Office of Director, 83/06/13, RANDAZZA, J N
Maine Yankee Atomic Power Co, 2pp 18078 163 24X
Fiche. 50-309,83/06/13,8306170260

8306230361 Forwards analysis of postulated fires in reactor coolant
pump bays. Rept supports 820701 request for exemption from
Section III D of App R requirements re installation of
lubricating oil collection sys qualified for SBE
ORDOCE, R H. Maine Yankee Atomic Power Co 83/06/21, CLARK, R. A
Operating Reactors Branch 3 2pp 18943 332 24X
Fiche: 50-309,83/06/21,8306230361

--8306230366 Analysis of postulated fires in reactor coolant pump bays
* Maine Yankee Atomic Power Co 83/06/21, 50pp 18943:334, 24X
Fiche 50-309,83/06/21,8306230361

G. Adjudicatory correspondence

8306010391 Third set of interrogatories re spent fuel pool storage &
sys expansion & requests for production of documents
Certificate of Svc encl
MILLER, D. B Affiliation Unknown 83/05/27 Maine Yankee Atomic
Power Co. 14pp 18682 213 24X Fiche. 50-309,83/05/27,8306010391

8306020358 Response to NRC 830516 opposition to 830427 renewal of
motion for complete & specific disclosure & request for
leave to file same Certificate of Svc encl
MILLER, D. B Sensible Maine Power 83/05/29 Atomic Safety and
Licensing Board Panel 4pp 18694 269 24X Fiche 50-309,83/05/29,
8306020358

8306060305 Response opposing Sensible Maine Power motion to compel util
answers to interrogatories & document requests & request for
leave to file motion Motion untimely Good cause not
shown Certificate of Svc encl
DIGNAN, T G., GAD, R K Maine Yankee Atomic Power Co DIGNAN, T G
Ropes & Gray 83/05/31 Atomic Safety and Licensing Board Panel
28pp 18729 102 24X Fiche 50-309,83/05/31,8306060305

8306060332 Response opposing Sensible Maine Power (SMP) motion for
extension of discovery period SMP did not diligently
prosecute original discovery period Certificate of Svc encl.
DIGNAN, T G., GAD, R K Maine Yankee Atomic Power Co DIGNAN, T G
Ropes & Gray 83/05/31 Atomic Safety and Licensing Board Panel
8pp 18726 353 24X Fiche 50-309,83/05/31,8306060332

8306070290 Interrogatories & request for production of documents
Certificate of Svc encl
DIGNAN, T G., GAD, R K Maine Yankee Atomic Power Co DIGNAN, T G
Ropes & Gray 83/06/02 Maine, State of 66pp 18744, 012 24X
Fiche 50-309,83/06/02,8306070290

8306070296 Interrogatories & request for production of documents
Certificate of Svc encl
DIGNAN, T G., GAD, R K Maine Yankee Atomic Power Co DIGNAN, T G
Ropes & Gray 83/06/02 Sensible Maine Power, 66pp 18741, 008
24X Fiche 50-309,83/06/02,8306070296

8306090218 Confirms agreement re future proceeding schedule Meeting
suggested within next 2 wks to discuss scheduling &
substantive matters impacting on schedule
AHRENS, P Maine, State of 83/06/06 LEBBY, R. P Hearing Branch 3
1p 18796 114 24X Fiche. 50-309,83/06/06,8306090218

8306130236 Response to first set of interrogatories & requests for
documents. Prof qualifications & Certificate of Svc encl
GODDARD, R. J Hearing Branch 3 83/06/06 Sensible Maine Power,
123pp 18850-241 24X Fiche 50-309,83/06/06,8306130236,

8306090296 Advises that parties will discuss scheduling & related
matters & repts results to ASLB ASLB should suspend ruling on
Sensible Maine Power 830523 motion to extend discovery
pending discussion results
GODDARD, R. J., LEBBY, R. P Hearing Branch 3 83/06/07 LAZO, R M,
MORRIS, P A., HAND, C H Atomic Safety and Licensing Board Panel,
2pp 18795, 231 24X Fiche 50-309,83/06/07,8306090296

8306100191 Forwards third set of interrogatories & requests for
production of documents to util Related correspondence
STERN, P Maine, State of 83/06/07 Docketing & Services Branch,
1p 18805, 326 24X Fiche 50-309,83/06/07,8306100191

--8306100193 Third set of interrogatories & requests for production of
documents, Certificate of Svc encl Related correspondence,
AHRENS, P., STERN, P Maine, State of 83/06/07 Maine Yankee
Atomic Power Co. 21pp, 18805 327 24X Fiche 50-309,83/06/07,
8306100191.

8306100204 Forwards third set of interrogatories & requests for
production of documents Related correspondence,
STERN, P Maine, State of 83/06/07 Docketing & Services Branch,
1p 18805, 209 24X Fiche 50-309,83/06/07,8306100204,

--8306100205 Third set of interrogatories & requests for production of
documents, Certificate of Svc encl Related correspondence
AHRENS, P., STERN, P Maine, State of, 83/06/07 Office of the
Executive Legal Director 20pp 18805, 210, 24X
Fiche 50-309,83/06/07,8306100204,

8306130298 Order extending time until 830715 for Commission to act to
review Director's decision dtd 830214,
CHILK, B J Office of the Secretary of the Commission 83/06/10,
Commissioners 1p, 18849 170, 24X Fiche. 50-309,83/06/10,
8306130298

8306150241 Response to first set of interrogatories & request for
documents Prof qualifications & Certificate of Svc encl.
GODDARD, R. J Hearing Branch 3 83/06/13 Maine, State of,
148pp, 18846, 139 24X Fiche: 50-309,83/06/13,8306150241,

8306230011 Response to 830519 second set of interrogatories & request
for documents Certificate of Svc encl,
GODDARD, R. J Hearing Branch 3, 83/06/20, Maine, State of, 43pp,
18947 130, 24X Fiche. 50-309,83/06/20,8306230011

DOCKETED ITEMS

P Operating license stage documents & correspondence

8306010337 Submits list of topics to be discussed at 830525 meeting re operational QA program
MARTIN, T Y Division of Engineering & Technical Programs 83/05/19,
RANDAZZA, J B Maine Yankee Atomic Power Co 2pp 18681, 287 24X
Fiche 50-309, 83/05/19, 8306010337.

8306030231 Advises that proposed Change 43 to Tech Specs re containment leakage testing acceptable, however Air cannot be used as test medium in Type C testing & add Tech Specs must be proposed to specify test pressure Safety evaluation encl
CLARK, R A Operating Reactors Branch 3 83/05/20 GARRITY, J H
Maine Yankee Atomic Power Co 2pp 18733 348 24X
Fiche 50-309, 83/05/20, 8306030231.

--8306030225 Safety evaluation supporting proposed Change 43 to Tech Specs re containment leakage testing Air cannot be used as test medium in Type C testing & add Tech Specs must be proposed to specify test pressure
a Office of Nuclear Reactor Regulation, Director. 83/05/20 2pp 18733 350 24X Fiche 50-309, 83/05/20, 8306030225

8306020015 Requests performance or documentation of completion of load test of reactor vessel head lifting fixture for control of heavy loads, Phase I within 120 days Guidelines for response & complete draft technical evaluation reft encl
CLARK, R A Operating Reactors Branch 3 83/05/24 GARRITY, J H
Maine Yankee Atomic Power Co 16pp 18701 146 24X
Fiche 50-309, 83/05/24, 8306020015

--8306020037 "Control of Heavy Loads (C-10), Maine Yankee Atomic Power Co, Main Yankee Nuclear Power Station," draft technical evaluation reft
VITTO, D J, BOWEN, C, BARGENT, I H Franklin Institute/Franklin Research Center, NRC-03-81-130, TER-C5506-365 DRAFT 82/12/30
CLEMENSEN, F NRC - No Detailed Affiliation Given 26pp 18701 142 24X Fiche 50-309, 83/05/24, 8306020015

8306020505 Forwards safety evaluation on status of thermal shield support structure Followup & monitoring investigation of failure mechanism recommended Continued operation acceptable
CLARK, R A Operating Reactors Branch 3 83/05/25 GARRITY, J H
Maine Yankee Atomic Power Co, 3pp 18715 148 24X
Fiche 50-309, 83/05/25, 8306020505

--8306020511 Safety evaluation supporting justification for continued operation re thermal shield integrity
a Operating Reactors Branch 3, 83/05/25, 3pp 18715 151, 24X
Fiche 50-309, 83/05/25, 8306020505

8306020146 Forwards info supporting post-implementation review of post-accident sampling sys Eleven criteria from NUREG-0737, item 11 & 13 addressed Description of reactor coolant & containment air post-accident sampling sys encl
GARRITY, J H Maine Yankee Atomic Power Co 83/05/26, CLARK, R A
Operating Reactors Branch 3 28pp 18694 130, 24X
Fiche 50-309, 83/05/26, 8306020146.

8306060310 Forwards revised Table 6.1 showing current spent fuel discharge projections vs spent fuel storage mod, per B1005 ltr. Revs do not alter proposed action or evaluation Alternative to reworking program encl.
GARRITY, J H Maine Yankee Atomic Power Co 83/05/26 CLARK, R A
Operating Reactors Branch 3 13pp 18729 187, 24X
Fiche 50-309, 83/05/26, 8306060310

8306020524 Discusses status of 820627 commitment to perform comprehensive stress analysis of reactor vessel closure head & internals lifting rigs to provide scope & schedule of effort Results scheduled for submittal by 830831
GARRITY, J H Maine Yankee Atomic Power Co 83/05/27, CLARK, R A
Operating Reactors Branch 3 2pp 18693 241 24X
Fiche 50-309, 83/05/27, 8306020524.

8306090377 Informs that B1123 response to Generic Ltr B1-21 re natural circulation cooldown acceptable. Final resolution of procedure adequacy deferred to TMI Action item I.C.1.
Summary of natural circulation cooldown tests requested
CLARK, R A Operating Reactors Branch 3 83/05/31, GARRITY, J H
Maine Yankee Atomic Power Co, 2pp 18814, 035, 24X
Fiche 50-309, 83/05/31, 8306090377.

--8306090380 Safety evaluation re Generic Ltr B1-21, natural circulation cooldown For Maine Yankee Atomic Power Station Approval contingent upon resolution of TMI Action Item I.C.1, generic review of vendor guidelines.
REAME, M E Office of Nuclear Reactor Regulation, Director 83/05/31 3pp 18814, 037, 24X Fiche 50-309, 83/05/31, 8306090377.

8306210304 Summary of 830510 meeting w/Util. Weston Geophysical Corp, Cygnus Energy Svc & Stevenson & Assoc re seismic safety margin program status reft Viewgraphs & resumes encl
HEITNER, K L Operating Reactors Branch 3 83/06/06 CLARK, R A
Operating Reactors Branch 3 122pp 18725 200 24X
Fiche 50-309, 83/06/06, 8306210304

8306220223 Informs of actions required to avoid degraded conditions of offsite power supplies, per completed review of 830324 submittal re 821214 offsite power supply degradation incident BFR encl
CLARK, R A Operating Reactors Branch 3 83/06/08 GARRITY, J H
Maine Yankee Atomic Power Co 4pp 18750 347 24X
Fiche 50-309, 83/06/08, 8306220223

--8306220226 Safety evaluation finding licensee commitment to upgrade Burawiec line to conform w/FSAR after const acceptable Load flow analysis reflecting modified sys & development of periodic reassessment procedures required
KANO, P Office of Nuclear Reactor Regulation, Director 83/06/08 4pp 18750 351 24X Fiche 50-309, 83/06/08, 8306220223

8306240357 Notification of 830628 meeting w/Util in Wisconsin, ME to discuss auxiliary feedwater sys evaluation
HEITNER, K L Operating Reactors Branch 3 83/06/21, CLARK, R A
Operating Reactors Branch 3 1p 18797, 155 24X
Fiche 50-309, 83/06/21, 8306240357.

8306290190 Requests proposed Tech Specs re limiting overtime for staff personnel which comply w/guidelines furnished in 820615 ltr Proposal dtd 830121 unacceptable
CLARK, R A Operating Reactors Branch 3 83/06/21 GARRITY, J H
Maine Yankee Atomic Power Co 3pp 17046 287 24X
Fiche 50-309, 83/06/21, 8306290190

8306280009 Forwards "Maine Yankee Seismic Analysis" Study employed both zonation & historic methods of seismic analysis
ORACE, R H Yankee Atomic Electric Co ORACE, R H Maine Yankee Atomic Power Co, 83/06/24 CLARK, R A Operating Reactors Branch 3 2pp 19000 007, 24X Fiche 50-309, 83/06/24, 8306280009.

--8306280011 "Maine Yankee Seismic Analysis"
a Yankee Atomic Electric Co YAE-1056 83/06/03 2/4pp 19000-009 24X Fiche 50-309, 83/06/24, 8306280009

Q Inspection reports, IE Bulletins & correspondence

8306060257 Discusses IE Insp Rept 50-309/02-05 on 820323-0503 & forwards notice of violations Response providing addl actions completed or planned to improve control of design changes per 820928 ltr requested
STAROSTECKI, R Division of Project & Resident Programs, 83/05/23,
RANDAZZA, J B Maine Yankee Atomic Power Co 4pp 18727 201 24X
Fiche 50-309, 83/05/23, 8306060257

--8306060258 Notice of violation from insp on 820323-0503 Noncompliances noted: procedures re design control not appropriate to effectively control plant design & failure to effectively correct pipe support clearance identified in previous insp
a Region I, Office of Director 83/05/23 2pp 18727 205 24X
Fiche 50-309, 83/05/23, 8306060257.

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl.
TAYLOR, J H Division of Safeguards & Inspection Programs (Post 830103), 83/05/26 Consolidated Edison Co of New York, Inc. 125pp 18831, 043 24X Fiche 50-000, 83/05/26, 8305110458.

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc. 115pp, 18732, 205, 24X Fiche 50-000, 83/05/26, 8305110460

8306030282 Forwards IE Enforcement Conference Rept 50-309/83-05 on 830421. No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs, 83/05/27,
RANDAZZA, J B Maine Yankee Atomic Power Co, 2pp 18708 342 24X
Fiche 50-309, 83/05/27, 8306030282.

--8306030316 IE Enforcement Conference Rept 50-309/83-05 on 830421. No noncompliance noted Major topics discussed: violations re degradation of HPSI sys.
GALLQ, R M, GREENMAN, E G, Region I, Office of Director, 83/05/04 3pp 18708 344 24X Fiche 50-309, 83/05/27, 8306030282.

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/31 Consolidated Edison Co. of New York, Inc 116pp, 18732, 208, 24X Fiche 50-000, 83/05/31, 8305110461

B306100276 Responds to Action Item 4 of IE Bulletin B3-03 re check valve failures in diesel generators raw cooling water sys. Preventive maint program revised to require that one check valve be inspected each refueling interval.
RANDAZZA, J B Maine Yankee Atomic Power Co B3/06/07 ALLAN, J M
Region 1, Office of Director 3pp 10005 139 24X
Fiche 50-309, B3/06/07, B306100276

B306210175 Responds to IE Bulletin B3-03 & IC Info Notice B2-08 re check valve failures in diesel generator raw water cooling sys. Listed HX inlet & outlet check valves will be inspected during next refueling outage.
RANDAZZA, J B Maine Yankee Atomic Power Co B3/06/07 ALLAN, J M
Region 1, Office of Director 3pp 1891B 101 24X
Fiche 50-309, B3/06/07, B306210175

B306170469 Forwards SER, technical evaluation rept & notice of granting relief from inservice insp requirements. Relief granted for Code requirements determined impractical to perform.
CLARK, R A Operating Reactors Branch 3 B3/06/08 GARRITY, J H
Maine Yankee Atomic Power Co 3pp 18894 230 24X
Fiche 50-309, B3/06/08, B306170469

--B306170472 Safety evaluation re util requests for relief from inservice insp requirements of ASME Boiler & Pressure Vessel Code, Section XI Relief from requirements determined impractical to perform granted.
* Office of Nuclear Reactor Regulation, Director B3/06/08 9pp
18894 233 24X Fiche 50-309, B3/06/08, B306170469

--B303220042 "ME Yankee Atomic Power Plant Inservice Insp Program," technical evaluation rept.
* Battelle Memorial Institute, Pacific Northwest Laboratory FIN
D-2157 B3/02/25 NRC -- No Detailed Affiliation Given 29pp
18894 243 24X Fiche 50-309, B3/06/08, B306170469

--B306170474 Notice of granting of relief from inservice insp requirements of ASME Boiler & Pressure Vessel Code.
* NRC -- No Detailed Affiliation Given B3/06/08 1p 18894 272
24X Fiche 50-309, B3/06/08, B306170469

B305110464 IE Info Notice B3-36, "Impact of Security Practices on Safe Operations." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B3/06/09 Consolidated Edison Co. of New
York, Inc 119pp 18830 280 24X Fiche 50-000, B3/06/09, B305110464

B305110470 IE Info Notice B3-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B3/06/13 Consolidated Edison Co. of New
York, Inc 118pp 18920 225 24X Fiche 50-000, B3/06/13, B305110470

B306090010 IE Info Notice B3-37, "Transformer Failure Resulting From Degraded Internal Connection Cables." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B3/06/13 Consolidated Edison Co. of New
York, Inc 243pp 18921 001 24X Fiche 50-000, B3/06/13, B306090010

B306290486 Responds to NRC B30520 ltr re violations noted in IE Insp Rept 50-309/B3-05 & B30520 proposed civil penalty. Corrective actions design change developed to modify B pump interlock & warning signs placed on safeguards pumps.
RANDAZZA, J B Maine Yankee Atomic Power Co B3/06/17 DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement 4pp.
19053 031 24X Fiche 50-309, B3/06/17, B306290486

B305110475 IE Info Notice B3-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B3/06/22 Consolidated Edison Co. of New
York, Inc 119pp 19021 179 24X Fiche 50-000, B3/06/22, B305110475

B305110477 IE Info Notice B3-41, "Actuation of Fire Suppression Bys Causing Inoperability of Safety-Related Equipment." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B3/06/22 Consolidated Edison Co. of New
York, Inc 120pp 18997 007 24X Fiche 50-000, B3/06/22, B305110477

B305110479 IE Info Notice B3-42, "Reactor Mode Switch Malfunctions." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B3/06/23 Consolidated Edison Co. of New
York, Inc 116pp 18996 242 24X Fiche 50-000, B3/06/23, B305110479

B305110483 IE Info Notice B3-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B3/06/24 Consolidated Edison Co. of New
York, Inc 116pp 19046 297 24X Fiche 50-000, B3/06/24, B305110483

R Periodic operating reports & related correspondence

B306020152 Monthly operating rept for Mar 1983 W/B30413 ltr
BATTERSON, S , ORDOCE, R H Maine Yankee Atomic Power Co B3/04/13,
HARTFIELD, R A Management Information Branch 5pp 18691 001 24X
Fiche 50-309, B3/04/13, B306020152

B306160444 Monthly operating rept for Apr 1983 W/B30512 ltr
BATTERSON, S , ORDOCE, R H Maine Yankee Atomic Power Co B3/05/12,
HARTFIELD, R A Management Information Branch 5pp 18864 210 24X
Fiche 50-309, B3/05/12, B306160444

B306020352 Forwards microfiche of annual 50 59 rept Equipment unavailable to provide for 24 1 reduction ratio & 98 frames per sheet, per B20809 NRC request. W/o Fiche.
GARRITY, J H Maine Yankee Atomic Power Co B3/05/24 ALLAN, J M
Region 1, Office of Director 1p 18694 323 24X
Fiche 50-309, B3/05/24, B306020352

S Reportable occurrences, LERs & related correspondence

B306010408 LER B3-01B/01T-0 on B30516, portion of gaseous radioactive decay drum different from one inadvertently released. Release terminated when discharge activity level exceeded setpoint. Caused by personnel error.
WOOD, E C Maine Yankee Atomic Power Co B3/05/17 Region 1,
Office of Director 1p 18679 340 24X Fiche 50-309, B3/05/17,
B306010408

B306030341 LER B3-014/03L-0 on B30425, during full power operation, Section 207 of 115 kV reserve station svc line became unavailable when struck by lightning while alternate out of svc for upgrading. Damaged arrestors replaced. W/B30525 ltr.
STEVENSON, J L , GARRITY, J H Maine Yankee Atomic Power Co B3/05/25
ALLAN, J M Region 1, Office of Director 3pp 18704 360 24X
Fiche 50-309, B3/05/25, B306030341

B306020425 Revised LER B3-01B/01T-0 on B30516, portion of gaseous radioactive decay drum D inadvertently released rather than permit-specified drum B. Caused by personnel error. Personnel re-instructed in reading permits. W/B30527 ltr.
STEVENSON, J L , GARRITY, J H Maine Yankee Atomic Power Co B3/05/27,
ALLAN, J M Region 1, Office of Director 4pp 18693 221 24X
Fiche 50-309, B3/05/27, B306020425

B306170186 LER B3-016/03L-0 on B30504, while performing ECCB hot monthly surveillance testing, safeguards recirculation stop valve B1A-M-54 failed to operate. Caused by mechanical binding of valve stem. Maint program to be upgraded. W/B30602 ltr.
LAFLAMME, S J , GARRITY, J H Maine Yankee Atomic Power Co B3/06/02
ALLAN, J M Region 1, Office of Director 3pp 18878 271 24X
Fiche 50-309, B3/06/02, B306170186

B306130455 Forwards NRR comments on draft AD rept to Congress for First Quarter 1983.
DENTON, H R Office of Nuclear Reactor Regulation, Director,
B3/06/07 HELTEMER, C J Director's Office 3pp 18830 176 24X
Fiche 50-000, B3/06/07, B306130455

B306170430 LER B3-017/03L-0 on B30509, B30517 & 18, cooling water outlet stop valve PCC-M-43 to RHR HX failed to open from main control board. Caused by misadjusted valve motor operator torque settings. W/B30608 ltr.
MCALLISTER, B A , GARRITY, J H Maine Yankee Atomic Power Co
B3/06/08 ALLAN, J M Region 1, Office of Director 4pp.
18879 009 24X Fiche 50-309, B3/06/08, B306170430

B306270295 LER B3-019/03L-0 on B30516, operable auxiliary feedwater pump tagged out of svc during installation of heavy shielding door. Caused by movement of massive door creating safety hazard, forcing degraded mode operation. W/B30611 ltr.
TAYLOR, J M , GARRITY, J H Maine Yankee Atomic Power Co B3/06/16,
MURLEY, T E Region 1, Office of Director 3pp 18990 138 24X
Fiche 50-309, B3/06/16, B306270295

V Operator Examinations

B306140619 Extends invitation to attend B30627 meeting in King of Prussia, PA to discuss transfer of reactor operator licensing function from Bethesda, MD to Region 1 ofc.
STAROSTECHKI, R Division of Project & Resident Programs B3/06/09
RANDAZZA, J B Maine Yankee Atomic Power Co 2pp 18841 260 24X
Fiche 50-309, B3/06/09, B306140619

DOCKETED ITEMS

DOCKET 50-311 SALEM NUCLEAR GENERATING STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8306070150 Forwards Submittal 3 to security training & qualification plan Submittal withheld (ref 10CFR73.21)
LIDEN, E. A. Public Service Electric & Gas Co. of New Jersey
83/05/02 Region 1, Office of Director 2pp 18736 291 24X
Fiche 50-272, 83/05/02, 8306070150

8306070164 Requests that revocation of Chapter 9 be taken into account during review of Rev 8 to security plan & that approval of plan not be delayed by review of Chapter 9 Notice withdrawing Chapter 9 & Procedure SP7 encl
LIDEN, E. A. Public Service Electric & Gas Co. of New Jersey
83/05/12 Region 1, Office of Director 3pp 18736 281 24X
Fiche 50-272, 83/05/12, 8306070164

8306020232 Forwards Rev 0 to Salem Generating Station Emergency Operating Procedures Generation Package, per Suppl 1 to NUREG-0737 (Generic Ltr 82-33).
LIDEN, E. A. Public Service Electric & Gas Co. of New Jersey
83/05/20 VARQA, B A Operating Reactors Branch 1 1p 18689 001
24X Fiche 50-272, 83/05/20, 8306020232

--8306020240 Rev 0 to "Salem Generating Station Emergency Operating Procedures Generation Package"
QUELLER, J. FRV, L., BERKLEY, J. Public Service Electric & Gas Co. of New Jersey 83/04/20 16pp 18689 002 24X
Fiche 50-272, 83/05/20, 8306020232

8306090052 Requests that proposed mod completion dates be included in Amend to License DPR-75 to include 10CFR50, App R, Section III Q 2, re Fire Area P20-1 Submittal within 30 days of ltr receipt requested
VARQA, B A Operating Reactors Branch 1 83/05/31 UDERITZ, R A Public Service Electric & Gas Co. of New Jersey 2pp 18797 358
24X Fiche 50-311, 83/05/31, 8306090052

8306170481 Forwards safety evaluation of util submittals re fire protection rule, incorporating BNL technical input Facilities in compliance w/App R to 10CFR50, Items III Q & III L re safe shutdown in relay cable spreading or control room
VARQA, B A Operating Reactors Branch 1 83/05/31 UDERITZ, R A Public Service Electric & Gas Co. of New Jersey 2pp 18894 307
24X Fiche 50-272, 83/05/31, 8306170481

--8306170483 Safety evaluation of util compliance w/App R to 10CFR50, Items III Q 3 & III L Facility design provides train of sys necessary to achieve & maintain safe shutdown conditions
* Office of Nuclear Reactor Regulation, Director 83/05/31 8pp 18894 309 24X Fiche 50-272, 83/05/31, 8306170481.

8306090049 Forwards Rev B, Amend 1 to security plan Rev withheld (ref 10CFR73.21)
LIDEN, E. A. Public Service Electric & Gas Co. of New Jersey
83/06/03 Region 1, Office of Director 2pp 18793 311 24X
Fiche 50-272, 83/06/03, 8306090049

8306230471 Forwards IE Safeguards Insp Repts 50-272/83-17 & 50-311/83-16 on 830516-20 No noncompliance noted
MARTIN, T. T. Division of Engineering & Technical Programs 83/06/08
UDERITZ, R A Public Service Electric & Gas Co. of New Jersey 2pp 18941 302 24X Fiche 50-272, 83/06/08, 8306230471

--8306230475 IE Safeguards Insp Repts 50-272/83-17 & 50-311/83-16 on 830516-20 No noncompliance noted Major areas inspected, security plan, contingency plan & previously identified items
SMITH, Q C Region 1, Office of Director 83/06/06 3pp 18941 304 24X Fiche 50-272, 83/06/08, 8306230471

H. General correspondence

8306140043 Requests JM Zupko & A Nassman be added to svc list for all correspondence re facilities HJ Midura should be deleted
LIDEN, E. A. Public Service Electric & Gas Co. of New Jersey
83/06/06 VARQA, B A Operating Reactors Branch 1 1p 18838 319
24X Fiche 50-272, 83/06/06, 8306140043

P. Operating license stage documents & correspondence

8306020562 Clarifies 830219 & 21 environ qualification SERs Upon completion of plant-specific review of all plants, cross-ref of nonqualified equipment will be conducted to determine if same equipment in other plants determined qualified
VARQA, B A Operating Reactors Branch 1 83/05/23 UDERITZ, R A Public Service Electric & Gas Co. of New Jersey 3pp 18715 120
24X Fiche 50-272, 83/05/23, 8306020562

8306030141 Submits long-term operational verification program for Westinghouse DD-50 reactor trip breakers Data will be used to assess reliability of undervoltage trip attachments Results of program expected in Oct 1983
UDERITZ, R A Public Service Electric & Gas Co. of New Jersey
83/05/31 EISENHUT, D O Division of Licensing 8pp 18704 281
24X Fiche 50-272, 83/05/31, 8306030141

8306150064 COPPER IN THE INTAKE AND DISCHARGE ZONES OF THE SURRY AND SALEM NUCLEAR POWER STATIONS
HARRISON, F. L., DISHOP, D. J., RICE, D. W. Lawrence Livermore Laboratory
FIN A-0119 NUREG/CR-2965 83/05/31 Division of Health, Safety & Waste Management 51pp Available at NRC \$4.00 18849 221
24X Fiche 50-000, 83/05/31, 8306150064

8306140059 Forwards "Analysis of Valve/Operator Interface Hardware for Containment Pressure & Vacuum Relief Valves 1 & 2 VC 5," in response to NRC 830519 request
LIDEN, E. A. Public Service Electric & Gas Co. of New Jersey
83/06/07 VARQA, B A Operating Reactors Branch 1 3pp 18838 261
24X Fiche 50-272, 83/06/07, 8306140059

--8306140063 "Analysis of Valve/Operator Interface Hardware for Containment Pressure & Vacuum Relief Valves 1 & 2 VC 5"
FOLEY, J. M., WOOD, J. C., KRAMER, E. W. Public Service Electric & Gas Co. of New Jersey 83/06/03 16pp 18838 270 24X
Fiche 50-272, 83/06/07, 8306140059

8306160438 Forwards RA Uderitz affidavit re 830607 response to NRC 830519 ltr re valve operability review for 10-inch pressure/vacuum relief valves used for purge or vent of containments
LIDEN, E. A. Public Service Electric & Gas Co. of New Jersey
83/06/08 VARQA, B A Operating Reactors Branch 1 2pp 18860 014
24X Fiche 50-272, 83/06/08, 8306160438

8306270299 Application for amend to Licenses DPR-70 & DPR-75, revising Amend Requests 79-01 & 81-19 re radiological effluent & administrative controls & Tech Specs re surveillance testing & reporting requirements for reactor trip breakers
LIDEN, E. A. Public Service Electric & Gas Co. of New Jersey
83/06/17 VARQA, B A Operating Reactors Branch 1 3pp 18994 278
24X Fiche 50-272, 83/06/17, 8306270299

--8306270304 Proposed Tech Specs revising radiological effluent & administrative controls & surveillance testing & reporting requirements for reactor trip breakers
* Public Service Electric & Gas Co. of New Jersey 83/06/17 249pp 18994 281 24X Fiche 50-272, 83/06/17, 8306270299

8306290313 Responds to 830523 clarification of SERs re environ qualification of safety-related electrical equipment requesting review of equipment in Categories IV, I B & II A
LIDEN, E. A. Public Service Electric & Gas Co. of New Jersey
83/06/21 VARQA, B A Operating Reactors Branch 1 3pp 19055 313
24X Fiche 50-272, 83/06/21, 8306290313

8306300190 Forwards Offsite Dose Calculation Manual per NRC 790118 ltr
LIDEN, E. A. Public Service Electric & Gas Co. of New Jersey
83/06/24 VARQA, B A Operating Reactors Branch 1 1p 19122 199
24X Fiche 50-272, 83/06/24, 8306300190

--8306300194 Offsite Dose Calculation Manual
* Public Service Electric & Gas Co. of New Jersey 83/03/31 75pp 19122 200 24X Fiche 50-272, 83/06/24, 8306300190

G. Inspection reports, IE Bulletins & correspondence

8306240046 Discusses IE insp on 830302-06 & forwards notice of violation & proposed imposition of civil penalty
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 83/05/03 SMITH, R Public Service Electric & Gas Co. of New Jersey 4pp 18987 217 24X Fiche 50-272, 83/05/05, 8306240046

--8306240049 Notice of violation & proposed imposition of civil penalty in amount of \$950,000 Noncompliance noted, reactor trip breaker failed to automatically open following receipt of valid trip signal
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 83/05/03 8pp 18987 221 24X
Fiche 50-272, 83/05/05, 8306240046

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl
TAYLOR, J. M. Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc. 123pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458.

8305110460 IC Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New
York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at JWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/31 Consolidated Edison Co of New
York, Inc 116pp 18732 200 24X Fiche 50-000, 83/05/31, 8305110461

8306140256 Ack receipt of 830317 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/83-36 & 50-311/83-03
STAROSTECKI, R Division of Project & Resident Programs 83/05/31
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 1p
18833 017 24X Fiche 50-272, 83/05/31, 8306140256

--8306140261 Responds to NRC 830215 ltr re violations noted in IE Insp Repts 50-272/83-36 & 50-311/83-03 Corrective actions Operations Directive 12, Tech Spec interpretations, expanded to include encl Guide-11 & Footnotes added to logs
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 83/03/17
HAYNES, R C Region 1, Office of Director
STAROSTECKI, R Division of Project & Resident Programs 3pp
18833 020 24X Fiche 50-272, 83/05/31, 8306140256

8306160130 Forwards IE Insp Repts 50-272/83-12 & 50-311/83-13 on 830326-0510 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 83/05/31
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 2pp
18862 005 24X Fiche 50-272, 83/05/31, 8306160130

--8306160137 Notice of violation from insp on 830326-0510
* Region 1, Office of Director 83/05/31 1p 18862 007, 24X
Fiche 50-272, 83/05/31, 8306160130

--8306160144 IE Insp Repts 50-272/83-12 & 50-311/83-13 on 830326-0510
Noncompliance noted failure to submit timely LERs
NORRHOLM, L J, SUMMERS, R J, TRIPP, L E Region 1, Office of
Director 83/05/27 1pp 18862 000 24X Fiche 50-272, 83/05/31,
8306160130

8306070177 Requests 30-day extension for response to 830505 notice of violation & proposed imposition of civil penalties Delay due to complexity of issues & consideration of available options
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 83/06/01
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 2pp 18736 327 24X Fiche 50-272, 83/06/01, 8306070177

8306160440 Ack receipt of 830416 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/83-01 & 50-311/83-01
MARTIN, T T Division of Engineering & Technical Programs 83/06/07
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 1p
18864 214 24X Fiche 50-272, 83/06/07, 8306160440

--8306160448 Responds to NRC 830304 ltr requesting addl info re violations noted in IE Insp Repts 50-272/83-01 & 50-311/83-01 Corrective actions Meter M-13/ returned to vendor for repair cost estimate
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 83/04/15
MARTIN, T T Division of Engineering & Technical Programs 3pp 18864 219 24X Fiche 50-272, 83/06/07, 8306160440

8306210176 Responds to IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators " Affected check valves associated w/each diesel generator listed.
LIDEN, E A Public Service Electric & Gas Co of New Jersey 83/06/07
ALLAN, J M Region 1, Office of Director 3pp
18915 239 24X Fiche 50-272, 83/06/07, 8306210176

8306230471 Forwards IE Safeguards Insp Repts 50-272/83-17 & 50-311/83-16 on 830516-20 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/06/08
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 2pp
18941 302 24X Fiche 50-272, 83/06/08, 8306230471

--8306230475 IE Safeguards Insp Repts 50-272/83-17 & 50-311/83-16 on 830516-20 No noncompliance noted, Major areas inspected security plan, contingency plan & previously identified items.
SMITH, G C, GOODY, A T Region 1, Office of Director 83/06/06
3pp 18941 304 24X Fiche 50-272, 83/06/08, 8306230471

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/09, Consolidated Edison Co of New
York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New
York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New
York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New
York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New
York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co of New
York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co of New
York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

R Periodic operating reports & related correspondence

8306150267 Forwards annual radiological rept for 1982, "Artificial Island Radiological Environ Monitoring Program "
LIDEN, E A Public Service Electric & Gas Co of New Jersey,
83/06/02 ALLAN, J M Region 1, Office of Director 1p 18849 263,
24X Fiche 50-272, 83/06/02, 8306150267

--8306150270 "Artificial Island Radiological Environ Monitoring Program," annual radiological rept for 1982
LIDEN, E A Public Service Electric & Gas Co of New Jersey
RMC-TR-83-03 83/04/20 135pp, 18849 264 24X
Fiche 50-272, 83/06/02, 8306150267

8306280542 "NPDES Discharge Monitoring Repts for May 1983 " W/830606 ltr
MILLER, L K Public Service Electric & Gas Co of New Jersey
83/06/06 21pp 19019 343 24X Fiche 50-272, 83/06/06, 8306280542

8306200240 "Annual Environ Operating Rept (Nonradiological), 1982 " W/830608 ltr
LIDEN, E A Public Service Electric & Gas Co of New Jersey
83/06/08 ALLAN, J M, BORES, R J Region 1, Office of Director,
1pp 18902 129 24X Fiche 50-272, 83/06/08, 8306200240

8306200132 Monthly operating rept for May 1983, W/830610 ltr
MILLER, L K, ZUPKO, J M Public Service Electric & Gas Co of New
Jersey 83/06/10 Director's Office, Office of Inspection and
Enforcement 12pp 18903 303 24X Fiche 50-311, 83/06/10,
8306200132

B Reportable occurrences, LERs & related correspondence

8306010328 LER 83-017/01P on 830425, discovered blank installed in line providing vent path for RCB w/both pressurizer overpressurization protection sys valves inoperable. Cause under investigation Detailed rept within 14 days
ZUPKO, J M Public Service Electric & Gas Co of New Jersey,
83/05/10 ALLAN, J M Region 1, Office of Director 1p 18681 276
24X Fiche 50-311, 83/05/10, 8306010328

8306030344 Supplemental LER 82-060/02X-1 on 820722, accumulator 24 declared inoperable when level found below operating band Accumulator 23 later declared inoperable Cause by level indication drift Level transmitters replaced W/830513 ltr
FRANK, R ZUPKO, J M Public Service Electric & Gas Co of New
Jersey 83/05/11 ALLAN, J M Region 1, Office of Director 5pp
18703 007 24X Fiche 50-311, 83/05/11, 8306030344

DOCKETED ITEMS

8306020406 IER 83-017/01T-0 on 830425, blank discovered installed on pressurizer relief line, isolating RCS ventpath. Caused by personnel misunderstanding. Personnel counseled W/830519 ltr. FRAHM, R., ZUPKO, J. M. Public Service Electric & Gas Co. of New Jersey 83/05/18 ALLAN, J. Region I, Office of Director 5pp 18695 162 24X Fiche 50-311, 83/05/18, 8306020406

8306030188 IER 83-019/03L-0 on 830430, vital instrument bus 20 deenergized & tagged out for maint. resulting in loss of power range channel N-44. Caused by shift supervisor being unaware of deenergization W/830520 ltr. FRAHM, R., ZUPKO, J. M. Public Service Electric & Gas Co. of New Jersey 83/05/20 ALLAN, J. Region I, Office of Director 4pp 18703 309 24X Fiche 50-311, 83/05/20, 8306030188

8306030301 IER 83-018/03L-0 on 830428, during pre-test insp of fuel handling area ventilation sys., roughing filter elements found installed in HEPA filter location in normal filter train. Filters replaced. Procedures revised W/830526 ltr. FRAHM, R., ZUPKO, J. M. Public Service Electric & Gas Co. of New Jersey 83/05/25 ALLAN, J. Region I, Office of Director 4pp 18704 021 24X Fiche 50-311, 83/05/25, 8306030301

8306030157 Staff requirements memo informing of Commission 830513 briefing in Washington, DC on NUREG-1000, "Generic Implications of ATWS Events at Salem Nuclear Power Plant." Operating criteria requested. CHILK, S. J. Office of the Secretary of the Commission 83/05/27 DIRCKS, W. J. Office of the Executive Director for Operations 1p 18723 313 24X Fiche 50-272, 83/05/27, 8306030157

8306170021 IER 83-020/03L-0 on 830512, senior shift supervisor notified that control room emergency air conditioning sys. design not consistent w/ Tech Spec Surveillance Requirement 4.7.4.1. O & License change to be submitted W/830609 ltr. FRAHM, R., ZUPKO, J. M. Public Service Electric & Gas Co. of New Jersey 83/06/01 ALLAN, J. Region I, Office of Director 4pp 18892 240 24X Fiche 50-311, 83/06/01, 8306170021

8306170153 IER 83-024/03L-0 on 830514 & 15, RHR sys. suction valve closed, eliminating flow in operating RHR loop. Caused by deenergized vital instrument bus 2B & failure of comparator 2PC-405A-B, respectively. Comparator replaced W/830609 ltr. FRAHM, R., ZUPKO, J. M. Public Service Electric & Gas Co. of New Jersey 83/06/08 ALLAN, J. Region I, Office of Director 4pp 18878 343 24X Fiche 50-311, 83/06/08, 8306170153

8306170207 IER 83-021/01T-0 on 830525, vital instrument inverter 2C deenergized for planned maint., rendering associated bus train inoperable. Containment integrity could not be established within 8 h time limit W/830608 ltr. FRAHM, R., ZUPKO, J. M. Public Service Electric & Gas Co. of New Jersey 83/06/08 ALLAN, J. Region I, Office of Director 5pp 18878 316 24X Fiche 50-311, 83/06/08, 8306170207

8306270188 IER 83-025/03L-0 on 830524, RHR pump & fuel handling bldg exhaust fan 21 tripped. Caused by floating logic line & internal circuitry noise in safeguards equipment control sys. Testing design change issued W/830614 ltr. FRAHM, R., ZUPKO, J. M. Public Service Electric & Gas Co. of New Jersey 83/06/08 ALLAN, J. Region I, Office of Director 4pp 18991 328 24X Fiche 50-311, 83/06/08, 8306270188

8306170362 IER 83-022/01T-0 on 830530, vital instrument inverter 2C failed, rendering associated electrical bus train inoperable. Caused by personnel failure to complete test procedures to be reviewed W/830610 ltr. FRAHM, R., ZUPKO, J. M. Public Service Electric & Gas Co. of New Jersey 83/06/10 ALLAN, J. Region I, Office of Director 5pp 18880 327 24X Fiche 50-311, 83/06/10, 8306170362

8306230334 PNO-I-83-066 on 830620, fire discovered in 480-volt vital switchgear room. Source of fire was phase C of 2B ABB transformer. Fire extinguished. Cause of fire under investigation. SUMMERS, R., COLLINS, S. Region I, Office of Director 83/06/20 1p 18942 348 24X Fiche 50-311, 83/06/20, 8306230334

V Operator Examinations

8306140036 Requests NRC concurrence in special requalification training program for JD Driscoll. Failure of reactor trip breakers in late Feb. & ensuing investigation & corrective action development prevented attendance w/ scheduled shift. LIDEN, E. A. Public Service Electric & Gas Co. of New Jersey 83/06/08 WARHOL, S. A. Operating Reactors Branch I 2pp 18938 309 24X Fiche 50-272, 83/06/08, 8306140036

8306140403 Extends invitation to attend 830627 meeting in King of Prussia, PA to discuss transfer of reactor operator licensing function from Bethesda, MD to Region I of C STAROSTECKI, R. Division of Project & Resident Programs 83/06/09 UDEWITZ, R. A. Public Service Electric & Gas Co. of New Jersey 2pp 18938 001 24X Fiche 50-272, 83/06/09, 8306140403

DOCKET 50-312 RANCHO SECO NUCLEAR GENERATING STATION

F Security, medical, emergency & fire protection plans

8306060400 Responds to FOIA request for lists of personnel in specified depts of nuclear plants & in state depts of health physics/radiology. Forwards listed documents. Document partially withheld (ref FOIA Exemption 6). FELTON, J. M. Division of Rules and Records 83/04/06 WE81, D. K. Affiliation Unknown 2pp 18751 292 24X Fiche 50-312, 83/04/06, 8306060400

8306080123 Forwards "Emergency Preparedness Evaluation Rept" re review of upgraded emergency plan & revs through 13 deficiencies noted. Requests page changes to plan correcting deficiencies or justification why revs unnecessary. SCARANO, R. A. Division of Radiological Safety & Safeguards Program 83/05/27 RODRIGUEZ, R. J. Sacramento Municipal Utility District 2pp 18773 008 24X Fiche 50-312, 83/05/27, 8306080123

--8306080127 "Emergency Preparedness Evaluation Rept" re review of upgraded emergency plan & revs through 13 deficiencies noted. Requests page changes to plan correcting deficiencies or justification why revs unnecessary. SCARANO, R. A. Division of Radiological Safety & Safeguards Program 83/05/27 RODRIGUEZ, R. J. Sacramento Municipal Utility District 2pp 18773 008 24X Fiche 50-312, 83/05/27, 8306080127

8306280175 Forwards IE Emergency Preparedness Insp Rept 50-312/83-09 on 830328-0401. No noncompliance noted. NORDERHAUG, L. R. Region 5, Office of Director 83/04/27 MATTINGOE, J. J. Sacramento Municipal Utility District 2pp 19014 149 24X Fiche 50-312, 83/05/27, 8306280175

--8306280183 IE Emergency Preparedness Insp Rept 50-312/83-09 on 830328-0401. No noncompliance noted. Major areas inspected. Corrective actions re 21 significant findings identified in 180331 immediate action ltr & emergency detection. NORTH, H. S., GILUSTER, M. D. Region 5, Office of Director 83/05/24 15pp 19014 151 24X Fiche 50-312, 83/05/27, 8306280175

8306140591 Forwards Amend II to security plan. Amend withheld (ref 10CFR73.21). RODRIGUEZ, R. J. Sacramento Municipal Utility District 83/06/09 Operating Reactors Branch 4 1p 18944 159 24X Fiche 50-312, 83/06/09, 8306140591

8306170375 Ack receipt of 830105 & 0201 changes to emergency plan implementing procedures. Changes do not decrease effectiveness of emergency response planning. NORDERHAUG, L. R. Region 5, Office of Director 83/06/13 RODRIGUEZ, R. J. Sacramento Municipal Utility District 1p 18980 311 24X Fiche 50-312, 83/06/13, 8306170375

8306230393 Discusses test program for state & tri-county (San Joaquin, Amador & Sacramento Counties) voice notification sys., effective 830627. RODRIGUEZ, R. J. Sacramento Municipal Utility District 83/06/17 MARTIN, J. P. Region 5, Office of Director KEARNS, J. J. California, State of. BARNER, O. San Joaquin County, CA 2pp 18943 129 24X Fiche 50-312, 83/06/17, 8306230393

O Adjudicatory correspondence

8306230337 Notice of LC Lanpher & firm of Hill, Christopher & Phillips removal from svc list. Certificate of Svc encl. LANPHER, L. C. Kirkpatrick, Lockhart, Hill, Christopher & Phillips 83/06/21 2pp 18942 349 24X Fiche 50-312, 83/06/21, 8306230337

J Insurance & indemnity information

8306270325 Forwards NELIA Policy X83-0007, MAELU Policy XTA-1389, Endorsements 1-7 to MAELU Policy TA-1380 & Endorsements 1-6 to NELIA Policy 1666. RODRIGUEZ, R. J. Sacramento Municipal Utility District 83/06/20 BALTIMAN, J. B. Antitrust & Economic Analysis Branch (Utility Finance) 83pp 19346 170 24X Fiche 50-312, 83/06/20, 8306270325

P. Operating license stage documents & correspondence

8306020317 Forwards generic safety evaluation supporting continued operation of PWRs w/ Dresser safety valves on primary sys. Valve ring settings adequate to meet min capacities for limiting transient for interim operation. STOLZ, J. F. Operating Reactors Branch 4 83/05/18 RODRIGUEZ, R. J. Sacramento Municipal Utility District 2pp 18715 281 24X Fiche 50-312, 83/05/18, 8306020317

DOCKETED ITEMS

133

8306010399 Informs that addl clad swell & rupture model calculations in progress, per NUREG-0630 implementation schedule. Final rept will be issued by 830620
RODRIGUEZ, R J Sacramento Municipal Utility District 83/05/23
STOLZ, J F Operating Reactors Branch 4 1p 18682 240 24X
Fiche 50-312, 83/05/23, 8306010399

8306140751 Forwards request for addl info in response to Generic Ltr B2-21 re natural circulation shutdown Response requested within 60 days
STOLZ, J F Operating Reactors Branch 4 83/05/25 RODRIGUEZ, R J Sacramento Municipal Utility District 6pp 18845 339 24X
Fiche 50-312, 83/05/25, 8306140751

8306070216 Corrected Board Notification 83-21C forwards Figures 1-6 inadvertently omitted from 830428 submittal re auxiliary feedwater effectiveness at BWR-designed plants
EISENHUT, D G Division of Licensing 83/05/26 Atomic Safety and Licensing Appeal Panel 2pp 18742 159 24X Fiche 50-312, 83/05/26, 8306070216

8306090393 Forwards request for addl info re three open items concerning controls for handling heavy loads Franklin Research Ctr draft technical evaluation encl Response requested within 60 days of receipt of ltr
STOLZ, J F Operating Reactors Branch 4 83/05/31 RODRIGUEZ, R J Sacramento Municipal Utility District 13pp 18815 037 24X
Fiche 50-312, 83/05/31, 8306090393

--8306090397 "Control of Heavy loads, Sacramento Municipal Util District, Rancho Seco Nuclear Generating Station," draft technical evaluation rept
VOGBURY, F W, VITO, D J, BANGENT, J H Franklin Institute/Franklin Research Center NRC-03-81-130 TER-C8237-368 DRFT 83/01/13
CLEMENSEN, B NRC - No Detailed Affiliation Given 20pp 18815 090 24X Fiche 50-312, 83/05/31, 8306090393

8306090233 Provides info for resolution of NUREG-0737, Item II E 1.1 open items re review of upgraded auxiliary feedwater sys
RODRIGUEZ, R J Sacramento Municipal Utility District 83/06/03
STOLZ, J F Operating Reactors Branch 4 2pp 18745 342 24X
Fiche 50-312, 83/06/03, 8306090233

8306170402 Application for amend to License DPH-54, revising Tech Spec Table 4.1-1 re requirement for nuclear instrumentation calibr
RODRIGUEZ, R J Sacramento Municipal Utility District 83/06/06
EISENHUT, D G Division of Licensing 2pp 18879 019 24X
Fiche 50-312, 83/06/06, 8306170402

--8306170407 Proposed Tech Spec Table 4.1-1, requiring nuclear instrumentation (NI) calibr only when heat balance measured power level exceeds NI measured power level by more than 2 percentage points
* Sacramento Municipal Utility District 83/06/06 1p 18879 021 24X Fiche 50-312, 83/06/06, 8306170407

8306140126 Forwards response to 830524 telcon request for addl info re spent fuel pool expansion Procedure for rerecking as follows to 830217 meeting also provided
RODRIGUEZ, R J Sacramento Municipal Utility District 83/06/07
STOLZ, J F Operating Reactors Branch 4 3pp 18839 089 24X
Fiche 50-312, 83/06/07, 8306140126

8306140377 Forwards revised Table D-1, "Preliminary Stress Level Comparison," showing value of stress concentration factor & higher calculated peak stresses. Higher peak stresses do not affect conclusions from 830506 meeting. Meeting summary encl
TAYLOR, J H Babcock & Wilcox Co 83/06/07 MINER, B NRC - No Detailed Affiliation Given 2pp 18843 067 24X
Fiche 50-000, 83/06/07, 8306140377

8306220206 Summary of 830217 meeting w/util & contractor in Orthesda, MI re proposed spent fuel pool expansion Supporting documentation encl
MINER, B Operating Reactors Branch 4 83/06/08 Operating Reactors Branch 4 35pp 18777 256 24X Fiche 50-312, 83/06/08, 8306220206

8306210048 Provides status of HPI/makeup nozzle thermal sleeve investigation. No evidence of fuel failure found as result of thermal sleeve pieces residing in reactor vessel. Sketch of thermal sleeve recovered from lower grid assembly encl
RODRIGUEZ, R J Sacramento Municipal Utility District 83/06/13
STOLZ, J F Operating Reactors Branch 4 3pp 18712 306 24X
Fiche 50-312, 83/06/13, 8306210048

8306220040 Notifies of error in 830506 ltr re containment instrumentation upgrades per NUREG-0737, Items II F 1.4, II F 1.5 & II F 1.6 Existing instrumented indicator is indicator not recorder.
RODRIGUEZ, R J Sacramento Municipal Utility District 83/06/17
STOLZ, J F Operating Reactors Branch 4 2pp 18928 208 24X
Fiche 50-312, 83/06/17, 8306220040

8306220075 Clarifies info provided in 830502 ltr re NUREG-0737, Item II B 3 "Post-Accident Sampling Sys (PASS)," per 830526 request Equipment ordered to allow powering of analyzer & solenoid valves from reliable source within 3 h
RODRIGUEZ, R J Sacramento Municipal Utility District 83/06/17
STOLZ, J F Operating Reactors Branch 4 6pp 18930 164 24X
Fiche 50-312, 83/06/17, 8306220075

8306220150 Provides addl info re 830428 request for exemption to allow delay until plant startup following Cycle 8 for upgrading loss of main feedwater portion of anticipatory reactor trip sys per TH Item II K 2.10
RODRIGUEZ, R J Sacramento Municipal Utility District 83/06/17
STOLZ, J F Operating Reactors Branch 4 2pp 18926 196 24X
Fiche 50-312, 83/06/17, 8306220150

8306230447 Responds to NRC 830603 & 10 telcon requests for addl info re NUREG-0737, Item II B 2, "Plant Shielding."
RODRIGUEZ, R J Sacramento Municipal Utility District 83/06/17
MARTIN, J B Region 5, Office of Director 4pp 18942 083 24X
Fiche 50-312, 83/06/17, 8306230447

8306270260 Forwards "Bounding Analytical Assessment of NUREG-0630 Models on LOCA kWh/ft Limits"
RODRIGUEZ, R J Sacramento Municipal Utility District 83/06/20
STOLZ, J F Operating Reactors Branch 4 2pp 18990 231 24X
Fiche 50-312, 83/06/20, 8306270260

8306270133 Forwards addl info re NUREG-0737, Item II E 1.1, "Auxiliary Feedwater Sys Upgrade Review," per 830502 & 0603 ltrs. in response to NRC 820407 ltr Condensate storage tank not damaged by wind loads generated by 175 mph winds
RODRIGUEZ, R J Sacramento Municipal Utility District 83/06/21
STOLZ, J F Operating Reactors Branch 4 3pp 18988 011 24X
Fiche 50-312, 83/06/21, 8306270133

G Inspection reports, IE Bulletins & correspondence

8306100009 Addl response to FOIA request for documents dtd 820101 or after re BALP. Forwards App A documents Documents also available in PDR
FELTON, J M Division of Rules and Records 83/04/11 CLARK, R, San Francisco Examiner 3pp 10815 252 24X Fiche 50-000, 83/04/11, 8306100009

--8306100014 Submits schedule for Region V BALP Board meetings for 820928-830523
ENOKKEN, R II Region 5, Office of Director 82/03/19
DENTON, H R Office of Nuclear Reactor Regulation, Director, DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director MICHELSON, C. Director's Office 1p 18815 255 24X Fiche 50-000, 83/04/11, 8306100009

--8306100032 Requests brief performance analysis & recommended conclusion for each functional area inspected, based on review of summary of insp activities & analyses of LERs & noncompliance items issued from Jul 1981 - Sept 1982.
STERNBERG, D M Region 5, Office of Director 82/03/23, YOUNG, T, CANTER, H, O'BRIEN, J Region 5, Office of Director 1p 18815 256 24X Fiche 50-000, 83/04/11, 8306100009

--8306100036 Discusses assignment of BALP coordinators for Reactor Operations Projects Branch facilities. Coordinators will be responsible for preparing input data used by board members in analyzing functional areas. Draft note from B Miner encl
STERNBERG, D M Region 5, Office of Director 82/03/24, Region 5, Office of Director 1pp 18815 257 24X
Fiche 50-000, 83/04/11, 8306100009

--8306100038 Forwards input to BALP rept
CHOKSHI, N Structural Engineering Branch 82/10/18, MINER, B, NRC - No Detailed Affiliation Given 6pp 18815 271 24X
Fiche 50-000, 83/04/11, 8306100009

--8306100039 Forwards evaluation of licensee performance for safeguards licensing portion of BALP review per Sternberg 821014 memo. Util has responded quickly & accurately to NRC-initiated comments & suggestions
MCCORKLE, G W. Power Reactor Safeguards Licensing Branch 82/11/04 NORDERHAUG, L Region 5, Office of Director 3pp 18815 288 24X Fiche 50-000, 83/04/11, 8306100009

--8306100040 Forwards brief description of investigative activities of seven cases re BALP during Jul 1981 - Sept 1982. Allegation against contract personnel using controlled drugs during outages still pending.
SHACKLEYON, O C Region 5, Office of Director 82/11/10, WILLET, D Region 5, Office of Director 2pp 18815 291 24X
Fiche 50-000, 83/04/11, 8306100009

DOCKETED ITEMS

--8306100044 Comments on 821014 memo re SALP Board review of facility NORTH.H Region 5, Office of Director 82/11/10 WILLEIT,D Region 5, Office of Director 2pp 10815 293 24X Fiche 50-000,83/04/11,8306100007

--8306100047 Forwards SALP rept inadvertently omitted from 821202 ltr & revised agenda for SALP 830105 meeting STERNBERG,D M Region 5, Office of Director 82/12/15 MATTIMOE,J J Sacramento Municipal Utility District 1p 10815,304 24X Fiche 50-000,83/04/11,8306100009

8306070364 Forwards IE Insp Rept 50-312/83-10 on 830310-0429 & notice of violation. STERNBERG,D M Region 5, Office of Director 83/05/09 RODRIGUEZ,R Sacramento Municipal Utility District 2pp 18743 062 24X Fiche 50-312,83/05/09,8306070364

--8306070378 Notice of violation from insp on 830310-0429 YOUNG,T. Region 5, Office of Director 83/05/09 1p 18743 064 24X Fiche 50-312,83/05/09,8306070364.

--8306070385 IE Insp Rept 50-312/83-10 on 830310-0429 Noncompliance noted failure to rept 830326 & 0401 degradation in fuel cladding within 24 h. CARTER,H L, O'BRIEN,J P, YOUNG,T Region 5, Office of Director 83/05/06 7pp. 18743 065 24X Fiche 50-312,83/05/09,8306070364

8306070057 Forwards IE Insp Rept 50-312/83-11 on 830411-15 No noncompliance noted. STERNBERG,D M Region 5, Office of Director 83/05/12 RODRIGUEZ,R J. Sacramento Municipal Utility District. 2pp 18739,320 24X Fiche 50-312,83/05/12,8306070057

--8306070065 IE Insp Rept 50-312/83-11 on 830411-15 No noncompliance noted Major areas inspected inservice insp program & implementing procedures,inservice insp activities & quality records WAGNER,W J, ZWETZIO,Q B Region 5, Office of Director 83/05/11 5pp 18739,322 24X Fiche 50-312,83/05/12,8306070057

8306070152 Forwards IE Insp Rept 50-312/83-12 on 830411-15 & notice of violation. SCARANO,R A Division of Radiological Safety & Safeguards Program 83/05/17. RODRIGUEZ,R J Sacramento Municipal Utility District 2pp 18736,243 24X Fiche 50-312,83/05/17,8306070152

--8306070157 Notice of violation from insp on 830411-15 WENBLAWSKI,F A. Region 5, Office of Director 83/05/17 2pp. 18736,245 24X Fiche 50-312,83/05/17,8306070152

--8306070176 IE Insp Rept 50-312/83-12 on 830411-15 Noncompliance noted failure to post & control radioactive contaminated areas, to properly package & identify packaged radioactive contaminated matl & enforce friking requirements. GILLIS,H, WENBLAWSKI,F A, BOOK,H E. Region 5, Office of Director 83/05/17 15pp 18736 247. 24X Fiche 50-312,83/05/17,8306070152

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl. TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103). 83/05/26 Consolidated Edison Co. of New York, Inc 123pp. 18831 043 24X Fiche 50-000,83/05/26,8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26. Consolidated Edison Co. of New York, Inc. 118pp 18732 085 24X Fiche 50-000,83/05/26,8305110460

8306280175 Forwards IE Emergency Preparedness Insp Rept 50-312/83-09 on 830328-0401 No noncompliance noted NORDERHAUG,L R Region 5, Office of Director 83/05/27 MATTIMOE,J J. Sacramento Municipal Utility District 2pp. 19014 149 24X Fiche 50-312,83/05/27,8306280175

--8306280183 IE Emergency Preparedness Insp Rept 50-312/83-09 on 830328-0401.No noncompliance noted Major areas inspected corrective actions re 21 significant findings identified in 810831 immediate action ltr & emergency detection NORTH,H S, SCHUSTER,M D Region 5, Office of Director 83/05/24. 15pp. 19014 151. 24X Fiche 50-312,83/05/27,8306280175

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs." Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc. 114pp. 18732,208. 24X Fiche 50-000,83/05/31,8305110461

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc 119pp 18830 280 24X Fiche 50-000,83/06/09,8305110464

8306280218 Forwards IE Insp Rept 50-312/83-15 on 830516-18 No noncompliance noted STERNBERG,D M Region 5, Office of Director 83/06/10 RODRIGUEZ,R J Sacramento Municipal Utility District 2pp 19014,179 24X Fiche 50-312,83/06/10,8306280218

--8306280226 IE Insp Rept 50-312/83-15 on 830516-18 No noncompliance noted Major areas inspected allegations re electrical const inadequacies IE mgt meeting conducted 830518 Insp Findings summarized Allegations not substantiated BURDWIN,J F, ZWETZIO,Q B Region 5, Office of Director 83/06/09 App 19014 181 24X Fiche 50-312,83/06/10,8306280218

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 118pp 18920 225 24X Fiche 50-000,83/06/13,8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting from Degraded Internal Connection Cables " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 243pp 18921 001 24X Fiche 50-000,83/06/13,8306090010

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 115pp 19021 179 24X Fiche 50-000,83/06/22,8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 120pp 18997 007 24X Fiche 50-000,83/06/22,8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co. of New York, Inc 114pp 18996 242 24X Fiche 50-000,83/06/23,8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc 116pp. 19046 277 24X Fiche 50-000,83/06/24,8305110483

8306300007 Ack receipt of 830606 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-312/83-10 STERNBERG,D M Region 5, Office of Director 83/06/24 RODRIGUEZ,R J Sacramento Municipal Utility District 1p 19121 031 24X Fiche 50-312,83/06/24,8306300007

--8306300011 Responds to NRC 830509 ltr re violations noted in IE Insp Rept 50-312/83-10 Corrective actions during Cycle 6,proper closure of penetrations prior to leaving cold shutdown will be verified by performing local leak rate test RODRIGUEZ,R J Sacramento Municipal Utility District 83/06/06 MARTIN,J B Region 5, Office of Director App 19121 032 24X Fiche 50-312,83/06/24,8306300007

R Periodic operating reports & related correspondence

8306210056 Monthly operating rept for May 1983 W/830608 ltr. COLOMBO,R, OUBRE,R P Sacramento Municipal Utility District 83/06/08 Director's Office, Office of Inspection and Enforcement 5pp 18911 344 24X Fiche 50-312,83/06/08,8306210056

S Reportable occurrences, LCRs & related correspondence

8306100070 Part 21 rept re abnormal indications in upper core barrel bolting identified during ultrasonic testing Initially reported on 830328 Samples to be removed from internals & examined TAYLOR,J M Babcock & Wilcox Co 83/04/11 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 5pp. 18802 075 24X Fiche 50-312,83/04/11,8306100070

DOCKETED ITEMS

135

8306070047 Revised LER 83-008/03L-1 on 830215, commitment made in response to 810908 SER to isolate auxiliary steam line penetrating HPI pump A room not implemented Caused by personnel not aware of requirement W/830520 ltr COLOMBO, R W., RODRIGUEZ, R J Sacramento Municipal Utility District 83/04/19 MARTIN, J B Region 3, Office of Director App 18740 095 24X Fiche 50-312, 83/04/19, 8306070047

8306170358 LER 83-016/03L-0 on 830331, during surveillance testing on snubbers, 10 snubbers mfg by Grinnell & Dergen-Patterson failed acceptance criteria Caused by defective seals, body corrosion & water in fluid Valves rebuilt W/830428 ltr COLOMBO, R W., RODRIGUEZ, R J Sacramento Municipal Utility District 83/04/28 MARTIN, J B Region 5, Office of Director App 18680 218 24X Fiche 50-312, 83/04/28, 8306170358

8306170223 RO on 830326-0505, cooling tower circulating basin drained for maint Folsom Canal also inoperable from 830408-26 From 830408-26, fire suppression water sys did not have two separate water supplies RODRIGUEZ, R J Sacramento Municipal Utility District 83/05/26 MARTIN, J B Region 5, Office of Director ip 18882 289 24X Fiche 50-312, 83/05/26, 8306170223

8306070069 Part 21 rept re defective Woodward governor/activator, Type EOB-13C Pointer discs machined to remove 1/16 inch from diameter Activator overhauled Util will replace brushes when spare parts available RODRIGUEZ, R J Sacramento Municipal Utility District, 83/05/27 MARTIN, J B Region 5, Office of Director App 18776 179 24X Fiche 50-312, 83/05/27, 8306070069

8306090304 Part 21 rept re defective Woodward Governor Co activator, Type EOB-13C Pointer discs machined to reduce disc diameter Commission notified of potential generic problem Brushes in 125-volt dc motor found worn after overhaul by manufacturer RODRIGUEZ, R J Sacramento Municipal Utility District 83/05/27 MARTIN, J B Region 5, Office of Director App 18795 187 24X Fiche 50-312, 83/05/27, 8306090304

8306170290 LER 83-022/03L-0 on 830507, cooling water to reactor bldg emergency cooling unit A 500c motor found to be drawing locked rotor current preventing valve from stroking Female control disconnect switch found spread apart W/830603 ltr COLOMBO, R W., RODRIGUEZ, R J Sacramento Municipal Utility District 83/06/03 MARTIN, J B Region 5, Office of Director App 18877 015 24X Fiche 50-312, 83/06/03, 8306170290

8306230396 Followup LER 82-020/03L-1 on 820726, nitrogen added to pressurizer liquid sample line, causing contamination of nitrogen sys & once-through steam generators due to water flowing into sys W/830607 ltr COLOMBO, R W., RODRIGUEZ, R J Sacramento Municipal Utility District 83/06/07 MARTIN, J B Region 5, Office of Director App 18943 122 24X Fiche 50-312, 83/06/07, 8306230396

8306230372 Part 21 rept re Brand-Rex Co Type G/C 12 wire cable deficiency Initially reported on 830613 Six suspect wire reels quarantined Records researched to insure suspect cable not used in Class 1 areas RODRIGUEZ, R J Sacramento Municipal Utility District 83/06/16 MARTIN, J B Region 5, Office of Director App 18742 300 24X Fiche 50-312, 83/06/16, 8306230372

8306230410 LER 83-024/03L-0 on 830519, breaker 524806 tripped on ground fault 4500 Caused by cable jacket & insulation damaged during installation Cable will be repulled & spliced to eliminate ground W/830615 ltr COLOMBO, R W., RODRIGUEZ, R J Sacramento Municipal Utility District 83/06/16 MARTIN, J B Region 5, Office of Director App 18943 134 24X Fiche 50-312, 83/06/16, 8306230410

DOCKET 50-313 ARKANBA8 NUCLEAR ONE, UNIT 1

F Security, medical, emergency & fire protection plans

8306070298 Submits supplemental response to IE Insp Repts 50-313/82-33 & 50-368/82-33 Completion date for revised procedures re fire barriers changed to 830531, Addl time necessary to incorporate App R changes MARSHALL, J R Arkansas Power & Light Co 83/04/12 SEIDLE, W C Region 4, Office of Director, ip 18740, 313 24X Fiche 50-313, 83/04/12, 8306070298

8306010101 Forwards IE Insp Repts 50-313/83-05 & 50-368/83-05 on 830314-17 No noncompliance noted Open items will be examined during future Insp SEIDLE, W C Region 4, Office of Director 83/05/12, GRIFFIN, J M, Arkansas Power & Light Co App 18674, 117, 24X Fiche 50-313, 83/05/12, 8306010101

--8306010107 IE Insp Repts 50-313/83-05 & 50-368/83-05 on 830314-17, No noncompliance noted Major areas inspected licensee performance & capabilities during full-scale exercise of emergency plans & procedures HACKNEY, C A., BANGART, R L., HOLLEY, W L. Region 1, Office of Director 83/05/09 2Bpp 18674 119 24X Fiche 50-313, 83/05/12, 8306010101

8306030073 Forwards safety evaluation re safe shutdown capability in event of fire Commitment requested for source range neutron flux monitoring capability & schedules for submittals by 830528 STOLZ, J F Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 83/05/13 GRIFFIN, J M Arkansas Power & Light Co App 18733 249 24X Fiche 50-313, 83/05/13, 8306030073

--8306030078 Safety evaluation re 10CFR50 App R, Items III Q 3 & III L, re safe shutdown capability, Util design acceptable * Office of Nuclear Reactor Regulation, Director 83/05/13 13pp 18733 251 24X Fiche 50-313, 83/05/13, 8306030073

8306090313 Documents recent telcon re 830315 Tech Spec change request to increase emergency plan & contingency plan audit frequency Spec applies to both plans. MARSHALL, J R Arkansas Power & Light Co 83/05/17 COLLINS, J T Region 4, Office of Director, ip 18795 227 24X Fiche 50-313, 83/05/17, 8306090313

8306090248 Provides status of transient brochure distribution program Purchase order for holders issued & delivery expected by 830606 MARSHALL, J R Arkansas Power & Light Co 83/05/23 COLLINS, J T Region 4, Office of Director ip 18795 318 24X Fiche 50-313, 83/05/23, 8306090248

8306060063 Ack receipt of 830429 partial response to 820625 Emergency Plan Evaluation Repts 50-313/81-22 & 50-368/81-21 Response addressing all outstanding deficiencies by revised plan or schedule for plan rev requested SEIDLE, W C Region 4, Office of Director, 83/05/31 GRIFFIN, J M Arkansas Power & Light Co App 18723 271 24X Fiche 50-313, 83/05/31, 8306060063

--8306060067 Response to NRC 820625 evaluation of emergency plans, Nuclear contingency plan & procedures & emergency plan being reviewed & revised Response to deficiencies identified by revs encl MARSHALL, J R, Arkansas Power & Light Co 83/04/29 COLLINS, J T, Region 4, Office of Director, 17pp 18723 273 24X Fiche 50-313, 83/05/31, 8306060063

8306080012 Notices of commitment to install source range monitoring capability on alternate shutdown sys, per 830513 ltr & 10CFR50 App R MARSHALL, J R Arkansas Power & Light Co 83/06/03 STOLZ, J F, Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 App 18773, 249 24X Fiche 50-313, 83/06/03, 8306080012

8306150032 Releases public version of revised emergency plan implementing procedure, FELTON, J M Division of Rules and Records 83/06/07, Document Management Branch ip 18871 288 24X Fiche 50-313, 83/06/07, 8306150032

--8306150034 Public version of Rev 5 to Emergency Plan Implementing Procedure 1903 40, "Emergency Supplies & Equipment," LEVINE, J M Arkansas Power & Light Co 83/05/05 76pp, 18871 289 24X Fiche 50-313, 83/06/07, 8306150032

8306200056 Releases public version of revised emergency plan implementing procedure, FELTON, J M Division of Rules and Records 83/06/07, Document Management Branch ip 18908 295 24X Fiche 50-313, 83/06/07, 8306200056

--8306200060 Public version of Rev 3 to Emergency Plan Implementing Procedure 1903 01, "Organization & Use of Emergency Plan Implementing Procedures " Receipt form encl, LEVINE, J M Arkansas Power & Light Co 83/04/28, NRC - No Detailed Affiliation Given 6pp 18908, 296, 24X Fiche 50-313, 83/06/07, 8306200056

8306140155 Notifies that 1 h fire barriers installed by 830422, per 830329 request for scheduler exemption from App R requirements for installation of barriers to 830801, MARSHALL, J R Arkansas Power & Light Co 83/06/08 STOLZ, J F Operating Reactors Branch 4 CLARK, R A, Operating Reactors Branch 3 ip 18839, 073, 24X Fiche 50-313, 83/06/08, 8306140155

DOCKETED ITEMS

8306230474 Submits addl info re radiation filtration sys for emergency control ctr (ECC), per NUREG-0737, Suppl 1 on emergency response Radiation Filtration sys designed to be manually activated Sketch of ECC filtration sys encl.
MARSHALL, J R Arkansas Power & Light Co 83/06/17 STOLZ, J F
Operating Reactors Branch 4 3pp 18741 307 24X
Fiche: 50-313, 83/06/17, 8306230474

8306240469 Requests exemption from 10CFR50.46(c) for all barriers, penetrations & fire suppression/detection sys be made more specific & detailed by identifying each area requiring exemption Schedule for submittal requested in 20 days.
STOLZ, J F Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 83/06/17 GRIFFIN, J M Arkansas Power & Light Co. 2pp. 18798 085 24X Fiche 50-313, 83/06/17, 8306240469

J Insurance & indemnity information

8306030294 Forwards certificate of insurance, Policy X82-002 for CY83
MARSHALL, J R Arkansas Power & Light Co. 83/04/22 DINI, T J
Office of Resource Management, Director 2pp 18703 327 24X
Fiche 50-313, 83/04/22, 8306030294

P Operating license stage documents & correspondence

8306060051 Addl response to FOIA request for three categories of documents re FRA of reactor safety study methodology application program repts & interim reliability evaluation program repts. Forwards App A documents Search continuing
FELTON, J M Division of Rules and Records 83/04/07 SHOLLY, S C
Union of Concerned Scientists 3pp 18752-001 24X
Fiche: 50-000, 83/04/07, 8306060051.

--8207280024 Discusses NUREG/CR-2787, "Interim Reliability Evaluation Program Analysis of AR Nuclear One-Unit 1 Nuclear Power Plant," first final rept on four integrated reliability evaluation program Phase II studies.
BERNERD, R M Division of Risk Analysis 82/06/24. HANAUER, S H.
Division of Human Factors Safety 5pp. 18752 074 24X
Fiche: 50-000, 83/04/07, 8306060051

--8306060061 Statement on background, issues, current status & future action re interim & natl reliability evaluation programs.
* NRC - No Detailed Affiliation Given 82/12/31. 2pp.
18752 039. 24X Fiche: 50-000, 83/04/07, 8306060051

8306010024 Forwards "Policy Statement re Alcohol/Drug Abuse & Theft," issued as part of util policies & procedures manual, per 830309 commitment.
MARSHALL, J R. Arkansas Power & Light Co 83/05/12 COLLINS, J T
Region 4, Office of Director. 1p 18674.070. 24X
Fiche 50-313, 83/05/12, 8306010024.

--8306010028 "Policy Statement re Alcohol/Drug Abuse & Theft "
* Arkansas Power & Light Co 83/05/03 2pp 18674:071. 24X
Fiche: 50-313, 83/05/12, 8306010024

8306090313 Documents recent telcon re 830315 Tech Spec change request to increase emergency plan & contingency plan audit frequency. Spec applies to both plans.
MARSHALL, J R Arkansas Power & Light Co 83/05/17. COLLINS, J T
Region 4, Office of Director. 1p. 18795 227. 24X
Fiche: 50-313, 83/05/17, 8306090313

8306020135 Comments on App B Tech Spec revs, per 830311 ltr issuing Amends 72 & 40 to Licenses DPR-52 & NPF-6, respectively.
Util will routinely provide NRC w/changes to NPDES discharge permit.
MARSHALL, J R. Arkansas Power & Light Co 83/05/20 STOLZ, J F
Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3. 2pp. 18691:244. 24X Fiche: 50-313, 83/05/20, 8306020135

8306010267 Withdraws request for exemption from requirements to install reactor vessel head vents, as installation of vents subsequently decided upon & completed during fifth refueling outage.
MARSHALL, J R. Arkansas Power & Light Co. 83/05/24. STOLZ, J F
Operating Reactors Branch 4. 1p 18672.251 24X
Fiche: 50-313, 83/05/24, 8306010267

8306130499 Forwards SER re justification for continued operation re environ qualification of safety-related electrical equipment.
STOLZ, J F Operating Reactors Branch 4 83/05/24. GRIFFIN, J M
Arkansas Power & Light Co. 3pp. 18854:348 24X
Fiche: 50-313, 83/05/24, 8306130499

--8306130501 Safety evaluation supporting 830228 & 0428 ltrs in response to 830126 ltr re SER of environ qualification of safety-related equipment
* Office of Nuclear Reactor Regulation, Director 83/05/24. 5pp.
18854:351. 24X Fiche: 50-313, 83/05/24, 8306130499.

8306150519 Forwards request for addl info re 81118 response to 810505 Generic Ltr 81-21, "Natural Circulation Cooled Down " Info should be received within 45 days of ltr receipt
STOLZ, J F Operating Reactors Branch 4 83/05/24 GRIFFIN, J M
Arkansas Power & Light Co 3pp 18864 329 24X
Fiche: 50-313, 83/05/24, 8306150519

8306010314 Submits update on B&W Owners Group plans to install shunt trip feature to reactor trip sys scram breakers Arkansas Power & Light Co will submit design info during wk of 830530 Owners group endorses facility shunt trip design
WALLACE, E O Babcock & Wilcox Operating Plants Owners Group.
WALLACE, E O General Public Utilities - GPU Service Corp 83/05/27
EISENHUT, D.O. Division of Licensing 1p 18672 310 24X
Fiche 50-313, 83/05/27, 8306010314

8306070193 Responds to 830322 ltr re open issues of NUREG-0737, Item II E 1.1, "Auxiliary Feedwater Sys Evaluation " Review of Recommendations QL-2 re environ qualification & QL-4 re flow test to be completed by 830731
MARSHALL, J R Arkansas Power & Light Co 83/05/31 STOLZ, J F
Operating Reactors Branch 4 2pp 18736 296 24X
Fiche: 50-313, 83/05/31, 8306070193

8306200059 Advises that NUREG-0737, Items II F 1.4, II F 1.5 & II F 1.6 requirements resolved per 801219, 820726 & 830408 submittals Environ qualification of equipment will be reviewed separately. SER encl.
STOLZ, J F Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3. 83/06/06 GRIFFIN, J M Arkansas Power & Light Co 7pp 18708 302 24X Fiche 50-313, 83/06/06, 8306200059.

8306140377 Forwards revised Table D-1, "Preliminary Stress Level Comparison," showing value of stress concentration factor & higher calculated peak stresses Higher peak stresses do not affect conclusions from 830506 meeting Meeting summary encl
TAYLOR, J M Babcock & Wilcox Co 83/06/07 MINER, S NRC - No Detailed Affiliation Given 2pp 18844 001 24X
Fiche 50-000, 83/06/07, 8306140377

8306160324 Forwards design info re addition of shunt trip to reactor protection sys trip breakers for NRC review & approval Shunt trip capability poses no unrevised safety question H/two oversize diagrams Aperture cards are available in PDR
MARSHALL, J R. Arkansas Power & Light Co 83/06/07 STOLZ, J F.
Operating Reactors Branch 4 49pp 18862 258 24X
Fiche 50-313, 83/06/07, 8306160324

8306160493 Forwards "Bounding Analytical Assessment of NUREG-0630 Models on LOCA kW/ft Limits," reflecting use of FLECSSET heat transfer correlation as compensating model to reduce impact of NUREG-0630 models
MARSHALL, J R. Arkansas Power & Light Co 83/06/08 STOLZ, J F
Operating Reactors Branch 4 1p 18862.083 24X
Fiche: 50-313, 83/06/08, 8306160493

--8306160497 "Bounding Analytical Assessment of NUREG-0630 Models on LOCA kW/ft Limits "
* Babcock & Wilcox Co 77-1143707-00 83/06/08 20pp
18862 085 24X Fiche: 50-313, 83/06/08, 8306160493

8306170275 Responds to NRC 830509 request for submittal of license amend applications incorporating snubber surveillance program into App A Tech Specs. Program outlined in 830228 ltr will be followed pending NRC review of ANBI OM-4 Btd
MARSHALL, J R. Arkansas Power & Light Co 83/06/10 STOLZ, J F
Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 2pp 18878 257 24X Fiche 50-313, 83/06/10, 8306170275

8306170408 Documents commitment to administratively impose temporary restrictions on plant operating LOCA limits as result of NUREG-0630, per 830608 telcon Review of FLECSSET data requested
MARSHALL, J R. Arkansas Power & Light Co 83/06/10 STOLZ, J F
Operating Reactors Branch 4 3pp 18879 022 24X
Fiche: 50-313, 83/06/10, 8306170408

8306230514 Requests remittance of Class III fee since review of 820602 application requesting exemption from certain requirements of 10CFR50.44(c)(3)(iii) re reactor vessel head vents begun prior to 830524 application withdrawal
DIQGB, R M License Fee Management Branch. 83/06/16 GRIFFIN, J M
Arkansas Power & Light Co 1p 18951 362 24X
Fiche: 50-313, 83/06/16, 8306230514

O. Inspection reports: IE Bulletins & correspondence

8306080192 Forwards IE Insp Rept 50-313/82-36 & 50-368/82-37 on 821213-16 & notice of violation
SEIDLE, W C. Region 4, Office of Director. 83/03/04 GRIFFIN, J M
Arkansas Power & Light Co 2pp. 18771 161. 24X
Fiche: 50-313, 83/03/04, 8306080192

- 8306080197 Notice of violation from insp on 821213-16
* Region 4, Office of Director 83/03/04 2pp 18771 163 24X
Fiche 50-313,83/03/04,8306080192
- 8306080238 IE Insp Rept 50-313/82-26 & 50-368/82-3/ on 821213-16
Noncompliance noted update of Unit 1 FSAR showed radiation
zones less than 100 m/h, when actual survey data indicated
radiation levels exceeded 100 m/h
CHANEY, H D, WILBORN, L, MURRAY, B Region 4, Office of Director
83/02/28 17pp 18771 165 24X Fiche 50-313,83/03/04,8306080192
- 8306160537 Responds to 821025 IE Insp Repts 50-313/82-14 &
50-368/82-11, Item 8 re control room dose calculations Item
re NUREG-0737, Item II D 2, "Plant Shielding," closed
MARSHALL, J R Arkansas Power & Light Co 83/03/24 COLLINS, J T
Region 4, Office of Director 2pp 18263 115 24X
Fiche 50-313,83/03/24,8306160537
- 8306070298 Submits supplemental response to IE Insp Repts 50-313/82-33
& 50-368/82-33 Completion date for revised procedures re
fire barriers changed to 830531 Addl time necessary to
incorporate App R changes
MARSHALL, J R Arkansas Power & Light Co 83/04/12 SEIDLE, W C
Region 4, Office of Director 1p 18740 313 24X
Fiche 50-313,83/04/12,8306070298
- 8306220204 Ack receipt of 83040/ payment of civil penalties proposed by
NRC 830308 ltr Corrective actions will be examined during
future insp
AKELRAD, J A Enforcement Staff 83/04/12 MARSHALL, J R Arkansas
Power & Light Co 2pp 18777 307 24X Fiche 50-313,83/04/12,
8306220204
- 8306010101 Forwards IE Insp Repts 50-313/83-05 & 50-368/83-05 on
830314-17 No noncompliance noted Open items will be
examined during future insp
SEIDLE, W C Region 4, Office of Director 83/05/12 GRIFFIN, J M
Arkansas Power & Light Co 2pp 18674 117 24X
Fiche 50-313,83/05/12,8306010101
- 8306010107 IE Insp Repts 50-313/83-05 & 50-368/83-05 on 830314-17 No
noncompliance noted Major areas inspected licensee
performance & capabilities during full-scale exercise of
emergency plans & procedures
HACKNEY, C A, BANGART, R L, HOLLEY, W L Region 1, Office of
Director 83/05/09 20pp 18674 117 24X Fiche 50-313,83/05/12,
8306010101
- 8306140359 Forwards IE Insp Repts 50-313/83-09 & 50-368/83-09 on
830401-20 No noncompliance noted
SEIDLE, W C Region 4, Office of Director 83/05/18 GRIFFIN, J M,
Arkansas Power & Light Co 2pp 18832 143 24X
Fiche 50-313,83/05/18,8306140359
- 8306140343 IE Insp Repts 50-313/83-09 & 50-368/83-09 on 830401-20, No
noncompliance noted Major areas inspected operational
safety verification, followup on reactor trip breaker failure
& plant startup after refueling
CALLAN, L J, CUMMINS, J L, JOHNSON, W D Region 4, Office of
Director 83/05/16 6pp 18832 145 24X Fiche 50-313,83/05/18,
8306140359
- 8306130222 Updates status of efforts & progress re drawing control
Progress made in program to update mnlrs transferred from
corporate ofc As of 830511, 2,714 drawings updated &
reissued Info responds to IE Bulletin 00-06
MARSHALL, J R Arkansas Power & Light Co 83/05/23 SEIDLE, W C
Region 4, Office of Director 3pp 18826 324 24X
Fiche 50-313,83/05/23,8306130222
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in
Well Logging Device " Svc list encl
TAYLOR, J M, Division of Safeguards & Inspection Programs (Post
830103) 83/05/26 Consolidated Edison Co. of New York, Inc
125pp 18831,043 24X Fiche 50-000,83/05/26,8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co. of New
York, Inc 115pp 18732 085 24X Fiche 50-000,83/05/26,8305110460
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods
Withdrawn at BWRs," Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/31 Consolidated Edison Co. of New
York, Inc 116pp 18732 208 24X Fiche 50-000,83/05/31,8305110461
- 8306060063 Ack receipt of 830429 partial response to 820625 Emergency
Plan Evaluation Repts 50-313/81-22 & 50-368/81-21 Response
addressing all outstanding deficiencies by revised plan or
schedule for plan rev requested
SEIDLE, W C Region 4, Office of Director 83/05/31 GRIFFIN, J M
Arkansas Power & Light Co 2pp 18723 271 24X
Fiche 50-313,83/05/31,8306060063
- 8306060067 Responds to NRC 820625 evaluation of emergency plans Nuclear
contingency plan & procedures & emergency plan being
reviewed & revised Response to deficiencies identified by
revs encl
MARSHALL, J R Arkansas Power & Light Co 83/04/29 COLLINS, J T
Region 4, Office of Director 17pp 18723 273 24X
Fiche 50-313,83/05/31,8306060063
- 8306070380 Ack receipt of 830517 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-313/83-06 &
50-368/83-06
SEIDLE, W C Region 4, Office of Director 83/06/02 GRIFFIN, J M
Arkansas Power & Light Co 2pp 18741 346 24X
Fiche 50-313,83/06/02,8306070380
- 8306070384 Responds to NRC 830418 ltr re violations noted in IE Insp
Repts 50-313/83-06 & 50-368/83-06 Corrective actions
procedures revised to define interface responsibilities &
coordination required for radioactive shipments
MARSHALL, J R Arkansas Power & Light Co 83/05/17 SEIDLE, W C
Region 4, Office of Director 4pp 18741 348 24X
Fiche 50-313,83/06/02,8306070380
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe
Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/09 Consolidated Edison Co. of New
York, Inc 119pp 18830 280 24X Fiche 50-000,83/06/09,8305110464
- 8306140050 Responds to IE Bulletin 83-03, "Check Valve Failures in Raw
Water Cooling Sys of Diesel Generators " Check valves
described in bulletin not employed at facilities Bulletin
not applicable
MARSHALL, J R Arkansas Power & Light Co 83/06/10 STOLZ, J F,
Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch
3 1p 18838 288 24X Fiche 50-313,83/06/10,8306140050
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive &
Seismically Induced Chatter in Relays Within Printed
Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co. of New
York, Inc 118pp 18920 225 24X Fiche 50-000,83/06/13,8305110470
- 8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From
Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co. of New
York, Inc 243pp 18921 001 24X Fiche 50-000,83/06/13,8306090010
- 8306160524 Ack receipt of 830324 ltr informing NRC of corrective
actions taken on open item identified in IE Insp Repts
50-313/82-14 & 50-368/82-11 Status of open item will be
reviewed in future insp
SEIDLE, W C Region 4, Office of Director 83/06/13 GRIFFIN, J M,
Arkansas Power & Light Co 1p 18862 231 24X
Fiche 50-313,83/06/13,8306160524
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co. of New
York, Inc 115pp, 19021 179 24X Fiche 50-000,83/06/22,8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys
Causing Inoperability of Safety Related Equipment," Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co. of New
York, Inc 120pp, 18997 007 24X Fiche 50-000,83/06/22,8305110477
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions,"
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co. of New
York, Inc 116pp 18996,242 24X Fiche 50-000,83/06/23,8305110479
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate
Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co. of New
York, Inc 116pp 19046,297 24X Fiche 50-000,83/06/24,8305110483

DOCKETED ITEMS

8306300075 Ack receipt of 830427 & 0527 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-315/83-02 & 50-368/83-02
SEIDLE, W C Region 4, Office of Director 83/06/27 GRIFFIN, J M
Arkansas Power & Light Co 1p 19114 247 24X
Fiche 50-315, 83/06/27, 8306300075

--8306300079 Responds to NRC 830513 ltr re violations noted in IE Insp Repts 50-315/83-02 & 50-368/83-02 Corrective actions review of all design change packages, closed out since administrative procedures revised, expected by 830701
MARSHALL, J R Arkansas Power & Light Co 83/05/27 SEIDLE, W C
Region 4, Office of Director 2pp 19114 248 24X
Fiche 50-315, 83/06/27, 8306300075

R Periodic operating reports & related correspondence

8306020081 Monthly operating rept for Mar 1983 W/830428 ltr.
MORTON, K L, MARSHALL, J R Arkansas Power & Light Co 83/04/27
HALLER, N M Office of Resource Management, Director 7pp
18691 216 24X Fiche 50-315, 83/04/27, 8306020081

8306130057 Advises that addl time required to review annual environ operating rept will be submitted by 830531
MARSHALL, J R Arkansas Power & Light Co 83/04/29 COLLINS, J T
Region 4, Office of Director 1p 18824 244. 24X
Fiche 50-315, 83/04/29, 8306130057

8306060253 Submits regulatory response & commitment control program fourth monthly progress rept Review of priority assignment scheme completed Next status rept will be sent by 830614
MARSHALL, J R Arkansas Power & Light Co 83/05/13 COLLINS, J T
Region 4, Office of Director 3pp 18727 226 24X
Fiche 50-315, 83/05/13, 8306060253

8306160561 Monthly operating rept for Apr 1983 W/830516 ltr
MARSHALL, J R, MORTON, K V Arkansas Power & Light Co 83/05/15
BASSETT, H B Division of Data Automation & Management Information 7pp 18865 128 24X Fiche 50-315, 83/05/15, 8306160561

8306210125 Forwards 1982 annual environ monitoring rept w/o encl.
MARSHALL, J R Arkansas Power & Light Co 83/06/03 COLLINS, J T
Region 4, Office of Director 1p 18918 133 24X
Fiche 50-315, 83/06/03, 8306210125

S. Reportable occurrences, LERs & related correspondence

8306130409 NPDES noncompliance notification on 830406, during routine surveillance of oily water separator, light oil film discovered being discharged from Outfall 003 Caused by leak from feedwater pump lube oil sys Bldg oil sumps cleaned
GRIFFIN, J Arkansas Power & Light Co 83/04/20 COLLINS, J T
Region 4, Office of Director 3pp 18823 240. 24X
Fiche 50-315, 83/04/20, 8306130409

8306160469 LER 83-012/03L-0 on 830519, w/plant heatup/startup in progress, auxiliary feedwater pump P-75 outboard mechanical seal failed Cause unknown Seal rebuilt & reinstalled
W/830609 ltr
MOEGENBERG, D., MARSHALL, J R Arkansas Power & Light Co 83/06/09
SEIDLE, W C Region 4, Office of Director 2pp 18863 231 24X
Fiche 50-315, 83/06/09, 8306160469

8306160614 LER 83-011/03L-0 on 830524, while performing annual surveillance on electric driven emergency feedwater pump P-7B, outboard thrust bearing temp observed to be high Caused by excessive thrust bearing clearance. W/830609 ltr
MOEGENBERG, D., MARSHALL, J R Arkansas Power & Light Co 83/06/09
SEIDLE, W C Region 4, Office of Director 3pp 18866 140. 24X
Fiche 50-315, 83/06/09, 8306160614

8306160317 PNO-IV-83-020A, on 830609, reactor tripped. Cause undetermined Trip breaker AKRA failed to close due to personnel failure to follow procedure Closing procedure revised & operations personnel trained.
HUNNICUTT, D. M., CALLAM, L J Region 4, Office of Director 83/06/10
1p 18866 143 24X Fiche 50-315, 83/06/10, 8306160317

8306160644 PNO-IV-83-020 on 830609, unit tripped from 99% power from unknown cause. Reactor will remain in cold shutdown until cause determined. On 830610, two ac-supplied reactor trip breakers failed to close Cause under investigation
HUNNICUTT, D. M., CALLAM, L J Region 4, Office of Director 83/06/10
1p 18866 100. 24X Fiche 50-315, 83/06/10, 8306160644

8306210003 LER 83-013/03L-0 on 830520, while raising steam generator level for wet layup, emergency feedwater pump P-7B indicated flow none...
ed by cavitation at high flows
ged glove W/830610 ltr
sas Power & Light Co 83/06/10
f Director 3pp 18712 285 24X
L

V Operator Examinations

8306220062 Forwards sample questions & answer keys for reactor operator & senior reactor operator requalification exams, per Generic Ltr 82-18 Program beneficial to operator training
MARSHALL, J R Arkansas Power & Light Co 83/06/15 STOLZ, J F
Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 748pp 18730 215 24X Fiche 50-315, 83/06/15, 8306220062

DOCKET 50-315 DONALD C COOK NUCLEAR POWER PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8306100271 Forwards IE Safeguards Insp Repts 50-315/83-06 & 50-316/83-07 on 830411-15 & notice of violation Notice of violation & rept details withheld (ref 10CFR73 21)
MILLER, J R Region 3, Office of Director 83/06/07 DOLAN, J E
American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co 4pp 18806 254 24X Fiche 50-315, 83/06/07, 8306100271

--8306100273 IE Safeguards Insp Repts 50-315/83-06 & 50-316/83-07 on 830411-15 Noncompliance noted agreement w/contractor contains no provisions per security plan & security plan for key control not being followed Safeguards info withheld
CHRISTOFFER, G., BELANGER, J L, CREED, J R Region 3, Office of Director 83/06/06 2pp 18806 256 24X Fiche 50-315, 83/06/07, 8306100271

8306300213 Responds to 820730 ltr re emergency preparedness appraisal rept & 820630 notice of violation Adequate performance demonstrated during 821021 exercise Exam of misrepresentation of facts in progress
KEPPLER, J O Region 3, Office of Director 83/06/09 DOLAN, J E
American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co 3pp 19122 101 24X Fiche 50-315, 83/06/09, 8306300213

8306210057 Ack receipt of 830606 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-315/83-04 & 50-316/83-05
SHAFFER, W D Region 3, Office of Director 83/06/14 DOLAN, J E
American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co 1p 18912 355 24X Fiche 50-315, 83/06/14, 8306210057

--8306210065 Responds to NRC 830506 ltr re violations noted in IE Insp Repts 50-315/83-04 & 50-316/83-05 Corrective actions fire watch established using closed circuit TV 1 h & 20 minutes after identification of missed surveillance
ALEXICH, M P Indiana & Michigan Electric Co 83/06/06
KEPPLER, J O Region 3, Office of Director 3pp 18912 356 24X
Fiche 50-315, 83/06/14, 8306210057

8306210343 Notification of 830623 meeting w/util in Bethesda, MD to discuss App R exemption requests & fire protection safe shutdown analysis
WIGGINTON, D Operating Reactors Branch 1 83/06/16 VARDA, S A
Operating Reactors Branch 1 2pp 18921 299 24X
Fiche 50-315, 83/06/16, 8306210343

8306230333 Forwards response to 830413 ltr re deficiency in approved physical security plan Response withheld
ALEXICH, M P Indiana & Michigan Electric Co 83/06/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 18942 347 24X Fiche 50-315, 83/06/20, 8306230333

P. Operating license stage documents & correspondence

8306020009 Forwards revised Pages 6-23 & 3/4-7 9 for Tech Spec changes re record retention Pages reflect changes made in Amendments 50, 53, 68 & 71
WIGGINTON, D Operating Reactors Branch 1 83/05/13 DOLAN, J
Indiana & Michigan Power Co 2pp 18702 347 24X
Fiche 50-315, 83/05/13, 8306020009

--8306020012 Revised Pages 6-23 & 3/4 7-6 & 7 for Tech Spec changes in Amendments 50, 53, 68 & 71 re records retention
* Operating Reactors Branch 1 83/05/13 App 18702 349. 24X
Fiche 50-315, 83/05/13, 8306020009

8306030290 Forwards addl guidance on acceptable solutions to open item re control of heavy loads in compliance w/NUREG-0612 & draft "Control of Heavy Loads (C-10), Donald C Cook Nuclear Plant Units 1 & 2," technical evaluation rept.
VARDA, S A Operating Reactors Branch 1 83/05/16 DOLAN, J
Indiana & Michigan Electric Co 14pp 18734 086 24X
Fiche 50-315, 83/05/16, 8306030290

--8306030277 Draft "Control of Heavy Loads (C-10), Donald C Cook Nuclear Power Plant Units 1 & 2," technical evaluation rept
VOSBURY, F W Franklin Institute/Franklin Research Center
NRC-03-81-J30 TER-C5506-344/345 DR 83/02/24 CLEMENSON, F NRC
- No Detailed Affiliation Given 33pp 18734 100 24X
Fiche 50-315, 83/05/16, 8306030270

8306020281 Responds to 830510 ltr requesting addl info re status of NUREG-0737, Item II F i Installation of Unit 2 high range containment monitor trending & recording function completed Monitor operational
HUNTER, R S Indiana & Michigan Electric Co 83/05/27 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 18690 315
24X Fiche 50-315, 83/05/27, 8306020281

8306070208 Responds to 830208 Generic Ltr 83-10D on plans & schedule for resolving NUREG-0737, Item II K 3 5 re trip criteria for reactor coolant pumps Util will follow guidance provided by Westinghouse & Westinghouse Owners Group
ALEXICH, M P Indiana & Michigan Electric Co 83/06/02
EISENHUT, D G Division of Licensing 11pp 18747 054 24X
Fiche 50-315, 83/06/02, 8306070208

8306210167 Responds to 830501 ltr re payment of processing fees for 81111 application, revised on 830225, for review of Tech Spec changes Fee encl
ALEXICH, M P Indiana & Michigan Electric Co 83/06/21 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 18915 256
24X Fiche 50-315, 83/06/21, 8306210167

8306270312 Forwards info re reactor vessel level instrumentation sys, in response to Generic Ltr 82-28 concerning inadequate core cooling instrumentation In-core thermocouple sys will be upgraded to NUREG-0737, Item II F 2 requirements
HERINO, R F Indiana & Michigan Electric Co 83/06/22
EISENHUT, D G Division of Licensing 19pp 18993 353 24X
Fiche 50-315, 83/06/22, 8306270312

G Inspection reports, IE Bulletins & correspondence

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc
123pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306130258 Forwards IE Insp Repts 50-315/83-07 & 50-316/83-08 on 830425-29 & 0507 & notice of violation
STREETEER, J F Region 3, Office of Director 83/06/01 DOLAN, J E, American Electric Power Service Corp DOLAN, J E, Indiana & Michigan Electric Co 2pp 18823 306 24X Fiche 50-315, 83/06/01, 8306130258

--8306130263 Notice of violation from insp on 830425-29 & 0507
STREETEER, J F Region 3, Office of Director 83/06/01 2pp.
18823 308 24X Fiche 50-315, 83/06/01, 8306130258

--8306130273 IE Insp Repts 50-315/83-07 & 50-316/83-08 on 830425-29 & 0507 Noncompliance noted incomplete record storage procedures & failure to provide 2-h fire resistant door on records storage vault
CHOWLES, N C, BUTHIN, R N, HAWKINS, F C Region 3, Office of Director 83/05/26 9pp. 18823.310. 24X Fiche 50-315, 83/06/01, 8306130258

8306100271 Forwards IE Safeguards Insp Repts 50-315/83-06 & 50-316/83-07 on 830411-15 & notice of violation Notice of violation & rept details withheld (ref 10CFR73.21).
MILLER, J R Region 3, Office of Director 83/06/07 DOLAN, J E
American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co 4pp 18806 254 24X Fiche 50-315, 83/06/07, 8306100271.

--8306100273 IE Safeguards Insp Repts 50-315/83-06 & 50-316/83-07 on 830411-15. Noncompliance noted agreement w/contractor contains no provisions per security plan & security plan for key control not being followed Safeguards info withheld
CHRISTOFFER, O., BELANGER, J L, CREED, J R Region 3, Office of Director 83/06/06 2pp. 18806 256. 24X Fiche 50-315, 83/06/07, 8306100271.

8305110444 IE Info Notice 83-36, "Impact of Security Practices on B&E Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110444

8306170129 Submits response to IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generator " List of job orders for check valves encl
ALEXICH, M P Indiana & Michigan Electric Co 83/06/09
KEPPLER, J G Region 3, Office of Director 5pp 18878 302. 24X
Fiche 50-315, 83/06/09, 8306170129

8306300213 Responds to 820730 ltr re emergency preparedness appraisal rept & 820630 notice of violation Adequate performance demonstrated during 821021 exercise Exam of misrepresentation of facts in progress
KEPPLER, J G Region 3, Office of Director 83/06/09 DOLAN, J E
American Electric Power Service Corp DOLAN, J E, Indiana & Michigan Electric Co 3pp 19122 101 24X Fiche 50-315, 83/06/09, 8306300213

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 118pp. 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8306210057 Ack receipt of 830606 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-315/83-04 & 50-316/83-05
SHAFER, W D Region 3, Office of Director 83/06/14 DOLAN, J E, American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co 1p 18912 355 24X Fiche 50-315, 83/06/14, 8306210057.

--8306210065 Responds to NRC 830506 ltr re violations noted in IE Insp Repts 50-315/83-04 & 50-316/83-05 Corrective actions
Fire watch established using closed circuit TV 1 h & 20 minutes after identification of missed surveillance
ALEXICH, M P Indiana & Michigan Electric Co. 83/06/06.
KEPPLER, J G Region 3, Office of Director 3pp 18912 356 24X
Fiche 50-315, 83/06/14, 8306210057.

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475.

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Bys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc. 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477.

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions. " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479.

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

R Periodic operating reports & related correspondence

8306020109 Forwards monthly operating rept for Mar 1983 & revised monthly operating rept Feb 1983
SMITH, W O Indiana & Michigan Electric Co 83/04/12 Office of Resource Management, Director 1p. 18691.255. 24X
Fiche 50-315, 83/04/12, 8306020109

--8306020111 Monthly operating rept for Mar 1983
MIGHT, A Indiana & Michigan Electric Co 83/04/12. 6pp
18691.256. 24X Fiche 50-315, 83/04/12, 8306020109

--8306020118 Revised monthly operating rept for Feb 1983
MIGHT, A. Indiana & Michigan Electric Co 83/03/02. 1p.
18691.261. 24X Fiche 50-315, 83/04/12, 8306020109.

DOCKETED ITEMS

B306160343 Forwards monthly operating rept for Apr 1983 & revised monthly operating rept for Mar 1983 correcting error in cumulative value for item 17, gross electrical energy generated (MMH).
SMITH, W. O. Indiana & Michigan Electric Co. 83/05/11 Office of
Resource Management, Director Ip 18859 232 24X
Fiche 50-315, 83/05/11, B306160343

--B306160358 Revised monthly operating rept for Mar 1983.
SMITH, W. O. Indiana & Michigan Electric Co. 83/04/12 Ip
18859 233 24X Fiche 50-315, 83/05/11, B306160343

--B306160367 Monthly operating rept for Apr 1983
TETZLAFF, A. L. Indiana & Michigan Electric Co. 83/05/04 7pp
18859 234. 24X Fiche 50-315, 83/05/11, B306160343.

B. Reportable occurrences, LERs & related correspondence

B306060183 Forwards LERs 83-039/03L-0 & 83-040/03L-0
SMITH, W. O. Indiana & Michigan Electric Co. 83/05/27 KEPPNER, J. O
Region 3, Office of Director Ip 18728 192 24X
Fiche 50-315, 83/05/27, B306060183

--B306060185 LER 83-039/03L-0 on 830427, during 609 turbine bldg sprinkler
sys isolation, gate on isolation valve FP322 failed. Cause
not stated Continuous fire watches posted. Valve yoke
replaced.
CARTEAUX, P. Indiana & Michigan Electric Co. 83/05/27 Region
3, Office of Director Ip 18728 193 24X Fiche 50-315, 83/05/27,
B306060183.

--B306060186 LER 83-040/03L-0 on 830504, primary & secondary temp
instrument trains for meteorological instrumentation found
out of spec Caused by inability to calibr temp processor
for secondary instrument train Train recalibr.
PALMER, R. A. Indiana & Michigan Electric Co. 83/05/27 Region
3, Office of Director Ip. 18728 194 24X Fiche: 50-315, 83/05/27,
B306060183

B306210128 Forwards LERs 83-041/03L-0 & 83-042/03L-0.
SMITH, W. O. Indiana & Michigan Electric Co. 83/06/06 KEPPNER, J. O
Region 3, Office of Director Ip. 18915 153 24X
Fiche 50-315, 83/06/06, B306210128

--B306210134 LER 83-041/03L-0 on 830509, during surveillance test on
automatic load sequence timing relays, two relay timers
found to exceed Tech Spec tolerance Caused by instrument
drift. Relay timers will be replaced
PALMER, R. A. Indiana & Michigan Electric Co. 83/06/06 Region
3, Office of Director Ip. 18915 151. 24X Fiche: 50-315, 83/06/06,
B306210128.

--B306210142 LER 83-042/03L-0 on 830512, during surveillance test on
pressurizer pressure protection set III, high pressure
reactor trip bistable would not trip. Caused by defective
high pressure reactor trip bistable Bistable replaced.
PALMER, R. A. Indiana & Michigan Electric Co. 83/06/06 Region
3, Office of Director Ip 18915 152 24X Fiche 50-315, 83/06/06,
B306210128

B306210038 LER 83-047/01T-0 on 830525, during audit, discovered testing
of steam generator stop valve not performed during B30327
startup. Caused by ambiguous due dates on status upgrade
sheets Lists reviewed & dates clarified. W/830608 ltr
STEPHENS, T. R., SMITH, W. O. Indiana & Michigan Electric Co. 83/06/08
KEPPNER, J. O. Region 3, Office of Director. 3pp. 18912 301. 24X
Fiche: 50-315, 83/06/08, B306210038

B306210259 Forwards LERs 83-043/03L-0, 83-044/03L-0, 83-045/03L-0 &
83-046/03L-0
SMITH, W. O. Indiana & Michigan Electric Co. 83/06/08 KEPPNER, J. O.
Region 3, Office of Director. Ip 18915 041. 24X
Fiche. 50-315, 83/06/08, B306210259.

--B306210267 LER 83-043/03L-0 on 830513, control room emergency
pressurization charcoal filter fire/trouble alarm received.
Caused by high resistance settings for prealarm & alarm
Alarm settings adjusted to proper values.
PALMER, R. A. Indiana & Michigan Electric Co. 83/06/08 Region
3, Office of Director. Ip. 18915 042. 24X Fiche 50-315, 83/06/08,
B306210259.

--B306210273 LER 83-044/03L-0 on 830515, containment sump flow monitoring
recorder 1-C8-001 chart paper did not advance Caused by
ripped holes in paper Chart paper realigned on drive wheel.
PALMER, R. A. Indiana & Michigan Electric Co. 83/06/08 Region
3, Office of Director. Ip. 18915 043. 24X Fiche: 50-315, 83/06/08,
B306210259.

--B306210279 LER 83-045/03L-0 on 830519, fire Door 519 would not latch
Cause not stated Strike plate replaced & door closer
mechanism adjusted
ROBINSON, D. Indiana & Michigan Electric Co. 83/06/08 Region
3, Office of Director Ip 18915 041 24X Fiche 50-315, 83/06/08,
B306210259

--B306210284 LER 83-046/03L-0 on 830511, east centrifugal charging pump
600-volt breaker miniflow valve found open Cause not
determined Shiftly valve insps initiated Corrective actions
not planned.
MURPHY, C. E. Indiana & Michigan Electric Co. 83/06/08 Region
3, Office of Director 2pp 18915 045 24X Fiche 50-315,
83/06/08, B306210259

B306270433 Forwards LERs 83-048/03L-0, 83-049/03L-0 & 83-050/03L-0
SMITH, W. O. Indiana & Michigan Electric Co. 83/06/16 KEPPNER, J. O
Region 3, Office of Director Ip 18992 052 24X
Fiche. 50-315, 83/06/16, B306270433

--B306270436 LER 83-048/03L-0 on 830518, security guard discovered diesel
room CD cardox sys isolated w/no names on entry board & no
personnel in room Caused by technician error Need for full
compliance w/fire protection rules emphasized
PALMER, R. A. Indiana & Michigan Electric Co. 83/06/16 Region
3, Office of Director Ip 18992 053 24X Fiche 50-315, 83/06/16,
B306270433

--B306270444 LER 83-049/03L-0 on 830520, review of surveillance log
revealed containment air lock 3-day door tests not performed
in required time Caused by lack of understanding Test
responsibility assigned to one individual
PALMER, R. A., SMITH, W. O. Indiana & Michigan Electric Co. 83/06/16
Region 3, Office of Director 2pp 18992 054 24X
Fiche 50-315, 83/06/16, B306270433

--B306270449 LER 83-050/03L-0 on 830523, five 4-kV bus degraded voltage
relays 27-T11A-1 & 2 & 27-T11D-1, 2 & 3, found to have
exceeded tolerance Caused by instrument drift Diesel
generator load shedding relays readjusted
PALMER, R. A. Indiana & Michigan Electric Co. 83/06/16 Region
3, Office of Director Ip 18992 056 24X Fiche 50-315, 83/06/16,
B306270433

B306300035 RD on 830612, performance of Train B boron injection tank
inlet piping heat trace circuitry questioned, but train not
declared inoperable until 830616 Investigation underway.
SMITH, W. O. Indiana & Michigan Electric Co. 83/06/17 KEPPNER, J. O
Region 3, Office of Director Ip 19121 001 24X
Fiche 50-315, 83/06/17, B306300035

DOCKET 50-316 DONALD C. COOK NUCLEAR POWER PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

B306100271 Forwards IE Safeguards Insp Repts 50-315/83-06 &
50-316/83-07 on 830411-15 & notice of violation Notice of
violation & rept details withheld (ref 10CFR73 21).
MILLER, J. R. Region 3, Office of Director 83/06/07 DOLAN, J. E
American Electric Power Service Corp 4pp 18806 254 24X
Fiche 50-315, 83/06/07, B306100271.

--B306100273 IE Safeguards Insp Repts 50-315/83-06 & 50-316/83-07 on
830411-15 Noncompliance noted agreement w/contractor
contains no provisions per security plan & security plan for
key control not being followed. Safeguards info withheld
CHRISTOFFER, O. Region 3, Office of Director. 83/06/06 2pp
18806 256 24X Fiche 50-315, 83/06/07, B306100271

B306300213 Responds to B20730 ltr re emergency preparedness appraisal
rept & B20630 notice of violation. Adequate performance
demonstrated during B21021 exercise. Exam of
misrepresentation of facts in progress.
KEPPNER, J. O. Region 3, Office of Director. 83/06/07 DOLAN, J. E
Electric Power Service Corp 3pp 19122 101 24X
Fiche. 50-315, 83/06/07, B306300213

B306210057 Ack receipt of B30606 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-315/83-04 &
50-316/83-05.
SHAFFER, W. D. Region 3, Office of Director. 83/06/14 DOLAN, J. E
Electric Power Service Corp Ip 18912 355 24X
Fiche. 50-315, 83/06/14, B306210057

--B306210065 Responds to NRC B30506 ltr re violations noted in IE Insp
Repts 50-315/83-04 & 50-316/83-05. Corrective actions
fire watch established using closed circuit TV 1 h & 20
minutes after identification of missed surveillance.
ALEXICH, M. P. Indiana & Michigan Electric Co. 83/06/06
KEPPNER, J. O. Region 3, Office of Director. 3pp. 18912 356 24X
Fiche 50-315, 83/06/14, B306210057

DOCKETED ITEMS

141

8306210343 Notification of 830623 meeting w/utill in Bethesda, MD to discuss App R exemption requests & fire protection safe shutdown analysis
WIGGINTON, D Operating Reactors Branch 1 83/06/16 VARGA, S A
Operating Reactors Branch 1 2pp 15/21 299 24X
Fiche 50-315, 83/06/16, 8306210343

8306230333 Forwards response to 830413 ltr re deficiency in approved physical security plan Response withheld
ALEXICH, M P Indiana & Michigan Electric Co 83/06/20 DENTON, H H
Office of Nuclear Reactor Regulation, Director 1p 18942 347
24X Fiche 50-315, 83/06/20, 8306230333

P Operating license stage documents & correspondence

8306020009 Forwards revised Pages 6-23 & 3/4-7 9 for Tech Spec changes re record retention Pages reflect changes made in Amends
50, 53, 68 & 71
WIGGINTON, D Operating Reactors Branch 1 83/05/13 DOLAN, J
Indiana & Michigan Power Co 2pp 18/02 347 24X
Fiche 50-315, 83/05/13, 8306020009

--8306020012 Revised Pages 6-23 & 3/4 7-6 & 7 for Tech Spec changes made in Amends 50, 53, 68 & 71 re records retention
* Operating Reactors Branch 1 83/05/13 4pp 1870P 349 24X
Fiche 50-315, 83/05/13, 8306020009

8306030290 Forwards addl guidance on acceptable solutions to open items re control of heavy loads in compliance w/NUREG-0612 &
draft "Control of Heavy Loads (C-10), Donald C Cook Nuclear
Plant Units 1 & 2," technical evaluation rept
VARGA, S A Operating Reactors Branch 1 83/05/16 DOLAN, J
Indiana & Michigan Electric Co 14pp 18/34 086 24X
Fiche 50-315, 83/05/16, 8306030290

--8306030297 Draft "Control of Heavy Loads (C-10), Donald C Cook Nuclear
Power Plant Units 1 & 2," technical evaluation rept
VOSJURY, F W Franklin Institute/Franklin Research Center
NRC-03-B1-130 TER-C5506-344/345 DR 83/02/24 CLEMENSON, R NRC
- No Detailed Affiliation Given 33pp 18734 100 24X
Fiche 50-315, 83/05/16, 8306030290

8306020281 Responds to 830510 ltr requesting addl info re status of
NUREG-0737, Item II F 1 Installation of Unit 2 high range
containment monitor trending & recording function completed
Monitor operational
HUNTER, R S Indiana & Michigan Electric Co 83/05/27 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 18670 315
24X Fiche 50-315, 83/05/27, 8306020281

8306070208 Responds to 830208 Generic Ltr 83-10B on plans & schedule
for resolving NUREG-0737, Item II K 3 5 re trip criteria for
reactor coolant pumps Util will follow guidance provided by
Westinghouse & Westinghouse Owners Group
ALEXICH, M P Indiana & Michigan Electric Co 83/06/02
EISENHUT, D G Division of Licensing 11pp 18747 054 24X
Fiche 50-315, 83/06/02, 8306070208

830621016/ Responds to 830501 ltr re payment of processing fees for
Billis application, revised on 830225, for review of Tech
Spec changes Fee encl
ALEXICH, M P Indiana & Michigan Electric Co 83/06/21 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 18915 256
24X Fiche 50-315, 83/06/21, 830621016/

8306270312 Forwards info re reactor vessel level instrumentation sys,
in response to Generic Ltr 82-28 concerning inadequate core
cooling instrumentation In-core thermocouple sys will be
upgraded to NUREG-0737, Item II F 2 requirements
HERING, R F Indiana & Michigan Electric Co 83/06/22
EISENHUT, D G Division of Licensing 19pp 18973 353 24X
Fiche 50-315, 83/06/22, 8306270312

0 Inspection reports, IE Bulletins & correspondence

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in
Well Logging Device " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post
830103) 83/05/26 Consolidated Edison Co of New York, Inc
125pp 18831 043, 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet,"
Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New
York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods
Withdrawn at BWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/31, Consolidated Edison Co of New
York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306130298 Forwards IE Insp Repts 50-315/83-07 & 50-316/83-08 on
830425-29 & 0509 & notice of violation
STREETER, J F Region 3, Office of Director 83/06/01 DOLAN, J E
American Electric Power Service Corp DOLAN, J E Indiana & Michigan
Electric Co 2pp 18823 306 24X Fiche 50-315, 83/06/01, 8306130298

--8306130263 Notice of violation from insp on 830425-29 & 0509
STREETER, J F Region 3, Office of Director 83/06/01 2pp
18823 308 24X Fiche 50-315, 83/06/01, 8306130298

--8306130273 IE Insp Repts 50-315/83-07 & 50-316/83-08 on 830425-29 &
0509 Noncompliance noted incomplete record storage
procedures & failure to provide 2-h fire resistant door on
records storage vault
CHODLES, N C, BUTHIN, R N, HAWKINS, F G Region 3, Office of
Director 83/05/26 9pp 18823 310 24X Fiche 50-315, 83/06/01,
8306130298

8306100271 Forwards IE Safeguards Insp Repts 50-315/83-06 &
50-316/83-07 on 830411-15 & notice of violation Notice of
violation & rept details withheld (ref 10CFR73 21)
MILLER, J R Region 3, Office of Director 83/06/07 DOLAN, J E
American Electric Power Service Corp DOLAN, J E Indiana & Michigan
Electric Co 4pp 18806 254 24X Fiche 50-315, 83/06/07, 8306100271.

--8306100273 IE Safeguards Insp Repts 50-315/83-06 & 50-316/83-07 on
830411-15 Noncompliance noted agreement w/contractor
contains no provisions per security plan & security plan for
key control not being followed Safeguards info withheld
CHRISTOFFER, O, BELANGER, J L, CREED, J R Region 3, Office of
Director 83/06/06 2pp 18806 256 24X Fiche 50-315, 83/06/07,
8306100271

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe
Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/09 Consolidated Edison Co of New
York, Inc 117pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8306170129 Submits response to IE Bulletin 83-03, "Check Valve Failures
in Raw Water Cooling Bys of Diesel Generator " List of job
orders for check valves encl
ALEXICH, M P Indiana & Michigan Electric Co 83/06/09
KEPPLER, J G Region 3, Office of Director 5pp 18878 302, 24X
Fiche 50-315, 83/06/09, 8306170129

8306300213 Responds to 820730 ltr re emergency preparedness appraisal
rept & 820630 notice of violation Adequate performance
demonstrated during 821021 exercise Exam of
misrepresentation of facts in progress
KEPPLER, J G Region 3, Office of Director 83/06/09, DOLAN, J E
American Electric Power Service Corp DOLAN, J E Indiana & Michigan
Electric Co 3pp 19122 101 24X Fiche 50-315, 83/06/09, 8306300213

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive &
Seismically Induced Chatter in Relays Within Printed
Circuit Cards " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New
York, Inc 110pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From
Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New
York, Inc 243pp 18921 001, 24X Fiche 50-000, 83/06/13, 8306090010

8306210057 Ack receipt of 830606 ltr informing NRC of steps taken to
correct violations noted in IF Insp Repts 50-315/83-04 &
50-316/83-05
SHAFFER, W D Region 3, Office of Director 83/06/14 DOLAN, J E,
American Electric Power Service Corp DOLAN, J E Indiana & Michigan
Electric Co 1p 18912 355, 24X Fiche 50-315, 83/06/14, 8306210057.

--8306210065 Responds to NRC 830506 ltr re violations noted in IE Insp
Repts 50-315/83-04 & 50-316/83-05 Corrective actions
Fire watch established using closed circuit TV 1 h & 20
minutes after identification of missed surveillance.
ALEXICH, M P Indiana & Michigan Electric Co 83/06/06,
KEPPLER, J G Region 3, Office of Director 3pp 18912 356 24X
Fiche 50-315, 83/06/14, 8306210057

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
Epoxy Grouts & Sealers " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New
York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475.

DOCKETED ITEMS

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18977 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co. of New York, Inc. 116pp 18976-242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc. 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

R Periodic operating reports & related correspondence

8306020186 Monthly operating rept for Mar 1983 W/830412 ltr
MIGHT, A., LEASE, R. S., SVENSSON, B. A. Indiana & Michigan Electric Co 83/04/12 8pp. 18690 245 24X Fiche 50-316, 83/04/12, 8306020186

8306160384 Monthly operating rept for Apr 1983 W/830511 ltr
TETZLAFF, A. L., SMITH, W. O. Indiana & Michigan Electric Co 83/05/04
Office of Resource Management, Director 7pp 18859, 280 24X
Fiche 50-316, 83/05/04, 8306160384

S Reportable occurrences, LERs & related correspondence

8306060183 Forwards LERs 83-039/03L-0 & 83-040/03L-0
SMITH, W. O. Indiana & Michigan Electric Co 83/05/27 KEPLER, J. O.
Region 3, Office of Director 1p 18728 192 24X
Fiche 50-316, 83/05/27, 8306060183

--8306060186 LER 83-040/03L-0 on 830504, primary & secondary temp instrument trains for meteorological instrumentation found out of spec. Caused by inability to calibr temp processor for secondary instrument train. Train recalibr.
PALMER, R. A. Indiana & Michigan Electric Co 83/05/27, Region 3, Office of Director 1p 18728 194 24X Fiche 50-316, 83/05/27, 8306060183

8306060269 Forwards LERs 83-046/03L-0 & 83-047/03L-0.
SMITH, W. O. Indiana & Michigan Electric Co 83/05/27 KEPLER, J. O.
Region 3, Office of Director 1p 18730 020 24X
Fiche 50-316, 83/05/27, 8306060269

--8306060271 LER 83-047/03L-0 on 830503, during surveillance test on solid state protection sys train B, logic test position tested unsatisfactorily, affecting power range high flux rate trip. Caused by failed logic card A-212 Card replaced.
PALMER, R. A. Indiana & Michigan Electric Co. 83/05/27 Region 3, Office of Director 1p 18730 021 24X Fiche 50-316, 83/05/27, 8306060269

--8306060273 LER 83-046/03L-0 on 830428, N-train battery room pyroalarm detector R-33A alarmed, rendering 633 auxiliary bldg detectors inoperable. Caused by rain leaking through roof shorting out detector Pyroalarm terminal block replaced.
CARTEAUX, P. Indiana & Michigan Electric Co 83/05/27 Region 3, Office of Director 1p. 18730. 022 24X Fiche 50-316, 83/05/27, 8306060269

8306210074 RO on 830603, during operational surveillance test, both containment spray sys made inoperable for approx 15 minutes. Error discovered in independent verification of valve lineup. Immediate action taken to restore spray sys.
TOWNLEY, E. L. Indiana & Michigan Electric Co 83/06/03
KEPLER, J. O. Region 3, Office of Director 1p 18911 362 24X
Fiche 50-316, 83/06/03, 8306210074

8306210325 RO, on 830603, maint personnel discovered gauge had been removed from outside wall of outer airlock door providing vent path from containment to auxiliary bldg when inner airlock door open. Pressure gauge reinstalled.
TOWNLEY, E. L. Indiana & Michigan Electric Co. 83/06/03
KEPLER, J. O. Region 3, Office of Director 1p 18914:035 24X
Fiche 50-316, 83/06/03, 8306210325

8306270158 LER 83-049/01T-0 on 830602, pressure gauge discovered missing from outside wall of outer air lock door in upper containment. Cause under investigation. Pressure gauge replaced. W/830626 ltr.
PALMER, R. A., SMITH, W. O. Indiana & Michigan Electric Co 83/06/16, KEPLER, J. O. Region 3, Office of Director 3pp. 18992 049 24X
Fiche: 50-316, 83/06/16, 8306270158

8306270161 LER 83-048/01T-0 on 830603, operators inadvertently closed manual isolation valve on HX of non-tested train, rendering trains inoperable. Caused by personnel error. Personnel counseled. W/830616 ltr
KRAUSE, D. F., SMITH, W. O. Indiana & Michigan Electric Co 83/06/16
KEPLER, J. O. Region 3, Office of Director 3pp 18992 034 24X
Fiche 50-316, 83/06/16, 8306270161

DOCKET 50-317 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8306070229 Forwards revs to training & qualification plan. Revs withheld (ref 10CFR73 21)
BOWMAKER, N. J. Baltimore Gas & Electric Co 83/02/23 HAYNES, R. C.
Region 1, Office of Director 1p 18/46 111 24X
Fiche 50-317, 83/02/23, 8306070229

8306010477 Informs that NUREG-0737, Item III A 2 i, "Emergency Preparedness, Upgrade Emergency Plans to App E, 10CFR50," completed. Item closed.
CLARK, R. A. Operating Reactors Branch 3 83/05/11 LUNDVALL, A. C.
Baltimore Gas & Electric Co 3pp 18688 359 24X
Fiche 50-317, 83/05/11, 8306010477

8306150082 Releases public version of revised emergency plan implementing procedure
FELTON, J. M. Division of Rules and Records 83/06/01 Document
Management Branch 1p 18871 169 24X Fiche 50-317, 83/06/01, 8306150082

--8306150086 Public version of Rev 10 to Emergency Plan Implementing Procedure ERPIP 4 1 17, "Security Team " W/830519 ltr & receipt form
RUSSELL, L. B. Baltimore Gas & Electric Co 83/05/11 12pp
18871 170 24X Fiche 50-317, 83/06/01, 8306150082

8306270195 Rev 2 to Emergency Response Plan Implementing Procedure ERPIP 4 4 7 6, "Post-Accident Sampling Sys & Analysis "
RUSSELL, J. B. Baltimore Gas & Electric Co 83/06/01 37pp
18991 287 24X Fiche 50-317, 83/06/01, 8306270195

8306270164 Rev 9 to Emergency Response Plan Implementing Procedure ERPIP 5 1, "Communications "
RUSSELL, J. B., WALL, O. F. Baltimore Gas & Electric Co 83/06/15
11pp 18988 023 24X Fiche 50-317, 83/06/15, 8306270164

8306280461 Discusses until 830315 response to violations noted in IE Insp Repts 50-317/B2-28 & 50-318/B2-24 & results of 830419 meeting re response to two security violations. Addl info required. Comments withheld (ref 10CFR73 21)
MARTIN, T. I. Division of Engineering & Technical Programs 83/06/22
BOWMAKER, N. J. Baltimore Gas & Electric Co 2pp 19019 183 24X
Fiche 50-317, 83/06/22, 8306280461

--8306280465 Responds to NRC 830216 ltr re violations noted in IE Insp Repts 50-317/B2-28 & 50-318/B2-24 Items 1 & 2 not valid. Violations Details withheld (ref 10CFR73 21)
BOWMAKER, N. J. Baltimore Gas & Electric Co 83/03/15, MARTIN, T. I.
Division of Engineering & Technical Programs 1p 19019 185
24X Fiche: 50-317, 83/06/22, 8306280461

P Operating license stage documents & correspondence

8306060051 Addl response to FOIA request for three categories of documents re PRA of reactor safety study methodology application program repts & interim reliability evaluation program repts. Forwards App A documents. Search continuing.
FELTON, J. M. Division of Rules and Records 83/04/07 SHOLLY, B. C.
Union of Concerned Scientists. 3pp 18752 001 24X
Fiche 50-000, 83/04/07, 8306060051

--8306060061 Statement on background, issues, current status & future action re interim & natl reliability evaluation programs
" NRC - No Detailed Affiliation Given 82/12/31 2pp
18752 059 24X Fiche 50-000, 83/04/07, 8306060051

8306010036 Requests publication in monthly FR of notice of consideration of issuance of amend to DL & proposed no significant hazards determination re onsite organization & snubber surveillance. Encl available in Central Files only.
CLARK, R. A. Operating Reactors Branch 3 83/05/25 Operating
Reactors Branch 3. 2pp 18683 241 24X Fiche, 50-317, 83/05/25, 8306010036

8306070047 Discusses reactor coolant pump seal ability to perform adequately after extended loss of component cooling water, per NUREG-0737, Item II K 3 25 "Effect of Loss of Alternating Current Power on Pump Seals." Item resolution requested. OLSON, R. C. Baltimore Gas & Electric Co. 83/05/25 CLARK, R. A. Operating Reactors Branch 3 2pp 18740 003 24X Fiche 50-317, 83/05/25, 8306070047

8306070156 Forwards response to questions re MacBeth critical heat flux correlation used in Unit 1 Cycle 6 & Unit 2 Cycle 5 steam line break analysis, per 830415 request. LUNDVALL, A. E. Baltimore Gas & Electric Co. 83/05/25 CLARK, R. A. Operating Reactors Branch 3 5pp 19746 217 24X Fiche 50-317, 83/05/25, 8306070156

--8306070197 Forwards section of Idaho Nuclear Corp Rept NY-123-69 re statistical verification of MacBeth correlation. KLING, C. L. Combustion Engineering, Inc. 73/08/01 SALAH, S. Atomic Energy Commission 15pp 18746 222 24X Fiche 50-317, 83/05/25, 8306070197

8306070427 Notification of 830601 meeting w/ util, E&O, ORNL & C-E in Bethesda, MD to review control sys on plant design for resolution of Unresolved Safety Issue A-47 "Safety Implications of Control Sys." SZUKIEWICZ, A. J. Generic Issues Branch 83/05/26 KNIEL, K. Generic Issues Branch 3pp 18780 348 24X Fiche 50-317, 83/05/26, 8306070427

8306060105 Application to amend Licenses DPR-53 & DPR-69, revising Tech Spec Page 3/4 6-17 re operability of containment isolation valves. LUNDVALL, A. E. Baltimore Gas & Electric Co. 83/05/27 CLARK, R. A. Operating Reactors Branch 3 3pp 18719 354 24X Fiche 50-317, 83/05/27, 8306060105

--8306060109 Proposed Tech Spec 3/4 6-19 re operability of containment isolation valves. * Baltimore Gas & Electric Co. 83/05/27 2pp 18719 357 24X Fiche 50-317, 83/05/27, 8306060109

8306070426 Forwards safety evaluation & technical evaluation rept, "Control of Heavy Loads." Guidelines of NUREG-0612 satisfied. CLARK, R. A. Operating Reactors Branch 3 83/05/27 LUNDVALL, A. E. Baltimore Gas & Electric Co. 2pp 18809 107 24X Fiche 50-317, 83/05/27, 8306070426

--8306070492 Safety evaluation accepting util response to "Control of Heavy Loads Phase I." Item resolved. * NRC - No Detailed Affiliation Given 83/05/27 2pp 18809 109 24X Fiche 50-317, 83/05/27, 8306070492

--8306030310 "Control of Heavy Loads (C-10) Calvert Cliffs Nuclear Power Plants Units 1 & 2," technical evaluation rept. BOHMERGER, C. Franklin Institute/Franklin Research Center. NRC-03-81-120 TER-C5506-342 83/05/31 CLEMENSON, F. NRC - No Detailed Affiliation Given 28pp 18809 111 24X Fiche 50-317, 83/05/27, 8306070492

8306290194 Forwards FR notice of consideration of issuance of amend to License DPR-53 & opportunity for prior hearing re 830307 application for revised limiting conditions for operation concerning containment tendons. CLARK, R. A. Operating Reactors Branch 3 83/06/07 LUNDVALL, A. E. Baltimore Gas & Electric Co. 3pp 19046 290 24X Fiche 50-317, 83/06/07, 8306290194

--8306290202 Notice of consideration of issuance of amend to License DPR-35 & opportunity for prior hearing re containment tendons. CLARK, R. A. Operating Reactors Branch 3 83/06/07 4pp 19046 293 24X Fiche 50-317, 83/06/07, 8306290194

Q Inspection reports, IE Bulletins & correspondence

8306010318 Forwards IE Insp Repts 50-317/83-11 & 50-318/83-11 on 830412-0510 & notice of violation. STARDRECK, J. R. Division of Project & Resident Programs. 83/05/16 LUNDVALL, A. E. Baltimore Gas & Electric Co. 2pp 18682 249 24X Fiche 50-317, 83/05/16, 8306010318

--8306010320 Notice of violation from insp on 830412-0510. * Region 1, Office of Director 83/05/16, 2pp, 18682, 251 24X Fiche 50-317, 83/05/16, 8306010318

--8306010324 IE Insp Repts 50-317/83-11 & 50-318/83-11 on 830412-0510. Noncompliance noted failure to procedurally require HEPA filter surveillance following fire & failure to perform required effluent sampling. ARCHITZEL, R. E., TRIMBLE, D. C., MCCABE, E. C. Region 1, Office of Director 83/05/16 15pp 18682 253 24X Fiche 50-317, 83/05/16, 8306010318

8306020402 Forwards IE Insp Repts 50-317/83-08 & 50-318/83-08 on 830404-08 & notice of violation. MARTIN, T. T. Division of Engineering & Technical Programs 83/05/20 LUNDVALL, A. E. Baltimore Gas & Electric Co. 3pp 18695 038 24X Fiche 50-317, 83/05/20, 8306020402

--8306020404 Notice of violation from insp on 830404-08. * Region 1, Office of Director 83/05/20 2pp 18695 041 24X Fiche 50-317, 83/05/20, 8306020402

--8306020407 IE Insp Repts 50-317/83-08 & 50-318/83-08 on 830404-08. Noncompliance noted failure to follow procedures re effluent sample confirmatory measurements & re records & repts in plant chemistry & radiochemistry areas. KOTTAN, J. J., JANG, J. C., PASCIAK, W. J. Region 1, Office of Director 83/05/17 8pp 18695 043 24X Fiche 50-317, 83/05/20, 8306020402

8306060371 Advises that 830517 submittal on main steam line break analysis will be reviewed per IE Bulletin 80-04, "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition." Importance of review of bulletin stressed. CLARK, R. A. Operating Reactors Branch 3 83/05/23 LUNDVALL, A. E. Baltimore Gas & Electric Co. 2pp 18750 336 24X Fiche 50-317, 83/05/23, 8306060371

8306070140 Forwards IE Insp Repts 50-317/83-10 & 50-318/83-10 on 830411-15 No noncompliance noted. MARTIN, T. T. Division of Engineering & Technical Programs 83/05/24 LUNDVALL, A. E. Baltimore Gas & Electric Co. 2pp 18739 233 24X Fiche 50-317, 83/05/24, 8306070140

--8306070146 IE Insp Repts 50-317/83-10 & 50-318/83-10 on 830411-15 No noncompliance noted. Major areas inspected: licensee actions on previous insp findings, audit program, organization & QC & surveillance program review. MEYER, O., PRELL, J. Region 1, Office of Director. CAPTON, D. L. Division of Engineering & Technical Programs 83/05/11 8pp 18739 235 24X Fiche 50-317, 83/05/24, 8306070140

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device." Svc list encl. TAYLOR, J. M. Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc. 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc. 115pp 18732 089 24X Fiche 50-000, 83/05/26, 8305110460

8305110461 IE Info Notice 83-38, "Fuel Movement W/Control Rods Withdrawn at DWRs." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc. 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306210121 Forwards responses to IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators." Check valves only verified tested in reverse direction. Only one valve failure identified in 16 yrs of operation. LUNDVALL, A. E. Baltimore Gas & Electric Co. 83/06/07 ALLAN, J. M. Region 1, Office of Director. 4pp 18714 174 24X Fiche 50-317, 83/06/07, 8306210121

8306130001 Forwards main steam line break final containment response analysis re IE Bulletin 80-04 & results of statistical evaluation performed for strengthened mats used in containment. LUNDVALL, A. E. Baltimore Gas & Electric Co. 83/06/08 CLARK, R. A. Operating Reactors Branch 3 13pp 18924 250 24X Fiche 50-317, 83/06/08, 8306130001

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/09 Consolidated Edison Co. of New York, Inc. 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8306230383 Forwards IE Insp Repts 50-317/83-12 & 50-318/83-12 on 830509-13 No noncompliance noted. MARTIN, T. T. Division of Engineering & Technical Programs 83/06/09 LUNDVALL, A. E. Baltimore Gas & Electric Co. 2pp 18944 136 24X Fiche 50-317, 83/06/09, 8306230383

DOCKETED ITEMS

--B306230388 IE Insp Repts 50-317/83-12 & 50-318/83-12 on B30509-13 No noncompliance noted Major areas inspected Followup on previously identified insp items, radioactive matl transport & QA audits of radioactive matl transport
COLLINS, D J, SHANBAKY, M M Region 1, Office of Director
B3/06/07 3pp 18944 138 24X Fiche 50-317, B3/06/09, B306230383

B305110470 IE Info Notice B3-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B3/06/13 Consolidated Edison Co. of New York, Inc 118pp 18920 225 24X Fiche 50-000, B3/06/13, B305110470

B306090010 IE Info Notice B3-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B3/06/13 Consolidated Edison Co. of New York, Inc 243pp 18921 001 24X Fiche 50-000, B3/06/13, B306090010

B306160323 Ack receipt of B30420 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/83-03 & 50-318/83-03
MARTIN, T T Division of Engineering & Technical Programs B3/06/14
LUNDVALL, A E Baltimore Gas & Electric Co 2pp 18860 056 24X Fiche 50-317, B3/06/14, B306160323

--B306160330 Responds to NRC B30322 ltr re violations noted in IE Insp Repts 50-317/83-03 & 50-318/83-03 Corrective actions
aperture card reader reproducing capability disabled, foreign print ing revised & new QA procedure proposed
LUNDVALL, A E Baltimore Gas & Electric Co B3/04/20 MARTIN, T T Division of Engineering & Technical Programs 2pp 18960 058 24X Fiche 50-317, B3/06/14, B306160323

B305110475 IE Info Notice B3-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B3/06/22 Consolidated Edison Co. of New York, Inc 118pp 19021 179 24X Fiche 50-000, B3/06/22, B305110475

B305110477 IE Info Notice B3-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B3/06/22 Consolidated Edison Co. of New York, Inc 120pp 18997 007 24X Fiche 50-000, B3/06/22, B305110477

B306280461 Discusses until B30315 response to violations noted in IE Insp Repts 50-317/82-28 & 50-318/82-24 & results of B30419 meeting re response to two security violations Addl info required Comments withheld (ref 10CFR73.21)
MARTIN, T T Division of Engineering & Technical Programs B3/06/22
BOHMAKER, N J Baltimore Gas & Electric Co 2pp 19019 183 24X Fiche 50-317, B3/06/22, B306280461

--B306280465 Responds to NRC B30216 ltr re violations noted in IE Insp Repts 50-317/82-28 & 50-318/82-24 Items 1 & 2 not valid violations Details withheld (ref 10CFR73.21)
BOHMAKER, N J Baltimore Gas & Electric Co B3/03/15 MARTIN, T T Division of Engineering & Technical Programs 1p 19019 185 24X Fiche 50-317, B3/06/22, B306280461

B305110479 IE Info Notice B3-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B3/06/23 Consolidated Edison Co. of New York, Inc 118pp 18996 242 24X Fiche 50-000, B3/06/23, B305110479

B305110483 IE Info Notice B3-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B3/06/24 Consolidated Edison Co. of New York, Inc 118pp 19046 297 24X Fiche 50-000, B3/06/24, B305110483

R Periodic operating reports & related correspondence

B306170018 Monthly operating repts for May 1983 W/B30614 ltr
LOTITO, E M Baltimore Gas & Electric Co B3/06/14 Director's Office, Office of Inspection and Enforcement 11pp 18882 259 24X Fiche 50-317, B3/06/14, B306170018

S Reportable occurrences, LERs & related correspondence

B306160081 Responds to FOIA request for eight categories of records re certain sys in C-E designed nuclear power plants, Forwards App A documents identified in Categories 5 & 6 Category B document not located, Remaining documents filed in NRR
FELTON, J M, Division of Rules and Records B3/04/19 BELL, N Coalition for Safe Power App 18893 204 24X Fiche 50-317, B3/04/19, B306160081

--B306160083 Submits daily highlight re diesel generator failures at Facility on B20603 Incident caused by paralleling of diesel generators w/buses powered from offsite source licensee investigating incident
JAFFE, D H Operating Reactors Branch 3 B2/06/04 DENTON, H R, CARTER, J, EISENHUT, D G NRC - No Detailed Affiliation Given 1p 18894 229 24X Fiche 50-317, B3/04/19, B306160081

B306010264 Updated LER B3-009/03X-2 on B20210, discovered snubber 2-15-10 not included in Tech Spec & surveillance missed on snubber 1-15-B Caused by snubber being incorrectly tagged
Snubber will be correctly tagged
FARRELL, E V, RUSSELL, L B Baltimore Gas & Electric Co B3/05/12
ALLAN, J M Region 1, Office of Director 3pp 18672 252 24X Fiche 50-317, B3/05/12, B306010264

B306010277 LER B3-017/03L-0 on B30418, ESI actuation sys Cabinet 2D deenergized in order to replace failed isolation module
Isolator for BL steam generator isolation signal logic module replaced & cabinet reenergized W/B30512 ltr
LAOIEWSKI, J S, BASSO, L F, RUSSELL, L B Baltimore Gas & Electric Co B3/05/12
ALLAN, J M Region 1, Office of Director 2pp 18672 239 24X Fiche 50-317, B3/05/12, B306010277

B306010300 LER B3-015/03L-0 on B30415, plant computer failed, rendering in-core detector monitoring sys inoperable Caused by out-of-step selection of multiple analog inputs to analog control board, resulting in blown power fuse W/B30512 ltr
LAOIEWSKI, J S, RAYNOR, J W, RUSSELL, L B Baltimore Gas & Electric Co B3/05/12
ALLAN, J M Region 1, Office of Director 2pp 18672 182 24X Fiche 50-317, B3/05/12, B306010300

B306070077 LER B3-021/01T-0 on B30429, to address concerns of IE Bulletin B3-04, steam line break event reanalyzed assuming failed open main feed reg valve Operating procedures modified to require manual feed sys trip W/B30512 ltr
BOHMAN, M E, RUSSELL, L B Baltimore Gas & Electric Co B3/05/12
ALLAN, J M Region 1, Office of Director 2pp 18737 359 24X Fiche 50-317, B3/05/12, B306070077

B306010307 LER B3-023/03L-0 on B30419, containment pump (CP) alarm would not clear, rendering sump inoperable per Tech Spec 3.4.6.1
Sump drained until alarm cleared Cause not determined W/B30519 ltr
JUNGE, M A, RAYNOR, J W, RUSSELL, L B Baltimore Gas & Electric Co B3/05/19
ALLAN, J M Region 1, Office of Director 2pp 18672 321 24X Fiche 50-317, B3/05/19, B306010307

B306020423 Updated LER B1-044/03X-1 on B10614, during routine shutdown, MSIV 12 would not shut within required time limit Caused by nonsteel ring binding stem Ring replaced Purchase spec revised W/B30519 ltr
DAVIS, B M, WEIR, S M, RUSSELL, L B Baltimore Gas & Electric Co B3/05/19
ALLAN, J M Region 1, Office of Director 3pp 18693 201 24X Fiche 50-317, B3/05/19, B306020423

B306020433 Updated LER B1-024/03X-1 on B10404, during routine shutdown, MSIV 12 closing time exceeded Tech Spec limit Caused by nonsteel ring binding stem Ring replaced Purchase spec revised W/B30519 ltr
DAVIS, B M, WEIR, F J, RUSSELL, L B Baltimore Gas & Electric Co B3/05/19
ALLAN, J M Region 1, Office of Director 3pp 18693 225 24X Fiche 50-317, B3/05/19, B306020433

B306020467 LER B3-020/03L-0 on B30423, weld leak found in sealing sys for 11A reactor coolant pump located in heat affected zone of weld joining Caused by vibration-induced fatigue Pipe replaced & flanges eliminated W/B30519 ltr
WENDERLICH, R L, CARTWRIGHT, W D, RUSSELL, L B Baltimore Gas & Electric Co B3/05/19
ALLAN, J M Region 1, Office of Director 2pp 18693 292 24X Fiche 50-317, B3/05/19, B306020467

B306020436 RO on B30412, oyster samples collected from Camp Conoy sampling location & analyzed for gamma-emitting radionuclides per Tech Spec requirements Based on average silver activity level in oyster samples, doses insignificant
FUHRMAN, O R Baltimore Gas & Electric Co B3/05/23 Region 1, Office of Director 2pp 18694 102 24X Fiche 50-317, B3/05/23, B306020436

B306200268 NPDES noncompliance notification on B30520, during receipt of load of black aqueous ammonia, storage tank overflowed & 50-100 gallons of ammonia solution entered Outfall 002
Caused by improper attention during chemical transfer
RUSSELL, L B Baltimore Gas & Electric Co B3/05/24
ALLAN, J M Region 1, Office of Director 3pp 18901 060 24X Fiche 50-317, B3/05/24, B306200268

B306170031 LER B3-024/03L-0 on B30427, during startup insp, heat damaged snubber discovered on piping between pressurizer & power operated relief blocking valve Caused by damaged reservoir on snubber 1-64-1 Snubber replaced W/B30525 ltr
PIERINGER, P, JENNINGS, R T, RUSSELL, L B Baltimore Gas & Electric Co B3/05/25
ALLAN, J M Region 1, Office of Director 3pp 18882 233 24X Fiche 50-317, B3/05/25, B306170031

8306210108 Updated LER 83-002/03X-1 on BJ0106, containment sump valve MOV-5462 would not operate caused by excessively worn worm gear. Gear replaced. Frequency of preventive maint will be increased to every refueling outage W/830526 ltr
LAGIEWSKI, J S, UNKLE, T J, RUSSELL, L B Baltimore Gas & Electric Co 83/05/26 ALLAN, J M Region 1, Office of Director Jpp 18914 111 24X Fiche 50-317, 83/05/26, 8306210108

8306170011 LER 83-027/04X-0 on BJ0412, oyster samples collected from Camp Canoy location showed Ag-110m higher than background activity. Caused by natural tendency of oysters to bioconcentrate environ silver W/830607 ltr
BROBST, G E, RUSSELL, L B Baltimore Gas & Electric Co 83/06/02 ALLAN, J M Region 1, Office of Director 2pp 18982 2/3 24X Fiche 50-317, 83/06/02, 8306170011

8306200089 Updated LER 80-046/03X-1 on 800816, containment RMS pump failed, resulting in loss of containment gaseous & particulate radiation monitors. Caused by corrosion & subsequent vane wear/failure due to humidity W/830602 ltr
DAVIS, S M, CARTWRIGHT, W D, RUSSELL, L B Baltimore Gas & Electric Co 83/06/02 ALLAN, J M Region 1, Office of Director Jpp 18903 340 24X Fiche 50-317, 83/06/02, 8306200089

8306200208 Updated LER 82-056/03X-1 on 820907, during normal operation, containment particulate & gaseous RMS sample pump tripped & would not restart. Caused by failure of shaft coupling. Coupling replaced W/830602 ltr
LAGIEWSKI, J S, CARTWRIGHT, W D, RUSSELL, L B Baltimore Gas & Electric Co 83/06/02 ALLAN, J M Region 1, Office of Director 3pp 18903 213 24X Fiche 50-317, 83/06/02, 8306200208

8306280447 LER 83-028/01T-0 on 830527, discovered that both ECCS pump room air coolers out of svc from 830524-25. Caused by failure to realize potential safety significance of coolers prior to isolation for maint W/830608 ltr
WENDERLICH, R L, RUSSELL, L B Baltimore Gas & Electric Co 83/06/08 ALLAN, J M Region 1, Office of Director 2pp 19019 177 24X Fiche 50-317, 83/06/08, 8306280447

8306210086 Updated LER 82-028/03X-1 on 820604, while performing surveillance testing, loss of redundant shutdown cooling loop & operable boration flow path experienced. Caused by improper bus fuses. Proper fuses installed W/830609 ltr
BASCO, L F, RUSSELL, L B Baltimore Gas & Electric Co 83/06/09 ALLAN, J M Region 1, Office of Director 3pp 18914 131 24X Fiche 50-317, 83/06/09, 8306210086

8306210101 Updated LER 79-031/01X-1 on 790731, during Followup testing on EFB actuation sys undervoltage logic circuit A15-volt dc power supplies to undervoltage logic A & B would not respond when signaled W/830609 ltr
BASCO, L F, RUSSELL, L B Baltimore Gas & Electric Co 83/06/09 ALLAN, J M Region 1, Office of Director 3pp 18914 217 24X Fiche 50-317, 83/06/09, 8306210101

V Operator Examinations

8306140714 Extends invitation to attend 830627 meeting in King of Prussia, PA to discuss transfer of licensing function from Bethesda, MD to Region 1 ofc
STAROSTECKI, R Division of Project & Resident Programs 83/06/09 LUNDVALL, A E Baltimore Gas & Electric Co 2pp 18941 294 24X Fiche 50-317, 83/06/09, 8306140714

DOCKET 50-318 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8306070229 Forwards revs to training & qualification plan Revs withheld (ref 10CFR73 P1)
BOWMAKER, N J Baltimore Gas & Electric Co 83/02/23 HAYNES, R C Region 1, Office of Director 1p 18746 111 24X Fiche 50-317, 83/02/23, 8306070229

8306010477 Informs that NUREG-0737, Item 111 A 2 I, "Emergency Preparedness, Upgrade Emergency Plans to App E, 10CFR50," completed. Item closed
CLARK, R A Operating Reactors Branch 3 83/05/11 LUNDVALL, A E Baltimore Gas & Electric Co 3pp 18608 359 24X Fiche 50-317, 83/05/11, 8306010477

8306150082 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/06/01 Document Management Branch 1p 18871 167 24X Fiche 50-317, 83/06/01, 8306150082

--8306150086 Public version of Rev 10 to Emergency Plan Implementing Procedure ERPIP 4 1 17, "Security Team " W/830519 ltr & receipt form
RUSSELL, L B Baltimore Gas & Electric Co 83/05/11 12pp 18871 170 24X Fiche 50-317, 83/06/01, 8306150082

8306270195 Rev 2 to Emergency Response Plan Implementing Procedure ERPIP 4 4 7 6, "Post-Accident Sampling Sys & Analysis"
RUSSELL, J B Baltimore Gas & Electric Co 83/06/01 37pp 18991 287 24X Fiche 50-317, 83/06/01, 8306270195

8306270164 Rev 9 to Emergency Response Plan Implementing Procedure ERPIP 5 1, "Communications"
RUSSELL, J B, WALL, G F Baltimore Gas & Electric Co 83/06/15 11pp 18988 023 24X Fiche 50-317, 83/06/15, 8306270164

8306280461 Discusses until 830315 response to violations noted in IE Insp Repts 80-317/82-28 & 50-318/82-24 & results of 830419 meeting re response to two security violations. Add'l info required. Comments withheld (ref 10CFR73 P1)
MARTIN, T T Division of Engineering & Technical Programs 83/06/22 BOWMAKER, N J Baltimore Gas & Electric Co 2pp 19019 183 24X Fiche 50-317, 83/06/22, 8306280461

--8306280465 Responds to NRC 830216 ltr re violations noted in IE Insp Repts 50-317/82-28 & 50-318/82-24 Items 1 & 2 not valid. Violations Details withheld (ref 10CFR73 P1)
BOWMAKER, N J Baltimore Gas & Electric Co 83/03/15 MARTIN, T T Division of Engineering & Technical Programs 1p 19019 183 24X Fiche 50-317, 83/06/22, 8306280461

P Operating license stage documents & correspondence

8306060051 Add'l response to FOIA request for three categories of documents re PRA of reactor safety study methodology: application program repts & interim reliability evaluation program repts. Forwards App A documents. Search continuing.
FELTON, J M Division of Rules and Records 83/04/07 SHOLLY, S C Union of Concerned Scientists 3pp 18752 001 24X Fiche 50-000, 83/04/07, 8306060051

8306010036 Requests publication in monthly R-R of notice of consideration of issuance of amend to DL & proposed no significant hazards determination re onsite organization & snubber surveillance. Encl available in Central Files only.
CLARK, R A Operating Reactors Branch 3 83/05/25 Operating Reactors Branch 3 2pp 18683 241 24X Fiche 50-317, 83/05/25, 8306010036

8306070047 Discusses reactor coolant pump seal ability to perform adequately after extended loss of component cooling water, per NUREG-0737, Item 111 K 3 25 "Effect of Loss of Alternating Current Power on Pump Seals." Item resolution requested.
OLSON, R C Baltimore Gas & Electric Co 83/05/25 CLARK, R A Operating Reactors Branch 3 2pp 18740 003 24X Fiche 50-317, 83/05/25, 8306070047

8306070156 Forwards response to questions re MacBeth critical heat flux correlation used in Unit 1 Cycle 6 & Unit 2 Cycle 5 steam line break analysis, per 830415 request
LUNDVALL, A E Baltimore Gas & Electric Co 83/05/25 CLARK, R A Operating Reactors Branch 3 5pp 18736 217 24X Fiche 50-317, 83/05/25, 8306070156

8306070427 Notification of 830601 meeting w/Util, EQ&O, ORNL & C-E in Bethesda, MD to review control sys on plant design for resolution of Unresolved Safety Issue A-47 "Safety Implications of Control Sys."
SZUKIEWICZ, A J Generic Issues Branch 83/05/26 KNIEL, K Generic Issues Branch 3pp 18780 348 24X Fiche 50-317, 83/05/26, 8306070427

8306060105 Application to amend Licenses DPR-53 & DPR-69, revising Tech Spec Page 3/4 6-19 re operability of containment isolation valves
LUNDVALL, A E Baltimore Gas & Electric Co 83/05/27 CLARK, R A Operating Reactors Branch 3 3pp 18719 354 24X Fiche 50-317, 83/05/27, 8306060105

--8306060109 Proposed Tech Spec 3/4 6-19 re operability of containment isolation valves
* Baltimore Gas & Electric Co 83/05/27 2pp 18719 357 24X Fiche 50-317, 83/05/27, 8306060109

8306090426 Forwards safety evaluation & technical evaluation rept, "Control of Heavy Loads." Guidelines of NUREG-0612 satisfied
CLARK, R A Operating Reactors Branch 3 83/05/27 LUNDVALL, A E Baltimore Gas & Electric Co 2pp 18809 107 24X Fiche 50-317, 83/05/27, 8306090426

DOCKETED ITEMS

--8306090492 Safety evaluation accepting util response to "Control of Heavy Loads Phase 1" item resolved
* NRC - No Detailed Affiliation Given 83/05/27 2pp
18809 109 24X Fiche 50-317,83/05/27,8306090492

--8306030310 "Control of Heavy Loads (C-10) Calvert Cliffs Nuclear Power Plants Units 1 & 2," technical evaluation rept
BOMBERGER, C Franklin Institute/Franklin Research Center
NRC-03-B1-130 TER-C5906-342 83/05/31 CLEMENSON, F NRC - No Detailed Affiliation Given 28pp. 18809 111 24X
Fiche 50-317,83/05/27,8306090492

G Inspection reports, IE Bulletins & correspondence

8306010318 Forwards IE Insp Repts 50-317/83-11 & 50-318/83-11 on 830412-0510 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 83/05/16
LUNDVALL, A E Baltimore Gas & Electric Co 2pp 18682 249 24X
Fiche 50-317,83/05/16,8306010318

--8306010320 Notice of violation from insp on 830412-0510
* Region 1, Office of Director, 83/05/16 2pp. 18682 251 24X
Fiche 50-317,83/05/16,8306010318

--8306010324 IE Insp Repts 50-317/83-11 & 50-318/83-11 on 830412-0510
Noncompliance noted failure to procedurally require HEPA filter surveillance following fire & failure to perform required effluent sampling
ARCHITZEL, R E, TRIMBLE, D C, MCCABE, E C. Region 1, Office of Director 83/05/16 19pp 18682 250 24X Fiche 50-317,83/05/16,8306010318

8306020402 Forwards IE Insp Repts 50-317/83-08 & 50-318/83-08 on 830404-08 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs 83/05/20
LUNDVALL, A E Baltimore Gas & Electric Co 3pp 18695 038 24X
Fiche 50-317,83/05/20,8306020402

--8306020404 Notice of violation from insp on 830404-08
* Region 1, Office of Director 83/05/20 2pp 18695 041 24X
Fiche 50-317,83/05/20,8306020402

--8306020407 IE Insp Repts 50-317/83-08 & 50-318/83-08 on 830404-08
Noncompliance noted failure to follow procedures re effluent sample confirmatory measurements & re records & repts in plant chemistry & radiochemistry areas
KOTTAN, J J, JANG, J C, PASCIAK, W J Region 1, Office of Director 83/05/17 8pp 18695 043 24X Fiche 50-317,83/05/20,8306020402

8306060371 Advises that 830517 submittal on main steam line break analysis will be reviewed per IE Bulletin 80-04, "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition" Importance of review of bulletin stressed
CLARK, R A Operating Reactors Branch 3 83/05/23 LUNDVALL, A E Baltimore Gas & Electric Co 2pp 18750 336 24X
Fiche 50-317,83/05/23,8306060371

8306070140 Forwards IE Insp Repts 50-317/83-10 & 50-318/83-10 on 830411-15. No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/05/24
LUNDVALL, A E Baltimore Gas & Electric Co 2pp 18739 233 24X
Fiche 50-317,83/05/24,8306070140

--8306070146 IE Insp Repts 50-317/83-10 & 50-318/83-10 on 830411-15 No noncompliance noted Major areas inspected, licensee actions on previous insp findings, audit program, organization & QC & surveillance program review
MEYER, O, PRELL, J. Region 1, Office of Director, CAPTON, D L Division of Engineering & Technical Programs. 83/05/18 8pp 18739 235 24X Fiche 50-317,83/05/24,8306070140

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc. 125pp 18831:043 24X Fiche 50-000,83/05/26,8305110458.

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp. 18732,085 24X Fiche 50-000,83/05/26,8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs," Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc. 116pp. 18732 208 24X Fiche 50-000,83/05/31,8305110461

8306210121 Forwards responses to IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators" Check valves only verified tested in reverse direction Only one valve failure identified in 16 yrs of operation
LUNDVALL, A E Baltimore Gas & Electric Co 83/06/07 ALLAN, J M Region 1, Office of Director 4pp 18914 174 24X
Fiche 50-317,83/06/07,8306210121

8306130001 Forwards main steam line break final containment response analysis re IE Bulletin 80-04 & results of statistical evaluation performed for strengthened molis used in containment
LUNDVALL, A E Baltimore Gas & Electric Co 83/06/08 CLARK, R A Operating Reactors Branch 3 13pp 18924 250 24X
Fiche 50-317,83/06/08,8306130001

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fiche 50-000,83/06/09,8305110464

8306230383 Forwards IE Insp Repts 50-317/83-12 & 50-318/83-12 on 830509-13 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/06/09 LUNDVALL, A E Baltimore Gas & Electric Co 2pp 18944 116 24X
Fiche 50-317,83/06/09,8306230383

--8306230388 IE Insp Repts 50-317/83-12 & 50-318/83-12 on 830509-13 No noncompliance noted Major areas inspected followup on previously identified insp items, radioactive matl transport & QA audits of radioactive matl transport
COLLINS, D J, SHANDAKY, M M Region 1, Office of Director 83/06/07 5pp 18944 138 24X Fiche 50-317,83/06/09,8306230383

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225 24X Fiche 50-000,83/06/13,8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000,83/06/13,8306090010

8306160323 Ack receipt of 830420 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/83-03 & 50-318/83-03
MARTIN, T T Division of Engineering & Technical Programs 83/06/14 LUNDVALL, A E Baltimore Gas & Electric Co 2pp 18860 056 24X
Fiche 50-317,83/06/14,8306160323

--8306160330 Responds to NRC 830322 ltr re violations noted in IE Insp Repts 50-317/83-03 & 50-318/83-03 Corrective actions
aperture card reader reproducing capability disabled, foreign print log revised & new QA procedure proposed
LUNDVALL, A E Baltimore Gas & Electric Co 83/04/20 MARTIN, T T Division of Engineering & Technical Programs 2pp 18860 058 24X Fiche 50-317,83/06/14,8306160323

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 116pp 19021 179 24X Fiche 50-000,83/06/22,8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18977 007 24X Fiche 50-000,83/06/22,8305110477

8306280461 Discusses until 830319 response to violations noted in IE Insp Repts 50-317/82-28 & 50-318/82-24 & results of 830419 meeting re response to two security violations. Addl info required Comments withheld (ref 10CFR73 21)
MARTIN, T T Division of Engineering & Technical Programs 83/06/22 DOWMAKER, N J Baltimore Gas & Electric Co 2pp 19019 183 24X
Fiche 50-317,83/06/22,8306280461

--8306280465 Responds to NRC 830216 ltr re violations noted in IE Insp Repts 50-317/82-28 & 50-318/82-24 Items 1 & 2 not valid violations Details withheld (ref 10CFR73 21)
DOWMAKER, N J Baltimore Gas & Electric Co 83/03/19 MARTIN, T T Division of Engineering & Technical Programs 1p 19019 185 24X Fiche 50-317,83/06/22,8306280461

DOCKETED ITEMS

147

B305110479 IE Info Notice B3-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B3/06/23 Consolidated Edison Co of New
York, Inc 116pp 18996 242 24X Fiche 50-000, B3/06/23, B305110479

B305110483 IE Info Notice B3-4's, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B3/06/24 Consolidated Edison Co of New
York, Inc 116pp 19046 297 24X Fiche 50-000, B3/06/24, B305110483

R Periodic operating reports & related correspondence

B306170018 Monthly operating repts for May 1983 W/B30614 ltr
LOTTITO, E M Baltimore Gas & Electric Co B3/06/14 Director's
Office, Office of Inspection and Enforcement lpp 18882 259 24X
Fiche 50-317, B3/06/14, B306170018

S Reportable occurrences, LERs & related correspondence

B306010270 LER B3-020/03L-0 on B30415, exhaust damper to ECCS room
exhaust fan 22 Found disconnected from actuator & in shut
position Caused by separation of damper lever arm from
bushing due to wear Level arm staked in place W/B30512 ltr
PIERINGER, P A, LYONS, W T, RUSSELL, L B Baltimore Gas & Electric
Co B3/05/12 ALLAN, J M Region 1, Office of Director 2pp
18672 249 24X Fiche 50-318, B3/05/12, B306010270

B306010273 LER B3-024/03L-0 on B30418, charging pump 22 removed from svc
upon discovery of leak on discharge relief valve line Caused
by crack in socket weld between coupling & inlet pipe of
relief valve, due to vibration Weld repaired W/B30512 ltr
JUNGE, M A, HUBBARD, D E, RUSSELL, L B Baltimore Gas & Electric Co
B3/05/12 ALLAN, J M Region 1, Office of Director 3pp
18672 243 24X Fiche 50-318, B3/05/12, B306010273

B306010299 Updated LER B1-050/03X-1 on B11020, reactor protective sys
Channel D thermal margin/low pressure trip unit bypassed for
maint after receiving spurious asymmetric steam generator
trips. Caused by failed signal isolator W/B30512 ltr
LAQUEWICK, J S, HINKLE, L B, RUSSELL, L B Baltimore Gas & Electric
Co B3/05/12 ALLAN, J M Region 1, Office of Director 2pp
18672 184 24X Fiche 50-318, B3/05/12, B306010299

B306020374 Updated LER B2-050/03X-1 on B31017, MBIV 21 stroked shut in
12 s exceeding 3 s Tech Spec limit Caused by valve packing
junk ring binding stem Ring replaced w/proper ring made of
mild steel & purchase spec revised W/B30519 ltr
WENDERLICH, R L, WEIR, P J, RUSSELL, L B Baltimore Gas & Electric
Co B3/05/19 ALLAN, J M Region 1, Office of Director 3pp
18695 110 24X Fiche 50-318, B3/05/19, B306020374

B306020430 Revised LER B1-007/03X-1 on B31018, MBIVs 21 & 22 failed to
shut within required time limit Caused by failed stems of
packing junk ring Rings replaced W/B30519 ltr
RUSSELL, L B, DAVIS, S M, WEIR, P J Baltimore Gas & Electric Co
B3/05/19 ALLAN, J M Region 1, Office of Director 3pp
18694 109 24X Fiche 50-318, B3/05/19, B306020430

B306020438 Updated LER B1-040/03L-1 on B31023, during surveillance
testing, MBIV 22 closing time exceeded Tech Spec limit Caused
by nonsteel ring binding stem Ring replaced Purchase spec
revised W/B30519 ltr
WENDERLICH, R L, WEIR, P J, RUSSELL, L B Baltimore Gas & Electric
Co B3/05/19 ALLAN, J M Region 1, Office of Director 3pp
18694 099 24X Fiche 50-318, B3/05/19, B306020438

B306020436 RD on B30412, oyster samples collected from Camp Conoy
sampling location & analyzed for gamma-emitting
radionuclides per Tech Spec requirements Based on average
alpha activity level in oyster samples, doses insignificant
FURMAN, O R Baltimore Gas & Electric Co B3/05/23 Region 1,
Office of Director 2pp 18694 102 24X Fiche 50-317, B3/05/23,
B306020436

B306200268 NPDES noncompliance notification on B30520, during receipt of
load of bulk aqueous ammonia, storage tank overflowed &
30-100 gallons of ammonia solution entered Outfall 002
Caused by improper attention during chemical transfer
RUSSELL, L B Baltimore Gas & Electric Co B3/05/24 ALLAN, J M
Region 1, Office of Director 3pp 18901 060 24X
Fiche 50-317, B3/05/24, B306200268

B306170072 LER B3-0P5/03L-0 on B30424, saltwater inlet valves to
circulating water pump room air coolers SW5250 & SW5251
discovered open while automatic safety injection actuation
signal disabled Caused by inadequate procedure W/B30525 ltr
WENDERLICH, R L, PAVIS, O B, RUSSELL, L B Baltimore Gas & Electric
Co B3/05/25 ALLAN, J M Region 1, Office of Director 3pp,
18882 244, 24X Fiche 50-318, B3/05/25, B306170072

B306210099 Updated LER B3-001/03X-1 on B30104, vital inverter 21
tripped, resulting in loss of vital instrument bus 2Y01 &
deenergizing pressure controller 2-PIC-103 Caused by use of
improper bus fuses W/B30526 ltr
PAVIS, O B, DASSO, L F, RUSSELL, L B Baltimore Gas & Electric Co.
B3/05/26 ALLAN, J M Region 1, Office of Director 3pp
18914 214 24X Fiche 50-318, B3/05/26, B306210099

B306210159 Updated LER B2-055/03X-1 on B2122B, vital ac inverter 22
failed, causing 120-volt ac vital bus 22 to deenergize Caused
by improper vital instrument bus fuses Proper fuses
installed W/B30526 ltr
JUNGE, M A, DASSO, L F, RUSSELL, L B Baltimore Gas & Electric Co
B3/05/26 ALLAN, J M Region 1, Office of Director 3pp,
18915 248 24X Fiche 50-318, B3/05/26, B306210159

B306210246 Revised LER B2-032/03X-1 on B20706, during routine
surveillance, diesel generator 21 would not start Caused by
broken inlet air check valve diaphragm Generator repaired
Counterweighting procedures revised W/B30526 ltr
LAQUEWICK, J S, HUBBARD, D E, RUSSELL, L B Baltimore Gas & Electric
Co B3/05/26 ALLAN, J M Region 1, Office of Director 4pp
18917 011 24X Fiche 50-318, B3/05/26, B306210246

B306170420 LER B3-021/03L-0 on B30504, containment sump alarms declared
inoperable Caused by defective alarm card, Alarm card
replaced. Annunciator alarm will be checked daily W/B30602
ltr
JUNGE, M A, RAYNOR, J W, RUSSELL, L B Baltimore Gas & Electric Co,
B3/06/02 ALLAN, J M Region 1, Office of Director 2pp
18879 060 24X Fiche 50-318, B3/06/02, B306170420

B306200118 Updated LER B3-047/03X-1 on B30104, during normal operation,
containment RMS pump failed resulting in loss of containment
gaseous & particulate radiation monitors Caused by
corrosion Pump replaced W/B30602 ltr
LAQUEWICK, J S, CARTRIGHT, W B, RUSSELL, L B Baltimore Gas &
Electric Co B3/06/02 ALLAN, J M Region 1, Office of Director.
3pp 18903 326 24X Fiche 50-318, B3/06/02, B306200118

B306210046 Updated LER B3-023/03X-1 on B30416, steam generator isolation
signal block B permitted steam generator isolation signal B
to be blocked & LDCI sequencer alarmed Caused by voltage
disturbance in inverter output W/B30609 ltr
DASSO, L F, RUSSELL, L B Baltimore Gas & Electric Co B3/06/09,
ALLAN, J M Region 1, Office of Director 3pp, 18911 226 24X
Fiche 50-318, B3/06/09, B306210046

B306280172 LER B3-028/03L-0 on B30516, accumulator 12 on MBIV 21 found
to have ruptured bladder No cause stated Accumulator
repaired & MBIV declared operable MBIV 21, accumulator 5, will
be replaced during next hot shutdown, W/B30609 ltr
PIERINGER, P A, WEIR, P J, RUSSELL, L B Baltimore Gas & Electric Co
B3/06/09 ALLAN, J M Region 1, Office of Director 2pp
19014 276 24X Fiche 50-318, B3/06/09, B306280172

B306280462 LER B3-029/03L-0 on B30515, during startup, dose equivalent
I-131 determined to be 1.38 uCi per g Caused by iodine
spiking due to leaking fuel pins & change in power level.
Sampling frequency increased, W/B30609 ltr
JUNGE, M A, RUSSELL, L B Baltimore Gas & Electric Co, B3/06/09,
ALLAN, J M Region 1, Office of Director 3pp 19018 324 24X
Fiche: 50-318, B3/06/09, B306280462

B306280352 LER B3-026/03L-0 on B30515, MBIV 21 stroked shut in 3.62 s,
exceeding Tech Spec limit Caused by loose arm on position
switch 2-25-4043A Arm adjusted & tightened & pull-stroke
test will be performed during next shutdown W/B30613 ltr
PIERINGER, P A, HINKLE, L B, RUSSELL, L B Baltimore Gas & Electric
Co, B3/06/13 ALLAN, J M Region 1, Office of Director 2pp,
19001 208 24X Fiche 50-318, B3/06/13, B306280352

V Operator Examinations

B306140714 Extends invitation to attend B30627 meeting in King of
Prussia, PA to discuss transfer of licensing function from
Bathesda, MD to Region 1 ofc
STAROBTECKI, R Division of Project & Resident Programs, B3/06/09,
LUNDVALL, A E Baltimore Gas & Electric Co 2pp 18841 292 24X
Fiche: 50-317, B3/06/09, B306140714

DOCKET 50-320 THREE MILE ISLAND NUCLEAR STATION, UNIT 2

F Security, medical, emergency & fire protection plans

B306060260 Forwards IE Insp Rept 50-320/B3-05 on B30404-0301 & notice
of violation
STAROBTECKI, R Division of Engineering & Technical Programs,
B3/05/23, KANOA, B K General Public Utilities - GPU Service Corp
2pp 18727 013 24X Fiche 50-320, B3/05/23, B306060260

DOCKETED ITEMS

--B306060262 Notice of violation from insp on B30404-0501
* Region I, Office of Director 83/05/23 1p 18727 015. 24X
Fiche: 50-320, 83/05/23, B306060260

--B306060266 IE Insp Rept 50-320/83-05 on B30404-0501 Noncompliance
noted failure to implement recovery mode procedure fully
during processing of reactor bldg sump water through
submerged demineralizer sys
WIEBE, J B, BELL, J M, BARR, K R Region I, Office of Director
83/05/20 9pp 18727 014 24X Fiche 50-320, 83/05/23, B306060260

B306240319 Act receipt of B30504 ltr re emergency info brochures Util
proposes to effect distribution primarily by direct mail to
agricultural community within plume exposure pathway
emergency planning zone
ROGAN, R E General Public Utilities - GPU Service Corp 83/05/31
HALLOWELL, P Pennsylvania, Commonwealth of, 1p 18980 153 24X
Fiche 50-289, 83/05/31, B306240319

G Adjudicatory correspondence

B306030007 FOIA request for rept or memo to Commissioners reviewing
evidence in recently-terminated lawsuit between GPU & B&W
in federal court, Southern District of NY
WEISS, E R Union of Concerned Scientists 83/02/23 FELTON, J
Division of Rules and Records 1p 18733 043 24X
Fiche: 50-320, 83/02/23, B306030007

B306080261 FOIA request for R Parks 56-page affidavit sent to US Dept
of Labor
ROMANO, F R Air and Water Pollution Patrol 83/03/31, Division
of Rules and Records 1p 18787 177 24X Fiche: 50-320, 83/03/31,
B306080261

B306030010 Responds to FOIA request for rept or memo to Commissioners
reviewing evidence in recently-terminated lawsuit between
GPU & B&W in federal court, Southern District of NY Rept
available in PDR
FELTON, J M Division of Rules and Records 83/04/01 WEISS, E R
Union of Concerned Scientists 1p 18733 044 24X
Fiche: 50-320, 83/04/01, B306030010

B306080262 Responds to FOIA request for R Parks 56-page affidavit sent
to US Dept of Labor Forwards 1 Devine B30323 ltr
transmitting RD Parks B30321 affidavit & RD Parks B30316 ltr
to Bechtel,
FELTON, J M Division of Rules and Records 83/04/12 ROMANO, F R
Air and Water Pollution Patrol, 1p 18787 178 24X
Fiche: 50-320, 83/04/12, B306080262

B306030329 Requests available evidence & conclusions re falsification
of TMI-2 records per H Hartman Mar 1980 allegations Info
should include NRC analyses & repts, mgt review records &
specific citations supporting NRC statement.
BLAKE, E L, Shaw, Pittman, Potts & Trenchbridge 83/06/01
PLAINE, H H Office of the General Counsel 3pp 18708 350 24X
Fiche 50-289, 83/06/01, B306030329

B306280387 Requests, under FOIA, to examine all files, documents, repts,
ltrs, memos & other info re probe conducted by T Martin in
1980 pertinent to leak rate data on water & hydrogen levels
at facility in 1978 Review of future info also requested
HEILTON, B L, Hoptford, Swartz, Menaker & Morgan 83/06/24
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
19001 272. 24X Fiche: 50-320, 83/06/24, B306280387.

I General correspondence

B306020043 Responds to B30502 ltr re B30328 NY Times article concerning
safety & effectiveness of cleanup, Addl info re review &
regulation of cleanup program encl.
DENTON, H R Office of Nuclear Reactor Regulation, Director,
83/05/24 COLEMAN, L S New Jersey, State of, 3pp 18699 338 24X
Fiche: 50-320, 83/05/24, B306020043.

B306020047 Requests review of questions raised in B30328 NY Times
article re safety & effectiveness of cleanup program Article
encl
COLEMAN, L S New Jersey, State of, 83/05/02, PALLADINO, N
Commissioners, 4pp. 18700 009. 24X Fiche 50-320, 83/05/24,
B306020043

O6150460 Responds to B30510 ltr re public input to programmatic EIS
on cleanup. Processed accident-generated water disposal
method will require Commission approval
SNYDER, B J, TMI Program Office, 83/06/07 HENDRICKS, M
Affiliation Unknown, 2pp. 18869 198. 24X Fiche 50-320, 83/06/07,
B306150460.

--B306150461 Expresses shock & disenchantment w/ lack of govt concern over
public view of cleanup efforts
HENDRICKS, M Affiliation Unknown 83/05/10 SNYDER, B J TMI
Program Office 1p 18869 200 24X Fiche 50-320, 83/06/07,
B306150460

F Operating license stage documents & correspondence

B306280202 FOIA request for copies of all permits allowing radioactive
mats in sewage or sewage sludge from plants or sanitary
landfills since B20101 or any repts from TMI concerning
levels of radiation or radionuclide contamination
HUNT, B D Three Mile Island Alert 83/04/07 Office of
Administration 1p 19043 214 24X Fiche 50-320, 83/04/07,
B306280202

B306280206 Partial response to FOIA request for copies of permits
allowing radioactive mats in sewage or sewage sludge from
TMI plant transported to area sewage treatment plants or
landfills Forwards App A documents Search continuing
FELTON, J M Division of Rules and Records 83/05/06 HUNT, B D
Three Mile Island Alert 2pp 19043 215 24X Fiche 50-320,
83/05/06, B306280206

--B306280211 Submits evaluation results of contaminated sewage in Gate 7
sewage holding tank Concentrations of radionuclides in
sewage in accordance w/ 10CFR20 303 Cs-137 & tritium
concentrations 0.023% mpc & 0.005% mpc, respectively
LAZARSKI, R F Region I, Office of Director 83/01/17
BARRETT, L H TMI Program Office 4pp 19043 261 24X
Fiche 50-320, 83/05/06, B306280206

--B306280216 Forwards info re Gate 7 sewage holding tank, located outside
west entrance to turbine bldg Info consists of effluent &
waste disposal & liquid effluent to summation of all
releases
BYRNE, J J Region I, Office of Director 83/02/04 BARRETT, L H
TMI Program Office 33pp 19043 265 24X Fiche 50-320, 83/05/06,
B306280206

--B306280220 Forwards GPU B30331 memo & related info re contamination
in Gate 7 sewage holding tanks Info results of King NY
Times article & Gischel affidavit
BARRETT, L H TMI Program Office 83/04/06 WARD, B Region I,
Office of Director 49pp 19043 297 24X Fiche 50-320, 83/05/06,
B306280206

B306030164 Submits status rept re Commission activities concerning
allegations raised by GPU employees & former employees on
mats to plant sys & components w/o proper review, tests &
approval
PALLADINO, N J Commissioners 83/05/12 MINNICH, J Advisory
Council for Decontamination of TMI Unit 2 1p 18733 332 24X
Fiche 50-320, 83/05/12, B306030164

B306230497 Notification of contract execution, Mod 1 to "Provision of
Technical Assistance to Assess Psychological Stress Related
to Decontamination & Disposal of Radwaste at TMI-2 "
Contractor Human Design Group
SMITH, P A Administrative Contracts Branch FIN D-7538 83/05/13
DENTON, H R Office of Nuclear Reactor Regulation, Director,
CLEARY, D P NRC - No Detailed Affiliation Given 1p 18782 035
24X Fiche 50-320, 83/05/13, B306230497

--B306230501 Mod 1, deobligating balance of funds, to "Provision of
Technical Assistance to Assess Psychological Stress Related
to Decontamination & Disposal of Radwaste at TMI Unit 2 "
BAUM, A S Human Design Group SMITH, P A Administrative
Contracts Branch, FIN D-7538 83/05/13 1p 18982 036 24X
Fiche 50-320, 83/05/13, B306230497

B306030498 Forwards corrected page previously issued w/ B30506 Amend 21
to License DPR-73
SNYDER, B J TMI Program Office 83/05/19 KANGA, B K General
Public Utilities - GPU Service Corp 1p 18735 227 24X
Fiche: 50-320, 83/05/19, B306030498

--B306030500 Corrected pages to Tech Specs issued w/ Amend 21 to license
DPR-73
* TMI Program Office 83/05/19 3pp. 18735 228 24X
Fiche: 50-320, 83/05/19, B306030498

B306020096 Responds to Committee on Interior & Insular Affairs B30504
request for documentation re cleanup activities & 790328
incident.
KANGA, B K General Public Utilities - GPU Service Corp 83/05/27.
BARRETT, L H TMI Program Office, 293pp 18691 266 24X
Fiche 50-320, 83/05/27, B306020096

DOCKETED ITEMS

149

8306160682 Forwards list of questions & clarification of items requiring response re review of underhead characterization SERs Majority of items discussed during 830825 meeting w/uttl
BARRETT, L H TMI Program Office 83/06/02 KANGA, B K General Public Utilities - GPU Service Corp 4pp 18876 036 24X Fiche 50-320, 83/06/02, 8306160682

8306220198 Forwards Vol 5, Number 4 to NUHCO-0090, "Rept to Congress on AGs," for Fourth Quarter CY02 One AG reported at NRC licensees re inoperability of containment spray sys Agreement states reported no AGs
AHEARNE, J F Commissioners 83/06/02 O'NEILL, T P House of Rep 2pp 18740 024 24X Fiche 50-000, 83/06/02, 8306220198

--8306220264 Agrees w/830225 view that B&W/uttl litigation should be carefully reviewed Responses to Questions 2 through 5 raised in 830225 ltr encl
AHEARNE, J F Commissioners 83/06/01 UDALL, M K House of Rep Interior & Insular Affairs 5pp 18740 107 24X Fiche 50-000, 83/06/02, 8306220198

--8306220268 Discusses importance of carefully analyzing 830222 record of hearing on uttl/B&W litigation to determine whether record contains info bearing on questions of competence & character requirements of OL holder Questions per TMI-2 accident encl
UDALL, M K House of Rep, Interior & Insular Affairs 83/02/25 PALLADINO, N Commissioners 2pp 18740 112 24X Fiche 50-000, 83/06/02, 8306220198

8306220161 Requests cooperation in responding to BNWL info requests to assist in preparation of suppl to preliminary EIS Staff member should be designated as coordinator
SNYDER, B J TMI Program Office 83/06/08 KANGA, B K General Public Utilities - GPU Service Corp 7pp 18937 028 24X Fiche 50-320, 83/06/08, 8306220161

8306170282 Advises that J Flanigan will be coordinator for BNWL work suppl to programmatic EIS, in response to 830608 ltr
KANGA, B K General Public Utilities - GPU Service Corp 83/06/13 SNYDER, B J TMI Program Office 1p 18978 170 24X Fiche 50-320, 83/06/13, 8306170282

8306220035 Forwards proposed Rev 7 to organization plan for facility, changing organization charts to indicate realignment of functions reporting to recovery operations section NRC approval & implementation data requested
KANGA, B K General Public Utilities - GPU Service Corp 83/06/14 SNYDER, B J TMI Program Office 3pp 18930 206 24X Fiche 50-320, 83/06/14, 8306220035

8306220037 Forwards fees incurred for review of underhead characterization study Documents consist of single safety issue.
KANGA, B K General Public Utilities - GPU Service Corp 83/06/15 SNYDER, B J TMI Program Office 1p 18901 031 24X Fiche 50-320, 83/06/15, 8306220037

8306280074 Requests uttl provide, within 30 days of ltr receipt, justification for instances where Tech Spec surveillance exemption invoked due to occupational exposure Enforcement action will be taken if issues not expeditiously addressed
SNYDER, B J TMI Program Office 83/06/15 KANGA, B K General Public Utilities - GPU Service Corp 3pp 19042 344 24X Fiche 50-320, 83/06/15, 8306280074

8306220054 Forwards Addendum I to polar crane load test SCR for review addendum incorporates responses to NRC & other comments re load test & operating procedures Changes discussed w/o encl.
KANGA, B K General Public Utilities - GPU Service Corp 83/06/17 BARRETT, L H TMI Program Office 2pp 18930 023 24X Fiche 50-320, 83/06/17, 8306220054

Q Inspection reports, IE Bulletins & correspondence

8306200438 FOIA request for NRC Investigation Rept I-83-003 re facilities
KILCOYNE, J J Kilroyne, J J 83/03/28 FELTON, J Division of Rules and Records 1p 18920 018 24X Fiche 50-289, 83/03/28, 8306200438

8306200434 Responds to FOIA request for NRC Investigation Rept I-83-003 re facilities Rept withheld (ref FOIA Exemptions 5 & 7)
FELTON, J M Division of Rules and Records 83/05/02 KILCOYNE, J J Kilroyne, J J 1p 18920 017 24X Fiche 50-289, 83/05/02, 8306200434

8306020008 Confirms 830516 identification of housekeeping & industrial safety hazard actions in response to 830505 insp
BARRETT, L H TMI Program Office 83/05/16 KANGA, B K General Public Utilities - GPU Service Corp 3pp 18702 353 24X Fiche 50-320, 83/05/16, 8306020008

8306060260 Forwards IE Insp Rept 50-320/BU-05 on 830404-0501 & notice of violation
STANDSTECKI, R Division of Engineering & Technical Programs 83/05/23 KANGA, B K General Public Utilities - GPU Service Corp 2pp 18727 013 24X Fiche 50-320, 83/05/23, 8306060260

--8306060262 Notice of Violation from insp on 830404-0501
* Region 1, Office of Director 83/05/23 1p 18727 013 24X Fiche 50-320, 83/05/23, 8306060260

--8306060266 IE Insp Rept 50-320/83-03 on 830404-0501 Noncompliance noted failure to implement recovery mode procedure fully during processing of reactor bldg sump water through submerged demineralizer sys
WIEDE, J S, DELL, J M, BARR, K R Region 1, Office of Director 83/05/20 9pp 18727 016 24X Fiche 50-320, 83/05/23, 8306060260

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BNWs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 200 24X Fiche 50-000, 83/05/31, 8305110461

8306080331 Staff requirements memo re Commission 830524 briefing on NRC revalidation of mgt competence identified in insps on 830518 & 19
CHILK, S J Office of the Secretary of the Commission 83/06/02, DIRCKS, W J Office of the Executive Director for Operations 1p 18789 355 24X Fiche 50-320, 83/06/02, 8306080331

8306130137 Responds to 830310 IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators " Inservice test program includes check valves in flow path of cooling water for diesel generators No change required.
KANGA, B K General Public Utilities - GPU Service Corp 83/06/07 ALLAN, J M Region 1, Office of Director 2pp 18824 282 24X Fiche 50-320, 83/06/07, 8306130137

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8306140600 Forwards Pickard, Lowe & Garrick, Inc investigation rept on allegations re use of polar crane Util response to rept encl Addl info forthcoming in response to rept recommendations
ARNOLD, R C General Public Utilities - GPU Service Corp 83/06/09, SNYDER, B J TMI Program Office 144pp 18824 021 24X Fiche 50-320, 83/06/09, 8306140600

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Statically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 110pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/21 Consolidated Edison Co of New York, Inc 115pp 19021 177 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Bys Causing Inoperability of Safety-Related Equipment." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

DOCKETED ITEMS

8305110483 IE Info Notice 83-42, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000,83/06/24,8305110483

R Periodic operating reports & related correspondence

8306010407 Correction to annual operating rept 1981 containing info on total aircraft movements at Harrisburg Intl Airport
MUKILL, H D General Public Utilities - GPU Service Corp 83/05/11
Region I, Office of Director 2pp 18679 312 24X
Fiche 50-289,83/05/11,8306010407

8306020654 THI Program Ofc weekly status rept for wk of 830515-21.
BARRETT, L H THI Program Office 83/05/23 DENTON, H R Office of Nuclear Reactor Regulation, Director SNYDER, B J THI Program Office 11pp 18716 258 24X Fiche 50-320,83/05/23,8306020654.

8306200044 Submits THI Program Ofc weekly status rept for wk of 830522-28
BARRETT, L H THI Program Office 83/05/27 DENTON, H R Office of Nuclear Reactor Regulation, Director SNYDER, B J THI Program Office 15pp 18908 271 24X Fiche 50-320,83/05/27,8306200044

8306070215 Forwards "THI Aquatic Study, Apr 1983"
RESSLER, W C General Public Utilities - GPU Service Corp 83/06/01
HICKEY, C NRC - No Detailed Affiliation Given 1p 18747 021
24X Fiche 50-289,83/06/01,8306070215

--8306070219 "THI Aquatic Study, Apr 1983"
NARDACCI, O A Ichthyological Associates, Inc 83/04/30 19pp
18747 022 24X Fiche 50-289,83/06/01,8306070215

8306200031 Submits THI Program Ofc weekly status rept for wk of 830529-0604
BARRETT, L H THI Program Office 83/06/06 DENTON, H R Office of Nuclear Reactor Regulation, Director SNYDER, B J THI Program Office 9pp 18919 295 24X Fiche 50-320,83/06/06,8306200031

8306160643 Forwards THI Program Ofc weekly status rept for wk of 830605-11
BARRETT, L H THI Program Office 83/06/13 DENTON, H R Office of Nuclear Reactor Regulation, Director SNYDER, B J THI Program Office 11pp 18884 330 24X Fiche 50-320,83/06/13,8306160643

8306280658 Submits THI Program Ofc weekly status rept for 830612-18
BARRETT, L H THI Program Office 83/06/20 DENTON, H R Office of Nuclear Reactor Regulation, Director SNYDER, B J THI Program Office 10pp 24X Fiche 50-320,83/06/20,8306280658

8306300162 Forwards "THI Aquatic Study, Monthly Rept for May 1983," prepared by Ichthyological Assoc, Inc
RESSLER, W C General Public Utilities - GPU Service Corp 83/06/27
HICKEY, C NRC - No Detailed Affiliation Given 1p 19119 280
24X Fiche 50-289,83/06/27,8306300162

--8306300164 "THI Aquatic Study, Monthly Rept for May 1983"
NARDACCI, O A Ichthyological Associates, Inc 83/05/31 23pp
19119 281 24X Fiche 50-289,83/06/27,8306300162

S Reportable occurrences, LERs & related correspondence

8306010329 LER 83-013/03L-0 on 830418, control room operator opened wrong breaker, tripping auxiliary & fuel handling bldg ventilation sys & control bldg chlorine monitors. Caused by operator error. Breaker closed W/830518 ltr.
WELLS, R, KANGA, B K General Public Utilities - GPU Service Corp, 83/05/18 ALLAN, J M Region I, Office of Director 3pp 18682 248 24X Fiche 50-320,83/05/18,8306010329

8306170025 LER 83-014/03L-0 on 830506, air intake tunnel Halon Sys activated causing actuation of deluge sys & tripped auxiliary & fuel handling bldg supply & exhaust fans. Caused by welding near air intake tunnel. Sys secured W/830606 ltr.
WELLS, R, KANGA, B K General Public Utilities - GPU Service Corp, 83/06/06 ALLAN, J M Region I, Office of Director 4pp 18882 236 24X Fiche 50-320,83/06/06,8306170025

V. Operator Examinations

8306140224 Extends invitation to attend 830627 meeting in King of Prussia, PA to discuss transfer of reactor operator licensing function from Bethesda, MD to Region I ofc.
STAROCHTECKI, R Division of Project & Resident Programs 83/06/09
KANGA, B K General Public Utilities - GPU Service Corp 2pp 18932 286 24X Fiche 50-320,83/06/09,8306140224

DOCKET 50-321 EDWIN I HATCH NUCLEAR PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8306030233 Forwards revised response to CCO/01 requests for example from 10CFR50 4B & App R requirements, per 830330 request. Rev reflects compliance w/10CFR50 4B & App R requirements & responds to 830120 draft LTR concerning
GUCWA, L I Georgia Power Co 83/05/27 STOLZ, J I (Operating Reactors Branch 4 164pp 18/05 093 24X Fiche 50-321,83/05/27,8306030233

8306140711 Approves issuance of SAMP Repts 50-321/83-06, 50-366/83-06, 50-424/83-06 & 50-425/83-06 for Jul 1981 - Oct 1981
LEWIS, R C Division of Project & Resident Programs 83/06/01
KELLY, R J Georgia Power Co Jpp 18841 196 24X
Fiche 50-000,83/06/01,8306140711

--8306140719 Advises of 830317 meeting in Atlanta, GA to discuss SAMP Repts 50-321/83-06, 50-366/83-06, 50-424/83-06 & 50-425/83-06 for Jul 1981 - Oct 1982
LEWIS, R C Division of Project & Resident Programs 83/06/01
KELLY, R J Georgia Power Co 2pp 18841 194 24X
Fiche 50-000,83/06/01,8306140711

--8306140730 SAMP Repts 50-321/83-06, 50-366/83-06, 50-424/83-06 & 50-425/83-06 for Jul 1981 - Oct 1982. No significant unit weaknesses identified
* Region 2, Office of Director 83/03/09 38pp 18841 201 24X
Fiche 50-000,83/06/01,8306140711

--8306140743 Ack receipt of SAMP Repts 50-321/83-06, 50-366/83-06, 50-424/83-06 & 50-425/83-06 for Jul 1981 - Oct 1982
Evaluation acceptable
BECKHAM, J T Georgia Power Co 83/04/18 G'RLITLY, J P Repts 2, Office of Director 1p 18841 203 24X Fiche 50-000,83/06/01,8306140711

8306150133 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/06/01 Document Management Branch 1p 18844 092 24X Fiche 50-321,83/06/01,8306150133

--8306150137 Forwards public version of revised emergency plan implementing procedures, including Procedures HNP-2-4219 re battery fire, HNP-4890 re exercises & drills & HNP-4621 re actions for personnel in site area emergency
NIX, H C Georgia Power Co 83/05/18 Office of Nuclear Reactor Regulation, Director 1p 18872 074 24X Fiche 50-321,83/06/01,8306150133

--8306150141 Public version of revised emergency plan implementing procedures, including Procedures HNP-2-4219 re battery fire, HNP-4890 re exercises & drills & HNP-4621 re actions for personnel in site area emergency
SUMNER, L Georgia Power Co 83/05/06 26pp 18871 094 24X
Fiche 50-321,83/06/01,8306150133

8306140237 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/06/06 Document Management Branch 1p 18844 258 24X Fiche 50-321,83/06/01,8306140237

--8306140246 Forwards public version of revised emergency plan implementing procedures, including Procedures HNP-8137 re portable ion chamber Model RD 2A, HNP-8143 re low vol air sampler Model H-809 VI & HNP-4200 re fire procedure
NIX, H C Georgia Power Co 83/05/24 Office of Nuclear Reactor Regulation, Director 4pp 18844 259 24X Fiche 50-321,83/06/01,8306140237

--8306140284 Public version of revised emergency plan implementing procedures, including Procedures HNP-8137 re portable ion chamber Model RD-2A, HNP-8143 re low vol air sampler Model H-809 VI & HNP-4200 re general fire procedure.
* Georgia Power Co 83/05/24 3pp 18844 243 24X
Fiche 50-321,83/06/01,8306140237

8306180037 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/06/07 Document Management Branch 1p 18871 182 24X Fiche 50-321,83/06/07,8306180037

DOCKETED ITEMS

151

--8306150041 Forwards public version of revised emergency plan implementing procedures, including Procedures HNP-0156 re Gamma-10 portal monitor operation, HNP-4623 re site emergency shift supervisor & HNP-4626 re rally point leader
NIX, H C Georgia Power Co 83/04/25 Office of Nuclear Reactor Regulation, Director 1p 18871 183 24X Fiche 50-321, 83/06/07, 8306150037

--8306150044 Public version of revised emergency plan implementing procedures, including Procedures HNP-0156 re gamma-10 portal monitor operation, HNP-4623 re site emergency-shift supervisor & HNP-4626 re rally point leader
NIX, H C Georgia Power Co 83/04/15 107pp 18871 184 24X Fiche 50-321, 83/06/07, 8306150037

8306220307 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rule and Records 83/05/07 Document Management Branch 1p 18940 114 24X Fiche 50-321, 83/06/07, 8306220307

--8306220313 Forwards public version of revised emergency plan implementing procedures, including Procedures HNP-8004 re personnel dosimeter program, HNP-8016 re shipment of radioactive matl & HNP-4622 re control room operators
NIX, H C Georgia Power Co 83/05/04 Office of Nuclear Reactor Regulation, Director 1p 18940 115 24X Fiche 50-321, 83/06/07, 8306220307

--8306220310 Public version of revised emergency plan implementing procedures, including Procedures HNP-0004 re personnel dosimeter program, HNP-8016 re shipment of radioactive matl & HNP-4622 re control room operators
ROSEB, W H, NIX, H C Georgia Power Co 83/04/26 Office of Nuclear Reactor Regulation, Director 18pp 18940 116 24X Fiche 50-321, 83/06/07, 8306220307

8306170202 Forwards addl info to justify 820701 10CFR50 AB & App R schedule exemption requests discussed at 830330 meeting
Plan being developed to complete maint & design changes
W/two oversize drawings Aprtiture cards available in PDR
QUCHA, L T Georgia Power Co 83/06/14 STOLZ, J F Operating Reactors Branch 4 4pp 18882 277 24X Fiche 50-321, 83/06/14, 8306170202

I Financial Information

8306070123 Forwards Annual Financial Repts, 1982
QUCHA, L T Georgia Power Co 83/05/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18739 038 24X Fiche 50-000, 83/06/02, 8306070123

--8306070127 Annual Financial Rept, 1982
VOORLE, A W The Southern Co 83/03/10 51pp 18739 039, 24X Fiche 50-000, 83/06/02, 8306070123

--8306070130 Annual Financial Rept, 1982
SCHERER, R W, MILLER, J H Georgia Power Co 83/03/07 36pp 18739 091 24X Fiche 50-000, 83/06/07, 8306070123

P Operating license stage documents & correspondence

8306030127 Informs that responsibility transferred from Region II to NRR Div of Licensing for all licensing actions re evaluation of util resolution of pipe cracking issues Acceptable resolution required prior to restart
STOLZ, J F Operating Reactors Branch 4 83/05/17 BECKHAM, J T Georgia Power Co 2pp 18733 304 24X Fiche 50-321, 83/05/17, 8306030127

8306070224 Forwards Rev 0 to "LI Hatch Nuclear Plant Units 1 & 2 Environ Qualification of Class IE Equipment," in response to IE Bulletin 79-018 & 10CFR50 49 requirements
QUCHA, L T Georgia Power Co 83/05/20, STOLZ, J F Operating Reactors Branch 4 219pp, 18746 192 24X Fiche 50-321, 83/05/20, 8306070224

8306070129 Requests withdrawal of 820430 proposed Tech Spec changes re safety-related snubber insp & surveillance requirements
Insoperable snubber conditions defined in proposed changes do not reflect actual operability concerns
QUCHA, L T Georgia Power Co 83/05/31 STOLZ, J F Operating Reactors Branch 4 1p 18739 254 24X Fiche 50-321, 83/05/31, 8306070129

8306070351 Application for amend to Licenses DPR-57 & NPF-5, revising dose equivalent iodine Tech Specs to reflect current requirements Info resolving outstanding purge & vent valve operability issues encl
BECKHAM, J T Georgia Power Co 83/05/31 STOLZ, J F Operating Reactors Branch 4 34pp 18742 071 24X Fiche 50-321, 83/05/31, 8306070351

--8306070357 Proposed changes to dose equivalent iodine Tech Specs & preliminary proposed Tech Specs for drywell & suppression chamber purge sys
* Georgia Power Co 83/05/31 5pp 18742 103 24X Fiche 50-321, 83/05/31, 8306070351

8306220219 Presents alternatives to automatic depressurization sys logic to eliminate need for manual actuation for core coverage per TH1 Item II K 3 18 Implementation schedule & proposed Tech Specs requested within 45 days of ltr receipt
STOLZ, J F Operating Reactors Branch 4 83/06/03 BECKHAM, J T Georgia Power Co 2pp 18951 001 24X Fiche 50-321, 83/06/03, 8306220219

8306140075 Advises that SER & technical evaluation repts re environ qualification of safety-related electrical equipment do not contain proprietary info Repts may be placed in PDR
QUCHA, L T Georgia Power Co 83/06/08 STOLZ, J F Operating Reactors Branch 4 1p 18839 114 24X Fiche 50-321, 83/06/08, 8306140075

8306160267 Forwards evaluation results demonstrating as-built acceptability of wetwell/drywell vacuum breakers on Mark I containments, in response to Generic Ltr 83-08
QUCHA, L T Georgia Power Co 83/06/09 STOLZ, J F Operating Reactors Branch 4 16pp 18859 329 24X Fiche 50-321, 83/06/09, 8306160267

8306220002 Application for amend to Licenses DPR-57 & NPF-5 changing Tech Specs 3/4 6-2, B 3/4 6-6 & adding 3/4 6-46 for Unit 2 & 3 7-10a, 3 7-34, 3 7-34a & adding 3 7-10b & 3 7-34b for Unit 1 re purge & vent valve operability
BECKHAM, J T Georgia Power Co 83/06/15, STOLZ, J F Operating Reactors Branch 4 5pp 18928 003 24X Fiche 50-321, 83/06/15, 8306220002

--8306220010 Proposed changes to Tech Specs 3/4 6-2, B 3/4 6-6 & added 3/4 6-46 for Unit 2 & 3 7-10a, 3 7-34, 3 7-34a & adding 3 7-10b & 3 7-34b for Unit 1 re purge & vent valve operability
* Georgia Power Co 83/06/15 55pp 18928 008 24X Fiche 50-321, 83/06/15, 8306220002

8306210335 Notification of 830623 meeting w/util in Atlanta, GA to discuss status of Region II review of inservice pump & valve test program & questions re program
RIVENBARK, O Operating Reactors Branch 4 83/06/20 STOLZ, J F Operating Reactors Branch 4 2pp 18935 313 24X Fiche 50-321, 83/06/20, 8306210335

G Inspection reports, IE Bulletins & correspondence

8306140116 Forwards summary of IE mgt meetings on 830318 & 22 w/util to discuss condition of electrical cable trays & associated equipment & lack of mgt controls
O'REILLY, J P Region 2, Office of Director 83/04/08 KELLY, R J Georgia Power Co 4pp 18839 092 24X Fiche 50-321, 83/04/08, 8306140116

8306070224 Forwards Rev 0 to "LI Hatch Nuclear Plant Units 1 & 2 Environ Qualification of Class IE Equipment," in response to IE Bulletin 79-018 & 10CFR50 49 requirements
QUCHA, L T Georgia Power Co 83/05/20 STOLZ, J F Operating Reactors Branch 4 219pp 18746 192 24X Fiche 50-321, 83/05/20, 8306070224

8306140515 Forwards IE Insp Repts 50-321/83-14 & 50-366/83-14 on 830426-29 & 0503-05 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/05/25 KELLY, R J Georgia Power Co 2pp 18843 238 24X Fiche 50-321, 83/05/25, 8306140515

--8306140522 IE Insp Repts 50-321/83-14 & 50-366/83-14 on 830426-29 & 0503-05 No noncompliance noted. Major areas inspected inservice insp, previous enforcement matters & welding
Meeting held to discuss IE Bulletin 83-02 insp results
CROWLEY, B R Region 2, Office of Director BLAKE, J J Division of Engineering & Radiological Safety Programs 83/05/23 15pp 18843 240 24X Fiche 50-321, 83/05/25, 8306140515

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc, 125pp 18831 043, 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

DOCKETED ITEMS

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306020179 EN-83-039 notice of violation & proposed imposition of civil penalty in amount of \$40,000 will be issued in May 1983
Proposed action based on licensee failure to ensure restoration of electrical cable tray sys
BARBER, G. J. AXELRAD, J. Director's Office, Office of Inspection and Enforcement 83/05/31 1p 18691 092 24X Fiche 50-321, 83/05/31, 8306020179.

8306070129 Requests withdrawal of 820430 proposed Tech Spec changes re safety-related snubber insp & surveillance requirements
Inoperable snubber conditions defined in proposed changes do not reflect actual operability concerns
QUACH, L. T. Georgia Power Co 83/05/31 STOLZ, J. F. Operating Reactors Branch 4 1p 18739 254 24X Fiche 50-321, 83/05/31, 8306070129

8306140711 Approves issuance of SALP Repts 50-321/83-06, 50-366/83-06, 50-424/83-06 & 50-425/83-06 for Jul 1981 - Oct 1982
LEWIS, R. C. Division of Project & Resident Programs 83/06/01
KELLY, R. J. Georgia Power Co 3pp 18841 196 24X Fiche 50-000, 83/06/01, 8306140711

--8306140719 Advises of 830317 meeting in Atlanta, GA to discuss SALP Repts 50-321/83-06, 50-366/83-06, 50-424/83-06 & 50-425/83-06 for Jul 1981 - Oct 1982
LEWIS, R. C. Division of Project & Resident Programs 83/03/09
KELLY, R. J. Georgia Power Co 2pp 18841 199 24X Fiche 50-000, 83/06/01, 8306140711

--8306140730 SALP Repts 50-321/83-06, 50-366/83-06, 50-424/83-06 & 50-425/83-06 for Jul 1981 - Oct 1982 No significant utility weaknesses identified
* Region 2, Office of Director 83/03/09, 38pp 18841 201 24X Fiche 50-000, 83/06/01, 8306140711

--8306140743 Ack receipt of SALP Repts 50-321/83-06, 50-366/83-06, 50-424/83-06 & 50-425/83-06 for Jul 1981 - Oct 1982
Evaluation acceptable
BECKHAM, J. T. Georgia Power Co 83/04/18 O'REILLY, J. P. Region 2, Office of Director 1p 18841 239 24X Fiche 50-000, 83/06/01, 8306140711

8306240006 Discusses IE insp on 830227-0326 & forwards notice of violation & proposed imposition of civil penalty
O'REILLY, J. P. Region 2, Office of Director 83/06/02 KELLY, R. J. Georgia Power Co 3pp 18987 341 24X Fiche 50-321, 83/06/02, 8306240006

--8306240014 Notice of violation & proposed imposition of civil penalty in amount of \$40,000 Noncompliance noted failure to restore cable tray sys to quality conditions & lack of QA planning for mods & maint re electrical cable tray installation
O'REILLY, J. P. Region 2, Office of Director 83/06/02 App 18987 344 24X Fiche 50-321, 83/06/02, 8306240006

8306290435 Submits addl response to IE Bulletin 81-03 fire protection sys uses water from deep well Sys not susceptible to clam infiltration Mytilus sp not present in Altamaha River in vicinity of plant
BECKHAM, J. T. Georgia Power Co 83/06/02 O'REILLY, J. P. Region 2, Office of Director 2pp 19052 181 24X Fiche 50-321, 83/06/02, 8306290435

8306140075 Advises that SER & technical evaluation repts re environ qualification of safety-related electrical equipment do not contain proprietary info Repts may be placed in PDR
QUACH, L. T. Georgia Power Co 83/06/08 STOLZ, J. F. Operating Reactors Branch 4 1p 18839 114 24X Fiche 50-321, 83/06/08, 8306140075

8306290264 Responds to IE Bulletin 83-03 re check valve failures in raw water cooling sys of diesel generators No check valves installed in cooling water sys at facilities
BECKHAM, J. T. Georgia Power Co 83/06/08 O'REILLY, J. P. Region 2, Office of Director 3pp 19056 079 24X Fiche 50-321, 83/06/08, 8306290264

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations," Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc. 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8306290254 Ack receipt of 830526 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/83-07 & 50-366/83-07
LEWIS, R. C. Division of Project & Resident Programs 83/06/16
KELLY, R. J. Georgia Power Co 1p 19056 058 24X Fiche 50-321, 83/06/16, 8306290254

--8306290265 Responds to NRC 830421 ltr re violations noted in IE Insp Repts 50-321/83-07 & 50-366/83-07 Corrective actions valve handwheels being painted orange, adjustable wrenches removed & procedures for key lock switches revised
BECKHAM, J. T. Georgia Power Co 83/05/26 O'REILLY, J. P. Region 2, Office of Director 4pp 19056 059 24X Fiche 50-321, 83/06/16, 8306290254

--8306290278 Forwards IE Insp Repts 50-321/83-07 & 50-366/83-07 on 830122-0226 & notice of violation
LEWIS, R. C. Division of Project & Resident Programs 83/04/21
KELLY, R. J. Georgia Power Co 2pp 19056 063 24X Fiche 50-321, 83/06/16, 8306290254

--8306290284 Notice of violation from insp on 830122-0226
* Region 2, Office of Director 83/04/21 2pp 19056 065 14X Fiche 50-321, 83/06/16, 8306290254

--8306290293 IE Insp Repts 50-321/83-07 & 50-366/83-07 on 830122 0226 Noncompliance noted failure to implement procedures properly re primary containment atmospheric control sys & operation of safety-related sys
CRLENJAK, R. V. HOLMES-RAY, P. Region 2, Office of Director
BROWNLEE, V. L. Division of Project & Resident Programs 83/04/12 6pp 19056 067 24X Fiche 50-321, 83/06/16, 8306290254

8306290298 Ack receipt of 830523 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/83-08 & 50-366/83-08
LEWIS, R. C. Division of Project & Resident Programs 83/06/16
KELLY, R. J. Georgia Power Co 1p 19056 017 24X Fiche 50-321, 83/06/16, 8306290298

--8306290303 Responds to NRC 830421 ltr re violations noted in IE Insp Repts 50-321/83-08 & 50-366/83-08 Corrective actions Procedure HNP-9 will be reviewed & revised to clarify requirements for revising procedures
QUACH, L. T. Georgia Power Co 83/05/23 O'REILLY, J. P. Region 2, Office of Director 2pp, 19056 018 24X Fiche 50-321, 83/06/16, 8306290298

--8306290312 Forwards IE Insp Repts 50-321/83-08 & 50-366/83-08 on 830314-18 & 25 & notice of violation
LEWIS, R. C. Division of Project & Resident Programs 83/04/21
KELLY, R. J. Georgia Power Co 2pp 19056 020 24X Fiche 50-321, 83/06/16, 8306290298

--8306290317 Notice of violation from insp on 830314-18 & 25
* Region 2, Office of Director 83/04/21 1p 19056 022 24X Fiche 50-321, 83/06/16, 8306290298.

--8306290332 IE Insp Repts 50-321/83-08 & 50-366/83-08 on 830314-18 & 25 Noncompliance noted, failure to revise Procedure HNP-2-3801, Rev 17, per Procedure HNP-9 requirements
GIRARD, E. H. ROSE, W. J. BLAKE, J. J. Region 2, Office of Director 83/04/20 13pp 19056 023 24X Fiche 50-321, 83/06/16, 8306290298

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 115pp, 19021 177 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 120pp 18977 007 24X Fiche 50-000, 83/06/22, 8305110477

DOCKETED ITEMS

153

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000,83/06/23,8305110479

8306300085 Responds to 830602 notice of violation & proposed imposition of civil penalties for violations noted in IE Insp Repts
50-321/83-09, 50-321/83-10, 50-366/83-09 & 50-366/83-10
Corrective actions Procedure HNP-69P1 revised
BECKHAM, J T Georgia Power Co 83/06/23 Director's Office,
Office of Inspection and Enforcement 6pp 19048 254 24X
Fiche 50-321,83/06/23,8306300085

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000,83/06/24,8305110483

R Periodic operating reports & related correspondence

8306170382 Monthly operating rept for May 1983 W/830610 ltr
REDWANZ, F J, NIX, H C Georgia Power Co 83/06/10 Director's
Office, Office of Inspection and Enforcement 23pp 18880 255 24X
Fiche: 50-321,83/06/10,8306170382

S Reportable occurrences, LERs & related correspondence

8305310144 RD 50-321/83-05 on 830407, w/unit at 100% power, alarm silenced on 243-P005 fire detection panel due to performance of mods Panel not restored to operable status within Tech Spec limits Continuous fire watch assigned
NIX, H C Georgia Power Co 83/05/16 O'REILLY, J P Region 2,
Office of Director 3pp 18659 044 24X Fiche 50-321,83/05/16,8305310144

8306070080 LER 83-050/03L-0 on 830429, plant svc water pump 1A tripped
Caused by component failure due to pump motor winding insulation breakdown Motor repaired & required testing performed W/830523 ltr
TIPPS, B B, NIX, H C Georgia Power Co 83/05/23 O'REILLY, J P
Region 2, Office of Director 4pp 18737 355 24X
Fiche 50-321,83/05/23,8306070080

8306070347 LER 83-049/03L-0 on 830505, sanitary water supply valve X42-F073D found open but not locked open Caused by personnel error Personnel counseled W/830523 ltr
TIPPS, B B, NIX, H C Georgia Power Co 83/05/23 O'REILLY, J P
Region 2, Office of Director 4pp 18742 067 24X
Fiche 50-321,83/05/23,8306070347

8306200261 LER 83-052/03L-0 on 830506, alarms received indicating trouble w/diesel generator auxiliaries. Generator untied & tripped Caused by normal supply breaker control power toggle switch being in off position Position adjusted W/830602 ltr
TIPPS, B B, NIX, H C Georgia Power Co 83/06/02 O'REILLY, J P
Region 2, Office of Director 4pp 18901 107 24X
Fiche 50-321,83/06/02,8306200261

8306200374 LER 83-053/03L-0 on 830508, 10 & 16, fission product particulate radiation monitor (1D11-K631) & fission product iodine monitor (1D11-K632) found inoperable Caused by component failure 1D11-K631 parts replaced W/830606 ltr
TIPPS, B B, NIX, H C Georgia Power Co 83/06/06 O'REILLY, J P
Region 2, Office of Director 5pp 18901 041 24X
Fiche 50-321,83/06/06,8306200374

8306200202 LER 83-037/03L-0 on 830510, while performing hydrogen & oxygen analyzer instrument procedure (HNP-1-3882), hydrogen analyzer (IP33-N002A) indicated incorrectly Caused by failed current transmitter Transmitter replaced W/830609 ltr
TIPPS, B B, NIX, H C Georgia Power Co 83/06/09 O'REILLY, J P
Region 2, Office of Director 4pp 18903 202 24X
Fiche 50-321,83/06/09,8306200202

8306280361 LER 83-055/03L-0 on 830517, RHR HX bypass valve (1E11-F048B) would not cycle completely open or closed Caused by loose valve stem nut Retainer Reinstalled & locked by staking W/830615 ltr
TIPPS, B B, NIX, H C Georgia Power Co 83/06/15 O'REILLY, J P
Region 2, Office of Director 4pp 19001 204 24X
Fiche: 50-321,83/06/15,8306280361

8306200203 PNO-II-83-04B on 830615, facility automatically shut down due to turbine trip caused by loss of power to electro hydraulic control sys Facility to be down until 830620 for replacement of safety relief valves
ROGGE, J C DANCE, H C Region 2, Office of Director 83/06/16 2pp 18903 206 24X Fiche 50-321,83/06/16,8306200203

V. Operator Examinations

8306140486 Forwards summary of 830503 meeting re NRC policies on senior operator licensing exam Tech Spec memorization requirements
Written exam requirements specified in draft Examiner Std E8-402 List of attendees encl
DANCE, H C Division of Project & Resident Programs 83/05/24
BECKHAM, J T Georgia Power Co 4pp 18843 090 24X
Fiche 50-000,83/05/24,8306140486

--8306140493 Requests meeting to discuss NRC policies on senior operator licensing exam Tech Spec memorization requirements Summary of Tech Spec sections covering required memorization encl
BECKHAM, J T Georgia Power Co 83/03/11 WILSON, B Region 2,
Office of Director 2pp 18843 094 24X Fiche 50-000,83/05/24,8306140486

DOCKET 50-322 SHOREHAM NUCLEAR POWER STATION

A Application/construction stage documents & correspondence

8306060349 Board Notification 83-67 forwards info re errors in computer analyses for Mark II containment Rept providing results of evaluations performed by S&W re Shoreham
Mark II containment also encl
NOVAK, T M Assistant Director for Licensing 83/05/19 Atomic
Safety and Licensing Board Panel 7pp 18753 079 24X
Fiche 50-000,83/05/19,8306060349

--8306060352 Final deficiency rept re QHOSH & rocking acceleration data transmittal discrepancy Initially reported on 821029 & 830318, respectively No changes to plant design required QA Category I load transmittals will be reviewed
MILLIGAN, M H Long Island Lighting Co 83/04/20 ALLAN, J M
Region 1, Office of Director 4pp 18753 085 24X
Fiche 50-000,83/05/19,8306060349

--8306060359 "Rept on Effects of Discrepancies in QHOSH Computer Program Used by S&W & in Labeling of Rocking Acceleration Units on Design of Shoreham Nuclear Power Station - Unit 1 "
* Stone & Webster Engineering Corp 83/04/30 87pp 18753 089, 24X Fiche 50-000,83/05/19,8306060349

8306020495 Notification of cancellation of 830524 meeting w/ representatives of Suffolk County in Bethesda, MD to evaluate positions re CP extension
CARUSO, R Licensing Branch 2 83/05/20 SCHWENCER, A Licensing
Branch 2 4pp 18715 192 24X Fiche 50-322,83/05/20,8306020495

8306150250 Forwards Teledyne Engineering Svc 820520 ltr transmitting independent design review documents Certificate of Svc encl
BORDENICK, B M Hearing Branch 3 83/05/27 BRENNER, L.,
CARPENTER, J L, MORRIS, P A Atomic Safety and Licensing Board Panel 10pp 18846 099 24X Fiche 50-322,83/05/27,8306150250

8306130236 Forwards summary of disposition of NRC generic ltrs for CV01 & CV02
SMITH, J L Long Island Lighting Co 83/06/07, DENTON, H R Office
of Nuclear Reactor Regulation, Director 7pp 18826 304 24X
Fiche 50-322,83/06/07,8306130236

8306130477 Notification of 830609 meeting w/util in Bethesda, MD to discuss proof & review process for Tech Specs
CARUSO, R Licensing Branch 2 83/06/07 SCHWENCER, A. Licensing
Branch 2 4pp 18830 167 24X Fiche 50-322,83/06/07,8306130477

8306140118 Notification of 830609 meeting w/util & OE in Bethesda, MD to discuss instrument setpoint tolerances in Tech Specs
CARUSO, R Licensing Branch 2 83/06/07 SCHWENCER, A Licensing
Branch 2 4pp 18844 181 24X Fiche 50-322,83/06/07,8306140118

8306210220 Forwards matl presented at Anderson, Greenwood & Co (AGCo) vacuum breaker test program owners group 830607 meeting w/ NRC re dynamic testing & analysis of AGCo vacuum breaker valve assemblies
O'CONNOR, D M Bechtel Corp 83/06/17, HOUSTON, R W Division of
Systems Integration (post 811005) 91pp 18919 038, 24X
Fiche, 50-000,83/06/17,8306210220

8306230004 Forwards Teledyne Engineering Svcs 830606 ltr w/attachments re independent design verification program Certificate of Svc encl
BORDENICK, B M Hearing Branch 3 83/06/21 BRENNER, L.,
CARPENTER, J L, MORRIS, P A Atomic Safety and Licensing Board Panel 12pp 18947 080 24X Fiche 50-322,83/06/21,8306230004

DOCKETED ITEMS

E NRC Safety Evaluation Report (SER), supp's & correspondence

8306070038 Informs that preservice insp program completed & available for onsite review Program should close out SER Open Item 19
SMITH, J. L. Long Island Lighting Co 83/06/02 DENTON, H. R. Office
of Nuclear Reactor Regulation, Director 2pp 18739 339. 24X
Fiche 50-322, 83/06/02, 8306070038

8306070013 Responds to request for environ qualification status of reactor bldg flood level alarms, per SER Open Item 61 re scram discharge vol (NUREG-0803) Testing program completed Documentation available for onsite review in approx 2 wks
SMITH, J. L. Long Island Lighting Co. 83/06/03 DENTON, H. R. Office
of Nuclear Reactor Regulation, Director 3pp 18736 359 24X
Fiche 50-322, 83/06/03, 8306070013

8306130326 Forwards technical justification of single frequency/single axis testing method, per SER, Suppl 3 Info should resolve concerns re applicability of testing method
SMITH, J. L. Long Island Lighting Co 83/06/06 DENTON, H. R. Office
of Nuclear Reactor Regulation, Director 4pp 18822 240 24X
Fiche 50-322, 83/06/06, 8306130326

--8306130328 Rev 2 to "Seismic Qualification Reevaluation, Class 1E Equipment for Shoreham Nuclear Power Station, Unit 1"
RAHABAS, E. S. Science Applications, Inc * General Electric Co
029-04-SO-PA R02, 81/04/03 5pp 18822 244 24X
Fiche 50-322, 83/06/06, 8306130328

--8306130331 "Seismic Qualification Reevaluation, Class 1E Equipment, Differential Pressure Transmitter for Shoreham Nuclear Power Station, Unit 1."
SHERBIN, W. C. HARDY, R. W., LURIA, N. General Electric Co 83/02/08
8pp 18822 249 24X Fiche 50-322, 83/06/06, 8306130331

--8306130332 Rev 23 to "Dynamic Qualification, Recirculation Discharge Gate Valve for Shoreham Nuclear Power Station, Unit 1."
LE, H. General Electric Co 83/F031 R23 82/11/22 5pp
18822 257 24X Fiche 50-322, 83/06/06, 8306130332

8306240230 Forwards GE "Shoreham Common Sensors Failures Evaluation Rept." to resolve SER Open Issue 47 Control sys failures, caused by common hydraulic headers, will not result in consequences outside scope of FSAR analyses.
SMITH, J. L. Long Island Lighting Co 83/06/20 DENTON, H. R. Office
of Nuclear Reactor Regulation, Director 3pp 18980 187. 24X
Fiche 50-322, 83/06/20, 8306240230

--8306240232 "Shoreham Common Sensors Failures Evaluation Rept."
CIHI, J. J. General Electric Co 83/05/31 46pp 18980 190. 24X
Fiche 50-322, 83/06/20, 8306240232

8306280547 Forwards revised Table 3.9.2B-3 of FSAR, per SER Item 10, denoting fuel lift under combined SSE & LOCA loadings as zero Value based on 84% nonrecurrence probability at 50% confidence level, consistent w/NEDE-21175-3-P
SMITH, J. L. Long Island Lighting Co 83/06/20 DENTON, H. R. Office
of Nuclear Reactor Regulation, Director 4pp 19018 102 24X
Fiche 50-322, 83/06/20, 8306280547

8306240250 Discusses Suppl 3 to SER re Item 62, "Remote Shutdown Panel." Info should be sufficient to close item as confirmatory issue for fuel load
SMITH, J. L. Long Island Lighting Co 83/06/21 DENTON, H. R. Office
of Nuclear Reactor Regulation, Director 3pp 18980 165 24X
Fiche 50-322, 83/06/21, 8306240250

8306280445 Forwards General Physics Corp evaluation results of items in corporate scope of review, Info should be sufficient to close SER open items
SMITH, J. L. Long Island Lighting Co 83/06/23 DENTON, H. R. Office
of Nuclear Reactor Regulation, Director 6pp 19020 178 24X
Fiche 50-322, 83/06/23, 8306280445

F Security, medical, emergency & fire protection plans

8306150609 Releases public version of transmittal notices
FELTON, J. M. Division of Rules and Records 83/06/07 Document
Management Branch 1p 18867:265 24X Fiche 50-322, 83/06/07,
8306150609

--8306150615 Forwards public version of transmittal notices indicating that confirmation of receipt of controlled documents not received, Verification of receipt requested
KEATINGE, L. A. Teledyne Engineering Services, 83/04/19,
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 7pp
18867 266 24X Fiche 50-322, 83/06/07, 8306150609

8306160072 Releases public version of revised emergency preparedness plan & implementing procedures
FELTON, J. M. Division of Rules and Records 83/06/07 Document
Management Branch 1p 18873 001 24X Fiche 50-322, 83/06/07,
8306160072

--8306160087 Forwards public version of Rev 4 to emergency preparedness plan & revised emergency preparedness implementing procedures, including Procedures EPIP 1-1 re unusual event, EPIP 1-2 re alert & EPIP 1-5 re notifications
SMITH, J. L. Long Island Lighting Co 83/05/31 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director 1p 18873 002
24X Fiche 50-322, 83/06/09, 8306160072

--8306160089 Public version of Rev 4 to emergency preparedness plan
* Long Island Lighting Co 83/05/31 200pp 18873 003 24X
Fiche 50-322, 83/06/09, 8306160072

--8306160091 Public version of revised emergency plan implementing procedures, including Procedures EPIP 1-1 re unusual event, EPIP 1-2 re alert & EPIP 1-5 re notifications Revised
Index encl
* Long Island Lighting Co 83/05/16 1,000pp 18873 224 24X
Fiche 50-322, 83/06/09, 8306160072

8306160096 Releases public version of offsite radiological emergency response plan & implementing procedures
FELTON, J. M. Division of Rules and Records 83/06/09 Document
Management Branch 1p 18885 001 24X Fiche 50-322, 83/06/09,
8306160096

--8306160100 Forwards public version of offsite radiological emergency response plan, App A & addendum to App A & offsite radiological emergency response plan implementing procedures
SMITH, J. L. Long Island Lighting Co 83/06/03 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director 3pp 18885 002
24X Fiche 50-322, 83/06/09, 8306160096

--8306160104 Public version of offsite radiological emergency response plan Oversize drawings encl Aperture cards available in PDR
* Long Island Lighting Co 82/10/31 1,100pp 18885 005 24X
Fiche 50-322, 83/06/09, 8306160096

--8306160108 Public version of local offsite radiological emergency response plan implementing procedures, including Procedure OPIP 3.5.1 re downwind surveying Two oversize drawings encl Aperture cards available in PDR
* Long Island Lighting Co 83/05/02 750pp 18889 041 24X
Fiche 50-322, 83/06/09, 8306160096

8306270305 Forwards ANL rept: "Element-By-Element Review of LILCO Transition Module of Shoreham Nuclear Power Station Offsite Radiological Emergency Response Plan," in response to 830601 request.
KRIMM, R. W. Federal Emergency Management Agency 83/04/23
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 2pp 18995 266 24X Fiche 50-322, 83/06/23,
8306270305

--8306270308 "Element-By-Element Review of LILCO Transition Module of Shoreham Nuclear Power Station Offsite Radiological Emergency Response Plan"
* Argonne National Laboratory 83/06/22 17pp 18995 268 24X
Fiche 50-322, 83/06/23, 8306270305

8306280034 Releases public version of revised emergency plan implementing procedures
FELTON, J. M. Division of Rules and Records 83/06/23 Document
Management Branch 1p 19043 001 24X Fiche 50-322, 83/06/23,
8306280034

--8306280042 Forwards public version of revised Emergency Plan implementing Procedures EPIP 2-8 re post-accident gaseous effluent sample analysis & EPIP 1-0 re classification of emergency action levels
SMITH, J. L. Long Island Lighting Co 83/06/08 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director 2pp 19043 003
24X Fiche 50-322, 83/06/23, 8306280034

--8306280046 Public version of revised Emergency Plan implementing Procedures EPIP 2-8 re post-accident gaseous effluent sample analysis & EPIP 1-0 re classification of emergency action levels
* Long Island Lighting Co 83/06/06 209pp 19043 005 24X
Fiche 50-322, 83/06/23, 8306280034

DOCKETED ITEMS

155

8306290673 Submits daily highlight for 830623 re FEMA identified technical discrepancies in util transition offsite emergency plan. Plan acceptability will not be determined until legal questions resolved & drills performed.
CARUSO, R Licensing Branch 2 83/06/27 BERNER, L J , CARL, F C ,
CARTER, J Office of Nuclear Reactor Regulation, Director 1p
19047 200 24X Fiche 50-322, 83/06/23, 8306290673

0 Adjudicatory correspondence

8306150211 Forwards executed Addendum 1 to resolution of Suffolk County Contention 13(a) re QA/QC - operations, replacing 830516
teletype version
BORDENICK, B M Hearing Branch 3 83/05/20 BRENNER, L J ,
MORRIS, P A , CARPENTER, J L Atomic Safety and Licensing Board Panel
2pp 18846 007 24X Fiche 50-322, 83/05/20, 8306150211

--8306150214 Addendum 1 to resolution of Suffolk County Contention 13(a) re QA/QC - operations, changing dates in Paragraphs II A, II B & II C & adding statement to Paragraph II C
BORDENICK, B M Hearing Branch 3 CARLEY, A F Long Island
Lighting Co DYNNER, A R Suffolk County, NY 83/05/16 2pp
18846 009 24X Fiche 50-322, 83/05/20, 8306150211

8306150250 Forwards Teledyne Engineering Svc 820520 ltr transmitting independent design review documents Certificate of Svc encl
BORDENICK, B M Hearing Branch 3 83/05/27 BRENNER, L J ,
CARPENTER, J L , MORRIS, P A Atomic Safety and Licensing Board Panel
10pp 18846 099 24X Fiche 50-322, 83/05/27, 8306150250

8306020181 Comments on util-county disagreements re unresolved QA/QC operations, in response to 830517 & 23 ltrs Matters discussed in stated ltrs need not be litigated or mediated by ASLB
BORDENICK, B M Hearing Branch 3 83/05/31 DYNNER, A R
Kirkpatrick, Lockhart, Hill, Christopher & Phillips 2pp
18849 230 24X Fiche 50-322, 83/05/31, 8306020181

8306020446 Forwards portion of ASLAB Decision ALAB-729 re sys interactions & NRC const of term "important to safety." Reasonable progress demonstrated & adequate justification for operation of facility shown
RAWSON, R J Hearing Branch 4 83/05/31 BRENNER, L J ,
CARPENTER, J L , MORRIS, P A Atomic Safety and Licensing Board Panel
2pp 18873 243, 24X Fiche 50-322, 83/05/31, 8306020446

8306060184 Response to util & NRC opposition to Suffolk County 830502 motion & 830510 addendum to motion for level to file new contentions re emergency diesel generators Proposed contention should be admitted
BROWN, H H Suffolk County, NY BROWN, H H Kirkpatrick, Lockhart, Hill, Christopher & Phillips 83/05/31 Atomic Safety and Licensing Board Panel 40pp 18728 195 24X Fiche 50-322, 83/05/31, 8306060184

--8306060188 Affidavit of MW Goldsmith advocating further investigation into facility diesel generator problems Prof qualifications & Certificate of Svc encl.
GOLDSMITH, M W Suffolk County, NY GOLDSMITH, M W Energy Research Group, Inc 83/05/31 36pp 18728 225 24X Fiche 50-322, 83/05/31, 8306060188

8306150404 Confirms 830520 telcon between A Dynner & R Caruso re cancellation of 830524 meeting on util request for CP extension Meeting should be rescheduled within 10 days
EISENHUT, D O Division of Licensing 83/06/01 BROWN, H H
Kirkpatrick, Lockhart, Hill, Christopher & Phillips 4pp
18848 353 24X Fiche 50-322, 83/06/01, 8306150404

8306060292 Reply to util 830516 & NRC 830523 filings, as suppl to Suffolk County findings & opinion on Suffolk County Contention II Util failed to address need to consider check valves in safety-related sys W/Certificate of Svc
LANPHER, L C Suffolk County, NY LANPHER, L C, Kirkpatrick, Lockhart, Hill, Christopher & Phillips 83/06/02 9pp 18730 008 24X Fiche 50-322, 83/06/02, 8306060292

8306270399 Demands limited appearance hearings be held
LABCELLE, K E Affiliation Unknown 83/06/02 LAURENSEN, J A
Atomic Safety and Licensing Board Panel 2pp 18994 136, 24X Fiche 50-322, 83/06/02, 8306270399

8306060312 Informs that Teledyne Engineering Svcs will issue final independent design verification program rept on 830711
BORDENICK, B M Hearing Branch 3 83/06/03 BRENNER, L J ,
MORRIS, P A , CARPENTER, J L Atomic Safety and Licensing Board Panel
2pp 18729 323 24X Fiche 50-322, 83/06/03, 8306060312

8306070381 Forwards executed MW Goldsmith affidavit supporting Suffolk County response to util & NRC opposition to motion for leave to file new contention re emergency diesel generators Related correspondence
MILLER, M S Kirkpatrick, Lockhart, Hill, Christopher & Phillips
MILLER, M S Suffolk County, NY 83/06/03 BRENNER, L J ,
BORDENICK, B M , REVELEY, W T Atomic Safety and Licensing Board Panel 1p 18741 321 24X Fiche 50-322, 83/06/03, 8306070381

--8306070385 Executed affidavit of MW Goldsmith demonstrating issues raised in Suffolk County proposed contention on diesel generators timely raised & present significant issues re generator safety function Certificate of Svc encl
GOLDSMITH, M W Suffolk County, NY GOLDSMITH, M W Energy Research Group, Inc 83/06/02 22pp 18741 322 24X Fiche 50-322, 83/06/03, 8306070385

8306070405 Corrects util 830526 memorandum of svc for supplemental emergency planning info Certificate of Svc encl
CHRISTIAN, J N Hutton & Williams 83/06/03 LAURENSEN, J A ,
KLINE, J R , LIVINGSTON, M B Atomic Safety and Licensing Board Panel
3pp 18742 281 24X Fiche 50-322, 83/06/03, 8306070405

8306080171 Forwards util response to Suffolk County submission re diesel generators Suffolk County unwarranted attack on util, util counsel & NRC w/o basis Leave to submit response to demonstrate no issues of fact exist requested.
ELLIS, T B Hutton & Williams ELLIS, T B Long Island Lighting Co, 83/06/03 BRENNER, L J , CARPENTER, J L , MORRIS, P A Atomic Safety and Licensing Board Panel 2pp 18772 278 24X Fiche 50-322, 83/06/03, 8306080171

--8306080177 Response to Suffolk County submission re diesel generators Submittal allegations & implications false Reopening of record not merited Discontinuities in cylinder blocks will not affect safety
ELLIS, T B Long Island Lighting Co ELLIS, T B Hutton & Williams 83/06/03 2pp 18772 280 24X Fiche 50-322, 83/06/03, 8306080177

--8306080182 Affidavit of EJ Youngling, demonstrating existence of no cracks in cylinder block castings which will propagate or adversely affect engines Certificate of Svc encl.
YOUNGLING, E J Long Island Lighting Co, 83/06/03 Bpp, 18772 282 24X Fiche 50-322, 83/06/03, 8306080171

8306080191 Order scheduling 830610 party conference in Bethesda, MD to clarify legal & technical points re Suffolk County motion to admit new contention on emergency diesel generators
BRENNER, L Atomic Safety and Licensing Board Panel 83/06/06 2pp 18772 190 24X Fiche 50-322, 83/06/06, 8306080191

8306130398 Requests limited appearance hearings be held on Long Island before formal litigation begins
PEIT, H R , FOX, C , PRICE, W, Affiliation Unknown 83/06/06, LAURENSEN, J A Atomic Safety and Licensing Board Panel 13pp 18823 260 24X Fiche 50-322, 83/06/06, 8306130398

8306080169 Response to util memorandum of svc of supplemental emergency planning info ASLB should reject proposed emergency plans until agreement reached w/entities to perform assigned duties Certificate of Svc encl.
BROWN, H H Suffolk County, NY BROWN, H H Kirkpatrick, Lockhart, Hill, Christopher & Phillips 83/06/07 Atomic Safety and Licensing Board Panel 14pp 18772 132 24X Fiche 50-322, 83/06/07, 8306080169

8306090216 Motion requesting Commission to reject util plans which do not provide adequate accident response preparedness & to conclude OL proceeding Certificate of Svc encl
BROWN, H H Suffolk County, NY BROWN, H H Kirkpatrick, Lockhart, Hill, Christopher & Phillips 83/06/07 Commissioners, 10pp 18796 001 24X Fiche 50-322, 83/06/07, 8306090216

8306090258 Advises that util proposal, per 830512 order re submission of util plan in absence of state & local govt plans, is simply unimplementable compendium of speculative & hypothetical alternatives. Facility shutdown recommended
COHALAN, P F Suffolk County, NY 83/06/07 PALLADINO, N J ,
GILINKEY, V , ASSELSTINE, J K, Commissioners, 3pp, 18794 316, 24X Fiche 50-322, 83/06/07, 8306090258

8306090295 Status rept on schedule for filing emergency planning contentions Four wks sufficient to produce draft contentions Contentions should address util-county plan & util interim plans Certificate of Svc encl.
MCCLISKEY, K E Long Island Lighting Co MCCLISKEY, K E Hutton & Williams, 83/06/07 5pp 18795 287 24X Fiche 50-322, 83/06/07, 8306090295

DOCKETED ITEMS

- 8306100240 Forwards response to Suffolk County submission of data re diesel generators & JC Higgins unexecuted affidavit re cracked emergency diesel generator engine block
BORDENICK, B M Hearing Branch 3 83/06/08. BRENNER, L, MORRIS, P A, CARPENTER, J L Atomic Safety and Licensing Board Panel 2pp 18807 126 24X Fiche 50-322, 83/06/08, 8306100240
- 8306100242 Response to Suffolk County 830526 submission of data re diesel generators Util promptly informed NRC of surface crack indications in diesel generator camshaft block area. Certificate of Svc encl.
BORDENICK, B M Hearing Branch 3 83/06/08 9pp 18807 126 24X Fiche 50-322, 83/06/08, 8306100240
- 8306130404 Motion for low-power OL Partial initial decision needed on full-power operation for issues on which record complete Certificate of Svc encl
REVELEY, W T Long Island Lighting Co REVELEY, W T Hutton & Williams 83/06/08 Atomic Safety and Licensing Board Panel 19pp 18823 245 24X Fiche 50-322, 83/06/08, 8306130404.
- 8306130411 Forwards motion for low-power OL Request involves evaluation of onsite emergency preparedness, contested health & safety issues & offsite emergency preparedness w/o encl
REVELEY, W T Hutton & Williams REVELEY, W T Long Island Lighting Co 83/06/08 BRENNER, L, CARPENTER, J N, MORRIS, P A Atomic Safety and Licensing Board Panel 5pp 18823 235. 24X Fiche 50-322, 83/06/08, 8306130411
- 8306130423 Rept on disagreements w/util re QA/QC operations Seven disagreements, all within scope of litigation, remain
DYNNER, A R Suffolk County, NY DYNNER, A R, Kirkpatrick, Lockhart, Hill, Christopher & Phillips 83/06/08 75pp 18823, 147 24X Fiche 50-322, 83/06/08, 8306130423
- 8306130446 Notice of appearance in proceeding Certificate of Svc encl
MONACHAN, J A Long Island Lighting Co MONACHAN, J A, Hutton & Williams 83/06/08 3pp. 18821 203 24X Fiche 50-322, 83/06/08, 8306130446
- 8306150378 Response opposing util 830526 filing of five emergency plans in compliance w/ASLB 830420 memorandum & order. Plans do not meet ASLB order criteria Certificate of Svc encl
SHAPIRO, R. North Shore Committee Against Nuclear & Thermal Pollution. 83/06/08 Atomic Safety and Licensing Board Panel 7pp 18847 258 24X Fiche 50-322, 83/06/08, 8306150378
- 8306160305 Supports limited appearance hearings prior to formal litigation, to be held on Long Island
LERMAN, D M Affiliation Unknown 83/06/08 LAURENSEN, J A Atomic Safety and Licensing Board Panel 1p 18859 231 24X Fiche 50-322, 83/06/08, 8306160305
- 8306130387 Forwards executed JC Higgins affidavit re diesel generators
BORDENICK, B M Hearing Branch 3 83/06/09 BRENNER, L, MORRIS, P A, CARPENTER, J L Atomic Safety and Licensing Board Panel 2pp 18823 011 24X Fiche 50-322, 83/06/09, 8306130387
- 8306130391 Affidavit of JC Higgins re diesel generators Util informed affiant of surface crack indications in camshaft blocks of diesel generators on 830330 Cracks caused by casting & cooling block, not preoperational testing
HIGGINS, J C NRC - No Detailed Affiliation Given 83/06/09 3pp 18823 013 24X Fiche 50-322, 83/06/09, 8306130391
- 8306150395 Forwards Suffolk County status re need for addl time to file draft emergency planning contentions, per ASLB 830505 order
MCMURRAY, C M Kirkpatrick, Lockhart, Hill, Christopher & Phillips MCMURRAY, C M Suffolk County, NY 83/06/09 LAURENSEN, J A Atomic Safety and Licensing Board Panel 1p 18847 001 24X Fiche 50-322, 83/06/09, 8306150395
- 8306130401 Status re requesting addl time to file draft emergency planning contentions If util transition plan only subj of contentions, extension needed until 830818 to submit draft contentions. Certificate of Svc encl.
MCMURRAY, C M. Suffolk County, NY MCMURRAY, C M, Kirkpatrick, Lockhart, Hill, Christopher & Phillips. 83/06/09. Atomic Safety and Licensing Board Panel 2pp 18847 002 24X Fiche 50-322, 83/06/09, 8306130401
- 8306130414 Response to ASLB 830526 question re passive mechanical valve failures Encl affidavit responds to question.
REPKA, D A Hearing Branch 3 83/06/10 1p. 18823:224 24X Fiche: 50-322, 83/06/10, 8306130414
- 8306130418 Affidavit of R Caruso responding to ASLB 830526 question re passive mechanical valve failures Discusses NRC resolution of generic equipment problems Prof qualifications & Certificate of Svc encl
CARUSO, R Division of Licensing 83/06/10. 10pp 18823 225 24X Fiche 50-322, 83/06/10, 8306130414.
- 8306150292 Order denying Suffolk County 830609 request for addl time to file draft emergency planning contentions No good cause shown for substantial delay
LAURENSEN, J A Atomic Safety and Licensing Board Panel 83/06/10 Suffolk County, NY 2pp 18849 171 24X Fiche 50-322, 83/06/10, 8306150292
- 8306150300 Order excusing parties from filing draft or final contentions re util alternative emergency plans until util establishes consent of one or more govt entities to participate in emergency plan functions
LAURENSEN, J A Atomic Safety and Licensing Board Panel 83/06/10 3pp 18849 167 24X Fiche 50-322, 83/06/10, 8306150300
- 8306150370 Response to ASLB 830526 memorandum & order directing clarification of certain matters re Contention BC 11 five safety-related check valve included in inservice testing program & tested in one of three ways
FLANAGAN, D D Long Island Lighting Co FLANAGAN, D D Hutton & Williams 83/06/10 3pp 18847 288 24X Fiche 50-322, 83/06/10, 8306150370
- 8306150373 Affidavit of JA Rigert, addressing questions re safety related check valve categories & testing
RIGERT, J A Long Island Lighting Co 83/06/09 5pp 18847 288 24X Fiche 50-322, 83/06/10, 8306150373
- 8306150381 Affidavit of JF Alexander, addressing independent safety engineering group evaluation of valve failures Certificate of Svc encl
ALEXANDER, J F Long Island Lighting Co 83/06/09 4pp 18847 296 24X Fiche 50-322, 83/06/10, 8306150381
- 8306150416 Order adding EL Frucci to svr list & deleting WJ Dwyer from svr list
FRUCCI, E L Atomic Safety and Licensing Board Panel 83/06/10 1p 18847 126 24X Fiche 50-322, 83/06/10, 8306150416
- 8306150379 Response supporting Suffolk County & North Shore Coalition for Safe Energy motion for order striking portions of util 830526 filing Emergency plans devoid of legal or practical substance Certificate of Svc encl
DOUGHERTY, J B Shoreham Opponents Coalition 83/06/10 Atomic Safety and Licensing Board Panel 4pp 18847 235 24X Fiche 50-322, 83/06/10, 8306150379
- 8306150397 Motion for immediate decision rejecting util transition plan Plan does not involve state & county govt participation, therefore adequate emergency preparedness not provided Certificate of Svc encl
BROWN, H H Philadelphia Electric Co BROWN, H H Kirkpatrick, Lockhart, Hill, Christopher & Phillips 83/06/13 Committee 5pp 18847 132 24X Fiche 50-322, 83/06/13, 8306150397
- 8306170394 Petition of Citizens for Orderly Energy Policy, Inc for leave to intervene in emergency planning hearing Member Affidavits, notice of appearance & Certificate of Svc encl
SWARTZ, L L Affiliation Unknown SWARTZ, L L Pacific Legal Foundation 83/06/14 Atomic Safety and Licensing Board Panel 23pp 18879, 293 24X Fiche 50-322, 83/06/14, 8306170394
- 8306160287 Response opposing Suffolk County 830607 & 13 motions for Commission ruling on util plan for emergency preparedness & immediate Commission decision rejecting transition plan Certificate of Svc encl
CHRISTMAN, J N Long Island Lighting Co CHRISTMAN, J N Hutton & Williams 83/06/15 Commissioners 14pp 18859 014 24X Fiche 50-322, 83/06/15, 8306160287
- 8306200337 Confirms ASLB 830615 oral granting of Suffolk County request for extension to 830627 for County to answer util 830601 motion for low power OL NRC response date extended until 830630
DYNNER, A R Kirkpatrick, Lockhart, Hill, Christopher & Phillips 83/06/15 BRENNER, L B, CARPENTER, J L, MORRIS, P A Atomic Safety and Licensing Board Panel 1p 18900 170 24X Fiche 50-322, 83/06/15, 8306200337
- 8306220094 Submits correct title & address for J Novarro
SITLER, P Long Island Lighting Co 83/06/15. Docketing & Services Branch 1p 18926 210 24X Fiche 50-322, 83/06/15, 8306220094
- 8306220088 Forwards affidavits supporting Citizens for Orderly Energy Policy, Inc 830614 petition to intervene
SWARTZ, L L Pacific Legal Foundation 83/06/16 LAURENSEN, J A & KLINE, J R, LIVINGSTON, M B Atomic Safety and Licensing Board Panel 1p 18926 034 24X Fiche 50-322, 83/06/16, 8306220088

DOCKETED ITEMS

157

--8306220093 Suppl to Citizens for Orderly Energy Policy 830614 petition to intervene consisting of J Policy, AB Mill, WK Kuer, JJ Cadwell & JP Ludus affidavits
* Affiliation Unknown 8/1/06/09 Atomic Safety and Licensing Board Panel 5pp 18926 045 24X Fiche 50-322, 83/06/14, 8306220093

8306220017 Advises that util presentation to Region 1 personnel on aspects of diesel generators scheduled for 830630 in King of Prussia, PA IE Mgt Meeting Rept 50-322/83-20 to be issued
Related correspondence
ELLIS, T S Hutton & Williams L.L.B.S. Long Island Lighting Co
83/06/17 BRENNER, L, MORRIS, P A, CARPENTER, J H Atomic Safety and Licensing Board Panel 1p 18927 32, 24X Fiche 50-322, 83/06/17, 8306220017

8306220134 Reply to util & NRC submissions on Suffolk County (Contention 1) Facts in util & NRC affidavits must be scrutinized carefully
LANPHER, L C Suffolk County, NY LANPHER, L C, Kirkpatrick, Lockhart, Hill, Christopher & Phillips 83/06/20 1p 18926 156 24X Fiche 50-322, 83/06/20, 8306220134

--8306220141 Affidavit of DO Wridenbaugh re info in record on Suffolk County Contention 1 re passive mechanical valve failure
Discusses deficiencies in inservice testing program
Certificate of Svc
BRIDENBAUGH, D Suffolk County, NY 83/06/17 9pp 18926 157 24X Fiche 50-322, 83/06/20, 8306220141

8306220004 Forwards Teledyne Engineering Svcs 830604 ltr w/attachments re independent design verification program Certificate of Svc encl
BORDENICK, B M Hearing Branch 3 83/06/21 BRENNER, L, CARPENTER, J L, MORRIS, P A Atomic Safety and Licensing Board Panel 12pp 18947 080 24X Fiche 50-322, 83/06/21, 8306220004

8306230008 Response opposing Suffolk County 830607 & 13 motions for summary rejection of util offsite emergency transition plan
Rejection w/o review & hearing could deny opportunity to present case on merits W/Certificate of Svc
REPKA, D A Hearing Branch 3 83/06/21 Commissioners 10pp 18947 120 24X Fiche 50-322, 83/06/21, 8306230008

8306270290 Requests to make limited appearance statements at 830714 hearings
FORST, M, KING, W, FOX, C Affiliation Unknown 83/06/21 Office of the Secretary of the Commission 3pp 18993 304 24X Fiche 50-322, 83/06/21, 8306270290

8306280572 Requests to make limited appearance statement at morning session of 830714 hearings
FORST, M Affiliation Unknown 83/06/21 Office of the Secretary of the Commission 2pp 19017 310 24X Fiche 50-322, 83/06/21, 8306280572

8306270144 Memorandum & order granting in part & denying in part Suffolk County 830502 motion to admit new contention re emergency diesel generators
BRENNER, L Atomic Safety and Licensing Board Panel 83/06/22 Suffolk County, NY 49pp 19012 197 24X Fiche 50-322, 83/06/22, 8306270144

8306270280 Citizens for Orderly Energy Policy, Inc draft contentions Util can develop emergency plan, per NRC & FEMA stds, to protect public health & safety adequately in event of emergency Certificate of Svc encl
SWARTZ, L L Affiliation Unknown SWARTZ, L L Pacific Legal Foundation 83/06/22 Atomic Safety and Licensing Board Panel 11pp 18996 209 24X Fiche 50-322, 83/06/22, 8306270280

8306280601 Consolidated draft emergency planning contentions of Suffolk County, Shorham Opponents Coalition, North Shore Committee & Town of Southampton, based on util transition plan
LETSCHE, K J Suffolk County, NY LETSCHE, K J, Kirkpatrick, Lockhart, Hill, Christopher & Phillips 83/06/23 Atomic Safety and Licensing Board Panel 174pp 19015 169 24X Fiche 50-322, 83/06/23, 8306280601

--8306280608 Draft emergency planning contentions of Town of Southampton Certificate of Svc encl
SHEA, J F Southampton, NY SHEA, J F, Twomey, Latham & Shea 83/06/22 Atomic Safety and Licensing Board Panel 8pp 19015 343 24X Fiche 50-322, 83/06/23, 8306280601

8306290393 Motion to amend svc list by deleting M Kelly & adding J Feinberg, Notice of appearance & Certificate of Svc encl
FEINBERG, J D Long Island Lighting Co FEINBERG, J D New York, State of, Energy Office 83/06/23 Atomic Safety and Licensing Board Panel 5pp 19055 274 24X Fiche 50-322, 83/06/23, 8306290393

8306270933 Advises that Town of Southampton joins in consolidated draft emergency planning contentions Finalized contentions, to be submitted on 830707, will delineate which intervenor will participate on litigation of individual contentions
MCMURRAY, C M Kirkpatrick, Lockhart, Hill, Christopher & Phillips 83/06/23 LAURENSEN, J A, KLINE, J R, LIVINGSTON, M S Atomic Safety and Licensing Board Panel 1p 19052 315 24X Fiche 50-322, 83/06/23, 8306270933

8306280506 Forwards FEMA 830623 Findings on util transition plan for offsite emergency preparedness
REPKA, D A Hearing Branch 3 83/06/24 LAURENSEN, J A, LIVINGSTON, M S, KLINE, J R Atomic Safety and Licensing Board Panel 22pp 19017 212 24X Fiche 50-322, 83/06/24, 8306280506

8306290480 Forwards answer opposing util motion for low power OL Offsite emergency preparedness insufficient to support full power OL Motion premature since ASLB cannot issue initial decision on controverted matters
DYNNER, A R Kirkpatrick, Lockhart, Hill, Christopher & Phillips DYNNER, A R Suffolk County, NY 83/06/27 BRENNER, L J, CARPENTER, J L Atomic Safety and Licensing Board Panel 5pp 19052 093 24X Fiche 50-322, 83/06/27, 8306290480

--8306290485 Answer opposing util 830608 motion for low power OL Commission has not ruled on certified question on emergency planning Motion premature since ASLB cannot issue partial initial decision
DYNNER, A R Suffolk County, NY DYNNER, A R Kirkpatrick, Lockhart, Hill, Christopher & Phillips 83/06/27 Atomic Safety and Licensing Board Panel 53pp 19052 098 24X Fiche 50-322, 83/06/27, 8306290480

--8306290492 Motion for leave to file contentions re onsite emergency preparedness Revised onsite plan defective & incapable of adequate implementation since County relied upon to participate in & implement plan Certificate of Svc encl
DYNNER, A R Suffolk County, NY 83/06/27 Atomic Safety and Licensing Board Panel 22pp 19052 193 24X Fiche 50-322, 83/06/27, 8306290480

8306290505 Clarifies petition to intervene re BNL dependence on power supplied by PASNY & LILCO PASNY supplies 75% of power over LILCO transmission lines LILCO supplies 25% of power
SWARTZ, L L Pacific Legal Foundation 83/06/27 LAURENSEN, J A, KLINE, J R, LIVINGSTON, M S Atomic Safety and Licensing Board Panel 1p 19052 214 24X Fiche 50-322, 83/06/27, 8306290505

8306300081 Motion for leave to file contentions re onsite emergency preparedness Contentions not capable of final resolution during Phase I emergency planning matters Certificate of Svc encl
DYNNER, A R Suffolk County, NY DYNNER, A R Kirkpatrick, Lockhart, Hill, Christopher & Phillips 83/06/27 Atomic Safety and Licensing Board Panel 23pp 19121 043 24X Fiche 50-322, 83/06/27, 8306300081

8306300094 Response to Citizens for Orderly Energy Policy, Inc 830614 petition to intervene Suffolk County does not oppose petition, but doubts NRC requirements met Certificate of Svc encl
LETSCHE, K J Suffolk County, NY LETSCHE, K J, Kirkpatrick, Lockhart, Hill, Christopher & Phillips 83/06/27 Atomic Safety and Licensing Board Panel 5pp 19048 346 24X Fiche 50-322, 83/06/27, 8306300094

8306300147 Answer supporting Citizens for Orderly Energy Policy, Inc 830614 petition to intervene in proceeding on emergency planning issues Criteria for untimely intervention met Certificate of Svc encl
REVELEY, W T Long Island Lighting Co REVELEY, W T Hutton & Williams 83/06/27 Atomic Safety and Licensing Board Panel 8pp 19122 298 24X Fiche 50-322, 83/06/27, 8306300147

8306300070 Response conditionally supporting util 830608 motion for low-power OL If Commission does not accept directed certification of emergency preparedness issue & items resolved, OL should be issued W/Certificate of Svc
BORDENICK, B M Hearing Branch 3 83/06/29 Atomic Safety and Licensing Board Panel 8pp 19121 003 24X Fiche 50-322, 83/06/29, 8306300070

8306300071 Response opposing Citizens for Orderly Energy Policy, Inc 830614 petition to intervene Citizens lack standing to intervene since no injury in fact shown as result of action W/Certificate of Svc
REPKA, D A Hearing Branch 3 83/06/29 Atomic Safety and Licensing Board Panel 17pp 19122 347 24X Fiche 50-322, 83/06/29, 8306300071

DOCKETED ITEMS

H General correspondence

8306140316 Responds to 830413 ltr forwarding constituent H Jaffe 830407 ltr re further development of nuclear power issue re safety classification of structures, sys & components will not delay plant completion & licensing
DIRCKS, W J Office of the Executive Director for Operations
83/05/23 LENT, N F House of Rep 4pp 18844 339 24X
Fiche 50-322, 83/05/23, 8306140316

--8306140323 Forwards constituent H Jaffe 830409 ltr re allegations that NRC halting efforts to develop nuclear power by delaying nuclear power plant licensing.
LENT, N F House of Rep 83/04/13 COMBS, F NRC - No Detailed Affiliation Given 4pp 18844 344 24X Fiche 50-322, 83/05/23, 8306140316

8306020347 Opposes facility restart
MACLEOD, B. Affiliation Unknown 83/05/26 BRENNER, L Atomic Safety and Licensing Board Panel 1p 18694 320 24X
Fiche 50-322, 83/05/26, 8306020347

8306080194 Requests limited appearance hearings re emergency evaluation planning to be held on Long Island
HICKEY, M, EDBALL, J, NICOTERA, C Affiliation Unknown 83/05/28 LAURENSEN, J Atomic Safety and Licensing Board Panel 12pp 18772 239 24X Fiche 50-322, 83/05/28, 8306080194

8306130401 Expresses concern re util-sponsored emergency plan Commission not ASLB must decide issue
PETIT, M. R. Affiliation Unknown 83/06/06 MORRIS, P Atomic Safety and Licensing Board Panel 2pp 18823 045 24X
Fiche 50-322, 83/06/06, 8306130401

8306270288 Supports independent insp of plant
STIMMERD, T. J. Affiliation Unknown 83/06/13 LAURENSEN, J NRC - No Detailed Affiliation Given 1p 18796 198 24X
Fiche 50-322, 83/06/13, 8306270288

8306290501 Demands public hearings re emergency planning
TERMIN, A Affiliation Unknown 83/06/23 LAURENSEN, J A Atomic Safety and Licensing Board Panel 1p 19052 330 24X
Fiche 50-322, 83/06/23, 8306290501

8306290526 Requests removal of JP Novarro from svc list Related correspondence
BITLER, P. Long Island Lighting Co 83/06/23 Docketing & Services Branch 1p 19052 329 24X Fiche 50-322, 83/06/23, 8306290526

I Inspection reports, IE Bulletins & correspondence

8306060210 Forwards IE Insp Rept 50-322/83-13 on 830426-28 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/05/23 POLLOCK, M S Long Island Lighting Co 2pp 18727 296 24X
Fiche 50-322, 83/05/23, 8306060210

--8306060215 IE Insp Rept 50-322/83-13 on 830426-28. No noncompliance noted. Major areas inspected action on previously identified items, work activities, procedures & records re current status & conduct of const & const QA activities
CERNE, A C Region 1, Office of Director. GALLO, R. M Division of Project & Resident Programs 83/05/18 8pp 18727 298 24X
Fiche 50-322, 83/05/23, 8306060210

8306060265 Forwards IE Insp Rept 50-322/83-14 on 830427-29 & 0506. No noncompliance noted.
STAROSTECKI, R Division of Project & Resident Programs 83/05/25 POLLOCK, M S Long Island Lighting Co 2pp 18727-033 24X
Fiche 50-322, 83/05/25, 8306060265

--8306060268 IE Insp Rept 50-322/83-14 on 830427-29 & 0506. No noncompliance noted. Major areas inspected license actions taken to comply w/requirements in NUREG-0737, Item II. B. 2. "Design Review of Plant Shielding"
KELLY, E. Region 1, Office of Director. GALLO, R. M Division of Project & Resident Programs 83/05/23 8pp 18727-035 24X
Fiche 50-322, 83/05/23, 8306060265

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device." Svc list encl.
TAYLOR, J. M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc. 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8306020071 Notification of 830602 significant license meeting w/util 52W in Hicksville, NY to discuss SAIP
MCCABE, E C Region 1, Office of Director 83/05/24 Region 1, Office of Director 1p 18701 337 24X Fiche 50-322, 83/05/26, 8306020071

8306090067 Forwards IE Insp Rept 50-322/83-10 on 830401-0507 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 83/05/27 POLLOCK, M S Long Island Lighting Co 2pp 18793 290 24X
Fiche 50-322, 83/05/27, 8306090067

--8306090069 Notice of violation from insp on 830401-0507
Region 1, Office of Director 83/05/27 1p 18793 292 24X
Fiche 50-322, 83/05/27, 8306090067

--8306090076 IE Insp Rept 50-322/83-10 on 830401-0507 Noncompliance noted. Failure to assure that changes to emergency diesel generator test procedures distributed & used
HIGGINS, J C, MCCABE, E C, KUNKLE, O L Region 1, Office of Director 83/05/25 14pp 18793 297 24X Fiche 50-322, 83/05/27, 8306090067

8306090128 Forwards IE Insp Rept 50-322/83-11 on 830405-16 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/05/27 POLLOCK, M S Long Island Lighting Co 2pp 18792 237 24X
Fiche 50-322, 83/05/27, 8306090128

--8306090131 IE Insp Rept 50-322/83-11 on 830405-16 No noncompliance noted. Major areas inspected structural acceptance test results evaluation, preoperational test program including status & implementation
NICHOLAS, H H, VARELA, A A, BEITENHAUSEN, L Region 1, Office of Director 83/05/23 13pp 18792 239 24X Fiche 50-322, 83/05/27, 8306090128

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at DWRs." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306070321 Submits addl confirmatory info re containment liner piping penetrations per NRC 830520 telcon info submitted should enable closure of IE Bulletin 80-08 as fuel load requirement
SMITH, J L Long Island Lighting Co 83/05/31 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 18746 081 24X
Fiche 50-322, 83/05/31, 8306070321

8306070440 Provides list of options available to correct deficiencies in separation of electrical cables & raceways noted in IE Insp Rept 50-322/79-07
SCHWENGER, A Licensing Branch 2 83/05/31 POLLOCK, M S Long Island Lighting Co 4pp 18776 359 24X Fiche 50-322, 83/05/31, 8306070440

8306140332 Ack receipt of 830509 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-322/83-05
STAROSTECKI, R Division of Project & Resident Programs 83/05/31 POLLOCK, M S Long Island Lighting Co 1p 18832 159 24X
Fiche 50-322, 83/05/31, 8306140332

--8306140358 Responds to NRC 830330 ltr re violations noted in IE Insp Rept 50-322/83-05 Corrective actions Bailey Meter Co 120-volt ac, 8 7 amp/24-volt dc, 20 amp power supplies certified to provide 24-volt dc 4% output at power supply
MUESELER, W J Long Island Lighting Co 83/05/07 STAROSTECKI, R Division of Project & Resident Programs 7pp 18832 160 24X
Fiche 50-322, 83/05/31, 8306140332

8306140739 Forwards preservice insp plan transmittal & inservice insp field change authorization Receipt ack requested
SMITH, J L Long Island Lighting Co 83/06/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 18841 096 24X
Fiche 50-322, 83/06/01, 8306140739

8306070038 Informs that preservice insp program completed & available for onsite review Program should close out SER Open Item 19
SMITH, J L Long Island Lighting Co 83/06/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18739 339 24X
Fiche 50-322, 83/06/02, 8306070038

8306140494 Ack receipt of 830517 ltr informing NRC of steps taken to correct violations & deviations noted in IE Insp Rept 50-322/83-08. Exceptions to EGF reset position will be reviewed
STAROSTECKI, R Division of Project & Resident Programs 83/06/03 POLLOCK, M S Long Island Lighting Co 2pp 18843 077 24X
Fiche 50-322, 83/06/03, 8306140494

DOCKETED ITEMS

159

--8306140498 Responds to NRC 830415 ltr re violations & deviations noted in IE Insp Rept 50-322/83-08 Corrective actions until startup personnel reviewed field installation of internal wiring to verify wiring installation
POLLOCK, M S Long Island Lighting Co 83/05/17 STAROSTECKI, R Division of Project & Resident Programs 10pp 18843 079 24X Fiche 50-322, 83/06/03, 8306140494

8306210104 Forwards IE Insp Rept 50-322/83-16 on 830510-12 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/06/07 POLLOCK, M S Long Island Lighting Co 2pp 18914 181 24X Fiche 50-322, 83/06/07, 8306210104

--8306210107 IE Insp Rept 50-322/83-16 on 830510-12 No noncompliance noted Major areas inspected licensee work & QC activities re corrective action for significant deficiencies & other outstanding items
NARRON, L J DURR, J P Region 1, Office of Director 83/06/05, 5pp 18914 183 24X Fiche 50-322, 83/06/07, 8306210104

8306140607 Provides addl engineering review in effort to completely resolve confusion associated w/complex issue re EBF reset control (IL Bulletin 80-06)
SMITH, J L Long Island Lighting Co 83/06/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 18833 099 24X Fiche 50-322, 83/06/08, 8306140607

--8306140615 Forwards response to 830415 ltr forwarding IE Insp Rept 50-322/83-08 & App B addressing notice of deviation re II Bulletin 80-06, "ESF Reset Controls"
POLLOCK, M S Long Island Lighting Co 83/05/17 STAROSTECKI, R Region 1, Office of Director 15pp 18833 103 24X Fiche 50-322, 83/06/08, 8306140607

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 110pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8306280265 Clarifies util understanding of insp requirements for jet pump hold-down beams beams retensioned per vendor recommendations & will be included in plant inservice insp program Commitment obviates need for addl preservice insp
SMITH, J L Long Island Lighting Co 83/06/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 8pp 19015 014 24X Fiche 50-322, 83/06/23, 8306280265

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

S Reportable occurrences, LERs & related correspondence

8306010432 Interim deficiency rept re failure of two Darling Valve Co motor-operated globe valves in RHR sys Initially reported on 830330 Operated globe valves by vendor to preclude malfunction
SMITH, J L Long Island Lighting Co 87/05/06 ALLAN, J M Region 1, Office of Director 4pp 18679 306 24X Fiche 50-322, 83/05/06, 8306010432

8306010011 Interim deficiency rept re failure of Brown Boveri K-line 480-volt load ctr circuit breaker prop latch assemblies Initially reported on 830418 Prop latch assemblies mfg in Dec 1974 & Jan & Feb 1975 will be replaced
SMITH, J L Long Island Lighting Co 83/05/18 ALLAN, J M Region 1, Office of Director 3pp 18673 267 24X Fiche 50-322, 83/05/18, 8306010011

8306060349 Board Notification 83-67 forwards info re errors in computer analyses for Mark II containment Rept providing results of evaluations performed by S&W re Shoreham Mark II containment also encl
NOVAK, T M Assistant Director for Licensing 83/05/19 Atomic Safety and Licensing Board Panel 7pp 18753 079 24X Fiche 50-000, 83/05/19, 8306060349

--8306060352 Final deficiency rept re G105H & rocking acceleration data transmittal discrepancy. Initially reported on 821029 & 830318, respectively No changes to plant design required QA Category I load transmittals will be reviewed
MILLIGAN, M H Long Island Lighting Co 83/04/20 ALLAN, J M Region 1, Office of Director 4pp 18733 083 24X Fiche 50-000, 83/05/19, 8306060349

8306020455 Interim deficiency rept re failure of two high pressure fuel oil injector lines on emergency standby diesel generators Initially reported on 830419 Program initiated to replace existing fuel oil injector line tubing
SMITH, J L Long Island Lighting Co 83/05/20 ALLAN, J M Region 1, Office of Director 4pp 18693 301 24X Fiche 50-322, 83/05/20, 8306020455

T Hearing transcripts on non-antitrust matters

8306080439 Forwards Commission determination statement withholding transcript of 830224 meeting from public disclosure
CHILK, B J Office of the Secretary of the Commission 83/05/18, Public Document Branch 1p 18792 213 24X Fiche 50-322, 83/05/18, 8306080439

--8306080442 Commission determination statement withholding transcript of 830224 meeting from public disclosure
CHILK, B J Office of the Secretary of the Commission 83/05/18, Office of the Secretary of the Commission 1p 18792, 214, 24X Fiche 50-322, 83/05/18, 8306080439

8306140263 Transcript of 830610 hearing in Bethesda, MD Pp 21, 179-21, 438
* Atomic Safety and Licensing Board Panel 83/06/10, 260pp 18842 103 24X Fiche 50-322, 83/06/10, 8306140263

U Congressional/Executive Correspondence

8306020229 Forwards answer to Subcommittee on Nuclear Regulation Question 7, in response to 830411 ltr on FY82-83 Authorization Act, Section 5 re current offsite emergency planning controversy
PALLADINO, N J Commissioners 83/05/09, OTTINGER, R L House of Rep 1p 18701 001 24X Fiche 50-322, 83/05/09, 8306020229

--8306020242 Forwards answer to Subcommittee on Nuclear Regulation Question 7, in response to 830411 ltr on FY82-83 Authorization Act, Section 5 re current offsite emergency planning controversy
PALLADINO, N J Commissioners 83/05/09, DOWNEY, T J House of Rep 6pp 18701 002 24X Fiche 50-322, 83/05/09, 8306020229

--8306020248 Emphasizes that NRC must not take undue liberties w/1982 Authorization Act, Section 5 re offsite emergency preparedness NRC cannot consider local govt plan developed by util if plan officially approved by local govt
DOWNEY, T J, OTTINGER, R L House of Rep. 83/04/11 PALLADINO, N J Commissioners 3pp 18701 008, 24X Fiche 50-322, 83/05/09, 8306020229

8306030170 Designates WJ Dircks, Executive Director for Operations, as representative to fact finding panel on facility per 830422 request
PALLADINO, N J Commissioners 83/05/10 CUOMO, M M New York, State of 2pp 18733 333 24X Fiche 50-322, 83/05/10, 8306030170

DOCKETED ITEMS

--8306030176 Requests assistance & participation in fact finding panel re scientific & economic issues surrounding debate on proposed nuclear power plant
CUSHB, H H New York, State of 83/04/22 Commissioners 1p
18733 334 24X Fiche 50-322, 83/05/10, 8306030170

V. Operator Examinations

8306140074 Requests attendance at 830627 meeting w/Region I in King of Prussia, PA to discuss transfer of reactor operating licensing function from Bethesda, MD to Region I of STAROSTECKI, R Division of Project & Resident Programs 83/06/09
POLLOCK, H B Long Island Lighting Co 2pp. 18038 344 24X
Fiche 50-322, 83/06/09, 8306140074

DOCKET 50-323 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 2

A Application/construction stage documents & correspondence

8306030162 Forwards response to Generic Ltr 83-10C re plans & schedules for resolution of TMI Action Item II K J 5, "Automatic Trip of Reactor Coolant Pumps." Util not required to submit analyses supporting selection of pump trip criteria
SCHUYLER, J O Pacific Gas & Electric Co 83/05/31 EISENHUT, D O Division of Licensing 7pp 18703 344. 24X Fiche 50-275, 83/05/31, 8306030162

8306070463 Forwards design verification program status summary as of 830606. Engineering effort & mod const required to be completed prior to fuel load.
DIRCKB, W J Office of the Executive Director for Operations 83/05/31. PALLADINO, N J, QILINSKY, V, AHEARNE, J F Commissioners 12pp. 18780 318 24X Fiche: 50-275, 83/05/31, 8306070463

8306240464 Forwards request for addl info needed to complete review of safety-related masonry walls & necessary corrective actions based on review of 830701 submittal. Info requested within 60 days of ltr receipt
KNIGHTON, Q W Licensing Branch 3 83/06/07 CRANE, P Pacific Gas & Electric Co 5pp 18998 103 24X Fiche 50-275, 83/06/07, 8306240464

8306140031 Forwards background for two articles published in Telegram-Tribune re welding deficiencies. Info confirms misunderstanding between util & reporter. At no time did util review NRC drafts of subg rept
SCHUYLER, J O Pacific Gas & Electric Co 83/06/09 EISENHUT, D O Division of Licensing. 2pp. 18838 331 24X Fiche: 50-275, 83/06/09, 8306140031.

8306210111 Comments on util 790914 & 1228 submittals re moderate energy line breaks. Info responds to NRC request to evaluate plant design for effects of line breaks on equipment required for safe shutdown. Shield barrier requirements eliminated
SCHUYLER, J O Pacific Gas & Electric Co 83/06/15 KNIGHTON, Q W Licensing Branch 3. 1p 18914. 178 24X Fiche: 50-275, 83/06/15, 8306210111

F Security, medical, emergency & fire protection plans

8306170196 Ack receipt & provides evaluation of various changes to emergency plan & corporate emergency plan implementing procedures. Changes do not decrease effectiveness of emergency response planning.
NORDERHAUG, L R Region 5, Office of Director 83/06/13. CRANE, P A Pacific Gas & Electric Co 2pp. 18882. 302 24X
Fiche: 50-275, 83/06/13, 8306170196

8306170305 Ack receipt of Dec 1982, Rev 1 to San Luis Obispo County emergency response plan. FEMA will provide NRC w/written confirmation of results of evaluations.
NORDERHAUG, L R Region 5, Office of Director. 83/06/13 CRANE, P A Pacific Gas & Electric Co. 1p. 18877 145 24X
Fiche: 50-275, 83/06/13, 8306170305

Q. Adjudicatory correspondence

8306060182 Response supporting Governor Deukmejian 830518 motion to reopen record in licensing proceeding re const GA. Further evidence needed re const GA/QC. Certificate of Svc encl.
REYNOLDS, J R Joint Intervenor-Diablo Canyon. REYNOLDS, J R Center for Law in the Public Interest. 83/05/31. Atomic Safety and Licensing Board Panel. 6pp 18728 186. 24X
Fiche: 50-275, 83/05/31, 8306060182.

8306060275 Response opposing Joint Intervenor 830510 & Governor Deukmejian 830517 motions to reopen record on const GA. Const GA program vigorous, thorough & in full compliance w/MIL regulations. Certificate of Svc encl.
NORTON, B Pacific Gas & Electric Co NORTON, B Norton, Burke, Berry & French 83/05/31 Atomic Safety and Licensing Appeal Panel 630pp 18730 031 24X Fiche 50-275, 83/05/31, 8306060275

8306070406 Response supporting Governor Deukmejian 830518 motion to reopen record on const GA. Disclosure of thousands of deficiencies warrants reopening. Certificate of Svc encl.
REYNOLDS, J R Joint Intervenor-Diablo Canyon. 83/05/31 Atomic Safety and Licensing Appeal Panel 5pp 18742 275 24X
Fiche 50-275, 83/05/31, 8306070406

8306150314 Notice of appearance in proceeding. Certificate of Svc encl.
HAVIAN, F Joint Intervenor-Diablo Canyon. HAVIAN, L Center for Law in the Public Interest 83/06/02 5pp 18849 132 24X
Fiche 50-275, 83/06/02, 8306150314

8306150230 Response opposing Joint Intervenor 830510 & Governor Deukmejian 830518 motions to reopen record on const GA. Motions fail to establish significance of info to GA. Findings in ASLB 810717 decision. Certificate of Svc encl.
CHANDLER, L J Hearing Branch 2 83/06/06 Atomic Safety and Licensing Board Panel 176pp 18830 044 24X Fiche 50-275, 83/06/06, 8306150230

8306090309 Order allowing Joint Intervenor & Governor Deukmejian to reply to responses to motions to reopen record on const GA.
by 830620
SHOENAKER, C J Atomic Safety and Licensing Appeal Panel 83/06/07 Joint Intervenor-Diablo Canyon 2pp 18795 191 24X
Fiche: 50-275, 83/06/07, 8306090309

8306150435 Petition for review of ASLB 830518 Decision ALAB-728, to establish schedule for briefing on issues raised & to reverse ASLB rulings in ALAB-728. Certificate of Svc encl.
REYNOLDS, J R Joint Intervenor-Diablo Canyon. REYNOLDS, J R Center for Law in the Public Interest 83/06/08 Commissioners 15pp 18847. 030 24X Fiche 50-275, 83/06/08, 8306150435

8306160579 First document production request. Related correspondence
NORTON, B Pacific Gas & Electric Co NORTON, B Norton, Burke, Berry & French 83/06/10 Joint Intervenor-Diablo Canyon 4pp 18866 161 24X Fiche 50-275, 83/06/10, 8306160579

--8306160584 First set of interrogatories. Related correspondence
NORTON, B Pacific Gas & Electric Co NORTON, B Norton, Burke, Berry & French 83/06/10 California, State of 17pp 18866 167 24X Fiche 50-275, 83/06/10, 8306160579

--8306160595 First set of interrogatories. Certificate of Svc encl. Related correspondence
NORTON, B Pacific Gas & Electric Co NORTON, B Norton, Burke, Berry & French 83/06/10 Joint Intervenor-Diablo Canyon 17pp 18866 184 24X Fiche 50-275, 83/06/10, 8306160579

8306140702 Notice of withdrawal of appearance in proceeding. Certificate of Svc encl.
GOLDBERG, J R Hearing Branch 2 83/06/13 3pp 18841 271 24X
Fiche 50-275, 83/06/13, 8306140702

8306220038 Response opposing util & NRC responses to intervenor motions to reopen issue on const GA. NRC ignored util improper & rampant disregard of GA requirement & obsession w/hearing speed & scheduling. Certificate of Svc encl.
REYNOLDS, J R Joint Intervenor-Diablo Canyon. REYNOLDS, J R Center for Law in the Public Interest 83/06/17 Atomic Safety and Licensing Appeal Panel 11pp 18930 180 24X
Fiche: 50-275, 83/06/17, 8306220038

8306220045 Reply to responses of NRC & util to Governor Deukmejian motion to reopen record on const GA. Submits new evidence of safety regulation violations & contends NRC & util response unacceptable.
KAUFMAN, P H California, State of 83/06/17 Atomic Safety and Licensing Appeal Panel 45pp 18927 289 24X Fiche 50-275, 83/06/17, 8306220045

--8306220052 Affidavit of R Hubbard re breakdowns in design & const GA/QC program & implementation. Util & NRC did not include significant items in const GA review. Implementation of GA/QC measures unacceptable. Certificate of Svc encl.
HUBBARD, R B California, State of 83/06/15 14pp 18927 305 24X Fiche: 50-275, 83/06/17, 8306220045

8306240275 Response opposing Joint Intervenor 830608 petition for review of ALAB-728. No important safety, procedural, common defense, antitrust or public policy issues raised. Certificate of Svc encl.
CHANDLER, L J Hearing Branch 2. 83/06/23 Commissioners 14pp 18980 080 24X Fiche: 50-275, 83/06/23, 8306240275

DOCKETED ITEMS

161

8306280522 Answer opposing Joint Intervenor's B30608 petition for review of ALAD-728 Joint Intervenor's fail to respond to rationale of ASLB decision Certificate of Evc encl
CRANE, P A Pacific Gas & Electric Co 83/06/23 Commissioners
7pp 19019 317 24X Fiche 50-275, 83/06/23, 8306280522

8306290435 Advises of concerns re evidence presented at B30614 independent design verification program meeting w/uttl/ Bechtel licensing team Util fails to appreciate meaning/ necessity of program Related correspondence
REYNOLDS, J R Center for Law in the Public Interest REYNOLDS, J R Joint Intervenor's-Diablo Canyon 83/06/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 19052 318 24X
Fiche 50-275, 83/06/23, 8306290435

8306280520 Proposes schedule for reopened hearings on design QA
NORTON, B Pacific Gas & Electric Co 83/06/24 Atomic Safety and Licensing Appeal Panel 3pp 19017 186 24X Fiche 50-275, 83/06/24, 8306280520

8306300052 Order scheduling B30/19 hearing on Governor Deukmejian & Joint Intervenor's motions to reopen record on const QA issue NRC to provide ASLB & parties w/NRC insp repts on const QA by B30708
SHOENAKEN, C J Atomic Safety and Licensing Appeal Panel 83/06/28 Office of the Executive Legal Director 4pp 19120 189 24X
Fiche 50-275, 83/06/28, 8306300052

8306300064 Requests that arrangements be made for removal & storage of security mats in NRC storage room Room requires repair & is needed for other purpose.
CHANDLER, L J Hearing Branch 2 83/06/29 STRUMWASSEN, M California, State of 1p 19121 011 24X Fiche 50-275, 83/06/29, 8306300064

H General correspondence

8306010336 Expresses alarm re recent news rept that PQ&E officials had seen preliminary drafts of NRC investigation rept concerning QA violations NRC investigation requested
REYNOLDS, J R Joint Intervenor's-Diablo Canyon REYNOLDS, J R Center for Law in the Public Interest 83/05/25 EISENHUT, D G Division of Licensing 4pp 18680 072 24X Fiche 50-275, 83/05/25, 8306010336

8306070036 Provides names & addresses for appropriate distribution of technical correspondence re facilities
SCHUYLER, J D Pacific Gas & Electric Co 83/06/02 DENTON, H R Office of Nuclear Reactor Regulation, Director EISENHUT, D G Division of Licensing MARTIN, J B Region 5, Office of Director 2pp 18739 337 24X Fiche 50-000, 83/06/02, 8306070036

Q Inspection reports, IE Bulletins & correspondence

8306100007 Addl response to FOIA request for documents dtd B20101 or after re BALP Forwards App A documents Documents also available in PDR
FELTON, J M Division of Rules and Records 83/04/11 CLARK, R Sm, Francisco Examiner 3pp 18815 252 24X Fiche 50-000, 83/04/11, 8306100007

--8306100014 Submits schedule for Region V BALP Board meetings for B20928-030523
ENGELKEN, R H Region 5, Office of Director 82/03/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18815 255 24X Fiche 50-000, 83/04/11, 8306100007

--8306100036 Discusses assignment of BALP coordinators for Reactor Operations Projects Branch facilities Coordinators will be responsible for preparing input data used by board members in analyzing functional areas Draft note from B Miner encl
STERNBERG, D M Region 5, Office of Director 82/03/24 Region 5, Office of Director 11pp 18815 P57 24X
Fiche 50-000, 83/04/11, 8306100007

8306070360 Forwards IE Insp Repts 50-275/83-15 & 50-323/83-12 on B30418-22 No noncompliance noted
BISHOP, T W Region 5, Office of Director 83/05/03 CRANE, P A Pacific Gas & Electric Co 2pp 18742 116 24X
Fiche 50-275, 83/05/03, 8306070360

--8306070369 IE Insp Repts 50-275/83-15 & 50-323/83-12 on B30418-22 No noncompliance noted Major areas inspected const activities & mods to annulus structural steel ventilation duct support, containment spray piping supports & circuit breakers
BURDOIN, J F, ZHETZIO, Q H Region 5, Office of Director 83/04/29 5pp 18742 118 24X Fiche 50-275, 83/05/03, 8306070360

8306070093 Forwards IE Insp Repts 50-275/83-14 & 50-323/83-11 on B30301-02 & 31 No noncompliance noted
BISHOP, T W Region 5, Office of Director 83/05/11 CRANE, P A Pacific Gas & Electric Co 2pp 18739 135 24X
Fiche 50-275, 83/05/11, 8306070093

--8306070098 IE Insp Repts 50-275/83-14 & 50-323/83-11 on B30301-02 & 31 No noncompliance noted Major areas inspected IE bulletins & circulars, followup on previous licensee commitments & independent insp
MORRILL, P J, KIRSCH, D F Region 5, Office of Director 83/05/09 4pp 18739 137 24X Fiche 50-275, 83/05/11, 8306070093

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post B30103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8306280189 Forwards IE Insp Repts 50-275/83-17 & 50-323/83-13 on B30403-30 & notice of violation W/g notice of violation
BISHOP, T W Region 5, Office of Director 83/05/26 CRANE, P A Pacific Gas & Electric Co 2pp 19014 124 24X
Fiche 50-275, 83/05/26, 8306280189

--8306280194 IE Insp Repts 50-275/83-17 & 50-323/83-13 on B30403-30 Noncompliance noted Failure of general const personnel to inform plant manager of observed damage to RCS piping
CARLSON, J D, MENDONCA, M M, KIRSCH, D F Region 5, Office of Director 83/05/25 10pp 19014 126 24X Fiche 50-275, 83/05/26, 8306280189

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306300041 Responds to IE Bulletin re check valve failures in raw water cooling sys of diesel generators Check valves not used in closed-loop jacket cooling water sys
SCHUYLER, J D, CRANE, P A Pacific Gas & Electric Co 83/06/06 MARTIN, J B Region 5, Office of Director 2pp 19168 129 24X
Fiche 50-275, 83/06/06, 8306300041

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/06/09 Consolidated Edison Co of New York, Inc 117pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards, " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/06/22 Consolidated Edison Co of New York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

DOCKETED ITEMS

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 14ppp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

R Periodic operating reports & related correspondence

8306210162 Forwards "Phase II Final Rept. Design Verification Program," per 81119 ltr specifying requirements for addl info
BRAND, D A Pacific Gas & Electric Co 83/06/13 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 18915 290 24X
Fiche 50-275, 83/06/13, 8306210162

--8306210171 "Phase II Final Rept. Design Verification Program"
* Pacific Gas & Electric Co 83/06/30 100pp 18915 291 24X
Fiche 50-275, 83/06/13, 8306210162

S Reportable occurrences, LERs & related correspondence

8305110488 Board Notification 83-73 Forwards 830309 ltr & PNO-V-83-021 re potential for inadequate welds in component cooling water piping sys
EISENHUT, D Q Division of Licensing 83/06/20 PALLADINO, N J,
OILINSKY, V, AHEARNE, J F Commissioners. 6pp 18978 003 24X
Fiche 50-275, 83/06/20, 8305110488

V. Operator Examinations

8306240465 Approves 830315 request for variance in std cold license certification on program, allowing abbreviated 3 wk version of Phase II program for 11 on-shift operators
KNIGHTON, O W Licensing Branch 3, 83/06/13 CRANE, P A Pacific Gas & Electric Co 2pp 18978 101 24X Fiche 50-275, 83/06/13, 8306240465.

DOCKET 50-324 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8306140698 Ack receipt of 830131 ltr informing NRC of corrective actions taken in response to 821101 confirmation of action ltr re emergency preparedness program
LEWIS, R C Division of Project & Resident Programs 83/03/31
FURR, B J Carolina Power & Light Co. 1p 18841 268 24X
Fiche 50-000, 83/03/31, 8306140698

--8306140708 Submits status of corrective actions for deficiencies noted in 821101 confirmation of action ltr re emergency preparedness program
UTLEY, E E Carolina Power & Light Co. 83/01/31 O'REILLY, J P
Region 2, Office of Director. 2pp 18841 269 24X
Fiche 50-000, 83/03/31, 8306140698

8306220273 Confirms telcon w/IE re acceptability of emergency response facilities Locations of alternate locations for offsite personnel to assemble to communicate w/emergency operations facilities acceptable
HURFORD, W J Carolina Power & Light Co 83/06/17 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 18926 033 24X
Fiche 50-000, 83/06/17, 8306220273

J. Insurance & indemnity information

8306210082 Forwards Endorsement 49 to NELA Policy NF-218.
BARHAM, C D Carolina Power & Light Co 83/06/13 SALTZMAN, J
Antitrust & Economic analysis Branch (Utility Finance). 2pp
18911 237 24X Fiche 50-324, 83/06/13, 8306210082.

8306210109 Forwards Endorsement 42 to MAELU Policy NF-80
BARHAM, C D Carolina Power & Light Co 83/06/13 SALTZMAN, J NRC
- No Detailed Affiliation Given. 2pp. 18914 179 24X
Fiche 50-324, 83/06/13, 8306210109

P. Operating license stage documents & correspondence

8306020020 Informs that, based on review of BWR Owners Group 801230 response to NUREG-0737, Item II K 3 45, "Depressurization w/ Other Than Automatic Depressurization Sys," complete
VASSALLO, D B Operating Reactors Branch 2 83/05/18 UTLEY, E E
Carolina Power & Light Co. 7pp. 18702 326 24X
Fiche 50-324, 83/05/18, 8306020020.

8306080080 Forwards nonproprietary & proprietary versions of NF-1583 04, "Verification of CP&L Ref BWR Thermal-Hydraulic Methods Using FIDWR Code" Affidavit encl Proprietary version withheld (ref 10CFR2 790)
ZIMMERMAN, S R Carolina Power & Light Co 83/05/31 VASSALLO, D B
Operating Reactors Branch 2 6pp 13/71 029 24X
Fiche 50-324, 83/05/31, 8306080080

--8306080083 Nonproprietary "Verification of CP&L Ref BWR Thermal Hydraulic Methods Using FIDWR Code"
POPE, M A, KUNITA, R K Carolina Power & Light Co NF-1583 04
(NP) 83/05/18 41pp 18711 035 24X Fiche 50-324, 83/05/31, 8306080080

8306070035 Responds to 830414 request for addl info re structural aspects of Mark I containment program plant-unique analysis rept Util in process of obtaining info from United Engineers & Constructors Response will be provided by 830805
ZIMMERMAN, S R Carolina Power & Light Co 83/06/02 VASSALLO, D B
Operating Reactors Branch 2 1p 18704 335 24X
Fiche 50-324, 83/06/02, 8306070035

8306150464 Forwards request for addl info re review of structural aspects of plant-unique analysis rept for Mark I long-term containment program Meeting should be held within 3 wks to discuss response
VASSALLO, D B Operating Reactors Branch 2 83/06/03 UTLEY, E E
Carolina Power & Light Co 6pp 18849 206 24X
Fiche 50-324, 83/06/03, 8306150464

8306240246 Discusses justification for continued safe operation of facility pending NRC issuance of necessary Tech Spec revs to support Cycle 4 Revs re plant sys actuation instrumentation expected within 30 days of startup
HOWE, F W Carolina Power & Light Co 83/06/20 VASSALLO, D B
Operating Reactors Branch 2 3pp 18700 168 24X
Fiche 50-324, 83/06/20, 8306240246

8306240008 Forwards "Reactor Containment Bldg Integrated Leak Rate Test" Test failed acceptance criteria during initial performance Next integrated leak rate test scheduled for Fall 1983 maint outage
DIETZ, C R Carolina Power & Light Co 83/06/21 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 18981 117 24X
Fiche 50-324, 83/06/21, 8306240008

--8306240012 "Reactor Containment Bldg Integrated Leak Rate Test"
LEVINSON, E D General Physics Corp GP-R-74002 82/07/31
175pp 18981 118 24X Fiche 50-324, 83/06/21, 8306240008

8306270225 Forwards results of plant-unique calculations which form bases for mod program in response to Generic Ltr 83-08, "Mod of Mark I Containment Vacuum Breakers"
ZIMMERMAN, S R Carolina Power & Light Co 83/06/23 VASSALLO, D B
Operating Reactors Branch 2 85pp 10788 293 24X
Fiche 50-324, 83/06/23, 8306270225

--8306270226 Rev 1 to "Improved Dynamic Vacuum Breaker Valve Response for Brunswick Plant"
* Continuum Dynamics, Inc 82/09/30 27pp 18989 016 24X
Fiche 50-324, 83/06/23, 8306270225

--8306270230 Rev 0 to "Mark I Vacuum Breaker Improved Valve Dynamic Model - Model Development & Validation"
SULLIVAN, J M Continuum Dynamics, Inc 82-31 R00 82/08/31
40pp 18989 043 24X Fiche 50-324, 83/06/23, 8306270225

8306280524 Supplemental application for amend to Licenses DPR-71 & DPR-62, revising Tech Specs re RCIC sys actuation instrumentation, per Generic Ltr 83-02 & NUREG-0737 items
HOWE, F W Carolina Power & Light Co 83/06/23 VASSALLO, D B
Operating Reactors Branch 2 4pp 19019 290 24X
Fiche 50-324, 83/06/23, 8306280524

--8306280544 Revised Tech Specs re RCIC sys actuation instrumentation
* Carolina Power & Light Co 83/06/23 21pp 19019 294 24X
Fiche 50-324, 83/06/23, 8306280524

Q Inspection reports, IE Bulletins & correspondence

8306140735 Confirms IE mgt meeting on 830318 at plant site to discuss status of facility improvement program Proposed meeting agenda encl
O'REILLY, J P Region 2, Office of Director 83/03/10, UTLEY, E E
Carolina Power & Light Co 2pp 18841 092 24X
Fiche 50-324, 83/03/10, 8306140735

DOCKETED ITEMS

163

8306140698 Ack receipt of 830131 ltr informing NRC of corrective actions taken in response to 821101 confirmation of action ltr re emergency preparedness program
LEWIS, R C Division of Project & Resident Programs 83/07/31
FURR, D J Carolina Power & Light Co 1p 18841 268 24X
Fiche 50-000, 83/03/31, 8306140698

--8306140708 Submits status of corrective actions for deficiencies noted in 821101 confirmation of action ltr re emergency preparedness program
UTLEY, E E Carolina Power & Light Co 83/01/31 O'REILLY, J P
Region 2, Office of Director 2pp 18841 269 24X
Fiche 50-000, 83/03/31, 8306140698

8306140397 Confirms 830510 mgt meeting in Raleigh, NC to review BALP program (first phase) results, per 830412 telcon Proposed agenda encl
LEWIS, R C Division of Project & Resident Programs 83/04/29
UTLEY, E E Carolina Power & Light Co 3pp 18832 093 24X
Fiche 50 000, 83/04/29, 8306140397

8306140547 Responds to Rev 1 to IE Bulletin 82-03 re reactor recirculation & RHR sys Defective welds repaired using weld overlay technique Weld indication tables & isometric drawings of defective weld locations encl
HOWE, P W Carolina Power & Light Co 83/05/16 O'REILLY, J P
Region 2, Office of Director 7pp 18043 281 24X
Fiche 50-324, 83/05/16, 8306140547

--8306140549 "Design Rept for Recirculation Sys Weld Overlay Repairs at Brunswick Steam Electric Plant, Unit 1"
CHARNLEY, J E, REEVES, P E, ADAMS, R H NUTECH Engineers, Inc
CPL-09-102 R00 83/05/05 75pp 18343 288 24X
Fiche 50-324, 83/05/16, 8306140547

8306020107 Forwards safety evaluation & notice of granting relief from inservice insp requirements
VASSALLO, D D Operating Reactors Branch 2 83/05/19 UTLEY, E E
Carolina Power & Light Co 3pp 18701 120 24X
Fiche 50 324, 83/05/19, 8306020107

--8306020116 Safety evaluation granting in part & denying in part, requests for exemption from inservice insp requirements
* Office of Nuclear Reactor Regulation, Director 83/05/19 0pp
18701 120 24X Fiche 50-324, 83/05/19, 8306020107

--8306020290 Notice granting in part & denying in part, relief from ASME Code Section XI inservice insp requirements
VASSALLO, D D, Operating Reactors Branch 2 83/05/19 2pp
18701 144 24X Fiche 50-324, 83/05/19, 8306020107

8306010311 Forwards "Environ Qualification of Electrical Equipment, Brunswick Steam Electric Plant, Units 1 & 2 - 10CRH-50 49 - 90 Day Response," Vols I & II, per IE Bulletin 79-01B & 820411 request list of items to be qualified encl
UTLEY, E E Carolina Power & Light Co 83/05/20 VASSALLO, D D
Operating Reactors Branch 2 79pp 18669 147 24X
Fiche 50-324, 83/05/20, 8306010311

8306140396 Ack receipt of 830505 ltr informing NRC of steps taken to correct violations noted in IE Special Training Assessment Repts 50-324/83-04 & 50-325/83-04
VERRELLI, D M Division of Project & Resident Programs 83/05/24
UTLEY, E E Carolina Power & Light Co 1p 18838 003 24X
Fiche 50-324, 83/05/24, 8306140396

--8306140404 Responds to NRC 830207 ltr re violations noted in IE Special Training Assessment Repts 50-324/83-04 & 50-325/83-04
Corrective actions orientation for new employees accomplished in accordance w/ TI-301
DIETZ, C R Carolina Power & Light Co 83/05/05 O'REILLY, J P
Region 2, Office of Director 3pp 18838 004 24X
Fiche 50-324, 83/05/24, 8306140396

--8306140412 Forwards IE Special Training Assessment Repts 50-324/83-04 & 50-325/83-04 on 830110-14 No noncompliance noted Significant weaknesses identified
VERRELLI, D M Division of Project & Resident Programs 83/02/07
UTLEY, E E Carolina Power & Light Co 2pp 18838 007 24X
Fiche 50-324, 83/05/24, 8306140396

--8306140423 IE Special Training Assessment Repts 50-324/83-04 & 50-325/83-04 on 830110-14 No noncompliance noted Major areas inspected licensed & nonlicensed operator training & requalification programs & on-shift/real time training
HEHL, C W, CASIATT, M E, RAULIN, K A Region 2, Office of Director 83/02/03 10pp 18838 009 24X Fiche 50-324, 83/05/24, 8306140396

8306140194 Forwards IE Mgt Meeting Repts 50-324/83-19 & 50-325/83-19 on 830518 Concerns re violations of regulatory requirements & mgt control raised
O'REILLY, J P Region 2, Office of Director 83/05/25 UTLEY, E E
Carolina Power & Light Co 2pp 18833 033 24X
Fiche 50-324, 83/05/25, 8306140194

--8306140201 IE Mgt Meeting Repts 50-324/83-19 & 50-325/83-19 on 830518
Major areas discussed enforcement issues resulting from recent events at site involving inoperability of Unit 2 condenser offgas monitoring sys
LEWIS, R C Division of Project & Resident Programs 83/05/24
3pp 18833 035 24X Fiche 50-324, 83/05/25, 8306140194

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc
125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8306140653 Ack receipt of 830523 ltr documenting 830527 commitment date for O-list procedure rev, in response to IE Insp Repts 50-324/82-45 & 50-325/82-45
VERRELLI, D M Division of Project & Resident Programs 83/05/27
UTLEY, E E Carolina Power & Light Co 1p 18843 006 24X
Fiche 50-324, 83/05/27, 8306140653

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BHRs" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306140677 Ack receipt of 830520 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/83-05 & 50-325/83-05
VERRELLI, D M Division of Project & Resident Programs 83/06/07
UTLEY, E E Carolina Power & Light Co 1p 18841 351 24X
Fiche 50-324, 83/06/07, 8306140677

--8306140682 Responds to NRC 830407 ltr re violations noted in IE Insp Repts 50-324/83-05 & 50-325/83-05 Corrective actions, operating procedures revised to accurately reflect desired position of fuel oil manual fill valves
DIETZ, C R Carolina Power & Light Co 83/05/20 O'REILLY, J P
Region 2, Office of Director 2pp 18841 352 24X
Fiche 50-324, 83/06/07, 8306140677

--8306140688 Ack receipt of IE Insp Repts 50-324/83-05 & 50-325/83-05 & notice of violation Response to rept will be submitted by 830520
DIETZ, C R Carolina Power & Light Co 83/05/05 O'REILLY, J P
Region 2, Office of Director 1p 18841 354 24X
Fiche 50-324, 83/06/07, 8306140677

--8306140693 Forwards IE Insp Repts 50-324/83-05 & 50-325/83-05 on 830215-0315 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 83/04/07
UTLEY, E E Carolina Power & Light Co 2pp 18841 355 24X
Fiche 50-324, 83/06/07, 8306140677

--8306140699 Notice of violation from insp on 830215-0315
* Region 2, Office of Director 83/04/07, 1p, 18841 357 24X
Fiche 50-324, 83/06/07, 8306140677

--8306140705 IE Insp Repts 50-324/83-05 & 50-325/83-05 on 830215-0315
Noncompliance noted inadequate operating procedures for filling emergency power diesel generator fuel oil tanks & lack of ventilation of svc water valves
MYERS, D D, GARNER, L W Region 2, Office of Director 83/04/07 9pp 18841 358 24X Fiche 50-324, 83/06/07, 8306140677

8306290402 Responds to IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators," per 830310 ltr, TECHN check valves used at facilities Valve arrangement drawings encl
HOWE, P W Carolina Power & Light Co 83/06/08 O'REILLY, J P
Region 2, Office of Director 2pp 17083 127, 24X
Fiche 50-324, 83/06/08, 8306290402

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 117pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

DOCKETED ITEMS

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp. 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8306290524 Approves issuance of SALP rept Notes improvement in safety-related activities, emergency preparedness & security & safeguards weaknesses in GA program will be monitored
O'REILLY, J P Region 2, Office of Director 83/06/14 UTLEY, E E Carolina Power & Light Co 5pp 19049 282 24X Fiche 50-000, 83/06/14, 8306290524

--8306290531 Forwards SALP Repts 50-325/83-09, 50-324/83-09, 50-261/83-01, 50-400/83-10 & 50-401/83-10 for Jan 1982 - Jan 1983
Evaluation will be discussed in Raleigh, NC on 830510
LEWIS, R C Division of Project & Resident Programs 83/05/03
UTLEY, E E Carolina Power & Light Co 2pp 19049 287 24X Fiche 50-000, 83/05/14, 8306290524

--8306290537 SALP rept for Jan 1982 - Jan 1983
* Region 2, Office of Director 83/05/03 64pp 19049 289 24X Fiche: 50-000, 83/06/14, 8306290524

--8306290553 Responds to 830503 SALP rept for Jan 1982 - Jan 1983 Reduced NRC attention may be appropriate for Category I re fire protection NRC attention should be maintained at normal levels for emergency preparedness
UTLEY, E E Carolina Power & Light Co 83/05/20. O'REILLY, J P Region 2, Office of Director 16pp 19049 354 24X Fiche: 50-000, 83/06/14, 8306290524.

--8306290555 Forwards replacement Page 2 to Attachment 2 of 830520 ltr which commented on SALP rept.
LURY, L W Carolina Power & Light Co 83/05/27. O'REILLY, J P Region 2, Office of Director 2pp 19050 009. 24X Fiche 50-000, 83/06/14, 8306290524

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc. 115pp 19021 179. 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007. 24X Fiche: 50-000, 83/06/22, 8305110477.

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp. 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc. 116pp. 19046 297. 24X Fiche 50-000, 83/06/24, 8305110483

8306300102 Ack receipt of 830502 ltr in response to notice of violation & proposed imposition of civil penalties from insps on 820712-14 & 20-22 Corrective actions responsive to problems but initiated only after violations confirmed.
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement. 83/06/28 UTLEY, E E. Carolina Power & Light Co 3pp 19048 207. 24X Fiche. 50-324, 83/06/28, 8306300102.

--8306300108 Order imposing civil penalties in amount of \$600,000 for violations identified during insps on 820712-14 & 20-22.
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/06/28. Carolina Power & Light Co. 6pp. 19048: 210. 24X Fiche: 50-324, 83/06/28, 8306300102.

R. Periodic operating reports & related correspondence

8306140214 Monthly operating repts for May 1983 W/830607 ltr
HARRISON, F., DIETZ, C R Carolina Power & Light Co. 83/06/07.
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement. 14pp. 18932 272 24X Fiche: 50-324, 83/06/07, 8306140214

S Reportable occurrences, LERs & related correspondence

8306140629 Confirms 830518 onsite enforcement meeting to discuss regulatory issues re isolation of Unit 2 condenser offgas radiation monitors, per 830516 telcon Proposed agenda encl
O'REILLY, J P Region 2, Office of Director 83/05/16 UTLEY, E E Carolina Power & Light Co 2pp 18842 087 24X Fiche 50-324, 83/05/16, 8306140629

8306010109 LER 83-036/03L-0 on 830424, routine surveillance revealed that primary containment multi-plant temp recorder showed temp indications but printed erratically Caused by failed 5 s timing relay which prevented printing W/830518 ltr
PASTVA, M J, DIETZ, C R Carolina Power & Light Co 83/05/10
O'REILLY, J P Region 2, Office of Director 2pp 18673 140 24X Fiche 50-324, 83/05/18, 8306010109

8306010105 Updated LER 82-131/03L-2 on 821206, 1/2 automatic reactor scram signal received due to instrument downscale signal from main steam/line radiation monitor D, 2-D12-RM-K603D Caused by loss of high voltage input to relay W/830523 ltr
PASTVA, M J, DIETZ, C R Carolina Power & Light Co 83/05/23
O'REILLY, J P Region 2, Office of Director 2pp 18674 040 24X Fiche 50-324, 83/05/23, 8306010105

8306010388 RO on 830509, main condenser steam jet air ejector offgas radiation monitors A & B failed to indicate power level Caused by closure of root isolation valves to each monitor Shift personnel counseled
DIETZ, C R Carolina Power & Light Co 83/05/23 O'REILLY, J P Region 2, Office of Director 5pp 18682 174 24X Fiche 50-324, 83/05/23, 8306010388

8306070097 LER 83-040/03L-0 on 830424, while performing operability test of remote shutdown RHR sys flow monitoring instrumentation PT-55 OPC, determined RHR sys flow transmitter 2-E11-F1-333H had no output response to applied test signal W/830526 ltr
PASTVA, M J, DIETZ, C R Carolina Power & Light Co 83/05/26
O'REILLY, J P Region 2, Office of Director 2pp 18739 210 24X Fiche 50-324, 83/05/26, 8306070097

8306070141 Suppl to special RO rept on 830509, main condenser steam jet air ejector offgas radiation monitors A & B found not indicating as expected for 2,320 power level Caused by closure of root isolation valves
DIETZ, C R Carolina Power & Light Co 83/05/29 O'REILLY, J P Region 2, Office of Director 5pp 18739 257 24X Fiche 50-324, 83/05/29, 8306070141

8306070102 Updated LER 83-002/03L-2 on 830102, during performance of PT-08 1 6, indicator 2-CAC-LR-2602 showed level of -31 inches while redundant indicators 2-CAC-LR-2601-1 & 3 & local level indicator showed level of -29 inches W/830531 ltr
PASTVA, M J, DIETZ, C R Carolina Power & Light Co 83/05/31
O'REILLY, J P Region 2, Office of Director 3pp 18739 197 24X Fiche 50-324, 83/05/31, 8306070102

8306070235 Updated LER 83-026/03L-2 on 830313, suppression pool level indicator/recorder 2-CAC-LR-2602 showed out-of-spec low level while redundant level indicators showed normal level Caused by transmitter LT-2602 out of calibr W/830531 ltr
PASTVA, M J, DIETZ, C R Carolina Power & Light Co 83/05/31
O'REILLY, J P Region 2, Office of Director 3pp 18741 159 24X Fiche 50-324, 83/05/31, 8306070235

8306070342 RO increased Co-60 activity found in two bottom sediment samples collected 830405 & 06 No Co-60 found in surface water samples from intake & discharge canals during Apr 1983 No radiation hazard or exposure to public observed
DIETZ, C R Carolina Power & Light Co 83/05/31 O'REILLY, J P Region 2, Office of Director 2pp 18741 294 24X Fiche 50-324, 83/05/31, 8306070342

8306100177 RO on 830521, during power operation, electrical panels H85 & H86 discovered deenergized basic ground rules by which test & const personnel may operate equipment not well understood at time of discovery
DIETZ, C R Carolina Power & Light Co 83/06/03 O'REILLY, J P Region 2, Office of Director 3pp 18806 032 24X Fiche 50-324, 83/06/03, 8306100177

8306130455 Forwards NRR comments on draft AU rept to Congress for First Quarter 1983
DENTON, H R Office of Nuclear Reactor Regulation, Director 83/06/07. HELTEMES, C J Director's Office 3pp 18830 176 24X Fiche 50-000, 83/06/07, 8306130455

8306200003 LER 83-049/03L-0 on 830511, main steam line channel instrument 2-D12-RM-K603D found actuating out of specified tolerances Caused by reverse diode VR5 failure in channel instrument drawer VR5 replaced W/830609 ltr
PASTVA, M J, DIETZ, C R Carolina Power & Light Co 83/06/09.
O'REILLY, J P Region 2, Office of Director 2pp 18903 360 24X Fiche: 50-324, 83/06/09, 8306200003

8306270119 RD on 830512 & 19, Fire Doors 106 109 & 201 declared inoperable due to high differential air pressure across each door preventing automatic self-closure Evaluation of air pressure problem underway
DIETZ, C R Carolina Power & Light Co 83/06/09 O'REILLY, J P
Region 2, Office of Director 1p 18788 112 24X
Fiche 50-324, 83/06/09, 8306270119

8306270196 RD on 830504, limiting condition for operation initiated for inoperable Fire Door 208 on 49 ft elevation of control bldg Caused by misalignment of door within door frame Door to be repaired upon receipt of parts
DIETZ, C R Carolina Power & Light Co 83/06/09 O'REILLY, J P
Region 2, Office of Director 1p 18791 286 24X
Fiche 50-324, 83/06/09, 8306270196

8306210096 IER 83-047/03L-0 on 830513, during supervisory technical review of completed test procedure for fire suppression water sys valve operability test, two sys valves not covered Test procedure temporarily revised W/830610 ltr
PASTVA, M J, DIETZ, C R Carolina Power & Light Co 83/06/10
O'REILLY, J P Region 2, Office of Director 3pp 18914 211 24X
Fiche 50-324, 83/06/10, 8306210096

8306270061 IER 83-048/03L-0 on 830520, surveillance revealed primary containment atmosphere oxygen analyzer 2-(AC-AT-1259-2 drywell oxygen concentration 1% higher than redundant analyzer Caused by caliber drift W/830614 ltr
PASTVA, M J, DIETZ, C R Carolina Power & Light Co 83/06/14
O'REILLY, J P Region 2, Office of Director 2pp 18788 050 24X
Fiche 50-324, 83/06/14, 8306270061

8306270245 RD on 830513, limiting condition of operation initiated for Fire Door 202 in diesel generator bldg Door inoperable due to high differential air pressure encountered across door preventing self-closure
DIETZ, C R Carolina Power & Light Co 83/06/14 O'REILLY, J P
Region 2, Office of Director 1p 18790 277 24X
Fiche 50-324, 83/06/14, 8306270245

8306270199 IER 83-035/03L-0 on 830520, reactor water cleanup differential flow indicator 2-G31 R615 indicated high Caused by low output signal from flow transmitter FT N012 Transmitter calibr & returned to svr W/830615 ltr
PASTVA, M J, DIETZ, C R Carolina Power & Light Co 83/06/15
O'REILLY, J P Region 2, Office of Director 3pp 18791 281 24X
Fiche 50-324, 83/06/15, 8306270199

8306270277 IER 83-041/03L-0 on 830520, rod drift annunciation received for control rod 38-39 Caused by problem in rod position indication probe Annunciation cleared Problem will be resolved during Sept 1983 outage W/830617 ltr
PASTVA, M J, DIETZ, C R Carolina Power & Light Co 83/06/17
O'REILLY, J P Region 2, Office of Director 2pp 18796 160 24X
Fiche 50-324, 83/06/17, 8306270277

8306300193 RD on 830502, gamma analysis of bottom sediment sample detected excessive Co-60 activity Sampling frequency increased from semiannually to monthly Sample represents seventh monthly sample
DIETZ, C R Carolina Power & Light Co 83/06/17 O'REILLY, J P
Region 2, Office of Director 2pp 19120 191 24X
Fiche 50-324, 83/06/17, 8306300193

8306300031 Advises that IER 2-U1-51 re inoperable Cbl low level switch 2E41-LB1 N003 on 830524 will be submitted by 830707
DIETZ, C R Carolina Power & Light Co 83/06/23 O'REILLY, J P
Region 2, Office of Director 1p 19120 312 24X
Fiche 50-324, 83/06/23, 8306300031

8306300012 IER 83-052/03L-0 on 830524, smoke observed emanating briefly from RHR sys flow transmitter signal converters 2-E11-FY-3138 & indicator did not show expected indication Caused by test leads shorting to ground W/830624 ltr
PASTVA, M J, DIETZ, C R Carolina Power & Light Co 83/06/24
O'REILLY, J P Region 2, Office of Director 2pp 19120 315 24X
Fiche 50-324, 83/06/24, 8306300012

8306300242 RD on 830504, during shutdown operations, limiting conditions for operations (LCD) initiated for inoperable Fire Door 203 Caused by door misalignment Due to job planning considerations, 7-day time frame of LCD exceeded
DIETZ, C R Carolina Power & Light Co 83/06/24 O'REILLY, J P
Region 2, Office of Director 1p 19119 350 24X
Fiche 50-324, 83/06/24, 8306300242

8306300106 EN-83-011A on 830210, notice of violation & proposed imposition of civil penalties will be issued in amount of \$600,000 Action based on failure to perform Tech Spec surveillances on safety sys & components
BARBER, G, AXELRAD, J Director's Office, Office of Inspection and Enforcement 83/06/28 1p 19048 216 24X Fiche 50-324, 83/06/28, 8306300106

V Operator Examinations

8306140141 Requests approved ref matl re operator exams by 820225 Missing deadline will result in delay in administering exams Applications should be submitted at least 60 days prior to first exam scheduled for wk of 830425
VERRELLI, D M Division of Project & Resident Programs 83/02/07
HOWE, J P Carolina Power & Light Co 4pp 18839 167 24X
Fiche 50-324, 83/02/07, 8306140141

8306140533 Confirms administration of written & oral requalification exams at facility during wk of 830627 Approved ref matl must be furnished by 830425
O'REILLY, J P Region 2, Office of Director 83/04/15 UTLEY, E E
Carolina Power & Light Co 3pp 18834 323 24X
Fiche 50-324, 83/04/15, 8306140533

8306140396 Ack receipt of 830505 ltr informing NRC of steps taken to correct violations noted in IE Special Training Assessment Repts 50-324/83-04 & 50-325/83-04
VERRELLI, D M Division of Project & Resident Programs 83/05/24
UTLEY, E E Carolina Power & Light Co 1p 18838 003 24X
Fiche 50-324, 83/05/24, 8306140396

--8306140404 Responds to NRC 830207 ltr re violations noted in IE Special Training Assessment Repts 50-324/83-04 & 50-325/83-04 Corrective actions orientation for new employees accomplished in accordance w/TT-301
DIETZ, C R Carolina Power & Light Co 83/05/05 O'REILLY, J P
Region 2, Office of Director 3pp 18838 004 24X
Fiche 50-324, 83/05/24, 8306140396

--8306140413 Forwards IE Special Training Assessment Repts 50-324/83-04 & 50-325/83-04 on 830110-14 No noncompliance noted Significant weaknesses identified
VERRELLI, D M Division of Project & Resident Programs 83/02/07
UTLEY, E E Carolina Power & Light Co 2pp 18838 007 24X
Fiche 50-324, 83/05/24, 8306140396

--8306140423 IE Special Training Assessment Repts 50-324/83-04 & 50-325/83-04 on 830110-14 No noncompliance noted Major areas inspected licensed & nonlicensed operator training & requalification programs & on-shift/real time training
HEHL, C W, CASHATT, M E, RAGLIN, K A Region 2, Office of Director 83/02/03 10pp 18838 009 24X Fiche 50-324, 83/05/24, 8306140396

DOCKET 50-325 DRUNSWICK STEAM ELECTRIC PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8306140690 Ack receipt of 830131 ltr informing NRC of corrective actions taken in response to 821101 confirmation of action ltr re emergency preparedness program
LEWIS, R C Division of Project & Resident Programs 83/03/31,
FURR, D J Carolina Power & Light Co 1p 18841 268 24X
Fiche 50-000, 83/03/31, 8306140690

--8306140708 Submits status of corrective actions for deficiencies noted in 821101 confirmation of action ltr re emergency preparedness program
UTLEY, E E Carolina Power & Light Co 83/01/31 O'REILLY, J P
Region 2, Office of Director 2pp 18841 269 24X
Fiche 50-000, 83/03/31, 8306140690

8306220273 Confirms telcon w/IL re acceptability of emergency response facilities Locations of alternate locations for offsite personnel to assemble to communicate w/emergency operations facilities acceptable
HURFORD, W J Carolina Power & Light Co 83/06/17 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 18926 033 24X
Fiche 50-000, 83/06/17, 8306220273

J Insurance & indemnity information

8306210082 Forwards Endorsement 49 to NCLIA Policy NF-218
BARHAM, C D Carolina Power & Light Co 83/06/13 BALTZMAN, J
Antitrust & Economic Analysis Branch (Utility Finance) 2pp 18911 237 24X Fiche 50-324, 83/06/13, 8306210082

8306210109 Forwards Endorsement 42 to MAFU Policy MI-80
BARHAM, C D Carolina Power & Light Co 83/06/13 BALTZMAN, J NRC
No Detailed Affiliation Given 2pp 18914 179 24X
Fiche 50-324, 83/06/13, 8306210109

DOCKETED ITEMS

P Operating license stage documents & correspondence

8306020699 Notice of consideration of issuance of amend to License DPR-71 & proposed no significant hazards consideration determination, incorporating limiting conditions for operation during fourth fuel cycle
VASSALLO, D B Operating Reactors Branch 2 83/05/16 5pp
18715 320 24X Fiche 50-324, 83/05/16, 8306020699

8306020020 Informs that, based on review of BWR Owners Group 001230 response to NUREG-0737, Item II K 3 45, "Depressurization W/ Other Than Automatic Depressurization Sys," complete
VASSALLO, D B Operating Reactors Branch 2 83/05/18 UTLEY, E E
Carolina Power & Light Co 7pp 18702 336 24X
Fiche 50-324, 83/05/18, 8306020020

8306080080 Forwards nonproprietary & proprietary versions of NF-1583 04, "Verification of CP&L Ref BWR Thermal-Hydraulic Methods Using FIBWR Code" Affidavit encl Proprietary version withheld (ref 10CFR2 7901)
ZIMMERMAN, S R Carolina Power & Light Co 83/05/31 VASSALLO, D B
Operating Reactors Branch 2 8pp 18771 029 24X
Fiche 50-324, 83/05/31, 8306080080

--8306080083 Nonproprietary "Verification of CP&L Ref BWR Thermal-Hydraulic Methods Using FIBWR Code"
POPE, H A, KUNITA, R K Carolina Power & Light Co NF-1583 04
(encl) 83/05/18 41pp 18771 035 24X Fiche 50-324, 83/05/31, 8306080083

8306070035 Responds to 830414 request for addl info re structural aspects of Mark I containment program plant-unique analysis report Util in process of obtaining info from United Engineers & Constructors Response will be provided by 830805
ZIMMERMAN, S R Carolina Power & Light Co 83/06/02 VASSALLO, D B
Operating Reactors Branch 2 1g 18739 335 24X
Fiche 50-324, 83/06/02, 8306070035

8306150464 Forwards request for addl info re review of structural aspects of plant-unique analysis report for Mark I long-term containment program Meeting should be held within 3 wks to discuss response
VASSALLO, D B Operating Reactors Branch 2 83/06/03 UTLEY, E E
Carolina Power & Light Co 8pp 18869 206 24X
Fiche 50-324, 83/06/03, 8306150464

8306240145 Application to amend License DPR-71, changing Tech Specs re snubber listings, drywell sump instrumentation numbers, remote shutdown panel instrumentation numbers & installation of NUREG-0737 mode for startup
HOME, P W Carolina Power & Light Co 83/06/20 DENTON, H R Officer
of Nuclear Reactor Regulation, Director 2pp 18981 041 24X
Fiche 50-325, 83/06/20, 8306240145

--8306240149 Revised Tech Spec re snubber listings, drywell sump instrumentation numbers, remote shutdown panel instrumentation numbers & installation of NUREG-0737 mode for startup
Carolina Power & Light Co 83/06/20 44pp 18981 042 24X
Fiche 50-325, 83/06/20, 8306240149

8306240246 Discusses justification for continued safe operation of facility pending NRC issuance of necessary Tech Spec revs to support Cycle 4 Reactor plant type activation instrumentation expected within 30 days of startup
HOME, P W Carolina Power & Light Co 83/06/20 VASSALLO, D B
Operating Reactors Branch 2 3pp 18980 168 24X
Fiche 50-324, 83/06/20, 8306240246

8306270225 Forwards results of plant-unique calculations which form bases for mod program in response to Generic Ltr 83-08, "Mod of Mark I Containment Vacuum Breakers"
ZIMMERMAN, S R Carolina Power & Light Co 83/06/23 VASSALLO, D B
Operating Reactors Branch 2 8pp 18988 293 24X
Fiche 50-324, 83/06/23, 8306270225

--8306270226 Rev 1 to "Improved Dynamic Vacuum Breaker Valve Response for Brunswick Plant"
Continuum Dynamics, Inc 82/09/30 27pp 18989 016 24X
Fiche 50-324, 83/06/23, 8306270226

--8306270230 Rev 0 to "Mark I Vacuum Breaker Improved Valve Dynamic Model - Model Development & Validation"
SULLIVAN, J K Continuum Dynamics, Inc 82-31 000 82/08/31
40pp 18989 042 24X Fiche 50-324, 83/06/23, 8306270230

8306280324 Supplemental application for amend to Licenses DPR-71 & DPR-42, revising Tech Specs re RCIC sys activation instrumentation per Generic Ltr 83-02 & NUREG-0737 items.
HOME, P W Carolina Power & Light Co 83/06/23 VASSALLO, D B
Operating Reactors Branch 2 4pp 19019 290 24X
Fiche 50-324, 83/06/23, 8306280324

--8306280544 Revised Tech Specs re RCIC sys activation instrumentation
Carolina Power & Light Co 83/06/23 21pp 19019 291 24X
Fiche 50-324, 83/06/23, 8306280544

Q Inspection reports, IE Bulletins & correspondence

8306140735 Confirms IE mgt meeting on 83/01/10 at plant site to discuss status of facility improvement program Proposed meeting agenda encl
O'REILLY, J P Region 2, Office of Director 83/01/10 UTLEY, E E
Carolina Power & Light Co 2pp 18041 092 24X
Fiche 50-324, 83/01/10, 8306140735

8306140078 Confirms 830328 enforcement meeting at Region 11 site to discuss recent events at Brunswick 1 re standby gen treatment deluge sys & violation involving radwaste shipments from Robinson 2 per 830322 telcon Agenda encl
O'REILLY, J P Region 2, Office of Director 83/01/29 UTLEY, E E
Carolina Power & Light Co 2pp 18038 342 24X
Fiche 50-000, 83/01/29, 8306140078

8306140698 Ack receipt of 830131 ltr informing NRC of corrective actions taken in response to 821101 confirmation of action ltr re emergency preparedness program
LEWIS, R C Division of Project & Resident Programs 83/01/11
UTLEY, E E Carolina Power & Light Co 1p 18041 340 24X
Fiche 50-000, 83/01/31, 8306140698

--8306140708 Submits status of corrective actions for deficiencies from 821101 confirmation of action ltr re emergency preparedness program
UTLEY, E E Carolina Power & Light Co 83/01/31 O'REILLY, J P
Region 2, Office of Director 2pp 18041 269 24X
Fiche 50-000, 83/01/31, 8306140708

8306140399 Confirms 830510 mgt meeting in Raleigh, NC to review "Risk Program (First Phase) results, per 830414 telcon Proposed agenda encl
LEWIS, R C Division of Project & Resident Programs 83/04/14
UTLEY, E E Carolina Power & Light Co 3pp 18836 056 24X
Fiche 50-000, 83/04/29, 8306140399

8306140547 Responds to Rev 1 to IE Bulletin 82-03 re reactor recirculation & RHR sys Defective welds repaired using weld overlay technique Weld indication tables & isometric drawings of defective weld locations encl
HOME, P W Carolina Power & Light Co 83/05/16 O'REILLY, J P
Region 2, Office of Director 7pp 18643 281 24X
Fiche 50-324, 83/05/16, 8306140547

--8306140549 "Design Rept for Recirculation Sys Weld Overlay Impacts at Brunswick Steam Electric Plant, Unit 1"
CHARLEY, J E, REEVES, P E, ADAMS, R H NUTECH Engineers, Inc
CPL-07-102 000 83/05/05 75pp 18643 280 24X
Fiche 50-324, 83/05/16, 8306140549

8306020107 Forwards safety evaluation & notice of granting relief from inservice insp requirements
VASSALLO, D B Operating Reactors Branch 2 83/05/19 UTLEY, E E
Carolina Power & Light Co 3pp 18701 170 24X
Fiche 50-324, 83/05/19, 8306020107

--8306020116 Safety evaluation granting in part & denying in part, requests for exemption from inservice insp requirements
Office of Nuclear Reactor Regulation, Director 83/05/19 2pp
18701 123 24X Fiche 50-324, 83/05/19, 8306020116

--8306020290 Notice granting in part & denying in part, relief from A Code Section XI inservice insp requirements
VASSALLO, D B Operating Reactors Branch 2 83/05/19 4pp
18701 144 24X Fiche 50-324, 83/05/19, 8306020290

8306010311 Forwards "Environment Qualification of Electrical Equipment, Brunswick Steam Electric Plant, Units 1 & 2 - 10CFR 50.49 - 40 Day Response," Vols I & II, per IE Bulletin 79-01B & 830411 request List of items to be qualified encl
UTLEY, E E Carolina Power & Light Co 83/05/20 VASSALLO, D B
Operating Reactors Branch 2 797pp 18669 147 24X
Fiche 50-324, 83/05/20, 8306010311

8306140294 Ack receipt of 830505 ltr informing NRC of steps taken to correct violations noted in II Special Training Assessment Repts 50-324/83-04 & 50-325/83-04
VERRELL, D H Division of Project & Resident Programs 83/05/24
UTLEY, E E Carolina Power & Light Co 1p 18838 003 24X
Fiche 50-324, 83/05/24, 8306140294

DOCKETED ITEMS

187

--8306140404 Responds to NRC 830207 ltr re violations noted in IF Special Training Assessment Repts 50-324/83-04 & 50-325/83-04
Corrective actions orientation for new employees accomplished in accordance w/TF-301
DIETZ, C R Carolina Power & Light Co 83/05/05 O'REILLY, J P
Region 2, Office of Director 2pp 18838 004 24X
Fiche 50-324, 83/05/24, 8306140376

--8306140413 Forwards IE Special Training Assessment Repts 50-324/83-04 & 50-325/83-04 on 830110-14 No noncompliance noted Significant weaknesses identified
VERRELLI, D M Division of Project & Resident Programs 83/02/07
UTLEY, E E Carolina Power & Light Co 2pp 18838 007 24X
Fiche 50-324, 83/05/24, 8306140376

--8306140423 IE Special Training Assessment Repts 50-324/83-04 & 50-325/83-04 on 830110-14 No noncompliance noted Major areas inspected licensed & nonlicensed operator training & requalification programs & on-shift/real time training
HEHL, C W, CASHATT, M E, RAGLIN, K A Region 2, Office of Director 83/02/03 10pp 18838 009 24X Fiche 50-324, 83/05/24, 8306140376

8306140194 Forwards IE Mgt Meeting Repts 50-324/83-19 & 50-325/83-19 on 830518 Concerns re violations of regulatory requirements & mgt control raised
O'REILLY, J P Region 2, Office of Director 83/05/25 UTLEY, E E
Carolina Power & Light Co 2pp 18838 033 24X
Fiche 50-324, 83/05/25, 8306140194

--8306140201 IE Mgt Meeting Repts 50-324/83-19 & 50-325/83-19 on 830518 Major areas discussed enforcement issues resulting from recent events at site involving inoperability of Unit 2 condenser offgas monitoring sys
LEWIS, R C Division of Project & Resident Programs 83/05/24 3pp 18838 035 24X Fiche 50-324, 83/05/25, 8306140194

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 123pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 113pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8306140653 Ack receipt of 830524 ltr documenting 830527 commitment date for Q-list procedure rev. in response to IF Insp Repts 50-324/83-45 & 50-325/83-45
VERRELLI, D M Division of Project & Resident Programs 83/05/27
UTLEY, E E Carolina Power & Light Co 1p 18843 006 24X
Fiche 50-324, 83/05/27, 8306140653

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at DWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc 116pp 18732 200 24X Fiche 50-000, 83/05/31, 8305110461

8306140677 Ack receipt of 830520 ltr informing NRC of steps taken to correct violations noted in IF Insp Repts 50-324/83-05 & 50-325/83-05
VERRELLI, D M Division of Project & Resident Programs 83/06/07
UTLEY, E E Carolina Power & Light Co 1p 18841 351 24X
Fiche 50-324, 83/06/07, 8306140677

--8306140682 Responds to NRC 830407 ltr re violations noted in IE Insp Repts 50-324/83-05 & 50-325/83-05 Corrective actions operating procedures revised to accurately reflect desired position of fuel oil manual fill valves
DIETZ, C R Carolina Power & Light Co 83/05/20 O'REILLY, J P
Region 2, Office of Director 2pp 18841 352 24X
Fiche 50-324, 83/06/07, 8306140677

--8306140688 Ack receipt of IE Insp Repts 50-324/83-05 & 50-325/83-05 & notice of violation Response to rept will be submitted by 830520
DIETZ, C R Carolina Power & Light Co 83/05/05 O'REILLY, J P
Region 2, Office of Director 1p 18841 354 24X
Fiche 50-324, 83/06/07, 8306140677

--8306140693 Forwards IE Insp Repts 50-324/83-05 & 50-325/83-05 on 830215-0315 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 83/04/07
UTLEY, E E Carolina Power & Light Co 2pp 18841 355 24X
Fiche 50-324, 83/06/07, 8306140677

--8306140699 Notice of violation from insp on 830215 0315
* Region 2, Office of Director 83/04/07 1p 18841 357 24X
Fiche 50-324, 83/06/07, 8306140677

--8306140705 IE Insp Repts 50-324/83-05 & 50-325/83-05 on 830215-0315 Noncompliance noted inadequate operating procedures for filling emergency power diesel generator fuel oil tanks & lack of ventilation of svc water valves
MYERS, D O, GARNER, L W Region 2, Office of Director BEHIS, P
Division of Project & Resident Programs 83/04/07 9pp, 18841 358 24X Fiche 50-324, 83/06/07, 8306140677

8306290402 Responds to IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators," per 830310 ltr
TECHNO check valves used at facilities Valve arrangement drawings encl
HOWE, P W Carolina Power & Light Co 83/06/08 O'REILLY, J P
Region 2, Office of Director 6pp 19053 127 24X
Fiche 50-324, 83/06/08, 8306290402

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 110pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8306290524 Approves issuance of SAMP rept Notes improvement in safety-related activities, emergency preparedness & security & safeguards Weaknesses in QA program will be monitored
O'REILLY, J P Region 2, Office of Director 83/06/14 UTLEY, E E
Carolina Power & Light Co 5pp 19049 282 24X
Fiche 50-000, 83/06/14, 8306290524

--8306290531 Forwards SAMP Repts 50-325/83-09, 50-324/83-09, 50-261/83-07, 50-400/83-10 & 50-401/83-10 for Jan 1982 - Jan 1983
Evaluation will be discussed in Raleigh, NC on 830510
LEWIS, R C Division of Project & Resident Programs 83/05/03
UTLEY, E E Carolina Power & Light Co 2pp 19049 287 24X
Fiche 50-000, 83/06/14, 8306290524

--8306290537 SAMP rept for Jan 1982 - Jan 1983
* Region 2, Office of Director 83/05/03, 44pp, 19049 289 24X
Fiche 50-000, 83/06/14, 8306290524

--8306290553 Responds to 830503 SAMP rept for Jan 1982 - Jan 1983 Reduced NRC attention may be appropriate for Category I re fire protection NRC attention should be maintained at normal levels for emergency preparedness
UTLEY, E E Carolina Power & Light Co 83/05/20 O'REILLY, J P
Region 2, Office of Director, 16pp 19049 334 24X
Fiche 50-000, 83/06/14, 8306290524

--8306290555 Forwards replacement Page 2 to Attachment 2 of 830520 ltr which commented on SAMP rept
EURY, L W Carolina Power & Light Co 83/05/27 O'REILLY, J P
Region 2, Office of Director 2pp 19050 009 24X
Fiche 50-000, 83/06/14, 8306290524

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 115pp 19021 177 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co. of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

DOCKETED ITEMS

8306280489 Lists commitments to implement addl monitoring & restrictive limits on unidentified RCS leakage per NUREG-0313, Rev 1, in response to IE Bulletin 83-02 Plans to be submitted to NRC 3 months prior to next refueling outage
HQUE, P W Carolina Power & Light Co 83/06/24 VASSALLO, D B
Operating Reactors Branch 2 4pp 19018 311 24X
Fiche 50-325, 83/06/24, 8306280489

8306300102 Ack receipt of 830507 ltr in response to notice of violation & proposed imposition of civil penalties from insps on 820712-14 & 20-22 Corrective actions responsive to problems but initiated only after violations confirmed
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/06/28 UILEY, E E Carolina Power & Light Co 3pp 19048 207 24X Fiche 50-324, 83/06/28, 8306300102

--8306300108 Order imposing civil penalties in amount of \$600,000 for violations identified during insps on 820712-14 & 20-22
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/06/28 Carolina Power & Light Co 6pp 19048 210 24X Fiche 50-324, 83/06/28, 8306300108

R Periodic operating reports & related correspondence

8306140214 Monthly operating repts for May 1983 W/830607 ltr
HARRISON, F, DIETZ, C R Carolina Power & Light Co 83/06/07
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 14pp, 18832 272 24X Fiche 50-324, 83/06/07, 8306140214

S Reportable occurrences, LERs & related correspondence

8306140629 Confirms 830518 onsite enforcement meeting to discuss regulatory issues re isolation of Unit 2 condenser offgas radiation monitors, per 830516 telcon (proposed agenda encl)
O'REILLY, J P Region 2, Office of Director 83/05/16 UILEY, E E Carolina Power & Light Co 7pp 18842 087 24X
Fiche 50-324, 83/05/16, 8306140629

8306010118 LER 83-016/03L-0 on 830425, routine surveillance revealed electrolyte levels of 125-volt dc Div 1 & II battery cells out of allowable level band mark Caused by changes in ambient battery room temps W/830523 ltr
PASTVA, M J, DIETZ, C R Carolina Power & Light Co 83/05/23
O'REILLY, J P Region 2, Office of Director 2pp 18673 358 24X
Fiche 50-325, 83/05/23, 8306010118

8306070053 LER 83-023/03L-0 on 830426, loss of offsite power occurred when 230 kV bus tripped Fire reported in 4160/480 transformer between emergency bus E-2 & E-6 Caused by personnel error Trip signal cleared W/830524 ltr
PULK, R M, DIETZ, C R Carolina Power & Light Co 83/05/24
O'REILLY, J P Region 2, Office of Director 3pp 18740 063 24X
Fiche 50-325, 83/05/24, 8306070053

8306070081 LER 83-019/03L-0 on 830425, standby liquid control sys relief valves 1-C41-F029A & B lifted at setpoints exceeding Tech Specs Caused by out of tolerance relief valve settings
Valves adjusted W/830525 ltr
PASTVA, M J, DIETZ, C R Carolina Power & Light Co 83/05/25
O'REILLY, J P Region 2, Office of Director 3pp 18737 352 24X
Fiche 50-325, 83/05/25, 8306070081

8306070342 RO increased Co-60 activity found in two bottom sediment samples collected 830405 & 06 No Co-60 found in surface water samples from intake & discharge canals during Apr 1983 No radiation hazard or exposure to public observed
DIETZ, C R Carolina Power & Light Co 83/05/31 O'REILLY, J P
Region 2, Office of Director 2pp 18741 294 24X
Fiche 50-324, 83/05/31, 8306070342

8306090136 RO on 830426, fire barrier limiting condition for operation initiated for augmented offgas bldg door Mod time frame exceeded 7-day specified period fire watches will remain in effect
DIETZ, C R Carolina Power & Light Co 83/06/01 O'REILLY, J P
Region 2, Office of Director 1p 19175 296 24X
Fiche 50-325, 83/06/01, 8306090136

8306100127 LER 83-018/03L-0 on 830503 & 14 average power range monitor inoperable due to failed power supply First failure caused by defective diode CR1 thyristor SCRI & capacitor C1 Cause of 830514 failure undetermined, W/830602 ltr
PASTVA, M J, DIETZ, C R Carolina Power & Light Co 83/06/02
O'REILLY, J P Region 2, Office of Director 3pp 18802 011 24X
Fiche 50-325, 83/06/02, 8306100127

8306130455 Forwards NRR comments on draft AD rept to Congress for First Quarter 1983
DENTON, H R Office of Nuclear Reactor Regulation, Director 83/06/07, HELTHEIS, C J Director's Office 3pp 18830 176 24X
Fiche 50-000, 83/06/07, 8306130455

8306270098 RO on 830504-05 Two first doubt (12/7-115) rendered inoperable to facilitate main work & high differential air pressure across door prevented self-closure, respectively
Fire watches in effect
DIETZ, C R Carolina Power & Light Co 83/06/09 O'REILLY, J P
Region 2, Office of Director 1p 18908 139 24X
Fiche 50-325, 83/06/09, 8306270098

8306210174 LER 83-022/03L-0 on 830513, during routine surveillance, fire hose Station 2-ADG-58 declared inoperable due to bent hose reel Caused by opening valve w/hose on reel Hose replaced W/830610 ltr
PASTVA, M J, DIETZ, C R Carolina Power & Light Co 83/06/10
O'REILLY, J P Region 2, Office of Director 2pp 18915 187 24X
Fiche 50-325, 83/06/10, 8306210174

8306270291 RO on 830513, limiting condition for operation initiated for Fire Door 213 in diesel generator bldg floor encountered high differential air pressure across door preventing self-closure Engineering evaluating pressure problem
DIETZ, C R Carolina Power & Light Co 83/06/17 O'REILLY, J P
Region 2, Office of Director 1p 17976 184 24X
Fiche 50-325, 83/06/17, 8306270291

8306300193 RO on 830502, gamma analysis of bottom sediment sample detected excessive Co-60 activity Sampling frequency increased from semiannually to monthly Sample represents seventh monthly sample
DIETZ, C R Carolina Power & Light Co 83/06/17 O'REILLY, J P
Region 2, Office of Director 2pp 19122 191 24X
Fiche 50-324, 83/06/17, 8306300193

8306300203 LER 83-020/03L-0 on 830524, intermediate range monitor A indicated instrument upscale Caused by moisture accumulation in monitor detector cable under vessel connector Connector replaced W/830623 ltr
PASTVA, M J, DIETZ, C R Carolina Power & Light Co 83/06/23
O'REILLY, J P Region 2, Office of Director 2pp 19119 347 24X
Fiche 50-325, 83/06/23, 8306300203

8306300106 EN-83-011A on 830210, notice of violation & proposed imposition of civil penalties will be issued in amount of \$600,000 Action based on failure to perform Tech Spec surveillances on safety sys & components
BARBER, Q, AXFLRAH, J Director's Office, Office of Inspection and Enforcement 83/06/28 1p 19048 216 24X Fiche 50-324, 83/06/28, 8306300106

V Operator Examinations

8306140141 Requests approved ref matl re operator exams by 830225
Missing deadline will result in delay in administering exams Applications should be submitted at least 60 days prior to first exam scheduled for wk of 830425
VERRELLI, D M Division of Project & Resident Programs 83/02/07
HOME, J P Carolina Power & Light Co 4pp 18839 167 24X
Fiche 50-324, 83/02/07, 8306140141

8306140533 Confirms administration of written & oral requalification exams at facility during wk of 830627 Approved ref matl must be furnished by 830425
O'REILLY, J P Region 2, Office of Director 83/04/15 UILEY, E E
Carolina Power & Light Co 3pp 18834 323 24X
Fiche 50-324, 83/04/15, 8306140533

8306140396 Ack receipt of 830505 ltr informing NRC of steps taken to correct violations noted in II Special Training Assessment Repts 50-324/83-04 & 50-325/83-04
VERRELLI, D M Division of Project & Resident Programs 83/05/14
UILEY, E E Carolina Power & Light Co 1p 18838 007 24X
Fiche 50-324, 83/05/14, 8306140396

--8306140404 Responds to NRC 830207 ltr re violations noted in IE Special Training Assessment Repts 50-324/83-04 & 50-325/83-04
Corrective actions orientation for new employees accomplished in accordance W/71-701
DIETZ, C R Carolina Power & Light Co 83/05/05 O'REILLY, J P
Region 2, Office of Director 3pp 18838 004 24X
Fiche 50-324, 83/05/05, 8306140404

--8306140413 Forwards IE Special Training Assessment Repts 50-324/83-04 & 50-325/83-04 on 830110-14 No noncompliance noted Significant weaknesses identified
VERRELLI, D M Division of Project & Resident Programs 83/02/07
UILEY, E E Carolina Power & Light Co 2pp 18838 007 24X
Fiche 50-324, 83/02/07, 8306140413

--8306140423 IE Special Training Assessment Repts 50-324/83-04 & 50-325/83-04 on 830110-14 No noncompliance noted Major areas inspected licensed & nonlicensed operator training & requalification programs & on-shift/real time training
HEHL, C W, MUNRO, J F Region 2, Office of Director 83/02/03 10pp 18838 009 24X Fiche 50-324, 83/02/03, 8306140423

DOCKET 50-126 UNIV OF CALIFORNIA AT IRVINE ICS REACTION

S Reportable occurrences, IIR & related correspondence

8306210184 RO on 830604, Fast transient control rod failed to return completely to core following manual scram caused by air cylinder being dry. Light oil added to cylinder. Maint checks under review for possible rev.
MILLER, G L California Univ of, Irvine 83/06/16
Standardization & Special Projects Branch 1p 10/15 253 24X
Fiche 50 326, 83/06/16, 8306210184

DOCKET 50 377 SQUOYAH NUCLEAR PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8306140535 Forwards IE Insp Repts 50-327/83-06 & 50-328/83-06 on 830328-0401 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/05/23
PARRIS, H G Tennessee Valley Authority 2pp 18/43 268 24X
Fiche 50 327, 83/05/23, 8306140535

--8306140542 IE Insp Repts 50-327/83-06 & 50-328/83-06 on 830328-0401 No noncompliance noted Major areas inspected emergency preparedness Deficiency in emergency detection & classification program noted
MARSTON, R R Region 2, Office of Director JENKINS, G R Division of Emergency Preparedness & Materials Safety 83/05/17 9pp 18843 270 24X Fiche 50-327, 83/05/23, 8306140535

8306070132 Forwards rev to physical security plan Rev withheld (ref 10CFR73.21)
MILLS, L M Tennessee Valley Authority 83/05/31 ADENSA, E
Licensing Branch 4 1p 10/19 277 24X Fiche 50 327, 83/05/31, 8306070132

8306150091 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/06/06 Document Management Branch 1p 18872 175 24X Fiche 50 327, 83/06/06, 8306150091

--8306150094 Forwards public version of revised emergency plan implementing procedures, including Procedures SQN-IP-2 re notification of unusual event, SQN-IP-3 re alert & SQN-IP-4 re site area emergency
HAMMER, D S Tennessee Valley Authority 83/04/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18872 126 24X Fiche 50 327, 83/06/06, 8306150091

--8306150098 Public version of revised emergency plan implementing procedures, including Procedures SQN-IP-2 re notification of unusual event, SQN-IP-3 re alert & SQN-IP-4 re site area emergency
MILLER, G L Tennessee Valley Authority 83/03/10 21pp 18872 127 24X Fiche 50 327, 83/06/06, 8306150091

8306150510 Discusses steps to be taken to resolve outstanding fire protection issues Tech Spec should be amended to include frequency of fire hazards training & drills should be held once per 72 days (evaluation end)
ADENSA, E G Licensing Branch 4 83/06/06 PARRIS, H G Tennessee Valley Authority 3pp 18844 371 24X Fiche 50-327, 83/06/06, 8306150510

8306210010 Forwards "Program Plan for Control Room Design Reviews for all TVA Nuclear Plants," in response to Generic L1: 02-33 re upgrade of emergency plans
HAMMER, D S Tennessee Valley Authority 83/06/07 ADENSA, E
Licensing Branch 4 3pp 10/13 001 24X Fiche 50-000, 83/06/07, 8306210010

--8306210016 Procedure B62207 (O, "Program Plan for Control Room Design Reviews for all TVA Nuclear Plants"
* Tennessee Valley Authority 83/06/04 200pp 18713 104 24X
Fiche 50 000, 83/06/07, 8306210010

Operating license stage documents & correspondence

8306060051 Addl response to FOIA request for three categories of documents re PRA of reactor safety study methodology application program repts & interim reliability evaluation program repts Forwards App A documents Search continuing
FELTON, J M Division of Rules and Records 83/04/07 SHIMIZU, G C Union of Concerned Scientists 3pp 10752 001 24X
Fiche 50 000, 83/04/07, 8306060051

--8306060051 Provides info on boron precipitation clogging HPI lines & failure of operator to switch to hot lag injection in order to flush out boron residue from core during recirculation
Info obtained from PRA
DAVIS, B NRC - No Detailed Affiliation Given 83/02/24
THAMANI, A NRC - No Detailed Affiliation Given 8pp 18752 206 24X Fiche 50-000, 83/04/07, 8306060051

8306080208 Advises that partial response to SER open items re environmental qualification of safety-related electrical equipment will be submitted by 830701 & remaining info by 830729
MILLS, L M Tennessee Valley Authority 83/06/02 ADENSA, E
Licensing Branch 4 2pp 10/11 183 24X Fiche 50-327, 83/06/02, 8306080208

8306080212 Requests meeting to discuss integrated mod schedule for Unit 2, mod deferrals proposed & justifications provided
Scheduled outages, coupled w/normal forced outage rate, could result in lack of sufficient operating reserves
MILLS, L M Tennessee Valley Authority 83/06/02 ADENSA, E
Licensing Branch 4 3pp 10/11 216 24X Fiche 50-327, 83/06/02, 8306080212

8306210027 Forwards Rev 7 to "Squoyah Nuclear Plant Offsite Dose Calculation Manual"
MILLS, L M Tennessee Valley Authority 83/06/15 ADENSA, E
Licensing Branch 4 1p 18711 261 24X Fiche 50-327, 83/06/15, 8306210027

--8306210032 Rev 7 to "Squoyah Nuclear Plant Offsite Dose Calculation Manual"
* Tennessee Valley Authority 83/07/23 81pp 18911 262 24X
Fiche 50-327, 83/06/15, 8306210027

8306210115 Application for amend to Licenses DPR-77 & DPR-79, changing Tech Spec 4 B 1 1 2 d 11 re surveillance for diesel generator Class III fee for Unit 1 & Class I fee for Unit 2 will be forwarded
MILLS, L M Tennessee Valley Authority 83/06/15 ADENSA, E
Licensing Branch 4 2pp 18914 102 24X Fiche 50-327, 83/06/15, 8306210115

--8306210117 Proposed changes to Tech Spec 4 B 1 1 2 d 11 re surveillance for diesel generator
* Tennessee Valley Authority 83/06/15 4pp 18914 104 24X
Fiche 50-327, 83/06/15, 8306210115

8306210180 Agrees w/NRC 830520 fee determination Fee will be submitted by wire transfer
MILLS, L M Tennessee Valley Authority 83/06/15 MILLER, W D License Fee Management Branch 1p 18918 256 24X
Fiche 50-327, 83/06/15, 8306210180

8306280178 Forwards 830615 change request for NPDES Permit TN0026450 re 60-day extension of submittal of thermal plume rept required by Part III E
MILLS, L M Tennessee Valley Authority 83/06/22 ADENSA, E
Licensing Branch 4 2pp 19015 084 24X Fiche 50-327, 83/06/22, 8306280178

Q Inspection reports, IE Bulletins & correspondence

8306140543 Confirms mgt meeting on 830421 in Chattanooga, TN to review results of first phase of annual appraisal of regulatory performance, per 830328 telcon
LEWIS, R C Division of Project & Resident Programs 83/04/12
PARRIS, H G Tennessee Valley Authority 3pp 18834 176 24X
Fiche 50-000, 83/04/12, 8306140543

8306140384 Forwards IE Insp Repts 50-327/83-07 & 50-328/83-07 on 830306-0405 No noncompliance noted
VERRELLI, D M Region 2, Office of Director 83/05/17, PARRIS, H G Tennessee Valley Authority 2pp 18932 076 24X
Fiche 50-327, 83/05/17, 8306140384

--8306140390 IE Insp Repts 50-327/83-07 & 50-328/83-07 on 830306-0405 No noncompliance noted Major areas inspected operational safety verification, IE bulletin closeout & LFR review & independent insp effort
FORD, E J, BUTLER, S D Region 2, Office of Director, QUICK, D R Division of Project & Resident Programs 83/05/17, 4pp 18932 078 24X Fiche 50-327, 83/05/17, 8306140384

8306140535 Forwards IE Insp Repts 50-327/83-06 & 50-328/83-06 on 830328-0401 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/05/23, PARRIS, H G Tennessee Valley Authority 2pp, 18843, 268 24X
Fiche 50-327, 83/05/23, 8306140535

DOCKETED ITEMS

- 8306140542 IE Insp Repts 50-327/83-06 & 50-328/83-06 on 830320-0401 Non compliance noted Major areas inspected emergency preparedness Deficiency in emergency detection & classification program noted
MARSTON, R R Region 2, Office of Director JENKINS, G R Division of Emergency Preparedness & Materials Safety 83/05/17 9pp
18843 270 24X Fiche 50-327, 83/05/23, 8306140535
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103), 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460
- 8306140137 Ack receipt of 830511 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/83-05 & 50-328/83-05
LEWIS, R C Division of Project & Resident Programs 83/05/26 PARRIS, H G Tennessee Valley Authority 1p 18839 115 24X Fiche 50-327, 83/05/26, 8306140137
- 8306140142 Responds to NRC 830414 ltr re violations noted in IE Insp Repts 50-327/83-05 & 50-328/83-05 Corrective actions training meetings held w/each operations shift group stressing importance of proper sys alignment
MILLS, L M Tennessee Valley Authority 83/05/11 O'REILLY, J P Region 2, Office of Director 4pp 18839 116 24X Fiche 50-327, 83/05/26, 8306140137.
- 8306140145 Forwards IE Insp Repts 50-327/83-05 & 50-328/83-05 on 830206-0305 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/04/14 PARRIS, H G Tennessee Valley Authority 2pp 18839 120 24X Fiche 50-327, 83/05/26, 8306140137.
- 8306140149 Notice of violation from insp on 830206-0305
* Region 2, Office of Director 83/04/14, 2pp 18839 122 24X Fiche 50-327, 83/05/26, 8306140137
- 8306140162 IE Insp Repts 50-327/83-05 & 50-328/83-05 on 830206-0305 Non compliance noted during planned release from cask decontamination tank, valve 0-77-573 was open, allowing release of approx 5,300 gallons from monitor tank
FORD, E J, BUTLER, S D Region 2, Office of Director QUICK, D H Division of Project & Resident Programs 83/04/07 7pp 18839 124 24X Fiche 50-327, 83/05/26, 8306140137
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461
- 8306290388 Forwards response to IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators " ERCW supply & discharge check valves will be disassembled & visually inspected at least once every 24 months.
MILLS, L M Tennessee Valley Authority 83/06/07 O'REILLY, J P Region 2, Office of Director 2pp 19055 293 24X Fiche 50-327, 83/06/07, 8306290388
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/06/09 Consolidated Edison Co of New York, Inc 115pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp, 18920 225 24X Fiche: 50-000, 83/06/13, 8305110470.
- 8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001. 24X Fiche 50-000, 83/06/13, 8306090010
- 8306290483 Approves issuance of SALP Repts 50-259/83-04, 50-260/83-04, 50-296/83-04, 50-327/83-04, 50-328/83-04, 50-390/83-07, 50-391/83-06, 50-438/83-06 & 50-439/83-06 for Jul 1981 - Dec 1982. No reply required
O'REILLY, J P Region 2, Office of Director 83/06/17 PARRIS, H G Tennessee Valley Authority. 3pp. 24X Fiche: 50-000, 83/06/17, 8306290483.
- 8306290490 Forwards SALP Repts 50-259/83-04, 50-260/83-04, 50-296/83-04, 50-327/83-04, 50-328/83-04, 50-390/83-07, 50-391/83-06, 50-438/83-06 & 50-439/83-06 for Jul 1981 - Dec 1982
LEWIS, R C Division of Project & Resident Programs 83/04/11 PARRIS, H G Tennessee Valley Authority 3pp 24X Fiche 50-000, 83/06/17, 8306290483
- 8306290503 SALP Repts 50-259/83-04, 50-260/83-04, 50-296/83-04, 50-327/83-04, 50-328/83-04, 50-390/83-07, 50-391/83-06, 50-438/83-06 & 50-439/83-06 for Jul 1981 - Dec 1982
* Region 2, Office of Director 83/04/13 92pp 24X Fiche 50-000, 83/06/17, 8306290483
- 8306290510 Comments on SALP Repts 50-259/83-04, 50-260/83-04, 50-296/83-04, 50-327/83-04, 50-328/83-04, 50-390/83-07, 50-391/83-06, 50-438/83-06 & 50-439/83-06 for Jul 1981 - Dec 1982
MILLS, L M Tennessee Valley Authority 83/05/10 O'REILLY, J P Region 2, Office of Director 2pp 24X Fiche 50-259, 83/06/17, 8306290483
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Multifunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483
- R Periodic operating reports & related correspondence
- 8306020197 Monthly operating repts for Mar 1983 W/830414 ltr
MASON, C C, DUMRICE, D C, EDDINGS, M Tennessee Valley Authority 83/04/14 27pp 18691 092 24X Fiche 50-327, 83/04/14, 8306020197
- 8306140526 "NPDCS Discharge Monitoring Rept. Feb-Apr 1983 "
EL-ASHRY, M Y Tennessee Valley Authority 83/05/28 90pp 18838 126 24X Fiche 50-327, 83/05/28, 8306140526
- S Reportable occurrences, LERs & related correspondence
- 8306010020 LER 83-065/03L-0 on 830502, during performance of Surveillance Instruction 166 P1, train A emergency gas treatment sys room cooler declared inoperable Caused by short in solenoid valve coil Coil replaced W/830524 ltr
CARVER, A M, GREEN, A M, HARDING, M R Tennessee Valley Authority 83/05/24 O'REILLY, J P Region 2, Office of Director 2pp 18674 048 24X Fiche 50-327, 83/05/24, 8306010020
- 8306010396 LER 83-057/03L-0 on 830426, subcooling margin monitor declared inoperable due to plant process computer failure Caused by power failure Computer supplied by maint power while inverter repaired W/830524 ltr
ROGERS, H R, HARDING, M R, GREEN, H J Tennessee Valley Authority 83/05/24 O'REILLY, J P Region 2, Office of Director 2pp 18682 235, 24X Fiche 50-327, 83/05/24, 8306010396
- 8306070284 LER 83-067/01T-0 on 830518, start bus 1B failed due to phase-to-phase fault Tech Spec 3 B 1.1 action statement 'a' entered Diesel generator not operable within 1-h limit Caused by bus sleeve insulation degradation W/830531 ltr
LUDWIG, W C, HARDING, M R, GREEN, H J Tennessee Valley Authority 83/05/31 O'REILLY, J P Region 2, Office of Director 4pp 18741 162 24X Fiche 50-327, 83/05/31, 8306070284
- 8306070039 LER 83-066/03L-0 on 830506, while changing out one upper head injection level switch & recalibr others, three or four switches found out of tolerance Probably caused by instrument drift Switches recalibr W/830601 ltr
LUDWIG, W C, HARDING, M R, GREEN, H J Tennessee Valley Authority 83/06/01 O'REILLY, J P Region 2, Office of Director 2pp 18739 358 24X Fiche 50-327, 83/06/01, 8306070039

DOCKETED ITEMS

171

8306200167 LER 83-071/03L-0 on 830512, waste gas disposal sys oxygen analyzer O-02AN-43-5000 found out of calibr & declared inoperable. Caused by analyzer zero adjustment drift. Analyzer recalibr & returned to svc W/830609 ltr
DUGGIN, G E, HARDING, M R, GREEN, H J Tennessee Valley Authority
83/06/09 O'REILLY, J P Region 2, Office of Director 2pp
18903 112 24X Fiche 50-327, 83/06/09, 8306200167

8306200332 LER 83-070/03L-0 on 830512, diesel generator 1A-A declared inoperable when unit tripped on high crankcase pressure due to cooling water leak. Caused by oil cooler failure due to normal end of life. Cooler replaced W/830609 ltr
LUDWIG, W C, HARDING, M R, GREEN, H J Tennessee Valley Authority
83/06/09 O'REILLY, J P Region 2, Office of Director 2pp
18900 199 24X Fiche 50-327, 83/06/09, 8306200332

8306210218 LER 83-075/03L-0 on 830516, power usage not indicated on kW meter for hydrogen recombiner. Caused by failure of GE Silicon control rectifier, Model GEC50M, due to normal end of component life. Meter circuit repaired W/830613 ltr
LUDWIG, W C, HARDING, M R, GREEN, H J Tennessee Valley Authority
83/06/13 O'REILLY, J P Region 2, Office of Director 2pp
18919 035 24X Fiche 50-327, 83/06/13, 8306210218

8306270250 LER 83-076/03L-0 on 830530, condensate demineralizer liquid effluent line radiation monitor O-RM-70-223 declared inoperable due to loss of sample flow. Caused by normal wear causing pump failure W/830616 ltr
ROGERS, H R, HARDING, M R, GREEN, H J Tennessee Valley Authority
83/06/16 O'REILLY, J P Region 2, Office of Director 2pp
18990 221 24X Fiche 50-327, 83/06/16, 8306270250

8306280192 LER 83-079/01T-0 on 830607, notified by Nonconformance Rpt SGNNB8304 re possibility of block wall failing during tornado. Caused by incorrect loading used in original calculations. Procedure revised W/830620 ltr
ROGERS, H R, HARDING, M R, GREEN, H J Tennessee Valley Authority
83/06/20 O'REILLY, J P Region 2, Office of Director 3pp
19013 077 24X Fiche 50-327, 83/06/20, 8306280192

X Onsite Storage of Low Level Waste

8306060102 Responds to 830422 ltr re determination of fees for low level radwaste amend applications. Fee determination acceptable
MILLS, L M Tennessee Valley Authority 83/06/01 MILLER, W D
License Fee Management Branch 1p 18719 359 24X
Fiche 50-000, 83/06/01, 8306060102

DOCKET 50-328 BEQUOYAH NUCLEAR PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8306140535 Forwards IE Insp Repts 50-327/83-06 & 50-328/83-06 on 830328-0401. No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/05/23
PARRIS, H Q Tennessee Valley Authority 2pp 18843 248 24X
Fiche 50-327, 83/05/23, 8306140535

--8306140542 IE Insp Repts 50-327/83-06 & 50-328/83-06 on 830328-0401. No noncompliance noted. Major areas inspected: emergency preparedness, deficiency in emergency detection & classification program noted
MARSTON, R R Region 2, Office of Director 83/05/17 7pp
18843 270 24X Fiche 50-327, 83/05/23, 8306140535

8306070132 Forwards rev to physical security plan Rev withheld (ref 10CFR73.21)
MILLS, L M Tennessee Valley Authority 83/05/31 ADENSAM, E
Licensing Branch 4 1p 18729 227 24X Fiche 50-327, 83/05/31, 8306070132

8306150091 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/06/06 Document
Management Branch 1p 18872 125 24X Fiche 50-327, 83/06/06, 8306150091

--8306150094 Forwards public version of revised emergency plan implementing procedures, including Procedures 83N-IP-2 re notification of unusual event; 83N-IP-3 re alert & 83N-IP-4 re site area emergency
KAMMER, D S Tennessee Valley Authority 83/04/25 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 18812 126 24X Fiche 50-327, 83/06/06, 8306150091

--8306150098 Public version of revised emergency plan implementing procedures, including Procedures 83N-IP-2 re notification of unusual event; 83N-IP-3 re alert & 83N-IP-4 re site area emergency
MILLS, L M Tennessee Valley Authority 83/03/10 21pp
18872 127 24X Fiche 50-327, 83/06/06, 8306150091

8306150510 Discusses steps to be taken to resolve outstanding fire protection issues. Tech Spec should be amended to include frequency of fire hazards training & drills should be held once per 92 days. Evaluation encl
ADENSAM, E O Licensing Branch 4 83/06/06 PARRIS, H Q Tennessee Valley Authority 8pp 18866 321 24X Fiche 50-327, 83/06/06, 8306150510

8306210010 Forwards "Program Plan for Control Room Design Reviews for all TVA Nuclear Plants," in response to Generic Ltr 82-33 re upgrade of emergency plans
KAMMER, D S Tennessee Valley Authority 83/06/09 ADENSAM, E
Licensing Branch 4 3pp 18913 001 24X Fiche 50-000, 83/06/09, 8306210010

--8306210016 Procedure 862209 10, "Program Plan for Control Room Design Reviews for all TVA Nuclear Plants"
* Tennessee Valley Authority 83/06/09 200pp 18913 004 24X
Fiche 50-000, 83/06/09, 8306210010

P Operating license stage documents & correspondence

8306060051 Addl response to FOIA request for three categories of documents re PRA of reactor safety study methodology application program repts & interim reliability evaluation program repts. Forwards App A documents. Search continuing
FELTON, J M Division of Rules and Records 83/04/07 SMOLLY, B C
Union of Concerned Scientists 3pp 18732 001 24X
Fiche 50-000, 83/04/07, 8306060051

--8306060085 Provides info on boron precipitation clogging HPI lines & failure of operator to switch to hot leg injection in order to flush out boron residue from core during recirculation. Info obtained from PRAs
DAVIS, B NRC - No Detailed Affiliation Given 83/02/24
THADANI, A NRC - No Detailed Affiliation Given 6pp 18732 206 24X Fiche 50-000, 83/04/07, 8306060085

8306140299 Advises that action required by 830216 Amend 14 to License DPR-79 & Generic Ltr 83-07 complete, based on util negotiation w/DOE re disposal of high level waste or spent nuclear fuel
ADENSAM, E O Licensing Branch 4 83/06/01 PARRIS, H Q Tennessee Valley Authority 2pp 18844 333 24X Fiche 50-328, 83/06/01, 8306140299

8306080208 Advises that partial response to BER open items re environ qualification of safety-related electrical equipment will be submitted by 830701 & remaining info by 830729
MILLS, L M Tennessee Valley Authority 83/06/02 ADENSAM, E
Licensing Branch 4 2pp 18771 183 24X Fiche 50-327, 83/06/02, 8306080208

8306080212 Requests meeting to discuss integrated mod schedule for Unit 2, mod deferrals proposed & justifications provided. Scheduled outages, coupled w/normal forced outage rate, could result in lack of sufficient operating reserves
MILLS, L M Tennessee Valley Authority 83/06/02 ADENSAM, E
Licensing Branch 4 36pp 18771 216 24X Fiche 50-327, 83/06/02, 8306080212

8306210027 Forwards Rev 7 to "Bequoyah Nuclear Plant Offsite Dose Calculation Manual"
MILLS, L M Tennessee Valley Authority 83/06/15 ADENSAM, E
Licensing Branch 4 1p 18911 261 24X Fiche 50-327, 83/06/15, 8306210027

--8306210032 Rev 7 to "Bequoyah Nuclear Plant Offsite Dose Calculation Manual."
* Tennessee Valley Authority 83/03/23 81pp 18911 262 24X
Fiche 50-327, 83/06/15, 8306210027

8306210115 Application for amend to Licenses DPR-77 & DPR-79, changing Tech Spec 4 B.1.1.2 d.11 re surveillance for diesel generator Class III fee for Unit 1 & Class I fee for Unit 2 will be forwarded
MILLS, L M Tennessee Valley Authority 83/06/15 ADENSAM, E
Licensing Branch 4 2pp 18914 102 24X Fiche 50-327, 83/06/15, 8306210115

--8306210117 Proposed changes to Tech Spec 4 B.1.1.2 d.11 re surveillance for diesel generator
* Tennessee Valley Authority 83/06/15 4pp 18914 104 24X
Fiche 50-327, 83/06/15, 8306210115

8306210180 Agrees w/NRC 830520 fee determination. Fee will be submitted by wire transfer
MILLS, L M Tennessee Valley Authority 83/06/15 MILLER, W D
License Fee Management Branch 1p 18918 236 24X
Fiche 50-327, 83/06/15, 8306210180

DOCKETED ITEMS

8306230272 Application for amend to License DPR-79, proposing changes to license conditions re post-accident sampling Description of proposed changes, justification & significant hazards determination for proposed license conditions encl
MILLS, L. M. Tennessee Valley Authority. 83/06/16 ADENSAH, E. Licensing Branch 4. 17pp. 18945 112 24X Fiche 50-328, 83/06/16, 8306230272

8306230444 Application to amend License DPR-79, temporarily changing Tech Spec surveillance requirements for rod drop times (Tech Specs 4.1 3 4 c) & for full-length control rod position limit switches in Table Tech Specs 4 3 3 5
MILLS, L. M. Tennessee Valley Authority. 83/06/21 ADENSAH, E. Licensing Branch 4. 2pp. 18942 100 24X Fiche 50-328, 83/06/21, 8306230444

--8306230453 Proposed temporary changes to Tech Specs 4.1 3 4 c re surveillance requirements for rod drop time & Tech Specs 4 3 3 5 re full-length control rod position limit switches
* Tennessee Valley Authority. 83/06/21 App. 18942 102. 24X Fiche 50-328, 83/06/21, 8306230444

8306280178 Forwards 830615 change request for NPDES Permit TN0026450 re 60-day extension of submittal of thermal plume report required by Part III E
MILLS, L. M. Tennessee Valley Authority. 83/06/22 ADENSAH, E. Licensing Branch 4. 2pp. 19015 084 24X Fiche 50-327, 83/06/22, 8306280178.

Q Inspection reports, IE Bulletins & correspondence

8306140543 Confirms met meeting on 830421 in Chattanooga, TN to review results of first phase of annual appraisal of regulatory performance, per 830328 telcon
LEWIS, R. C. Division of Project & Resident Programs. 83/04/12 PARRIS, H. O. Tennessee Valley Authority. 3pp. 18934 176 24X Fiche 50-000, 83/04/12, 8306140543

8306140386 Forwards IE Insp Repts 50-327/83-07 & 50-328/83-07 on 830306-0405 No noncompliance noted
VERRELLI, D. M. Region 2, Office of Director. 83/05/17 PARRIS, H. O. Tennessee Valley Authority. 2pp. 18832 076. 24X Fiche 50-327, 83/05/17, 8306140386

--8306140390 IE Insp Repts 50-327/83-07 & 50-328/83-07 on 830306-0405. No noncompliance noted Major areas inspected operational safety verification, IE bulletin closeout & LER review & independent insp effort
FORD, E. J., BUTLER, B. D. Region 2, Office of Director. QUICK, D. R. Division of Project & Resident Programs. 83/05/17. 6pp. 18832-078 24X Fiche 50-327, 83/05/17, 8306140386

8306140535 Forwards IE Insp Repts 50-327/83-06 & 50-328/83-06 on 830328-0401. No noncompliance noted.
VERRELLI, D. M. Division of Project & Resident Programs. 83/05/23 PARRIS, H. O. Tennessee Valley Authority. 2pp. 18843 268. 24X Fiche 50-327, 83/05/23, 8306140535

--8306140542 IE Insp Repts 50-327/83-06 & 50-328/83-06 on 830328-0401 No noncompliance noted Major areas inspected emergency preparedness, deficiency in emergency detection & classification program noted
HARSTON, R. R. Region 2, Office of Director. JENKINS, O. R. Division of Emergency Preparedness & Materials Safety. 83/05/17 9pp. 18843-270. 24X Fiche 50-327, 83/05/23, 8306140535

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl
TAYLOR, J. M. Division of Safeguards & Inspection Programs (Post 830103). 83/05/26. Consolidated Edison Co. of New York, Inc. 129pp. 18931 043. 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/26 Consolidated Edison Co. of New York, Inc. 115pp. 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8306140137 Ack receipt of 830511 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/83-05 & 50-328/83-05
LEWIS, R. C. Division of Project & Resident Programs. 83/05/26 PARRIS, H. O. Tennessee Valley Authority. 1p. 18839 115 24X Fiche 50-327, 83/05/26, 8306140137

--8306140142 Responds to NRC 830414 ltr re violations noted in IE Insp Repts 50-327/83-05 & 50-328/83-05, Corrective actions training meetings held w/each operations shift group stressing importance of proper sig alignment.
MILLS, L. M. Tennessee Valley Authority. 83/05/11 O'REILLY, J. P. Region 2, Office of Director. App. 18839 116. 24X Fiche 50-327, 83/05/26, 8306140137.

--8306140145 Forwards IE Insp Repts 50-327/83-05 & 50-328/83-05 on 830206-0305 & notice of violation
LEWIS, R. C. Division of Project & Resident Programs. 83/04/14 PARRIS, H. O. Tennessee Valley Authority. 2pp. 18839 120 24X Fiche 50-327, 83/05/26, 8306140137

--8306140149 Notice of violation from insp on 830206-0305
* Region 2, Office of Director. 83/04/14 2pp. 18839 122 24X Fiche 50-327, 83/05/26, 8306140137

--8306140162 IE Insp Repts 50-327/83-05 & 50-328/83-05 on 830306-0305 Noncompliance noted during planned release from tank decontamination tank, valve 0-77-573 was open, allowing release of approx 5,300 gallons from monitor tank
FORD, E. J., BUTLER, B. D. Region 2, Office of Director. QUICK, D. R. Division of Project & Resident Programs. 83/04/07 7pp. 18839 124 24X Fiche 50-327, 83/05/26, 8306140137

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/31 Consolidated Edison Co. of New York, Inc. 116pp. 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306290388 Forwards response to IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators" ERCW supply & discharge check valves will be disassembled & visually inspected at least once every 24 months
MILLS, L. M. Tennessee Valley Authority. 83/06/07 O'REILLY, J. P. Region 2, Office of Director. App. 19055 293 24X Fiche 50-327, 83/06/07, 8306290388

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/09 Consolidated Edison Co. of New York, Inc. 119pp. 18830 280 24X Fiche 50-000, 83/06/09, 8305110461

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/13 Consolidated Edison Co. of New York, Inc. 118pp. 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/13 Consolidated Edison Co. of New York, Inc. 243pp. 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8306290483 Approves issuance of SALP Repts 50-259/83-04, 50-260/83-04, 50-296/83-04, 50-327/83-04, 50-328/83-04, 50-390/83-07, 50-391/83-06, 50-438/83-06 & 50-439/83-06 for Jul 1981 - Dec 1982 No reply required
O'REILLY, J. P. Region 2, Office of Director. 83/06/17 PARRIS, H. O. Tennessee Valley Authority. 3pp. 24X Fiche 50-000, 83/06/17, 8306290483

--8306290490 Forwards SALP Repts 50-259/83-04, 50-260/83-04, 50-296/83-04, 50-327/83-04, 50-328/83-04, 50-390/83-07, 50-391/83-06, 50-438/83-06 & 50-439/83-06 for Jul 1981 - Dec 1982.
LEWIS, R. C. Division of Project & Resident Programs. 83/04/13 PARRIS, H. O. Tennessee Valley Authority. 3pp. 24X Fiche 50-000, 83/06/17, 8306290483

--8306290503 SALP Repts 50-259/83-04, 50-260/83-04, 50-296/83-04, 50-327/83-04, 50-328/83-04, 50-390/83-07, 50-391/83-06, 50-438/83-06 & 50-439/83-06 for Jul 1981 - Dec 1982
* Region 2, Office of Director. 83/04/13 92pp. 24X Fiche 50-000, 83/06/17, 8306290483

--8306290510 Comments on SALP Repts 50-259/83-04, 50-260/83-04, 50-296/83-04, 50-327/83-04, 50-328/83-04, 50-390/83-07, 50-391/83-06, 50-438/83-06 & 50-439/83-06 for Jul 1981 - Dec 1982
MILLS, L. M. Tennessee Valley Authority. 83/05/10 O'REILLY, J. P. Region 2, Office of Director. 2pp. 24X Fiche 50-259, 83/06/17, 8306290483.

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/22 Consolidated Edison Co. of New York, Inc. 115pp. 19021 179. 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment" Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp. 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

0305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, C L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000,83/06/23,8305110479

0305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000,83/06/24,8305110483

Periodic operating reports & related correspondence

06020197 Monthly operating repts for Mar 1983 W/830414 ltr
MASON, C C , DUPREE, D C , EDDINGS, M Tennessee Valley Authority
83/04/14 27pp 18691 093 24X Fiche 50-327,83/04/14,8306020197

06140526 "NPDES Discharge Monitoring Rept, Feb-Apr 1983 "
CLASHRY, M T Tennessee Valley Authority 83/05/28 90pp
18638 126 24X Fiche 50-327,83/05/28,8306140526

Reportable occurrences, LERs & related correspondence

06010014 Updated LER 83-004/03X-1 on 830107, during performance of Surveillance Instruction (SI) 51 low boron concentration discovered in refueling water storage tank Cause not stated
No leakage paths discovered W/830524 ltr
CARVER, A M , GREEN, H J , HARDING, M R Tennessee Valley Authority
83/05/24 O'REILLY, J P Region 2, Office of Director 2pp
18673 264 24X Fiche 50-328,83/05/24,8306010014

06010169 LER 83-061/03L-0 on 830429, steam generator 2 pressure indicator failed low & declared inoperable Caused by failed Forboro model current-to-current module due to faulty transistors Transistors replaced W/830524 ltr
OGERB, H R , HARDING, M R , ORFLN, H J Tennessee Valley Authority
83/05/24 O'REILLY, J P Region 2, Office of Director 2pp
18673 037 24X Fiche 50-328,83/05/24,8306010169

06070218 LER 83-068/03L-0 on 830504, during routine filling of cold leg 2 accumulator, safety injection pump inadvertently left on, resulting in accumulator being overfilled & overpressurized Caused by personnel error W/830601 ltr
UDWIG, W C , HARDING, M R , GREEN, H J Tennessee Valley Authority
83/06/01 O'REILLY, J P Region 2, Office of Director 2pp
8746 150 24X Fiche 50-328,83/06/01,8306070218

06100173 LER 83-072/03L-0 on 830506, while in Mode 1, remote shutdown team generator 1 pressure indicator declared inoperable due to failing high Caused by loose connection on oscillator connection repaired & isolator recalibr W/830603 ltr
OGERB, H R , HARDING, M R , GREEN, H J Tennessee Valley Authority
83/06/03 O'REILLY, J P Region 2, Office of Director 2pp
8805 324 24X Fiche 50-328,83/06/03,8306100173

06130242 LER 83-069/03L-0 on 830508, RCS subcooling margin monitor declared inoperable due to loss of plant process computer caused by breaker operation on power grid sys Computer restarted & monitor returned to svc W/830603 ltr
OGERB, H R , HARDING, M R , GREEN, H J Tennessee Valley Authority
83/06/03 O'REILLY, J P Region 2, Office of Director 2pp
8826 307 24X Fiche 50-328,83/06/03,8306130242

06210290 LER 83-073/03L-0 on 830517, shield bldg exhaust gaseous effluent radiation monitor 0-RM-90-100 failed to meet surveillance requirements Caused by weak photomultiplier ube Tube replaced W/830614 ltr
OGERB, H R , HARDING, M R , GREEN, H J Tennessee Valley Authority
83/06/14 O'REILLY, J P Region 2, Office of Director 2pp
8915 125 24X Fiche 50-328,83/06/14,8306210290

06210090 LER 83-074/03L-0 on 830517, due to failure of plant process computer, RCS subcooling margin monitor declared inoperable caused by power interruption Computer restarted & monitor returned to svc W/830615 ltr
OGERB, H R , HARDING, M R , GREEN, H J Tennessee Valley Authority
83/06/15 O'REILLY, J P Region 2, Office of Director 2pp
8914 166 24X Fiche 50-328,83/06/15,8306210090

06210106 LER 83-078/03L-0 on 830523, steam generator liquid effluent line radiation monitor 2-RM-90-120/121 declared inoperable due to loss of sample flow Caused by loose tubing connection monitor flow switch Connection tightened W/830615 ltr
OGERB, H R , HARDING, M R , GREEN, H J Tennessee Valley Authority
83/06/15 O'REILLY, J P Region 2, Office of Director 2pp
1914, 114 24X Fiche 50-328,83/06/15,8306210106

X Onsite Storage of Low Level Waste

8306060102 Responds to 830422 ltr re determination of fees for low level radwaste amend applications Fee determination acceptable
MILLER, L M Tennessee Valley Authority 83/06/01 MILLER, W D
License Fee Management Branch 1p 18719 359 24X
Fiche 50-000,83/06/01,8306060102

DOCKET 50-329 MIDLAND PLANT, UNIT 1

A Application/construction stage documents & correspondence

8306160035 FOIA request, on behalf of EE Kent, for documents re Jul 1982 stop work order issued to util
GARDE, B Government Accountability Project 83/02/16, Office of Administration 1p 18892 334 24X Fiche 50-329,83/02/16,8306160035

8306160031 Clarifies NRC final response to FOIA request for documents re Zack Co &/or work performed by Zack in const of facilities App D Document 5 deleted since document identical to App A Document 135
FELTON, J M Division of Rules and Records 83/04/14
PRENDERGAST, R Prendergast, R J 1p 18872 356 24X
Fiche 50-000,83/04/14,8306160031

8306160033 Responds to FOIA request for documents re Jul 1982 stop work order issued to util Request withdrawn, per 830414 telcon between requester & N Toms Case closed.
FELTON, J M Division of Rules and Records 83/04/14 GARDE, B
Government Accountability Project 1p 18892 333 24X
Fiche 50-329,83/04/14,8306160033

8306150220 Forwards M Srinivasan 830121 memo responding to Region III request for NRR position on applicant exceptions to Reg Guide 1 29 re emergency diesel generator exhaust sys hangers NRR position on issue undeveloped
WILCOVE, M N Hearing Branch 2 83/05/13 BERNABEI, L Government Accountability Project 4pp 18846 314 24X Fiche 50-329,83/05/13,8306150220

8306030191 Summary of 830208 meeting w/applicant, NUTECH Corp & Structural Mechanics Assoc in Bethesda, MD re seismic & dynamic equipment qualification program Attendance list, meeting agenda & viewgraphs encl
HERNAN, R W Licensing Branch 4 83/05/19 Licensing Branch 4
107pp 18734 132 24X Fiche 50-329,83/05/19,8306030191

8306020601 Requests deletion of LL Bishop from TERA Corp independent design & const verification program list
ADENBAM, E O Licensing Branch 4 83/05/24 LEVIN, H. TERA Corp.
2pp 18715 056 24X Fiche 50-329,83/05/24,8306020601

8306020611 Board Notification 83-21C forwards evaluation of Board Notification BN-83-21 re effectiveness of auxiliary feedwater spray potentially significant w/respect to achieving & maintaining natural circulation in B&W reactors
NOVAK, T M Assistant Director for Licensing, 83/05/24 Atomic Safety and Licensing Board Panel 3pp 18715 047 24X
Fiche 50-329,83/05/24,8306020611

8306070449 Summary of 830322 meeting w/util & consultants in Bethesda, MD re reactor vessel hotlines weld (WF-70) anomaly (Unresolved Safety Issue A-11), Attendance list encl.
HERNAN, R W Licensing Branch 4 83/05/25 Licensing Branch 4.
4pp 18780 355 24X Fiche 50-329,83/05/25,8306070449

8306060189 Lists remedial soils work activities authorized for June 1983
HARRISON, J J. Region 3, Office of Director 83/05/27, MILLER, D. B
Consumers Power Co 2pp 18728 274, 24X Fiche 50-329,83/05/27,8306060189

--8306060192 Requests work authorization for svc water pump structure underpinning program & train B svc water pipe replacement
MOONEY, J A Consumers Power Co 83/05/25, HARRISON, J J Region 3, Office of Director 1p 18728 275 24X Fiche 50-329,83/05/27,8306060192

8306070454 Summary of 830511 meeting w/util & B&W in Bethesda, MD re natural circulation cooldown capabilities & reactor vessel head vent installation Attendance list & agenda encl.
HERNAN, R W Licensing Branch 4 83/05/31 Licensing Branch 4
8pp 18782 305 24X Fiche 50-329,83/05/31,8306070454

8306070425 Summary of 830419-21 meetings w/util, Bechtel & NRC Caseload Forecast Panel re const completion schedules Supporting documentation encl
HOOD, D Licensing Branch 4 83/06/01, Licensing Branch 4.
111pp 18782 159, 24X Fiche 50-329,83/06/01,8306070425

DOCKETED ITEMS

- 8306090321 Forwards proposed remedial soils work activity lists for June & Jul 1993, per ASLB 830430 order, for review, comment & authorization
MOONEY, J A Consumers Power Co 83/06/01 HARRISON, J J Region 3, Office of Director 23pp 18795 127 24X Fiche 50-329, 83/06/01, 8306090321
- 8306130368 Forwards Rev 2 to Bechtel Field Instruction FIC-5 100, "Excavation Permit Sys." for review Rev increases scope of work to include excavations associated w/underpinning of auxiliary bldg & svc water pump structure
MILLER, D B Consumers Power Co 83/06/02 HARRISON, J J Region 3, Office of Director 1p 18822 164 24X Fiche 50-329, 83/06/02, 8306130368
- 8306130372 Rev 2 to Field Instruction FIC-5 100, "Excavation Permit Sys."
LEUTSCH, R, HARVEY, S, NEUVILLE, C L Bechtel Corp 83/06/01 19pp 18822 163 24X Fiche 50-329, 83/06/02, 8306130368
- 8306100268 Forwards "Const Completion Program" & Rev 1 to "Quality Verification Program," per listed submittals
COOK, J W Consumers Power Co 83/06/03 KEPLER, J D Region 3, Office of Director 3pp 18806 259 24X Fiche 50-329, 83/06/03, 8306100268
- 8306100269 "Const Completion Program"
* Consumers Power Co 83/06/03 37pp 18806 262 24X Fiche 50-329, 83/06/03, 8306100268
- 8306100272 Rev 1 to "Quality Verification Program Midland Nuclear Co Generation Plant Units 1 & 2"
* Consumers Power Co PR483-0014A-0L07 R1 83/05/24 64pp 18806 299 24X Fiche 50-329, 83/06/03, 8306100268
- 8306130308 Forwards chronology of vendor participation in initial overview of const completion program
BARANOW, S W Stone & Webster Engineering Corp 83/06/03 KEPLER, J D Region 3, Office of Director 3pp 18823 331 24X Fiche 50-329, 83/06/03, 8306130308
- 8306140377 Forwards revised Table D-1, "Preliminary Stress Level Comparison," showing value of stress concentration factor & higher calculated peak stresses. Higher peak stresses do not affect conclusions from 830506 meeting. Meeting summary encl
TAYLOR, J H Dabcock & Hilcor Co 83/06/07 MINER, S NRC - No Detailed Affiliation Given 2pp 18844 001 24X Fiche 50-000, 83/06/07, 8306140377
- 8306140524 Forwards repts & procedures re sys interaction program. Documents are to be used in identification phase of program
COOK, J W Consumers Power Co 83/06/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18837 018 24X Fiche 50-329, 83/06/07, 8306140524
- 8306140532 Rev 1 to "Program Manual Spatial Sys Interaction Program/Beismic Midland Energy Ctr."
CARMEAN, A R Mark G Jones Engineering Consultants, Inc 83/06/06 114pp 18837 020 24X Fiche 50-329, 83/06/07, 8306140524
- 8306140534 Rev 2 to "QA Manual"
COHAN, K Mark G Jones Engineering Consultants, Inc 83/01/12 22pp 18837 134 24X Fiche 50-329, 83/06/07, 8306140524
- 8306140539 Rev 2 to "Midland Energy Ctr Spatial Sys Interaction Program/Beismic MOJEC Project Quality Plan"
DURAND, R J Mark G Jones Engineering Consultants, Inc 83/06/02 15pp 18837 166 24X Fiche 50-329, 83/06/07, 8306140524
- 8306140540 Rev 2 to 8301-PIP-1-0, "Procedure for Project Interface Control."
DURAND, R J, Mark G Jones Engineering Consultants, Inc 83/06/01 6pp 18837 181 24X Fiche 50-329, 83/06/07, 8306140524
- 8306140544 Rev 2 to 8301-1-0, "Qualifications of QA Audit Personnel"
DURAND, R J, Mark G Jones Engineering Consultants, Inc 83/06/01 7pp 18837 187 24X Fiche 50-329, 83/06/07, 8306140524
- 8306140546 Rev 2 to 8301-WTP-1-0, "Procedure for Documentation of Postulated Interactions."
DURAND, R J, Mark G Jones Engineering Consultants, Inc 83/06/01 7pp 18837 194 24X Fiche 50-329, 83/06/07, 8306140524
- 8306140548 Rev 2 to 8301-WTP-2-0, "Procedure for Training of SSIP/S Walkdown Team Members"
DURAND, R J Mark G Jones Engineering Consultants, Inc 83/06/01 7pp 18837 201 24X Fiche 50-329, 83/06/07, 8306140524
- 8306140552 Rev 2 to 8301-WTP-3-0, "Procedure for Performing Walkdown of SSIP/S Targets"
DURAND, R J Mark G Jones Engineering Consultants, Inc 83/06/01 18837 208 24X Fiche 50-329, 83/06/07, 8306140524
- 8306140555 Rev 2 to ATP-1-0, "Procedure for Control of Project Correspondence"
* Mark G Jones Engineering Consultants, Inc 83/03/26 10pp 18837 214 24X Fiche 50-329, 83/06/07, 8306140524
- 8306140557 Rev 3 to ATP-2-0, "Procedure for Distribution & Verification of Quality Related Procedures"
* Mark G Jones Engineering Consultants, Inc 83/06/01 4pp 18837 224 24X Fiche 50-329, 83/06/07, 8306140524
- 8306140560 Rev 1 to ATP-4-0, "Procedure for Providing MOJEC QA Program"
* Mark G Jones Engineering Consultants, Inc 83/01/20 5pp 18837 230 24X Fiche 50-329, 83/06/07, 8306140524
- 8306140566 Rev 1 to ATP-5-0, "Procedure for Providing Project Orientation"
* Mark G Jones Engineering Consultants, Inc 83/01/28 5pp 18837 235 24X Fiche 50-329, 83/06/07, 8306140524
- 8306140573 Rev 2 to ATP-6-0, "Procedure for Performing Internal QA Audits"
DURAND, R J Mark G Jones Engineering Consultants, Inc 83/03/18 8pp 18837 240 24X Fiche 50-329, 83/06/07, 8306140524
- 8306140579 Rev 2 to ATP-7-0, "Procedure for Training MOJEC Audit Team Members"
DURAND, R J Mark G Jones Engineering Consultants, Inc 83/03/18 3pp 18837 248 24X Fiche 50-329, 83/06/07, 8306140524
- 8306140587 Rev 2 to ATP-8-0, "Procedure for Control of Computer Programs"
DURAND, R J Mark G Jones Engineering Consultants, Inc 83/03/31 6pp 18837 253 24X Fiche 50-329, 83/06/07, 8306140524
- 8306140592 Rev 1 to ATP-9-0, "10CFR21-Procedure for Reporting of Defects & Noncompliance"
* Mark G Jones Engineering Consultants, Inc 83/05/26 7pp 18837 259 24X Fiche 50-329, 83/06/07, 8306140524
- 8306140597 Rev 1 to ATP-10-0, "Procedure for Document Control"
DURAND, R J Mark G Jones Engineering Consultants, Inc 83/06/01 8pp 18837 266 24X Fiche 50-329, 83/06/07, 8306140524
- 8306140605 Rev 1 to ATP-11-0, "Procedure for Identification, Documentation & Corrective Action for Nonconformances"
DURAND, R J Mark G Jones Engineering Consultants, Inc 83/01/01 7pp 18837 274 24X Fiche 50-329, 83/06/07, 8306140524
- 8306160235 Requests authorization to perform listed remedial soils work on const of new ring beam
MOONEY, J A Consumers Power Co 83/06/08 HARRISON, J J Region 3, Office of Director 1p 18861 235 24X Fiche 50-329, 83/06/08, 8306160235
- 8306170477 Summary of 830413 meeting w/Util & TERA Corp in Bethesda, MD re independent design & const verification program items discussed included protocol for reporting & communications & TERA team organization
MOODY, D Licensing Branch 4 83/06/09 Licensing Branch 4, 4pp 18894 325 24X Fiche 50-329, 83/06/09, 8306170477
- 8306270242 Requests authorization to install svc water pump structure dewatering wells to elevation 570 ft. Evaluation of continuous sampling of borings encl w/three oversize drawings. Aperture cards are available in PDR
MOONEY, J A Consumers Power Co 83/06/10 HARRISON, J J Region 3, Office of Director 38pp 18990 150 24X Fiche 50-329, 83/06/10, 8306270242
- 8306230250 Requests authorization to begin work on installation of dewatering discharge sys, including headers, tank, pumps & electrical (Activity 207050636)
MOONEY, J A Consumers Power Co 83/06/13 HARRISON, J J Region 3, Office of Director 1p 18745 227 24X Fiche 50-329, 83/06/13, 8306230250
- 8306230121 Forwards Rev 0 to const implementation overview organization chart, dtd 830401.
BARANOW, S W Stone & Webster, Inc 83/06/15 KEPLER, J D Region 3, Office of Director 5pp 18947 049 24X Fiche 50-329, 83/06/15, 8306230121

DOCKETED ITEMS

175

8306270309 Forwards project QA plan & QC instruction, developed to implement const implementation overview of const completion program for review & comment
BARANOW, S W Stone & Webster, Inc 83/06/16 KEPLER, J G Region 3, Office of Director 10pp 18995 24X Fiche 50-329, 83/06/16, 8306270309

8306270262 Forwards mgt review committee const implementation overview observations of 830601 meeting re quality verification program Quality verification program conditionally approved
BARANOW, S W Stone & Webster, Inc 83/06/17 KEPLER, J G Region 3, Office of Director 5pp 18990 191 24X Fiche 50-329, 83/06/17, 8306270262

8306270336 Authorizes listed remedial soils work activities scheduled for June 1983
HARRISON, J J Region 3, Office of Director 83/06/20 MILLER, D D Consumers Power Co 2pp 18993 161 24X Fiche 50-329, 83/06/20, 8306270336

8306270367 Requests details of remedial soils activities in Section 1 of Attachment A, scheduled for month of Jul 1983 & identified as critical work activities in Section 3 scheduled for month of Jul 1983 reviewed & determined noncritical
HARRISON, J J Region 3, Office of Director 83/06/21 MILLER, D D Consumers Power Co 3pp 18993 315 24X Fiche 50-329, 83/06/21, 8306270367

8306270438 Summary of 830606 meeting w/ Miller, util counsel, re testimony by Region III witnesses in facilities proceeding
LEWIS, B H Region 3, Office of Director 83/06/21 Region 3, Office of Director 1p 18792 066 24X Fiche 50-329, 83/06/21, 8306270438

8306280070 Reiterates position that all safety-related equipment needed for safe shutdown must be demonstrated to be functional during & after seismic margin earthquake
Adherence necessary for acceptance of seismic qualification
NOVAK, T M Assistant Director for Licensing 83/06/21 (COOK, J W Consumers Power Co 3pp 17049 316 24X Fiche 50-329, 83/06/21, 8306280070

8306270150 Forwards const completion program dtd 830610 for review & approval Response requested by 830701 Quality verification plan/statistical sampling plan review not needed until
830902 Licensee can begin team training on 830620 W/o encl
WARNICK, R F Region 3, Office of Director 83/06/23 EISENHAUT, D G Division of Licensing TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 1p 18993 041 24X Fiche 50-329, 83/06/23, 8306270150

8306270339 Authorizes util to proceed w/scheduled remedial soils activities (207050605, 207050600 & 207050609) for June 1983
HARRISON, J J Region 3, Office of Director 83/06/23 MILLER, D D Consumers Power Co 2pp 18993 125 24X Fiche 50-329, 83/06/23, 8306270339

--8306270349 Requests authorization to install remaining ejector wells & piezometers, per remedial soils work activities (207050605 & 207050600)
MOONEY, J A Consumers Power Co 83/06/10 HARRISON, J J Region 3, Office of Director 1p 18993 127 24X Fiche 50-329, 83/06/23, 8306270339

8306290493 Discusses noncompliance w/penetration flued head mntl specs & forwards "Reclassification of Flued Head Fittings at Midland Plant Units 1 & 2"
DEWITT, R D Consumers Power Co 83/06/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 27pp 19049 001 24X Fiche 50-329, 83/06/23, 8306290493

--8306290494 "Reclassification of Flued Head Fittings at Midland Plant Units 1 & 2"
BYRON, J D, EGAN, O R Aptech Engineering Services 83/06/30 27pp 19049 029 24X Fiche 50-329, 83/06/23, 8306290493

8306280539 Advises that review of IERA expanded engineering program plan for independent design & const verification program completed No comments or questions generated
WARNICK, R F Region 3, Office of Director 83/06/24 NOVAK, T M Assistant Director for Licensing 1p 19019 374 24X Fiche 50-329, 83/06/24, 8306280539

8306300065 Documents 830622 telcon between R Wieland & R Landsman Util intends to install expansion anchors for formwork & concrete mudmat for new borated water storage tank under Activities
31215007 & 32215007
MOONEY, J A Consumers Power Co 83/06/24 HARRISON, J J Region 3, Office of Director 1p 19120 272 24X Fiche 50-329, 83/06/24, 8306300065

8306300101 Informs of completion of preliminary review of 830610 submittal re const completion program initiation of program training activities authorized
WARNICK, R F Region 3, Office of Director 83/06/27 COOK, J W Consumers Power Co 2pp 19048 097 24X Fiche 50-329, 83/06/27, 8306300101

--8306300105 Forwards Rev 1 to "Const Completion Program," incorporating comments & changes suggested by Region III Rev 2 to "Quality Verification Program," included as app
COOK, J W Consumers Power Co 83/06/10 KEPLER, J G Region 3, Office of Director 3pp 19048 099 24X Fiche 50-329, 83/06/27, 8306300101

--8306300109 Rev 1 to "Const Completion Program" Viewgraphs encl
* Consumers Power Co 83/06/10 38pp 19048 102 24X Fiche 50-329, 83/06/27, 8306300101

--8306300112 Rev 2 to "Quality Verification Program"
* Consumers Power Co 83/06/10 67pp 19048 140 24X Fiche 50-329, 83/06/27, 8306300101

E NRC Safety Evaluation Report (SER), suppl & correspondence

8306020062 Forwards request for addl info necessary to complete review of seismic margin review, Vol I, "Methodology & Criteria," identified in Suppl 2 to SER
ADENSAM, E O Operating Reactors Branch 4 83/05/26 COOK, J W Consumers Power Co 7pp 18701 342 24X Fiche 50-329, 83/05/26, 8306020062

8306030510 Forwards request for addl info re SER Confirmatory Issues 15, 18 & 19 Issue 19 reclassified as open item
ADENSAM, E O Licensing Branch 4 83/05/31 COOK, J W Consumers Power Co 5pp 18735 062 24X Fiche 50-329, 83/05/31, 8306030510

8306280064 Forwards request for addl info re seismic margin review Vol VI, "Borated Water Storage Tank & Foundation," per Suppl 2 to SER
ADENSAM, E O Licensing Branch 4 83/06/21 COOK, J W Consumers Power Co 6pp 19042 310 24X Fiche 50-329, 83/06/21, 8306280064,

F Security, medical, emergency & fire protection plans

8306090114 Forwards consolidated Regional Assistance Committee comments for five unrated planning elements Comments should be part of initial FEMA findings & determination of effectiveness of offsite emergency planning
MCLOUGHLIN, D Federal Emergency Management Agency 83/05/18 DIRCKS, W J Office of the Executive Director for Operations 5pp 18793 324 24X Fiche 50-329, 83/05/18, 8306090114,

8306150344 Releases public version of revised replacement pages to Bay, Saginaw & Midland County emergency preparedness plans
FELTON, J M Division of Rules and Records 83/06/06 Document Management Branch 1p 18869 004 24X Fiche 50-329, 83/06/06, 8306150344

--8306150346 Forwards public version of revised replacement pages to nuclear accident apps to Bay, Saginaw & Midland County emergency preparedness plans in response to FEMA 821214 interim findings
COOK, J W Consumers Power Co 83/03/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 18869 005 24X Fiche 50-329, 83/06/06, 8306150344

--8306150351 Public version of revised replacement pages to nuclear accident apps to Bay, Saginaw & Midland County emergency preparedness plans
* Consumers Power Co 83/03/30 137pp 18869 012 24X Fiche 50-329, 83/06/06, 8306150344,

G Adjudicatory correspondence

8306150220 Forwards M Srinivasan 830121 memo responding to Region III request for NRR position on applicant exceptions to Reg Guide 1 29 re emergency diesel generator exhaust system hangers NRR position on issue undeveloped
WILCOVE, M N Hearing Branch 2 83/05/13 BERNABEI, L Government Accountability Project, App 18846 314 24X Fiche 50-329, 83/05/13, 8306150220

8306150274 Concurs w/util 830412 ltr identifying portions of All Savage deposition transcript to be admitted into evidence w/ exception Page 10, Lines 19 - 24, outside scope of contention
WILCOVE, M N Hearing Branch 2 83/05/13 BECHHOEFER, C, COWAN, F P, HARBOUR, J Atomic Safety and Licensing Board Panel, 2pp 18849 174, 24X Fiche 50-329, 83/05/13, 8306150274,

DOCKETED ITEMS

8306020489 Memorandum & order granting, in part, applicant 830509 revised motion requiring lead intervenors to submit cross-examination plans & establish time limits on cross-examination
BECHHOEFER, C Atomic Safety and Licensing Board Panel 83/05/31
Consumers Power Co 14pp 18693 166 24X Fiche 50-329, 83/05/31, 8306020489

8306060315 Advises that M Cioni deposition rescheduled for 830608 in Chicago, IL Svc list encl
PROCTOR, S D Isham, Lincoln & Beale 83/06/01 KELLEY, F J
Michigan, State of CHERRY, M M Cherry, M M /Cherry, Flynn & Kenter MARSHALL, W H Marshall, W H 2pp 18729 185 24X
Fiche 50-329, 83/06/01, 8306060315

8306080206 Requests info re total number of wells & amount of electricity required to operate wells for dewatering
MARSHALL, W H Mapleton Intervenor 83/06/01 Commissioners
1p 18771 232 24X Fiche 50-329, 83/06/01, 8306080206

8306130420 Notice of scheduling of evidentiary hearings on 0A/0C for 830627-0701 & if necessary, for 830725-29, in Midland, MI
BECHHOEFER, C Atomic Safety and Licensing Board Panel 83/06/09
1p 18821 230 24X Fiche 50-329, 83/06/09, 8306130420

8306140660 Forwards NRC 820317 ltr, transmitting IE Insp Rept 50-410/B1-13 & notice of violation per 830608 evidentiary hearing commitment
WRIGHT, N A Hearing Branch 2 83/06/09 BERNABEI, L Government Accountability Project 1p 18833 284 24X Fiche 50-329, 83/06/09, 8306140660

8306140727 Responds to 830601 ltr ASLB, in 830428 ruling, denied 830422 request for production of documents on dewatering issue since discovery ended
WRIGHT, N A Hearing Branch 2 83/06/09 MARSHALL, W H Mapleton Intervenor 1p 18841 009 24X Fiche 50-329, 83/06/09, 8306140727

8306200306 Advises that AT Howard deposition scheduled for 830614-16 being continued Svc list encl. Related correspondence
PROCTOR, S D Isham, Lincoln & Beale 83/06/13 KELLEY, F J
Michigan, State of KELLEY, F J Cherry, M M /Cherry, Flynn & Kenter MARSHALL, W H Marshall, W H 2pp 18900 168 24X
Fiche 50-329, 83/06/13, 8306200306

8306220006 Advises that L Hallberg deposition, originally scheduled for 830621, continued. New date will be announced Svc list encl
Related correspondence
PROCTOR, S D Isham, Lincoln & Beale 83/06/16 BECHHOEFER, C Atomic Safety and Licensing Board Panel KELLEY, F J Michigan, State of 2pp 18927 358 24X Fiche 50-329, 83/06/16, 8306220006

8306220069 Advises of 830623 & 24 depositions of L Clark & T Devine, respectively Svc list encl. Related correspondence.
PROCTOR, S D Isham, Lincoln & Beale 83/06/16 KARR, J W Karr & Lyons 2pp 18930 172 24X Fiche 50-329, 83/06/16, 8306220069

8306270154 Forwards corrected copy of 820307 notice of violation package for Niagara Mohawk Power Corp.
WRIGHT, N A Hearing Branch 2, 83/06/22 BERNABEI, L Government Accountability Project 1p 19012 148 24X Fiche 50-329, 83/06/22, 8306270154

8306290498 Notice of appearance in proceeding Certificate of Svc encl
KARR, J W Government Accountability Project KARR, J W, Karr & Lyons 83/06/27 4pp 19052 331 24X Fiche 50-329, 83/06/27, 8306290498

8306290530 Motion to quash until subpoenas commanding testimony at proceedings to identify whistleblowers Subpoenas violate first amend of US Constitution Commission cannot issue subpoena in violation of confidentiality promise
KARR, J W Government Accountability Project KARR, J W, Karr & Lyons 83/06/27 Atomic Safety and Licensing Board Panel 13pp 19053 001 24X Fiche 50-329, 83/06/27, 8306290530

--8306290531 Affidavit of L Clark re representation of whistleblowers If Govt Accountability Project required to name whistleblowers, ultimate damage will be to public interest in full & free flow of info on important issues Certificate of Svc encl
CLARK, L Government Accountability Project 83/06/24 15pp 19053 014 24X Fiche 50-329, 83/06/27, 8306290530

M. Antitrust correspondence

8306030242 Forwards FR notice of finding of no significant antitrust changes & time for filing of requests for reevaluation
REGAN, W H Site Analysis Branch 83/05/24 COMBS, T Docketing & Services Branch 2pp 18734 024 24X Fiche 50-329, 83/05/24, 8306030242

--8306030246 Notice of finding of no significant antitrust changes & time for filing of requests for reevaluation
REGAN, W H Site Analysis Branch 83/05/24 2pp 18734 026 24X Fiche 50-329, 83/05/24, 8306030246

8306140345 Forwards FR notice of finding of no significant antitrust changes since CP reviews & of time for filing requests for reevaluation
REGAN, W H Site Analysis Branch 83/05/24 COOK, J W Consumers Power Co 2pp 18854 129 24X Fiche 50-329, 83/05/24, 8306140345

--8306140350 Notice of finding of no significant antitrust changes since CP review & of time for filing requests for reevaluation
REGAN, W H Site Analysis Branch 83/05/24 12pp 18854 131 24X Fiche 50-329, 83/05/24, 8306140350

8306140360 Forwards FR notice of finding of no significant antitrust changes since CP review & of time for filing requests for reevaluation
REGAN, W H Site Analysis Branch 83/05/24 COMBS, T Docketing & Services Branch 2pp 18844 349 24X Fiche 50-329, 83/05/24, 8306140360

Q Inspection reports, IE Bulletin & correspondence

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/24 Consolidated Edison Co. of New York, Inc 125pp 18831 043 24X Fiche 50-000, 83/05/24, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/24 Consolidated Edison Co. of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/24, 8305110460

8306090243 Forwards IE Insp Repts 50-329/83-06 & 50-330/83-06 on 830329-31 & 0401 & notice of violation
WARRICK, R F Region 3, Office of Director 83/05/27 COOK, J W Consumers Power Co 2pp 18795 321 24X Fiche 50-329, 83/05/27, 8306090243

--8306090244 Notice of violation from insp on 830329-31 & 0401
WARRICK, R F Region 3, Office of Director 83/05/27 1p 18795 323 24X Fiche 50-329, 83/05/27, 8306090244

--8306090245 IE Insp Repts 50-329/83-06 & 50-330/83-06 on 830329-31 & 0401 Noncompliance noted failure to follow policy procedures re control of purchased matl & svcs
SIMON, J A, BATHER, A, HARRISON, J J Region 3, Office of Director 83/05/23 4pp 18795 324 24X Fiche 50-329, 83/05/27, 8306090245

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306060048 Ack receipt of 830513 ltr informing NRC of steps taken to correct violations noted in IF Insp Repts 50-329/83-05 & 50-330/83-05
WARRICK, R F Region 3, Office of Director 83/05/31 COOK, J W Consumers Power Co 1p 18719 247 24X Fiche 50-329, 83/05/31, 8306060048

--8306060055 Responds to NRC 830304 ltr re violations noted in IE Insp Repts 50-329/83-05 & 50-330/83-05 Corrective actions Bechtel maint form written to cover installed O & non-O mechanical snubbers & 100% initial insp will be performed
COOK, J W Consumers Power Co 83/05/13 KERPLER, J O Region 3, Office of Director 4pp 18719 248 24X Fiche 50-329, 83/05/31, 8306060048

8306210443 Requests Region III inspect adequacy of util program to initially verify & periodically check for continued presence & effectiveness of Boraflex as neutron poison in spent fuel racks
CRONIN, W T Uranium Fuel Licensing Branch 83/06/08 HARRISON, J J Region 3, Office of Director 3pp 18735 359 24X
Fiche 50-329, 83/06/08, 8306210443

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

DOCKETED ITEMS

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting from Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18976 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

R Periodic operating reports & related correspondence

8306030172 Forwards Bechtel, B&W & util nonconformance repts for Apr 1983
COOK, J W Consumers Power Co 83/05/25 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 73pp 18709 096 24X Fiche 50-329, 83/05/25, 8306030172

8306270067 Forwards "Independent Design & Const Verification Program, Monthly Status Rept No 1, Period Inception Through 830527 "
LEVIN, H A TERA Corp 83/05/27 KEPPLER, J G Region 3, Office of Director [EISENHUT, D G Division of Licensing COOK, J W Consumers Power Co 3pp 19013 017 24X Fiche 50-329, 83/05/27, 8306270067

--8306270069 "Independent Design & Const Verification Program, Monthly Status Rept No 1, Period Inception Through 830527 "
TULODICKSKI, D TERA Corp 83/05/27 65pp 19013 020 24X Fiche 50-329, 83/05/27, 8306270069

S Reportable occurrences, LLRs & related correspondence

8306070242 Interim Deficiency Rept 82-06 re B&W steam generator auxiliary feedwater header design change Internal headers stabilized Mod will be completed upon receipt of thermal sleeves Next rept by 830801
COOK, J W Consumers Power Co 83/05/31 KEPPLER, J G Region 3, Office of Director 2pp 18744 244 24X Fiche 50-329, 83/05/31, 8306070242

8306130281 Interim deficiency rept re underrated terminal strips & use of terminal blocks w/o proper environ qualification in Limitorque valve operators Bechtel has requested addl info from Limitorque re qualifying terminal block types
COOK, J W Consumers Power Co 83/06/07 KEPPLER, J G Region 3, Office of Director 12pp 18824 128 24X Fiche 50-329, 83/06/07, 8306130281

8306170448 Board Notification 83-79 Forwards Zack Rept on welder record discrepancies Rept documents Zack investigation & subsequent decision that item does not constitute IOCFR21 deficiency W/s encl
NOVAK, T M Assistant Director for Licensing 83/06/09 Atomic Safety and Licensing Board Panel 2pp 18906 361 24X Fiche 50-329, 83/06/09, 8306170448

8306210302 Interim deficiency rept re adequacy of shear reinforcements at major containment penetrations As-designed & as-built containment satisfactory Repts to FSAR initiated Final or interim rept expected by 831031
COOK, J W Consumers Power Co 83/06/13 KEPPLER, J G Region 3, Office of Director 2pp 18914 015 24X Fiche 50-329, 83/06/13, 8306210302

8306220007 Part 21 rept re adequacy of fittings supplied by Tube-Line Corp through Capitol Pipe & Steel Products Co for use on new auxiliary feedwater headers of steam generators Flanges not heat-treated as required by matl specs
TAYLOR, J H Babcock & Wilcox Co 83/06/17 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 4pp 18927 354 24X Fiche 50-000, 83/06/17, 8306220007

8306270181 PNO-III-83-051 on 830621, util authorized to proceed w/installation of electrical penetration area temporary support beams & excavation under auxiliary bldg Workers laid off 830617 & 18 recalled
LANDSHAN, R HARRISON, J Region 3, Office of Director 83/06/21 1p 18991 344 24X Fiche 50-329, 83/06/21, 8306270181

T Hearing transcripts on non-antitrust matters

8306070073 Transcript of 830601 evidentiary hearing in Midland, MI Pp 16, 367-16, 552
* Atomic Safety and Licensing Board Panel 83/06/01 188pp 18740 105 24X Fiche 50-329, 83/06/01, 8306070073

8306070180 Transcript of 830602 evidentiary hearing in Midland, MI Pp 15, 553-16, 765
* Atomic Safety and Licensing Board Panel 83/06/02 205pp 18737 128 24X Fiche 50-329, 83/06/02, 8306070180

8306070187 Transcript of 830603 hearing in Midland, MI Pp 16, 766-16, 967
* Atomic Safety and Licensing Board Panel 83/06/03 205pp 18738 001 24X Fiche 50-329, 83/06/03, 8306070187

8306070162 Transcript of 830604 evidentiary hearing in Midland, MI Pp 16, 968-17, 104 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/06/04 210pp 18736 001 24X Fiche 50-329, 83/06/04, 8306070162

8306100063 Transcript of 830606 evidentiary hearing in Midland, MI Pp 17, 105-17, 195
* Atomic Safety and Licensing Board Panel 83/06/06 89pp 18802 338 24X Fiche 50-329, 83/06/06, 8306100063

8306130215 Transcript of 830607 evidentiary hearing in Midland, MI, Pp 17, 196-17, 412
* Atomic Safety and Licensing Board Panel 83/06/07 213pp 18827 011 24X Fiche 50-329, 83/06/07, 8306130215

8306140103 Transcript of 830608 evidentiary hearing in Midland, MI, Pp 17, 413-17, 637
* Atomic Safety and Licensing Board Panel 83/06/08 131pp 18839 286 24X Fiche 50-329, 83/06/08, 8306140103

8306150142 Transcript of 830609 evidentiary hearing in Midland, MI Pp 17, 638-17, 065
* Atomic Safety and Licensing Board Panel 83/06/09 86pp 18851 220 24X Fiche 50-329, 83/06/09, 8306150142

8306140108 Transcript of 830610 evidentiary hearing in Midland, MI Pp 17, 066-17, 977
* Atomic Safety and Licensing Board Panel 83/06/10 115pp 18839 171 24X Fiche 50-329, 83/06/10, 8306140108

8306200016 Transcript of Commission 830615 briefing in Washington, DC re status of GA & soil settlement at facility, Pp 1-64, Supporting documentation encl
* Commissioners 83/06/15 76pp 18909 238 24X Fiche 50-329, 83/06/15, 8306200016

V Operator Examinations

8306270271 Advises that MO Jones Engineering Consultants, Inc (MOJEC) training program, evaluated on 830608, satisfactory & may be implemented immediately Spatial sys interaction program procedures approved by util & issued by MOJEC
BARANOW, S W Stone & Webster, Inc 83/06/17 KEPPLER, J G Region 3, Office of Director 1p 18990 207 24X Fiche 50-329, 83/06/17, 8306270271

DOCKET 50-330 MIDLAND PLANT, UNIT 2

A Application/construction stage documents & correspondence

8306160035 FOIA request, on behalf of EE Kent, for documents re Jul 1982 stop work order issued to util
GARDE, D Government Accountability Project 83/02/16 Office of Administration 1p 18892 334 24X Fiche 50-329, 83/02/16, 8306160035

DOCKETED ITEMS

8306160031 Clarifies NRC final response to FOIA request for documents re Zack Co &/or work performed by Zack in const of facilities App D Document 5 deleted since document identical to App A Document 135
FELTON, J M Division of Rules and Records 83/04/14
PRENDERGAST, R Prendergast, R J 1p 18872 356 24X
Fiche 50-000, 83/04/14, 8306160031

8306160033 Responds to FOIA request for documents re Jul 1982 stop work order issued to util Request withdrawn, per 830414 telcon between requester & N Toms Case closed
FELTON, J M Division of Rules and Records 83/04/14 GARDE, D
Government Accountability Project 1p 18892 333 24X
Fiche 50-329, 83/04/14, 8306160033

8306150220 Forwards M Srinivasan 830121 memo responding to Region III request for NRR position on applicant exceptions to Reg Guide 1 29 re emergency diesel generator exhaust sys hangers NRR position on issue undeveloped.
WILCOVE, H N Hearing Branch 2 83/05/13 BERNABEI, L Government Accountability Project 4pp 18846 314 24X Fiche 50-329, 83/05/13, 8306150220

8306030191 Summary of 830208 meeting w/applicant, NUTECH Corp & Structural Mechanics Assoc in Bethesda, MD re seismic & dynamic equipment qualification program Attendance list, meeting agenda & viewgraphs encl
HERNAN, R W Licensing Branch 4 83/05/19 Licensing Branch 4 107pp 18734-132 24X Fiche 50-329, 83/05/19, 8306030191

8306020601 Requests deletion of LL Bishop from TERA Corp independent design & const verification program list
ADENSIAN, E G Licensing Branch 4 83/05/24 LEVIN, H TERA Corp 2pp 18715 056 24X Fiche 50-329, 83/05/24, 8306020601

8306020611 Board Notification 83-21C Forwards evaluation of Board Notification DN-83-21 re effectiveness of auxiliary feedwater spray potentially significant w/respect to achieving & maintaining natural circulation in B&W reactors
NOVAK, T M Assistant Director for Licensing 83/05/24 Atomic Safety and Licensing Board Panel 3pp 18715 047 24X
Fiche 50-329, 83/05/24, 8306020611

8306070449 Summary of 830322 meeting w/util & consultants in Bethesda, MD re reactor vessel beltline weld (WF-70) anomaly (Unresolved Safety Issue A-11) Attendance list encl
HERNAN, R W Licensing Branch 4 83/05/25 Licensing Branch 4 4pp 18780 355 24X Fiche 50-329, 83/05/25, 8306070449

8306060189 Lists remedial soils work activities authorized for June 1983
HARRISON, J J Region 3, Office of Director 83/05/27 MILLER, D B Consumers Power Co 2pp 10728 274 24X Fiche 50-329, 83/05/27, 8306060189

--8306060192 Requests work authorization for svc water pump structure underpinning program & train B svc water pipe replacement
MOONEY, J A Consumers Power Co 83/05/25 HARRISON, J J Region 3, Office of Director 1p 18728 275 24X Fiche 50-329, 83/05/27, 8306060189

8306070454 Summary of 830511 meeting w/util & B&W in Bethesda, MD re natural circulation cooldown capabilities & reactor vessel head vent installation Attendance list & agenda encl
HERNAN, R W Licensing Branch 4 83/05/31 Licensing Branch 4 8pp 18782-305 24X Fiche 50-329, 83/05/31, 8306070454

8306070425 Summary of 830419-21 meetings w/util, Bechtel & NRC Caseload Forecast Panel re const completion schedules, Supporting documentation encl
HOOD, D Licensing Branch 4 83/06/01 Licensing Branch 4, 111pp 18782-159 24X Fiche 50-329, 83/06/01, 8306070425

8306070321 Forwards proposed remedial soils work activity lists for June & Jul 1983, per ASLJ 830430 order, for review, comment & authorization
MOONEY, J A Consumers Power Co 83/06/01 HARRISON, J J Region 3, Office of Director 23pp 18775 127 24X Fiche 50-329, 83/06/01, 8306070321

8306130368 Forwards Rev 2 to Bechtel Field Instruction FIC-5 100, "Excavation Permit Sys," for review Rev increases scope of work to include excavations associated w/underpinning of auxiliary bldg & svc water pump structure.
MILLER, D B Consumers Power Co 83/06/02 HARRISON, J J Region 3, Office of Director 1p 18822-164 24X Fiche 50-329, 83/06/02, 8306130368

8306100268 Forwards "Const Completion Program" & Rev 1 to "Quality Verification Program," per listed submittals
COOK, J W Consumers Power Co 83/06/03 KEPLER, J Q Region 3, Office of Director 3pp 18806 259 24X Fiche 50-329, 83/06/03, 8306100268

--8306100267 "Const Completion Program"
* Consumers Power Co 83/06/03 3/pp 18806 242 24X
Fiche 50-329, 83/06/03, 8306100268

--8306100272 Rev 1 to "Quality Verification Program Midland Nuclear Co Generation Plant Units 1 & 2"
* Consumers Power Co PRQ483-0014A QL07 RI 83/05/24 64pp 18806 299 24X Fiche 50-329, 83/06/03, 8306100268

8306130308 Forwards chronology of vendor participation in initial overview of const completion program
BARAND, S W Stone & Webster Engineering Corp 83/06/03
KEPLER, J Q Region 3, Office of Director 3pp 18823 331 24X
Fiche 50-329, 83/06/03, 8306130308

8306140377 Forwards revised Table D-1, "Preliminary Stress Level Comparison," showing value of stress concentration factor & higher calculated peak stresses Higher peak stresses do not affect conclusions from 830506 meeting Meeting summary encl
FAYLOR, J H Babcock & Wilcox Co 83/06/07 MINER, S NRC - No Detailed Affiliation Given 2pp 18344 001 24X
Fiche 50-000, 83/06/07, 8306140377

8306140524 Forwards repts & procedures re sys interaction program Documents are to be used in identification phase of program
COOK, J W Consumers Power Co 83/06/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18837 018 24X
Fiche 50-329, 83/06/07, 8306140524

--8306140532 Rev 1 to "Program Manual Spatial Sys Interaction Program/ Seismic Midland Energy Ctr"
CARRISAN, A R Mark G Jones Engineering Consultants, Inc 83/06/06 114pp 18837 020 24X Fiche 50-329, 83/06/07, 8306140524

--8306140534 Rev 2 to "QA Manual"
COHAN, K Mark G Jones Engineering Consultants, Inc 83/01/12 32pp 18837 134 24X Fiche 50-329, 83/06/07, 8306140524

--8306140539 Rev 2 to "Midland Energy Ctr Spatial Sys Interaction Program/Seismic MOJEC Project Quality Plan"
DURAND, R J Mark G Jones Engineering Consultants, Inc 83/06/02 15pp 18837 166 24X Fiche 50-329, 83/06/07, 8306140524

--8306140540 Rev 2 to 8301-PIP-1-G, "Procedure for Project Interface Control"
DURAND, R J Mark G Jones Engineering Consultants, Inc 83/06/01 6pp 18837 181 24X Fiche 50-329, 83/06/07, 8306140524

--8306140544 Rev 2 to STD-1-G, "Qualifications of QA Audit Personnel"
DURAND, R J Mark G Jones Engineering Consultants, Inc 83/06/01 7pp 18837 187 24X Fiche 50-329, 83/06/07, 8306140524

--8306140546 Rev 2 to 8301-WTP-1-G, "Procedure for Documentation of Postulated Interactions"
DURAND, R J Mark G Jones Engineering Consultants, Inc 83/06/01 7pp 18837 194 24X Fiche 50-329, 83/06/07, 8306140524

--8306140548 Rev 2 to 8301-WTP-2-G, "Procedure for Training of SSIP/S Walkdown Team Members"
DURAND, R J Mark G Jones Engineering Consultants, Inc 83/06/01 7pp 18837 201 24X Fiche 50-329, 83/06/07, 8306140524

--8306140552 Rev 2 to 8301-WTP-3-G, "Procedure for Performing Walkdowns of SSIP/S Targets"
DURAND, R J Mark G Jones Engineering Consultants, Inc 83/06/01 6pp 18837-208 24X Fiche 50-329, 83/06/07, 8306140524

--8306140555 Rev 2 to ATP-1-G, "Procedure for Control of Project Correspondence"
* Mark G Jones Engineering Consultants, Inc 83/05/26 10pp 18837 214 24X Fiche 50-329, 83/06/07, 8306140524

--8306140557 Rev 3 to ATP-2-G, "Procedure for Distribution & Verifying Implementation of Quality Related Procedures"
* Mark G Jones Engineering Consultants, Inc 83/06/01 6pp 18837 224 24X Fiche 50-329, 83/06/07, 8306140524

--8306140560 Rev 1 to ATP-4-G, "Procedure for Providing MOJEC QA Program"
* Mark G Jones Engineering Consultants, Inc 83/01/28 5pp 18837-230 24X Fiche 50-329, 83/06/07, 8306140524

--8306140566 Rev 1 to ATP-5-G, "Procedure for Providing Project Orientation"
* Mark G Jones Engineering Consultants, Inc 83/01/28 5pp 18837 235 24X Fiche 50-329, 83/06/07, 8306140524

DOCKETED ITEMS

179

- 8306140573 Rev 2 to ATP-6-G, "Procedure for Performing Internal QA Audits"
DURAND, R J Mark G Jones Engineering Consultants, Inc 83/06/01
5pp 18837 240 24X Fiche 50-329, 83/06/07, 8306140524
- 8306140579 Rev 2 to ATP-7-G, "Procedure for Training MGCJC Audit Team Members"
DURAND, R J Mark G Jones Engineering Consultants, Inc 83/06/01
5pp 18837 248 24X Fiche 50-329, 83/06/07, 8306140524
- 8306140587 Rev 2 to ATP-8-G, "Procedure for Control of Computer Programs"
DURAND, R J Mark G Jones Engineering Consultants, Inc 83/06/01
6pp 18837 253 24X Fiche 50-329, 83/06/07, 8306140524
- 8306140592 Rev 1 to ATP-9-G, "10CFR21-Procedure for Reporting Of Defects & Noncompliance"
* Mark G Jones Engineering Consultants, Inc 83/05/26 7pp
18837 259 24X Fiche 50-329, 83/06/07, 8306140524
- 8306140597 Rev 1 to ATP-10-G, "Procedure for Document Control"
DURAND, R J Mark G Jones Engineering Consultants, Inc 83/06/01
6pp 18837 266 24X Fiche 50-329, 83/06/07, 8306140524
- 8306140605 Rev 1 to ATP-11-G, "Procedure for Identification, Documentation & Corrective Action for Nonconformances"
DURAND, R J Mark G Jones Engineering Consultants, Inc 83/06/01
7pp 18837 274 24X Fiche 50-329, 83/06/07, 8306140524
- 8306160235 Requests authorization to perform listed remedial soils work on const of new ring beam
MOONEY, J A Consumers Power Co 83/06/08 HARRISON, J J Region 3, Office of Director 1p 18861 239 24X Fiche 50-329, 83/06/08, 8306160235
- 8306170477 Summary of 830413 meeting w/Util & TERA Corp in Bethesda, MD re independent design & const verification program items discussed included protocol for reporting & communications & TERA team organization
HOOD, D Licensing Branch 4 83/06/07 Licensing Branch 4 4pp
18894 325 24X Fiche 50-329, 83/06/09, 8306170477
- 8306270242 Requests authorization to install svc water pump structure dewatering wells to elevation 570 ft Evaluation of continuous sampling of borings encl W/ three oversize drawings Aperture cards are available in PDR
MOONEY, J A Consumers Power Co 83/06/10 HARRISON, J J Region 3, Office of Director 38pp 18990 150 24X Fiche 50-329, 83/06/10, 8306270242
- 8306230250 Requests authorization to begin work on installation of dewatering discharge sys. including headers, tank, pumps & electrical (Activity 207050635)
MOONEY, J A Consumers Power Co 83/06/13 HARRISON, J J Region 3, Office of Director 1p 18945 227 24X Fiche 50-329, 83/06/13, 8306230250
- 8306230121 Forwards Rev O to const implementation overview organization chart, dtd 830601
BARANOW, S W Stone & Webster, Inc 83/06/15 KEPPLE, J G Region 3, Office of Director 5pp 18947 049 24X Fiche 50-329, 83/06/15, 8306230121
- 8306270309 Forwards project QA plan & QC instruction, developed to implement const implementation overview of const completion program, for review & comment
BARANOW, S W Stone & Webster, Inc 83/06/16 KEPPLE, J G Region 3, Office of Director 10pp 18995 22a 24X Fiche 50-329, 83/06/16, 8306270309
- 8306270262 Forwards mgt review committee const implementation overview observations of 830601 meeting re quality verification program Quality verification program conditionally approved
BARANOW, S W Stone & Webster, Inc 83/06/17 KEPPLE, J G Region 3, Office of Director 5pp 18990 191 24X Fiche 50-329, 83/06/17, 8306270262
- 8306270336 Authorizes listed remedial soils work activities scheduled for June 1983
HARRISON, J J Region 3, Office of Director 83/06/20 MILLER, D B Consumers Power Co 2pp 18993 161 24X Fiche 50-329, 83/06/20, 8306270336
- 8306270367 Requests details of remedial soils activities in Section 1 of Attachment A, scheduled for month of Jul 1983 & identified as critical work Work activities in Section 3 scheduled for month of Jul 1983 reviewed & determined noncritical
HARRISON, J J Region 3, Office of Director 83/06/21 MILLER, D B Consumers Power Co 3pp 18993 315 24X Fiche 50-329, 83/06/21, 8306270367
- 8306270438 Summary of 830606 meeting w/M Miller, util counsel, re testimony by Region III witnesses in facilities proceeding
LEWIS, S H Region 3, Office of Director 83/06/21 Region 3, Office of Director 1p 18992 066 24X Fiche 50-329, 83/06/21, 8306270438
- 8306280070 Reiterates position that all safety-related equipment needed for safe shutdown must be demonstrated to be functional during & after seismic margin earthquake Adherence necessary for acceptance of seismic qualification
NOVAK, T M Assistant Director for Licensing 83/06/21 COOK, J W Consumers Power Co 5pp 19042 316 24X Fiche 50-329, 83/06/21, 8306280070
- 8306270150 Forwards const completion program dtd 830610 for review & approval Response requested by 830701 Quality verification plan/statistical sampling plan review not needed until 830902 Licensee can begin team training on 830620 W/o encl.
WARNICK, R F Region 3, Office of Director 83/06/23 EISENHUT, D G Division of Licensing TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 1p 18993 041 24X Fiche 50-329, 83/06/23, 8306270150
- 8306270339 Authorizes util to proceed w/scheduled remedial soils activities (207050605, 207050600 & 207050635) for June 1983
HARRISON, J J Region 3, Office of Director 83/06/23 MILLER, D B Consumers Power Co 2pp 18993 125 24X Fiche 50-329, 83/06/23, 8306270339
- 8306270349 Requests authorization to install remaining ejector wells & piezometers, per remedial soils work activities (207050605 & 207050600)
MOONEY, J A Consumers Power Co 83/06/10 HARRISON, J J Region 3, Office of Director 1p 18993 127 24X Fiche 50-329, 83/06/23, 8306270339
- 8306290493 Discusses noncompliance w/penetration flued head matl specs & forwards "Reclassification of Flued Head Fittings at Midland Plant Units 1 & 2"
DEWITT, R D Consumers Power Co 83/06/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 27pp 19049 001 24X Fiche 50-329, 83/06/23, 8306290493
- 8306290496 "Reclassification of Flued Head Fittings at Midland Plant Units 1 & 2"
BYRON, J D, EGAN, O R Aptech Engineering Services 83/06/30 27pp 19049 029 24X Fiche 50-329, 83/06/23, 8306290493
- 8306280539 Advises that review of TERA expanded engineering program plan for independent design & const verification program completed No comments or questions generated
WARNICK, R F Region 3, Office of Director 83/06/24 NOVAK, T M, Assistant Director for Licensing 1p 19019 324, 24X Fiche 50-329, 83/06/24, 8306280539
- 8306300065 Documents 830422 telcon between R Wieland & R Landsman Util intends to install expansion anchors for formwork & concrete mudmat for new borated water storage tank under Activities 31215007 & 32215007
MOONEY, J A Consumers Power Co 83/06/24 HARRISON, J J Region 3, Office of Director 1p 19120 272 24X Fiche 50-329, 83/06/24, 8306300065
- 8306300101 Informs of completion of preliminary review of 830610 submittal re const completion program Initiation of program training activities authorized
WARNICK, R F Region 3, Office of Director 83/06/27 COOK, J W, Consumers Power Co 2pp 19048 097 24X Fiche 50-329, 83/06/27, 8306300101
- 8306300105 Forwards Rev 1 to "Const Completion Program," incorporating comments & changes suggested by Region III Rev 2 to "Quality Verification Program," included as app
COOK, J W Consumers Power Co 83/06/10 KEPPLE, J G, Region 3, Office of Director 3pp 19048 099 24X Fiche 50-329, 83/06/27, 8306300101
- 8306300109 Rev 1 to "Const Completion Program," Viewgraphs encl
* Consumers Power Co 83/06/10 38pp 19048 102 24X Fiche 50-329, 83/06/27, 8306300101
- 8306300112 Rev 2 to "Quality Verification Program"
* Consumers Power Co 83/06/10 67pp 19048 140 24X Fiche 50-329, 83/06/27, 8306300101

DOCKETED ITEMS

E NRC Safety Evaluation Report (SER), suppl & correspondence

8306020062 Forwards request for addl info necessary to complete review of seismic margin review, Vol 1, "Methodology & Criteria," identified in Suppl 2 to SER
ADENSAH, E G Operating Reactors Branch 4 83/05/86 COOK, J W Consumers Power Co 7pp 18701 342 24X Fiche 50-329, 83/05/26, 8306020062

8306030510 Forwards request for addl info re SER Confirmatory Issues 15, 18 & 19 Issue 19 reclassified as open item
ADENSAH, E G Licensing Branch 4, 83/05/31 COOK, J W Consumers Power Co 5pp 18733 062 24X Fiche 50-329, 83/05/31, 8306030510

8306280054 Forwards request for addl info re seismic margin review Vol VI, "Borated Water Storage Tank & Foundation," per Suppl 2 to SER
ADENSAH, E G Licensing Branch 4 83/06/21 COOK, J W Consumers Power Co 6pp 19042 310 24X Fiche 50-329, 83/06/21, 8306280054

F Security, medical, emergency & fire protection plans

8306090114 Forwards consolidated Regional Assistance Committee comments for five unratified planning elements Comments should be part of initial FEMA findings & determination of effectiveness of offsite emergency planning
MCLOUGHLIN, D. Federal Emergency Management Agency 83/05/18 DIRCKS, W J Office of the Executive Director for Operations 5pp 18793 324 24X Fiche 50-329, 83/05/18, 8306090114

8306150344 Releases public version of revised replacement pages to Bay, Saginaw & Midland County emergency preparedness plans
FELTON, J M Division of Rules and Records 83/06/06 Document Management Branch 1p 18869 004 24X Fiche 50-329, 83/06/06, 8306150344

--8306150346 Forwards public version of revised replacement pages to nuclear accident appx to Bay, Saginaw & Midland County emergency preparedness plans in response to FEMA 821214 interim findings
COOK, J W Consumers Power Co 83/03/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 18869 005 24X Fiche 50-329, 83/06/06, 8306150344

--8306150351 Public version of revised replacement pages to nuclear accident appx to Bay, Saginaw & Midland County emergency preparedness plans
* Consumers Power Co 83/03/30 139pp. 18869, 012 24X Fiche 50-329, 83/06/06, 8306150344

G Adjudicatory correspondence

8306150220 Forwards M Srinivasan 830121 memo responding to Region III request for NRR position on applicant exceptions to Reg Guide 1.29 re emergency diesel generator exhaust sys hangers, NRR position on issue undeveloped
WILCOVE, M N Hearing Branch 2 83/05/13 BERNABEI, L Government Accountability Project, App. 18846 314, 24X Fiche 50-329, 83/05/13, 8306150220

8306150274 Concurs w/utl 830412 ltr identifying portions of AB Savage deposition transcript to be admitted into evidence w/ exception. Page 101, Lines 19 - 24, outside scope of contention
WILCOVE, M N. Hearing Branch 2 83/05/13 BECHHOEFER, C, COHAN, F P, HARBOUR, J Atomic Safety and Licensing Board Panel 2pp. 18849, 174 24X Fiche 50-329, 83/05/13, 8306150274

8306020489 Memorandum & order granting, in part, applicant 830609 revised motion requiring lead intervenors to submit cross-examination plans & establish time limits on cross-examination
BECHHOEFER, C Atomic Safety and Licensing Board Panel 83/05/31 Consumers Power Co 14pp 18693, 166 24X Fiche 50-329, 83/05/31, 8306020489

8306060315 Advises that M Cloni deposition rescheduled for 830608 in Chicago, IL Svc list encl
PROCTOR, B D Isham, Lincoln & Deale, 83/06/01 KELLEY, F J Michigan, State of CHERRY, M M Cherry, M M /Cherry, Flynn & Kanter MARSHALL, W H Marshall, W H 2pp. 18729, 185 24X Fiche 50-329, 83/06/01, 8306060315

number of wells & amount of
for dewatering
83/06/01 Commissioners
/06/01, 8306080206

8306130420 Notice of scheduling of evidentiary hearings on 04/04 for 830627-0701 & if necessary, for 830725, 79, in Midland, MI
BECHHOEFER, C Atomic Safety and Licensing Board Panel 83/06/09 1p 18821 230 24X Fiche 50-329, 83/06/09, 8306130420

8306140660 Forwards NRC 820317 ltr, transmitting IE Insp Rept 50-410/01-13 & notice of violation, per 030608 evidentiary hearing commitment
WRIGHT, N A Hearing Branch 2 83/06/07 BERNABEI, L Government Accountability Project 1p 18433 284 24X Fiche 50-329, 83/06/09, 8306140660

8306140727 Responds to 830601 ltr ASLB in 830428 ruling, denied 830422 request for production of documents on dewatering issue since discovery ended
WRIGHT, N A Hearing Branch 2 83/06/07 MARSHALL, W H Mapleton Intervenor 1p 18841 009 24X Fiche 50-329, 83/06/09, 8306140727

8306200306 Advises that AT Howard deposition scheduled for 830614-16 being continued Svc list encl Related correspondence
PROCTOR, B D Isham, Lincoln & Deale 83/06/13 KELLEY, F J Michigan, State of KELLEY, F J Cherry, M M /Cherry, Flynn & Kanter MARSHALL, W H Marshall, W H 2pp 18900 168 24X Fiche 50-329, 83/06/13, 8306200306

8306220006 Advises that L Hallberg deposition, originally scheduled for 830621, continued New date will be announced Svc list encl Related correspondence
PROCTOR, B D Isham, Lincoln & Deale 83/06/16 BECHHOEFER, C Atomic Safety and Licensing Board Panel KELLEY, F J Michigan, State of 2pp 18927 350 24X Fiche 50-329, 83/06/16, 8306220006

8306220049 Advises of 830623 & 24 depositions of L Clark & T Devine, respectively Svc list encl Related correspondence
PROCTOR, B D Isham, Lincoln & Deale 83/06/16 KARR, J W Karr & Lyons 2pp 18930 172 24X Fiche 50-329, 83/06/16, 8306220049

8306270154 Forwards corrected copy of 820707 notice of violation package for Niagara Mohawk Power Corp
WRIGHT, N A Hearing Branch 2 83/06/22 BERNABEI, L Government Accountability Project 1p 19012 148 24X Fiche 50-329, 83/06/22, 8306270154

8306290498 Notice of appearance in proceeding Certificate of Svc encl
KARR, J W Government Accountability Project KARR, J W Karr & Lyons 83/06/27 4pp 19052 331 24X Fiche 50-329, 83/06/27, 8306290498

8306290530 Motion to quash util subpoenas commanding testimony at proceedings to identify whistleblowers Subpoenas violate first amend of US Constitution, Commission cannot issue subpoena in violation of confidentiality promise
KARR, J W Government Accountability Project * Karr & Lyons 83/06/27 Atomic Safety and Licensing Board Panel 13pp 19053 001 24X Fiche 50-329, 83/06/27, 8306290530

--8306290551 Affidavit of L Clark re representation of whistleblowers If Govt Accountability Project required to name whistleblowers, ultimate damage will be to public interest in full & free flow of info on important issues Certificate of Svc encl
CLARK, L Government Accountability Project 83/06/24 15pp 19053 014 24X Fiche 50-329, 83/06/27, 8306290530

M Antitrust correspondence

8306030242 Forwards FR notice of finding of no significant antitrust changes & time for filing of requests for reevaluation
REGAN, W H Siting Analysis Branch 83/05/24 COMBS, T Docketing & Services Branch 2pp 18734 024 24X Fiche 50-329, 83/05/24, 8306030242

--8306030246 Notice of finding of no significant antitrust changes & time for filing of requests for reevaluation
REGAN, W H Siting Analysis Branch 83/05/24 2pp 18734 024 24X Fiche 50-329, 83/05/24, 8306030242

8306140345 Forwards FR notice of finding of no significant antitrust changes since CP reviews & of time for filing requests for reevaluation
REGAN, W H Site Analysis Branch 83/05/24, COOK, J W Consumers Power Co 2pp 18854 129 24X Fiche 50-329, 83/05/24, 8306140345

--8306140350 Notice of finding of no significant antitrust changes since CP review & of time for filing requests for reevaluation
REGAN, W H Site Analysis Branch 83/05/24, 12pp 18854 131 24X Fiche 50-329, 83/05/24, 8306140345

8306140360 Forwards FR notice of finding of no significant antitrust changes since CP review & of time for filing requests for reevaluation
REGAN, W H Site Analysis Branch 83/05/24 COMBS, J Docketing & Services Branch 2pp 18844 349 24X Fiche 50-329, 83/05/24, 8306140360

Q Inspection reports, IE Bulletins & correspondence

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl
TAYLOR, J H Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IC Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8306090243 Forwards IE Insp Repts 50-329/83-06 & 50-330/83-06 on 830329-31 & 0401 & notice of violation
WARNICK, R F Region 3, Office of Director 83/05/27 COOK, J W Consumers Power Co 2pp 18795 321 24X Fiche 50-329, 83/05/27, 8306090243

--8306090244 Notice of violation from insp on 830329-31 & 0401
WARNICK, R F Region 3, Office of Director 83/05/27 1p 18795 323 24X Fiche 50-329, 83/05/27, 8306090243

--8306090245 IE Insp Repts 50-329/83-06 & 50-330/83-06 on 830329-31 & 0401 Noncompliance noted failure to follow policy procedures re control of purchased mail & svcs
SIMON, J A, SATHER, A, HARRISON, J J Region 3, Office of Director 83/05/23 4pp 18795 324 24X Fiche 50-329, 83/05/27, 8306090243

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306060048 Ack receipt of 830513 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-329/83-05 & 50-330/83-05
WARNICK, R F Region 3, Office of Director 83/05/31 COOK, J W Consumers Power Co 1p 18719 247 24X Fiche 50-329, 83/05/31, 8306060048

--8306060055 Responds to NRC 830304 ltr re violations noted in IE Insp Repts 50-329/83-05 & 50-330/83-05 Corrective actions Bechtel maint form written to cover installed Q & non-Q mechanical snubbers & 100% initial insp will be performed
COOK, J W Consumers Power Co 83/05/13 KEPLER, J Q Region 3, Office of Director 4pp 18719 240 24X Fiche 50-329, 83/05/31, 8306060048

8306210443 Requests Region III inspect adequacy of util program to initially verify & periodically check for continued presence & effectiveness of Boraflex as neutron poison in spent fuel racks
CROW, W T Uranium Fuel Licensing Branch 83/06/08 HARRISON, J Region 3, Office of Director 3pp 18735 359 24X Fiche 50-329, 83/06/08, 8306210443

8305110464 IC Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 110pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8305110475 IC Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IC Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

R Periodic operating reports & related correspondence

8306030172 Forwards Bechtel, B&W & util nonconformance repts for Apr 1983
COOK, J W Consumers Power Co 83/05/25 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 73pp 18709 096 24X Fiche 50-329, 83/05/25, 8306030172

8306270067 Forwards "Independent Design & Const Verification Program; Monthly Status Rept No 1, Period Inception Through 830527 " LEVIN, H A TERA Corp 83/05/27 KEPLER, J Q Region 3, Office of Director EISENHUT, D Q Division of Licensing COOK, J W Consumers Power Co 3pp 19013 017 24X Fiche 50-329, 83/05/27, 8306270067

--8306270069 "Independent Design & Const Verification Program; Monthly Status Rept No 1, Period Inception Through 830527, " TULLOCHESKI, D TERA Corp 83/05/27 65pp 19013 020 24X Fiche 50-329, 83/05/27, 8306270067

S Reportable occurrences, LERs & related correspondence

8306070242 Interim Deficiency Rept 82-06 re B&W steam generator auxiliary feedwater header design change Internal headers stabilized Mod will be completed upon receipt of thermal sleeves Next rept by 830801
COOK, J W Consumers Power Co 83/05/31, KEPLER, J Q, Region 3, Office of Director 2pp 18744 244 24X Fiche: 50-329, 83/05/31, 8306070242

8306130281 Interim deficiency rept re underrated terminal strips & use of terminal blocks w/o proper environ qualification in Limitorque valve operators Bechtel has requested addl info from Limitorque re qualifying terminal block types
COOK, J W Consumers Power Co 83/06/07 KEPLER, J Q Region 3, Office of Director 12pp 18824 128 24X Fiche 50-329, 83/06/07, 8306130281

8306170448 Board Notification 83-79 forwards Zack Rept on welder record discrepancies Rept documents Zack investigation & subsequent decision that item does not constitute IOCFR21 deficiency W/o encl
NOVAK, T M Assistant Director for Licensing, 83/06/09 Atomic Safety and Licensing Board Panel 2pp 18906 361 24X Fiche 50-329, 83/06/09, 8306170448

8306210302 Interim deficiency rept re adequacy of shear reinforcements at major containment penetrations As-designed & as-built containment satisfactory Revs to FSAR initiated Final or interim rept expected by 831031.
COOK, J W Consumers Power Co 83/06/13 KEPLER, J Q Region 3, Office of Director 2pp 18914 015 24X Fiche: 50-329, 83/06/13, 8306210302

8306220007 Part 21 rept re adequacy of fittings supplied by Tube-Line Corp through Capital Pipe & Steel Products Co for use on new auxiliary feedwater headers of steam generators. Flanges not heat-treated as required by matl specs
TAYLOR, J H Babcock & Wilcox Co 83/06/17 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 4pp 18927 354 24X Fiche 50-000, 83/06/17, 8306220007

8306270181 PNO-III-83-051 on 830621, util authorized to proceed w/installation of electrical penetration area temporary support beams & excavation under auxiliary bldg Workers laid off 830617 & 18 recalled
LANDSMAN, R, HARRISON, J Region 3, Office of Director 83/06/21, 1p 18991 344 24X Fiche 50-329, 83/06/21, 8306270181.

DOCKETED ITEMS

T Hearing transcripts on non-antitrust matters

8306070073 Transcript of 830601 evidentiary hearing in Midland, MI Pp 16, 367-16, 552.
* Atomic Safety and Licensing Board Panel 83/06/01 188pp
18740 105 24X Fiche 50-329, 83/06/01, 8306070073

8306070180 Transcript of 830602 evidentiary hearing in Midland, MI Pp 15, 553-16, 765
* Atomic Safety and Licensing Board Panel 83/06/02 205pp
18737 128 24X Fiche 50-329, 83/06/02, 8306070180

8306070187 Transcript of 830603 hearing in Midland, MI Pp 16, 766-16, 967.
* Atomic Safety and Licensing Board Panel 83/06/03 203pp
18738 001 24X Fiche 50-329, 83/06/03, 8306070187

8306070162 Transcript of 830604 evidentiary hearing in Midland, MI Pp 16, 768-17, 104 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/06/04 210pp
18736 001 24X Fiche 50-329, 83/06/04, 8306070162

8306100063 Transcript of 830606 evidentiary hearing in Midland, MI Pp 17, 105-17, 195
* Atomic Safety and Licensing Board Panel 83/06/06 89pp
18802 338 24X Fiche 50-329, 83/06/06, 8306100063

8306130215 Transcript of 830607 evidentiary hearing in Midland, MI Pp 17, 196-17, 412
* Atomic Safety and Licensing Board Panel 83/06/07 213pp
18827 011 24X Fiche 50-329, 83/06/07, 8306130215

8306140103 Transcript of 830608 evidentiary hearing in Midland, MI Pp 17, 413-17, 637
* Atomic Safety and Licensing Board Panel 83/06/08 131pp
18839 286 24X Fiche 50-329, 83/06/08, 8306140103

8306150142 Transcript of 830609 evidentiary hearing in Midland, MI Pp 17, 638-17, 865.
* Atomic Safety and Licensing Board Panel 83/06/09 85pp
18851 220 24X Fiche: 50-329, 83/06/09, 8306150142

8306140108 Transcript of 830610 evidentiary hearing in Midland, MI Pp 17, 866-17, 977.
* Atomic Safety and Licensing Board Panel. 83/06/10 115pp
18829 171 24X Fiche: 50-329, 83/06/10, 8306140108

8306200016 Transcript of Commission 830615 briefing in Washington, DC re status of QA & soil settlement at facility Pp 1-64
Supporting documentation encl
* Commissioners 83/06/15 76pp 18909 238 24X
Fiche 50-329, 83/06/15, 8306200016

V. Operator Examinations

8306270271 Advise that MQ Jones Engineering Consultants, Inc (MQJEC) training program, evaluated on 830608, satisfactory & may be implemented immediately Spatial sys interaction program procedures approved by util & issued by MQJEC
BARANOW, S W. Stone & Webster, Inc. 83/06/17. KEPPLER, J G Region 3, Office of Director 1p 18990 209 24X Fiche 50-329, 83/06/17, 8306270271.

DOCKET 50-331 DUANE ARNOLD ENERGY CENTER *

A. Application/construction stage documents & correspondence

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc 119pp 18830:280 24X Fiche 50-000, 83/06/09, 8305110464

F. Security, medical, emergency & fire protection plans

8306130363 Informs that LASL vital area analysis program personnel will reanalyze original sites visited in early stages of program during CY83 & CY84 Revisit necessary to gather addl info due to major mods & reduction of program by NRC.
HIND, J A. Division of Radiological & Materials Safety Programs 83/06/08 LIU, L. Iowa Electric Light & Power Co. 1p 18821 270 24X Fiche: 50-331, 83/06/08, 8306130363

J Insurance & indemnity information

8306030167 Forwards Endorsement 58 to NEL 1A Policy NF-214 & Endorsement 47 to MAELU Policy MF-72
SHEA, K H Lowenstein, Newman, Reis, Axelrod & Toll 83/05/27
SALTZMAN, J S Assistant Director for State & License Relations
3pp 18704 035 24X Fiche 50 331, 83/05/27, 8306030167

P Operating license stage documents & correspondence

8306020205 Forwards safety evaluation re valve operability for 18-inch butterfly valves used for purge or vent of containment InPs submitted fails to demonstrate valve ability to close against containment pressure buildup during LOCA
VASSALLO, D B Operating Reactors Branch 2 83/05/20 LIU, L Iowa Electric Light & Power Co 3pp 18701 057 24X
Fiche 80-331, 83/05/20, 8306020205

--8306020209 Safety evaluation re demonstration of containment purge & vent valve operability for 18 inch butterfly valves Info submitted fails to demonstrate valve ability to close against containment pressure buildup during LOCA
* Office of Nuclear Reactor Regulation, Director 83/05/20 2pp
18701 060 24X Fiche 50-331, 83/05/20, 8306020209

8306160389 Forwards response to NRC 830520 request for info re assessment of containment purge & vent valve operability
Valves will close during design basis LOCA Valves will not be sealed
MCQUAGHY, R W Iowa Electric Light & Power Co 83/06/10
DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp
18860 210 24X Fiche 50-331, 83/06/10, 8306160389

8306230348 Forwards response to NRC 830420 request for addl info re Mark I containment long-term program NUTECH rept "Mark I Containment Ring Girder Modelling & Stress Evaluation Utilizing Eccentric Beams" encl
MCQUAGHY, R W Iowa Electric Light & Power Co 83/06/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp 18943 011 24X Fiche 50-331, 83/06/20, 8306230348

--8306230351 "Mark I Containment Ring Girder Modelling & Stress Evaluation Utilizing Eccentric Beams"
CHANG, D K, STURKEY, J J, HALLARD, T A NUTECH Engineers, Inc
MKI-03-008 80/04/30 41pp 18943 017 24X
Fiche 50-331, 83/06/20, 8306230348

8306270420 Application for Proposed Change RTS-124, Rev 2 to License DPR-49, changing Tech Specs re single recirculation loop operation to be consistent w/Cycle 7 reload licensing amend
Changes supersede 801017 changes
MCQUAGHY, R W Iowa Electric Light & Power Co 83/06/24
DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp
18993 069 24X Fiche 50-331, 83/06/24, 8306270420

--8306270426 Proposed Change RTS-124, Rev 2 re single recirculation loop operation, changing Tech Specs to be consistent w/Cycle 7 reload licensing amend
* Iowa Electric Light & Power Co 83/06/24 41pp 18993 074 24X Fiche 50-331, 83/06/24, 8306270420

Q Inspection reports, IE Bulletins & correspondence

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 123pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc 114pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306070154 Ack receipt of 830228 ltr updating NRC on plan of action to upgrade regulatory performance Matters will be examined in subsequent insp Discussion of update planned after SALP 830623 meeting
NORELIUS, C E Division of Project & Resident Programs 83/05/31
LIU, L Iowa Electric Light & Power Co 1p 18736 270 24X
Fiche 50-331, 83/05/31, 8306070154

DOCKETED ITEMS

183

8306090316 Ack receipt of 830510 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-331/83-01
SHAFER, W D Region 3, Office of Director 83/06/03 LIO, L Iowa Electric Light & Power Co 1p 18795 123 24X
Fiche 50-331, 83/06/03, 8306090316

--83060903P6 Responds to NRC 830418 ltr re violations noted in IE Insp Rept 50-331/83-01 Corrective actions vessel head insulation removal/installation procedures revised & thermometer calibrator ordered
RODT, L D Iowa Electric Light & Power Co RC 83/05/10
KEPPLER, J O Region 3, Office of Director 3pp 18795 124 24X
Fiche 50-331, 83/06/03, 8306090316

8306140590 Forwards response to Items 1-4 of IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators " Inservice test program will be modified to provide for disassembly & insp of valves
MCQUAGHY, R W Iowa Electric Light & Power Co 83/06/08
KEPPLER, J O Region 3, Office of Director 2pp 18814 156 24X
Fiche 50-331, 83/06/08, 8306140590

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8306270089 Advises that info re doses for tasks & dose rates for various areas of facility provided to NRC on informal basis during 830614 unannounced insp
MINECK, D L Iowa Electric Light & Power Co 83/06/14 KEPPLER, J O Region 3, Office of Director 1p 18788 122 24X
Fiche 50-331, 83/06/14, 8306270089

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

R Periodic operating reports & related correspondence

8306130375 NPDES noncompliance notification during Apr. monthly average suspended solids effluent concentration exceeded permitted monthly average Caused by large number of personnel onsite to support refueling outage
MCQUAGHY, R W Iowa Electric Light & Power Co 83/06/08
KEPPLER, J O Region 3, Office of Director 1p 18822 184 24X
Fiche 50-331, 83/06/08, 8306130375

--8306130378 "Operation Permit Sys Monthly Monitoring Rept for Apr 1983 " ADAMS, L T Iowa Electric Light & Power Co 83/06/08 2pp 18822 185 24X Fiche 50-331, 83/06/08, 8306130378

8306200223 Monthly operating rept for May 1983 W/830615 ltr
ANDERSEN, M MINECK, D L Iowa Electric Light & Power Co 83/06/15
Director's Office, Office of Inspection and Enforcement 9pp 18702 299 24X Fiche 50-331, 83/06/15, 8306200223

S Reportable occurrences, LCRs & related correspondence

8306060209 LER 83-014/03L-0 on 830428, relay B21-K2A did not pick up as required on high flow signal Caused by sticking plunger in flow meter & faulty capacitor in flow switch circuit Plunger freed & capacitor replaced W/830527 ltr
KIBLER, D R, MINECK, D L Iowa Electric Light & Power Co 83/05/27
KEPPLER, J O Region 3, Office of Director 2pp 18727 358 24X
Fiche 50-331, 83/05/27, 8306060209

8306100103 RO on 830527, both divs of hydrogen/oxygen analyzers determined inoperable Orderly shutdown commenced On 830527, A sys returned to operable status
MINECK, D L Iowa Electric Light & Power Co 83/05/27 KEPPLER, J O Region 3, Office of Director 1p 18803 072 24X
Fiche 50-331, 83/05/27, 8306100103

8306130327 PNO-III-83-040 on 830605, licensee noticed increase in chloride concentration in reactor cooling water from leak or leaks in main condenser tubes Condenser tubes repaired or plugged Chlorine level reduced
CLARDY, L, JORDAN, M, SHAFER, W Region 3, Office of Director 83/06/07 1p 18822 355 24X Fiche 50-331, 83/06/07, 8306130327

8306130375 NPDES noncompliance notification during Apr. monthly average suspended solids effluent concentration exceeded permitted monthly average Caused by large number of personnel onsite to support refueling outage
MCQUAGHY, R W Iowa Electric Light & Power Co 83/06/08
KEPPLER, J O Region 3, Office of Director 1p 18822 184 24X
Fiche 50-331, 83/06/08, 8306130375

--8306130378 "Operation Permit Sys Monthly Monitoring Rept for Apr 1983 " ADAMS, L T Iowa Electric Light & Power Co 83/06/08 2pp 18822 185 24X Fiche 50-331, 83/06/08, 8306130378

8306170337 LER 83-021/01T-0: on 830527, containment H202 analyzer channel A rendered inoperable Caused by calibr difficulties due to fouled pressure regulators resulting from sys contamination. Tech Specs revised W/830610 ltr
MILLER, W J, MINECK, D L Iowa Electric Light & Power Co 83/06/10
KEPPLER, J O Region 3, Office of Director 3pp 18881 019 24X
Fiche 50-331, 83/06/10, 8306170337

8306210242 PNO-III-83-045 on 830614, bomb threat received from male caller complaining of increased electric rates & state & federal economic policies Sheriff & FBI notified
CHRISTOFFER, G, CREED, J Region 3, Office of Director 83/06/15, 1p 18916 351 24X Fiche 50-331, 83/06/15, 8306210242

8306270290 LER 83-015/031-0: on 830517, during routine surveillance, 4 kV essential bus degraded voltage relay 127/A1 tripped out of spec at 8.6 s Caused by instrument drift Time setting adjusted & relay tested satisfactorily W/830616 ltr
KIBLER, D R, MINECK, D L Iowa Electric Light & Power Co 83/06/16
KEPPLER, J O Region 3, Office of Director 2pp 18996 182 24X
Fiche 50-331, 83/06/16, 8306270290

DOCKET 50-333 JAMES A FITZPATRICK NUCLEAR POWER PLANT

F Security, medical, emergency & fire protection plans

8306140158 Ack receipt of 830527 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-333/83-06, STARDSTECKI, R Division of Project & Resident Programs 83/06/09, MCNEILL, C A Power Authority of the State of New York 1p 18839 031 24X Fiche 50-333, 83/06/09, 8306140158

--8306140169 Responds to NRC 830428 ltr re violations noted in IE Insp Rept 50-333/83-06 Corrective actions out of date annunciator response procedures revised Pathway & area transversed by employees outside restricted area surveyed
MCNEILL, C A Power Authority of the State of New York, 83/05/27
STARDSTECKI, R Division of Project & Resident Programs 2pp 18839 032 24X Fiche, 50-333, 83/06/09, 8306140158

8306170038 Informs that LABI Vital Area Analysis (VAA) Program personnel will be reanalyzing original 10 sites visited during early stages of VAA program, during CY83 & 84 Revisit necessary to gather addl info due to major NRC mods
ALLAN, J M Region 1, Office of Director 83/06/13 MCNEILL, C A Power Authority of the State of New York 2pp 18878 291 24X
Fiche 50-333, 83/06/13, 8306170038

8306200279 Advises that Class III fee appropriate for portion of B10319 application proposing mods & alternate safe shutdown capability to meet App R requirements Remittance requested, MILLER, W O License Fee Management Branch 83/06/14 SINCLAIR, L W Power Authority of the State of New York 1p 18919 263 24X
Fiche 50-333, 83/06/14, 8306200279

DOCKETED ITEMS

8306230456 Forwards corrected cover sheet for IE Insp Rept 50-333/83-08 Insp dates changed from 830321-0426 to 830321-25.
MARTIN, T. T. Division of Engineering & Technical Programs 83/06/20
MCNEILL, C. A. Power Authority of the State of New York 1p
18942.057 24X Fiche 50-333, 83/06/20, 8306230456

--8306230459 Forwards IE Insp Rept 50-333/83-08 on 830321-25 & notice of violation
MARTIN, T. T. Division of Engineering & Technical Programs
83/05/27 MCNEILL, C. A. Power Authority of the State of New York
2pp 18942 058 24X Fiche 50-333, 83/06/20, 8306230456

--8306230463 Notice of violation from insp on 830321-25
* Division of Engineering & Technical Programs 83/05/27 2pp
18942 060 24X Fiche 50-333, 83/06/20, 8306230456

--8306230469 IE Insp Rept 50-333/83-08 on 830321-25 Noncompliance noted. Failure to establish adequate procedures for respiratory protection equipment & failure to implement procedures controlling radiation work permits
MCBRIDE, M. H., SHANBAXY, M. Region 1, Office of Director 83/05/26
14pp 18942 062 24X Fiche 50-333, 83/06/20, 8306230456

I Financial information

8306130111 "Annual Financial Rept 1982 " W/830607 ltr
DYSON, J. B., BAYNE, J. P. Power Authority of the State of New York
83/06/07 Office of Nuclear Reactor Regulation, Director 41pp
18927 224 24X Fiche 50-000, 83/06/07, 8306130111.

P Operating license stage documents & correspondence

8306030032 Responds to 830311 request for exemption from scheduler requirement of 10CFR50.49, environ qualification of equipment Confirms submittal date of 830620
VASSALLO, D. B. Operating Reactors Branch 2 83/05/27 BAYNE, J. P.
Power Authority of the State of New York 2pp 18733 174 24X
Fiche 50-333, 83/05/27, 8306030032

8306030224 Notifies that util name changed from Power Authority of State of NY to New York Power Authority New name does not reflect change in status, but clarifies public identity.
BAYNE, J. P. Power Authority of the State of New York 83/05/27.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp
18703 332. 24X Fiche 50-000, 83/05/27, 8306030224

8306060121 Forwards evaluations submitted re NUREQ-0612, "Control of Heavy Loads at Nuclear Power Plants " Handling shielded shipping casks over spent fuel pool will be prohibited until measures taken to reduce probability of cask drop.
BAYNE, J. P. Power Authority of the State of New York 83/06/02
VASSALLO, D. B. Operating Reactors Branch 2 14pp 18722 275 24X
Fiche 50-333, 83/06/02, 8306060121.

8306070303 Advises that individual program plan will be submitted by 831019 referencing BWR Owners Group generic program plan re NRC 830419 Generic Ltr 83-18, Suppl 1 to NUREQ-0737, item 1, D. 1, "Control Room Design Review"
BAYNE, J. P. Power Authority of the State of New York 83/06/03
VASSALLO, D. B. Operating Reactors Branch 2 2pp 18740 301 24X
Fiche 50-333, 83/06/03, 8306070303

8306100100 Reaffirms justifications for continued operation for equipment identified as Categories Ib, IIa & IV for which qualification programs still in progress Qualification info not accurate representation Addl items encl
BAYNE, J. P. Power Authority of the State of New York 83/06/06
VASSALLO, D. B. Operating Reactors Branch 2 37pp 18802 266 24X
Fiche 50-333, 83/06/06, 8306100100

8306140318 Informs that addl info requested on 830511 re NUREQ-0737, item 11 K 3 2B, "Qualification of Automatic Depressurization Sys Accumulators," will be provided by 830930.
BAYNE, J. P. Power Authority of the State of New York 83/06/07
VASSALLO, D. B. Operating Reactors Branch 2. 3pp 18832 207. 24X
Fiche 50-333, 83/06/07, 8306140318

8306230170 Forwards Offsite Dose Calculation Manual to accompany proposed radiological effluent Tech Specs submitted on 830429.
BAYNE, J. P. Power Authority of the State of New York 83/06/21.
VASSALLO, D. B. Operating Reactors Branch 2 1p 18944 171. 24X
Fiche 50-333, 83/06/21, 8306230170.

--8306230174 Offsite Dose Calculation Manual
* Power Authority of the State of New York. 83/06/21. 204pp
18944:172 24X Fiche 50-333, 83/06/21, 8306230170.

8306280508 Forwards addl info re compliance w/NUREG-0737, item 11 F 1 4, "Containment Pressure Monitor" & 11 F 1 5, "Containment Water Level Monitor," per 030408 commitment
BAYNE, J. P. Power Authority of the State of New York 83/06/23
VASSALLO, D. B. Operating Reactors Branch 2 7pp 19017 208 24X
Fiche 50-333, 83/06/23, 8306280508

Q Inspection reports, IE Bulletins & correspondence

8306010227 Forwards IE Insp Rept 50-333/83-10 on 830412-15 & notice of deviation
MARTIN, T. T. Division of Engineering & Technical Programs 83/05/16
MCNEILL, C. A. Power Authority of the State of New York 2pp
18672 349 24X Fiche 50-333, 83/05/16, 8306010227

--8306010229 Notice of deviation from insp on 830412-15
* Region 1, Office of Director 83/05/16 2pp 18672 351. 24X
Fiche 50-333, 83/05/16, 8306010227

--8306010231 IE Insp Rept 50-333/83-10 on 830412-15 Deviation noted. failure to meet commitment to include all safety-related valves in test program & failure to establish max allowed stroke times for power operated valves
REKIMO, W. A., BETTENHAUSEN, L. Region 1, Office of Director
83/05/06 10pp 18672 353 24X Fiche 50-333, 83/05/16, 8306010227

8306060230 Forwards IE Insp Rept 50-333/83-09 on 830401-30 & notice of violation
STAROSTECKI, R. Division of Project & Resident Programs 83/05/23
MCNEILL, C. A. Power Authority of the State of New York 2pp
18726 329 24X Fiche 50-333, 83/05/23, 8306060230

--8306060234 Notice of violation from insp on 830401-30
* Region 1, Office of Director 83/05/23 2pp 18726 371 24X
Fiche 50-333, 83/05/23, 8306060230

--8306060237 IE Insp Rept 50-333/83-09 on 830401-30 Noncompliance noted failure to implement or establish adequate measuring & test equipment controls properly
LINVILLE, J. C., DORFLEIN, L. J., KISTER, H. B. Region 1, Office of Director
83/05/17 14pp 18726 333 24X Fiche 50-333, 83/05/23, 8306060230

8306130481 Forwards request for addl info re masonry wall design per IE Bulletin 80-11 response Info requested within 45 days
VASSALLO, D. B. Operating Reactors Branch 2 83/05/25 BAYNE, J. P.
Power Authority of the State of New York 3pp 18830 164 24X
Fiche 50-333, 83/05/25, 8306130481

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl
TAYLOR, J. M. Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc
125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306140147 Ack receipt of 830421 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-333/83-04 Improvement on proposed 830801 issue date for procedure describing delegation of audit functions encouraged
STAROSTECKI, R. Division of Project & Resident Programs 83/05/31
MCNEILL, C. A. Power Authority of the State of New York 2pp
18839 076 24X Fiche 50-333, 83/05/31, 8306140147

--8306140153 Responds to NRC 830321 ltr re violations noted in IE Insp Rept 50-333/83-04 Corrective actions two surveillance audits re limiting conditions of operations performed Program addressing audit functions, per Procedure 18 i, developed
MCNEILL, C. A. Power Authority of the State of New York 83/04/21
STAROSTECKI, R. Division of Project & Resident Programs 2pp
18839 078 24X Fiche 50-333, 83/05/31, 8306140147

8306210156 Responds to IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators " Pump & valve program will be modified to include check valves in flow path of cooling water for diesel generators
MCNEILL, C. A. Power Authority of the State of New York 83/06/08
BEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 2pp 18915 191 24X Fiche 50-333, 83/06/08, 8306210156

DOCKETED ITEMS

18E

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8306140158 Ack receipt of 83052/ ltr informing NRC of steps taken to correct violations noted in IL Insp Rept 50-333/83-06
STAROSTECKI, R Division of Project & Resident Programs 83/06/09
MCNEILL, C A Power Authority of the State of New York 1p 18839 031 24X Fiche 50-333, 83/06/09, 8306140158

--8306140169 Responds to NRC 830428 ltr re violations noted in IE Insp Rept 50-333/83-06 Corrective actions out of date annunciator response procedures revised Pathway & area transversed by employees outside restricted area surveyed
MCNEILL, C A Power Authority of the State of New York 83/05/27
STAROSTECKI, R Division of Project & Resident Programs 2pp 18839 032 24X Fiche 50-333, 83/06/09, 8306140158

8305110470 IC Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IC Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8306200338 Ack receipt of 83053/ ltr informing NRC of steps taken to correct violations noted in IL Insp Rept 50-333/82-28
STAROSTECKI, R Division of Project & Resident Programs 83/06/14
MCNEILL, C A Power Authority of the State of New York 1p 18900 208 24X Fiche 50-333, 83/06/14, 8306200338

--8306200344 Responds to NRC 830303 ltr re violations noted in IE Insp Rept 50-333/82-28 Corrective actions work procedure revised to include insp & hold points as appropriate, during biennial review of procedure
MCNEILL, C A Power Authority of the State of New York 83/05/31
STAROSTECKI, R Division of Project & Resident Programs 2pp 18900 209 24X Fiche 50-333, 83/06/14, 8306200338

8306230456 Forwards corrected cover sheet for IE Insp Rept 50-333/83-08 Insp dates changed from 830321-0426 to 830321-25
MARTIN, T T Division of Engineering & Technical Programs 83/06/20
MCNEILL, C A Power Authority of the State of New York 1p 18942 057 24X Fiche 50-333, 83/06/20, 8306230456

--8306230457 Forwards IE Insp Rept 50-333/83-08 on 830321-25 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs 83/05/27
MCNEILL, C A Power Authority of the State of New York 2pp 18942 058 24X Fiche 50-333, 83/06/20, 8306230456

--8306230463 Notice of violation from insp on 830321-25
* Division of Engineering & Technical Programs 83/05/27 2pp 18942 060 24X Fiche 50-333, 83/06/20, 8306230456

--8306230469 IE Insp Rept 50-333/83-08 on 830321-25 Noncompliance noted failure to establish adequate procedures for respiratory protection equipment & failure to implement procedures controlling radiation work permits
MCORRIDE, M H, SHANBAKY, M Region I, Office of Director 83/05/26 14pp 18942 062 24X Fiche 50-333, 83/06/20, 8306230456

8305110475 IC Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 115pp 19021 177 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110477

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

R Periodic operating reports & related correspondence

830610001/ Monthly operating rept for May 1983 W/830603 ltr
COOK, J, MCNEILL, C A Power Authority of the State of New York
83/06/03 Director's Office, Office of Inspection and Enforcement 7pp 18802 104 24X Fiche 50-333, 83/06/03, 8306100017

S Reportable occurrences, LEIRs & related correspondence

8306010112 Updated LER 81-082/03X-2 on 811230, erratic reading noted on source range monitors & intermediate range monitor instruments Caused by low voltage on 24-volt dc batteries Battery recharge restored sys to normal W/830518 ltr
LEBEND, R T, MCNEILL, C A Power Authority of the State of New York 83/05/16
ALLAN, J M Region I, Office of Director 2pp 18673 334 24X Fiche 50-333, 83/05/16, 8306010112

8306010312 Updated LER 80-006/03X-1 on 800108, core spray injection valve 14-MOV-12A improperly operated during 791221 surveillance test Caused by misoperation of valve circuit breaker overload trip device W/830517 ltr
CHILDS, V, MCNEILL, C A Power Authority of the State of New York 83/05/17
ALLAN, J M Region I, Office of Director 2pp 18672 312 24X Fiche 50-333, 83/05/17, 8306010312

8306200139 LER 83-019/03L-0 on 830501, LPC1 independent power supply inverter, B indicated minor trouble alarm Caused by failed gate firing module printed circuit board Board replaced Inverter returned to svc W/830531 ltr
MCNEILL, C A Power Authority of the State of New York 83/05/20
ALLAN, J M Region I, Office of Director 3pp 18903 266 24X Fiche 50-333, 83/05/20, 8306200139

8306200375 LER 83-018/04T-0 on 830426, standby gas treatment sys A charcoal failed offsite methyl iodide efficiency test Caused by defective test instrument Charcoal replaced W/830601 ltr
MULCAHEY, E, MCNEILL, C A Power Authority of the State of New York 83/05/31
ALLAN, J M Region I, Office of Director 3pp 18999 098 24X Fiche 50-333, 83/05/31, 8306200375

8306140080 PND-I-83-057 on 830607, while preparing weld on 3-inch control rod drive (CRD) return header for ultrasonic exam, through wall crack found in weld 4 ft from reactor pressure vessel CRD return nozzle Header cut out
KISTER, H, MEINIG, R Region I, Office of Director 83/06/08 1p 18838 346 24X Fiche 50-333, 83/06/08, 8306140080

8306280486 LER 83-020/03L-0 on 830520, during monthly valve cycling surveillance test of 23 MD-60 (HPC) outboard containment isolation bypass valve, valve motor tripped on overload Caused by hard valve packing W/830620 ltr
PETERB, R, MCNEILL, C A Power Authority of the State of New York 83/06/20
MURLTY, T E Region I, Office of Director, 2pp 19018 287 24X Fiche 50-333, 83/06/20, 8306280486

V Operator Examinations

8306140665 Extends invitation to attend 830627 meeting in King of Prussia, PA to discuss transfer of reactor operator licensing function from Bethesda, MD to Region I of STAROSTECKI, R. Division of Project & Resident Programs 83/06/09
MCNEILL, C A Power Authority of the State of New York 2pp 18842 067 24X Fiche 50-333, 83/06/09, 8306140665

DOCKET 50-334 BEAVER VALLEY POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8306070264 Forwards corrected Page 2-4 of Rev 4 to physical security plan; training qualification plan & approval sheet, Encls withheld (ref 10CFR73, 21)
CAREY, J J Duquesne Light Co 83/04/22
ALLAN, J M Region I, Office of Director 1p 18740 334 24X Fiche 50-334, 83/04/22, 8306070264

8306070076 Forwards Rev II to Issue 2 of physical security plan Rev withheld (ref 10CFR2 790)
CAREY, J J Duquesne Light Co 83/04/29
ALLAN, J M Region I, Office of Director 2pp 18739 208 24X Fiche 50-334, 83/04/29, 8306070076

DOCKETED ITEMS

8306010326 Forwards IE Safeguards Insp Rept 50-334/83-09 on 830418-22 No noncompliance noted
 MARTIN, T T Division of Engineering & Technical Programs 83/05/17
 CAREY, J J Duquesne Light Co 2pp 18679 358 24X
 Fiche 50-334, 83/05/17, 8306010326

--8306010327 IE Safeguards Insp Rept 50-334/83-09 on 830418-22 No noncompliance noted Major areas inspected physical barriers (protected area), security sys power supply, access control (personnel) & detection aids (protected area, vital areas)
 SMITH, O C, GDDY, A T Region 1, Office of Director 83/05/13
 3pp 18679 360 24X Fiche 50-334, 83/05/17, 8306010326

8306060200 Forwards IE Insp Rept 50-334/83-08 on 830405-0502 & notice of violation
 STAROSTECKI, R Division of Project & Resident Programs 83/05/23
 CAREY, J J Duquesne Light Co 2pp 18727 256 24X
 Fiche 50-334, 83/05/23, 8306060200

--8306060204 Notice of violation from insp on 830405-0502
 * Region 1, Office of Director 83/05/23 1p 18727 258 24X
 Fiche 50-334, 83/05/23, 8306060200

--8306060214 IE Insp Rept 50-334/83-08 on 830405-0502 Noncompliance noted, failure to demonstrate ECCS valve operability within specified surveillance interval
 TROSKOSKI, W M, TRIPP, L E Region 1, Office of Director 83/05/17, 22pp 18727 259 24X Fiche 50-334, 83/05/23, 8306060200

8306090189 Advises of plan to deviate from originally scheduled emergency preparedness exercise dates of Feb 1984 & 1985 Dates changed to June to allow for testing under various weather conditions Two previous exercises performed in Feb
 CAREY, J J Duquesne Light Co 83/06/01 VARQA, S A Operating Reactors Branch 1 2pp 18796 079 24X Fiche 50-334, 83/06/01, 8306090189

8306280490 Forwards BALP rept for evaluation period Dec 1981 - Nov 1982 Fire protection & housekeeping rating upgraded to Category 2
 MURLEY, T E Region 1, Office of Director 83/06/23 CAREY, J J Duquesne Light Co 4pp 19019 189 24X Fiche 50-334, 83/06/23, 8306280490

--8306280492 Forwards BALP rept conducted on 830124 for Dec 1981 - Nov 1982 Meeting scheduled for 830215 at site to discuss assessment
 STAROSTECKI, R Division of Project & Resident Programs 83/02/07
 CAREY, J J Duquesne Light Co 2pp 19019 193 24X
 Fiche 50-334, 83/06/23, 8306280490

--8306280495 Responds to NRC 830207 ltr re results of BALP Board review Reconsideration of rating given to Item 5, "Fire Protection & Housekeeping," requested
 CAREY, J J Duquesne Light Co 83/03/02 HAYNES, R C Region 1, Office of Director 7pp 19019 195 24X Fiche 50-334, 83/06/23, 8306280490

--8306280497 BALP rept for Dec 1981 - Nov 1982
 * Region 1, Office of Director 83/01/24 32pp 19019 202 24X
 Fiche 50-334, 83/06/23, 8306280490

P Operating license stage documents & correspondence

8306020676 Informs that NUREG-0737, Items 11 F 1 4, "Containment Pressure Monitor," & 11 F 1 5, "Containment Hydrogen Monitor," completed items closed
 VARQA, S A Operating Reactors Branch 1 83/05/17 CAREY, J J Duquesne Light Co 6pp 18716 249 24X Fiche 50-334, 83/05/17, 8306020676

8306090190 Forwards revised pages to Tech Specs for Amend 66 to License DPR-66, per 830426 Proposed Change Request B4 correcting administrative errors
 TAM, P B Operating Reactors Branch 1 83/05/25 CAREY, J J Duquesne Light Co 2pp 18809 256 24X Fiche 50-334, 83/05/25, 8306090190

--8306090193 Rev to Amend 66 to License DPR-66, consisting of Tech Spec page changes to correct administrative errors
 * Operating Reactors Branch 1 83/05/25 3pp 18809 258 24X
 Fiche 50-334, 83/05/25, 8306090190

8306030243 Forwards request for addl info re N-1 loop operation Response required within 60 days of receipt of ltr to meet Dec 1983 target close out date
 VARQA, S A Operating Reactors Branch 1 83/05/27 CAREY, J J Duquesne Light Co 3pp 18734 028 24X Fiche 50-334, 83/05/27, 8306030243

8306030247 Informs that WCAP 10176, "Second Cycle Performance of Beaver Valley Unit 1, Loop," provides excellent description of comprehensive fuel exam performed Fuel exams provide confirmation of satisfactory performance of fuel design
 VARQA, S A Operating Reactors Branch 1 83/05/27 CAREY, J J Duquesne Light Co 2pp 18714 062 24X Fiche 50-334, 83/05/27, 8306030247

8306090360 Requests authorization for removal of interim operating restrictions on automatic rod control, effective w/ cycle 4, since UND design basis met for dropped rod accident
 CAREY, J J Duquesne Light Co 83/05/17 VARQA, S A Operating Reactors Branch 1 2pp 18714 317 24X Fiche 50-334, 83/05/27, 8306090360

8306140639 Application to amend License DPR 66, consisting of Rev 1 to 781004 Tech Spec Change Request 34, revising reactor vessel overpressure protection sys at low temps
 CAREY, J J Duquesne Light Co 83/05/31 VARQA, S A Operating Reactors Branch 1 2pp 18843 023 24Y Fiche 50-334, 83/05/31, 8306140639

--8306140643 Proposed Tech Spec re reactivity control sys, RCB & ECCS
 * Duquesne Light Co 83/05/31 1pp 18843 025 24X
 Fiche 50-334, 83/05/31 8306140643

8306080073 Comments on deviation in procurement of chemical addition pumps, specifically, plan to procure pumps w/o N stamp, per 830214 ltr Based on listed provisions, deviation acceptable
 VARQA, S A Operating Reactors Branch 1 83/06/03 CAREY, J J Duquesne Light Co 2pp 18711 293 24X Fiche 50-334, 83/06/03, 8306080073

8306200334 Advises that implementation date for Reg Guide 1.13, "Fuel Oil Sys for Standby Diesel Generator," delayed until 840201 Revised schedule necessary due to excavation required to install new fuel oil tank, per UCP 390
 CAREY, J J Duquesne Light Co 83/06/07 VARQA, S A Operating Reactors Branch 1 1p 18919 214 24X Fiche 50-334, 83/06/07, 8306200334

Q Inspection reports, IE Bulletins & correspondence

8306010326 Forwards IE Safeguards Insp Rept 50-334/83-09 on 830418-22 No noncompliance noted
 MARTIN, T T Division of Engineering & Technical Programs 83/05/17
 CAREY, J J Duquesne Light Co 2pp 18679 358 24X
 Fiche 50-334, 83/05/17, 8306010326

--8306010327 IE Safeguards Insp Rept 50-334/83-09 on 830418-22 No noncompliance noted Major areas inspected physical barriers (protected area), security sys power supply, access control (personnel) & detection aids (protected area, vital areas)
 SMITH, O C, GDDY, A T Region 1, Office of Director 83/05/13
 3pp 18679 360 24X Fiche 50-334, 83/05/17, 8306010326

8306060200 Forwards IE Insp Rept 50-334/83-08 on 830405-0502 & notice of violation
 STAROSTECKI, R Division of Project & Resident Programs 83/05/23
 CAREY, J J Duquesne Light Co 2pp 18727 256 24X
 Fiche 50-334, 83/05/23, 8306060200

--8306060204 Notice of violation from insp on 830405-0502
 * Region 1, Office of Director 83/05/23 1p 18727 258 24X
 Fiche 50-334, 83/05/23, 8306060200

--8306060214 IE Insp Rept 50-334/83-08 on 830405-0502 Noncompliance noted failure to demonstrate ECCS valve operability within specified surveillance interval
 TROSKOSKI, W M, TRIPP, L E Region 1, Office of Director 83/05/17 22pp 18727 259 24X Fiche 50-334, 83/05/23, 8306060200

8306100104 Forwards fees for review of 330517 application for relief from ASME Code interservice insp requirements for RHR nozzle-to-vessel weld volumetric exam
 SIEBER, J D Duquesne Light Co 83/05/24 License Fee Management Branch 3pp 18803 073 24X Fiche 50-334, 83/05/24, 8306100104

8305110458 IE Info Notice 83-34, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl
 TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

DOCKETED ITEMS

187

8306030270 Ack receipt of 830516 ltr informing NRC of steps taken to correct violations noted in IE Insp Rpt 50-334/83 07
STAROSTECKI, R Division of Project & Resident Programs 83/05/26
CAREY, J J Duquesne Light Co 2pp 11/04 001 24X
Fiche 50-334,83/05/26,8306030270

--8306030303 Responds to NRC 830420 ltr re violations noted in IE Insp Rpt 50-334/83-07 Corrective action supplemental repts prepared for listed LERs reviewed for issuance prior to 830527
CAREY, J J Duquesne Light Co 83/05/18 STAROSTECKI, R Division of Project & Resident Programs 4pp 18/04 003 24X
Fiche 50-334,83/05/26,8306030303

8305110461 IE Info Notice 83 J6, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 203 24X Fiche 50-000,83/05/31,8305110461

8306140620 Forwards response to IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators " Valve integrity verification procedures will be performed Info required to complete Item 5 forthcoming
CAREY, J J Duquesne Light Co 83/06/07 Region 1, Office of Director 8pp 18841 250 24X Fiche 50-334,83/06/07,8306140620

8306280435 Responds to IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators " Info requested by Action Items 1,2, 3 & 4 re pump & valve inservice program encl
CAREY, J J Duquesne Light Co 83/06/07 Region 1, Office of Director 8pp 19018 340 24X Fiche 50-334,83/06/07,8306280435

8305110464 IE Info Notice 83 J6, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/07 Consolidated Edison Co of New York, Inc 117pp 18830 200 24X Fiche 50-000,83/06/07,8305110464

8305110470 IE Info Notice 83-J6, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 110pp 18920 225 24X Fiche 50-000,83/06/13,8305110470

8306070010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/17 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000,83/06/13,8306070010

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 115pp 19021 174 24X Fiche 50-000,83/06/22,8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000,83/06/22,8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000,83/06/23,8305110479

8306280490 Forwards SALP rpt for evaluation period Dec 1981 ~ Nov 1982 Fire protection & housekeeping rating upgraded to Category 2
MURLEY, T E Region 1, Office of Director 83/06/23 CAREY, J J Duquesne Light Co 4pp 19019 187 24X Fiche 50-334,83/06/23,8306280490

--8306280492 Forwards SALP rpt conducted on 830124 for Dec 1981 ~ Nov 1982 Meeting scheduled for 830215 at site to discuss assessment
STAROSTECKI, R Division of Project & Resident Programs 83/02/07 CAREY, J J Duquesne Light Co 2pp 19019 193 24X
Fiche 50-334,83/06/23,8306280490

--8306280495 Responds to NRC 830207 ltr re results of SALP Board review Reconsideration of rating given to Item 5, "Fire Protection & Housekeeping," requested
CAREY, J J Duquesne Light Co 83/03/02 HAYNES, R C Region 1, Office of Director 7pp 19019 195 24X Fiche 50-334,83/06/23,8306280490

--8306280497 SALP rpt for Dec 1981 ~ Nov 1982
* Region 1, Office of Director 83/01/24 32pp 19019 202 24X
Fiche 50-334,83/06/23,8306280490

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000,83/06/24,8305110483

R Periodic operating reports & related correspondence

8306020218 Monthly operating rpt for Mar 1983 W/830406 ltr
HOLTZ, J L, CAREY, J J Duquesne Light Co 83/04/06 Office of Resource Management, Director 4pp 18690 269 24X
Fiche 50-334,83/04/06,8306020218

8306160476 Monthly operating rpt for Apr 1983 W/830505 ltr
HOLTZ, J L, CAREY, J J Duquesne Light Co 83/05/05 Office of Resource Management, Director 5pp 18662 237 24X
Fiche 50-334,83/05/05,8306160476

8306070120 NPDES monthly discharge monitoring repts for Apr 1983 W/830525 ltr
FEITHNECHT, C Duquesne Light Co 83/05/25 REID, R W Operating Reactors Branch 4 16pp 18739 282 24X Fiche 50-334,83/05/25,8306070120

8306300210 "NPDES Discharge Monitoring Rept for May 1983 " W/830627 ltr
FEITHNECHT, C, STEED, L S Duquesne Light Co 83/06/24 REID, R W Operating Reactors Branch 4 16pp 19119 150 24X
Fiche 50-334,83/06/24,8306300210

S Reportable occurrences, LERs & related correspondence

8304110818 Forwards LER 83-008/03L 0
LACEY, W S Duquesne Light Co 83/03/10 HAYNES, R C Region 1, Office of Director 2pp 17919 334 24X Fiche 50-334,83/03/10,8304110818

--8304110827 LER 83-008/03L-0 on 830218, during routine surveillance test on turbine driven auxiliary feedwater pump, pump packing overheated Caused by burr on follower rubbing pump shaft Follower hand dressed Pump repacked
DRUGA, R J Duquesne Light Co 83/03/08 Region 1, Office of Director 2pp 17919 336 24X Fiche 50-334,83/03/10,8304110818

8306010302 Updated LER 83-002/03X-1 on 830107, 138 kV bus 1 lost Caused by inadvertent operation of bus pack-up timer relay Relay tested satisfactorily Cause of actuation unknown Possible causes listed W/830503 ltr
LACEY, W S Duquesne Light Co 83/05/02 ALLAN, J M Region 1, Office of Director 4pp 18672 178 24X Fiche 50-334,83/05/02,8306010302

8306010295 Updated LER 81-083/03X-1 on 810906, nuclear instrumentation power range monitor N44 failed low due to power supply problems Power supply replaced Failed monitor sent to Westinghouse for repair W/830507 ltr
LACEY, W S Duquesne Light Co 83/05/05 ALLAN, J M Region 1, Office of Director 4pp 18672 191 24X Fiche 50-334,83/05/05,8306010295

8306020440 LER 83-013/03L-0 on 830505, during normal operation, chlorine detector B wick observed dry while electrolyte reservoir indicated full Caused by binding level indicator Indicator freed W/830519 ltr
LACEY, W S Duquesne Light Co 83/05/10 ALLAN, J M Region 1, Office of Director 4pp 18693 187 24X Fiche 50-334,83/05/10,8306020440

8306020324 Updated LER 81-048/03X-1 on 810503, while putting RHR sys in operation, one RHR pump suction valve would not open Cause unknown Adjustment made to torque switch bypass limit switch & all wiring connections inspected W/830520 ltr
LACEY, W S Duquesne Light Co 83/05/20 ALLAN, J M Region 1, Office of Director 4pp 18694 281 24X Fiche 50-334,83/05/20,8306020324

8306020383 Updated LER 81-042/03X-1 on 810428, block valve MOV-RC-535 failed to shut as indicated by control room valve status light Cause undetermined Motor limit switch assembly replaced W/830520 ltr
LACEY, W S Duquesne Light Co 83/05/20 ALLAN, J M Region 1, Office of Director 4pp 18694 356 24X Fiche 50-334,83/05/20,8306020383

DOCKETED ITEMS

8306170030 Updated LER 83-014/03L-0 on 830503, monthly valve stroke tests of refueling water storage tank to low head safety injection pump suction valves not conducted. Caused by deficiency in surveillance program W/830601 ltr. LACEY, W S Duquesne Light Co 83/06/02 ALLAN, J M Region 1, Office of Director 4pp 18878 287 24X Fiche 50-335, 83/06/02, 8306170030

8306200382 LER 83-012/03L-0 on 830509, 15 & 16 core cooling monitor failed, rendering data retrieval impossible. Caused by broken card cage & defective card in spare core cooling monitor unit. Card cage repaired W/830603 ltr. LACEY, W S Duquesne Light Co 83/06/02 ALLAN, J M Region 1, Office of Director 4pp 18879 012 24X Fiche 50-334, 83/06/03, 8306200382

8306210248 PNS-I-83-014 on 830615, control room received low seal flow alarm & lost indication of seal leak-off flow on reactor coolant pump IC Valve CH210. Found closed. Licensee interviewing personnel working in containment area. MCKEOWN, M, ODDY, JOYNER Region 1, Office of Director 83/06/16 2pp 18915 251 24X Fiche 50-334, 83/06/06, 8306210248

8306280139 LER 83-015/03L-0 on 830524, during normal power operation, relay 51-VD106X experienced spurious actuation, causing inadvertent isolation of emergency bus 1DF from normal supply. Caused by personnel error W/830617 ltr. LACEY, W S Duquesne Light Co 83/06/17 ALLAN, J M Region 1, Office of Director 4pp 19014 329 24X Fiche 50-334, 83/06/17, 8306280139

8306230462 PNS-I-83-014A updates PNS-I-83-014 re possible equipment tampering on 830615. On 830617, FBI concluded no evidence of deliberate equipment tampering evident. Valve probably inadvertently closed. BAILEY Region 1, Office of Director 83/06/20 1p 18941 328 24X Fiche 50-334, 83/06/20, 8306230462

V Operator Examinations

8306200442 Notification of 830609 significant licensee meeting in King of Prussia, PA to discuss qualifications for reactor operator licensing. KELLER, R M Region 1, Office of Director 83/05/26 Region 1, Office of Director 1p 18701 362 24X Fiche 50-334, 83/05/26, 8306200442

8306140662 Extends invitation to attend 830627 meeting in King of Prussia, PA, to discuss transfer of reactor operator licensing function from Bethesda, MD to Region 1. STARDOSTECKI, R Division of Project & Resident Programs 83/06/09 CARNEY, J J Duquesne Light Co 2pp 18838 339 24X Fiche 50-334, 83/06/09, 8306140662

DOCKET 50-335 ST LUCIE PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8306140646 Confirms 830223 onsite enforcement meeting to discuss incident re vital area security door left ajar on 830104, per 830217 telcon. Proposed meeting agenda encl. O'REILLY, J P Region 2, Office of Director 83/02/18 UHRIE, R E Florida Power & Light Co 2pp 18841 140 24X Fiche 50-335, 83/02/18, 8306140646

8306140538 Forwards IE Insp Repts 50-335/83-06 & 50-389/83-20 on 830314-18. No noncompliance noted. DANCE, H C Division of Project & Resident Programs 83/05/18 UHRIE, R E Florida Power & Light Co 2pp 18834 145 24X Fiche 50-335, 83/05/18, 8306140538

--8306140541 IE Insp Repts 50-335/83-06 & 50-389/83-20 on 830314-18. No noncompliance noted. Major areas inspected emergency planning. HUFFMAN, O N Region 2, Office of Director JENKINS, O R Division of Emergency Preparedness & Materials Safety 83/05/17 6pp 18834 167 24X Fiche 50-335, 83/05/18, 8306140538

8306140302 Forwards IE Insp Repts 50-335/83-18 & 50-389/83-41 on 830506. No noncompliance noted. DANCE, H C Division of Project & Resident Programs 83/05/23 UHRIE, R E Florida Power & Light Co 2pp 18832 090 24X Fiche 50-335, 83/05/23, 8306140302

--8306140310 IE Insp Repts 50-335/83-18 & 50-389/83-41 on 830506. No noncompliance noted. Major areas inspected emergency preparedness accountability drill. HUFFMAN, O N Region 2, Office of Director JENKINS, O R Division of Emergency Preparedness & Materials Safety 83/05/19 4pp 18832 100 24X Fiche 50-335, 83/05/23, 8306140302

8306290209 Forwards IE Insp Repts 50-335/83-17 & 50-389/83-34 on 830509-13. No noncompliance noted. DANCE, H C Division of Project & Resident Programs 83/06/01 UHRIE, R E Florida Power & Light Co 2pp 19056 114 24X Fiche 50-335, 83/06/01, 8306290209

--8306290221 IE Insp Repts 50-335/83-17 & 50-389/83-34 on 830509-13. No noncompliance noted. Major areas inspected enforcement responses, Insp Followup items, containment cable tray covers & App R electrical cable re-routing. HUNT, M D, CONLON, T E Region 2, Office of Director 83/05/26 6pp 19056 116 24X Fiche 50-335, 83/06/01, 8306290209

8306140023 Releases public version of revised offnormal emergency plan implementing procedures. FELTON, J M Division of Rules and Records 83/06/06 Document Management Branch 1p 18831 166 24X Fiche 50-335, 83/06/06, 8306140023

--8306140033 Forwards public version of revised offnormal emergency plan implementing procedures, including Procedures 2-0030131 re plant annunciator summary, 2-0030141 re control room inaccessibility & 2-0440030 re SDC/LBI offnormal operation. WETHY, C M Florida Power & Light Co 83/05/17 Office of Nuclear Reactor Regulation, Director 1p 18831 167 24X Fiche 50-335, 83/06/06, 8306140023

--8306140038 Public version of revised offnormal emergency plan implementing procedures, including Procedures 2-0030131 re plant annunciator summary, 2-0030141 re control room inaccessibility & 2-0440030 re SDC/LBI offnormal operation. * Florida Power & Light Co 83/05/12 263pp 18831 168 24X Fiche 50-335, 83/06/06, 8306140023

8306220225 Releases public version of revised offnormal & emergency operating procedures. FELTON, J M Division of Rules and Records 83/06/06 Document Management Branch 1p 18977 167 24X Fiche 50-335, 83/06/06, 8306220225

--8306220230 Forwards public version of revised offnormal & emergency operating procedures, including Procedures 2-0030140 re blackout operation, 2-0030143 re total loss of power & 2-0250030 re emergency boration. WETHY, C M Florida Power & Light Co 83/04/27 Director's Office, Office of Inspection and Enforcement 1p 18977 168 24X Fiche 50-335, 83/06/06, 8306220225

--8306220236 Public version of revised offnormal & emergency operating procedures, including Procedures 2-0030140 re blackout operation, 2-0030143 re total loss of ac power & 2-0250030 re emergency boration. * Florida Power & Light Co 83/04/26 Director's Office, Office of Inspection and Enforcement 87pp 18977 169 24X Fiche 50-335, 83/06/06, 8306220225

J Insurance & indemnity information

8306270103 Amend B to Indemnity Agreement D-76, adding Orlando Utilities Commission of City of Orlando, FL as licensee. SALTZMAN, J Assistant Director for State & Licensee Relations 83/03/28 1p 18988 117 24X Fiche 50-335, 83/03/28, 8306270103

8306270128 Amend 9 to Indemnity Agreement D-76, adding Florida Municipal Power Agency as licensee. SALTZMAN, J Assistant Director for State & Licensee Relations 83/03/29 1p 18988 092 24X Fiche 50-335, 83/03/29, 8306270103

8306270210 Unexecuted Amend 10 to Indemnity Agreement D-76, substituting listed item 3 re license numbers. SALTZMAN, J Assistant Director for State & Licensee Relations 83/04/06 1p 18991 218 24X Fiche 50-335, 83/04/06, 8306270210

P Operating license stage documents & correspondence

8306080161 "Radiological Effluent Tech Specs (RETS) Implementation St Lucie Unit 1 Nuclear Generating Plant." SIMPSON, F D, SERRANO, W., DUCL, S W ECKG, Inc FIN A-6459 E00-PHYS-6241 83/04/26 Division of Systems Integration (post 811005) 49pp 18789 279 24X Fiche 50-335, 83/04/26, 8306080161

8306140784 Notices of review of Rev 1 to 830308 process control program. Program contains necessary process parameters & boundary conditions to assure that dewatering of bead resin will be complete w/no free liquid. Program acceptable. KNIGHTON, O W Licensing Branch 3 83/05/10 UHRIE, R E Florida Power & Light Co 2pp 18845 331 24X Fiche 50-335, 83/05/10, 8306140784

8306080251 Forwards "Control of Heavy Loads (C-10) St Lucie Unit 1," draft technical report per util response to Section 2.1 of 801222 generic ltr re NUREG-0612 Completion of review by 830617 requested
CLARK, R A Operating Reactors Branch 3 83/05/24 UHR10, R E
Florida Power & Light Co 2pp 18787 137 24X
Fiche 50-335, 83/05/24, 8306080251

--8306080252 "Control of Heavy Loads (C-10) St Lucie Unit 1," draft technical evaluation report
BOMBARDIER, C, AHMED, N Franklin Institute/Franklin Research Center NRC-03-81-130 TCR-C5506-394 DRAFT 83/04/29
CLEMENS, G NRC - No Detailed Affiliation Given 36pp
18787 141 24X Fiche 50-335, 83/05/24, 8306080251

8306020046 Notification of 830603 meeting w/util & C E in Bethesda, MD to discuss loose parts monitoring sys & installed ex-core instrumentation
SELLS, D F Operating Reactors Branch 3 83/05/25 CLARK, R A
Operating Reactors Branch 3 2pp 18701 355 24X
Fiche 50-335, 83/05/25, 8306020046

8306080094 Notice of consideration of issuance of amend to License DPR-67 & proposed no significant hazards consideration determination & opportunity for hearing re improved & larger capacity 125-volt dc battery sys
CLARK, R A Operating Reactors Branch 3 83/05/25 9pp 18787 327 24X Fiche 50-335, 83/05/25, 8306080094

8306140414 Informs that interim plan to reduce blocked position from 50 to 140 degrees acceptable pending review of 830115 rept re out of plane upstream elbow BWP & 2 4 & Positions 6 & 7 of TH1 Action Item 11 C 4 2 closed
CLARK, R A Operating Reactors Branch 3 83/05/27 UHR10, R E
Florida Power & Light Co 6pp 18854 072 24X
Fiche 50-335, 83/05/27, 8306140414

8306160288 Notice of consideration of issuance of amend to License DPR-67 & proposed no significant hazards consideration determination & opportunity for hearing
CLARK, R A Operating Reactors Branch 3 83/05/27 9pp 18893 001 24X Fiche 50-335, 83/05/27, 8306160288

8306100087 Discusses updated submittal dates for reactor vessel internals & thermal shield recovery programs as followup to safety assessment provided at 830603 meeting
UHR10, R E Florida Power & Light Co 83/06/07 CLARK, R A
Operating Reactors Branch 3 3pp 18002 234 24X
Fiche 50-335, 83/06/07, 8306100087

8306210311 Requests for publication of notice of consideration of issuance of amend to License DPR-67 & proposed no significant hazards consideration determination & opportunity for hearing re surveillance requirements
CLARK, R A Operating Reactors Branch 3 83/06/13 CLARK, R A
Operating Reactors Branch 3 3pp 18722 360 24X
Fiche 50-335, 83/06/13, 8306210311

8306170317 Notifies that vendor safety analysis to support installation of mods to auxiliary feedwater sys, returned to vendor for reanalysis
UHR10, R E Florida Power & Light Co 83/06/15 CLARK, R A
Operating Reactors Branch 3 1p 18870 216 24X
Fiche 50-335, 83/06/15, 8306170317

8306290249 Advises that methodology used to calculate beta dose for radiation profile for equipment qualification not acceptable Resubmittal of beta analysis based upon methodology in NUREG-0588 required by 830630
CLARK, R A Operating Reactors Branch 3 83/06/17 UHR10, R E
Florida Power & Light Co 2pp 19046 116 24X
Fiche 50-335, 83/06/17, 8306290249

8306280250 Forwards assessment of safety impacts of removal of thermal shield from Facility, per 830419 commitment Assessment addresses Cycle & reload safety analysis of plant recovery program
UHR10, R E Florida Power & Light Co 83/06/23 CLARK, R A
Operating Reactors Branch 3 32pp, 19014 197 24X
Fiche 50-335, 83/06/23, 8306280250

8306280356 Comments on plant recovery program re reactor vessel internals & thermal shield (gamma heating effect of removal of thermal shield) Gamma heating slight benefit to vessel integrity
UHR10, R E Florida Power & Light Co 83/06/23 CLARK, R A
Operating Reactors Branch 3 2pp 19014 095 24X
Fiche: 50-335, 83/06/23, 8306280356

G Inspection reports, IE Bulletins & correspondence

8306140622 Submits confirmation of action ltr re 830411 telcon & 830203 mgt meeting on deficiencies in operating & emergency procedures Actions to be taken to correct deficiencies listed
O'REILLY, J P Region 2, Office of Director 83/04/11 ADDMAT, E A
Florida Power & Light Co 2pp 18843 007 24X
Fiche 50-335, 83/04/11, 8306140622

8306140343 Forwards IE Insp Rept 50-335/83-14 on 830425-27 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/05/17
UHR10, R E Florida Power & Light Co 2pp 18832 176 24X
Fiche 50-335, 83/05/17, 8306140343

--8306140349 IE Insp Rept 50-335/83-14 on 830425-27 No noncompliance noted Major areas inspected inservice insp review of program procedures, observation of work & LER followup
KLEINBORGE, W P, BLAKE, J J Region 2, Office of Director 83/05/12 5pp 18832 178 24X Fiche 50-335, 83/05/17, 8306140343

8306140538 Forwards IE Insp Repts 50-335/83-06 & 50-389/83-20 on 830314-18 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/05/18
UHR10, R E Florida Power & Light Co 2pp 18834 165 24X
Fiche 50-335, 83/05/18, 8306140538

--8306140541 IE Insp Repts 50-335/83-06 & 50-389/83-20 on 830314-18 No noncompliance noted Major areas inspected, emergency planning
HUFFMAN, G N Region 2, Office of Director JENKINS, Q R Division of Emergency Preparedness & Materials Safety 83/05/17 6pp 18834 167 24X Fiche 50-335, 83/05/18, 8306140538

8306140190 Forwards IE Insp Rept 50-335/83-16 on 830426-29 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/05/19
UHR10, R E Florida Power & Light Co 2pp 18833 038 24X
Fiche 50-335, 83/05/19, 8306140190

--8306140196 IE Insp Rept 50-335/83-16 on 830426-29 No noncompliance noted Major areas inspected periodic integrated leak rate test & exam of test condition & test performance & results
WHITENER, H L Region 2, Office of Director JAEF, F Division of Engineering & Radiological Safety Programs 83/05/18 6pp 18833 040 24X Fiche 50-335, 83/05/19, 8306140190

8306140302 Forwards IE Insp Repts 50-335/83-18 & 50-389/83-41 on 830506 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/05/23
UHR10, R E Florida Power & Light Co 2pp 18832 098 24X
Fiche 50-335, 83/05/23, 8306140302

--8306140310 IE Insp Repts 50-335/83-18 & 50-389/83-41 on 830506 No noncompliance noted Major areas inspected, emergency preparedness accountability drill
HUFFMAN, G N Region 2, Office of Director JENKINS, Q R Division of Emergency Preparedness & Materials Safety 83/05/19 4pp 18832 100 24X Fiche 50-335, 83/05/23, 8306140302

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc. 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8306140640 Documents concurrence w/util actions taken in response to 830411 Confirmation of Action Ltrs CAL-335/83-01 & 389/83-01 Insp during wk of 830516 concluded that Unit 2 procedures adequate for startup & operation
O'REILLY, J P Region 2, Office of Director 83/05/27 ADDMAT, E A
Florida Power & Light Co 2pp 18841 161 24X
Fiche 50-335, 83/05/27, 8306140640

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs," Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306290209 Forwards IE Insp Repts 50-335/83-17 & 50-389/83-39 on 830509-13 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/06/01
UHR10, R E Florida Power & Light Co 2pp 19056 114 24X
Fiche 50-335, 83/06/01, 8306290209

DOCKETED ITEMS

--8306290221 IE Insp Repts 50-335/83-17 & 50-389/83-39 on 830509-13 Non compliance noted Major areas inspected enforcement responses, insp followup items, containment cable tray covers & App R electrical cable rerouting
HUNT, M D, CONLON, T E Region 2, Office of Director. 83/05/26 6pp 19056 116 24X Fiche 50-335, 83/06/01, 8306290209

8306290398 Responds to IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators " Closed cooling radiator sys contains no check valves Bulletin not applicable
UHRIG, R E Florida Power & Light Co 83/06/08 O'REILLY, J P Region 2, Office of Director 2pp 19052 183 24X Fiche 50-000, 83/06/08, 8306290398

8305110444 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 117pp 18930 280 24X Fiche 50-000, 83/06/09, 8305110444

8305110470 IE Info Notice 83-38, "Defective Heat Smt Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 116pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8306290327 Ack receipt of 830420 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-335/82-36
DANCE, H C Division of Project & Resident Programs 83/06/17 UHRIG, R E Florida Power & Light Co 1p 19050 194 24X Fiche 50-335, 83/06/17, 8306290327

--8306290338 Suppls 830106 response to NRC 821207 ltr re violations noted in IE Insp Rept 50-335/82-36 Corrective actions employee responsibilities during procedure control & maint implementation emphasized
UHRIG, R E Florida Power & Light Co 83/04/20 O'REILLY, J P, Region 2, Office of Director 1p 19050 195 24X Fiche 50-335, 83/06/17, 8306290327

--8306290351 Responds to NRC 821207 ltr re violations noted in IE Insp Rept 50-335/82-36 Corrective actions caution tags hung & valves closed at time of notification on 821008 Responsible dept will be notified when restricted equipment installed
UHRIG, R E Florida Power & Light Co 83/01/06 O'REILLY, J P Region 2, Office of Director 2pp 19050 196 24X Fiche 50-335, 83/06/17, 8306290327

--8306290359 Forwards IE Insp Repts 50-335/82-36 & 50-389/82-55 on 821011-1110 & notice of violation
DANCE, H C Division of Project & Resident Programs 82/12/07 UHRIG, R E Florida Power & Light Co 2pp 19050 198 24X Fiche 50-335, 83/06/17, 8306290327

--8306290368 Notice of violation from insp on 821011-1110
* Region 2, Office of Director 82/12/07 1p 19050 200 24X Fiche 50-335, 83/06/17, 8306290327

--8306290379 IE Insp Repts 50-335/82-36 & 50-389/82-55 on 821011-1111. Noncompliance noted use of unqualified matl in emergency diesel generator lube oil sys
ELROD, B A, BIBB, H E Region 2, Office of Director JULIAN, C A Division of Project & Resident Programs 82/12/06 11pp 19050 201 24X Fiche 50-335, 83/06/17, 8306290327

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

R Periodic operating reports & related correspondence

8306020216 Monthly operating repts for Mar 1983 W/830415 ltr
PACE, P L, WILLIAMS, J W Florida Power & Light Co 83/04/15 Office of Resource Management, Director 13pp 18670 256 24X Fiche 50-000, 83/04/15, 8306020216

8306160638 Monthly operating repts for Apr 1983 W/830516 ltr
PACE, P L, WILLIAMS, J W Florida Power & Light Co 83/05/16 Office of Resource Management, Director 17pp 18666 105 24X Fiche 50-000, 83/05/16, 8306160638

S Reportable occurrences, LERS & related correspondence

8306140683 Part 21 rept supplementing 830506 notification of potential significant safety hazard re matl defects in stainless steel tubing pressure boundary component Ultrasonic exam shows assemblies acceptable per ASME Code, Section III
SCHERER, A E Combustion Engineering, Inc 83/06/07 BEYOUNG, R C Director's Office, Office of Inspection and Enforcement 1p 18842 066 24X Fiche 50-335, 83/06/07, 8306140683

V Operator Examinations

8306140745 Discusses shift staffing at facilities Util intends to initially operate Unit 2 & continue Unit 1 operations w/five full shifts of licensed operators on each unit Planned actions for filling vacant positions provided
UHRIG, R E Florida Power & Light Co 83/06/03 EISENHUT, D G Division of Licensing 3pp 18841 192 24X Fiche 50-335, 83/06/03, 8306140745

8306140572 Forwards revised shift staffing chart based on 830606 notification that seven licensee candidates received reactor operator licenses
UHRIG, R E Florida Power & Light Co 83/06/07 EISENHUT, D G Division of Licensing 2pp 18844 149 24X Fiche 50-335, 83/06/07, 8306140572

DOCKET 50-336 HILLSTONE NUCLEAR POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8306070136 Forwards Rev 16 to modified amended security plan Rev withheld (ref 10CFR2 790 & 10CFR73 21)
COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W G Northeast Utilities 83/05/12 ALLAN, J M Region 1, Office of Director 1p 18739 219 24X Fiche 50-245, 83/05/12, 8306070136

8306060154 Provides addl info re util request for exemption from 10CFR50, App R re control room fire per 830318 meeting
Alternate operator actions can be completed to facilitate safe shutdown following fire in control boards
COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W G Northeast Utilities 83/05/25 EISENHUT, D G Division of Licensing 31pp 18719 166 24X Fiche 50-336, 83/05/25, 8306060154

8306090238 Forwards IE Insp Repts 50-245/83-11 & 50-336/83-13 on 830417-0507 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/05/27 COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 18795 299 24X Fiche 50-245, 83/05/27, 8306090238

--8306090241 IE Insp Repts 50-245/83-11 & 50-336/83-13 on 830417-0507 No noncompliance noted Major areas inspected evaluations of plant operations, startup testing, equipment alignments & readiness, radiation protection & physical security
SHEDLOSKY, J T Region 1, Office of Director 83/05/20 17pp 18795 301 24X Fiche 50-245, 83/05/27, 8306090238

8306200307 Ack receipt of 830225 & 0415 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-245/83-01 & 50-336/83-01 Confirms understanding that uninterruptable power supply sys was operable by 830501
HARTIN, T T Division of Engineering & Technical Programs 83/06/15 COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 18900 164 24X Fiche 50-245, 83/06/15, 8306200307

DOCKETED ITEMS

191

--8306200313 Responds to NRC ltr re violations noted in IE Insp Repts 50-245/83-01 & 50-336/83-01 Forwards info requested during IE security insp info withheld (ref 10CFR73 21 & 10CFR2 790)
COUNSIL, W Q Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/02/25 HAYNES, R C Region 1, Office of Director 1p 18900 166 24X Fiche 50-245, 83/06/15, 8306200307

--8306200322 Responds to NRC ltr re violation noted in IE Insp Repts 50-245/83-01 & 50-336/83-01 Forwards info requested during IE security insp info withheld (ref 10CFR73 21 & 10CFR2 790)
COUNSIL, W Q Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/04/15 ALLAN, J M Region 1, Office of Director 1p 18900 167 24X Fiche 50-245, 83/06/15, 8306200307

H General correspondence

8306060090 Requests rev to "cc" distribution list for NRR correspondence reflecting position & title changes within utility
COUNSIL, W Q Connecticut Yankee Atomic Power Co COUNSIL, W Q Northeast Utilities COUNSIL, W Q Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/05/31 CLARK, R A Operating Reactors Branch 3 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 18/19 360 24X Fiche 50-000, 83/05/31, 8306060090

P Operating license stage documents & correspondence

8306020642 Summary of 830504 meeting w/util & Westinghouse in Bethesda, MD re steam generator sleeving Request for Tech Spec changes expected by 830601
LEECH, P H Operating Reactors Branch 3 83/05/17 CLARK, R A Operating Reactors Branch 3 26pp 18716 278 24X Fiche 50-336, 83/05/17, 8306020642

8306010340 Forwards Rev 13 to corporate organization for nuclear incidents procedures manual table of contents & Rev 3 to CONI 4 02, "On-Call Manager of Radiological Consequence Assessment, Responsibilities & General Guidelines" w/o encl
COUNSIL, W Q SEARBY, C F Connecticut Yankee Atomic Power Co COUNSIL, W Q Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/05/18 EISENHUT, D Q Division of Licensing 1p 18682 271 24X Fiche 50-000, 83/05/18, 8306010340

8306030012 Forwards SER re thermal shield & support sys Continued operation until 830528 scheduled shutdown justified Request findings re 10-yr inservice insp of shield & barrel assembly components
CLARK, R A Operating Reactors Branch 3 83/05/18 COUNSIL, W Q Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 18733 141 24X Fiche 50-336, 83/05/18, 8306030012

--8306030016 Safety evaluation supporting continued operation w/thermal shield & support sys
* NRC - No Detailed Affiliation Given 83/05/18 3pp 18733 143 24X Fiche 50-336, 83/05/18, 8306030012

8306060098 "Environ Qualification of Safety-Related Electrical Equipment"
COUNSIL, W Q SEARBY, C F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W Q Northeast Utilities 83/05/20 EISENHUT, D Q Division of Licensing 71pp 18723 001 24X Fiche 50-336, 83/05/20, 8306060098

8306060092 Advises that requirements of NUREG-0737, Item II. B 2 re plant shielding for vital areas will be met when mods described in encl safety evaluation implemented Review of corrective actions completed
CLARK, R A Operating Reactors Branch 3 83/05/24 COUNSIL, W Q Northeast Nuclear Energy Co (subs of Northeast Utilities) 5pp 18791 253 24X Fiche 50-336, 83/05/24, 8306060092

8306130491 Ack receipt of 830503 ltr requesting Total Axial Shape Index utilized in safety analyses be withheld from public disclosure (ref 10CFR2 790) Request approved
CLARK, R A Operating Reactors Branch 3 83/06/01 COUNSIL, W Q Northeast Nuclear Energy Co (subs of Northeast Utilities) 4pp 18830 140 24X Fiche 50-336, 83/06/01, 8306130491

8306080431 Notifies that util 830425 ltr informing NRC that technical evaluation re environ qualification of safety-related electrical equipment no longer proprietary
CLARK, R A Operating Reactors Branch 3 83/06/03 BAILEY, I Division of Technical Information & Document Control 1p 18792 189 24X Fiche 50-336, 83/06/03, 8306080431

8306140352 Releases, for public disclosure, 830406 technical evaluation rept re resolution of outstanding issues from environ qualification SERs F-11 & D-60 for Facility per 830425 util ltr
CLARK, R A Operating Reactors Branch 3 83/06/03 BAILEY, I Records Services & Facilities Branch 1p 18835 001 24X Fiche 50-336, 83/06/03, 8306140352

--8306140361 Responds to 830406 SER re environ qualification of electrical equipment for Facility Corresponding technical evaluation rept contains no proprietary info & can be released for public disclosure, per 10CFR2 790
COUNSIL, W Q Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W Q Northeast Utilities 83/04/25 CLARK, R A Operating Reactors Branch 3 2pp 18835 002 24X Fiche 50-336, 83/06/03, 8306140362

--8302250381 "Review of Licensee Resolution of Outstanding Issues from NRC Equipment Environ Qualification SERs (F-11 & D-60)," nonproprietary technical evaluation rept
TOMAN, O J Franklin Institute/Franklin Research Center NRC-03-77-118 TER-C5257-467 83/02/21 SHEMANSKI, P NRC - No Detailed Affiliation Given 669pp 18836 001 24X Fiche 50-336, 83/06/03, 8306140352

8306160283 Notice of consideration of issuance of amends to Licenses DPR-21 & DPR-65 & proposed no significant hazards consideration determination & opportunity for hearing
CLARK, R A Operating Reactors Branch 3 83/06/03 10pp 18893 010 24X Fiche 50-245, 83/06/03, 8306160283

8306270255 Application for amend to License DPR-65, revising Tech Specs re repair of defective steam generator tubes through plugging or sleeving
COUNSIL, W Q Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W Q Northeast Utilities 83/06/03 CLARK, R A Operating Reactors Branch 3 4pp 18989 162 24X Fiche 50-336, 83/06/03, 8306270255

--8306270258 Proposed Tech Spec rev re repair of defective steam generator tubes through plugging or sleeving
* Northeast Utilities 83/06/30 26pp 18989 167 24X Fiche 50-336, 83/06/03, 8306270255

8306160412 Forwards draft Rev 5 to "QA Program Topical Rept"
COUNSIL, W Q Northeast Utilities Service Co COUNSIL, W Q Northeast Utilities 83/06/09 MURLEY, T E Region 1, Office of Director App. 18859 090 24X Fiche 50-000, 83/06/09, 8306160412

--8306160424 Draft Rev 5 to "QA Program Topical Rept"
* Northeast Utilities 83/06/09 133pp 18859 096 24X Fiche 50-000, 83/06/09, 8306160412

8306200278 Forwards request for addl info on methodology of analyses re reload Cycle 6, to complete review of 830413 submittal
Response requested by 830701
CLARK, R A Operating Reactors Branch 3 83/06/10 COUNSIL, W Q Northeast Nuclear Energy Co (subs of Northeast Utilities) 4pp 18909 359 24X Fiche 50-336, 83/06/10, 8306200278

8306240200 Forwards listed revs to Corporate Organization for Nuclear Incidents procedure manual, per Section V of App E to 10CFR50 w/o encl
COUNSIL, W Q Connecticut Yankee Atomic Power Co COUNSIL, W Q Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W Q Northeast Utilities 83/06/17 EISENHUT, D Q Division of Licensing 2pp 18980 263 24X Fiche 50-000, 83/06/17, 8306240200

8306290152 Requests FR notice of consideration of issuance of amend to License DPR-65 & proposed no significant hazards consideration & opportunity for hearing re insp of hydraulic snubbers Hazards determination available in Central Files.
CLARK, R A Operating Reactors Branch 3 83/06/22 KREUTZER, P M Operating Reactors Branch 3 3pp 19046 266 24X Fiche 50-336, 83/06/22, 8306290152

8306300140 Informs that addl nondegree personnel will be assigned to shift technical advisor position per NUREG-0737, Item I A 1 i Info re experience, college educ & current operator licenses encl.
COUNSIL, W Q Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W Q Northeast Utilities 83/06/22 CRUTCHFIELD, D Operating Reactors Branch 5 CLARK, R A Operating Reactors Branch 3 3pp 19122 020 24X Fiche 50-245, 83/06/22, 8306300140

DOCKETED ITEMS

0 Inspection reports, IE Bulletins & correspondence

8306030012 Forwards BER re thermal shield & support sys. Continued operation until 830528 scheduled shutdown justified. Requests findings re 10-yr inservice insp of shield & barrel assembly components.
CLARK, R.A. Operating Reactors Branch 3 83/05/18 COUNCIL, W.G. Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp. 18733 141 24X Fiche 50-336, 83/05/18, 8306030012.

8306060160 Forwards IE Insp Repts 50-245/83-06 & 50-336/83-08 on 830227-0416 & notice of violation.
STAROSTECKI, R. Region I, Office of Director. 83/05/23 COUNCIL, W.G. Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp. 18719 205 24X Fiche 50-245, 83/05/23, 8306060160

--8306060165 Notice of violation from insp on 830227-0416.
* Region I, Office of Director 83/05/23 ip 18719.207 24X Fiche 50-245, 83/05/23, 8306060160

--8306060171 IE Insp Repts 50-245/83-06 & 50-336/83-08 on 830227-0416 Noncompliance noted failure to maintain reactor power below 89% while monitoring core linear heat rate w/zer-core detector monitoring sys.
SHELOOSKY, J.T., LIPINSKI, D.R., ELSABER, T.C. Region I, Office of Director 83/05/21. 19pp. 18719 208. 24X Fiche 50-245, 83/05/23, 8306060160.

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device." Svc list encl
TAYLOR, J.M. Division of Safeguards & Inspection Programs (Post 830103) 83/05/26. Consolidated Edison Co. of New York, Inc. 12pp. 18831.043. 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26. Consolidated Edison Co. of New York, Inc. 115pp. 18732-089 24X Fiche 50-000, 83/05/26, 8305110460

8306090238 Forwards IE Insp Repts 50-245/83-11 & 50-336/83-13 on 830417-0507. No noncompliance noted.
STAROSTECKI, R. Division of Project & Resident Programs 83/05/27 COUNCIL, W.G. Northeast Nuclear Energy Co. (subs of Northeast Utilities) 2pp. 18795 299. 24X Fiche 50-245, 83/05/27, 8306090238

--8306090241 IE Insp Repts 50-245/83-11 & 50-336/83-13 on 830417-0507 No noncompliance noted Major areas inspected, evaluations of plant operations, startup testing, equipment alignments & readiness, radiation protection & physical security.
SHELOOSKY, J.T., LIPINSKI, D.R. Region I, Office of Director. ELSABER, T.C. Division of Project & Resident Programs 83/05/20. 17pp. 18795.301. 24X Fiche: 50-245, 83/05/27, 8306090238.

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs" Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31. Consolidated Edison Co. of New York, Inc. 116pp. 18732 208 24X Fiche 50-000, 83/05/31, 8305110461.

8306170391 Responds to IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators" No check valves installed in loop of piping to diesel generators from svc water piping.
COUNCIL, W.G. Northeast Nuclear Energy Co. (subs of Northeast Utilities). COUNCIL, W.G. Connecticut Yankee Atomic Power Co. COUNCIL, W.G. Northeast Utilities 83/05/31. MURLEY, T.E. Region I, Office of Director. 3pp. 18880-240 24X Fiche. 50-000, 83/05/31, 8306170391.

8306140352 Releases for public disclosure, 830406 technical evaluation rept re resolution of outstanding issues from environ qualification SERs F-11 & B-60 for Facility per 830425 util 1tr.
CLARK, R.A. Operating Reactors Branch 3 83/06/03. BAILEY, I. Records Services & Facilities Branch 1p. 18835.001 24X Fiche 50-336, 83/06/03, 8306140352

--8302250381 "Review of Licensee Resolution of Outstanding Issues From NRC Equipment Environ Qualification SERs (F-11 & B-60)," nonproprietary technical evaluation reft.
TOMAN, O.J. Franklin Institute/Franklin Research Center NRC-83-79-118. TER-C5257-467. 83/02/21. SHEMANSKI, P. NRC - No Detailed Affiliation Given 647pp. 18836.001. 24X Fiche. 50-336, 83/06/03, 8306140352

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/09. Consolidated Edison Co. of New York, Inc. 119pp. 18830.280. 24X Fiche 50-000, 83/06/09, 8305110464.

8306230215 Forwards IE Insp Rept 50-336/83-14 on 830518-20 No noncompliance noted.
MARTIN, T.T. Division of Engineering & Technical Programs 83/06/10 COUNCIL, W.G. Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp. 18945 255 24X Fiche 50-336, 83/06/10, 8306230215

--8306230216 IE Insp Rept 50-336/83-14 on 830518-20 No noncompliance noted Major areas inspected licensee planning for outage review of selected areas of radiation protection program.
NINITZ, R.L., SHANBAKY, M.M. Region I, Office of Director 83/06/08 7pp. 18945 257 24X Fiche 50-336, 83/06/10, 8306230215

8305110470 IE Info Notice 83-30, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards" Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13. Consolidated Edison Co. of New York, Inc. 118pp. 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13. Consolidated Edison Co. of New York, Inc. 243pp. 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8306200307 Ack receipt of 830225 & 0415 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-245/83-01 & 50-336/83-01 Confirms understanding that uninterrupted power supply sys was operable by 830501.
MARTIN, T.T. Division of Engineering & Technical Programs. 83/06/15 COUNCIL, W.G. Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp. 18900 164 24X Fiche 50-245, 83/06/15, 8306200307

--8306200313 Responds to NRC ltr re violations noted in IE Insp Repts 50-245/83-01 & 50-336/83-01 Forwards info requested during IE security insp info withheld (ref 10CFR73.21 & 10CFR2.790).
COUNCIL, W.G. Northeast Nuclear Energy Co (subs of Northeast Utilities). COUNCIL, W.G. Northeast Utilities 83/06/25. HAYNES, R.C. Region I, Office of Director 1p. 18900 166 24X Fiche. 50-245, 83/06/15, 8306200307

--8306200322 Responds to NRC ltr re violation noted in IE Insp Repts 50-245/83-01 & 50-336/83-01 Forwards info requested during IE security insp info withheld (ref 10CFR73.21 & 10CFR2.790).
COUNCIL, W.G. Northeast Nuclear Energy Co (subs of Northeast Utilities). COUNCIL, W.G. Northeast Utilities 83/06/15. ALLAN, J.M. Region I, Office of Director 1p. 18900 167 24X Fiche 50-245, 83/06/15, 8306200307

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers" Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22. Consolidated Edison Co. of New York, Inc. 115pp. 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment" Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22. Consolidated Edison Co. of New York, Inc. 120pp. 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8306280414 Notifies that entire core will be off-loaded during current refueling outage to affect 10-yr inservice insp program re bailed fuel impact on Cycle 6 safety analyses Fuel sipping performed to detect defective cladding.
COUNCIL, W.G. Northeast Nuclear Energy Co (subs of Northeast Utilities). COUNCIL, W.G. Northeast Utilities 83/06/22. CLARK, R.A. Operating Reactors Branch 3 3pp. 19020 293 24X Fiche 50-336, 83/06/22, 8306280414

8306290152 Requests FR notice of consideration of issuance of amend to License DPR-65 & proposed no significant hazards consideration & opportunity for hearing re insp of hydraulic snubbers Hazards determination available in Central Files.
CLARK, R.A. Operating Reactors Branch 3 83/06/22. KREUTZER, P.M. Operating Reactors Branch 3 3pp. 19046 266 24X Fiche 50-336, 83/06/22, 8306290152

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions" Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23. Consolidated Edison Co. of New York, Inc. 116pp. 18996 242. 24X Fiche: 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints" Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/24. Consolidated Edison Co. of New York, Inc. 116pp. 19046 297. 24X Fiche 50-000, 83/06/24, 8305110483

R Periodic operating reports & related correspondence

8306020077 Monthly operating rept for Mar 1983 W/830415 ltr
 QIBSON, J., MROGZKA, E J Northeast Nuclear Energy Co (subs of
 Northeast Utilities) MROGZKA, E J Northeast Utilities 83/04/13
 Office of Resource Management, Director 7pp 18691 203 24X
 Fiche 50-336, 83/04/13, 8306020077

S Reportable occurrences, LERs & related correspondence

8306020397 RO 83 02 on 830223, excessive levels of activity observed in
 sample of mussels. Dose consequences evaluated for First
 Quarter 1983 by using effluent transport models. No
 operational corrective actions necessary.
 MROGZKA, E J, HERBERT, R J Northeast Nuclear Energy Co (subs of
 Northeast Utilities) MROGZKA, E J Northeast Utilities 83/05/24
 MURLEY, T E Region I, Office of Director 3pp 18695 100 24X
 Fiche 50-245, 83/05/24, 8306020397

8306170042 LER 83-018/03L-Q on 830506, reactor protection sys Channel A,
 low steam generator pressure bypass removal setpoints found
 out of spec. Caused by instrument drift due to high
 sensitivity to changes in input resistance. W/830602 ltr
 DEGLANDES, K D, MROGZKA, E J Northeast Nuclear Energy Co (subs of
 Northeast Utilities) DEGLANDES, K D Northeast Utilities
 83/06/02 MURLEY, T E Region I, Office of Director 2pp
 18882 223 24X Fiche 50-336, 83/06/02, 8306170042

8306200104 Advises of GA verification of 830413 ltr re reevaluation of
 steam generator tube rupture event in support of Cycle 6
 operation. Verification confirms conclusions.
 COUNSIL, W O Northeast Nuclear Energy Co (subs of Northeast
 Utilities) COUNSIL, W O Northeast Utilities 83/06/03
 CLARK, R A Operating Reactors Branch 3 1p 18903 284 24X
 Fiche 50-336, 83/06/03, 8306200104

8306280231 LER 83-020 ongoing eddy current exams identified number of
 steam generator tubes w/defects which required both steam
 generators to be placed in C-3 insp category. Frequency of
 occurrence primarily on cold leg side.
 MROGZKA, E J Northeast Nuclear Energy Co (subs of Northeast
 Utilities) MROGZKA, E J Northeast Utilities 83/06/13
 MURLEY, T E Region I, Office of Director 1p 19015 040 24X
 Fiche 50-336, 83/06/13, 8306280231

8306230001 PNS-I-83-015 on 830616, unannounced narcotics search of site
 initiated & one marijuana cigarette found in pocketbook
 belonging to contract security watchperson. Individuals
 employment terminated.
 MADSEN, W, GODY, A, JOYNER, J Region I, Office of Director
 83/06/17 1p 18947 077 24X Fiche 50-245, 83/06/17, 8306230001

8306280353 Updated LER 82-037/03L-1 on 830902, blocking valve 2-RC-403
 would not close. Caused by Limitorque Type SMO000 torque
 switch out of adjustment. Switch readjusted & tightened.
 Stroke test completed in hot standby W/830617 ltr
 FOSTER, E R, MROGZKA, E J Northeast Nuclear Energy Co (subs of
 Northeast Utilities) MROGZKA, E J Northeast Utilities 83/06/17
 MURLEY, T E Region I, Office of Director 2pp 19001 316 24X
 Fiche 50-336, 83/06/17, 8306280353

8306280430 LER 83-019/03L-Q on 830528, following reactor trip from 40%
 power, surveillance testing indicated activity of greater
 than 1.0 uCi per gram dose equivalent I-131 in primary
 coolant. Caused by degraded fuel pins W/830618 ltr
 BORCHERT, R, MROGZKA, E J Northeast Nuclear Energy Co (subs of
 Northeast Utilities) MROGZKA, E J Northeast Utilities 83/06/18
 MURLEY, T E Region I, Office of Director 3pp 19018 337 24X
 Fiche 50-336, 83/06/18, 8306280430

V Operator Examinations

8306140231 Extends invitation to attend 830627 meeting in King of
 Prussia, PA to discuss transfer of reactor operator
 licensing function from Bethesda, MD to Region I ofc.
 STAROSTECKI, R Division of Project & Resident Programs, 83/06/09
 COUNSIL, W O Northeast Nuclear Energy Co (subs of Northeast
 Utilities) 2pp, 18832 351 24X Fiche 50-336, 83/06/09, 8306140231

DOCKET 50-336 NORTH ANNA POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8306080225 Application for amend to Licenses NPF-4 & NPF-7, changing
 Tech Specs to revise audit frequencies for emergency &
 security plans to once every 12 months. Rev consistent w/
 Generic Ltr 82-23
 STEWART, W L Virginia Electric & Power Co 82/11/22 DENTON, H R
 Office of Nuclear Reactor Regulation, Director CLARK, R A
 Operating Reactors Branch 3 3pp 18771 094 24X
 Fiche 50-338, 82/11/22, 8306080225

--8306080228 Proposed Tech Spec change revising audit frequencies for
 emergency & security plans to once every 12 months
 * Virginia Electric & Power Co 82/11/22 4pp 18771 097 24X
 Fiche 50-338, 82/11/22, 8306080225

8306160397 Clarifies position on App R requirements re fixed fire
 suppression sys. Installed standpipe, hose rack, portable
 equipment & Halon 1301 sys provide adequate fire protection.
 STEWART, W L Virginia Electric & Power Co 83/06/13 DENTON, H R
 Office of Nuclear Reactor Regulation, Director CLARK, R A
 Operating Reactors Branch 3 1p 18859 311 24X
 Fiche 50-338, 83/06/13, 8306160397

O Adjudicatory correspondence

8306150422 Memorandum discussing two issues briefed by applicant, for
 ASLB ASLB has jurisdiction to consider health & safety
 impacts & reasonably foreseeable environ impacts of
 transshipment of spent fuel from Surry to North Anna
 WOLFE, S J, KLINE, J R Atomic Safety and Licensing Board Panel
 83/06/10 9pp 18947 109 24X Fiche 50-338, 83/06/10, 8306150422

P Operating license stage documents & correspondence

8306080225 Application for amend to Licenses NPF-4 & NPF-7, changing
 Tech Specs to revise audit frequencies for emergency &
 security plans to once every 12 months. Rev consistent w/
 Generic Ltr 82-23
 STEWART, W L Virginia Electric & Power Co 82/11/22 DENTON, H R
 Office of Nuclear Reactor Regulation, Director CLARK, R A
 Operating Reactors Branch 3 3pp 18771 094 24X
 Fiche 50-338, 82/11/22, 8306080225

--8306080228 Proposed Tech Spec change revising audit frequencies for
 emergency & security plans to once every 12 months
 * Virginia Electric & Power Co 82/11/22 4pp 18771 097 24X
 Fiche 50-338, 82/11/22, 8306080225

8306030067 Forwards synopsis of issues to resolve conformance
 w/NUREG-0612 re control of heavy loads (Phase I) & draft
 technical evaluation rept.
 CLARK, R A Operating Reactors Branch 3 83/05/17 STEWART, W L
 Virginia Electric & Power Co 13pp 18733 211 24X
 Fiche 50-338, 83/05/17, 8306030067

--8306030070 "Control of Heavy Loads (C-10), Virginia Electric Power Co,
 North Anna Power Station Units 1 & 2," draft technical
 evaluation rept.
 BOMBERGER, C R, VOSBURY, F W, BARGENT, I H Franklin
 Institute/Franklin Research Center NRC-03-B1-130
 TER-C9806-372/373 DR 83/02/22 NRC - No Detailed Affiliation
 Given 28pp, 18733 224 24X Fiche 50-338, 83/05/17, 8306030067,

8306140208 Application for amend to Licenses NPF-4 & NPF-7, adding addl
 accident monitoring instrumentation & instrumentation for
 detection of inadequate core cooling per requirements of
 NUREG-0737, Items II F 1 & II F 2
 STEWART, W L Virginia Electric & Power Co 83/06/03 DENTON, H R
 Office of Nuclear Reactor Regulation, Director CLARK, R A
 Operating Reactors Branch 3 4pp 18841 165 24X
 Fiche 50-338, 83/06/03, 8306140208

--8306140222 Proposed changes to Tech Specs adding addl accident
 monitoring instrumentation & instrumentation for detection
 of inadequate core cooling per requirements of NUREG-0737,
 Items II F 1 & II F 2
 * Virginia Electric & Power Co 83/06/03 22pp 18841:169 24X
 Fiche 50-338, 83/06/03, 8306140208

8306150514 Advises of refund of fees re 821217 application to amend
 Licenses NPF-7 & NPF-4 proposing radiological effluent Tech
 Spec changes
 MILLER, W O License Fee Management Branch 83/06/07 STEWART, W L
 Virginia Electric & Power Co 1p, 18854 359 24X
 Fiche 50-338, 83/06/07, 8306150514.

8306160405 Responds to 830111 ltr & safety evaluation re possible
 overvoltage on motor control ctr contactor coils &
 resolution of motor valve rotating Test results & schedule
 for overvoltage problem will be submitted by 840131
 STEWART, W L Virginia Electric & Power Co 83/06/07 DENTON, H R
 Office of Nuclear Reactor Regulation, Director CLARK, R A
 Operating Reactors Branch 3 2pp, 18860 031 24X
 Fiche 50-338, 83/06/07, 8306160405

8306160249 Suppl to application for amend to Licenses NPF-4 & NPF-7,
 providing Tech Specs for NUREG-0737, Item II B 1, "Reactor
 Vessel Head Vent." No addl license amend fee required
 STEWART, W L Virginia Electric & Power Co 83/06/09 DENTON, H R
 Office of Nuclear Reactor Regulation, Director CLARK, R A
 Operating Reactors Branch 3 2pp 18861 211 24X
 Fiche 50-338, 83/06/09, 8306160249

DOCKETED ITEMS

--8306160266 Tech Specs re NUREG-0737, Item 11 B 1, "Reactor Vessel Head Vent." Discussion of proposed Tech Spec change also encl
* Virginia Electric & Power Co. 83/06/09 11pp 18861 214 24X
Fiche 50-338, 83/06/09, 8306160249

8306270214 Forwards addl info re 820820 application for amend to Licenses NPF-4 & NPF-7, allowing installation & use of neutron absorber spent fuel storage racks in pool, per NRC request
STEWART, W. L. Virginia Electric & Power Co. 83/06/16 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3 5pp 18988 036 24X
Fiche 50-338, 83/06/16, 8306270214

8306300240 Forwards revised environ qualification master list, originally submitted by 830520 response to 10CFR50, Paragraph 50.49(g) re environ qualification of safety-related electrical equipment.
STEWART, W. L. Virginia Electric & Power Co. 83/06/22 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3 5pp 19122 295 24X
Fiche 50-338, 83/06/22, 8306300240

8306300096 Advises of potential source of operator error resulting from Hagan process controller mod. Design change will be instituted to eliminate "inverse acting" feature of controller. Mod will be performed during refueling outage.
STEWART, W. L. Virginia Electric & Power Co. 83/06/27 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3 4pp 19121 036 24X
Fiche 50-338, 83/06/27, 8306300096

G Inspection reports, IE Bulletins & correspondence

8306140556 Confirms mgt meeting on 830217 in Richmond, VA to review results of first phase of annual appraisal of regulatory performance. Proposed meeting agenda encl.
LEWIS, R. C. Division of Project & Resident Programs 83/02/08
STEWART, W. L. Virginia Electric & Power Co. 3pp 18834 217 24X
Fiche 50-000, 83/02/08, 8306140556

8306140608 Forwards IE Insp Repts 50-338/83-08 & 50-339/83-08 on 830306-0405 No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs 83/05/17
STEWART, W. L. Virginia Electric & Power Co. 2pp 18834 341 24X
Fiche 50-338, 83/05/17, 8306140608

--8306140647 IE Insp Repts 50-338/83-08 & 50-339/83-08 on 830306-0405 No noncompliance noted. Major areas inspected: surveillance & maint activities, LERs, followup of previously identified items, IE bulletin followup & plant operations.
SHYMLUCK, H. B. Region 2, Office of Director. JULIAN, C. Division of Project & Resident Programs. 83/05/16 8pp 18834 345 24X
Fiche 50-338, 83/05/17, 8306140648

8306140641 Forwards IE Insp Repts 50-338/83-10 & 50-339/83-10 on 830411-14 & 21-22 No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs 83/05/17
STEWART, W. L. Virginia Electric & Power Co. 2pp 18833 273 24X
Fiche 50-338, 83/05/17, 8306140641

--8306140652 IE Insp Repts 50-338/83-10 & 50-339/83-10 on 830411-14 & 21-22 No noncompliance noted. Major areas inspected: inservice insp data review & evaluation & observation of steam generator tube eddy current insp.
ECONOMOS, N. Region 2, Office of Director. BLAKE, J. J. Division of Engineering & Radiological Safety Programs. 83/05/05 9pp 18833 275 24X
Fiche 50-338, 83/05/17, 8306140641

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Wall Logging Device." Svc list encl.
TAYLOR, J. M. Division of Safeguards & Inspection Programs (Post 830103). 83/05/26 Consolidated Edison Co. of New York, Inc. 125pp 18831 043 24X
Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/26 Consolidated Edison Co. of New York, Inc. 115pp 18732 085 24X
Fiche 50-000, 83/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/31 Consolidated Edison Co. of New York, Inc. 116pp 18732 208 24X
Fiche 50-000, 83/05/31, 8305110461

8306290331 Forwards response to IE Bulletin 83-08, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators." Svc list encl.
STEWART, W. L. Virginia Electric & Power Co. 83/06/08 O'REILLY, J. P. Region 2, Office of Director 3pp 19055 303 24X
Fiche 50-000, 83/06/08, 8306290331

8305110444 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/09 Consolidated Edison Co. of New York, Inc. 119pp 18830 280 24X
Fiche 50-000, 83/06/09, 8305110444

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/13 Consolidated Edison Co. of New York, Inc. 118pp 18920 225 24X
Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/13 Consolidated Edison Co. of New York, Inc. 243pp 18921 001 24X
Fiche 50-000, 83/06/13, 8306090010

8306290383 Ack receipt of 830527 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-338/82-25 & 50-339/82-25.
LEWIS, R. C. Division of Project & Resident Programs 83/06/17
STEWART, W. L. Virginia Electric & Power Co. 1p 19055 297 24X
Fiche 50-338, 83/06/17, 8306290383

--8306290387 Forwards response to NRC 820806 ltr re violations noted in IE Insp Repts 50-338/82-25 & 50-339/82-25. Corrective actions procedure w/valve lineup sheet & sys sketch provided. Personnel surveyed to identify necessary controls.
STEWART, W. L. Virginia Electric & Power Co. 83/05/27 O'REILLY, J. P. Region 2, Office of Director 5pp 19055 298 24X
Fiche 50-338, 83/06/17, 8306290383

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/22 Consolidated Edison Co. of New York, Inc. 115pp 19021 179 24X
Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18997 007 24X
Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/23 Consolidated Edison Co. of New York, Inc. 116pp 18996 242 24X
Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/24 Consolidated Edison Co. of New York, Inc. 116pp 19046 297 24X
Fiche 50-000, 83/06/24, 8305110483

R Periodic operating reports & related correspondence

8306020092 Monthly operating repts for Mar 1983 W/830414 ltr
STEWART, W. L., SCHMITENDORF, G. Virginia Electric & Power Co. 83/04/05 10pp 18591 177 24X
Fiche 50-338, 83/04/05, 8306020092

8306160532 Monthly operating repts for Apr 1983 W/830513 ltr
SCHMITENDORF, G. Virginia Electric & Power Co. 83/05/02 HALLER, N. M. Office of Resource Management, Director 10pp 18864 034 24X
Fiche 50-338, 83/05/02, 8306160532

S Reportable occurrences, LERs & related correspondence

8306070281 LER 83-028/03L-O on 830507, inside containment recirculation spray pump 1-RB-P-18 tripped during surveillance testing. Caused by faulty B phase overcurrent device in breaker. Replacement breaker installed W/830525 ltr.
HARRELL, E. W. Virginia Electric & Power Co. 83/05/25 O'REILLY, J. P. Region 2, Office of Director 4pp 18741 101 24X
Fiche 50-338, 83/05/25, 8306070281

DOCKETED ITEMS

195

8306070173 LER 83-029/03L-0 on 830509, following rapid rampdown from 100% to 4% power, I-131 dose equivalent exceeded 1.0 uCi/g. Caused by unidentified fuel element defect worsened by post-rampdown conditions. Sampling increased W/830526 ltr. HARRELL, E W Virginia Electric & Power Co 83/05/26 O'REILLY, J P Region 2, Office of Director App 18736 333 24X Fiche 50-338, 83/05/26, 8306070173

8306090137 LER 83-017/03L-0 on 830516, while in Mode 1, individual rod position indication for control bank B rod D-10 deviated from group demand position. Caused by detector & signal conditioning card drift W/830601 ltr. HARRELL, E W Virginia Electric & Power Co 83/06/01 O'REILLY, J P Region 2, Office of Director App 18792 254 24X Fiche 50-338, 83/06/01, 8306090137

8306090158 LER 83-027/03L-0 on 830505, one header (42 bottles) of control room bottled air pressurized sys found to have lower than required pressure (2,290 vs 2,300 psig). Probably caused by leakage when compressor malfunctioned W/830601 ltr. HARRELL, E W Virginia Electric & Power Co 83/06/01 O'REILLY, J P Region 2, Office of Director App 18809 199 24X Fiche 50-338, 83/06/01, 8306090158

8306090318 LER 83-030/03L-0 on 830511, containment personnel hatch inner door failed leakage surveillance test. Caused by dirt accumulating on inner door seal during containment entries prior to test. HARRELL, E W Virginia Electric & Power Co 83/06/01 O'REILLY, J P Region 2, Office of Director App 18795 175 24X Fiche 50-338, 83/06/01, 8306090318

8306200232 LER 83-024/03L-0 on 830517, engineering review of steam driven auxiliary feedwater pump periodic tests revealed pump bearing temps not being measured in accordance w/ASME XI IHP requirements W/830609 ltr. HARRELL, E W Virginia Electric & Power Co 83/06/09 O'REILLY, J P Region 2, Office of Director App 18902 331 24X Fiche 50-338, 83/06/09, 8306200232

8306270104 LER 83-040/03L-0 on 830603, w/unit at 100% power, Fire Door S71-19 would not close w/o assistance. Caused by reclosure mechanism out of adjustment. Mechanism readjusted. Design mods to fire door being investigated W/830615 ltr. HARRELL, E W Virginia Electric & Power Co 83/06/15 O'REILLY, J P Region 2, Office of Director App 18988 143 24X Fiche 50-338, 83/06/15, 8306270104

8306270366 LER 83-041/03L-0 on 830606, following reactor trip from 100% power, I-131 dose equivalent exceeded 10 mCi/g. Caused by fuel element defect in reactor core. Accelerated sampling frequency implemented W/830615 ltr. HARRELL, E W Virginia Electric & Power Co 83/06/15 O'REILLY, J P Region 2, Office of Director App 18993 199 24X Fiche 50-338, 83/06/15, 8306270366

8306270430 LER 83-032/03L-0 on 830521, during Mode 1 operation, containment temp rose to greater than 105 F for 30 minutes. Caused by malfunctioning mechanical chiller. Steam jet chiller aligned to containment cooling coils W/830615 ltr. HARRELL, E W Virginia Electric & Power Co 83/06/15 O'REILLY, J P Region 2, Office of Director App 24X Fiche 50-338, 83/06/15, 8306270430

8306280568 LER 83-033/03L-0 on 830523, w/Unit 2 in Mode 5, pressurizer PORV PCV-2458c lifted three times to mitigate RCB pressure transient caused by inadvertent SJ actuation. Caused by inadequate instrumentation procedures W/830615 ltr. HARRELL, E W Virginia Electric & Power Co 83/06/15 O'REILLY, J P Region 2, Office of Director App 19017 314 24X Fiche 50-338, 83/06/15, 8306280568

8306300020 LER 83-035/03L-0 on 830528, following rapid rampdown from 100% to 0% power, I-131 dose equivalent exceeded Tech Spec limit. Level returned to limit within 12 h. Caused by fuel element defect in reactor core W/830621 ltr. HARRELL, E W Virginia Electric & Power Co 83/06/21 O'REILLY, J P Region 2, Office of Director App 19120 230 24X Fiche 50-338, 83/06/21, 8306300020

V Operator Examinations

8306240261 Advises that no reasonable basis exists to reverse denial of application for operator license. Applicant for operator license entitled to request hearing on denial of license. Reapplication permitted as of 830622. BURNS, G O Regional Operations & Enforcement Division 83/06/08 TIBLIS, D B Virginia Electric & Power Co App 18980 144 24X Fiche 50-338, 83/06/08, 8306240261

DOCKET 50-339 NORTH ANNA POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8306080225 Application for amend to Licenses NPF-4 & NPF-7, changing Tech Specs to revise audit frequencies for emergency & security plans to once every 12 months. Rev consistent w/ Generic Ltr 82-23. STEWART, W L Virginia Electric & Power Co 82/11/22 DENTON, H R Office of Nuclear Reactor Regulation, Director App 18771 094 24X Fiche 50-338, 82/11/22, 8306080225

--8306080228 Proposed Tech Spec change revising audit frequencies for emergency & security plans to once every 12 months. * Virginia Electric & Power Co 82/11/22 App 18771 097 24X Fiche 50-338, 82/11/22, 8306080228

8306160399 Clarifies position on App R requirements re fixed fire suppression sys. Installed standpipes, hose rack, portable equipment & Halon 1301 sys provide adequate fire protection. STEWART, W L Virginia Electric & Power Co 83/06/13 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 App 18859 311 24X Fiche 50-338, 83/06/13, 8306160399

G Adjudicatory correspondence

8306150422 Memorandum discussing two issues briefed by applicant, for ASLB. ASLB has jurisdiction to consider health & safety impacts & reasonably foreseeable environmental impacts of transportation of spent fuel from Surry to North Anna. WOLFE, S J, KLINE, J R Atomic Safety and Licensing Board Panel, 83/06/10 App 18847 109 24X Fiche 50-338, 83/06/10, 8306150422

P Operating license stage documents & correspondence

8306080225 Application for amend to Licenses NPF-4 & NPF-7, changing Tech Specs to revise audit frequencies for emergency & security plans to once every 12 months. Rev consistent w/ Generic Ltr 82-23. STEWART, W L Virginia Electric & Power Co 82/11/22 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 App 18771 094 24X Fiche 50-338, 82/11/22, 8306080225

--8306080228 Proposed Tech Spec change revising audit frequencies for emergency & security plans to once every 12 months. * Virginia Electric & Power Co 82/11/22 App 18771 097 24X Fiche 50-338, 82/11/22, 8306080228

8306030067 Forwards synopsis of issues to resolve conformance w/NUREG-0612 re control of heavy loads (Phase I) & draft technical evaluation report. CLARK, R A Operating Reactors Branch 3 83/05/17 STEWART, W L Virginia Electric & Power Co App 18733 211 24X Fiche 50-338, 83/05/17, 8306030067

--8306030070 "Control of Heavy Loads (C-10), Virginia Electric Power Co, North Anna Power Station Units 1 & 2." draft technical evaluation report. BOMBERGER, C R, VOSBURV, F W, SARGENT, I H Franklin Institute/Franklin Research Center NRC-03-81-130, TER-C5506-372/373 DR 83/02/22 NRC - No Detailed Affiliation Given App 18733 224 24X Fiche 50-338, 83/05/17, 8306030067

8306140208 Application for amend to Licenses NPF-4 & NPF-7, adding add'l accident monitoring instrumentation & instrumentation for detection of inadequate core cooling per requirements of NUREG-0737, Items II.F.1 & II.F.2. STEWART, W L Virginia Electric & Power Co 83/06/03 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 App 18841 165 24X Fiche 50-338, 83/06/03, 8306140208

--8306140222 Proposed changes to Tech Specs adding add'l accident monitoring instrumentation & instrumentation for detection of inadequate core cooling per requirements of NUREG-0737, Items II.F.1 & II.F.2. * Virginia Electric & Power Co 83/06/03 App 18841 169 24X Fiche 50-338, 83/06/03, 8306140208

8306150516 Advises of refund of fees re 821217 application to amend Licenses NPF-7 & NPF-4 proposing radiological effluent Tech Spec changes. MILLER, W O License Fee Management Branch 83/06/07 STEWART, W L Virginia Electric & Power Co App 18854 359 24X Fiche 50-338, 83/06/07, 8306150516

DOCKETED ITEMS

8306140405 Responds to 830111 ltr & safety evaluation re possible overvoltage on motor control ctr contactor coils & resolution of motor valve retarding Test results & schedule for overvoltage problem will be submitted by 840131
STEWART, W L Virginia Electric & Power Co 83/06/07 DENTON, H R
Office of Nuclear Reactor Regulation, Director CLARK, R A
Operating Reactors Branch 3 2pp 18860 031 24X
Fiche 50-338, 83/06/07, 8306140405

8306160249 Suppl to application for amend to Licenses NPF-4 & NPF-7, providing Tech Specs for NUREG-0737, Item II B 1, "Reactor Vessel Head Vent" No add'l license amend fee required
STEWART, W L Virginia Electric & Power Co 83/06/09 DENTON, H R
Office of Nuclear Reactor Regulation, Director CLARK, R A
Operating Reactors Branch 3 2pp 18861 211 24X
Fiche 50-338, 83/06/09, 8306160249

--8306160266 Tech Specs re NUREG-0737, Item II B 1, "Reactor Vessel Head Vent" Discussion of proposed Tech Spec change also encl
* Virginia Electric & Power Co. 83/06/09 11pp 18861 214 24X
Fiche 50-338, 83/06/09, 8306160249

8306290296 Discusses status of License Condition 2 C(4)(c) re replacement of wide & narrow range resistance temp detectors in RCB Status of vendor repair, redesign or provisions for obtaining resistance temp detectors requested.
CLARK, R A Operating Reactors Branch 3 83/06/15 STEWART, W L
Virginia Electric & Power Co. 3pp 19046 122 24X
Fiche 50-339, 83/06/15, 8306290296

8306290302 Advises that stipulation & implementation as specified in License Condition 2 C(10) re containment backup overcurrent protection sys complete
CLARK, R A Operating Reactors Branch 3 83/06/15 STEWART, W L
Virginia Electric & Power Co 2pp 19046 125 24X
Fiche 50-339, 83/06/15, 8306290302

8306270214 Forwards add'l info re 820820 application for amend to Licenses NPF-4 & NPF-7, allowing installation & use of neutron absorber spent fuel storage racks in pool, per NRC request.
STEWART, W L Virginia Electric & Power Co 83/06/16 DENTON, H R
Office of Nuclear Reactor Regulation, Director CLARK, R A
Operating Reactors Branch 3 5pp 18988 036 24X
Fiche 50-338, 83/06/16, 8306270214

8306300240 Forwards revised environ qualification master list, originally submitted by 830820 response to 10CFR50, Paragraph 50.47(g) re environ qualification of safety-related electrical equipment.
STEWART, W L Virginia Electric & Power Co 83/06/22 DENTON, H R
Office of Nuclear Reactor Regulation, Director CLARK, R A
Operating Reactors Branch 3 3pp 19122 295 24X
Fiche 50-338, 83/06/22, 8306300240

8306300096 Advises of potential source of operator error resulting from Hagan process controller mod Design change will instituted to eliminate "inverse acting" feature of controller Mod will be performed during refueling outage
STEWART, W L Virginia Electric & Power Co 83/06/27 DENTON, H R
Office of Nuclear Reactor Regulation, Director CLARK, R A
Operating Reactors Branch 3 4pp 19121 036 24X
Fiche 50-338, 83/06/27, 8306300096

0. Inspection reports, IE Bulletins & correspondence

8306140556 Confirms mgt meeting on 830217 in Richmond, VA to review results of first phase of annual appraisal of regulatory performance Proposed meeting agenda encl.
LEWIS, R C Division of Project & Resident Programs, 83/02/08
STEWART, W L Virginia Electric & Power Co 3pp 18834 217 24X
Fiche 50-000, 83/02/08, 8306140556

8306140608 Forwards IE Insp Repts 50-338/83-08 & 50-339/83-08 on 830306-0405 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/05/17
STEWART, W L Virginia Electric & Power Co 2pp 18834 341 24X
Fiche 50-338, 83/05/17, 8306140608

--8306140647 IE Insp Repts 50-338/83-08 & 50-339/83-08 on 830306-0405, No noncompliance noted. Major areas inspected surveillance & maint activities, LERs, followup of previously identified items, IE bulletin followup & plant operations.
SHYMLUCK, M B Region 2, Office of Director, JULIAN, C Division of Project & Resident Programs 83/05/16 8pp 18834 343 24X
Fiche 50-338, 83/05/17, 8306140608

8306140641 Forwards IE Insp Repts 50-338/83-10 & 50-339/83-10 on 830411-14 & 21-22, No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/05/17
STEWART, W L Virginia Electric & Power Co. 2pp 18833 273 24X
Fiche 50-338, 83/05/17, 8306140641

--8306140652 IE Insp Repts 50-338/83-10 & 50-339/83-10 on 830411-14 & 21-22 No noncompliance noted Major areas inspected inservice insp data review & evaluation & observation of steam generator tube eddy current insp
ECONOMOS, N Region 2, Office of Director BLAKE, J J Division of Engineering & Radiological Safety Programs 83/05/05 9pp
18833 275 24X Fiche 50-338, 83/05/17, 8306140641

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 118pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306290331 Forwards response to IE Bulletin 83-08, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators" Sorry has no valves in emergency diesel generator cooling sys Raw cooling water sys not used at North Anna
STEWART, W L Virginia Electric & Power Co 83/06/08 O'REILLY, J P
Region 2, Office of Director 3pp 19055 303 24X
Fiche 50-000, 83/06/08, 8306290331

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8306290383 Ack receipt of 83052/ ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-338/82-25 & 50-339/82-25
LEWIS, R C Division of Project & Resident Programs 83/06/17
STEWART, W L Virginia Electric & Power Co 1p 19055 297 24X
Fiche 50-338, 83/06/17, 8306290383

--8306290387 Forwards response to NRC 820806 ltr re violations noted in IE Insp Repts 50-338/82-25 & 50-339/82-25 Corrective actions procedure w/valve lineup sheet & sys sketch provided Personnel surveyed to identify necessary controls
STEWART, W L Virginia Electric & Power Co 83/05/27 O'REILLY, J P Region 2, Office of Director 5pp 19055 298 24X
Fiche 50-338, 83/06/17, 8306290383

8306290086 Advises that requirements of license Condition 2 C(17) re low pressure turbine inservice insp met Rept requested re identification of cause of low pressure turbine disc cracking
CLARK, R A Operating Reactors Branch 3 83/06/20 STEWART, W L
Virginia Electric & Power Co 3pp 19046 170 24X
Fiche 50-339, 83/06/20, 8306290086

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 118pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Activation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

DOCKETED ITEMS

197

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000,83/06/23,8305110479

8305110483 IE Info Notice 83-42, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000,83/06/24,8305110483

R Periodic operating reports & related correspondence

8306020092 Monthly operating repts for Mar 1983 W/830414 ltr
STEWART, W L, SCHMITENDORF, G Virginia Electric & Power Co
83/04/05 10pp 18671 177 24X Fiche 50-338,83/04/05,8306020092

8306160532 Monthly operating repts for Apr 1983 W/830513 ltr
SCHMITENDORF, G Virginia Electric & Power Co 83/05/02
HALLER, M M Office of Resource Management, Director 10pp
18844 034 24X Fiche 50-338,83/05/02,8306160532

S Reportable occurrences, LERs & related correspondence

8306090314 LER 83-039/03L-0 on 830513, train B solid-state protection sys undervoltage output board found failed during channel functional test; rendering trip function inoperable Cause not stated W/830601 ltr
HARRELL, E W Virginia Electric & Power Co 83/05/13 O'REILLY, J P
Region 2, Office of Director 2pp 10795 228 24X
Fiche 50-339,83/05/13,8306090314

8306070276 LER 83-037/03L-0 on 830602, containment particulate (RM-259) & gaseous (RM-260) activity monitors found isolated w/ containment purge & exhaust sys in operation Caused by failure to reopen manual isolation valve W/830525 ltr
HARRELL, E W Virginia Electric & Power Co 83/05/25 O'REILLY, J P
Region 2, Office of Director 4pp 10746 138 24X
Fiche 50-339,83/05/25,8306070276

8306070249 LER 83-038/03L-0 on 830503, suction to RHR pump B lost while transferring water from RCS to refueling water storage tank via refueling purification sys Caused by pumping RCS below established operating limit RCS refilled W/830526 ltr
HARRELL, E W Virginia Electric & Power Co 83/05/26 O'REILLY, J P
Region 2, Office of Director 3pp 10740 325 24X
Fiche 50-339,83/05/26,8306070249

8306070148 Deficiency rept re narrow range resistance temp detectors installed to meet license condition failing to operate Cause under investigation Detectors replaced Testing modified until design revised Also reportable per Part 21
STEWART, W L Virginia Electric & Power Co 83/05/27 DENTON, H R
Office of Nuclear Reactor Regulation, Director CLARK, R A
Operating Reactors Branch 3 2pp 18746 266 24X
Fiche 50-339,83/05/27,8306070148

8306200114 LER 83-040/03L-0 on 830518, during refueling outage, Type C tests revealed that 17 containment isolation valves exceeded total allowable leakage Caused by dirt or debris on seating surfaces Seats cleaned, inspected & repaired W/830609 ltr
HARRELL, E W Virginia Electric & Power Co 83/06/09 O'REILLY, J P
Region 2, Office of Director 3pp 10703 232 24X
Fiche 50-339,83/06/09,8306200114

8306200207 LER 83-033/03L-0 on 830515, pressure in nitrogen supply tank B for pressurizer PORV (PCV-2455C) dropped below min pressure required Caused by downstream nitrogen supply to PORV relief valve lifting Regulators reset W/830609 ltr
HARRELL, E W Virginia Electric & Power Co 83/06/09 O'REILLY, J P
Region 2, Office of Director 3pp 10903 215 24X
Fiche 50-339,83/06/09,8306200207

8306270142 LER 83-046/03L-0 on 830527-29, 31 & 0614 & 22, individual rod position indicators deviated from group demand position Caused by instrument drift Indicator channels recalibr W/830615 ltr
HARRELL, E W Virginia Electric & Power Co 83/06/15 O'REILLY, J P
Region 2, Office of Director 2pp 18988 034 24X
Fiche 50-339,83/06/15,8306270142

8306270183 LER 83-041/03L-0 on 830517, two containment isolation trip valves failed Cause undetermined Broken plunger spring found on one valve. Stem assembly on TV-8S-206A & valve TV-8S-203A replaced W/830615 ltr
HARRELL, E W Virginia Electric & Power Co 83/06/15 O'REILLY, J P
Region 2, Office of Director 3pp 18991 341 24X
Fiche 50-339,83/06/15,8306270183

8306270316 LER 83-042/03L-0 on 830522, w/unit in Mode 4, RCS unidentified leakage exceeded Tech Spec 4 & 2 limit Caused by shaft sleeve gasket failure on RHR pump A No cause determined Mechanical seal & gasket replaced W/830615 ltr
HARRELL, E W Virginia Electric & Power Co 83/06/15 O'REILLY, J P
Region 2, Office of Director 2pp 18996 220 24X
Fiche 50-339,83/06/15,8306270316

8306230248 PNO-11-83-049 on 830616, licensee shut reactor down in compliance w/plant operating requirements because one of two emergency power diesel generators was inoperable Caused by cooling water leak into cylinders
JULIAN, C A, VERRELLI, D M Region 2, Office of Director 83/06/17
2pp 18945 228 24X Fiche 50-339,83/06/17,8306230248

V Operator Examinations

8306240261 Advises that no reasonable basis exists to reverse denial of application for operator license Applicant for operator license entitled to request hearing on denial of license Reapplication permitted as of 830622
BURNS, S G Regional Operations & Enforcement Division 83/06/08
TIBLIS, D B Virginia Electric & Power Co 2pp 18980 144, 24X
Fiche 50-338,83/06/08,8306240261

DOCKET 50-341 ENRICO FERMI ATOMIC POWER PLANT, UNIT 2

A Application/construction stage documents & correspondence

8306200295 FOIA request for eight categories of documents re Facility, JOHNSTON, M M Affiliation Unknown, 83/04/11 Division of Rules and Records 2pp 18920 222 24X Fiche 50-341,83/04/11,8306200295

8306200299 Partial response to FOIA request for eight categories of documents re Facility Copies of listed documents will be provided NUREG available from NTIS
FELTON, J M Division of Rules and Records 83/05/04 JOHNSTON, M M
Affiliation Unknown 1p 18920 224 24X Fiche 50-341,83/05/04,8306200299

8306030171 Submits response to telcon request for addl info re low-low set design & analysis Limiting operational transient for subsequent safety relief valve actuation is fast MSIV closure
TAUBER, H Detroit Edison Co. 83/05/26 YOUNGBLOOD, B J Licensing Branch 1 3pp 18703 324 24X Fiche 50-341,83/05/26,8306030171

8306010168 Forwards Amend 48 to amended & substituted OL application, consisting of Amend 48 to FSAR
LANDGRAFF, L C LeBeuf, Lamb, Leiby & MacRae LANDGRAFF, L C Detroit Edison Co 83/05/27 DENTON, H Office of Nuclear Reactor Regulation, Director 1p 18679 019 24X Fiche 50-341,83/05/27,8306010168,

--8306010174 Amend 48 to amended & substituted OL application, consisting of Amend 48 to FSAR
HEIDEL, C M Detroit Edison Co 83/05/23 1p 18679 020 24X
Fiche 50-341,83/05/27,8306010168

8306080435 Notification of 830615 meeting w/util in Bethesda, MD to discuss independent design verification program
LYNCH, M D Licensing Branch 1 83/05/27, YOUNGBLOOD, B J
Licensing Branch 1 3pp 18792 194 24X Fiche 50-341,83/05/27,8306080435

8306140614 Forwards Certificate of Svc for Amend 48 to amended & substituted application for licenses
MATERB, B R Detroit Edison Co 83/06/07 Office of Nuclear Reactor Regulation, Director 3pp 18837 015 24X
Fiche 50-341,83/06/07,8306140614

8306160357 Forwards "Enrico Fermi Atomic Power Plant, Unit 2, Plant-Unique Analysis Rept for Torus Attached Piping & Suppression Chamber Penetrations " Submittal responds to 820526 ltr & SER (NUREG-0798) requirements
TAUBER, H Detroit Edison Co 83/06/10, YOUNGBLOOD, B J, Licensing Branch 1 2pp 18858 247 24X Fiche 50-341,83/06/10,8306160357

--8306160366 Rev D to "Enrico Fermi Atomic Power Plant, Unit 2, Plant-Unique Analysis Rept for Torus Attached Piping & Suppression Chamber Penetrations " HIGGINSBOTHAM, A, YOSHIDA, D K NUTECH Engineers, Inc. DET-19-076-6
R00 83/06/30 192pp 18858 249 24X Fiche 50-341,83/06/10,8306160357

8306220106 Forwards request for info to complete review of Tech Spec applications re methodology for establishing setpoints for reactor protection & ESF instrumentation. Methodology should be submitted by 831230
YOUNGBLOOD, B J, Licensing Branch 1, 83/06/14 TAUBER, H Detroit Edison Co 3pp 18977 340 24X Fiche 50-341,83/06/14,8306220106

DOCKETED ITEMS

8306280438 Confirms that scheduled fuel load date revised to 831230
Continued cooperation in resolving outstanding items
requested
TAUBER, H Detroit Edison Co 83/06/22 YOUNGBLOOD, B J Licensing
Branch 1 1p 19018 302 24X Fiche 50-341, 83/06/22, 8306280438

8306290142 Requests rerouting of cables & analysis of installation of
Class IE equipment to satisfy FSAR commitments re design
criteria for standby liquid control sys
YOUNGBLOOD, B J Licensing Branch 1 83/06/22 TAUBER, H Detroit
Edison Co 3pp 19046 247 24X Fiche 50-341, 83/06/22, 8306290142

E NRC Safety Evaluation Report (SER), supp's & correspondence

8306160357 Forwards "Enrico Fermi Atomic Power Plant, Unit 2,
Plant-Unique Analysis Rept for Torus Attached Piping &
Suppression Chamber Penetrations " Submittal responds to
820526 ltr & SER (NUREG-0798) requirements
TAUBER, H Detroit Edison Co 83/06/10 YOUNGBLOOD, B J Licensing
Branch 1 2pp 18858 247 24X Fiche 50-341, 83/06/10, 8306160357

--8306160366 Rev 0 to "Enrico Fermi Atomic Power Plant, Unit 2,
Plant-Unique Analysis Rept for Torus Attached Piping &
Suppression Chamber Penetrations "
HIGGINS, A, YOSHIDA, D K NUTECH Engineers, Inc DET-19-076-6
R00 83/06/30 192pp 18858 249 24X Fiche 50-341, 83/06/10,
8306160357.

F. Security, medical, emergency & fire protection plans

8306240266 Responds to request for info re procedures for consideration
of Monroe County, MI 2.206 petition re offsite emergency
planning issues. Relevant submittals will be considered in
decisionmaking process
CRY, K D Regional Operations & Enforcement Division 83/03/08
MINOCK, J R Minock, J 5pp 18980 103 24X Fiche 50-341, 83/03/08,
8306240266

8306010321 Notification of location & date change for 830512 meeting
w/utl in Bethesda, MD to discuss fire protection of safety-
related cables Date changed to 830614
LYNCH, M D Licensing Branch 1 83/05/06 YOUNGBLOOD, B J
Licensing Branch 1 3pp 18696 070 24X Fiche 50-341, 83/05/06,
8306010321

8306100210 Forwards IE Insp Rept 50-341/83-11 on 830506 No
noncompliance noted Insp performed to determine util
readiness for preoperational emergency preparedness
appraisal
HIND, J A Division of Radiological & Materials Safety Programs
83/05/20 WELLS, D A Detroit Edison Co 2pp 18805 288 24X
Fiche 50-341, 83/05/20, 8306100210

--8306100212 IE Insp Rept 50-341/83-11 on 830506 No noncompliance noted
Major areas inspected emergency preparedness, including
implementing procedures
PATTERSON, J P, PAPERIELLO, C J, AXELSON, W Region 3, Office of
Director 83/05/19 4pp 18805 289 24X Fiche 50-341, 83/05/20,
8306100210

8306300053 Forwards IE Insp Rept 50-341/83-12 on 830318, 21 & 0510-13 &
notice of violation
LITTLE, W B Region 3, Office of Director 83/06/16 WELLS, D A
Detroit Edison Co 2pp 19120 292 24X Fiche 50-341, 83/06/16,
8306300053

--8306300061 Notice of violation from insp on 830318, 21 & 0510-13
LITTLE, W B Region 3, Office of Director 83/06/16 2pp,
19120 294 24X Fiche 50-341, 83/06/16, 8306300053

--8306300067 IE Insp Rept 50-341/83-12 on 830318, 21 & 0510-13
Noncompliance noted, failure to control procurement of
mats-fire doors
MAURA, F A, RANNEY, C B, ULIE, J H Region 3, Office of Director
83/06/16 7pp 19120 296 24X Fiche 50-341, 83/06/16, 8306300053

8306280385 Responds to Generic Ltr 82-33 (NUREG-0737, Suppl 1) re
requirements for emergency response capability Proposed
completion dates encl
TAUBER, H Detroit Edison Co 83/06/23 YOUNGBLOOD, B J Licensing
Branch 1 2pp 19018 026 24X Fiche 50-341, 83/06/23, 8306280385.

G Adjudicatory correspondence

8306240266 Responds to request for info re procedures for consideration
of Monroe County, MI 2.206 petition re offsite emergency
planning issues. Relevant submittals will be considered in
decisionmaking process
CRY, K D Regional Operations & Enforcement Division 83/03/08
MINOCK, J R Minock, J 5pp 18980 103 24X Fiche 50-341, 83/03/08,
8306240266.

8306060276 Decision ALAB-730, affirming AFD 821029 Initial Decision
LBP-82-96, authorizing DL issuance. No substantial reason
exists why asserted significance of facts long available
should not have been raised earlier
SNOEMAKER, C J Atomic Safety and Licensing Appeal Panel 83/06/02
25pp 18729 001 24X Fiche 50-341, 83/06/02, 8306060276

8306270218 Petition for review of ASLAP 830602 decision affirming ASLH
821029 decision authorizing issuance of full-power DL Monroe
County does not have radiological emergency response plan &
will not implement draft Certificate of Svc encl
MINOCK, J R Citizens for Energy & Employment MINOCK, J R Minock,
J 83/06/22 Commissioners 8pp 18991 225 24X
Fiche 50-341, 83/06/22, 8306270218

K Utility Final Safety Analysis Report (FSAR) & amends

8306010168 Forwards Amend 4B to amended & substituted DL application,
consisting of Amend 4B to FSAR
LANDGRAF, L C Landgraf, Lamb, Leib & MacRae LANDGRAF, L C Detroit
Edison Co 83/05/27 DENTON, H Office of Nuclear Reactor
Regulation, Director 1p 18679 019 24X Fiche 50-341, 83/05/27,
8306010168

--8306010174 Amend 4B to amended & substituted DL application, consisting
of Amend 4B to FSAR
HEIDEL, C M Detroit Edison Co 83/05/23 1p 18679 020 24X
Fiche 50-341, 83/05/27, 8306010168

--8306010178 Amend 4B to FSAR
* Detroit Edison Co 83/05/31 255pp 18679 021 24X
Fiche 50-341, 83/05/27, 8306010168

G Inspection reports, IE Bulletins & correspondence

8306100210 Forwards IE Insp Rept 50-341/83-11 on 830506 No
noncompliance noted Insp performed to determine util
readiness for preoperational emergency preparedness
appraisal
HIND, J A Division of Radiological & Materials Safety Programs
83/05/20 WELLS, D A Detroit Edison Co 2pp 18805 288 24X
Fiche 50-341, 83/05/20, 8306100210

--8306100212 IE Insp Rept 50-341/83-11 on 830506 No noncompliance noted
Major areas inspected emergency preparedness, including
implementing procedures
PATTERSON, J P, PAPERIELLO, C J, AXELSON, W Region 3, Office of
Director 83/05/19 4pp 18805 289 24X Fiche 50-341, 83/05/20,
8306100210

8306210291 Forwards IE Insp Rept 50-341/83-09 on 830503-06 No
noncompliance noted
KNOPF, R C Region 3, Office of Director 83/05/23 WELLS, D A
Detroit Edison Co 2pp 18915 127 24X Fiche 50-341, 83/05/23,
8306210291

--8306210298 IE Insp Rept 50-341/83-09 on 830503-06 No noncompliance
noted Major areas inspected followup on IE bulletins &
circulars & 10CFR50 55(e) repts
WESCOTT, H M, PARKER, M E, KONKLIN, J E Region 3, Office of
Director 83/05/19 10pp 18915 129 24X Fiche 50-341, 83/05/23,
8306210291

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in
Well Logging Device " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post
830103), 83/05/26 Consolidated Edison Co of New York, Inc
125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New
York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8306170049 Forwards IE Insp Rept 50-341/83-10 on 830301-0430 No
noncompliance noted
KNOPF, R C Region 3, Office of Director 83/05/27 WELLS, D A
Detroit Edison Co 2pp 18882 213 24X Fiche 50-341, 83/05/27,
8306170049

--8306170055 IE Insp Rept 50-341/83-10 on 830301-0430 No noncompliance
noted Major areas inspected followup on previously
identified items, followup on headquarters request &
preoperational test program implementation.
LITTLE, B H, BYRON, P M, KONKLIN, J E Region 3, Office of
Director 83/05/28 8pp 18882 215 24X Fiche 50-341, 83/05/27,
8306170049.

DOCKETED ITEMS

199

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000,83/05/31,8305110461

8306070082 Ack receipt of 830525 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-341/83-05
NORELIUS, C E Division of Project & Resident Programs 83/06/03
WELLS, D A Detroit Edison Co 1p 18739 142 24X Fiche 50-341,83/06/03,8306070082

--8306070085 Responds to NRC 830411 ltr re violations noted in IE Insp Rept 50-341/83-05 Corrective actions Rev 3 of Startup Instruction 4 5 1 01 issued on 830110 mandating use of test change notice for ink changes & page replacements
WELLS, D A Detroit Edison Co 83/05/25 NORELIUS, C E Division of Project & Resident Programs 10pp 18739 143 24X Fiche 50-341,83/06/03,8306070082

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fiche 50-000,83/06/09,8305110464

8306130285 Ack receipt of 830509 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-341/82-21 Final terrestrial monitoring repts for 1979 & 80 close out Open Item 01 in IE Insp Rept 50-341/78-06
PAPERICELLO, C J Region 3, Office of Director 83/06/10 WELLS, D A Detroit Edison Co 1p 18823 303 24X Fiche 50-341,83/06/10,8306130285

--8306130292 Forwards final terrestrial monitoring repts for 1979 & 80 in response to open Item 01 in IE Insp Rept 50-341/78-06 per violation in IE Insp Rept 50-341/82-21 W/a encl
WELLS, D A Detroit Edison Co 83/05/09 HIND, J A Region 3, Office of Director 2pp 18823 304 24X Fiche 50-341,83/06/10,8306130292

8305110470 IE Info Notice 83-30, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 110pp 10720 225 24X Fiche 50-000,83/06/13,8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000,83/06/13,8306090010

8306220016 Ack receipt of 830527 & 0609 ltrs informing NRC of steps taken to correct noncompliance noted in IE Insp Rept 50-341/83-04
SPESBARD, R L Region 3, Office of Director 83/06/15 WELLS, D A Detroit Edison Co 1p 18927 323 24X Fiche 50-341,83/06/15,8306220016

--8306220024 Responds to NRC 830427 ltr re noncompliance noted in IE Insp Rept 50-341/83-04 Corrective actions all power cables now properly tagged & work per Noncompliance Rept 82-043 completed for cable identified on noncompliance
WELLS, D A Detroit Edison Co 83/05/27 SPESBARD, R L Division of Engineering 11pp 18927 324 24X Fiche 50-341,83/06/15,8306220024

--8306220030 Forwards two corrected pages to previous response to noncompliance noted in IE Insp Rept 50-341/83-04 Responses to Items 83-04-04 & 83-04-07 correct, however, statements of noncompliance inadvertently interchanged
WELLS, D A Detroit Edison Co 83/06/09 SPESBARD, R L Division of Engineering 3pp 18927 335 24X Fiche 50-341,83/06/15,8306220030

8306300053 Forwards IE Insp Rept 50-341/83-12 on 830318, 21 & 0510-13 & notice of violation
LITTLE, W S Region 3, Office of Director 83/06/16 WELLS, D A Detroit Edison Co 2pp 19120 292 24X Fiche 50-341,83/06/16,8306300053

--8306300061 Notice of violation from insp on 830318, 21 & 0510-13
LITTLE, W S Region 3, Office of Director 83/06/16 2pp 19120 294 24X Fiche 50-341,83/06/16,8306300061

--8306300067 IE Insp Rept 50-341/83-12 on 830318, 21 & 0510-13 Noncompliance noted failure to control procurement of mats-fire doors
MAURA, F A, RAMSEY, C B, ULIE, J M Region 3, Office of Director, 83/06/16 7pp 19120 296 24X Fiche 50-341,83/06/16,8306300067

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 115pp 19021 179 24X Fiche 50-000,83/06/22,8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Bys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000,83/06/22,8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000,83/06/23,8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000,83/06/24,8305110483

G Reportable occurrences, LERs & related correspondence

8306060187 Deficiency Rept 94 re potential problem w/loose pole piece wedges on four emergency diesel generators Initially reported on 830429 Util requested Deloit Power Bys to review & evaluate circumstances to determine cause
WELLS, D A Detroit Edison Co 83/05/27 KEPPLER, J O Region 3, Office of Director 2pp 18728 271 24X Fiche 50-341,83/05/27,8306060187

8306060245 Final deficiency rept re overpressurizing primary containment pipe penetration bellow Initially reported on 821213 Test program & procedure developed Bellow meet or exceed acceptance criteria
WELLS, D A Detroit Edison Co 83/05/27 KEPPLER, J O Region 3, Office of Director 2pp 18728 281 24X Fiche 50-341,83/05/27,8306060245

8306170233 Final Deficiency Rept 71 re improper assembly of core spray pump P18 E21-01-C001A Initially reported on 820615 Shaft repaired & impeller reinstalled in correct orientation per maint procedure rev
WELLS, D A Detroit Edison Co 83/05/27 KEPPLER, J O Region 3, Office of Director 2pp 18882 320 24X Fiche 50-341,83/05/27,8306170233

8306170419 Final Deficiency Rept 42 re spacing on concrete anchors Initially reported on 810326 Anchor bolts dispositioned Gateway inserts grouted Personnel attended anchor bolt installation training class
WELLS, D A Detroit Edison Co 83/06/03 KEPPLER, J O Region 3, Office of Director 2pp 18879 065 24X Fiche 50-341,83/06/03,8306170419

DOCKET 50-344 TROJAN NUCLEAR PLANT

F Security, medical, emergency & fire protection plans

8306210314 FOIA request for NRC records re security violations & safeguards events at nuclear facilities
GOLDENBERG, O Scripps-Howard Newspapers 83/04/22 FELTON, J M Office of Administration 2pp 18925 198 24X Fiche 50-000,83/04/22,8306210314

8306210306 Partial response to FOIA request for NRC records re security violations & safeguards events at nuclear facilities Repts listed on App A available in PDR Search for addl documents subj to request continuing
FELTON, J M Division of Rules and Records 83/05/16 GOLDENBERG, O Scripps-Howard Newspapers 2pp 18925 196 24X Fiche 50-000,83/05/16,8306210306

8306240308 Forwards "1982 Trojan Nuclear Power Plant Exercise" based on 821118 exercise State & local plans & preparedness adequate
KRIMM, R W Federal Emergency Management Agency 83/05/18 JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 1p 18979 075 24X Fiche 50-344,83/05/18,8306240308

--8306240310 "1982 Trojan Nuclear Power Plant Exercise " * Federal Emergency Management Agency 82/12/10 80pp 18979 076 24X Fiche 50-344,83/05/18,8306240308

DOCKETED ITEMS

8306070015 Forwards IE Insp Rept 50-344/83-11 on 830328-0429 No noncompliance noted
STERNBERG, D M Region 5, Office of Director 83/05/23
WITHERS, B D Portland General Electric Co 2pp 18737 339 24X
Fiche 50-344, 83/05/23, 8306070015

--8306070017 IE Insp Rept 50-344/83-11 on 830328-0429 No noncompliance noted Major areas inspected plant operations, surveillance testing, security, maint, refueling & followup on corrective action to NUREG-0737 items
MALMROG, M H, DODDS, R T Region 5, Office of Director 83/05/17 6pp 18737 341 24X Fiche 50-344, 83/05/23, 8306070015

8306280131 Forwards IE Insp Rept 50-344/83-09 on 830328-0401 No noncompliance noted
NORDEHAU, L R Region 5, Office of Director 83/06/03
WITHERS, B D Portland General Electric Co 2pp 19015 001 24X
Fiche 50-344, 83/06/03, 8306280131

--8306280136 IE Insp Rept 50-344/83-09 on 830328-0401 No noncompliance noted Major areas inspected emergency preparedness plan & implementing procedures
ZURAKOWSKI, P R, SCHUSTER, M D Region 5, Office of Director 83/06/03 11pp 19015 003 24X Fiche 50-344, 83/06/03, 8306280131

8306100146 Forwards IE Safeguards Insp Rept 50-344/83-14 on 830523-26 No noncompliance noted Rept withheld (ref 10CFR2.790)
NORDEHAU, L R Region 5, Office of Director 83/06/06
WITHERS, B D Portland General Electric Co 2pp 18801 176 24X
Fiche 50-344, 83/06/06, 8306100146

8306130415 Requests exemption from 10CFR50.49(c) schedule requirements, per 10CFR50.12, for completion of fire protection mods at fuel & auxiliary bldg 45-ft elevations Deferral requested due to const manpower commitment
WITHERS, B D Portland General Electric Co 83/06/07 CLARK, R A Operating Reactors Branch 3 2pp 18823 136 24X
Fiche 50-344, 83/06/07, 8306130415

8306170148 Ack receipt & provides evaluation of four sets of changes to listed emergency plan implementing procedures Changes do not decrease effectiveness of emergency response planning Review of Procedure EP-1, Rev 7 will be completed in near future
NORDEHAU, L R Region 5, Office of Director 83/06/13 WITHERS, B D Portland General Electric Co 2pp 18878 349 24X
Fiche 50-344, 83/06/13, 8306170148

8306200191 Forwards rev to Security Plan PGE-1017, Rev withheld
WITHERS, B D Portland General Electric Co 83/06/14 Office of Nuclear Reactor Regulation, Director 2pp 18903 196 24X
Fiche 50-344, 83/06/14, 8306200191

8306240256 Requests reconsideration of denial of exemption request in SECY-83-199 re primary emergency operations facility (EOF) Current EOF location found acceptable by Region V, FEMA & state & local govts
WITHERS, B D Portland General Electric Co 83/06/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 18981 315 24X Fiche 50-344, 83/06/17, 8306240256

H General correspondence

8306270394 Requests NRC-specific style guide re util documents to promote consistency & cost effectiveness in producing documents
ROUSE, E A Portland General Electric Co 83/06/20 NRC - No Detailed Affiliation Given 2pp 18994 150 24X
Fiche 50-344, 83/06/20, 8306270394

I. Financial information

8306200207 Forwards Annual Financial Repts 1982
WITHERS, B D Portland General Electric Co 83/06/07 CLARK, R A Operating Reactors Branch 3 1p 18902 154 24X
Fiche 50-344, 83/06/07, 8306200207

--8306200210 Annual Financial Rept 1982
SHORT, R H, LINDBLAD, W J Portland General Electric Co 83/06/07 3pp 18902 155 24X Fiche 50-344, 83/06/07, 8306200207

--8306200213 Annual Financial Rept 1982
FRISBEE, D Pacific Power & Light Co 83/06/07 46pp 18902 196 24X Fiche 50-344, 83/06/07, 8306200207

--8306200215 Annual Financial Rept 1982
TIFFANY, J A Eugene Water & Electricity Board 83/06/07 31pp 18902 243 24X Fiche 50-344, 83/06/07, 8306200207

J Insurance & indemnity information

8306030293 Forwards Endorsement 51 to NLI IA Policy NF-225 & MACIU Policy MF-04
JOHANSEN, E Portland General Electric Co 83/05/05 SALT/MAN, J Office of State Programs, Director 3pp 18703 334 24X
Fiche 50-344, 83/05/05, 8306030293

P Operating license stage documents & correspondence

8306070207 Forwards preliminary Cycle VI radial peaking factor rept as followup to util 830509 ltr No changes expected in final rept
WITHERS, B D Portland General Electric Co 83/05/23 MARTIN, J B Region 5, Office of Director 3pp 18747 051 24X
Fiche 50-344, 83/05/23, 8306070207

8306010316 Advises that performance of load test in excess of 100% of max load unnecessary since crane operator training & safety programs ensure safest possible operations, in response to 801222 ltr re control of heavy loads (NUREG-0612)
WITHERS, B D Portland General Electric Co 83/05/24 EISENHART, D G Division of Licensing 3pp 18682 138 24X Fiche 50-344, 83/05/24, 8306010316

8306060357 Notice of consideration of issuance of amend to License NPF-1 & proposed no significant hazards consideration determination & opportunity for hearing
CLARK, R A Operating Reactors Branch 3 83/05/24 9pp 18751 273 24X Fiche 50-344, 83/05/24, 8306060357

8306060377 Advises that NUREG-0707, Items II F 1 4, "Containment Pressure Monitor, II F 1 5, "Containment Water Level Monitor" & II F 1 6, "Containment Hydrogen Monitor," resolved, per 821217 submittal Safety evaluation encl
CLARK, R A Operating Reactors Branch 3 83/05/24 WITHERS, B D Portland General Electric Co 9pp 18750 338 24X
Fiche 50-344, 83/05/24, 8306060377

8306030241 Advises that revised schedule for submittal of certain core physics data for Cycle 6 core acceptable Data will be available approx 30 days prior to scheduled criticality.
CLARK, R A Operating Reactors Branch 3 83/05/25 WITHERS, B D Portland General Electric Co 2pp 18734 022 24X
Fiche 50-344, 83/05/25, 8306030241

8306080332 Forwards request for addl info re potential mudflows from postulated failure of Spirit Lake blockage info required within 30 days of ltr receipt
CLARK, R A Operating Reactors Branch 3 83/05/27 WITHERS, B D Portland General Electric Co 2pp 18787 339 24X
Fiche 50-344, 83/05/27, 8306080332

8306070207 Forwards License Change Application 93 requesting amend to License NPF-1 Amend modifies balanced flow criteria for HPBI & LPSI lines Amend needed to enter Mode 3 on 830707 Certificate of Svc encl
BROEHL, D J Portland General Electric Co 83/06/03 CLARK, R A Operating Reactors Branch 3 3pp 18747 065 24X
Fiche 50-344, 83/06/03, 8306070207

--8306070211 Application for amend to License NPF-1, modifying balanced flow criteria for high & low pressure safety injection lines
BROEHL, D J Portland General Electric Co 83/06/03 4pp 18747 068 24X Fiche 50-344, 83/06/03, 8306070207

--8306070213 Proposed Tech Spec replacement pages re flow balance testing for ECCS
Portland General Electric Co 83/06/03 2pp 18747 072 24X
Fiche 50-344, 83/06/03, 8306070207

8306170303 Requests extension until 830729 for submittal of QA program Extension due to imminent organizational changes
WITHERS, B D Portland General Electric Co 83/06/03 MARTIN, J B Region 5, Office of Director 1p 18788 215 24X
Fiche 50-344, 83/06/03, 8306170303

8306160255 Notice of consideration of issuance of amend to License NPF-1 & proposed no significant hazards consideration determination
CLARK, R A Operating Reactors Branch 3 83/06/10 6pp 18892 341 24X Fiche 50-344, 83/06/10, 8306160255

8306160645 Requests notice of consideration of issuance of amend to License NPF-1 & proposed no significant hazards consideration determination & opportunity for hearing re snubber testing be published in FR.
CLARK, R A Operating Reactors Branch 3 83/06/10 KREUTZER, P M Operating Reactors Branch 3 2pp 18804 328 24X
Fiche 50-344, 83/06/10, 8306160645

8306280613 Clarification to 830603 application to amend License NPF-1, modifying flow balance of cold leg high-pressure safety injection lines
BROEHL, D. J. Portland General Electric Co 83/06/21 CLARK, R. A
Operating Reactors Branch 3 App 19016 003 24X
Fiche 50-344, 83/06/21, 8306280613

--8306280617 Proposed Tech Spec re flow balance of cold-leg, high-pressure safety injection lines
Portland General Electric Co 83/06/21 1p 19016 007 24X
Fiche 50-344, 83/06/21, 8306280613

4 Inspection reports, IE Bulletins & correspondence

8306100007 Addl response to FOIA request for documents dtd 820101 or after re SALP Forwards App A documents Documents also available in PDR
FELTON, J. M. Division of Rules and Records 83/04/11 CLARK, R. San Francisco Examiner App 18815 252 24X Fiche 50-000, 83/04/11, 8306100007

--8306100014 Submits schedule for Region V SALP Board meetings for 820928-830523
ENGELKEN, R. H. Region 5, Office of Director 82/03/19
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 1p 18815 255 24X Fiche 50-000, 83/04/11, 8306100007

--8306100036 Discusses assignment of SALP coordinators for Reactor Operations Projects Branch facilities Coordinators will be responsible for preparing input data used by board members (in analyzing functional areas Draft note from S Miner encl)
STERNBERG, D. M. Region 5, Office of Director 02/03/24 Region 5, Office of Director 11pp 18815 257 24X
Fiche: 50-000, 83/04/11, 8306100007

8306070075 Forwards IE Insp Rept 50-344/83-10 on 830418-22 No noncompliance noted
STERNBERG, D. M. Region 5, Office of Director 83/05/11
WITHERS, B. D. Portland General Electric Co 2pp 18739 274 24X
Fiche 50-344, 83/05/11, 8306070075

--8306070083 IE Insp Rept 50-344/83-10 on 830418-22 No noncompliance noted. Major areas inspected offsite support staff, QA/QC administration program, followup on previous insp findings & IE bulletin & independent insp
WILLETT, D. J., DODDS, R. T. Region 5, Office of Director 83/05/11 6pp 18739 276 24X Fiche 50-344, 83/05/11, 8306070075

8306070009 Forwards IE Insp Rept 50-344/83-13 on 830509-10 No noncompliance noted Insp conducted in Region V ofc
BOOK, H. E. Region 5, Office of Director 83/05/20 WITHERS, B. D. Portland General Electric Co 2pp 18737 333 24X
Fiche 50-344, 83/05/20, 8306070009

--8306070011 IE Insp Rept 50-344/83-13 on 830509-10 No noncompliance noted Major areas inspected results of split sample of liquid waste obtained during 830117-20 insp Insp conducted in Region V ofc
HAMADA, G. H., WENSLAWSKI, F., BOOK, H. E. Region 5, Office of Director 83/05/20 4pp 18737 335 24X Fiche 50-344, 83/05/20, 8306070009

8306070015 Forwards IE Insp Rept 50-344/83-11 on 830328-0429 No noncompliance noted
STERNBERG, D. M. Region 5, Office of Director 83/05/23
WITHERS, B. D. Portland General Electric Co 2pp 18737 339 24X
Fiche 50-344, 83/05/23, 8306070015

--8306070017 IE Insp Rept 50-344/83-11 on 830328-0429 No noncompliance noted Major areas inspected plant operations, surveillance testing, security, maint, refueling & followup on corrective action to NUREG-0737 items
MALMROS, M. H., DODDS, R. T. Region 5, Office of Director 83/05/17 6pp 18737 341 24X Fiche 50-344, 83/05/23, 8306070015

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Bvc list encl
TAYLOR, J. M. Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Bvc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs" Bvc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306280333 Forwards IE Insp Rept 50-344/83-15 on 830516-20 No noncompliance noted
STERNBERG, D. M. Region 5, Office of Director 83/06/02
WITHERS, B. D. Portland General Electric Co 2pp 19001 223 24X
Fiche 50-344, 83/06/02, 8306280333

--8306280339 IE Insp Rept 50-344/83-15 on 830516-20 No noncompliance noted Major areas inspected inservice insp activities
WAGNER, W. J., ZWETZLO, G. B. Region 5, Office of Director 83/06/01 4pp 19001 225 24X Fiche 50-344, 83/06/02, 8306280333

8306280131 Forwards IE Insp Rept 50-344/83-09 on 830328-0401 No noncompliance noted
NORDERHAUG, L. R. Region 5, Office of Director 83/06/03
WITHERS, B. D. Portland General Electric Co 2pp 19015 001 24X
Fiche 50-344, 83/06/03, 8306280131

--8306280136 IE Insp Rept 50-344/83-09 on 830328-0401 No noncompliance noted Major areas inspected emergency preparedness plan & implementing procedures
ZURAKOWSKI, P. R., SCHUSTER, M. D. Region 5, Office of Director 83/06/03 11pp 19015 003 24X Fiche 50-344, 83/06/03, 8306280131

8306100166 Forwards IE Safeguards Insp Rept 50-344/83-14 on 830523-26. No noncompliance noted Rept withheld (ref IOCFR2 7901).
NORDERHAUG, L. R. Region 5, Office of Director 83/06/06
WITHERS, B. D. Portland General Electric Co 2pp 18801 196 24X
Fiche 50-344, 83/06/06, 8306100166

8306170400 Updates status of plant mods to resolve in-plant communication sys deficiencies identified in response to IE Bulletin 79-18, "Audibility Problem Encountered on Evacuation of Personnel From High - Noise Areas"
WITHERS, B. D. Portland General Electric Co 83/06/07 MARTIN, J. B. Region 5, Office of Director 1p 18879 317 24X
Fiche 50-344, 83/06/07, 8306170400

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations" Bvc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8306280620 Forwards IE Insp Rept 50-344/83-12 on 830502-06 No noncompliance noted
BOOK, H. E. Region 5, Office of Director 83/06/10 WITHERS, B. D. Portland General Electric Co 2pp 19016 008 24X
Fiche: 50-344, 83/06/10, 8306280620

--8306280632 IE Insp Rept 50-344/83-12 on 830502-06 No noncompliance noted Major areas inspected radiation protection program, including procedures, surveys, general employee training, posting & labeling & internal & external exposure control
CILLIS, M., WENSLAWSKI, F. A., BOOK, H. E. Region 5, Office of Director 83/06/10 11pp 19016 010 24X Fiche 50-344, 83/06/10, 8306280620

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards" Bvc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Bvc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8306240316 Forwards invoice covering extraordinary expenses incurred during performance of 1983 IAEA spent fuel insp Transmittal of invoice to IAEA requested for reimbursement
WITHERS, B. D. Portland General Electric Co 83/06/17 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 3pp 18980 154 24X Fiche: 50-344, 83/06/17, 8306240316

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers" Bvc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 115pp 19021 177 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Bys Causing Inoperability of Safety-Related Equipment." Bvc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

DOCKETED ITEMS

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

R. Periodic operating reports & related correspondence

8306020119 Monthly operating rept for Mar 1983 W/830407 ltr
KAMMEYER, D J, YUNDT, C P Portland General Electric Co 83/04/07
6pp 18691 227 24X Fiche 50-344, 83/04/07, 8306020119

8306160392 Monthly operating rept for Apr 1983 W/830506 ltr
KAMMEYER, D J, YUNDT, C P Portland General Electric Co 83/05/06
9pp 18861 143 24X Fiche 50-344, 83/05/06, 8306160392

8306200152 Monthly operating rept for May 1983 W/830613 ltr
KENT, Q J, YUNDT, C P Portland General Electric Co 83/06/13
ADP Systems Development Branch 5pp 18903 113 24X
Fiche 50-344, 83/06/13, 8306200152

B Reportable occurrences, LERs & related correspondence

8306010073 LER 83-002/03L-0 on 830122, after securing auxiliary feedwater pumps following auto-start, two steam generator levels reached low level causing reactor trip. Caused by licensed operator error. W/830516 ltr
BLAIR, Q O, YUNDT, C P Portland General Electric Co 83/05/16
MARTIN, J B Region 5, Office of Director 5pp 18674 091 24X
Fiche 50-344, 83/05/16, 8306010073

8306070071 LER 83-004/03L-0 on 830426, level transmitters LT-517 for steam generator A discovered out of calibr. Caused by instrument drift. Transmitter immediately recalibr & calibr date will be observed to detect degradation. W/830525 ltr
BLAIR, Q O, YUNDT, C P Portland General Electric Co 83/05/25
MARTIN, J B Region 5, Office of Director 3pp 18740 087 24X
Fiche 50-344, 83/05/25, 8306070071

8306070212 RD on 830525, during refueling outage, MSIVs did not shut as required per Tech Specs & SAR. Condition prevented restriction of single steam generator blowdown during certain steam line break accidents w/MSIV failure.
YUNDT, C P Portland General Electric Co 83/05/26 MARTIN, J B
Region 5, Office of Director 1p 18747 045 24X
Fiche 50-344, 83/05/26, 8306070212

8306170317 LER 83-005/03L-0 on 830504, pressurizer level transmitter LT-461 found out of calibr. Caused by instrument drift. Instrument recalibr. W/830606 ltr
BLAIR, Q O, YUNDT, C P Portland General Electric Co 83/06/06
MARTIN, J B Region 5, Office of Director 4pp 18977 064 24X
Fiche 50-344, 83/06/06, 8306170317

8306170193 LER 83-006/03L-0 on 830317, four main steam nonreturn check valves found stuck open. Analysis completed on 830524 showed possible insufficient torque to close valves. Caused by packing induced friction. Packing adjusted. W/830608 ltr.
BLAIR, Q O, YUNDT, C P Portland General Electric Co 83/06/08
MARTIN, J B Region 5, Office of Director 4pp 18882 281 24X
Fiche 50-344, 83/06/08, 8306170193

DOCKET 50-346 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8306090057 Releases public version of Rev 17B to emergency plan supporting procedures rev index
FELTON, J M Division of Rules and Records 83/06/01 Document
Management Branch 1p 18797:348 24X Fiche 50-346, 83/06/01, 8306090057

--8306090060 Public version of Rev 17B to emergency plan supporting procedures rev index, W/830513 ltr receipt form.
* Toledo Edison Co 83/05/13 2pp 18797 349 24X
Fiche 50-346, 83/06/01, 8306090057

8306090281 Releases public version of revised emergency plan supporting procedure administrative memo & rev index
FELTON, J M Division of Rules and Records 83/06/01 Document
Management Branch 1p 18810:035 24X Fiche 50-346, 83/06/01, 8306090281

--8306090283 Public version of Rev 15 to Emergency Plan Supporting Procedure Administrative Memo 39, "Fire Brigade" & Rev 179 to rev index W/830519 ltr
MURRAY, T D Toledo Edison Co 83/05/13 4pp 18810 036 24X
Fiche 50-346, 83/06/01, 8306090281

8306160676 Releases public version of revised emergency plan administrative procedure
FELTON, J M Division of Rules and Records 83/06/01 Document
Management Branch 1p 18876 300 24X Fiche 50-344, 83/06/01, 8306160676

--8306160679 Public version of Rev 13 to Emergency Plan Administrative Procedure AD 1827 10, "Emergency Offsite Dose Estimates" & Rev 177 to rev index W/830311 ltr & receipt form
MURRAY, T D Toledo Edison Co 83/05/05 33pp 18876 301 24X
Fiche 50-346, 83/06/01, 8306160676

8306090370 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/06/06 Document
Management Branch 1p 18814 018 24X Fiche 50-346, 83/06/06, 8306090370

--8306090375 Public version of Rev 4 to Emergency Plan Implementing Procedure EI 1300 07 0, "Technical Support Ctr Activation" & rev index
MURRAY, T D Toledo Edison Co 83/04/07 12pp 18014 019 24X
Fiche 50-346, 83/06/06, 8306090370

8306160686 Releases public version of temporary mod request
FELTON, J M Division of Rules and Records 83/06/06 Document
Management Branch 1p 18876 293 24X Fiche 50-346, 83/06/06, 8306160686

--8306160690 Public version of Temporary Mod Request T-7111 to Emergency Plan Implementing Procedure AD 1827 10, "Offsite Dose Calculations" Rev 174 to rev index encl
DOWNING, G Toledo Edison Co 83/04/12 3pp 18876 294 24X
Fiche 50-346, 83/06/06, 8306160686

8306170075 Forwards Temporary Mod T-7187 to Rev 19 to industrial security plan Mod withheld (ref 10CFR73 21)
CROUSE, R F Toledo Edison Co 83/06/07 Office of Nuclear Reactor Regulation, Director 1p 18878 358 24X
Fiche 50-346, 83/06/07, 8306170075

8306220252 Releases public version of updated emergency plan & revised emergency plan implementing & station supporting procedures
FELTON, J M Division of Rules and Records 83/06/07 Document
Management Branch 1p 18938 001 24X Fiche 50-346, 83/06/07, 8306220252

--8306220257 Forwards public version of updated emergency plan & revised emergency plan implementing & station supporting procedures Receipt form encl
CROUSE, R F Toledo Edison Co 83/05/04 DENISON, H R Office of Nuclear Reactor Regulation, Director 2pp 18938 002 24X
Fiche 50-346, 83/06/07, 8306220252

--8306220260 Public version of updated emergency plan
MURRAY, T Toledo Edison Co 83/05/01 Office of Nuclear Reactor Regulation, Director 316pp 18938 004 24X
Fiche 50-346, 83/06/07, 8306220252

--8306220263 Public version of revised emergency plan implementing & supporting procedures, including Procedures EI 1300 00 re station response, EI 1300 01 re emergency plan activation & EI 1300 02 re unusual events
MURRAY, T Toledo Edison Co 83/05/01 Office of Nuclear Reactor Regulation, Director 424pp 18938 320 24X
Fiche 50-346, 83/06/07, 8306220252

8306130278 Forwards IE Safeguards Insp Rept 50-346/83-08 on 830502-06 & notice of violation. Notice of violation withheld (ref 10CFR73 21)
HIND, J A Division of Radiological & Materials Safety Programs 83/06/10 CROUSE, R F Toledo Edison Co 2pp 18822 189 24X
Fiche 50-346, 83/06/10, 8306130278

--8306130319 IE Safeguards Insp Rept 50-346/83-08 on 830502-06 Noncompliance noted security investigation results not properly documented. Details withheld (ref 10CFR73 21).
PIRTLE, Q L, BELANGER, J L, CREED, J R Region 3, Office of Director 83/06/09 2pp 18822 191 24X Fiche 50-346, 83/06/10, 8306130278

8306210161 Ack receipt of 830920 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-346/83-03.
PAPERIELLO, C J Region 3, Office of Director 83/06/15 CROUSE, R F Toledo Edison Co 1p 18917 003 24X
Fiche 50-346, 83/06/15, 8306210161

DOCKETED ITEMS

203

--8306210170 Responds to NRC 830422 ltr re violations noted in IE Insp Rept 50-346/83-03 Corrective actions procedures revised to emphasize methods available for contacting Ottawa County sheriff & shift supervisor provided with add'l guidance
CROUSE, R P Toledo Edison Co 83/05/20 KEPLER, J Q Region 3, Office of Director 7pp 18917 004 24X Fiche 50-346, 83/06/15, 8306210161

8306270204 Ack receipt of 830516 ltr re emergency planning exercise for May 1983, per IE Insp Rept 50-346/83-07 No violations or deviations noted Response to weaknesses identified in observations over exercise period encl
CROUSE, R P Toledo Edison Co 83/06/21 KEPLER, J Q Region 3, Office of Director 6pp 18991 264 24X Fiche 50-346, 83/06/21, 8306270204

P Operating license stage documents & correspondence

8306030503 Forwards safety evaluation supporting response to TMI Items I A 2 I 4 & II B 2 Requirements satisfied
DEAGAZIO, A Operating Reactors Branch 4 83/05/13 CROUSE, R P Toledo Edison Co 4pp 18747 167 24X Fiche 50-346, 83/05/13, 8306030503

--8209030325 "Improvements in Training & Requalification Programs As Required By TMI Action Items I A 2 I 4 & II B 4 for Davis-Besse Nuclear Power Station," technical evaluation rept
* Science Applications, Inc NRC-03-82-096 GAI-186-029-2B 82/08/31 NRC - No Detailed Affiliation Given 15pp 18747 172 24X Fiche 50-346, 83/05/13, 8306030503

8306150508 Forwards BER supporting 830128 submittal re TMI Action Plan Items II F 1 4, "Containment Pressure Monitor," II F 1 5, "Containment Water Level Monitor," & II F 1 6, "Containment Hydrogen Monitor," Requirements met
STOLZ, J F Operating Reactors Branch 4 83/05/24 CROUSE, R P Toledo Edison Co 2pp 18866 313 24X Fiche 50-346, 83/05/24, 8306150508

--8306150515 Safety evaluation supporting licensee 830128 submittal re NUREG-0737, Items II F 1 4, "Containment Pressure Monitor," II F 1 5, "Containment Water Level Monitor," & II F 1 6, "Containment Hydrogen Monitor," Requirements met.
* Office of Nuclear Reactor Regulation, Director 83/05/24 5pp 18866 315 24X Fiche 50-346, 83/05/24, 8306150908

8306080234 Forwards BER on 810313 revs to seismic reanalysis contained in Amend 30 to License NPF-3 Reva acceptable
STOLZ, J F Operating Reactors Branch 4 83/05/31 CROUSE, R P Toledo Edison Co 2pp 18785 321 24X Fiche 50-346, 83/05/31, 8306080234

--8306080237 Safety evaluation supporting 810313 revs to Amend 30 to License NPF-3 re seismic reanalysis of piping sys & components
* Office of Nuclear Reactor Regulation, Director 83/05/31 8pp 18785 323 24X Fiche 50-346, 83/05/31, 8306080234

8306140703 Forwards request for add'l info re natural circulation cooldown, per Generic Ltr 81-21 Rev to 820127 response requested Demonstration of void formation necessary for demonstrating adequacy of procedures
STOLZ, J F Operating Reactors Branch 4 83/06/01 CROUSE, R P Toledo Edison Co 4pp 18844 358 24X Fiche 50-346, 83/06/01, 8306140703

8306220215 Designates O Leinas as licensing contact to coordinate staff interactions w/B&W Owners Group subcommittees re generic regulatory issues.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 83/06/01 CROUSE, R P Toledo Edison Co CROUSE, R P Babcock & Wilcox Operating Plants Owners Group 5pp 18991 015 24X Fiche 50-346, 83/06/01, 8306220215

8306140377 Forwards revised Table D-1, "Preliminary Stress Level Comparison," showing value of stress concentration factor & higher calculated peak stresses Higher peak stresses do not affect conclusions from 830506 meeting. Meeting summary encl
TAYLOR, J. H Babcock & Wilcox Co 83/06/07 MINER, B NRC - No Detailed Affiliation Given 2pp 18844 001 24X Fiche 50-000, 83/06/07, 8306140377.

8306140500 Forwards responses to 801222 ltr re NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants," Info addresses overhead handling sys for fuel storage pool
CROUSE, R P Toledo Edison Co 83/06/10 STOLZ, J F Operating Reactors Branch 4 142pp 18843 096 24X Fiche 50-346, 83/06/10, 8306140500

8306170027 Advises that 830520 B&W Task Force rept, "Summary Rept of NRC/B&W Owners Group Meeting on Reactor Vessel Internals Bolting 830506, BAW-1784," constitutes basis for continued operation per 830506 presentation
CROUSE, R P Toledo Edison Co 83/06/10 STOLZ, J F Operating Reactors Branch 4 1p 18878 286 24X Fiche 50-346, 83/06/10, 8306170027

8306200393 Application for amend to License NPF-3, revising Tech Spec surveillance test requirements to include flow test to verify normal path availability of auxiliary feedwater to steam generator Class III amend fee encl
CROUSE, R P Toledo Edison Co 83/06/15 STOLZ, J F Operating Reactors Branch 4 4pp 18899 041 24X Fiche 50-346, 83/06/15, 8306200393

--8306200394 Proposed Tech Specs revising surveillance test requirements to include flow test to verify normal path availability of auxiliary feedwater to steam generator
* Toledo Edison Co 83/06/15 2pp 18899 045 24X Fiche 50-346, 83/06/15, 8306200393

8306210026 Responds to 830314 ltr re order requiring completion of TMI Item II F 1 5 on containment water level by 830615
Environ & seismic qualification repts received & under review.
CROUSE, R P Toledo Edison Co 83/06/15 STOLZ, J F Operating Reactors Branch 4 1p 18910 359 24X Fiche 50-346, 83/06/15, 8306210026

8306230259 Forwards Rev O to "Detailed Control Room Design Review (DCRDR) Program Plan for Davis Besse Nuclear Power Plant," in response to NRC B21217 ltr & commitments per util 830415 ltr
CROUSE, R P Toledo Edison Co 83/06/15 STOLZ, J F Operating Reactors Branch 4 1p 18945 021 24X Fiche 50-346, 83/06/15, 8306230259.

--8306230262 Rev O to "Detailed Control Room Design Review (DCRDR) Program Plan for Davis Besse Nuclear Power Plant"
* Toledo Edison Co 83/06/15 50pp 18945 022 24X Fiche 50-346, 83/06/15, 8306230259

Q Inspection reports, IE Bulletins & correspondence

8306270379 Ack receipt of 830324 ltr summarizing IE Enforcement Conference Rept 50-346/83-06 on 830309 Util 830429 ltr formally submits maint & drawing control programs outlined at conference.
CROUSE, R P Toledo Edison Co 83/05/20 NORELIUS, E Division of Project & Resident Programs 1p 18994 154 24X Fiche 50-346, 83/05/20, 8306270379

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Bvc list encl
TAYLOR, J. M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc. 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Bvc list encl
JORDAN, E. L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 119pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460.

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs" Bvc list encl
JORDAN, E. L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461.

8306070155 Ack receipt of 830513 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-346/83-04.
STREETER, J F Region 3, Office of Director 83/06/01 CROUSE, R P Toledo Edison Co 1p 18736 237 24X Fiche 50-346, 83/06/01, 8306070155

--8306070166 Responds to NRC 830427 ltr re violations noted in IE Insp Rept 50-346/83-04 Corrective actions policy of waiving radiological controls training for chemistry & health physics dept personnel rewritten
CROUSE, R P Toledo Edison Co 83/05/13 NORELIUS, C. E Region 3, Office of Director 3pp 18736 238 24X Fiche 50-346, 83/06/01, 8306070155

8306070397 Forwards rev to inservice insp pump & valve program submitted on 800515. Changes reflect results of 830525-26 telcons w/NRC Synopsis of current program changes, relief requests & specific program changes encl
CROUSE, R. P. Toledo Edison Co 83/06/02 STOLZ, J. F. Operating Reactors Branch 4 13pp 18742 003 24X Fiche 50-346, 83/06/02, 8306070397

DOCKETED ITEMS

- 830614044B Responds to IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators." Diesel generators cooled by water supplied from component cooling water sys. Three 14-inch Velan check valves used for testing CROUSE, R.P. Toledo Edison Co. 83/06/02 DEYOUNG, R.C. Office of International Programs, Director. 2pp. 18836 347 24X Fiche 50-346, 83/06/02, 830614044B
- 8306220037 Forwards IE Insp Rept 50-346/83-05 on 830201-0429 & notice of violation Causes of malfunctions should be determined, evaluated & documented prior to returning equipment to normal operating status. NORELIOUS, C.E. Division of Project & Resident Programs. 83/06/07. CROUSE, R.P. Toledo Edison Co. 2pp. 18930 191 24X Fiche: 50-346, 83/06/07, 8306220037
- 8306220041 Notice of violation from insp on 830201-0429 NORELIOUS, C.E. Division of Project & Resident Programs. 83/06/07. 2pp. 18930, 193. 24X Fiche: 50-346, 83/06/07, 8306220037
- 8306220050 IE Insp Rept 50-346/83-05 on 830201-0429 Noncompliance noted: administrative procedures & QA manual did not include controls to prevent procedures from becoming inadequate & followup LER not issued re trip breaker malfunction PEEBLES, T.A., ROQERS, W.O., JACKI, W.J.N. Region 3, Office of Director. 83/06/06. 11pp. 18930, 195. 24X Fiche 50-346, 83/06/07, 8309220037.
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/09. Consolidated Edison Co. of New York, Inc. 119pp. 18830 280 24X Fiche: 50-000, 83/06/09, 8305110464.
- 8306130298 Forwards IE Safeguards Insp Rept 50-346/83-08 on 830502-06 & notice of violation Notice of violation withheld (ref 10CFR73 21). HIND, J.A. Division of Radiological & Materials Safety Programs. 83/06/10. CROUSE, R.P. Toledo Edison Co. 2pp. 18822, 189 24X Fiche: 50-346, 83/06/10, 8306130298
- 8306130319 IE Safeguards Insp Rept 50-346/83-08 on 830502-06 Noncompliance noted: security investigation results not properly documented Details withheld (ref 10CFR73 21). PIRYLE, O.L., BELANGER, J.L., CREED, J.R. Region 3, Office of Director 83/06/09. 2pp. 18822 191 24X Fiche 50-346, 83/06/10, 8306130298.
- 8306230253 Forwards IE Insp Rept 50-346/83-10 on 830504-05 No noncompliance noted. LITTLE, W.B. Region 3, Office of Director 83/06/10. CROUSE, R.P. Toledo Edison Co. 2pp. 18945 219 24X Fiche: 50-346, 83/06/10, 8306230253.
- 8306230255 IE Insp Rept 50-346/83-10 on 830504-05. No noncompliance noted. Major areas inspected: followup of previously identified problem w/containment electrical penetrations MENDEZ, R., WILLIAMS, C.C. Region 3, Office of Director. 83/06/10. 5pp. 18945 221. 24X Fiche: 50-346, 83/06/10, 8306230253.
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/13. Consolidated Edison Co. of New York, Inc. 118pp. 18920 223. 24X Fiche: 50-000, 83/06/13, 8305110470
- 8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/13. Consolidated Edison Co. of New York, Inc. 243pp. 18921 001. 24X Fiche: 50-000, 83/06/13, 8306090010
- 8306300060 Forwards IE Insp Rept 50-346/83-13 on 830502-06 & 16-20 No noncompliance noted. STREYER, J.F. Region 3, Office of Director 83/06/14. CROUSE, R.P. Toledo Edison Co. 2pp. 19120 273. 24X Fiche: 50-346, 83/06/14, 8306300060.
- 8306300063 IE Insp Rept 50-346/83-13 on 830502-06 & 16-20. No noncompliance noted. Major areas inspected: instrument calibr procedures & records, test & measurement equipment procedures & records & nonroutine reporting procedures FARRELL, R.E., HAWKINS, F.C. Region 3, Office of Director. 83/06/14. 4pp. 19120 275. 24X Fiche: 50-346, 83/06/14, 8306300060
- 8306210161 Ack receipt of 830520 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-346/83-03 PAPERIELLO, C.J. Region 3, Office of Director. 83/06/15. CROUSE, R.P. Toledo Edison Co. 1p. 18917 003 24X Fiche: 50-346, 83/06/15, 8306210161.
- 8306210170 Responds to NRC 830422 ltr re violations noted in IE Insp Rept 50-346/83-03 Corrective actions procedures revised to reemphasize methods available for contacting Ottawa County Sheriff & shift supervisor provided with addl guidance CROUSE, R.P. Toledo Edison Co. 83/05/20. KEPPLER, J.O. Region 3, Office of Director 7pp. 18917 004 24X Fiche 50-346, 83/06/15, 8306210161.
- 8306300022 Forwards IE Insp Rept 50-346/83-12 on 830527 No noncompliance noted LITTLE, W.B. Region 3, Office of Director 83/06/17. CROUSE, R.P. Toledo Edison Co. 2pp. 19120 349. 24X Fiche 50-346, 83/06/17, 8306300022
- 8306300029 IE Insp Rept 50-346/83-12 on 830527 No noncompliance noted Major areas inspected implementation of IE Bulletin 79-14 & followup on previously identified items YIN, I.T., DANIELSON, D.H. Region 3, Office of Director 83/06/17 3pp. 19120 351 24X Fiche 50-346, 83/06/17, 8306300022
- 8306300251 Forwards IE Insp Rept 50-346/83-14 on 830524-26 No noncompliance noted LITTLE, W.B. Region 3, Office of Director 83/06/17. CROUSE, R.P. Toledo Edison Co. 2pp. 19119 343 24X Fiche 50-346, 83/06/17, 8306300251
- 8306300252 IE Insp Rept 50-346/83-14 on 830524-26 No noncompliance noted Major areas inspected licensee action on previous insp findings. MENDEZ, R., WILLIAMS, C.C. Region 3, Office of Director 83/06/17 5pp. 19119 345. 24X Fiche 50-346, 83/06/17, 8306300251
- 8306270204 Ack receipt of 830516 ltr re emergency planning exercise for May 1983 per IE Insp Rept 50-346/83-07 No violations or deviations noted. Response to weaknesses identified in observations over exercise period encl. CROUSE, R.P. Toledo Edison Co. 83/06/21. KEPPLER, J.O. Region 3, Office of Director 6pp. 18991 264 24X Fiche 50-346, 83/06/21, 8306270204
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/22. Consolidated Edison Co. of New York, Inc. 118pp. 19021 179 24X Fiche 50-000, 83/06/22, 8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/22. Consolidated Edison Co. of New York, Inc. 120pp. 18997 007 24X Fiche 50-000, 83/06/22, 8305110477
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/23. Consolidated Edison Co. of New York, Inc. 116pp. 18996 242. 24X Fiche: 50-000, 83/06/23, 8305110479
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/24. Consolidated Edison Co. of New York, Inc. 116pp. 19046 297 24X Fiche 50-000, 83/06/24, 8305110483
- 8306300044 Confirms arrangements for rescheduling 830627 meeting, to discuss BALP, to 830712 at Region III ofc NORELIOUS, C.E. Division of Project & Resident Programs. 83/06/24. CROUSE, R.P. Toledo Edison Co. 1p. 19120 222 24X Fiche: 50-346, 83/06/24, 8306300044
- R Periodic operating reports & related correspondence
- 8306020129 Monthly operating rept for Mar 1983 W/830408 ltr BARBOUR, B., MURRAY, T.D. Toledo Edison Co. 83/04/08. HALLER, N. Office of Resource Management, Director 9pp. 18691 246 24X Fiche: 50-346, 83/04/08, 8306020129
- 8306160540 Monthly operating rept for Apr 1983 W/830509 ltr BARBOUR, B., MURRAY, T.D. Toledo Edison Co. 83/05/09. HALLER, N. Office of Management and Program Analysis. 9pp. 18865 051. 24X Fiche: 50-346, 83/05/09, 8306160540
- 8306170276 "May 1983 Wastewater rept" MURRAY, T.D. Toledo Edison Co. 83/06/14. Ohio, State of. 9pp. 18878 259 24X Fiche 50-346, 83/06/14, 8306170276.

S Reportable occurrences, LERs & related correspondence

8306060137 LER 83-027/03L-0 on 830428, valve RC240B would not close w/o repeated signals from control room. Caused by valve operator torquing out due to dirty & improperly lubricated stem. Stem cleaned & torque switch reset W/830526 ltr
MURRAY, T D., LONG, J. Toledo Edison Co. 83/05/26 KEPLER, J Q
Region 3, Office of Director App 18719 016 24X
Fiche 50-346, 83/05/26, 8306060137

8306100124 LER 83-021/03L-0 on 830502, operator found Fuel Handling Access Corridor Door 406 ajar. Caused by failure of closure mechanism. Closure mechanism adjusted to force door closed
WOLFE, R., MURRAY, J D. Toledo Edison Co. 83/05/31 KEPLER, J Q
Region 3, Office of Director App 18802 014 24X
Fiche 50-346, 83/05/31, 8306100124

8306210262 LER 83-022/03L-0 on 830513, determined erratic generator output in response to speed change input on 830413 reportable. Caused by loose connection on electronic governor control box. Terminal screw cross threaded W/830606 ltr
UEBBING, R., RICHTER, L., MURRAY, T D. Toledo Edison Co. 83/06/06 KEPLER, J Q, Region 3, Office of Director App 18915 052 24X
Fiche 50-346, 83/06/06, 8306210262

8306170429 Revised LER 83-002/03X-2 on 830115, 18, 0409, 10 & 0510, RCS dose equivalent I-131 exceeded Tech Spec limit. Caused by slight fission product leakage through fuel cladding. Level of I-131 monitored, W/830607 ltr
RICHTER, L., MURRAY, T D. Toledo Edison Co. 83/06/07 KEPLER, J Q
Region 3, Office of Director App 18879 050 24X
Fiche 50-346, 83/06/07, 8306170429

8306170414 LER 83-023/03L-0 on 830510, 120-volt ac essential bus Y4 lost, resulting in deenergizing reactor protection & safety features. actuation sys Channel 4. Caused by blown fuse in inverter YV4. Power restored to bus, W/830608 ltr
ROHLAND, M., MURRAY, T D. Toledo Edison Co. 83/06/08 KEPLER, J Q
Region 3, Office of Director App 18879 001 24X
Fiche 50-346, 83/06/08, 8306170414

8306170142 LER 83-024/03L-0 on 830511, while starting up from 830510 reactor trip, quadrant power tilt in quadrant Y2 exceeded Tech Spec steady-state limit. Caused by inherent design of B&W NSSB & negative moderator temp coefficient, W/830609 ltr
O'CONNOR, B., MURRAY, T D. Toledo Edison Co. 83/06/09 KEPLER, J Q
Region 3, Office of Director App 18878 307 24X
Fiche 50-346, 83/06/09, 8306170142

8306210084 LER 83-025/03L-0 on 830429, Fire Detection Zone 410 on containment east passage alarmed & could not be reset. Caused by faulty detector string. Corrective action planned during next refueling outage W/830610 ltr
BOYBIAK, M., MURRAY, T D. Toledo Edison Co. 83/06/10 KEPLER, J Q
Region 3, Office of Director App 18911 234 24X
Fiche 50-346, 83/06/10, 8306210084

8306220007 Part 21 rept re adequacy of fittings supplied by Tube-Line Corp. through Capitol Pipe & Steel Products Co. for use on new auxiliary feedwater headers of steam generators. Flanges not heat-treated as required by matl specs
TAYLOR, J H., Babcock & Wilcox Co. 83/06/17 DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement App 18927 354, 24X Fiche 50-000, 83/06/17, 8306220007

DOCKET 50-348 JOSEPH M. FARLEY NUCLEAR PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8306090319 Forwards IE Safeguards Insp Repts 50-348/83-07 & 50-344/83-03 on 830227-0303 & notice of violation, Rept details & notice of violation withheld (ref 10CFR73 21)
LEWIS, R C. Division of Project & Resident Programs, 83/03/23, MCDONALD, R P. Alabama Power Co. 2pp. 18795 112 24X
Fiche 50-348, 83/03/23, 8306090319

--8306090324 IE Safeguards Insp Repts 50-348/83-07 & 50-344/83-05 on 830227-0303 Noncompliance noted. Failure of vital area alarms in access mode to indicate tamper. Details withheld (ref 10CFR73 21).
MOORE, D E. Region 2, Office of Director. MCQUIRE, D R. Division of Emergency Preparedness & Materials Safety, 83/03/23. 1p 18795 114, 24X Fiche 50-348, 83/03/23, 8306090319

8306020570 Comments on NUREG-0737, Item III A.2.1, "Emergency Preparedness, Upgrade Emergency Plans to App E, 10CFR50," Onsite & offsite emergency preparedness adequate. Item closed.
VARGA, B A. Operating Reactors Branch 1, 83/05/24. CLAYTON, F L. Alabama Power Co. 2pp. 18715 066, 24X Fiche 50-348, 83/05/24, 8306020570

8306010332 Forwards IE Safeguards Insp Repts 50-348/83-14 & 50-344/83-12 on 830509-13. No noncompliance noted.
VERRELLI, D. Division of Project & Resident Programs, 83/05/26. MCDONALD, R P. Alabama Power Co. 2pp. 18682 150 24X
Fiche 50-348, 83/05/26, 8306010332

--8306010333 IE Safeguards Insp Repts 50-348/83-14 & 50-344/83-12 on 830507-13. No noncompliance noted. Major areas inspected. site orientation, security organization-mgt, personnel & response. Details withheld (ref 10CFR73 21).
HALL, B L. Region 2, Office of Director. MCQUIRE, D R. Division of Emergency Preparedness & Materials Safety, 83/05/24. 1p 18682 152 24X Fiche 50-348, 83/05/26, 8306010332

8306140645 Forwards IE Insp Repts 50-348/83-11 & 50-344/83-09 on 830418-22. No noncompliance noted.
VERRELLI, D M. Division of Project & Resident Programs, 83/05/26. MCDONALD, R P. Alabama Power Co. 2pp. 18841 242, 24X
Fiche 50-348, 83/05/26, 8306140645

--8306140655 IE Insp Repts 50-348/83-11 & 50-344/83-09 on 830418-22. No noncompliance noted. Major areas inspected. emergency preparedness.
HARSTON, R R. Region 2, Office of Director. JENKINS, G R. Division of Emergency Preparedness & Materials Safety, 83/05/24. 6pp. 18841 244 24X Fiche 50-348, 83/05/26, 8306140645

8306090204 Releases public version of emergency plan administrative procedures.
FELTON, J M. Division of Rules and Records, 83/06/01. Document Management Branch. 1p. 18809 229 24X Fiche 50-348, 83/06/01, 8306090204

--8306090208 Public version of Emergency Plan Administrative Procedure FNP-83-0497, "On-Call Schedule." Schedule will be filed w/Procedure FNP-0-EIP-B, W/830311 ltr
HUDEPETH, J B. Alabama Power Co. 83/05/11. 4pp. 18809 230, 24X
Fiche 50-348, 83/06/01, 8306090204

8306090329 Ack receipt of 830418 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-348/83-07 & 50-344/83-05
LEWIS, R C. Division of Project & Resident Programs, 83/06/06. MCDONALD, R P. Alabama Power Co. 2pp. 18795 070, 24X
Fiche 50-348, 83/06/06, 8306090329

--8306090332 Responds to NRC 830323 ltr re violations noted in IE Safeguards Insp Repts 50-348/83-07 & 50-344/83-05. Corrective actions withheld.
CLAYTON, F L. Alabama Power Co. 83/04/18. LEWIS, R C. Region 2, Office of Director. 1p. 18795 072, 24X Fiche 50-348, 83/06/06, 8306090329

8306160027 Releases public version of revised emergency plan implementing procedure.
FELTON, J M. Division of Rules and Records, 83/06/06. Document Management Branch. 1p. 18872 295 24X Fiche 50-348, 83/06/06, 8306160027

--8306160032 Public version of Rev 11 to Emergency Plan Implementing Procedure FNP-0-EIP-4, "Chemistry & Health Physics Support to Emergency Plan." W/830524 ltr.
HUDEPETH, J B. Alabama Power Co. 83/05/19. 18pp. 18872 296 24X
Fiche 50-348, 83/06/06, 8306160027

8306210363 Releases public version of revised emergency plan implementing procedure.
FELTON, J M. Division of Rules and Records, 83/06/06. Document Management Branch. 1p. 18937 097, 24X Fiche 50-348, 83/06/06, 8306210363

--8306210365 Public version of Rev 12 to Emergency Plan Implementing Procedure FNP-0-EIP-9, "Radiation Exposure Estimation & Classification of Emergencies." Receipt form encl W/830421 ltr.
HUDEPETH, J B. Alabama Power Co. 83/04/14. Office of Nuclear Reactor Regulation, Director. 13pp. 18937 098, 24X
Fiche 50-348, 83/06/06, 8306210363

8306290198 Ack receipt of 830608 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/83-09 & 50-344/83-07
LEWIS, R C. Division of Project & Resident Programs, 83/06/16. MCDONALD, R P. Alabama Power Co. 2pp. 19056 095, 24X
Fiche 50-348, 83/06/16, 8306290198

--8306290207 Responds to NRC 830510 ltr re violations noted in IE Insp Repts 50-348/83-09 & 50-344/83-07. Corrective actions: personnel instructed to close fire doors unless fire watch established & preventive maint program updated.
CLAYTON, F L. Alabama Power Co. 83/06/08. LEWIS, R C. Region 2, Office of Director. 4pp. 19056 097 24X Fiche 50-348, 83/06/16, 8306290198

DOCKETED ITEMS

--8306290222 IE Insp Repts 50-348/83-09 & 50-364/83-07 on 830306-0410
Noncompliance noted: failure to follow calibr & recycle
procedures & Tech Spec requirements for fire doors &
Procedure FNP-1-87P-256 15, Rev 3, inadequate
BRADFORD, H H, RULAND, H H Region 2, Office of Director
CLAYTON, F L Division of Project & Resident Programs 83/05/06
10pp 19056 104, 24X Fiche 50-348, 83/06/16, 8306290198

P. Operating license stage documents & correspondence

8306010331 Submits list of post-trip review procedures to be modified
following review of results of NUREG-0977 (Salem event) &
discussion w/NRC Mods will be made within 30 days
CLAYTON, F L Alabama Power Co. 83/05/24, VARQA, S A Office of
Nuclear Reactor Regulation, Director 1p 18681 278 24X
Fiche 50-348, 83/05/24, 8306010331.

8306020036 Act receipt of 830510 ltr informing NRC of commitment for
resolution of reactor protection sys BS-416 breaker problem
Program being reviewed Responsibility for review of
conclusions transferred to Region II
VARQA, S A Operating Reactors Branch 1 83/05/25, CLAYTON, F L
Alabama Power Co 2pp 18702-324, 24X Fiche 50-348, 83/05/25,
8306020036.

8306030307 Suppl to 821116 application to amend GL adding snubbers
attached to nonsafety-related piping assumed to be operable
for safety-related seismic stress analysis to Tech Spec
snubber tables.
CLAYTON, F L Alabama Power Co. 83/05/27 Office of Nuclear
Reactor Regulation, Director 2pp 18708 280 24X
Fiche 50-348, 83/05/27, 8306030307.

--8306030311 Proposed Tech Spec changes adding snubbers attached to
nonsafety-related piping assumed to be operable for
safety-related seismic stress analysis to snubber tables.
* Alabama Power Co 83/05/27, 40pp 18708 282 24X
Fiche 50-348, 83/05/27, 8306030307

8306060201 Submits status & schedule re design changes, test procedures
& confirmatory life program for DB-416 reactor trip
breakers, per 830510 ltr & 830531 commitment. Maint program
will be modified upon completion of 6-month test program
CLAYTON, F L Alabama Power Co 83/05/31, VARQA, S A Office of
Nuclear Reactor Regulation, Director. 4pp 18727 324 24X
Fiche: 50-348, 83/05/31, 8306060201

8306140610 Requests that until previous date of 830901 for approval of
proposed amend to Tech Spec 3/4.1.3 re movable control
assemblies be advanced to 830715 due to increase in control
rod sys events.
CLAYTON, F L Alabama Power Co. 83/06/03 VARQA, S A Office of
Nuclear Reactor Regulation, Director. 2pp. 18842:077 24X
Fiche: 50-348, 83/06/03, 8306140610.

8306130429 Application for amend to Licenses NPF-2 & NPF-8, changing
Tech Specs re operating personnel, per NUREG-0737, Item
I A.1.3 & Generic Ltrs 82-02 & 82-12, to incorporate current
practices.
CLAYTON, F L Alabama Power Co. 83/06/06 VARQA, S A Office of
Nuclear Reactor Regulation, Director. 3pp. 18821 223 24X
Fiche: 50-348, 83/06/06, 8306130429

--8306130442 Proposed Tech Specs re use of overtime for operating
personnel
* Alabama Power Co 83/06/06, 3pp. 18821 226 24X
Fiche: 50-348, 83/06/06, 8306130429

8306140593 Commits to addl action items associated w/Westinghouse
reactor trip breakers, Model DB-416, based on 830602 telcon.
Only replacement undervoltage trip attachments w/record of
25 cycles will be used.
CLAYTON, F L Alabama Power Co 83/06/06 VARQA, S A Office of
Nuclear Reactor Regulation, Director. 3pp. 18844:153 24X
Fiche: 50-348, 83/06/06, 8306140593.

8306160278 Forwards status of all licensing items identified in util
830113 ltr.
CLAYTON, F L Alabama Power Co. 83/06/10 VARQA, S A Office of
Nuclear Reactor Regulation, Director 7pp 18860 177, 24X
Fiche: 50-348, 83/06/10, 8306160278.

8306210193 Application for amend to License NPF-2 requesting one-time
change to Tech Spec permitting extension of subsequent
visual insp of inaccessible hydraulic snubbers to fifth
outage or next plant shutdown of sufficient duration.
CLAYTON, F L Alabama Power Co. 83/06/17 VARQA, S A Office of
Nuclear Reactor Regulation, Director. 2pp. 18914:152 24X
Fiche: 50-348, 83/06/17, 8306210193.

--8306210201 Proposed Tech Spec re one-time change to inaccessible
hydraulic snubber visual insp
* Alabama Power Co 83/06/17 1p 18914 154 24X
Fiche 50-348, 83/06/17, 8306210193

8306230378 Application to amend Licenses NPF-2 & NPF-8, deleting Tech
Spec requirement for river water sys surveillance & svc
water bldg battery sys discharge test during shutdown
CLAYTON, F L Alabama Power Co 83/06/20 VARQA, S A Office of
Nuclear Reactor Regulation, Director 3pp 18943 247 24X
Fiche 50-348, 83/06/20, 8306230378

--8306230382 Proposed Tech Spec changes, deleting requirement for river
water sys surveillance & svc water bldg battery sys
discharge test during shutdown
* Alabama Power Co 83/06/20 9pp 18943 249 24X
Fiche 50-348, 83/06/20, 8306230378

8306240040 Requests specific license amends discussed during May 1983
telcons w/NRC be given priority to meet review schedules
Evaluation will avoid need to resubmit changes as emergency
Tech Spec changes
CLAYTON, F L Alabama Power Co 83/06/20 VARQA, S A Office of
Nuclear Reactor Regulation, Director 5pp 18981 089 24X
Fiche 50-348, 83/06/20, 8306240040

G Inspection reports, IE Bulletins & correspondence

8306090319 Forwards IE Safeguards Insp Repts 50-348/83-07 &
50-364/83-05 on 830227-0303 & notice of violation Rept
details & notice of violation withheld (ref 10CFR73 21)
LEHIS, R C Division of Project & Resident Programs 83/03/23
MCDONALD, R P Alabama Power Co 2pp 18795 112 24X
Fiche 50-348, 83/03/23, 8306090319

--8306090324 IE Safeguards Insp Repts 50-348/83-07 & 50-364/83-05 on
830227-0303 Noncompliance noted failure of vital area
alarms in access mode to indicate tamper Details withheld
(ref 10CFR73 21)
MOORE, D E Region 2, Office of Director MCQUIRE, D R Division of
Emergency Preparedness & Materials Safety 83/03/23 1p
18795 114 24X Fiche 50-348, 83/03/23, 8306090319

8306140473 Forwards IE Insp Repts 50-348/83-12 & 50-364/83-10 on
830421-22 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/05/16
MCDONALD, R P Alabama Power Co 2pp 18834 326 24X
Fiche 50-348, 83/05/16, 8306140473

--8306140477 IE Insp Repts 50-348/83-12 & 50-364/83-10 on 830421-22 No
noncompliance noted Major areas inspected licensee program
for keeping radiation exposures ALARA
DEBS, B T, MOSEY, C M Region 2, Office of Director BARR, K P,
Division of Engineering & Radiological Safety Programs 83/05/12
7pp 18834 328 24X Fiche 50-348, 83/05/16, 8306140473

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in
Well Logging Device" Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post
830103) 83/05/26 Consolidated Edison Co of New York, Inc
123pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458.

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet"
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New
York, Inc. 113pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8306010332 Forwards IE Safeguards Insp Repts 50-348/83-14 &
50-364/83-12 on 830507-13 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/05/26
MCDONALD, R P Alabama Power Co 2pp 18682 150 24X
Fiche 50-348, 83/05/26, 8306010332

--8306010333 IE Safeguards Insp Repts 50-348/83-14 & 50-364/83-12 on
830507-13 No noncompliance noted Major areas inspected site
orientation, security organization-mgt, personnel & response
Details withheld (ref 10CFR73 21)
HALL, B L Region 2, Office of Director, MCQUIRE, D R Division of
Emergency Preparedness & Materials Safety 83/05/24 1p,
18682 152 24X Fiche 50-348, 83/05/26, 8306010332

8306140645 Forwards IE Insp Repts 50-348/83-11 & 50-364/83-09 on
830418-22, No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/05/26,
MCDONALD, R P Alabama Power Co 2pp. 18841:242 24X
Fiche: 50-348, 83/05/26, 8306140645

DOCKETED ITEMS

207

- 8306140455 IE Insp Repts 50-348/83-11 & 50-364/83-09 on 830418-22 No noncompliance noted Major areas inspected emergency preparedness
HARRISON, R R Region 2, Office of Director JENKINS, G R Division of Emergency Preparedness & Materials Safety 83/05/24 App
18841 244 24X Fiche 50-348,83/05/26,8306140455
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at DHRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000,83/05/31,8305110461
- 8306140071 Responds to IE Bulletin 82-02, "Degradation of Threaded Fasteners in RCPB of PWR Plants " Maint & QA measures implemented Listed closure connection threaded fasteners opened for component insp/maint
CLAYTON, F L Alabama Power Co 83/05/31 O'REILLY, J P Region 2, Office of Director 3pp 18838 261 24X Fiche 50-348,83/05/31,8306140071
- 8306090329 Ack receipt of 830418 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-348/83-07 & 50-364/83-05
LEWIS, R C Division of Project & Resident Programs 83/06/06 McDONALD, R P Alabama Power Co 2pp 18793 070 24X Fiche 50-348,83/06/06,8306090329
- 8306090332 Responds to NRC 830323 ltr re violations noted in IE Safeguards Insp Repts 50-348/83-07 & 50-364/83-05 Corrective actions withheld
CLAYTON, F L Alabama Power Co 83/04/18 LEWIS, R C Region 2, Office of Director 1p 18795 072 24X Fiche 50-348,83/06/06,8306090332
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fiche 50-000,83/06/09,8305110464
- 8306170357 Submits evaluation of plant design & initial description of planned actions in response to IE Bulletin 83-03 re diesel generator svc water sys Check valve design & matls superior Final evaluation forthcoming
CLAYTON, F L Alabama Power Co 83/06/10 O'REILLY, J P Region 2, Office of Director 3pp 18880 178 24X Fiche 50-348,83/06/10,8306170357
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225 24X Fiche 50-000,83/06/13,8305110470
- 8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000,83/06/13,8306090010
- 8306290198 Ack receipt of 830608 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/83-09 & 50-364/83-07
LEWIS, R C Division of Project & Resident Programs 83/06/16 McDONALD, R P Alabama Power Co 2pp 19056 095 24X Fiche 50-348,83/06/16,8306290198
- 8306290207 Responds to NRC 830510 ltr re violations noted in IE Insp Repts 50-348/83-09 & 50-364/83-07 Corrective actions personnel instructed to close fire doors unless fire watch established & preventive maint program updated.
CLAYTON, F L Alabama Power Co 83/06/08 LEWIS, R C Region 2, Office of Director 4pp 19056 097 24X Fiche 50-348,83/06/16,8306290198
- 8306290213 Forwards IE Insp Repts 50-348/83-09 & 50-364/83-07 on 830306-0410 & notice of violation.
LEWIS, R C Division of Project & Resident Programs 83/05/10 McDONALD, R P Alabama Power Co 2pp 19056 101 24X Fiche 50-348,83/06/16,8306290198
- 8306290216 Notice of violation from insp on 830306-0410
* Region 2, Office of Director 83/05/10 1p 19056 103 24X Fiche 50-348,83/06/16,8306290198
- 8306290222 IE Insp Repts 50-348/83-09 & 50-364/83-07 on 830306-0410 Noncompliance noted Failure to follow calibr & recycle procedures & Tech Spec requirements for fire doors & Procedures FNP-1-57P-256 15, Rev 3, inadequate
BRADFORD, W H, RULAND, W H Region 2, Office of Director CANTRELL, F S Division of Project & Resident Programs 83/05/06 10pp 19056 104 24X Fiche 50-348,83/06/16,8306290198
- 8306210193 Application for amend to License NPF-2 requesting one-time change to Tech Spec permitting extension of subsequent visual insp of inaccessible hydraulic snubbers to fifth outage or next plant shutdown of sufficient duration
CLAYTON, F L Alabama Power Co 83/06/17 VAROA, B A Office of Nuclear Reactor Regulation, Director 2pp 18914 152 24X Fiche 50-348,83/06/17,8306210193
- 8306210201 Proposed Tech Spec re one-time change to inaccessible hydraulic snubber visual insp
* Alabama Power Co 83/06/17 1p 18914 154 24X Fiche 50-348,83/06/17,8306210193
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 113pp 19021 179 24X Fiche 50-000,83/06/22,8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000,83/06/22,8305110477
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions, " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000,83/06/23,8305110479
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000,83/06/24,8305110483
- R. Periodic operating reports & related correspondence
- 8306160327 Monthly operating rept for May 1983 W/830610 ltr
HARRISON, W O, CLAYTON, F L Alabama Power Co 83/06/02 9pp 18860 233 24X Fiche 50-348,83/06/02,8306160327
- S Reportable occurrences, LERs & related correspondence
- 8306100270 LER 83-021/03L-0 on 830506, power supply breaker HBL7R opened. Possibly caused by personnel inadvertently tripping breaker by closing locker. Locker moved W/830606 ltr
CLAYTON, F L, HARRISON, W O Alabama Power Co 83/06/06 Region 2, Office of Director 3pp 18807 001 24X Fiche 50-348,83/06/06,8306100270
- 8306200336 LER 83-022/03L-0 on 830511, during monthly operability check, charging pump IC declared inoperable when breaker 0006 would not close Caused by broken follower-roller in breaker spring charging mechanism. Broken part replaced W/830608 ltr
HARRISON, W O, CLAYTON, F L Alabama Power Co 83/06/08 Region 2, Office of Director 2pp 18900 196 24X Fiche 50-348,83/06/08,8306200336
- 8306200216 Forwards LERs 83-023/03L-0, 83-023/03L-0 & 83-024/03L-0.
CLAYTON, F L Alabama Power Co 83/06/10 Region 2, Office of Director 1p 18902 279 24X Fiche 50-348,83/06/10,8306200216
- 8306200220 LER 83-023/03L-0 on 830511, RCS controlled leakage determined to be 32 gpm, contrary to Tech Spec limit of 31 gpm Caused by increase in seal injection flow as result of manual throttle valve vibrating open slightly. Valves adjusted.
HARRISON, W O Alabama Power Co 83/06/10 Region 2, Office of Director 1p 18902 280 24X Fiche 50-348,83/06/10,8306200216
- 8306200227 LER 83-023/03L-0 on 830511, train B reactor trip breaker would not reclose Caused by design inadequacy Voltage available to undervoltage device coil marginally sufficient to allow undervoltage device to remain latched.
HARRISON, W O Alabama Power Co 83/06/10 Region 2, Office of Director 4pp 18902 281 24X Fiche 50-348,83/06/10,8306200216

DOCKETED ITEMS

--8306200233 LER 83-024/03L-0 on 830512, rod control sys declared inoperable upon receipt of failure alarm on power cabinet
2AC Caused by failure of regulator circuitry card Card replaced
HAIRSTON, W Q. Alabama Power Co. 83/06/10 Region 2, Office of Director 1p 18902 283 24X Fiche 50-348, 83/06/10, 8306200216

8306270229 Forwards LERS 83-025/03L-0 & 83-026/03L-0
CLAYTON, F L. Alabama Power Co. 83/06/16 Region 2, Office of Director 1p 18993 320 24X Fiche 50-348, 83/06/16, 8306270229.

--8306270232 LER 83-025/03L-0 on 830602, chlorine detector sys train A declared inoperable due to inoperable sensor Caused by broken wire in detector fiber optics wire repaired Chlorine detector declared operable following FWP-0-BTP-318 1
HAIRSTON, W Q. Alabama Power Co. 83/06/16 Region 2, Office of Director 1p 18993 318 24X Fiche 50-348, 83/06/16, 8306270229

--8306270369 LER 83-026/03L-0 on 830526, containment particulate activity monitor R-11 declared inoperable Caused by vacuum pump failure Monitor declared operable following Alignment to alternate pump inoperable pump replaced.
HAIRSTON, W Q. Alabama Power Co. 83/06/16 Region 2, Office of Director 1p. 18993, 319 24X Fiche 50-348, 83/06/16, 8306270229

DOCKET 50-352 LIMERICK GENERATING STATION, UNIT 1

A Application/construction stage documents & correspondence

8306030086 Notification of 830525 meeting w/util in Bethesda, MD to resolve issues re accident evaluation identified in NRC 830311 1tr
MARTIN, R E. Licensing Branch 2 83/05/20. SCHWENCER, A Licensing Branch 2. 4pp 18733 269 24X Fiche 50-352, 83/05/20, 8306030086

8306010292 Forwards draft changes to FBAR, design assessment rept & to previously provided responses in answer to Issues 5b, 5c, 5d, 5e & 20 discussed at 830407 meeting Rept on functionality of purge & vent valves will be submitted in June 1983
BRADLEY, E J. Philadelphia Electric Co. 83/05/26 SCHWENCER, A Licensing Branch 2 75pp 18678 304 24X Fiche 50-352, 83/05/26, 8306010292

8306020649 Notification of 830608 meeting w/util & BMNL in Bethesda, MD to discuss severe accident risk assessment (SARA).
MARTIN, R E. Licensing Branch 2 83/05/27 SCHWENCER, A Licensing Branch 2. 4pp 18716-271 24X Fiche 50-352, 83/05/27, 8306020649

8306010233 Forwards application for Amend 51 to DL application (filed in Category A) consisting of environ qualification rept, Rev 20 to FBAR (filed in Category K) & Rev 13 to environ rept (filed in Category C).
BRADLEY, E J. Philadelphia Electric Co. 83/05/31. DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 18675, 001. 24X Fiche: 50-352, 83/05/31, 8306010233.

--8306010239 Application for Amend 51 to DL application, consisting of Rev 20 to FBAR, environ qualification rept & Rev 13 to environ rept
BAUER, E Q. Philadelphia Electric Co. 83/05/24 6pp 18675 004. 24X Fiche 50-352, 83/05/31, 8306010233

8306090196 Notification of 830608 meeting w/util & Bechtel in San Francisco, CA to discuss outstanding items in structural engineering review area.
MARTIN, R E. Licensing Branch 2 83/06/02 SCHWENCER, A Licensing Branch 2 3pp. 18809, 292 24X Fiche: 50-352, 83/06/02, 8306090196.

8306070239 Forwards revised draft response to Question 410 17 re CP application compliance w/NUREG-0800 per 830330 meeting w/NRC. Changes will be incorporated in FBAR rev scheduled for June 1983.
BRADLEY, E J. Philadelphia Electric Co. 83/06/03. SCHWENCER, A, Licensing Branch 2 3pp. 18747-048. 24X Fiche: 50-352, 83/06/03, 8306070239.

8306100109 Forwards revised draft response to Question 430, 48 re level of training for operators, maint crew & GA personnel. Response will be incorporated into FBAR rev scheduled for Jul 1983
BRADLEY, E J. Philadelphia Electric Co. 83/06/06 SCHWENCER, A Licensing Branch 2. 6pp. 18802, 205. 24X Fiche: 50-352, 83/06/06, 8306100109.

8306100065 Forwards draft FBAR change re bleed line depressurization branch per Accident Evaluation Branch request Change will be incorporated into Jul 1983 FBAR rev.
BRADLEY, E J. Philadelphia Electric Co. 83/06/07 SCHWENCER, A, Licensing Branch 2. 3pp 18803:069 24X Fiche: 50-352, 83/06/07, 8306100065.

8306100241 Forwards revised draft response to FBAR mgt technology section re licensed operator courses & operating activities transmitted in 830506 ltr, per 830527 request Changes will be incorporated into FBAR rev scheduled for Jul 1983
BRADLEY, E J. Philadelphia Electric Co. 83/06/07 SCHWENCER, A Licensing Branch 2 4pp 18807 093 24X Fiche 50-352, 83/06/07, 8306100241

8306150321 Forwards request for addl info re FBAR Design Criteria Summary, Item 260 5a reflecting requirements of NUREG-0737, "Clarification of TMI Action Plan Requirements"
SCHWENCER, A Licensing Branch 2 83/06/07. BAUER, E Q Philadelphia Electric Co. 7pp. 18870 010 24X Fiche 50-352, 83/06/07, 8306150321

8306160340 Responds to QA Branch 830527 telcon request re proposed organization change in Electric Production Dept reflecting change in QC Program for Operational Phase
DALTROFF, S L. Philadelphia Electric Co. 83/06/07 SCHWENCER, A Licensing Branch 2. 8pp 18899 082 24X Fiche 50-352, 83/06/07, 8306160340

8306160310 Forwards Final response to NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants-Resolution of TAP A-36"
Response includes analyses for loads handled over reactor vessel
KEMPER, J B. Philadelphia Electric Co. 83/06/13 EISENHUT, D Q Division of Licensing 126pp 18860 243 24X Fiche 50-352, 83/06/13, 8306160310

8306160377 Forwards rev to Page 1 2 of 830531 environ qualification rept, to be formally incorporated into Oct 1983 rept rev.
BRADLEY, E J. Philadelphia Electric Co. 83/06/13 SCHWENCER, A Licensing Branch 2. 3pp 18861 123 24X Fiche 50-352, 83/06/13, 8306160377

8306170210 Forwards draft responses to requests for addl info Questions 252 1 through 252 7 & related draft FBAR text changes Draft changes will be incorporated in FBAR in rev scheduled for Jul 1983
BRADLEY, E J. Philadelphia Electric Co. 83/06/14 SCHWENCER, A Licensing Branch 2 100pp 18883 153 24X Fiche 50-352, 83/06/14, 8306170210

8306170309 Provides marked-up draft FBAR pages per QA Branch 830527 request for addl info Page changes will be incorporated in FBAR rev scheduled for Jul 1983
BRADLEY, E J. Philadelphia Electric Co. 83/06/14 SCHWENCER, A Licensing Branch 2 16pp. 18877 113 24X Fiche 50-352, 83/06/14, 8306170309

8306210418 Notification of 830615 meeting w/util, Bechtel & GE in Bethesda, MD to discuss high radiation isolation signals on containment purge/vent valves
MARTIN, R E. Licensing Branch 2 83/06/14 SCHWENCER, A Licensing Branch 2 4pp 18937, 065 24X Fiche: 50-352, 83/06/14, 8306210418

8306200117 Forwards response to Metis Engineering Branch 830603 request for info re turbine missile issue
BRADLEY, E J. Philadelphia Electric Co. 83/06/15 SCHWENCER, A Licensing Branch 2 3pp 18903-247 24X Fiche 50-352, 83/06/15, 8306200117

8306210220 Forwards matl presented at Anderson, Greenwood & Co (AGCo) vacuum breaker test program owners group 830607 meeting w/NRC re dynamic testing & analysis of AGCo vacuum breaker valve assemblies.
O'CONNOR, D M. Bechtel Corp. 83/06/17. HOUSTON, R W. Division of Systems Integration (post 811005). 91pp 18919 038 24X Fiche 50-000, 83/06/17, 8306210220

8306240412 Notification of 830621-24 meetings w/util, Bechtel & GE in San Jose & San Francisco, CA to discuss outstanding items in Metis Engineering Branch review of compliance w/QDC 51
MARTIN, R E. Licensing Branch 2 83/06/17 SCHWENCER, A Licensing Branch 2 4pp 18998 013. 24X Fiche 50-352, 83/06/17, 8306240412

8306230276 Responds to NRC 830523 request for proposed resolution to TMI Item II K.3 18, "Mod of Automatic Depressurization Sys Logic" Justification for bypass timer setting will be provided prior to implementation of mod
KEMPER, J B. Philadelphia Electric Co. 83/06/20 SCHWENCER, A, Licensing Branch 2. 3pp 18945, 135. 24X Fiche 50-352, 83/06/20, 8306230276

8306240138 Notification of 830623 meeting w/util & Bechtel in Bethesda, MD to discuss Auxiliary Sys Branch open issues
ABELEON, H. Licensing Branch 2. 83/06/20. SCHWENCER, A Licensing Branch 2 4pp 18987-213. 24X Fiche: 50-352, 83/06/20, 8306240138

DOCKETED ITEMS

209

8306290599 Summarizes NRC Caseload Forecast Panel 830413-15 meetings w/util re assessment of schedule for completing const & other activities necessary to support issuance of OL OL expected by Second Quarter 1985
NOVAK, T.M. Assistant Director For Licensing 83/06/20 BAUER, E. O
Philadelphia Electric Co 3pp 19047 09B 24X
Fiche 50-352, 83/06/20, 8306290599

8306240367 Summary of Caseload Forecast Panel 830413 meetings w/util, Bechtel & Conner & Wetterhahn in Valley Forge, PA re review of const progress & to collect data for estimating NRC resource needs for licensing activities Agenda encl
HAUGHEY, M.F. Licensing Branch 2 83/06/21 Licensing Branch 2
16pp 18999 139 24X Fiche 50-352, 83/06/21, 8306240367

8306270212 Forwards revs to FSAR Sections 7.5.6.3, 7.2.8.3 & 9.5-10 info will be incorporated into rev to FSAR scheduled for Jul 1983
BRADLEY, E.J. Philadelphia Electric Co 83/06/21 SCHWENCER, A.
Licensing Branch 2 10pp 18990 252 24X Fiche 50-352, 83/06/21, 8306270212

8306270365 Forwards revised draft response to FSAR Question 410.70 re design temp for essential svc water & RHR svc water sys Draft change will be incorporated into FSAR rev scheduled for Jul 1983
BRADLEY, E.J. Philadelphia Electric Co 83/06/21, SCHWENCER, A.
Licensing Branch 2 6pp, 18993 193 24X Fiche 50-352, 83/06/21, 8306270365

8306270423 Forwards draft FSAR changes prepared in response to Containment Sys Branch Open Item 18 Changes state isolation valves will be sealed closed info will be incorporated into FSAR rev scheduled for Jul 1983
BRADLEY, E.J. Philadelphia Electric Co 83/06/23, SCHWENCER, A.
Licensing Branch 2 7pp 18992 126 24X Fiche 50-352, 83/06/23, 8306270423

8306270459 Forwards draft revised responses to NRC Questions 410.05, 410.10, 410.37, 410.52, 410.85 & 410.89, per telcon w/Auxiliary Sys Branch Responses will be incorporated in FSAR scheduled for Jul 1983
BRADLEY, E.J. Philadelphia Electric Co. 83/06/23 SCHWENCER, A.
Licensing Branch 2 20pp 18992.075, 24X Fiche 50-352, 83/06/23, 8306270459

8306280589 Informs that Aug 1984 const completion date scheduled in last quarterly rept consistent w/ongoing const efforts, per NRC B10B11 ltr
BRADLEY, E.J. Philadelphia Electric Co 83/06/23 EISENHUT, D.O.
Division of Licensing 2pp 19018 240 24X Fiche 50-352, 83/06/23, 8306280589

8306300024 Responds to 830609 request for addl info, forwarding documents used by Structural Mechanics Assoc in seismic fragility development
BRADLEY, E.J. Philadelphia Electric Co. 83/06/27, SCHWENCER, A.
Division of Licensing. 200pp 19114 250, 24X Fiche 50-352, 83/06/27, 8306300024

8306300221 Forwards draft FSAR changes re loose parts monitoring sys for rev scheduled for Jul 1983, Detailed sys description per Reg Guide 1.133 submitted, pending receipt of BER.
BRADLEY, E.J. Philadelphia Electric Co 83/06/27 SCHWENCER, A.
Licensing Branch 2 7pp 19120.001, 24X Fiche 50-352, 83/06/27, 8306300221

8306300133 Forwards draft revised response to TMI Item I.O. 1, "Training During Low-Power Testing," per 830627 conference call. info contained in draft revised response will be incorporated into FSAR rev scheduled for Aug 1983.
BRADLEY, E.J. Philadelphia Electric Co. 83/06/28 SCHWENCER, A.
Licensing Branch 2 5pp, 19122.311 24X Fiche: 50-352, 83/06/28, 8306300133,

C Utility Environmental Report (ER), amends & correspondence

8306010233 Forwards Rev 13 to environ rept
BRADLEY, E.J. Philadelphia Electric Co. 83/05/31, DENTON, H.R.
Office of Nuclear Reactor Regulation, Director 3pp 18675:001
24X Fiche: 50-352, 83/05/31, 8306010233.

--8306010243 Rev 13 to environ rept. Environ qualification rept for safety-related equipment encl
Philadelphia Electric Co 83/05/31, 237pp, 18675:010 24X
Fiche: 50-352, 83/05/31, 8306010233.

8306210283 Forwards Affidavit of Svc re distribution of Rev 20 to FSAR, Rev 13 to environ rept & Rev 3 to fire protection evaluation rept.
BRADLEY, E.J. Philadelphia Electric Co. 83/06/17 DENTON, H.R.
Office of Nuclear Reactor Regulation, Director, 5pp, 18918:022.
24X Fiche: 50-352, 83/06/17, 8306210283.

E NRC Safety Evaluation Report (SER), supp's & correspondence

8306070330 Forwards responses to listed Procedures & Test Review Branch SER open items Draft response to TMI Item I.C.1, "Operating & Maint Procedures & ATHS," incorporated in May FSAR rev
BRADLEY, E.J. Philadelphia Electric Co 83/06/03 SCHWENCER, A.
Licensing Branch 2 4pp 18746 065 24X Fiche 50-352, 83/06/03, 8306070330

8306150579 Forwards request for addl info re BER open items Action plan & associated dates for response required within 7 working days of receipt of ltr
SCHWENCER, A. Licensing Branch 2 83/06/03 BAUER, E. O
Philadelphia Electric Co 24pp 18867 03B 24X
Fiche 50-352, 83/06/03, 8306150579

8306100110 Forwards Final response to Reactor Sys Branch draft BER Item 3 re high/low pressure interlocks on ECCS injection valves, per discussion at 830517 meeting in Bethesda, MD
BRADLEY, E.J. Philadelphia Electric Co 83/06/07 SCHWENCER, A.
Licensing Branch 2. 4pp 18802 201, 24X Fiche: 50-352, 83/06/07, 8306100110

8306140545 Responds to Geotechnical Engineering Branch draft BER open items transmitted via 830311 ltr. Properties of foundation bedrock, backfill, lateral loading & response of in-situ soil & backfill matls to dynamic loading discussed
BRADLEY, E.J. Philadelphia Electric Co 83/06/09, SCHWENCER, A.
Licensing Branch 2 25pp 18834 179 24X Fiche: 50-352, 83/06/09, 8306140545.

8306140606 Forwards response to Structural Engineering Branch draft BER Open Items 1, 4, 8 & 9. All open items closed out. Items 1, 4 & 8 represent Formal response while Item 9 indicates FSAR page changes.
BAUER, E. O Philadelphia Electric Co. 83/06/10 SCHWENCER, A.
Licensing Branch 2 38pp 18833 061 24X Fiche: 50-352, 83/06/10, 8306140606

8306140624 Forwards draft responses to BER Open Items 2, 7, 9, 11, 12, 16, 18, 19, 21, 27 & 34 re fire protection Fire protection evaluation rept will be submitted in Aug 1983
BRADLEY, E.J. Philadelphia Electric Co 83/06/10, SCHWENCER, A.
Licensing Branch 2 33pp 18833:326 24X Fiche: 50-352, 83/06/10, 8306140624

8306160001 Forwards draft FSAR page changes, in response to Reactor Sys Branch draft BER Item 1, "DDYN Analysis of Pressurization Transients." Changes will be incorporated into FSAR rev scheduled for Jul 1983
BRADLEY, E.J. Philadelphia Electric Co 83/06/13, SCHWENCER, A.
Licensing Branch 2 58pp 18862.023, 24X Fiche: 50-352, 83/06/13, 8306160001.

8306160371 Forwards draft responses & draft FSAR page changes in response to Meteorology & Effluent Treatment Branch draft BER Items 2, 4, 5 & Request for Addl Info RAI 451.14.
BRADLEY, E.J. Philadelphia Electric Co 83/06/13, SCHWENCER, A.
Licensing Branch 2. 43pp, 18864:164 24X Fiche: 50-352, 83/06/13, 8306160371

8306160527 Forwards response to Core Performance Branch draft BER. Draft page changes will be included in FSAR rev scheduled for Jul 1983
BRADLEY, E.J. Philadelphia Electric Co 83/06/13, SCHWENCER, A.
Licensing Branch 2. 91pp, 18863:140 24X Fiche: 50-352, 83/06/13, 8306160527

8306160572 Forwards draft BER, Section II, "Test Review," Item 2, consisting of FSAR changes to be incorporated into FSAR rev scheduled for Jul 1983
BRADLEY, E.J. Philadelphia Electric Co 83/06/13, SCHWENCER, A.
Licensing Branch 2. 70pp 18866:211, 24X Fiche: 50-352, 83/06/13, 8306160572

8306170349 Forwards response to Accident Evaluation Branch draft BER, per 830525 meeting request. Draft page changes will be included in FSAR rev scheduled for Jul 1983.
BRADLEY, E.J. Philadelphia Electric Co 83/06/14, SCHWENCER, A.
Licensing Branch 2. 17pp 18880:193 24X Fiche: 50-352, 83/06/14, 8306170349

8306200317 Forwards draft responses to NRC draft BER Questions 250.1, 250.2, 250.3, 250.4 & 250.5 re preservice insp of reactor pressure vessels, pumps & valves. Responses will be incorporated in Jul 1983 FSAR rev.
BRADLEY, E.J. Philadelphia Electric Co 83/06/14, SCHWENCER, A.
Licensing Branch 2. 31pp, 18899:212, 24X Fiche 50-352, 83/06/14, 8306200317.

DOCKETED ITEMS

830624041B Notification of 830624 meeting w/uttl & OE in Bethesda, MD to discuss Effluent Treatment Sys Branch open SER items
MARTIN, R E Licensing Branch 2 83/06/20 SCHWENGER, A Licensing Branch 2 App 18998 009 24X Fiche 50-352, 83/06/20, 830624041B

8306270086 Forwards revised draft response to Question 480 7, including revised Section 6 2 & 5 1 & Table 14 2-4 in response to Containment Sys Branch draft SER Issue 1 & revised draft Section 6 2 3 2 3 & Table 6 2-15
BRADLEY, E J. Philadelphia Electric Co 83/06/21 SCHWENGER, A Licensing Branch 2 23pp. 19013:129 24X Fiche 50-352, 83/06/21, 8306270086

8306270315 Provides response to structural engineering review draft SER open items discussed & resolved at 830603 meeting re response spectra, reactor encl & control structure.
KEMPER, J S Philadelphia Electric Co. 83/06/21 SCHWENGER, A Licensing Branch 2 19pp. 18994 010. 24X Fiche 50-352, 83/06/21, 8306270315

8306270340 Forwards revised Table 6 2-17, adding power sources in containment penetration, in response to Containment Sys Branch draft SER Issue 15 Info will be incorporated into FBAR scheduled for Jul 1983
BRADLEY, E J. Philadelphia Electric Co 83/06/23 SCHWENGER, A Licensing Branch 2 App. 18991 210 24X Fiche 50-352, 83/06/23, 8306270340

8306280381 Forwards calculate post-LOCA bounding drywell temp profile, per 830510 Rev 20 changes to FBAR Section 3.11, in response to Containment Sys Branch draft SER, Item 4
KEMPER, J S Philadelphia Electric Co 83/06/24 SCHWENGER, A Licensing Branch 2 App 19014, 063 24X Fiche 50-352, 83/06/24, 8306280381

8306300016 Forwards draft rev to response to Question 640.10 re low power & power ascension testing, providing info necessary to close Item 3 of draft SER, Section II, "Test Review" Info will be included in FBAR rev scheduled for Jul 1983
BRADLEY, E J. Philadelphia Electric Co 83/06/27 SCHWENGER, A Licensing Branch 2 3pp. 19120:252 24X Fiche 50-352, 83/06/27, 8306300016

8306300200 Forwards list of Auxiliary Sys Branch open SER issues per 830623 meeting & marked-up draft FBAR pages responding to issues.
BRADLEY, E J. Philadelphia Electric Co 83/06/28 SCHWENGER, A Licensing Branch 2 5pp. 19122:126 24X Fiche 50-352, 83/06/28, 8306300200

F. Security, medical, emergency & fire protection plans

8306140395 Forwards draft change to FBAR re emergency ac lighting, per 830607 telcon commitment Change will be formally incorporated into FBAR rev scheduled for Jul 1983
BRADLEY, E J. Philadelphia Electric Co. 83/06/10 SCHWENGER, A Licensing Branch 2 App. 18832, 089 24X Fiche 50-352, 83/06/10, 8306140395

8306140624 Forwards draft responses to SER Open Items 2, 7, 9, 11, 12, 16, 18, 19, 21, 27 & 34 re fire protection. Fire protection evaluation rept will be submitted in Aug 1983
BRADLEY, E J. Philadelphia Electric Co 83/06/10 SCHWENGER, A Licensing Branch 2 33pp. 18833:326. 24X Fiche 50-352, 83/06/10, 8306140624

8306200183 Forwards draft changes to FBAR Section 9 5, 3, 2, 2 & Question 430.61 re outdoor security & roadway lighting. Changes will be incorporated into FBAR rev scheduled for Jul 1983.
BRADLEY, E J. Philadelphia Electric Co. 83/06/15 SCHWENGER, A Licensing Branch 2 App. 18903, 173. 24X Fiche 50-352, 83/06/15, 8306200183

8306210283 Forwards Affidavit of Svc re distribution of Rev 20 to FBAR, Rev 13 to environ rept & Rev 3 to fire protection evaluation rept.
BRADLEY, E J. Philadelphia Electric Co. 83/06/17 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 5pp 18915:022. 24X Fiche 50-352, 83/06/17, 8306210283

G. Adjudicatory correspondence

8306010464 Discusses 1E Insp Rept 50-353/76-06 re inaccessible welds. Welds capriciously & unilaterally declared acceptable following convenient & unscientific decision that welds cannot be inspected due to inaccessibility.
RODMAN, F. R. Air and Water Pollution Patrol. 83/05/25 Atomic Safety and Licensing Board Panel. 2pp 18679:319. 24X Fiche 50-352, 83/05/25, 8306010464

8306010372 Forwards motion for reconsideration of ASLB 830509-11 ruling re coordination of contention filing w/Limerick Ecology Action
AU, T Y Pennsylvania, Commonwealth of. 83/05/26 BRENNER, L, MORRIS, P A, COLE, R F Atomic Safety and Licensing Board Panel 1p 18682 091 24X Fiche 50-352, 83/05/26, 8306010372

--8306010380 Motion for reconsideration of ASLB 830509-11 rulings re coordination of contention filing w/Limerick Ecology Action Ruling undermines role of state in presenting issues in neutral manner Certificate of Svc encl
AU, T Y Pennsylvania, Commonwealth of. 83/05/26 Atomic Safety and Licensing Board Panel 11pp 18682 092 24X Fiche 50-352, 83/05/26, 8306010372

8306010369 Petition to withdraw as intervenor representative in OL proceeding RJ Sugarman will continue to represent intervenor Draft order encl
NEILL, J M Del-Aware Unlimited, Inc 83/05/31 Atomic Safety and Licensing Board Panel 2pp 18682 105 24X Fiche 50-352, 83/05/31, 8306010369

8306030280 Response supporting NRC reply to ASLB 830516 order re use of PRA & subsequent risk-related documents Certificate of Svc & RK Weathermax prof qualifications encl
DORSEY, J A Limerick Ecology Action. DORSEY, J A Dorsey, J A 83/05/31 Atomic Safety and Licensing Board Panel 27pp 18703, 187 24X Fiche 50-352, 83/05/31, 8306030280

8306020351 Memorandum & order denying Del-Aware 830308 motion to reopen record & add proposed new Contention U-26 Contention is not significant & would not affect outcome of decision
BRENNER, L Atomic Safety and Licensing Board Panel 83/06/01 Del-Aware Unlimited, Inc. 11pp 18694 247 24X Fiche 50-352, 83/06/01, 8306020351

8306030286 Order granting JM Neill petition to withdraw appearance request
BRENNER, L Atomic Safety and Licensing Board Panel 83/06/01 1p 18703 331 24X Fiche 50-352, 83/06/01, 8306030286

8306060322 Advises that Bucks County, PA citizens voted for County withdrawal from further participation in Point Pleasant Diversion Project intended to supply supplemental cooling water to plant Referendum does not affect contractor rights
CONNER, T B Conner & Wetterhahn. CONNER, T B Philadelphia Electric Co 83/06/02 KOHL, C N, EDLES, G J, GUTCHY, R L Atomic Safety and Licensing Appeal Panel 13pp 18729 172 24X Fiche 50-352, 83/06/02, 8306060322

8306060330 Order scheduling resumed appellate process matters Exceptions to ASLB 830601 order, denying Del-Aware 830308 motion, due 830616 Briefs supporting all exceptions due 830718
SHOENMAKER, C J Atomic Safety and Licensing Appeal Panel 83/06/02 2pp. 18726 361 24X Fiche 50-352, 83/06/02, 8306060330

8306070295 First set of interrogatories & request for production of documents
WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 83/06/03 Air and Water Pollution Patrol 0pp 18741 186. 24X Fiche 50-352, 83/06/03, 8306070295

--8306070299 First set of interrogatories & request for production of documents
WETTERHAHN, M J Philadelphia Electric Co. WETTERHAHN, M J Conner & Wetterhahn 83/06/03 Friends of the Earth 9pp 18741 194 24X Fiche 50-352, 83/06/03, 8306070295

--8306070301 First set of interrogatories & request for production of documents Certificate of Svc encl.
WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J, Conner & Wetterhahn 83/06/03 LEWIS, M I Lewis, M 9pp 18741 203 24X Fiche 50-352, 83/06/03, 8306070295

8306090212 Forwards Attachments 2 & 3 to 830520 ltr Attachments may have been miscollocated or incomplete
WETTERHAHN, M J Conner & Wetterhahn. WETTERHAHN, M J Philadelphia Electric Co. 83/06/06 BRENNER, L, MORRIS, P A, COLE, R F Atomic Safety and Licensing Board Panel. 11pp 18796 103 24X Fiche 50-352, 83/06/06, 8306090212

8306090240 Motion for extension until 830610 to respond to NRC use of facility PRA Filing allowed per ASLB 830516 order confirming schedules. Certificate of Svc encl
WETTERHAHN, M J Philadelphia Electric Co. WETTERHAHN, M J Conner & Wetterhahn 83/06/06 Atomic Safety and Licensing Board Panel 4pp 18795 328 24X Fiche 50-352, 83/06/06, 8306090240

DOCKETED ITEMS

211

8306080167 Order granting until 830606 motion for extension until 830610 to file response to NRC & Limerick Ecology Action Filings on PRA contentions Parties consent & good cause shown
BRENNER, L. Atomic Safety and Licensing Board Panel 83/06/07
Philadelphia Electric Co 1p 18772 154 24X Fiche 50-352, 83/06/07, 8306080167

8306090301 Order extending time until 830627 for Commission to act to review ALAB-726
CHILK, S. J. Office of the Secretary of the Commission 83/06/07
Commissioners 1p 18795 241 24X Fiche 50-352, 83/06/07, 8306090301

8306100175 Order requiring NRC to update schedule estimate for issuance of DES All parties under duty to inform ABLB of any change in mail info
BRENNER, L. Atomic Safety and Licensing Board Panel 83/06/09
Commissioners 2pp 18806 017 24X Fiche 50-352, 83/06/09, 8306100175

8306130366 Advises that if Pennsylvania Emergency Mgt Agency draft emergency plans available by 831115, FEMA would complete review by mid Feb 1984 FEMA will expedite review & should be placed on svc list
VOGLER, B. H. Hearing Branch 2 83/06/09 BRENNER, L., MORRIS, P. A., COLE, R. F. Atomic Safety and Licensing Board Panel 2pp 18821 268 24X Fiche 50-352, 83/06/09, 8306130366

8306140676 Responds to request for definition of safety classification terms by transmitting relevant portions of ASLB 830526 Decision ALAB-729
HODDGDN, A. P. Hearing Branch 2 83/06/10 LEWIS, M. I. Lewis, M. 6pp 18942 069 24X Fiche 50-352, 83/06/10, 8306140676

8306140715 Response to first set of interrogatories on pressurized thermal shock, Contention 1-62 Certificate of Bvc encl
HODDGDN, A. P. Hearing Branch 2 83/06/10 Lewis, M. 27pp 18941 276 24X Fiche 50-352, 83/06/10, 8306140715

8306140722 Response to ASLB 830609 order requiring NRC to update schedule for DES issuance Schedule unchanged since dates set at 830509-11 second special prehearing conference DES, except Chapter 7, to be published on 830613
HODDGDN, A. P. Hearing Branch 2 83/06/10 BRENNER, L., MORRIS, P. A., COLE, R. F. Atomic Safety and Licensing Board Panel 2pp 18841 094 24X Fiche 50-352, 83/06/10, 8306140722

8306150362 Discusses Contentions I-33B, D, E, K & I-45 re TMI Action Plan Items I, C, 6, I, O, I, I, D, I, I, I, D, 3 & I, I, I, D 2 Contentions denied w/o prejudice by ASLB 830516 memorandum & order, for lack of specificity
DORSEY, J. A. Dorsey, J. A. Limerick Ecology Action 83/06/10 BRENNER, L., MORRIS, P. A., COLE, R. F. Atomic Safety and Licensing Board Panel 2pp 18847 145 24X Fiche 50-352, 83/06/10, 8306150362

8306150393 Response to NRC use of Facility PRA & Limerick Ecology Action Response to ASLB 830516 memorandum & order confirming schedules, Certificate of Bvc encl
WETTERHAHN, M. J. Philadelphia Electric Co WETTERHAHN, M. J. Conner 1pp 18847 159 24X Fiche 50-352, 83/06/10, 8306150393

8306160603 Forwards until answer to MI Lewis first set of interrogatories on pressurized thermal shock contention
WETTERHAHN, M. J. Conner & Wetterhahn WETTERHAHN, M. J. Philadelphia Electric Co 83/06/13 LEWIS, M. I. Lewis, M. 1p 18866 144 24X Fiche 50-352, 83/06/13, 8306160603

--8306160609 Answers to first set of interrogatories on pressurized thermal shock contention Certificate of Bvc encl
BOYER, V. B. Philadelphia Electric Co 83/06/13 LEWIS, M. I. Lewis, M. 16pp 18866 145 24X Fiche 50-352, 83/06/13, 8306160609

8306220043 Answer to first set of interrogatories re pressurized thermal shock in BWRs
LEWIS, M. I. Lewis, M. 83/06/15 Philadelphia Electric Co 2pp 18926 255 24X Fiche 50-352, 83/06/15, 8306220043

8306220051 Files addl exceptions to ASLB 830601 order refusing to consider Interstate Delaware River Mgt 830517 recommendations & referendum Certificate of Bvc encl
SUGARMAN, R. J. Del-Aware Unlimited, Inc. SUGARMAN, R. J. Sugarman, R. J. 83/06/16 Atomic Safety and Licensing Appeal Panel 5pp 18926 198 24X Fiche 50-352, 83/06/16, 8306220051

8306220103 Forwards Commonwealth of PA Supreme Court decision, unanimously reversing Commonwealth Court & holding that PUC of PA acted within power & acted properly when ordering until to cancel or suspend const of Unit 2
SUGARMAN, R. J. Sugarman, R. J. 83/06/16 BRENNER, L., COLE, R. F., MORRIS, P. A. Atomic Safety and Licensing Board Panel, 16pp. 18926 038 24X Fiche 50-352, 83/06/16, 8306220103

8306270297 Forwards onsite emergency planning contentions, in response to ASLB 830516 memorandum of order
DORSEY, J. A. Dorsey, J. A. 83/06/17 BRENNER, L., COLE, R. F., MORRIS, P. A. Atomic Safety and Licensing Board Panel 35pp 18995 170 24X Fiche 50-352, 83/06/17, 8306270297

--8306270300 Onsite emergency planning contentions Certificate of Bvc encl
* Limerick Ecology Action 83/06/17 32pp 18995 172 24X Fiche 50-352, 83/06/17, 8306270297

8306270038 Answer to first set of interrogatories Related correspondence
ANTHONY, R. C. Friends of the Earth ANTHONY, R. C. Anthony, R. L. 83/06/20 Philadelphia Electric Co 2pp 18988 135 24X Fiche 50-352, 83/06/20, 8306270038

8306290364 Discusses Air & Water Pollution Patrol response to until 830606 interrogatories Related correspondence
ROMANO, F. R. Air and Water Pollution Patrol 83/06/21 BRENNER, L., COLE, R. F., MORRIS, P. A. Atomic Safety and Licensing Board Panel 1p 19055 226 24X Fiche 50-352, 83/06/21, 8306290364

8306290509 Response to 830606 interrogatories Related correspondence
ROMANO, F. R. Air and Water Pollution Patrol 83/06/21 Atomic Safety and Licensing Board Panel, 5pp 19052 209 24X Fiche 50-352, 83/06/21, 8306290509

8306270413 Advises that until does not object to Limerick Ecology Action position in 830610 ltr on contentions related to NUREG-0737
WETTERHAHN, M. J. Conner & Wetterhahn WETTERHAHN, M. J. Philadelphia Electric Co 83/06/23 BRENNER, L., MORRIS, P. A., COLE, R. F. Atomic Safety and Licensing Board Panel 2pp 18994 146 24X Fiche 50-352, 83/06/23, 8306270413

8306280566 Responds to Del-Aware 830616 ltr ASLB requesting admittance of new contention Del-Aware failed to comply w/procedure re late-filed contentions
HODDGDN, A. P. Hearing Branch 2 83/06/27 BRENNER, L., MORRIS, P. A., COLE, R. F. Atomic Safety and Licensing Board Panel 2pp 19017 330 24X Fiche 50-352, 83/06/27, 8306280566

8306300143 Advises that time for Commission to review ALAB-726 expired. Commission declined review Decision became final agency action on 830627
CHILK, S. J. Office of the Secretary of the Commission 83/06/29 Office of the Executive Legal Director 1p 19168 117 24X Fiche 50-352, 83/06/29, 8306300143

H General correspondence

8306020380 Requests further discussion of 10CFR50.54(i) & (j) re single failure criterion issue of common mode failure of all solenoids litigable
LEWIS, M. I. Lewis, M. 83/05/26 TRAMMELL, C. M. NRC - No Detailed Affiliation Given 2pp 18694 362 24X Fiche 50-352, 83/05/26, 8306020380

8306170387 Opposes DL issuance until local officials agree upon acceptable emergency plan providing adequate protection to affected population
MORRIS, B. A. Affiliation Unknown 83/06/09 BRENNER, L. Atomic Safety and Licensing Board Panel, 1p 18880 070 24X Fiche 50-352, 83/06/09, 8306170387

K Utility Final Safety Analysis Report (FSAR) & amendments

8306010233 Forwards Rev 20 to FSAR.
BRADLEY, E. J. Philadelphia Electric Co 83/05/31. DENTON, H. R. Office of Nuclear Reactor Regulation, Director 3pp 18675 001 24X Fiche 50-352, 83/05/31, 8306010233

--8306010240 Rev 20 to FSAR
* Philadelphia Electric Co 83/05/31, 10pp. 18675 247 24X Fiche 50-352, 83/05/31, 8306010233

8306210283 Forwards Affidavit of Bvc re distribution of Rev 20 to FSAR, Rev 13 to environ rept & Rev 3 to fire protection evaluation rept.
BRADLEY, E. J. Philadelphia Electric Co 83/06/17. DENTON, H. R. Office of Nuclear Reactor Regulation, Director 5pp 18915 022 24X Fiche 50-352, 83/06/17, 8306210283

Q Inspection reports, IE Bulletins & correspondence

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Wall Logging Device" Bvc list encl
TAYLOR, J. M. Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc. 125pp. 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

DOCKETED ITEMS

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/24 Consolidated Edison Co. of New York, Inc. 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8306090140 Forwards IE Insp Repts 50-352/83-05 & 50-353/83-02 on 830319-0422 & notice of violation
STAROSTECKI, R. Division of Project & Resident Programs 83/05/24
KEMPER, J. B. Philadelphia Electric Co 2pp 18792 259 24X Fiche 50-352, 83/05/26, 8306090140

--8306090143 Notice of violation from insp on 830319-0422
" Division of Project & Resident Programs 83/05/26 2pp 18792-261 24X Fiche 50-352, 83/05/26, 8306090140

--8306090151 IE Insp Repts 50-352/83-05 & 50-353/83-02 on 830319-0422
Noncompliance noted separation requirement for electrical raceway (cable trays) not verified & GC instruction did not include appropriate insp methods for conduit bands
CHAUDHARY, B. K., PAOLINO, R. J., NICHOLAS, H. H. Region I, Office of Director. 83/05/26 7pp 18792 263 24X Fiche 50-352, 83/05/26, 8306090140.

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn At BWRs " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/31. Consolidated Edison Co. of New York, Inc. 116pp 18732:208 24X Fiche. 50-000, 83/05/31, 8305110461

8306150237 Forwards IE Insp Repts 50-352/83-07 & 50-353/83-04 on 830424-0528 No noncompliance noted.
STAROSTECKI, R. Division of Project & Resident Programs 83/06/02
KEMPER, J. B. Philadelphia Electric Co 2pp 18846 011 24X Fiche 50-352, 83/06/02, 8306150237.

--8306150247 IE Insp Repts 50-352/83-07 & 50-353/83-04 on 830424-0528 No noncompliance noted Major areas inspected: control rod drive supports, following of Part 21 repts, design change control & personnel training
CHAUDHARY, B. K., GRANT, J. M., CONNER, E. L. Region I, Office of Director. 83/06/02. 5pp 18846:013 24X Fiche. 50-352, 83/06/02, 8306150237.

8306090212 Forwards Attachments 2 & 3 to 830520 ltr. Attachments may have been miscolated or incomplete
WETTERHANN, M. J., Conner & Wetterhann WETTERHANN, M. J. Philadelphia Electric Co 83/06/06. BRENNER, I., MORRIS, P. A., COLE, R. F. Atomic Safety and Licensing Board Panel. 11pp 18796-103 24X Fiche. 50-352, 83/06/06, 8306090212.

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/09 Consolidated Edison Co. of New York, Inc. 119pp. 18830-280 24X Fiche 50-000, 83/06/09, 8305110464.

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/13 Consolidated Edison Co. of New York, Inc. 118pp 18920-225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/13. Consolidated Edison Co. of New York, Inc. 245pp 18921-001. 24X Fiche. 50-000, 83/06/13, 8306090010

8306200317 Forwards draft responses to NRC draft SER Questions 250 I, 250.2, 250.3, 250.4 & 250.5 re preservice insp of reactor pressure vessels, pumps & valves Responses will be incorporated in Jul 1983 FBAR rev
BRADLEY, E. J. Philadelphia Electric Co. 83/06/14 SCHWENCER, A. Licensing Branch 2. 3pp. 18899 212 24X Fiche. 50-352, 83/06/14, 8306200317.

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/22. Consolidated Edison Co. of New York, Inc. 115pp. 19021:179. 24X Fiche. 50-000, 83/06/22, 8305110475.

8305110477 IE Info Notice 83-41, "Activation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp. 18997-007. 24X Fiche: 50-000, 83/06/22, 8305110477.

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/23 Consolidated Edison Co. of New York, Inc. 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/24 Consolidated Edison Co. of New York, Inc. 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

B Reportable occurrences, LERs & related correspondence

8306100092 Part 21 rept re potential incorrect interface w/reactor pressure vessel instrument piping Caused by error on four local instrument panel piping diagrams Field deviation disposition requests issued No operating plants affected
SHERROD, G. O. General Electric Co 82/11/18 DEVOUNO, R. C. Director's Office, Office of Inspection and Enforcement 3pp 18802 226 24X Fiche 50-352, 82/11/18, 8306100092

8306280417 Part 21 Deficiency Rept 80 re damaged insulation on MCC Powers Co shielded multiconductor cable on HVAC control panels. Also reported by MCC Power
KEMPER, J. B. Philadelphia Electric Co 83/06/01 MURLEY, T. E. Region I, Office of Director. 1p 19020 296 24X Fiche. 50-352, 83/06/01, 8306280417

V Operator Examinations

8306140449 Requests attendance at 830627 meeting in King of Prussia, PA to discuss transfer of operating reactor licensing function from Bethesda, MD to Region I of
STAROSTECKI, R. Division of Project & Resident Programs 83/06/09
KEMPER, J. B. Philadelphia Electric Co 2pp 18836 345 24X Fiche 50-352, 83/06/09, 8306140449

DOCKET 50-353 LIMERICK GENERATING STATION, UNIT 2

A Application/construction stage documents & correspondence

8306030086 Notification of 830525 meeting w/util in Bethesda, MD to resolve issues re accident evaluation identified in NRC
830311 ltr
MARTIN, R. E. Licensing Branch 2 83/05/20 SCHWENCER, A. Licensing Branch 2 4pp 18733 269 24X Fiche 50-352, 83/05/20, 8306030086

8306010292 Forwards draft changes to FBAR, design assessment rept & to previously provided responses in answer to issues 5b, 5c, 5d, 5e & 20 discussed at 830407 meeting Rept on functionality of purge & vent valves will be submitted in June 1983
BRADLEY, E. J. Philadelphia Electric Co 83/05/26 SCHWENCER, A. Licensing Branch 2 75pp 18678 304 24X Fiche 50-352, 83/05/26, 8306010292

8306020649 Notification of 830608 meeting w/util & BMNL in Bethesda, MD to discuss severe accident risk assessment (SARA)
MARTIN, R. E. Licensing Branch 2 83/05/27 SCHWENCER, A. Licensing Branch 2 4pp 18716 271 24X Fiche 50-352, 83/05/27, 8306020649

8306010233 Forwards application for Amend 51 to DL application (filed in Category A) consisting of environ qualification rept, Rev 20 to FBAR (filed in Category K) & Rev 13 to environ rept (filed in Category C)
BRADLEY, E. J. Philadelphia Electric Co 83/05/31 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 3pp 18675 001 24X Fiche. 50-352, 83/05/31, 8306010233.

--8306010237 Application for Amend 51 to DL application, consisting of Rev 20 to FBAR, environ qualification rept & Rev 13 to environ rept
BAUER, E. G. Philadelphia Electric Co 83/05/24 4pp 18675 004 24X Fiche. 50-352, 83/05/31, 8306010233

8306090196 Notification of 830608 meeting w/util & Bechtel in San Francisco, CA to discuss outstanding items in structural engineering review area
MARTIN, R. E. Licensing Branch 2 83/06/02 SCHWENCER, A. Licensing Branch 2. 3pp 18809 252 24X Fiche. 50-352, 83/06/02, 8306090196

8306070239 Forwards revised draft response to Question 410 17 re CP application compliance w/NUREG-0800 per 830330 meeting w/NRC Changes will be incorporated in FBAR rev scheduled for June 1983.
BRADLEY, E. J. Philadelphia Electric Co 83/06/03 SCHWENCER, A. Licensing Branch 2 3pp. 18747 048 24X Fiche. 50-352, 83/06/03, 8306070239.

8306100109 Forwards revised draft response to Question 430 4B re level of training for operators, maint crew & QA personnel Response will be incorporated into FBAR rev scheduled for Jul 1983
BRADLEY, E J Philadelphia Electric Co 83/06/06 SCHWENCER, A
Licensing Branch 2 6pp 18802 205 24X Fiche 50-352, 83/06/06, 8306100109

8306100065 Forwards draft FBAR change re breed line depressurization branch per Accident Evaluation Branch request Change will be incorporated into Jul 1983 FBAR rev
BRADLEY, E J Philadelphia Electric Co 83/06/07 SCHWENCER, A
Licensing Branch 2 3pp 18803 069 24X Fiche 50-352, 83/06/07, 8306100065

8306100241 Forwards revised draft response to FBAR mgt technology section re licensed operator courses & operating activities transmitted in 830506 ltr, per 830527 request Changes will be incorporated into FBAR rev scheduled for Jul 1983
BRADLEY, E J Philadelphia Electric Co 83/06/07 SCHWENCER, A
Licensing Branch 2 4pp 18807 053 24X Fiche 50-352, 83/06/07, 8306100241

8306150321 Forwards request for addl info re FBAR Design Criteria Summary, Item 260 56 reflecting requirements of NUREG-0797, "Clarification of TMI Action Plan Requirements"
SCHWENCER, A Licensing Branch 2 83/06/07 BAUER, E G
Philadelphia Electric Co 7pp 18870 010 24X
Fiche 50-352, 83/06/07, 8306150321

8306160340 Responds to QA Branch 830527 telcon request re proposed organization change in Electric Production Dept reflecting change in QC Program for Operational Phase
DALTRDFF, S L Philadelphia Electric Co 83/06/07 SCHWENCER, A
Licensing Branch 2 8pp 18859 082 24X Fiche 50-352, 83/06/07, 8306160340

8306160310 Forwards final response to NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants-Resolution of TAP A-36"
Response includes analyses for loads handled over reactor vessel
KEMPER, J S Philadelphia Electric Co 83/06/13 EISENHUT, D G
Division of Licensing 126pp 18860 243 24X Fiche 50-352, 83/06/13, 8306160310

8306160377 Forwards rev to Page 1 2 of 830531 environ qualification rept, to be formally incorporated into Oct 1983 rept rev
BRADLEY, E J Philadelphia Electric Co 83/06/13 SCHWENCER, A
Licensing Branch 2 3pp 18861 123 24X Fiche 50-352, 83/06/13, 8306160377

8306170210 Forwards draft responses to requests for addl info Questions 252 1 through 252 7 & related draft FBAR text changes. Draft changes will be incorporated in FBAR in rev scheduled for Jul 1983
BRADLEY, E J Philadelphia Electric Co 83/06/14 SCHWENCER, A
Licensing Branch 2 100pp 18883 153 24X Fiche 50-352, 83/06/14, 8306170210

8306170309 Provides marked-up draft FBAR pages per QA Branch 830527 request for addl info Page changes will be incorporated in FBAR rev scheduled for Jul 1983
BRADLEY, E J Philadelphia Electric Co 83/06/14 SCHWENCER, A
Licensing Branch 2 16pp 18877 113 24X Fiche 50-352, 83/06/14, 8306170309

8306210418 Notification of 830615 meeting w/util, Bechtel & QE in Bethesda, MD to discuss high radiation isolation signals on containment purge/vent valves
MARTIN, R E Licensing Branch 2 83/06/14 SCHWENCER, A
Branch 2 4pp 18937 065 24X Fiche 50-352, 83/06/14, 8306210418

8306200117 Forwards response to Matls Engineering Branch 830603 request for info re turbine missile issue.
BRADLEY, E J Philadelphia Electric Co 83/06/15 SCHWENCER, A
Licensing Branch 2 3pp 18903 247 24X Fiche 50-352, 83/06/15, 8306200117

8306210220 Forwards matl presented at Anderson, Greenwood & Co (AGCo) vacuum breaker test program owners group 830607 meeting w/ NRC re dynamic testing & analysis of AGCo vacuum breaker valve assemblies
O'CONNOR, D M Bechtel Corp 83/06/17 HOUSTON, R W Division of Systems Integration (post 811003) 91pp 18919 038 24X
Fiche 50-000, 83/06/17, 8306210220

8306240412 Notification of 830621-24 meetings w/util, Bechtel & QE in San Jose & San Francisco, CA to discuss outstanding items in Matls Engineering Branch review of compliance w/QDC 51
MARTIN, R E Licensing Branch 2 83/06/17 SCHWENCER, A
Branch 2 4pp 18978 013 24X Fiche 50-352, 83/06/17, 8306240412

8306230276 Responds to NRC 830523 request for proposed resolution to TMI Item 11 K 3 18, "Mod of Automatic Depressurization Sys Logic" Justification for bypass timer setting will be provided prior to implementation of mod
KEMPER, J S Philadelphia Electric Co 83/06/20 SCHWENCER, A
Licensing Branch 2 3pp 18945 135 24X Fiche 50-352, 83/06/20, 8306230276

8306270212 Forwards revs to FBAR Sections 9 5 & 3, 7, 2, B 3 & 9 5-10, Info will be incorporated into rev to FBAR scheduled for Jul 1983
BRADLEY, E J Philadelphia Electric Co 83/06/21 SCHWENCER, A
Licensing Branch 2 10pp 18990 252 24X Fiche 50-352, 83/06/21, 8306270212

8306270365 Forwards revised draft response to FBAR Question 410 70 re design temp for essential svc water & RHR svc water sys
Draft change will be incorporated into FBAR rev scheduled for Jul 1983
BRADLEY, E J Philadelphia Electric Co 83/06/21 SCHWENCER, A
Licensing Branch 2 6pp 18993 193 24X Fiche 50-352, 83/06/21, 8306270365

8306270423 Forwards draft FBAR changes prepared in response to Containment Sys Branch Open Item 18 Changes state isolation valves will be sealed closed, Info will be incorporated into FBAR rev scheduled for Jul 1983
BRADLEY, E J Philadelphia Electric Co 83/06/23 SCHWENCER, A
Licensing Branch 2 7pp 18992 126 24X Fiche 50-352, 83/06/23, 8306270423

8306270459 Forwards draft revised responses to NRC Questions 410 05, 410 10, 410 37, 410 52, 410 85 & 410 89, per telcon w/Auxiliary Sys Branch Responses will be incorporated in FBAR scheduled for Jul 1983
BRADLEY, E J Philadelphia Electric Co 83/06/23 SCHWENCER, A
Licensing Branch 2 20pp 18992 075 24X Fiche 50-352, 83/06/23, 8306270459

8306300024 Responds to 830609 request for addl info, forwarding documents used by Structural Mechanics Assoc in seismic fragility development
BRADLEY, E J Philadelphia Electric Co 83/06/27 SCHWENCER, A
Division of Licensing 200pp 19114 250 24X Fiche 50-352, 83/06/27, 8306300024

8306300221 Forwards draft FBAR changes re loose parts monitoring sys for rev scheduled for Jul 1983 Detailed sys description per Reg Guide 1 193 submitted, pending receipt of BER
BRADLEY, E J Philadelphia Electric Co 83/06/27 SCHWENCER, A
Licensing Branch 2 7pp 19120 001 24X Fiche 50-352, 83/06/27, 8306300221

8306300133 Forwards draft revised response to TMI Item 1 Q 1, "Training During Low-Power Testing," per 830627 conference call Info contained in draft revised response will be incorporated into FBAR rev scheduled for Aug 1983
BRADLEY, E J Philadelphia Electric Co 83/06/28 SCHWENCER, A
Licensing Branch 2 5pp 19122 311 24X Fiche 50-352, 83/06/28, 8306300133

C Utility Environmental Report (ER), amends & correspondence

8306010233 Forwards Rev 13 to environ rept.
BRADLEY, E J Philadelphia Electric Co 83/05/31 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 18675 001
24X Fiche 50-352, 83/05/31, 8306010233

--8306010243 Rev 13 to environ rept. Environ qualification rept for safety-related equipment encl
* Philadelphia Electric Co 83/05/31 237pp, 18675 010 24X
Fiche 50-352, 83/05/31, 8306010243

8306210283 Forwards Affidavit of Bvc re distribution of Rev 20 to FBAR, Rev 13 to environ rept & Rev 3 to fire protection evaluation rept.
BRADLEY, E J Philadelphia Electric Co 83/06/17 DENTON, H R
Office of Nuclear Reactor Regulation, Director 5pp 18915 022
24X Fiche 50-352, 83/06/17, 8306210283

E NRC Safety Evaluation Report (SER), suppls & correspondence

8306070330 Forwards responses to listed Procedures & Test Review Branch SER open items Draft response to TMI Item 1 C 1, "Operating & Maint Procedures & ATWS," incorporated in May FBAR rev.
BRADLEY, E J Philadelphia Electric Co 83/06/03 SCHWENCER, A
Licensing Branch 2 4pp 18746 065 24X Fiche 50-352, 83/06/03, 8306070330

DOCKETED ITEMS

8306150579 Forwards request for addl info re SER open items Action plan & associated dates for response required within 7 working days of receipt of ltr
SCHWENCER, A Licensing Branch 2 83/06/03 BAUER, E O
Philadelphia Electric Co 24pp. 18867 038. 24X
Fiche. 50-352, 83/06/03, 8306150579.

8306100110 Forwards final response to Reactor Sys Branch draft SER Item 3 re high/low pressure interlocks on ECCS injection valves, per discussion at 830517 meeting in Bethesda, MD
BRADLEY, E. J. Philadelphia Electric Co 83/06/07 SCHWENCER, A
Licensing Branch 2 4pp 18802-201 24X Fiche 50-352, 83/06/07, 8306100110

8306140545 Responds to Geotechnical Engineering Branch draft SER open items transmitted via 830311 ltr. Properties of foundation bedrock, backfill, lateral loading & response of in-situ soil & backfill mats to dynamic loading discussed
BRADLEY, E. J. Philadelphia Electric Co 83/06/09 SCHWENCER, A.
Licensing Branch 2 25pp 18834 179 24X Fiche 50-352, 83/06/09, 8306140545

8306140604 Forwards response to Structural Engineering Branch draft SER Open Items 1, 4, 8 & 9. All open items closed out Items 1, 4 & 8 represent formal response while Item 9 indicates FSAR page changes
BAUER, E. O. Philadelphia Electric Co 83/06/10 SCHWENCER, A
Licensing Branch 2 38pp 18833 061. 24X Fiche: 50-352, 83/06/10, 8306140604.

8306140624 Forwards draft responses to SER Open Items 2, 7, 9, 11, 12, 16, 18, 19, 21, 27 & 34 re fire protection. Fire protection evaluation rept will be submitted in Aug 1983
BRADLEY, E. J. Philadelphia Electric Co 83/06/10 SCHWENCER, A
Licensing Branch 2. 33pp, 18833 326 24X Fiche 50-352, 83/06/10, 8306140624.

8306160001 Forwards draft FSAR page changes, in response to Reactor Sys Branch draft SER Item 1, "DDYN Analysis of Pressurization Transients." Changes will be incorporated into FSAR rev scheduled for Jul 1983
BRADLEY, E. J. Philadelphia Electric Co 83/06/13 SCHWENCER, A
Licensing Branch 2 58pp 18862, 025 24X Fiche. 50-352, 83/06/13, 8306160001

8306160371 Forwards draft responses & draft FSAR page changes in response to Meteorology & Effluent Treatment Branch draft SER Items 2, 4, 5 & Request for Addl Info RAI 431, 14
BRADLEY, E. J. Philadelphia Electric Co 83/06/13 SCHWENCER, A
Licensing Branch 2 43pp. 18864 164. 24X Fiche. 50-352, 83/06/13, 8306160371.

8306160527 Forwards response to Core Performance Branch draft SER Draft page changes will be included in FSAR rev scheduled for Jul 1983.
BRADLEY, E. J. Philadelphia Electric Co 83/06/13 SCHWENCER, A.
Licensing Branch 2 91pp, 18863-140 24X Fiche 50-352, 83/06/13, 8306160527

8306160572 Forwards draft SER, Section II, "Test Review," Item 2, consisting of FSAR changes to be incorporated into FSAR rev scheduled for Jul 1983
BRADLEY, E. J. Philadelphia Electric Co 83/06/13 SCHWENCER, A.
Licensing Branch 2. 73pp. 18866 211 24X Fiche. 50-352, 83/06/13, 8306160572

8306170369 Forwards response to Accident Evaluation Branch draft SER, per 830525 meeting request. Draft page changes will be included in FSAR rev scheduled for Jul 1983
BRADLEY, E. J. Philadelphia Electric Co. 83/06/14. SCHWENCER, A.
Licensing Branch 2 17pp. 18880-193. 24X Fiche. 50-352, 83/06/14, 8306170369

8306200317 Forwards draft responses to NRC draft SER Questions 250 1, 250, 2, 250, 3, 250, 4 & 250, 5 re preservice insp of reactor pressure vessels, pumps & valves. Responses will be incorporated in Jul 1983 FSAR rev.
BRADLEY, E. J. Philadelphia Electric Co 83/06/14 SCHWENCER, A
Licensing Branch 2. 31pp 18879; 212. 24X Fiche 50-352, 83/06/14, 8306200317.

8306240418 Notification of 830624 meeting w/ util & OE in Bethesda, MD to discuss Effluent Treatment Sys Branch open SER items
MARTIN, R. E Licensing Branch 2. 83/06/20 SCHWENCER, A Licensing
Branch 2. 4pp. 18978: 007. 24X Fiche: 50-352, 83/06/20, 8306240418.

8306270086 Forwards revised draft responses to Question 480 7, including revised Section 6.2.6.3.1 & Table 14.2-4 in response to Containment Sys Branch draft SER Issue 1 & revised draft Section 6.2.3.2.3 & Table 6.2-15
BRADLEY, E. J. Philadelphia Electric Co 83/06/21. SCHWENCER, A.
Licensing Branch 2. 23pp. 19013-125. 24X Fiche: 50-352, 83/06/21, 8306270086.

8306270319 Provides response to structural engineering review draft SER open items discussed & resolved at 830603 meeting re response spectra, reactor encl & control structure
KEMPER, J. B Philadelphia Electric Co 83/06/21 SCHWENCER, A
Licensing Branch 2 19pp 18974 010 24X Fiche 50-352, 83/06/21, 8306270319

8306270340 Forwards revised Table 6.2-17, adding power sources in containment penetration, in response to Containment Sys Branch draft SER Issue 15 Info will be incorporated into FSAR scheduled for Jul 1983
BRADLEY, E. J Philadelphia Electric Co 83/06/23 SCHWENCER, A
Licensing Branch 2 8pp 18991 210 24X Fiche 50-352, 83/06/23, 8306270340

8306280381 Forwards calculate post-LOCA bounding drywell temp profile, per 830510 Rev 20 changes to FSAR Section 3.11 in response to Containment Sys Branch draft SER, Item 4
KEMPER, J. B Philadelphia Electric Co 83/06/24 SCHWENCER, A
Licensing Branch 2 4pp 19014 063 24X Fiche 50-352, 83/06/24, 8306280381

8306300016 Forwards draft rev to response to Question 640 10 re low power & power ascension testing, providing info necessary to close Item 5 of draft SER, Section II, "Test Review" Info will be included in FSAR rev scheduled for Jul 1983
BRADLEY, E. J Philadelphia Electric Co 83/06/27 SCHWENCER, A
Licensing Branch 2 3pp 19120 252 24X Fiche 50-352, 83/06/27, 8306300016

8306300200 Forwards list of Auxiliary Sys Branch open SER issues per 830623 meeting & marked-up draft FSAR pages responding to issues
BRADLEY, E. J. Philadelphia Electric Co 83/06/28 SCHWENCER, A
Licensing Branch 2 51pp 19122 126 24X Fiche 50-352, 83/06/28, 8306300200

F Security, medical, emergency & fire protection plans

8306140395 Forwards draft change to FSAR re emergency ac lighting, per 830607 telcon commitment Change will be formally incorporated into FSAR rev scheduled for Jul 1983
BRADLEY, E. J Philadelphia Electric Co 83/06/10 SCHWENCER, A
Licensing Branch 2 4pp 18832 089 24X Fiche 50-352, 83/06/10, 8306140395

8306140624 Forwards draft responses to SER Open Items 2, 7, 9, 11, 12, 16, 18, 19, 21, 27 & 34 re fire protection. Fire protection evaluation rept will be submitted in Aug 1983
BRADLEY, E. J Philadelphia Electric Co 83/06/10 SCHWENCER, A
Licensing Branch 2 33pp 18833 326 24X Fiche 50-352, 83/06/10, 8306140624

8306200183 Forwards draft changes to FSAR Section 9.5.3.2.2 & Question 430 61 re outdoor security & roadway lighting. Changes will be incorporated into FSAR rev scheduled for Jul 1983
BRADLEY, E. J Philadelphia Electric Co 83/06/15 SCHWENCER, A
Licensing Branch 2 5pp 18903 173 24X Fiche 50-352, 83/06/15, 8306200183

8306210283 Forwards Affidavit of Svc re distribution of Rev 20 to FSAR, Rev 13 to environ rept & Rev 3 to fire protection evaluation rept
BRADLEY, E. J Philadelphia Electric Co 83/06/17 DENTON, H. R
Office of Nuclear Reactor Regulation, Director 5pp 18915.022
24X Fiche 50-352, 83/06/17, 8306210283

O Adjudicatory correspondence

8306010464 Discusses IE Insp Rept 50-353/76-06 re inaccessible welds. Welds capriciously & unilaterally declared acceptable following convenient & unscientific decision that welds cannot be inspected due to inaccessibility
ROMANO, F. R Air and Water Pollution Patrol 83/05/25 Atomic
Safety and Licensing Board Panel 2pp 18679 319. 24X
Fiche. 50-352, 83/05/25, 8306010464

8306010372 Forwards motion for reconsideration of ASLB 830509-11 ruling re coordination of contention filing w/ Limerick Ecology Action.
AU, T. Y Pennsylvania, Commonwealth of, 83/05/26 BRENNER, L.,
MORRIS, P. A., COLE, R. F Atomic Safety and Licensing Board Panel 1p
18682.091. 24X Fiche. 50-352, 83/05/26, 8306010372

--8306010380 Motion for reconsideration of ASLB 830509-11 rulings re coordination of contention filing w/ Limerick Ecology Action
Ruling undermines role of state in presenting issues in neutral manner. Certificate of Svc encl
AU, T. Y Pennsylvania, Commonwealth of, 83/05/26 Atomic
Safety and Licensing Board Panel 11pp. 18682.092. 24X
Fiche 50-352, 83/05/26, 8306010372

DOCKETED ITEMS

215

8306010369 Petition to withdraw as intervenor representative in OL proceeding RJ Sugarman will continue to represent intervenor Draft order encl
NEILL, J M Del-Aware Unlimited, Inc 83/05/31 Atomic Safety and Licensing Board Panel 2pp 18482 105 24X Fiche 50-352, 83/05/31, 8306010369

8306030280 Response supporting NRC reply to ASLB 830516 order re use of PRA & subsequent risk-related documents Certificate of Svc & RK Weatherwax prof qualifications encl
DORSEY, J A Limerick Ecology Action DORSEY, J A Dorsey, J A 83/05/31 Atomic Safety and Licensing Board Panel 27pp 18705 187 24X Fiche 50-352, 83/05/31, 8306030280

8306020351 Memorandum & order denying Del-Aware 830308 motion to reopen record & add proposed new Contention V-26 Contention is not significant & would not affect outcome of decision
BRENNER, L Atomic Safety and Licensing Board Panel 83/06/01 Del-Aware Unlimited, Inc 11pp 18694 247 24X Fiche 50-352, 83/06/01, 8306020351

8306030286 Order granting JM Neill petition to withdraw appearance request.
BRENNER, L Atomic Safety and Licensing Board Panel 83/06/01 1p 18703 331 24X Fiche 50-352, 83/06/01, 8306030286

8306060322 Advises that Bucks County, PA citizens voted for County withdrawal from further participation in Point Pleasant Diversion Project intended to supply supplemental cooling water to plant Referendum does not affect contractor rights
CONNER, T B Conner & Wetterhahn CONNER, T B Philadelphia Electric Co 83/06/02 KOHL, C N, EDLEB, G J, OOTCHY, R L Atomic Safety and Licensing Appeal Panel 13pp 18729 172 24X Fiche 50-352, 83/06/02, 8306060322

8306060330 Order scheduling resumed appellate process matters Exceptions to ASLB 830601 order, denying Del-Aware 830308 motion, due 830616 Briefs supporting all exceptions due 830718
SHOMAKER, C J Atomic Safety and Licensing Appeal Panel 83/06/02, 2pp 18726 361 24X Fiche 50-352, 83/06/02, 8306060330

8306070295 First set of interrogatories & request for production of documents
WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 83/06/03 Air and Water Pollution Patrol Bpp 18741 186 24X Fiche 50-352, 83/06/03, 8306070295

--8306070297 First set of interrogatories & request for production of documents
WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 83/06/03 Friends of the Earth 9pp 18741, 194 24X Fiche 50-352, 83/06/03, 8306070295

--8306070301 First set of interrogatories & request for production of documents Certificate of Svc encl
WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 83/06/03 LEWIS, M I Lewis, M 9pp 18741 203, 24X Fiche 50-352, 83/06/03, 8306070295

8306090212 Forwards Attachments 2 & 3 to 830520 1tr Attachments may have been miscolated or incomplete.
WETTERHAHN, M J Conner & Wetterhahn WETTERHAHN, M J Philadelphia Electric Co 83/06/06 BRENNER, L, MORRIS, P A, COLE, R F Atomic Safety and Licensing Board Panel 11pp, 18796 103 24X Fiche 50-352, 83/06/06, 8306090212

8306090240 Motion for extension until 830610 to respond to NRC use of Facility PRA, Filing allowed per ASLB 830516 order confirming schedules Certificate of Svc encl
WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 83/06/06 Atomic Safety and Licensing Board Panel 4pp 18795 328 24X Fiche 50-352, 83/06/06, 8306090240.

8306080167 Order granting until 830606 motion for extension until 830610 to file response to NRC & Limerick Ecology Action filings on PRA contentions. Parties consent & good cause shown.
BRENNER, L Atomic Safety and Licensing Board Panel 83/06/07, Philadelphia Electric Co, 1p 18772 154, 24X Fiche: 50-352, 83/06/07, 8306080167

8306090301 Order extending time until 830627 for Commission to act to revise ALAB-726.
CHILK, S J Office of the Secretary of the Commission 83/06/07, Commissioners 1p, 18795:241, 24X Fiche 50-352, 83/06/07, 8306090301

8306100195 Order requiring NRC to update schedule estimate for issuance of DEB, All parties under duty to inform ASLB of any change in meet info
BRENNER, L Atomic Safety and Licensing Board Panel 83/06/09 Commissioners 2pp, 18806:017, 24X Fiche: 50-352, 83/06/09, 8306100195.

8306130366 Advises that if Pennsylvania Emergency Mgt Agency draft emergency plans available by 831113, FEMA would complete review by mid Feb 1984 FEMA will expedite review & should be placed on svc list
VOGLER, B H Hearing Branch 2 83/06/09 BRENNER, L, MORRIS, P A, COLE, R F Atomic Safety and Licensing Board Panel 2pp 18821, 268 24X Fiche 50-352, 83/06/09, 8306130366

8306140676 Responds to request for definition of safety classification terms by transmitting relevant portions of ASLB 830526 Decision ALAB-729
HODGDON, A P Hearing Branch 2 83/06/10 LEWIS, M I Lewis, M 6pp 18842 069 24X Fiche 50-352, 83/06/10, 8306140676

8306140715 Response to first set of interrogatories on pressurized thermal shock, Contention I-62 Certificate of Svc encl
HODGDON, A P Hearing Branch 2 83/06/10 Lewis, M 27pp 18841 296 24X Fiche 50-352, 83/06/10, 8306140715

8306140722 Responds to ASLB 830609 order requiring NRC to update schedule for DEB issuance Schedule unchanged since dates set at 830509-11 second special prehearing conference, DEB, except Chapter 7, to be published on 830613
HODGDON, A P Hearing Branch 2, 83/06/10 BRENNER, L, MORRIS, P A, COLE, R F Atomic Safety and Licensing Board Panel 2pp 18841:094 24X Fiche 50-352, 83/06/10, 8306140722

8306150362 Discusses Contentions I-33D, D, E, K & I-45 re TMI Action Plan Items I C & I D I, I D I, I I F, I, I, D 3 & I I B, 2. Contentions denied w/o prejudice by ASLB 830516 memorandum & order, for lack of specificity
DORSEY, J A Dorsey, J A DORSEY, J A Limerick Ecology Action 83/06/10 BRENNER, L, MORRIS, P A, COLE, R F Atomic Safety and Licensing Board Panel 2pp, 18847 149 24X Fiche 50-352, 83/06/10, 8306150362

8306150393 Response to NRC use of facility PRA & Limerick Ecology Action response to ASLB 830516 memorandum & order confirming schedules Certificate of Svc encl
WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 83/06/10 Atomic Safety and Licensing Board Panel, 11pp, 18847 159, 24X Fiche 50-352, 83/06/10, 8306150393

8306160603 Forwards until answer to MI Lewis first set of interrogatories on pressurized thermal shock contention.
WETTERHAHN, M J Conner & Wetterhahn WETTERHAHN, M J Philadelphia Electric Co 83/06/13 LEWIS, M I Lewis, M 1p 18866:144, 24X Fiche 50-352, 83/06/13, 8306160603.

--8306160609 Answers to first set of interrogatories on pressurized thermal shock contention, Certificate of Svc encl
BOYER, V B Philadelphia Electric Co 83/06/09 LEWIS, M I Lewis, M 16pp 18866 149 24X Fiche 50-352, 83/06/13, 8306160603

8306220043 Answer to first set of interrogatories re pressurized thermal shock in BWRs.
LEWIS, M I Lewis, M 83/06/15 Philadelphia Electric Co, 2pp 18926 255 24X Fiche 50-352, 83/06/15, 8306220043

8306220051 Files addl exceptions to ASLB 830601 order refusing to consider Interstate Delaware River Mgt 830517 recommendations & referendum, Certificate of Svc encl
SUGARMAN, R J Del-Aware Unlimited, Inc SUGARMAN, R J, Sugarman, R J 83/06/16 Atomic Safety and Licensing Appeal Panel, 5pp, 18926, 198 24X Fiche 50-352, 83/06/16, 8306220051.

8306220103 Forwards Commonwealth of PA Supreme Court decision, unanimously reversing Commonwealth Court & holding that PUC of PA acted within power & acted properly when ordering until to cancel or suspend const of Unit 2.
SUGARMAN, R J Sugarman, R J 83/06/16 BRENNER, L, COLE, R F, MORRIS, P A Atomic Safety and Licensing Board Panel, 16pp 18926 038 24X Fiche 50-352, 83/06/16, 8306220103.

8306270297 Forwards onsite emergency planning contentions, in response to ASLB 830516 memorandum of order.
DORSEY, J A Dorsey, J A 83/06/17 BRENNER, L, COLE, R F, MORRIS, P A Atomic Safety and Licensing Board Panel, 35pp, 18995:170 24X Fiche 50-352, 83/06/17, 8306270297.

--8306270300 Onsite emergency planning contentions Certificate of Svc encl
* Limerick Ecology Action, 83/06/17 32pp 18995:172 24X Fiche 50-352, 83/06/17, 8306270297

8306270038 Answer to first set of interrogatories, Related correspondence.
ANTHONY, R C Friends of the Earth ANTHONY, R C Anthony, R L, 83/06/20, Philadelphia Electric Co, 2pp, 18988:135, 24X Fiche: 50-352, 83/06/20, 8306270038

DOCKETED ITEMS

8306290344 Discusses Air & Water Pollution Patrol response to util
830606 interrogatories Related correspondence.
ROMANO, F. R. Air and Water Pollution Patrol. 83/06/21 BRENNER, L.,
COLE, R. F., MORRIS, P. A. Atomic Safety and Licensing Board Panel 1p
19055.226 24X Fiche 50-352, 83/06/21, 8306290344

8306290909 Response to 830606 interrogatories, Related correspondence
ROMANO, F. R. Air and Water Pollution Patrol. 83/06/21 Atomic
Safety and Licensing Board Panel 5pp 19052-209. 24X
Fiche 50-352, 83/06/21, 8306290909

8306270413 Advises that util does not object to Limerick Ecology Action
position in 830610 ltr on contentions related to NUREG-0737.
WETTERHAHN, M. J. Conner & Wetterhahn WETTERHAHN, M. J. Philadelphia
Electric Co. 83/06/23 BRENNER, L., MORRIS, P. A., COLE, R. F. Atomic
Safety and Licensing Board Panel. 2pp 18994 146 24X
Fiche 50-352, 83/06/23, 8306270413

8306280566 Responds to Del-Aware 830616 ltr ABLB requesting admittance
of new contention Del-Aware failed to comply w/procedure
re late-filed contentions.
HODGSON, A. P. Hearing Branch 2. 83/06/27 BRENNER, L., MORRIS, P. A.,
COLE, R. F. Atomic Safety and Licensing Board Panel 2pp. 19017.330
24X Fiche 50-352, 83/06/27, 8306280566

8306300143 Advises that time for Commission to review ALAB-72d expired
Commission declined review Decision became final agency
action on 830627.
CHTLK, B. J. Office of the Secretary of the Commission 83/06/29.
Office of the Executive Legal Director 1p 19168 117 24X
Fiche 50-352, 83/06/29, 8306300143

H General correspondence

8306020380 Requests further discussion of 10CFR50.54(x) & (y) re single
failure criterion. Issue of common mode failure of all
solenoids litigable
LEWIS, M. I. Lewis, M. 83/05/26 TRAMMELL, C. M. NRC - No Detailed
Affiliation Given. 2pp. 18694.362. 24X Fiche 50-352, 83/05/26,
8306020380

8306170387 Opposes OL issuance until local officials agree upon
acceptable emergency plan providing adequate protection to
affected population.
HORDIS, B. A. Affiliation Unknown 83/06/09 BRENNER, L. Atomic
Safety and Licensing Board Panel. 1p 18880.070 24X
Fiche 50-352, 83/06/09, 8306170387

K Utility Final Safety Analysis Report (FSAR) & amendments

8306010233 Forwards Rev 20 to FSAR.
BRADLEY, E. J. Philadelphia Electric Co. 83/05/31. DENTON, H. R.
Office of Nuclear Reactor Regulation, Director. 3pp. 18675.001.
24X Fiche 50-352, 83/05/31, 8306010233

8306010240 Rev 20 to FSAR
* Philadelphia Electric Co. 83/05/31. 10pp. 18675.247 24X
Fiche 50-352, 83/05/31, 8306010233

8306210283 Forwards Affidavit of SVC re distribution of Rev 20 to FSAR,
Rev 13 to environ rept & Rev 3 to fire protection evaluation
rept.
BRADLEY, E. J. Philadelphia Electric Co. 83/06/17. DENTON, H. R.
Office of Nuclear Reactor Regulation, Director. 3pp. 18915.022
24X Fiche 50-352, 83/06/17, 8306210283.

Q Inspection reports, IE Bulletins & correspondence

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in
Well Logging Device " Svc list encl
TAYLOR, J. M. Division of Safeguards & Inspection Programs (Post
830103). 83/05/26. Consolidated Edison Co. of New York, Inc.
125pp 18831.043 24X Fiche 50-000, 83/05/26, 8305110458.

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet."
Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/05/26. Consolidated Edison Co. of New
York, Inc. 115pp. 18732.085. 24X Fiche 50-000, 83/05/26, 8305110460.

8306090140 Forwards IE Insp Repts 50-352/83-05 & 50-353/83-02 on
830319-0422 & notice of violation.
STAROSTECKI, R. Division of Project & Resident Programs. 83/05/26.
KEMPER, J. B. Philadelphia Electric Co. 2pp. 18792.259. 24X
Fiche 50-352, 83/05/26, 8306090140.

8306090151 IE Insp Repts 50-352/83-05 & 50-353/83-02 on 830319-0422
Noncompliance noted separation requirement for electrical
raceway (cable trays) not verified & GC instruction did not
include appropriate insp methods for conduit bends
CHAUDHARY, S. K., PAOLINO, R. J., NICHOLAS, H. H. Region 1, Office of
Director 83/05/26 7pp 18792.263 24X Fiche 50-352, 83/05/26,
8306090140

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods
Withdrawn at BWRs " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/05/31. Consolidated Edison Co. of New
York, Inc. 116pp. 18732.208 24X Fiche 50-000, 83/05/31, 8305110461.

8306150237 Forwards IE Insp Repts 50-352/83-07 & 50-353/83-04 on
830424-0528 No noncompliance noted
STAROSTECKI, R. Division of Project & Resident Programs 83/06/02
KEMPER, J. B. Philadelphia Electric Co. 2pp 18846.011 24X
Fiche 50-352, 83/06/02, 8306150237

8306150247 IE Insp Repts 50-352/83-07 & 50-353/83-04 on 830424-0528. No
noncompliance noted Major areas inspected control rod drive
supports, followup of Part 21 repts, design change control &
personnel training
CHAUDHARY, S. K., GRANT, J. M., CONNER, E. L. Region 1, Office of
Director 83/06/02 3pp 18846.013 24X Fiche 50-352, 83/06/02,
8306150237

8306090212 Forwards Attachments 2 & 3 to 830520 ltr Attachments may
have been miscollocated or incomplete
WETTERHAHN, M. J. Conner & Wetterhahn 83/06/06 BRENNER, L. Atomic
Safety and Licensing Board Panel 11pp 18796.103 24X
Fiche 50-352, 83/06/06, 8306090212

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe
Operations " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/06/09. Consolidated Edison Co. of New
York, Inc. 119pp. 18830.280 24X Fiche 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive &
Seismically Induced Chatter in Relays Within Printed
Circuit Cards " Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/06/13. Consolidated Edison Co. of New
York, Inc. 118pp 18920.225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From
Degraded Internal Connection Cables " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/06/13. Consolidated Edison Co. of New
York, Inc. 243pp. 18921.001 24X Fiche 50-000, 83/06/13, 8306090010

8306200317 Forwards draft responses to NRC draft SER Questions 250.1,
250.2, 250.3, 250.4 & 250.5 re preservice insp of reactor
pressure vessels, pumps & valves Responses will be
incorporated in Jul 1983 FSAR rev
BRADLEY, E. J. Philadelphia Electric Co. 83/06/14. SCHWENGER, A.
Licensing Branch 2 31pp 18899.212 24X Fiche 50-352, 83/06/14,
8306200317.

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
Epoxy Grouts & Sealers " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/06/22. Consolidated Edison Co. of New
York, Inc. 115pp 19021.179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys
Causing Inoperability of Safety-Related Equipment." Svc list
encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/06/22. Consolidated Edison Co. of New
York, Inc. 120pp. 18997.007. 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions "
Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/06/23. Consolidated Edison Co. of New
York, Inc. 116pp. 18996.242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate
Range (IR) High Flux Trip Setpoints." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/06/24. Consolidated Edison Co. of New
York, Inc. 116pp 19046.297 24X Fiche 50-000, 83/06/24, 8305110483

DOCKETED ITEMS

217

S Reportable occurrences, LERs & related correspondence

8306100092 Part 21 rept re potential incorrect interface w/reactor pressure vessel instrument piping Caused by error on four local instrument panel piping diagrams Field deviation disposition requests issued No operating plants affected
SHERWOOD, G O General Electric Co 82/11/18 DEYQUNO, R C
Director's Office, Office of Inspection and Enforcement 3pp
18802 226 24X Fiche 50-352, 82/11/18, 8306100092

8306280417 Part 21 Deficiency Rept 80 re damaged insulation on MCC Powers Co shielded multiconductor cable on HVAC control panels Also reported by MCC Power.
KEMPER, J S Philadelphia Electric Co 83/06/01 MURLEY, T E
Region I, Office of Director 1p 19020 296 24X
Fiche 50-352, 83/06/01, 8306280417

V Operator Examinations

8306140447 Requests attendance at 830627 meeting in King of Prussia, PA to discuss transfer of operating reactor licensing function from Bethesda, MD to Region I of STAROSTECKI, R Division of Project & Resident Programs 83/06/09
KEMPER, J S Philadelphia Electric Co 2pp 18836 345 24X
Fiche 50-352, 83/06/09, 8306140447

DOCKET 50-354 HOPE CREEK NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8306290407 Forwards amended application for DL for Hope Creek Generating Station, Unit 1
MITTL, R L Public Service Electric & Gas Co. of New Jersey
83/06/28 SCHWENGER, A Licensing Branch 2 2pp 19575 001 24X
Fiche 50-354, 83/06/28, 8306290407

--8306290432 Amended application for DL for Hope Creek Generating Station, Unit 1
* Public Service Electric & Gas Co. of New Jersey. 83/06/28
19pp 19575 003 24X Fiche 50-354, 83/06/28, 8306290407

C Utility Environmental Report (ER), amends & correspondence

--8306290435 Environ rept - DL stage, for Hope Creek Generating Station, Unit 1, Vols 1 & 2
* Public Service Electric & Gas Co. of New Jersey 83/06/28
600pp 19543 001 24X Fiche 50-354, 83/06/28, 8306290407

K Utility Final Safety Analysis Report (FSAR) & amends

8306290409 Forwards FSAR, amended application for DL (filed in PDR Category A) & environ rept (filed in PDR Category C), for Hope Creek Generating Station, Unit 1 Schedule of responses to NRC questions will be provided within 60 days
MITTL, R L Public Service Electric & Gas Co. of New Jersey
83/06/28 SCHWENGER, A Licensing Branch 2 2pp 19575 001 24X
Fiche 50-354, 83/06/28, 8306290409

--8306290431 Hope Creek Generating Station, Unit 1, FSAR, Vols 1-18
* Public Service Electric & Gas Co. of New Jersey 83/06/28
9,008pp 19575 022 24X Fiche 50-354, 83/06/28, 8306290407

--8306290444 Chapter 1 to Hope Creek Generating Station, Unit 1, FSAR, "Introduction & General Description of Plant"
* Public Service Electric & Gas Co. of New Jersey 83/06/28
500pp 19575 028 24X Fiche 50-354, 83/06/28, 8306290407

--8306290448 Chapter 2 to Hope Creek Generating Station, Unit 1, FSAR, "Site Characteristics"
* Public Service Electric & Gas Co. of New Jersey 83/06/28
830pp 19576 165 24X Fiche 50-354, 83/06/28, 8306290407

--8306290449 Chapter 3 to Hope Creek Generating Station, Unit 1, FSAR, "Design of Structures, Components, Equipment & Sys"
* Public Service Electric & Gas Co. of New Jersey 83/06/28
1,100pp. 19578 304 24X Fiche 50-354, 83/06/28, 8306290407

--8306290451 App 3A to Hope Creek Generating Station, Unit 1, FSAR, "Computer Programs Used in Structural Analysis & Design."
* Public Service Electric & Gas Co. of New Jersey 83/06/28
17pp. 19582 073 24X Fiche 50-354, 83/06/28, 8306290407

--8306290454 App 3B to Hope Creek Generating Station, Unit 1, FSAR, "Hart I Long-Term Program Plant-Unique Analysis FSAR Summary Rept."
* Public Service Electric & Gas Co. of New Jersey 83/06/28
43pp 19582 092 24X Fiche 50-354, 83/06/28, 8306290407

--8306290456 App 3C to Hope Creek Generating Station, Unit 1, FSAR, "Reactor Asymmetric Load Analysis"
* Public Service Electric & Gas Co. of New Jersey 83/06/28
4pp 19582 134 24X Fiche 50-354, 83/06/28, 8306290407

--8306290457 Chapter 4 to Hope Creek Generating Station, Unit 1, FSAR, "Reactor"
* Public Service Electric & Gas Co. of New Jersey 83/06/28
155pp 19582 144 24X Fiche 50-354, 83/06/28, 8306290407

--8306290458 Chapter 5 to Hope Creek Generating Station, Unit 1, FSAR, "RCB & Connected Sys"
* Public Service Electric & Gas Co. of New Jersey 83/06/28
200pp 19582 335 24X Fiche 50-354, 83/06/28, 8306290407

--8306290460 Chapter 6 to Hope Creek Generating Station, Unit 1, FSAR, "ESF"
* Public Service Electric & Gas Co. of New Jersey 83/06/28
700pp. 19583 253 24X Fiche 50-354, 83/06/28, 8306290407

--8306290465 App 6A to Hope Creek Generating Station, Unit 1, FSAR, "Negative Pressure Design Evaluation"
* Public Service Electric & Gas Co. of New Jersey 83/06/28
23pp 19585 111 24X Fiche 50-354, 83/06/28, 8306290407

--8306290468 App 6B to Hope Creek Generating Station, Unit 1, FSAR, "Subcompartment Differential Pressure Considerations."
* Public Service Electric & Gas Co. of New Jersey 83/06/28
63pp 19585 134 24X Fiche 50-354, 83/06/28, 8306290407

--8306290469 Chapter 7 to Hope Creek Generating Station, Unit 1, FSAR, "Instrumentation & Controls"
* Public Service Electric & Gas Co. of New Jersey 83/06/28
1,500pp 19589 190 24X Fiche 50-354, 83/06/28, 8306290407

--8306290471 Chapter 8 to Hope Creek Generating Station, Unit 1, FSAR, "Electric Power"
* Public Service Electric & Gas Co. of New Jersey 83/06/28
500pp 19587 247 24X Fiche 50-354, 83/06/28, 8306290407

--8306290473 Chapter 9 to Hope Creek Generating Station, Unit 1, FSAR, "Auxiliary Sys"
* Public Service Electric & Gas Co. of New Jersey 83/06/28
1,200pp 19589 130 24X Fiche 50-354, 83/06/28, 8306290407

--8306290474 Chapter 9A to Hope Creek Generating Station, Unit 1, FSAR, "App R Comparison"
* Public Service Electric & Gas Co. of New Jersey. 83/06/28
113pp. 19590 265 24X Fiche 50-354, 83/06/28, 8306290407

--8306290477 Chapter 10 to Hope Creek Generating Station, Unit 1, FSAR, "Steam & Power Conversion Sys."
* Public Service Electric & Gas Co. of New Jersey. 83/06/28
300pp 19591 016 24X Fiche 50-354, 83/06/28, 8306290407

--8306290478 Chapter 11 to Hope Creek Generating Station, Unit 1, FSAR, "Radwaste Mgt"
* Public Service Electric & Gas Co. of New Jersey. 83/06/28
300pp. 19591 123 24X Fiche 50-354, 83/06/28, 8306290407

--8306290479 Chapter 12 to Hope Creek Generating Station, Unit 1, FSAR, "Radiation Protection"
* Public Service Electric & Gas Co. of New Jersey 83/06/28
600pp. 19592 003 24X Fiche 50-354, 83/06/28, 8306290407

--8306290482 Chapter 13 to Hope Creek Generating Station, Unit 1, FSAR, "Conduct of Operations."
* Public Service Electric & Gas Co. of New Jersey 83/06/28
200pp 19593 146 24X Fiche 50-354, 83/06/28, 8306290407

--8306290484 Chapter 14 to Hope Creek Generating Station, Unit 1, FSAR, "Initial Test Program."
* Public Service Electric & Gas Co. of New Jersey. 83/06/28
150pp. 19593 337 24X Fiche 50-354, 83/06/28, 8306290407

--8306290487 Chapter 15 to Hope Creek Generating Station, Unit 1, FSAR, "Accident Analysis"
* Public Service Electric & Gas Co. of New Jersey. 83/06/28
400pp. 19594 121 24X Fiche 50-354, 83/06/28, 8306290407

--8306290489 App 15A to Hope Creek Generating Station, Unit 1, FSAR.
* Public Service Electric & Gas Co. of New Jersey 83/06/28
22pp 19595 221 24X Fiche 50-354, 83/06/28, 8306290407

--8306290491 Chapter 16 to Hope Creek Generating Station, Unit 1, FSAR, "Tech Specs."
* Public Service Electric & Gas Co. of New Jersey 83/06/28. 1p.
19595 248 24X Fiche 50-354, 83/06/28, 8306290407

DOCKETED ITEMS

--8306290494 Chapter 17 to Hope Creek Generating Station, Unit 1, FSAR, "QA"
 * Public Service Electric & Gas Co. of New Jersey 83/04/28 1p
 19595,251 24X Fiche 50-354, 83/06/28, 8306290409

--8306290497 Chapter 18 to Hope Creek Generating Station, Unit 1, FSAR, "Human Factors Engineering"
 * Public Service Electric & Gas Co. of New Jersey 83/06/28
 12pp 19595 305 24X Fiche 50-354, 83/06/28, 8306290409

Q Inspection reports, IE Bulletins & correspondence

8306060010 FOIA request for documents re investigation of L. Berstler allegations concerning facility
 HODAS, D.R., Potter & Carmins 83/03/18 Office of Administration
 1p, 18752 305 24X Fiche 50-354, 83/03/18, 8306060010

8306060013 Responds to FOIA request for documents re investigation of L. Berstler allegations concerning facility Forwards listed documents.
 FELTON, J.M. Division of Rules and Records 83/04/15 HODAS, D.R.
 Potter & Carmins. 2pp 18752 306 24X Fiche 50-354, 83/04/15, 8306060013

--8306060016 IE inquiry rept on 820819, Major area investigated L. Berstler allegations re deficiencies in installation & testing of HVAC sys at Facility Inquiry closed
 SHEPHERD, R.E., CHRISTOPHER, R. Region 1, Office of Director
 82/11/22 14pp 18752 308 24X Fiche 50-354, 83/04/15, 8306060013

--8306060018 Statement of LR Berstler alleging deficiencies in installation & testing of HVAC sys at facility Leak test rept forms for nongas-tight ductwork & worksheet encl.
 BERSTLER, L.R. Affiliation Unknown 82/04/13 6pp 18752 322.
 24X Fiche 50-354, 83/04/15, 8306060013

--8306060021 Discusses L. Berstler, former Willard & Hirsch, Arkin, Hersham (W-H) QC inspector, allegations re HVAC installation at Facility, Bechtel preliminary review indicated minor hardware deficiencies & QC paperwork problem
 TRIPP, L.E. Division of Project & Resident Programs 82/05/04
 Division of Project & Resident Programs 2pp 18752 328 24X
 Fiche 50-354, 83/04/15, 8306060013

--8306060023 Discusses L. Berstler, former Willard & Hirsch, Arkin, Hersham (W-H) QC inspector, allegations re deficiencies in installation & testing of HVAC sys at Facility.
 SHEPHERD, R.E. Region 1, Office of Director. 82/12/16 Region 1, Office of Director 1p 18752 330 24X Fiche 50-354, 83/04/15, 8306060013.

8306020375 Forwards IE Insp Rept 50-354/83-07 on 830418-22 No noncompliance noted
 MARTIN, T.J. Division of Project & Resident Programs. 83/05/20
 MARTIN, T.J. Public Service Electric & Gas Co. of New Jersey 2pp.
 18695 113 24X Fiche 50-354, 83/05/20, 8306020375

--8306020376 IE Insp Rept 50-354/83-07 on 830418-22 No noncompliance noted, Major areas inspected procurement, qualification, insp & installation of electrical raceways, cables, valves & instrument lines
 PAOLINO, R., GREGG, M.I., ANDERSON, C. Region 1, Office of Director.
 83/05/16 7pp 18695 115 24X Fiche 50-354, 83/05/20, 8306020375.

8306280586 Ack receipt of 830601 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-354/83-05
 STAROSTECKI, R. Division of Project & Resident Programs 83/06/20
 MARTIN, T.J. Public Service Electric & Gas Co. of New Jersey. 1p.
 19017 325. 24X Fiche 50-354, 83/06/20, 8306280586

--8306280590 Responds to NRC 830502 ltr re violations noted in IE Insp Rept 50-354/83-05 Corrective actions: QC & engineering personnel re-instructed on HVAC installation & acceptance criteria & Engineering Drawing C-0388-0 revised
 MARTIN, T.J. Public Service Electric & Gas Co. of New Jersey
 83/06/01. ALLAN, J.M. Region 1, Office of Director. 2pp
 19017 326 24X Fiche 50-354, 83/06/20, 8306280586

V. Operator Examinations

8306140148 Extends invitation to attend 830627 meeting in King of Prussia, PA to discuss transfer of reactor licensing function from Bethesda, MD to Region 1 ofc.
 STAROSTECKI, R. Division of Project & Resident Programs 83/06/09.
 MARTIN, T.J. Public Service Electric & Gas Co. of New Jersey 2pp
 18839 027 24X Fiche 50-354, 83/06/09, 8306140148

DOCKET 50-355 HOPE CREEK NUCLEAR STATION, UNIT 2

V Operator Examinations

8306140148 Extends invitation to attend 830627 meeting in King of Prussia, PA to discuss transfer of reactor licensing function from Bethesda, MD to Region 1 ofc.
 STAROSTECKI, R. Division of Project & Resident Programs 83/06/09
 MARTIN, T.J. Public Service Electric & Gas Co. of New Jersey 2pp
 18839 027 24X Fiche 50-354, 83/06/09, 8306140148

DOCKET 50-356 UNIV OF ILLINOIS LOPRA RESEARCH REACTOR

G Inspection reports, IE Bulletins & correspondence

8306100217 Forwards IE Insp Repts 50-151/83-01 & 50-356/83-01 on 830504-05 No noncompliance noted
 PAPERIELLO, C.J. Region 3, Office of Director 83/05/25 MILEY, G.H.
 Illinois, Univ of, Urbana-Champaign 2pp 18805 189 24X
 Fiche 50-151, 83/05/25, 8306100217

--8306100220 IE Insp Repts 50-151/83-01 & 50-356/83-01 on 830504-05 No noncompliance noted Major areas inspected radwaste mgt & radiation protection program, audits, training, procedures & instruments & equipment
 GRANT, W.B., GREGG, L.R. Region 3, Office of Director 83/05/23
 6pp 18805 191 24X Fiche 50-151, 83/05/25, 8306100217

8306090023 Responds to violation noted in IE insp rept Forwards data showing that calibr checks performed on dosimeters on 830616
 BECK, G.P. Illinois, Univ of, Urbana-Champaign 83/05/31.
 GRANT, W.B. Region 3, Office of Director 2pp 18792 356. 24X
 Fiche 50-151, 83/05/31, 8306090023

DOCKET 50-358 WILLIAM H ZIMMER NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8306080307 FOIA request for info re safety & const violations at facility
 BADINO, A. Affiliation Unknown 83/04/01 Division of Rules and
 Records 1p 18792 217 24X Fiche 50-358, 83/04/01, 8306080307

8306080305 Responds to FOIA request for info re safety & const violations at facility Info available in LPDR, per 830407
 telcon
 FELTON, J.M. Division of Rules and Records 83/04/08 BADINO, A.
 Affiliation Unknown 1p 18792 216 24X Fiche 50-358, 83/04/08, 8306080305

8305040156 Forwards summary of Ofc of Investigation rept re allegations concerning presence of Bechtel representatives at site prior to Nov 1982, potentially compromising objectivity of independent review Allegations not substantiated.
 FORTUNA, R.A. Office of Investigation 83/04/26 SCOTT, B. Division
 of Technical Information & Document Control 4pp 18541 131 24X
 Fiche 50-358, 83/04/26, 8305040156

8306010042 Forwards request for addl info re diesel engine reliability to complete DL application review Amend to DL application should be amended to comply w/requirements in encl
 YOUNGBLOOD, B.J. Licensing Branch 1. 83/05/17 WILLIAMS, J.
 Cincinnati Gas & Electric Co. 5pp 18687 098 24X
 Fiche 50-358, 83/05/17, 8306010042

8306060349 Board Notification 83-67, forwards info re errors in computer analyses for Mark II containments Rept providing results of evaluations performed by S&W re Shorsham Mark II containment also encl
 NOVAK, T.M. Assistant Director for Licensing 83/05/19. Atomic
 Safety and Licensing Board Panel 7pp 18753 079 24X
 Fiche 50-000, 83/05/19, 8306060349

8306010151 Amend 149 to application for DL, consisting of Rev 95 to FSAR.
 WILLIAMS, J. Cincinnati Gas & Electric Co. 83/05/31 DENTON, H.R.
 Office of Nuclear Reactor Regulation, Director 2pp 18678 258
 24X Fiche 50-358, 83/05/31, 8306010151.

8306060071 Ack receipt of 830513 ltr informing NRC of actions to expand quality confirmation program, Details will be reviewed during future insps
 WARNICK, R.F. Region 3, Office of Director 83/05/31 WILLIAMS, J.
 Cincinnati Gas & Electric Co. 2pp 18719 927 24X
 Fiche 50-358, 83/05/31, 8306060071

--B306060074 Informs of intention to realign existing programs under quality confirmation program Details of addl expansions will be submitted
WILLIAMS, J Cincinnati Gas & Electric Co 83/05/13 KEPPLER, J O
Region 3, Office of Director 2pp 18719 329 24X
Fiche 50-358,83/05/31,8306060071

B306070359 Summarizes 830526 meeting to discuss planned changes to initial program plan Util interfaces w/Reactor Control, Inc should be added to program scope
NEVLAM, A J Torrey Pines Technology 83/05/31 DICKHONER, W H
Cincinnati Gas & Electric Co 1p 18742 065 24X
Fiche 50-358,83/05/31,8306070359

B306060254 Informs that definite fuel load date cannot be provided until 821112 Show Cause Order CLI-82-33 requirements met & safety-related const resumes Fuel load estimated for Fourth Quarter 1984
WILLIAMS, J Cincinnati Gas & Electric Co 83/06/01 DENTON, H
Office of Nuclear Reactor Regulation, Director 2pp 18727 224
24X Fiche 50-358,83/06/01,8306060254

B306130381 Forwards Certificate of Bvc for Amend 149, in form of Rev 95 to FSAR.
WILLIAMS, J Cincinnati Gas & Electric Co 83/06/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 18822 347
24X Fiche 50-358,83/06/03,8306130381

B306220078 Submits 830606 request for documents re Kaiser Engineers, Inc QA/QC personnel
NEVLAM, A J Torrey Pines Technology 83/06/09 HEDZICK, W
Cincinnati Gas & Electric Co 1p 18727 182 24X
Fiche 50-358,83/06/09,8306220078

B306270332 Discusses effort to improve util organization Copy of ltr to editor which appeared in Cincinnati Enquirer & reply encl
Expansion of QC program to cover bolting, masonry walls & seismic columns requested
WILLIAMS, J Cincinnati Gas & Electric Co 83/06/16 KEPPLER, J O
Region 3, Office of Director 4pp 18993 151 24X
Fiche 50-358,83/06/16,8306270332

B306280359 Forwards list of electronic communicating hardware installed in various depts at facility, per 830304 request
WILLIAMS, J Cincinnati Gas & Electric Co 83/06/20 KEPPLER, J O
Region 3, Office of Director 3pp 19014 092 24X
Fiche 50-358,83/06/20,8306280359

B306270374 Ack receipt of 830601 ltr informing NRC of steps taken to provide current QA program in FSAR Util plans to submit rev to FSAR Chapter 17 I within 60 days of Region III approval of Torrey Pines recommended plan
WARNICK, R F Region 3, Office of Director 83/06/22 WILLIAMS, J
Cincinnati Gas & Electric Co 2pp 18993 208 24X
Fiche 50-358,83/06/22,8306270374

--B306270378 Requests extension of 830610 deadline for submitting current QA program changes & rev to FSAR Chapter 17 I until 60 days after Region III approval of plan resulting from Torrey Pines Technology mgt review
WILLIAMS, J Cincinnati Gas & Electric Co 83/06/01 KEPPLER, J O
Region 3, Office of Director 2pp 18993 210 24X
Fiche 50-358,83/06/22,8306270374

B306280208 Responds to 830601 ltr requesting approval to continue activities re removal of wire ties at top of all previously installed Kellum Grips Request approved Initial installation of wire ties requires further detailed evaluation
WARNICK, R F Region 3, Office of Director 83/06/24 WILLIAMS, J
Cincinnati Gas & Electric Co 2pp 19015 098 24X
Fiche 50-358,83/06/24,8306280208

--B306280213 Requests approval of encl Const Work Approval Request 98, Rev 1 re removal of wire ties at top of all previously installed Kellum Grips.
WILLIAMS, J Cincinnati Gas & Electric Co 83/06/01 KEPPLER, J O
Region 3, Office of Director 13pp 19015 060 24X
Fiche 50-358,83/06/24,8306280208

E NRC Safety Evaluation Report (SER), supp's & correspondence

B306060099 Forwards Rev 4 to "Transport of Toxic Chemicals & Control Room Habitability Study," in response to NRC request & in conjunction w/Suppl 3 to SER
WILLIAMS, J Cincinnati Gas & Electric Co 83/06/01 DENTON, H
Office of Nuclear Reactor Regulation, Director 1p 18731 301 24X
Fiche 50-358,83/06/01,8306060099

--B306060101 Rev 4 to "Transport of Toxic Chemicals & Control Room Habitability Study" One oversize graph encl Aperture card is available in PDR
BOEN, P E Cincinnati Gas & Electric Co 83/05/18 114pp
18731,303 24X Fiche 50-358,83/06/01,8306060099

B306080137 Forwards "WH Zimmer Nuclear Power Station, Unit 1, Heavy Loads Rept," in response to supplemental SER (NUREG-0528, Suppl 3) & NUREG-0612 re control of heavy loads
WILLIAMS, J Cincinnati Gas & Electric Co 83/06/02 DENTON, H
Office of Nuclear Reactor Regulation, Director 87pp 18768,275
24X Fiche 50-358,83/06/02,8306080137

--B306080140 "WH Zimmer Nuclear Power Station, Unit 1, Heavy Loads Rept." * Cincinnati Gas & Electric Co 83/06/01 108pp 1876B 277
24X Fiche 50-358,83/06/02,8306080137

F Security, medical, emergency & fire protection plans

B306030412 Forwards final schedule for satisfying requirements of Generic Ltr 82-33, Suppl 1 to NUREG-0737 "Requirements for Emergency Response Capability"
YOUNGBLOOD, B J Licensing Branch 1 83/05/18 WILLIAMS, J
Cincinnati Gas & Electric Co App 18747 141 24X
Fiche 50-358,83/05/18,8306030412

B306080213 Informs that station blackout procedure approved & available for NRC review, per NUREG-0528, Suppl 3, Subsection B 1 2
WILLIAMS, J Cincinnati Gas & Electric Co 83/06/01 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 18771:182 24X
Fiche 50-358,83/06/01,8306080213

G Adjudicatory correspondence

B306030321 Ack receipt of request to file amicus curiae brief w/brief supporting Miami Valley Power Project motion for admission of eight QA contentions Request to file brief moot
Certificate of Bvc encl
FRYE, J H Atomic Safety and Licensing Board Panel 83/06/01
DAVIS, M Affiliation Unknown 1p 1870B 349 24X
Fiche 50-358,83/06/01,8306030321

B306060075 Motion to reopen record for admission of eight contentions on QA & character & competence or, alternatively, for ASLB to exercise discretion to consider whether stds for 830715 demonstration of sua sponte authority met
DEVINE, T Miami Valley Power Project 83/06/03 Atomic Safety
and Licensing Board Panel 23pp 18723-023 24X
Fiche 50-358,83/06/03,8306060075

B306070373 Requests Commission ignore Miami Valley Power Project 830525 ltr requesting Commission modify IE Director's Decision, 8D-82-03, ruling on Project 820824 petition to suspend plant const
CONNER, T B Conner & Wetterhahn, CONNER, T B Cincinnati Gas & Electric Co 83/06/03 CHILK, B J Office of the Secretary of the Commission 3pp. 18741 355 24X Fiche 50-358,83/06/03,8306070373

B306080250 Amicus curiae brief supporting Miami Valley Power Project motion to reopen record for admission of eight contentions on QA & util character & competence. Hearings only comprehensive way to address problems W/Certificate of Bvc.
AMADON, P W, KRAUS, T, FREMONT, B Affiliation Unknown 83/06/03, Atomic Safety and Licensing Board Panel 7pp. 18771 081 24X
Fiche 50-358,83/06/03,8306080250

B306080203 Request to file amicus curiae brief supporting Miami Valley Power Project efforts to obtain further public hearing
SHEARER, V M, KRAUS, G Affiliation Unknown, POWELL, T, Affiliation Unknown 83/06/06 Atomic Safety and Licensing Board Panel 2pp 18770 251 24X Fiche 50-358,83/06/06,8306080203

--B306080205 Brief supporting Miami Valley Power Project request to reopen licensing hearing re plant operation. Certificate of Bvc encl
SHEARER, V M, POWELL, T, KRAUS, G Affiliation Unknown, 83/06/06 Atomic Safety and Licensing Board Panel, App. 18770.253, 24X
Fiche 50-358,83/06/06,8306080203

B306080215 Motion for leave to file amicus curiae brief supporting Miami Valley Power Project motion to reopen record to admit eight contentions on QA & character & competence
AMADON, P W, KRAUS, T, FREMONT, B Affiliation Unknown 83/06/06, Atomic Safety and Licensing Board Panel, App. 18771 212 24X
Fiche 50-358,83/06/06,8306080215

B306080162 Order delineating time for filing responses to requests to file amicus curiae briefs supporting Miami Valley Power Project renewed attempt to obtain hearings on eight QA contentions
FRYE, J H Atomic Safety and Licensing Board Panel 83/06/07 2pp, 18772, 15B 24X Fiche 50-358,83/06/07,8306080162

DOCKETED ITEMS

8306130453 Affirms Nuclear Study Committee, Southern Ohio District Church of Brethren 830603 amicus curiae brief Health, safety & well-being of Southern Ohio & Northern Kentucky communities must be assured Certificate of Svc encl
DEARDORFF, D., MASON, J. M. Affiliation Unknown 83/06/07 Atomic Safety and Licensing Board Panel 3pp 18821 206 24X
Fiche 50-358, 83/06/07, 8306130453

8306150384 Motion of Cumberland Chapter of Sierra Club for extension to file previously submitted amicus curiae brief supporting Miami Valley Power Project renewed attempt to obtain hearing on eight QA contentions
* Sierra Club 83/06/10 Atomic Safety and Licensing Board Panel 1p 18847-231 24X Fiche 50-358, 83/06/10, 8306150384

--8306150386 Motion of Appalachia-Science for extension to file previously submitted amicus curiae brief supporting Miami Valley Power Project renewed attempt to obtain hearing on eight QA contentions Certificate of Svc encl
* Affiliation Unknown 83/06/10 Atomic Safety and Licensing Board Panel 3pp 18847 232 24X Fiche 50-358, 83/06/10, 8306150386

8306160632 Order extending time until 830713 for Commission to act to review ALAB-727.
CHILK, B. J. Office of the Secretary of the Commission 83/06/13 Commissioners 1p 18865:076 24X Fiche 50-358, 83/06/13, 8306160632

8306160581 Advises that Sierra Club, Cumberland Chapter, request to file amicus curiae brief or brief should not be refiled, Responses to request will be filed w/ responses to Miami Valley Power Project motion
FRYE, J. H. Atomic Safety and Licensing Board Panel 83/06/14, DAVIS, M. Sierra Club 1p. 18866 102 24X Fiche 50-358, 83/06/14, 8306160581

8306200333 Advises that NRC does not object to ASLB receipt of amicus curiae briefs re Miami Valley Power Project request for reconsideration of ASLB 820715 decision on eight QA/QC contentions
BARTH, C. A. Hearing Branch 1 83/06/16 FRYE, J. H., LIVINGSTON, M. B., HODPER, F. F. Atomic Safety and Licensing Board Panel 1p 18900-195 24X Fiche 50-358, 83/06/16, 8306200333

8306200335 Petition for leave to file amicus curiae brief re Miami Valley Power Project motion to reopen record to admit eight contentions on QA & character & competence Requests extension of time, Certificate of Svc encl
0000, R. Sierra Club 0000, R. Good, R. P. 83/06/16 Atomic Safety and Licensing Board Panel 6pp 18900 321 24X
Fiche: 50-358, 83/06/16, 8306200335

--8306200341 Ohio Sierra Club amicus curiae brief supporting Miami Valley Power Project motion to reopen record to admit eight contentions. Contentions provide evidence that QA problems exist Certificate of Svc encl.
0000, R. Sierra Club 0000, R. Affiliation Unknown 83/06/16 Atomic Safety and Licensing Board Panel 6pp. 18900.327. 24X
Fiche. 50-358, 83/06/16, 8306200335

--8306200345 Forwards Appalachia-Science in the Public Interest request to file amicus curiae brief Amicus curiae brief not sent to NRC internal mail or docketing sections
CLARK, L. Government Accountability Project 83/06/15 Docketing & Services Branch 1p 18900-333 24X
Fiche. 50-358, 83/06/16, 8306200335.

--8306200348 Appalachia-Science in the Public Interest request to file amicus curiae brief supporting Miami Valley Power Project renewed attempt to obtain hearing on eight QA contentions
* Affiliation Unknown. 83/05/20. Atomic Safety and Licensing Board Panel. 3pp 18900.334. 24X Fiche 50-358, 83/06/16, 8306200335.

--8306200351 Appalachia-Science in the Public Interest amicus curiae brief supporting Miami Valley Power Project renewed attempt to obtain hearings on eight QA contentions Certificate of Svc encl
DAVIS, M. Affiliation Unknown 83/05/17 Atomic Safety and Licensing Board Panel 5pp 18900 337 24X Fiche 50-358, 83/06/16, 8306200335.

--8306200359 Forwards Cumberland Chapter of Sierra Club request to file amicus curiae brief Amicus curiae brief not sent to NRC internal mail or docketing sections.
CLARK, L. Government Accountability Project 83/06/15 Docketing & Services Branch 1p 18900:342. 24X
Fiche. 50-358, 83/06/16, 8306200335

--8306200372 Cumberland Chapter of Sierra Club request to file amicus curiae brief supporting Miami Valley Power Project renewed attempt to obtain hearing on eight QA contentions
* Sierra Club 83/05/31 Atomic Safety and Licensing Board Panel 3pp 18900 343 24X Fiche 50-358, 83/06/16, 8306200335

8306220031 Response opposing Miami Valley Power Project 830603 motion to reopen record for admission of eight QA contentions Motion untimely
WETTERHAHN, M. J. Cincinnati Gas & Electric Co. WETTERHAHN, M. J. Conner & Wetterhahn 83/06/20 Atomic Safety and Licensing Board Panel 46pp 18920 045 24X Fiche 50-358, 83/06/20, 8306220031

--8306220036 Response opposing motions to file amicus curiae brief in support of Miami Valley Power Project motion to reopen record for admission of eight QA contentions Certificate of Svc encl
WETTERHAHN, M. J. Cincinnati Gas & Electric Co. WETTERHAHN, M. J. Conner & Wetterhahn 83/06/20 Atomic Safety and Licensing Board Panel 7pp 18930 093 24X Fiche 50-358, 83/06/20, 8306220031

8306240267 Brief opposing Miami Valley Power Project petition to admit eight QA contentions Project failed to comply w/ legal stds for reconsideration No program or policy supports reopening of record Certificate of Svc encl
BARTH, C. A. Hearing Branch 1 83/06/20 Atomic Safety and Licensing Board Panel 16pp 18980 110 24X Fiche, 50-358, 83/06/20, 8306240267

8306270410 Memorandum supporting Miami Valley Power Project 830602 motion to reopen record to admit eight contentions on QA & lack of corporate character & competence Reopening necessary to foster public confidence in NRC W/Certificate of Svc
WEBB, D. F. Mentor, KY. 83/06/22 Atomic Safety and Licensing Board Panel 6pp 18994 140 24X Fiche 50-358, 83/06/22, 8306270410

H General correspondence

8306210269 Informs that NRC correspondence should be directed to O C Fiche Revised address for svc list submitted
FLYNN, J. D. Cincinnati Gas & Electric Co. 83/06/16 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 1p 18915 051 24X
Fiche 50-358, 83/06/16, 8306210269

8306230435 Notifies that effective immediately, all correspondence from NRC should be directed to OC Fiche, Manager, Nuclear Licensing Dept at listed address
FLYNN, J. D. Cincinnati Gas & Electric Co. 83/06/16 KEPLER, J. O. Region 3, Office of Director 1p 18942 077 24X
Fiche: 50-358, 83/06/16, 8306230435

K Utility Final Safety Analysis Report (FSAR) & amends

8306010151 Amend 149 to application for OL, consisting of Rev 95 to FSAR.
WILLIAMS, J. Cincinnati Gas & Electric Co. 83/05/31 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 18676 P58 24X Fiche. 50-358, 83/05/31, 8306010151

--8306010156 Rev 95 to FSAR
* Cincinnati Gas & Electric Co. 83/05/31 44pp 18678 260 24X
Fiche 50-358, 83/05/31, 8306010151

8306130381 Forwards Certificate of Svc for Amend 149, in form of Rev 95 to FSAR.
WILLIAMS, J. Cincinnati Gas & Electric Co. 83/06/03 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 18882 247 24X Fiche 50-358, 83/06/03, 8306130381

G Inspection reports, IE Bulletins & correspondence

8304040422 Forwards rept of investigation of allegations re presence of Bechtel representatives prior to Nov 1982 No evidence establishing Bechtel presence onsite prior to Nov 1982 W/o encl.
HAYES, B. B. Office of Investigation 83/03/16 KEPLER, J. O. Region 3, Office of Director 2pp 18812 059 24X Fiche 50-358, 83/03/16, 8304040422.

8306060129 Forwards IE Insp Rept 50-358/82-13 on 830810-1104 & notice of violation No response required due to 821112 order suspending const
KEPLER, J. O. Region 3, Office of Director 83/05/23 WILLIAMS, J. Cincinnati Gas & Electric Co. 3pp. 18719.031 24X
Fiche 50-358, 83/05/23, 8306060129.

--8306060132 Notice of violation from insp on 820810-1104.
KEPLER, J. O. Region 3, Office of Director 83/05/23 8pp 18719 034. 24X Fiche: 50-358, 83/05/23, 8306060129

DOCKETED ITEMS

221

--830606013B IE Insp Rept 50-358/82-13 on 820810-1104 Noncompliance noted QA manuals failed to provide adequate description of Catalytic, Inc purpose & function re site safety-related work activities
YEN, I T, BARRETT, P A, MAUKA, F A Region 3, Office of Director
83/04/21 33pp 18719 042 24X Fiche 50-000, 83/05/23, 8306060129

8305110450 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 200 24X Fiche 50-000, 83/05/31, 8305110461

8306070033 Forwards IE Mgt Meeting Rept 50-358/83-05 on 830425
KEPPLER, J O Region 3, Office of Director 83/06/01 WILLIAMS, J Cincinnati Gas & Electric Co 1p 18740 005 24X Fiche 50-358, 83/06/01, 8306070033

--8306070042 IE Mgt Meeting Rept 50-358/83-05 on 830425 Major areas discussed Torrey Pines Technology independent mgt review of util mgt
HUNTER, D R, WARNICK, R F Region 3, Office of Director 83/05/27 2pp 18740 006 24X Fiche 50-358, 83/06/01, 8306070033

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 117pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8306230353 Forwards IE Insp Rept 50-358/82-17 on 821206-830218 & notice of violation
WARNICK, R F Region 3, Office of Director 83/06/10 WILLIAMS, J Cincinnati Gas & Electric Co 2pp 18743 288 24X Fiche 50-358, 83/06/10, 8306230353

--8306230357 Notice of violation from insp on 821206-830218
WARNICK, R F Region 3, Office of Director 83/06/10 1p 18943 290 24X Fiche 50-358, 83/06/10, 8306230353

--8306230357 IE Insp Rept 50-358/82-17 on 821206-830218 Noncompliance noted license corrective action statements re final
Deficiency Repts M-29 & M-35 concerning welder qualifications inappropriately dispositioned
CHRISTIANSON, W, OWYNN, T P, NIGHTINGALE, E Region 3, Office of Director 83/06/08 18pp 18943 291 24X Fiche 50-358, 83/06/10, 8306230353

8305110470 IE Info Notice 83-30, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18720 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting from Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8306300212 Forwards IE Insp Rept 50-358/83-03 on 830419-21 No noncompliance noted
LITTLE, W B Region 3, Office of Director 83/06/15 WILLIAMS, J Cincinnati Gas & Electric Co 2pp 1912P 104 24X Fiche 50-358, 83/06/15, 8306300212

--8306300218 IE Insp Rept 50-358/83-03 on 830419-21 No noncompliance noted Major areas inspected previous insp findings, IE bulletins & IOCFR50 55(e) items
WARD, K D, DANIELSON, D H Region 3, Office of Director 83/05/23 11pp 19122 106 24X Fiche 50-358, 83/06/15, 8306300212

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

R Periodic operating reports & related correspondence

8306070354 Forwards biweekly status rept on independent review of util project mgt covering period 830507-20.
NEYLAN, A J Torrey Pines Technology 83/05/31 DICKHONER, W H Cincinnati Gas & Electric Co 3pp 18742 107 24X Fiche 50-358, 83/05/31, 8306070354

8306170321 Forwards quality confirmation program monthly status rept & summary sheet for Apr 1983, in response to 821230 ltr
WILLIAMS, J Cincinnati Gas & Electric Co 83/06/03 KEPPLER, J O Region 3, Office of Director 26pp 18878 217 24X Fiche 50-358, 83/06/03, 8306170321

8306230131 Forwards "Independent Review of Zimmer Project Mgt," Biweekly Status Rept 3, for 830521-0603
NEYLAN, A J Torrey Pines Technology 83/06/10 DICKHONER, W H Cincinnati Gas & Electric Co 1p 18947 001 24X Fiche 50-358, 83/06/10, 8306230131

--8306230133 "Independent Review of Zimmer Project Mgt," Biweekly Status Rept 3, for 830521-0603
* Torrey Pines Technology, 83/06/10 46pp 18947 002 24X Fiche 50-358, 83/06/10, 8306230131

S Reportable occurrences, LERs & related correspondence

8306060197 Interim deficiency rept re lack of procedural qualification for pipe bands initially reported on 821107 Post-qualification program for small bore pipe bending operations being conducted to date, 24 of 35 tests completed
WILLIAMS, J Cincinnati Gas & Electric Co 83/05/25 KEPPLER, J O Region 3, Office of Director 2pp 18727 322 24X Fiche 50-358, 83/05/25, 8306060197

8306070135 Supplemental final deficiency rept re inadequate RHR HX valves. Required matl expected within 1 month. Installation & testing to be scheduled after matl received & Commission 821112 show cause order lifted.
WILLIAMS, J Cincinnati Gas & Electric Co 83/05/27 KEPPLER, J O Region 3, Office of Director 2pp 18739 262 24X Fiche 50-358, 83/05/27, 8306070135

8306070232 Interim deficiency rept re defective GE HMA relays initially reported on 830225 NRC 821112 order to show cause & order immediately suspending const must be lifted to permit completion of corrective actions
WILLIAMS, J Cincinnati Gas & Electric Co 83/05/27 KEPPLER, J O Region 3, Office of Director 2pp 18746 103 24X Fiche 50-358, 83/05/27, 8306070232

8306070267 Interim deficiency rept re failure of Brown Boveri solid-state trip devices initially reported on 830307 Order to show cause & order immediately suspending const dtd 821112 must be lifted before work can be completed
WILLIAMS, J Cincinnati Gas & Electric Co 83/05/27 KEPPLER, J O Region 3, Office of Director 2pp 18747 074 24X Fiche 50-358, 83/05/27, 8306070267

8306070267 Interim deficiency rept re failure of Brown Boveri solid-state trip devices initially reported on 830307 Order to show cause & order immediately suspending const dtd 821112 must be lifted before work can be completed.
WILLIAMS, J Cincinnati Gas & Electric Co 83/05/27 KEPPLER, J O Region 3, Office of Director 2pp 18747 074 24X Fiche 50-358, 83/05/27, 8306070267

DOCKETED ITEMS

8306090084 Deficiency rept re qualification of weld procedures consistent w/830207 response to 10CFR50 55(e) Item M-29 (QA-224B) Activities in compliance w/82112 order to show cause & order immediately suspending const
WILLIAMS, J Cincinnati Gas & Electric Co 83/06/01 KEPLER, J O
Region 3, Office of Director 2pp 18793 308 24X
Fiche 50-358, 83/06/01, 8306090084

8306090127 Interim Deficiency Rept M-49 re radiographic & weld defects in sacrificial shields, containment monorail & vent stack welds Analysis reviewed Corrective actions contingent upon lifting of NRC 82112 show cause order
WILLIAMS, J Cincinnati Gas & Electric Co 83/06/01 KEPLER, J O
Region 3, Office of Director 2pp 18792 252 24X
Fiche 50-358, 83/06/01, 8306090127

8306210058 Interim deficiency rept for Item S-11 re inadequacy of structural steel bolting program to assure compliance w/design spec & FSAR criteria Initially reported on 830513 Followup rept expected by 830912
WILLIAMS, J Cincinnati Gas & Electric Co 83/06/10 KEPLER, J O
Region 3, Office of Director 2pp 18911 224 24X
Fiche 50-358, 83/06/10, 8306210058

8306210054 Interim deficiency rept re Item S-10 concerning masonry wall const not per design spec & FSAR criteria Quality confirmation program will be expanded Followup rept will be submitted by 830912
WILLIAMS, J Cincinnati Gas & Electric Co 83/06/13 KEPLER, J O
Region 3, Office of Director 2pp 18912 304 24X
Fiche 50-358, 83/06/13, 8306210054

8306210294 Interim deficiency rept, Item S-9 re soil structure compaction outside power area not per design spec & FSAR criteria Initially reported on 830513 All safety-related structures & sys will be identified
WILLIAMS, J Cincinnati Gas & Electric Co 83/06/13 KEPLER, J O
Region 3, Office of Director 2pp 18915 147 24X
Fiche 50-358, 83/06/13, 8306210294

8306230472 Interim deficiency rept on Item M-40 re indeterminate heat treatment for small bore pipe Initially reported on 820422 Required corrective action contingent on NRC approval or release of 82112 order
WILLIAMS, J Cincinnati Gas & Electric Co 83/06/14 KEPLER, J O
Region 3, Office of Director 2pp 18941 323 24X
Fiche 50-358, 83/06/14, 8306230472

8306230081 Interim deficiency rept re Item M-56, inadequate installation of gamma plugs Requests due date of 830615 for next rept be extended to 830622 to allow coordination of status rept w/responsible dept managers
WILLIAMS, J Cincinnati Gas & Electric Co 83/06/15 KEPLER, J O
Region 3, Office of Director 1p 18947 076 24X
Fiche 50-358, 83/06/15, 8306230081

8306230089 Interim deficiency rept re Item M-87, inadequacy of design control process to assure design output documents contain adequate erection & insp criteria Initially reported on 830513 Item not reportable under 10CFR50 55(e)
WILLIAMS, J Cincinnati Gas & Electric Co 83/06/15 KEPLER, J O
Region 3, Office of Director 2pp 18947 074 24X
Fiche 50-358, 83/06/15, 8306230089

8306230268 Final deficiency rept on Item M-62 re fire damper failure Initially reported on 821029 Orientation of "J" hooks on all seismic Air Balance Inc fire dampers have been reversed so that open end is pointed away from blade
WILLIAMS, J Cincinnati Gas & Electric Co 83/06/15 KEPLER, J O
Region 3, Office of Director 2pp 18945 102 24X
Fiche 50-358, 83/06/15, 8306230268

8306230395 Interim deficiency rept re Item S-5 on inadequate svc Level I coatings Initially reported on 830414 Extension to 830624 requested for interim status rept submittal
WILLIAMS, J Cincinnati Gas & Electric Co 83/06/15 KEPLER, J O
Region 3, Office of Director 1p 18943 090 24X
Fiche 50-358, 83/06/15, 8306230395

8306230442 Interim deficiency rept re diesel generator control logic Initially reported on 820913 Scheduling & completion of design change mod contingent on NRC release of 820912 order to show cause & order immediately suspending const
WILLIAMS, J Cincinnati Gas & Electric Co 83/06/15 KEPLER, J O
Region 3, Office of Director 2pp 18942 081 24X
Fiche 50-358, 83/06/15, 8306230442

8306210123 Responds to 830519 deficiency rept re potentially reportable condition involving essential instruments attached to nonessential/nonseismic piping Initially reported on 830420 Further evaluation required on design criteria
WARNICK, R F Region 3, Office of Director 83/06/16 WILLIAMS, J
Cincinnati Gas & Electric Co 2pp 18918 134 24X
Fiche 50-358, 83/06/16, 8306210123

8306230196 Interim deficiency rept, Item E-45 re failure of Static-Q Ring Model SN pressure switch during environ qualification testing Engineering change request will be submitted to NRC to replace switches w/qualified pressure switches
WILLIAMS, J Cincinnati Gas & Electric Co 83/06/16 KEPLER, J O
Region 3, Office of Director 3pp 18746 349 24X
Fiche 50-358, 83/06/16, 8306230196

8306270331 Interim deficiency rept re Item E-20, insp of inadequate cable tray hanger Initially reported on 820503 Insp criteria for weld quality acceptance will be established from analysis of Sargent & Lundy reinsp program Next rept 831010
WILLIAMS, J Cincinnati Gas & Electric Co 83/06/20 KEPLER, J O
Region 3, Office of Director 2pp 18793 119 24X
Fiche 50-358, 83/06/20, 8306270331

8306270180 Interim deficiency rept re installation of gamma plugs Initially reported on 820804 Engineering evaluation & dispositioning of nonconformance repts will be completed by 830930 Next rept will be submitted by 831015
WILLIAMS, J Cincinnati Gas & Electric Co 83/06/21 KEPLER, J O
Region 3, Office of Director 2pp 18791 345 24X
Fiche 50-358, 83/06/21, 8306270180

8306300160 Interim deficiency rept re inadequate Svc Level I coatings (Item S-5) Initially reported on 820928 Removal & replacement of coating necessary except where inaccessible Corrective action program being developed
WILLIAMS, J Cincinnati Gas & Electric Co 83/06/23 KEPLER, J O
Region 3, Office of Director 2pp 19119 306 24X
Fiche 50-358, 83/06/23, 8306300160

DOCKET 50-361 SAN ONOFRE NUCLEAR STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8306070251 Forwards IE Insp Repts 50-206/83-10, 50-361/83-17 & 50-362/83-17 on 830411-27 & notice of violation
BISHOP, T W Region 5, Office of Director 83/05/16 PAPAY, L T
Southern California Edison Co 2pp 18746 088 24X
Fiche 50-206, 83/05/16, 8306070251

--8306070255 Notice of violation from insp on 830411-27
KIRCH, D F Region 5, Office of Director 83/05/16 2pp
18746 090 24X Fiche 50-206, 83/05/16, 8306070255

--8306070261 IE Insp Repts 50-206/83-10, 50-361/83-17 & 50-362/83-17 on 830411-27, Noncompliance noted failure to install fully B-h emergency lighting units in access/egress routes
SCOMM, K M Region 5, Office of Director 83/05/11 1pp
18746 092 24X Fiche 50-206, 83/05/16, 8306070251

8306160011 Advises that 830323 Rev 9 to physical security plan consistent w/10CFR73 21 provisions & does not decrease plan effectiveness Changes acceptable
KNIGHTON, O W Licensing Branch 3 83/06/06 DIETCH, R Southern California Edison Co HOLCOMBE, J C San Diego Gas & Electric Co 3pp 18872 148 24X Fiche 50-206, 83/06/06, 8306160011

8306220291 Responds to 830406 ltr re changes to physical security plan Changes consistent w/10CFR50 54(p) & do not decrease effectiveness of plan
KNIGHTON, O W Licensing Branch 3 83/06/10 DIETCH, R Southern California Edison Co HOLCOMBE, J C San Diego Gas & Electric Co 3pp 18940 344 24X Fiche 50-206, 83/06/10, 8306220291

8306220294 Responds to 830323 ltr re Rev 2 to guard training & qualification plan Changes consistent w/10CFR50 54(p) provisions & do not decrease effectiveness of plan
KNIGHTON, O W Licensing Branch 3 83/06/10 DIETCH, R Southern California Edison Co HOLCOMBE, J C San Diego Gas & Electric Co 3pp 18940 312 24X Fiche 50-206, 83/06/10, 8306220294

8306230520 Responds to 830427 ltr re temporary changes to physical security plan Changes consistent w/10CFR50 54(p) requirements & acceptable
KNIGHTON, O W Licensing Branch 3 83/06/10 DIETCH, R Southern California Edison Co HOLCOMBE, J C San Diego Gas & Electric Co 2pp 18954 361 24X Fiche 50-206, 83/06/10, 8306230520

8306230455 Ack receipt & provides evaluation of changes to emergency plan implementing procedures submitted in 821029 & 831103 ltrs Changes do not decrease effectiveness of emergency response planning
NORRERHAU, L R Division of Radiological Safety & Safeguards Program 83/06/20 BASKIN, K P Southern California Edison Co 1p 18941 360 24X Fiche 50-206, 83/06/20, 8306230455

DOCKETED ITEMS

223

O Adjudicatory correspondence

8306080195 Comments re offsite medical svcs, objections to applicant motion to augment record & request for hearing & proposed licensing condition Adequate arrangements for medical svcs not met Further hearings required
MCCLUNG, C E Affiliation Unknown MCCLUNG, C E Fleming, Anderson, McClung & Finch 83/06/06 Atomic Safety and Licensing Board Panel 7pp 18772 251 24X Fiche 50-361,83/06/06,8306080195

8306080214 Response to util 830516 motion to augment record, position re Commission Memorandum & Order CL1-83-10 on offsite medical svcs & proposed findings of fact Supports motion & proposed findings
VOGLER, B II Hearing Branch 2 83/06/06 Atomic Safety and Licensing Board Panel 7pp 18771 101 24X Fiche 50-361,83/06/06,8306080214

--8306080216 Affidavit of DE Matthews that util ensured appropriate provisions for medical svcs to general public traumatically injured or contaminated during emergency Prof qualifications & Certificate of Svc encl
MATTHEWS, D B Section B (Pre 820201) 83/06/06 7pp 18771 108 24X Fiche 50-361,83/06/06,8306080216

8306080157 Order extending time until 830614 for Commission to act to review ALAD-717
CHILK, S J Office of the Secretary of the Commission 83/06/07 Commissioners 1p 18772 174 24X Fiche 50-361,83/06/07,8306080157

8306160635 Order extending time until 830621 for Commission to act to review ALAD-717
CHILK, S J Office of the Secretary of the Commission 83/06/14 Commissioners 1p 18866 034 24X Fiche 50-361,83/06/14,8306160635

8306210288 Response opposing GUARD & Carstens 830606 joint request for hearing on medical svcs issues Issue of sufficiency of medical resources already litigated Hearing unnecessary to obtain authentication Certificate of Svc encl
CHANDLER, L J Hearing Branch 2 83/06/17 Atomic Safety and Licensing Board Panel 8pp 18915 011 24X Fiche 50-361,83/06/17,8306210288

8306220084 Reply to intervenor 830606 briefs on status of medical svcs issue Further hearings unjustified since Commission already ruled on adequacy of on-site medical svcs Declaration of Svc encl
PIOTTI, D R Southern California Edison Co PIOTTI, D R Orrick, Herrington & Sutcliffe 83/06/17 8pp 18927 173 24X Fiche 50-361,83/06/17,8306220084

8306220127 Affidavit of FK Massey supporting util 830516 motion to augment record, authenticating documents as portions of Orange & San Diego County emergency plans
MASSEY, F K Southern California Edison Co 83/06/17 5pp 18926 107 24X Fiche 50-361,83/06/17,8306220127

J Insurance & indemnity information

8306270172 Forwards Endorsements 95,96 & 97 to NELIA Policy NF-146, & Endorsements 83,84 & 85 to MAELU Policy MF-38 & Endorsement 38 to NELIA Policy NG-282
ROCCO, J Southern California Edison Co, 83/06/13 DINI72, I Antitrust & Economic analysis Branch (Utility Finance). 8pp 18971 349 24X Fiche 50-206,83/06/13,8306270172

K Utility Final Safety Analysis Report (FSAR) & amends

8306150002 Amend 32 to FSAR W/830606 ltr
DIETCH, R Southern California Edison Co COTTON, O D San Diego Gas & Electric Co 83/05/31 DENTON, H R Office of Nuclear Reactor Regulation, Director 332pp 18854 001 24X Fiche 50-361,83/05/31,8306150002

8306160275 Forwards Affidavit of Svc for Amend 32 to FSAR
MEDFORD, H O, PEMBERTON, H R Southern California Edison Co 83/06/14 KNIGHTON, O W Licensing Branch 3 4pp 10860 173 24X Fiche 50-361,83/06/14,8306160275

P Operating license stage documents & correspondence

8306030062 Evaluation proposal to conduct xenon oscillation control test at 50% power vs 65% power specified in FSAR Reduction acceptable
KNIGHTON, O W Licensing Branch 3, 83/05/23 DIETCH, R Southern California Edison Co HOLCOMBE, J C San Diego Gas & Electric Co 4pp 18733 204 24X Fiche 50-361,83/05/23,8306030062

8306070313 Discusses enhanced surveillance & maint activities of reactor trip breakers Tech Spec changes not appropriate at present time
BASKIN, K P Southern California Edison Co 83/06/03 KNIGHTON, O W Licensing Branch 3 2pp 18741 113 24X Fiche 50-361,83/06/03,8306070313

8306080020 Forwards resolution of NRC comments on post-trip/restart review procedure, identifying procedure changes in response to NRC comments in Section III B 7 of SER
BASKIN, K P Southern California Edison Co 83/06/03 KNIGHTON, O W Licensing Branch 3 4pp 18773 001 24X Fiche 50-361,83/06/03,8306080020

8306090498 Requests remittance of Class III fees for 82119,1203 & 20 Tech Spec amend requests, re shutdown cooling trains, turbine overspeed protection & component cooling water loop
MILLER, W O License Fee Management Branch 83/06/06 DIETCH, R Southern California Edison Co 2pp 18812 062 24X Fiche 50-361,83/06/06,8306090498

8306090502 Ack receipt of 830128 partial payment for review of 820816 & 0930 amend applications re turbine overspeed protection sys inoperability Payment of remaining fee requested
MILLER, W O License Fee Management Branch 83/06/06 BASKIN, K P Southern California Edison Co 1p 18812 070 24X Fiche 50-361,83/06/06,8306090502

8306090156 Application to amend License NPF-10, extending Tech Spec surveillance interval to 18 months Approval requested by 830712
BASKIN, K P Southern California Edison Co 83/06/07 KNIGHTON, O W Licensing Branch 3 1p 18792 316 24X Fiche 50-361,83/06/07,8306090156

--8306090164 Proposed Tech Spec change extending 18-month surveillance requirement to 831001
Southern California Edison Co 83/06/07 2pp 18792 317 24X Fiche 50-361,83/06/07,8306090164

8306130386 Forwards Amend 6 to Topical Rept SCE-1-A, "QA Program," & miscellaneous documents per Final Rule 10CFR50.54(a) Rept supercedes program described in FSAR, App D
BASKIN, K P Southern California Edison Co 83/06/09 MARTIN, J B Region 5, Office of Director 3pp 18821 271 24X Fiche 50-206,83/06/09,8306130386

--8306130392 Amend 6 to Topical Rept SCE-1-A, "QA Program"
Southern California Edison Co SCE-1-A A06 83/04/30 200pp 18821 274 24X Fiche 50-206,83/06/09,8306130386

8306140444 Confirms mode to high pressure governor valves 2 & 4 & to provide analyses of valve opening force & adequacy of mechanical clamps per 830208 commitment Analyses encl
BASKIN, K P Southern California Edison Co 83/06/09 KNIGHTON, O W Licensing Branch 3 4pp 18838 019 24X Fiche 50-361,83/06/09,8306140444

8306140178 Revised application to amend License NPF-10 delaying until 831001 18-month interval surveillance requirements which cannot be completed w/o extended outage
MEDFORD, H O Southern California Edison Co 83/06/10 KNIGHTON, O W Licensing Branch 3 8pp 18839 048 24X Fiche 50-361,83/06/10,8306140178

8306140644 Submits post-accident sampling sys (PASS) progress rept as of 830601 PASS outage scheduled for 830617-0810 Operator training course produced two qualified PASS operators License Conditions 2 C (19) i 1 & (17) d 4 satisfied
BASKIN, K P Southern California Edison Co 83/06/10 KNIGHTON, O W Licensing Branch 3 3pp 18843 003 24X Fiche 50-361,83/06/10,8306140644

8306240477 Forwards FR notice of consideration of issuance of amend to License NPF-7 & proposed no significant hazards consideration determination & opportunity for hearing re natural circulation tests to be conducted during startup
RODD, H Licensing Branch 3 83/06/10 DIETCH, R Pacific Gas & Electric Co HOLCOMBE, J C San Diego Gas & Electric Co 2pp 18977 163 24X Fiche 50-361,83/06/10,8306240477

--8306240479 Notice of consideration of issuance of amend to License NPF-7 & proposed no significant hazards consideration determination & opportunity for hearing re natural circulation tests to be conducted during startup
KNIGHTON, O W Licensing Branch 3 83/05/31 9pp 18977 165 24X Fiche 50-361,83/06/10,8306240477

DOCKETED ITEMS

8306230498 Advises that NRR has reassessed Class III Fee position on 820314 application for amend to License NPF-10 re implementation of environ qualification program Addl fees not applicable per util 821203 ltr
DIOGB, R. M. License Fee Management Branch 83/06/16 BASKIN, K. P.
Southern California Edison Co 1p 18982.037 24X
Fiche 50-206, 83/06/16, 8306230498.

8306300057 Forwards C-E repts, "Depressurization & DHR, Responses to NRC Questions," Suppl 1 to "PRA of Effects of PORVs on Depressurization & DHR" & "Responses to Plant-Specific Questions on Depressurization," per 820327 request
BASKIN, K. P. Southern California Edison Co 83/06/22 KNIIGHTON, G. W.
Licensing Branch 3 3pp 19117.062 24X Fiche 50-361, 83/06/22, 8306300057

--8306300125 "Depressurization & DHR, Responses to NRC Questions."
* Combustion Engineering, Inc. CEN-239 83/06/30 390pp.
19117.065 24X Fiche 50-361, 83/06/22, 8306300057

--8306300126 Suppl 1 to CEN-239, "PRA of Effects of PORVs on Depressurization & DHR, San Onofre Nuclear Generating Station, Units 2 & 3"
* Combustion Engineering, Inc CEN-239 801. 83/06/30 363pp.
19118.083 24X Fiche 50-361, 83/06/22, 8306300057

--8306300144 "Responses to Plant-Specific Questions on Depressurization & DHR (Questions 6a, 6b, 12, 13a, 13c & 13d)"
* Southern California Edison Co. 83/06/30 37pp 19119.088
24X Fiche 50-361, 83/06/22, 8306300057.

8306270362 Application for amend to License NPF-10, revising Tech Specs re radioactive gaseous effluent monitoring instrumentation to permit replacement of reactor coolant pump seals & maintain personnel exposure ALARA Change description encl
BASKIN, K. P. Southern California Edison Co 83/06/24 KNIIGHTON, G. W.
Licensing Branch 3 3pp 18993.188 24X Fiche 50-361, 83/06/24, 8306270362.

0 Inspection reports, IE Bulletins & correspondence

8306160046 FOIA request, on behalf of EE Kent, for records prepared by US govt employees re Alliance for Survival, T Carpenter &/or ongoing NRC investigation of facilities
CARPENTER, T. Orange County Alliance for Survival. 83/03/14
Office of Administration 1p 18893.031 24X Fiche 50-206, 83/03/14, 8306160046

8306100009 Addl response to FOIA request for documents dtd 820101 or after re BALP. Forwards App A documents Documents also available in PDR.
FELTON, J. M. Division of Rules and Records 83/04/11 CLARK, R. San Francisco Examiner. 3pp 18815.252 24X Fiche 50-000, 83/04/11, 8306100009.

--8306100014 Submits schedule for Region V BALP Board meetings for 820928-830523
ENGELKEN, R. M. Region 5, Office of Director. 82/03/19
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 1p 18815.253 24X Fiche 50-000, 83/04/11, 8306100009.

--8306100036 Discusses assignment of BALP coordinators for Reactor Operations Projects Branch facilities. Coordinators will be responsible for preparing input data used by board members in analyzing functional areas Draft note from B Miner encl
STERNBERG, D. M. Region 5, Office of Director. 82/03/24 Region 5, Office of Director. 1pp 18815.257 24X
Fiche 50-000, 83/04/11, 8306100009.

8306160052 Responds to FOIA request for records prepared by US govt employees re Alliance for Survival, T Carpenter &/or ongoing NRC investigation of facilities Forwards App A documents. Search for addl documents in progress.
FELTON, J. M. Division of Rules and Records 83/04/14, CARPENTER, T. Orange County Alliance for Survival. 2pp. 18893.032 24X
Fiche 50-206, 83/04/14, 8306160052

8306160197 Responds to FOIA request for documents re FOIA Request 82-618. Forwards App A documents. Documents 18 & 19(d) partially deleted (ref FOIA Exemption 4).
FELTON, J. M. Division of Rules and Records 83/04/25 GARDE, B. P. Government Accountability Project. 4pp 18893.125 24X
Fiche 50-206, 83/04/25, 8306160197.

--8306160200 Forwards FOIA request Releasability determinations indicated in response ltrs to requester. No action required.
FELTON, J. M. Division of Rules and Records. 83/03/24. DIETCH, R. Southern California Edison Co. 1p 18893.129. 24X
Fiche 50-206, 83/04/25, 8306160197.

--8306160209 Requests disclosure determination for listed documents subj to FOIA Request 82-618
GRIMBLEY, D. H. Division of Rules and Records 83/02/07
ALEXANDER, I. Region 5, Office of Director 2pp 18893.148 24X
Fiche 50-206, 83/04/25, 8306160197

--8306160218 Forwards documents re B Garde FOIA request, on behalf of EE Kent, for documents regarding 821120 IE rept "Special NRC Insp of San Onofre 1, 2 & 3 (FOIA-82-618)" w/o encl
FORTUNA, R. A. Office of Investigation 83/01/24 CARR, J. C.
Division of Rules and Records 3pp 18893.150 24X
Fiche 50-206, 83/04/25, 8306160197

--8306160223 Request disclosure determination for document originated by ofc re FOIA Request 82-618 by noon on 830119
CARR, J. C. Division of Rules and Records 83/01/12 WILSON, V.
Office of Nuclear Reactor Regulation, Director 2pp 18893.157
24X Fiche 50-206, 83/04/25, 8306160197

--8306160230 Submits list of Region V Ofc of Investigation File Serials 26-42, "EDONB-Alligations Re Welding of Piping by EE Kent," Case 5-82-021 Serials 1-25 previously provided in response to FOIA Request 82-528
SHACKLETON, D. C. Office of Investigation 83/01/03 FORTUNA, R. A.
Office of Investigation 3pp 18893.159 24X
Fiche 50-206, 83/04/25, 8306160197

--8306160243 Forwards list of documents available at Region V re B Garde FOIA Request 82-618 on EE Kent behalf, for documents concerning 821130 IE rept "Special NRC Insp of San Onofre 1, 2 & 3"
ALEXANDER, I. Region 5, Office of Director 83/12/28 REED, C. A.
Division of Rules and Records 3pp 18893.162 24X
Fiche 50-206, 83/04/25, 8306160197

--8306160253 Forwards DC Shackleton 821109 memo transmitting documents subj to FOIA Request 82-528 Review of Documents 1, 2, 10 & 19 by Region V recommended Confidentiality not sought by EE Kent
FORTUNA, R. A. Office of Investigation 82/12/10 CARR, J. C.
Division of Rules and Records 1p 18893.165 24X
Fiche 50-206, 83/04/25, 8306160197

--8306160263 Forwards list of documents responsive to FOIA Request 82-528 re EE Kent allegations concerning facilities from Oct 1980 to present. Region V not aware of allegation until Oct 1982
SHACKLETON, D. C. Region 5, Office of Director. 82/11/09
FORTUNA, R. A. Office of Investigation 5pp 18893.166 24X
Fiche 50-206, 83/04/25, 8306160197

--8306160276 Requests info responsive to FOIA Request 82-528 for documents re EE Kent allegation concerning facilities from Oct 1980 to present be forwarded to Div of Rules & Records by 821116
CARR, J. C. Division of Rules and Records 82/11/04 KIME, C.
Director's Office, Office of Inspection and Enforcement
ALEXANDER, I. Region 5, Office of Director BOWERS, H. Office of Inspector & Auditor 1p 18893.171 24X Fiche 50-206, 83/04/25, 8306160197

--8306160281 Forwards list of documents responsive to FOIA Request 82-528 re EE Kent allegations concerning facilities from Oct 1980 to present, per 821104 memo Related info encl
ENGELKEN, R. H. Region 5, Office of Director 82/11/17. CARR, J. C.
Division of Rules and Records 5pp 18893.174 24X
Fiche 50-206, 83/04/25, 8306160197

--8306160301 Forwards FOIA Request 82-618 for documents re 821130 IE rept "Special NRC Insp of San Onofre 1, 2 & 3." Documents responsive to request should be forwarded to Div of Rules & Records by 830104
CARR, J. C. Division of Rules and Records 82/12/22 FORTUNA, R.
Office of Inspector & Auditor ALEXANDER, I. Region 5, Office of Director 1p 18893.195 24X Fiche 50-206, 83/04/25, 8306160197

8306160070 Addl response to FOIA request for records prepared by US govt employees re Alliance for Survival, T Carpenter &/or ongoing NRC investigation of facilities IE Insp Repts 50-206/82-31, 50-361/82-31 & 50-362/82-27 available in PDR
FELTON, J. M. Division of Rules and Records 83/04/28 CARPENTER, T.
Orange County Alliance for Survival 2pp 18892.338 24X
Fiche 50-206, 83/04/28, 8306160070

8306070240 Forwards IE Insp Repts 50-206/83-13, 50-361/83-21 & 50-362/83-19 on 830401-29 No noncompliance noted.
BISHOP, T. W. Region 5, Office of Director 83/05/13 PAPAY, L. T.
Southern California Edison Co. 2pp. 18746.047 24X
Fiche 50-206, 83/05/13, 8306070240

- 8306070244 IE Insp Repts 50-206/83-13, 50-361/83-21 & 50-362/83-19 on 830401-29 No noncompliance noted Major areas inspected plant operations during long-term shutdown, monthly maint & surveillance activities & LERs
MILLER, L., KIRSCH, D F Region 5, Office of Director 83/05/12
8pp 18746 049 24X Fiche 50-206, 83/05/13, 8306070240
- 8306070333 Forwards IE Insp Repts 50-206/83-08, 50-361/83-17 & 50-362/83-20 on 830329-0406 No noncompliance noted
BOOK, H E Region 5, Office of Director 83/05/13 PAPAY, L T
Southern California Edison Co 2pp 18741 077 24X
Fiche: 50-206, 83/05/13, 8306070333
- 8306070339 IE Insp Repts 50-206/83-08, 50-361/83-17 & 50-362/83-20 on 830329-0406 No noncompliance noted Major areas inspected lab QA program, including independent confirmatory measurements re Region V mobile lab
HARADA, G H, TEMPLE, G H, GARCIA, E Region 5, Office of Director 83/05/12 10pp 18741 079 24X Fiche 50-206, 83/05/13, 8306070339
- 8306070361 Forwards IE Insp Repts 50-361/83-22 & 50-362/83-21 on 830326-0422 No noncompliance noted
BISHOP, T W Region 5, Office of Director 83/05/13 PAPAY, L T
Southern California Edison Co 2pp 18742 110 24X
Fiche: 50-361, 83/05/13, 8306070361
- 8306070368 IE Insp Repts 50-361/83-22 & 50-362/83-21 on 830326-0422, No noncompliance noted Major areas inspected operational safety verification & LER review
PATE, R J, KIRSCH, D F Region 5, Office of Director 83/05/12 4pp 18742 112 24X Fiche 50-361, 83/05/13, 8306070361
- 8306220139 Ack receipt of 830502 ltr & full payment of civil penalty AXELRAD, J A Director's Office, Office of Inspection and Enforcement 83/05/13 PAPAY, L T Southern California Edison Co 2pp 18937 350, 24X Fiche 50-361, 83/05/13, 8306220139.
- 8306070251 Forwards IE Insp Repts 50-206/83-10, 50-361/83-19 & 50-362/83-17 on 830411-27 & notice of violation
BISHOP, T W Region 5, Office of Director 83/05/16 PAPAY, L T
Southern California Edison Co 2pp 18746 088 24X
Fiche 50-206, 83/05/16, 8306070251
- 8306070255 Notice of violation from insp on 830411-27
KIRSCH, D F Region 5, Office of Director 83/05/16 2pp 18746 090 24X Fiche 50-206, 83/05/16, 8306070251
- 8306070261 IE Insp Repts 50-206/83-10, 50-361/83-19 & 50-362/83-17 on 830411-27 Noncompliance noted Failure to install fully B-h emergency lighting units in access/egress routes
SCOWIN, K H, KIRSCH, D F Region 5, Office of Director 83/05/11 11pp 18746 092 24X Fiche 50-206, 83/05/16, 8306070251
- 8306010159 Ack receipt of 830518 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-361/83-14 & 50-362/83-14
BOOK, H E Region 5, Office of Director 83/05/25 PAPAY, L T
Southern California Edison Co 1p 18673 046, 24X
Fiche: 50-361, 83/05/25, 8306010159
- 8306010164 Responds to NRC 830418 ltr re violations noted in IE Insp Repts 50-361/83-14 & 50-362/83-14 Corrective actions, release procedures revised, requiring observance of monitor response & design change package ALARA review criteria strengthened.
FOGARTY, D J Southern California Edison Co 83/05/18
MARTIN, J B Region 5, Office of Director 8pp 18673 047, 24X
Fiche: 50-361, 83/05/25, 8306010159.
- 8305110498 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl.
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103), 83/05/26 Consolidated Edison Co. of New York, Inc. 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110498
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc. 115pp. 18732 085 24X Fiche: 50-000, 83/05/26, 8305110460.
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at DWRs " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc 116pp 18732 208, 24X Fiche 50-000, 83/05/31, 8305110461
- 8306070029 Responds to IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sys on Diesel Generator " Raw water cooling sys & check valves not utilized in diesel generator at facilities
HAYNES, J O Southern California Edison Co 83/06/03 MARTIN, J B Region 5, Office of Director 1p 18739 329 24X
Fiche 50-361, 83/06/03, 8306070029
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464.
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/06/13 Consolidated Edison Co. of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470.
- 8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13, Consolidated Edison Co. of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010
- 8306280498 Forwards IE Insp Repts 50-361/83-24 & 50-362/83-23 on 830425-0602 No noncompliance noted
BISHOP, T W Region 5, Office of Director 83/06/15, PAPAY, L T, Southern California Edison Co 2pp 19017 293 24X
Fiche: 50-361, 83/06/15, 8306280498
- 8306280511 IE Insp Repts 50-361/83-24 & 50-362/83-23 on 830425-0602 No noncompliance noted Major areas inspected: startup test programs, including operational safety verification, power ascension testing, plant trips & LER review
PATE, R J, CHAFFEE, A E, STEWART, J P Region 5, Office of Director 83/06/14 7pp 19017 297 24X Fiche: 50-361, 83/06/15, 8306280498
- 8306200378 Ack receipt of 830516 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-361/83-13 & 50-362/83-12, Undervoltage coil mechanism important Violation A cited properly
MARTIN, J B Region 5, Office of Director 83/06/17, FOGARTY, D J Southern California Edison Co 3pp 18899 087, 24X
Fiche: 50-361, 83/06/17, 8306200378.
- 8306200381 Responds to NRC 830414 ltr re violations noted in IE Insp Repts 50-361/83-13 & 50-362/83-12 Item A in notice of violation re surveillance testing of reactor trip breaker unwarranted.
FOGARTY, D J Southern California Edison Co 83/05/16
MARTIN, J B Region 5, Office of Director 7pp 18899 090 24X
Fiche: 50-361, 83/06/17, 8306200378
- 8306280546 Forwards IE Insp Repts 50-361/83-15 & 50-362/83-13 on 830323-0602 & notice of violation
BISHOP, T W Region 5, Office of Director 83/06/17, PAPAY, L T, Southern California Edison Co 3pp 19018 109 24X
Fiche: 50-361, 83/06/17, 8306280546
- 8306280551 Notice of violation from insp on 830323-0602.
KIRSCH, D F Region 5, Office of Director 83/06/17 7pp. 19018 112 24X Fiche 50-361, 83/06/17, 8306280546.
- 8306280561 IE Insp Repts 50-361/83-15 & 50-362/83-13 on 830323-0602. Noncompliance noted inadequate valve sys lineup procedures, failure to maintain certain fire protection valves locked open & alterations of official records.
CHAFFEE, A, STEWART, P, KIRSCH, D F Region 5, Office of Director 83/06/16 11pp 19018 119, 24X Fiche: 50-361, 83/06/17, 8306280546.
- 8306230211 Responds to IE Bulletin 83-05, "ASME Nuclear Code Pumps & Spare Parts Mfg by Hayward Tyler Pump Co " No subj pumps or spare parts in use or planned for use at facility
HAYNES, J O Southern California Edison Co 83/06/20 MARTIN, J B Region 5, Office of Director 1p 18746 348, 24X
Fiche: 50-361, 83/06/20, 8306230211
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22, Consolidated Edison Co. of New York, Inc. 115pp. 19021:179 24X Fiche: 50-000, 83/06/22, 8305110475.
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp. 18997:007 24X Fiche: 50-000, 83/06/22, 8305110477.

DOCKETED ITEMS

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co of New
York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co of New
York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

R Periodic operating reports & related correspondence

8306160489 Monthly operating repts for Apr 1983 W/830513 ltr
MAYHEATHER, L. RAY, H B Southern California Edison Co 83/05/13
Management Information Branch 12pp 18864 139 24X
Fiche 50-361, 83/05/13, 8306160489

B Reportable occurrences, LERs & related correspondence

8306100054 LER 83-030/03L-0 on 830406, CREACUS train B declared inoperable for investigation of ground on fan motor ME-419
Limiting condition for operation invoked Caused by oily residue on windings Grease fittings removed W/830506 ltr
RAY, H B Southern California Edison Co 83/05/06 MARTIN, J B
Region 5, Office of Director App 18802 119 24X
Fiche 50-361, 83/05/06, 8306100054

8306100098 LER 83-040/01T-0 on 830507, containment isolation valve NU-099 (safety injection drain to refueling water storage tank) found open Caused by foreman initiating incomplete startup procedures W/830523 ltr
RAY, H B Southern California Edison Co 83/05/23 MARTIN, J B
Region 5, Office of Director App 18802 262 24X
Fiche 50-361, 83/05/23, 8306100098

8306100069 LER 83-048/03L-0 on 830424, pilot flames of trains A & B toxic gas isolation sys butane/propane monitors experienced persistent flame-out Caused by high impurity level in replacement hydrogen gas bottle replaced W/830524 ltr
RAY, H B Southern California Edison Co 83/05/24 MARTIN, J B
Region 5, Office of Director App 18802 178 24X
Fiche 50-361, 83/05/24, 8306100069

8306100072 RO on 830506, NFPA 72D std not met, due to improper design change which eliminated ability to differentiate between trouble & alarm signals Design change package will be prepared by 830615 to modify circuitry.
RAY, H B Southern California Edison Co 83/05/24 MARTIN, J B
Region 5, Office of Director App 18802 181 24X
Fiche 50-361, 83/05/24, 8306100072

8306100115 LER 83-047/03L-0 on 830427, toxic gas isolation sys train A declared inoperable & subsequent insp revealed battery discharged & alarm function defeated Caused by discharged battery supply & misaligned setpoint, W/830527 ltr
RAY, H B Southern California Edison Co 83/05/27 MARTIN, J B
Region 5, Office of Director App 18802 023 24X
Fiche 50-361, 83/05/27, 8306100115

8306140684 LER 83-041/07L-0 on 830429, documentation could not be located indicating operability testing, including testing required by inservice insp & testing program, Caused by inadequate administrative controls W/830529 ltr
RAY, H B Southern California Edison Co 83/05/29 MARTIN, J B
Region 5, Office of Director App 18842 062 24X
Fiche: 50-361, 83/05/29, 8306140684

8306140039 LER 83-049/03L-0 on 830429, emergency chiller E-336 (Train A) failed to start following invalid TQIS Caused by misalignment of supply breaker Breaker aligned W/830601 ltr
RAY, H B Southern California Edison Co 83/06/01 MARTIN, J B
Region 5, Office of Director App 18838 253 24X
Fiche 50-361, 83/06/01, 8306140039

8306140250 LER 83-051/03L-0 on 830501, w/Unit 2 in Mode 3 & Unit 3 in Mode 5, control room complex isolation damper 2/3HV9702 did not close as required Cause unknown Physical insp of relays, contacts & wiring will be conducted W/830601 ltr
RAY, H B Southern California Edison Co 83/06/01 MARTIN, J B
Region 5, Office of Director App 18933 014 24X
Fiche 50-361, 83/06/01, 8306140250

8306140007 LER 83-045/03L-0 on 830504, while working on plant protection sys Channel A reactor trip circuit breaker TCB-1 tripped open, rendering channel inoperable Caused by loose cable terminal block screws Screws tightened W/830603 ltr
RAY, H B Southern California Edison Co 83/06/03 MARTIN, J B
Region 5, Office of Director App 18838 244 24X
Fiche: 50-361, 83/06/03, 8306140007

8306210113 LER 83-046/03L-0 on 830506, reactor coolant cold leg temp Tc found outside Limiting Condition for Operation 3 2 & Caused by personnel failure to properly monitor & control Tc Tc restored to limits W/830606 ltr
RAY, H B Southern California Edison Co 83/06/06 MARTIN, J B
Region 5, Office of Director App 18915 076 24X
Fiche 50-361, 83/06/06, 8306210113

8306210352 LER 83-060/01T-0 on 830529, hourly instead of continuous flow watch established & backup fire suppression equipment in place until Zone 5 deluge water spray sys returned to svc Caused by inadequate procedures W/830606 ltr
RAY, H B Southern California Edison Co 83/06/06 MARTIN, J B
Region 5, Office of Director App 18914 018 24X
Fiche 50-361, 83/06/06, 8306210352

8306230266 LER 83-051/03X-0 on 830501, control room complex isolation damper 2/3HV9702 did not close as required on spurious TQIU Caused by dirt on reset relay Relays cleaned W/830610 ltr
RAY, H B Southern California Edison Co 83/06/10 MARTIN, J B
Region 5, Office of Director App 18945 083 24X
Fiche 50-361, 83/06/10, 8306230266

8306280267 LER 83-058/03L-0 on 830514, failure of core protection calculator Channel B indicated by lights on DNDR trip & linear power density trip & alarm Caused by multi-purpose acquisition & control sys Error Code 10 W/830613 ltr
RAY, H B Southern California Edison Co 83/06/13 MARTIN, J B
Region 5, Office of Director App 19014 102 24X
Fiche 50-361, 83/06/13, 8306280267

8306280350 LER 83-052/03L-0 on 830524, purge/vent stack radiation monitor ZRI-7865 failed Caused by failure of crystal oscillator & input/output board in microprocessor Crystal oscillator & board replaced W/830614 ltr
RAY, H B, RAY, H B Southern California Edison Co 83/06/14 MARTIN, J B
Region 5, Office of Director App 19001 263 24X
Fiche 50-361, 83/06/14, 8306280350

8306280252 LER 83-056/03L-0 on 830516, w/plant in Mode 1, core protection calculator (CPC) D failed & placed in bypass condition Caused by degraded power supply, probably due to CPC cabinet cooling fan bearing failure W/830615 ltr
RAY, H B Southern California Edison Co 83/06/15 MARTIN, J B
Region 5, Office of Director App 19015 025 24X
Fiche 50-361, 83/06/15, 8306280252

8306280273 LER 83-050/03L-0 on 830519, during surveillance testing, core protection calculator channel C declared inoperable due to automatic restarts exceeding number allowed for 12 h period Caused by intermittent losses of power, W/830615 ltr
RAY, H B Southern California Edison Co 83/06/15 MARTIN, J B
Region 5, Office of Director App 19014 231 24X
Fiche 50-361, 83/06/15, 8306280273

8306280410 LER 83-044/01T-0 on 830210, review of circuitry associated w/Kirk Key interlock operation of HPB1 pumps 2P017 & 2P018 identified electrical continuity within breaker could result in simultaneous actuation of pumps W/830615 ltr
RAY, H B Southern California Edison Co 83/06/15 MARTIN, J B
Region 5, Office of Director App 19001 332 24X
Fiche 50-361, 83/06/15, 8306280410

8306230398 PNO-V-83-024 on 830616, while increasing condenser vacuum & resetting trip setpoint, low vacuum turbine trip occurred followed by reactor trip from 100% power, Caused by low primary plant pressure
ECKHARDT, J H, KIRSCH, D F Region 5, Office of Director 03/06/16
1p 18943 075 24X Fiche: 50-361, 83/06/16, 8306230398

U. Congressional/Executive Correspondence

8306160052 Response to FOIA request for records prepared by US govt employees re Alliance for Survival, T Carpenter &/or ongoing NRC investigation of facilities, Forwards App A documents Search for addl documents in progress
FELTON, J M Division of Rules and Records 83/04/14 CARPENTER, T
Orange County Alliance for Survival 2pp 18893 032 24X
Fiche 50-206, 83/04/14, 8306160052

--821160565 Forwards Community Energy Action Network 821018 ltr & Los Angeles Times article re potential problem w/welds at facilities
CRANSTON, A Senate, 82/10/29 KRAEMERER, C. Office of Congressional Affairs App 18893 056 24X Fiche: 50-206, 83/04/14, 8306160052

DOCKETED ITEMS

227

DOCKET 50-362 SAN ONOFRE NUCLEAR STATION, UNIT 3

F Security, medical, emergency & fire protection plans

8306070251 Forwards IE Insp Repts 50-206/83-10, 50-361/83-19 & 50-362/83-17 on 830411-27 & notice of violation
BISHOP, T W Region 5, Office of Director 83/05/16 PAPAY, L T
Southern California Edison Co 2pp 18746 088 24X
Fiche 50-206, 83/05/16, 8306070251

--8306070255 Notice of violation from insp on 830411-27
KIRBCH, D F Region 5, Office of Director 83/05/16 2pp
18746 090 24X Fiche 50-206, 83/05/16, 8306070251

--8306070261 IE Insp Repts 50-206/83-10, 50-361/83-19 & 50-362/83-17 on 830411-27 Noncompliance noted Failure to install fully 8-h emergency lighting units in access/egress routes
SCOWH, K M Region 5, Office of Director 83/05/11 1pp
18746 092 24X Fiche 50-206, 83/05/16, 8306070251

8306160011 Advises that 830323 Rev 9 to physical security plan consistent w/10CFR73 21 provisions & does not decrease plan effectiveness Changes acceptable
KNIGHTON, Q W Licensing Branch 3 83/06/06 DIETCH, R Southern California Edison Co HOLCOMBE, J C San Diego Gas & Electric Co 3pp
18872 148 24X Fiche 50-206, 83/06/06, 8306160011

8306220291 Responds to 830406 ltr re changes to physical security plan Changes consistent w/10CFR50 54(p) & do not decrease effectiveness of plan
KNIGHTON, Q W Licensing Branch 3 83/06/10 DIETCH, R Southern California Edison Co HOLCOMBE, J C San Diego Gas & Electric Co 3pp
18940 344 24X Fiche 50-206, 83/06/10, 8306220291

8306220294 Responds to 830323 ltr re Rev 2 to guard training & qualification plan Changes consistent w/10CFR50 54(p) provisions & do not decrease effectiveness of plan
KNIGHTON, Q W Licensing Branch 3 83/06/10 DIETCH, R Southern California Edison Co HOLCOMBE, J C San Diego Gas & Electric Co 3pp
18940 312 24X Fiche 50-206, 83/06/10, 8306220294

8306230520 Responds to 830427 ltr re temporary changes to physical security plan Changes consistent w/10CFR50 54(p) requirements & acceptable
KNIGHTON, Q W Licensing Branch 3 83/06/10 DIETCH, R Southern California Edison Co HOLCOMBE, J C San Diego Gas & Electric Co 2pp
18954 361 24X Fiche 50-206, 83/06/10, 8306230520

8306230455 Ack receipt & provides evaluation of changes to emergency plan implementing procedures submitted in 821029 & 831103 ltrs Changes do not decrease effectiveness of emergency response planning
NORRERHAU, L R Division of Radiological Safety & Safeguards Program 83/06/20 BASKIN, K P Southern California Edison Co 1p
18941 360 24X Fiche 50-206, 83/06/20, 8306230455

0 Adjudicatory correspondence

8306080195 Comments re offsite medical svcs, objections to applicant motion to augment record & request for hearing & proposed licensing condition Adequate arrangements for medical svcs not met. Further hearings required
MCCLUNG, C E Affiliation Unknown MCCLUNG, C E Flemming, Anderson, McClung & Finch 83/06/06 Atomic Safety and Licensing Board Panel 7pp
18772 251 24X Fiche 50-361, 83/06/06, 8306080195

8306080214 Response to util 830516 motion to augment record, position re Commission Memorandum & Order CLI-83-10 on offsite medical svcs & proposed findings of fact Supports motion & proposed findings
VOGLER, D H Hearing Branch 2 83/06/06 Atomic Safety and Licensing Board Panel 7pp
18771 101 24X Fiche 50-361, 83/06/06, 8306080214

--8306080216 Affidavit of DB Matthews that util ensured appropriate provisions for medical svcs to general public traumatically injured or contaminated during emergency Prof qualifications & Certificate of Svc encl.
MATTHEWS, D B Section 8 (Pre 820201) 83/06/06 7pp 18771 108, 24X Fiche 50-361, 83/06/06, 8306080214

8306080157 Order extending time until 830614 for Commission to act to review ALAB-717
CHILK, B J Office of the Secretary of the Commission 83/06/07 Commissioners 1p 18772:174, 24X Fiche 50-361, 83/06/07, 8306080157

8306160635 Order extending time until 830621 for Commission to act to review ALAB-717
CHILK, B J Office of the Secretary of the Commission 83/06/14 Commissioners 1p 18866 034 24X Fiche 50-361, 83/06/14, 8306160635

8306210288 Response opposing GUARD & Carstens 830606 joint request for hearing on medical svcs issues Issue of sufficiency of medical resources already litigated Hearing unnecessary to obtain authentication Certificate of Svc encl
CHANDLER, L J Hearing Branch 2 83/06/17 Atomic Safety and Licensing Board Panel 8pp
18915 011 24X Fiche 50-361, 83/06/17, 8306210288

8306220084 Reply to intervenor 830606 briefs on status of medical svcs issue Further hearings unjustified since Commission already ruled on adequacy of onsite medical svcs Declaration of Svc encl
PIGOTT, D R Southern California Edison Co PIGOTT, D R Orrick, Herrington & Sutcliffe 83/06/17 8pp 18927 173 24X Fiche 50-361, 83/06/17, 8306220084

8306220127 Affidavit of FK Massey supporting util 830516 motion to augment record, authenticating documents as portions of Orange & San Diego County emergency plans.
MABSEY, F K Southern California Edison Co 83/06/17 5pp
18926 107 24X Fiche 50-361, 83/06/17, 8306220127

J Insurance & indemnity information

8306270172 Forwards Endorsements 95, 96 & 97 to NELIA Policy NF-146, & Endorsements 83, 84 & 85 to MAELU Policy MF-38 & Endorsement 38 to NELIA Policy NB-282
ROCCO, J Southern California Edison Co 83/06/13 DINI, T I Antitrust & Economic Analysis Branch (Utility Finance) 8pp
18991 349, 24X Fiche 50-206, 83/06/13, 8306270172

K Utility Final Safety Analysis Report (FSAR) & amends

8306150002 Amend 32 to FSAR W/830606 ltr
DIETCH, R Southern California Edison Co COTTON, O D San Diego Gas & Electric Co 83/05/31 DENTON, H R Office of Nuclear Reactor Regulation, Director 332pp 18854 001 24X Fiche 50-361, 83/05/31, 8306150002

8306160275 Forwards Affidavit of Svc for Amend 32 to FSAR
MCDONALD, D P, PEMBERTON, H R Southern California Edison Co 83/06/14 KNIGHTON, Q W Licensing Branch 3 4pp 18860 173, 24X Fiche 50-361, 83/06/14, 8306160275

P Operating license stage documents & correspondence

8306070313 Discusses enhanced surveillance & maint activities of reactor trip breakers Tech Spec changes not appropriate at present time
BASKIN, K P Southern California Edison Co 83/06/03 KNIGHTON, Q W Licensing Branch 3 2pp 18741 115 24X Fiche 50-361, 83/06/03, 8306070313

8306080020 Forwards resolution of NRC comments on post-trip/restart review procedure, identifying procedure changes in response to NRC comments in Section III B 7 of SER.
BASKIN, K P Southern California Edison Co 83/06/03, KNIGHTON, Q W Licensing Branch 3 4pp 18773 001 24X Fiche 50-361, 83/06/03, 8306080020

8306090498 Requests remittance of Class III fees for 82119, 1203 & 20 Tech Spec amend requests, re shutdown cooling trains, turbine overspeed protection & component cooling water loop
MILLER, W D License Fee Management Branch 83/06/06 DIETCH, R Southern California Edison Co 2pp 18812 062 24X Fiche 50-361, 83/06/06, 8306090498

8306130386 Forwards Amend 6 to Topical Rept SCE-1-A, "QA Program," & miscellaneous documents per Final Rule 10CFR50 54(a) Rept supersedes program described in FSAR, App D
BASKIN, K P Southern California Edison Co 83/06/09, MARTIN, J B Region 5, Office of Director 3pp 18821:271 24X Fiche 50-206, 83/06/09, 8306130386

--8306130392 Amend 6 to Topical Rept SCE-1-A, "QA Program," * Southern California Edison Co SCE-1-A A06 83/04/30, 200pp, 18821:274 24X Fiche 50-206, 83/06/09, 8306130386

8306140644 Submits post-accident sampling sys (PASS) progress rept as of 830601 PASS outage scheduled for 830617-0810, Operator training course produced two qualified PASS operators
License Conditions 2 C, (19)1.1 & (17)1.4 satisfied
BASKIN, K P Southern California Edison Co 83/06/10 KNIGHTON, Q W Licensing Branch 3 3pp 18843 003, 24X Fiche 50-361, 83/06/10, 8306140644

DOCKETED ITEMS

- 8306300057 Forwards C-E repts, "Depressurization & DHR, Responses to NRC Questions," Suppl 1 to "PRA of Effects of PORVs on Depressurization & DHR" & "Responses to Plant-Specific Questions on Depressurization," per 820327 request BASKIN, K P Southern California Edison Co, 83/04/22 KNIGHTON, O W Licensing Branch 3 3pp 19117 062 24X Fiche: 50-361, 83/04/22, 8306300057
- 8306300136 Suppl 1 to CEN-239, "PRA of Effects of PORVs on Depressurization & DHR, San Onofre Nuclear Generating Station, Units 2 & 3," * Combustion Engineering, Inc CEN-239 801, 83/04/30 363pp 19118.083 24X Fiche 50-361, 83/04/22, 8306300057
- 8306300144 "Responses to Plant-Specific Questions on Depressurization & DHR (Questions 6a, 6b, 12, 13a, 13c & 13d)" * Southern California Edison Co 83/04/30 37pp 19119.088 24X Fiche: 50-361, 83/04/22, 8306300057.
- Q Inspection reports, IE Bulletins & correspondence
- 8306160046 FOIA request, on behalf of EE Kent, for records prepared by US govt employees re Alliance for Survival, T Carpenter &/or ongoing NRC investigation of facilities CARPENTER, T Orange County Alliance for Survival 83/03/14 Office of Administration 1p 18893 031 24X Fiche: 50-206, 83/03/14, 8306160046
- 8306100009 Addl response to FOIA request for documents dtd 820101 or after re BALP Forwards App A documents Documents also available in PDR. FELTON, J M Division of Rules and Records 83/04/11 CLARK, R San Francisco Examiner. 3pp. 18815 252 24X Fiche 50-000, 83/04/11, 8306100009
- 8306100014 Submits schedule for Region V BALP Board meetings for 820928-830523. ENOELKEN, R H Region 5, Office of Director. 82/03/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18815 255. 24X Fiche: 50-000, 83/04/11, 8306100009.
- 8306100036 Discusses assignment of BALP coordinators for Reactor Operations Projects Branch facilities Coordinators will be responsible for preparing input data used by board members in analyzing functional areas Draft note from B Miner encl STERNBERG, D M. Region 5, Office of Director 82/03/24, Region 5, Office of Director 11pp. 18815 257 24X Fiche: 50-000, 83/04/11, 8306100009
- 8306160197 Responds to FOIA request for documents re FOIA Request 82-618 Forwards App A documents. Documents 18 & 19(d) partially deleted (ref FOIA Exemption 4) FELTON, J. M. Division of Rules and Records 83/04/25 GARDE, B P Government Accountability Project App. 18893 125 24X Fiche 50-206, 83/04/25, 8306160197
- 8306160200 Forwards FOIA request Reliability determinations indicated in response ltrs to requester No action required FELTON, J M Division of Rules and Records 83/03/24 DIETCH, R. Southern California Edison Co. 1p. 18893 129 24X Fiche: 50-206, 83/04/25, 8306160197.
- 8306160209 Requests disclosure determination for listed documents subj to FOIA Request 82-618 GRIMBLEY, D. H. Division of Rules and Records. 83/02/07 ALEXANDER, I Region 5, Office of Director 2pp. 18893 148. 24X Fiche: 50-206, 83/04/25, 8306160197.
- 8306160218 Forwards documents re B Garde FOIA request, on behalf of EE Kent, for documents regarding 821120 IE rept "Special NRC Insp of San Onofre 1, 2 & 3 (FOIA-82-618)" W/o encl FORTUNA, R A Office of Investigation. 83/01/24. CARR, J C. Division of Rules and Records. 3pp. 18893 150 24X Fiche: 50-206, 83/04/25, 8306160197.
- 8306160223 Request disclosure determination for document originated by OFC re FOIA Request 82-618 by noon 830119. CARR, J. C. Division of Rules and Records. 83/01/12 WILSON, V. Office of Nuclear Reactor Regulation, Director. 2pp 18893: 157 24X Fiche: 50-206, 83/04/25, 8306160197
- 8306160230 Submits list of Region V Ofc of Investigation File Serials 24-42. "820408-Allegations Re: Holding of Piping by EE Kent," Case 5-82-021. Serials 1-25 previously provided in response to FOIA Request 82-528. SHACKLETON, D. C. Office of Investigation. 83/01/03. FORTUNA, R. A. Office of Investigation. 3pp. 18893: 159. 24X Fiche: 50-206, 83/04/25, 8306160197.
- 8306160243 Forwards list of documents available at Region V re B Garde FOIA Request 82-618 on EE Kent behalf, for documents concerning 821120 IE rept "Special NRC Insp of San Onofre 1, 2 & 3." ALEXANDER, I Region 5, Office of Director 83/12/28 NEED, C A Division of Rules and Records 3pp 18893 162 24X Fiche 50-206, 83/04/25, 8306160197
- 8306160253 Forwards DC Shackleton 821109 memo transmitting documents subj to FOIA Request 82-528 Review of Documents 1, 2, 10 & 19 by Region V recommended Confidentiality not sought by EE Kent FORTUNA, R A Office of Investigation 82/12/10 CARR, J C Division of Rules and Records 1p 18893 165 24X Fiche 50-206, 83/04/25, 8306160197
- 8306160263 Forwards list of documents responsive to FOIA Request 82-528 re EE Kent allegations concerning facilities from Oct 1980 to present Region V not aware of allegation until Oct 1982 SHACKLETON, D C Region 5, Office of Director 82/11/09 FORTUNA, R A Office of Investigation 5pp 18893 166 24X Fiche 50-206, 83/04/25, 8306160197
- 8306160276 Requests info responsive to FOIA Request 82-538 for documents re EE Kent allegations concerning facilities from Oct 1980 to present be forwarded to Div of Rules & Records by 821116 CARR, J C Division of Rules and Records 82/11/04. KIME, C Director's Office, Office of Inspection and Enforcement. 1p 18893 171 24X Fiche 50-206, 83/04/25, 8306160197
- 8306160281 Forwards list of documents responsive to FOIA Request 82-538 re EE Kent allegations concerning facilities from Oct 1980 to present, per 821104 memo Related info encl ENOELKEN, R H Region 5, Office of Director 82/11/17 CARR, J C Division of Rules and Records 5pp 18893 174 24X Fiche 50-206, 83/04/25, 8306160197
- 8306160301 Forwards FOIA Request 82-618 for documents re 821130 IE rept "Special NRC Insp of San Onofre 1, 2 & 3" Documents responsive to request should be forwarded to Div of Rules & Records by 830104. CARR, J. C. Division of Rules and Records 82/12/22 FORTUNA, R Office of Inspector & Auditor 1p. 18893 195. 24X Fiche 50-206, 83/04/25, 8306160197
- 8306160070 Addl response to FOIA request for records prepared by US govt employees re Alliance for Survival, T Carpenter &/or ongoing NRC investigation of facilities. IE Insp Repts 50-206/82-31, 50-361/82-31 & 50-362/82-27 available in PDR FELTON, J. M. Division of Rules and Records 83/04/28 CARPENTER, T. Orange County Alliance for Survival. 2pp 18892 338 24X Fiche: 50-206, 83/04/28, 8306160070
- 8306070240 Forwards IE Insp Repts 50-206/83-13, 50-361/83-21 & 50-362/83-19 on 830401-29. No noncompliance noted BISHOP, T W Region 5, Office of Director 83/05/13 PAPAY, L T Southern California Edison Co. 2pp. 18746 047 24X Fiche: 50-206, 83/05/13, 8306070240
- 8306070244 IE Insp Repts 50-206/83-13, 50-361/83-21 & 50-362/83-19 on 830401-29. No noncompliance noted Major areas inspected plant operations during long-term shutdown, monthly maint & surveillance activities & LERS. MILLER, L, KIRBCH, D F Region 5, Office of Director 83/05/12 8pp 18746 049 24X Fiche: 50-206, 83/05/13, 8306070240
- 8306070333 Forwards IE Insp Repts 50-206/83-08, 50-361/83-17 & 50-362/83-20 on 830329-0406 No noncompliance noted BOOK, H. E. Region 5, Office of Director 83/05/13 PAPAY, L T. Southern California Edison Co 2pp 18741: 077 24X Fiche: 50-206, 83/05/13, 8306070333.
- 8306070339 IE Insp Repts 50-206/83-08, 50-361/83-17 & 50-362/83-20 on 830329-0406 No noncompliance noted Major areas inspected lab QA program, including independent confirmatory measurements re Region V mobile lab. HAMADA, Q. H. TEMPLE, Q. M., GARCIA, E Region 5, Office of Director 83/05/12 10pp. 18741: 079 24X Fiche: 50-206, 83/05/13, 8306070333
- 8306070361 Forwards IE Insp Repts 50-361/83-22 & 50-362/83-21 on 830326-0422 No noncompliance noted. BISHOP, T W Region 5, Office of Director. 83/05/13. PAPAY, L T. Southern California Edison Co 2pp. 18742: 110. 24X Fiche: 50-361, 83/05/13, 8306070361
- 8306070368 IE Insp Repts 50-361/83-22 & 50-362/83-21 on 830326-0422. No noncompliance noted. Major areas inspected operational safety verification & LER review PATE, R. J., KIRBCH, D. F. Region 5, Office of Director. 83/05/12 4pp. 18742: 112 24X Fiche: 50-361, 83/05/13, 8306070361.

DOCKETED ITEMS

229

8306070251 Forwards IE Insp Repts 50-206/83-10, 50-361/83-19 & 50-362/83-17 on 830411-27 & notice of violation
BISHOP, T W Region 5, Office of Director 83/05/16 PAPAY, L T
Southern California Edison Co 2pp 18746 08B 24X
Fiche 50-206, 83/05/16, 8306070251

--8306070255 Notice of violation from insp on 830411-27
KIRSCH, D F Region 5, Office of Director 83/05/16 2pp
18746 090 24X Fiche 50-206, 83/05/16, 8306070251

--8306070261 IE Insp Repts 50-206/83-10, 50-361/83-19 & 50-362/83-17 on 830411-27 Noncompliance noted failure to install fully 8-h emergency lighting units in access/egress routes
SCDWN, K M, KIRSCH, D F Region 5, Office of Director 83/05/11 11pp 18746 092 24X Fiche 50-206, 83/05/16, 8306070251

8306010159 Ack receipt of 830518 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-361/83-14 & 50-362/83-14
BOOK, H E Region 5, Office of Director 83/05/25 PAPAY, L T
Southern California Edison Co 1p 18673 046 24X
Fiche 50-361, 83/05/25, 8306010159

--8306010164 Responds to NRC 830418 ltr re violations noted in IE Insp Repts 50-361/83-14 & 50-362/83-14 Corrective actions release procedures revised, requiring observance of monitor response & design change package ALARA review criteria strengthened.
FOOARTY, D J Southern California Edison Co 83/05/18 MARTIN, J B Region 5, Office of Director 4pp 18673 047 24X
Fiche 50-361, 83/05/25, 8306010159

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103). 83/05/26. Consolidated Edison Co of New York, Inc 125pp 18831-043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26. Consolidated Edison Co of New York, Inc 115pp 18732-085 24X Fiche 50-000, 83/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31. Consolidated Edison Co of New York, Inc 116pp 18732-208 24X Fiche 50-000, 83/05/31, 8305110461

8306070029 Responds to IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Bys on Diesel Generator." Raw water cooling sys & check valves not utilized in diesel generator at facilities
HAYNEB, J G Southern California Edison Co 83/06/03 MARTIN, J B Region 5, Office of Director 1p 18739 329 24X
Fiche 50-361, 83/06/03, 8306070029

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc. 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464.

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp. 18921-001 24X Fiche 50-000, 83/06/13, 8306090010

8306280498 Forwards IE Insp Repts 50-361/83-24 & 50-362/83-23 on 830425-0602 No noncompliance noted.
BISHOP, T W Region 5, Office of Director. 83/06/15 PAPAY, L T. Southern California Edison Co. 2pp. 19017 295. 24X
Fiche: 50-361, 83/06/15, 8306280498.

--8306280511 IE Insp Repts 50-361/83-24 & 50-362/83-23 on 830425-0602 No noncompliance noted. Major areas inspected startup test programs, including operational safety verification, power ascension testing, plant trips & LER review.
PATE, R J., CHAFFEE, A. E., STEWART, J. P. Region 5, Office of Director. 83/06/14 7pp. 19017:297 24X Fiche: 50-361, 83/06/15, 8306280498.

8306200378 Ack receipt of 830516 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-361/83-13 & 50-362/83-12 Undervoltage coil mechanism important. Violation A cited properly.
MARTIN, J B Region 5, Office of Director 83/06/17 FOOARTY, D J, Southern California Edison Co 3pp 18899 087 24X
Fiche 50-361, 83/06/17, 8306200378

--8306200381 Responds to NRC 830414 ltr re violations noted in IE Insp Repts 50-361/83-13 & 50-362/83-12. Item A in notice of violation re surveillance testing of reactor trip breaker unwarranted
FOOARTY, D J Southern California Edison Co 83/05/16 MARTIN, J B Region 5, Office of Director 7pp 18899 090 24X
Fiche 50-361, 83/06/17, 8306200378

8306280546 Forwards IE Insp Repts 50-361/83-15 & 50-362/83-13 on 830323-0602 & notice of violation
BISHOP, T W Region 5, Office of Director 83/06/17 PAPAY, L T. Southern California Edison Co. 3pp. 19018:109 24X
Fiche 50-361, 83/06/17, 8306280546

--8306280551 Notice of violation from insp on 830323-0602
KIRSCH, D.F. Region 5, Office of Director 83/06/17 7pp
19018:112 24X Fiche 50-361, 83/06/17, 8306280546

--8306280561 IE Insp Repts 50-361/83-15 & 50-362/83-13 on 830323-0602. Noncompliance noted, inadequate valve sys lineup procedures, failure to maintain certain fire protection valves locked open & alterations of official records
CHAFFEE, A., STEWART, P., KIRSCH, D.F. Region 5, Office of Director. 83/06/16 11pp. 19018.119 24X Fiche: 50-361, 83/06/17, 8306280546.

8306230211 Responds to IE Bulletin 83-05, "ASME Nuclear Code Pumps & Spare Parts Mfg by Hayward Tyler Pump Co " No sub pumps or spare parts in use or planned for use at facility
HAYNEB, J. G Southern California Edison Co 83/06/20 MARTIN, J B Region 5, Office of Director. 1p. 18946:348 24X
Fiche 50-361, 83/06/20, 8306230211.

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 115pp 19021.179 24X Fiche: 50-000, 83/06/22, 8305110475.

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Bys Causing Inoperability of Safety-Related Equipment " Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22. Consolidated Edison Co. of New York, Inc 120pp. 18997:007 24X Fiche: 50-000, 83/06/22, 8305110477.

8306240002 Application to amend License NPF-15, authorizing full-power operation on 830819.
DIETCH, R. Southern California Edison Co. 83/06/22 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 18981:309. 24X
Fiche. 50-362, 83/06/22, 8306240002

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co. of New York, Inc. 116pp 18996:242 24X Fiche: 50-000, 83/06/23, 8305110479.

8305110483 IE Info Notice 83-43, "Improper Bettings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc. 116pp. 19046:297. 24X Fiche: 50-000, 83/06/24, 8305110483

R. Periodic operating reports & related correspondence

8306160489 Monthly operating repts for Apr 1983 W/830513 ltr.
HAYWEATHER, L., RAY, H. B Southern California Edison Co. 83/05/13 Management Information Branch. 12pp 18864 139. 24X
Fiche: 50-361, 83/05/13, 8306160489.

S. Reportable occurrences, LERs & related correspondence

8306100072 RO on 830506, NFPA 72D std not met, due to improper design change which eliminated ability to differentiate between trouble & alarm signals. Design change package will be prepared by 830615 to modify circuitry.
RAY, H. B. Southern California Edison Co. 83/05/24 MARTIN, J B. Region 5, Office of Director. 2pp. 18802 181. 24X
Fiche. 50-361, 83/05/24, 8306100072.

DOCKETED ITEMS

8306140239 RO 83-034 on 830527, qualified safety parameter display sys failed to operate during completion & maint of inadequate core cooling instrumentation Caused by shorting of power cable due to abrasion
RAY, H B Southern California Edison Co 83/05/31 MARTIN, J B
Region 5, Office of Director 2pp 18833 001 24X
Fiche 50-362, 83/05/31, 8306140239

8306230447 LER 83-013/03L-0 on 830509, partial disengagement of rod-end bushing on mechanical shock snubber identified Caused by bearing assembly not properly secured Snubber reworked W/ 830608 ltr
RAY, H B Southern California Edison Co 83/06/08 MARTIN, J B
Region 5, Office of Director 4pp 18941 335 24X
Fiche 50-362, 83/06/08, 8306230447

8306230369 LER 83-038/03L-0 on 830511, spray sys protecting cable tunnel Section 3 declared inoperable when internals to deluge panel 315H8951 found corroded Caused by water intrusion due to improper closure of panel W/830610 ltr
RAY, H B Southern California Edison Co 83/06/10 MARTIN, J B
Region 5, Office of Director 3pp 18944 132 24X
Fiche 50-362, 83/06/10, 8306230369

U. Congressional/Executive Correspondence

8211160565 Forwards Community Energy Action Network 821018 ltr & Los Angeles Times article re potential problem w/welds at facilities
CRANSTON, A Senate 82/10/29 KRAMMERER, C Office of Congressional Affairs 3pp 18893 056 24X Fiche 50-206, 83/04/14, 8306160032

DOCKET 50-364 JOSEPH M FARLEY NUCLEAR PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8306090319 Forwards IE Safeguards Insp Repts 50-348/83-07 & 50-364/83-05 on 830227-0303 & notice of violation Rept details & notice of violation withheld (ref 10CFR73 21).
LEWIS, R C Division of Project & Resident Programs 83/03/23
MCDONALD, R P Alabama Power Co 2pp 18795 112 24X
Fiche 50-348, 83/03/23, 8306090319

--8306090324 IE Safeguards Insp Repts 50-348/83-07 & 50-364/83-05 on 830227-0303 Noncompliance noted failure of vital area alarms in access mode to indicate tamper Details withheld (ref 10CFR73 21)
MOORE, D E Region 2, Office of Director 83/03/23 1p 18795 114 24X Fiche 50-348, 83/03/23, 8306090319

8306020570 Comments on NUREG-0737, Item III A 2.1, "Emergency Preparedness, Upgrade Emergency Plans to App E, 10CFR50 " Onsite & offsite emergency preparedness adequate Item closed
VARQA, S A Operating Reactors Branch 1 83/05/24 CLAYTON, F L
Alabama Power Co 2pp 18715 066 24X Fiche 50-348, 83/05/24, 8306020570

8306010332 Forwards IE Safeguards Insp Repts 50-348/83-14 & 50-364/83-12 on 830509-13 No noncompliance noted
VERRELLI, D Division of Project & Resident Programs 83/05/26
MCDONALD, R P Alabama Power Co 2pp 18682 150 24X
Fiche 50-348, 83/05/26, 8306010332

--8306010333 IE Safeguards Insp Repts 50-348/83-14 & 50-364/83-12 on 830509-13 No noncompliance noted Major areas inspected site orientation, security organization-mst, personnel & response Details withheld (ref 10CFR73 21)
HALL, S L Region 2, Office of Director 83/05/24 1p 18682 152 24X Fiche 50-348, 83/05/26, 8306010332

8306140645 Forwards IE Insp Repts 50-348/83-11 & 50-364/83-09 on 830418-22 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/05/26
MCDONALD, R P Alabama Power Co 2pp 18841, 242 24X
Fiche 50-348, 83/05/26, 8306140645

--8306140655 IE Insp Repts 50-348/83-11 & 50-364/83-09 on 830418-22 No noncompliance noted Major areas inspected emergency preparedness
HARSTON, R R Region 2, Office of Director 83/05/24 6pp 18841 244 24X Fiche 50-348, 83/05/26, 8306140645

8306090204 Releases public version of emergency plan administrative procedures
FELTON, J M Division of Rules and Records 83/06/01 Document Management Branch 1p 18809 229 24X Fiche 50-348, 83/06/01, 8306090204

--8306090208 Public version of Emergency Plan Administrative Procedure FNP-83-0497, "On-Call Schedule " Schedule will be filed w/Procedure FNP-0-EIP-8 W/830811 ltr
HUDSPETH, J B Alabama Power Co 83/05/11 4pp 10009 230 24X
Fiche 50-348, 83/06/01, 8306090204

8306090329 Ack receipt of 830418 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-348/83-07 & 50-364/83-05
LEWIS, R C Division of Project & Resident Programs 83/06/06
MCDONALD, R P Alabama Power Co 2pp 18795 070 24X
Fiche 50-348, 83/06/06, 8306090329

--8306090332 Responds to NRC 830323 ltr re violations noted in IE Safeguards Insp Repts 50-348/83-07 & 50-364/83-05 Corrective actions withheld
CLAYTON, F L Alabama Power Co 83/04/18 LEWIS, R C Region 2, Office of Director 1p 18795 072 24X Fiche 50-348, 83/06/06, 8306090329

8306160027 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/06/06 Document Management Branch 1p 18072 295 24X Fiche 50-348, 83/06/06, 8306160027

--8306160032 Public version of Rev 11 to Emergency Plan Implementing Procedure FNP-0-EIP-4, "Chemistry & Health Physics Support to Emergency Plan " W/830824 ltr
HUDSPETH, J B Alabama Power Co 83/05/19 18pp 18072 246 24X
Fiche 50-348, 83/06/06, 8306160027

8306210363 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/06/06 Document Management Branch 1p 18937 097 24X Fiche 50-348, 83/06/06, 8306210363

--8306210365 Public version of Rev 12 to Emergency Plan Implementing Procedure FNP-0-EIP-9, "Radiation Exposure Estimation & Classification of Emergencies " Receipt form encl W/830421 ltr
HUDSPETH, J B Alabama Power Co 83/04/14 Office of Nuclear Reactor Regulation, Director 130pp 18937 098 24X
Fiche 50-348, 83/06/06, 8306210363

8306290198 Ack receipt of 830608 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/83-07 & 50-364/83-07
LEWIS, R C Division of Project & Resident Programs 83/06/16
MCDONALD, R P Alabama Power Co 2pp 19056 075 24X
Fiche 50-348, 83/06/16, 8306290198

--8306290207 Responds to NRC 830510 ltr re violations noted in IE Insp Repts 50-348/83-09 & 50-364/83-07 Corrective actions personnel instructed to close fire doors unless fire watch established & preventive maint program updated
CLAYTON, F L Alabama Power Co 83/06/08 LEWIS, R C Region 2, Office of Director 4pp 19056 077 24X Fiche 50-348, 83/06/16, 8306290198

--8306290222 IE Insp Repts 50-348/83-09 & 50-364/83-07 on 830306-0410 Noncompliance noted failure to follow calibr & recycle procedures & Tech Spec requirements for fire doors & Procedure FNP-1-57P-256 15, Rev 3, inadequate
BRADFORD, W H Region 2, Office of Director 83/05/06 10pp 19056 104 24X Fiche 50-348, 83/06/16, 8306290198

P Operating license stage documents & correspondence

8306010331 Submits list of post-trip review procedures to be modified following review of results of NUREG-0977 (Salem event) & discussion w/NRC Mods will be made within 30 days
CLAYTON, F L Alabama Power Co 83/05/24 VARQA, S A Office of Nuclear Reactor Regulation, Director 1p 18681 270 24X
Fiche 50-348, 83/05/24, 8306010331

8306020036 Ack receipt of 830510 ltr informing NRC of commitment for resolution of reactor protection sys DS-416 breaker problem. Program being reviewed Responsibility for review of conclusions transferred to Region 17
VARQA, S A Operating Reactors Branch 1 83/05/25, CLAYTON, F L
Alabama Power Co 2pp 18702 324 24X Fiche 50-348, 83/05/25, 8306020036

8306020030 Requests remittance of Class III fee for 821119 application to amend License NPF-8 re safety-related masonry wall design.
MILLER, W D License Fee Management Branch 83/05/26, CLAYTON, F L
Alabama Power Co 1p 18702, 332 24X Fiche 50-364, 83/05/26, 8306020030

8306010426 Application for amend to OL/proposing one-time Tech Spec 4 3 4 2a & 2b change to waive turbine valve testing during remainder of current fuel cycle Approval of 821008 request to delete Tech Spec 3/4 3 4 negates one-time change request
CLAYTON, F L Alabama Power Co 83/05/27 VARGA, S A Office of Nuclear Reactor Regulation, Director 3pp 18674 250 24X
Fiche 50-348, 83/05/27, 8306010426

--8306010429 Proposed one-time change to Tech Spec 4 3 4 2a & 2b waiving turbine valve testing during remainder of current fuel cycle
Alabama Power Co 83/05/27 2pp 18674 253 24X
Fiche 50-348, 83/05/27, 8306010426

8306060115 Appeals NRC 830429 decision that no basis exists for deleting turbine valve testing requirements NRC conclusion not factually based Interim relief from Tech Spec 3/4 3 4 requested Detailed comments submitted
CLAYTON, F L Alabama Power Co 83/05/31 VARGA, S A Office of Nuclear Reactor Regulation, Director 5pp 18719 077 24X
Fiche 50-348, 83/05/31, 8306060115

8306060201 Submits status & schedule re design changes, test procedures & confirmatory life program for DB-414 reactor trip breakers, per 830510 ltr & 830531 commitment Maint program will be modified upon completion of 6-month test program
CLAYTON, F L Alabama Power Co 83/05/31 VARGA, S A Office of Nuclear Reactor Regulation, Director 4pp 18727 324 24X
Fiche 50-348, 83/05/31, 8306060201

8306070326 Forwards RCS pressure isolation valve leakage results performed during first refueling outage, in response to 820810 & 1223 requests Valve disassembled & inspected Loose corrosion products may have prevented closure
CLAYTON, F L Alabama Power Co 83/06/03 VARGA, S A NRC - No Detailed Affiliation Given App 18741 111 24X
Fiche 50-348, 83/06/03, 8306070326

8306140610 Requests that until previous date of 830901 for approval of proposed amend to Tech Spec 3/4 1 3 re movable control assemblies be advanced to 830715 due to increase in control rod sys events
CLAYTON, F L Alabama Power Co 83/06/03 VARGA, S A Office of Nuclear Reactor Regulation, Director 2pp 18842 077 24X
Fiche 50-348, 83/06/03, 8306140610

8306130429 Application for amend to Licenses NPF-2 & NPF-B, changing Tech Specs re operating personnel, per NUREG-0737, Item I A 1 3 & Generic Ltrs 82-02 & 82-12, to incorporate current practices
CLAYTON, F L Alabama Power Co 83/06/06 VARGA, S A Office of Nuclear Reactor Regulation, Director 3pp 18821 223 24X
Fiche: 50-348, 83/06/06, 8306130429

--8306130442 Proposed Tech Specs re use of overtime for operating personnel
Alabama Power Co 83/06/06 3pp 18821 226 24X
Fiche 50-348, 83/06/06, 8306130429

8306140593 Commits to add action items associated w/Westinghouse reactor trip breakers, Model DB-416, based on 830602 telcon Only replacement undervoltage trip attachments w/record of 25 cycles will be used.
CLAYTON, F L Alabama Power Co 83/06/06 VARGA, S A Office of Nuclear Reactor Regulation, Director 3pp 18844 153 24X
Fiche: 50-348, 83/06/06, 8306140593

8306160278 Forwards status of all licensing items identified in Util 830113 ltr
CLAYTON, F L Alabama Power Co 83/06/10 VARGA, S A Office of Nuclear Reactor Regulation, Director 7pp 18860 177 24X
Fiche: 50-348, 83/06/10, 8306160278

8306230378 Application to amend Licenses NPF-2 & NPF-B, deleting Tech Spec requirement for river water sys surveillance & svc water bldg battery sys discharge test during shutdown
CLAYTON, F L Alabama Power Co 83/06/20 VARGA, S A Office of Nuclear Reactor Regulation, Director 3pp 18943 247 24X
Fiche 50-348, 83/06/20, 8306230378

--8306230382 Proposed Tech Spec changes, deleting requirement for river water sys surveillance & svc water bldg battery sys discharge test during shutdown
Alabama Power Co 83/06/20 9pp 18943 249 24X
Fiche: 50-348, 83/06/20, 8306230378

8306240040 Requests specific license amendments discussed during May 1983 telcons w/NRC be given priority to meet review schedules. Evaluation will avoid need to resubmit changes as emergency Tech Spec changes
CLAYTON, F L Alabama Power Co 83/06/20 VARGA, S A Office of Nuclear Reactor Regulation, Director 6pp 18981 089 24X
Fiche 50-348, 83/06/20, 8306240040

G Inspection reports, IE Bulletins & correspondence

8306090319 Forwards IE Safeguards Insp Repts 50-348/83-07 & 50-348/83-09 on 830227-0303 & notice of violation Rept details & notice of violation withheld (ref 10CFR73 21)
LEWIS, R C Division of Project & Resident Programs 83/03/23
MCDONALD, R P Alabama Power Co 2pp 18795 112 24X
Fiche 50-348, 83/03/23, 8306090319

--8306090324 IE Safeguards Insp Repts 50-348/83-07 & 50-348/83-09 on 830227-0303 Noncompliance noted Failure of vital area alarms in access mode to indicate tamper Details withheld (ref 10CFR73 21)
MOORE, D E Region 2, Office of Director MCQUIRE, D R Division of Emergency Preparedness & Materials Safety 83/03/23 1p 18795 114 24X Fiche 50-348, 83/03/23, 8306090319

8306140473 Forwards IE Insp Repts 50-348/83-12 & 50-348/83-10 on 830421-22 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/05/16
MCDONALD, R P Alabama Power Co 2pp 18834 326 24X
Fiche 50-348, 83/05/16, 8306140473

--8306140477 IE Insp Repts 50-348/83-12 & 50-348/83-10 on 830421-22 No noncompliance noted Major areas inspected, licenses program for keeping radiation exposures ALARA
DEBB, D T, MOSEY, C M Region 2, Office of Director BARR, K P Division of Engineering & Radiological Safety Programs 83/05/12 7pp 18834 328 24X Fiche 50-348, 83/05/16, 8306140473

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc. 129pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8306010332 Forwards IE Safeguards Insp Repts 50-348/83-14 & 50-348/83-12 on 830509-13 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/05/26
MCDONALD, R P Alabama Power Co 2pp 18682 150 24X
Fiche 50-348, 83/05/26, 8306010332

--8306010333 IE Safeguards Insp Repts 50-348/83-14 & 50-348/83-12 on 830509-13 No noncompliance noted Major areas inspected, site orientation, security organization-mgt, personnel & response, Details withheld (ref 10CFR73 21)
HALL, S L Region 2, Office of Director MCQUIRE, D R Division of Emergency Preparedness & Materials Safety 83/05/24 1p 18682 152 24X Fiche 50-348, 83/05/26, 8306010332

8306140645 Forwards IE Insp Repts 50-348/83-11 & 50-348/83-09 on 830418-22 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/05/26
MCDONALD, R P Alabama Power Co 2pp 18841 242 24X
Fiche 50-348, 83/05/26, 8306140645

--8306140655 IE Insp Repts 50-348/83-11 & 50-348/83-09 on 830418-22 No noncompliance noted Major areas inspected emergency preparedness
MARBTON, R R Region 2, Office of Director JENKINS, O R Division of Emergency Preparedness & Materials Safety 83/05/24 6pp 18841 244 24X Fiche 50-348, 83/05/26, 8306140645

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306140071 Responds to IE Bulletin 82-02, "Degradation of Threaded Fasteners in RCPB of PWR Plants " Maint & QA measures implemented Listed closure connection threaded fasteners opened for component insp/maint
CLAYTON, F L Alabama Power Co 83/05/31 O'REILLY, J P Region 2, Office of Director 3pp 18898 261 24X Fiche 50-348, 83/05/31, 8306140071

8306090329 Ack receipt of 830418 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-348/83-07 & 50-348/83-09
LEWIS, R C Division of Project & Resident Programs 83/06/06
MCDONALD, R P Alabama Power Co 2pp 18795 070 24X
Fiche: 50-348, 83/06/06, 8306090329

--8306090332 Responds to NRC 830323 ltr re violations noted in IE Safeguards Insp Repts 50-348/83-07 & 50-348/83-09, Corrective actions withheld
CLAYTON, F L Alabama Power Co 83/04/18 LEWIS, R C Region 2, Office of Director 1p 18795 072 24X Fiche 50-348, 83/06/06, 8306090329

DOCKETED ITEMS

8305110444 IE Info Notice 83-34, "Impact of Security Practices on Safe Operations." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/09. Consolidated Edison Co. of New
York, Inc. 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110444

8306170357 Submits evaluation of plant design & initial description of
planned actions in response to IE Bulletin 83-03 re diesel
generator svc water sys Check valve design & matts superior.
Final evaluation forthcoming
CLAYTON, F. L. Alabama Power Co. 83/06/10 O'REILLY, J. P. Region 2,
Office of Director 3pp 18880 178. 24X Fiche: 50-348, 83/06/10,
8306170357

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive &
Seismically Induced Chatter in Relays Within Printed
Circuit Cards." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13. Consolidated Edison Co. of New
York, Inc. 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From
Degraded Internal Connection Cables." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13. Consolidated Edison Co. of New
York, Inc. 243pp. 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8306290198 Ack receipt of 830608 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-348/83-09 &
50-364/83-07.
LEWIS, R. C. Division of Project & Resident Programs 83/06/16
MCDONALD, R. P. Alabama Power Co. 2pp. 19036 095. 24X
Fiche: 50-348, 83/06/16, 8306290198

--8306290207 Responds to NRC 830510 ltr re violations noted in IE Insp
Repts 50-348/83-09 & 50-364/83-07 Corrective actions
personnel instructed to close fire doors unless fire watch
established & preventive maint program updated
CLAYTON, F. L. Alabama Power Co. 83/06/08 LEWIS, R. C. Region 2,
Office of Director 4pp. 19036 097 24X Fiche: 50-348, 83/06/16,
8306290198

--8306290213 Forwards IE Insp Repts 50-348/83-09 & 50-364/83-07 on
830306-0410 & notice of violation
LEWIS, R. C. Division of Project & Resident Programs. 83/05/10
MCDONALD, R. P. Alabama Power Co. 2pp 19036 101 24X
Fiche: 50-348, 83/06/16, 8306290198

--8306290216 Notice of violation from insp on 830306-0410.
* Region 2, Office of Director. 83/05/10 1p. 19036 103. 24X
Fiche: 50-348, 83/06/16, 8306290198

--8306290222 IE Insp Repts 50-348/83-09 & 50-364/83-07 on 830306-0410
Noncompliance noted: failure to follow calibr & recycle
procedures & Tech Spec requirements for fire doors &
Procedure FNP-1-57P-256 15, Rev 3, inadequate.
BRADFORD, M. H., RULAND, W. H. Region 2, Office of Director.
CANTRELL, F. B. Division of Project & Resident Programs. 83/05/06.
10pp. 19036 104. 24X Fiche: 50-348, 83/06/16, 8306290198.

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
Epoxy Grouts & Sealers." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22. Consolidated Edison Co. of New
York, Inc. 115pp 19021 179 24X Fiche: 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys
Causing Inoperability of Safety-Related Equipment." Svc list
encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22. Consolidated Edison Co. of New
York, Inc. 120pp. 18997 007 24X Fiche: 50-000, 83/06/22, 8305110477.

8305110483 IE Info Notice 83-42, "Improper Settings of Intermediate
Range (IR) High Flur Trip Setpoints." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24. Consolidated Edison Co. of New
York, Inc. 116pp. 19046 297. 24X Fiche: 50-000, 83/06/24, 8305110483

R. Periodic operating reports & related correspondence

8306160119 Monthly operating rept for May 1983, W/830610 ltr
CLAYTON, F. L., HAIRSTON, W. O. Alabama Power Co. 83/06/02. Office
of Resource Management, Director. 7pp. 18861 273 24X
Fiche: 50-344, 83/06/02, 8306160119.

S Reportable occurrences, LERs & related correspondence

8306200216 Forwards LERs 83-023/03L-0, 83-023/03L-0 & 83-024/03L-0.
CLAYTON, F. L. Alabama Power Co. 83/06/10. Region 2, Office of
Director 1p. 18902 279. 24X Fiche: 50-348, 83/06/10, 8306200216

--8306200227 LER 83-023/03L-0 on 830511, train B reactor trip breaker
would not reclose Caused by design inadequacy Voltage
available to undervoltage device coil marginally sufficient
to allow undervoltage device to remain latched
HAIRSTON, W. O. Alabama Power Co. 83/06/10 Region 2, Office of
Director 4pp 18902 281 24X Fiche 50-348, 83/06/10, 8306200216

--8306200233 LER 83-024/03L-0 on 830512, rod control sys declared
inoperable upon receipt of failure alarm on power cabinet
2AC Caused by failure of regulator circuitry card Card
replaced
HAIRSTON, W. O. Alabama Power Co. 83/06/10 Region 2, Office of
Director 1p 18902 285 24X Fiche 50-348, 83/06/10, 8306200216

DOCKET 50-366 EDWIN I HATCH NUCLEAR PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8306030233 Forwards revised response to 820701 requests for exemption
from 10CFR50.48 & App R requirements, per 830330 request Rev
reflects compliance w/10CFR50.48 & App R requirements &
responds to 830120 draft SER concerns
GUCHA, L. T. Georgia Power Co. 83/05/27 STOLZ, J. F. Operating
Reactors Branch 4 164pp 18705 023 24X Fiche 50-321, 83/05/27,
8306030233

8306140711 Approves issuance of BALP Repts 50-321/83-06, 50-366/83-06,
50-424/83-06 & 50-425/83-06 for Jul 1981 - Oct 1982
LEWIS, R. C. Division of Project & Resident Programs 83/06/01
KELLY, R. J. Georgia Power Co. 3pp 18841 196 24X
Fiche 50-000, 83/06/01, 8306140711

--8306140719 Advises of 830317 meeting in Atlanta, GA to discuss BALP
Repts 50-321/83-06, 50-366/83-06, 50-424/83-06 & 50-425/83-06
for Jul 1981 - Oct 1982
LEWIS, R. C. Division of Project & Resident Programs 83/03/09
KELLY, R. J. Georgia Power Co. 2pp 18841 199 24X
Fiche 50-000, 83/06/01, 8306140711

--8306140730 BALP Repts 50-321/83-06, 50-366/83-06, 50-424/83-06 &
50-425/83-06 for Jul 1981 - Oct 1982 No significant util
weaknesses identified
* Region 2, Office of Director 83/03/09 38pp 18841 201 24X
Fiche 50-000, 83/06/01, 8306140711

--8306140743 Ack receipt of BALP Repts 50-321/83-06, 50-366/83-06,
50-424/83-06 & 50-425/83-06 for Jul 1981 - Oct 1982
Evaluation acceptable
BECKHAM, J. T. Georgia Power Co. 83/04/18 O'REILLY, J. P. Region
2, Office of Director 1p 18841 239 24X Fiche 50-000, 83/06/01,
8306140711

8306150133 Releases public version of revised emergency plan
implementing procedures
FELTON, J. M. Division of Rules and Records 83/06/01 Document
Management Branch 1p 18872 092 24X Fiche 50-321, 83/06/01,
8306150133

--8306150137 Forwards public version of revised emergency plan
implementing procedures, including Procedures HNP-2-4219 re
battery fire, HNP-4890 re exercises & drills & HNP-4621 re
actions for personnel in site area emergency
NIX, H. C. Georgia Power Co. 83/05/18 Office of Nuclear Reactor
Regulation, Director 1p 18872 093 24X Fiche 50-321, 83/06/01,
8306150133

--8306150141 Public version of revised emergency plan implementing
procedures, including Procedures HNP-2-4219 re battery fire,
HNP-4890 re exercises & drills & HNP-4621 re actions for
personnel in site area emergency
BUHNER, L. Georgia Power Co. 83/05/06 26pp 18872 094 24X
Fiche: 50-321, 83/06/01, 8306150133.

8306140237 Releases public version of revised emergency plan
implementing procedures
FELTON, J. M. Division of Rules and Records 83/06/06 Document
Management Branch 1p 18844 258 24X Fiche 50-321, 83/06/06,
8306140237

--8306140246 Forwards public version of revised emergency plan
implementing procedures, including Procedures HNP-8137 re
portable ion chamber Model RD-2A, HNP-8143 re low vol air
sampler Model H-809 VI & HNP-4200 re fire procedure.
NIX, H. C. Georgia Power Co. 83/05/24 Office of Nuclear Reactor
Regulation, Director 4pp 18844 259 24X Fiche 50-321, 83/06/06,
8306140237

--B306140254 Public version of revised emergency plan implementing procedures, including Procedures HNP-8137 re portable ion chamber Model RO-2A, HNP-8143 re low vol air sampler Model H-809 VI & HNP-4200 re general fire procedure
* Georgia Power Co 83/05/24 37pp 18844 263 24X
Fiche 50-321,83/06/06,8306140237

B306150037 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/06/07 Document
Management Branch 1p 18871 182 24X Fiche 50-321,83/06/07,
B306150037

--B306150041 Forwards public version of revised emergency plan implementing procedures, including Procedures HNP-8156 re Gamma-10 portal monitor operation, HNP-4623 re site emergency shift supervisor & HNP-4626 re rally point leader
NIX, H C Georgia Power Co 83/04/25 Office of Nuclear Reactor Regulation, Director 1p 18871 183 24X Fiche 50-321,83/06/07,
B306150037

--B306150044 Public version of revised emergency plan implementing procedures, including Procedures HNP-8156 re gamma-10 portal monitor operation, HNP-4623 re site emergency-shift supervisor & HNP-4626 re rally point leader
NIX, H C Georgia Power Co 83/04/15 105pp 18871 184 24X
Fiche 50-321,83/06/07,8306150037

B306220307 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/06/07 Document
Management Branch 1p 18940 114 24X Fiche 50-321,83/06/07,
B306220307

--B306220313 Forwards public version of revised emergency plan implementing procedures, including Procedures HNP-8004 re personnel dosimeter program, HNP-8016 re shipment of radioactive matl & HNP-4622 re control room operators
NIX, H C Georgia Power Co 83/05/04 Office of Nuclear Reactor Regulation, Director 1p 18940 115 24X Fiche 50-321,83/06/07,
B306220307

--B306220310 Public version of revised emergency plan implementing procedures, including Procedures HNP-8004 re personnel dosimeter program, HNP-8016 re shipment of radioactive matl & HNP-4622 re control room operators
ROGERS, W H, NIX, H C Georgia Power Co 83/04/26 Office of Nuclear Reactor Regulation, Director 181pp 18940 116 24X
Fiche 50-321,83/06/07,8306220307

B306170202 Forwards addl info to justify B20701 10CFR50 4B & App R schedule exemption requests discussed at B30330 meeting. Plan being developed to complete maint & design changes w/two oversize drawings Aperture cards available in PDR
GUCHA, L T Georgia Power Co 83/06/14 STOLZ, J F Operating Reactors Branch 4 4pp 18882 277 24X Fiche 50-321,83/06/14,
B306170202

I Financial information

B306070123 Forwards Annual Financial Repts, 1982
GUCHA, L T Georgia Power Co 83/06/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18739 038 24X
Fiche 50-000,83/06/02,8306070123,

--B306070127 Annual Financial Rept, 1982
VOGTLE, A W The Southern Co 83/03/10 51pp 18739 039 24X
Fiche 50-000,83/06/02,8306070123

--B306070130 Annual Financial Rept, 1982
SCHERER, R W, MILLER, J H, Georgia Power Co 83/03/07 36pp
18739 091 24X Fiche 50-000,83/06/02,8306070123

P Operating license stage documents & correspondence

B306010056 Advises that addl Tech Specs needed to assure that current Tech Spec limits for min critical power ratio are conservative. Tech Spec must assure operability of sys for inclusion in reload amend prior to restart
STOLZ, J F Operating Reactors Branch 4 83/05/12 BECKHAM, J T Georgia Power Co 6pp 18687 091 24X Fiche 50-366,83/05/12,
B306010056

B306150478 Discusses B30223 application for amend to License NPF-5, modifying Tech Specs to provide addl & revised trip setpoints reflecting design mods to reduce containment loads from transients FR notice of consideration encl.
RIVENBARK, O W, Operating Reactors Branch 4 83/05/12 BECKHAM, J T Georgia Power Co 2pp 18867 347 24X Fiche 50-366,83/05/12,
B306150478.

--B306150484 Notice of consideration of issuance of amend to License NPF-5 & proposed no significant hazards consideration determination & opportunity for hearing
STOLZ, J F Operating Reactors Branch 4 83/05/12 8pp
18867 349 24X Fiche 50-366,83/05/12,8306150478

B306030239 Forwards request for addl info re B30330 reload application for Cycle 4 operation Expedited response requested
STOLZ, J F Operating Reactors Branch 4 83/05/19 BECKHAM, J T Georgia Power Co 3pp 18734 019 24X Fiche 50-366,83/05/19,
B306030239

B306070224 Forwards Rev 0 to "EI Hatch Nuclear Plant Units 1 & 2 Environ Qualification of Class IE Equipment," in response to IE Bulletin 79-01B & 10CFR50 49 requirements
GUCHA, L T Georgia Power Co 83/05/20 STOLZ, J F Operating Reactors Branch 4 219pp 18746 152 24X Fiche 50-321,83/05/20,
B306070224

B306010367 Application for amend to License NPF-5, proposing addl Tech Spec surveillance requirements for high reactor water level trip function & main turbine bypass valves
BECKHAM, J T Georgia Power Co 83/05/24 STOLZ, J F Operating Reactors Branch 4 3pp 18682 107 24X Fiche 50-366,83/05/26,
B306010367

--B306010371 Proposed Tech Specs re addl surveillance requirements for high reactor water level trip function & main turbine bypass valves
* Georgia Power Co 83/05/26 7pp 18682 110 24X
Fiche 50-366,83/05/26,8306010367

B306030082 Notification of B30601 meeting w/util in Bethesda, MD to discuss util evaluation & repair of cracks discovered in weld areas of recirculation & reactor heat removal sys piping
RIVENBARK, O W Operating Reactors Branch 4 83/05/27 STOLZ, J F Operating Reactors Branch 4 2pp 18733 264 24X
Fiche 50-366,83/05/27,8306030082

B306070129 Requests withdrawal of B20430 proposed Tech Spec changes re safety-related snubber insp & surveillance requirements. Inoperable snubber conditions defined in proposed changes do not reflect actual operability concerns
GUCHA, L T Georgia Power Co 83/05/31 STOLZ, J F Operating Reactors Branch 4 1p 18739 254 24X Fiche 50-321,83/05/31,
B306070129

B306070351 Application for amend to Licenses DPR-57 & NPF-5, revising dose equivalent iodine Tech Specs to reflect current requirements Info resolving outstanding purge & vent valve operability issues encl
BECKHAM, J T Georgia Power Co 83/05/31 STOLZ, J F Operating Reactors Branch 4 34pp 18742 071 24X Fiche 50-321,83/05/31,
B306070351

--B306070357 Proposed changes to dose equivalent iodine Tech Specs & preliminary proposed Tech Specs for drywell & suppression chamber purge sys
* Georgia Power Co 83/05/31 5pp 18742 103 24X
Fiche 50-321,83/05/31,8306070351.

B306070125 Submits revs to B30525 augmented RCS leak detection submittal & inservice insp program commitment, incorporating surveillance frequencies per NUREG-0313, Rev 1, Insp & for mod plans for recirculation & RHR sys piping forthcoming
GUCHA, L T Georgia Power Co 83/06/02 STOLZ, J F Operating Reactors Branch 4 2pp 18739 266 24X Fiche 50-366,83/06/02,
B306070125

B306160397 Forwards revised pages to plant unique analysis rept re resolution of torus-attached piping pump & valve evaluation Pages reflect satisfactory results of evaluation of 14 valves & two pumps.
GUCHA, L T Georgia Power Co 83/06/02 STOLZ, J F Operating Reactors Branch 4 6pp 18860 102 24X Fiche 50-366,83/06/02,
B306160397

B306220219 Presents alternatives to automatic depressurization sys logic to eliminate need for manual actuation for core coverage per TMI Item II K 3 18 Implementation schedule & proposed Tech Specs requested within 45 days of ltr receipt
STOLZ, J F Operating Reactors Branch 4 83/06/03 BECKHAM, J T Georgia Power Co 2pp 18951 001 24X Fiche 50-321,83/06/03,
B306220219

B306100132 Forwards Rev 0 to "Design Rept for Weld Overlay Repairs & Flaw Evaluations in Recirculation & RHR Sys " Sensor check will be performed every 4 hours in addition to interval required by Tech Specs, effective at restart
GUCHA, L T Georgia Power Co 83/06/08 STOLZ, J F Operating Reactors Branch 4 2pp 18801 262 24X Fiche 50-366,83/06/08,
B306100132

DOCKETED ITEMS

--B3061400136 Rev 0 to "Design Rept for Weld Overlay Repairs & Flaw Evaluations in Recirculation & RHR Sys."
GUSTIN, H. L., CHARLNEY, J. E., MCINNES, I. D. NUTECH Engineers, Inc
QPC-07-102 R00 83/06/07 104pp 18801 244 24X
Fiche 50-366, 83/06/08, B3061400132

B306140075 Advises that SER & technical evaluation repts re environ qualification of safety-related electrical equipment do not contain proprietary info. Repts may be placed in PDR.
GUCHA, L. T. Georgia Power Co 83/06/08 STOLZ, J. F. Operating Reactors Branch 4 1p 18839.114 24X Fiche: 50-321, 83/06/08, B306140075

B306150228 Forwards revised Page B 3/4 3-6 of proposed Tech Spec changes re reactor vessel water level submitted on B30526, in response to NRC B30512 request
GUCHA, L. T. Georgia Power Co 83/06/09 STOLZ, J. F. Operating Reactors Branch 4 1p 18846 287 24X Fiche 50-366, 83/06/09, B306150228

--B306150232 Revised Page B 3/4 3-6 of B30526 proposed Tech Spec changes re reactor vessel water level.
* Georgia Power Co 83/06/09 1p 18846 288, 24X
Fiche 50-366, 83/06/09, B306150228

B306160267 Forwards evaluation results demonstrating as-built acceptability of wetwell/drywell vacuum breakers on Mari I containments, in response to Generic Ltr 83-08
GUCHA, L. T. Georgia Power Co 83/06/09 STOLZ, J. F. Operating Reactors Branch 4 16pp 18859 329 24X Fiche: 50-321, 83/06/09, B306160267,

B306220002 Application for amend to Licenses DPR-57 & NPF-5 changing Tech Specs 3/4 6-2, B 3/4 6-6 & adding 3/4 6-4b for Unit 2 & 3 7-10a, 3 7-34, 3 7-34a & adding 3 7-10b & 3 7-34b for Unit 1 re purge & vent valve operability
BECKHAM, J. T. Georgia Power Co 83/06/15 STOLZ, J. F. Operating Reactors Branch 4 3pp 18928.003, 24X Fiche 50-321, 83/06/15, B306220002

--B306220010 Proposed changes to Tech Specs 3/4 6-2, B 3/4 6-6 & added 3/4 6-4b for Unit 2 & 3, 7-10a, 3 7-34, 3 7-34a & adding 3 7-10b & 3 7-34b for Unit 1 re purge & vent valve operability.
* Georgia Power Co 83/06/15, 55pp 18928 008 24X
Fiche: 50-321, 83/06/15, B306220002

B306210335 Notification of B30623 meeting w/uttl in Atlanta, GA to discuss status of Region II review of inservice pump & valve test program & questions re program
RIVENBARK, O. Operating Reactors Branch 4 83/06/20 STOLZ, J. Operating Reactors Branch 4 2pp 18935-313 24X
Fiche: 50-321, 83/06/20, B306210335

B306270170 Application for amend to License NPF-5, revising Tech Spec Table 3 3 2-1 re isolation actuation instrumentation
CAUSEY, J. C. Georgia Power Co 83/06/20 STOLZ, J. F. Operating Reactors Branch 4 3pp 18992 003 24X Fiche: 50-366, 83/06/20, B306270170

--B306270175 Proposed Tech Spec Table 3 3 2-1 re isolation actuation instrumentation.
* Georgia Power Co 83/06/20 4pp 18992 006 24X
Fiche 50-366, 83/06/20, B306270170,

B306270120 Submits addl info re B30620 request for Tech Spec relief from requirement to have Group II isolation to occur on reactor water level low signal.
BECKHAM, J. T. Georgia Power Co 83/06/21, STOLZ, J. F. Operating Reactors Branch 4 2pp 18988.110 24X Fiche 50-366, 83/06/21, B306270120

0. Inspection reports, IE Bulletins & correspondence

B306140116 Forwards summary of IE mgt meetings on B30318 & 22 w/uttl to discuss condition of electrical cable trays & associated equipment & lack of mgt controls.
O'REILLY, J. P. Region 2, Office of Director. 83/04/08 KELLY, R. J. Georgia Power Co 4pp 18839.092, 24X Fiche: 50-321, 83/04/08, B306140116

B306070224 Forwards Rev 0 to "EI Hatchh Nuclear Plant Units 1 & 2 Environ Qualification of Class IE Equipment," in response to IE Bulletin 79-01B & 10CFR30.49 requirements.
GUCHA, L. T. Georgia Power Co 83/05/20 STOLZ, J. F. Operating Reactors Branch 4 10pp 18747.001 24X Fiche: 50-321, 83/05/20, B306070224

B306140515 Forwards IE Insp Repts 50-321/83-14 & 50-366/83-14 on B30426-29 & 0503-05 No noncompliance noted
DANCE, H. C. Division of Project & Resident Programs 83/05/25 KELLY, R. J. Georgia Power Co 2pp 18843 238 24X
Fiche 50-321, 83/05/25, B306140515

--B306140522 IE Insp Repts 50-321/83-14 & 50-366/83-14 on B30426-29 & 0503-05 No noncompliance noted Major areas inspected inservice insp, previous enforcement matters & welding Meeting held to discuss IE Bulletin 83 02 insp results
CROWLEY, B. R. Region 2, Office of Director BLAKE, J. J. Division of Engineering & Radiological Safety Programs 83/05/23 15pp 18849 240 24X Fiche 50-321, 83/05/25, B306140515

B305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl
TAYLOR, J. M. Division of Safeguards & Inspection Programs (Post B30103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000, 83/05/26, B305110458

B305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, B305110460

B306140563 Corrected response to IE Bulletin 83-02 re inservice insp activities concerning stress corrosion cracking in large diameter, stainless steel recirculation sys piping at BWR plants Weld exam list encl
BECKHAM, J. T. Georgia Power Co 83/05/26 O'REILLY, J. P. Region 2, Office of Director 27pp 18834 239 24X Fiche 50-366, 83/05/26, B306140563

B305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, B305110461

B306070129 Requests withdrawal of B20420 proposed Tech Spec changes re safety-related snubber insp & surveillance requirements Inoperable snubber conditions defined in proposed changes do not reflect actual operability concerns
GUCHA, L. T. Georgia Power Co 83/05/31 STOLZ, J. F. Operating Reactors Branch 4 1p 18739 254 24X Fiche 50-321, 83/05/31, B306070129

B306140711 Approves issuance of SALP Repts 50-321/83-06, 50-366/83-06, 50-424/83-06 & 50-425/83-06 for Jul 1981 - Oct 1982
LEWIS, R. C. Division of Project & Resident Programs 83/06/01 KELLY, R. J. Georgia Power Co 3pp 18841 196 24X
Fiche 50-000, 83/06/01, B306140711

--B306140719 Advises of B30317 meeting in Atlanta, GA to discuss SALP Repts 50-321/83-06, 50-366/83-06, 50-424/83-06 & 50-425/83-06 for Jul 1981 - Oct 1982
LEWIS, R. C. Division of Project & Resident Programs 83/03/09 KELLY, R. J. Georgia Power Co 2pp 18841 199 24X
Fiche 50-000, 83/06/01, B306140711

--B306140730 SALP Repts 50-321/83-06, 50-366/83-06, 50-424/83-06 & 50-425/83-06 for Jul 1981 - Oct 1982 No significant util weaknesses identified
* Region 2, Office of Director 83/03/09 38pp 18841 201 24X
Fiche 50-000, 83/06/01, B306140711

--B306140743 Ack receipt of SALP Repts 50-321/83-06, 50-366/83-06, 50-424/83-06 & 50-425/83-06 for Jul 1981 - Oct 1982
Evaluation acceptable
BECKHAM, J. T. Georgia Power Co 83/04/18 O'REILLY, J. P. Region 2, Office of Director 1p 18841 239 24X Fiche 50-000, 83/06/01, B306140711

B306070125 Submits revs to B30525 augmented RCS leak detection submittal & inservice insp program commitment incorporating surveillance frequencies per NUREG-0313, Rev 1 Insp &/or mod plans for recirculation & RHR sys piping forthcoming
GUCHA, L. T. Georgia Power Co 83/06/02 STOLZ, J. F. Operating Reactors Branch 4 2pp 18739 266 24X Fiche 50-366, 83/06/02, B306070125

B306240006 Discusses IE insp on B30227-0226 & forwards notice of violation & proposed imposition of civil penalty
O'REILLY, J. P. Region 2, Office of Director, 83/06/02 KELLY, R. J. Georgia Power Co 3pp 18987 341 24X Fiche 50-321, 83/06/02, B306240006

- 8306240014 Notice of violation & proposed imposition of civil penalty in amount of \$40,000 Noncompliance noted failure to restore cable tray sys to quality conditions & lack of QA planning for mods & maint re electrical cable tray installation
O'REILLY, J P Region 2, Office of Director 83/06/02 App 18987 344 24X Fiche 50-321,83/06/02,8306240006
- 8306290455 Submits addl response to IE Bulletin B1-03 Fire protection sys uses water from deep well Sys not susceptible to clam infiltration Mutilus sp not present in Altamaha River in vicinity of plant
BECKHAM, J T Georgia Power Co 83/06/02 O'REILLY, J P Region 2, Office of Director 2pp 19052 181 24X Fiche 50-321,83/06/02,8306290455
- 8306140075 Advises that SER & technical evaluation repts re environ qualification of safety-related electrical equipment do not contain proprietary info Repts may be placed in PDR
GUCHA, L T Georgia Power Co 83/06/08 STOLZ, J F Operating Reactors Branch 4 1p 18839 114 24X Fiche 50-321,83/06/08,8306140075
- 8306290264 Responds to IE Bulletin 83-03 re check valve failures in raw water cooling sys of diesel generators No check valves installed in cooling water sys at facilities
BECKHAM, J T Georgia Power Co 83/06/08 O'REILLY, J P Region 2, Office of Director 3pp 19056 075 24X Fiche 50-321,83/06/08,8306290264
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 11pp 18830 280 24X Fiche 50-000,83/06/09,8305110464
- 8305110470 IE Info Notice 83-30, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 11pp 18920 225 24X Fiche 50-000,83/06/13,8305110470
- 8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 24pp 18921 001 24X Fiche 50-000,83/06/13,8306090010
- 8306290254 Ack receipt of 830526 ltr informing NRC of steps taken to correct violations noted in IF Insp Repts 50-321/83-07 & 50-366/83-07
LEWIS, R C Division of Project & Resident Programs 83/06/16 KELLY, R J Georgia Power Co 1p 19056 058 24X Fiche 50-321,83/06/16,8306290254
- 8306290265 Responds to NRC 830421 ltr re violations noted in IE Insp Repts 50-321/83-07 & 50-366/83-07 Corrective actions valve handwheels being painted orange, adjustable wrenches removed & procedures for key lock switches revised
BECKHAM, J T Georgia Power Co 83/05/26 O'REILLY, J P Region 2, Office of Director 4pp 19056 059 24X Fiche 50-321,83/06/16,8306290254
- 8306290278 Forwards IE Insp Repts 50-321/83-07 & 50-366/83-07 on 830122-0226 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/04/21 KELLY, R J Georgia Power Co 2pp 19056 063 24X Fiche 50-321,83/06/16,8306290254
- 8306290293 IE Insp Repts 50-321/83-07 & 50-366/83-07 on 830122-0226 Noncompliance noted failure to implement procedures properly re primary containment atmospheric control sys & operation of safety-related sys.
CARLENAK, R V, HOLMES-RAY, P. Region 2, Office of Director BROUNLEE, V L Division of Project & Resident Programs 83/04/12 6pp 19056 067 24X Fiche 50-321,83/06/16,8306290254
- 8306290298 Ack receipt of 830523 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/83-08 & 50-366/83-08
LEWIS, R C Division of Project & Resident Programs 83/06/16 KELLY, R J Georgia Power Co 1p 19056 017 24X Fiche 50-321,83/06/16,8306290298
- 8306290303 Responds to NRC 830421 ltr re violations noted in IE Insp Repts 50-321/83-08 & 50-366/83-08 Corrective actions Procedure HNP-9 will be reviewed & revised to clarify requirements for revising procedures
GUCHA, L T Georgia Power Co 83/05/23 O'REILLY, J P Region 2, Office of Director 2pp 19056 018 24X Fiche 50-321,83/06/16,8306290298
- 8306290312 Forwards IE Insp Repts 50-321/83-08 & 50-366/83-08 on 830314-18 & 25 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/04/21 KELLY, R J Georgia Power Co 2pp 19056 020 24X Fiche 50-321,83/06/16,8306290298
- 8306290317 Notice of violation from insp on 830314-18 & 25
* Region 2, Office of Director 83/04/21 1p 19056 022 24X Fiche 50-321,83/06/16,8306290298
- 8306290332 IE Insp Repts 50-321/83-08 & 50-366/83-08 on 830314-18 & 25 Noncompliance noted failure to revise Procedure HNP-2-3801, Rev 17, per Procedure HNP-9 requirements
GIRARD, E H, ROSS, W J, BLAKE, J J Region 2, Office of Director, 83/04/20 13pp 19056 023 24X Fiche 50-321,83/06/16,8306290298
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 11pp 19021 179 24X Fiche 50-000,83/06/22,8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 12pp 18977 007 24X Fiche 50-000,83/06/22,8305110477
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 11pp 18996 242 24X Fiche 50-000,83/06/23,8305110479
- 8306300085 Responds to 830602 notice of violation & proposed imposition of civil penalties for violations noted in IE Insp Repts 50-321/83-09, 50-321/83-10, 50-366/83-09 & 50-366/83-10. Corrective actions Procedure HNP-6921 revised
BECKHAM, J T Georgia Power Co 83/06/23 Director's Office, Office of Inspection and Enforcement App 19048 254, 24X Fiche 50-321,83/06/23,8306300085
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 11pp 19046 297 24X Fiche 50-000,83/06/24,8305110483
- R Periodic operating reports & related correspondence
- 8306170382 Monthly operating rept for May 1983 W/830610 ltr.
REDMANZ, F J, NIX, H C. Georgia Power Co. 83/06/10 Director's Office, Office of Inspection and Enforcement 23pp 18980 255, 24X Fiche 50-321,83/06/10,8306170382
- G Reportable occurrences, LERs & related correspondence
- 8306070259 LER 83-028/03L-O on 830420, B plant svc water isolation valve 2F41-F316B failed to auto-close upon loss-of-sys-pressure signal initiation Cause under investigation
W/830601 ltr
TIPPS, B B, NIX, H. C. Georgia Power Co. 83/06/01 O'REILLY, J P Region 2, Office of Director App 18746 084, 24X Fiche 50-366,83/06/01,8306070259
- 8306130264 Updated LER B1-098/03X-1 on B11007,RHR svc water pumps B & D found incapable of establishing required flow.Caused by damaged Cavitrol V trim in HX discharge valve W/830602 ltr.
TIPPS, B B, NIX, H. C. Georgia Power Co. 83/06/02 O'REILLY, J P. Region 2, Office of Director 2pp 18824 191, 24X Fiche 50-366,83/06/02,8306130264
- 8306200004 LER 83-034/01T-O on 830525, select isotopes identified but omitted from process computer E BAR library when program originally initiated Caused by incorrect computer program. Library will be corrected.W/830606 ltr.
TIPPS, B B, NIX, H C Georgia Power Co. 83/06/06 O'REILLY, J. P. Region 2, Office of Director App. 18903 256 24X Fiche 50-366,83/06/06,8306200004
- 8306200205 LER 83-035/03L-O on 830511, standby gas treatment (SBOT) humidity controllers 2T46-N015B & 2T46-N017B out of calibr & SBOT train B inoperable. On 830525, SBOT train B carbon filter would not remove 99% test gas W/830606 ltr.
TIPPS, B B, NIX, H. C. Georgia Power Co. 83/06/06 O'REILLY, J. P. Region 2, Office of Director App. 18903:208, 24X Fiche 50-366,83/06/06,8306200205

DOCKETED ITEMS

8306270328 LER 83-031/01T-0 on 830530, while performing fuel movement operation Procedure (HNP-2-9302), 11 fuel assemblies discovered loaded out of proper core orientation. Caused by personnel error. Individual counseled W/830609 ltr TTPB, B. B. NIX, H. C. Georgia Power Co. 83/06/09. O'REILLY, J. P. Region 2, Office of Director App 18793-047 24X Fiche: 50-366, 83/06/09, 8306270328.

8306280468 LER 83-021/03L-0 on 830516, during reactor coolant instrumentation line excess flow check valve operability Procedure (HNP-2-3960), five valves failed. Caused by component failure. Valves freed or replaced W/830615 ltr TTPB, B. B. NIX, H. C. Georgia Power Co. 83/06/15. O'REILLY, J. P. Region 2, Office of Director App 19020 129 24X Fiche: 50-366, 83/06/15, 8306280468

V Operator Examinations

8306140486 Forwards summary of 830503 meeting re NRC policies on senior operator licensing exam Tech Spec memorization requirements. Written exam requirements specified in draft Examiner Std EB-402. List of attendees encl. DANCE, H. C. Division of Project & Resident Programs 83/05/24. BECKHAM, J. T. Georgia Power Co App. 18843.090 24X Fiche: 50-000, 83/05/24, 8306140486

--8306140493 Requests meeting to discuss NRC policies on senior operator licensing exam Tech Spec memorization requirements. Summary of Tech Spec sections covering required memorization encl. BECKHAM, J. T. Georgia Power Co 83/03/11. WILSON, B. Region 2, Office of Director App. 18843.094 24X Fiche: 50-000, 83/05/24, 8306140486.

DOCKET 50-367 BAILY GENERATING STATION

Q Adjudicatory correspondence

8306230368 Responds to 830609 ltr re status of Business & Prof People for Public Interest application for fees under Equal Access to Justice Act. Final Comptroller General opinion will not be issued for at least 1 month. FITZGERALD, J. A. Office of the General Counsel. 83/06/22. WHICHER, J. M. Businessman for the Public Interest App 18944 129 24X Fiche: 50-367, 83/06/22, 8306230368

--8306230370 Requests status of Business & Prof People for Public Interest 820604 application for fees under Equal Access to Justice Act. WHICHER, J. M. Businessman for the Public Interest 83/06/09. PLATNE, H. H. Office of the General Counsel. App. 18944-130 24X Fiche: 50-367, 83/06/22, 8306230368

DOCKET 50-368 ARKANSAS NUCLEAR ONE, UNIT 2

F. Security, medical, emergency & fire protection plans

8306070298 Submits supplemental response to IE Insp Repts 50-313/82-33 & 50-348/82-33. Completion date for revised procedures re fire barriers changed to 830531. Add'l time necessary to incorporate App R changes. MARSHALL, J. R. Arkansas Power & Light Co 83/04/12. SEIDLE, W. C. Region 4, Office of Director App 18740-313. 24X Fiche: 50-313, 83/04/12, 8306070298

8306010101 Forwards IE Insp Repts 50-313/83-03 & 50-348/83-05 on 830314-17. No noncompliance noted. Open items will be examined during future insp. SEIDLE, W. C. Region 4, Office of Director 83/05/12. GRIFFIN, J. M. Arkansas Power & Light Co App 18674.117. 24X Fiche: 50-313, 83/05/12, 8306010101

--8306010107 IE Insp Repts 50-313/83-05 & 50-348/83-05 on 830314-17. No noncompliance noted. Major areas inspected, licensee performance & capabilities during full-scale exercise of emergency plans & procedures. HACHNEY, C. A., MANN, J., BROWN, P. Region 1, Office of Director 83/05/09. 28pp. 18674.119. 24X Fiche: 50-313, 83/05/12, 8306010101.

8306030073 Forwards safety evaluation re safe shutdown capability in event of fire. Commitment requested for source range neutron flux monitoring capability & schedules for submittals by 830528. STOLZ, J. F. Operating Reactors Branch 4. CLARK, R. A. Operating Reactors Branch 3. 83/05/13. GRIFFIN, J. M. Arkansas Power & Light Co. App. 18733.249. 24X Fiche: 50-313, 83/05/13, 8306030073.

--8306030078 Safety evaluation re 10CFR50 App R. Items III, G, 3 & III L, re safe shutdown capability. Util design acceptable. Office of Nuclear Reactor Regulation, Director. 83/05/13. 13pp. 18733.251. 24X Fiche: 50-313, 83/05/13, 8306030073

8306090313 Documents recent telcon re 830315 Tech Spec change request to increase emergency plan & contingency plan audit frequency. Spec applies to both plans. MARSHALL, J. R. Arkansas Power & Light Co 83/05/17. COLLINS, J. T. Region 4, Office of Director App 18795.227 24X Fiche: 50-313, 83/05/17, 8306090313

8306090248 Provides status of transient brochure distribution program. Purchase order for holders issued & delivery expected by 830606. MARSHALL, J. R. Arkansas Power & Light Co 83/05/23. COLLINS, J. T. Region 4, Office of Director App 18795.318 24X Fiche: 50-313, 83/05/23, 8306090248

8306060063 Ack receipt of 830429 partial response to 820625 Emergency Plan Evaluation Repts 50-313/81-22 & 50-368/81-21. Response addressing all outstanding deficiencies by revised plan or schedule for plan rev requested. SEIDLE, W. C. Region 4, Office of Director 83/05/31. GRIFFIN, J. M. Arkansas Power & Light Co App 18723.271 24X Fiche: 50-313, 83/05/31, 8306060063

--8306060067 Responds to NRC 820625 evaluation of emergency plans Nuclear contingency plan & procedures & emergency plan being reviewed & revised. Response to deficiencies identified by revs encl. MARSHALL, J. R. Arkansas Power & Light Co 83/04/29. COLLINS, J. T. Region 4, Office of Director App 18723.273 24X Fiche: 50-313, 83/05/31, 8306060063

8306080012 Notifies of commitment to install source range monitoring capability on alternate shutdown sys. per 830513 ltr & 10CFR50 App R. MARSHALL, J. R. Arkansas Power & Light Co 83/06/03. STOLZ, J. F. Operating Reactors Branch 4. CLARK, R. A. Operating Reactors Branch 3 App 18773.249 24X Fiche: 50-313, 83/06/03, 8306080012

8306140155 Notifies that 1 h fire barriers installed by 830422, per 830327 request for scheduler exemption from App R requirements for installation of barriers to 830501. MARSHALL, J. R. Arkansas Power & Light Co 83/06/08. STOLZ, J. F. Operating Reactors Branch 4. CLARK, R. A. Operating Reactors Branch 3 App 18839.073 24X Fiche: 50-313, 83/06/08, 8306140155

8306230474 Submits add'l info re radiation filtration sys for emergency control ctr (ECC), per NUREG-0737, Suppl 1 on emergency response. Radiation filtration sys designed to be manually activated. Sketch of ECC filtration sys encl. MARSHALL, J. R. Arkansas Power & Light Co 83/06/17. STOLZ, J. F. Operating Reactors Branch 4 App 18941.307 24X Fiche: 50-313, 83/06/17, 8306230474

8306240469 Requests exemption from 10CFR50 48(c) for all barriers, penetrations & fire suppression/detection sys be made more specific & detailed by identifying each area requiring exemption. Schedule for submittal requested in 20 days. STOLZ, J. F. Operating Reactors Branch 4. CLARK, R. A. Operating Reactors Branch 3. 83/06/17. GRIFFIN, J. M. Arkansas Power & Light Co App 18998.085 24X Fiche: 50-313, 83/06/17, 8306240469

J Insurance & indemnity information

8306030294 Forwards certificate of insurance, Policy XBR-002 for CY83. MARSHALL, J. R. Arkansas Power & Light Co 83/04/22. DINI, T. J. Office of Resource Management, Director App 18703.327 24X Fiche: 50-313, 83/04/22, 8306030294

P Operating license stage documents & correspondence

8306010024 Forwards "Policy Statement re Alcohol/Drug Abuse & Theft," issued as part of util policies & procedures manual, per 830309 commitment. MARSHALL, J. R. Arkansas Power & Light Co 83/05/12. COLLINS, J. T. Region 4, Office of Director App 18674.070 24X Fiche: 50-313, 83/05/12, 8306010024

--8306010028 "Policy Statement re Alcohol/Drug Abuse & Theft" Arkansas Power & Light Co 83/05/03 App 18674.071 24X Fiche: 50-313, 83/05/12, 8306010024.

8306090313 Documents recent telcon re 830315 Tech Spec change request to increase emergency plan & contingency plan audit frequency. Spec applies to both plans. MARSHALL, J. R. Arkansas Power & Light Co 83/05/17. COLLINS, J. T. Region 4, Office of Director App 18795.227. 24X Fiche: 50-313, 83/05/17, 8306090313

DOCKETED ITEMS

237

8306020135 Comments on App B Tech Spec revs. per 830311 ltr issuing Amends 72 & 40 to Licenses DPR-52 & NPF-6, respectively. Util will routinely provide NRC w/changes to NPDES discharge permit.
MARSHALL, J R Arkansas Power & Light Co 83/05/20 STOLZ, J F
Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 2pp 18691 244 24X Fiche 50-313, 83/05/20, 8306020135

8306020466 Submits supplementary info re environ qualification of Category II b items, in response to NRC requests Rosemount transmitter satisfied all acceptance criteria.
MARSHALL, J R Arkansas Power & Light Co 83/05/26 CLARK, R A
Operating Reactors Branch 3 2pp 10673 199 24X
Fiche 50-368, 83/05/26, 8306020466

8306070054 Provides results of technical evaluation of need to upgrade core protection calculator local power density penalty factor software & proposed implementation schedule, per 830414 commitment.
MARSHALL, J R Arkansas Power & Light Co 83/05/31 CLARK, R A
Operating Reactors Branch 3 2pp 18740 083 24X
Fiche 50-368, 83/05/31, 8306070054

8306200059 Advises that NUREG-0737, Items II F 1 4, II F 1 5 & II F 1 6 requirements resolved per 801219, 820726 & 830408 submittals. Environ qualification of equipment will be reviewed separately. BER encl.
STOLZ, J F Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 83/06/06 GRIFFIN, J M Arkansas Power & Light Co 7pp 18908 302 24X Fiche 50-313, 83/06/06, 8306200059

8306200055 Requests that submittal of justification for conclusion that shoulder gap clearance of 16x16 fuel will not be safety concern for Cycle 4 operations. Preliminary results of Cycle 3 fuel insps also requested.
CLARK, R A Operating Reactors Branch 3 83/06/08 GRIFFIN, J M Arkansas Power & Light Co 3pp 18908 292 24X
Fiche 50-368, 83/06/08, 8306200055

8306170275 Responds to NRC 830509 request for submittal of license amend applications incorporating snubber surveillance program into App A Tech Specs Program outlined in 830228 ltr. Will be followed pending NRC review of ANSI OM-4 Std.
MARSHALL, J R Arkansas Power & Light Co 83/06/10 STOLZ, J F Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 2pp 18878 257 24X Fiche 50-313, 83/06/10, 8306170275

8306250229 Responds to 830411 ltr re steam generator reactor protection sys (RPS) bypass. Boron dilution alarm installed & will be operational following operator training. Need to bypass steam generator RPS low & high level inputs in Mode 5 negated.
MARSHALL, J R Arkansas Power & Light Co 83/06/17 CLARK, R A Operating Reactors Branch 3 2pp 18915 189 24X
Fiche 50-368, 83/06/17, 8306250229

8306230487 Forwards justifications for continued operation for environ qualification deficiencies in NRC Categories I B, II, A & IV, in response to NRC 830415 BER & associated technical evaluation re: Flooding issue adequately addressed.
MARSHALL, J R Arkansas Power & Light Co 83/06/20 CLARK, R A Operating Reactors Branch 3 11pp 18941 185 24X
Fiche 50-368, 83/06/20, 8306230487

4 Inspection reports, IE Bulletins & correspondence

8306080192 Forwards IE Insp Rept 50-313/82-36 & 50-368/82-37 on 821213-16 & notice of violation.
BEIDLE, W C Region 4, Office of Director 83/03/04 GRIFFIN, J M Arkansas Power & Light Co 2pp 18771 161 24X
Fiche 50-313, 83/03/04, 8306080192

--8306080197 Notice of violation from insp on 821213-16
* Region 4, Office of Director 83/03/04 2pp 18771 163 24X
Fiche 50-313, 83/03/04, 8306080197

--8306080238 IE Insp Rept 50-313/82-36 & 50-368/82-37 on 821213-16. Noncompliance noted. Update of Unit 1 FSAR showed radiation zones less than 100 m/h, when actual survey data indicated radiation levels exceeded 100 m/h.
CHANEY, H D , WILBORN, L , MURRAY, B Region 4, Office of Director 83/03/28 17pp 18771 165 24X Fiche 50-313, 83/03/04, 8306080192.

8306160537 Responds to 821025 IE Insp Repts 50-313/82-14 & 50-368/82-11, Item 8 re control room dose calculations. Item re NUREG-0737, Item II B 2, "Plant Shielding," closed.
MARSHALL, J R Arkansas Power & Light Co 83/03/24 COLLINS, J T Region 4, Office of Director 2pp 18863 115 24X
Fiche 50-313, 83/03/24, 8306160537

8306070298 Submits supplemental response to IE Insp Repts 50-313/82-33 & 50-368/82-33. Completion date for revised procedures re fire barriers changed to 830531. Addl time necessary to incorporate App R changes.
MARSHALL, J R Arkansas Power & Light Co 83/04/12 BEIDLE, W C Region 4, Office of Director 1p 18740 313 24X
Fiche 50-313, 83/04/12, 8306070298

8306010101 Forwards IE Insp Repts 50-313/83-05 & 50-368/83-05 on 830314-17. No noncompliance noted. Open items will be examined during future insp.
BEIDLE, W C Region 4, Office of Director 83/05/12 GRIFFIN, J M Arkansas Power & Light Co 2pp 18674 117 24X
Fiche 50-313, 83/05/12, 8306010101

--8306010107 IE Insp Repts 50-313/83-05 & 50-368/83-05 on 830314-17. No noncompliance noted. Major areas inspected: licensee performance & capabilities during full-scale exercise of emergency plans & procedures.
HACKNEY, C A , DANOART, R L , HOLLEY, W L Region 1, Office of Director 83/05/09 28pp 18674 119 24X Fiche 50-313, 83/05/12, 8306010101

8306140359 Forwards IE Insp Repts 50-313/83-09 & 50-368/83-09 on 830401-30. No noncompliance noted.
BEIDLE, W C Region 4, Office of Director 83/05/18 GRIFFIN, J M Arkansas Power & Light Co 2pp 18832 143 24X
Fiche 50-313, 83/05/18, 8306140359.

--8306140363 IE Insp Repts 50-313/83-09 & 50-368/83-09 on 830401-30. No noncompliance noted. Major areas inspected: operational safety verification, followup on reactor trip breaker failure & plant startup after refueling.
CALLAN, L J , CUMMINS, J E , JOHNSON, W D Region 4, Office of Director 83/05/16 6pp 18832 145 24X Fiche 50-313, 83/05/18, 8306140359

8306130222 Updates status of efforts & progress re drawing control. Progress made in program to update mylars transferred from corporate ofc. As of 830311, 2,714 drawings updated & released. Info responds to IE Bulletin 80-06.
MARSHALL, J R Arkansas Power & Light Co 83/05/23 BEIDLE, W C Region 4, Office of Director 3pp 18926 324 24X
Fiche 50-313, 83/05/23, 8306130222

8303110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device." Svc list encl.
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc. 12pp 18831 043 24X Fiche 50-000, 83/05/26, 8303110458.

8303110460 IE Info Notice 83-34, "Event Notification Info Worksheet." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 115pp 18732 083 24X Fiche 50-000, 83/05/26, 8303110460

8303110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8303110461

8306060063 Ack receipt of 830429 partial response to 820625 Emergency Plan Evaluation Repts 50-313/81-22 & 50-368/81-21. Response addressing all outstanding deficiencies by revised plan or schedule for plan rev requested.
BEIDLE, W C Region 4, Office of Director 83/05/31 GRIFFIN, J M Arkansas Power & Light Co 2pp 18723 271 24X
Fiche 50-313, 83/05/31, 8306060063.

--8306060067 Responds to NRC 820625 evaluation of emergency plans. Nuclear contingency plan & procedures & emergency plan being revised & revised. Response to deficiencies identified by revs encl.
MARSHALL, J R Arkansas Power & Light Co 83/04/29 COLLINS, J T Region 4, Office of Director 17pp 18723 273 24X
Fiche 50-313, 83/05/31, 8306060063.

8306070380 Ack receipt of 830517 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/83-06 & 50-368/83-06.
BEIDLE, W C Region 4, Office of Director 83/06/02 GRIFFIN, J M Arkansas Power & Light Co 2pp 18741 346 24X
Fiche 50-313, 83/06/02, 8306070380

--8306070384 Responds to NRC 830418 ltr re violations noted in IE Insp Repts 50-313/83-06 & 50-368/83-06. Corrective actions, procedures revised to define interface responsibilities & coordination required for radioactive shipments.
MARSHALL, J R Arkansas Power & Light Co 83/05/17 BEIDLE, W C Region 4, Office of Director 4pp 18741 348 24X
Fiche 50-313, 83/06/02, 8306070380

DOCKETED ITEMS

--8306210097 Summary Rpt of Radiological Aspects of Mod of McGuire Nuclear Station, Unit 1 Steam Generator " * Duke Power Co 83/06/15 19pp 18919 195 24X Fiche 50-369, 83/06/15, 8306210092

8306240205 Provides info re DB-416 undervoltage trip attachments to be utilized in NRC evaluation of Facility, per B Wright request RAHE, E P Westinghouse Electric Corp 83/06/17 DENTON, H Office of Nuclear Reactor Regulation, Director App 18980 246 24X Fiche 50-369, 83/06/17, 8306240205

8306280029 Forwards notice of consideration of issuance of amend to OLs & proposed no significant hazards consideration determination & opportunity for hearing re B21123 reactor coolant flow rate computation method submittal W/O encl ADENSAM, E O Licensing Branch A 83/06/21 TUCKER, H B Duke Power Co 1p 19042, 358 24X Fiche: 50-369, 83/06/21, 8306280029

8306300002 Forwards responses to questions raised in 830617 telcon re testing of Type DB-416 circuit breaker undervoltage & shunt trip attachments for reactor trip switchgear Test description supplementing 830603 submittal encl TUCKER, H B Duke Power Co 83/06/28 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E O Licensing Branch 4 16pp, 19120, 333 24X Fiche 50-369, 83/06/28, 8306300002

Q Inspection reports, IE Bulletins & correspondence

8306140530 Forwards IE Insp Rpts 50-369/83-17 & 50-370/83-24 on 830411-19 No noncompliance noted. DANCE, H C Division of Project & Resident Programs 83/05/17 TUCKER, H B Duke Power Co 2pp 18843 258 24X Fiche 50-369, 83/05/17, 8306140530

--8306140537 IE Insp Rpts 50-369/83-17 & 50-370/83-24 on 830411-19 No noncompliance noted Major areas inspected review of outstanding insp items, snubber inservice insp & testing & witnessing Unit 1 integrated leak rate test WHITENER, H L Region 2, Office of Director JAF, F Division of Engineering & Radiological Safety Programs 83/05/12 Upp 18843 260 24X Fiche 50-369, 83/05/17, 8306140530

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device." Svc list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 123pp, 18831, 043, 24X Fiche: 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp, 18732, 085 24X Fiche 50-000, 83/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs." Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732, 208 24X Fiche: 50-000, 83/05/31, 8305110461

8306290282 Forwards response to IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators." No check valves installed in cooling water sys at facilities TUCKER, H B Duke Power Co 83/06/07 O'REILLY, J P Region 2, Office of Director 2pp, 19056 036, 24X Fiche 50-369, 83/06/07, 8306290282

8306290517 Forwards IE Insp Rpts 50-369/83-20 & 50-370/83-27 on 830502-12 No noncompliance noted. DANCE, H C Division of Project & Resident Programs 83/06/08 TUCKER, H B Duke Power Co, 2pp, 19052, 186, 24X Fiche, 50-369, 83/06/08, 8306290517

--8306290519 IE Insp Rpts 50-369/83-20 & 50-370/83-27 on 830502-12 No noncompliance noted Major areas inspected: preoperational test results, surveillance testing, post-mod startup of Unit 1 & initial criticality of Unit 2 BURNETT, P T, THOMAS, M, JAF, F, Region 2, Office of Director, 83/06/07 7pp, 19052, 186, 24X Fiche 50-369, 83/06/08, 8306290517

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations." Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09, Consolidated Edison Co of New York, Inc, 119pp 18830, 280, 24X Fiche, 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Mechanically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13, Consolidated Edison Co of New York, Inc 118pp, 18920, 225 24X Fiche: 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting from Degraded Internal Connection Cables " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8306170151 Forwards IE Safeguards Insp Rpt 50-369/83-23 on 830524-26 No noncompliance noted DANCE, H C Division of Project & Resident Programs 83/06/14 TUCKER, H B Duke Power Co 2pp 18878 311 24X Fiche 50-369, 83/06/14, 8306170151

--8306170162 IE Safeguards Rpt 50-369/83-23 on 830524-26 No noncompliance noted Major areas inspected review of licensee investigation of apparent willful manipulation of non-vital equipment Details withheld (ref 10CFR73.21) TOBIN, W J Region 2, Office of Director MCGUIRE, D R Division of Emergency Preparedness & Materials Safety 83/06/14 1p 18878 313 24X Fiche 50-369, 83/06/14, 8306170151

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

R Periodic operating reports & related correspondence

8306170311 Monthly operating rpts for May 1983 W/830615 ltr REAVIS, J A, TUCKER, H B Duke Power Co 83/06/15 Director's Office, Office of Inspection and Enforcement 8pp 18877 105 24X Fiche 50-369, 83/06/15, 8306170311

S Reportable occurrences, LERs & related correspondence

8306010401 LER 83-020/01T-0 on 830503, soap bubble test of 47 secondary containment bypass leakage paths not performed during initial integrated leak rate test Caused by procedural deficiency Procedures revised W/830517 ltr NARDOLCI, P B, TUCKER, H B Duke Power Co 83/05/17 O'REILLY, J P Region 2, Office of Director App 18682 245 24X Fiche 50-369, 83/05/17, 8306010401

8306010256 LER 83-021/03L-0 on 830419, while in Mode 5, nuclear svc water sys valve IRN 69 actuator w/mechanical latch replaced by actuator requiring electrical antihammer circuit Caused by deficient procedure W/830519 ltr NARDOLCI, P B, TUCKER, H B Duke Power Co 83/05/19 O'REILLY, J P Region 2, Office of Director 2pp 18672 292 24X Fiche, 50-369, 83/05/19, 8306010256

8306010098 LER 83-023/01T-0 on 830506, discovered that RHR sys (NB) train A improperly declared operable on 830423 & subsequent change from Mode 5 to Mode 4 occurred on 830428 Caused by water hammer failures W/830520 ltr NARDOLCI, P B, TUCKER, H B Duke Power Co 83/05/20 O'REILLY, J P Region 2, Office of Director App 18674 111 24X Fiche, 50-369, 83/05/20, 8306010098

8306010123 LER 83-022/03L-0 on 830421, bellows leak test not performed on penetration M354 after initial integrated leak rate test Caused by procedural deficiency since penetration not listed in initial procedures W/830520 ltr NARDOLCI, P B, TUCKER, H B Duke Power Co 83/05/20 O'REILLY, J P Region 2, Office of Director, 2pp 18674 019 24X Fiche 50-369, 83/05/20, 8306010123

8306070143 LER 83-018/03L-0 on 83040, following identification of inoperable AHR sys (ND) hanger & snubbers, sys walkdown revealed addl hanger failure caused by ND sys water hammer Hangers repaired & procedures revised W/830520 ltr
NARDOCI, P B, TUCKER, H B Duke Power Co 83/05/20 O'REILLY, J P
Region 2, Office of Director 5pp 10/29 228 24X
Fiche 50-369, 83/05/20, 8306070143

8306090147 LER 83-024/03L-0 on 830426, Fire Door 1000H declared inoperable when damage, consisting of bent door, broken hinge, bent hinge, broken door lock & broken door closer discovered Cause unknown Fire watch established W/830526 ltr
NARDOCI, P B, TUCKER, H B Duke Power Co 83/05/26 O'REILLY, J P
Region 2, Office of Director 2pp 10/92 303 24X
Fiche 50-369, 83/05/26, 8306090147

8306130342 LER 83-025/03L-0 on 830508, while in Mode P, fire detection sys Zones 72 & 149 declared inoperable due to alarms remaining in alarm condition Fire watch patrol established Cause by control interface module failure W/830527 ltr
NARDOCI, P B, TUCKER, H B Duke Power Co 83/05/27 O'REILLY, J P
Region 2, Office of Director 2pp 10/92 280 24X
Fiche 50-369, 83/05/27, 8306130342

8306130448 LER 83-026/03L-0 on 830430, performance of RCU leakage calculation determined unidentified leakage greater than 1 gpm Caused by leakage past bonnet seal ring on valves INC-1B & INV-237 Valves sealed W/830527 ltr
NARDOCI, P B, TUCKER, H B Duke Power Co 83/05/27 O'REILLY, J P
Region 2, Office of Director 2pp 10/92 034 24X
Fiche 50-369, 83/05/27, 8306130448

8306200212 LER 83-027/03L-0 on 830503, discovery of water in outside air pressure filter train 2 led to control area ventilation sys train B inoperability Caused by water backflow through drain lines into filter package filter cleaned W/830603 ltr
NARDOCI, P B, TUCKER, H B Duke Power Co 83/06/03 O'REILLY, J P
Region 2, Office of Director 2pp 10/92 277 24X
Fiche 50-369, 83/06/03, 8306200212

8306200245 LER 83-028/01T-0 on 830525, impulse lines for two redundant steam generator ID level instruments came within 2 inches of each other at one point Caused by const/installation deficiency One line rerouted W/830608 ltr
NARDOCI, P B, TUCKER, H B Duke Power Co 83/06/08 O'REILLY, J P
Region 2, Office of Director 4pp 10/92 344 24X
Fiche 50-369, 83/06/08, 8306200245

8306200237 LER 83-029/03L-0 on 830510, & 15, boron concentration dropped below 1,900 ppm in cold leg injection accumulator Caused by leakage into accumulator from RCB through check valves IN170 & IN171 Valves repaired W/830607 ltr
NARDOCI, P B, TUCKER, H B Duke Power Co 83/06/07 O'REILLY, J P
Region 2, Office of Director 2pp 10/92 342 24X
Fiche 50-369, 83/06/07, 8306200237

8306270074 RO on 830527, containment pressure control sys monthly surveillance not performed at required interval & when performed, pressure found out of allowable limits Analysis incomplete Rpts will be submitted by 830624
TUCKER, H B Duke Power Co 83/06/07 O'REILLY, J P Region 2, Office of Director 1p 10/98 121 24X Fiche 50-369, 83/06/07, 8306270074

8306200264 LER 83-032/03L-0 on 830613, control area ventilation sys train A failed to meet pressurization criteria Caused by degradation of door seals & lack of trip interlocks Door seals taped & later replaced test rerun W/830610 ltr
NARDOCI, P B, TUCKER, H B Duke Power Co 83/06/10 O'REILLY, J P
Region 2, Office of Director 4pp 10/91 101 24X
Fiche 50-369, 83/06/10, 8306200264

8306270227 LER 83-031/03L-0 on 830512, reactor coolant pump taken out of svc following sporadic low oil level alarms from pump motor ID upper reservoir Level found slightly low. Cause not determined Oil added Pump restarted W/830610 ltr
NARDOCI, P B, TUCKER, H B Duke Power Co 83/06/10 O'REILLY, J P
Region 2, Office of Director 2pp 10/98 235 24X
Fiche 50-369, 83/06/10, 8306270227

8306280427 LER 83-033/03L-0 on 830513, investigation of trouble alarm on fire detection sys received in control room that would not clear led to fire detection zone EFA 150 being declared inoperable Caused by spurious alarm, W/830610 ltr
NARDOCI, P B, TUCKER, H B Duke Power Co 83/06/10 O'REILLY, J P
Region 2, Office of Director 2pp 10/98 348 24X
Fiche 50-369, 83/06/10, 8306280427

8306270124 RO 83-035, on 830515, Tech Spec 3.4.3 re pressurizer heaters each having capacity of at least 150 kW violated. Investigation continuing Next rpt will be submitted by 830628
TUCKER, H B Duke Power Co 83/06/14 O'REILLY, J P Region 2, Office of Director 1p 10/98 085 24X Fiche 50-369, 83/06/14, 8306270124

8306270301 LER 83-034/03L-0 on 830515, cold leg injection accumulator (CLA) "A" declared inoperable due to vol exceeding Tech Spec limits Caused by leakage through valve seats of valves IN1-55, IN1-56 & IN1-57 Valves replaced W/830614 ltr
NARDOCI, P B, TUCKER, H B Duke Power Co 83/06/17 O'REILLY, J P
Region 2, Office of Director 2pp 10/95 288 24X
Fiche 50-369, 83/06/14, 8306270301

8306300191 Forwards LERs 83-036/03L-0 & 83-022/03L-0
TUCKER, H B Duke Power Co 83/06/23 O'REILLY, J P Region 2, Office of Director 3pp 1919 250 24X Fiche 50-369, 83/06/23, 8306300191

--8306300198 LER 83-036/03L-0 on 830524 & 26, listed functional test procedures failed to satisfy monthly setpoint requirements Caused by failure to identify & incorporate changes into procedures Setpoints verified
NARDOCI, P B Duke Power Co 83/06/23 1p 1919 253 24X
Fiche 50-369, 83/06/23, 8306300191

--8306300204 LER 83-022/03L-0 on 830524 & 26, listed functional test procedures failed to satisfy monthly setpoint requirements Caused by failure to identify & incorporate changes into procedures Setpoints verified
NARDOCI, P B Duke Power Co 83/06/23 1p 1919 254 24X
Fiche 50-369, 83/06/23, 8306300191

V Operator Examinations

8306140346 Advises that based on results of oral exams administered to all personnel per 820825 request for waiver of exams, amended licenses will be forwarded for personnel w/appropriately submitted applications
DANCE, H C Division of Project & Resident Programs 83/02/10
TUCKER, H B Duke Power Co 1p 10832 175 24X
Fiche 50-369, 83/02/10, 8306140346

DOCKET 50-370 WILLIAM B MCQUIRE NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8306030259 Staff requirements memo re 830527 discussion/possible vote in Washington, DC on full power OL authorization, License amend to be modified re maint of circuit breakers, Meeting requested w/breaker mfg
CHILK, S J Office of the Secretary of the Commission 83/05/27
DRACKB, W J Office of the Executive Director for Operations 1p, 10734 071 24X Fiche 50-370, 83/05/27, 8306030259

E NRC Safety Evaluation Report (SER), supp & correspondence

8306020103 Proposes 830608 meeting in Bethesda, MD to discuss Suppl 1 to SER for McQuire & SER for standby shutdown facility for Ocone
STOLZ, J F Operating Reactors Branch 4 83/05/17 TUCKER, H B, Duke Power Co 1p 10701 279 24X Fiche 50-000, 83/05/17, 8306020103

8306020603 Forwards briefing package for forthcoming Commission meeting re full power operation Package includes briefing slides, SER Suppl 7, OL issued on 830303 & proposed amend.
DRACKB, W J Office of the Executive Director for Operations 83/05/24
PALLADINO, N, OILINKBY, V, AHEARNE, J Commissioners 147pp 10717 158 24X Fiche 50-370, 83/05/24, 8306020603

8306160665 SAFETY EVALUATION REPORT RELATED TO OPERATION OF MCQUIRE NUCLEAR STATION, UNITS 1 AND 2, Docket Nos 50-369 And 50-370 (Duke Power Company)
* Division of Licensing NUREG-0422 607 83/05/31, 100pp, 10876 164 24X Fiche 50-369, 83/05/31, 8306160665

8306230482 Forwards Suppl 7 to SER re application for OLs w/o encl.
NOVAK, T M Assistant Director for Licensing 83/06/16 TUCKER, H B, Duke Power Co 2pp 10702 042 24X Fiche 50-369, 83/06/16, 8306230482

F Security, medical, emergency & fire protection plans

8306070269 Forwards Class III & I fees for approval of use of public address sys for local fire alarms inside containment, per 830506 request
TUCKER, H B Duke Power Co 83/05/24 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAH, E O, Licensing Branch 4 1p 10740 350 24X Fiche 50-369, 83/05/24, 8306070269

8306070433 Responds to 830206 ltr re physical security plan Rev 14. Changes consistent w/provisions of 10CFR50.34(p) & acceptable
ADENSAH, E O Licensing Branch 4 83/06/03 TUCKER, H B, Duke Power Co 2pp, 10776 347 24X Fiche 50-369, 83/06/03, 8306070433

DOCKETED ITEMS

8306090328 Ack receipt of 830506 request for approval of plans for local fire alarms inside containment Remittance of Class III fee requested
DICKS, R. H. License Fee Management Branch 83/06/06 TUCKER, H. B.
Duke Power Co. 1p 18797 110 24X Fiche 50-369, 83/06/06,
8306090328

8306270189 Forwards Rev 4 to training & qualification plan Rev withheld (ref 100FR73 21)
TUCKER, H. B. Duke Power Co. 83/06/14 O'REILLY, J. P. Region 2,
Office of Director. 1p 18791 327 24X Fiche 50-369, 83/06/14,
8306270189

I. Financial information

8306200352 Forwards Annual Financial Rept 1982.
TUCKER, H. B. Duke Power Co. 83/06/15 DENTON, H. R. Office of
Nuclear Reactor Regulation, Director. ADENSAH, E. Q. Licensing Branch
4 2pp 18899 101 24X Fiche 50-000, 83/06/15, 8306200352

--8306200356 Annual Financial Rept 1982
* North Carolina Municipal Power Agencies 83/06/15 20pp.
18999 103 24X Fiche 50-000, 83/06/15, 8306200356

P. Operating license stage documents & correspondence

8306020598 Forwards draft BER, NUREG-0422, Suppl 7 & "Evaluation of McGuire Units 1 & 2 Undervoltage Trip Attachment Failures," interim technical evaluation rept & draft full power OL amend
NOVAK, T. H. Assistant Director for Licensing 83/05/24 TUCKER, H. B.
Duke Power Co. 44pp 18718 001 24X Fiche 50-369, 83/05/24,
8306020598

8306020603 Forwards briefing package for forthcoming Commission meeting re full power operation Package includes briefing slides, BER Suppl 7, OL issued on 830303 & proposed amend
DIRCKS, W. J. Office of the Executive Director for Operations
83/05/24 PALLADINO, N., OILINSKY, V., AHEARNE, J. Commissioners
147pp. 18717 158 24X Fiche 50-370, 83/05/24, 8306020603

8306030315 Forwards addl Class I fee for 830311 request for relief from ASME Code Section XI requirement re hydrostatic testing on feedwater sys to steam generators, in response to NRC 830311 request
TUCKER, H. B. Duke Power Co. 83/05/24 DENTON, H. R. Office of
Nuclear Reactor Regulation, Director. ADENSAH, E. Q. Licensing Branch
4 1p. 18708 327. 24X Fiche 50-369, 83/05/24, 8306030315

8306070428 Forwards Amend 2 to License NPF-17 & notice of issuance & availability Amend requires testing of reactor trip breakers & changes license conditions for environ equipment & hydrogen control measures.
ADENSAH, E. Q. Licensing Branch 4 83/05/27 TUCKER, H. B. Duke Power Co. 2pp 18776:338 24X Fiche 50-370, 83/05/27, 8306070428.

--8306070431 Amend 2 to License NPF-17, modifying environ equipment & hydrogen control measures & requiring testing of reactor trip breakers
EISENHUT, D. Q. Division of Licensing 83/05/27 4pp 18776:340
24X Fiche 50-370, 83/05/27, 8306070428.

--8306070434 Notice of issuance & availability of Amend 2 to License NPF-17
ADENSAH, E. Q. Licensing Branch 4 83/05/27 3pp 18776 344 24X
Fiche 50-370, 83/05/27, 8306070428.

8306070131 Forwards info supporting 821123 & 830427 applications for amend to Licenses NPF-9 & NPF-17, respectively. Significant hazards consideration analysis & info re penalty for undetected feedwater venturi fouling encl.
TUCKER, H. B. Duke Power Co. 83/06/02 DENTON, H. R. Office of
Nuclear Reactor Regulation, Director. ADENSAH, E. Q. Licensing Branch
4. 4pp. 18739 243 24X Fiche 50-369, 83/06/02, 8306070131.

--8306070134 Proposed Tech Specs re RCS flow rate & nuclear enthalpy ris hot channel factor measurement
* Duke Power Co. 83/06/02 7pp 18739 247 24X
Fiche 50-369, 83/06/02, 8306070131

8306070283 Forwards description of test program verifying reliability of undervoltage trip attachment on Westinghouse DB-416 breakers. Submittal satisfies License Condition 2 C(12)a. NRC timely review requested
TUCKER, H. B. Duke Power Co. 83/06/03 DENTON, H. R. Office of
Nuclear Reactor Regulation, Director. ADENSAH, E. Q. Licensing Branch
4. 3pp. 18741-214. 24X Fiche 50-369, 83/06/03, 8306070283.

8306140680 Forwards Suppl I to "Reactor Containment Bldg Integrated Leak Rate Test (ILRT)" Addendum to Section VI, Page 4 of ILRT test rept requested to close out Unit 2 ILRT outstanding items
TUCKER, H. B. Duke Power Co. 83/06/09 DENTON, H. R. Office of
Nuclear Reactor Regulation, Director. ADENSAH, E. Q. Licensing Branch
4 1p 18842 058 24X Fiche 50-370, 83/06/09, 8306140680

--8306140686 Suppl I to "Reactor Containment Bldg Integrated Leak Rate Test (ILRT)"
* Duke Power Co. 83/06/09 3pp 18842 059 24X
Fiche 50-370, 83/06/09, 8306140680

8306150177 Application for amend to Licenses NPF-9 & NPF-17, extending time limit for operation w/reactor coolant flow greater than 395,850 gpm & adding stricter limit for nuclear enthalpy rise hot channel factor during operation
WHITES, A. C. Duke Power Co. 83/06/09 DENTON, H. R. Office of Nuclear
Reactor Regulation, Director. ADENSAH, E. Q. Licensing Branch 4
3pp 18846 359 24X Fiche 50-369, 83/06/09, 8306150177

8306210406 Forwards notice of consideration of issuance of amend to Licenses NPF-9 & NPF-17 & proposed no significant hazards determination & opportunity for hearing re setpoint tolerance for upper head injection accumulators
ADENSAH, E. Q. Licensing Branch 4 83/06/09 TUCKER, H. B. Duke Power Co. 2pp 18937 073 24X Fiche 50-369, 83/06/09, 8306210406

--8306210427 Notice of consideration of issuance of amend to licenses NPF-9 & NPF-17 & proposed no significant hazards consideration determination & opportunity for hearing re setpoint tolerance for upper head injection accumulator
JABBOUK, K. N. Licensing Branch 4 83/06/09 7pp 18937 073 24X
Fiche 50-369, 83/06/09, 8306210406

8306160277 Forwards synopsis of issues & Franklin Research Ctr draft technical evaluation rept re NUREG-0612, "Control of Heavy Loads, Phase I" w/o encls
ADENSAH, E. Q. Licensing Branch 4 83/06/10 TUCKER, H. B. Duke Power Co. 2pp 18872 170 24X Fiche 50-369, 83/06/10, 8306160277

8306160725 Summary of 830324 meeting w/utis & Westinghouse in Bethesda, MD re design review panel review of new Westinghouse stress analysis on manifold fasteners for D2/D3 steam generator mod
HOPKINS, J. B. Licensing Branch 4 83/06/10 Licensing Branch 4
7pp 18874 277 24X Fiche 50-000, 83/06/10, 8306160725

8306290573 Summary of Design Review Panel 830321 meeting w/utis & Westinghouse in Bethesda, MD re D2/D3 steam generator mod & Westinghouse stress analysis of manifold fasteners
HOPKINS, J. B. Licensing Branch 4 83/06/10 Licensing Branch 4
7pp 19047 085 24X Fiche 50-000, 83/06/10, 8306290573

8306240205 Provides info re DB-416 undervoltage trip attachments to be utilized in NRC evaluation of facility, per B Wright request
RAHE, E. P. Westinghouse Electric Corp. 83/06/17 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 4pp 18980 246 24X
Fiche 50-369, 83/06/17, 8306240205

8306280029 Forwards notice of consideration of issuance of amend to OLs & proposed no significant hazards consideration determination & opportunity for hearing re 821123 reactor coolant flow rate computation method submittal w/o encl
ADENSAH, E. Q. Licensing Branch 4 83/06/21 TUCKER, H. B. Duke Power Co. 1p. 19042 358 24X Fiche 50-369, 83/06/21, 8306280029

8306300002 Forwards responses to questions raised in 830617 telcon re testing of Type DB-416 circuit breaker undervoltage & shunt trip attachments for reactor trip switchgear Test description supplementing 830603 submittal encl
TUCKER, H. B. Duke Power Co. 83/06/28 DENTON, H. R. Office of
Nuclear Reactor Regulation, Director. ADENSAH, E. Q. Licensing Branch
4 16pp 19120 333 24X Fiche 50-369, 83/06/28, 8306300002

Q. Inspection reports, IE Bulletins & correspondence

8306140530 Forwards IE Insp Repts 50-369/83-17 & 50-370/83-24 on 830411-19 No noncompliance noted
DANCE, H. C. Division of Project & Resident Programs 83/05/17
TUCKER, H. B. Duke Power Co. 2pp 18843 258 24X
Fiche 50-369, 83/05/17, 8306140530

--8306140537 IE Insp Repts 50-369/83-17 & 50-370/83-24 on 830411-19 No noncompliance noted Major areas inspected review of outstanding insp items, snubber inservice insp & testing & witnessing Unit 1 integrated leak rate test
WHITENER, H. L. Region 2, Office of Director. JAPE, F. Division of Engineering & Radiological Safety Programs 83/05/12. 6pp
18843 260 24X Fiche 50-369, 83/05/17, 8306140530

DOCKETED ITEMS

243

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post
830103) 83/05/26 Consolidated Edison Co of New York, Inc
125pp 18831 043 24X Fiche 50-000,83/05/26,8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche 50-000,83/05/26,8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at DWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000,83/05/31,8305110461

8306290282 Forwards response to IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators " No check valves installed in cooling water sys at facilities
TUCKER, H B Duke Power Co 83/06/07 O'REILLY, J P Region 2, Office of Director 2pp 17056 036 24X Fiche 90-769,83/06/07,8306290282

8306290517 Forwards IE Insp Repts 50-369/83-20 & 50-370/83-27 on 830502-12 No noncompliance noted
DANCE, C Division of Project & Resident Programs 83/06/08 TUCKER, H B Duke Power Co 3pp 19052 186 24X Fiche 50-369,83/06/08,8306290517

--8306290519 IE Insp Repts 50-369/83-20 & 50-370/83-27 on 830502-12 No noncompliance noted Major areas inspected preoperational test results, surveillance testing, post-mod startup of Unit 1 & initial criticality of Unit 2
BURNETT, P T, THOMAS, M, JAPE, F Region 2, Office of Director 83/06/07 7pp 17052 188 24X Fiche 50-369,83/06/08,8306290517

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fiche 50-000,83/06/09,8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225 24X Fiche 50-000,83/06/13,8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000,83/06/13,8306090010

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 119pp 19021 177 24X Fiche 50-000,83/06/22,8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000,83/06/22,8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000,83/06/23,8305110479

8305110483 IE Info Notice 83-43, "Improper Bettings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000,83/06/24,8305110483

R. Periodic operating reports & related correspondence

8306170311 Monthly operating repts for May 1983 W/830615 ltr
REAVIS, J A, TUCKER, H B Duke Power Co 83/06/15 Director's Office, Office of Inspection and Enforcement 6pp 18877 105 24X Fiche 50-369,83/06/15,8306170311

S Reportable occurrences, LERs & related correspondence

8306010015 LER 83-007/01T-0 on 830503, during Tech Spec review, soap bubble test of 47 secondary containment bypass leakage paths discovered not performed Caused by procedural deficiency
Temporary test procedure written W/830517 ltr
NARDOCCI, P B, TUCKER, H B Duke Power Co 83/05/17 O'REILLY, J P Region 2, Office of Director 4pp 18674 064 24X Fiche 50-370,83/05/17,8306010015

8306010104 LER 83-009/03L-0 on 830421, discovered that bellows leak test not performed on penetration fuel transfer canal tube after initial integrated leak rate test Caused by procedural deficiency Procedure changed W/830520 ltr
NARDOCCI, P B, TUCKER, H B Duke Power Co 83/05/20 O'REILLY, J P Region 2, Office of Director 2pp 18674 147 24X Fiche 50-370,83/05/20,8306010104

8306090015 LER 83-012/03L-0 on 830427, investigation determined that main steam safety relief valve 28V-20 lifted briefly while pressure below lift setpoint range Caused by setpoint drift
Setpoint adjusted W/830527 ltr
NARDOCCI, P B, TUCKER, H B Duke Power Co 83/05/27 O'REILLY, J P Region 2, Office of Director 2pp 18792 346 24X Fiche 50-370,83/05/27,8306090015

8306090040 LER 83-010/03L-0 on 830427, data gathering panels 7 & 23 would not respond to fire detection sys processor Caused by water in bottom of panel 23 & W1020A encl Water removed & boards in W1020A encl replaced W/830527 ltr
NARDOCCI, P B, TUCKER, H B Duke Power Co 83/05/27 O'REILLY, J P Region 2, Office of Director 2pp 18793 278 24X Fiche 50-370,83/05/27,8306090040

8306100216 LER 83-011/03L-0 on 830427, PORV block valve 2NC-31B declared inoperable due to steam leaking past shaft to containment atmosphere Caused by failure of packing gland eye bolts Valve closed & actuator deenergized W/830527 ltr
NARDOCCI, P B, TUCKER, H B Duke Power Co 83/05/27 Region 2, Office of Director 4pp 18805 349 24X Fiche 50-370,83/05/27,8306100216

8306130314 LER 83-013/03L-0 on 830430, fire detection Zones 87,88 & 100 declared inoperable due to constant invalid alarms Fire watches & containment temp monitoring established Caused by dirt accumulation in smoke detectors W/830527 ltr
NARDOCCI, P B, TUCKER, H B Duke Power Co 83/05/27 O'REILLY, J P Region 2, Office of Director 4pp 18822 233 24X Fiche 50-370,83/05/27,8306130314

8306100138 LER 83-014/03L-0 on 830501, refueling water storage tank boron concentration found low Caused by low reactor makeup blender effluent concentration Boric acid added & procedures revised W/830531 ltr
TUCKER, H B, NARDOCCI, P B Duke Power Co 83/05/31 O'REILLY, J P Region 2, Office of Director 2pp 18801 248 24X Fiche 50-370,83/05/31,8306100138

8306100164 LER 83-015/03L-0 on 830501, while in Mode 3, radiation monitors 2EMF-3B & 2EMF-39 declared inoperable when low flow alarm could not be cleared Vacuum switch found stuck Switch exercised & returned to normal svc
NARDOCCI, P B, TUCKER, H B Duke Power Co 83/05/31 O'REILLY, J P Region 2, Office of Director 2pp 18807 230 24X Fiche 50-370,83/05/31,8306100164

8306100185 LER 83-017/03L-0 on 830509, radiation monitor 2EMF-10 declared inoperable when monitor failed high Caused by RP23A power supply failing due to cabinet temp Power supply replaced W/830531 ltr
TUCKER, H B, NARDOCCI, P B Duke Power Co 83/05/31 O'REILLY, J P Region 2, Office of Director 2pp 18803 283 24X Fiche 50-370,83/05/31,8306100185

8306100243 LER 83-016/03L-0 on 830506, radiation monitor 2EMF-12 did not respond to check source Caused by water in detector canister & bad OM tube OM tube replaced & board & canister decontaminated W/830531 ltr
NARDOCCI, P B, TUCKER, H B Duke Power Co 83/05/31 O'REILLY, J P Region 2, Office of Director 2pp 18807 137 24X Fiche 50-370,83/05/31,8306100243

8306130312 Updated RO-370/83-07 re discrepancies in initial integrated leak rate test Soap bubble test of hot penetrations will be incorporated in periodic test procedure
TUCKER, H B Duke Power Co 83/06/03 O'REILLY, J P Region 2, Office of Director 1p 18823 329 24X Fiche 50-370,83/06/03,8306130312

DOCKETED ITEMS

8306200238 LER 83-008/03L-0 on 830418, upper & lower personnel airlocks declared inoperable when blown & ruptured inner seals, respectively, discovered on auxiliary bldg door. Caused by design deficiency W/830603 ltr
TUCKER, H. B., NARDOCI, P. B. Duke Power Co 83/06/03 O'REILLY, J. P
Region 2, Office of Director App 18902 351 24X
Fiche: 50-370, 83/06/03, 8306200238.

8306270094 RO on 830527, containment pressure control sys monthly surveillance not performed at required interval & when performed, pressure found out of allowable limits. Analysis incomplete. Repts will be submitted by 830624
TUCKER, H. B. Duke Power Co 83/06/09 O'REILLY, J. P Region 2,
Office of Director Ip 18988 121 24X Fiche 50-369, 83/06/09,
8306270094.

8306200321 RO 370/83-018 on 830513, radioactive liquid effluent monitoring instrumentation channels inoperable. Investigation incomplete. Next rept will be submitted by 830620
TUCKER, H. B. Duke Power Co. 83/06/10 O'REILLY, J. P Region 2,
Office of Director Ip 18999 011. 24X Fiche 50-370, 83/06/10,
8306200321.

8306300114 LER 83-020/03L-0 on 830519, shutdown rod bank A Group 1 & control rod banks A & C Group 1 failed to move on command. Caused by malfunction in input/output ac amplifier card AB05 due to transistor failure. Card replaced W/830617 ltr
NARDOCI, P. B., TUCKER, H. B. Duke Power Co 83/06/17 O'REILLY, J. P
Region 2, Office of Director App 19121 067 24X
Fiche: 50-370, 83/06/17, 8306300114

8306300171 RO 370/83-18 on 830513, radioactive liquid effluent monitoring instrumentation channels failed. Incident determined not reportable. No 30-day rept will be submitted
TUCKER, H. B. Duke Power Co. 83/06/20 O'REILLY, J. P. Region 2,
Office of Director Ip. 19119 271 24X Fiche 50-370, 83/06/20,
8306300171

8306300232 LER 83-021/03L-0 on 830521, while in Mode 2, control room steam generator D wide range level recorder indication incorrect. Caused by tube fitting leak on level transmitter high-pressure sensor line. Fitting replaced W/830620 ltr.
NARDOCI, P. B., TUCKER, H. B. Duke Power Co. 83/06/20 O'REILLY, J. P
Region 2, Office of Director App 19119 182 24X
Fiche 50-370, 83/06/20, 8306300232

8306300189 LER 83-023/03L-0 on 830524, upper head injection surge tank low pressure alarm received. Bull nitrogen not immediately available & pressure fell below limit. Caused by leakage of gas relief valve on nitrogen accumulator W/830623 ltr.
NARDOCI, P. B., TUCKER, H. B. Duke Power Co 83/06/23 O'REILLY, J. P.
Region 2, Office of Director App. 19122 193 24X
Fiche: 50-370, 83/06/23, 8306300189

8306300191 Forwards LERs 83-036/03L-0 & 83-022/03L-0
TUCKER, H. B. Duke Power Co. 83/06/23 O'REILLY, J. P Region 2,
Office of Director App. 19119:250 24X Fiche: 50-369, 83/06/23,
8306300191

--8306300204 LER 83-022/03L-0 on 830524 & 26, listed functional test procedures failed to satisfy monthly setpoint requirements. Caused by failure to identify & incorporate changes into procedures. Setpoints verified
NARDOCI, P. B. Duke Power Co. 83/06/23 Ip 19119:254 24X
Fiche: 50-369, 83/06/23, 8306300191

T. Hearing transcripts on non-antitrust matters

8306020700 Transcript of Commission 830527 discussion & possible vote in Washington, DC on full power DL Pp 1-83, Supporting documentation encl.
* Commissioners. 83/05/27 112pp. 10717-046. 24X
Fiche: 50-370, 83/05/27, 8306020700.

V. Operator Examinations

8306140346 Advises that based on results of oral exams administered to all personnel per 820825 request for waiver of exams, amended licenses will be forwarded for personnel w/appropriately submitted applications.
DANCE, H. C. Division of Project & Resident Programs 83/02/10,
TUCKER, H. B. Duke Power Co. Ip. 18832:175. 24X
Fiche: 50-369, 83/02/10, 8306140346.

DOCKET 50-373 LASALLE COUNTY STATION, UNIT 1

A Application/construction stage documents & correspondence

8306230005 Addl response to FOIA request for all drafts, insp evaluation repts & comments on J Keppler 820719 rept re special safety insp during May-Jul 1982 of activities at Unit 1 Forwards documents listed in App B Addl records under review
FELTON, J. M. Division of Rules and Records 83/03/25 GARDE, B
Government Accountability Project 3pp 18952 001 24X
Fiche 50-373, 83/03/25, 8306230005

--8306230028 Forwards trip rept of 820625-26 visit to Region 111 & site re containment bolt installation problem. Engineering discussion, recommendations & exam conclusion included
HOOD, A. C. SPS Technologies 82/06/20 JACKIN, I. N. NRC - No
Detailed Affiliation Given 16pp 18952 361 24X
Fiche 50-373, 83/03/25, 8306230005

--8306230031 Comments on agenda items for 820625 site meeting re technical aspects of torque wrench calibr Motor operator/ yoke connection tightness check, torque wrench calibr accuracy & expansion anchor installation discussed
RODABAUGH, E. C. E. C. Rodabaugh Associates, Inc 82/06/26
TERAD, D. Mechanical Engineering Branch App 18953 015 24X
Fiche 50-373, 83/03/25, 8306230005

--8306230037 Forwards QA Manual 18-1 2 audit rept Plant const satisfactory.
REED, C. Commonwealth Edison Co 82/07/08 KEPPLER, J. G. Region 3,
Office of Director Ip 18953 021 24X Fiche 50-373, 83/03/25,
8306230005

--8306230039 QA Manual 18-1 2 audit rept Related correspondence encl
HANSING, K. J. Commonwealth Edison Co 81/08/04 80pp 18953 022
24X Fiche 50-373, 83/03/25, 8306230005

--8306230051 Discusses changes in Section X of util rept resulting from consultant concerns re bolting issue. Rept revised to reflect verification of procedures & data
NORELUB, C. C. Division of Engineering 82/07/19 JOBLONGAI, F.,
KNICELEY, J., REIHANN, F. Region 3, Office of Director 3pp
18953 085 24X Fiche 50-373, 83/03/25, 8306230005

8306160031 Clarifies NRC final response to FOIA request for documents re Zack Co &/or work performed by Zack in const of facilities. App D Document 5 deleted since document identical to App A Document 435
FELTON, J. M. Division of Rules and Records 83/04/14
PRENDERGAST, R. Prendergast, R. J. Ip 18872 336 24X
Fiche 50-000, 83/04/14, 8306160031

F Security, medical, emergency & fire protection plans

8306070355 Forwards response to 830428 request for addl info re Question 10 74 on fire protection for safe shutdown. Addl detectors to be installed prior to startup following refueling outage for Unit 1
SCHROEDER, C. W. Commonwealth Edison Co 83/05/31 SCHWENGER, A.
Licensing Branch 2 App 18742 153 24X Fiche 50-373, 83/05/31,
8306070355

8306150632 Releases public version of revised emergency plan implementing procedure
FELTON, J. M. Division of Rules and Records 83/06/07 Document
Management Branch Ip 18868 020, 24X Fiche 50-373, 83/06/07,
8306150632

--8306150634 Public version of Rev 2 to Emergency Plan Implementing Procedure L2P-1330-32, "Post-Accident Sampling of QA Wide-Range Gas Monitor" Offsite procedure mod forms & revised index encl
* Commonwealth Edison Co 83/05/03 Office of Nuclear Reactor
Regulation, Director 18pp 18868 021 24X Fiche 50-373,
83/06/07, 8306150632

8306160391 Ack receipt of 830527 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-373/82-94 & 50-374/82-22
SPEERARD, R. L. Region 3, Office of Director 83/06/10 REED, C.
Commonwealth Edison Co. 3pp 18860 037 24X Fiche 50-373, 83/06/10,
8306160391.

--8306160435 Responds to NRC 830428 ltr re violations noted in 1E Insp Repts 50-373/82-94 & 50-374/82-22. Corrective actions, addl insp criteria utilized during reinsp of cable penetration firestops & during initial installation at Unit 2
FARRAR, D. L. Commonwealth Edison Co. 83/05/27 KEPPLER, J. G.
Region 3, Office of Director App 18860 040 24X
Fiche: 50-373, 83/06/10, 8306160391

DOCKETED ITEMS

245

8306210205 Submits program for resolution of License Condition 2 C (25)(d) re unlabeled fire doors Bullet resistant assembly Door 277 will be removed & replaced w/smaller assembly door mfg by Chicago Bullet Proof Co
SCHROEDER, C W Commonwealth Edison Co 83/06/15 SCHWENCER, A Licensing Branch 2 3pp 18919 019 24X Fiche 50-373, 83/06/15, 8306210205

8306300117 Advises that DOE will respond to requests for emergency radiological assistance from licensees, federal, state & local agencies, private organizations or individuals involved in incident involving source, byproduct or SNM
BAUER, R H Energy, Dept of 83/06/23 DIEDERICH, G J Commonwealth Edison Co 1p 19121 076 24X Fiche 50-373, 83/06/23, 8306300117

J. Insurance & indemnity information

8306020183 Forwards Certificate of Insurance N-83 to NELIA Policy 1 & Certificate of Insurance M-83 to MAELU Policy 1
OSTER, J Commonwealth Edison Co 83/05/24 BALTZMAN, J Assistant Director for State & Licensee Relations 13pp 18690 232 24X Fiche 50-373, 83/05/24, 8306020183

8306170283 Forwards Endorsements 25 & 10 to NELIA Policy NF-253 & MAELU Policy NF-104, respectively.
OSTER, J Commonwealth Edison Co 83/06/13 BALTZMAN, J Assistant Director for State & Licensee Relations 3pp 18777 017 24X Fiche 50-373, 83/06/13, 8306170283

P. Operating license stage documents & correspondence

8305190370 Forwards computer listing of "Environ Qualification Status Rept - IE Equipment (Harsh)" Unit 2 currently expected to begin fuel loading in Aug 1983
SCHROEDER, C W Commonwealth Edison Co 83/05/13 SCHWENCER, A Licensing Branch 2 2pp 18500 087 24X Fiche 50-373, 83/05/13, 8305190370

--8305190373 "Environ Qualification Status Rept - IE Equipment (Harsh)"
* Sargent & Lundy, Inc 83/05/05 98pp 18500 089 24X Fiche 50-373, 83/05/13, 8305190370

8306040146 Forwards alternate & complete solution to resolve NRC concerns re detection of inadequate core cooling in reactor water level ref leg cooling sys W/one oversize drawing
Aperture card is available in PDR
SCHROEDER, C W Commonwealth Edison Co 83/05/31, SCHWENCER, A Licensing Branch 2 9pp 18732 076 24X Fiche 50-373, 83/05/31, 8306040146

8306050238 Responds to A Bournia request for rept of status of util negotiations w/Secretary of DOE re Nuclear Waste Policy Act of 1982 Agreement will be reached & contract executed within required 830630 time frame
SCHROEDER, C W Commonwealth Edison Co 83/05/31 SCHWENCER, A Licensing Branch 2 1p 18728 360 24X Fiche 50-373, 83/05/31, 8306050238

8306090194 Discusses util interpretation of 10CFR50.49, "Environ Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants" Intent of rulemaking is to require upgrade program for replacement equipment not parts
FARRAR, D L Commonwealth Edison Co 83/06/03 DENTON, H R Office of Nuclear Reactor Regulation, Director, 3pp. 18796 090 24X Fiche 50-000, 83/06/03, 8306090194

8306100062 Submits clarification of multiple fuel lift values due to criteria differences used by OE Engineering & OE Generic Licensing Groups as result of continued refinements to generic model
SCHROEDER, C W Commonwealth Edison Co 83/06/03 SCHWENCER, H Licensing Branch 2 3pp 18802 235 24X Fiche 50-373, 83/06/03, 8306100062

8306150532 Forwards assessment of "Quick Look" rept in response to 830304 & 30 ltr re submittal of initial evaluation of safety relief valve in-plant test results Addl info requested.
SCHWENCER, A Licensing Branch 2 83/06/07 FARRAR, D L Commonwealth Edison Co 5pp 18867, 029 24X Fiche 50-373, 83/06/07, 8306150532

8306280077 Ack receipt of 830302 ltr, providing reasons for not paying Class II fee for review of 82118 & 1207 applications for exemption from primary containment inerting requirements Fee requested in 830128 ltr no longer required.
DIOGS, R M License Fee Management Branch 83/06/17 FARRAR, D L Commonwealth Edison Co 1p, 19042 347 24X Fiche 50-373, 83/06/17, 8306280077

8306240406 Notification of 830621 meeting w/util in Bethesda, MD to discuss & clarify responses re multiple control sys failures
BURNIA, A Licensing Branch 2 83/06/20 SCHWENCER, A Licensing Branch 2 3pp 18998 017 24X Fiche 50-373, 83/06/20, 8306240406.

8306280323 Forwards table listing results of fuel lift max gap per License Condition 2 C (12) Results calculated per NEDE-21175-3-P
SCHROEDER, C W Commonwealth Edison Co 83/06/20 SCHWENCER, A Licensing Branch 2 3pp 19001 213 24X Fiche 50-373, 83/06/20, 8306280323

8306280502 Forwards supplemental response to EQ&O, Phase I, Apr 1983 rept re NUREG-0612, "Control of Heavy Loads," reflecting areas of concern addressed during 830614 telcon
SWARTZ, E D Commonwealth Edison Co 83/06/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 26pp 19019 236 24X Fiche 50-373, 83/06/22, 8306280502

Q. Inspection reports, IE Bulletins & correspondence

8306230005 Addl response to FOIA request for all drafts, insp evaluation repts & comments on J Keppler 820719 rept re special safety insp during May-Jul 1982 of activities at Unit 1, Forwards documents listed in App D Addl records under review
FELTON, J M Division of Rules and Records 83/03/25 GARDE, B. Government Accountability Project 3pp 18952, 001 24X Fiche 50-373, 83/03/25, 8306230005

--8306230012 Insp Evaluation Rept 82-35 re allegations of drilling & const deficiencies at site Concerns resolved effectively by licensee & NRC Related draft info encl
* NRC - No Detailed Affiliation Given 83/03/25 265pp 18952 004 24X Fiche 50-373, 83/03/25, 8306230005

--8306230015 Evaluation Rept on Atty General of IL allegations re drilling & const deficiencies at site. Allegations w/o merit
* Structural Engineering Branch 83/03/25 4pp. 18952 249. 24X Fiche 50-373, 83/03/25, 8306230005

--8306230019 Summary of 820611 mgt meeting at site re ongoing investigation of Atty General of IL allegations concerning drilling & const problems.
DAVIS, A B Region 3, Office of Director 82/06/17 Region 3, Office of Director 3pp 18952, 280 24X Fiche 50-373, 83/03/25, 8306230005

--8306230022 Discusses readiness of facility to receive OL per request. Initial recommendation or issuance of OL withdrawn pending further quantification & clarification of const QC issues
Insp evaluation & related info encl
REIMANN, F W Region 3, Office of Director, 82/06/28, JACKIW, I N, WALKER, R D Region 3, Office of Director 74pp. 18952 283 24X Fiche 50-373, 83/03/25, 8306230005

--8306230043 Discusses 820630, 0707 & 08 telcons re investigations of allegations concerning facilities Allegations not properly investigated & could result in "whitewash".
CUMMINGS, J J Office of Inspector & Auditor 82/07/15 DIRCKS, W. Office of the Executive Director for Operations 2pp. 18953 083, 24X Fiche 50-373, 83/03/25, 8306230005

--8306230056 Discusses results of insp of allegations considered to have potential effect on facility operation No reason evident to limit power operation at facility
KEPPLER, J O Region 3, Office of Director, 82/07/19, DENTON, H R. Office of Nuclear Reactor Regulation, Director 1p 18953 088 24X Fiche 50-373, 83/03/25, 8306230005.

--8306230061 Discusses concurrence w/Section X of IE Insp Repts 50-373/82-35 & 50-374/82-06 re allegation that Morrison Co torque wrench calibr records falsified Audit not sufficiently comprehensive to draw meaningful conclusions.
REIMANN, F W Region 3, Office of Director, 82/07/21, Region 3, Office of Director 1p 18953 089 24X Fiche 50-373, 83/03/25, 8306230005

--8306230065 Summarizes 820811 meeting w/N Jackiw, R Lipinski & representatives of public interest groups re affidavits submitted by bricklayers subsequent to completion of initial special insp of facility Insp evaluation repts encl
NORELIUS, C E Region 3, Office of Director 82/08/18 Region 3, Office of Director 15pp. 18953 090. 24X Fiche 50-373, 83/03/25, 8306230005.

8306100252 Forwards IE Insp Rept 50-373/83-18 on 830425-28 & notice of violation
PAPERIELLO, C J Region 3, Office of Director 83/05/20 REED, C. Commonwealth Edison Co 2pp. 18807, 042 24X Fiche 50-373, 83/03/20, 8306100252

DOCKETED ITEMS

--8306100255 Notice violation from insp on 830425-28
PAPERIELLO, C J Region 3, Office of Director 83/05/19 1p
18807 044 24X Fiche 50-373, 83/05/20, 8306100252

--8306100258 IE Insp Rept 50-373/83-18 on 830425-28 Noncompliance
noted failure to follow applicable procedure when completing
radiation work permit requirements
MILLER, D E, OREGON, L R Region 3, Office of Director. 83/05/19
7pp 18807 045 24X Fiche: 50-373, 83/05/20, 8306100252

8306100172 Forwards IE Insp Repts 50-373/83-16 & 50-374/83-14 on
830411-0506 & notice of violation
STREETER, J F Region 3, Office of Director 83/05/24 REED, C
Commonwealth Edison Co 2pp. 18805 265 24X Fiche 50-373, 83/05/24,
8306100172

--8306100174 Notice of violation from insp on 830411-0506
STREETER, J F Region 3, Office of Director 83/05/24 2pp
18805 267 24X Fiche 50-373, 83/05/24, 8306100172

--8306100175 IE Insp Repts 50-373/83-16 & 50-374/83-14 on 830411-0506
Noncompliance noted failure to have adequate cable
separation & failure to have adequate housekeeping practices
in cable tray areas.
LANKSBURY, R D, DUPONT, B O, REYES, L A Region 3, Office of
Director 83/05/24 5pp. 18805 269 24X Fiche: 50-373, 83/05/24,
8306100172

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in
Well Logging Device " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post
830103) 83/05/26 Consolidated Edison Co of New York, Inc
125pp. 18831 043. 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New
York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460.

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods
Withdrawn at BWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/31 Consolidated Edison Co. of New
York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306100245 Ack receipt of 830526 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-373/83-11 &
50-374/83-06
STREETER, J F Region 3, Office of Director 83/06/06 REED, C
Commonwealth Edison Co 1p 18807:061 24X Fiche: 50-373, 83/06/06,
8306100245.

--8306100250 Responds to NRC 830428 ltr re violations noted in IE Insp
Repts 50-373/83-11 & 50-374/83-06 Corrective actions test
engineers restructured re test procedures
FARRAR, D L Commonwealth Edison Co 83/05/26 KEPLER, J Q
Region 3, Office of Director 3pp. 18807 062 24X
Fiche: 50-373, 83/06/06, 8306100245.

8306100094 Forwards response to IE Bulletin 83-03 re diesel generator
cooling water check valves. Plants utilize Mission Duo-Check
valves employing hinge-to-pin design for protection against
vibration-induced failure
BARNES, P L Commonwealth Edison Co 83/06/07. KEPLER, J Q Region
3, Office of Director 7pp 18802 233 24X Fiche: 50-000, 83/06/07,
8306100094.

8306170380 Forwards response to IE Bulletin 83-03 re diesel generator
cooling water check valves. Valves at Dresden & LaSalle
acceptable w/o further insp Rept on valve failures at Quad
Cities will be submitted within 90 days of insp completion.
BARNES, P L Commonwealth Edison Co 83/06/07 KEPLER, J Q Region
3, Office of Director 7pp. 18880 211. 24X Fiche 50-000, 83/06/07,
8306170380

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe
Operations." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/09 Consolidated Edison Co. of New
York, Inc. 119pp 18830 280. 24X Fiche: 50-000, 83/06/09, 8305110464.

to notice of violation from IE Insp Rept
1 830425-28. Corrective actions all
permits will be reviewed for

1 Edison Co. 83/06/10. KEPLER, J Q Region
2pp. 18861:302 24X Fiche: 50-373, 83/06/10,

8306160391 Ack receipt of 830527 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-373/82-54 &
50-374/82-22
SPESSARD, R L Region 3, Office of Director 83/06/10 REED, C
Commonwealth Edison Co 3pp 18860 637 24X Fiche 50-373, 83/06/10,
8306160391

--8306160435 Responds to NRC 830428 ltr re violations noted in IE Insp
Repts 50-373/82-54 & 50-374/82-22 Corrective actions addl
insp criteria utilized during reinsp of cable penetration
firestops & during initial installation at Unit 2
FARRAR, D L Commonwealth Edison Co 83/05/27 KEPLER, J Q
Region 3, Office of Director 8pp 18860 040 24X
Fiche 50-373, 83/06/10, 8306160391

8306300129 Forwards IE Insp Repts 50-373/83-12 & 50-374/83-10 on
830311-0410 & notice of violation
SHAFFER, W D Region 3, Office of Director 83/06/11 REED, C
Commonwealth Edison Co 2pp 19122 333 24X Fiche 50-373, 83/06/11,
8306300129

--8306300135 Notice of violation from insp on 830311-0410
SHAFFER, W D Region 3, Office of Director 83/06/11 1p
19122 335 24X Fiche 50-373, 83/06/11, 8306300129

--8306300141 IE Insp Rept 50-373/83-12 & 50-374/83-10 on 830311-0410
Noncompliance noted HPCS automatically initiated & no
unusual event declared, following reactor scram on 830322
GULDEMOND, W, MADISON, A, WALKER, R D Region 3, Office of
Director 83/06/08 11pp 19122 336 24X Fiche 50-373, 83/06/11,
8306300129

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive &
Seismically Induced Chatter in Relays Within Printed
Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New
York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From
Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New
York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New
York, Inc 115pp 19021 177 24X Fiche 50-000, 83/06/22, 8305110475.

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys
Causing Inoperability of Safety-Related Equipment " Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New
York, Inc. 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions "
Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co of New
York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8306270215 Forwards IE Insp Repts 50-373/83-17 & 50-374/83-16 on
830411-0517 & notice of violation
SHAFFER, W D Region 3, Office of Director 83/06/23 REED, C
Commonwealth Edison Co. 2pp 18988 282 24X Fiche 50-373, 83/06/23,
8306270215

--8306270220 Notice of violation from insp on 830411-0517
SHAFFER, W D Region 3, Office of Director 83/06/23 1p
18988 284 24X Fiche 50-373, 83/06/23, 8306270215

--8306270222 IE Insp Rept 50-373/83-17 & 50-374/83-16 on 830411-0517
Noncompliance noted inadequate procedure re traversing
in-core probe eyes
MADISON, A, GULDEMOND, W, WALKER, R D Region 3, Office of
Director 83/06/22 8pp 18988 285 24X Fiche: 50-373, 83/06/23,
8306270215

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate
Range (IR) High Flux Trip Setpoints " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co. of New
York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

8306300068 Ack receipt of 830610 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-373/83-18
PAPERIELLO, C J Region 3, Office of Director 83/06/27 REED, C
Commonwealth Edison Co 1p 19120 266. 24X Fiche 50-373, 83/06/27,
8306300068.

--8306300073 Responds to NRC 830520 ltr re violations noted in IE Insp Rept 50-373/83-18 Corrective actions radiation protection foremen instructed to review each radiation work permit for completeness prior to signing by shift engineer
FARRAR, D L Commonwealth Edison Co 83/06/10 KEPLER, J Q
Region 3, Office of Director 2pp 19120 247 24X
Fiche 50-373, 83/06/27, 8306300068

S Reportable occurrences, LERs & related correspondence

8306060206 LER 83-043/03L-0 on 830427, while performing charger capacity test, Div 1 charger SCR output fuse F-1 blew & charger feed breaker tripped shutting down charger. Caused by problem w/ battery capacity tester Fuse replaced W/830526 ltr
HIETAI, A J J, DIEDERICH, Q J Commonwealth Edison Co 83/05/26
KEPLER, J Q Region 3, Office of Director 3pp 18732 346 24X
Fiche 50-373, 83/05/26, 8306060206

8306210308 Special rept correcting 830517 rept re ECIS actuation & injection of water into RCS On 830522, HPCS & RCIC sys auto initiated due to low water level. Caused by setpoints more conservative than Tech Spec
DIEDERICH, Q J Commonwealth Edison Co 83/05/26 KEPLER, J Q
Region 3, Office of Director 1p 18914 004 24X
Fiche 50-373, 83/05/26, 8306210308

8306130349 LER 83-044/03L-0 on 830505, reactor water pH dropped below Tech Spec while in cold shutdown. Suppression pool & ICVOIT contaminated w/organics. Caused by processing Freon & organic solvents through radwaste into ICVOIT W/830531 ltr
SHEARER, L N, DIEDERICH, Q J Commonwealth Edison Co 83/05/31
KEPLER, J Q Region 3, Office of Director 3pp 18822 337 24X
Fiche 50-373, 83/05/31, 8306130349

8306130352 LER 83-045/03L-0 on 830504, during reactor vessel high water level HPCS injection valve closure calibr & functional test, level indicating switch 1B21-N100A found out of tolerance. Caused by instrument drift W/830601 ltr
MASTERSON, V V, DIEDERICH, Q J Commonwealth Edison Co 83/06/01
KEPLER, J Q Region 3, Office of Director 3pp 18822 307 24X
Fiche 50-373, 83/06/01, 8306130352

8306210277 LER 83-046/03L-0 on 830508, surveillance frequency for offsite to onsite breaker alignment, onsite breaker alignment & low pressure carbon dioxide sys exceeded spec. Caused by shift supervisor error W/830602 ltr
CAMPBELL, L D, DIEDERICH, Q J Commonwealth Edison Co 83/06/02
KEPLER, J Q Region 3, Office of Director 4pp 18914 241 24X
Fiche 50-373, 83/06/02, 8306210277

8306210045 LER 83-048/03L-0 on 830510, during visual insps, mechanical snubber NB13-1006B found locked between hot & cold settings. Possibly caused by excessive snubber travel or defective snubber. Snubber replaced W/830606 ltr
SPENCER, D A, DIEDERICH, Q J Commonwealth Edison Co 83/06/06
KEPLER, J Q Region 3, Office of Director 3pp 18910 360 24X
Fiche 50-373, 83/06/06, 8306210045

8306210089 Updated LER 83-033/03X-1 on 830402, radwaste effluent monitor declared inoperable. Caused by high fixed level of background radiation. Inner chamber surface experimentally coated w/ acrylic resin W/830606 ltr
ARAND, J, DIEDERICH, Q J Commonwealth Edison Co 83/06/06
KEPLER, J Q Region 3, Office of Director 3pp 18919 191 24X
Fiche 50-373, 83/06/06, 8306210089

8306210263 LER 83-047/03L-0 on 830507, liquid radwaste effluent process radiation monitor declared inoperable. Caused by alarm trip point exceeding Tech Spec limit. Monitor decontaminated & investigation of geometry change continuing W/830606 ltr
ARAND, J J, DIEDERICH, Q J Commonwealth Edison Co 83/06/06
KEPLER, J Q Region 3, Office of Director 3pp 18915 047 24X
Fiche 50-373, 83/06/06, 8306210263

8306270302 LER 83-049/03L-0 on 830520, during evaluation of turbine bypass valve sys response time requirements, data from LIS-EH-03 improperly evaluated. Caused by incorrect wiring of control circuitry for valves 2 & 5 W/830608 ltr
KALHON, K, DIEDERICH, Q J Commonwealth Edison Co 83/06/08
KEPLER, J Q Region 3, Office of Director 3pp 18995 205 24X
Fiche 50-373, 83/06/08, 8306270302

8306220019 LER 83-050/03L-0 on 830518, administrative/clerical errors found in Table 3 7 9-2. Caused by personnel inability to transpose design info into Tech Spec table. Discrepancies corrected. W/830609 ltr
SPENCER, D, DIEDERICH, Q J Commonwealth Edison Co 83/06/09
KEPLER, J Q Region 3, Office of Director 3pp 18980 212 24X
Fiche 50-373, 83/06/09, 8306220019

8306160169 PNO-III-83-043 on 830610, while removing filter from reactor water cleanup sample panel, radiation protection technician received eye contamination from dry matl adhering to filter. Eye flushing reduced contamination to 30,000 dpm
HUETER, L, MILLER, J Region 3, Office of Director 83/06/10, 1p
18861 272 24X Fiche 50-373, 83/06/10, 8306160169

8306210192 LER 83-051/03L-0 on 830513, VC chlorine detector B tripped & would not reset. Caused by loose ground wire on circuit board. Wire tightened W/830613 ltr
ARAND, J J, DIEDERICH, Q J Commonwealth Edison Co 83/06/13
KEPLER, J Q Region 3, Office of Director 3pp 18914 116 24X
Fiche 50-373, 83/06/13, 8306210192

8306220044 LER 83-051/03L-0 on 830516, reactor protection sys trip channel H2 limit switch failed to operate properly. Cause unknown. Limit switch readjusted W/830614 ltr
HOUSTON, R W, DIEDERICH, Q J Commonwealth Edison Co 83/06/14
KEPLER, J Q Region 3, Office of Director 3pp 18928 182 24X
Fiche 50-373, 83/06/14, 8306220044

8306270002 LER 83-054/03L-0 on 830520, drywell air & suppression chamber air/water temp functional test discovered not performed since 820427. Caused by personnel failure to incorporate test in computerized surveillance program W/830616 ltr
TRAINOR, A F, DIEDERICH, Q J Commonwealth Edison Co 83/06/16
KEPLER, J Q Region 3, Office of Director 3pp 18908 107 24X
Fiche 50-373, 83/06/16, 8306270002

8306270282 Potential Part 21 rept re discrepancy in welding of turnbuckle assembly, turnbuckle-bolt interface & on top plate assembly variable springs 8A307 Grade B bolts not ABMC Section IX matl. Investigation underway
KARAOIANIS, J A Elcen Metal Products Co 83/06/17 KEPLER, J Q
Region 3, Office of Director 2pp 18996 207 24X
Fiche 50-000, 83/06/17, 8306270282

8306300026 PNO-III-83-053, on 830621, one of two manual isolation valves for vacuum breakers D found closed, rendering vacuum breaker inoperable. Cause being reviewed. Appropriate enforcement action to be initiated
JORGENSEN, B L, SHAFFER, W D Region 3, Office of Director 83/06/24, 2pp 19120 313 24X Fiche 50-373, 83/06/24, 8306300026

DOCKET 50-374 LABALLE COUNTY STATION, UNIT 2

A Application/construction stage documents & correspondence

8306230005 Addl response to FOIA request for all drafts, insp evaluation repts & comments on J Kepler 820719 rept re special safety insp during May-Jul 1982 of activities at Unit 1. Forwards documents listed in App B Addl records under review
FELTON, J H Division of Rules and Records 83/03/25, GARDE, D, Government Accountability Project 3pp 18952 001 24X
Fiche 50-373, 83/03/25, 8306230005

--8306230028 Forwards trip rept of 820425-26 visit to Region III & site re containment bolt installation problem. Engineering discussion, recommendations & exam conclusion included
HOOD, A C SP8 Technologies, 82/06/20 JACKIN, I M, NRC - No Detailed Affiliation Given 16pp 18952 361 24X
Fiche 50-373, 83/03/25, 8306230028

--8306230031 Comments on agenda items for 820625 site meeting re technical aspects of torque wrench calibr. Motor operator/yoke connection tightness check, torque wrench calibr accuracy & expansion anchor installation discussed.
RODABAUGH, E C E C Rodabaugh Associates, Inc. 82/06/26, TERAO, D Mechanical Engineering Branch 3pp 18953 015 24X
Fiche 50-373, 83/03/25, 8306230031

--8306230037 Forwards QA Manual 1B-1.2 audit rept. Plant const satisfactory
REED, C Commonwealth Edison Co 82/07/08 KEPLER, J Q Region 3, Office of Director 1p 18953 021 24X Fiche 50-373, 83/03/25, 8306230037

--8306230039 QA Manual 1B-1.2 audit rept. Related correspondence encl.
HANBING, K J Commonwealth Edison Co 81/08/04, 40pp, 18953 022, 24X Fiche 50-373, 83/03/25, 8306230039

--8306230051 Discusses changes in Section X of util rept resulting from consultant concerns re bolting issues. Rept revised to reflect verification of procedures & data
NOBLE, C E Division of Engineering 82/07/19 JOBLONSKI, F., KNICELEY, J, REIMANN, F Region 3, Office of Director 3pp 18953 085, 24X Fiche 50-373, 83/03/25, 8306230051

DOCKETED ITEMS

8306160031 Clarifies NRC final response to FOIA request for documents re Zack Co &/or work performed by Zack in const of facilities App D Document 5 deleted since document identical to App A Document 135
FELTON, J M Division of Rules and Records 83/04/14
PRENDERGAST, R Prendergast, R J 1p 18872 356 24X
Fiche 50-000, 83/04/14, 8306160031

8305190370 Forwards computer listing of "Environ Qualification Status Rept - IE Equipment (Harsh) " Unit 2 currently expected to begin fuel loading in Aug 1983
SCHROEDER, C W Commonwealth Edison Co 83/05/13 SCHWENCER, A
Licensing Branch 2 2pp 18500 087 24X Fiche 50-373, 83/05/13, 8305190370

--8305190373 "Environ Qualification Status Rept - IE Equipment (Harsh) "
* Bargent & Lundy, Inc 83/05/05, 9pp 18900 087 24X
Fiche 50-373, 83/05/13, 8305190370

8306060146 Forwards alternate & complete solution to resolve NRC concerns re detection of inadequate core cooling in reactor water level ref leg cooling sys W/one oversize drawing
Aperture card is available in PDR
SCHROEDER, C W Commonwealth Edison Co 83/05/31 SCHWENCER, A
Licensing Branch 2 7pp 10732, 076, 24X Fiche 50-373, 83/05/31, 8306060146

8306060238 Responds to A Bournie request for rept of status of util negotiations w/Secretary of DOE re Nuclear Waste Policy Act of 1982 Agreement will be reached & contract executed within required 830630 time frame.
SCHROEDER, C W Commonwealth Edison Co 83/05/31 SCHWENCER, A
Licensing Branch 2 1p 18728 360 24X Fiche 50-373, 83/05/31, 8306060238

8306070334 Confirms 830531 telcon correcting gap calculations of fuel lift results contained in Generic Rept NEDE-21175-3-P
SCHROEDER, C W Commonwealth Edison Co 83/06/01 SCHWENCER, A
Licensing Branch 2, 2pp, 18746 063 24X Fiche 50-374, 83/06/01, 8306070334

8306090194 Discusses util interpretation of 10CFR50.49, "Environ Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants " Intent of rulemaking is to require upgrade program for replacement equipment not parts
FARRAR, D L Commonwealth Edison Co 83/06/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 18776 090 24X
Fiche 50-000, 83/06/03, 8306090194

8306280323 Forwards table listing results of fuel lift max gap per License Condition 2.C (12) Results calculated per NEDE-21175-3-P
SCHROEDER, C W Commonwealth Edison Co 83/06/20 SCHWENCER, A
Licensing Branch 2 3pp 19001 213 24X Fiche 50-373, 83/06/20, 8306280323

8306240252 Revises estimated fuel load dates to Oct 1983 for LaSalle County & Dec 1983 & May 1985 for Byron Units 1 & 2, respectively
STIEDE, W L Commonwealth Edison Co 83/06/21 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18781 323 24X
Fiche 50-000, 83/06/21, 8306240252

8306300032 Revises estimated fuel load dates, based on const activity & preoperational testing budget review Fuel load scheduled for 831001, Dec 1983 & May 1985 for LaSalle County Unit 2 & Byron Units 1 & 2, respectively
STIEDE, W L Commonwealth Edison Co 83/06/21 KEPLER, J O Region 3, Office of Director, 1p, 19120, 311, 24X Fiche 50-000, 83/06/21, 8306300032

8306280502 Forwards supplemental response to EG&O, Phase I, Apr 1983 rept re NUREG-0612, "Control of Heavy Loads," reflecting areas of concern addressed during 830614 telcon.
SHWARTZ, E D Commonwealth Edison Co 83/06/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 26pp 19019 236 24X
Fiche 50-373, 83/06/22, 8306280502

F Security, medical, emergency & fire protection plans

8306070355 Forwards response to 830428 request for addl info re Question O10.74 on fire protection for safe shutdown. Addl detectors to be installed prior to startup following refueling outage for Unit 1.
SCHROEDER, C W Commonwealth Edison Co, 83/05/31, SCHWENCER, A
Licensing Branch 2, 6pp, 18742, 153, 24X Fiche 50-373, 83/05/31, 8306070355

8306150632 Releases public version of revised emergency plan implementing procedure.
FELTON, J M Division of Rules and Records, 83/06/07, Document Management Branch, 1p, 18868 020, 24X Fiche 50-373, 83/06/07, 8306150632

--8306150636 Public version of Rev 2 to Emergency Plan Implementing Procedure L2P-1330-02, "Post-Accident Sampling of QA Wide-Range Gas Monitor " Offsite procedure mod forms & revised index encl
* Commonwealth Edison Co 83/05/03 Office of Nuclear Reactor Regulation, Director 18pp 18868 021 24X Fiche 50-373, 83/06/07, 8306150632

8306160391 Ack receipt of 830527 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/82-54 & 50-374/82-22
RPESSARD, R L Region 3, Office of Director 83/06/10 REED, C
Commonwealth Edison Co 3pp 18860 037 24X Fiche 50-373, 83/06/10, 8306160391

--8306160439 Responds to NRC 830428 ltr re violations noted in IE Insp Repts 50-373/82-54 & 50-374/82-22 Corrective actions addl insp criteria utilized during reinsp of cable penetration firestops & during initial installation at Unit 2
FARRAR, D L Commonwealth Edison Co 83/05/27 KEPLER, J O Region 3, Office of Director 6pp 18860 040 24X
Fiche 50-373, 83/06/10, 8306160391

8306210205 Submits program for resolution of License Condition 2 C (25)(d) re unlabeled fire doors Bullet resistant assembly Door 279 will be removed & replaced w/smaller assembly door mfg by Chicago Bullet Proof Co
SCHROEDER, C W Commonwealth Edison Co 83/06/15 SCHWENCER, A
Licensing Branch 2 3pp, 18919 019, 24X Fiche 50-373, 83/06/15, 8306210205

8306300117 Advises that DOE will respond to requests for emergency radiological assistance from licensees, federal, state & local agencies, private organizations or individuals involved in incident involving source, byproduct or SNM
BAUER, R H Energy, Dept of 83/06/23 DIEDERICH, O J
Commonwealth Edison Co 1p 19121 076 24X Fiche 50-373, 83/06/23, 8306300117

P Operating license stage documents & correspondence

8306100062 Submits clarification of multiple fuel lift values due to criteria differences used by GE Engineering & GE Generic Licensing Groups as result of continued refinements to generic model
SCHROEDER, C W Commonwealth Edison Co 83/06/03, SCHWENCER, A
Licensing Branch 2 3pp 18802 239 24X Fiche 50-373, 83/06/03, 8306100062

8306240406 Notification of 830621 meeting w/util in Bethesda, MD to discuss & clarify responses re multiple control sys failures
BOURNIA, A Licensing Branch 2 83/06/20 SCHWENCER, A
Licensing Branch 2 3pp 18978 017, 24X Fiche 50-373, 83/06/20, 8306240406

G Inspection reports, IE Bulletins & correspondence

8306230005 Addl response to FOIA request for all drafts, insp evaluation repts & comments on J Kepler B20719 rept re special safety insp during May-Jul 1982 of activities at Unit 1, Forwards documents listed in App B. Addl records under review
FELTON, J M Division of Rules and Records 83/03/25 GARDE, B
Government Accountability Project 3pp 18952 001 24X
Fiche 50-373, 83/03/25, 8306230005

--8306230012 Insp Evaluation Rept 82-35 re allegations of drilling & const deficiencies at site Concerns resolved effectively by licensee & NRC Related draft info encl
* NRC - No Detailed Affiliation Given 83/03/25 265pp
18952 004 24X Fiche 50-373, 83/03/25, 8306230005

--8306230015 Evaluation Rept on Atty General of IL allegations re drilling & const deficiencies at site Allegations w/o merit.
* Structural Engineering Branch 83/03/25 4pp 18952 269 24X
Fiche 50-373, 83/03/25, 8306230005

--8306230019 Summary of B20611 mgt meeting at site re ongoing investigation of Atty General of IL allegations concerning drilling & const problems
DAVID, A B Region 3, Office of Director 82/06/17, Region 3, Office of Director 3pp 18952 280 24X Fiche 50-373, 83/03/25, 8306230005

--8306230022 Discusses readiness of facility to receive OL per request Initial recommendation or issuance of OL withdrawn pending further quantification & clarification of const GC issues Insp evaluation & related info encl
REIMANN, F W Region 3, Office of Director 82/06/20 JACKLIN, I N, WALKER, R D Region 3, Office of Director 74pp, 18952, 283 24X Fiche 50-373, 83/03/25, 8306230005

- 8306230043 Discusses 820630, 0707 & 08 telcons re investigations of allegations concerning Facilities Allegations not properly investigated & could result in "whitewash"
CUMMINGS, J J Office of Inspector & Auditor 82/07/13 DIRCKS, W
Office of the Executive Director for Operations 2pp 18953 083
24X Fiche 50-373, 83/03/25, 8306230005
- 8306230061 Discusses concurrence w/Section X of IE Insp Repts 50-373/82-35 & 50-374/82-06 re allegation that Morrison Co torque wrench calibr records falsified Audit not sufficiently comprehensive to draw meaningful conclusions
REIMANN, F W Region 3, Office of Director 82/07/21 Region 3, Office of Director 1p 18953 089 24X Fiche 50-373, 83/03/25, 8306230005
- 8306030209 Forwards IE Insp Rept 50-374/83-13 on 830412-15 & 19-21 No noncompliance noted
LITTLE, W B Region 3, Office of Director 83/05/19 REED, C
Commonwealth Edison Co 2pp 18703 290 24X Fiche 50-374, 83/05/19, 8306030209
- 8306030213 IE Insp Rept 50-374/83-13 on 830412-15 & 19-21 No noncompliance noted Major areas inspected exam of const & as-built drawings for incorporation of design changes, review & approvals
KEY, W J, DANIELSON, D H Region 3, Office of Director 83/05/18 10pp 18703 292 24X Fiche 50-374, 83/05/19, 8306030209
- 8306100172 Forwards IE Insp Repts 50-373/83-16 & 50-374/83-14 on 830411-0506 & notice of violation
STREETER, J F Region 3, Office of Director 83/05/24 REED, C, Commonwealth Edison Co 2pp 18805 265 24X Fiche 50-373, 83/05/24, 8306100172
- 8306100174 Notice of violation from Insp on 830411-0506
STREETER, J F Region 3, Office of Director 83/05/24 2pp, 18805 267 24X Fiche 50-373, 83/05/24, 8306100172
- 8306100175 IE Insp Repts 50-373/83-16 & 50-374/83-14 on 830411-0506 Noncompliance noted failure to have adequate cable separation & failure to have adequate housekeeping practices in cable tray areas
LANKS BURY, R D, DUPONT, S G, REYER, L A Region 3, Office of Director 83/05/24 5pp 18805 269 24X Fiche 50-373, 83/05/24, 8306100172
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 123pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/26 Consolidated Edison Co. of New York, Inc 119pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460
- 8306100263 Forwards IE Insp Rept 50-374/83-17 on 830425-0504 No noncompliance noted
LITTLE, W B Region 3, Office of Director 83/05/27 REED, C
Commonwealth Edison Co 2pp 18807 005 24X Fiche 50-374, 83/05/27, 8306100263
- 8306100266 IE Insp Rept 50-374/83-17 on 830425-0504 No noncompliance noted Major areas inspected 10CFR50 55(e) item re ERCS pumps, instrument racks & installation records
NAIDU, K R, AHMED, I, WILLIAMS, C C Region 3, Office of Director 83/05/26 6pp, 18807 007 24X Fiche 50-374, 83/05/27, 8306100263,
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461
- 8306100245 Ack receipt of 830526 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/83-11 & 50-374/83-06
STREETER, J F Region 3, Office of Director 83/06/06 REED, C
Commonwealth Edison Co 1p 18807/061, 24X Fiche 50-373, 83/06/06, 8306100245
- 8306100250 Responds to NRC 830428 ltr re violations noted in IE Insp Repts 50-373/83-11 & 50-374/83-06 Corrective actions: test engineers re-instructed re test procedures.
FARRAR, D L Commonwealth Edison Co 83/05/26 KEPLER, J Q Region 3, Office of Director 3pp 18807/062, 24X Fiche 50-373, 83/06/06, 8306100245
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464.
- 8306160391 Ack receipt of 830527 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/82-54 & 50-374/82-22
SPEERARD, R L Region 3, Office of Director 83/06/10 REED, C, Commonwealth Edison Co 3pp 18860 037 24X Fiche 50-373, 83/06/10, 8306160391
- 8306160435 Responds to NRC 830428 ltr re violations noted in IE Insp Repts 50-373/82-54 & 50-374/82-22 Corrective actions addl insp criteria utilized during reinsp of cable penetration firestops & during initial installation at Unit 2
FARRAR, D L Commonwealth Edison Co, 83/05/27 KEPLER, J Q Region 3, Office of Director 8pp 18860 040, 24X Fiche 50-373, 83/06/10, 8306160391
- 8306230418 Forwards IE Insp Rept 50-374/83-12 on 830324-20 & 0505 No noncompliance noted
STREETER, J F Region 3, Office of Director 83/06/10, REED, C, Commonwealth Edison Co 2pp 18942:048 24X Fiche: 50-374, 83/06/10, 8306230418
- 8306230423 IE Insp Rept 50-374/83-12 on 830324-30 & 0505 No noncompliance noted Major areas inspected: mgt of QA program, auditing activities, control of design changes & nonconformance control
VANDEL, T E., KISH, J N, HAWKINS, F C Region 3, Office of Director, 83/06/10 7pp 18942 050 24X Fiche 50-374, 83/06/10, 8306230418.
- 8306300129 Forwards IE Insp Repts 50-373/83-12 & 50-374/83-10 on 830311-0410 & notice of violation
SHAFFER, W D Region 3, Office of Director 83/06/11 REED, C
Commonwealth Edison Co 2pp, 19122 333 24X Fiche 50-373, 83/06/11, 8306300129
- 8306300135 Notice of violation from Insp on 830311-0410.
SHAFFER, W D Region 3, Office of Director, 83/06/11 1p, 19122 333 24X Fiche 50-373, 83/06/11, 8306300129
- 8306300141 IE Insp Rept 50-373/83-12 & 50-374/83-10 on 830311-0410. Noncompliance noted: HPCB automatically initiated & no unusual event declared, following reactor scram on 830322.
GULDEHOND, W, MADISON, A., WALKER, R D. Region 3, Office of Director 83/06/08 11pp 19122 336 24X Fiche 50-373, 83/06/11, 8306300129
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13, Consolidated Edison Co. of New York, Inc 118pp, 18920 225 24X Fiche 50-000, 83/06/13, 8305110470.
- 8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13, Consolidated Edison Co. of New York, Inc 243pp, 18921/001 24X Fiche 50-000, 83/06/13, 8306090010
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475.
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Bys Causing Inoperability of Safety-Related Equipment " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 120pp 18997, 007 24X Fiche 50-000, 83/06/22, 8305110477.
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions. " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/06/23, Consolidated Edison Co. of New York, Inc 116pp 18996 242 24X Fiche: 50-000, 83/06/23, 8305110479.
- 8306270215 Forwards IE Insp Repts 50-373/83-17 & 50-374/83-16 on 830411-0517 & notice of violation
SHAFFER, W D. Region 3, Office of Director, 83/06/23, REED, C, Commonwealth Edison Co 2pp, 18988 282, 24X Fiche: 50-373, 83/06/23, 8306270215

DOCKETED ITEMS

--8306270222 IE Insp Rept 50-373/83-17 & 50-374/83-16 on 830411-0517
Noncompliance noted inadequate procedure re traversing
in-core probe sys
MADISON, A., OULDEMOND, W., WALKER, R. D. Region 3, Office of
Director 83/06/22 8pp 18788 285 24X Fiche 50-373, 83/06/23,
8306270215

830510483 IE Info Notice 83-43, "Improper Settings of Intermediate
Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co of New
York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 830510483

G Reportable occurrences, LERs & related correspondence

8306100234 Final deficiency rept re problems w/Riley temp switches
Initially reported on 830316 Based on engineering
evaluation by Riley, switches accurately perform intended
function when calibr w/modified procedure
SCHROEDER, C. Commonwealth Edison Co 83/06/03 KEPLER, J. Q.
Region 3, Office of Director 2pp 18805 321 24X
Fiche: 50-374, 83/06/03, 8306100234

8306160169 PNO-III-83-043 on 830610, while removing filter from reactor
water cleanup sample panel, radiation protection technician
received eye contamination from dry matl adhering to filter
Eye flushing reduced contamination to 30,000 dpm
HUETER, L., MILLER, J. Region 3, Office of Director 83/06/10 1p
18861 272 24X Fiche 50-373, 83/06/10, 8306160169

8306270282 Potential Part 21 rept re discrepancy in welding of
turnbuckle assembly, turnbuckle-bolt interface & on top plate
assembly variable springs SA307 Grade B bolts not ASME
Section IX matl investigation underway
KARAOIANIS, J. A. Elcen Metal Products Co 83/06/17 KEPLER, J. Q.
Region 3, Office of Director 2pp 18796 207 24X
Fiche: 50-000, 83/06/17, 8306270282

DOCKET 50-382 WATERFORD GENERATING STATION, UNIT 3

A Application/construction stage documents & correspondence

8306020687 Requests confirmation of NRC understanding that FSAR states
that testing meets provisions of IEEE-308 & Reg Guide 1.22
re ESF activation sys surveillance requirements
KNIGHTON, Q. W. Licensing Branch 3 83/05/10 MAURIN, L. V. Louisiana
Power & Light Co 4pp 18715 328 24X Fiche 50-382, 83/05/10,
8306020687

8306020641 Notification of 830609 meeting w/util & Torrey Pines in
Bethesda, MD to discuss Torrey Pines independent design
verification program for emergency feedwater sys
WILSON, J. H. Licensing Branch 3 83/05/16 KNIGHTON, Q. W. Licensing
Branch 3 3pp 18716 331 24X Fiche 50-382, 83/05/16, 8306020641

8306070090 Advises of no adverse effect re cultural resources described
in protection plan on Areas 3 & 4 re plantation overseers
house & plantation workers quarters, respectively
DEBIEUX, R. B. Louisiana, State of 83/05/27 REGAN, W. H. Biting
Analysis Branch 1p 18739 206 24X Fiche 50-382, 83/05/27,
8306070090

8306130206 Forwards revised FSAR Chapter 17 re QA program, per
10CFR30.54 & 55 Rev constitutes complete rewrite of QA
program description for operations phase & will be
incorporated into next amend scheduled for Jul 1983
GERRETS, T. F. Louisiana Power & Light Co 83/06/07, KNIGHTON, Q. W.
Licensing Branch 3, 220pp 18886 054 24X Fiche 50-382, 83/06/07,
8306130206

8306270206 Advises of planned use of respiratory protective equipment
per 10CFR20.103. Use of equipment not anticipated prior to
fuel load
DRUMMOND, F. J. Louisiana Power & Light Co 83/06/13 COLLINS, J. T.
Region 4, Office of Director 1p 18991 263 24X
Fiche 50-382, 83/06/13, 8306270206

8306210124 Informs that CE Owners Group study on depressurization &
DHR schedule will be accelerated to provide response to
NRC questions by 830630 Response date originally scheduled
for 830815.
DRUMMOND, F. J. Louisiana Power & Light Co 83/06/16 KNIGHTON, Q. W.
Licensing Branch 3, 1p 18914 205 24X Fiche 50-382, 83/06/16,
8306210124.

8306300166 Forwards supplemental description of CE Owners Group program
& schedule in response to Generic Ltr 83-10A re guidance
for closing out NUREG-0737, Item II.K 3.5, "Automatic Trip
of Reactor Coolant Pumps"
DRUMMOND, F. J. Louisiana Power & Light Co 83/06/27 KNIGHTON, Q. W.
Licensing Branch 3 6pp 19119 273, 24X Fiche 50-382, 83/06/27,
8306300166.

E NRC Safety Evaluation Report (SER), supplis & correspondence

8306130280 Submits results of preoperational piping thermal expansion
testing per SER Confirmatory Issue 3.9.2 Piping & component
expansions acceptable, except for deviations noted
Requirements satisfied
DRUMMOND, F. J. Louisiana Power & Light Co 83/06/00 KNIGHTON, Q. W.
Licensing Branch 3 2pp 18824 140 24X Fiche 50-382, 83/06/00,
8306130280

F Security, medical, emergency & fire protection plans

8306130118 Forwards IE Insp Rept 50-382/83-15 on 830301-0430 No
noncompliance noted
MADSEN, G. L. Region 4, Office of Director 83/05/25 MAURIN, L. V.
Louisiana Power & Light Co 2pp 18824 284 24X
Fiche 50-382, 83/05/25, 8306130118

--8306130127 IE Insp Rept 50-382/83-15 on 830301-0430 No noncompliance
noted Major areas inspected organizational changes, emergency
& general plant operations procedure review, preoperational
test witnessing & unusual event at Union Carbide
CONSTABLE, G. L., FLIPPO, T. A., CROSSMAN, W. A. Region 4, Office of
Director 83/05/23 9pp 18824 286 24X Fiche 50-382, 83/05/25,
8306130118

8306140631 Forwards IE Emergency Preparedness Appraisal Rept
50-382/83-08 on 830222-0304 No noncompliance noted Schedule
for completing corrective actions for deficiency noted in
App A requested within 30 days of receipt of ltr
MADSEN, G. L. Region 4, Office of Director 83/05/27 MAURIN, L. V.
Louisiana Power & Light Co 16pp 18837 281 24X
Fiche 50-382, 83/05/27, 8306140631

--8306140636 IE Emergency Preparedness Appraisal Rept 50-382/83-08 on
830222-0304 No noncompliance noted Major areas inspected
administration, emergency organization, training & retraining
& emergency facilities
HACKNEY, C. A., PERROTTI, D. J., WISNER, C. C. Region 4, Office of
Director 83/05/21 57pp 18837 247 24X Fiche 50-382, 83/05/27,
8306140631

8306090406 Releases public version of revised emergency plan
implementing procedures
FELTON, J. M. Division of Rules and Records 83/06/06 Document
Management Branch 1p 18812 071 24X Fiche 50-382, 83/06/06,
8306090406

--8306090411 Forwards public version of revised emergency plan
implementing procedures, including Procedures EP-1-010 re
unusual event, EP-1-020 re alert & EP-1-030 re site
emergency
MAURIN, L. V. Louisiana Power & Light Co 83/05/12 Office of
Nuclear Reactor Regulation, Director 1p 18812 072 24X
Fiche 50-382, 83/06/06, 8306090406

--8306090416 Public version of revised emergency plan implementing
procedures, including Procedures EP-1-010 re unusual event,
EP-1-020 re alert & EP-1-030 re site emergency
* Louisiana Power & Light Co 83/04/12 663pp 18812 071 24X
Fiche 50-382, 83/06/06, 8306090406

8306170266 Ack receipt of 830517 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-382/83-13
MADSEN, G. L. Region 4, Office of Director 83/06/15 MAURIN, L. V.
Louisiana Power & Light Co 1p 18878 155 24X
Fiche 50-382, 83/06/15, 8306170266

--8306170268 Responds to NRC 830413 ltr re violations noted in IE Insp
Rept 50-382/83-13 Corrective actions walkdown of attachments
to seismic supports for fire protection piping made
ASB-IV-98-1 forms generated for existing attachments,
DRUMMOND, F. J. Louisiana Power & Light Co 83/05/17 MADSEN, G. L.
Region 4, Office of Director 5pp 18878 156 24X
Fiche 50-382, 83/06/15, 8306170266

G Adjudicatory correspondence

8306070417 Forwards until 830524 news release postponing 830525
emergency planning exercise State of LA requested
postponement due to actual emergency conditions caused by
flooding. Svc list encl
CHURCHILL, B. W. Shaw, Pittman, Potts & Trowbridge CHURCHILL, B. W.
Louisiana Power & Light Co 83/06/03 EILPERIN, S. F. Atomic Safety
& Licensing Board Panel JOHNSON, W. R., KOHL, C. N. Atomic Safety
& Licensing Appeal Panel 5pp 18742 243 24X
Fiche 50-382, 83/06/03, 8306070417

DOCKETED ITEMS

251

8306150368 Exceptions to ASLB 0305/16 partial initial decision Certificate of Svc encl
CROESCH, G L Joint Intervenor-Waterford 83/06/10 Atomic
Safety and Licensing Appeal Panel 4pp 18847 302 24X
Fiche 50-382, 83/06/10, 8306150368

8306280536 Forwards CH Burstein 830616 ltr to SJ Wolfe, not served on parties
WOLFE, S J Atomic Safety and Licensing Board Panel 83/06/27
Office of the Executive Legal Director 1p 19020 003 24X
Fiche 50-382, 83/06/27, 8306280536

--8305280541 Advises that author appointed Joint Intervenor counsel
Procedures necessary to reopen Contention 22 re cracked slab
requested
BURSTEIN, C H Burstein, C H BURSTEIN, C H Joint
Intervenor-Waterford 83/06/16 WOLF, S J Atomic Safety and
Licensing Board Panel 1p 19020 004 24X Fiche 50-382, 83/06/27,
8306280536

I Financial information

8306060117 Forwards LA Power & Light Co & Middle South Utils, Inc
Annual Financial Repts 1982
DRUMMOND, F J Louisiana Power & Light Co 83/05/30 Office of
Nuclear Reactor Regulation, Director 1p 18728 024 24X
Fiche 50-382, 83/05/30, 8306060117

--8306060120 Annual Financial Rept 1982
CAIN, J M, WYATT, J M Louisiana Power & Light Co 83/02/24
28pp 18728 025 24X Fiche 50-382, 83/05/30, 8306060117

--8306060225 Annual Financial Rept 1982
LEWIS, F M Middle South Utilities, Inc - Middle South Energy,
Inc 83/05/30 40pp 18728 052 24X Fiche 50-382, 83/05/30,
8306060117

4 Inspection reports, IE Bulletins & correspondence

8306080069 Forwards IE Insp Rept 50-382/83-04 on 830117-21 No
noncompliance noted
MADSEN, G L Region 4, Office of Director 83/04/04 MAURIN, L V
Louisiana Power & Light Co 2pp 18773 219 24X
Fiche 50-382, 83/04/04, 8306080069

--8306080074 IE Insp Rept 50-382/83-04 on 830117-21 No noncompliance
noted. Major areas inspected radiation program actions taken
on 19 open items identified in IE Insp Rept 50-382/82-04 &
Insp of radiation protection controls for reactor fuel
CHANNEY, H D, MURRAY, B, CROSSMAN, W A Region 4, Office of
Director 83/03/24 32pp 18773 217 24X Fiche 50-382, 83/04/04,
8306080069

8306010223 Forwards summary rept for action plan for task force review
of installed structures/components, per Enforcement Action
B2-109 Structures acceptable
MAURIN, L V Louisiana Power & Light Co 83/04/08 COLLINS, J T
Region 4, Office of Director 7pp 18672 342 24X
Fiche 50-382, 83/04/08, 8306010223

8306080078 Forwards IE Insp Rept 50-382/83-07 on 830124-28 No
noncompliance noted
MADSEN, G L Region 4, Office of Director 83/04/20 MAURIN, L V
Louisiana Power & Light Co 2pp 18773 055 24X
Fiche 50-382, 83/04/20, 8306080078

--8306080079 IE Insp Rept 50-382/83-07 on 830124-28 No noncompliance
noted. Major areas inspected radwaste program, including
organization, training, personnel qualifications,
waste sys, effluent release controls & air cleaning sys
BAER, R E, MURRAY, B, CROSSMAN, W A Region 4, Office of Director
83/04/12 21pp 18773 057 24X Fiche 50-382, 83/04/20, 8306080078

8306010152 Informs that IE Insp Rept 50-382/83-11 canceled
MADSEN, G L Region 4, Office of Director 83/05/25 MAURIN, L V
Louisiana Power & Light Co 1p 18674 049 24X
Fiche 50-382, 83/05/25, 8306010152

8306130118 Forwards IE Insp Rept 50-382/83-15 on 830301-0430 No
noncompliance noted
MADSEN, G L Region 4, Office of Director 83/05/25 MAURIN, L V
Louisiana Power & Light Co 3pp 18824 284 24X
Fiche 50-382, 83/05/25, 8306130118

--8306130129 IE Insp Rept 50-382/83-15 on 830301-0430 No noncompliance
noted. Major areas inspected organizational changes, emergency
& general plant operations procedure review, preoperational
test witnessing & unusual event at Union Carbide
COMSTABLE, O L, FLIPPO, T A, CROSSMAN, W A Region 4, Office of
Director 83/05/23 9pp 18824 286 24X Fiche 50-382, 83/05/25,
8306130118

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in
Well Logging Device " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post
830103) 83/05/26 Consolidated Edison Co of New York, Inc
125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New
York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8306140631 Forwards IE Emergency Preparedness Appraisal Rept
50-382/83-08 on 830222-0304 No noncompliance noted. Schedule
for completing corrective actions for deficiency noted in
App A requested within 30 days of receipt of ltr
MADSEN, G L Region 4, Office of Director 83/05/27 MAURIN, L V
Louisiana Power & Light Co 16pp 18837 281 24X
Fiche 50-382, 83/05/27, 8306140631

--8306140636 IE Emergency Preparedness Appraisal Rept 50-382/83-08 on
830222-0304 No noncompliance noted. Major areas inspected
administration, emergency organization, training & retraining
& emergency facilities
HACKNEY, C A, PERROTTI, D J, WISNER, C E Region 4, Office of
Director 83/05/21 57pp 18837 297 24X Fiche 50-382, 83/05/27,
8306140631

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods
Withdrawn at BWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/31 Consolidated Edison Co of New
York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306210061 Forwards IE Insp Rept 50-382/83-17 on 830418-21 & notice of
violation
MADSEN, G L Region 4, Office of Director 83/06/06 MAURIN, L V
Louisiana Power & Light Co 2pp 18712 318 24X
Fiche 50-382, 83/06/06, 8306210061

--8306210064 Notice of violation from insp on 830418-21
* Region 4, Office of Director 83/06/06 3pp 18912 320 24X
Fiche 50-382, 83/06/06, 8306210061

--8306210070 IE Insp Rept 50-382/83-17 on 830418-21 Noncompliance noted
failure to provide safety-related records in accordance w/
established procedures on emergency feedwater sys & failure
to establish adequate document control
OBREGO, C R, JOHNSON, C E, ROBERDS, H J Region 4, Office of
Director 83/05/27 13pp 18912 323 24X Fiche 50-382, 83/06/06,
8306210061

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe
Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/09 Consolidated Edison Co of New
York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive &
Seismically Induced Chatter in Relays Within Printed
Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New
York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From
Degraded Internal Connection Cables." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New
York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8306170266 Ack receipt of 830517 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-382/83-13
MADSEN, G L Region 4, Office of Director 83/06/15 MAURIN, L V
Louisiana Power & Light Co 1p 18878 155 24X
Fiche 50-382, 83/06/15, 8306170266

--8306170268 Responds to NRC 830413 ltr re violations noted in IE Insp
Rept 50-382/83-13 Corrective actions walkdown of attachments
to seismic supports for fire protection piping made
ASP-1V-58-1 forms generated for existing attachments
DRUMMOND, F J Louisiana Power & Light Co 83/05/17 MADSEN, G L
Region 4, Office of Director 5pp 18878 156 24X
Fiche 50-382, 83/06/15, 8306170266

8306170346 Ack receipt of 830429 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-382/83-09,
MADSEN, G L Region 4, Office of Director 83/06/15 MAURIN, L V
Louisiana Power & Light Co 1p 18880 158 24X
Fiche 50-382, 83/06/15, 8306170346

DOCKETED ITEMS

--B306170349 Responds to NRC B30331 ltr re violations noted in IE Insp Rept 50-382/B3-09 Corrective actions fan motor installation verified, personnel trained in use of red-line drawing procedure & Ebasco force account QC group established MAURIN, L.V. Louisiana Power & Light Co. B3/04/29 24X
Region 4, Office of Director. App 18890.159
Fiche 50-382, B3/06/15, B306170346

B305110475 IE Info Notice B3-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/06/22 Consolidated Edison Co. of New York, Inc. 119pp 19021 179. 24X Fiche 50-000, B3/06/22, B305110475

B305110477 IE Info Notice B3-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18997 007 24X Fiche 50-000, B3/06/22, B305110477

B305110479 IE Info Notice B3-42, "Reactor Mode Switch Malfunctions." Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/06/23 Consolidated Edison Co. of New York, Inc. 116pp. 18996 242 24X Fiche 50-000, B3/06/23, B305110479

B305110483 IE Info Notice B3-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/06/24 Consolidated Edison Co. of New York, Inc. 116pp 19046 297 24X Fiche 50-000, B3/06/24, B305110483

R Periodic operating reports & related correspondence

B306010297 Forwards monthly rept of recruiting & upgrading total corporate capability per 810806 meeting commitment.
MAURIN, L.V. Louisiana Power & Light Co. B3/05/16. WILSON, J. NRC ~
No Detailed Affiliation Given App 18672.186 24X
Fiche 50-382, B3/05/16, B306010297

B306280342 Forwards 22nd monthly rept re recruiting & upgrading of total corporate capability
MAURIN, L.V. Louisiana Power & Light Co. B3/06/20 WILSON, J. NRC ~
No Detailed Affiliation Given App 19001 210 24X
Fiche 50-382, B3/06/20, B306280342

9 Reportable occurrences, LERs & related correspondence

B306070307 First interim Significant Const Deficiency Rept B1 re shelf life exceeded on Okonite cable splice & termination tape. Engineering evaluation ongoing Next rept will be submitted by B30722
DRUMMOND, F.J. Louisiana Power & Light Co. B3/05/24 COLLINS, J.T.
Region 4, Office of Director. App 18740.359 24X
Fiche 50-382, B3/05/24, B306070307

B306070317 First interim Significant Const Deficiency B3 re heat tracing design electrical interference identified during hot functional testing Corrective action ongoing Completion expected by B30815 Next rept by B30826
DRUMMOND, F.J. Louisiana Power & Light Co. B3/05/24 COLLINS, J.T.
Region 4, Office of Director App 18744.241 24X
Fiche 50-382, B3/05/24, B306070317

B306010084 Interim Significant Const Deficiency Rept B2 re bent control element assembly rods. Initially reported on B30425 Control element assemblies LA-13 & LA-38 sent to vendor for evaluation Add'l info expected by B30816
DRUMMOND, F.J. Louisiana Power & Light Co. B3/05/25 COLLINS, J.T.
Region 4, Office of Director App 18674.098 24X
Fiche 50-382, B3/05/25, B306010084.

B306070169 Sixth interim rept of Significant Const Deficiency B7 re failures of resistance temp detectors (RTD). Due to restrictions placed on entering RTD cabinets during testing, submittal of final rept delayed until B30812.
DRUMMOND, F.J. Louisiana Power & Light Co. B3/05/26 COLLINS, J.T.
Region 4, Office of Director ip 18736.280 24X
Fiche 50-382, B3/05/26, B306070169.

B306070274 Significant Const Deficiency 42 R-1 re HMA auxiliary relays. Initially reported on B30328 NCR W3-3361 redispensed to use heat shrink tubing available onsite. Final rept delayed until B30717
DRUMMOND, F.J. Louisiana Power & Light Co. B3/05/26. COLLINS, J.T.
Region 4, Office of Director. ip 18744 082. 24X
Fiche 50-382, B3/05/26, B306070274.

B306070133 Third interim rept re Significant Const Deficiency B8 concerning spurious ESF actuation sys. actuation Initially reported on B30331 Corrective action completed Supporting info assembled for QA review Final rept by B30624
DRUMMOND, F.J. Louisiana Power & Light Co. B3/05/30 COLLINS
Region 4, Office of Director ip 18709 214 24X
Fiche 50-382, B3/05/30, B306070133

B306160002 Final rept of Significant Const Deficiency B1 re inco friction factor in pipe support hanger designed by Bergen-Paterson Nonconformance Rept W3-2732 identified, dispositioned & tracked all supports requiring rev & rework
DRUMMOND, F.J. Louisiana Power & Light Co. B3/06/08 COLLINS
Region 4, Office of Director. App 18061 322 24X
Fiche 50-382, B3/06/08, B306160002

B306270052 Interim Significant Const Deficiency Rept 79 re unqua components in hydrogen analyzers Qualified replacement pump makers not yet installed Final rept expected by B30729
DRUMMOND, F.J. Louisiana Power & Light Co. B3/06/15 COLLINS
Region 4, Office of Director ip 19013 359 24X
Fiche 50-382, B3/06/15, B306270052

B306270127 Interim Significant Const Deficiency Rept 84 re tube welding not meeting AWS D 1.1 requirements FCR-ICP-861 R-1 issued on B30511 by Ebasco Engineering to provide corrective action guidelines Final rept expected by B30831
DRUMMOND, F.J. Louisiana Power & Light Co. B3/06/15 COLLINS
Region 4, Office of Director App 18900 089 24X
Fiche 50-382, B3/06/15, B306270127

B306270213 Second interim deficiency rept re American Bridge re auxiliary & fuel handling bldg bolting & welding
Significant Const Deficiency BCD 73 combined w/BCD 78. Reinsp will be completed on B30815, w/rept by B30831
DRUMMOND, F.J. Louisiana Power & Light Co. B3/06/15 COLLINS
Region 4, Office of Director ip 18971 257 24X
Fiche 50-382, B3/06/15, B306270213

B306270310 Second interim Significant Const Deficiency Rept 74 re undersize Schedule 80 socket welds All rework completed except for two flanges Final rept expected by B30729
DRUMMOND, F.J. Louisiana Power & Light Co. B3/06/15 COLLINS
Region 4, Office of Director ip 18975 221 24X
Fiche 50-382, B3/06/15, B306270310

B306270330 Fourth interim rept re Significant Const Deficiency 1 concerning possible failure of GE Type HFA relays Initially reported on B30429 Corrective action incomplete Final rept will be submitted by B30726
DRUMMOND, F.J. Louisiana Power & Light Co. B3/06/15 COLLINS
Region 4, Office of Director ip 18993 045 24X
Fiche 50-382, B3/06/15, B306270330

B306300099 Third interim rept on Significant Const Deficiency 76 480-volt trip coil failure to drop out after tripping Corrective action complete & supporting documentation under review Final rept will be submitted by B30722
DRUMMOND, F.J. Louisiana Power & Light Co. B3/06/22 COLLINS
Region 4, Office of Director ip 19121 040 24X
Fiche 50-382, B3/06/22, B306300099

B306300188 Fourth interim rept on Significant Const Deficiency 1 spurious ESF actuation sys operation Required mode completed Testing still underway Final rept will be submitted by B30826
DRUMMOND, F.J. Louisiana Power & Light Co. B3/06/22 COLLINS
Region 4, Office of Director ip 19119 255 24X
Fiche 50-382, B3/06/22, B306300188

DOCKET 50-387 SUBQUEHANNA STEAM ELECTRIC STATION, UNIT 1

E NRC Safety Evaluation Report (SER), supp's & correspondence

B306140648 Forwards supplemental response to SER Open Item 3 10 Fatigue cycling effects on NBBB equipment due to safety relief loads (License Condition 23(a)) discussed
CURTIS, N.W. Pennsylvania Power & Light Co. B3/06/09 SCONE
Licensing Branch 2 83pp 18933 182 24X Fiche 50-387, B3/06/09
B306140648.

B306230430 Forwards listings of Reg Guide 1.97 Rev 2, instrument of equipment qualification for post-accident monitoring equipment, in response to SER, Suppl 3 Qualification of equipment will be completed by B30331 for Unit 2
CURTIS, N.W. Pennsylvania Power & Light Co. B3/06/20 SCONE
Licensing Branch 2 17pp 18943 215 24X Fiche 50-387, B3/06/20
B306230430

DOCKETED ITEMS

253

8306230466 Responds to SER, Suppl 5, Item 3 11 i(1)(a) re nonsafety-related electrical equipment Failure of nonsafety-related equipment unlikely due to classification under qualification program
CURTIS, N W Pennsylvania Power & Light Co 83/06/20 SCHWENCER, A
Licensing Branch 2 1p 18941 159 24X Fiche 50-387, 83/06/20, 8306230466

F Security, medical, emergency & fire protection plans

8306070214 Forwards Change N to physical security plan Change withheld (ref 10CFR2.790)
KENYON, B D Pennsylvania Power & Light Co 83/05/06 ALLAN, J M
Region 1, Office of Director 1p 18747 020 24X
Fiche 50-387, 83/05/06, 8306070214

8306010171 Ack receipt of 830428 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-387/83-04
MARTIN, T T Division of Engineering & Technical Programs 83/05/26
KENYON, B D Pennsylvania Power & Light Co 1p 18673 034 24X
Fiche 50-387, 83/05/26, 8306010171

--8306010177 Responds to NRC 830331 ltr re violations noted in IE Insp Rept 50-387/83-04 Corrective actions separate security event log established per 10CFR73.71(c)
KENYON, B D Pennsylvania Power & Light Co 83/04/28 MARTIN, T T
Division of Engineering & Technical Programs 2pp 18673 035
24X Fiche 50-387, 83/05/26, 8306010171

8306090010 Releases public version of revised emergency plan Implementing procedure & responses to request for addl info
FELTON, J M Division of Rules and Records 83/06/06 Document
Management Branch 1p 18798 178 24X Fiche 50-387, 83/06/06, 8306090010

--8306090021 Forwards public version of response to request for addl info re emergency plan & Rev O to Emergency Plan Implementing Procedure EP-IP-101 re inventory, insp, operational testing & calibr of emergency equipment & supplies
CURTIS, N W Pennsylvania Power & Light Co 83/05/26
SCHWENCER, A Licensing Branch 2 9pp 18798 179 24X
Fiche 50-387, 83/06/06, 8306090010

--8306090026 Public version of Rev O to Emergency Plan Implementing Procedure EP-IP-101 re inventory, insp, operational testing & calibr of emergency equipment & supplies
KEISER, H W Pennsylvania Power & Light Co 82/07/15 57pp
18790 188 24X Fiche 50-387, 83/06/06, 8306090010

8306210143 Forwards change to physical security plan Change withheld (ref 10CFR2.790)
KENYON, B D Pennsylvania Power & Light Co 83/06/16 ALLAN, J M
Region 1, Office of Director 1p 18919 037 24X
Fiche 50-387, 83/06/16, 8306210143

8306280368 Provides addl justification for 830427 proposed Amend 23 to License NPF-14 Safety parameter display sys for emergency situation will be operational by 831230, following completion of training & verification
CURTIS, N W Pennsylvania Power & Light Co 83/06/23 SCHWENCER, A
Licensing Branch 2 2pp 19001 276 24X Fiche 50-387, 83/06/23, 8306280368

8306300092 Informs of emergency power supply addition to recirculation pump seals in cooling sys Action on License Condition 2 C 28(F) closed.
CURTIS, N W Pennsylvania Power & Light Co 83/06/27 SCHWENCER, A
Licensing Branch 2 1p 19121 041 24X Fiche 50-387, 83/06/27, 8306300092

P Operating license stage documents & correspondence

8208060366 Board Notification 82-70 notifies of differing prof opinion re sensitization of BWR stainless steel weldments.
EISENHUT, D G Division of Licensing 82/07/20 PALLADINO, N J,
GILINSKY, V, AHEARNE, J Commissioners. App 17043 001 24X
Fiche 50-387, 82/07/20, 8208060366

8306010330 Notifies that BWR Owners Group control room survey program not utilized at facilities per Generic Ltr 83-18 Initial control room design review conducted prior to licensing, NRC evaluation of review contained in App F to SER.
CURTIS, N W Pennsylvania Power & Light Co 83/05/26 SCHWENCER, A
Licensing Branch 2 1p 18681 277 24X Fiche 50-387, 83/05/26, 8306010330

8306020429 Forwards state historical preservation of response concurring w/util opinion that plant const will have no adverse effect on archaeological sites in area, per 830315 request
CURTIS, N W Pennsylvania Power & Light Co 83/05/31 SCHWENCER, A
Licensing Branch 2 4pp 18694 104 24X Fiche 50-387, 83/05/31, 8306020429

8306150275 Submits daily highlight Util announced that plant began commercial operation on 830608
PERCH, R L Licensing Branch 2 83/06/08 DENTON, H R, CASE, E Q,
CARTER, J Office of Nuclear Reactor Regulation, Director 1p
18869 360 24X Fiche 50-387, 83/06/08, 8306150275

8306170445 Notification of 830617 meeting w/util in Bethesda, MD to discuss ECCB activation instrumentation
PERCH, R Licensing Branch 2 83/06/08 SCHWENCER, A Licensing
Branch 2 3pp 18907 330 24X Fiche 50-387, 83/06/08, 8306170445

8306170188 Forwards "Susquehanna Steam Electric Station Unit 1 Startup Rept," per Tech Spec Section 6 9 i 1 Supplemental rept will be submitted within 90 days
KENYON, B D Pennsylvania Power & Light Co 83/06/10 ALLAN, J M
Region 1, Office of Director 1p 18802 326 24X
Fiche 50-387, 83/06/10, 8306170188

--8306170191 "Susquehanna Steam Electric Station Unit 1 Startup Rept"
KEISER, H W Pennsylvania Power & Light Co 83/06/09 172pp
18882 327 24X Fiche 50-387, 83/06/10, 8306170188

8306230297 Forwards final response to Humphrey Issues 3 i & 3 j re hydrodynamic loads caused by actuation of RHR safety relief valve during steam condensing mode of RHR sys
CURTIS, N W Pennsylvania Power & Light Co 83/06/15 SCHWENCER, A
Licensing Branch 2 44pp 18945 169 24X Fiche 50-387, 83/06/15, 8306230297

8306210220 Forwards matl presented at Anderson, Greenwood & Co (AGCo) vacuum breaker test program owners group 830607 meeting w/ NRC re dynamic testing & analysis of AGCo vacuum breaker valve assemblies
O'CONNOR, D M Bechtel Corp 83/06/17 HOUSTON, R W Division of
Systems Integration (post 811005) 91pp 18919 038 24X
Fiche 50-000, 83/06/17, 8306210220

8306280368 Provides addl justification for 830427 proposed Amend 23 to License NPF-14 Safety parameter display sys for emergency situation will be operational by 831230, following completion of training & verification
CURTIS, N W Pennsylvania Power & Light Co 83/06/23 SCHWENCER, A
Licensing Branch 2 2pp 19001 276 24X Fiche 50-387, 83/06/23, 8306280368

8306300185 Advises that NRC concern re primary containment vacuum breaker cyclic impact loading caused by pool swell phenomena during LOCA event should be considered resolved based on listed refs, per 830627 ltr
CURTIS, N W Pennsylvania Power & Light Co 83/06/27 SCHWENCER, A
Licensing Branch 2 1p 19122 195 24X Fiche 50-387, 83/06/27, 8306300185

Q Inspection reports, IE Bulletins & correspondence

8306220155 Discusses IE insp on 830112-0308 & forwards notice of violation & proposed imposition of civil penalty
ALLAN, J M Region 1, Office of Director. 83/04/22 KENYON, B D
Pennsylvania Power & Light Co App 18937 330 24X
Fiche 50-387, 83/04/22, 8306220155

--8306220159 Notice of violation & proposed imposition of civil penalty in amount of \$60,000 Noncompliance noted inadequate review & approval of maint activity, which resulted in inoperability of both subsystems of standby gas treatment sys
ALLAN, J M Region 1, Office of Director 83/04/22 5pp
18937 334 24X Fiche 50-387, 83/04/22, 8306220155

8306010121 Forwards IE Insp Repts 50-387/83-11 & 50-388/83-04 on 830406-0503 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 83/05/16
KENYON, B D Pennsylvania Power & Light Co 2pp 18674 001 24X
Fiche 50-387, 83/05/16, 8306010121

--8306010124 Notice of violation from insp on 830406-0503
Region 1, Office of Director 83/05/16 1p 18674 003 24X
Fiche 50-387, 83/05/16, 8306010121

DOCKETED ITEMS

- 8306010134 IE Insp Repts 50-387/83-11 & 50-388/83-04 on 830406-0503 Noncompliance noted numerous fuses had one terminal disconnected on temporary mod control panels 2C661 B2 & 3; opening circuit & no identification tags applied
RHODAS, O, MCCANN, J Region 1, Office of Director MCCABE, E C
Division of Project & Resident Programs 83/05/13 15pp
18674-004 24X Fiche 50-387, 83/05/16, 8306010121
- 8306020442 Ack receipt of 830328 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-387/83-02
MARTIN, T T Division of Engineering & Technical Programs 83/05/20
KENYON, B D Pennsylvania Power & Light Co 2pp 18694 088 24X
Fiche 50-387, 83/05/20, 8306020442
- 8306020444 Responds to NRC 830224 ltr re violations noted in IE Insp Rept 50-387/83-02 Corrective actions memo sent to all members of chemistry group re changes to performance check procedures
KENYON, B D Pennsylvania Power & Light Co 83/03/28 MARTIN, T T
Division of Engineering & Technical Programs 9pp 18694 090
24X Fiche 50-387, 83/03/20, 8306020442
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831-043 24X Fiche 50-000, 83/05/26, 8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732-085 24X Fiche 50-000, 83/05/26, 8305110460
- 8306010171 Ack receipt of 830428 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-387/83-04
MARTIN, T T Division of Engineering & Technical Programs 83/05/26
KENYON, B D Pennsylvania Power & Light Co 1p 18673 034 24X
Fiche 50-387, 83/05/26, 8306010171
- 8306010177 Responds to NRC 830331 ltr re violations noted in IE Insp Rept 50-387/83-04 Corrective actions separate security event log established per 10CFR73 71(c)
KENYON, B D Pennsylvania Power & Light Co 83/04/28 MARTIN, T T
Division of Engineering & Technical Programs 2pp 18673 035
24X Fiche 50-387, 83/05/26, 8306010171
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461
- 8306150278 Ack receipt of 830520 ltr & full payment of proposed civil penalty Response to notice of violation to be evaluated during future insp
AXELRAD, J A Director's Office, Office of Inspection and Enforcement 83/06/06 KENYON, B D Pennsylvania Power & Light Co 2pp 18869, 320. 24X Fiche 50-387, 83/06/06, 8306150278
- 8306200135 Forwards IE Insp Rept 50-387/83-08 on 830310-0428 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/06/06
KENYON, B D Pennsylvania Power & Light Co 2pp 18903 274 24X
Fiche 50-387, 83/06/06, 8306200135
- 8306200136 IE Insp Rept 50-387/83-08 on 830310-0428 No noncompliance noted Major areas inspected, startup test exceptions, power escalation testing, Conditions 4 & 6 transient testing & warranty test.
CHUNG, J W, BETTENHAUSEN, L Region 1, Office of Director 83/06/01 8pp 18903 276 24X Fiche 50-387, 83/06/06, 8306200135
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830, 280 24X Fiche 50-000, 83/06/09, 8305110464
- 8306140482 Responds to IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators " Listed check valves in essential svc water flowpath will be included in Rev 2 to 830630 pump & valve inservice test program.
KENYON, B D Pennsylvania Power & Light Co 83/06/09 ALLAN, J M
Region 1, Office of Director 3pp 18834-173 24X
Fiche 50-387, 83/06/09, 8306140482
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Electrically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920-225 24X Fiche 50-000, 83/06/13, 8305110470
- 8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483
- R Periodic operating reports & related correspondence
- 8306020223 Monthly operating rept for Mar 1983 W/830415 ltr
KUCZYNSKI, L A, KENYON, B D Pennsylvania Power & Light Co 83/04/08 DEEBE, M R Management Information Branch 6pp 18691 129 24X Fiche 50-387, 83/04/08, 8306020223
- 8306270248 Forwards "Annual Environ Operating Rept (Nonradiological) 1982 " & "Radiological Environ Monitoring Program 1982 "
KENYON, B D Pennsylvania Power & Light Co 83/04/28 ALLAN, J M
Region 1, Office of Director 1p 18995 290 24X
Fiche 50-387, 83/04/28, 8306270248
- 8306270251 "Radiological Environ Monitoring Program 1982 " * Radiation Management Corp RMC-TR-83-02 83/04/30 71pp 18995 291 24X Fiche 50-387, 83/04/28, 8306270248
- 8306270253 "Annual Environ Operating Rept (Nonradiological) 1982 " FIELDS, J S, SHANK, K E, MILLER, D W Pennsylvania Power & Light Co 83/04/27 135pp 18996 037 24X Fiche 50-387, 83/04/28, 8306270248
- 8306160472 Monthly operating rept for Apr 1983 W/830510 ltr
KUCZYNSKI, L A, KENYON, B D Pennsylvania Power & Light Co 83/05/06 DEEBE, M R Division of Data Automation & Management Information 5pp 18862 248 24X Fiche 50-387, 83/05/06, 8306160472
- S Reportable occurrences, LERs & related correspondence
- 8306010070 LER 83-061/01P-0 on 830414, during loss of offsite power test; controller for heater element in standby gas treatment sys failed Caused by loss of power condition initiating low temp
KEISER, H W Pennsylvania Power & Light Co 83/05/09 ALLAN, J M
Region 1, Office of Director 1p 18673 362 24X
Fiche 50-387, 83/05/09, 8306010070
- 8306010313 LER 83-065/01P-0 on 830511 & i2, reactor bldg, turbine bldg & standby gas treatment sys sample flow rate monitors out of svc Caused by switch to alternate power supply in preparation for loss of offsite power test
KEISER, H W Pennsylvania Power & Light Co 83/05/12 ALLAN, J M
Region 1, Office of Director 1p 18672 311 24X
Fiche 50-387, 83/05/12, 8306010313
- 8306010323 LER 83-057/01T-0 on 830428, bypass leakage calculations for feedwater sys found invalid Caused by assuming 30-day water seal during post-LOCA conditions Nonbypass leakage boundary valves reworked W/830512 ltr
KEISER, H W, PIENOTTESE, A P Pennsylvania Power & Light Co 83/05/12 ALLAN, J M
Region 1, Office of Director 3pp 18882 272 24X Fiche 50-387, 83/05/12, 8306010323
- 8306010068 LER 83-064/03L-0 on 830414, local leak rate test for main steam line C exceeded Tech Spec value Cause not stated Inboard MSIV reworked & valve retested W/830513 ltr
TODD, J T, KEISER, H W Pennsylvania Power & Light Co 83/05/12 ALLAN, J M
Region 1, Office of Director 2pp 18674 089 24X
Fiche 50-387, 83/05/13, 8306010068

DOCKETED ITEMS

26

8306010099 LER 83-062/03L-0 on 830414, local leak rate test on main steam line A discovered leakage in excess of Tech Specs Cause not stated Inboard MSIV reworked Normal lapping performed on valve disc & seat W/830513 ltr TODD, J T, KEISER, H W Pennsylvania Power & Light Co 83/05/13 ALLAN, J M Region 1, Office of Director 2pp 18674 115 24X Fiche 50-387, 83/05/13, 8306010099

8306010150 LER 83-066/03L-0 on 830414, during removal of Pacific check valve internals, valve disc found lodged in pipe & cotter pin & nut missing Cause not stated Insp will be performed to locate nut W/830513 ltr KUCZYNSKI, L A, KEISER, H W Pennsylvania Power & Light Co 83/05/13 ALLAN, J M Region 1, Office of Director 3pp 18674 057 24X Fiche 50-387, 83/05/13, 8306010150

8306010061 LER 83-067/01P-0 half scram received & MSIV B status light went out after reactor mode switch moved to startup position Neither switch would reset Addl info re cause & corrective action forthcoming KEISER, H W Pennsylvania Power & Light Co 83/05/17 ALLAN, J M Region 1, Office of Director 1p 18674 086 24X Fiche 50-387, 83/05/17, 8306010061

8306010309 LER 83-070/01P-0 on 830518, control room emergency outside air sys declared inoperable Cause by discrepancies in 5.810 cfm flowrate specified Tech Spec requirements Sys inoperable until procedure changed KEISER, H W Pennsylvania Power & Light Co 83/05/18 ALLAN, J M Region 1, Office of Director 1p 18672 318 24X Fiche 50-387, 83/05/18, 8306010309

8306010278 LER 83-068/03L-0 on 830419, during surveillance testing to demonstrate diesel generator operability Following maint, diesel generator A failed to start within required 10 s Cause by lines drained during maint W/830819 ltr KUCZYNSKI, L A, KEISER, H W Pennsylvania Power & Light Co 83/05/19 ALLAN, J M Region 1, Office of Director 2pp 18672.237 24X Fiche 50-387, 83/05/19, 8306010278

8306020369 LER 83-061/01T-0 on 830508, during performance of simulated loss of offsite power test to close startup test exception, standby gas treatment sys failed to develop 10 degree Delta T across heater within 200 s time delay W/830520 ltr PIEMONTESE, A P, KEISER, H W Pennsylvania Power & Light Co 83/05/20 ALLAN, J M Region 1, Office of Director 3pp 18695 103 24X Fiche 50-387, 83/05/20, 8306020369

8306020394 LER 83-069/03L-0 on 830424, during precommercial operation outage & removal of ECCS, leaking relief valve discovered in core spray keep-fill sys Cause by inadequate pressure control in sys W/830524 ltr KUCZYNSKI, L A, KEISER, H W Pennsylvania Power & Light Co 83/05/24 ALLAN, J M Region 1, Office of Director 3pp 18695.006 24X Fiche 50-387, 83/05/24, 8306020394

8306010218 Part 21 rept re screw-clamp type lugs which may not form adequate connection when used w/14 BIS stranded wire Defective lugs identified as ILSCO Corp SLUH-70 ILSCO lugs replaced w/proper sized crimped connection ring lugs KEHOM, B D Pennsylvania Power & Light Co 83/05/25 ALLAN, J M Region 1, Office of Director 2pp 18673 003 24X Fiche 50-387, 83/05/25, 8306010218

8306020382 LER 83-065/01T-0 on 830511, while preparing for standby gas treatment sys testing, three vent monitor sample pumps lost for 5 h & 15 minutes Cause unknown Procedural & stack monitoring sys reviews will be performed W/830525 ltr KUCZYNSKI, L A, KEISER, H W Pennsylvania Power & Light Co 83/05/25 ALLAN, J M Region 1, Office of Director 5pp 18694 348 24X Fiche 50-387, 83/05/25, 8306020382

8306020401 Updated LER 83-059/03X-1 on 830404, plant placed in cold shutdown per planned outage/test schedules Analysis of test data on 830405 showed Level 1 test criteria not met for one valve Cause by leaking dashpot W/830525 ltr PIEMONTESE, A P, KEISER, H W Pennsylvania Power & Light Co 83/05/25 Region 1, Office of Director 4pp 18695 138 24X Fiche 50-387, 83/05/25, 8306020401

8306170217 LER 83-071/03L-0 on 830424, overvoltage setting on one RPS alternate electrical protection assembly found greater than Tech Spec limit Cause by instrument drift Overvoltage setting calibr within limits W/830526 ltr KUCZYNSKI, L A, KEISER, H W Pennsylvania Power & Light Co 83/05/26 ALLAN, J M Region 1, Office of Director 2pp 18878 314 24X Fiche 50-387, 83/05/26, 8306170217

8306210212 Updated LER 83-043/01X-1 on 830322, reactor mode switch turned to shutdown position actuated half scram Cause by two reactor mode switch contact failures Switch replaced Procedures revised W/undated forwarding ltr KEISER, H W, KUCZYNSKI, L A Pennsylvania Power & Light Co 83/05/26 ALLAN, J M Region 1, Office of Director 3pp 18919.027 24X Fiche 50-387, 83/05/26, 8306210212

8306280434 RD fire door Found blocked open for period in excess of 7 days Cause by welding lead run through doorway during approved work activity Welding lead removed upon completion of job KEISER, H W Pennsylvania Power & Light Co 83/05/26 ALLAN, J M Region 1, Office of Director 1p 19020 328 24X Fiche 50-387, 83/05/26, 8306280434

8306170015 LER 83-075/01T-0 on 830515, found chlorine detectors on control room emergency outside air supply may prevent operation in pressurization mode following loss of power Emergency operation procedures revised W/830527 ltr PIEMONTESE, A P, KEISER, H W Pennsylvania Power & Light Co 83/05/27 ALLAN, J M Region 1, Office of Director 3pp 18882 270 24X Fiche 50-387, 83/05/27, 8306170015

8306170037 LER 83-070/01T-0 on 830517, flow rates required to maintain positive pressure in control structure appeared to exceed Tech Spec limits Flow limit inadvertently omitted from procedure Procedure corrected W/830527 ltr PIEMONTESE, A P, KEISER, H W Pennsylvania Power & Light Co 83/05/27 ALLAN, J M Region 1, Office of Director 3pp 18882 229 24X Fiche 50-387, 83/05/27, 8306170037

8306170413 LER 83-067/01T-0 on 830516, reactor mode switch placed in startup position & half scram developed Cause by improper functioning of reactor mode switch contacts Switch replaced. W/830527 ltr KUCZYNSKI, L A, KEISER, H W Pennsylvania Power & Light Co 83/05/27 ALLAN, J M Region 1, Office of Director 4pp 18879 329 24X Fiche 50-387, 83/05/27, 8306170413

8306090246 LER 83-076/01P-0 on 830527, walkdown of control room emergency outside air supply sys revealed cables run through open door Cables removed & door closed KEISER, H W Pennsylvania Power & Light Co 83/05/31 ALLAN, J M Region 1, Office of Director 1p 18795 320 24X Fiche 50-387, 83/05/31, 8306090246

8306280399 LER 83-082/01P-0 on 830607, main turbine trip function (high reactor vessel level) bypassed for post-mod testing on turbine control valves Trip Function not returned to svc prior to Operational Condition 1 KEISER, H W Pennsylvania Power & Light Co 83/06/08 ALLAN, J M Region 1, Office of Director 1p 19001 358 24X Fiche 50-387, 83/06/08, 8306280399

8306280518 LER 83-081/03L-0 on 830511, in Operational Condition 4, shutdown cooling not promptly returned to svc following ABME Class 1 boundary leak test Cause by amount of time required to fill vent sys following leak test W/830608 ltr PIEMONTESE, A P, KEISER, H W Pennsylvania Power & Light Co 83/06/08 ALLAN, J M Region 1, Office of Director 3pp 19017 209 24X Fiche 50-387, 83/06/08, 8306280518

8306280348 LER 83-077/03L-0 on 830510, seven snubbers w/inadequate clearance identified, indicating possible rear bracket interference Cause by lack of info from snubber vendor. Snubbers reworked W/830609 ltr KUCZYNSKI, L A, KEISER, H W Pennsylvania Power & Light Co 83/06/09 ALLAN, J M Region 1, Office of Director 3pp 19001 260 24X Fiche 50-387, 83/06/09, 8306280348

8306280140 LER 83-080/03L-0 on 830513, setpoint for PD18-E-11-INQ19B (shutdown cooling high flow) found out of tolerance Cause by setpoint drift Switch recalibr & returned to svc W/830610 ltr PIEMONTESE, A P, KEISER, H W Pennsylvania Power & Light Co 83/06/10 ALLAN, J M Region 1, Office of Director 2pp 19014 327 24X Fiche 50-387, 83/06/10, 8306280140

8306280510 LER 83-076/01T-0 on 830527, w/control structure door blocked open to run electrical cables through for battery testing, control room emergency outside air supply sys unable to pressurize Cause by personnel error W/830610 ltr EISENHUTH, F T, KEISER, H W Pennsylvania Power & Light Co 83/06/10 ALLAN, J M Region 1, Office of Director 3pp 19017 238 24X Fiche 50-387, 83/06/10, 8306280510

8306280548 Requests that 830926 release date & Transmittal Number PLA-1690 be added to LER 83-043/01X-1 transmittal ltr KEISER, H W Pennsylvania Power & Light Co 83/06/10 ALLAN, J M Region 1, Office of Director 1p 19017.304 24X Fiche 50-387, 83/06/10, 8306280548

8306170343 PNO-1-83-060 on 830614, reactor tripped from 100% power due to high radiation signal sensed in main steam lines Cause by air packet in steam lines Safety relief valve cycled & RCIC manually restarted RHOADS, Q, GREENMAN, E Region 1, Office of Director 83/06/14 1p 18880 083 24X Fiche 50-387, 83/06/14, 8306170343

DOCKETED ITEMS

8306210050 IER 83-079/03L-O on 830515, inboard & outboard dilution flow transmitters found valved out caused by personnel error. Event reprimed given to personnel & will be discussed at next meeting W/830614 ltr. KUZCYNBSKI, L. A., KEISER, H. W. Pennsylvania Power & Light Co. 83/06/14. ALLAN, J. M. Region 1, Office of Director 3pp. 18911 352 24X Fiche 50-387, 83/06/14, 8306210050.

8306280582 PNS-I-83-016: on 830622, bomb threat by unidentified male caller received at plant site & TV station Reactor & turbine bldgs evacuated & search procedures initiated, per emergency & safeguards contingency plans. Results negative. MADDEN, W., ODDY, A. Region 1, Office of Director 83/06/23 2pp. 19017 328 24X Fiche 50-387, 83/06/23, 8306280582.

8306280006 NPDES noncompliance notification on 830619, total iron limit in Discharge 041A exceeded level. Cause under investigation. FIELDS, J. B. Pennsylvania Power & Light Co. 83/06/24. KOVAL, P. Pennsylvania, Commonwealth of, 1p. 19001 122 24X Fiche 50-387, 83/06/24, 8306280006.

V Operator Examinations

8306140017 Extends invitation to attend 830627 meeting in King of Prussia, PA to discuss transfer of reactor operator licensing function from Bethesda, MD to Region 1 of STAROSTECKI, R. Division of Project & Resident Programs 83/06/09. KENYON, B. D. Pennsylvania Power & Light Co. 2pp. 18938 235 24X Fiche 50-387, 83/06/09, 8306140017.

DOCKET 50-388 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 2

A Application/construction stage documents & correspondence

8208060366 Board Notification 82-70 notifies of differing prof opinion re sensitization of BWR stainless steel weldments. EISENHUT, D. G. Division of Licensing 82/07/20. PALLADINO, N. J., QILINSKY, V., AHEARNE, J. Commissioners 4pp. 17043 001 24X Fiche 50-387, 82/07/20, 8208060366.

8306010330 Notifies that BWR Owners Group control room survey program not utilized at facilities per Generic Ltr 83-18. Initial control room design review conducted prior to licensing NRC evaluation of review contained in App F to SER. CURTIS, N. W. Pennsylvania Power & Light Co. 83/05/26. SCHWENCER, A. Licensing Branch 2. 1p. 18681 277 24X Fiche 50-387, 83/05/26, 8306010330.

8306020429 Forwards state historical preservation of response concurring w/utl opinion that plant const will have no adverse effect on archaeological sites in area, per 830315 request. CURTIS, N. W. Pennsylvania Power & Light Co. 83/05/31. SCHWENCER, A. Licensing Branch 2. 4pp. 18694 104. 24X Fiche 50-387, 83/05/31, 8306020429.

8306230297 Forwards final response to Humphrey Issues 3 I & 3 J re hydrodynamic loads caused by actuation of RHR safety relief valve during steam condensing mode of RHR sys. CURTIS, N. W. Pennsylvania Power & Light Co. 83/06/15. SCHWENCER, A. Licensing Branch 2. 4pp. 18745 169 24X Fiche 50-387, 83/06/15, 8306230297.

8306210220 Forwards matl presented at Anderson, Greenwood & Co (AGCo) vacuum breaker test program owners group 830607 meeting w/ NRC re dynamic testing & analysis of AGCo vacuum breaker valve assemblies. O'CONNOR, D. M. Bechtel Corp. 83/06/17. HOUSTON, R. W. Division of Systems Integration (Post 811005) 9pp. 18919 038. 24X Fiche 50-000, 83/06/17, 8306210220.

8306300185 Advises that NRC concern re primary containment vacuum breaker cyclic impact loading caused by pool swell phenomena during LOCA event should be considered resolved based on listed refs, per 830627 ltr. CURTIS, N. W. Pennsylvania Power & Light Co. 83/06/27. SCHWENCER, A. Licensing Branch 2. 1p. 19122 195 24X Fiche 50-387, 83/06/27, 8306300185.

E. NRC Safety Evaluation Report (SER), suppl's & correspondence

8306140448 Forwards supplemental response to SER Open Item 3.10.1(3). Fatigue cycling effects on NSSB equipment due to safety relief loads (License Condition 23(a)) discussed. CURTIS, N. W. Pennsylvania Power & Light Co. 83/06/09. SCHWENCER, A. Licensing Branch 2. 83pp. 18833 182 24X Fiche 50-387, 83/06/09, 8306140448.

8306230430 Forwards listings of Reg Guide 1.97 Rev 2, instrument status of equipment qualification for post-accident monitoring equipment, in response to SER, Suppl 5. Qualification of equipment will be completed by 830331 for Unit 2. CURTIS, N. W. Pennsylvania Power & Light Co. 83/06/20. SCHWENCER, A. Licensing Branch 2. 17pp. 18943 215 24X Fiche 50-387, 83/06/20, 8306230430.

8306230466 Responds to SER, Suppl 5, Item 3.11.1(1)(a) re nonsafety-related electrical equipment. Failure of nonsafety-related equipment unlikely due to classification under qualification program. CURTIS, N. W. Pennsylvania Power & Light Co. 83/06/20. SCHWENCER, A. Licensing Branch 2. 1p. 18941 159 24X Fiche 50-387, 83/06/20, 8306230466.

F Security, medical, emergency & fire protection plans

8306090018 Releases public version of revised emergency plan implementing procedure & responses to request for addl info. FELTON, J. M. Division of Rules and Records 83/06/06. Document Management Branch. 1p. 18798 178 24X Fiche 50-387, 83/06/06, 8306090018.

--8306090021 Forwards public version of response to request for addl info re emergency plan & Rev 0 to Emergency Plan implementing Procedure EP-IP-101 re inventory, insp, operational testing & calibr of emergency equipment & supplies. CURTIS, N. W. Pennsylvania Power & Light Co. 83/05/26. SCHWENCER, A. Licensing Branch 2. 4pp. 18798 179 24X Fiche 50-387, 83/05/26, 8306090021.

--8306090026 Public version of Rev 0 to Emergency Plan implementing Procedure EP-IP-101 re inventory, insp, operational testing & calibr of emergency equipment & supplies. KEISER, H. Pennsylvania Power & Light Co. 82/07/15. 5pp. 18798 180 24X Fiche 50-387, 83/06/06, 8306090026.

G Inspection reports, IE Bulletins & correspondence

8306010121 Forwards IE Insp Repts 50-387/83-11 & 50-388/83-04 on 830406-0503 & notice of violation. STAROSTECKI, R. Division of Project & Resident Programs 83/05/16. KENYON, B. D. Pennsylvania Power & Light Co. 2pp. 18674 001 24X Fiche 50-387, 83/05/16, 8306010121.

--8306010124 Notice of violation from insp on 830406-0503. * Region 1, Office of Director 83/05/16. 1p. 18674 003 24X Fiche 50-387, 83/05/16, 8306010124.

--8306010134 IE Insp Repts 50-387/83-11 & 50-388/83-04 on 830406-0503. Noncompliance noted numerous fuses had one terminal disconnected on temporary mod control panels 2C661 B2 & 7, opening circuit & no identification tags applied. RHODAS, G., MCCANN, J. Region 1, Office of Director. MCCARE, E. C. Division of Project & Resident Programs 83/05/13. 13pp. 18674 004 24X Fiche 50-387, 83/05/16, 8306010134.

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Wall Logging Device." Svc list encl. TAYLOR, J. M. Division of Safeguards & Inspection Programs (Post 830103) 83/05/26. Consolidated Edison Co. of New York, Inc. 125pp. 18931 042. 24X Fiche 50-000, 83/05/26, 8305110458.

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26. Consolidated Edison Co. of New York, Inc. 115pp. 18732 085 24X Fiche 50-000, 83/05/26, 8305110460.

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31. Consolidated Edison Co. of New York, Inc. 116pp. 18732 208 24X Fiche 50-000, 83/05/31, 8305110461.

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09. Consolidated Edison Co. of New York, Inc. 119pp. 18830 280 24X Fiche 50-000, 83/06/09, 8305110464.

8306140482 Responds to IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators." Listed check valves in essential svc water flowpath will be included in Rev 2 to 830630 pump & valve inservice test program. KENYON, B. D. Pennsylvania Power & Light Co. 83/06/09. ALLAN, J. M. Region 1, Office of Director 3pp. 18934 173 24X Fiche 50-387, 83/06/09, 8306140482.

DOCKETED ITEMS

257

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

B Reportable occurrences, LERs & related correspondence

8306170250 Interim deficiency rept re potential excessive offsite dose concerning feedwater containment penetrations not maintaining water seal for 30 days post-LOCA Also reportable under Part 21
CURTIS, N W Pennsylvania Power & Light Co 83/05/31 ALLAN, J M Region 1, Office of Director App 18078 276 24X Fiche 50-388, 83/05/31, 8306170250

8306210079 Interim deficiency rept re lack of movement in ITT Grinnell snubber brackets initially reported on 830429. All snubbers will be reinspected & design & installation processes under review. Final rept due Oct 1983 Also reported per Part 21.
CURTIS, N W Pennsylvania Power & Light Co 83/05/31 ALLAN, J M Region 1, Office of Director App 18711 241 24X Fiche 50-388, 83/05/31, 8306210079

8306280582 PNS-I-83-016 on 830622, bomb threat by unidentified male caller received at plant site & IV station Reactor & turbine bldgs evacuated & search procedures initiated, per emergency & safeguards contingency plans. Results negative.
MADDEN, W, GDDY, A Region 1, Office of Director 83/06/23 2pp 19017 328, 24X Fiche 50-387, 83/06/23, 8306280582.

8306280006 NPDEB noncompliance notification on 830619, total iron limit in Discharge 041A exceeded level Cause under investigation
FIELDS, J S Pennsylvania Power & Light Co 83/06/24 KOVAL, P Pennsylvania, Commonwealth of, Ip 19001 122 24X Fiche 50-387, 83/06/24, 8306280006

V Operator Examinations

8306140017 Extends invitation to attend 830627 meeting in King of Prussia, PA to discuss transfer of reactor operator licensing function from Bethesda, MD to Region 1 ofc
STAROSTECKI, R Division of Project & Resident Programs 83/06/09 KENYON, B D Pennsylvania Power & Light Co, 2pp, 18838, 235, 24X Fiche 50-387, 83/06/09, 8306140017

DOCKET 50-389 ST LUCIE PLANT, UNIT 2

A Application/construction stage documents & correspondence

8306140066 Confirms IE mgt meeting on 830524 in Region III ofc to discuss status of facility completion & readiness for license issuance. Proposed meeting agenda encl.
O'REILLY, J P Region 2, Office of Director 83/03/22 UHRIG, R E Florida Power & Light Co 2pp 18632 139 24X Fiche 50-389, 83/03/22, 8306140066

E NRC Safety Evaluation Report (SER), supply & correspondence

8306010057 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF ST. LUCIE PLANT, UNIT NO 2 Docket No 50-389 (Florida Power And Light Company, And Orlando Utilities Commission Of The City Of Orlando, Florida)
* Office of Nuclear Reactor Regulation, Director NUREG-0843 802 82/09/30 79pp Available at NRC 45 50 18684 321 24X Fiche 50-389, 82/09/30, 8306010057

8306240056 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF ST LUCIE PLANT, UNIT NO 2 Docket No 50-389 (Florida Power And Light Company And Orlando Utilities Commission Of The City Of Orlando, Florida)
* Division of Licensing NUREG-0843 804 83/06/30 26pp 18986 245 24X Fiche 50-389, 83/06/30, 8306240056

F Security, medical, emergency & fire protection plans

8306140272 Confirms 830203 mgt meeting in King of Prussia, PA, per 830201 telcon. Meeting requested to discuss recent insp concerns re civil turnovers, plans for fire protection equipment installation & status of operating procedure preparation
LEWIS, R C Division of Project & Resident Programs 83/02/01 UHRIG, R E Florida Power & Light Co 3pp 18832, 222 24X Fiche 50-389, 83/02/01, 8306140272

8306140650 Summarizes 830203 mgt meeting at Region II ofc re recent insp concerns about civil turnover packages, fire protection plans & operating & emergency procedures. Meeting details & attendee list encl.
LEWIS, R C Division of Project & Resident Programs 83/02/22, UHRIG, R E Florida Power & Light Co 5pp 18843, 062, 24X Fiche 50-389, 83/02/22, 8306140650

8306140538 Forwards IE Insp Repts 50-335/83-06 & 50-389/83-20 on 830314-18 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/05/18 UHRIG, R E Florida Power & Light Co, 2pp 18834 165 24X Fiche: 50-335, 83/05/18, 8306140538

--8306140541 IE Insp Repts 50-335/83-06 & 50-389/83-20 on 830314-18 No noncompliance noted. Major areas inspected emergency planning,
HUFFMAN, Q N Region 2, Office of Director 83/05/17 6pp, 18834 167 24X Fiche 50-335, 83/05/18, 8306140538

8306140302 Forwards IE Insp Repts 50-335/83-18 & 50-389/83-41 on 830506 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/05/23 UHRIG, R E Florida Power & Light Co 2pp 18832 098 24X Fiche 50-335, 83/05/23, 8306140302

--8306140310 IE Insp Repts 50-335/83-18 & 50-389/83-41 on 830506 No noncompliance noted. Major areas inspected emergency preparedness accountability drill
HUFFMAN, Q N Region 2, Office of Director 83/05/19 4pp 18832 100 24X Fiche, 50-335, 83/05/23, 8306140302

8306290209 Forwards IE Insp Repts 50-335/83-17 & 50-389/83-39 on 830509-13 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/06/01, UHRIG, R E Florida Power & Light Co 2pp 19056, 114 24X Fiche: 50-335, 83/06/01, 8306290209

--8306290221 IE Insp Repts 50-335/83-17 & 50-389/83-39 on 830509-13. No noncompliance noted. Major areas inspected enforcement responses, insp followup items, containment cable tray covers & App R electrical cable rerouting
HUNT, M D Region 2, Office of Director 83/05/26 6pp 19056: 116 24X Fiche 50-335, 83/06/01, 8306290209.

8306140023 Releases public version of revised offnormal emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/06/06 Document Management Branch, 1p 18831, 166 24X Fiche, 50-335, 83/06/06, 8306140023

--8306140033 Forwards public version of revised offnormal emergency plan implementing procedures, including Procedures 2-0030131 re plant annunciator summary, 2-0030141 re control room inaccessibility & 2-0440030 re SDC/LPBI offnormal operation.
WETHY, C M Florida Power & Light Co 83/05/17 Office of Nuclear Reactor Regulation, Director, 1p, 18831: 167, 24X Fiche, 50-335, 83/06/06, 8306140023,

--8306140038 Public version of revised offnormal emergency plan implementing procedures, including Procedures 2-0030131 re plant annunciator summary, 2-0030141 re control room inaccessibility & 2-0440030 re SDC/LPBI offnormal operation
* Florida Power & Light Co 83/05/12, 263pp, 18831, 168 24X Fiche: 50-335, 83/06/06, 8306140023

DOCKETED ITEMS

8306160660 Releases public version of revised offnormal & emergency operating procedures
FELTON, J M Division of Rules and Records 83/06/06 Document
Management Branch 1p 18876 340 24X Fiche 50-389, 83/06/06,
8306160660

--8306160662 Forwards public version of revised offnormal & emergency operating procedures, including Procedures 2-0120031 re excessive RCS leakage & 2-0910031 re main transformer offnormal operation.
WETHY, C M Florida Power & Light Co 83/04/21 Director's
Office, Office of Inspection and Enforcement 1p 18876 341 24X
Fiche 50-389, 83/06/06, 8306160660

--8306160666 Public version of revised offnormal & emergency operating procedures, including Procedures 2-0120031 re excessive RCS leakage, 2-0910031 re main transformer offnormal operation & 2-0950030 re boric acid heat tracing sys
HARD Florida Power & Light Co 83/04/20 21pp 18876 342 24X
Fiche 50-389, 83/06/06, 8306160660

8306210382 Releases public version of revised offnormal & emergency operating procedures
FELTON, J M Division of Rules and Records 83/06/06 Document
Management Branch 1p 18936 001 24X Fiche 50-389, 83/06/06,
8306210382

-8306210388 Forwards public version of revised offnormal & emergency operating procedures, including Procedures 2-0030140 re blackout operation, 2-0030141 re control room inaccessibility & 2-0910030 re start-up transformer
WETHY, C M Florida Power & Light Co 83/05/10, Director's
Office, Office of Inspection and Enforcement. 1p 18936 002 24X
Fiche 50-389, 83/06/06, 8306210382

-8306210392 Public version of revised offnormal & emergency operating procedures, including Procedures 2-0030140 re blackout operation, 2-0030141 re control room inaccessibility & 2-0910030 re start-up transformer
HALLEN Florida Power & Light Co 83/05/09 Director's Office,
Office of Inspection and Enforcement 200pp 18936 003 24X
Fiche. 50-389, 83/06/06, 8306210382

8306220225 Releases public version of revised offnormal & emergency operating procedures
FELTON, J M Division of Rules and Records 83/06/06 Document
Management Branch 1p 18977 167 24X Fiche 50-335, 83/06/06,
8306220225

8306220230 Forwards public version of revised offnormal & emergency operating procedures, including Procedures 2-0030140 re blackout operation, 2-0030143 re total loss of power & 2-0250030 re emergency boration
WETHY, C M Florida Power & Light Co 83/04/27 Director's
Office, Office of Inspection and Enforcement 1p 18977 168 24X
Fiche 50-335, 83/06/06, 8306220225

8306220236 Public version of revised offnormal & emergency operating procedures, including Procedures 2-0030140 re blackout operation, 2-0030143 re total loss of ac power & 2-0250030 re emergency boration
* Florida Power & Light Co 83/04/26 Director's Office,
Office of Inspection and Enforcement 87pp 18977 169 24X
Fiche. 50-335, 83/06/06, 8306220225

8306130156 Advises that sentence in util 810914 response to Human Engineering Discrepancy A.1.3 re key storage stating, "Remote Shutdown Panel SIS block keys will be maintained at TAB control access point," should be deleted
UHRIG, R E Florida Power & Light Co 83/06/08 EISENHUT, D G
Division of Licensing 1p. 18824 266 24X Fiche 50-389, 83/06/08,
8306130156.

Insurance & indemnity information

8306170210 Unexecuted Amend 10 to Indemnity Agreement B-76, substituting listed item 3 re license numbers
ALITZMAN, J Assistant Director for State & Licensee Relations
83/04/06 1p. 18971 218 24X Fiche 50-335, 83/04/06, 8306170210

Operating license stage documents & correspondence

8306140784 Notifies of review of Rev 1 to 830308 process control program contains necessary process parameters & boundary conditions to assure that dewatering of head resin will be complete w/no free liquid program acceptable
KNIGHTON, G W Licensing Branch 3 83/05/10 UHRIG, R E Florida
Power & Light Co 2pp 18845 331 24X Fiche: 50-335, 83/05/10,
8306140784

8306020616 Forwards G McCorkle 830510 memo providing add'l info re results of vital area validation review w/o encl
THOMAS, C O Standardization & Special Projects Branch 83/05/26
PARR, D D Auxiliary Systems Branch (LAYTON, B H Procedures &
Systems Review Branch 1p 18715 044 24X Fiche 50-389, 83/05/26,
8306020616

8306140111 Forwards list of equipment, justifications for interim operation & response to request for add'l info re 10CFR50.49 equipment qualification program
UHRIG, R E Florida Power & Light Co 83/05/26 EISENHUT, D G
Division of Licensing 8pp 18840 05/ 24X Fiche 50-389, 83/05/26,
8306140111

--8306140115 "Florida Power & Light, St Lucie, Unit 2, 10CFR50.49 Equipment List"
* Ebasco Services, Inc (subs of Enserch Corp) 83/05/25
114pp 18840 066 24X Fiche 50-389, 83/05/26, 8306140111

8306030074 Fulfills commitment made in 830331 ltr re investigating feasibility of performing demonstration test for loss of ac power Util developed three add'l preoperational tests to demonstrate ability to cross-connect diesel generators
UHRIG, R E Florida Power & Light Co 83/05/27 EISENHUT, D G
Division of Licensing 3pp 18703 359 24X Fiche 50-389, 83/05/27,
8306030074

8306060082 Forwards justification for interim operation re qualification of CONAX assembly used in inadequate core cooling instrumentation Test exposure to DBE/LOCA conditions successfully completed
UHRIG, R E Florida Power & Light Co 83/05/31 EISENHUT, D G
Division of Licensing 3pp 18719 33/ 24X Fiche 50-389, 83/05/31,
8306060082

8306160630 Forwards draft "Control of Heavy Loads at Nuclear Power Plants, St Lucie Plant, Unit 2 (Phase 1)" & synopsis of NRC interpretation of guidelines of NUREG-0612 for use in resolving open items
KNIGHTON, G W Licensing Branch 3 83/05/31 UHRIG, R E Florida
Power & Light Co 14pp 18884 283 24X Fiche 50-389, 83/05/31,
8306160630

--8306160641 Draft "Control of Heavy Loads at Nuclear Power Plants, St Lucie Plant, Unit 2 (Phase 1)," technical evaluation rept
SHADER, C R EG&G, Inc FIN A-6457 EGG-HB-6263 DRAFT 83/04/30
NRC - No Detailed Affiliation Given 16pp 18804 297 24X
Fiche 50-389, 83/05/31, 8306160630

8306100140 Application to amend License DPR-67, revising Tech Specs to extend testing cycle of valves utilized as part of turbine overspeed protection sys Change based on vendor recommendation
UHRIG, R E Florida Power & Light Co 83/06/06 EISENHUT, D G
Division of Licensing 4pp 18801 250 24X Fiche 50-389, 83/06/06,
8306100140

--8306100144 Proposed Tech Spec 3/4.3.4 re turbine overspeed protection
* Florida Power & Light Co 83/06/06 1p 18801 254 24X
Fiche 50-389, 83/06/06, 8306100140

8306130268 Advises that license conditions for 5% power completed power ascension will be commenced upon completion of low power physics testing
UHRIG, R E Florida Power & Light Co 83/06/06 EISENHUT, D G
Division of Licensing 8pp 18824 162 24X Fiche 50-389, 83/06/06,
8306130268

8306240466 Clarifies NRC position re ESF actuation sys surveillance testing required by Tech Specs & FSAR commitments Util required to test ESF actuation sys at power including complete operation of actuation devices
KNIGHTON, G W Licensing Branch 3 83/06/07 UHRIG, R E Florida
Power & Light Co 3pp 18977 241 24X Fiche 50-389, 83/06/07,
8306240466

8306170287 Forwards 2-0030133, Rev 4 to 2-0030140 & Rev 2 to 2-0120037, offnormal & emergency operating procedures
WETHY, C M Florida Power & Light Co 83/06/08 Director's
Office, Office of Inspection and Enforcement 1p 18877, 146, 24X
Fiche. 50-389, 83/06/08, 8306170287

--8306170292 Rev 4 to 2-0030140, "Blackout Operation,"
* Florida Power & Light Co 83/05/31 15pp 18877 147 24X
Fiche. 50-389, 83/06/08, 8306170287

--8306170297 Procedure 2-0030133, "Local Annunciator Summary"
COUTURE, C Florida Power & Light Co 83/06/01 56pp 18877 162
24X Fiche 50-389, 83/06/08, 8306170287

DOCKETED ITEMS

259

--8306170304 Rev 2 to 2-012003/, "Reactor Coolant Gas Vent Sys Off-Normal Operation"
* Florida Power & Light Co 83/06/06 15pp 18877 218 24X
Fiche 50-389, 83/06/08, 8306170307

8306130291 Application for mod to license condition P C 7 for License NFF-16, changing requirement from "prior to exceeding 50% of rated thermal power" to "prior to completion of startup testing" Mod requested due to testing delays at San Onofre
UHRIO, R E Florida Power & Light Co 83/06/09 EISENHUT, D O
Division of Licensing 3pp 18824 12' 24X Fiche 50-389, 83/06/09, 8306130291

8306140009 Advises that post-reactor trip procedures will be modified to include addl criteria for post-reactor trip review
Procedures will be available onsite for NRC concurrence within 60 days following approval of full power OL
UHRIO, R E Florida Power & Light Co 83/06/09 EISENHUT, D O
Division of Licensing 1p 18838 240 24X Fiche 50-389, 83/06/09, 8306140009

8306200026 Staff requirements memo re 830610 discussion & possible vote in Washington, DC on full power OL Commission voted 5 0 to authorize full power operation License amend to be modified re post-trip procedures
CHILK, S J Office of the Secretary of the Commission 83/06/13
DIRCKS, W J Office of the Executive Director for Operations 1p 18908 355 24X Fiche 50-389, 83/06/13, 8306200026

8306200310 Application to amend License NFF-16, allowing use of alternate means of detecting PORV position indication
UHRIO, R E Florida Power & Light Co 83/06/15 EISENHUT, D O
Division of Licensing 5pp 18900 150 24X Fiche 50-389, 83/06/15, 8306200310

8306200194 Forwards corrected Tech Spec Table 3 3-10 re accident monitoring instrumentation submitted in 830615 application to amend license Superscript re min channel operability should have two asterisks instead of three
UHRIO, R E Florida Power & Light Co 83/06/16 EISENHUT, D O
Division of Licensing 1p 18902 355 24X Fiche 50-389, 83/06/16, 8306200194

--8306200195 Corrected Tech Spec Table 3 3-10 re accident monitoring instrumentation
* Florida Power & Light Co 83/06/16 1p 18902 356 24X
Fiche 50-389, 83/06/16, 8306200194

8306210160 Application to amend License NFF-16 revising Tech Spec requirement for primary & secondary coolants in steam generator to be greater than 100 F when coolant pressure greater than 200 psig (ER encl)
UHRIO, R E Florida Power & Light Co 83/06/17 EISENHUT, D O
Division of Licensing 4pp 18914 226 24X Fiche 50-389, 83/06/17, 8306210160

--8306210167 Proposed Tech Specs revising requirement for primary & secondary coolants in steam generator to be greater than 100 F when coolant pressure greater than 200 psig
* Florida Power & Light Co 83/06/17 7pp 18914 230 24X
Fiche 50-389, 83/06/17, 8306210160

8306210261 Forwards addl info supporting proposed license amend request on PORV indication, per 830615 & 16 ltrs Chronology of PORV events, current status & addl info on significant hazards consideration encl
UHRIO, R E Florida Power & Light Co 83/06/17 EISENHUT, D O
Division of Licensing 5pp 18915 056 24X Fiche 50-389, 83/06/17, 8306210261

G. Inspection reports, IE Bulletins & correspondence

8306140272 Confirms 830203 mgt meeting in King of Prussia, PA, per 830201 telcon Meeting requested to discuss recent insp concerns re civil turnovers, plans for fire protection equipment installation & status of operating procedure preparation
LEWIS, R C Division of Project & Resident Programs 83/02/01
UHRIO, R E Florida Power & Light Co 3pp 18832 222 24X
Fiche 50-389, 83/02/01, 8306140272

8306140650 Summarizes 830203 mgt meeting at Region II ofc re recent insp concerns about civil turnover packages, fire protection plans & operating & emergency procedures Meeting details & attendee list encl
LEWIS, R C Division of Project & Resident Programs 83/02/22
UHRIO, R E Florida Power & Light Co 5pp 18843 062 24X
Fiche 50-389, 83/02/22, 8306140650

8306140011 Responds to IE Bulletin 83-04, "Failure of Under Voltage Trip Function of Reactor Trip Breakers" Representatives from util & GE are testing performance of breakers per electrical maint Procedure 0110060
UHRIO, R E Florida Power & Light Co 83/03/31 O'REILLY, J P
Region 2, Office of Director 1p 18838 239 24X
Fiche 50-389, 83/03/31, 8306140011

8306140174 Forwards IE Insp Rept 50-389/83-36 on 830425-28 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/05/16
UHRIO, R E Florida Power & Light Co 2pp 18839 039 24X
Fiche 50-389, 83/05/16, 8306140174

--8306140180 IE Insp Rept 50-389/83-36 on 830425-28 No noncompliance noted Major areas inspected licensee action on previous insp findings, licensee identified item & previously identified inspector followup item
LENAHAN, J J Region 2, Office of Director CONLON, T E Division of Engineering & Radiological Safety Programs 83/05/13 5pp 18839 041 24X Fiche 50-389, 83/05/16, 8306140174

8306140186 Forwards IE Insp Rept 50-389/83-34 on 830425-29 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/05/16
UHRIO, R E Florida Power & Light Co 2pp 18839 058 24X
Fiche 50-389, 83/05/16, 8306140186

--8306140191 IE Insp Rept 50-389/83-34 on 830425-29, No noncompliance noted Major areas inspected preoperational procedure review & preoperational test results review
KRUDE, H E, TAYLOR, P A Region 2, Office of Director JAFFE, F
Division of Engineering & Radiological Safety Programs 83/05/12, 5pp 18839 060 24X Fiche 50-389, 83/05/16, 8306140186

8306140538 Forwards IE Insp Repts 50-335/83-06 & 50-389/83-20 on 830314-18 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/05/18
UHRIO, R E Florida Power & Light Co 2pp 18834 165 24X
Fiche 50-335, 83/05/18, 8306140538

--8306140541 IE Insp Repts 50-335/83-06 & 50-389/83-20 on 830314-18 No noncompliance noted Major areas inspected emergency planning
HUFFMAN, O N Region 2, Office of Director JENKINS, O R Division of Emergency Preparedness & Materials Safety 83/05/17 6pp 18834 167 24X Fiche 50-335, 83/05/18, 8306140538

8306140302 Forwards IE Insp Repts 50-335/83-18 & 50-389/83-41 on 830506 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/05/23
UHRIO, R E Florida Power & Light Co 2pp 18832 078 24X
Fiche 50-335, 83/05/23, 8306140302

--8306140310 IE Insp Repts 50-335/83-18 & 50-389/83-41 on 830506 No noncompliance noted Major areas inspected emergency preparedness accountability drill
HUFFMAN, O N Region 2, Office of Director JENKINS, O R Division of Emergency Preparedness & Materials Safety 83/05/19 4pp 18832 100 24X Fiche 50-335, 83/05/23, 8306140302

8306140633 Forwards summary of 830513 mgt meeting in Atlanta, GA re util actions on 830411 confirmation of action ltr on plant operating & emergency procedures
LEWIS, R C Division of Project & Resident Programs 83/05/23
UHRIO, R E Florida Power & Light Co 4pp 18843 056 24X
Fiche 50-389, 83/05/23, 8306140633

8306140638 Forwards schedule for completion of responses to IE Bulletin 80-11, "Masonry Wall Design" Required mods to masonry walls will be completed prior to completion of first refueling outage item closed
UHRIO, R E Florida Power & Light Co 83/05/24 O'REILLY, J P
Region 2, Office of Director 3pp 18043 043 24X
Fiche 50-389, 83/05/24, 8306140638

8306140504 Ack receipt of 830509 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-389/83-16
DANCE, H C Division of Project & Resident Programs 83/05/25
UHRIO, R E Florida Power & Light Co 1p 18838 108 24X
Fiche 50-389, 83/05/25, 8306140504

--8306140510 Responds to NRC 830325 ltr re violations noted in IE Insp Rept 50-389/83-16 Corrective actions process sheets will include const hold points that will be signed off, providing ongoing status of required/completed insps.
UHRIO, R E Florida Power & Light Co 83/05/09 O'REILLY, J P
Region 2, Office of Director 3pp 18838 109 24X
Fiche 50-389, 83/05/25, 8306140504

DOCKETED ITEMS

--8306140514 Forwards IE Insp Rept 50-389/83-16 on 830222-25 & notice of violation
LEWIS, R. C. Division of Project & Resident Programs 83/03/25
UHRIG, R. E. Florida Power & Light Co 2pp 18938 112 24X
Fiche 50-389, 83/05/25, 8306140504

--8306140516 Notice of violation from insp on 830222-25
* Division of Project & Resident Programs 83/03/25 1p
18838-114 24X Fiche 50-389, 83/05/25, 8306140504

--8306140520 IE Insp Rept 50-389/83-16 on 830222-25 Noncompliance noted
failure to execute & maintain status of structural steel
insp program
LENAHAN, J. J., CONLON, T. E. Region 2, Office of Director 83/03/14
5pp, 18838, 115, 24X Fiche 50-389, 83/05/25, 8306140504

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in
Well Logging Device." Svc list encl.
TAYLOR, J. M. Division of Safeguards & Inspection Programs (Post
830103) 83/05/26 Consolidated Edison Co. of New York, Inc
129pp, 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet."
Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co. of New
York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8306140640 Documents concurrence w/utl actions taken in response to
830411 Confirmation of Action Ltrs CAL-335/83-01 &
389/83-01 Insp during wk of 830516 concluded that Unit 2
procedures adequate for startup & operation
O'REILLY, J. P. Region 2, Office of Director 83/05/27 ADDMAT, E. A.
Florida Power & Light Co. 2pp 18841 161 24X
Fiche: 50-335, 83/05/27, 8306140640

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods
Withdrawn at DHRs." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/31 Consolidated Edison Co. of New
York, Inc 116pp, 18732-208 24X Fiche 50-000, 83/05/31, 8305110461

8306140097 Responds to IE Bulletin 79-14, "Seismic Analysis for As-
Built Safety-Related Piping Sys." Program verifying piping
geometry, including support/restraint/valve locations
re piping sys & restraint function, complete
UHRIG, R. E. Florida Power & Light Co 83/06/01 O'REILLY, J. P.
Region 2, Office of Director. 2pp, 18939 109 24X
Fiche: 50-389, 83/06/01, 8306140097

8306140581 Submits final response to IE Bulletin 79-02 re
safety-related concrete expansion anchors Stringent design
criteria & systematic QA program implemented to ensure
proper installation & testing of anchors
UHRIG, R. E. Florida Power & Light Co. 83/06/01, O'REILLY, J. P.
Region 2, Office of Director 2pp 18844-151 24X
Fiche: 50-389, 83/06/01, 8306140581

8306290209 Forwards IE Insp Repts 50-335/83-17 & 50-389/83-39 on
830509-13, No noncompliance noted
DANCE, H. C. Division of Project & Resident Programs 83/06/01
UHRIG, R. E. Florida Power & Light Co 2pp 19056-114, 24X
Fiche: 50-335, 83/06/01, 8306290209

--8306290221 IE Insp Repts 50-335/83-17 & 50-389/83-39 on 830509-13 No
noncompliance noted. Major areas inspected: enforcement
responses, insp followup items, containment cable tray covers
& App R electrical cable rerouting.
HUNT, M. D., CONLON, T. E. Region 2, Office of Director 83/05/26
6pp 19056, 116 24X Fiche: 50-335, 83/06/01, 8306290209

8306290421 Forwards IE Insp Rept 50-389/83-40 on 830509-12 No
noncompliance noted
DANCE, H. C. Division of Project & Resident Programs 83/06/01,
UHRIG, R. E. Florida Power & Light Co 2pp 19052-174, 24X
Fiche: 50-389, 83/06/01, 8306290421.

--8306290424 IE Insp Rept 50-389/83-40 on 830509-12 No noncompliance
noted. Major areas inspected: seismic analysis for as-built
safety-related piping sys & pipe support baseplate design
using concrete expansion anchor bolts (IE Bulletin 79-14)
AND, M. P. Region 2, Office of Director. BLAKE, J. J. Division of
Engineering & Radiological Safety Programs 83/05/27, 5pp,
19053-176 24X Fiche 50-389, 83/06/01, 8306290421

8306130268 Advises that license conditions for 5% power completed.
Power ascension will be commenced upon completion of low
power physics testing.
UHRIG, R. E. Florida Power & Light Co. 83/06/06, EISENHUT, D. G.
Division of Licensing 8pp, 18824-182 24X Fiche: 50-389, 83/06/06,
8306130268.

8306290217 Forwards IE Insp Rept 50-389/83-43 on 830516-20 No
noncompliance noted
DANCE, H. C. Region 2, Office of Director 83/06/08 UHRIG, R. E.
Florida Power & Light Co 2pp 19056 200 24X
Fiche 50-389, 83/06/08, 8306290217

--8306290225 IE Insp Rept 50-389/83-43 on 830516-20 No noncompliance
noted. Major areas inspected: plant operating & surveillance
procedures
XRUG, H. C., VOGT-LOWELL, R., HIBB, H. E. Region 2, Office of Director
83/06/06 3pp 19056 202 24X Fiche 50-389, 83/06/08, 8306290217

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe
Operations." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/09 Consolidated Edison Co. of New
York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive &
Seismically Induced Chatter in Relays Within Printed
Circuit Cards." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co. of New
York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From
Degraded Internal Connection Cables." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co. of New
York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8306290327 Ack receipt of 830420 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-335/82-36
DANCE, H. C. Division of Project & Resident Programs 83/06/17
UHRIG, R. E. Florida Power & Light Co 1p 19050 194 24X
Fiche 50-335, 83/06/17, 8306290327

--8306290359 Forwards IE Insp Repts 50-335/82-36 & 50-389/82-55 on
821011-1110 & notice of violation
DANCE, H. C. Division of Project & Resident Programs 82/12/07
UHRIG, R. E. Florida Power & Light Co 2pp 19050 198 24X
Fiche 50-335, 83/06/17, 8306290327

--8306290379 IE Insp Repts 50-335/82-36 & 50-389/82-55 on 821011-1111
Noncompliance noted: use of unqualified matl in emergency
diesel generator lube oil sys
ELROD, S. A., HIBB, H. E. Region 2, Office of Director JULIAN, C. A.
Division of Project & Resident Programs 82/12/06 11pp
19050 201 24X Fiche 50-335, 83/06/17, 8306290327

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
Epoxy Grouts & Sealers." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co. of New
York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys
Causing Inoperability of Safety-Related Equipment." Svc list
encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co. of New
York, Inc 120pp, 18997 007 24X Fiche 50-000, 83/06/23, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions."
Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co. of New
York, Inc 116pp, 18996 242, 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate
Range (IR) High Flux Trip Setpoints." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co. of New
York, Inc 116pp, 19046-297 24X Fiche 50-000, 83/06/24, 8305110483

R Periodic operating reports & related correspondence

8306160638 Monthly operating repts for Apr 1983 W/830516 ltr
PAGE, P. L. Florida Power & Light Co 83/05/16 Office of Resource
Management, Director 17pp 18866 105 24X Fiche 50-000, 83/05/16,
8306160638

S Reportable occurrences, LERs & related correspondence

8306300202 Part 21 rept re short-term reliability problem w/position
indicating mechanism in solenoid valve used to control
PORV 3750010 Magnet position indicating mechanism replaced
on 830507 Corrective action in progress
JOHNSON, V. M. Garrett Corp 83/05/09 Director's Office, Office
of Inspection and Enforcement 3pp 19122-123 24X
Fiche 50-389, 83/05/09, 8306300202

8306010116 LER 83-002/03L-0 on 830421, while in Mode 6, refueling bus tie breaker 2A2 & 2A3 opened, deenergizing bus 2A3 & causing loss of low pressure safety injection pump A. Caused by shorted contact due to personnel error. Bus 2A3 restored.
BRANNIN, J P, WILLIAMS, J W Florida Power & Light Co 83/05/23
O'REILLY, J P Region 2, Office of Director 2pp 18473 356 24X
Fiche 50-389, 83/05/23, 8306010116

8306010252 LER 83-005/01T-0 on 830507, while reviewing plant status following mode change to hot shutdown, discovered safety injection tanks had remained isolated. Caused by personnel error. Operators counseled on procedures. W/830523 ltr.
VALDES, S A, WILLIAMS, J W Florida Power & Light Co 83/05/23
O'REILLY, J P Region 2, Office of Director 2pp 18472 294 24X
Fiche 50-389, 83/05/23, 8306010252

8306010007 LER 83-004/03L-0 on 830424, during initial fill & vent, wide-range pressure indicator discovered reading zero psig. Caused by erroneously isolated pressure transmitter, rendering PORV inoperable. Valve lineup performed successfully. W/830524 ltr.
VALDES, S A, WILLIAMS, J W Florida Power & Light Co 83/05/24
O'REILLY, J P Region 2, Office of Director 2pp 18474 149 24X
Fiche 50-389, 83/05/24, 8306010007

8306070181 LER 83-006/01T-0 on 830511, leak of approx 1 quart per minute developed in weld on 1-inch drain line for safety injection header 2B1. Cause unknown. Cracked weld & associated piping replaced. Weld undergoing exam. W/830524 ltr.
BRANNIN, J P, WILLIAMS, J W Florida Power & Light Co 83/05/24
O'REILLY, J P Region 2, Office of Director 2pp 18736 325 24X
Fiche 50-389, 83/05/24, 8306070181

8306070058 LER 83-007/03L-0 on 830428, during cold shutdown, PORV 1474 failed to open at required pressure. Cause not determined. Sys pressure reduced & PORV tested satisfactorily. W/830531 ltr.
BRANNIN, J P, WILLIAMS, J W Florida Power & Light Co 83/05/31
O'REILLY, J P Region 2, Office of Director 2pp 18740 080 24X
Fiche 50-389, 83/05/31, 8306070058

8306070191 PNO-II-83-043 on 830602, initial criticality achieved w/factual parameters in close agreement w/predicted conditions. Low power testing began immediately & scheduled to be completed within 5 days.
JULIAN, C A, DANCE, H C Region 2, Office of Director 83/06/02
lp 18736 293 24X Fiche 50-389, 83/06/02, 8306070191

8306200146 Submits supplemental info to LER 83-06 re safety injection sys vent/drain vibration restraints. Field insp program, field vent/drain insp & plant change/mod procedure initiated. Info to be included in revised LER.
UHRIG, R E Florida Power & Light Co 83/06/06 O'REILLY, J P
Region 2, Office of Director 3pp 18703 121 24X
Fiche 50-389, 83/06/06, 8306200146

8306200180 LER 83-011/03L-0 on 830510, during precritical testing, initial performance of Tech Spec surveillance found three valve motor operators missing thermal overload bypass switches. Caused by design error. Design changed. W/830609 ltr.
WEST, D, WILLIAMS, J W Florida Power & Light Co 83/06/09
O'REILLY, J P Region 2, Office of Director 2pp 18903 178 24X
Fiche 50-389, 83/06/09, 8306200180

8306200094 LER 83-010/03L-0 on 830511, power lost to side B vital & nonvital buses. Caused by opening incorrect breaker at distribution switchyard. Personnel instructed on importance of proper switching.
VALDES, S A, WILLIAMS, J W Florida Power & Light Co 83/06/10
O'REILLY, J P Region 2, Office of Director 2pp 18903 337 24X
Fiche 50-389, 83/06/10, 8306200094

8306210081 LER 83-008/03L-0 on 830514, while in Mode 3, operator observed all position indication lights on PORV 1475 were out. Caused by loss of magnetic property to magnet on valve shaft due to high temps in environs. Magnet replaced. W/830613 ltr.
BRANNIN, J P, WILLIAMS, J W Florida Power & Light Co 83/06/13
O'REILLY, J P Region 2, Office of Director 2pp 18911 239 24X
Fiche 50-389, 83/06/13, 8306210081

8306220014 LER 83-009/03L-0 on 830514, while in Mode 3, hot standby, personnel airlock was in use & outer equalizing valve did not shut. Airlock declared inoperable. Caused by broken equalizing valve. Broken piece repaired. W/830613 ltr.
BRANNIN, J P, WILLIAMS, J W Florida Power & Light Co 83/06/13
O'REILLY, J P Region 2, Office of Director 2pp 18927 340 24X
Fiche 50-389, 83/06/13, 8306220014

8306280476 LER 83-013/03L-0 on 830520, while leak testing escape airlock, excessive leak rate detected. Caused by linkages for inner & outer door equalizing valves being slightly out of adjustment. Linkages readjusted. W/830620 ltr.
PARKB, D, WILLIAMS, J W Florida Power & Light Co 83/06/20
O'REILLY, J P Region 2, Office of Director 2pp 19018 289 24X
Fiche 50-389, 83/06/20, 8306280476

8306300153 LER 83-014/03L-0 on 830522, main feed water isolation valve B drifted open twice. Caused by thermal relief orifice installed in hydraulic line to top of actuator. Thermal relief orifice in hydraulic sys plugged. W/830622 ltr.
WALLING, O E, WILLIAMS, J W Florida Power & Light Co 83/06/22
O'REILLY, J P Region 2, Office of Director 3pp 19048 356 24X
Fiche 50-389, 83/06/22, 8306300153

8306300025 LER 83-016/03L-0 on 830527, during preoperational testing, two of three charging pumps inoperable for approx 15 h. Caused by sealwater sys gasket leak & charging pump relief valve failure. Pumps repaired & retested. W/830624 ltr.
WEST, D, WILLIAMS, J W Florida Power & Light Co 83/06/24
O'REILLY, J P Region 2, Office of Director 2pp 19120 356 24X
Fiche 50-389, 83/06/24, 8306300025

T Hearing transcripts on non-antitrust matters

8306160673 Transcript of Commission 830610 meeting re discussion & possible vote on full-power OL in Washington, DC. Pp 1-90.
Supporting documentation encl.
* Commissioners 83/06/10 150pp 18884.045 24X
Fiche 50-389, 83/06/10, 8306160673

V Operator Examinations

8306140745 Discusses shift staffing at Facilities Util intends to initially operate Unit 2 & continue Unit 1 operations w/five full shifts of licensed operators on each unit. Planned actions for filling vacant positions provided.
UHRIG, R E Florida Power & Light Co 83/06/03, EISENHUT, D O,
Division of Licensing 3pp 18841 192 24X Fiche 50-335, 83/06/03, 8306140745

8306140572 Forwards revised shift staffing chart based on 830606 notification that seven licensee candidates received reactor operator licenses.
UHRIG, R E Florida Power & Light Co 83/06/07, EISENHUT, D O,
Division of Licensing 2pp 18844 149 24X Fiche 50-335, 83/06/07, 8306140572

DOCKET 50-390 WATTS BAR NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

8306080006 Forwards "TVA Watts Bar Nuclear Plant Auxiliary Feedwater Sys Independent Review Rept." Rept initially provided on 830418.
MILLS, L M Tennessee Valley Authority 83/05/11, ADENBAM, E,
Licensing Branch 4, lp 18754 057 24X Fiche 50-390, 83/05/11, 8306080006

--8306080009 "TVA Watts Bar Nuclear Plant Auxiliary Feedwater Sys Independent Review Rept."
* Black & Veatch 83/04/12, 4, 800pp, 18754 058, 24X
Fiche 50-390, 83/05/11, 8306080009

8306020604 Notification of 830520 meeting w/util in Bethesda, MD to discuss measures to prevent liquefaction of soils beneath ERCH pipeline.
KENYON, T J, Licensing Branch 4 83/05/17, ADENBAM, E O, Licensing Branch 4 3pp 18715 053 24X Fiche 50-390, 83/05/17, 8306020604

8306020606 Confirms NRC caseload forecast panel findings resulting from 830302-04 site visit to assess const completion schedules. Issuance of suppl to SER (NUREG-0847) scheduled for Nov 1983.
NOVAH, T M, Assistant Director for Licensing, 83/05/24, PARRIS, H O,
Tennessee Valley Authority 3pp 18715 050 24X
Fiche 50-390, 83/05/24, 8306020606

8306140287 Forwards request for addl info re analysis of sheathpile walls & seismic analysis of buried pipes, based on review of util 821130 & 830325 submittals. Response requested by 830630 & expedite facility review.
ADENBAM, E O, Licensing Branch 4 83/06/01, PARRIS, H O, Tennessee Valley Authority 3pp 18844 310 24X Fiche 50-390, 83/06/01, 8306140287

8306080071 Forwards responses to NRC concerns re SIRT issues for facility, per 830311 telcon. Further audit of safety-related electrical & mechanical equipment not warranted.
MILLS, L M Tennessee Valley Authority 83/06/03, ADENBAM, E,
Licensing Branch 4 22pp 18773.193 24X Fiche 50-390, 83/06/03, 8306080071

DOCKETED ITEMS

8306160060 Summary of 830520 meeting w/uttl, Woodward-Clyde consultants & NBS in Bethesda, MD re liquefaction of soils beneath ERCH pipeline. Issue must be resolved to permit completion of remedial work by fuel load
MILLER, M A Licensing Branch 4 83/06/06 Licensing Branch 4
26pp 18872 323 24X Fiche 50-390, 83/06/06, 8306160060

8306130362 Forwards revised response to NUREG-0737, Item II F 1, committing to install GA Co Model RD-23 high-range gas monitors by fuel load
MILLER, L M Tennessee Valley Authority 83/06/07 ADENSAH, E
Licensing Branch 4 4pp 18822 157 24X Fiche 50-390, 83/06/07, 8306130362

8306160533 Forwards Page 11 inadvertently omitted from encl to 830603 responses to questions from SGRT
MILLER, L M Tennessee Valley Authority 83/06/10 ADENSAH, E
Licensing Branch 4 22pp 18863 117 24X Fiche 50-390, 83/06/10, 8306160533

8306160725 Summary of 830324 meeting w/uttl & Westinghouse in Bethesda, MD re design review panel review of new Westinghouse stress analysis on manifold fasteners for D2/D3 steam generator mod
HOPKINS, J B Licensing Branch 4 83/06/10 Licensing Branch 4
7pp 18876, 277, 24X Fiche 50-000, 83/06/10, 8306160725

8306170335 Forwards Rev A to "Thermal Capability Curves for CONAX Electric Penetration Assemblies & Electric Conductor Seal Assemblies," inadvertently omitted from 830609 ltr
MILLER, L M Tennessee Valley Authority 83/06/10 ADENSAH, E
Licensing Branch 4 4pp 18880, 084 24X Fiche 50-390, 83/06/10, 8306170335

--8306170336 Rev A to "Thermal Capability Curves for CONAX Electric Penetration Assemblies & Electric Conductor Seal Assemblies"
FEDERICK, W C, RHODES, Q M Conax Corp. IPB-701 81/07/16 70pp
18880 088 24X Fiche 50-390, 83/06/10, 8306170335

8306290573 Summary of Design Review Panel 830321 meeting w/uttl & Westinghouse in Bethesda, MD re D2/D3 steam generator mod & Westinghouse stress analysis of manifold fasteners
HOPKINS, J B Licensing Branch 4 83/06/10 Licensing Branch 4
7pp 19047 085 24X Fiche 50-000, 83/06/10, 8306290573

8306240366 Summary of 830525 telcon w/uttl, NBS & Corps of Engineers re liquefaction Util proposal to construct underground barriers. feasible Detailed plans requested for NRC review
MILLER, M Licensing Branch 4 83/06/22 Licensing Branch 4,
5pp 18998 356 24X Fiche 50-390, 83/06/22, 8306240366

8306290163 Forwards evaluation re peak horizontal ground acceleration for use in soil liquefaction analyses Amplification Factor of approx 2 appropriate Peak horizontal acceleration of 0.4 g should be used for analyses.
NOVAK, T M Assistant Director for Licensing 83/06/22 PARRIS, H O
Tennessee Valley Authority. 7pp 19046 280 24X
Fiche 50-390, 83/06/22, 8306290163

E NRC Safety Evaluation Report (SER), suppl & correspondence

8306210217 Forwards responses to actions to resolve issues in Chapter B of SER & issues raised at 820701-04 site visit & drawing review
KAMMER, D B Tennessee Valley Authority 83/06/09 ADENSAH, E
Licensing Branch 4 18pp 18918 076, 24X Fiche 50-390, 83/06/09, 8306210217

8306220011 Forwards updated listing showing status of each SER open & confirmatory item
MILLER, L M Tennessee Valley Authority 83/06/16 ADENSAH, E
Licensing Branch 4 11pp 18927 343 24X Fiche 50-390, 83/06/16, 8306220011

F Security, medical, emergency & fire protection plans

8306210010 Forwards "Program Plan for Control Room Design Reviews for all TVA Nuclear Plants," in response to Generic Ltr 82-33 re upgrade of emergency plans
KAMMER, D B Tennessee Valley Authority. 83/06/09, ADENSAH, E
Licensing Branch 4. 3pp 18913-001 24X Fiche 50-000, 83/06/09, 8306210010

--8306210016 Procedure 862207, 10, "Program Plan for Control Room Design Reviews for all TVA Nuclear Plants"
* Tennessee Valley Authority 83/06/09 200pp 18913 004 24X
Fiche 50-000, 83/06/09, 8306210010,

8306200034 Responds to 83010/ & 10 requests for evaluation of three unresolved insp items Chemical Engineering Branch/Fire Protection Section fire protection issues encl Interior fire hose sys conforms to guidelines
EISENHUT, D O Division of Licensing 83/06/13 OLSHINSKI, J A
Division of Emergency Preparedness & Materials Safety 6pp
18919 304 24X Fiche 50-390, 83/06/13, 8306200034

8306230178 Responds to NRC 830325 ltr re need for addl instrumentation in auxiliary control room for plant cooldown instrumentation meets all App R requirements
MILLER, L M Tennessee Valley Authority 83/06/17 ADENSAH, E
Licensing Branch 4 3pp 18946 361 24X Fiche 50-390, 83/06/17, 8306230178

G Inspection reports, IE Bulletins & correspondence

8306100239 Supple 821216 response to violations noted in IE Insp Repts 50-390/82-20 & 50-391/82-20 Vendor insp of dampers requested Three addl dampers replaced Corrective actions to be completed by 830331
MILLER, L M Tennessee Valley Authority 83/01/31 O'REILLY, J P
Region 2, Office of Director ip 10007 052 24X
Fiche 50-390, 83/01/31, 8306100239

8306140543 Confirms mgt meeting on 830421 in Chattanooga, TN to review results of first phase of annual appraisal of regulatory performance, per 830328 telcon
LEWIS, R C Division of Project & Resident Programs 83/04/12
PARRIS, H O Tennessee Valley Authority 3pp 18834 176 24X
Fiche 50-000, 83/04/12, 8306140543

8306140355 Forwards IE Insp Rept 50-390/83-13 on 830418-22 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/05/13
PARRIS, H O Tennessee Valley Authority 2pp 18832 167 24X
Fiche 50-390, 83/05/13, 8306140355

--8306140362 IE Insp Rept 50-390/83-13 on 830418-22 No noncompliance noted Major areas inspected preoperational test procedure review, test witnessing, test results review & followup on previous insp findings
THOMAS, M, MATHIS, J L, JAPE, F Region 2, Office of Director
83/05/12 6pp 18832 169 24X Fiche 50-390, 83/05/13, 8306140355

8306140562 Forwards IE Insp Repts 50-390/83-15 & 50-391/83-11 on 830321-0422 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/05/20
PARRIS, H O Tennessee Valley Authority 2pp 18844 129 24X
Fiche 50-390, 83/05/20, 8306140562

--8306140580 IE Insp Repts 50-390/83-15 & 50-391/83-11 on 830321 0422 No noncompliance noted Major areas inspected plant tour, operating, maint & emergency procedure insps, preoperational test procedure review & observation of structural concrete
HEATHERLY, T L, SWAN, W Region 2, Office of Director QUICK, D R
Division of Project & Resident Programs 83/05/20 18pp
18844 131 24X Fiche 50-390, 83/05/20, 8306140562

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc
129pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458,

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26, Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8306140415 Ack receipt of 830513 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/83-08 & 50-391/83-07
LEWIS, R C Division of Project & Resident Programs 83/05/27
PARRIS, H O Tennessee Valley Authority 1p 18838 053 24X
Fiche 50-390, 83/05/27, 8306140415

--8306140420 Responds to NRC 830414 ltr re violations noted in IE Insp Repts 50-390/83-08 & 50-391/83-07 Corrective actions loose matl removed from Unit 1 steam generators & Unit 2 generators will be inspected before secondary side closure
KAMMER, D B Tennessee Valley Authority 83/05/13 O'REILLY, J P
Region 2, Office of Director 4pp 18838 054 24X
Fiche 50-390, 83/05/27, 8306140415

--8306140425 Forwards IE Insp Repts 50-390/83-08 & 50-391/83-07 on 830223-0320 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/04/14
PARRIS, H O Tennessee Valley Authority 2pp 18838, 058 24X
Fiche 80-390, 83/05/27, 8306140415

DOCKETED ITEMS

263

--8306140428 Notice of violation from insp on 830223-0320
* Region 2, Office of Director 83/04/14 1p 18038 060 24X
Fiche 50-390, 83/05/27, 8306140415

--8306140434 IE Insp Repts 50-390/83-08 & 50-391/83-07 on 830223-0320
Noncompliance noted unscheduled insps during 830302-14
Identified foreign matl in secondary side of steam
generators
HEATHERLY, T L, SWAN, W Region 2, Office of Director QUICK, D R
Division of Project & Resident Programs 83/04/13 8pp
18838 061 24X Fiche 50-390, 83/05/27, 8306140415

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods
Withdrawn at BHRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/31 Consolidated Edison Co of New
York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306290428 Forwards IE Insp Rept 50-390/83-20 on 830516-20 No
noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/06/06
PARRIS, H G Tennessee Valley Authority 2pp 17050 187 24X
Fiche 50-390, 83/06/06, 8306290428

--8306290511 IE Insp Rept 50-390/83-20 on 830516-20 No noncompliance
noted Major areas inspected containment structural integrity
testing, containment integrated leakage rate testing &
preoperational test procedure review
BROOKS, E, THOMAS, M, MATHIS, J Region 2, Office of Director
83/06/02 5pp 19050 189 24X Fiche 50-390, 83/06/06, 8306290428

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe
Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/09 Consolidated Edison Co of New
York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive &
Seismically Induced Chatter in Relays Within Printed
Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New
York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From
Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New
York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010.

8306290308 Ack receipt of 83060P ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-390/83-12 &
50-391/83-09
VERRELLI, D M. Division of Project & Resident Programs 83/06/15
PARRIS, H G Tennessee Valley Authority 1p 19056 001 24X
Fiche 50-390, 83/06/15, 8306290308

--8306290316 Responds to NRC 830506 ltr re violations noted in IE Insp
Repts 50-390/83-12 & 50-391/83-09 Corrective actions
Nonconformance Rept 4778R initiated on 830420 to document
concrete test cylinder 5532 testing below design strength
MILLS, L M Tennessee Valley Authority 83/06/02 O'REILLY, J P
Region 2, Office of Director 3pp 19056 002 24X
Fiche 50-390, 83/06/15, 8306290308

--8306290318 Forwards IE Insp Repts 50-390/83-12 & 50-391/83-09 on
830418-20 & notice of violation
VERRELLI, D M. Division of Project & Resident Programs 83/05/06
PARRIS, H G Tennessee Valley Authority 2pp 19056 004 24X
Fiche 50-390, 83/06/15, 8306290308

--8306290324 Notice of violation from insp on 830418-20
* Region 2, Office of Director 83/05/06 1p 19056 006 24X
Fiche 50-390, 83/06/15, 8306290308

--8306290328 IE Insp Repts 50-390/83-12 & 50-391/83-09 on 830418-20
Noncompliance noted nonconformance rept not issued for test
cylinder 5532 testing below design strength Disputes item
1 re failure to provide certified mail test rept
HARRIS, J R, CONLON, T E Region 2, Office of Director 83/05/05
4pp 19056 007 24X Fiche 50-390, 83/06/15, 8306290308

8306290483 Approves issuance of BALP Repts 50-259/83-04, 50-260/83-04,
50-276/83-04, 50-327/83-04, 50-328/83-04, 50-390/83-07,
50-391/83-06, 50-438/83-06 & 50-439/83-06 for Jul 1981 - Dec
1982 No reply required
O'REILLY, J P Region 2, Office of Director 83/06/17 PARRIS, H G
Tennessee Valley Authority 3pp 24X Fiche 50-000, 83/06/17,
8306290483

--8306290490 Forwards BALP Repts 50-259/83-04, 50-260/83-04,
50-276/83-04, 50-327/83-04, 50-328/83-04, 50-390/83-07,
50-391/83-06, 50-438/83-06 & 50-439/83-06 for Jul 1981 - Dec
1982
LEWIS, R C Division of Project & Resident Programs 83/04/13
PARRIS, H G Tennessee Valley Authority 3pp 24X
Fiche 50-000, 83/06/17, 8306290483

--8306290503 BALP Repts 50-259/83-04, 50-260/83-04, 50-276/83-04,
50-327/83-04, 50-328/83-04, 50-390/83-07, 50-391/83-06,
50-438/83-06 & 50-439/83-06 for Jul 1981 - Dec 1982
* Region 2, Office of Director 83/04/13 92pp 24X
Fiche 50-000, 83/06/17, 8306290483

--8306290510 Comments on BALP Repts 50-259/83-04, 50-260/83-04,
50-276/83-04, 50-327/83-04, 50-328/83-04, 50-390/83-07,
50-391/83-06, 50-438/83-06 & 50-439/83-06 for Jul 1981 - Dec
1982
MILLS, L M Tennessee Valley Authority 83/05/10 O'REILLY, J P
Region 2, Office of Director. 2pp 24X Fiche 50-259, 83/06/17,
8306290483

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New
York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Bys
Causing Inoperability of Safety-Related Equipment " Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New
York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions,"
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co of New
York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479.

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate
Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co of New
York, Inc 116pp 19046 277 24X Fiche 50-000, 83/06/24, 8305110483

R Periodic operating reports & related correspondence

8306280612 "Environ Radioactivity Levels, Watts Bar Nuclear Plant,"
annual rept for 1982 W/830620 ltr
MILLS, L M. Tennessee Valley Authority 83/05/31 DENTON, H R
Office of Nuclear Reactor Regulation, Director 66pp 19016 023
24X Fiche 50-390, 83/05/31, 8306280612

B Reportable occurrences, LERs & related correspondence

8306010113 First interim deficiency rept re nonconforming seismic
analysis of steam valve rooms Initially reported on 830502
Reanalysis performed to correct all deficiencies in
original analysis Next rept by 830923
MILLS, L M Tennessee Valley Authority 83/05/24 O'REILLY, J P
Region 2, Office of Director 2pp 18673 340 24X
Fiche 50-390, 83/05/24, 8306010113

8306010136 Fourth interim deficiency rept re failure to evaluate
operator actions to realign ERCW Train A Initially reported
on 820510 Analysis continuing Next rept will be submitted by
831603
MILLS, L M Tennessee Valley Authority 83/05/24 O'REILLY, J P
Region 2, Office of Director 1p 18674 041 24X
Fiche 50-390, 83/05/24, 8306010136

8306010143 Supplemental info to deficiency rept re failure to inspect
stud welds on flush-mounted embedded plates Initially
reported on 820812 Completion date of 830513 for corrective
actions not met Work will be completed by 830729
MILLS, L M Tennessee Valley Authority 83/05/24 O'REILLY, J P
Region 2, Office of Director 1p 18674.045 24X
Fiche 50-390, 83/05/24, 8306010143.

8306010283 First interim deficiency rept re Westinghouse pump motors
supplied w/o seismic analysis or operability demonstrated
Initially reported on 830428 Investigation continuing Next
rept will be submitted by 830829
MILLS, L M Tennessee Valley Authority 83/05/24, O'REILLY, J P
Region 2, Office of Director. 2pp 18672 340 24X
Fiche 50-390, 83/05/24, 8306010283

DOCKETED ITEMS

8306070072 Fifth interim deficiency rept re engineering change notice review & handling Initially reported on 811215 Personnel retained & corrective actions presented to Ofc of QA for approval Addl info will be submitted by 830722
MILLS,L.M. Tennessee Valley Authority 83/05/24. O'REILLY,J.P.
Region 2, Office of Director 2pp 18740 085 24X
Fiche 50-000,83/05/24,8306070072.

8306010274 Third interim deficiency rept re sheared motor pinion keys in Limitorque motor operators Initially reported on 820830 Field change notices issued to replace keys Next rept will be sent by 830922 Also reportable per Part 21
MILLS,L.M. Tennessee Valley Authority 83/05/25 O'REILLY,J.P.
Region 2, Office of Director 2pp 18674 322 24X
Fiche 50-000,83/05/25,8306010274

8306010431 Second interim deficiency rept re corrosion in high pressure fire protection sys Initially reported on 820903 Sys contains carbon steel piping Corrosion analyses in progress Next rept to be submitted by 821004
MILLS,L.M. Tennessee Valley Authority 83/05/25 O'REILLY,J.P.
Region 2, Office of Director 2pp 18674 255 24X
Fiche 50-000,83/05/25,8306010431

8306070064 Seventh interim deficiency rept re qualification of epoxy grout for safety-related applications Initially reported on 810827 Design Criteria DB-1 7.1, "General Anchorage to Concrete," & drawing for support mods being revised
MILLS,L.M. Tennessee Valley Authority 83/05/26. O'REILLY,J.P.
Region 2, Office of Director 1p 18740:099 24X
Fiche 50-390,83/05/26,8306070064

8306070074 First interim deficiency rept re incorrect max pipe movements contained in TIPIE program Initially reported on 830504 W/o encl Next rept expected by 830922
MILLS,L.M. Tennessee Valley Authority 83/05/26 O'REILLY,J.P.
Region 2, Office of Director 1p 18739.319. 24X
Fiche 50-000,83/05/26,8306070074.

8306070048 Final deficiency rept re potentially overstressed embedded plates Initially reported on 820412 Interim spacing requirements implemented to control spacing of future attachments to embedded plates
MILLS,L.M. Tennessee Valley Authority 83/05/27. O'REILLY,J.P.
Region 2, Office of Director 2pp 18739 341 24X
Fiche 50-390,83/05/27,8306070048

8306070138 Third interim deficiency rept re voiding of engineering change notices w/o proper review Initially reported on 820816 Change notices being reviewed & unresolved safety question determination performed Next rept by 830923
MILLS,L.M. Tennessee Valley Authority 83/05/31. O'REILLY,J.P.
Region 2, Office of Director 2pp 18739 264 24X
Fiche 50-000,83/05/31,8306070138.

8306090322 Final deficiency rept re faulty fillet welds Initially reported on 800220 Listed ABME Code welds reinspected & marked for tracking Clarified insp criteria & mechanical aids (fillet gauges) used in routine visual insp.
MILLS,L.M. Tennessee Valley Authority 83/06/01 O'REILLY,J.P.
Region 2, Office of Director 4pp 18795 115 24X
Fiche 50-390,83/06/01,8306090322

8306090135 Second interim deficiency rept re Henry Pratt butterfly valve Initially reported on 821109 Valve air-operator yoke mod kits delivered & mod in progress Operators removed & returned to OH Bettis Co. Also reported per Part 21
MILLS,L.M. Tennessee Valley Authority 83/06/02. O'REILLY,J.P.
Region 2, Office of Director 1p 18795 297 24X
Fiche 50-000,83/06/02,8306090135

8306090142 Final deficiency rept re control bldg isolation dampers leaking Initially reported on 830504 New leaktight butterfly valves received & installed Const drawings revised to indicate new valves
MILLS,L.M. Tennessee Valley Authority 83/06/02 O'REILLY,J.P.
Region 2, Office of Director 2pp 18795 293 24X
Fiche 50-390,83/06/02,8306090142

8306140466 Revised final deficiency rept re auxiliary power sys. Initially reported on 800925 ECN 2786 issued to modify transmission grid-auxiliary power sys interface to ensure adequate offsite power to safety-related buses
MILLS,L.M. Tennessee Valley Authority 83/06/03 O'REILLY,J.P.
Region 2, Office of Director 3pp 18834:313 24X
Fiche 50-390,83/06/03,8306140466

8306140427 Second interim deficiency rept re pipe supports not designed or modified per ECN 2576 Initially reported on 830118 Auxiliary feedwater sys review completed & drawings revised Generic implications reviewed Next rept by 830822
MILLS,L.M. Tennessee Valley Authority 83/06/04 O'REILLY,J.P.
Region 2, Office of Director 2pp 18838.047. 24X
Fiche 50-390,83/06/04,8306140427

8306140435 First interim deficiency rept re DB-16 reactor trip breaker design error identified by Westinghouse Initially reported on 830505 Undervoltage attachments will be replaced Next rept by 830926 Also reported per Part 21
MILLS,L.M. Tennessee Valley Authority 83/06/06 O'REILLY,J.P.
Region 2, Office of Director 2pp 18838 035 24X
Fiche 50-390,83/06/06,8306140435

8306200169 Final deficiency rept re fire dampers improperly installed & damaged Initially reported on 830505 Damage caused by improper handling & installation by const craft due to inadequate QC New dampers purchased
MILLS,L.M. Tennessee Valley Authority 83/06/07 O'REILLY,J.P.
Region 2, Office of Director 3pp 18702 360 24X
Fiche 50-390,83/06/07,8306200169

8306200145 First interim deficiency rept re Meriam Instrument failure to implement QA program Initially reported on 830910 Investigation underway Next rept to be submitted by 830922
MILLS,L.M. Tennessee Valley Authority 83/06/09 O'REILLY,J.P.
Region 2, Office of Director 2pp 18703 124 24X
Fiche 50-390,83/06/09,8306200145

8306210051 Supplemental interim deficiency rept re potentially overstressed embedded plates Initially reported on 820412 Next submittal scheduled for 840217 instead of 830622 as originally stated
MILLS,L.M. Tennessee Valley Authority 83/06/10 O'REILLY,J.P.
Region 2, Office of Director 1p 18914 009 24X
Fiche 50-000,83/06/10,8306210051

8306210088 Final deficiency rept re failure to shut down redundant auxiliary bldg exhaust fans upon secondary containment isolation signal Initially reported on 830505 Engineering Change Notice ECN 3011 issued & logic drawings revised
MILLS,L.M. Tennessee Valley Authority 83/06/10 O'REILLY,J.P.
Region 2, Office of Director 2pp 18619 188 24X
Fiche 50-390,83/06/10,8306210088

8306210150 Final deficiency rept for Unit 1 & sixth interim deficiency rept for Unit 2 re loading criteria for structural steel & supports Initially reported on 81117 Ongoing training programs in engineering procedures will resolve problems
MILLS,L.M. Tennessee Valley Authority 83/06/13 O'REILLY,J.P.
Region 2, Office of Director 3pp 18916 028 24X
Fiche 50-390,83/06/13,8306210150

8306210039 First interim deficiency rept re lack of isolation capability for post-accident sampling facility air intakes Initially reported on 830517 Safety-grade redundant isolation valves to be installed Next rept by 830822
MILLS,L.M. Tennessee Valley Authority 83/06/15 O'REILLY,J.P.
Region 2, Office of Director 2pp 18912 337 24X
Fiche 50-390,83/06/15,8306210039

8306210087 First interim deficiency rept re containment isolation valves installed in chilled water sys not designed to be leaktight Initially reported on 830517 Engineering Change Notices 3861 & 3864 initiated Next rept by 830913
MILLS,L.M. Tennessee Valley Authority 83/06/15 O'REILLY,J.P.
Region 2, Office of Director 2pp 18914 134 24X
Fiche 50-390,83/06/15,8306210087

8306210116 Final deficiency rept re solid state protection sys test procedures Initially reported on 820831 Procedural change initiating use of test probe w/indicator lamp connected to ground implemented Also reportable under Part 21.
MILLS,L.M. Tennessee Valley Authority 83/06/15 O'REILLY,J.P.
Region 2, Office of Director 4pp 18714 098 24X
Fiche 50-390,83/06/15,8306210116

8306270354 Fifth interim deficiency rept re frequency criteria for piping supports Initially reported on 820713 Subsections B.2.2 & B.2.3 of WB-DC-40-31 9 revised to provide clarification Next rept by 830921
MILLS,L.M. Tennessee Valley Authority 83/06/16 O'REILLY,J.P.
Region 2, Office of Director 2pp 18796 226 24X
Fiche 50-390,83/06/16,8306270354

8306270386 Second interim deficiency rept re flexible hoses not provided in drawings issued under ECN 2104 Engineering procedures checklist revised Next rept expected by 830906
MILLS,L.M. Tennessee Valley Authority 83/06/16 O'REILLY,J.P.
Region 2, Office of Director 2pp 18793 166 24X
Fiche 50-390,83/06/16,8306270386

8306280426 Supplemental deficiency rept re post-accident readings from containment sump level transmitters Initially reported on 820708 Fuel load data rescheduled to Jan 1984 Also reportable per Part 21
MILLS,L.M. Tennessee Valley Authority 83/06/17 O'REILLY,J.P.
Region 2, Office of Director 1p 19018 350 24X
Fiche 50-390,83/06/17,8306280426.

DOCKETED ITEMS

265

8306280578 Interim deficiency rept re resolution of listed items due for submittal in late June Corrective actions in progress List identifying each item schedule for next submittal & level of interim rept encl
MILLS,L M Tennessee Valley Authority 83/06/17 O'REILLY, J R
Region 2, Office of Director 2pp 17018 193 24X
Fiche 50-000,83/06/17,8306280578

8306280572 Second interim deficiency rept re Westinghouse gate valve position indication problems Initially reported on 830203 Field change notices prepared to correct closure indication problems Next rept will be submitted by 830928
MILLS,L M Tennessee Valley Authority 83/06/20 O'REILLY, J P
Region 2, Office of Director 2pp 17017 320 24X
Fiche 50-390,83/06/20,8306280573

8306300013 Supplemental final deficiency rept re containment penetration protection Initially reported on 811207 Deficiency expanded to cover Unit 2 on 020730 Correct completion date for Unit 2 is 840815
MILLS,L M Tennessee Valley Authority 83/06/21 O'REILLY, J P
Region 2, Office of Director 2pp 17120 354 24X
Fiche:50-390,83/06/21,8306300013

8306300038 Sixth interim deficiency rept re foam seals in mechanical pipe sleeves Initially reported on 811204 Design std providing requirements & procedures to sleeve designers in final review Next rept by 830928
MILLS,L M Tennessee Valley Authority 83/06/21 O'REILLY, J P
Region 2, Office of Director 1p 17120 305 24X
Fiche 50-390,83/06/21,8306300038

8306300205 Final deficiency rept re rerouting high-pressure fire protection piping w/o proper analyses Initially reported on 830130 Based on head/flow tests on calculated worst case fire condition determined not reportable per 10CFR50 55(e)
MILLS,L M Tennessee Valley Authority 83/06/21 O'REILLY, J P
Region 2, Office of Director 2pp 17122 121 24X
Fiche 50-390,83/06/21,8306300205

8306300051 Sixth interim deficiency rept re failure of Limitorque motor operators during valve closure Initially reported on 820124 Westinghouse & Limitorque determining cause of failures Next rept expected by 830928 Also reportable per Part 21
MILLS,L M Tennessee Valley Authority 83/06/22 O'REILLY, J P
Region 2, Office of Director 2pp 19120 193 24X
Fiche 50-390,83/06/22,8306300051

8306300054 Final deficiency rept re piping sys analysis tracking Initially reported on 820902 Engineering Procedures 3 03 & 4 25 revised to correct problem of tracking closure of engineering change notices prior to Class 1 analysis
MILLS,L M Tennessee Valley Authority 83/06/22 O'REILLY, J P
Region 2, Office of Director 2pp 17120 290 24X
Fiche 50-390,83/06/22,8306300054

8306300214 Second interim deficiency rept re tubeline mats supplied by Capital Pipe & Steel not mfg under QA program Initially reported on 830329 Contractor will perform dimensional checks for pipes & fittings Next rept by 830928
MILLS,L M Tennessee Valley Authority 83/06/23 O'REILLY, J P
Region 2, Office of Director 5pp 19119 351 24X
Fiche 50-000,83/06/23,8306300214

8306300228 Second interim deficiency rept re postulated accident blowdown of more than one steam generator Initially reported on 821122 Westinghouse analysis indicated no core damage will occur for postulated event Next rept by 830928
MILLS,L M Tennessee Valley Authority 83/06/23 O'REILLY, J P
Region 2, Office of Director 2pp 19119 180 24X
Fiche 50-390,83/06/23,8306300228

8306300033 Second interim deficiency rept re spacing & clearance in auxiliary bldg high-pressure fire protection sprinkler sys Initially reported on 830331 Review of installation configuration incomplete Next rept by 831005
MILLS,L M Tennessee Valley Authority 83/06/24 O'REILLY, J P
Region 2, Office of Director 2pp 17120 308 24X
Fiche 50-390,83/06/24,8306300033

8306300082 Fourth interim deficiency rept re concrete anchorage free edge violation Initially reported on 830328 Redesign &/or rework will be required on 99 of 477 supports. Next rept by 830917
MILLS,L M Tennessee Valley Authority 83/06/24 O'REILLY, J P
Region 2, Office of Director 3pp 17048 332 24X
Fiche 50-390,83/06/24,8306300082

DOCKET 50-391 WATTS BAR NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

8306080004 Forwards "TVA Watts Bar Nuclear Plant Auxiliary Feedwater Sys Independent Review Rept " Rept initially provided on 830418
MILLS,L M Tennessee Valley Authority 83/05/11 ADENSAH,E
Licensing Branch 4 1p 18754 057 24X Fiche 50-390,83/05/11,8306080006

--8306080009 "TVA Watts Bar Nuclear Plant Auxiliary Feedwater Sys Independent Review Rept "
* Black & Veatch 83/04/12 4,800pp 18754 058 24X
Fiche 50-390,83/05/11,8306080006

8306020604 Notification of 830520 meeting w/util in Bethesda, MD to discuss measures to prevent liquefaction of soils beneath ERCW pipeline
KENYON,T J Licensing Branch 4 83/05/17 ADENSAH,E G Licensing Branch 4 3pp 18715 053 24X Fiche 50-390,83/05/17,8306020604

8306020606 Confirms NRC caseload forecast panel findings resulting from 830302-04 site visit to assess const completion schedules Issuance of suppl to SER (NUREG-0847) scheduled for Nov 1983
NOVAK,T M Assistant Director for Licensing 83/05/24 PARRIS,H Q Tennessee Valley Authority 3pp 18715 050 24X
Fiche 50-390,83/05/24,8306020606

8306140287 Forwards request for addl info re analysis of sheathpile walls & seismic analysis of buried pipes, based on review of util 821130 & 830325 submittals Response requested by 830630 to expedite facility review
ADENSAH,E G Licensing Branch 4 83/06/01 PARRIS,H Q Tennessee Valley Authority 3pp 18844 310 24X Fiche 50-390,83/06/01,8306140287

8306080071 Forwards responses to NRC concerns re BQRT issues for facility, per 830311 telcon Further audit of safety-related electrical & mechanical equipment not warranted.
MILLS,L M Tennessee Valley Authority 83/06/03 ADENSAH,E
Licensing Branch 4 22pp 18773 193 24X Fiche 50-390,83/06/03,8306080071

8306160060 Summary of 830520 meeting w/util, Woodward-Cycle consultants & NSB in Bethesda, MD re liquefaction of soils beneath ERCW pipeline issue must be resolved to permit completion of remedial work by fuel load
MILLER,M A Licensing Branch 4 83/06/06 Licensing Branch 4 26pp 18872 323 24X Fiche 50-390,83/06/06,8306160060

8306130362 Forwards revised response to NUREG-0737, Item II.F.1, committing to install QA Co Model RD-23 high-range gas monitors by fuel load
MILLS,L M Tennessee Valley Authority 83/06/07 ADENSAH,E
Licensing Branch 4 4pp 18822 157 24X Fiche 50-390,83/06/07,8306130362

8306160533 Forwards Page 11 inadvertently omitted from encl to 830603 responses to questions from BQRT
MILLS,L M Tennessee Valley Authority 83/06/10 ADENSAH,E
Licensing Branch 4 22pp 18863 117 24X Fiche:50-390,83/06/10,8306160533

8306160725 Summary of 830324 meeting w/utills & Westinghouse in Bethesda, MD re design review panel review of new Westinghouse stress analysis on manifold fasteners for D2/D3 steam generator mod
HOPKINS, J B Licensing Branch 4 83/06/10 Licensing Branch 4 7pp 18876 277 24X Fiche 50-000,83/06/10,8306160725

8306170335 Forwards Rev A to "Thermal Capability Curves for CDNAX Electric Penetration Assemblies & Electric Conductor Seal Assemblies," inadvertently omitted from 830609 ltr
MILLS,L M Tennessee Valley Authority 83/06/10 ADENSAH,E
Licensing Branch 4 4pp 18880-084 24X Fiche 50-390,83/06/10,8306170335

8306290573 Summary of Design Review Panel 830321 meeting w/utills & Westinghouse in Bethesda, MD re D2/D3 steam generator mod & Westinghouse stress analysis of manifold fasteners.
HOPKINS, J B Licensing Branch 4 83/06/10 Licensing Branch 4 7pp 19047-085 24X Fiche 50-000,83/06/10,8306290573

8306240366 Summary of 830525 telcon w/util, NSB & Corps of Engineers re liquefaction Util proposal to construct underground barriers feasible Detailed plans requested for NRC review
MILLER,M Licensing Branch 4 83/06/22 Licensing Branch 4 3pp 18798 356 24X Fiche 50-390,83/06/22,8306240366

DOCKETED ITEMS

8306290163 Forwards evaluation re peak horizontal ground acceleration for use in soil liquefaction analyses Amplification factor of approx 2 appropriate Peak horizontal acceleration of 0.4 g should be used for analyses
NOVAK, T M Assistant Director for Licensing 83/06/22 PARRIS, H Q
Tennessee Valley Authority 7pp 17046 280 24X
Fiche 50-390, 83/06/22, 8306290163

E NRC Safety Evaluation Report (SER), suppl & correspondence

8306210217 Forwards responses to actions to resolve issues in Chapter 8 of SER & issues raised at 820701-04 site visit & drawing review
KAMMER, D B Tennessee Valley Authority 83/06/09 ADENSAH, E
Licensing Branch 4 18pp 18918 076 24X Fiche 50-390, 83/06/09, 8306210217

8306220011 Forwards updated listing showing status of each SER open & confirmatory item
MILLS, L M Tennessee Valley Authority 83/06/16 ADENSAH, E
Licensing Branch 4 11pp 18927 343 24X Fiche 50-390, 83/06/16, 8306220011

F. Security, medical, emergency & fire protection plans

8306210010 Forwards "Program Plan for Control Room Design Reviews for all TVA Nuclear Plants," in response to Generic Ltr 82-33 re upgrade of emergency plans
KAMMER, D B Tennessee Valley Authority 83/06/09 ADENSAH, E
Licensing Branch 4 3pp 18913 001 24X Fiche 50-000, 83/06/09, 8306210010

--8306210016 Procedure 862209 10, "Program Plan for Control Room Design Reviews for all TVA Nuclear Plants"
* Tennessee Valley Authority 83/06/09 200pp 18913 004 24X
Fiche 50-000, 83/06/09, 8306210016

8306200034 Responds to 830107 & 10 requests for evaluation of three unresolved insp items Chemical Engineering Branch/Fire Protection Section Fire protection issues encl Interior fire hose sys conforms to guidelines
EISENHUT, D G Division of Licensing 83/06/13 DLGHIINSKI, J A
Division of Emergency Preparedness & Materials Safety 4pp 18919 304 24X Fiche 50-390, 83/06/13, 8306200034

8306230178 Responds to NRC 830325 ltr re need for addl instrumentation in auxiliary control room for plant cooldown instrumentation meets all App R requirements
MILLS, L M Tennessee Valley Authority 83/06/17 ADENSAH, E
Licensing Branch 4 3pp 18946 361 24X Fiche 50-390, 83/06/17, 8306230178

G Inspection reports, IE Bulletins & correspondence

8306100239 Suppls 821216 response to violations noted in IE Insp Repts 50-390/82-20 & 50-391/82-20 Vendor insp of dampers requested Three addl dampers replaced Corrective actions to be completed by 830331
MILLS, L M Tennessee Valley Authority 83/01/31 O'REILLY, J P
Region 2, Office of Director 1p 18807 032 24X
Fiche 50-390, 83/01/31, 8306100239

8306140543 Confirms mgt meeting on 830421 in Chattanooga, TN to review results of first phase of annual appraisal of regulatory performance, per 830328 telcon
LEWIS, R C Division of Project & Resident Programs 83/04/12
PARRIS, H Q Tennessee Valley Authority 3pp 18834 176 24X
Fiche 50-000, 83/04/12, 8306140543

8306140562 Forwards IE Insp Repts 50-390/83-15 & 50-391/83-11 on 830321-0422 No noncompliance noted.
VERRELLI, D M Division of Project & Resident Programs 83/05/20
PARRIS, H Q Tennessee Valley Authority 2pp 18844 129 24X
Fiche 50-390, 83/05/20, 8306140562

--8306140580 IE Insp Repts 50-390/83-15 & 50-391/83-11 on 830321-0422 No noncompliance noted Major areas inspected, plant tour, operating, maint & emergency procedure insps, preoperational test procedure review & observation of structural concrete
HEATHERLY, T L, SWAN, W Region 2, Office of Director QUICK, D R
Division of Project & Resident Programs 83/05/20 18pp
18844 131, 24X Fiche 50-390, 83/05/20, 8306140580

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26, Consolidated Edison Co of New York, Inc.
125pp, 18831 043, 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8306140415 Ack receipt of 830513 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/83-08 & 50-391/83-07
LEWIS, R C Division of Project & Resident Programs 83/05/27
PARRIS, H Q Tennessee Valley Authority 1p 18830 053 24X
Fiche 50-390, 83/05/27, 8306140415

--8306140420 Responds to NRC 830414 ltr re violations noted in IE Insp Repts 50-390/83-08 & 50-391/83-07 Corrective actions loose matl removed from Unit 1 steam generators & Unit 2 generators will be inspected before secondary side closure
KAMMER, D B Tennessee Valley Authority 83/05/13 O'REILLY, J P
Region 2, Office of Director 4pp 18838 054 24X
Fiche 50-390, 83/05/27, 8306140415

--8306140425 Forwards IE Insp Repts 50-390/83-08 & 50-391/83-07 on 830223-0320 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/04/14
PARRIS, H Q Tennessee Valley Authority 2pp 18838 058 24X
Fiche 50-390, 83/05/27, 8306140415

--8306140428 Notice of violation from insp on 830223-0320
* Region 2, Office of Director 83/04/14 1p 18838 060 24X
Fiche 50-390, 83/05/27, 8306140415

--8306140434 IE Insp Repts 50-390/83-08 & 50-391/83-07 on 830223-0320 Noncompliance noted unscheduled insps during 830302-14 identified foreign matl in secondary side of steam generators
HEATHERLY, T L, SWAN, W Region 2, Office of Director QUICK, D R
Division of Project & Resident Programs 83/04/13 8pp
18838 061 24X Fiche 50-390, 83/05/27, 8306140415

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at DWRs" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8306290308 Ack receipt of 830602 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/83-12 & 50-391/83-09
VERRELLI, D M Division of Project & Resident Programs 83/06/15
PARRIS, H Q Tennessee Valley Authority 1p 19056 001 24X
Fiche 50-390, 83/06/15, 8306290308

--8306290316 Responds to NRC 830506 ltr re violations noted in IE Insp Repts 50-390/83-12 & 50-391/83-09 Corrective actions Nonconformance Rept 4798R initiated on 830420 to document concrete test cylinder 5532 testing below design strength
MILLS, L M Tennessee Valley Authority 83/06/02 O'REILLY, J P
Region 2, Office of Director 3pp 19056 002 24X
Fiche 50-390, 83/06/15, 8306290308

--8306290318 Forwards IE Insp Repts 50-390/83-12 & 50-391/83-09 on 830418-20 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 83/05/06
PARRIS, H Q Tennessee Valley Authority 2pp 19056 004 24X
Fiche 50-390, 83/06/15, 8306290308

--8306290324 Notice of violation from insp on 830418-20
* Region 2, Office of Director, 83/05/06 1p 19056 006 24X
Fiche 50-390, 83/06/15, 8306290308

DOCKETED ITEMS

287

--8306290728 IE Insp Repts 50-390/83-12 & 50-391/83-09 on 830418-20
Noncompliance noted nonconformance rept not issued for test
cylinder 5522 testing below design strength Disputes Item
1 re failure to provide certified mill test rept
HARRIS, J R , CONLON, T E Region 2, Office of Director 83/05/05
4pp 19056 007 24X Fiche 50-390, 83/06/15, 8306290308

8306290483 Approves issuance of SALP Repts 50-259/83-04, 50-260/83-04,
50-296/83-04, 50-327/83-04, 50-328/83-04, 50-390/83-07,
50-391/83-06, 50-438/83-06 & 50-439/83-06 for Jul 1981 - Dec
1982 No reply required
O'REILLY, J P Region 2, Office of Director 83/06/17 PARRIS, H O
Tennessee Valley Authority 3pp 24X Fiche 50-000, 83/06/17,
8306290483

--8306290490 Forwards SALP Repts 50-259/83-04, 50-260/83-04,
50-296/83-04, 50-327/83-04, 50-328/83-04, 50-390/83-07,
50-391/83-06, 50-438/83-06 & 50-439/83-06 for Jul 1981 - Dec
1982
LEWIS, R C Division of Project & Resident Programs 83/04/13
PARRIS, H O Tennessee Valley Authority 3pp 24X
Fiche 50-000, 83/06/17, 8306290483

--8306290503 SALP Repts 50-259/83-04, 50-260/83-04, 50-296/83-04,
50-327/83-04, 50-328/83-04, 50-390/83-07, 50-391/83-06,
50-438/83-06 & 50-439/83-06 for Jul 1981 - Dec 1982
* Region 2, Office of Director 83/04/13 92pp 24X
Fiche 50-000, 83/06/17, 8306290483

--8306290510 Comments on SALP Repts 50-259/83-04, 50-260/83-04,
50-296/83-04, 50-327/83-04, 50-328/83-04, 50-390/83-07,
50-391/83-06, 50-438/83-06 & 50-439/83-06 for Jul 1981 - Dec
1982
MILLS, L M Tennessee Valley Authority 83/05/10 O'REILLY, J P
Region 2, Office of Director 2pp 24X Fiche 50-259, 83/06/17,
8306290483

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New
York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys
Causing Inoperability of Safety-Related Equipment " Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New
York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions. "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co of New
York, Inc. 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate
Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co of New
York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

A Periodic operating reports & related correspondence

8306280612 "Environ Radioactivity Levels, Watts Bar Nuclear Plant,"
annual rept for 1982 W/830620 1tr
MILLS, L M Tennessee Valley Authority 83/05/31 DENTON, H H
Office of Nuclear Reactor Regulation, Director 46pp 19016 023
24X Fiche 50-390, 83/05/31, 8306280612

B Reportable occurrences, LERs & related correspondence

8306010113 First interim deficiency rept re nonconforming seismic
analysis of steam valve rooms Initially reported on 830502
Reanalysis performed to correct all deficiencies in
original analysis Next rept by 830923
MILLS, L M Tennessee Valley Authority 83/05/24 O'REILLY, J P
Region 2, Office of Director 2pp 18673 340 24X
Fiche 50-390, 83/05/24, 8306010113

8306010136 Fourth interim deficiency rept re failure to evaluate
operator actions to realign ERCW Train A Initially reported
on 820510 Analysis continuing Next rept will be submitted by
831003
MILLS, L M Tennessee Valley Authority 83/05/24 O'REILLY, J P
Region 2, Office of Director 1p 18674 041 24X
Fiche 50-390, 83/05/24, 8306010136

8306010143 Supplemental info to deficiency rept re failure to inspect
stud welds on flush-mounted embedded plates Initially
reported on 820812 Completion date of 830513 for corrective
actions not met Work will be completed by 830729
MILLS, L M Tennessee Valley Authority 83/05/24 O'REILLY, J P
Region 2, Office of Director 1p 18674 045 24X
Fiche 50-390, 83/05/24, 8306010143

8306010283 First interim deficiency rept re Westinghouse pump motors
supplied w/o seismic analysis or operability demonstrated
Initially reported on 830428 Investigation continuing Next
rept will be submitted by 830829
MILLS, L M Tennessee Valley Authority 83/05/24 O'REILLY, J P
Region 2, Office of Director 2pp 18672 340 24X
Fiche 50-390, 83/05/24, 8306010283

8306070072 Fifth interim deficiency rept re engineering change notice
review & handling Initially reported on 811215 Personnel
retrained & corrective actions presented to Ofc of QA for
approval Addl info will be submitted by 830722
MILLS, L M Tennessee Valley Authority 83/05/24 O'REILLY, J P
Region 2, Office of Director 2pp 18740 085 24X
Fiche 50-000, 83/05/24, 8306070072

8306010274 Third interim deficiency rept re sheared motor pinion keys
in Limitorque motor operators Initially reported on 820830
Field change notices issued to replace keys Next rept will
be sent by 830922 Also reportable per Part 21
MILLS, L M Tennessee Valley Authority 83/05/25 O'REILLY, J P
Region 2, Office of Director 2pp 18674 322 24X
Fiche 50-000, 83/05/25, 8306010274

8306010431 Second interim deficiency rept re corrosion in high pressure
fire protection sys Initially reported on 820903 Sys
contains carbon steel piping Corrosion analyses in progress
Next rept to be submitted by 821004
MILLS, L M Tennessee Valley Authority 83/05/25 O'REILLY, J P
Region 2, Office of Director 2pp 18674 255 24X
Fiche 50-000, 83/05/25, 8306010431

8306070064 Seventh interim deficiency rept re qualification of epoxy
grout for safety-related applications Initially reported on
10827 Design Criteria DB-1 7 i, "General Anchorage to
Concrete," & drawing for support mods being revised
MILLS, L M Tennessee Valley Authority 83/05/26 O'REILLY, J P
Region 2, Office of Director 1p 18740 099 24X
Fiche 50-390, 83/05/26, 8306070064

8306070074 First interim deficiency rept re incorrect max pipe
movements contained in TPIPE program Initially reported on
830504 W/o encl Next rept expected by 830922
MILLS, L M Tennessee Valley Authority 83/05/26 O'REILLY, J P
Region 2, Office of Director 1p 18739 319 24X
Fiche 50-000, 83/05/26, 8306070074

8306070048 Final deficiency rept re potentially overstressed embedded
plates Initially reported on 820412 Interim spacing
requirements implemented to control spacing of future
attachments to embedded plates
MILLS, L M Tennessee Valley Authority 83/05/27 O'REILLY, J P
Region 2, Office of Director 2pp 18739 341 24X
Fiche 50-390, 83/05/27, 8306070048

8306070138 Third interim deficiency rept re voiding of engineering
change notices w/o proper review Initially reported on
820816 Change notices being reviewed & unresolved safety
question determination Performed Next rept by 830923
MILLS, L M Tennessee Valley Authority 83/05/31 O'REILLY, J P
Region 2, Office of Director 2pp 18739 264 24X
Fiche 50-000, 83/05/31, 8306070138

8306090322 Final deficiency rept re faulty fillet welds Initially
reported on 800220 Listed ASME Code welds reinspected &
marked for tracking Clarified insp criteria & mechanical
aids (fillet gauges) used in routine visual insp
MILLS, L M Tennessee Valley Authority 83/06/01 O'REILLY, J P
Region 2, Office of Director 4pp 18795 115 24X
Fiche 50-390, 83/06/01, 8306090322

8306090135 Second interim deficiency rept re Henry Pratt butterfly
valve Initially reported on 821109 Valve air-operator yoke
mod kits delivered & mod in progress Operators removed &
returned to OH Bettis Co Also reported per Part 21
MILLS, L M Tennessee Valley Authority 83/06/02 O'REILLY, J P
Region 2, Office of Director 1p 18795 297 24X
Fiche 50-000, 83/06/02, 8306090135

8306090142 Final deficiency rept re control bldg isolation dampers
leaking Initially reported on 830504 New leaktight butterfly
valves received & installed Const drawings revised to
indicate new valves.
MILLS, L M Tennessee Valley Authority 83/06/02 O'REILLY, J P
Region 2, Office of Director 2pp 18795 293 24X
Fiche 50-390, 83/06/02, 8306090142

DOCKETED ITEMS

8306140446 Revised final deficiency rept re auxiliary power sys Initially reported on 830925 EGN 2786 issued to modify transmission grid-auxiliary power sys interface to ensure adequate offsite power to safety-related buses MILLS, L M Tennessee Valley Authority 83/06/03 O'REILLY, J P Region 2, Office of Director 2pp 18034 313 24X Fiche 50-390, 83/06/03, 8306140446

8306140435 First interim deficiency rept re DB-16 reactor trip breaker design error identified by Westinghouse Initially reported on 830505 Undervoltage attachments will be replaced Next rept by 830926 Also reported per Part 21 MILLS, L M Tennessee Valley Authority 83/06/06 O'REILLY, J P Region 2, Office of Director 2pp 18038 035 24X Fiche 50-390, 83/06/06, 8306140435

8306200169 Final deficiency rept re fire dampers improperly installed & damaged. Initially reported on 830505 Damage caused by improper handling & installation by const craft due to inadequate QC. New dampers purchased MILLS, L M Tennessee Valley Authority 83/06/07 O'REILLY, J P Region 2, Office of Director 2pp 18702 360 24X Fiche 50-390, 83/06/07, 8306200169

8306200145 First interim deficiency rept re Meriam Instrument failure to implement QA program Initially reported on 830510 Investigation underway Next rept to be submitted by 830922 MILLS, L M Tennessee Valley Authority 83/06/09 O'REILLY, J P Region 2, Office of Director 2pp 18703 124 24X Fiche 50-390, 83/06/09, 8306200145

8306210051 Supplemental interim deficiency rept re potentially overstressed embedded plates Initially reported on 830412 Next submittal scheduled for 840217 Instead of 830622 as originally stated MILLS, L M Tennessee Valley Authority 83/06/10 O'REILLY, J P Region 2, Office of Director 1p 18914 009 24X Fiche 50-000, 83/06/10, 8306210051

8306210088 Final deficiency rept re failure to shut down redundant auxiliary bldg exhaust fans upon secondary containment isolation signal Initially reported on 830505 Engineering Change Notice EGN 3011 issued & logic drawings revised MILLS, L M Tennessee Valley Authority 83/06/10 O'REILLY, J P Region 2, Office of Director 2pp 18719 188 24X Fiche 50-390, 83/06/10, 8306210088

8306210150 Final deficiency rept for Unit 1 & sixth interim deficiency rept for Unit 2 re loading criteria for structural steel & supports. Initially reported on 811117 Ongoing training programs in engineering procedures will resolve problems MILLS, L M Tennessee Valley Authority 83/06/13 O'REILLY, J P Region 2, Office of Director 2pp 18916 028 24X Fiche 50-390, 83/06/13, 8306210150

8306210039 First interim deficiency rept re lack of isolation capability for post-accident sampling facility air intakes Initially reported on 830517 Safety-grade redundant isolation valves to be installed. Next rept by 830922 MILLS, L M Tennessee Valley Authority 83/06/15 O'REILLY, J P Region 2, Office of Director 2pp 18712 337 24X Fiche 50-390, 83/06/15, 8306210039

8306210087 First interim deficiency rept re containment isolation valves installed in chilled water sys not designed to be leaktight. Initially reported on 830517 Engineering Change Notice 3861 & 3864 initiated. Next rept by 830913 MILLS, L M Tennessee Valley Authority 83/06/15 O'REILLY, J P Region 2, Office of Director 2pp 18914 134 24X Fiche 50-390, 83/06/15, 8306210087

8306210116 Final deficiency rept re solid state protection sys test procedures. Initially reported on 820831 Procedural change initiating use of test probe w/indicator lamp connected to ground implemented Also reportable under Part 21 MILLS, L M Tennessee Valley Authority 83/06/15 O'REILLY, J P Region 2, Office of Director 2pp 18714 098 24X Fiche 50-390, 83/06/15, 8306210116

8306270354 Fifth interim deficiency rept re frequency criteria for piping supports Initially reported on 820713 Subsections B 2 & C 2 of 48-DC-40-31, 7 revised to provide clarification. Next rept by 830921 MILLS, L M Tennessee Valley Authority 83/06/16 O'REILLY, J P Region 2, Office of Director 2pp 18796 226 24X Fiche 50-390, 83/06/16, 8306270354

8306280426 Supplemental deficiency rept re post-accident readings from containment sump level transmitters. Initially reported on 820708 Fuel load date rescheduled to Jan 1984 Also reportable per Part 21 MILLS, L M Tennessee Valley Authority 83/06/17 O'REILLY, J P Region 2, Office of Director 1p 19018 350 24X Fiche 50-390, 83/06/17, 8306280426

8306280578 Interim deficiency rept re resolution of listed items due for submittal in late June Corrective actions in progress List identifying each item scheduled for next submittal & level of interim rept encl MILLS, L M Tennessee Valley Authority 83/06/17 O'REILLY, J P Region 2, Office of Director 2pp 19018 193 24X Fiche 50-000, 83/06/17, 8306280578

8306280573 Second interim deficiency rept re Westinghouse gate valve position indicatinn problems Initially reported on 830203 Field change notices prepared to correct closure indication problems Next rept will be submitted by 830928 MILLS, L M Tennessee Valley Authority 83/06/20 O'REILLY, J P Region 2, Office of Director 2pp 19017 320 24X Fiche 50-390, 83/06/20, 8306280573

8306300013 Supplemental final deficiency rept re containment penetration protection Initially reported on 811207 Deficiency expanded to cover Unit 2 on 820730 Correct completion date for Unit 2 is 840815 MILLS, L M Tennessee Valley Authority 83/06/21 O'REILLY, J P Region 2, Office of Director 2pp 19120 354 24X Fiche 50-390, 83/06/21, 8306300013

8306300028 Sixth interim deficiency rept re foam seals in mechanical pipe sleeves Initially reported on 811204 Design std providing requirements & procedures to sleeve designers in final review Next rept by 830928 MILLS, L M Tennessee Valley Authority 83/06/21 O'REILLY, J P Region 2, Office of Director 1p 19120 305 24X Fiche 50-390, 83/06/21, 8306300028

8306300205 Final deficiency rept re rerouting high-pressure fire protection piping w/o proper analyses Initially reported on 830130 Based on head/flow tests on calculated worst case fire, condition determined not reportable per 10CFR50 55(a) MILLS, L M Tennessee Valley Authority 83/06/21 O'REILLY, J P Region 2, Office of Director 2pp 19122 121 24X Fiche 50-390, 83/06/21, 8306300205

8306300051 Sixth interim deficiency rept re failure of limit torque motor operators during valve closure Initially reported on 820126 Westinghouse & Limit torque determining cause of failures Next rept expected by 830928 Also reportable per Part 21 MILLS, L M Tennessee Valley Authority 83/06/22 O'REILLY, J P Region 2, Office of Director 2pp 19120 193 24X Fiche 50-390, 83/06/22, 8306300051

8306300054 Final deficiency rept re piping sys analysis tracking Initially reported on 820902 Engineering Procedures C 03 & 4 25 revised to correct problem of tracking closure of engineering change notices prior to Class 1 analysis MILLS, L M Tennessee Valley Authority 83/06/22 O'REILLY, J P Region 2, Office of Director 2pp 19120 290 24X Fiche 50-390, 83/06/22, 8306300054

8306300214 Second interim deficiency rept re tubeline matls supplied by Capital Pipe & Steel not mfg under QA program Initially reported on 830329 Contractor will perform dimensional checks for pipes & fittings Next rept by 830922 MILLS, L M Tennessee Valley Authority 83/06/23 O'REILLY, J P Region 2, Office of Director 2pp 19119 391 24X Fiche 50-000, 83/06/23, 8306300214

8306300228 Second interim deficiency rept re postulated accident blowdown of more than one steam generator Initially reported on 821128 Westinghouse analysis indicated no core damage will occur for postulated event Next rept by 830928 MILLS, L M Tennessee Valley Authority 83/06/23 O'REILLY, J P Region 2, Office of Director 2pp 19119 180 24X Fiche 50-390, 83/06/23, 8306300228

8306300033 Second interim deficiency rept re spacing & clearance in auxiliary bldg high-pressure fire protection sprinkler sys Initially reported on 830331 Review of installation configuration incomplete Next rept by 831005 MILLS, L M Tennessee Valley Authority 83/06/24 O'REILLY, J P Region 2, Office of Director 2pp 19120 308 24X Fiche 50-390, 83/06/24, 8306300033

8306300082 Fourth interim deficiency rept re concrete anchorage free edge violation Initially reported on 830528 Redesign w/or rework will be required on 99 of 477 supports Next rept by 830919 MILLS, L M Tennessee Valley Authority 83/06/24 O'REILLY, J P Region 2, Office of Director 2pp 19048 332 24X Fiche 50-390, 83/06/24, 8306300082

DOCKETED ITEMS

269

DOCKET 50-394 CALIFORNIA STATE POLYTECH COLLEGE RES REACTOR

Q Inspection reports, IE Bulletins & correspondence

8303110460 IE Info Notice 83-34, "Event Notification Info Worksheet"
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Past 830103) 83/05/26 Consolidated Edison Co of New
York, Inc 118pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

DOCKET 50-395 VIRGIL C SUMMER NUCLEAR STATION, UNIT 1

P Operating license stage documents & correspondence

8306010325 Forwards Rev 2 to "Inservice Insp Program, First Interval,"
Rev 5 to "General Test Procedure for Inservice Testing of
Pumps" & Rev 5 to "General Test Procedure for Inservice
Testing of Valves"
DIXON, D W South Carolina Electric & Gas Co 83/05/23 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 18681 053
24X Fiche 50-395, 83/05/23, 8306010325

--8306010366 Rev 5 to QTP-001, "General Test Procedure for Inservice
Testing of Pumps"
* South Carolina Electric & Gas Co 83/04/14 34pp. 18681 065
24X Fiche 50-395, 83/05/23, 8306010325

--8306010374 Rev 5 to QTP-002, "General Test Procedure for Inservice
Testing of Valves"
TURKETT, J South Carolina Electric & Gas Co 83/04/28 177pp
18681 099 24X Fiche 50-395, 83/05/23, 8306010325

8306020661 Notification of 830526 meeting w/util in Bethesda, MD to
discuss reactor trip breakers
HOPKINS, J B Licensing Branch 4 83/05/25 ADENSAH, E G Licensing
Branch 4 2pp 18716 254 24X Fiche 50-395, 83/05/25, 8306020661

8306020385 Forwards addl fee for 830413 Class III amend, in response to
NRC 830524 request
DIXON, D W South Carolina Electric & Gas Co 83/05/31 DICKS, R M
License Fee Management Branch 1p 18694 360 24X
Fiche 50-395, 83/05/31, 8306020385

8306070402 Withdraws requests for changes to Tech Spec Sections
3 4 9 3.3 2 3 & Table 3 3-3, requested in 821010 & 830215
ltr
DIXON, D W South Carolina Electric & Gas Co 83/06/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 18742 280
24X Fiche 50-395, 83/06/03, 8306070402

8306130417 Confirms agreements reached at 830526 meeting re issuance
of SER for reactor trip breaker issue Maint procedures will
include check of dimensional tolerance of pre- & post-travel
of trip tabs
DIXON, D W South Carolina Electric & Gas Co 83/06/08 DENTON, H R
Office of Nuclear Reactor Regulation, Director 4pp 18823 138
24X Fiche 50-395, 83/06/08, 8306130417

8306160299 Summary of 830428 meeting w/util, Dames & Moore, Etec, USOB,
Gilbert Assoc & URB/Blume in Bethesda, MD re seismic
confirmatory program
HOPKINS, J B Licensing Branch 4 83/06/10 Licensing Branch 4
3pp 18893 026 24X Fiche 50-395, 83/06/10, 8306160299

8306160725 Summary of 830324 meeting w/util & Westinghouse in
Bethesda, MD re design review panel review of new
Westinghouse stress analysis on manifold fasteners for
B2/D3 steam generator mod.
HOPKINS, J B Licensing Branch 4 83/06/10 Licensing Branch 4
7pp 18876 277 24X Fiche 50-000, 83/06/10, 8306160725

8306290573 Summary of Design Review Panel 830321 meeting w/util &
Westinghouse in Bethesda, MD re B2/D3 steam generator mod &
Westinghouse stress analysis of manifold fasteners
HOPKINS, J B Licensing Branch 4 83/06/10 Licensing Branch 4
7pp 19047 085 24X Fiche 50-000, 83/06/10, 8306290573

8306230521 Advises that mod of Model B2/D3 steam generators acceptable
& modified steam generators can be operated at 100% of
design capacity w/mod in place
DIRCKS, W J Office of the Executive Director for Operations.
83/06/14 PALLADINO, N J, OILINSKY, V, AHEARNE, J Commissioners
3pp 18951 357 24X Fiche 50-395, 83/06/14, 8306230521

8306230086 Requests written concurrence that load swing/load rejection
tests intended for normal plant operations & that transient
conditions initiated by util to complete Phase III test
program do not violate License Condition 2 C(22)
DIXON, D W South Carolina Electric & Gas Co 83/06/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 18947 072,
24X Fiche 50-395, 83/06/20, 8306230086

8306240351 Summary of 830526 meeting w/util & Westinghouse in Bethesda,
MD re Westinghouse Model DS-416 reactor trip breakers Tech
Spec interpretation & meaning of preserving evidence of
failure will be examined
HOPKINS, J B Licensing Branch 4 83/06/21 Licensing Branch 4
4pp 18999 163 24X Fiche 50-395, 83/06/21, 8306240351

8306270356 Forwards responses to NRC questions discussed at 830428
meeting re seismic confirmatory program Equipment margin
analysis for safe shutdown equipment for ACRS response
spectrum scheduled after first refueling outage
DIXON, D W South Carolina Electric & Gas Co 83/06/22 DENTON, H R
Office of Nuclear Reactor Regulation, Director 123pp 18994 155,
24X Fiche 50-395, 83/06/22, 8306270356

Q Inspection reports, IE Bulletins & correspondence

8306140637 Confirms mgt meeting on 830527 at plant site to review
results of annual appraisal of regulatory performance, per
830511 telcon
LEWIS, R C Division of Project & Resident Programs 83/05/20
DIXON, D W South Carolina Electric & Gas Co 2pp. 18843 040 24X
Fiche 50-395, 83/05/20, 8306140637

8306010325 Forwards Rev 2 to "Inservice Insp Program, First Interval,"
Rev 5 to "General Test Procedure for Inservice Testing of
Pumps" & Rev 5 to "General Test Procedure for Inservice
Testing of Valves"
DIXON, D W South Carolina Electric & Gas Co 83/05/23 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 18681 053
24X Fiche 50-395, 83/05/23, 8306010325

--8306010357 Rev 2 to "Inservice Insp Program, First Interval"
TURKETT, J, QUINTON, M D, MOORE, D R South Carolina Electric & Gas
Co 83/05/19 9pp 18681 056 24X Fiche 50-395, 83/05/23,
8306010325

--8306010366 Rev 5 to QTP-001, "General Test Procedure for Inservice
Testing of Pumps"
* South Carolina Electric & Gas Co 83/04/14 34pp 18681 065
24X Fiche 50-395, 83/05/23, 8306010325

--8306010374 Rev 5 to QTP-002, "General Test Procedure for Inservice
Testing of Valves"
TURKETT, J South Carolina Electric & Gas Co. 83/04/28 177pp.
18681 099 24X Fiche 50-395, 83/05/23, 8306010325

8306140452 Ack receipt of 830511 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-395/83-08.
LEWIS, R C Division of Project & Resident Programs. 83/05/25
DIXON, D W South Carolina Electric & Gas Co. 1p. 18834 267 24X
Fiche 50-395, 83/05/25, 8306140452

--8306140457 Responds to NRC 830413 ltr re violations noted in IE Insp
Rept 50-395/83-08 Corrective actions meeting held w/QA staff
to emphasize importance of timely issuance of audit reports &
Procedure III A & employee reading list revised.
DIXON, D W South Carolina Electric & Gas Co 83/05/11
O'REILLY, J P Region 2, Office of Director. 7pp 18834 268 24X
Fiche 50-395, 83/05/25, 8306140452

--8306140461 Forwards IE Insp Rept 50-395/83-08 on 830307-11 & notice
of violation
LEWIS, R C Division of Project & Resident Programs. 83/04/13
DIXON, D W South Carolina Electric & Gas Co 2pp. 18834 275,
24X Fiche 50-395, 83/05/25, 8306140452

--8306140465 Notice of violation from insp on 830307-11.
* Region 2, Office of Director. 83/04/13 3pp 18834 277 24X
Fiche 50-395, 83/05/25, 8306140452

--8306140471 IE Insp Rept 50-395/83-08 on 830307-11 Noncompliance noted,
failure to issue audits within Tech Spec time limits,
to respond to audit findings, to meet all operator training
requirements of 10CFR55, App A & to perform required reading,
BELISLE, O A, DEBBAGE, A P, FOSTER, L E Region 2, Office of
Director. 83/04/06 31pp 18834 280 24X Fiche 50-395, 83/05/25,
8306140452

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in
Well Logging Device" Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Past
830103). 83/05/26, Consolidated Edison Co of New York, Inc
123pp 18831 043. 24X Fiche 50-000, 83/05/26, 8305110458.

DOCKETED ITEMS

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8306140045 Confirms 830607 enforcement meeting at Region II ofc to discuss 830523 startup w/safety-related instrument tagged in isolated condition & other recent events. Agenda encl
LEWIS, R C Division of Project & Resident Programs 83/05/27
DIXON, O W South Carolina Electric & Gas Co 3pp 18838 248 24X
Fiche 50-395, 83/05/27, 8306140045

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306140382 Ack receipt of 830520 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-395/83-01
LEWIS, R C Division of Project & Resident Programs 83/06/01
DIXON, O W South Carolina Electric & Gas Co. 1p 18832 073 24X
Fiche 50-395, 83/06/01, 8306140382

--8306140388 Suppls response to NRC 830301 ltr re violations noted in IE Insp Rept 50-395/83-01 Corrective actions, training sessions in methods of tripping logic bistables in Westinghouse 7300 process cabinets held on 830317 & 0407
DIXON, O W South Carolina Electric & Gas Co 83/05/20
O'REILLY, J P Region 2, Office of Director 2pp 18832 074 24X
Fiche 50-395, 83/06/01, 8306140388

8306220221 Denies 830127 request for exemption from ASME Code Section XI, Subarticle IWA-1400(f), requirements for first interval of inservice insp program Facility personnel cannot provide same insp assurance as authorized insp agency
NOVAK, T M Assistant Director for Licensing 83/06/08 DIXON, O W South Carolina Electric & Gas Co 3pp 18977 360 24X
Fiche 50-395, 83/06/08, 8306220221

8306290088 Responds to IE Bulletin 83-03 re pump & valve inservice insp program Two check valves applicable BTP-123 003 will be revised to include reverse flow test by 830731 Refueling outage presently scheduled for Oct 1984
DIXON, O W South Carolina Electric & Gas Co 83/06/08
O'REILLY, J P Region 2, Office of Director 2pp 17056 209 24X
Fiche 50-395, 83/06/08, 8306290088

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 117pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8306140487 Forwards IE Enforcement Conference Rept 50-395/83-21 on 830607, concerns re recent violations of regulatory requirements expressed
O'REILLY, J P Region 2, Office of Director 83/06/09 DIXON, O W South Carolina Electric & Gas Co 2pp 18843 069 24X
Fiche 50-395, 83/06/09, 8306140487

--8306140492 IE Enforcement Conference Rept 50-395/83-21 on 830607 Major areas discussed: several recent violations of regulatory requirements, licensees discussed root cause & corrective actions taken or planned to ensure proper plant operation
VERRELLI, D M Division of Project & Resident Programs 83/06/09 3pp 18843: 071 24X Fiche 50-395, 83/06/09, 8306140492

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Electrically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 228 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
AN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

83-40, "Need to Environmentally Qualify " Svc list encl
Division of Emergency Preparedness & Engineering
83/06/22 Consolidated Edison Co of New York, Inc 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18977 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18976 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

R Periodic operating reports & related correspondence

8306020142 Monthly operating rept for Mar 1983 W/830412 ltr
TAYLOR, G J, DIXON, O W South Carolina Electric & Gas Co 83/04/11
BARRY, L W Office of Resource Management, Director 5pp 18691 233 24X Fiche 50-395, 83/04/11, 8306020142

8306160570 Monthly operating rept for Apr 1983 W/830505 ltr
TAYLOR, G J, DIXON, O W South Carolina Electric & Gas Co 83/05/07
BARRY, L W Office of Resource Management, Director 5pp 18866 285 24X Fiche 50-395, 83/05/07, 8306160570

S Reportable occurrences, LERs & related correspondence

8306140670 Final deficiency rept re frozen safety-related snubbers identified per IE Bulletin 81-01 insp Initially reported on 820622 Caused by improper installation, overloading & mishandling Handling procedures will be revised
DIXON, O W South Carolina Electric & Gas Co 83/04/22
O'REILLY, J P Region 2, Office of Director 4pp 18842 079 24X
Fiche 50-395, 83/04/22, 8306140670

8306070202 LER 83-037/03L-0 on 830503, emergency feedwater valve IPV-3556-EF failed to remain closed for 3 h Caused by air leak around valve positioner basket Positioner cover tightened down & valve tested satisfactorily W/830526 ltr
BOURNIGHT, R J, DIXON, O W South Carolina Electric & Gas Co 83/05/26
O'REILLY, J P Region 2, Office of Director 3pp 18747 017 24X Fiche 50-395, 83/05/26, 8306070202

8306070128 Followup RO on 830307, plant outage initiated to perform required steam generator D-3 mods & mods requiring fire barrier removal One-hour fire watch established for affected areas during outage List of affected areas encl
DIXON, O W South Carolina Electric & Gas Co 83/05/27
O'REILLY, J P Region 2, Office of Director 3pp 18739 316 24X
Fiche 50-395, 83/05/27, 8306070128

8306100142 Updated LER 83-034/03L-J on 830409, RHR pump B motor termination box cover found partially burned Caused by cable weight forcing B phase terminal lug against cover
Termination retaped & procedures revised W/830602 ltr
MCKINNEY, C J, DIXON, O W South Carolina Electric & Gas Co 83/06/02
O'REILLY, J P Region 2, Office of Director 4pp 18801 205 24X Fiche 50-395, 83/06/02, 8306100142

8306100213 LER 83-042/01T-0 on 830519, steam leak activated smoke detector, tripping open intermediate bldg preaction sprinkler sys deluge valve, Caused by personnel error & lack of sys knowledge Deluge valve reset W/830502 ltr
MCKINNEY, C J, DIXON, O W South Carolina Electric & Gas Co 83/06/02
O'REILLY, J P Region 2, Office of Director 5pp 18805 197 24X Fiche 50-395, 83/06/02, 8306100213

8306100163 LER 83-041/01T-0 on 830520, plant entered Mode 3 w/train D of heat tracing associated w/boron injection tank flow path deenergized Caused by personnel error & inadequate procedure Panel energized W/830603 ltr
BOURNIGHT, R J, DIXON, O W South Carolina Electric & Gas Co 83/06/03
O'REILLY, J P Region 2, Office of Director 5pp 18807 232 24X Fiche 50-395, 83/06/03, 8306100163

8306100208 LER 83-043/03L-0 on 830506, while in Mode 5, operations personnel stepped through Haronite board fire barrier, Caused by personnel error Fire watch established Area posted Barrier repaired W/830603 ltr
FIELD, H C, DIXON, O W South Carolina Electric & Gas Co 83/06/03
O'REILLY, J P Region 2, Office of Director 2pp 18806 005 24X
Fiche 50-395, 83/06/03, 8306100208

8306100261 LER 83-040/03L-0 on 830506, control room emergency ventilation sys trains A & B inoperable for 26 h Caused by failure in implementing procedural controls Personnel counseled W/830603 ltr
BOUKNIGHT, R J, DIXON, D W South Carolina Electric & Gas Co
83/06/03 O'REILLY, J P Region 2, Office of Director 3pp
18807 035 24X Fiche 50-395, 83/06/03, 8306100261

8306140088 LER 83-044/01T-0 on 830523, steam generator B feedwater flow transmitter FT-486 did not respond to change in feedwater flow Caused by personnel error in not properly identifying transmitter on tagout sheet W/830606 ltr
MCKINNEY, C J, DIXON, D W South Carolina Electric & Gas Co
83/06/06 O'REILLY, J P Region 2, Office of Director App
18839 003 24X Fiche 50-395, 83/06/06, 8306140088

8306210021 LER 83-046/03L-0 on 830520, sampling line from pressurizer valve VXX-9337-B8 indicated intermediate position Caused by out of adjustment limit switches on valve Switches adjusted W/830610 ltr
BOUKNIGHT, R J, DIXON, D W South Carolina Electric & Gas Co
83/06/10 O'REILLY, J P Region 2, Office of Director 2pp
18910 357 24X Fiche 50-395, 83/06/10, 8306210021

8306210209 LER 83-045/01T-0 on 830531, speed control (SC-2034A) for turbine driven emergency feedwater pump on main control board found in slow speed position Caused by operator error & procedure deficiencies W/830610 ltr
BOUKNIGHT, R J, DIXON, D W South Carolina Electric & Gas Co
83/06/10 O'REILLY, J P Region 2, Office of Director App
18918 127 24X Fiche 50-395, 83/06/10, 8306210209

8306280067 LER 83-047/03L-0 on 830517, w/plant in Mode 4, turbine bldg sump radiation monitor (RM-LB) removed from svc because of inadequate sample pump flow Caused by sludge buildup Pump disassembled & cleaned W/830615 ltr
MCKINNEY, C J, DIXON, D W South Carolina Electric & Gas Co
83/06/15 O'REILLY, J P Region 2, Office of Director 3pp
19001 177 24X Fiche 50-395, 83/06/15, 8306280067

8306280504 LER 83-048/03L-0 on 830517, w/plant in Mode 4, Zone 4 of fire svc sys locked in "trouble alarm" status Caused by water damage to two modules located in preaction sprinkler panel XPN-091 Engineering evaluation requested W/830615 ltr
KOLB, L E, DIXON, D W South Carolina Electric & Gas Co
83/06/15 O'REILLY, J P Region 2, Office of Director 3pp
19018 353 24X Fiche 50-395, 83/06/15, 8306280504

8306270136 LER 83-050/03L-1 on 830520 & 22, sump pump XPP-13B lost prime & became incapable of pumping water, rendering reactor bldg sump leakage detection sys inoperable Caused by vapor lock Pump primed Air vent valve will be installed W/830616 ltr
MCKINNEY, C J, DIXON, D W South Carolina Electric & Gas Co
83/06/16 O'REILLY, J P Region 2, Office of Director 3pp
18998 149 24X Fiche 50-395, 83/06/16, 8306270136

8306270289 Part 21 rept re heat sink adhesive bond failures & NTC cord relay problems within Westinghouse 7300 process sys Investigation underway to determine number of cards requiring heat sink replacement
DIXON, D W South Carolina Electric & Gas Co
83/06/17 O'REILLY, J P Region 2, Office of Director App
18996 170 24X Fiche 50-395, 83/06/17, 8306270289

8306300122 RD on 830608, main plant vent radiation monitor RM-A13 declared inoperable when channel indicated high radiation Caused by loose cover on reed switch housing of preamplifier circuit board interfering w/electronic components
DIXON, D W South Carolina Electric & Gas Co
83/06/20 O'REILLY, J P Region 2, Office of Director 3pp
19121 078 24X Fiche 50-395, 83/06/20, 8306300122

8306300156 LER 83-049/03L-0 on 830606, svc water booster pump A discharge check valve, XVC-3135A-BW declared inoperable due to failure to close on reverse flow Caused by worn linkage Hinge & key replaced & valve disk lapped W/830620 ltr
BOUKNIGHT, R J, DIXON, D W South Carolina Electric & Gas Co
83/06/20 O'REILLY, J P Region 2, Office of Director 3pp
19048 353 24X Fiche 50-395, 83/06/20, 8306300156

8306300018 Final Part 21 evaluation rept re potential failure of Brown Boveri Model HPL-C speed switches for component cooling pump & svc water pump motors Initially reported on 830524. Failed motor replaced & defective motors repaired
DIXON, D W South Carolina Electric & Gas Co
83/06/24 O'REILLY, J P Region 2, Office of Director 3pp
19120 234 24X Fiche 50-395, 83/06/24, 8306300018

8306300047 LER 83-053/03L-0 on 830528, reactor vessel upper plenum level indicator ILI-1320 on main control board removed from svc due to high reading Caused by instrument drift Programmable function generator recalibr W/830624 ltr
KOLB, L E, DIXON, D W South Carolina Electric & Gas Co
83/06/24 O'REILLY, J P Region 2, Office of Director 3pp
19120, 195 24X Fiche 50-395, 83/06/24, 8306300047

8306300196 LER 83-052/03L-0 on 830528, main control board indication for steam generator B steam pressure failed high Caused by broken wires on transmitter PT-486 strain gage assembly Assembly replaced PT-486 calibr W/830624 ltr
MCKINNEY, C J, DIXON, D W South Carolina Electric & Gas Co
83/06/24 O'REILLY, J P Region 2, Office of Director 3pp
19122 180 24X Fiche 50-395, 83/06/24, 8306300196

V Operator Examinations

8306140135 Requests approved ref matl re operator exams by 830228 Missing deadline will result in delay in administering exams Applications should be submitted at least 60 days prior to first exam scheduled for wk of 830411
DANCE, H C Division of Project & Resident Programs
83/01/28 DIXON, D W South Carolina Electric & Gas Co App
18839 131 24X Fiche 50-395, 83/01/28, 8306140135

DOCKET 50-396 UNIV OF VIRGINIA CAVALIER REACTOR

F Security, medical, emergency & fire protection plans

8306220228 Forwards request for addl info re Univ of VA research reactor 820827 emergency plan to continue review per 10CFR50, App E, Reg Guide 2.6, Rev 1 & ANSI/ANS-15.16-1982 requirements Info requested within 30 days of ltr date
THOMAS, C O Standardization & Special Projects Branch
83/06/10 BRENNER, J S Virginia, Univ of, Charlottesville, VA 5pp
18977 355 24X Fiche 50-062, 83/06/10, 8306220228

DOCKET 50-397 WPPSS NUCLEAR PROJECT, UNIT 2

A Application/construction stage documents & correspondence

8306010236 Clarifies responses to NUREG-0612, "Control of Heavy Loads" Turbine Crane MT-CRA-1 meets guidelines of NUREG
BOUCHEY, O D Washington Public Power Supply System
83/04/13 SCHWENGER, A Licensing Branch 2 1p
18673 001 24X Fiche 50-397, 83/04/13, 8306010236

8306010413 Forwards descriptions of responsibilities of nuclear safety assurance group, in confirmation of 830209 meeting Encl provides revised response to TMI Items I B 1 2 & I C 5
BOUCHEY, O D Washington Public Power Supply System
83/04/15 SCHWENGER, A Licensing Branch 2 6pp
18674 244 24X Fiche 50-397, 83/04/15, 8306010413

8306010249 Advises that Tech Spec 3/4 10.1, "Primary Containment Integrity," will be limiting condition for operation during primary containment integrated leak rate preoperational & startup testing program
BOUCHEY, O D Washington Public Power Supply System
83/05/16 SCHWENGER, A Licensing Branch 2 2pp
18672 296 24X Fiche 50-397, 83/05/16, 8306010249

8306030020 Forwards "Control of Heavy Loads at Nuclear Power Plants, Washington Nuclear Project 2 (Phase II - Interim)," technical evaluation rept
SCHWENGER, A Licensing Branch 2
83/05/24 FERGUSON, R L Washington Public Power Supply System 2pp
18733 146 24X Fiche 50-397, 83/05/24, 8306030020

--8306030088 "Control of Heavy Loads at Nuclear Power Plants, Washington Nuclear Project 2 (Phase II - Interim)," draft technical evaluation rept.
DIXON, B W, STICKLEY, T H EQ&O, Inc
FIN A-6457
83/05/24 NRC - No Detailed Affiliation Given 20pp
18733 148 24X Fiche 50-397, 83/05/24, 8306030088

8306070481 Notification of 830607 meeting w/util in Bethesda, MD to discuss radiological Tech Specs.
AULUCK, R Licensing Branch 2
83/05/31 SCHWENGER, A Licensing Branch 2 3pp
18776 335 24X Fiche 50-397, 83/05/31, 8306070481

8306080039 Forwards addl info re containment out-of-roundness, per 830419 telcon request, AE evaluation concluded that localized reductions in structural & shielding capacity of biological shield wall insignificant.
BOUCHEY, O D Washington Public Power Supply System
83/06/01, SCHWENGER, A Licensing Branch 2 5pp
18773 078 24X Fiche 50-397, 83/06/01, 8306080039

8306070030 Notification of 830607 significant licensee meeting w/util at Region V ofc to review program status re engineering, licensing, const, test & startup program & quality verification Meeting rescheduled from 830524.
* Region 5, Office of Director, 83/06/02, Region 5, Office of Director 2pp.
18739 327 24X Fiche 50-397, 83/06/02, 8306070030

DOCKETED ITEMS

8306130004 Requests authorization to use encl ASME Code Case N-343, "Alternative Scope of Exam of Attachment Welds for Exam Categories B-H, B-K-1 & CC Section XI, Div 1 " Rev 2 to Reg Guide 1 147 will include code case w/no addl requirements
BOUCHEY, O D Washington Public Power Supply System 83/06/02
SCHWENCER, A Licensing Branch 2 2pp 18824 24X
Fiche 50-397, 83/06/02, 8306130004

8306210120 Forwards partial response to TAA 830516 audit rept Findings 15 & 16 of independent verification program Response to Finding 14 Forthcoming
BOUCHEY, O D Washington Public Power Supply System 83/06/08
SCHWENCER, A Licensing Branch 2 4pp 18918 105 24X
Fiche 50-397, 83/06/08, 8306210120

8306280596 Forwards responses to NRC telcon questions re B&R technical rept, "Effect of Hydrodynamic Loads on Safety-Related Equipment & Piping Outside Containment," transmitted by 830328 ltr
BOUCHEY, O D Washington Public Power Supply System 83/06/16
SCHWENCER, A Licensing Branch 2 17pp 19018 197 24X
Fiche 50-397, 83/06/16, 8306280596

E NRC Safety Evaluation Report (SER), suppl's & correspondence

8306010043 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF WPPSS NUCLEAR PROJECT NO. 2 Docket No 50-397 (Washington Public Power Supply System)
* Division of Licensing NUREG-0892 803 83/05/31 46pp
Available at NRC \$4 75. 18684 082 24X Fiche 50-397, 83/05/31, 8306010043

8306200243 Forwards three listed repts to expedite resolution of SER Outstanding Issue 13 re control sys failures, in response to NRC Questions 031, 135, 137 & 138
BOUCHEY, O D Washington Public Power Supply System 83/06/10
SCHWENCER, A Licensing Branch 2 1p. 18901, 304 24X
Fiche 50-397, 83/06/10, 8306200243

--8306200247 "Cold Shutdown Power Bus Failure Analysis Rept."
WORTHAM, T R, KINSTON, P B General Electric Co 83/02/28 130pp
18901 305 24X Fiche 50-397, 83/06/10, 8306200243

--8306200251 "Evaluation of High Energy Line Breaks & Consequential Control Sys Failures (IE Info Notice 79-22 Summary Rept)"
PARKER, J E Washington Public Power Supply System 83/02/28 36pp, 18902 043 24X Fiche 50-397, 83/06/10, 8306200243

--8306200253 "Common Sensor Failures Evaluation Rept."
SCHERER, P R General Electric Co 83/04/30 48pp 18902 082 24X Fiche 50-397, 83/06/10, 8306200243

8306280453 Forwards "Control Sys Failures Evaluation Rept," inadvertently omitted from 830610 response to NRC request for info re SER 3 Outstanding Issue 13.
BOUCHEY, O D Washington Public Power Supply System 83/06/21
SCHWENCER, A Licensing Branch 2 1p 19020, 141 24X
Fiche 50-397, 83/06/21, 8306280453

--8306280456 "Control Sys Failures Evaluation Rept"
SCHERER, P R, WORTHAM, T R, ECHERT, E C General Electric Co 82/09/30 26pp 19020:142 24X Fiche 50-397, 83/06/21, 8306280453

F Security, medical, emergency & fire protection plans

8306010400 Forwards proposed schedule re current status of emergency response capability per Region V 830301 meeting (Generic Ltr 82-33 & Suppl 1 to NUREG-0737)
BOUCHEY, O D Washington Public Power Supply System 83/04/15
SCHWENCER, A Licensing Branch 2 4pp, 18682, 241 24X
Fiche 50-397, 83/04/15, 8306010400

8306010241 Provides addl info re Yakima Indian Nation, per verbal request, State of WA utilizes law enforcement teletype sys to notify contiguous counties of event w/potential offsite consequences Yakima County would notify tribal police.
DONOVAN, R W Federal Emergency Management Agency 83/05/19
AULUCK, R Licensing Branch 2 11pp 18673, 009 24X
Fiche 50-397, 83/05/19, 8306010241

G Utility Final Safety Analysis Report (FSAR) & amends

8306160147 Amend 30 to FSAR W/830513 ltr
* Washington Public Power Supply System 83/06/30. 966pp, 18856:001. 24X Fiche 50-397, 83/06/30, 8306160147.

G Inspection reports, IE Bulletins & correspondence

8306170215 Forwards 12th progress rept re review of completed safety-related work, per 80071/ commitments & Enforcement Action 80-20 per notice of violation
MATLOCK, R G Washington Public Power Supply System 82/10/19
ENDELKEN, R H Region 5, Office of Director 16pp 18883 137 24X
Fiche 50-397, 82/10/19, 8306170215

8306100009 Addl response to FOIA request for documents dtd 820101 or after re SALP Forwards App A documents Documents also available in PDR
FELTON, J M Division of Rules and Records 83/04/11 CLARK, R San Francisco Examiner 3pp 18815 252 24X Fiche 50-000, 83/04/11, 8306100009

--8306100014 Submits schedule for Region V SALP Board meetings for 820928-830523
ENDELKEN, R H Region 5, Office of Director 82/03/19
DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18815 255 24X Fiche 50-000, 83/04/11, 8306100009

8306010368 Forwards final response to IE Bulletin 79-02, Rev 2 re reliability of pipe support base plates using concrete expansion anchor bolts in Seismic Category I piping sys
Approx 10,000 Seismic Category I supports utilized
CARLISLE, C S Washington Public Power Supply System 83/05/19
MARTIN, J B Region 5, Office of Director 51pp 18682 001 24X
Fiche 50-397, 83/05/19, 8306010368

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 123pp 18831, 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8306020079 Ack receipt of 830505 amended response informing NRC of steps taken to correct violations noted in IE Insp Rept 50-397/82-27
STERNBERG, D M Region 5, Office of Director 83/05/27
CARLISLE, C S Washington Public Power Supply System 1p 18691 262 24X Fiche 50-397, 83/05/27, 8306020079

--8306020104 Amended response to NRC 830104 ltr re violations noted in IE Insp Rept 50-397/82-27 Corrective actions reinsp of all large & small bore-type bracket installations complete No addl rework or welding required
CARLISLE, C S Washington Public Power Supply System 83/05/05
STERNBERG, D M Region 5, Office of Director 3pp 18691 263 24X Fiche 50-397, 83/05/27, 8306020079

8306280503 Forwards IE Insp Rept 50-397/83-15 on 830503-05 No noncompliance noted
BOOK, H E Region 5, Office of Director. 83/05/27 CARLISLE, C S Washington Public Power Supply System 2pp 19018 356 24X
Fiche 50-397, 83/05/27, 8306280503

--8306280507 IE Insp Rept 50-397/83-15 on 830503-05 No noncompliance noted Major areas inspected lab capability for performing chemical & radiochemical assays & adequacy of lab QA program
HAMADA, Q H, TEMPLE, G, WENSLAWSKI, F Region 5, Office of Director 83/05/27 3pp 19018 358 24X Fiche 50-397, 83/05/27, 8306280503

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306280209 Forwards IE Insp Rept 50-397/83-18 on 830328-0408 No noncompliance noted
STERNBERG, D M Region 5, Office of Director 83/06/02
CARLISLE, C S Washington Public Power Supply System 2pp 19015 047 24X Fiche 50-397, 83/06/02, 8306280209

--8306280215 IE Insp Rept 50-397/83-18 on 830328-0408 No noncompliance noted Major areas inspected previously identified followup items & const deficiencies in areas of concrete expansion anchor & safety-related electrical sys installation.
ELIN, J P, DODDS, R T Region 5, Office of Director. 83/05/23 9pp 19015 049 24X Fiche 50-397, 83/06/02, 8306280209

DOCKETED ITEMS

273

8306280334 Forwards IE Insp Rept 50-397/83-14 on 830401-30 & notice of violation w/o notice of violation
STERNBERG, D M Region 5, Office of Director 83/06/03
CARLISLE, C S Washington Public Power Supply System 2pp
19001 283 24X Fiche 50-397, 83/06/03, 8306280334

--8306280341 IE Insp Rept 50-397/83-14 on 830401-30 Noncompliance noted Failure to prevent damage to installed equipment & failure to assure adequate repairs & conformance to contamination & concrete cover requirements
TOTH, A D, FEIL, R A, DODDS, R T Region 5, Office of Director 83/06/02 14pp 19001 285 24X Fiche 50-397, 83/06/03, 8306280334

8306280516 Forwards IE Insp Rept 50-397/83-17 on 830401-30 No noncompliance noted
STERNBERG, D M Region 5, Office of Director 83/06/06
CARLISLE, C S Washington Public Power Supply System 2pp
19017 189 24X Fiche 50-397, 83/06/06, 8306280516

--8306280521 IE Insp Rept 50-397/83-17 on 830401-30 No noncompliance noted Major areas inspected Fuel receipt & storage, preoperational test program implementation & test witnessing & independent insp effort
FEIL, R A, DODDS, R T Region 5, Office of Director 83/06/02 8pp 19017 191 24X Fiche 50-397, 83/06/06, 8306280516

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8306200243 Forwards three listed repts to expedite resolution of SER Outstanding Issue 13 re control sys failures in response to NRC Questions 031 135, 137 & 138
BOUCHEY, O D Washington Public Power Supply System 83/06/10
SCHWENGER, A Licensing Branch 2 1p 18901 304 24X Fiche 50-397, 83/06/10, 8306200243

--8306200247 "Cold Shutdown Power Bus Failure Analysis Rept "
WORTHAM, T R, KINSTON, P B General Electric Co 83/02/28 130pp
18901 305 24X Fiche 50-397, 83/06/10, 8306200243

--8306200251 "Evaluation of High Energy Line Breaks & Consequential Control Sys Failures (IE Info Notice 79-22 Summary Rept). "
PARKER, J E Washington Public Power Supply System 83/02/28 36pp 18902 043 24X Fiche 50-397, 83/06/10, 8306200243

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8306280371 Forwards IE Insp Rept 50-397/83-20 on 830516-20 No noncompliance noted
STERNBERG, D M Region 5, Office of Director 83/06/15
CARLISLE, C S Washington Public Power Supply System 2pp
19001 323 24X Fiche 50-397, 83/06/15, 8306280371

--8306280380 IE Insp Rept 50-397/83-20 on 830516-20 No noncompliance noted Major areas inspected QA program, THI (NUREG-0737) activities, including Confirmatory Issue 22 & independent insp
WILLET, D J, DODDS, R T Region 5, Office of Director 83/06/15 7pp 19001 325 24X Fiche 50-397, 83/06/15, 8306280371

8306210240 Forwards IE Mgt Meeting Rept 50-397/83-25 on 830606 No noncompliance noted
STERNBERG, D M Region 5, Office of Director 83/06/17
CARLISLE, C S Washington Public Power Supply System 1p
18917 015 24X Fiche 50-397, 83/06/17, 8306210240

--8306210245 IE Mgt Meeting Rept 50-397/83-25 on 830606 No noncompliance noted Major areas discussed sys completion, engineering & licensing, quality verification & test & startup programs & operations & planning Viewgraphs encl
DODDS, R T Region 5, Office of Director 83/06/16 130pp
18917 016 24X Fiche 50-397, 83/06/17, 8306210240

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Activation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

R Periodic operating reports & related correspondence

8306170215 Forwards 12th progress rept re review of completed safety-related work, per 800717 commitments & Enforcement Action 80-20 per notice of violation
MATLOCK, R O Washington Public Power Supply System 82/10/19
ENGELKEN, R H Region 5, Office of Director 16pp 18883 137 24X Fiche 50-397, 82/10/19, 8306170215

S Reportable occurrences, LERs & related correspondence

8306100122 Part 21 Rept 82-10 re path of in-leakage in MSIV leakage control sys Path exists because valve not powered from critical bus Valve MS-V-146 will be powered from critical bus to assure that MSIV-1CS can perform intended function
CONN, W O Burns & Roe Co 82/11/09 ENGELKEN, R H Region 5, Office of Director 4pp 18802 031 24X Fiche 50-397, 82/11/09, 8306100122

8306070095 Interim Deficiency Repts 216 & 223 re gaseous release from RHR relief valve vents & inadequate standby liquid control sys, respectively Final Deficiency Rept 232 re improper installation of RHR support pin receptacle also encl
CARLISLE, C S Washington Public Power Supply System 83/05/17
MARTIN, J B Region 5, Office of Director 6pp 18739 129 24X Fiche 50-397, 83/05/17, 8306070095

8306010220 Final Deficiency Repts 229 & 254 re hangers not installed in turned over HPCS sys 7 i & improper installation of Lubrite assemblies, respectively Interim rept 251 re Limitorque motor operators w/motors supplied by Baldor encl
CARLISLE, C S Washington Public Power Supply System 83/05/23
MARTIN, J B Region 5, Office of Director 4pp 18673 005 24X Fiche 50-397, 83/05/23, 8306010220

8306240191 Part 21 Evaluation Rept 83-07 re improperly sized overcurrent fuses in dc motor feeders Initially reported on 830603 Fuses sized for 225% of full load current will be provided for jogging pump
VANDERBER, J J Burns & Roe Co 83/06/06 COLLINS, J T Region 4, Office of Director 16pp 18981 003 24X Fiche 50-397, 83/06/06, 8306240191

8306270347 Recommends deletion of all refs to RHR steam condensing sys from encl Interim Deficiency Rept 216 re RHR relief valve vents Steam condensing mode of RHR sys will be deactivated
BOUCHEY, O D Washington Public Power Supply System 83/06/22
SCHWENGER, A Licensing Branch 2 2pp 18993 135 24X Fiche 50-397, 83/06/22, 8306270347

--8306270353 Interim Deficiency Rept 216 re RHR relief valve vents. Initially reported on 821022 Relief valves will be removed, containment leakage path will be eliminated & steam condensing mode will be deactivated Next rept by 830817
CARLISLE, C S Washington Public Power Supply System 83/05/18
MARTIN, J B Region 5, Office of Director 4pp 18993 137 24X Fiche 50-397, 83/06/22, 8306270347

DOCKET 50-400 SHEARDN HARRIS NUCLEAR POWER PLANT, UNIT 1

A Application/construction stage documents & correspondence

8306140659 Summarizes 830128 meeting at plant site re results of self-evaluation programs & to tour plant. Meeting beneficial.
O'REILLY, J P Region 2, Office of Director 83/02/09 UTLEY, E. E. Carolina Power & Light Co 1p 18833 360 24X Fiche 50-400, 83/02/09, 8306140659

DOCKETED ITEMS

8306160657 Forwards Mechanical Engineering Branch request for addl info re criteria used for design & const of piping supports in FSAR Clarification of codes & stds used for design & const required to complete review
KNIGHTON, G W Licensing Branch 3 83/06/01 UTLEY, E E Carolina Power & Light Co 3pp 18894 353 24X Fiche 50-400, 83/06/01, 8306160657

8306200017 Notification of 830615 meeting w/util in Bethesda, MD to discuss issues re structural analysis & consideration of soil structure interaction in analysis
KADAMBI, N P Licensing Branch 3 83/06/03 KNIGHTON, G W Licensing Branch 3 3pp 18909 118 24X Fiche 50-400, 83/06/03, 8306200017

8306270012 Notification of 830623 meeting w/util in Bethesda, MD to discuss applicant mgt organizational & operational structure
KADAMBI, N P Licensing Branch 3 83/06/10 KNIGHTON, G W Licensing Branch 3 3pp 18999 346 24X Fiche 50-400, 83/06/10, 8306270012

8306200019 Summary of 830331 meeting w/util & Westinghouse in Bethesda, MD re Westinghouse analysis & evaluation of D4/D5/E steam generator mod
HOPKINS, J B Licensing Branch 4 83/06/14 Licensing Branch 4 2pp 18908 327 24X Fiche 50-000, 83/06/14, 8306200019

8306210002 Forwards addl info re FSAR Amend 5 per NRC request info includes responses to safety review questions, revs to reg guide positions in FSAR Chapter 1 & revs to nuclear operations dept organization
MC DUFFIE, M A Carolina Power & Light Co 83/06/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 10pp 18911 001 24X Fiche 50-400, 83/06/17, 8306210002

8306270113 Responds to 830421 ltr & forwards design documents per 830201-03 meetings w/Mechanical Engineering Branch W/o encl
MC DUFFIE, M A Carolina Power & Light Co 83/06/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 18988 103 24X Fiche 50-400, 83/06/22, 8306270113

D NRC Draft/Final Environmental Statements, supplis & correspondence

8306280269 Informs that review of DES complete Major factors of environ concern to Soil Conservation Svc adequately covered
GARRETT, C A Agriculture, Dept of 83/06/22 Division of Licensing 2pp 19014 362 24X Fiche 50-400, 83/06/22, 8306280269

E NRC Safety Evaluation Report (SER), supplis & correspondence

8306080064 Forwards addl input to draft SER & request for info re turbine missiles Items should be added to list in Chapter 1 of draft SER as confirmatory items
KNIGHTON, G W Licensing Branch 3 83/05/24 UTLEY, E E Carolina Power & Light Co 3pp 18787 300 24X Fiche 50-400, 83/05/24, 8306080064

8306160272 Forwards change pages to draft SER Changes cover turbine missiles, fuel design reactor matls, functional design of reactivity control sys & steam generator matls
KNIGHTON, G W Licensing Branch 3 83/06/01 UTLEY, E E Carolina Power & Light Co 45pp 18972 172 24X Fiche 50-400, 83/06/01, 8306160272

8306060152 Forwards response to draft SER Open Item 210 re results of evaluation of chemical & vol control sys malfunction event Transient scenario would not experience significant change except for delay of pressurizer low pressure trip
MC DUFFIE, M A Carolina Power & Light Co 83/06/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 18728 097 24X Fiche 50-400, 83/06/02, 8306060152

8306060202 Forwards response to draft SER Open Item 304 re rated load test sequence for diesel generator load acceptance testing FSAR Section B 3 1 1 2 14K will be revised as listed in future amend
MC DUFFIE, M A Carolina Power & Light Co 83/06/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18727 293 24X Fiche 50-400, 83/06/02, 8306060202

8306070122 Forwards response to draft SER Open Item 182 re process & effluent monitoring program
MC DUFFIE, M A Carolina Power & Light Co 83/06/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18739 210 24X Fiche 50-400, 83/06/02, 8306070122

8306080032 Forwards responses to draft SER Open Items 156 & 157 re main condenser evacuation sys (NCEs) capacity & MCE's quality group correlation w/Reg Guide 1 26 Group D
MC DUFFIE, M A Carolina Power & Light Co 83/06/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 18773 605 24X Fiche 50-400, 83/06/02, 8306080032

8306070151 Forwards response to draft SER Open Items 32 & 37 re irradiation strengthened Zircaloy yield strengths & predicted cladding collapse time, respectively Response corrects 830518 submittal
ZIMMERMAN, S R Carolina Power & Light Co 83/06/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 18756 267 24X Fiche 50-400, 83/06/03, 8306070151

8306240463 Forwards results of NRC 830307-11 structural audit of plant at Ebasco in New York, NY List of open items should be included in open items list of Chapter 1 of draft SER
KNIGHTON, G W Licensing Branch 3 83/06/03 UTLEY, E E Carolina Power & Light Co 11pp 18997 244 24X Fiche 50-400, 83/06/03, 8306240463

8306100188 Forwards revised response to draft SER Open Item 34, re identification of SA-340, Class 1 & 2 matl used for closure bolting in reactor coolant pumps
MC DUFFIE, M A Carolina Power & Light Co 83/06/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18905 281 24X Fiche 50-400, 83/06/07, 8306100188

8306240467 Forwards open items list of resolve questions re quality group classification to be included in draft SER as subitems of Section 17 5
KNIGHTON, G W Licensing Branch 3 83/06/07 UTLEY, E E Carolina Power & Light Co 4pp 18998 096 24X Fiche 50-400, 83/06/07, 8306240467

8306240468 Forwards trip rept of geotechnical engineering 830417 14 site visit & audit List of open items in rept should be added to open items list in Chapter 1 of draft SER
KNIGHTON, G W Licensing Branch 3 83/06/10 UTLEY, E E Carolina Power & Light Co 8pp 18998 088 24X Fiche 50-400, 83/06/10, 8306240468

8306160116 Forwards responses to Power Sys Branch draft SER Open Item 117 re cooling water leakage Impact of Flooding from postulated breaks in moderate energy fluid sys have no adverse effects on diesel generator areas
MC DUFFIE, M A Carolina Power & Light Co 83/06/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18861 202 24X Fiche 50-400, 83/06/13, 8306160116

8306170224 Forwards responses to draft SER Open Items 37, 39 & 43 re fracture toughness, exemption from testing four heats of manual metal arc electrodes & compliance w/Charpy V-notch impact orientation requirements, respectively
MC DUFFIE, M A Carolina Power & Light Co 83/06/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 18882 316 24X Fiche 50-400, 83/06/14, 8306170224

8306200083 Forwards response to Power Sys Branch draft SER Open Item 126 re crankcase vent line Rupture or breakage of crankcase vent line will not impede engine capability to start or operate as required
MC DUFFIE, M A Carolina Power & Light Co 83/06/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18903 343 24X Fiche 50-400, 83/06/14, 8306200083

8306200307 Forwards responses to Containment Sys Branch draft SER Open Items 64 & 71 re containment pressure instrument lines & containment leakage testing program, respectively Responses to remaining open items forthcoming
MC DUFFIE, M A Carolina Power & Light Co 83/06/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 18900 155 24X Fiche 50-400, 83/06/14, 8306200307

8306210204 Forwards response to draft SER Open Item 145 re solid waste processing sys & Item 176 concerning process control program Absence of free water will be verified by use of process control program per Tech Spec 3/4 11 3
MC DUFFIE, M A Carolina Power & Light Co 83/06/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 18918 111 24X Fiche 50-400, 83/06/17, 8306210204

8306270100 Forwards responses to draft SER Open Items 290 & 291 re combined seismic & dynamic loads to be used in qualification program & qualification of safety-related electrical equipment, respectively
MC DUFFIE, M A Carolina Power & Light Co 83/06/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 18988 110 24X Fiche 50-400, 83/06/22, 8306270100

8306270217 Forwards responses to Power Sys Branch draft SER Items 102, 114, 120, 122, 124, 125, 304, 305, 309 & 311 Diesel generator training will be given to licensed operators & operations supervisory, maint & QA/QC personnel
MCODUFFIE, M A Carolina Power & Light Co 83/06/22 DENTON, H R
Office of Nuclear Reactor Regulation, Director 17pp 18991 233
24X Fiche 50-400, 83/06/22, 8306270217

8306270241 Forwards draft SER Open Item 100, providing ref to correspondence & status info Addl open items include NRC 930411, 0503 & 24 ltrs, & telecopied Q list items, audit items & evaluation of IMI Item III D I I
MCODUFFIE, M A Carolina Power & Light Co 83/06/22 DENTON, H R
Office of Nuclear Reactor Regulation, Director 79pp 18989 083
24X Fiche 50-400, 83/06/22, 8306270241

8306270292 Forwards draft SER Open Item 4, responses for Structural & Geotechnical Engineering Branch
MCODUFFIE, M A Carolina Power & Light Co 83/06/22 DENTON, H R
Office of Nuclear Reactor Regulation, Director 64pp 18990 075
24X Fiche 50-400, 83/06/22, 8306270292

8306270448 Forwards response to Power Sys Branch draft SER Open Items 110 & 113 re growth of algae in diesel fuel oil storage tank & quality & reliability of fuel oil supply for emergency diesel generator operation, respectively
MCODUFFIE, M A Carolina Power & Light Co 83/06/22 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 18992 063
24X Fiche 50-400, 83/06/22, 8306270448

F Security, medical, emergency & fire protection plans

8306060112 Forwards supplemental info to detailed control room design review summary rept "Human Factors Design Evaluation Rept for Shearon Harris Unit 1 Control Room," per Generic Ltr 82-33 Errata sheets to 821207 rept encl
WILEY, E E Carolina Power & Light Co 83/06/01 DENTON, H R
Office of Nuclear Reactor Regulation, Director 43pp 18722 178
24X Fiche 50-400, 83/06/01, 8306060112

G Adjudicatory correspondence

8306010355 Advises that negotiations on first set of responses to interrogatories in progress Motion to compel will be issued if negotiations fail
EDDLEMAN, W Eddleman, W 83/05/26 KELLEY, J Atomic Safety and Licensing Board Panel 1p 18681 347 24X Fiche 50-400, 83/05/26, 8306010355

8306010359 Advises that scheduling of negotiations re second set of responses to interrogatories in progress Motion to compel will be issued if negotiations fail
EDDLEMAN, W Eddleman, W 83/05/26 KELLEY, J Atomic Safety and Licensing Board Panel 1p 18681 348 24X Fiche 50-400, 83/05/26, 8306010359

8306010390 Response to W Eddleman request for production of documents contained in general interrogatories & interrogatories on Contentions 64(f) & 67 (second set)
O'NEILL, J H Carolina Power & Light Co O'NEILL, J H Shaw, Pittman, Potts & Trowbridge 83/05/27 EDDLEMAN, W Eddleman, W 2pp 18682 179 24X Fiche 50-400, 83/05/27, 8306010390

--8306010395 Response to W Eddleman general interrogatories & interrogatories on Contentions 64(f) & 67 (second set) Affidavits, Certificate of Svc & certification of counsel encl
O'NEILL, J H Carolina Power & Light Co O'NEILL, J H Shaw, Pittman, Potts & Trowbridge 83/05/27 EDDLEMAN, W Eddleman, W 32pp 18682 181 24X Fiche 50-400, 83/05/27, 8306010390

8306010439 Memorandum & order ruling on cost saving contentions, discovery disputes & scheduling matters informal discussion on proposed contentions between NRC applicants & intervenors prior to prehearing conference recommended
BRIGHT, O D, CARPENTER, J H, KELLEY, J L Atomic Safety and Licensing Board Panel 83/05/27 26pp 18679 276 24X Fiche 50-400, 83/05/27, 8306010439

8306020175 Response to W Eddleman 830507 proposed Contention 161 re possible malfunctions of Westinghouse 1B-416 circuit breakers Contention admissible per 10CFR2.714(b) Certificate of Svc encl
ROTHSCHEILD, M U Hearing Branch I 83/05/31 Atomic Safety and Licensing Board Panel 8pp 18691 084 24X Fiche 50-400, 83/05/31, 8306020175

8306030336 Response opposing W Eddleman proposed new Contention 161 re 1B-416 circuit breakers Proposed contention should be rejected or, alternatively, deferred pending W Eddleman review of proposed design change Certificate of Svc encl
O'NEILL, J H Carolina Power & Light Co O'NEILL, J H Shaw, Pittman, Potts & Trowbridge 83/05/31 Atomic Safety and Licensing Board Panel 8pp 18706 165 24X Fiche 50-400, 83/05/31, 8306030336

8306030337 Confirms that J O'Neill ofc contacted to open negotiations re applicant 830527 response to Eddleman Interrogatories 64F & 67 Applicant responses incomplete
EDDLEMAN, W Eddleman, W 83/05/31 KELLEY, J Atomic Safety and Licensing Board Panel 1p 18705 022 24X Fiche 50-400, 83/05/31, 8306030337

8306070291 Responses to second set of interrogatories on Contention 1VC Certificate of Svc encl
O'NEILL, J H Carolina Power & Light Co O'NEILL, J H Shaw, Pittman, Potts & Trowbridge 83/06/02 WILSON, R Wilson, R 12pp 18741 202 24X Fiche 50-400, 83/06/02, 8306070291

8306070393 Memorandum & order memorializing 830602 telcons & granting intervenor request for extension until 830607 to file reply brief on proposed expert qualifications
KELLEY, J L Atomic Safety and Licensing Board Panel 83/06/03 2pp 18742 016 24X Fiche 50-400, 83/06/03, 8306070393

8306080147 Response to request for production of documents on Contention 45 Certificate of Svc & Certification of counsel encl
FLYNN, B F Carolina Power & Light Co 83/06/03 EDDLEMAN, W Eddleman, W 4pp 18772 219 24X Fiche 50-400, 83/06/03, 8306080147

8306080160 Answers to first set of general interrogatories & interrogatories on Contention 45 Certificate of Svc encl Related correspondence
FLYNN, B F Carolina Power & Light Co 83/06/03 EDDLEMAN, W Eddleman, W 15pp 18772 159 24X Fiche 50-400, 83/06/03, 8306080160

8306090222 Advises that negotiations to discuss 830603 responses to interrogatories re Eddleman 45 (water hammer) will begin 830623 Motion to compel will be issued if negotiations fail
EDDLEMAN, W Eddleman, W 83/06/06 KELLEY, J Atomic Safety and Licensing Board Panel 1p 18796 233 24X Fiche 50-400, 83/06/06, 8306090222

8306090225 Reply brief re qualification of intervenor security experts Plan review restrictions will not expedite matters Board requested to permit listed experts to review relevant portions of plan Certificate of Svc encl
GREENBLATT, D Affiliation Unknown GREENBLATT, D Greenblatt, D 83/06/06 Atomic Safety and Licensing Board Panel 14pp 18795 348 24X Fiche 50-400, 83/06/06, 8306090225

8306100091 Requests clarification of "Joint Intervenor" in order to direct next round of discovery requests w/ specificity & efficiency by 830630 Response requested within 10 days Related correspondence Svc list encl
BAXTER, T A Shaw, Pittman, Potts & Trowbridge BAXTER, T A Carolina Power & Light Co 83/06/07 PAYNE, H T Edelstein & Payne 4pp 18802 100 24X Fiche 50-400, 83/06/07, 8306100091

8306230345 Advises of util request for identification of author/authors of answers to util interrogatories Svc list encl
BAXTER, T A Shaw, Pittman, Potts & Trowbridge BAXTER, T A Carolina Power & Light Co 83/06/16 EDDLEMAN, W Eddleman, W 5pp 18942 279 24X Fiche 50-400, 83/06/16, 8306230345

8306220090 Memorandum & order ruling on intervenor proffered security expert qualifications BJ Tuggle, JR Maples, L Stevens & ER Blecher qualify as experts in respective fields, J Mackie disqualified as expert
KELLEY, J L, DRIGILL, O D, CARPENTER, J H Atomic Safety and Licensing Board Panel 83/06/17 11pp 18926 211 24X Fiche 50-400, 83/06/17, 8306220090

8306220108 Response to second set of general interrogatories & interrogatories on Contentions 29 & 37B
BAUSER, D B Carolina Power & Light Co BAUSER, D B, Shaw, Pittman, Potts & Trowbridge 83/06/17 EDDLEMAN, W Eddleman, W 119pp 18926 257 24X Fiche 50-400, 83/06/17, 8306220108

--8306220111 Response to second request for production of documents on Contentions 29 & 37B Notice of appearance, Certificate of Svc & certification of counsel encl
BAUSER, D B Carolina Power & Light Co BAUSER, D B, Shaw, Pittman, Potts & Trowbridge 83/06/17 EDDLEMAN, W Eddleman, W 10pp 18927 006 24X Fiche 50-400, 83/06/17, 8306220108

DOCKETED ITEMS

8306220125 Forwards executed LI Loflin & LB Wilson affidavits, for inclusion in util 830510 response to R Wilson interrogatories on Contentions 1(a) - (d), 1(e) - (f) Svr list encl Related correspondence
CARROW, H Carolina Power & Light Co 83/06/17 KELLEY, J L
BRIGHT, O O, CARPENTER, J H Atomic Safety and Licensing Board Panel
4pp 18926 103 24X Fiche 50-400, 83/06/17, 8306220125

8306270307 Responses to NRC DES DES does not impact contentions on safety, mgt capability, security or emergency planning
EDDLEMAN, W Eddleman, W 83/06/20 3pp 18995 232 24X
Fiche 50-400, 83/06/20, 8306270307

--8306270313 Amended interrogatory responses Certificate of Svc encl
EDDLEMAN, W Eddleman, W 83/06/20 Carolina Power & Light Co
2pp 18995 264 24X Fiche 50-400, 83/06/20, 8306270307

8306270402 Advises of attempts to open negotiations re interrogatories on Contentions 29 & 370 Negotiations toll time for motion to compel, which will follow within 10 days of failure of negotiation
EDDLEMAN, W Eddleman, W 83/06/22 KELLEY, J Atomic Safety and Licensing Board Panel 1p 18994 149 24X Fiche 50-400, 83/06/22, 8306270402

8306280090 Response to W Eddleman & Joint intervenors 830506 interrogatories Prof qualifications & Certificate of Svc encl
BARTH, C A Hearing Branch 1 83/06/24 EDDLEMAN, W Eddleman, W
125pp 19000 288 24X Fiche 50-400, 83/06/24, 8306280090

8306290361 Responds to 830616 ltr re discovery issues Names of experts providing info to W Eddleman will not be provided since exceptional circumstances not demonstrated Certificate of Svc encl
EDDLEMAN, W Eddleman, W 83/06/25 BAXTER, T Shaw, Pittman, Potts & Trowbridge 10pp 19055 227 24X Fiche 50-400, 83/06/25, 8306290361

8306290381 Motion for extension until 830720 to file addl interrogatories on environ contentions & Eddleman Contentions 29 & 378
EDDLEMAN, W Eddleman, W 83/06/26 Atomic Safety and Licensing Board Panel 4pp 19053 204 24X Fiche 50-400, 83/06/26, 8306290381

8306290395 Motion to establish schedule for responses to W Eddleman pleading on DES Requests deadline date of 830701 be extended to 830708 Certificate of Svc encl
BAXTER, T A Carolina Power & Light Co BAXTER, T A Shaw, Pittman, Potts & Trowbridge 83/06/27 Atomic Safety and Licensing Board Panel 5pp 19055 269 24X Fiche 50-400, 83/06/27, 8306290395

Q Inspection reports, IE Bulletins & correspondence

8306140399 Confirms 830510 mgt meeting in Raleigh, NC to review SALP program (first phase) results, per 830412 telcon Proposed agenda encl
LEWIS, R C Division of Project & Resident Programs 83/04/29
UTLEY, E E Carolina Power & Light Co 3pp 18837 093 24X
Fiche 50-000, 83/04/29, 8306140399

8306140368 Forwards IE Insp Repts 50-400/83-17 & 50-401/83-17 on 830503-06 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/05/24
UTLEY, E E Carolina Power & Light Co 2pp 18832 134 24X
Fiche 50-400, 83/05/24, 8306140368

--8306140375 IE Insp Repts 50-400/83-17 & 50-401/83-17 on 830503-06 No noncompliance noted. Major areas inspected independent insp effort, electrical work (cable & terminations) & work activities & inspector followup item
O'BRIEN, T D Region 2, Office of Director CONLON, T E Division of Engineering & Radiological Safety Programs 83/05/20 3pp 18832 136 24X Fiche 50-400, 83/05/24, 8306140368

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at DWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306140483 Ack receipt of 830602 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-400/83 07
VERRELLI, D M Division of Project & Resident Programs 83/06/02
UTLEY, E E Carolina Power & Light Co 1p 18833 118 24X
Fiche 50-400, 83/06/02, 8306140483

--8306140490 Responds to NRC 830412 ltr re violations noted in IE Insp Rept 50-400/83 07 Violation denied A'ML Section III, 1971 Edition, Summer 1973 addendum requires no specific documentation for upgrading components
PARSONS, R M Carolina Power & Light Co 83/05/12 O'REILLY, J P Region 2, Office of Director 2pp 18833 119 24X
Fiche 50-400, 83/06/02, 8306140483

--8306140495 Forwards corrected Page 3 to IE Insp Repts 50-400/83 07 & 50-401/83 07 submitted w/830412 ltr
LEWIS, R C Division of Project & Resident Programs 83/04/18
UTLEY, E E Carolina Power & Light Co 2pp 18833 121 24X
Fiche 50-400, 83/06/02, 8306140483

--8306140499 Corrected Page 3 to IE Insp Repts 50-400/83 07 & 50-401/83 07
* Division of Engineering & Radiological Safety Programs
83/04/18 1p 18833 122 24X Fiche 50-400, 83/06/02, 8306140483

--8306140503 Forwards IE Insp Repts 50-400/83-07 & 50-401/83 07 on 830308-11 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/04/18
UTLEY, E E Carolina Power & Light Co 2pp 18833 123 24X
Fiche 50-400, 83/06/02, 8306140483

--8306140507 Notice of violation from Insp on 830308-11
* Region 2, Office of Director 83/04/12 1p 18833 124 24X
Fiche 50-400, 83/06/02, 8306140483

--8306140512 IE Insp Repts 50-400/83-07 & 50-401/83-07 on 830308-11 Noncompliance noted documentation not available to confirm that matl had been upgraded to meet Class 1 requirements
MCFARLAND, C R, JACKSON, L H Region 2, Office of Director
UPRIGHT, C M Division of Engineering & Radiological Safety Programs 83/04/08 12pp 18833 126 24X Fiche 50-400, 83/06/02, 8306140483

8305110444 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/07 Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110444

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Geometrically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 110pp 18920 22b 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection (ables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8306290524 Approves issuance of SALP rept Notes improvement in safety-related activities, emergency preparedness & security & safeguards Weaknesses in QA program will be monitored
O'REILLY, J P Region 2, Office of Director 83/06/14 UTLEY, E E Carolina Power & Light Co 5pp 24X Fiche 50-000, 83/06/14, 8306290524

--8306290531 Forwards SALP Repts 50-325/83-09, 50-324/83-09, 50-261/83-07, 50-400/83-10 & 50-401/83-10 for Jan 1982 - Jan 1983
Evaluation will be discussed in Raleigh, NC on 830510
LEWIS, R C Division of Project & Resident Programs 83/05/03
UTLEY, E E Carolina Power & Light Co 2pp 24X
Fiche 50-000, 83/06/14, 8306290524

--8306290537 SALP rept for Jan 1982 - Jan 1983
* Region 2, Office of Director 83/05/03 64pp 24X
Fiche 50-000, 83/06/14, 8306290524

--8306290553 Responds to 830503 SALP rept for Jan 1982 - Jan 1983 Reduced NRC attention may be appropriate for Category 1 re fire protection. NRC attention should be maintained at normal levels for emergency preparedness
UTLEY, E E Carolina Power & Light Co 83/05/20 O'REILLY, J P Region 2, Office of Director 16pp 24X Fiche 50-000, 83/06/14, 8306290524

--830629055b Forwards replacement Page 2 to Attachment J of 830520 1tr which commented on SALP rept
EURV, L W Carolina Power & Light Co 83/05/27 O'REILLY, J P
Region 2, Office of Director App 24X Fiche 50-000, 83/06/14,
830629055P4

830510475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 830510475

830510477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 00/ 24X Fiche 50-000, 83/06/22, 830510477

830510479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 830510479

830510483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (1R) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 29/ 24X Fiche 50-000, 83/06/24, 830510483

S Reportable occurrences, LLRs & related correspondence

8306010128 Interim rept re welding deficiencies in Class IE auxiliary control panels Initially reported on 830401 Welds repaired Vendor comments & analysis forthcoming Final rept will be submitted by 830726
PARSONS, R M Carolina Power & Light Co 83/05/25 O'REILLY, J P
Region 2, Office of Director App 186/4 021 24X
Fiche 50-400, 83/05/25, 8306010128

8306010422 Interim deficiency rept re Gould, Inc Class IE 480 volt motor control ctr protective ground Initially reported on 830425 Work underway to implement listed corrective actions Next rept by 831216 Also reportable per Part 21
PARSONS, R M Carolina Power & Light Co 83/05/25 O'REILLY, J P
Region 2, Office of Director App 18479 324 24X
Fiche 50-400, 83/05/25, 8306010422

8306070217 Interim rept re Item 105, weld deficiencies in auxiliary relay cabinets Initially reported on 831101 Apparent deficiencies evaluated by vendor cabinets acceptable & seismically qualified Next rept will be submitted by 830729
PARSONS, R M Carolina Power & Light Co 83/05/26 O'REILLY, J P
Region 2, Office of Director App 18747 041 24X
Fiche 50-400, 83/05/26, 8306070217

8306070231 Interim deficiency rept re main reactor trip breakers design discrepancy Initially reported on 830427 Westinghouse will replace undervoltage attachments to accommodate new retaining ring Also reportable per Part 21
PARSONS, R M Carolina Power & Light Co 83/05/26 O'REILLY, J P
Region 2, Office of Director App 18/46 105 24X
Fiche 50-400, 83/05/26, 8306070231

8306070364 Interim deficiency rept on bolted structural connections (Item 112) Initially reported on 830426 Adul training conducted for insp & craft personnel re insp & erection of structural steel final rept by 840120
PARSONS, R M Carolina Power & Light Co 83/05/26 O'REILLY, J P
Region 2, Office of Director App 10741 308 24X
Fiche 50 400, 83/05/26, 8306070364

8306070389 Interim deficiency rept, Item 102, re grease in friction type structural connections Initially reported on 820915 Reinsp of turbine & containment bldgs completed Procedures revised Final rept by 840120
PARSONS, R M Carolina Power & Light Co 83/05/26 O'REILLY, J P
Region 2, Office of Director App 18742 019 24X
Fiche 50-400, 83/05/26, 8306070389

8306070400 Interim deficiency rept re Item 92, bolted structural connections w/excessive gaps & ASTM A325 nuts on ASTM A490 bolts Initially reported on 830702 Reinsp of turbine & containment bldgs completed Next rept by 840120
PARSONS, R M Carolina Power & Light Co 83/05/26 O'REILLY, J P
Region 2, Office of Director App 18741 358 24X
Fiche 50-400, 83/05/26, 8306070400

8306090242 Second interim rept, Item 117, re welding deficiencies on Class 1E 6 9 kV circuit breakers Initially reported on 830211 All breakers returned to vendor for fabrication Also reportable under Part 21
PARSONS, R M Carolina Power & Light Co 83/05/31 O'REILLY, J P
Region 2, Office of Director App 18795 332 24X
Fiche 50 400, 83/05/31, 8306090242

8306090046 Interim deficiency rept re failure to perform verification of anchor bolt matl type when tags lost (Item 131) Initially reported on 830503 Evaluation of anchor bolts continuing Submittal of rept on reportability extended until 830805
PARSONS, R M Carolina Power & Light Co 83/06/01 O'REILLY, J P
Region 2, Office of Director App 18793 287 24X
Fiche 50-400, 83/06/01, 8306090046

8306090180 Third interim deficiency rept re reactor protection sys failure Following secondary high energy line rupture Initially reported on 800707 Insulation of steam generator ref leg underway Also reportable per Part 21
PARSONS, R M Carolina Power & Light Co 83/06/01 O'REILLY, J P
Region 2, Office of Director App 18792 271 24X
Fiche 50-400, 83/06/01, 8306090180

8306090191 Third interim deficiency rept re potential damage to safety injection charging pump following secondary side high energy line rupture (Item 38) Initially reported on 800707 Resolution under review Also reportable per Part 21
PARSONS, R M Carolina Power & Light Co 83/06/01 O'REILLY, J P
Region 2, Office of Director App 18796 086 24X
Fiche 50-400, 83/06/01, 8306090191

8306090251 Final deficiency rept re Item 119, Seismic Class I electrical, HVAC & conduit supports Initially reported on 830303 Item not reportable under 10CFR50 55(e)
CHIANG, N J Carolina Power & Light Co 83/06/01 O'REILLY, J P
Region 2, Office of Director App 18795 292 24X
Fiche 50-400, 83/06/01, 8306090251

8306100230 Interim deficiency rept re Item 127, shop weld defects in ITT Hammel Dahl chilled water valve Item also reportable under Part 21 Valve returned to manufacturer Final rept expected by 830701
PARSONS, R M Carolina Power & Light Co 83/06/03 O'REILLY, J P
Region 2, Office of Director App 18807 154 24X
Fiche 50-400, 83/06/03, 8306100230

8306100234 Second interim rept on Item 104 re defective welds on 480-volt switchgear supplied by Brown-Boveri Electric Co. Initially reported on 830304 Major defects repaired Minor defects to be modeled in upcoming seismic test
PARSONS, R M Carolina Power & Light Co 83/06/03 O'REILLY, J P
Region 2, Office of Director App 1880/ 038 24X
Fiche 50-400, 83/06/03, 8306100234

8306200116 Addendum 1 to final deficiency rept, Item 91, re welded studs on embedded strip plates Any testing performed by site receipt insp unit is in excess of code requirements since same procedure revealed problem
PARSONS, R M Carolina Power & Light Co 83/06/09 O'REILLY, J P
Region 2, Office of Director App 18903 250 24X
Fiche 50-400, 83/06/09, 8306200116

8306200200 Addendum 1 to 830220 final deficiency rept re lamination in main rail support plates (Item 28) Info provided to justify not conducting addl insp of similar matl
PARSONS, R M Carolina Power & Light Co 83/06/09 O'REILLY, J P
Region 2, Office of Director App 18903 198 24X
Fiche 50-400, 83/06/09, 8306200200

8306270223 Interim deficiency & Part 21 repts re boric acid transfer pumps, Westinghouse Shop Order 205, Item 113 Initially reported on 830113 Support bolting will be replaced & gusset stiffener spot welds supplemented by 830701
PARSONS, R M Carolina Power & Light Co 83/06/14 O'REILLY, J P
Region 2, Office of Director App 18990 227 24X
Fiche 50-400, 83/06/14, 8306270223

8306280088 Deficiency rept Item 128 re welding defects in emergency svc water strainers supplied by RP Adams Initially reported on 830408 Condition not reportable per 10CFR50 55(e) or Part 21
CHIANG, N J Carolina Power & Light Co 83/06/16 O'REILLY, J P
Region 2, Office of Director App 17001, 156 24X
Fiche 50-400, 83/06/16, 8306280088

8306280463 Interim deficiency rept re Item 121, welding deficiencies in main steam/feedwater support frames. Initially reported on 830318 Extension requested until 830715 to submit complete evaluation Also reportable per Part 21
PARSONS, R M Carolina Power & Light Co 83/06/17 O'REILLY, J P
Region 2, Office of Director App 19018 294 24X
Fiche 50-400, 83/06/17, 8306280463

DOCKETED ITEMS

8306300192 Final Part 21 rept on Item 133 re safety injection valves made of carbon steel instead of stainless steel Initially reported on 830524 Valves of correct matl reordered & incorrect valves retagged
PARSONS, R M Carolina Power & Light Co 83/06/22 O'REILLY, J P Region 2, Office of Director App 19122 187 24X
Fiche 50-400, 83/06/22, 8306300192

V Operator Examinations

8306140132 Requests approved ref matl to operator exams by 830425
Missing deadline will result in delay in administering exams Applications should be submitted at least 60 days prior to first exam scheduled for 830513
VERRELLI, D M Division of Project & Resident Programs 83/04/08
FURR, B J Carolina Power & Light Co App 18839 086 24X
Fiche 50-400, 83/04/08, 8306140132

DOCKET 50-401 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 2

A Application/construction stage documents & correspondence

8306140659 Summarizes 830128 meeting at plant site re results of self-evaluation programs & to tour plant Meeting beneficial
O'REILLY, J P Region 2, Office of Director 83/02/09 UTLEY, E E Carolina Power & Light Co 1p 18833 360 24X
Fiche 50-400, 83/02/09, 8306140659

8306160657 Forwards Mechanical Engineering Branch request for addl info re criteria used for design & const of piping supports in FSAR Clarification of codes & stds used for design & const required to complete review
KNIGHTON, G W Licensing Branch 3 83/06/01 UTLEY, E E Carolina Power & Light Co 3pp 18894 353 24X Fiche 50-400, 83/06/01, 8306160657

8306200017 Notification of 830615 meeting w/util in Bethesda, MD to discuss issues re structural analysis & consideration of soil structure interaction in analysis
KADAMBI, N P Licensing Branch 3 83/06/03, KNIGHTON, G W Licensing Branch 3 3pp 18909 118 24X Fiche 50-400, 83/06/03, 8306200017

8306270012 Notification of 830623 meeting w/util in Bethesda, MD to discuss applicant mgt organizational & operational structure
KADAMBI, N P Licensing Branch 3 83/06/10 KNIGHTON, G W Licensing Branch 3 3pp 18999 346 24X Fiche 50-400, 83/06/10, 8306270012

8306200019 Summary of 830331 meeting w/utls & Westinghouse in Bethesda, MD re Westinghouse analysis & evaluation of 4/05/E steam generator mod
HOPKINS, J B Licensing Branch 4 83/06/14 Licensing Branch 4 22pp 18908 327 24X Fiche 50-000, 83/06/14, 8306200019

8306210002 Forwards addl info re FSAR Amend 5 per NRC request Info includes responses to safety review questions, revs to reg guide positions in FSAR Chapter 1 & revs to nuclear operations dept organization
MCDUFFIE, M A Carolina Power & Light Co 83/06/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 110pp 18911 001 24X Fiche: 50-400, 83/06/17, 8306210002

8306270113 Responds to 830421 ltr & forwards design documents per 830201-03 meetings w/Mechanical Engineering Branch w/o encl
MCDUFFIE, M A Carolina Power & Light Co 83/06/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 18908 103 24X Fiche 50-400, 83/06/22, 8306270113

D. NRC Draft/Final Environmental Statements, supp's & correspondence

8306280269 Informs that review of DEB complete Major factors of environ concern to Soil Conservation Svc adequately covered
GARRETT, C A Agriculture, Dept of 83/06/22, Division of Licensing 2pp 19014 362 24X Fiche 50-400, 83/06/22, 8306280269

1C Safety Evaluation Report (SER), supp's & correspondence

addl input to draft SER & request for info re items should be added to list in Chapter 1
-irradiation items
ing Branch 3, 83/05/24, UTLEY, E E Carolina Power & Light Co 18/07 000 24X Fiche 50-400, 83/05/24,

8306160272 Forwards change page to draft SER Changes cover turbine missiles, fuel design reactor matls, functional design of reactivity control sys, steam generator matls
KNIGHTON, G W Licensing Branch 3 83/06/01 UTLEY, E E Carolina Power & Light Co 45pp 18674 172 24X Fiche 50-400, 83/06/01, 8306160272

8306060152 Forwards response to draft SER Open Item 210 re results of evaluation of chemical & vol control sys malfunction event Transient scenario would not experience significant change except for delay of pressure low pressure trip
MCDUFFIE, M A Carolina Power & Light Co 83/06/02 DENTON, H R Office of Nuclear Reactor Regulation, Director App 18741 077 24X Fiche 50-400, 83/06/02, 8306060152

8306060202 Forwards response to draft SER Open Item 306 re rated load test sequence for diesel generator load acceptance testing
FSAR Section 6.3.1.2.14K will be revised as listed in future amend
MCDUFFIE, M A Carolina Power & Light Co 83/06/02 DENTON, H R Office of Nuclear Reactor Regulation, Director App 18741 079 24X Fiche 50-400, 83/06/02, 8306060202

8306070122 Forwards response to draft SER Open Item 102 re process & effluent monitoring program
MCDUFFIE, M A Carolina Power & Light Co 83/06/02 DENTON, H R Office of Nuclear Reactor Regulation, Director App 18749 010 24X Fiche 50-400, 83/06/02, 8306070122

8306080032 Forwards responses to draft SER Open Items 156 & 157 re main condenser evacuation sys (MCIS) capacity & MCIS quality group correlation w/Reg Guide 1.26 Group B
MCDUFFIE, M A Carolina Power & Light Co 83/06/02 DENTON, H R Office of Nuclear Reactor Regulation, Director App 18771 005 24X Fiche 50-400, 83/06/02, 8306080032

8306070151 Forwards response to draft SER Open Items 3P & 3J re irradiation strengthened Zircaloy yield strengths & predicted cladding collapse time, respectively Response corrects 830518 submittal
ZIMMERMAN, S R Carolina Power & Light Co 83/06/03 DENTON, H R Office of Nuclear Reactor Regulation, Director App 18736 264 24X Fiche 50-400, 83/06/03, 8306070151

8306240463 Forwards results of NRC 830307-11 structural audit of plant at Ebasco in New York, NY List of open items should be included in open items list of Chapter 1 of draft SER
KNIGHTON, G W Licensing Branch 3 83/06/03 UTLEY, E E Carolina Power & Light Co 11pp 18497 244 24X Fiche 50-400, 83/06/03, 8306240463

8306100188 Forwards revised response to draft SER Open Item 34, re identification of SA-540, Class 1 & 2 matl used for closure bolting in reactor coolant pumps
MCDUFFIE, M A Carolina Power & Light Co 83/06/07 DENTON, H R Office of Nuclear Reactor Regulation, Director App 18901 741 24X Fiche 50-400, 83/06/07, 8306100188

8306240467 Forwards open items list of resolve questions re quality group classification to be included in draft SER as subitem of Section 17.5
KNIGHTON, G W Licensing Branch 3 83/06/07 UTLEY, E E Carolina Power & Light Co 4pp 18978 096 24X Fiche 50-400, 83/06/07, 8306240467

8306240468 Forwards trip rept of geotechnical engineering 830412-14 site visit & audit List of open items in rept should be added to open items list in Chapter 1 of draft SER
KNIGHTON, G W Licensing Branch 3 83/06/10 UTLEY, E E Carolina Power & Light Co 6pp 18978 088 24X Fiche 50-400, 83/06/10, 8306240468

8306160116 Forwards responses to Power Sys Branch draft SER Open Item 117 re cooling water leakage impact of flooding from postulated breaks in moderate energy fluid sys have no adverse effects on diesel generator areas
MCDUFFIE, M A Carolina Power & Light Co 83/06/13 DENTON, H R Office of Nuclear Reactor Regulation, Director App 18861 282 24X Fiche 50-400, 83/06/13, 8306160116

8306170224 Forwards responses to draft SER Open Items 37, 39 & 43 re fracture toughness, exemption from testing four heats of manual metal arc electrodes & compliance w/Charpy V-notch impact orientation requirements, respectively
MCDUFFIE, M A Carolina Power & Light Co 83/06/14 DENTON, H R Office of Nuclear Reactor Regulation, Director App 18802 316 24X Fiche 50-400, 83/06/14, 8306170224

8306200083 Forwards response to Power Sys Branch draft SER Open Item 126 re crankcase vent line rupture or breakage of crankcase vent line will not impede engine capability to start or operate as required
MCUFFIE, M A Carolina Power & Light Co 83/06/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director 5pp 18703 343
24X Fiche 50-400, 83/06/14, 8306200083

8306200309 Forwards responses to Containment Sys Branch draft SER Open Items 64 & 71 re containment pressure instrument lines & containment leakage testing program, respectively Responses to remaining open items forthcoming
MCUFFIE, M A Carolina Power & Light Co 83/06/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director 5pp 18700 155
24X Fiche 50-400, 83/06/14, 8306200309

8306210204 Forwards response to draft SLR Open Item 165 re solid waste processing sys & item 176 concerning process control program Absence of free water will be verified by use of process control program per tech Spec J/4 11 3
MCUFFIE, M A Carolina Power & Light Co 83/06/17 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 18718 111
24X Fiche 50-400, 83/06/17, 8306210204

8306270100 Forwards responses to draft SER Open Items 290 & 291 re combined seismic & dynamic loads to be used in qualification program & qualification of safety-related electrical equipment, respectively
MCUFFIE, M A Carolina Power & Light Co 83/06/22 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 18708 118
24X Fiche 50-400, 83/06/22, 8306270100

8306270217 Forwards responses to Power Sys Branch draft SER Items 102, 114, 120, 122, 124, 125, 304, 305, 309 & 311 Diesel generator training will be given to licensed operators & operations supervisory, maint & QA/QC personnel
MCUFFIE, M A Carolina Power & Light Co 83/06/22 DENTON, H R
Office of Nuclear Reactor Regulation, Director 15pp 18791 233
24X Fiche 50-400, 83/06/22, 8306270217

8306270241 Forwards draft SER Open Item 100, providing ref to correspondence & status info Addl open items include NRC 830411, 0503 & 24 ltrs, & telecopied 0 list items, audit items & evaluation of 7M1 Item 111 b 1
MCUFFIE, M A Carolina Power & Light Co 83/06/22 DENTON, H R
Office of Nuclear Reactor Regulation, Director 7pp 18789 087
24X Fiche 50-400, 83/06/22, 8306270241

8306270292 Forwards draft SER Open Item 22 responses for Structural & Geotechnical Engineering Branch
MCUFFIE, M A Carolina Power & Light Co 83/06/22 DENTON, H R
Office of Nuclear Reactor Regulation, Director 64pp 18990 075
24X Fiche 50-400, 83/06/22, 8306270292

830627044B Forwards response to Power Sys Branch draft SER Open Items 110 & 113 re growth of algae in diesel fuel oil storage tank & quality & reliability of fuel oil supply for emergency diesel generator operation, respectively
MCUFFIE, M A Carolina Power & Light Co 83/06/22 DENTON, H R
Office of Nuclear Reactor Regulation, Director 4pp 18992 063
24X Fiche 50-400, 83/06/22, 830627044B

0 Adjudicatory correspondence

8306010390 Response to W Eddleman request for production of documents contained in general interrogatories & interrogatories on Contentions 64(f) & 67 (second set)
O'NEILL, J H Carolina Power & Light Co O'NEILL, J H Shaw, Pittman, Potts & Trowbridge 83/05/27 EDDLEMAN, W Eddleman, W 5pp 18682 179 24X Fiche 50-400, 83/05/27, 8306010390

--8306010395 Response to W Eddleman general interrogatories & interrogatories on Contentions 64(f) & 67 (second set) Affidavits, Certificate of Svc & certification of counsel encl
O'NEILL, J H Carolina Power & Light Co O'NEILL, J H Shaw, Pittman, Potts & Trowbridge 83/05/27 EDDLEMAN, W Eddleman, W 32pp 18682 181 24X Fiche 50-400, 83/05/27, 8306010390

8306010439 Memorandum & order, ruling on cost saving contentions, discovery disputes & scheduling matters Informal discussions on proposed contentions between NRC, applicants & intervenors prior to prehearing conference recommended
BRIGHT, O D, CARPENTER, J H, KELLEY, J L Atomic Safety and Licensing Board Panel 83/05/27 26pp 18679 276 24X Fiche 50-400, 83/05/27, 8306010439

8306020175 Response to W Eddleman 83050/ proposed Contention 161 re possible malfunctions of Westinghouse 4B-416 circuit breakers Contention admissible per 101(RR 714(b) Certificate of Svc encl
ROTHSCHILD, M U Hearing Branch 1 83/05/31 Atomic Safety and Licensing Board Panel 8pp 18671 084 24X Fiche 50-400, 83/05/31, 8306020175

8306030336 Response opposing W Eddleman proposed new Contention 161 re 4B-416 circuit breakers Proposed contention should be rejected or, alternatively, deferred pending W Eddleman review of proposed design change Certificate of Svc encl
O'NEILL, J H Carolina Power & Light Co O'NEILL, J H Shaw, Pittman, Potts & Trowbridge 83/05/31 Atomic Safety and Licensing Board Panel 8pp 18706 165 24X Fiche 50-400, 83/05/31, 8306030336

8306030337 Confirms that J O'Neill ofc contacted to open negotiations re applicant 830527 response to Eddleman Interrogatories 64F & 67 Applicant responses incomplete
EDDLEMAN, W Eddleman, W 83/05/31 KELLY, J Atomic Safety and Licensing Board Panel 1p 18705 022 24X Fiche 50-400, 83/05/31, 8306030337

8306070291 Responses to second set of interrogatories on Contention IVC Certificate of Svc encl
O'NEILL, J H Carolina Power & Light Co O'NEILL, J H Shaw, Pittman, Potts & Trowbridge 83/06/02 WILSON, R Wilson, R. 12pp 18741 282 24X Fiche 50-400, 83/06/02, 8306070291

8306070393 Memorandum & order memorializing 830602 telcons & granting intervenor request for extension until 830607 to file reply brief on proposed expert qualifications
KELLEY, J L Atomic Safety and Licensing Board Panel 83/06/03 2pp 18742 016 24X Fiche 50-400, 83/06/03, 8306070393

8306080149 Response to request for production of documents on Contention 45 Certificate of Svc & Certification of counsel encl
FLYNN, S F Carolina Power & Light Co 83/06/03 EDDLEMAN, W Eddleman, W 4pp 18772 217 24X Fiche 50-400, 83/06/03, 8306080149

8306080160 Answers to first set of general interrogatories & interrogatories on Contention 45 Certificate of Svc encl. Related correspondence
FLYNN, S F Carolina Power & Light Co 83/06/03 EDDLEMAN, W Eddleman, W 15pp 18772 159 24X Fiche 50-400, 83/06/03, 8306080160

8306090222 Advises that negotiations to discuss 830603 responses to interrogatories re Eddleman 45 (water hammer) will begin
830623 Motion to compel will be issued if negotiations fail
EDDLEMAN, W Eddleman, W 83/06/06 KELLEY, J Atomic Safety and Licensing Board Panel 1p 18796 233 24X Fiche 50-400, 83/06/06, 8306090222

8306090225 Reply brief re qualification of intervenor security experts Plan review restrictions will not expedite matters Board requested to permit listed experts to review relevant portions of plan Certificate of Svc encl
GREENBLATT, D Affiliation Unknown GREENBLATT, D Greenblatt, D 83/06/06 Atomic Safety and Licensing Board Panel. 14pp 18795 348 24X Fiche 50-400, 83/06/06, 8306090225

8306100091 Requests clarification of "Joint Intervenors" in order to direct next round of discovery requests w/specificity & efficiency by 830630 Response requested within 10 days
Related correspondence Svc list encl.
BAXTER, T A Shaw, Pittman, Potts & Trowbridge BAXTER, T A Carolina Power & Light Co 83/06/07 PAYNE, M T, Edelstein & Payne, 4pp 18802 100 24X Fiche 50-400, 83/06/07, 8306100091

8306230345 Advises of util request for identification of author/authors of answers to util interrogatories Svc list encl
BAXTER, T A Shaw, Pittman, Potts & Trowbridge BAXTER, T A Carolina Power & Light Co 83/06/16 EDDLEMAN, W Eddleman, W 5pp 18742 279 24X Fiche 50-400, 83/06/16, 8306230345

8306220090 Memorandum & order ruling on intervenor proffered security expert qualifications BJ Tuggle, JR Maples, L Stevens & ER Bleacher qualify as experts in respective fields
J Mackie disqualified as expert
KELLEY, J L, BRIGHT, O D, CARPENTER, J H Atomic Safety and Licensing Board Panel. 83/06/17 11pp 18926 211 24X Fiche 50-400, 83/06/17, 8306220090

8306220108 Response to second set of general interrogatories & interrogatories on Contentions 29 & 37B
BAUSER, D B Carolina Power & Light Co BAUSER, D B Shaw, Pittman, Potts & Trowbridge 83/06/17 EDDLEMAN, W Eddleman, W. 119pp. 18926 237 24X Fiche 50-400, 83/06/17, 8306220108

--8306220111 Response to second request for production of documents on Contentions 29 & 37B Notice of appearance, Certificate of Svc & certification of counsel encl
BAUSER, D B Carolina Power & Light Co. BAUSER, D B Shaw, Pittman, Potts & Trowbridge 83/06/17. EDDLEMAN, W. Eddleman, W 10pp. 18927 006 24X Fiche 50-400, 83/06/17, 8306220108

DOCKETED ITEMS

8306220125 Forwards executed LI Loflin & LH Wilson affidavits, for inclusion in util 830510 response to R Wilson interrogatories on Contentions 1(a) - (d), (e) - (f) Svc list encl Related correspondence
CARROW, H Carolina Power & Light Co. 83/06/17 KELLEY, J L ,
BRIGHT, O D , CARPENTER, J H Atomic Safety and Licensing Board Panel
4pp 18926 103 24X Fiche 50-400, 83/06/17, 8306220125

8306270307 Responses to NRC DES DES does not impact contentions on safety, mgt capability, security or emergency planning
Eddleman, W 83/06/20 52pp 18975 272 24X
Fiche 50-400, 83/06/20, 8306270307

--8306270313 Amended interrogatory responses Certificate of Svc encl
Eddleman, W Eddleman, W 83/06/20 Carolina Power & Light Co
2pp 18995 264 24X Fiche 50-400, 83/06/20, 8306270307

8306270402 Advises of attempts to open negotiations re interrogatories on Contentions 29 & 37B Negotiations toll time for motion to compel, which will follow within 10 days of failure of negotiation
Eddleman, W Eddleman, W 83/06/22 KELLEY, J Atomic Safety and Licensing Board Panel 1p 18994 149 24X Fiche 50-400, 83/06/22, 8306270402

8306280090 Response to W Eddleman & Joint Intervenor 830506 interrogatories Prof qualifications & Certificate of Svc encl
BARTH, C A Hearing Branch 1 83/06/24 EDDLEMAN, W Eddleman, W
125pp 19000 288 24X Fiche 50-400, 83/06/24, 8306280090

8306290361 Responds to 830616 ltr re discovery issues Names of experts providing info to W Eddleman will not be provided since exceptional circumstances not demonstrated Certificate of Svc encl
Eddleman, W Eddleman, W 83/06/25 BAXTER, T Shaw, Pittman, Potts & Trowbridge 10pp 19055 227 24X Fiche 50-400, 83/06/25, 8306290361.

8306290381 Motion for extension until 830720 to file addl interrogatories on environ contentions & Eddleman
Contentions 27 & 37B
Eddleman, W Eddleman, W 83/06/26 Atomic Safety and Licensing Board Panel 4pp 19053 204 24X Fiche 50-400, 83/06/26, 8306290381

8306290395 Motion to establish schedule for responses to W Eddleman pleading on DES. Requests deadline date of 830701 be extended to 830708 Certificate of Svc encl
BAXTER, T A Carolina Power & Light Co BAXTER, T A Shaw, Pittman, Potts & Trowbridge 83/06/27, Atomic Safety and Licensing Board Panel 5pp, 19055 269 24X Fiche 50-400, 83/06/27, 8306290395

Q Inspection reports, IE Bulletins & correspondence

8306140399 Confirms 830510 mgt meeting in Raleigh, NC to review SALP program (first phase) results, per 830412 telcon Proposed agenda encl
LEWIS, R C Division of Project & Resident Programs 83/04/29
UTLEY, E E Carolina Power & Light Co 3pp 18832 093 24X
Fiche 50-000, 83/04/29, 8306140399

8306140368 Forwards IE Insp Repts 50-400/83-17 & 50-401/83-17 on 830503-06 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/05/24
UTLEY, E E Carolina Power & Light Co 2pp 18832 134 24X
Fiche 50-400, 83/05/24, 8306140368.

--8306140375 IE Insp Repts 50-400/83-17 & 50-401/83-17 on 830503-06 No noncompliance noted Major areas inspected independent insp effort, electrical work (cable & terminations) & work activities & Inspector Followup item
O'BONN, T D Region 2, Office of Director CONLON, T E Division of Engineering & Radiological Safety Programs 83/05/20 3pp 18832 136 24X Fiche 50-400, 83/05/24, 8306140368.

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in gging Device " Svc list encl
J M Division of Safeguards & Inspection Programs (Post 83/05/26 Consolidated Edison Co of New York, Inc.
--831-047 24V Fiche 50-000, 83/05/26, 8305110458

3-34, "Event Notification Info Worksheet "

Emergency Preparedness & Engineering
1/05/26 Consolidated Edison Co of New
85 24X Fiche 50-000, 83/05/26, 8305110460

--35, "Fuel Movement W/Control Rods
st encl.
Emergency Preparedness & Engineering
3/05/31, Consolidated Edison Co of New
208, 24X Fiche 50-000, 83/05/31, 8305110461.

8306140483 Ack receipt of 830602 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-400/83 07
VERRELLI, D M Division of Project & Resident Programs 83/06/02
UTLEY, E E Carolina Power & Light Co 1p 18833 116 24X
Fiche 50-400, 83/06/02, 8306140483

--8306140495 Forwards corrected Page 3 to IE Insp Repts 50-400/83-07 & 50-401/83 07 submitted w/830412 ltr
LEWIS, R C Division of Project & Resident Programs 83/04/18
UTLEY, E E Carolina Power & Light Co 2pp 18833 121 24X
Fiche 50-400, 83/06/02, 8306140483

--8306140499 Corrected Page 3 to IE Insp Repts 50-400/83-07 & 50-401/83 07
" Division of Engineering & Radiological Safety Programs
83/04/18 1p 18833 122 24X Fiche 50-400, 83/06/02, 8306140483

--8306140503 Forwards IE Insp Repts 50-400/83-07 & 50-401/83 07 on 830308-11 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/04/12
UTLEY, E E Carolina Power & Light Co 2pp 18833 123 24X
Fiche 50-400, 83/06/02, 8306140483

--8306140512 IE Insp Repts 50-400/83-07 & 50-401/83-07 on 830308-11 Noncompliance noted documentation not available to confirm that matl had been upgraded to meet Class 1 requirements
MCFARLAND, C R , JACKSON, L H Region 2, Office of Director
UPRIGHT, C M Division of Engineering & Radiological Safety Programs 83/04/08 12pp, 18833 126 24X Fiche 50-400, 83/06/02, 8306140483

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/09, Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 229 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8306290524 Approves issuance of SALP rept Notes improvement in safety-related activities, emergency preparedness & security & safeguards Weaknesses in QA program will be monitored
O'REILLY, J P Region 2, Office of Director 83/06/14 UTLEY, E E Carolina Power & Light Co 5pp 24X Fiche 50-000, 83/06/14, 8306290524

--8306290531 Forwards SALP Repts 50-325/83-09, 50-324/83-09, 50-261/83-07, 50-400/83-10 & 50-401/83-10 for Jan 1982 - Jan 1983
Evaluation will be discussed in Raleigh, NC on 830510
LEWIS, R C Division of Project & Resident Programs 83/05/03
UTLEY, E E Carolina Power & Light Co 2pp 24X
Fiche 50-000, 83/06/14, 8306290524

--8306290537 SALP rept for Jan 1982 - Jan 1983
" Region 2, Office of Director 83/05/03 64pp 24X
Fiche 50-000, 83/06/14, 8306290524

--8306290553 Responds to 830503 SALP rept for Jan 1982 - Jan 1983 Reduced NRC attention may be appropriate for Category 1 re fire protection NRC attention should be maintained at normal levels for emergency preparedness
UTLEY, E E Carolina Power & Light Co 83/05/20 O'REILLY, J P
8306290524 16pp 24X Fiche 50-000, 83/06/14, 8306290524

--8306290555 Forwards replacement Page 2 to Attachment 2 of 830520 ltr which commented on SALP rept
EURY, L W Carolina Power & Light Co 83/05/27 O'REILLY, J P
Region 2, Office of Director 2pp 24X Fiche 50-000, 83/06/14, 8306290524

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety Related Equipment " 3vc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 03/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " 3vc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 03/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " 3vc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 03/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

S Reportable occurrences, LCRs & related correspondence

8306070231 Interim deficiency rept re main reactor trip breakers design discrepancy Initially reported on 830427 Westinghouse will replace undervoltage attachments, to accommodate new retaining ring Also reportable per Part 21
PARSONS, R M Carolina Power & Light Co 03/05/26 O'REILLY, J P
Region 2, Office of Director 1p 18746 105 24X
Fiche 50-400, 83/05/26, 8306070231

8306090046 Interim deficiency rept re failure to perform verification of anchor bolt matl type when tags lost (Item 131) Initially reported on 830503 Evaluation of anchor bolts continuing
Submittal of rept on reportability extended until 830805
PARSONS, R M Carolina Power & Light Co 03/06/01 O'REILLY, J P
Region 2, Office of Director 1p 18793 287 24X
Fiche 50-400, 83/06/01, 8306090046

8306090180 Third interim deficiency rept re reactor protection sys failure following secondary high energy line rupture Initially reported on 800707 Insulation of steam generator ref leg underway Also reportable per Part 21
PARSONS, R M Carolina Power & Light Co 03/06/01 O'REILLY, J P
Region 2, Office of Director 4pp 18792 271 24X
Fiche 50-400, 83/06/01, 8306090180

8306090191 Third interim deficiency rept re potential damage to safety injection charging pump following secondary side high energy line rupture (Item 38) Initially reported on 800707 Resolution under review Also reportable per Part 21
PARSONS, R M Carolina Power & Light Co 03/06/01 O'REILLY, J P
Region 2, Office of Director 1p 18796 086 24X
Fiche 50-400, 83/06/01, 8306090191

8306100254 Second interim rept on Item 104 re defective welds on 480-volt switchgear supplied by Brown-Overly Electric Co Initially reported on 830304 Major defects repaired Minor defects to be modeled in upcoming seismic test
PARSONS, R M Carolina Power & Light Co 03/06/03 O'REILLY, J P
Region 2, Office of Director 4pp 18807 038 24X
Fiche 50-400, 83/06/03, 8306100254

8306200116 Addendum 1 to final deficiency rept, Item 91, re welded studs on embedded strip plates Any testing performed by site receipt insp unit is in excess of code requirements since same procedure revealed problem
PARSONS, R M Carolina Power & Light Co 03/06/09 O'REILLY, J P
Region 2, Office of Director 2pp 18703 250 24X
Fiche 50-400, 83/06/09, 8306200116

8306270223 Interim deficiency & Part 21 repts re boric acid transfer pumps, Westinghouse Shop Order 20b, Item 113 Initially reported on 830113 Support bolting will be replaced & gusset stiffener spot welds supplemented by 830701
PARSONS, R M Carolina Power & Light Co 03/06/14 O'REILLY, J P
Region 2, Office of Director 4pp 18790 227 24X
Fiche 50-400, 83/06/14, 8306270223

8306280463 Interim deficiency rept re Item 121, welding deficiencies in main steam/feedwater support frames Initially reported on 830318 Extension requested until 830715 to submit complete evaluation Also reportable per Part 21
PARSONS, R M Carolina Power & Light Co 03/06/17 O'REILLY, J P
Region 2, Office of Director 1p 17018 274 24X
Fiche 50-400, 83/06/17, 8306280463

V Operator Examinations

8306140132 Requests approved ref matl re operator exams by 830425 Missing deadline will result in delay in administering exams Applications should be submitted at least 60 days prior to first exam scheduled for 830613
VERRELLI, D M Division of Project & Resident Programs 03/04/08
FURR, B J Carolina Power & Light Co 3pp 18839 086 24X
Fiche 50-400, 83/04/08, 8306140132

DOCKET 50-404 NORTH ANNA POWER STATION, UNIT 3

A Application/construction stage documents & correspondence

8306300036 Withdraws 820708 application to extend CP
SPENCER, W C Virginia Electric & Power Co 03/06/22 DENTON, H R.
Office of Nuclear Reactor Regulation, Director NOVAK, T H Division of Licensing 2pp 19120 306 24X Fiche 50-404, 83/06/22, 8306300036

DOCKET 50-407 UNIV OF UTAH RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8306140188 Forwards IE Insp Rept 50-407/83-01 on 830418-20 No noncompliance noted
SEIDLE, W C Region 4, Office of Director 03/05/11 JACOBBS, H R.
Utah, Univ of 2pp 18833 046 24X Fiche 50-407, 83/05/11, 8306140188

--8306140197 IE Insp Rept 50-407/83-01 on 830418-20 No noncompliance noted Major areas inspected licensee organization, operations & maint logs & operating procedures, internal review program, requalification program & emergency program
MURPHY, M E, JOHNSON, W D Region 4, Office of Director 03/05/11
3pp 18833 048 24X Fiche 50-407, 83/05/11, 8306140188

8306160189 Releases public version of emergency plan
FELTON, J M Division of Rules and Records 03/06/06 Document
Management Branch 1p 18873 093 24X Fiche 50-072, 83/06/06, 8306160189

--8306160194 Public version of "Emergency Plan for Training & Research Reactors " W/830512 ltr
SANDQUIST, G M, BROPHY, J J Utah, Univ of UTEC ME 82-100
02/11/01 Office of Nuclear Reactor Regulation, Director 27pp.
18873 096 24X Fiche 50-072, 83/06/06, 8306160189

G Inspection reports, IE Bulletins & correspondence

8306140188 Forwards IE Insp Rept 50-407/83-01 on 830418-20 No noncompliance noted
SEIDLE, W C Region 4, Office of Director 03/05/11 JACOBBS, H R.
Utah, Univ of 2pp 18833 046 24X Fiche 50-407, 83/05/11, 8306140188

--8306140197 IE Insp Rept 50-407/83-01 on 830418-20 No noncompliance noted Major areas inspected licensee organization, operations & maint logs & operating procedures, internal review program, requalification program & emergency program
MURPHY, M E, JOHNSON, W D Region 4, Office of Director 03/05/11
3pp 18833 048 24X Fiche 50-407, 83/05/11, 8306140188

DOCKET 50-409 LA CROSSE BOILING WATER REACTOR

F Security, medical, emergency & fire protection plans

8306210314 FOIA request for NRC records re security violations & safeguards events at nuclear facilities
OLDENBERG, O Scripps-Howard Newspapers 03/04/22 FELTON, J M.
Office of Administration 2pp 18725 198 24X
Fiche 50-000, 83/04/22, 8306210314

8306210306 Partial response to FOIA request for NRC records re security violations & safeguards events at nuclear facilities Repts listed on App A available in PDR Search for addl documents sub to request continuing
FELTON, J M Division of Rules and Records 03/05/16 OLDENBERG, O.
Scripps-Howard Newspapers 2pp 18925 196 24X
Fiche 50-000, 83/05/16, 8306210306

8306070311 Forwards revised emergency plan in partial response to NRC 830324 request for changes & clarifications to make plan more workable & readable W/d encl.
LINDER, F Dairyland Power Cooperative 03/06/01 HIND, J A
Division of Radiological & Materials Safety Programs 3pp 18741 089 24X Fiche 50-409, 83/06/01, 8306070311.

DOCKETED ITEMS

8306070332 Forwards rev to emergency plan to bring plan in conformance w/IE Emergency Preparedness Insp Rept 50-409/82-15 Findings
W/o encl
LINDER, F Dairyland Power Cooperative 83/06/01 KEPPLEN, J G
Region 3, Office of Director 2pp 18741 155 24X
Fiche 50-409, 83/06/01, 8306070332

8306160269 Releases public version of Issue 9 to emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/06/06 Document
Management Branch 1p 18872 151 24X Fiche 50-409, 83/06/06, 8306160269

--8306160279 Public version of Issue 9 to Emergency Plan Implementing Procedure EPP-2, "Organization & Operations During Emergencies" W/830523 ltr
LINDER, F Dairyland Power Cooperative 83/05/10 CRUTCHFIELD, D
Operating Reactors Branch 5 17pp 18872 152 24X
Fiche 50-409, 83/06/06, 8306160269

8306130311 Ack receipt of 830520 ltr informing NRC of steps taken to correct violations noted in IE insp
PAPERIELLO, C J Region 3, Office of Director 83/06/10
LINDER, F W Dairyland Power Cooperative 1p 18823 299 24X
Fiche 50-409, 83/06/10, 8306130311

--8306130314 Responds to NRC 830324 ltr re violations noted in IE insp
Corrective actions Lock & Dam 8 will be removed as backup meteorological site & revised joint frequency distribution resulting from meteorological data submitted
LINDER, F Dairyland Power Cooperative 83/05/20 HIND, J A
Division of Radiological & Materials Safety Programs 3pp 18823 300 24X Fiche 50-409, 83/06/10, 8306130311

8306210292 Forwards exemption from 10CFR50, App E, Section IV F 1 full-scale emergency preparedness exercise requirements, in response to 830408 request Next full-scale exercise scheduled for May or June 1984
CRUTCHFIELD, D Operating Reactors Branch 5 83/06/20 LINDER, F
Dairyland Power Cooperative 3pp 18915 139 24X
Fiche 50-409, 83/06/20, 8306210292

--8306210299 Exemption from 10CFR50, App E, Section IV F 1 full-scale emergency preparedness exercise requirements One-time delay of emergency exercises will not significantly affect state of emergency preparedness
EISENHUT, D O Division of Licensing 83/06/20 Dairyland Power Cooperative App 18915 142 24X Fiche 50-409, 83/06/20, 8306210292

G Adjudicatory correspondence

8306060325 Notice of ASLB reconstitution C Dechhoefer, chairman & QC Anderson & HC Paxton, members
COTTER, B P Atomic Safety and Licensing Board Panel 83/06/03
2pp 18727 001. 24X Fiche 50-409, 83/06/03, 8306060325

8306070356 Order undertaking sua sponte review of ASLB 830421 initial decision. Initial decision not to be treated as final agency action pending further order
SHOENAKER, C J Atomic Safety and Licensing Appeal Panel 83/06/03
2pp 18742 123 24X Fiche 50-409, 83/06/03, 8306070356

8306300134 Notice of ASLB reconstitution AS Rosenthal, chairman & JH Buck & TS Moore, members.
SHOENAKER, C J Atomic Safety and Licensing Appeal Panel 83/06/27
1p 19122 316 24X Fiche 50-409, 83/06/27, 8306300134.

D Advisory Committee on Reactor Safeguards reports & correspondence

8306010199 Summarizes ACRS 277th meeting on 830512-14 re SEP review of plant Defers review of full-term GL application until NRC completes action on remaining SEP topics, unresolved safety issues & TMI action items
EBERSOLE, J C ACRS - Advisory Committee on Reactor Safeguards 83/05/17 PALLADINO, J Commissioners 3pp 18696 197 24X
Fiche 50-409, 83/05/17, 8306010199

8306150330 Advises that NRC will revise draft integrated plant SAR reflecting addl info provided by licensee responding to recommendations & comments by NRC consultants & incorporating licensee scheduler commitments
DIRCKB, W J Office of the Executive Director for Operations 83/06/08, EBERSOLE, J C ACRS - Advisory Committee on Reactor Safeguards 3pp 18870 001 24X Fiche 50-409, 83/06/08, 8306150330

P Operating license stage documents & correspondence

8306070079 Forwards schedule for completion of full-term license SIP commitments contained in NUREG-0827 Three items resolved after issuance of draft NUREG 0827 listed
LINDER, F Dairyland Power Cooperative 83/06/02 CRUTCHFIELD, D
Operating Reactors Branch 5 10pp 18738 206 24X
Fiche 50-409, 83/06/02, 8306070079

8306100184 Forwards comments on draft NUREG-0827, "Integrated Plant Safety Assessment, SEP," to help improve rept accuracy
LINDER, F Dairyland Power Cooperative 83/06/02 CRUTCHFIELD, D
Operating Reactors Branch 5 5pp 18806 024 24X
Fiche 50-409, 83/06/02, 8306100184

8306140707 Forwards addl info re NUREG-0737, Items II F 1 4, II F 1 5 & II F 1 6 Due to small reactor size & low population density, existing equipment adequate for safe operation
LINDER, F Dairyland Power Cooperative 83/06/03 CRUTCHFIELD, D
Operating Reactors Branch 5 7pp 18841 279 24X
Fiche 50-409, 83/06/03, 8306140707

8306150277 Application for amend to License DMR-45, adding Sections 4/5 3 & 4/5 4, "Radioactive Effluents" & "Radiological Environ Monitoring," respectively, to Tech Specs
LINDER, F Dairyland Power Cooperative 83/06/08 CRUTCHFIELD, D
Operating Reactors Branch 5 5pp 18849 207 24X
Fiche 50-409, 83/06/08, 8306150277

--8306150283 Proposed revs to Tech Specs, adding Sections 4/5 3 & 4/5 4, "Radioactive Effluents" & "Radiological Environ Monitoring," respectively, incorporating 10CFR50, App I, requirements
* Dairyland Power Cooperative 83/06/08 5pp 18849 212 24X
Fiche 50-409, 83/06/08, 8306150277

8306170478 Notification of 8307 meeting w/util & NER in LaGrasse, WI to discuss seismic open items addressed in SEP Topic III-6 SER
CHENG, T M Systematic Evaluation Program Branch 83/06/10
RUSSELL, W T Systematic Evaluation Program Branch 3pp 18894 322 24X Fiche 50-409, 83/06/10, 8306170478

8306210066 Forwards addl info re SEP Topic III-6, "Seismic Design Consideration," providing addl detail on LACBWR & Genoa J stacks seismic capability
LINDER, F Dairyland Power Cooperative 83/06/13 CRUTCHFIELD, D
Operating Reactors Branch 5 2pp 18915 080 24X
Fiche 50-409, 83/06/13, 8306210066

--8304290092 Forwards calculations of effect of flue openings at base of Genoa III chimney stack using ACI 307-79 criteria
FINNAN, C F Nuclear Energy Service, Inc 83/04/15 CHENG, T
Systematic Evaluation Program Branch 10pp 18915 082 24X
Fiche 50-409, 83/06/13, 8306210066

--8306210122 Forwards stress calculations for LACBWR stack using ACI 307-79 working stress method, per 830329 telcon
Calculations performed at weakest node of Nuclear Energy Svcs stack model
LANE, G Dairyland Power Cooperative 83/04/05 CHENG, T
Systematic Evaluation Program Branch 6pp 18915 113 24X
Fiche 50-409, 83/06/13, 8306210066

8306210132 Responds to R Dudley 830607 telcon request for util commitment to incorporate procedures in Vol I of operations manual re instructions to obtain addl fuel for emergency svc water supply sys pumps
LINDER, F Dairyland Power Cooperative 83/06/14 CRUTCHFIELD, D
Operating Reactors Branch 5 2pp 18918 120 24X
Fiche 50-409, 83/06/14, 8306210132

8306280197 Forwards safety evaluation of util design review of TMI Action Item II B 2 2, "Plant Shielding" Plant shielding adequate to assure post-accident access to vital areas
CRUTCHFIELD, D Operating Reactors Branch 5 83/06/27 LINDER, F
Dairyland Power Cooperative 3pp 19015 074 24X
Fiche 50-409, 83/06/27, 8306280197

Q Inspection reports, IE Bulletins & correspondence

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/24 Consolidated Edison Co of New York, Inc
125pp 18831 043 24X Fiche 50-000, 83/05/24, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

DOCKETED ITEMS

283

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000,83/05/31,8305110461

8306070332 Forwards rev to emergency plan to bring plan in conformance w/IE Emergency Preparedness Insp Rept 50-409/82-15 findings w/c encl
LINDER, F Dairyland Power Cooperative 83/06/01 KEPPLER, J G Region 3, Office of Director 2pp 18741 155 24X Fiche 50-409,83/06/01,8306070332

8306070074 Confirms 830609 meeting to discuss regulatory improvement program Meeting will provide NRC w/status & effectiveness of program
KEPPLER, J G Region 3, Office of Director 83/06/02 LINDER, F W Dairyland Power Cooperative 1p 18739 207 24X Fiche 50-409,83/06/02,8306070074

8306100145 Confirms 830609 onsite enforcement conference to discuss discovery of containment bldg pressure transmitter capped sensing line
MORRELIUS, C E Division of Project & Resident Programs 83/06/07 LINDER, F W Dairyland Power Cooperative 1p 18001 211 24X Fiche 50-409,83/06/07,8306100145

8306230411 Forwards IE Insp Rept 50-409/83-06 on 830509 No noncompliance noted
LITTLE, W B Region 3, Office of Director 83/06/08 LINDER, F W Dairyland Power Cooperative 2pp 18941 154 24X Fiche 50-409,83/06/08,8306230411

--8306230420 IE Insp Rept 50-409/83-06 on 830509 No noncompliance noted Major areas inspected licensee action re IE Bulletin 80-11, "Masonry Wall Design "
MORTON, J F, WILLIAMS, C C Region 3, Office of Director 83/06/08 3pp 18941 156 24X Fiche 50-409,83/06/08,8306230411

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fiche 50-000,83/06/09,8305110464

8306130311 Ack receipt of 830520 ltr informing NRC of steps taken to correct violations noted in IE insp
PAPERIELLO, C J Region 3, Office of Director 83/06/10 LINDER, F W Dairyland Power Cooperative 1p 18823 299 24X Fiche 50-409,83/06/10,8306130311

--8306130314 Responds to NRC 830324 ltr re violations noted in IE insp Corrective actions Lock & Dam B will be removed as backup meteorological site & revised joint frequency distribution resulting from meteorological data submitted
LINDER, F Dairyland Power Cooperative 83/06/20 HIND, J A Division of Radiological & Materials Safety Programs 3pp 18823 300 24X Fiche 50-409,83/06/10,8306130311

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225 24X Fiche 50-000,83/06/13,8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000,83/06/13,8306090010

8306300226 Forwards IE Insp Rept 50-409/83-07 on 830516-18 No noncompliance noted
PAPERIELLO, C J Region 3, Office of Director 83/06/14 LINDER, F W Dairyland Power Cooperative 2pp 19119 173 24X Fiche 50-409,83/06/14,8306300226

--8306300231 IE Insp Rept 50-409/83-07 on 830516-18 No noncompliance noted Major areas inspected status of post-TMI requirements
PAUL, R A, GREGER, L R Region 3, Office of Director 83/06/14 3pp 19119 175 24X Fiche 50-409,83/06/14,8306300226

8306270382 Responds to IE Bulletin 83-05, "ASME Nuclear Code Pumps & Spare Parts Mfg by Hayward Tyler Pump Co " Subj pumps not in use or planned for use at Facility
LINDER, F Dairyland Power Cooperative 83/06/16 KEPPLER, J G Region 3, Office of Director 2pp 18994 152 24X Fiche 50-409,83/06/16,8306270382

8306270381 Forwards IE Insp Rept 50-409/83-05 on 830301-0515 & notice of violation
SHAHER, W D Region 3, Office of Director 83/06/17 LINDER, F W Dairyland Power Cooperative 2pp 18993 241 24X Fiche 50-409,83/06/17,8306270381

--8306270383 Notice of Violation from insp on 830301-0515
SHAHER, W D Region 3, Office of Director 83/06/17 1p 18993 243 24X Fiche 50-409,83/06/17,8306270381

--8306270389 IE Insp Rept 50-409/83-05 on 830301-0515 Noncompliance noted emergency core spray pump IB failed to operate when challenged due to improper maint
BRANCH, M W, DUDRY, N E, JACKIW, I N Region 3, Office of Director 83/06/17 8pp 18993 244 24X Fiche 50-409,83/06/17,8306270381

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 115pp 19021 179 24X Fiche 50-000,83/06/22,8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Bys Causing Inoperability of Safety-Related Equipment," Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000,83/06/22,8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000,83/06/23,8305110479

8305110483 IE Info Notice 83-43, "Improper Bettings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000,83/06/24,8305110483

R Periodic operating reports & related correspondence

8306020291 Monthly operating rept for Mar 1983 W/83040B ltr
OODMAN, L S, LINDER, F Dairyland Power Cooperative 83/04/06 9pp 18670 332 24X Fiche 50-409,83/04/06,8306020291

8306160378 Monthly operating rept for Apr 1983 W/830509 ltr
OODMAN, L S, LINDER, F Dairyland Power Cooperative 83/05/04 Office of Resource Management, Director 8pp 18839 345 24X Fiche 50-409,83/05/04,8306160378

B Reportable occurrences, LERs & related correspondence

8306070040 RD 83-03 on 830527, one of two redundant containment bldg pressure sensing lines found capped Caused by personnel error. Cap removed Broken identification tag replaced. Line modified to prevent future capping W/830609 ltr
LINDER, F Dairyland Power Cooperative 83/05/31 KEPPLER, J G Region 3, Office of Director 1p 18739 360 24X Fiche 50-409,83/05/31,8306070040.

8306170376 LER 83-003/017-0 on 830527, two containment bldg pressure sensing lines found capped Caused by personnel error. Cap removed Broken identification tag replaced. Line modified to prevent future capping W/830609 ltr
OODMAN, L S, LINDER, F Dairyland Power Cooperative 83/06/09 KEPPLER, J G Region 3, Office of Director 4pp 18880 226 24X Fiche 50-409,83/06/09,8306170376

8306270337 LER 83-002/031-0 on 830520, during leakage rate testing, electrical penetration unit 5 leakage found above Tech Spec limit Caused by cracked gland on individual penetration RBB. Assembly replaced W/830616 ltr
OODMAN, L S, LINDER, F Dairyland Power Cooperative 83/06/16 KEPPLER, J G Region 3, Office of Director 4pp 18993 121 24X Fiche 50-409,83/06/16,8306270337.

8306300006 Forwards Special Rept 83-01 re sampling analysis results & addl info concerning occasions when reactor thermal power changed by more than 15% within 1 h while in Operational Condition 1 or 2
LINDER, F Dairyland Power Cooperative 83/06/22 KEPPLER, J G Region 3, Office of Director, 12pp 19120 321 24X Fiche 50-409,83/06/22,8306300006

DOCKETED ITEMS

DOCKET 50-410 NINE MILE POINT NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8306010027 Notification of 830523 significant licensee meeting w/utills in King of Prussia, PA to discuss current const problems LAZARUS, H J Region 1, Office of Director 83/05/17 Region 1, Office of Director 1p 18687 177 24X Fiche 50-410, 83/05/17, 8306010027

8306090205 Notification of 830607 meeting w/utills & B&W in Cherry Hill, NJ to discuss GDC 51 compliance (fracture prevention of containment pressure boundary) HAYOHEY, M, WEINKAM, E Licensing Branch 2 83/06/02 NOVAK, T M Assistant Director for Licensing 4pp 18809 225 24X Fiche 50-000, 83/06/02, 8306090205

8306080273 Forwards repts re aquatic ecology of facility & "Nine Mile Point Aquatic Ecology Summary (1973-B1)," in response to NRC Acceptance Review Requests E291 A(a) & E291 I(b) Bibliography of publications encl MANGAN, C V Niagara Mohawk Power Corp 83/06/06 EISENHUT, D O Division of Licensing 3pp 18769 025 24X Fiche 50-410, 83/06/06, 8306080273

--8306080274 "Nine Mile Point Aquatic Ecology Summary (1973-B1)" * Lawler, Matusky & Stelly Engineers 83/05/31 258pp 18769 028 24X Fiche 50-410, 83/06/06, 8306080273

--8306080294 "Submerged Multipoint Diffuser Thermal Discharges From Conceptual Design to Post-Operational Survey," presented at Proceedings of Conference on Waste Heat Mgt & Utilization on 770509-11, Miami Beach, FL TSAI, Y J, BURRIS, B E Stone & Webster Engineering Corp 77/05/09 22pp 18769 341 24X Fiche 50-410, 83/06/06, 8306080273

--8306080298 "Fish Return Sys." presented at Proceedings of 25th Annual Hydraulics Div Specialty Conference, ASCE at Texas A&M University, College Station, TX, Aug 1977 MUSSALLI, Y O, TAFT, E P Stone & Webster Engineering Corp 77/08/31 9pp 18770 001 24X Fiche 50-410, 83/06/06, 8306080273

--8306080303 "Designing Offshore Intakes for Fish Protection," presented at ASCE Natl Convention, Atlanta, GA in Oct 1979 MUSSALLI, Y O, TAFT, E P Stone & Webster Engineering Corp LARSEN, J Alden Research Laboratory 79/10/31 21pp 18770 010 24X Fiche 50-410, 83/06/06, 8306080273

--8306080306 "Influence of Fish Protection Considerations on Design of Cooling Water Intakes," presented at Joint Intl Symposium on Design & Operation of Fluid Machinery at CO State Univ, Fort Collins, CO on 780612-14 MUSSALLI, Y O, HOFMANN, P, TAFT, E P Stone & Webster Engineering Corp 78/06/12 12pp 18770 031 24X Fiche 50-410, 83/06/06, 8306080273

--8306080312 "Developing Adequate Hydrothermal Monitoring Program," presented at AIF Topical Conference on Water Quality Considerations For Siting & Operating Nuclear Power Plants on 721001-04 in Washington, DC BRODFELD, D Stone & Webster Engineering Corp 72/10/01 29pp 18770 043 24X Fiche 50-410, 83/06/06, 8306080273

--8306080328 "Engineering Implications of New Fish Screening Concepts," presented at Proceedings of Fourth Natl Workshop on Entrainment & Impingement on 771205-07 in Chicago, IL MUSSALLI, Y O, TAFT, E P, HOFMANN, P Stone & Webster Engineering Corp 77/12/05 16pp 18770 115 24X Fiche 50-410, 83/06/06, 8306080273

--8306080338 "Environ Engineering Studies for Thermal Discharges at Coastal Sites," presented at 1972 Joint Power Generation Conference on 720911 in Boston, MA MATCHETT, D L, TSAI, Y J Stone & Webster Engineering Corp 72/09/11 34pp 18770 140 24X Fiche 50-410, 83/06/06, 8306080273

--8306080343 "Lab Evaluation of Larval Fish Impingement & Diversion Sys.," presented at Proceedings of Workshop of Advanced Intake Technology on 810422-24 in San Diego, CA TAFT, E P, BERGER, R H, LARSEN, J Stone & Webster Engineering Corp 81/04/22 22pp 18770 174 24X Fiche 50-410, 83/06/06, 8306080273

--8306080351 "Experimental Approach to Design of Sys for Alleviating Fish Impingement at Existing & Proposed Power Plant Intake Structures," presented at Third Natl Workshop on Entrainment & Impingement in New York City, NY in Feb 1976 TAFT, E P, HOFMANN, P, EISELE, P J Stone & Webster Engineering Corp 76/02/29 13pp 18770 196 24X Fiche 50-410, 83/06/06, 8306080273

--8306080360 "Biological Engineering Investigation of Angled Flush Fish Diversion Screens," presented at 25th Annual Hydraulics Div Specialty Conference, ASCE at Texas A&M Univ, College Station, TX on 770810-12 TAFT, E P, MUSSALLI, Y O Stone & Webster Engineering Corp 77/08/10 10pp 18770 209 24X Fiche 50-410, 83/06/06, 8306080273

8306140440 Responds to 830324 request for addl info re application for OL Info addresses Encls 1-15 re distribution list for environ rept & FBAR, safety-related structure sys & components controlled by QA program MANGAN, C V Niagara Mohawk Power Corp 83/06/10 EISENHUT, D O Division of Licensing 3pp 18838 029 24X Fiche 50-410, 83/06/10, 8306140440

8306280296 Advises that applicant proposed tech Specs do not represent SRP difference since current generic STS used as bases MIRAGLIA, F J Assistant Director for Safety Assessment 83/06/21 NOVAK, T M Assistant Director for Licensing 1p 84X Fiche 50-410, 83/06/21, 8306280296

C Utility Environmental Report (ER), amends & correspondence

8306220096 Forwards Suppl 2 to environ rept - OL stage MANGAN, C V Niagara Mohawk Power Corp 83/06/06 EISENHUT, D O Division of Licensing 1p 18932 275 24X Fiche 50-410, 83/06/06, 8306220096

--8306220107 Suppl 2 to environ rept - OL stage * Niagara Mohawk Power Corp 83/06/30 238pp 18933 321 24X Fiche 50-410, 83/06/06, 8306220096

8306200250 Forwards Affidavit of Svc indicating that Amend 3 & Suppl 2 to FBAR & environ rept - OL stage have been provided to appropriate parties as requested in NRC 830329 ltr MANGAN, C V Niagara Mohawk Power Corp 83/06/14 EISENHUT, D O Division of Licensing 2pp 18901 177 24X Fiche 50-410, 83/06/14, 8306200250

F Security, medical, emergency & fire protection plans

8306130303 Forwards response to 830329 questions re physical security plan Response withheld (ref 10CFR73.21) BURNER, J J Niagara Mohawk Power Corp 83/06/08 EISENHUT, D O Division of Licensing 1p 18823 330 24X Fiche 50-410, 83/06/08, 8306130303

G Adjudicatory correspondence

8306220123 Petition by New York State Energy Dfc to participate as interested State Certificate of Svc encl KLIMBERG, S B New York, State of, Energy Office 83/06/07 Commissioners 3pp 18926 100 24X Fiche 50-410, 83/06/07, 8306220123

8306160575 Forwards Multiple Intervenor petition to intervene WHITE, A F DeGraff, Foy, Conway & Holt-Harris 83/06/10 Docketing & Services Branch 1p 18366 806 24X Fiche 50-410, 83/06/10, 8306160575

--8306160582 Petition to intervene & request for hearing Licensing decision will directly affect reliable supply & price of energy to member facilities Affidavit of Svc encl WHITE, A F Affiliation Unknown WHITE, A F DeGraff, Foy, Conway & Holt-Harris 83/06/10 Commissioners 4pp 18866 307 24X Fiche 50-410, 83/06/10, 8306160575

8306220070 Notice of ASLB constitution MD Margulies chairman & EE Hill & PM Purdom, members COTTER, D P Atomic Safety and Licensing Board Panel 83/06/17 2pp 18930 170 24X Fiche 50-410, 83/06/17, 8306220070

8306270294 Answer to New York State Energy Dfc 830607 petition to participate as interested state Applicants raise objection to request if hearing held Notices of appearance & Certificate of Svc encl CONNER, T B Niagara Mohawk Power Corp CONNER, T B Conner & Wetterhahn 83/06/22 Atomic Safety and Licensing Board Panel 3pp 18996 185 24X Fiche 50-410, 83/06/22, 8306270294

8306240273 Response supporting New York State Energy Dfc 830607 petition for leave to participate as interested state if hearing held as result of contested issue Certificate of Svc encl BORDENICK, B M Hearing Branch 3 83/06/23 Atomic Safety and Licensing Board Panel 4pp 18980 094 24X Fiche 50-410, 83/06/23, 8306240273

830624027B Response opposing Multiple Intervenors 830610 petition for leave to intervene in OL proceeding Requisite interest & standing not established Specific aspects to be litigated not identified Certificate of Svc encl
BORDENICK, B M Hearing Branch 3 03/06/23 Atomic Safety and Licensing Board Panel 12pp 18979 2/4 24X Fiche 50-410, 83/06/23, 830624027B

830624035S Notices of appearance in proceeding Certificate of Svc encl
BORDENICK, B M, PERLIS, R Q Hearing Branch 3 83/06/23 3pp 18980 131 24X Fiche 50-410, 83/06/23, 830624035S

830628055D Response re Multiple Intervenors 830610 petition for leave to intervene Multiple Intervenors counsel withdrawal of petition to intervene demonstrates that no basis exists for hearing Certificate of Svc encl
CONNER, T B Niagara Mohawk Power Corp 83/06/23 Commissioners 2pp 19017 305 24X Fiche 50-410, 83/06/23, 830628055D

K Utility Final Safety Analysis Report (FSAR) & amendments

8306220096 Forwards Amend 3 to FSAR & Suppl 2 to environ rept - OL stage (filed in PDR Category C)
MANGAN, C V Niagara Mohawk Power Corp 83/06/06 EISENHUT, D Q Division of Licensing 1p 18932 275 24X Fiche 50-410, 83/06/06, 8306220096

--8306220104 Amend 3 to FSAR
" Niagara Mohawk Power Corp 83/06/30 405pp 18932 276 24X Fiche 50-410, 83/06/06, 8306220096

830622025B Forwards Affidavit of Svc indicating that Amend 3 & Suppl 2 to FSAR & environ rept - OL stage have been provided to appropriate parties as requested in NRC 830329 ltr
MANGAN, C V Niagara Mohawk Power Corp 83/06/14 EISENHUT, D Q Division of Licensing 2pp 18901 177 24X Fiche 50-410, 83/06/14, 830622025B

Q Inspection reports, IE Bulletins & correspondence

8306220149 Discusses IE insp on 820830-0950 & forwards notice of violation & proposed imposition of civil penalty
ALLAN, J M Region 1, Office of Director 83/04/26 RHODE, G K Niagara Mohawk Power Corp 3pp 18951 342 24X Fiche 50-410, 83/04/26, 8306220149

--8306220154 Notice of violation & proposed imposition of civil penalty in amount of \$100,000 Noncompliance noted improper implementation of QA program by S&W, principal contractor for util, & falsification of QC records
ALLAN, J M Region 1, Office of Director 83/04/26 3pp 18937 345 24X Fiche 50-410, 83/04/26, 8306220149

8306210200 Responds to IE Bulletin 82-04 re deficient Bunker Ramo Co primary containment electrical penetration assemblies
Assemblies not used at facility
MANNO, S F Niagara Mohawk Power Corp 83/05/25 ALLAN, J M Region 1, Office of Director 2pp 18918 138 24X Fiche 50-410, 83/05/25, 8306210200

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet"
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at DWRs"
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306140441 Ack receipt of 830406 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-410/83-01
STAROSTECKI, R Division of Project & Resident Programs 83/05/31 RHODE, G K Niagara Mohawk Power Corp 1p 18838 025 24X Fiche 50-410, 83/05/31, 8306140441

--8306140445 Responds to NRC 830228 ltr re violations noted in IE Insp Rept 50-410/83-01 Corrective actions foremen trained in importance of making welding procedures available to welder & procedures available at weld rod issue stations
MANGAN, C V Niagara Mohawk Power Corp 83/04/06 STAROSTECKI, R Division of Project & Resident Programs 3pp 18938 026 24X Fiche 50-410, 83/05/31, 8306140441

8306140554 Ack receipt of 830525 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-410/82-14
STAROSTECKI, R Division of Project & Resident Programs 83/06/02 RHODE, G K Niagara Mohawk Power Corp 1p 18834 208 24X Fiche 50-410, 83/06/02, 8306140554

--8306140558 Provides addl response to IE Insp Rept 50-410/82-14, S&W field QC performing in-process insp of bolting crews to assure compliance w/installation section of RCRBBJ spec
MANNO, S F Niagara Mohawk Power Corp 83/05/25 STAROSTECKI, R Division of Project & Resident Programs 1p 18834 209 24X Fiche 50-410, 83/06/02, 8306140554

--8306140564 Responds to NRC 830110 ltr re violations noted in IE Insp Rept 50-410/82-14 Corrective actions S&W will perform addl torque tests on 200 bolts installed by each contractor involved in safety-related high strength bolting
MANNO, S F, DISE, D P Niagara Mohawk Power Corp 83/03/09 STAROSTECKI, R Division of Project & Resident Programs 7pp 18834 210 24X Fiche 50-410, 83/06/02, 8306140564

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations"
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards"
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables"
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers"
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment"
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions"
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co. of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8306270122 Requests extension of time until & including 830705, to complete response to 830426 notice of violation & proposed imposition of civil penalty Addl time necessary to review & edit final response & to coordinate review w/S&W.
WETTERHAHN, M J Conner & Wetterhahn WETTERHAHN, M J Niagara Mohawk Power Corp 83/06/23 DEYOUNG, R Director's Office, Office of Inspection and Enforcement 2pp 18988 018 24X Fiche 50-410, 83/06/23, 8306270122

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints"
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

8305110488 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device"
Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 123pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110488

R Periodic operating reports & related correspondence

8306080273 Forwards rpts re aquatic ecology of facility & "Nine Mile Point Aquatic Ecology Summary (1973-81)," in response to NRC Acceptance Review Requests E291 6(a) & E291 11(b).
Bibliography of publications encl
MANGAN, C V Niagara Mohawk Power Corp 83/06/06 EISENHUT, D Q Division of Licensing 3pp 18769 025 24X Fiche 50-410, 83/06/06, 8306080273

--8306080274 "Nine Mile Point Aquatic Ecology Summary (1973-81),"
* Lawler, Matysky & Skelly Engineers 83/05/31 258pp 18769 028 24X Fiche 50-410, 83/06/06, 8306080273

DOCKETED ITEMS

B Reportable occurrences, LERs & related correspondence

8306010493 Final deficiency rept re undersized Power Generation control complex floor module welds Initially reported on 830207 Welds inspected & accepted Procedures revised to require weld leg length verification using fillet weld gauge
MANNO, B F. Niagara Mohawk Power Corp 83/05/20 STAROSTECKI, R
Division of Project & Resident Programs 3pp 18674.315 24X
Fiche 50-410, 83/05/20, 8306010493

8306200262 Interim deficiency rept re nonconformance of pipe fittings mfg by Tube-Line Corp Initially reported on 830422 Final rept expected by 830919
MANNO, B F. Niagara Mohawk Power Corp 83/05/25 STAROSTECKI, R
Division of Project & Resident Programs 2pp 18901 105 24X
Fiche 50-410, 83/05/25, 8306200262

8306210195 Interim deficiency rept re failure of main steam safety relief valve actuator during environ qualification testing Initially reported on 830503 Failure due to seals in actuator assembly Investigation ongoing
MANNO, B F. Niagara Mohawk Power Corp 83/06/01 STAROSTECKI, R
Division of Project & Resident Programs 2pp 18914 158 24X
Fiche 50-410, 83/06/01, 8306210195

8306280605 Final deficiency rept re faulty Clow Corp valves used in svc water, LPCS & RHR sys. Initially reported on 820523 Valves returned to manufacturer for heat treatment rework. Completion expected by 830831
MANNO, B F. Niagara Mohawk Power Corp 83/06/02 STAROSTECKI, R
Division of Project & Resident Programs 2pp 19016 021 24X
Fiche 50-410, 83/06/02, 8306280605

8306210182 Final deficiency rept re QA inspector certification Initially reported on 830429 Qualification/certification records reviewed & found complete Deficiency not reportable per 10CFR50.55(e)
DISE, D P. Niagara Mohawk Power Corp 83/06/03 STAROSTECKI, R
Division of Project & Resident Programs 2pp 18915.254 24X
Fiche 50-410, 83/06/03, 8306210182

8306280597 Final deficiency rept re weld radiograph indications on Associated Piping & Engineering Corp recirculation piping spool piece Initially reported on 830113 Discontinuity excavated, repaired & verified per final NDE
DISE, D P. Niagara Mohawk Power Corp 83/06/13 STAROSTECKI, R
Division of Project & Resident Programs 2pp 19018 195 24X
Fiche 50-410, 83/06/13, 8306280597

8306280255 Final deficiency rept re failure to obtain ambient temp for HPCS diesel generator equipment qualification documentation. Initially reported on 820805 OE provided operating experience info to support qualification.
DISE, D P. Niagara Mohawk Power Corp 83/06/20, STAROSTECKI, R
Division of Project & Resident Programs 3pp 19015 022 24X
Fiche: 50-410, 83/06/20, 8306280255

V. Operator Examinations

8306140322 Requests attendance at 830627 meeting in King of Prussia, PA to discuss transfer of reactor operator licensing function from Bethesda, MD to Region I ofc
STAROSTECKI, R. Division of Project & Resident Programs 83/06/09
RHODE, O. K. Niagara Mohawk Power Corp. 2pp 18832 210 24X
Fiche: 50-410, 83/06/09, 8306140322.

DOCKET 50-412 BEAVER VALLEY POWER STATION, UNIT 2

A Application/construction stage documents & correspondence

8306020013 Requests mgt meeting on 830607 to discuss licensing review of OL application. List of info to be highlighted included
KNIGHTON, G W. Licensing Branch 3 83/05/13 WOOLFEVER, E J
Duquesne Light Co. 3pp 18702 344 24X Fiche 50-412, 83/05/13, 8306020013

8306020491 Notification of 830523 meeting w/utl in Bethesda, MD to discuss fracture toughness of mats in containment pressure boundary
LAZOL, L. Licensing Branch 3 83/05/16 KNIGHTON, G W. Licensing Branch 3 3pp 18715.177 24X Fiche 50-412, 83/05/16, 8306020491.

8306150149 Forwards FR notice of receipt of application for OL, notice of availability of environ rept & notice of opportunity for hearing.
KNIGHTON, G W. Licensing Branch 3 83/05/19 WOOLFEVER, E J
Duquesne Light Co 3pp 18870 079 24X Fiche 50-412, 83/05/19, 8306150149

--8306150150 Notice of receipt of application for OL, notice of availability of environ rept, notice of consideration of issuance of OL & notice of opportunity for hearing
KNIGHTON, G W. Licensing Branch 3 83/05/19 9pp 18870 080 24X Fiche 50-412, 83/05/19, 8306150149

8306030034 Notification of 830607 meeting w/utl in Bethesda, MD to discuss plans for review of OL application
LAZOL, L. Licensing Branch 3 83/05/24 KNIGHTON, G W. Licensing Branch 3 3pp 18733 176 24X Fiche 50 412, 83/05/24, 8306030034

C Utility Environmental Report (ER), amends & correspondence

8306090401 Advises that general info. filed in environ rept - OL stage & FSAR, sufficiently complete for docketing application & initiation of safety & environ reviews Projected fuel date is 831231
EISENHUT, D G. Division of Licensing 83/05/04 WOOLFEVER, E J
Duquesne Light Co 67pp 18815 078 24X Fiche 50-412, 83/05/04, 8306090401

8306150149 Forwards FR notice of receipt of application for OL, notice of availability of environ rept & notice of opportunity for hearing
KNIGHTON, G W. Licensing Branch 3 83/05/19 WOOLFEVER, E J
Duquesne Light Co 3pp 18870 079 24X Fiche 50-412, 83/05/19, 8306150149

--8306150150 Notice of receipt of application for OL, notice of availability of environ rept, notice of consideration of issuance of OL & notice of opportunity for hearing
KNIGHTON, G W. Licensing Branch 3 83/05/19 9pp 18870 080 24X Fiche 50-412, 83/05/19, 8306150149

8306140365 Comments on environ rept - OL stage Calculations utilizing recent data, scheduled shutdowns in summertime only & rev to support conclusion for downstream phytoplankton sites recommended
KULP, C J. Interior, Dept. of Fish & Wildlife Service 83/06/04
MCINTIRE, W. Duquesne Light Co 2pp 18832 141 24X
Fiche 50-412, 83/06/04, 8306140365

G Inspection reports, IE Bulletins & correspondence

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl
TAYLOR, J H. Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 113pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8306060289 Ack receipt of 830504 ltr Confirms understanding that CP holder has sole reporting obligations per 10CFR50.55(e) Part 21 reporting requirements excused if util awaits NRC adequately informed of defect or failures
ALLAN, J H. Region I, Office of Director 83/05/26 WOOLFEVER, E J
Duquesne Light Co 1p 18729 039 24X Fiche 50 412, 83/05/26, 8306060289

--8306060293 Discusses role & responsibility of 10CFR50.55(e) reporting Westinghouse directed to rept all future potential significant deficiency findings for Facility only to util & util will rept to NRC
WOOLFEVER, E J. Duquesne Light Co 83/05/04 ALLAN, J H. Region I, Office of Director 3pp 18729 040 24X Fiche 50-412, 83/05/26, 8306060289

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at DHRs" Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306150349 Ack receipt of 830520 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-412/83-04
STAROSTECKI, R. Division of Project & Resident Programs 83/06/03 WOOLFEVER, E J. Duquesne Light Co 1p 18847 147 24X
Fiche 50-412, 83/06/03, 8306150349

--8306150355 Responds to NRC 830408 ltr re violations noted in IE Insp Rept 50-412/83-04 Corrective actions engineering analysis completed for piping sys presently welded to containment penetration upheld by support further down pipe
WOOLFEVER, E J. Duquesne Light Co 83/05/20 STAROSTECKI, R
Division of Project & Resident Programs 3pp 18847 148 24X
Fiche 50-412, 83/06/03, 8306150349

8306140658 Summarizes 830215 meeting re SALP conducted on 830124 SALP report evaluation covers Dec 1981 - Nov 1982 Overall performance in constructing facility acceptable
ALLAN, J M Region 1, Office of Director 83/06/08 WOODLEVER, E J
Duquesne Light Co 3pp 18942 005 24X Fiche 50-412, 83/06/08, 8306140658

--8306140663 Forwards SALP rept for Dec 1981 - Nov 1982 Site meeting scheduled for 830215 to discuss assessment List of meeting attendees encl
STAROSTECKI, R Division of Project & Resident Programs 83/01/31
WOODLEVER, E J Duquesne Light Co 7pp 18942 007 24X
Fiche 50-412, 83/06/08, 8306140658

--8306140667 SALP rept for Dec 1981 - Nov 1982 (Const Phase) Performance Categories II & III assigned
* Region 1, Office of Director 83/01/24 31pp 18942 010 24X
Fiche 50-412, 83/06/08, 8306140658

--8306140672 Forwards response to 830131 ltr forwarding SALP for Dec 1981 - Nov 1982 conducted on 830124 Response covers four areas assessed as Category II & one area assessed as Category III
WOODLEVER, E J Duquesne Light Co 83/03/08 STAROSTECKI, R
Division of Project & Resident Programs 7pp 18942 043 24X
Fiche 50-412, 83/06/08, 8306140658

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/09 Consolidated Edison Co of New
York, Inc 119pp 18930 280 24X Fiche 50-000, 83/06/09, 8305110464

8306230415 Forwards IE Insp Rept 50-412/03-07 on 830502-31 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 83/06/10
WOODLEVER, E J Duquesne Light Co 2pp 18943 190 24X
Fiche 50-412, 83/06/10, 8306230415

--8306230417 Notice of violation from insp on 830502-31
* Region 1, Office of Director 83/06/10 1p 18943 192 24X
Fiche 50-412, 83/06/10, 8306230415

--8306230424 IE Insp Rept 50-412/03-07 on 830502-31 Noncompliance noted failure of S&W to correctly consider "dead weight" when performing calculations for pipe supports
WALTON, G A, TRIPP, L E Region 1, Office of Director 83/06/08
10pp 18943 193 24X Fiche 50-412, 83/06/10, 8306230415

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New
York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New
York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New
York, Inc 115pp 19021 177 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New
York, Inc 120pp 18977 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co of New
York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co of New
York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

S Reportable occurrences, LERs & related correspondence

8306010092 Second Interim Significant Deficiency Rept 82-04 re potential problem in Westinghouse solid state protection sys Initially reported on 820806 Design changes being reviewed Next rept expected by 830731
WOODLEVER, E J Duquesne Light Co 83/05/19 ALLAN, J M Region 1,
Office of Director 3pp 18673 266 24X Fiche 50-412, 83/05/19, 8306010092

8306020428 Final Significant Deficiency Rept 83-01 re Westinghouse gate valve position indication Initially reported on 830112 Inaccurate position indication could result in improper sys isolation Mod will be completed by June 1984
WOODLEVER, E J Duquesne Light Co 83/05/23 ALLAN, J M Region 1,
Office of Director 4pp 18693 191 24X Fiche 50-412, 83/05/23, 8306020428

8306210141 Interim Significant Deficiency Rept 83-03 re misoperation of Westinghouse DS-416 reactor trip switchgear undervoltage attachments Initially reported on 830426 Util evaluating deficiency Next rept expected by 830901
WOODLEVER, E J Duquesne Light Co 83/05/26 ALLAN, J M Region 1,
Office of Director 3pp 18914 192 24X Fiche 50-412, 83/05/26, 8306210141

V Operator Examinations

8306140044 Requests attendance at 830627 meeting w/Region 1 in King of Prussia, PA to discuss transfer of reactor operating licensing function from Bethesda, MD to Region 1 of STAROSTECKI, R Division of Project & Resident Programs 83/06/09,
WOODLEVER, E J Duquesne Light Co 2pp 18938 311 24X
Fiche 50-412, 83/06/09, 8306140044

DOCKET 50-413 CATAWBA NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8306030300 Forwards Vols 1 & 2 to Rev 1 to "Duke Power Co Response to Suppl 1 to NUREG-0737 for Catawba Nuclear Station " TUCKER, H B Duke Power Co 83/06/01 DENTON, H R Office of
Nuclear Reactor Regulation, Director ADENBAM, E O Licensing Branch
4 215pp 18704 038 24X Fiche 50-413, 83/06/01, 8306030300

8306160725 Summary of 830324 meeting w/utis & Westinghouse in Bethesda, MD re design review panel review of new Westinghouse stress analysis on manifold fasteners for D2/D3 steam generator mod
HOPKINS, J B Licensing Branch 4 83/06/10 Licensing Branch 4
7pp 18976 277 24X Fiche 50-000, 83/06/10, 8306160725

8306290573 Summary of Design Review Panel 830321 meeting w/utis & Westinghouse in Bethesda, MD re D2/D3 steam generator mod & Westinghouse stress analysis of manifold fasteners
HOPKINS, J B Licensing Branch 4 83/06/10 Licensing Branch 4,
7pp 19047 085 24X Fiche 50-000, 83/06/10, 8306290573

E NRC Safety Evaluation Report (SER), supp's & correspondence

8306070206 Forwards "Overpressure Protection Rept for Catawba Nuclear Power Plant, Units 1 & 2 as Required by ASME Boiler & Pressure Vessel Code, Section III, Article NB-7300" & response to SER Open Item 7 & Confirmatory Item 24
TUCKER, H B Duke Power Co 83/06/27 DENTON, H R Office of
Nuclear Reactor Regulation, Director ADENBAM, E O Licensing Branch
4 2pp 18747 076 24X Fiche 50-413, 83/05/27, 8306070206

--8306070206 "Overpressure Protection Rept for Catawba Nuclear Power Plant, Units 1 & 2 as Required by ASME Boiler & Pressure Vessel Code, Section III, Article NB-7300 " FORCHT, K A, LAND, G E, WITSEMANN, R A Duke Power Co 82/07/31,
14pp 18747 078 24X Fiche 50-413, 83/05/27, 8306070206

8306070314 Advises that internal corrosion protection for fuel oil storage tanks in conformance w/ANSI N195 & that internal coating applied to fuel oil storage tank not necessary per BER Section 9.5.4.2
TUCKER, H B Duke Power Co 83/06/01 DENTON, H R Office of
Nuclear Reactor Regulation, Director ADENBAM, E O Licensing Branch
4 14pp 18744 227 24X Fiche 50-413, 83/06/01, 8306070314

8306140018 Forwards six oversize electrical elementary diagrams in response to SER Confirmatory Item 34 Diagrams confirm removal of key-locked switches from control room HVAC circuits Aperture cards are available in PDR
TUCKER, H B Duke Power Co 83/06/07 DENTON, H R Office of
Nuclear Reactor Regulation, Director ADENBAM, E O Licensing Branch
4 2pp 18932 071 24X Fiche 50-413, 83/06/07, 8306140018

DOCKETED ITEMS

8306170316 Forwards revised FSAK pages responding to SER Confirmatory Items 14, 16 & 17 re containment isolation valve data & containment purge sys from 830525 meeting in Bethesda, MD
TUCKER, H B Duke Power Co 83/06/07 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 15pp 18877 027 24X Fiche 50-413, 83/06/07, 8306170316

8306240123 Forwards two oversize electrical elementary diagrams in response to SER Confirmatory Item 30
TUCKER, H B Duke Power Co 83/06/20 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 2pp 18978 001 24X Fiche 50-413, 83/06/20, 8306240123

8306240183 Forwards revised FSAK pages re hydrologic engineering, in response to NRC 830506 ltr & SER Confirmatory Item 1 Revised pages will be included in Rev B to FSAK w/ three oversize figures Aperture cards are available in PDR
TUCKER, H B Duke Power Co 83/06/21 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 26pp 24X Fiche 50-413, 83/06/21, 8306240183

8306270384 Forwards brochure entitled, "Catauba Nuclear Station Emergency Plan," per SER, Suppl 1, Section 13 3 2 7
TUCKER, H B Duke Power Co 83/06/22 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 18pp 18972 134 24X Fiche 50-413, 83/06/22, 8306270384

F Security, medical, emergency & fire protection plans

8306140664 Forwards 1E Insp Repts 50-413/83-07 & 50-414/83-07 on 830426-29 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/05/24
TUCKER, H B Duke Power Co 2pp 18842 050 24X Fiche 50-413, 83/05/24, 8306140664

--8306140671 1E Insp Repts 50-413/83-07 & 50-414/83-07 on 830426-29 No noncompliance noted Major areas inspected cable penetration firestops, installation of instrument sensing lines, electrical cable terminations & review of QC records
RUFF, A B Region 2, Office of Director CONLON, Division of Engineering & Radiological Safety Programs 83/05/20 6pp 18842 052 24X Fiche 50-413, 83/05/24, 8306140664

8306070349 Forwards "Study of Fire Resistive Performance of Fire Div Walls Used in Power Plant Const," as partial response to Open Item 14 of fire protection program Three oversize drawings encl Aperture cards are available in PDR
TUCKER, H B Duke Power Co 83/05/31 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 2pp 18743 200 24X Fiche 50-413, 83/05/31, 8306070349

--8306070352 "Study of Fire Resistive Performance of Fire Div Walls Used in Power Plant Const"
BLETZACKER, R W Richard W Bletzacker & Associates, Inc 83/04/08 170pp 18743 202 24X Fiche 50-413, 83/05/31, 8306070349

8306220289 Releases public version of emergency plans
FELTON, J M Division of Rules and Records 83/06/17 Document Management Branch 1p 18948 089 24X Fiche 50-413, 83/06/17, 8306220289

--8306220295 Forwards public version of State of SC operational radiological emergency response plan, State of NC emergency response plan & York County emergency operation plan
TUCKER, H B Duke Power Co 83/06/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 18948 090 24X Fiche 50-413, 83/06/17, 8306220289

--8306220299 Public version of State of SC operational radiological emergency response plan, State of NC emergency response plan & York County emergency operation plan
* South Carolina, State of 83/05/31 938pp 18948 094 24X Fiche 50-413, 83/06/17, 8306220289

8306270384 Forwards brochure entitled, "Catauba Nuclear Station Emergency Plan," per SER, Suppl 1, Section 13 3 2 7
TUCKER, H B Duke Power Co, 83/06/22 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 18pp 18972:134 24X Fiche 50-413, 83/06/22, 8306270384.

G Adjudicatory correspondence

8306060297 Further supplementary responses to util interrogatories re Contentions 6, 7, B, 16 & 44 & NRC interrogatories re Contention 7 & responses to util & NRC followup interrogatories, Certificate of Svc encl
JDB, P H, Palmetto Alliance 83/05/27, Duke Power Co 46pp 18729 325 24X Fiche 50-413, 83/05/27, 8306060297

8306060072 Response opposing Palmetto Alliance 830525 motion to establish discovery schedule on OA Contention 6 & Alliance allotted reasonable opportunity to conduct discovery Certificate of Svc encl
JOHNSON, G E Hearing Branch 4 83/06/02 Atomic Safety and Licensing Board Panel 17pp 18723 214 24X Fiche 50-413, 83/06/02, 8306060072

8306060301 Response opposing Palmetto Alliance motion to establish discovery schedule on OA Contention 6 & Alliance afforded every opportunity to obtain info necessary to support contention Certificate of Svc encl
MCGARRY, J M Duke Power Co MCGARRY, J M Debevoise & Liberman 83/06/02 Atomic Safety and Licensing Board Panel 48pp 18729 049 24X Fiche 50-413, 83/06/02, 8306060301

8306070041 Motion for sanctions against Palmetto Alliance Alliance Contentions 7 & 44 should be dismissed for failure to meet discovery deadlines Certificate of Svc encl
JOHNSON, G E Hearing Branch 4 83/06/03 Atomic Safety and Licensing Board Panel 14pp 18729 344 24X Fiche 50-413, 83/06/03, 8306070041

8306080170 Motion for sanctions against Palmetto Alliance & Carolina Environ Study Group Number & scope of contentions should be limited for failure to respond to discovery requests Certificate of Svc encl
MCGARRY, J M Duke Power Co MCGARRY, J M Debevoise & Liberman 83/06/06 Atomic Safety and Licensing Board Panel 146pp 18771 346 24X Fiche 50-413, 83/06/06, 8306080170

8306070305 Forwards Region II 830602 ltr transmitting notice of violation & proposed imposition of civil penalties in amount of \$180,000 for violations noted in 1E Insp Repts 50-269/83-11, 50-270/83-11 & 40 287/83-11
JOHNSON, G E Hearing Branch 4 83/06/06 KELLEY, J L, FUSIER, R I, CALLIHAN, D Atomic Safety and Licensing Board Panel 1pp 18775 179 24X Fiche 50-413, 83/06/06, 8306070305

8306100196 Responses to util 830523 followup interrogatories on NRC Contentions 11, 17 & 19
* Palmetto Alliance * Carolina Environmental Study Group 83/06/06 Duke Power Co 13pp 18805 354 24X Fiche 50-413, 83/06/06, 8306100196

8306100197 Supplemental response to Interrogatory 17 on Contention 7
CARR, A V Duke Power Co CARR, A V Debevoise & Liberman 83/06/08 2pp 18806 010 24X Fiche 50-413, 83/06/08, 8306100197

--8306100199 Motion for extension until 830701 to file motions for summary disposition Palmetto Alliance allowed to make discovery past scheduled time Certificate of Svc encl
MCGARRY, J M Duke Power Co MCGARRY, J M Debevoise & Liberman 83/06/08 Atomic Safety and Licensing Board Panel 5pp 18806 012 24X Fiche 50-413, 83/06/08, 8306100197

8306130437 Notice of change of address
PRESLER, H A Charlotte-Mecklenburg Environmental Coalition 83/06/08 Docketing & Services Branch 1p 18871 194 24X Fiche 50-413, 83/06/08, 8306130437

8306150385 Response opposing applicant & NRC motions for sanctions re Contentions 6, 7, B, 16 & 44/18 & Contentions 7 & 44, respectively Applicant & NRC motions should be denied Discovery obligations fulfilled Certificate of Svc encl
QUILD, R Palmetto Alliance QUILD, R Carolina Environmental Study Group QUILD, R Guild, R 83/06/10 Atomic Safety and Licensing Board Panel 26pp 18847 170 24X Fiche 50-413, 83/06/10, 8306150385

8306160612 Memorandum & order ruling on Palmetto Alliance motion to establish discovery schedule on OA Contention 6 & Denies portion of motion requesting extension for unrestricted discovery Addl time allotted to take depositions re welding
KELLEY, J L Atomic Safety and Licensing Board Panel 83/06/13 Palmetto Alliance, 9pp 18866 131 24X Fiche 50-413, 83/06/13, 8306160612

8306170365 Response supporting util 830608 motion for extension until 830701 to file motions for summary disposition Palmetto filed discovery responses late Motions to dismiss for failure to make discovery pending w/ Certificate of Svc
JOHNSON, G E Hearing Branch 4 83/06/15 Atomic Safety and Licensing Board Panel 5pp 18880 321 24X Fiche 50-413, 83/06/15, 8306170365

8306220092 Submits position on conduct re dispositions of util employees ordered by ASLB 830613 memorandum & order Related correspondence
CARR, A V Duke Power Co 83/06/15 QUILD, R Guild, R 2pp 18927 171 24X Fiche 50-413, 83/06/15, 8306220092

DOCKETED ITEMS

289

8306210296 Forwards NRC 830602 response to Palmetto Alliance request to extend discovery on Contention 6 re QA Filing inadvertently sent to wrong address W/o encl
JOHNSON, G E Hearing Branch 4 83/05/17 FOSTER, R F Atomic Safety and Licensing Board Panel 1p 18914 024 24X Fiche 50-413, 83/06/17, 8306210296

8306220059 Memorandum & order ruling on NRC 830603 motion for sanctions based on Palmetto Alliance (PA) failure to make discovery on Contentions 7 & 44 & until 830606 motion for sanctions requesting dismissal of PA Contentions 6, 7, 8, 16 & 44
KELLEY, J L Atomic Safety and Licensing Board Panel 83/06/20 19pp 18728 185 24X Fiche 50-413, 83/06/20, 8306220059

8306270284 Response to interrogatories & requests to produce re Carolina Environ Study Group Contention 13 Affirmation of Svc encl Related correspondence
RILEY, J L Carolina Environmental Study Group 83/06/20 Duke Power Co 8pp 18996 199 24X Fiche 50-413, 83/06/20, 8306270284.

8306290459 Forwards joint motion for approval of stipulation & stipulation re settlement of contentions
CARR, A V Duke Power Co 83/06/23 KELLEY, J L, CALLIHAN, A. D, FOSTER, R F Atomic Safety and Licensing Board Panel 1p 19052 17b 24X Fiche 50-413, 83/06/23, 8306290459

--8306290461 Joint motion for approval of stipulation
CARR, A V Duke Power Co PRCELER, H A Charlotte-Mecklenburg Environmental Coalition 83/06/23 Atomic Safety and Licensing Board Panel 2pp 19052 176 24X Fiche 50-413, 83/06/23, 8306290459

--8306290464 Stipulation re settlement of contentions Charlotte-Mecklenburg Environ Coalition withdraws contentions from proceedings
CARR, A V Duke Power Co * Charlotte-Mecklenburg Environmental Coalition 83/06/23 3pp 19052 178 24X Fiche 50-413, 83/06/23, 8306290459

8306290540 Discusses Palmetto Alliance notices of depositions Some individuals unavailable on dates proposed Related correspondence
GIBSON, R L Duke Power Co 83/06/23 GUILD, R Palmetto Alliance GUILD, R Guild, R 2pp 19052 316 24X Fiche 50-413, 83/06/23, 8306290540

8306280084 Comments on ASLB revised tentative prehearing schedule listed in ASLB 830620 memorandum & order Suggests revs if Charlotte-Mecklenburg Environ Coalition Contentions 1-4 dismissed Certificate of Svc encl
JOHNSON, G E Hearing Branch 4 83/06/24 7pp 19001 161 24X Fiche 50-413, 83/06/24, 8306280084

I Financial information

8306200352 Forwards Annual Financial Rept 1982
TUCKER, H B Duke Power Co 83/06/15 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENBAM, C O Licensing Branch 4 2pp 18899 101 24X Fiche 50-000, 83/06/15, 8306200352

--8306200356 Annual Financial Rept 1982
* North Carolina Municipal Power Agencies 83/06/15 20pp 18899 103 24X Fiche 50-000, 83/06/15, 8306200352

O Advisory Committee on Reactor Safeguards reports & correspondence

8306170438 Summary of ACRS Subcommittee on Catawba Nuclear Station 830304-05 meetings in Charlotte, NC re DL application review
* ACRS - Advisory Committee on Reactor Safeguards 83/05/11 ACRS - Advisory Committee on Reactor Safeguards 39pp 18908 017, 24X Fiche 50-413, 83/05/11, 8306170438

O Inspection reports, IE Bulletins & correspondence

8306140565 Confirms mgt meeting on 830301 at plant site to discuss self-initiated evaluation of project mgt, design & const of facility.
O'REILLY, J P. Region 2, Office of Director 83/02/10 OWEN, W H Duke Power Co 1p 18834 266 24X Fiche 50-413, 83/02/10, 8306140565

8306140129 Ack receipt of IE Insp Repts 50-413/83-03 & 50-414/83-03 No proprietary info
TUCKER, H B Duke Power Co 83/04/22 O'REILLY, J P. Region 2, Office of Director 1p 18839 135 24X Fiche 50-413, 83/04/22, 8306140129

8306140119 Ack receipt of IE Insp Repts 50-413/83-05 & 50-414/83-05 No proprietary info
TUCKER, H B Duke Power Co 83/05/13 O'REILLY, J P. Region 2, Office of Director 1p 18839 161 24X Fiche 50-413, 83/05/13, 8306140119

8306140123 Ack receipt of IE Insp Repts 50-413/83-06 & 50-414/83-06 No proprietary info
TUCKER, H B Duke Power Co 83/05/19 O'REILLY, J P. Region 2, Office of Director 1p 18839 162 24X Fiche 50-413, 83/05/19, 8306140123

8306140664 Forwards IE Insp Repts 50-413/83-07 & 50-414/83-07 on 830426-29 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/05/24 TUCKER, H B Duke Power Co 2pp 18942 050 24X Fiche 50-413, 83/05/24, 8306140664

--8306140671 IE Insp Repts 50-413/83-07 & 50-414/83-07 on 830426-29 No noncompliance noted Major areas inspected cable penetration firestops, installation of instrument sensing lines, electrical cable terminations & review of QC records
RUFF, A B Region 2, Office of Director CONLON, Division of Engineering & Radiological Safety Programs 83/05/20. 6pp. 18842 052 24X Fiche 50-413, 83/05/24, 8306140664

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl.
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc. 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet," Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460.

8306140497 Ack receipt of 830512 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/83-04 & 50-414/83-04
DANCE, H C Division of Project & Resident Programs 83/05/27 TUCKER, H B Duke Power Co 1p 18838 096 24X Fiche 50-413, 83/05/27, 8306140497

--8306140502 Responds to NRC 830412 ltr re violations noted in IE Insp Repts 50-413/83-04 & 50-414/83-04 Corrective actions QA insp group inspected & accepted hanger 1-R-NV-1385 w/location outside of tolerance required by drawing
TUCKER, H B Duke Power Co 83/05/12 O'REILLY, J P. Region 2, Office of Director 3pp 18838 097. 24X Fiche 50-413, 83/05/27, 8306140497

--8306140506 Forwards IE Insp Repts 50-413/83-04 & 50-414/83-04 on 830315-18 & notice of violation.
DANCE, H C Division of Project & Resident Programs 83/04/12 TUCKER, H B Duke Power Co 2pp 18838 100 24X Fiche: 50-413, 83/05/27, 8306140497

--8306140508 Notice of violation from insp on 830315-18
* Region 2, Office of Director 83/05/12 1p 18838 102 24X Fiche: 50-413, 83/05/27, 8306140497

--8306140511 IE Insp Repts 50-413/83-04 & 50-414/83-04 on 830315-18 Noncompliance noted Failure to follow procedure & drawings for fabrication, erection of hangers, supports & seismic controls & component supports.
YORK, J W Region 2, Office of Director, BLAKE, J J Division of Engineering & Radiological Safety Programs 83/04/08 3pp 18838 103 24X Fiche 50-413, 83/05/27, 8306140497

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc. 116pp 18732 208. 24X Fiche: 50-000, 83/05/31, 8305110461.

8306290186 Forwards IE Insp Repts 50-413/83-10 & 50-414/83-10 on 830517-20 No noncompliance noted
DANCE, H C. Division of Project & Resident Programs 83/06/03 TUCKER, H B Duke Power Co 2pp 19056 211 24X Fiche 50-413, 83/06/03, 8306290186

--8306290192 IE Insp Repts 50-413/83-10 & 50-414/83-10 on 830517-20 No noncompliance noted Major areas inspected RCPB piping, safety-related piping & structures & licensee identified 10CFR50 55e items.
CROWLEY, B R, BLAKE, J J Region 2, Office of Director 83/06/02, 8pp 19056, 213 24X Fiche 50-413, 83/06/03, 8306290186

DOCKETED ITEMS

8306290396 Forwards IE Insp Repts 50-413/83-09 & 50-414/83-09 on 830516-20 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/06/03
TUCKER, H B Duke Power Co 2pp 19055 263 24X
Fiche 50-413, 83/06/03, 8306290396

--8306290404 IE Insp Repts 50-413/83-09 & 50-414/83-09 on 830516-20 No noncompliance noted Major areas inspected preoperational test program review & plant tour
TAYLOR, P A Region 2, Office of Director JAPE, F Division of Engineering & Radiological Safety Programs 83/06/04 4pp 19055 265 24X Fiche 50-413, 83/06/03, 8306290396

8306090305 Forwards Region II 830402 ltr transmitting notice of violation & proposed imposition of civil penalties in amount of \$180,000 for violations noted in IE Insp Repts 50-269/83-11, 50-270/83-11 & 50-287/83-11
JOHNSON, D E Hearing Branch 4 83/06/06 KELLEY, J L, FOSTER, R F, CALLIHAN, D Atomic Safety and Licensing Board, Panel 8pp 18795 179 24X Fiche 50-413, 83/06/06, 8306090305

8306290300 Forwards IE Insp Repts 50-413/83-08 & 50-414/83-08 on 830326-0425 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/06/07
TUCKER, H B Duke Power Co 2pp 19056 011 24X
Fiche 50-413, 83/06/07, 8306290300

--8306290305 IE Insp Repts 50-413/83-08 & 50-414/83-08 on 830326-0425 No noncompliance noted Major areas inspected followup on NRC identified items, review of nonconforming items, observation of QA training & attendance at INPO mgt meeting
VANDORRN, P K Region 2, Office of Director BROWNLEE, V L Division of Project & Resident Programs 83/06/07 4pp 19056; 013 24X Fiche 50-413, 83/06/07, 8306290300

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921, 001 24X Fiche 50-000, 83/06/13, 8306090010

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp, 18996; 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp, 19046, 297 24X Fiche 50-000, 83/06/24, 8305110483

B Reportable occurrences, LERs & related correspondence

8306070066 Informs of closeout of AITS F02700285 re nonrelevant linear indications in 3/4-inch Kerotest check valve body w/o any branch action
POTAPOV, U Division of Vendor & Technical Programs 83/06/02
LEWIS, R C Division of Project & Resident Programs 1p 18740 098 24X Fiche 50-413, 83/06/02, 8306070066,

8306100176 PNO-II-83-045 on 830608, Cardox carbon dioxide fire protection sys in diesel room inadvertently activated
Precautionary evacuation conducted No serious injuries reported
IGNATONIS, A, BROWNLEE, V Region 2, Office of Director 07/06/08 2pp 18805 262 24X Fiche 50-413, 83/06/08, 8306100176

8306270118 Revised Significant Deficiency Rept SD 413/02-10 re non-Class IC communication fire detection & lighting cables attached to essential cable tray side rails Initially reported on 820329 Cables qualified per IEEE 383-1974 test
TUCKER, H B Duke Power Co 83/06/15 O'REILLY, J P Region 2, Office of Director 3pp 18988 107 24X Fiche 50-413, 83/06/15, 8306270118

DOCKET 50-414 CATAWBA NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8306030300 Forwards Vols 1 & 2 to Rev 1 to "Duke Power Co Response to Suppl 1 to NUREG-0737 for Catawba Nuclear Station "
TUCKER, H B Duke Power Co 83/06/01 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAH, E G Licensing Branch 4 215pp 18704 038 24X Fiche 50-413, 83/06/01, 8306030300

8306200019 Summary of 830331 meeting w/utls & Westinghouse in Bethesda, MD re Westinghouse analysis & evaluation of D4/DS/E steam generator mod
HOPKINS, J B Licensing Branch 4 83/06/14 Licensing Branch 4 22pp 18908 327 24X Fiche 50-000, 83/06/14, 8306200019

E NRC Safety Evaluation Report (SER), supls & correspondence

8306070206 Forwards "Overpressure Protection Rept for Catawba Nuclear Power Plant, Units 1 & 2 as Required by ASME Boiler & Pressure Vessel Code, Section III, Article NB-7300 " & response to SER Open Item 7 & Confirmatory Item 24
TUCKER, H B Duke Power Co 83/06/27 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAH, E G Licensing Branch 4 2pp 18747 076 24X Fiche 50-413, 83/06/27, 8306070206

--8306070210 "Overpressure Protection Rept for Catawba Nuclear Power Plant, Units 1 & 2 as Required by ASME Boiler & Pressure Vessel Code, Section III, Article NB-7300 "
FORCHT, K A, LANG, O E, WIESEHANN, R A Duke Power Co 02/07/31 14pp 18747 070 24X Fiche 50-413, 83/06/27, 8306070206

8306070314 Advises that internal corrosion protection for fuel oil storage tanks in conformance w/ANSI N175 & that internal coating applied to fuel oil storage tank not necessary, per SER Section 7 5 4 2
TUCKER, H B Duke Power Co 83/06/01 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAH, E G Licensing Branch 4 14pp 18744 227 24X Fiche 50-413, 83/06/01, 8306070314

8306140018 Forwards six oversize electrical elementary diagrams, in response to SER Confirmatory Item 34 Diagrams confirm removal of key-locked switches from control room HVAC circuits Aperture cards are available in PDR
TUCKER, H B Duke Power Co 83/06/07 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAH, E G Licensing Branch 4 2pp 18832 071 24X Fiche 50-413, 83/06/07, 8306140018

8306170316 Forwards revised FSAR pages responding to SER Confirmatory Items 14, 16 & 17 re containment isolation valve data & containment purge sys from 830525 meeting in Bethesda, MD
TUCKER, H B Duke Power Co 83/06/07 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAH, E G Licensing Branch 4 15pp 18877 027 24X Fiche 50-413, 83/06/07, 8306170316

8306240123 Forwards two oversize electrical elementary diagrams, in response to SER Confirmatory Item 30
TUCKER, H B Duke Power Co 83/06/20 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAH, E G Licensing Branch 4 2pp 18978 001 24X Fiche 50-413, 83/06/20, 8306240123

8306240183 Forwards revised FSAR pages re hydrologic engineering, in response to NRC 830506 ltr & SER Confirmatory Item 1 Revised pages will be included in Rev B to FSAR w/three oversize figures Aperture cards are available in PDR
TUCKER, H B Duke Power Co 83/06/21 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAH, E G Licensing Branch 4 26pp 24X Fiche 50-413, 83/06/21, 8306240183

8306270384 Forwards brochure entitled, "Catawba Nuclear Station Emergency Plan," per SER, Suppl 1, Section 13.3.2.7
TUCKER, H B Duke Power Co 83/06/22 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAH, E G Licensing Branch 4 18pp 18792 134 24X Fiche 50-413, 83/06/22, 8306270384

DOCKETED ITEMS

291

F Security, medical, emergency & fire protection plans

B306140664 Forwards IE Insp Repts 50-413/83-07 & 50-414/83-07 on B30426-29 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/05/24
TUCKER, H B Duke Power Co 2pp 18842 050 24X
Fiche 50-413, 83/05/24, B306140664

--B306140671 IE Insp Repts 50-413/83-07 & 50-414/83-07 on B30426-29 No noncompliance noted Major areas inspected cable penetration firestops, installation of instrument sensing lines, electrical cable terminations & review of GC records
RUFF, A B Region 2, Office of Director 83/05/20 6pp
18842 052 24X Fiche 50-413, 83/05/24, B306140664

B306070349 Forwards "Study of Fire Resistive Performance of Fire Div Walls Used in Power Plant Const." as partial response to Open Item 14 of fire protection program Three oversize drawings encl Aperture cards are available in PUR
TUCKER, H B Duke Power Co 83/05/31 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSA, E O Licensing Branch 4 2pp 18743 200 24X Fiche 50-413, 83/05/31, B306070349

--B306070352 "Study of Fire Resistive Performance of Fire Div Walls Used in Power Plant Const"
BLETZACKER, R W Richard W Blotzacker & Associates, Inc 83/04/08 170pp 18743 202 24X Fiche 50-413, 83/05/31, B306070349

B306220289 Releases public version of emergency plans
FELTON, J M Division of Rules and Records 83/06/17 Document Management Branch 1p 18948 089 24X Fiche 50-413, 83/06/17, B306220289

--B306220295 Forwards public version of State of SC operational radiological emergency response plan, State of NC emergency response plan & York County emergency operation plan
TUCKER, H B Duke Power Co 83/06/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 18948 090 24X Fiche 50-413, 83/06/17, B306220289

--B306220299 Public version of State of SC operational radiological emergency response plan, State of NC emergency response plan & York County emergency operation plan
* South Carolina, State of 83/05/31 930pp 18948 094 24X Fiche 50-413, 83/06/17, B306220289

B306270384 Forwards brochure entitled, "Catawba Nuclear Station Emergency Plan," per SER, Suppl 1, Section 13 3 2 7
TUCKER, H B Duke Power Co 83/06/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 18pp 18992 134 24X Fiche 50-413, 83/06/22, B306270384

G Adjudicatory correspondence

B306060297 Further supplementary responses to util interrogatories re Contentions 6, 7, 8, 16 & 44 & NRC interrogatories re Contention 7 & responses to util & NRC followup interrogatories Certificate of Svc encl
JOS, P H Palmetto Alliance 83/05/27 Duke Power Co 46pp 18729 325 24X Fiche 50-413, 83/05/27, B306060297

B306060072 Response opposing Palmetto Alliance B30525 motion to establish discovery schedule on GA Contention 6 Alliance allotted reasonable opportunity to conduct discovery Certificate of Svc encl
JOHNSON, Q E Hearing Branch 4 83/06/02 Atomic Safety and Licensing Board Panel 17pp 18723 254 24X Fiche 50-413, 83/06/02, B306060072

B306060301 Response opposing Palmetto Alliance motion to establish discovery schedule on GA Contention 6 Alliance afforded every opportunity to obtain info necessary to support Contention Certificate of Svc encl
MCQARRY, J M Duke Power Co MCQARRY, J M Debevoise & Liberman 83/06/02 Atomic Safety and Licensing Board Panel 48pp 18729 049 24X Fiche 50-413, 83/06/02, B306060301

B306070041 Motion for sanctions against Palmetto Alliance Alliance Contentions 7 & 44 should be dismissed for failure to meet discovery deadlines Certificate of Svc encl
JOHNSON, Q E Hearing Branch 4 83/06/03 Atomic Safety and Licensing Board Panel 14pp 18739, 344 24X Fiche 50-413, 83/06/03, B306070041

B306080170 Motion for sanctions against Palmetto Alliance & Carolina Environ Study Group Number & scope of contentions should be limited for failure to respond to discovery requests Certificate of Svc encl
MCQARRY, J M Duke Power Co MCQARRY, J M Debevoise & Liberman 83/06/06 Atomic Safety and Licensing Board Panel 146pp 18771 346 24X Fiche 50-413, 83/06/06, B306080170

B306090305 Forwards Region II B30402 ltr transmitting notice of violation & proposed imposition of civil penalties in amount of \$180,000 for violations noted in IE Insp Repts 50-269/83-11, 50-270/83-11 & 50-287/83-11
JOHNSON, Q E Hearing Branch 4 83/06/06 KELLEY, J L, FOSTER, R F, CALLIHAN, D Atomic Safety and Licensing Board Panel 8pp 18775 179 24X Fiche 50-413, 83/06/06, B306090305

B306100196 Responses to util B30523 followup interrogatories on DEB Contentions 11, 17 & 19
* Palmetto Alliance * Carolina Environmental Study Group 83/06/06 Duke Power Co 13pp 18803 354 24X Fiche 50-413, 83/06/06, B306100196

B306100197 Supplemental response to Interrogatory 17 on Contention 7
CARR, A V Duke Power Co CARR, A V Debevoise & Liberman 83/06/08 2pp 18806 010 24X Fiche 50-413, 83/06/08, B306100197

--B306100199 Motion for extension until B30701 to file motions for summary disposition Palmetto Alliance allowed to make discovery past scheduled time Certificate of Svc encl
MCQARRY, J M Duke Power Co MCQARRY, J M Debevoise & Liberman 83/06/08 Atomic Safety and Licensing Board Panel 5pp 18806 012 24X Fiche 50-413, 83/06/08, B306100197

B306130437 Notice of change of address
PRESLER, H A Charlotte-Mecklenberg Environmental Coalition 83/06/08 Docketing & Services Branch 1p 18821 194 24X Fiche 50-413, 83/06/08, B306130437

B306150385 Response opposing applicant & NRC motions for sanctions re Contentions 6, 7, 8, 16 & 44/18 & Contentions 7 & 44, respectively Applicant & NRC motions should be denied. Discovery obligations fulfilled Certificate of Svc encl
GUILD, R Palmetto Alliance GUILD, R Carolina Environmental Study Group, GUILD, R Guild, R 83/06/10 Atomic Safety and Licensing Board Panel 26pp 18847, 170 24X Fiche 50-413, 83/06/10, B306150385

B306160612 Memorandum & order ruling on Palmetto Alliance motion to establish discovery schedule on GA Contention 6 Denies portion of motion requesting extension for unrestricted discovery Addl time allotted to take depositions re holding KELLEY, J L Atomic Safety and Licensing Board Panel 83/06/13 Palmetto Alliance 9pp 18866 131 24X Fiche 50-413, 83/06/13, B306160612

B306170365 Response supporting util B30604 motion for extension until B30701 to file motions for summary disposition Palmetto filed discovery responses late Motions to dismiss for failure to make discovery pending W/Certificate of Svc.
JOHNSON, Q E Hearing Branch 4 83/06/15 Atomic Safety and Licensing Board Panel 5pp 18880, 322 24X Fiche 50-413, 83/06/15, B306170365

B306220092 Submits position on conduct re dispositions of util employees ordered by ASLB B30613 memorandum & order Related correspondence.
CARR, A V Duke Power Co 83/06/15 GUILD, R Guild, R 2pp 18927 171 24X Fiche 50-413, 83/06/15, B306220092

B306210296 Forwards NRC B30602 response to Palmetto Alliance request to extend discovery on Contention 6 re GA Filing inadvertently sent to wrong address W/o encl
JOHNSON, Q E Hearing Branch 4 83/06/17 FOSTER, R F Atomic Safety and Licensing Board Panel 1p 18914 024, 24X Fiche 50-413, 83/06/17, B306210296

B306220099 Memorandum & order ruling on NRC B30603 motion for sanctions based on Palmetto Alliance (PA) failure to make discovery on Contentions 7 & 44 & util B30606 motion for sanctions requesting dismissal of PA Contentions 6, 7, 8, 16 & 44
KELLEY, J L Atomic Safety and Licensing Board Panel 83/06/20 19pp 18928 185 24X Fiche 50-413, 83/06/20, B306220099

B306270284 Response to interrogatories & requests to produce re Carolina Environ Study Group Contention 13 Affirmation of Svc encl Related correspondence.
RILEY, J L Carolina Environmental Study Group 83/06/20 Duke Power Co 8pp 18996 199 24X Fiche 50-413, 83/06/20, B306270284

B306290459 Forwards joint motion for approval of stipulation & stipulation re settlement of contentions
CARR, A V Duke Power Co 83/06/23 KELLEY, J L, CALLIHAN, A D, FOSTER, R F Atomic Safety and Licensing Board Panel 1p 19032, 175 24X Fiche 50-413, 83/06/23, B306290459

--B306290461 Joint motion for approval of stipulation.
CARR, A V Duke Power Co PRESLER, H A Charlotte-Mecklenberg Environmental Coalition 83/06/23 Atomic Safety and Licensing Board Panel 2pp 19032 176 24X Fiche 50-413, 83/06/23, B306290459

DOCKETED ITEMS

--8306290464 Stipulation re settlement of contentions Charlotte-Mecklenburg Environ Coalition withdraws contentions from proceedings
CARR, A V Duke Power Co * Charlotte Mecklenburg Environmental Coalition 83/06/23 3pp 19032 178 24X Fiche 50-413, 83/06/23, 8306290459

8306290540 Discusses Palmetto Alliance notices of depositions Some individuals unavailable on dates proposed Related correspondence
O'BRYEN, R L Duke Power Co 83/06/23 GUILD, R Palmetto Alliance GUILD, R Guild, R 2pp 19052 316 24X Fiche 50-413, 83/06/23, 8306290540

8306260084 Comments on ASLB revised tentative prehearing schedule listed in ASLB 830620 memorandum & order Suggests revs if Charlotte-Mecklenburg Environ Coalition Contentions 1-4 dismissed Certificate of Gvc encl
JOHNSON, O E Hearing Branch 4 83/06/24 7pp 19001 161 24X Fiche 50-413, 83/06/24, 8306260084

I Financial information

8306200352 Forwards Annual Financial Rept 1982
TUCKER, H B Duke Power Co 83/06/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18899 101 24X Fiche 50-000, 83/06/15, 8306200352

--8306200356 Annual Financial Rept 1982
* North Carolina Municipal Power Agencies 83/06/15 20pp 18899 103 24X Fiche 50-000, 83/06/15, 8306200356

O Advisory Committee on Reactor Safeguards reports & correspondence

8306170438 Summary of ACRS Subcommittee on Catawba Nuclear Station 830304-05 meetings in Charlotte, NC re CL application review
* ACRS - Advisory Committee on Reactor Safeguards 83/05/11 ACRS - Advisory Committee on Reactor Safeguards 39pp 18908 017 24X Fiche 50-413, 83/05/11, 8306170438

G Inspection reports, IE Bulletins & correspondence

8306140565 Confirms mgt meeting on 830301 at plant site to discuss self-initiated evaluation of project mgt, design & const of facility
O'REILLY, J P Region 2, Office of Director, 83/02/10 OWEN, W II Duke Power Co 1p 18834 266 24X Fiche 50-413, 83/02/10, 8306140565

8306140129 Ack receipt of IE Insp Repts 50-413/83-03 & 50-414/83-03 No proprietary info
TUCKER, H B Duke Power Co 83/04/22 O'REILLY, J P Region 2, Office of Director 1p 18839 135 24X Fiche 50-413, 83/04/22, 8306140129

8306140119 Ack receipt of IE Insp Repts 50-413/83-05 & 50-414/83-05 No proprietary info
TUCKER, H B Duke Power Co 83/05/13 O'REILLY, J P Region 2, Office of Director 1p 18839 161 24X Fiche 50-413, 83/05/13, 8306140119

8306140123 Ack receipt of IE Insp Repts 50-413/83-06 & 50-414/83-06 No proprietary info
TUCKER, H B Duke Power Co 83/05/19 O'REILLY, J P Region 2, Office of Director 1p 18839 162 24X Fiche 50-413, 83/05/19, 8306140123

8306140664 Forwards IE Insp Repts 50-413/83-07 & 50-414/83-07 on 830426-29 No noncompliance noted.
DANCE, H C Division of Project & Resident Programs 83/05/24 TUCKER, H B Duke Power Co 2pp 18842 050 24X Fiche 50-413, 83/05/24, 8306140664

--8306140671 IE Insp Repts 50-413/83-07 & 50-414/83-07 on 830426-29 No noncompliance noted Major areas inspected cable penetration firestops, installation of instrument sensing lines, electrical cable terminations & review of QC records
RUFF, A B Region 2, Office of Director CONLON, Division of Engineering & Radiological Safety Programs 83/05/20 6pp 18842, 052 24X Fiche 50-413, 83/05/24, 8306140664

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device." Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103), 83/05/26 Consolidated Edison Co of New York, Inc 12pp, 18831, 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8306140497 Ack receipt of 830512 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/83-04 & 50-414/83-04
DANCE, H C Division of Project & Resident Programs 83/05/27 TUCKER, H B Duke Power Co 1p 18839 096 24X Fiche 50-413, 83/05/27, 8306140497

--8306140502 Responds to NRC 830412 ltr re violations noted in IE Insp Repts 50-413/83-04 & 50-414/83-04 Corrective actions QA insp group inspected & accepted hanger 1-R-NV-1785 w/location outside of tolerance required by drawing
TUCKER, H B Duke Power Co 83/05/12 O'REILLY, J P Region 2, Office of Director 3pp 18838 077 24X Fiche 50-413, 83/05/27, 8306140497

--8306140506 Forwards IE Insp Repts 50-413/83-04 & 50-414/83-04 on 830315-18 & notice of violation
DANCE, H C Division of Project & Resident Programs 83/04/12 TUCKER, H B Duke Power Co 2pp 18838 100 24X Fiche 50-413, 83/05/27, 8306140497

--8306140511 IE Insp Repts 50-413/83-04 & 50-414/83-04 on 830315-18 Noncompliance noted Failure to follow procedure & drawings for fabrication, erection of hangers, supports & seismic controls & component supports
YORK, J W Region 2, Office of Director BLAKE, J J Division of Engineering & Radiological Safety Programs 83/04/08 3pp 18838 103 24X Fiche 50-413, 83/05/27, 8306140497

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306290186 Forwards IE Insp Repts 50-413/83-10 & 50-414/83-10 on 830317-20 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/06/03 TUCKER, H B Duke Power Co 2pp 19056 211 24X Fiche 50-413, 83/06/03, 8306290186

--8306290192 IE Insp Repts 50-413/83-10 & 50-414/83-10 on 830317-20 No noncompliance noted Major areas inspected RCPB piping, safety-related piping & structures & licensee identified 10 CFR 50.55e items
CROWLEY, B R, BLAKE, J J Region 2, Office of Director 03/06/02 8pp 19056 213 24X Fiche 50-413, 83/06/03, 8306290186

8306290396 Forwards IE Insp Repts 50-413/83-09 & 50-414/83-09 on 830516-20 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/06/03 TUCKER, H B Duke Power Co 2pp 19055 263 24X Fiche 50-413, 83/06/03, 8306290396

--8306290404 IE Insp Repts 50-413/83-09 & 50-414/83-09 on 830516-20 No noncompliance noted Major areas inspected preoperational test program review & plant tour
TAYLOR, P A Region 2, Office of Director JAPF, F Division of Engineering & Radiological Safety Programs 83/06/04 4pp 19055 265 24X Fiche 50-413, 83/06/03, 8306290396

8306090305 Forwards Region II 830602 ltr transmitting notice of violation & proposed imposition of civil penalties in amount of \$180,000 for violations noted in IE Insp Repts 50-269/83-11, 50-270/83-11 & 50-287/83-11
JOHNSON, O E Hearing Branch 4 83/06/06 KELLEY, J L Atomic Safety and Licensing Board Panel 8pp 18795 179 24X Fiche 50-413, 83/06/06, 8306090305

8306290300 Forwards IE Insp Repts 50-413/83-08 & 50-414/83-08 on 830326-0425 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/06/07 TUCKER, H B Duke Power Co 2pp 19056 011 24X Fiche 50-413, 83/06/07, 8306290300

--8306290305 IE Insp Repts 50-413/83-08 & 50-414/83-08 on 830326-0425 No noncompliance noted Major areas inspected followup on NRC identified items, review of nonconforming items, observation of QA training & attendance at INPD mgt meeting
VANDORRN, P K Region 2, Office of Director BROWNLEE, V L Division of Project & Resident Programs 83/06/07 4pp 19056, 013 24X Fiche 50-413, 83/06/07, 8306290300

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 117pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 116pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

DOCKET 50-416 GRAND GULF NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8306060051 Addl response to FOIA request for three categories of documents re PRA of reactor safety study methodology application program repts & interim reliability evaluation program repts Forwards App A documents search continuing
FELTON, J M Division of Rules and Records 83/04/07 SHOLLY, S C
Union of Concerned Scientists 2pp 10752 001 24X
Fiche 50-000, 83/04/07, 8306060051

--8304120488 Discusses results of Sandia Natl Labs Study, "Reactor Safety Study Methodology Application Program Grand Gulf 1 BWR Power Plant (NUREG/CR-1659, Vol 1) "
ERNST, M L Assistant Director for Technology Review 82/04/04
TEDESCO, R L Assistant Director for Licensing 2pp 18752-067
24X Fiche 50-000, 83/04/07, 8306060051

--8306060059 Requests meeting w/NRC to discuss concerns re reactor safety study methodology application program conservative rather than realistic assumptions & calculations used in analysis
DALE, L F Mississippi Power & Light Co 81/07/23 BERNERD, R M
Division of Risk Analysis 2pp 18752 016 24X
Fiche 50-000, 83/04/07, 8306060051

8306140666 Summarizes 830511 meeting at Region II of re changes to Tech Specs required prior to Unit 1 startup Meeting details & attendees list encl
LEHIG, R C Division of Project & Resident Programs 83/05/27
RICHARD, J B Mississippi Power & Light Co 5pp 18842 089 24X
Fiche 50-416, 83/05/27, 8306140666

E NRC Safety Evaluation Report (SER), supp's & correspondence

8306210331 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF GRAND GULF NUCLEAR STATION, UNITS 1 & 2 Docket Nos 50-416 & 50-417 (Mississippi Power and Light Company)
* Division of Licensing NUREG-0831 004 83/05/31 156pp
Available at NRC *\$ 50 18722 197 24X Fiche 50-416, 83/05/31, 8306210331

8306200429 Forwards Suppl 4 to SER, NUREG-0831 W/o encl
SCHWENGER, A Licensing Branch 2 83/06/13 MCCOUGHY, J P
Mississippi Power & Light Co 4pp 18720 019 24X
Fiche 50-416, 83/06/13, 8306200429

--8306200430 Forwards Suppl 4 to SER W/o encl
* Office of Nuclear Reactor Regulation, Director 83/06/13
SIMPSON, A Senate, Environment & Public Works 1p 18920 023
24X Fiche 50-416, 83/06/13, 8306200429

--8306200431 Forwards Suppl 4 to SER W/o encl
* Office of Nuclear Reactor Regulation, Director 83/06/13
UDALL, M House of Rep., Interior & Insular Affairs 1p
18920 024 24X Fiche 50-416, 83/06/13, 8306200429

--8306200432 Forwards Suppl 4 to SER W/o encl
* Office of Nuclear Reactor Regulation, Director 83/06/13
OTTINGER, R House of Rep., Energy & Commerce 1p 18920 028
24X Fiche 50-416, 83/06/13, 8306200429

F Security, medical, emergency & fire protection plans

8306140519 Confirms 830511 enforcement conference at Region II of to discuss security violations at facility & Tech Spec changes required prior to nuclear startup, per 830505 telcon Proposed meeting agenda encl.
O'REILLY, J P Region 2, Office of Director 83/05/06, RICHARD, J B
Mississippi Power & Light Co 2pp 18838 106 24X
Fiche 50-416, 83/05/06, 8306140519

8306140235 Forwards IE Insp Rept 50-416/83-13 on 830329-0401 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/05/17
RICHARD, J B Mississippi Power & Light Co 2pp 18832 353 24X
Fiche 50-416, 83/05/17, 8306140235

--8306140244 IE Insp Rept 50-416/83-13 on 830329-0401. No noncompliance noted Major areas inspected exam of procedures & records, personnel interviews & observations re emergency preparedness
CLINE, W E Region 2, Office of Director, JENKINS, G R Division of Emergency Preparedness & Materials Safety 83/05/13 9pp
18832, 353 24X Fiche 50-416, 83/05/17, 8306140235

8306060079 Confirms 830602 telcon re submittal of implementation schedule for backup emergency operations facility by 830617
DALE, L F Mississippi Power & Light Co 83/06/02 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 18719 331 24X
Fiche 50-416, 83/06/02, 8306060079

8306210236 Discusses IE Insp on 830429 & 0503-04 & forwards notice of violation & proposed imposition of civil penalty as result of violations identified in IE Insp Rept 50-416/83-17
O'REILLY, J P Director's Office, Office of Inspection and Enforcement 83/06/13 RICHARD, J B Mississippi Power & Light Co.
2pp 18916 059 24X Fiche 50-416, 83/06/13, 8306210236

--8306210243 Notice of violation & proposed imposition of civil penalty in amount of \$40,000 Noncompliance noted security force member posted to control access to lower containment hatch, found asleep
O'REILLY, J P Director's Office, Office of Inspection and Enforcement 83/06/13 2pp 18916 061, 24X
Fiche 50-416, 83/06/13, 8306210236

8306210140 Advises that Baxter Wilson plant selected for backup emergency operations facility Telephone capability will be expanded & antennae for offsite radiological monitoring radio will be installed Emergency plan revised
DALE, L F Mississippi Power & Light Co 83/06/17 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 18914 224
24X Fiche 50-416, 83/06/17, 8306210140

K Utility Final Safety Analysis Report (FSAR) & amendments

8306200186 Forwards Amend 5b to FSAR, updating sections dealing primarily w/fire protection & incorporating minor editorial corrections & clarifications to other FSAR sections
MCCOUGHY, J P Mississippi Power & Light Co 83/06/17, DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 18905, 003
24X Fiche 50-416, 83/06/17, 8306200186

--8306200189 Amend 5b to FSAR
MCCOUGHY, J P Mississippi Power & Light Co 83/06/30 1,200pp
18905-006 24X Fiche 50-416, 83/06/17, 8306200186

P Operating license stage documents & correspondence

8306060236 Forwards qualification status & compliance summary on environ qualification of electrical equipment important to safety, per JOCRF50 49
DALE, L F Mississippi Power & Light Co 83/05/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director 62pp 18728 298,
24X Fiche 50-416, 83/05/20, 8306060236

DOCKETED ITEMS

8306010074 Forwards comments re review of 830118 proposed changes to STB, per informal request Proposed change to Surveillance Requirement 4 & 3 re continuous operation of heaters should not be implemented
DALE, L F Mississippi Power & Light Co 83/05/24 HOUSTON, M D
Division of Licensing 2pp 18673 272 24X Fiche 50-416, 83/05/24, 8306010074

8306020286 Application to amend License NPF-13, changing submittal dates for dynamic, inservice insp & communication sys tests
MCOAUGHY, J P Mississippi Power & Light Co 83/05/31 DENTON, H R
Office of Nuclear Reactor Regulation, Director 5pp 18690 308 24X Fiche 50-416, 83/05/31, 8306020286

8306140724 Application to amend License NPF-13, consisting of Tech Spec Change PCOL-83/08, per 821020 confirmation of action ltr
Changes enhance clarity & provide consistency w/plant design & operation
DALE, L F Mississippi Power & Light Co 83/06/09 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 18841 017 24X Fiche 50-416, 83/06/09, 8306140724

--8306140729 Proposed Tech Spec Change PCOL-83/08, enhancing clarity & providing consistency w/plant design & operation, per 821020 confirmation of action ltr
* Mississippi Power & Light Co 83/06/09 72pp 18841 019 24X Fiche: 50-416, 83/06/09, 8306140724

8306220258 Notification of 830629 meeting w/BWR-Hydrogen Control Owners Group in Bethesda, MD to discuss hydrogen control program
HOUSTON, D Licensing Branch 2 83/06/09 SCHWENCER, A Licensing Branch 2 9pp 18951 054 24X Fiche 50-416, 83/06/09, 8306220258

8306160271 Application to amend License NPF-13, clarifying & providing consistency w/plant design & operation
DALE, L F Mississippi Power & Light Co 83/06/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 18860 125 24X Fiche 50-416, 83/06/14, 8306160271

--8306160274 Proposed changes to Tech Specs re plant design & operation
* Mississippi Power & Light Co 83/06/14 46pp 18860 127 24X Fiche 50-416, 83/06/14, 8306160271

8306200204 Submits steps taken to satisfy Items 1 C & 3 of License NPF-13 re control room envelope leak tightness test Control room leakage reduced Allowable leakage increased & analysis performed verifying SRP (NUREG-0800) conformance
DALE, L F Mississippi Power & Light Co 83/06/16 DENTON, H R
Office of Nuclear Reactor Regulation, Director 7pp 18903 236 24X Fiche 50-416, 83/06/16, 8306200204

8306230167 Forwards addl info re Hydrogen Control Owners Group program, per NRC 830203 request Proprietary & nonproprietary versions of "Grand Gulf Drywell Break Sensitivity Summary" encl
Proprietary rept withheld (ref 10CFR2 7x0)
DALE, L F Mississippi Power & Light Co 83/06/16 DENTON, H R
Office of Nuclear Reactor Regulation, Director, 11pp 18745 297 24X Fiche 50-416, 83/06/16, 8306230167

--8306230169 Nonproprietary version of "Grand Gulf Drywell Break Sensitivity Summary"
QUINTER, D S Offshore Power Systems (subs of Westinghouse Electric Corp.), OPS-39A82 RA 83/05/11 397pp 18745 311 24X Fiche 50-416, 83/06/16, 8306230167

8306290559 Provides list of proposed Tech Spec changes disapproved by NRC in response to 830324, 0407, 25, 0607 & 14 submittals
List should be reviewed & revs submitted
SCHWENCER, A Licensing Branch 2 83/06/21 MCOAUGHY, J P
Mississippi Power & Light Co 3pp 19046 137 24X Fiche 50-416, 83/06/21, 8306290559

8306270077 Application to amend License NPF-13, changing Tech Specs to enhance clarity or provide consistency w/plant design & operation re trip setpoint & function, in response to 821020 confirmation of action ltr
DALE, L F Mississippi Power & Light Co 83/06/23 DENTON, H R
Office of Nuclear Reactor Regulation, Director, 2pp 19013 234 24X Fiche: 50-416, 83/06/23, 8306270077

--8306270080 Proposed Tech Spec changes enhancing clarity or providing consistency w/plant design & operation re trip setpoint & function
* Mississippi Power & Light Co 83/06/23 72pp 19013 236 24X Fiche: 50-416, 83/06/23, 8306270077

8306270285 Clarifies capabilities of hydrogen ignition sys under all circumstances, per Schwencer 81106 ltr & NUREG/CR-2486 Under worst case conditions, min voltage required would be 10 08 volts.
DALE, L F Mississippi Power & Light Co 83/06/23 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 18976 196 24X Fiche: 50-416, 83/06/23, 8306270285

8306280505 Forwards affidavit requesting that final test rept, "Safety Relief Valve In-Plant Discharge Test for Kuosheng Nuclear Power Station," be withheld (ref 10CFR2 790 & 10CFR9 5)
DALE, L F Mississippi Power & Light Co 83/06/24 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 19019 001 24X Fiche 50-416, 83/06/24, 8306280505

Q Inspection reports, IE Bulletins & correspondence

8306140561 Confirms mgt meeting on 830210 in Jackson, MS to discuss results of review of first phase of annual appraisal of regulatory performance Proposed meeting agenda encl
LEWIS, R C Division of Project & Resident Programs 83/01/28 STAMPLEY, N L Mississippi Power & Light Co 3pp 18834 236 24X Fiche 50-416, 83/01/28, 8306140561

8306140028 Confirms 830408 mgt meeting at Region II ofc, per 830329 telcon Util will discuss "Grand Gulf Nuclear Station Operations Enhancement Program" Agenda encl
O'REILLY, J P Region 2, Office of Director 83/03/25 RICHARD, J B
Mississippi Power & Light Co 2pp 10838 229 24X Fiche 50-416, 83/03/25, 8306140028

8306140602 Confirms 830420 enforcement conference at Region II ofc to discuss control of mods & maint & adequacy of corrective action in area of temporary alterations per 830408 & 11 telcons Agenda encl
O'REILLY, J P Region 2, Office of Director 83/04/13 RICHARD, J B
Mississippi Power & Light Co 3pp 10833 175 24X Fiche 50-416, 83/04/13, 8306140602

8306140634 Forwards summary of 830408 meeting in Atlanta, GA re util 830311 rept, "Grand Gulf Nuclear Station Operations Enhancement Program" Implementation will be beneficial to plant operations W/attendance list
LEWIS, R C Division of Project & Resident Programs 83/04/29 RICHARD, J B
Mississippi Power & Light Co 6pp 18843 050 24X Fiche 50-416, 83/04/29, 8306140634

8306140519 Confirms 830511 enforcement conference at Region II ofc to discuss security violations at Facility & Tech Spec changes required prior to nuclear startup, per 830505 telcon Proposed meeting agenda encl
O'REILLY, J P Region 2, Office of Director 83/05/06 RICHARD, J B
Mississippi Power & Light Co 2pp 10838 106 24X Fiche 50-416, 83/05/06, 8306140519

8306140235 Forwards IE Insp Rept 50-416/83-13 on 830329-0401 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs, 83/05/17 RICHARD, J B
Mississippi Power & Light Co 2pp 18832 357 24X Fiche 50-416, 83/05/17, 8306140235

--8306140244 IE Insp Rept 50-416/83-13 on 830329-0401 No noncompliance noted Major areas inspected exam of procedures & records, personnel interviews & observations re emergency preparedness
CLINE, W E Region 2, Office of Director JENKINS, G R Division of Emergency Preparedness & Materials Safety 83/05/13 9pp 18832 355 24X Fiche 50-416, 83/05/17, 8306140235

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at DWRs" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306020286 Application to amend License NPF-13, changing submittal dates for dynamic, inservice insp & communication sys tests
MCOAUGHY, J P Mississippi Power & Light Co 83/05/31 DENTON, H R
Office of Nuclear Reactor Regulation, Director 5pp 18690 308 24X Fiche 50-416, 83/05/31, 8306020286

8306290236 Forwards IE Insp Rept 50-416/83-20 on 830604 13 Nu noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/06/03 RICHARD, J B
Mississippi Power & Light Co 2pp 19056 236 24X Fiche 50-416, 83/06/03, 8306290236

DOCKETED ITEMS

295

- B306290214 IE Insp Rept 50-416/83-20 on 8J0609-13 No noncompliance noted Major areas inspected radiation protection program, including liquid, solid & gaseous preoperational test program & previous inspector identified items
COLLINS, T R , BARR, K P Region 2, Office of Director 03/06/02 6pp 19056 238 24X Fiche 50-416, 83/06/03, B306290236
- B306290365 Forwards IE Insp Repts 50-416/83-16 & 50-417/83-05 on 830509-17 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/06/03
RICHARD, J B Mississippi Power & Light Co 2pp 19055 230 24X Fiche 50-416, 83/06/03, B306290765
- B306290371 IE Insp Repts 50-416/83-16 & 50-417/83 05 on 830509-13 No noncompliance noted Major areas inspected licensee action in previous enforcement matters, structural concrete, licensee identified items & followup items
HARRIS, J R Region 2, Office of Director CONLON, T E Division of Engineering & Radiological Safety Programs 83/05/31 4pp 19058 292 24X Fiche 50-416, 83/06/03, B306290365
- B306140450 Ack receipt of 830519 ltr informing NRC of steps taken to correct violations noted in II Insp Rept 50-416/83-12
VERRELLI, D M Division of Project & Resident Programs 83/06/07
RICHARD, J B Mississippi Power & Light Co 1p 18840 187 24X Fiche 50-416, 83/06/07, B306140450
- B306140454 Responds to NRC 830419 ltr re violations noted in IE Insp Rept 50-416/83-12 Corrective actions walkdown of rebar concrete masonry wall w/structural mods performed by Bechtel Field Engineering performed
MCGAUGHY, J P Mississippi Power & Light Co 83/05/19
O'REILLY, J P Region 2, Office of Director 2pp 18840 180 24X Fiche 50-416, 83/06/07, B306140450
- B306140463 Forwards IE Insp Repts 50-416/83-12 & 50-417/83 04 on 830322-25 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 83/04/19
RICHARD, J B Mississippi Power & Light Co 2pp 18840 190 24X Fiche 50-416, 83/06/07, B306140450
- B306140468 Notice of violation from insp on 830322-25
* Region 2, Office of Director 83/04/19 2pp 18840 192 24X Fiche 50-416, 83/06/07, B306140450
- B306140474 IE Insp Repts 50-416/83-12 & 50-417/83-04 on 830322-25 Noncompliance noted Failure to complete control bldg masonry wall mods in accordance w/drawing requirements
LENAHAN, J J Region 2, Office of Director CONLON, T E Division of Engineering & Radiological Safety Programs 83/04/14 7pp 18840 194 24X Fiche 50-416, 83/06/07, B306140450
- B306140559 Ack receipt of 830506 ltr informing NRC of steps taken to correct violation & deviation noted in IE Insp Repts 50-416/83-06 & 50-417/83-03 Notice of deviation retracted based on 820319 & 0421 ltrs referenced in suppl 2 to SER
LEWIS, R C Division of Project & Resident Programs 83/06/07
RICHARD, J B Mississippi Power & Light Co 1p 18834 220 24X Fiche 50-416, 83/06/07, B306140559
- B306140567 Responds to NRC 830329 ltr re violation & deviation noted in IE Insp Rept 50-416/83-06 Corrective actions Rev 7 to Procedures 09-S-01-8 & 01-S 07-4 issued & preparation for training in progress
MCGAUGHY, J P Mississippi Power & Light Co 83/05/06
O'REILLY, J P Region 2, Office of Director 3pp 18834 221, 24X Fiche 50-416, 83/06/07, B306140559
- B306140569 Forwards IE Insp Repts 50-416/83-06 & 50-417/83 03 on 830215-17 & notices of violation & deviation
LEWIS, R C Division of Project & Resident Programs 83/03/29
RICHARD, J B Mississippi Power & Light Co 2pp 18834 224 24X Fiche 50-416, 83/06/07, B306140559
- B306140571 Notice of violation from insp on 830215-17
* Region 2, Office of Director 83/03/29 1p 18834 224 24X Fiche 50-416, 83/06/07, B306140559
- B306140574 Notice of deviation from insp on 830215-17
* Region 2, Office of Director 83/03/29 1p 18834 227 24X Fiche 50-416, 83/06/07, B306140559
- B306140583 IE Insp Repts 50-416/83-06 & 50-417/83-03 on 830215-17 Noncompliance noted failure to conduct training in facility design changes Deviation from commitments contained in FEAR re shift technical advisor training also noted
HEHL, C W , MUNRO, J F , CASIATI, M E Region 2, Office of Director 83/03/10 8pp 18834 228 24X Fiche 50-416, 83/06/07, B306140559
- B306290211 Responds to IE Bulletin 83-03 re check valve failures in raw water cooling sys of diesel generators Three check valves in standby svc water sys meet applicable criteria Addl response will be submitted when valve verification completed
RICHARD, J B Mississippi Power & Light Co 83/06/07 O'REILLY, J P Region 2, Office of Director 4pp 19056 130 24X Fiche 50-416, 83/06/07, B306290211
- B305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, B305110464
- B306140724 Application to amend License N/F-13, consisting of Tech Spec Change PCOL-83/08, per 821020 confirmation of action ltr Changes enhance clarity & provide consistency w/plant design & operation
DALE, L F Mississippi Power & Light Co 83/06/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18841 017 24X Fiche 50-416, 83/06/09, B306140724
- B306140729 Proposed Tech Spec Change PCOL-83/08, enhancing clarity & providing consistency w/plant design & operation, per 821020 confirmation of action ltr
* Mississippi Power & Light Co 83/06/09 72pp 18841 019 24X Fiche 50-416, 83/06/09, B306140724
- B305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, B305110470
- B306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, B306090010
- B306210236 Discusses IE insp on 830429 & 0503-04 & forwards notice of violation & proposed imposition of civil penalty as result of violations identified in IE Insp Rept 50-416/83-17
O'REILLY, J P Director's Office, Office of Inspection and Enforcement 83/06/13 RICHARD, J B Mississippi Power & Light Co 2pp 18916 059 24X Fiche 50-416, 83/06/13, B306210236
- B306210243 Notice of violation & proposed imposition of civil penalty in amount of \$40,000 Noncompliance noted security force member, posted to control access to lower containment hatch, found asleep
O'REILLY, J P Director's Office, Office of Inspection and Enforcement 83/06/13 2pp 18916 061 24X Fiche 50-416, 83/06/13, B306210236
- B305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, B305110475
- B305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, B305110477
- B305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, B305110479
- B306270114 Revises 800319 commitment in response to Question 8 in IE Bulletin 79-08 re maint & test procedures Operations section procedure will specify verification by test or insp of operability of redundant safety-related sys
DALE, L F Mississippi Power & Light Co 83/06/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 18988 020 24X Fiche 50-416, 83/06/23, B306270114
- B305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, B305110483

DOCKETED ITEMS

R Periodic operating reports & related correspondence

8306200412 Monthly operating rept for May 1983 W/830615 ltr
 RICHARDSON, J D, DALE, L F Mississippi Power & Light Co 83/06/14
 DEYOUNG, R C Director's Office, Office of Inspection and
 Enforcement 7pp 18899 004 24X Fiche 50-416, 83/06/14, 8306200412

S Reportable occurrences, LHs & related correspondence

8306070237 Updated LER 83-041/03X-1 on 830131, eight penetrations
 opened in control bldg to allow conduit routing. Caused by
 planned maint Hourly fire watch conducted for open
 penetrations Restoration scheduled for 830630 W/830509 ltr
 ROHRER, M V, MCGAUGHY, J P Mississippi Power & Light Co 83/05/07
 O'REILLY, J P Region 2, Office of Director 3pp 18740 293 24X
 Fiche 50-416, 83/05/09, 8306070237

8306140303 Summaries 830420 meeting at Region 11 of re const
 deficiency rept on plates embedded in reactor pressure
 vessel pedestal & newly formed Nuclear Oversight Committee
 of Middle South Utilis Meeting details & attendee list and
 LEWIS, R C Division of Project & Resident Programs 83/05/09
 RICHARD, J B Mississippi Power & Light Co 3pp 18832 104 24X
 Fiche 50-416, 83/05/09, 8306140303

8306070089 Updated RO 83-001/1 on 830204, smoke detectors in L445 pump
 room covered to perform planned activity Hourly fire watch
 established Work still in progress Restoration date for
 smoke detectors estimated for 830615
 MCGAUGHY, J P Mississippi Power & Light Co 83/05/17
 O'REILLY, J P Region 2, Office of Director 2pp 18739 113 24X
 Fiche 50-416, 83/05/17, 8306070089

8306010244 Updated LER 83-039/44X-1 on 830112, Halon panel 1H1JP911
 detector A found continuously alarming w/no fire or smoke &
 could not be reset Alarm reset Limiting condition of
 operation lifted on 830503 W/830520 ltr
 MCGAUGHY, J P, BYRD, R Mississippi Power & Light Co 83/05/20
 O'REILLY, J P Region 2, Office of Director 2pp 18672 292 24X
 Fiche 50-416, 83/05/20, 8306010244

8306010261 RO 83-035/0 on 830415, Fire Door 1A401 blocked open to
 prevent possibility of personnel injury due to high
 differential pressure across door as result of secondary
 containment boundary Door to be closed 830630
 MCGAUGHY, J P Mississippi Power & Light Co 83/05/20
 O'REILLY, J P Region 2, Office of Director 2pp 18672 289 24X
 Fiche 50-416, 83/05/20, 8306010261

8306070142 RO 83-037/0 on 830421, Fire Doors 1A214 & 1A210 opened to
 route air hoses into adjacent motor control ctr Div I
 switchgear rooms for planned maint during scheduled
 electrical outage Doors secured on 830509
 MCGAUGHY, J P Mississippi Power & Light Co 83/05/25
 O'REILLY, J P Region 2, Office of Director 2pp 18739 255 24X
 Fiche: 50-416, 83/05/25, 8306070142

8306070230 RO 83-036/0 on 830418, fire-rated penetration DE-20A opened
 to route cable to supply temporary power to Div I lighting
 transformer 1X113 during planned electrical outage
 Restoration scheduled for 830615
 MCGAUGHY, J P Mississippi Power & Light Co 83/05/25
 O'REILLY, J P Region 2, Office of Director 2pp 18746 109 24X
 Fiche 50-416, 83/05/25, 8306070230

8306070228 RO 83-039/0 on 830414, fire detection zone 2-1B alarmed &
 would not reset Caused by dust particles on ionization
 detector. Detectors cleaned & restored to operability on
 830505
 MCGAUGHY, J P Mississippi Power & Light Co 83/05/26
 O'REILLY, J P Region 2, Office of Director 1p 18744 216 24X
 Fiche 50-416, 83/05/26, 8306070228

8306070410 RO 83-038/0 on 830426, control room ambient air temp
 exceeded area temp limit of Tech Spec Table 3 7 8-1 Caused
 by lack of operating control room HVAC subvys Availability
 of operability of equipment not affected
 MCGAUGHY, J P Mississippi Power & Light Co 83/05/26
 O'REILLY, J P Region 2, Office of Director 2pp 18742 273 24X
 Fiche: 50-416, 83/05/26, 8306070410

8306070004 Updated LER 83-058/01X-1 on 830211, discovered that fire
 watches not conducted in two areas of fire detection zone
 2-19 Limiting conditions for operation entered on 830227
 Caused by personnel oversight Zone restored W/830527 ltr
 BYRD, R, MCGAUGHY, J P Mississippi Power & Light Co 83/05/27
 O'REILLY, J P Region 2, Office of Director 3pp 18728 344 24X
 Fiche 50-416, 83/05/27, 8306070004

8306090134 RO 83-040/0 on 830424, listed fire rated penetrations
 to implement design change packages Hourly fire watches
 established & will be maintained Work tasks expected to be
 completed by 830701
 RICHARD, J B Mississippi Power & Light Co 83/05/31 O'REILLY
 Region 2, Office of Director 3pp 18742 276 24X
 Fiche 50-416, 83/05/31, 8306090134

8306100251 Final Deficiency Rept PRD-82/27 re potential for p...
 flooding based on PMP flood level Watertight door seals, toe
 plate & curb to be installed & two penetrations raised Also
 reportable under Part 21
 MCGAUGHY, J P Mississippi Power & Light Co 83/05/31
 O'REILLY, J P Region 2, Office of Director 3pp 18807 117 24X
 Fiche 50-416, 83/05/31, 8306100251

8306100219 Sixth Interim Deficiency Rept PRD-02/14 re sheared bolts
 diesel generator rear crankcase cover Initially reported on
 820322 Deficiency reportable under 10CFR50 55(c) & Part 21
 for Unit 1, Div 11 diesel generator only
 MCGAUGHY, J P Mississippi Power & Light Co 83/06/01
 O'REILLY, J P Region 2, Office of Director 6pp 18805 183 24X
 Fiche 50-416, 83/06/01, 8306100219

8306140046 LER 83-021/01T-0 on 830519, while in cold shutdown, the
 gas treatment sys flow monitoring instrumentation found
 reading in error Caused by incorrect calibr range Correct
 calibr ranges issued W/830602 ltr
 BYRD, R, SHINGLETON, B, MCGAUGHY, J P Mississippi Power & Light Co
 83/06/02 O'REILLY, J P Region 2, Office of Director 2pp
 18838 300 24X Fiche 50-416, 83/06/02, 8306140046

8306140084 Updated LER 82-150/99X-2 on 821122, limiting condition
 operation entered when five fire rated floor penetrations in
 auxiliary bldg opened Caused by cable routing Penetrations
 resealed W/830602 ltr
 BYRD, R, MCGAUGHY, J P Mississippi Power & Light Co 83/06/02
 O'REILLY, J P Region 2, Office of Director 3pp 18838 351 24X
 Fiche 50-416, 83/06/02, 8306140084

8306140384 Updated LER 83-010/47X-1 on 830105, during insp of coils
 fire protection deficiencies on redundant raceways, similar
 deficiencies noted in auxiliary, turbine & control bldgs
 Const completion expected by Jul 1983 W/830602 ltr
 BYRD, R, MCGAUGHY, J P Mississippi Power & Light Co 83/06/02
 O'REILLY, J P Region 2, Office of Director 4pp 18832 115 24X
 Fiche 50-416, 83/06/02, 8306140384

8306140669 Updated LER 83-052/02X-1 on 830411, vessel head & vessel
 flange thermocouples not physically mounted on respective
 surfaces Event incorrectly reported due to inadequate
 procedures Procedures to be revised by 830701 W/830602 ltr
 ROHRER, M V, SHINGLETON, B, MCGAUGHY, J P Mississippi Power &
 Light Co 83/06/02 O'REILLY, J P Region 2, Office of Director
 3pp 18842 094 24X Fiche 50-416, 83/06/02, 8306140669

8306140611 LER 83-062/03L-0 on 830504, limiting condition for operat...
 entered due to inoperability of diesel generators Caused by
 binding linkage from engine governor to fuel injector pump
 W/830603 ltr
 BYRD, R, MCGAUGHY, J P Mississippi Power & Light Co 83/06/03
 O'REILLY, J P Region 2, Office of Director 3pp 18842 077 24X
 Fiche 50-416, 83/06/03, 8306140611

8306100235 Final Deficiency Rept PRD-83/06 re failure to provide
 corrosion resistant matl in carbon steel instrument air
 penetration Initially reported on 830315 Util preparing
 design change package Also reportable per Part 21
 MCGAUGHY, J P Mississippi Power & Light Co 83/06/06
 O'REILLY, J P Region 2, Office of Director 4pp 18807 131 24X
 Fiche 50-416, 83/06/06, 8306100235

8306140259 Final Deficiency Rept PRD-83/05 re stress relieving of A...
 sockets by vendor not appearing on AE evaluated supplier
 list Initially reported on 830308 Condition not reportable
 per 10CFR50 55(c)
 MCGAUGHY, J P Mississippi Power & Light Co 83/06/06
 O'REILLY, J P Region 2, Office of Director 4pp 18833 023 24X
 Fiche 50-416, 83/06/06, 8306140259

8306200121 LER 83-064/01T-0 on 830524, inconsistencies & problems
 associated w/onsite chlorine storage identified during
 internal review of FSAR Caused by lack of administrative
 controls W/830607 ltr
 SHINGLETON, B, MCGAUGHY, J P Mississippi Power & Light Co
 83/06/07 O'REILLY, J P Region 2, Office of Director 3pp
 18903 323 24X Fiche 50-416, 83/06/07, 8306200121

8306200133 Interim Deficiency Rept 3 re Neutron stud failures on type
 embed plates Initially reported on 821211 Unit 1 embed
 plates replaced w/surface mounted plates final rept to be
 submitted by 830705 Also reported per Part 21
 MCGAUGHY, J P Mississippi Power & Light Co 83/06/07
 O'REILLY, J P Region 2, Office of Director 6pp 18903 285 24X
 Fiche 50-416, 83/06/07, 8306200133

DOCKETED ITEMS

297

B306200250 RD B3 041/0 on B30424, smoke detectors in upper & lower cable spreading rooms of control bldg were covered & deactivated to prevent inadvertent activation from welding activities. Detectors not uncovered within 14 days.
MCGAUGHY, J P Mississippi Power & Light Co B3/06/07
O'REILLY, J P Region 2, Office of Director 1p 18701 186 24X
Fiche 50-416, B3/06/07, B306200250

B306140676 EN-B3 041 on B30613, notice of violation & proposed imposition of civil penalty in amount of \$40,000 will be issued. Action based on utility failure to control access to vital area. Licensee may respond within 30 days.
RDSANU, R, AXILRAD, J Director's Office, Office of Inspection and Enforcement B3/06/08 1p 18741 24, 24X Fiche 50-416, B3/06/08, B306140676

B306200142 LER B3-064/OIT-0 on B30526, deficiencies in 18-month battery cell & terminal connection resistance readings identified. Caused by personnel error & procedural inadequacy. Surveillance procedure will be revised W/B30609 ltr.
BYRD, R, MCGAUGHY, J P Mississippi Power & Light Co B3/06/09
O'REILLY, J P Region 2, Office of Director 3pp 18703 24, 24X
Fiche 50-416, B3/06/09, B306200142

B306270439 Second Interim Part II Rept R40-B3/08 re inability to maintain pressurized water supply to HR pumps & discharge piping. Initially reported on B30415. Final rept expected by B40201.
MCGAUGHY, J P Mississippi Power & Light Co B3/06/13
O'REILLY, J P Region 2, Office of Director 3pp 18792 067 24X
Fiche 50-416, B3/06/13, B306270439

B306280327 Updated RD B3-010/1 on B30209, smoke detectors covered to prevent continuous alarms during grinding & welding. Hourly fire watch conducted. Zones expected to be restored by B30630. Add'l fire zone listed.
MCGAUGHY, J P Mississippi Power & Light Co B3/06/13
O'REILLY, J P Region 2, Office of Director 3pp 17003 24, 24X
Fiche 50-416, B3/06/13, B306280327

B306270146 Final Deficiency Rept R40-B3/07 re two Div II cables improperly routed outside scheduled conduit. Initially reported on B30414. Design change package issued to rework cables. Also reportable per Part II for Unit 1.
MCGAUGHY, J P Mississippi Power & Light Co B3/06/14
O'REILLY, J P Region 2, Office of Director 4pp 18796 122 24X
Fiche 50-416, B3/06/14, B306270146

B306270126 Updated RD B3-015/2 three open penetrations identified. Caused by incomplete design drawings on const oversight. Mail nonconformance repts initiated to correct deficiencies. Estimated restoration date is B30721.
MCGAUGHY, J P Mississippi Power & Light Co B3/06/15
O'REILLY, J P Region 2, Office of Director 2pp 18788 087 24X
Fiche 50-416, B3/06/15, B306270126

B306270132 RD B3-047/0 on B30504, smoke detectors in control of control bldg covered to allow welding. Hourly fire watch established. Detectors will be restored by B30725.
MCGAUGHY, J P Mississippi Power & Light Co B3/06/15
O'REILLY, J P Region 2, Office of Director 2pp 18788 147 24X
Fiche 50-416, B3/06/15, B306270132

B306280188 RD B3 043/0 on B30504, smoke detector N524E, in Zone 1 24 (control cabinet room), alarmed continuously after being bumped by maint worker. Fire detection zone declared inoperable. Fire watch established. No cruise found.
MCGAUGHY, J P Mississippi Power & Light Co B3/06/15
O'REILLY, J P Region 2, Office of Director 1p 17015 003 24X
Fiche 50-416, B3/06/15, B306280188

B306280287 RD B3 044/0 on B30509, listed fire-related penetrations opened to implement design change packages. Hourly fire watches established within 1 h & maintained for duration of planned maint activities.
MCGAUGHY, J P Mississippi Power & Light Co B3/06/15
O'REILLY, J P Region 2, Office of Director 3pp 17014 246 24X
Fiche 50-416, B3/06/15, B306280287

B306280471 LER B3-066/031-0 on B30517, while in cold shutdown, at dc electrical power distribution weekly lineup exceeded 10% date of B30516. Limiting conditions of operations entered. Caused by improper scheduling W/B30616 ltr.
BYRD, R, MCGAUGHY, J P Mississippi Power & Light Co B3/06/16
O'REILLY, J P Region 2, Office of Director 3pp 17018 291 24X
Fiche 50-416, B3/06/16, B306280471

B306280555 LER B3-068/OIT-0 on B30603, discrepancy noted between Tech Spec Table 3 & 6 B-1 & FSAR Section 15.7.4.5.2 isolation damper max closure time. Tech Spec change requested. Procedures revised W/B30616 ltr.
BYRD, R, MCGAUGHY, J P Mississippi Power & Light Co B3/06/16
O'REILLY, J P Region 2, Office of Director 3pp 17017 301 24X
Fiche 50-416, B3/06/16, B306280555

B306270165 RD B3 045/0 on B30515, Fire Doors DC901 & DC503 on east side of control room blocked open to allow routing of hoses to seal fire-rated penetrations in control room. Fire watch established. Completion expected by B30725.
MCGAUGHY, J P Mississippi Power & Light Co B3/06/17
O'REILLY, J P Region 2, Office of Director 2pp 18792 021 24X
Fiche 50-416, B3/06/17, B306270165

B306300175 RD B3 046/0 on B30515, during surveillance testing, Fire Door DC103 found damaged & in constant alarm. Caused by damaged latch mechanism due to heavy use. Repair work will be completed by B30630. Hourly fire watch established.
MCGAUGHY, J P Mississippi Power & Light Co B3/06/20
O'REILLY, J P Region 2, Office of Director 2pp 17119 267 24X
Fiche 50-416, B3/06/20, B306300175

B306300163 RD B3-048/0 on B30517, reactor protection sys motor generator room Fire Door DC412 blocked open to support planned work activity. Fire watch established until door restored on B30602.
MCGAUGHY, J P Mississippi Power & Light Co B3/06/22
O'REILLY, J P Region 2, Office of Director 1p 17119 279 24X
Fiche 50-416, B3/06/22, B306300163

V Operator Examinations

B306140102 Requests approved re: mat re operator exams by B30531. Missing deadline will delay in administering exams. All applications should be submitted at least 60 days prior to first exam scheduled for B30725.
VERRELLI, D M Division of Project & Resident Programs B3/04/27
RICHARD, J B Mississippi Power & Light Co 3pp 18839 097 24X
Fiche 50-416, B3/04/27, B306140102

DOCKET 50-417 GRAND GULF NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

B306010074 Forwards comments re review of B30118 proposed changes to STB, per informal request. Proposed change to Surveillance Requirement 4 & 6.3 re continuous operation of heaters should not be implemented.
DALE, L F Mississippi Power & Light Co B3/05/24
HOUSTON, M D Division of Licensing 2pp 18673 272 24X
Fiche 50-416, B3/05/24, B306010074

B306140666 Summarizes B30511 meeting at Region II of re changes to Tech Specs required prior to Unit 1 startup. Meeting details & attendee list encl.
LEWIS, R C Division of Project & Resident Programs B3/05/27
RICHARD, J B Mississippi Power & Light Co 3pp 18842 089 24X
Fiche 50-416, B3/05/27, B306140666

B306230167 Forwards add'l info re Hydrogen Control Owners Group program, per NRC B30203 request. Proprietary & nonproprietary versions of "Grand Gulf Drywell Break Sensitivity Summary" encl.
DALE, L F Mississippi Power & Light Co B3/06/16
DENTON, H R Office of Nuclear Reactor Regulation, Director 1pp, 18745 299, 24X
Fiche 50-416, B3/06/16, B306230167

--B306230167 Nonproprietary version of "Grand Gulf Drywell Break Sensitivity Summary".
GUNTER, A D Offshore Power Systems (subs of Westinghouse Electric Corp.) OPS-39AB2 RA B3/05/11 397pp 18745 311 24X
Fiche 50-416, B3/05/11, B306230167

B306270289 Clarifies capabilities of hydrogen ignition sys under all circumstances, per Schwencer 811106 ltr & NUREG/CR-2484. Under worst case conditions, min voltage required would be 10.0B volts.
DALE, L F Mississippi Power & Light Co B3/06/23
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18796 196 24X
Fiche 50-416, B3/06/23, B306270289

E NRC Safety Evaluation Report (SER), supp's & correspondence

B306210331 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF GRAND GULF NUCLEAR STATION, UNITS 1 & 2. Docket Nos 50-416 & 50-417 (Mississippi Power and Light Company).
* Division of Licensing NUREG-0831 004 B3/05/31, 156pp
Available at NRC \$5.50 10722 197 24X
Fiche 50-416, B3/05/31, B306210331

B306200429 Forwards Suppl 4 to SER, NUREG-0831 W/O encl.
SCHWENCER, A Licensing Branch 2 B3/06/13
MCGAUGHY, J P Mississippi Power & Light Co 4pp 10720 019 24X
Fiche 50-416, B3/06/13, B306200429

DOCKETED ITEMS

--B306200430 Forwards Suppl 4 to SER W/o encl
 * Office of Nuclear Reactor Regulation, Director 03/06/17
 SIMPSON, A Senate, Environment & Public Works 1p 18720 043
 24X Fiche 50-416, 83/06/13, B306200429

--B306200431 Forwards Suppl 4 to SER W/o encl
 * Office of Nuclear Reactor Regulation, Director 03/06/17
 UDALL, M House of Rep., Interior & Insular Affairs 1p
 18920 024 24X Fiche 50-416, 83/06/13, B306200429

--B306200432 Forwards Suppl 4 to SER W/o encl
 * Office of Nuclear Reactor Regulation, Director 03/06/13
 OTTINGER, R House of Rep., Energy & Commerce 1p 18920 024
 24X Fiche 50-416, 83/06/13, B306200429

F Security, medical, emergency & fire protection plans

B306140519 Confirms B30511 enforcement conference at Region II o/c to discuss security violations at facility & Tech Spec changes required prior to nuclear heatup, per B30505 telcon Proposed meeting agenda encl
 O'REILLY, J P Region 2, Office of Director 03/05/06 RICHARD, J B
 Mississippi Power & Light Co 2pp 18838 106 24X
 Fiche 50-416, 83/05/06, B306140519

B306060079 Confirms B30602 telcon re submittal of implementation schedule for backup emergency operations facility by B30617
 DALE, L F Mississippi Power & Light Co 03/06/02 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 1p 18719 031 24X
 Fiche 50-416, 83/06/02, B306060079

B306210140 Advises that Baxter Wilson plant selected for backup emergency operations facility Telephone capability will be expanded & antennas for offsite radiological monitoring radio will be installed Emergency plan revised
 DALE, L F Mississippi Power & Light Co 03/06/17 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 2pp 18914 224
 24X Fiche 50-416, 83/06/17, B306210140

K Utility Final Safety Analysis Report (FSAR) & amends

B306200186 Forwards Amend 56 to FSAR, updating sections dealing primarily w/fire protection & incorporating minor editorial corrections & clarifications to other FSAR sections
 MCGOUGH, J P Mississippi Power & Light Co 03/06/17 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 3pp 18905 003
 24X Fiche 50-416, 83/06/17, B306200186

--B306200189 Amend 56 to FSAR
 MCGOUGH, J P Mississippi Power & Light Co 03/06/30 1.200pp
 18905 006 24X Fiche 50-416, 83/06/17, B306200186

Q Inspection reports, IE Bulletins & correspondence

B306140561 Confirms mgt meeting on B30210 in Jackson, MS to discuss results of review of first phase of annual appraisal of regulatory performance Proposed meeting agenda encl
 LEWIS, R C Division of Project & Resident Programs 03/01/28
 STAMPLEY, N L Mississippi Power & Light Co 3pp 18834 236 24X
 Fiche 50-416, 83/01/28, B306140561

B306140028 Confirms B30408 mgt meeting at Region II o/c, per B30323 telcon Util will discuss "Grand Gulf Nuclear Station Operations Enhancement Program" Agenda encl
 O'REILLY, J P Region 2, Office of Director 03/03/25 RICHARD, J B
 Mississippi Power & Light Co 2pp 18838 229 24X
 Fiche 50-416, 83/03/25, B306140028

B306140602 Confirms B30420 enforcement conference at Region II o/c to discuss control of mods & maint & adequacy of corrective action in area of temporary alterations, per B30408 & II telcons Agenda encl
 O'REILLY, J P Region 2, Office of Director 03/04/13 RICHARD, J B
 Mississippi Power & Light Co 3pp 18833 175 24X
 Fiche 50-416, 83/04/13, B306140602

B306140634 Forwards summary of B30408 meeting in Atlanta, GA re util B30311 rept, "Grand Gulf Nuclear Station Operations Enhancement Program" Implementation will be beneficial to plant operations W/attendance list
 LEWIS, R C Division of Project & Resident Programs 03/04/29
 RICHARD, J B Mississippi Power & Light Co 6pp 18843 050 24X
 Fiche 50-416, 83/04/29, B306140634

B306140519 Confirms B30511 enforcement conference at Region II o/c to discuss security violations at facility & Tech Spec changes required prior to nuclear heatup, per B30505 telcon Proposed meeting agenda encl
 O'REILLY, J P Region 2, Office of Director 03/05/06 RICHARD, J B
 Mississippi Power & Light Co 2pp 18838 106 24X
 Fiche 50-416, 83/05/06, B306140519

B305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl
 TAYLOR, J M Division of Safeguards & Inspection Programs (Post B30103) 03/05/26 Consolidated Edition Co of New York, Inc
 125pp 18831 043 24X Fiche 50-000, 83/05/26, B305110458

B305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 03/05/26 Consolidated Edition Co of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, B305110460

B305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs" Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 03/05/31 Consolidated Edition Co of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, B305110461

B306290365 Forwards IE Insp Repts 50-416/83-16 & 50-417/83-05 on B30507-13 Noncompliance noted
 VERRELLI, D M Division of Project & Resident Programs 03/06/03
 RICHARD, J B Mississippi Power & Light Co 2pp 17055 220 24X
 Fiche 50-416, 83/06/03, B306290365

--B306290371 IE Insp Repts 50-416/83-16 & 50-417/83-05 on B30507 13 Noncompliance noted Major areas inspected licensee action in previous enforcement matters, structural concrete, licensee identified items & followup items
 HARRIS, J R Region 2, Office of Director CONNOLLY, T F Division of Engineering & Radiological Safety Programs 03/05/31 4pp 19053 222 24X Fiche 50-416, 83/06/03, B306290365

B306140450 Ack receipt of B30517 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-416/83-12
 VERRELLI, D M Division of Project & Resident Programs 03/06/07
 RICHARD, J B Mississippi Power & Light Co 1p 18840 18/ 24X
 Fiche 50-416, 83/06/07, B306140450

--B306140463 Forwards IE Insp Repts 50-416/83-12 & 50-417/83-04 on B30322-25 & notice of violation
 VERRELLI, D M Division of Project & Resident Programs 03/04/19
 RICHARD, J B Mississippi Power & Light Co 2pp 18840 190 24X
 Fiche 50-416, 83/06/07, B306140450

--B306140474 IE Insp Repts 50-416/83-12 & 50-417/83-04 on B30122-25 Noncompliance noted failure to complete control bldg masonry wall mods in accordance w/drawing requirements
 LENAHAN, J J Region 2, Office of Director CONNOLLY, T F Division of Engineering & Radiological Safety Programs 03/04/14 7pp 18840 194 24X Fiche 50-416, 83/06/07, B306140450

B306140559 Ack receipt of B30506 ltr informing NRC of steps taken to correct violation & deviation noted in IE Insp Repts 50-416/83-06 & 50-417/83-03 Notice of deviation retracted based on B30319 & 0421 ltrs referenced in suppl 2 to SER
 LEWIS, R C Division of Project & Resident Programs 03/06/07
 RICHARD, J B Mississippi Power & Light Co 1p 18834 220 24X
 Fiche 50-416, 83/06/07, B306140559

--B306140569 Forwards IE Insp Repts 50-416/83-06 & 50-417/83-03 on B30215-17 & notices of violation & deviation
 LEWIS, R C Division of Project & Resident Programs 03/03/29
 RICHARD, J B Mississippi Power & Light Co 2pp 18834 224 24X
 Fiche 50-416, 83/06/07, B306140559

--B306140583 IE Insp Repts 50-416/83-06 & 50-417/83-03 on B30215-17 Noncompliance noted failure to conduct training in facility design changes Deviation from commitments contained in FSAR re shift technical advisor training also noted
 HEHL, C W, MUNRO, J F, CASHIAT, M L Region 2, Office of Director 03/03/10 6pp 18834 228 24X Fiche 50-416, 83/06/07, B306140559

B306290211 Responds to IE Bulletin 83-03 re check valve failures in raw water cooling sys of diesel generators Three check valves in standby svc water sys meet applicable criteria Add'l responses will be submitted when valve verification completed
 RICHARD, J B Mississippi Power & Light Co 03/06/07 O'REILLY, J P
 Region 2, Office of Director 4pp 19056 130 24X
 Fiche 50-416, 83/06/07, B306290211

B305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations" Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 03/06/09 Consolidated Edition Co of New York, Inc 117pp 18830 280 24X Fiche 50-000, 83/06/09, B305110464

B305110470 IE Info Notice 83-30, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards" Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 03/06/13 Consolidated Edition Co of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, B305110470

DOCKETED ITEMS

299

8306070010 IE Info Notice 83-37, "Transformer Failure Resulting from Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 24pp 18921 001 24X Fiche 50-000,83/06/13,8306070010

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 115pp 19021 177 24X Fiche 50-000,83/06/23,8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000,83/06/22,8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000,83/06/23,8305110479

S Reportable occurrences, LERs & related correspondence

8306140303 Summarizes 830420 meeting at Region II of re const deficiency rept on plates embedded in reactor pressure vessel pedestal & newly formed Nuclear Oversight Committee of Middle South Util Meeting details & attendee list encl
LEWIS, R C Division of Project & Resident Programs 83/05/07
RICHARD, J B Mississippi Power & Light Co 5pp 18802 104 24X Fiche 50-416,83/05/07,8306140303

8306100251 Final Deficiency Rept PRD-82/27 re potential for plant flooding based on PMP flood level Watertight door seals, top plate & curb to be installed & two penetrations raised Also reportable under Part 21
MCQUAGHY, J P Mississippi Power & Light Co 83/05/31
O'REILLY, J P Region 2, Office of Director 5pp 18807 149 24X Fiche 50-416,83/05/31,8306100251

8306100219 Sixth Interim Deficiency Rept PRD-82/14 re sheared bolts on diesel generator rear crankcase cover Initially reported on 820322 Deficiency reportable under 10CFR50 55(e) & Part 21 for Unit 1, Div II diesel generator only
MCQUAGHY, J P Mississippi Power & Light Co 83/06/01
O'REILLY, J P Region 2, Office of Director 6pp 18805 183 24X Fiche 50-416,83/06/01,8306100219

8306100235 Final Deficiency Rept PRD-83/06 re failure to provide corrosion-resistant matl in carbon steel instrument air penetration Initially reported on 830315 Util prepaving design change package Also reportable per Part 21
MCQUAGHY, J P Mississippi Power & Light Co 83/06/06
O'REILLY, J P Region 2, Office of Director 4pp 18807 150 24X Fiche 50-416,83/06/06,8306100235

8306140257 Final Deficiency Rept PRD-83/05 re stress relieving of R608 sockets by vendor not appearing on AE evaluated supplier list Initially reported on 830308 Condition not reportable per 10CFR50 55(e)
MCQUAGHY, J P Mississippi Power & Light Co 83/06/06
O'REILLY, J P Region 2, Office of Director 4pp 18803 073 24X Fiche 50-416,83/06/06,8306140257

8306200133 Interim Deficiency Rept 3 re Nelson stud failures on Type 06 embed plates Initially reported on 821221 Unit 1 embed plates replaced w/surface mounted plates Final rept to be submitted by 830705 Also reported per Part 21
MCQUAGHY, J P Mississippi Power & Light Co 83/06/07
O'REILLY, J P Region 2, Office of Director 6pp 18903 285 24X Fiche 50-416,83/06/07,8306200133

8306270439 Second Interim Part 21 Rept PRD-83/08 re inability to maintain pressurized water supply to MHR pumps & discharge piping Initially reported on 830415 Final rept expected by 840201
MCQUAGHY, J P Mississippi Power & Light Co 83/06/13
O'REILLY, J P Region 2, Office of Director 5pp 18992 067 24X Fiche 50-416,83/06/13,8306270439

8306270346 Final Deficiency Rept PRD-83/07 re two Div II cables improperly routed outside scheduled conduit Initially reported on 830412 Design change package issued to rework cables Also reportable per Part 21 for Unit 1
MCQUAGHY, J P Mississippi Power & Light Co 83/06/14
O'REILLY, J P Region 2, Office of Director 4pp 18996 222 24X Fiche 50-416,83/06/14,8306270346

V Operator Examinations

8306140102 Requests approved ref matl re operator exams by 830531 Missing deadline will delay in administering exams All applications should be submitted at least 60 days prior to first exam scheduled for 830725
VERRELLI, D M Division of Project & Resident Programs 83/04/27
RICHARD, J B Mississippi Power & Light Co 3pp 18839 097 24X Fiche 50-416,83/04/27,8306140102

DOCKET 50-423 HILLSTONE NUCLEAR POWER STATION, UNIT 3

A Application/construction stage documents & correspondence

8306020069 Notification of 830601-02 meetings w/util & B&W in Bethesda, MD to discuss safety review questions re portions of FSAR
DODLITTLE, E L Licensing Branch 1 83/05/24 Licensing Branch 1 4pp 18701 338 24X Fiche 50-423,83/05/24,8306020069

8306060143 Submits revised list of joint facility owners All other names should be deleted from svc list
COUNSILL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSILL, W G Northeast Utilities 83/05/31
YOUNGBLOOD, B J Licensing Branch 1 2pp 18719 022 24X Fiche 50-423,83/05/31,8306060143

8306070459 Forwards request for addl info re application for OL Requests are result of Instrumentation & Control Sys, Reactor Sys, Accident Evaluation, Core Performance & Power Sys Branch review of FSAR
YOUNGBLOOD, B J Licensing Branch 1 83/05/31 COUNSILL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 71pp 18780 240 24X Fiche 50-423,83/05/31,8306070459

8306080433 Notification of 830602 & 09 meetings w/util in Bethesda, MD to discuss NRC safety review questions re portions of FSAR Meeting originally scheduled for 830601
DODLITTLE, E L Licensing Branch 1 83/06/01 YOUNGBLOOD, B J Licensing Branch 1 4pp 18792 189 24X Fiche 50-423,83/06/01,8306080433

8306160412 Forwards draft Rev 5 to "QA Program Topical Rept " COUNSILL, W G Northeast Utilities Service Co 83/06/09 MURLEY, T E Region 1, Office of Director 6pp 18859 090 24X Fiche 50-000,83/06/09,8306160412

--8306160424 Draft Rev 5 to "QA Program Topical Rept " Northeast Utilities 83/06/09 135pp 18859 096 24X Fiche 50-000,83/06/09,8306160412

8306220167 Notification of 830707 meeting w/util in Waterford & Berlin, CT to discuss applicants responses to QA Branch safety review questions
DODLITTLE, E L Licensing Branch 1 83/06/10 YOUNGBLOOD, B J Licensing Branch 1 3pp 18737 319 24X Fiche 50-423,83/06/10,8306220167

8306230141 Notification of 830629 meeting w/util in Bethesda, MD to discuss specific design info needed by NRC to complete review of RCPB matls Meeting originally scheduled on 830616
DODLITTLE, E L Licensing Branch 1 83/06/21 YOUNGBLOOD, B J Licensing Branch 1 3pp 18954 349 24X Fiche 50-423,83/06/21,8306230141

8306230145 Notification of 830726-28 meetings w/util & S&W in Boston, MA to discuss Instrumentation & Control Sys Branch safety review meeting agenda items
DODLITTLE, E L Licensing Branch 1 83/06/21 YOUNGBLOOD, B J Licensing Branch 1 3pp 18954 352 24X Fiche 50-423,83/06/21,8306230145

C Utility Environmental Report (ER), amends & correspondence

8306020045 Notifies of changes in schedule for review of environ rept. Adjustments will result in Nov 1984 issuance date Safety review schedule unchanged Overall licensing schedule not expected to be affected
NOVAK, T M Division of Licensing 83/05/27 KNIGHT, J P Assistant Director for Comp & Structures Engineering (Pre 830201)
JOHNSTON, W V Assistant Director for Matls & Qualif Engineering (Pre 830201) MULLER, D R Assistant Director for Radiation Protection 4pp 18701 358 24X Fiche 50-423,83/05/27,8306020045

DOCKETED ITEMS

D NRC Draft/Final Environmental Statements, suppl's & correspondence

B306240077 Notifies of B30720-21 site visit as part of review process for EIS associated w/application for OL Open public meeting planned on B30721 Agenda encl
NOVAK, T H Assistant Director for Licensing B3/06/20
BETTENCOURT, L Waterford, CT 3pp 18787 136 24X
Fiche 50-423, B3/06/20, B306240077

G Inspection reports, IE Bulletins & correspondence

B306060205 Forwards IE Insp Rept 50-423/B3-06 on B30328-0501 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs B3/05/23
COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 18727 339 24X Fiche 50-423, B3/05/23, B306060205

--B306060211 IE Insp Rept 50-423/B3-06 on B30328-0501 No noncompliance noted Major areas inspected environ protection commitments, welds in main control room panels, baseline inservice insp of reactor vessel head & licensee reportable items
REBELDMSKI, T, ORANT, J, ELSSASSER, T C Region 1, Office of Director B3/05/18 7pp 18727 341 24X Fiche 50-423, B3/05/23, B306060205

B305110458 IE Info Notice B3-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post B30103) B3/05/26 Consolidated Edison Co of New York, Inc 125pp 18821 043 24X Fiche 50-000, B3/05/26, B305110458

B305110460 IE Info Notice B3-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche 50-000, B3/05/26, B305110460

B305110461 IE Info Notice B3-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000, B3/05/31, B305110461

B306200082 Forwards IE Insp Rept 50-423/B3-09 on B30510-12 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs B3/06/04
COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 18903 345 24X Fiche 50-423, B3/06/06, B306200082

--B306200086 IE Insp Rept 50-423/B3-09 on B30510-12 No noncompliance noted Major areas inspected installation of electrical safety-related equipment
FINKEL, A E, ANDERSON, C Region 1, Office of Director B3/06/01 6pp 18903 347 24X Fiche 50-423, B3/06/06, B306200082

B305110464 IE Info Notice B3-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fiche 50-000, B3/06/09, B305110464

B305110470 IE Info Notice B3-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225 24X Fiche 50-000, B3/06/13, B305110470

B306090010 IE Info Notice B3-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000, B3/06/13, B306090010

B305110475 IE Info Notice B3-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/06/22 Consolidated Edison Co of New York, Inc 119pp 19021 179 24X Fiche 50-000, B3/06/22, B305110475

B305110477 IE Info Notice B3-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000, B3/06/22, B305110477

B305110479 IE Info Notice B3-42, "Reactor Mode Switch Malfunction " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000, B3/06/23, B305110479

B305110483 IE Info Notice B3-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000, B3/06/24, B305110483

S Reportable occurrences, IERs & related correspondence

B306280346 Interim Significant Deficiency Rpt B3-33 re svc water pump lubricating water strainer clogging Initially reported on B30331 New strainers of increased mesh size will be installed & shaft sleeves replaced by late Fall 1983
COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W G Northeast Utilities B3/06/13
MURLEY, T E Region 1, Office of Director 1p 19001 266 24X
Fiche 50-423, B3/06/13, B306280346

B306280482 Final Deficiency Rept B3-33 re clogged svc water pump lubricating water strainer Initially reported on B30331 New strainers of increased mesh size & new shaft sleeves w/harder sleeve matl will be installed by Fall 1983
COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W G Northeast Utilities B3/06/13
MURLEY, T E Region 1, Office of Director 1p 19010 190 24X
Fiche 50-423, B3/06/13, B306280482

V Operator Examinations

B306140673 Extends invitation to attend B30627 meeting in King of Prussia, PA to discuss transfer of reactor operator licensing function from Bethesda, MD to Region 1 ofc
STAROSTECKI, R Division of Project & Resident Programs B3/06/09
COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 18842 075 24X Fiche 50-423, B3/06/09, B306140673

DOCKET 50-424 ALVIN W VOOSTLE NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

B306140157 Confirms B30302 meeting at Region 1 ofc to discuss field change control for project per B3022P telcon Proposed meeting agenda encl
LEWIS, R C Division of Project & Resident Programs B3/06/04
KELLY, R J Georgia Power Co 2pp 18839 034 24X
Fiche 50-424, B3/02/24, B306140157

B306140721 Forwards summary of B30302 mtg meeting in Atlanta, GA re tentative proposals to improve staffing & handling of changes at const site Attendance list encl
LEWIS, R C Division of Project & Resident Programs B3/06/04
KELLY, R J Georgia Power Co App 18841 332 24X
Fiche 50-424, B3/03/25, B306140721

B306100264 Forwards application for OL, consisting of Suppl 9 to PSAR Chapter 17 re QA Basic QA program not changed significantly Proposed mds to field change request program transmitted on B30504
FOSTER, D O Georgia Power Co B3/06/10 O'REILLY, J P Region 1 Office of Director 2pp 18804 292 24X Fiche 50-424, B3/06/10, B306100264

--B306100265 Application for OL, consisting of suppl 9 to PSAR Chapter 17 re QA
FOSTER, D O Georgia Power Co B3/06/10 1p 18804 294 24X
Fiche 50-424, B3/06/10, B306100264

--B306100267 Suppl 9 to PSAR Chapter 17 re QA
Georgia Power Co B3/06/10 173pp 18804 295 24X
Fiche 50-424, B3/06/10, B306100264

B306240274 Forwards response to criteria for resolution of NUREG O-17, Item II K 3.5, "Automatic Trip of Reactor Coolant Pumps," stated in NRC B30208 Generic Ltr B3-10C Westinghouse Owners Group program addressing criteria will be evaluated.
FOSTER, D O Georgia Power Co FOBIER, D O Southern Co Services, Inc. B3/06/16 ADENAM, E G Licensing Branch 4 5pp 18980 146 24X
Fiche 50-424, B3/06/16, B306240274

DOCKETED ITEMS

301

B Utility Preliminary Safety Analysis Report, amends

8306100264 Forwards application for OL, consisting of Suppl 9 to PSAR Chapter 17 re GA Basic OA program not changed significantly. Proposed mods to field change request program transmitted on 830504.
FOSTER, D O Georgia Power Co 83/06/10 O'REILLY, J P Region 2, Office of Director 2pp 18804 292 24X Fiche 50-424, 83/06/10, 8306100264

--8306100367 Suppl 9 to PSAR Chapter 17 re GA
* Georgia Power Co 83/06/10 178pp 18804 295 24X
Fiche 50-424, 83/06/10, 8306100264

F Security, medical, emergency & fire protection plans

8306140711 Approves issuance of SALP Repts 50-321/83-06, 50-366/83-06, 50-424/83-06 & 50-425/83-06 for Jul 1981 - Oct 1982
LEWIS, R C Division of Project & Resident Programs 83/06/01
KELLY, R J Georgia Power Co 3pp 10341 196 24X
Fiche 50-000, 83/06/01, 8306140711

--8306140719 Advises of 830317 meeting in Atlanta, GA to discuss SALP Repts 50-321/83-06, 50-366/83-06, 50-424/83-06 & 50-425/83-06 for Jul 1981 - Oct 1982
LEWIS, R C Division of Project & Resident Programs 83/03/09
KELLY, R J Georgia Power Co 2pp 18841 199 24X
Fiche 50-000, 83/06/01, 8306140711

--8306140730 SALP Repts 50-321/83-06, 50-366/83-06, 50-424/83-06 & 50-425/83-06 for Jul 1981 - Oct 1982 No significant util weaknesses identified
* Region 2, Office of Director 83/03/09 38pp 18841 201 24X
Fiche 50-000, 83/06/01, 8306140711

--8306140743 Ack receipt of SALP Repts 50-321/83-06, 50-366/83-06, 50-424/83-06 & 50-425/83-06 for Jul 1981 - Oct 1982
Evaluation acceptable
BECKHAM, J T Georgia Power Co 83/04/18 O'REILLY, J P Region 2, Office of Director 1p 18841 239 24X Fiche 50-000, 83/06/01, 8306140711

I Financial information

8306070123 Forwards Annual Financial Repts, 1982
OUCHE, L T Georgia Power Co 83/06/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18739 038 24X
Fiche 50-000, 83/06/02, 8306070123

--8306070127 Annual Financial Rept, 1982
VOOTIL, A W The Southern Co 83/03/10 51pp 10739 039 24X
Fiche 50-000, 83/06/02, 8306070123

--8306070130 Annual Financial Rept, 1982
SCHERRER, R W, MILLER, J H Georgia Power Co 83/03/07 36pp 18739 091 24X Fiche 50-000, 83/06/02, 8306070123

G Inspection reports, IE Bulletins & correspondence

8306140432 Forwards IE Insp Repts 50-424/83-09 & 50-425/83-09 on 830425-29 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/05/19
KELLY, R J Georgia Power Co 2pp 18838 037 24X
Fiche 50-424, 83/05/19, 8306140432

--8306140439 IE Insp Repts 50-424/83-09 & 50-425/83-09 on 830425-29 No noncompliance noted Major areas inspected independent insp, containment steel, weld heat treatment of structures & supports & visual exam of welds for structures & supports
YORK, J W Region 2, Office of Director BLAKE, J J Division of Engineering & Radiological Safety Programs 83/05/18 4pp 18838 037 24X Fiche 50-424, 83/05/19, 8306140432

830511045B IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl
TAYLOR, J H Division of Safeguards & Inspection Programs (Post 830103) 83/05/24 Consolidated Edison Co. of New York, Inc 125pp 18831:040 24X Fiche 50-000, 83/05/24, 830511045B

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/24 Consolidated Edison Co. of New York, Inc 115pp 18732:085 24X Fiche 50-000, 83/05/24, 8305110460

8306140711 Approves issuance of SALP Repts 50-321/83-06, 50-366/83-06, 50-424/83-06 & 50-425/83-06 for Jul 1981 - Oct 1982
LEWIS, R C Division of Project & Resident Programs 83/06/01
KELLY, R J Georgia Power Co 3pp 18841 196 24X
Fiche 50-000, 83/06/01, 8306140711

--8306140719 Advises of 830317 meeting in Atlanta, GA to discuss SALP Repts 50-321/83-06, 50-366/83-06, 50-424/83-06 & 50-425/83-06 for Jul 1981 - Oct 1982
LEWIS, R C Division of Project & Resident Programs 83/03/09
KELLY, R J Georgia Power Co 2pp 18841 199 24X
Fiche 50-000, 83/06/01, 8306140711

--8306140730 SALP Repts 50-321/83-06, 50-366/83-06, 50-424/83-06 & 50-425/83-06 for Jul 1981 - Oct 1982 No significant util weaknesses identified
* Region 2, Office of Director 83/03/09 38pp 18841 201 24X
Fiche 50-000, 83/06/01, 8306140711

--8306140743 Ack receipt of SALP Repts 50-321/83-06, 50-366/83-06, 50-424/83-06 & 50-425/83-06 for Jul 1981 - Oct 1982
Evaluation acceptable
BECKHAM, J T Georgia Power Co 83/04/18 O'REILLY, J P Region 2, Office of Director 1p 18841 239 24X Fiche 50-000, 83/06/01, 8306140711

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc 119pp 18930 280 24X Fiche 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 118pp 17021:179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 120pp 18977 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co. of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc 116pp 17046 297 24X Fiche 50-000, 83/06/24, 8305110483

B Reportable occurrences, IERs & related correspondence

8306100221 Interim deficiency rept re embeds - 1982 Addl info required before evaluation can be completed. Info expected by 830610, Final rept will be submitted by 830624.
FOSTER, D O Georgia Power Co 83/06/01 O'REILLY, J P Region 2, Office of Director 1p 18805:353 24X Fiche 50-424, 83/06/01, 8306100221

8306100231 Interim deficiency rept re use of defective matl for pinion keys in Limitorque motor operators Initially reported on 830627. Also reportable per Part 21. Rept contains no proprietary info
FOSTER, D O Georgia Power Co 83/06/01 O'REILLY, J P Region 2, Office of Director 3pp 18807:189 24X Fiche 50-424, 83/06/01, 8306100231

8306100259 Interim deficiency rept re Pullman Power Products weld radiograph quality Final rept to be submitted by 830624
FOSTER, D O Georgia Power Co 83/06/01 O'REILLY, J P Region 2, Office of Director 1p 18807:004 24X Fiche 50-424, 83/06/01, 8306100259

DOCKETED ITEMS

8306100274 Interim deficiency rept re use of cadwelds as end anchorages info from AE expected within next month final rept will be submitted 830727
FOSTER, D O Georgia Power Co 83/06/01 O'REILLY, J P Region 2, Office of Director 1p 18806 258 24X Fiche 50-424, 83/06/01, 8306100274

8306270166 Interim deficiency rept re Westinghouse DG-416 reactor trip breakers initially reported on 830505 Util review in progress final rept will be submitted by 830707
FOSTER, D O Georgia Power Co FOSTER, D O Southern Co Services, Inc 83/06/13 O'REILLY, J P Region 2, Office of Director 1p 18992 020 24X Fiche 50-424, 83/06/13, 8306270166

V Operator Examinations

8306140486 Forwards summary of 830503 meeting re NRC policies on senior operator licensing exam Tech Spec memorization requirements Written exam requirements specified in draft Examiner Std EB-402 List of attendees encl
DANCE, H C Division of Project & Resident Programs 83/05/24
BECKHAM, J T Georgia Power Co 4pp 18843 090 24X Fiche 50-000, 83/05/24, 8306140486

--8306140493 Requests meeting to discuss NRC policies on senior operator licensing exam Tech Spec memorization requirements Summary of Tech Spec sections covering required memorization encl
BECKHAM, J T Georgia Power Co 83/03/11 WILSON, B Region 2, Office of Director 2pp 18843 094 24X Fiche 50-000, 83/05/24, 8306140486

DOCKET 50-425 ALVIN W VOGTLE NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

8306140159 Confirms 830302 meeting at Region II ofc to discuss field change control for project per 830222 telcon Proposed meeting agenda encl
LEWIS, R C Division of Project & Resident Programs 83/02/24
KELLY, R J Georgia Power Co 2pp 18839 034 24X Fiche 50-424, 83/02/24, 8306140159.

8306140721 Forwards summary of 830302 mgt meeting in Atlanta, GA re tentative proposals to improve staffing & handling of changes at const site Attendance list encl
LEWIS, R C Division of Project & Resident Programs 83/03/25
KELLY, R J Georgia Power Co 4pp 18841 332 24X Fiche 50-424, 83/03/25, 8306140721

8306100264 Forwards application for OL, consisting of Suppl 9 to PSAR Chapter 17 re GA Basic QA program not changed significantly Proposed mods to field change request program transmitted on 830504
FOSTER, D O Georgia Power Co 83/06/10 O'REILLY, J P Region 2, Office of Director 2pp 18804 292 24X Fiche 50-424, 83/06/10, 8306100264

--8306100265 Application for OL, consisting of suppl 9 to PSAR Chapter 17 re GA
FOSTER, D O Georgia Power Co 83/06/10 1p 18804 294 24X Fiche 50-424, 83/06/10, 8306100264

8306240274 Forwards response to criteria for resolution of NUREG-0737, Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps," stated in NRC 830208 Generic Ltr 83-10C Westinghouse Owners Group program addressing criteria will be evaluated
FOSTER, D O Georgia Power Co FOSTER, D O Southern Co Services, Inc 83/06/16 ADENBAM, E O Licensing Branch 4 5pp 18980 126 24X Fiche 50-424, 83/06/16, 8306240274

B Utility Preliminary Safety Analysis Report, amendments

8306100264 Forwards application for OL, consisting of Suppl 9 to PSAR Chapter 17 re GA Basic QA program not changed significantly Proposed mods to field change request program transmitted on 830504
FOSTER, D O Georgia Power Co 83/06/10 O'REILLY, J P Region 2, Office of Director 2pp 18804 292 24X Fiche 50-424, 83/06/10, 8306100264

--8306100267 Suppl 9 to PSAR Chapter 17 re GA
Georgia Power Co 83/06/10 178pp 18804 295 24X Fiche 50-424, 83/06/10, 8306100264

F Security, medical, emergency & fire protection plans

8306140711 Approves issuance of SAMP Repts 50-321/83-06, 50-366/83-06, 50-424/83-06 & 50-425/83-06 for Jul 1981 - Oct 1982
LEWIS, R C Division of Project & Resident Programs 83/06/01
KELLY, R J Georgia Power Co 3pp 18841 196 24X Fiche 50-000, 83/06/01, 8306140711

--8306140719 Advises of 830317 meeting in Atlanta, GA to discuss SAMP Repts 50-321/83-06, 50-366/83-06, 50-424/83-06 & 50-425/83-06 for Jul 1981 - Oct 1982
LEWIS, R C Division of Project & Resident Programs 83/03/07
KELLY, R J Georgia Power Co 2pp 18841 199 24X Fiche 50-000, 83/06/01, 8306140711

--8306140730 SAMP Repts 50-321/83-06, 50-366/83-06, 50-424/83-06 & 50-425/83-06 for Jul 1981 - Oct 1982 No significant util weaknesses identified
Region 2, Office of Director 83/03/07 38pp 18841 201 24X Fiche 50-000, 83/06/01, 8306140711

--8306140743 Ack receipt of SAMP Repts 50-321/83-06, 50-366/83-06, 50-424/83-06 & 50-425/83-06 for Jul 1981 - Oct 1982 Evaluation acceptable
BECKHAM, J T Georgia Power Co 83/04/18 O'REILLY, J P Region 2, Office of Director 1p 18841 217 24X Fiche 50-000, 83/06/01, 8306140711

I Financial information

8306070123 Forwards Annual Financial Repts, 1982
QUCHA, L T Georgia Power Co 83/06/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18739 038 24X Fiche 50-000, 83/06/02, 8306070123

--8306070127 Annual Financial Rept, 1982
VOGTLE, A W The Southern Co 83/03/10 51pp 18739 039 24X Fiche 50-000, 83/06/02, 8306070123

--8306070130 Annual Financial Rept, 1982
SCHERER, R W Georgia Power Co 83/03/07 36pp 18739 091 24X Fiche 50-000, 83/06/02, 8306070123

G Inspection reports, IE Bulletins & correspondence

8306140432 Forwards IE Insp Repts 50-424/83-09 & 50-425/83-09 on 830425-29 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/05/19
KELLY, R J Georgia Power Co 2pp 18838 037 24X Fiche 50-424, 83/05/19, 8306140432

--8306140439 IE Insp Repts 50-424/83-09 & 50-425/83-09 on 830425-29 No noncompliance noted Major areas inspected independent insp, containment steel, weld heat treatment of structures & supports & visual exam of welds for structures & supports
YORK, J W Region 2, Office of Director BLAKE, J J Division of Engineering & Radiological Safety Programs 83/05/18 4pp 18838 039 24X Fiche 50-424, 83/05/19, 8306140432

8305110158 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110160 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 113pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306140711 Approves issuance of SAMP Repts 50-321/83-06, 50-366/83-06, 50-424/83-06 & 50-425/83-06 for Jul 1981 - Oct 1982
LEWIS, R C Division of Project & Resident Programs 83/06/01
KELLY, R J Georgia Power Co 3pp 18841 196 24X Fiche 50-000, 83/06/01, 8306140711

--8306140719 Advises of 830317 meeting in Atlanta, GA to discuss SAMP Repts 50-321/83-06, 50-366/83-06, 50-424/83-06 & 50-425/83-06 for Jul 1981 - Oct 1982
LEWIS, R C Division of Project & Resident Programs 83/03/07
KELLY, R J Georgia Power Co 2pp 18841 199 24X Fiche 50-000, 83/06/01, 8306140711

--B306140730 SALP Repts 50-321/83-06, 50-366/83-06, 50-424/83-06 & 50-425/83-06 for Jul 1981 - Oct 1982 No significant util weaknesses identified
* Region 2, Office of Director 83/03/09 38pp 18841 201 24X
Fiche 50-000, 83/06/01, B306140711

--B306140743 Ack receipt of SALP Repts 50-321/83-06, 50-366/83-06, 50-424/83-06 & 50-425/83-06 for Jul 1981 - Oct 1982
Evaluation acceptable
BECKHAM, J T Georgia Power Co 83/04/18 O'REILLY, J P Region 2, Office of Director 1p 18841 219 24X Fiche 50-000, 83/06/01, B306140711

B305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, C L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, B305110464

B305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, C L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, B305110470

B306090010 IE Info Notice 83-37, "Transformer Failure Resulting from Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, B306090010

B305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 113pp 19021 179 24X Fiche 50-000, 83/06/22, B305110475

B305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, C L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18977 007 24X Fiche 50-000, 83/06/22, B305110477

B305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, B305110479

B305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, B305110483

S Reportable occurrences, LERs & related correspondence

B306100221 Interim deficiency rept re embeds - 1982 Addl info required before evaluation can be completed info expected by B30610
Final rept will be submitted by B30624
FOSTER, D O Georgia Power Co 83/06/01 O'REILLY, J P Region 2, Office of Director 1p 18805 353 24X Fiche 50-424, 83/06/01, B306100221

B306100231 Interim deficiency rept re use of defective matl for pinion keys in Litorque motor operators initially reported on 820827 Also reportable per Part 21 Rept contains no proprietary info
FOSTER, D O Georgia Power Co 83/06/01 O'REILLY, J P Region 2, Office of Director 5pp 19007 189 24X Fiche 50-424, 83/06/01, B306100231

B306100259 Interim deficiency rept re Pullman Power Products weld radiograph quality Final rept to be submitted by B30624
FOSTER, D O Georgia Power Co 83/06/01 O'REILLY, J P Region 2, Office of Director 1p 18807 004 24X Fiche 50-424, 83/06/01, B306100259

B306100274 Interim deficiency rept re use of cadwelds as end anchorages Info from AE expected within next month Final rept will be submitted B30727
FOSTER, D O Georgia Power Co 83/06/01 O'REILLY, J P Region 2, Office of Director 1p 18806 258 24X Fiche 50-424, 83/06/01, B306100274

B306270166 Interim deficiency rept re Westinghouse DS-416 reactor trip breakers Initially reported on 830505 Util review in progress Final rept will be submitted by B30709
FOSTER, D O Georgia Power Co FOSTER, D O Southern Co Services, Inc 83/06/13 O'REILLY, J P Region 2, Office of Director 1p 18992 020 24X Fiche 50-424, 83/06/13, B306270166

V Operator Examinations

B306140486 Forwards summary of 830503 meeting re NRC policies on senior operator licensing exam Tech Spec memorization requirements
Written exam requirements specified in draft Examiner Std ES-402 List of attendees encl
DANCE, H C Division of Project & Resident Programs 83/05/24
BECKHAM, J T Georgia Power Co 4pp 18843 090 24X
Fiche 50-000, 83/05/24, B306140486

--B306140493 Requests meeting to discuss NRC policies on senior operator licensing exam Tech Spec memorization requirements Summary of Tech Spec sections covering required memorization encl
BECKHAM, J T Georgia Power Co 83/03/11 WILSON, J Region 2, Office of Director 2pp 18843 094 24X Fiche 50-000, 83/05/24, B306140486

DOCKET 50-438 BELLEFONTE NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

B306100123 Advises of withholding of certain matl contained in util B30428 transmittal of documentation demonstrating compliance w/Code Case N-192 for use of flexible metal instrumentation hose assemblies, per 10CFR2 790 Listing of matl encl
MILLS, L M Tennessee Valley Authority 83/06/06 ADENSAH, E
Licensing Branch 4 2pp 18802 008 24X Fiche 50-438, 83/06/06, B306100123

B306130340 Informs of suspension of preoperational radiological monitoring activities until 1 yr before plant operation
Reimplemented program will reflect appropriate changes in regulatory requirements on monitoring philosophy
MILLS, L M Tennessee Valley Authority 83/06/07 ADENSAH, E
Licensing Branch 4 2pp 18822 210 24X Fiche 50-438, 83/06/07, B306130340

F Security, medical, emergency & fire protection plans

B306210010 Forwards "Program Plan for Control Room Design Reviews for all TVA Nuclear Plants," in response to Generic Ltr 82-33 re upgrade of emergency plans
KAMMER, D S Tennessee Valley Authority 83/06/09 ADENSAH, E
Licensing Branch 4 3pp 18913 001 24X Fiche 50-000, 83/06/09, B306210010

--B306210016 Procedure B42209 10, "Program Plan for Control Room Design Reviews for all TVA Nuclear Plants "
* Tennessee Valley Authority 83/06/09 200pp 18913 004 24X
Fiche 50-000, 83/06/09, B306210010

B306290309 Ack receipt of 830524 ltr advising NRC that IE Insp Repts 50-438/83-13 & 50-439/83-13 contain safeguards-related matl
Rept will be withheld (ref 10CFR73 21)
VERRELLI, D M Division of Project & Resident Programs 83/06/15
PARRISH, H O Tennessee Valley Authority 1p 19055 351 24X
Fiche 50-438, 83/06/15, B306290309

--B306290319 Responds to NRC 830519 ltr re violations noted in IE Insp Repts 50-438/83-13 & 50-439/83-13 Safeguards info should be withheld (ref 10CFR73 21)
MILLS, L M Tennessee Valley Authority 83/05/24 O'REILLY, J P
Region 2, Office of Director 1p 19055 352 24X
Fiche 50-438, 83/06/15, B306290309

--B306290334 IE Insp Repts 50-438/83-13 & 50-439/83-13 on 830301-0430, No noncompliance noted. Major areas inspected const surveillance & licensee action on previous enforcement matters Safeguards info deleted (ref 10CFR73 21)
WILCOX, J D Region 2, Office of Director, QUICK, D R Division of Project & Resident Programs 83/05/19 8pp 19055 355 24X
Fiche 50-438, 83/06/15, B306290309

G Inspection reports, IE Bulletins & correspondence

B306140570 Confirms mgt meeting on B30216 at Region II ofc to discuss results of self-initiated evaluation of activities at facility conducted under INPO guidelines Proposed meeting agenda encl
O'REILLY, J P Region 2, Office of Director 83/02/09 PARRISH, H O
Tennessee Valley Authority 2pp 18844 162 24X
Fiche 50-438, 83/02/09, B306140570

DOCKETED ITEMS

8306140618 Forwards summary of 830216 meeting re licensee-initiated evaluation of const activities, per INPO guidelines
LEWIS, R C Division of Project & Resident Programs 03/02/22
PARRIS, H O Tennessee Valley Authority App 18834 017 24X
Fiche 50-438, 83/02/22, 8306140618

8306140543 Confirms mgt meeting on 830421 in Chattanooga, TN to review results of first phase of annual appraisal of regulatory performance, per 830328 telcon
LEWIS, R C Division of Project & Resident Programs 03/04/12
PARRIS, H O Tennessee Valley Authority 3pp 18834 176 24X
Fiche 50-000, 83/04/12, 8306140543

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl
JORDAN, E L Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 129pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8306140143 Ack receipt of 830516 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/83-07 & 50-439/83-07
VERRELLI, D M Division of Project & Resident Programs 83/05/26
PARRIS, H O Tennessee Valley Authority 1p 18839 007 24X
Fiche 50-438, 83/05/26, 8306140143

--8306140150 Responds to NRC 830414 ltr re violations noted in IE Insp Repts 50-438/83-07 & 50-439/83-07 Corrective actions equipment named in violation tagged on returned to instrument test lab for repair of calibr
MILLS, L M Tennessee Valley Authority 83/05/16 O'REILLY, J P Region 2, Office of Director 7pp 18839 008 24X
Fiche 50-438, 83/05/26, 8306140143

--8306140157 Forwards IE Insp Repts 50-438/83-07 & 50-439/83-07 on 830307-11 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 83/04/14
PARRIS, H O Tennessee Valley Authority 1p 18839 015 24X
Fiche 50-438, 83/05/26, 8306140143

--8306140164 Notice of violation from insp on 830307-11
* Region 2, Office of Director 83/04/14 2pp 18839 017 24X
Fiche 50-438, 83/05/26, 8306140143

--8306140172 IE Insp Repts 50-438/83-07 & 50-439/83-07 on 830307-11 Noncompliance noted failure to control & calibr measuring & test equipment & failure to audit several site const activities on annual basis
WRIGHT, R H, WRIGHT, C M Region 2, Office of Director 83/04/13 8pp 18839 019 24X Fiche 50-438, 83/05/26, 8306140143

8306140114 Ack receipt of 830512 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/83-05 & 50-439/83-05
VERRELLI, D M Division of Project & Resident Programs 83/05/27
PARRIS, H O Tennessee Valley Authority 1p 18839 138 24X
Fiche 50-438, 83/05/27, 8306140114

--8306140128 Responds to NRC 830412 ltr re violations noted in IE Insp Repts 50-438/83-05 & 50-439/83-05 Corrective actions checklist prepared & issued to unit training officer delineating documentation requirements for NDE personnel
MILLS, L M Tennessee Valley Authority 83/05/12 O'REILLY, J P Region 2, Office of Director 5pp 18839 139 24X
Fiche 50-438, 83/05/27, 8306140114

--8306140131 Forwards IE Insp Repts 50-438/83-05 & 50-439/83-05 on 830214-0304 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 83/04/12
PARRIS, H O Tennessee Valley Authority 2pp 18839 144 24X
Fiche 50-438, 83/05/27, 8306140114

--8306140134 Notice of violation from insp on 830214-0304
* Region 2, Office of Director 83/04/12 2pp 18839 146 24X
Fiche 50-438, 83/05/27, 8306140114

--8306140139 IE Insp Repts 50-438/83-05 & 50-439/83-05 on 830214-0304 Noncompliance noted, sufficient records affecting quality such as qualification of QC personnel not maintained.
YORK, J W, LIU, H C, BLAKE, J J Region 2, Office of Director 83/04/06 13pp, 18839 148 24X Fiche 50-438, 83/05/27, 8306140114

8306140757 Concurs w/util position contained in 821109 ltr supporting denial of violation identified in IE Insp Repts 50-438/82-24 & 50-439/82-24 Violation will be deleted from NRC records
VERRELLI, D M Division of Project & Resident Programs 83/05/27
PARRIS, H O Tennessee Valley Authority 1p 18841 195 24X
Fiche 50-438, 83/05/27, 8306140757

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8306290231 Forwards IE Insp Repts 50-438/83-12 & 50-439/83-12 on 830516-20 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/06/09
PARRIS, H O Tennessee Valley Authority 2pp 19056 087 24X
Fiche 50-438, 83/06/09, 8306290231

--8306290235 IE Insp Repts 50-438/83-12 & 50-439/83-12 on 830516-20 No noncompliance noted Major areas inspected previous enforcement matters, safety-related pipe support & restraint sys & licensee action on previously identified insp items
YORK, J W, BLAKE, J J Region 2, Office of Director 83/06/06 5pp 19056 089 24X Fiche 50-438, 83/06/09, 8306290231

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting from Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8306290309 Ack receipt of 830524 ltr advising NRC that IE Insp Repts 50-438/83-13 & 50-439/83-13 contain safeguards-related matl Rept will be withheld (ref 10CFR73 21)
VERRELLI, D M Division of Project & Resident Programs 83/06/15
PARRIS, H O Tennessee Valley Authority 1p 19055 391 24X
Fiche 50-438, 83/06/15, 8306290309

--8306290319 Responds to NRC 830519 ltr re violations noted in IE Insp Repts 50-438/83-13 & 50-439/83-13 Safeguards info should be withheld (ref 10CFR73 21)
MILLS, L M Tennessee Valley Authority 83/05/24 O'REILLY, J P Region 2, Office of Director 1p 19055 352 24X
Fiche 50-438, 83/06/15, 8306290309

--8306290325 Forwards IE Insp Repts 50-438/83-13 & 50-439/83-13 on 830301-0430 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 07/05/19
PARRIS, H O Tennessee Valley Authority 2pp 19055 353 24X
Fiche 50-438, 83/06/15, 8306290309

--8306290334 IE Insp Repts 50-438/83-13 & 50-439/83-13 on 830301-0430 No noncompliance noted Major areas inspected const surveillance & licensee action on previous enforcement matters Safeguards info deleted (ref 10CFR73 21)
WILCOX, J D Region 2, Office of Director QUICK, D R Division of Project & Resident Programs 83/05/19 8pp 19055 355 24X
Fiche 50-438, 83/06/15, 8306290309

8306290483 Approves issuance of BALP Repts 50-259/83-04, 50-260/83-04, 50-296/83-04, 50-327/83-04, 50-328/83-04, 50-390/83-07, 50-391/83-06, 50-438/83-06 & 50-439/83-06 for Jul 1981 - Dec 1982 No reply required
O'REILLY, J P Region 2, Office of Director 83/06/17 PARRIS, H O Tennessee Valley Authority 3pp 24X Fiche 50-000, 83/06/17, 8306290483

--8306290490 Forwards BALP Repts 50-259/83-04, 50-260/83-04, 50-296/83-04, 50-327/83-04, 50-328/83-04, 50-390/83-07, 50-391/83-06, 50-438/83-06 & 50-439/83-06 for Jul 1981 - Dec 1982
LEWIS, R C Division of Project & Resident Programs 83/04/13
PARRIS, H O Tennessee Valley Authority 3pp 24X
Fiche 50-000, 83/06/17, 8306290483

--8306290503 SALP Repts 50-259/83-04, 50-260/83-04, 50-276/83-04, 50-327/83-04, 50-328/83-04, 50-390/83-07, 50-391/83-06, 50-438/83-06 & 50-439/83-06 for Jul 1981 - Dec 1982
* Region 2, Office of Director 8/1/04/13 92pp 24X
Fiche 50-000, 83/06/17, 8306290483

--8306290510 Comments on SALP Repts 50-259/83-04, 50-260/83-04, 50-276/83-04, 50-327/83-04, 50-328/83-04, 50-390/83-07, 50-391/83-06, 50-438/83-06 & 50-439/83-06 for Jul 1981 - Dec 1982
MILLS, L M Tennessee Valley Authority 83/05/10 O'REILLY, J P
Region 2, Office of Director 2pp 24X Fiche 50-259, 83/06/17, 8306290483

8306290239 Ack receipt of 830610 ltr informing NRC of steps taken to correct violations noted in II Insp Repts 50-438/81-27 & 50-439/81-29
VERARELLI, D M Division of Project & Resident Programs 83/06/20
PARRISH, H O Tennessee Valley Authority 1p 19036 244 24X
Fiche 50-438, 83/06/20, 8306290239

--8306290246 Submits supplemental response to NRC 811208 ltr re violations noted in IE Insp Repts 50-438/81-27 & 50-439/81-29 Corrective actions letdown coolers to be installed upon receipt of B&W info re support deficiencies
MILLS, L M Tennessee Valley Authority 83/06/10 O'REILLY, J P
Region 2, Office of Director 3pp 19036 245 24X
Fiche 50-438, 83/06/20, 8306290239

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co. of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

S Reportable occurrences, LERs & related correspondence

8306070072 Fifth interim deficiency rept re engineering change notice review & handling initially reported on 811215 Personnel restrained & corrective actions presented to Ufc of QA for approval Addl info will be submitted by 830722
MILLS, L M Tennessee Valley Authority 83/05/24 O'REILLY, J P
Region 2, Office of Director 2pp 18/40 085 24X
Fiche 50-000, 83/05/24, 8306070072

8306010251 Third interim deficiency rept re undersigned snubber on main feedwater piping in Valve Room B initially reported on 821013 Process of documenting completed. Analysis & review underway. Next rept by 840118
MILLS, L M Tennessee Valley Authority 83/05/25 O'REILLY, J P
Region 2, Office of Director 1p 18673 033 24X
Fiche 50-438, 83/05/25, 8306010251

8306010274 Third interim deficiency rept re sheared motor pinion keys in Limitorque motor operators initially reported on 820830 Field change notices issued to replace keys Next rept will be sent by 830928 Also reportable per Part 21
MILLS, L M Tennessee Valley Authority 83/05/25 O'REILLY, J P
Region 2, Office of Director 2pp 18674:322 24X
Fiche 50-000, 83/05/25, 8306010274

8306010405 Fourth interim deficiency rept re failure of BIF butterfly valve seats initially reported on 820511 Valves returned to BIF & tested satisfactorily Final rept by 830801 Also reportable per Part 21
MILLS, L M Tennessee Valley Authority 83/05/25 O'REILLY, J P
Region 2, Office of Director 2pp 18679 328 24X
Fiche 50-438, 83/05/25, 8306010405

8306010431 Second interim deficiency rept re corrosion in high pressure fire protection sys initially reported on 820903 Sys contains carbon steel piping Corrosion analysis in progress. Next rept to be submitted by 821004
MILLS, L M Tennessee Valley Authority 83/05/25 O'REILLY, J P
Region 2, Office of Director 2pp 18674 255 24X
Fiche 50-000, 83/05/25, 8306010431

8306070074 First interim deficiency rept re incorrect max pipe movements contained in TPIPE program initially reported on 830504 W/o encl Next rept expected by 830922
MILLS, L M Tennessee Valley Authority 83/05/26 O'REILLY, J P
Region 2, Office of Director 1p 18739 319 24X
Fiche 50-000, 83/05/26, 8306070074

8306070121 Second interim deficiency rept re failure of Ingersoll Rand air compressor motor initially reported on 821209 Replacement of stators w/Class IE motors initiated & cause & corrective actions investigated Next rept by 840109
MILLS, L M Tennessee Valley Authority 83/05/26 O'REILLY, J P
Region 2, Office of Director 2pp 18739 314 24X
Fiche 50-438, 83/05/26, 8306070121

8306070160 Fifth interim deficiency rept re defects in reactor protection & EBF actuation sys modules supplied by Bailey Meter Co initially reported on 820414 B&W investigating use of yellowish bonding agent Also reportable per Part 21
MILLS, L M Tennessee Valley Authority 83/05/26 O'REILLY, J P
Region 2, Office of Director 3pp 18736 288 24X
Fiche 50-438, 83/05/26, 8306070160

8306070188 Final rept re deficient welds on NAVCO spool pieces initially reported on 820224 Five welds on spool pieces IND-176, 178, 200, 202 & INV-242 do not conform to ASME Section III Not reportable per 10CFR50.55(a)
MILLS, L M Tennessee Valley Authority 83/05/27 O'REILLY, J P
Region 2, Office of Director 2pp 18736 299 24X
Fiche 50-438, 83/05/27, 8306070188

8306070138 Third interim deficiency rept re voiding of engineering change notices w/o proper review initially reported on 820816 Change notices being reviewed & unresolved safety question determination performed Next rept by 830923
MILLS, L M Tennessee Valley Authority 83/05/31 O'REILLY, J P
Region 2, Office of Director 2pp 18739 264 24X
Fiche 50-000, 83/05/31, 8306070138

8306090310 Second interim deficiency rept re tube leaks in component cooling water HXs initially reported on 830218 Corrosion pitting revealed by metallurgical exam Alloys investigated for replacement
MILLS, L M Tennessee Valley Authority 83/06/03 O'REILLY, J P
Region 2, Office of Director 3pp 18793 193 24X
Fiche 50-438, 83/06/03, 8306090310

8306200141 Sixth interim deficiency rept re Viking flow control valves in fire protection sys initially reported on 811124 Drawing rev review continuing Next rept to be submitted by 830809 Also reportable per Part 21
MILLS, L M Tennessee Valley Authority 83/06/07 O'REILLY, J P
Region 2, Office of Director 1p 18903 264 24X
Fiche 50-438, 83/06/07, 8306200141

8306200143 First interim deficiency rept re failure to specify IEEE class of safety-related sys components on procurement specs. Initially reported on 830309 Suppliers being contacted Next rept to be submitted 831119
MILLS, L M Tennessee Valley Authority 83/06/09 O'REILLY, J P
Region 2, Office of Director 2pp 18903 289 24X
Fiche 50-438, 83/06/09, 8306200143

8306210051 Supplemental interim deficiency rept re potentially overstressed embedded plates initially reported on 820412 Next submittal scheduled for 840217 instead of 830622 as originally stated
MILLS, L M Tennessee Valley Authority 83/06/10 O'REILLY, J P
Region 2, Office of Director 1p 18914 009 24X
Fiche 50-000, 83/06/10, 8306210051

8306210005 First interim deficiency rept re max temp inside containment initially reported on 830513. Util requested B&W to respond to nonconformance rept by 830715. Next rept to be submitted by 830826 Also reported per Part 21.
MILLS, L M Tennessee Valley Authority 83/06/13 O'REILLY, J P
Region 2, Office of Director 2pp 18912:283 24X
Fiche 50-438, 83/06/13, 8306210005

8306210018 First interim deficiency rept re B&W plant internal bolt failures initially reported on 830513. B&W & B&W Owners Group assessing situation to determine scope of problem & corrective actions. Next rept to be submitted by 831206
MILLS, L M Tennessee Valley Authority 83/06/13 O'REILLY, J P
Region 2, Office of Director 2pp 18914:239 24X
Fiche 50-438, 83/06/13, 8306210018

DOCKETED ITEMS

8306210252 Second interim deficiency rept re failure to identify grade of nuts due to orientation w/grade markings facing against structural member Initially reported on 830126 Testing in progress Next rept by 830930
MILLS, L M Tennessee Valley Authority 83/06/14 O'REILLY, J P
Region 2, Office of Director 2pp 10718 099 24X
Fiche 50-438, 83/06/14, 8306210252

8306210004 First interim deficiency rept re in-core monitoring sys Dutchman pipes offset from longitudinal axis of pipe runs Initially reported on 830516 Util requested B&W to advise of corrective action Next rept to be submitted on 830824
MILLS, L M Tennessee Valley Authority 83/06/15 O'REILLY, J P
Region 2, Office of Director 2pp 18911 360 24X
Fiche 50-438, 83/06/15, 8306210004

8306210042 Fifth interim deficiency rept re seismic analysis of auxiliary control bldg Initially reported on 820226 Seismic analysis rept revised & two new walls will be constructed Next rept to be submitted by 840622
MILLS, L M Tennessee Valley Authority 83/06/15 O'REILLY, J P
Region 2, Office of Director 2pp 10712 299 24X
Fiche 50-438, 83/06/15, 8306210042

8306280479 Final deficiency rept re improperly welded chiller unit piping components Initially reported on 820111 Radiographic exam to be performed on all safety-related chiller piping Also reportable per Part 21
MILLS, L M Tennessee Valley Authority 83/06/17 O'REILLY, J P
Region 2, Office of Director 3pp 19020 116 24X
Fiche 50-438, 83/06/17, 8306280479

8306280578 Interim deficiency rept re resolution of listed items due for submittal in late June Corrective actions in progress List identifying each item, schedule for next submittal & level of interim rept encl
MILLS, L M Tennessee Valley Authority 83/06/17 O'REILLY, J P
Region 2, Office of Director 2pp 19018 193 24X
Fiche 50-000, 83/06/17, 8306280578

8306280619 Fourth interim deficiency rept re incorrect installation of pressure relief & safety valves Initially reported on 830305 Two 3-inch relief valves, exhausting into waste disposal header, added Next rept to be submitted by 840718
MILLS, L M Tennessee Valley Authority 83/06/17 O'REILLY, J P
Region 2, Office of Director 2pp 19016 001 24X
Fiche 50-438, 83/06/17, 8306280619

8306280092 Second interim deficiency rept re disruption & collapse of sodium hydroxide storage tank Initially reported on 821124, Const Test Procedure DNP-CTP-6 1 revised to include positive measures for monitoring tank levels Next rept by 831216
MILLS, L M Tennessee Valley Authority 83/06/20 O'REILLY, J P
Region 2, Office of Director 25pp 19001 131 24X
Fiche 50-438, 83/06/20, 8306280092

8306280367 Second interim deficiency rept re incorrect seismic pipe support insps Approx 3,600 completed insp records for rigorously analyzed supports identified Support location will be shown on detail drawings Next rept by 831213
MILLS, L M Tennessee Valley Authority 83/06/20 O'REILLY, J P
Region 2, Office of Director 2pp 19014, 083 24X
Fiche 50-438, 83/06/20, 8306280367

8306280425 Fourth interim deficiency rept re B&W design of RCS supports & restraints Initially reported on 820601 Majority of blocks installed Shear bar evaluation expected by 830801 Also reported per Part 21
MILLS, L M Tennessee Valley Authority 83/06/20 O'REILLY, J P
Region 2, Office of Director 2pp 19020 300 24X
Fiche 50-438, 83/06/20, 8306280425

8306300254 Final deficiency rept re overpressurized sys during flushing Initially reported on 821130 Drawings of affected pipes & valves reviewed & evaluated Item determined not reportable per 10CFR50.55(e)
MILLS, L M Tennessee Valley Authority 83/06/21 O'REILLY, J P
Region 2, Office of Director 2pp 19119 208 24X
Fiche 50-438, 83/06/21, 8306300254

8306300159 Part 21 rept re spot welds in Bailey Controls Co cabinets w/smaller diameter than specified Cabinets strengthened by seam & edge welding on bolting
TAYLOR, J H Dabcock & Wilcox Co 83/06/23 DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement 2pp 19119 308 24X Fiche 50-000, 83/06/23, 8306300159

8306300214 Second interim deficiency rept re tubeline mats supplied by Capitol Pipe & Steel not mfg under QA program Initially reported on 830329 Contractor will perform dimensional checks for pipes & fittings Next rept by 830922
MILLS, L M Tennessee Valley Authority 83/06/23 O'REILLY, J P
Region 2, Office of Director 5pp 19119 351 24X
Fiche 50-000, 83/06/23, 8306300214

8306300008 Fourth interim deficiency rept re possibility of exceeding turbine driven auxiliary feedwater pump room temp Initially reported on 811006 Fan motors will be replaced Next rept by 840430
MILLS, L M Tennessee Valley Authority 83/06/24 O'REILLY, J P
Region 2, Office of Director 2pp 19120 317 24X
Fiche 50-438, 83/06/24, 8306300008

8306300245 Final deficiency rept re analysis for loss of feedwater event Initially reported on 810316 Util does not consider subj nonconforming condition adverse to safe operation of plant Condition not reportable per 10CFR50.55(e)
MILLS, L M Tennessee Valley Authority 83/06/24 O'REILLY, J P
Region 2, Office of Director 2pp 19119 341 24X
Fiche 50-438, 83/06/24, 8306300245

DOCKET 50-439 BELLEFONTE NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

8306100123 Advises of withholding of certain matl contained in util 830428 transmittal of documentation demonstrating compliance w/Code Case N-192 for use of flexible metal instrumentation hose assemblies, per 10CFR2.770 Listing of matl encl
MILLS, L M Tennessee Valley Authority 83/06/06 ADENSAH, E
Licensing Branch 4 2pp 18802 008 24X Fiche 50-438, 83/06/06, 8306100123

8306130340 Informs of suspension of preoperational radiological monitoring activities until 1 yr before plant operation Reimplemented program will reflect appropriate changes in regulatory requirements on monitoring philosophy
MILLS, L M Tennessee Valley Authority 83/06/07 ADENSAH, E
Licensing Branch 4 2pp 18823 210 24X Fiche 50-438, 83/06/07, 8306130340

F Security, medical, emergency & fire protection plans

8306210010 Forwards "Program Plan for Control Room Design Reviews for all TVA Nuclear Plants," in response to Generic Ltr 92-33 re upgrade of emergency plans
KAMMER, D S Tennessee Valley Authority 83/06/09 ADENSAH, E
Licensing Branch 4 3pp 18913 001 24X Fiche 50-000, 83/06/09, 8306210010

--8306210016 Procedure 862209 10, "Program Plan for Control Room Design Reviews for all TVA Nuclear Plants"
* Tennessee Valley Authority 83/06/09 200pp 18913 004 24X
Fiche 50-000, 83/06/09, 8306210010

8306290309 Ack receipt of 830524 ltr advising NRC that IF Insp Repts 50-438/83-13 & 50-439/83-13 contain safeguards-related matl (Rept will be withheld (ref 10CFR73.21))
VERRELLI, D M Division of Project & Resident Programs 83/06/15 PARRIS, H O Tennessee Valley Authority 1p 19053 351 24X
Fiche 50-438, 83/06/15, 8306290309

--8306290319 Responds to NRC 830519 ltr re violations noted in IF Insp Repts 50-438/83-13 & 50-439/83-13 Safeguards info should be withheld (ref 10CFR73.21)
MILLS, L M Tennessee Valley Authority 83/05/24 O'REILLY, J P
Region 2, Office of Director 1p 19055 352 24X
Fiche 50-438, 83/06/15, 8306290309

--8306290334 IE Insp Repts 50-438/83-13 & 50-439/83-13 on 830301-0410 No noncompliance noted Major areas inspected const surveillance & license action on previous enforcement matters Safeguards info deleted (ref 10CFR73.21)
WILCOX, J D Region 2, Office of Director 83/05/19 8pp 19055 355 24X Fiche 50-438, 83/06/15, 8306290309

G Inspection reports, IE Bulletins & correspondence

8306140570 Confirms mgt meeting on 830216 at Region 11 ofc to discuss results of self-initiated evaluation of activities at facility conducted under INPO guidelines Proposed meeting agenda encl
O'REILLY, J P Region 2, Office of Director 83/02/09 PARRIS, H O
Tennessee Valley Authority 2pp 18844 162 24X
Fiche 50-438, 83/02/09, 8306140570

8306140618 Forwards summary of 830216 meeting re licensee-initiated evaluation of const activities, per INPO guidelines
LEWIS, R C Division of Project & Resident Programs 83/02/22 PARRIS, H O Tennessee Valley Authority 4pp 18834 017 24X
Fiche 50-438, 83/02/22, 8306140618

DOCKETED ITEMS

307

8306140543 Confirms mgt meeting on 830421 in Chattanooga, TN to review results of first phase of annual appraisal of regulatory performance, per 830328 telcon
LEWIS, R C Division of Project & Resident Programs 83/04/12
PARRIS, H Q Tennessee Valley Authority Jpp 18834 176 24X
Fiche 50-000, 83/04/12, 8306140543

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 119pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8306140143 Ack receipt of 830516 ltr informing NRC of steps taken to correct violations noted in IL Insp Repts 50-438/83-07 & 50-439/83-07
VERRELLI, D M Division of Project & Resident Programs 83/05/26
PARRIS, H Q Tennessee Valley Authority 1p 18839 007 24X
Fiche 50-438, 83/05/26, 8306140143

--8306140150 Responds to NRC 830414 ltr re violations noted in IE Insp Repts 50-438/83-07 & 50-439/83-07 Corrective actions equipment named in violation tagged or returned to instrument test lab for repair or calibr
MILLS, L M Tennessee Valley Authority 83/05/16 O'REILLY, J P Region 2, Office of Director 7pp 18839 008 24X
Fiche 50-438, 83/05/26, 8306140143

--8306140157 Forwards IE Insp Repts 50-438/83-07 & 50-439/83-07 on 830307-11 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 83/04/14
PARRIS, H Q Tennessee Valley Authority 1p 18839 015 24X
Fiche 50-438, 83/05/26, 8306140143

--8306140144 Notice of violation from insp on 830307-11
* Region 2, Office of Director 83/04/14 2pp 18839 017 24X
Fiche 50-438, 83/05/26, 8306140143

--8306140172 IE Insp Repts 50-438/83-07 & 50-439/83-07 on 830307-11 Noncompliance noted failure to control & calibr measuring & test equipment & failure to audit several site const activities on annual basis
WRIGHT, R W, UPRIGHT, C M Region 2, Office of Director 83/04/17 8pp 18839 019 24X Fiche 50-438, 83/05/26, 8306140143

8306140114 Ack receipt of 830512 ltr informing NRC of steps taken to correct violations noted in IL Insp Repts 50-438/83-05 & 50-439/83-05
VERRELLI, D M Division of Project & Resident Programs 83/05/27
PARRIS, H Q Tennessee Valley Authority 1p 18839 138 24X
Fiche 50-438, 83/05/27, 8306140114

--8306140125 Responds to NRC 830412 ltr re violations noted in IL Insp Repts 50-438/83-05 & 50-439/83-05 Corrective actions checklist prepared & issued to unit training officer delineating documentation requirements for NDE personnel
MILLS, L M Tennessee Valley Authority 83/05/12 O'REILLY, J P Region 2, Office of Director 5pp 18839 139 24X
Fiche 50-438, 83/05/27, 8306140114

--8306140131 Forwards IE Insp Repts 50-438/83-05 & 50-439/83-05 on 830214-0304 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 83/04/12
PARRIS, H Q Tennessee Valley Authority 2pp 18839 144 24X
Fiche 50-438, 83/05/27, 8306140114

--8306140134 Notice of violation from insp on 830214-0304
* Region 2, Office of Director 83/04/12 2pp 18839 146 24X
Fiche 50-438, 83/05/27, 8306140114

--8306140139 IE Insp Repts 50-438/83-05 & 50-439/83-05 on 830214-0304 Noncompliance noted sufficient records affecting quality such as qualification of QC personnel not maintained
YORK, J W, LIU, W C, BLAKE, J J Region 2, Office of Director 83/04/05 13pp 18839 148 24X Fiche 50-438, 83/05/27, 8306140114

8306140757 Concurs w/util position contained in 821109 ltr supporting denial of violation identified in IE Insp Repts 50-438/82-24 & 50-439/82-24 Violation will be deleted from NRC records
VERRELLI, D M Division of Project & Resident Programs 83/05/27
PARRIS, H Q Tennessee Valley Authority 1p 18841 195 24X
Fiche 50-438, 83/05/27, 8306140757

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8306290231 Forwards IE Insp Repts 50-438/83-12 & 50-439/83-12 on 830516-20 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/06/09
PARRIS, H Q Tennessee Valley Authority 2pp 19055 087 24X
Fiche 50-438, 83/06/09, 8306290231

--8306290235 IE Insp Repts 50-438/83-12 & 50-439/83-12 on 830516-20 No noncompliance noted Major areas inspected previous enforcement matters, safety-related pipe support & restraint sys & licensee action on previously identified insp items
YORK, J W, BLAKE, J J Region 2, Office of Director 83/06/06 5pp 19055 089 24X Fiche 50-438, 83/06/09, 8306290231

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8306290309 Ack receipt of 830524 ltr advising NRC that IE Insp Repts 50-438/83-13 & 50-439/83-13 contain safeguards-related matl
Rept will be withheld (ref 10CFR73 21)
VERRELLI, D M Division of Project & Resident Programs 83/06/15
PARRIS, H Q Tennessee Valley Authority 1p 19055 351 24X
Fiche 50-438, 83/06/15, 8306290309

--8306290319 Responds to NRC 830519 ltr re violations noted in IE Insp Repts 50-438/83-13 & 50-439/83-13 Safeguards info should be withheld (ref 10CFR73 21)
MILLS, L M Tennessee Valley Authority, 83/05/24 O'REILLY, J P Region 2, Office of Director 1p 19055 352 24X
Fiche 50-438, 83/06/15, 8306290309

--8306290325 Forwards IE Insp Repts 50-438/83-13 & 50-439/83-13 on 830301-0430 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/05/19
PARRIS, H Q Tennessee Valley Authority 2pp 19055 353 24X
Fiche 50-438, 83/06/15, 8306290309

--8306290334 IE Insp Repts 50-438/83-13 & 50-439/83-13 on 830301-0430 No noncompliance noted Major areas inspected const surveillance & licensee action on previous enforcement matters Safeguards info deleted (ref 10CFR73 21)
WILCOX, J D Region 2, Office of Director QUICK, D R Division of Project & Resident Programs 83/05/19 8pp 19055 355 24X
Fiche 50-438, 83/06/15, 8306290309

8306290483 Approves issuance of SALP Repts 50-259/83-04, 50-260/83-04, 50-296/83-04, 50-327/83-04, 50-328/83-04, 50-390/83-07, 50-391/83-06, 50-438/83-06 & 50-439/83-06 for Jul 1981 - Dec 1982 No reply required
O'REILLY, J P Region 2, Office of Director 83/06/17 PARRIS, H Q Tennessee Valley Authority 3pp 24X Fiche 50-000, 83/06/17, 8306290483

--8306290490 Forwards SALP Repts 50-259/83-04, 50-260/83-04, 50-296/83-04, 50-327/83-04, 50-328/83-04, 50-390/83-07, 50-391/83-06, 50-438/83-06 & 50-439/83-06 for Jul 1981 - Dec 1982
LEWIS, R C Division of Project & Resident Programs 83/04/13
PARRIS, H Q Tennessee Valley Authority 3pp 24X
Fiche 50-000, 83/06/17, 8306290483

--8306290503 SALP Repts 50-259/83-04, 50-260/83-04, 50-296/83-04, 50-327/83-04, 50-328/83-04, 50-390/83-07, 50-391/83-06, 50-438/83-06 & 50-439/83-06 for Jul 1981 - Dec 1982
* Region 2, Office of Director 83/04/13 92pp 24X
Fiche 50-000, 83/06/17, 8306290483

DOCKETED ITEMS

--8306290510 Comments on SALP Repts 50-259/83-04, 50-260/83-04, 50-264/83-04, 50-327/83-04, 50-328/83-04, 50-390/83-07, 50-391/83-06, 50-438/83-06 & 50-439/83-06 for Jul 1981 - Dec 1982
MILLS, L. M. Tennessee Valley Authority 83/05/10 O'REILLY, J. P.
Region 2, Office of Director 2pp 24X Fiche 50-259, 83/06/17, 8306290483

8306290239 Act receipt of 830610 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/81-29 & 50-439/81-29
VERRELLI, D. M. Division of Project & Resident Programs 83/06/20
PARRIS, H. O. Tennessee Valley Authority 1p. 19056 244 24X
Fiche 50-438, 83/06/20, 8306290239

--8306290246 Submits supplemental response to NRC B11208 ltr re violations noted in IE Insp Repts 50-438/81-29 & 50-439/81-29 Corrective actions letdown coolers to be installed upon receipt of B&W info re support deficiencies
MILLS, L. M. Tennessee Valley Authority 83/06/10 O'REILLY, J. P.
Region 2, Office of Director 2pp 19056 245 24X
Fiche 50-438, 83/06/20, 8306290239

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Egozy Grouts & Sealers." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Node Switch Malfunctions." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co. of New York, Inc. 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc. 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

8 Reportable occurrences, LERs & related correspondence

8306070072 Fifth interim deficiency rept re engineering change notice review & handling Initially reported on B11215 Personnel retrained & corrective actions presented to Dfc of QA for approval Addl info will be submitted by 830722
MILLS, L. M. Tennessee Valley Authority 83/05/24 O'REILLY, J. P.
Region 2, Office of Director 2pp 18740:085 24X
Fiche 50-000, 83/05/24, 8306070072

8306010251 Third interim deficiency rept re undersigned snubber on main feedwater piping in Valve Room D Initially reported on B21013 Process of documenting completed Analysis & review underway Next rept by 840118.
MILLS, L. M. Tennessee Valley Authority 83/05/25 O'REILLY, J. P.
Region 2, Office of Director 1p 18673 033 24X
Fiche 50-438, 83/05/25, 8306010251

8306010274 Third interim deficiency rept re sheared motor pinion keys in Limitorque motor operators Initially reported on B20830 Field change notices issued to replace keys. Next rept will be sent by 830922. Also reportable per Part 21.
MILLS, L. M. Tennessee Valley Authority 83/05/25 O'REILLY, J. P.
Region 2, Office of Director 2pp 18674 322 24X
Fiche 50-000, 83/05/25, 8306010274

8306010431 Second interim deficiency rept re corrosion in high pressure fire protection sys. Initially reported on B20903. Sys contains carbon steel piping Corrosion analyses in progress Next rept to be submitted by 831004.
MILLS, L. M. Tennessee Valley Authority 83/05/25 O'REILLY, J. P.
Region 2, Office of Director, 2pp. 18674 255 24X
Fiche 50-000, 83/05/25, 8306010431

8306070074 First interim deficiency rept re incorrect max pipe movements contained in TPIPE program. Initially reported on 830504. W/o encl. Next rept expected by 830922
MILLS, L. M. Tennessee Valley Authority 83/05/26 O'REILLY, J. P.
Region 2, Office of Director 1p 18739 319 24X
Fiche 50-000, 83/05/26, 8306070074

8306070160 Fifth interim deficiency rept re defects in reactor protection & CSF actuation sys modules supplied by Bailey Meter Co Initially reported on B20414 B&W investigating use of yellowish bonding agent Also reportable per Part 21
MILLS, L. M. Tennessee Valley Authority 83/05/26 O'REILLY, J. P.
Region 2, Office of Director 3pp 18/36 288 24X
Fiche 50-438, 83/05/26, 8306070160

8306070138 Third interim deficiency rept re voiding of engineering change notices w/o proper review Initially reported on B20816 Change notices being reviewed & unresolved safety question determination performed Next rept by 830923
MILLS, L. M. Tennessee Valley Authority 83/05/31 O'REILLY, J. P.
Region 2, Office of Director 2pp 18/39 264 24X
Fiche 50-000, 83/05/31, 8306070138

8306090310 Second interim deficiency rept re tube leaks in component cooling water HXs Initially reported on B30218 Corrosion pitting revealed by metallurgical exam Alloys investigated for replacement
MILLS, L. M. Tennessee Valley Authority 83/06/03 O'REILLY, J. P.
Region 2, Office of Director 3pp 18/99 193 24X
Fiche 50-438, 83/06/03, 8306090310

8306200141 Sixth interim deficiency rept re Viking Flow control valves in fire protection sys Initially reported on B1124 Drawing rev review continuing Next rept to be submitted by 830809
Also reportable per Part 21
MILLS, L. M. Tennessee Valley Authority 83/06/07 O'REILLY, J. P.
Region 2, Office of Director 1p 18903 264 24X
Fiche 50-438, 83/06/07, 8306200141

8306200143 First interim deficiency rept re failure to specify IEEE class of safety-related sys components on procurement specs Initially reported on 830509 Suppliers being contacted Next rept to be submitted 831119
MILLS, L. M. Tennessee Valley Authority 83/06/09 O'REILLY, J. P.
Region 2, Office of Director 2pp 10/03 257 24X
Fiche 50-438, 83/06/09, 8306200143

8306210051 Supplemental interim deficiency rept re potentially overstressed embedded plates Initially reported on B20412 Next submittal scheduled for 840217 instead of 830622 as originally stated
MILLS, L. M. Tennessee Valley Authority 83/06/10 O'REILLY, J. P.
Region 2, Office of Director 1p 18914 009 24X
Fiche 50-000, 83/06/10, 8306210051

8306210005 First interim deficiency rept re max temp inside containment Initially reported on 830513 Util requested B&W to respond to nonconformance rept by 930715 Next rept to be submitted by 830826 Also reported per Part 21
MILLS, L. M. Tennessee Valley Authority 83/06/13 O'REILLY, J. P.
Region 2, Office of Director 2pp 10912 283 24X
Fiche 50-438, 83/06/13, 8306210005

8306210010 First interim deficiency rept re B&W plant internal bolt failures Initially reported on 830513 B&W & B&W Owners Group assessing situation to determine scope of problem & corrective actions Next rept to be submitted by 831206
MILLS, L. M. Tennessee Valley Authority 83/06/13 O'REILLY, J. P.
Region 2, Office of Director 2pp 10914 237 24X
Fiche 50-438, 83/06/13, 8306210010

8306210252 Second interim deficiency rept re failure to identify grade of nuts due to orientation w/grade markings facing against structural member Initially reported on B30126 Testing in progress Next rept by 830930
MILLS, L. M. Tennessee Valley Authority 83/06/14 O'REILLY, J. P.
Region 2, Office of Director 2pp 18718 099 24X
Fiche 50-438, 83/06/14, 8306210252

8306210042 Fifth interim deficiency rept re seismic analysis of auxiliary control bldg Initially reported on B20226 Seismic analysis rept revised & two new walls will be constructed Next rept to be submitted by 840622
MILLS, L. M. Tennessee Valley Authority 83/06/15 O'REILLY, J. P.
Region 2, Office of Director 2pp 10912 279 24X
Fiche 50-438, 83/06/15, 8306210042

8306280479 Final deficiency rept re improperly welded chiller unit piping components Initially reported on B20111 Radiographic exam to be performed on all safety-related chiller piping Also reportable per Part 21
MILLS, L. M. Tennessee Valley Authority 83/06/17 O'REILLY, J. P.
Region 2, Office of Director 3pp 19020 116 24X
Fiche 50-438, 83/06/17, 8306280479

8306280578 Interim deficiency rept re resolution of listed items due for submittal in late June Corrective actions in progress List identifying each item, schedule for next submittal & level of interim rept encl
MILLS, L. M. Tennessee Valley Authority 83/06/17 O'REILLY, J. P.
Region 2, Office of Director 2pp 19018 193 24X
Fiche 50-000, 83/06/17, 8306280578

8306280614 Fourth interim deficiency rept re incorrect installation of pressure relief & safety valves initially reported on 830305 Two 3-inch relief valves, exhausting into waste disposal header, added Next rept to be submitted by 840718
MILLS, L M Tennessee Valley Authority 83/06/17 O'REILLY, J P
Region 2, Office of Director 2pp 17016 001 24X
Fiche 50-438, 83/06/17, 8306280617

8306280222 Revised final deficiency rept re DHR valve initially reported on 820212 Lower stem valve plug & lock pin replaced Control valve design sold to company not qualified as nuclear industry supplier Also reportable per Part 21
MILLS, L M Tennessee Valley Authority 83/06/20 O'REILLY, J P
Region 2, Office of Director 2pp 17014 185 24X
Fiche 50-439, 83/06/20, 8306280222

8306280367 Second interim deficiency rept re incorrect seismic pipe support insps Approx 3,800 completed insps records for rigorously analyzed supports identified Support location will be shown on detail drawings Next rept by 831213
MILLS, L M Tennessee Valley Authority 83/06/20 O'REILLY, J P
Region 2, Office of Director 2pp 17014 083 24X
Fiche 50-438, 83/06/20, 8306280367

8306280425 Fourth interim deficiency rept re B&W design of RCS supports & restraints Initially reported on 820601 Majority of blocks installed Shear bar evaluation, expected by 830801 Also reported per Part 21
MILLS, L M Tennessee Valley Authority 83/06/20 O'REILLY, J P
Region 2, Office of Director 2pp 17020 300 24X
Fiche 50-438, 83/06/20, 8306280425

8306300157 Part 21 rept re spot welds in Bailey Controls Co cabinets w/smaller diameter than specified Cabinets strengthened by seam & edge welding or bolting
TAYLOR, J H Babcock & Wilcox Co 83/06/23 DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement 2pp 19119 308 24X Fiche 50-000, 83/06/23, 8306300159

8306300214 Second interim deficiency rept re tubeline matis supplied by Capitol Pipe & Steel not mfg under QA program Initially reported on 830324 Contractor will perform dimensional checks for pipes & fittings Next rept by 830922
MILLS, L M Tennessee Valley Authority 83/06/23 O'REILLY, J P
Region 2, Office of Director 3pp 19119 351 24X
Fiche 50-000, 83/06/23, 8306300214

8306300008 Fourth interim deficiency rept re possibility of exceeding turbine driven auxiliary feedwater pump room temp Initially reported on 811006 Fan motors will be replaced Next rept by 840430
MILLS, L M Tennessee Valley Authority 83/06/24 O'REILLY, J P
Region 2, Office of Director 2pp 19120 317 24X
Fiche 50-438, 83/06/24, 8306300008

8306300245 Final deficiency rept re analysis for loss of feedwater event Initially reported on 810316 Util does not consider subj nonconforming condition adverse to safe operation of plant Condition not reportable per 10CFR50.55(c)
MILLS, L M Tennessee Valley Authority 83/06/24 O'REILLY, J P
Region 2, Office of Director 2pp 19119 341 24X
Fiche 50-438, 83/06/24, 8306300245

DOCKET 50-440 PERRY NUCLEAR POWER PLANT, UNIT 1

A Application/construction stage documents & correspondence

8306060381 Appeals denial of FOIA request for documents re risk to facilities from low trajectory turbine missiles
HIATT, S L Ohio Citizens for Responsible Energy 83/03/03
DIRCKS, W J Office of the Executive Director for Operations 3pp 18750 329 24X Fiche 50-440, 83/03/03, 8306060381

8306060384 Responds to appeal re partial denial of FOIA request for documents concerning risks to facilities from low trajectory turbine missiles Appeal denied Documents withheld (ref FOIA Exemption 5)
DIRCKS, W J Office of the Executive Director for Operations 83/04/06 HIATT, S L Ohio Citizens for Responsible Energy 1p 18750 332 24X Fiche 50-440, 83/04/06, 8306060384

8306030509 Informs that each LRQ-II member must submit numerical value determined by CE for respective plants on fuel assembly lift off displacement due to error in fuel assembly topical rept re LRQ-II Generic Issue P-CFH
NOVAK, T M Assistant Director for Licensing 83/05/23
HOLTZSCHER, D L Licensing Review Group II 3pp 18735 051 24X
Fiche 50-000, 83/05/23, 8306030509

8306060373 Responds to 820903 ltr submitting position papers which included Licensing Review Group II proposed solution for Issue 4-MEB, intended to protect in-core instrument tubes from flow-induced vibration issue unresolved
YOUNGBLOOD, B J Licensing Branch 1 83/05/26 HOLTZSCHER, D L
Licensing Review Group II HOLTZSCHER, D L Illinois Power Co 4pp 18751 287 24X Fiche 50-000, 83/05/26, 8306060373

8306080044 Forwards "Analysis of Inaccessible & Potentially Rejectable Defects in Perry Nuclear Power Plant," per 830426 meeting commitment
EDELMAN, M R Cleveland Electric Illuminating Co 83/05/31
YOUNGBLOOD, B J Licensing Branch 1 1p 18774 115 24X
Fiche 50-440, 83/05/31, 8306080044

--8306080048 "Analysis of Inaccessible & Potentially Rejectable Defects in Perry Nuclear Power Plant"
MCNAUGHTON, W P, EGAN, O R, BYRON, J D Aptech Engineering Services 83/05/31 117pp 18774 116 24X Fiche 50-440, 83/05/31, 8306080044

8306140661 Forwards response to R Dimbar ltr re salt cavity storage area Encl FSAR changes will be incorporated into future FSAR amendment
EDELMAN, M R Cleveland Electric Illuminating Co 83/06/01
YOUNGBLOOD, B J Licensing Branch 1 4pp 18834 001 24X
Fiche 50-440, 83/06/01, 8306140661

8306100180 Forwards current description of QA program for design & const of Facilities Program acceptable, per 10CFR50, App B
EDELMAN, M R Cleveland Electric Illuminating Co 83/06/02
KEPPLER, J G Region 3, Office of Director 3pp 18804 029 24X
Fiche 50-440, 83/06/02, 8306100180

8306240186 Forwards addl info on safety relief valve piping & quencher device & safety-related piping supports, in response to Questions 210 9, 210 10 & 210 11 in NRC 821214 & 830401
1trs Lateral instability will not occur
EDELMAN, M R Cleveland Electric Illuminating Co 83/06/21
YOUNGBLOOD, B J Licensing Branch 1 9pp 18981 021 24X
Fiche 50-440, 83/06/21, 8306240186

8306240390 Requests submittal of proof & review Tech Specs accompanied by detailed discussion of methodology used in establishing setpoint values for reactor protection sys & CBF instrumentation 4 months prior to Unit 1 licensing
YOUNGBLOOD, B J Licensing Branch 1 83/06/21 EDELMAN, M R
Cleveland Electric Illuminating Co 3pp 18987 350 24X
Fiche 50-440, 83/06/21, 8306240390

8306280161 Responds to Generic Ltr 83-10, "NRC Review of DWR Owners Group Control Room Survey Program" Plant-specific info to be addressed listed
EDELMAN, M R Cleveland Electric Illuminating Co 83/06/21
YOUNGBLOOD, B J Licensing Branch 1 2pp 19015 100 24X
Fiche 50-440, 83/06/21, 8306280161

E NRC Safety Evaluation Report (SER), suppl & correspondence

8306020694 Submits rept re turbine missile issue Rept completes NRR action requested in ACRS 820713 ltr Results documented in Suppl 3 to SER (NUREG-0887).
NOVAK, T M Assistant Director for Licensing, 83/05/23 RAY, J J
ACRS - Advisory Committee on Reactor Safeguards. 10pp 18716 237, 24X Fiche 50-440, 83/05/23, 8306020694

8306010058 Responds to 830506 ltr on procedures generation package per SER Outstanding Issue 21 Dec 1983 scheduled completion date provided in 830415 suppl to Generic Ltr 82-33
EDELMAN, M R Cleveland Electric Illuminating Co 83/05/27
YOUNGBLOOD, B J Licensing Branch 1 1p 18674 073 24X
Fiche 50-440, 83/05/27, 8306010058

8306080437 Summary of 830526 meeting w/util in Bethesda, MD re present containment purge sys design, Outstanding Issue 10 in SER (NUREG-0887)
STEFANO, J J Licensing Branch 1 83/06/03 YOUNGBLOOD, B J
Licensing Branch 1 12pp 18792 197 24X Fiche 50-440, 83/06/03, 8306080437

8306200085 Clarifies commitment to perform addl start & load qualification testing on standby diesel generators, as outlined in SER Section 8 3 1 Total of 20 addl tests will be conducted
EDELMAN, M R Cleveland Electric Illuminating Co 83/06/15
YOUNGBLOOD, B J Licensing Branch 1 2pp 18903 393 24X
Fiche 50-440, 83/06/15, 8306200085

DOCKETED ITEMS

8306240269 Forwards study results of effects of grating on drywell & containment response, per SER Outstanding Issue 9 re pool dynamic loads App 30 incorporated in Amend 11 to FSAR providing description of hydrodynamic loads
EDELMAN, M R Cleveland Electric Illuminating Co 83/06/20
YOUNGBL00D, B J Licensing Branch 1 5pp 18980 078 24X
Fiche 50-440, 83/06/20, 8306240269

8306240064 Notifies that addl info re list of safety-related items in FSAR Table 3 2-1 (OA-list) acceptable Outstanding Issue 23 in Suppl 3 to SER (NUREG-0087) will be changed to confirmatory issue per FSAR, Amend 12 review
YOUNGBL00D, B J Licensing Branch 1 83/06/21 EDELMAN, M R
Cleveland Electric Illuminating Co 2pp 18987 134 24X
Fiche 50-440, 83/06/21, 8306240064

8306240288 Requests addl info to resolve SER Confirmatory Issue 10 re fast scram hydrodynamic loads on control rod drive sys Response within 7 days of ltr receipt requested
YOUNGBL00D, B J Licensing Branch 1 83/06/21 EDELMAN, M R
Cleveland Electric Illuminating Co 3pp 18999 167 24X
Fiche 50-440, 83/06/21, 8306240288

8306290137 Submits evaluation findings on outstanding & confirmatory instrumentation & control sys issues documented in SER Addl info requested. Response requested within 7 days
YOUNGBL00D, B J Licensing Branch 1 83/06/22 EDELMAN, M R
Cleveland Electric Illuminating Co 25pp 19046 222 24X
Fiche 50-440, 83/06/22, 8306290137

F Security, medical, emergency & fire protection plans

8306010058 Responds to 830506 ltr on procedures generation package per SER Outstanding Issue 21 Dec 1983 scheduled completion date provided in 830415 suppl to Generic Ltr 82-33
EDELMAN, M R Cleveland Electric Illuminating Co 83/05/27
YOUNGBL00D, B J Licensing Branch 1 1p 18674 073 24X
Fiche 50-440, 83/05/27, 8306010058

G Adjudicatory correspondence

8306010433 Motion for summary disposition of Issue 13 No genuine issue of matl fact exists & NRC entitled to favorable decision Affidavit, Certificate of Svc & prof qualifications encl
CUTCHIN, J M Hearing Branch 4 83/05/31 Atomic Safety and Licensing Board Panel 11pp 18674 257 24X Fiche 50-440, 83/05/31, 8306010433

8306090345 Notice of Ohio Citizens for Responsible Energy 10CFR2 206 petition alleging false util statements in application re use of herbicides to control vegetation along transmission lines
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 83/06/06 1p 18794 335 24X Fiche 50-440, 83/06/06, 8306090345

8306140706 Forwards NRC answers to two ASLB questions posed during 830509 telephone conference re declaration of sua sponte issue Operators will be trained to differentiate between instrument failures & transients & accidents
CUTCHIN, J M Hearing Branch 4 83/06/13 BLOCH, P B, BRIGHT, G D, KLINE, J R Atomic Safety and Licensing Board Panel 5pp 18841 274 24X Fiche 50-440, 83/06/13, 8306140706

8306160596 Answer opposing Ohio Citizens for Responsible Energy 830510 motion to admit five new contentions on SNM license application Contentions unjustifiably late, outside ASLB jurisdiction or moot Certificate of Svc encl
SILBERG, J E Commonwealth Edison Co SILBERG, J E Shaw, Pittman, Potts & Trowbridge 83/06/13 Atomic Safety and Licensing Board Panel 23pp 18892 286 24X Fiche 50-440, 83/06/13, 8306160596

8306160611 Provides estimate of hearing dates In-core thermocouples & steam erosion issue will be disposed of by summary disposition Standby liquid control sys initiation & hydrogen control issues should be resolved by rulemaking
SILBERG, J E Shaw, Pittman, Potts & Trowbridge SILBERG, J E Cleveland Electric Illuminating Co 83/06/14 BLOCH, P B, KLINE, J R, BRIGHT, G D Atomic Safety and Licensing Board Panel 3pp 18866 097 24X Fiche 50-440, 83/06/14, 8306160611

8306220080 Answer opposing NRC 830531 motion for summary disposition of Issue 13 re adequacy of proposed turbine maint program w/turbine missile probability Statement of matl fact & Certificate of Svc encl Related correspondence
LODGE, T J Sunflower Alliance 83/06/15 Atomic Safety and Licensing Board Panel 5pp 18930 157 24X Fiche 50-440, 83/06/15, 8306220080

8306170399 Advises of incorrect cite in NRC 830713 answer opposing Ohio Citizens for Responsible Energy motion to file contentions on SNM license application
CUTCHIN, J M Hearing Branch 4 83/06/16 BLOCH, P B, BRIGHT, G D, KLINE, J R Atomic Safety and Licensing Board Panel 1p 18880 017 24X Fiche 50-440, 83/06/16, 8306170399

8306270014 Responses to fourth set of interrogatories & request for production of documents Related correspondence
HIATT, S L Ohio Citizens for Responsible Energy 83/06/21
Cleveland Electric Illuminating Co 7pp 18988 050 24X
Fiche 50-440, 83/06/21, 8306270014

--8306270017 Supplemental response to third set of interrogatories Certificate of Svc encl
HIATT, S L Ohio Citizens for Responsible Energy 83/06/21
Cleveland Electric Illuminating Co 3pp 18988 055 24X
Fiche 50-440, 83/06/21, 8306270014

8306290536 Response opposing NRC 830531 motion for summary disposition of Issue 13 re turbine missile hazards Motion premature Valuable evidence would be excluded if motion granted Statement of matl facts encl Related correspondence
HIATT, S L Ohio Citizens for Responsible Energy 83/06/23
Atomic Safety and Licensing Board Panel 7pp 19052 292 24X
Fiche 50-440, 83/06/23, 8306290536

--8306290549 Affidavit of SL Hiatt that Ohio Citizens for Responsible Energy cannot currently present facts to justify opposition to NRC motion for summary disposition of Issue 13 since info still being reviewed Certificate of Svc encl
HIATT, S L Ohio Citizens for Responsible Energy 83/06/23 14pp 19052 299 24X Fiche 50-440, 83/06/23, 8306290549

8306290214 Answer supporting NRC 830531 motion for summary disposition of Issue 13 No genuine issue of matl fact exists & no good cause provided Certificate of Svc encl Related correspondence
SILBERG, J E Cleveland Electric Illuminating Co SILBERG, J E Shaw, Pittman, Potts & Trowbridge 83/06/27 Atomic Safety and Licensing Board Panel 12pp 19056 140 24X Fiche 50-440, 83/06/27, 8306290214

--8306290220 Affidavit of DP Timo & LH Johnson, supporting NRC 830531 motion for summary disposition of Issue 13 Prof qualifications encl
TIMO, D P, JOHNSON, L H NRC - No Detailed Affiliation Given
TIMO, D P General Electric Co 83/06/24 35pp 19056 160 24X
Fiche 50-440, 83/06/27, 8306290214

--8306290240 Affidavit of EJ Turk, supporting NRC 830531 motion for summary disposition of Issue 13 Prof qualifications re testing of overspeed protection sys Prof qualifications encl
TURK, E J NRC - No Detailed Affiliation Given * Cleveland Electric Illuminating Co 83/06/24 5pp 19056 195 24X
Fiche 50-440, 83/06/27, 8306290214

H General correspondence

8306030280 Notice of change of counsel address Certificate of Svc encl
LODGE, T J Lodge, T J 83/05/31 1p 18703 357 24X
Fiche 50-440, 83/05/31, 8306030280

8306290144 Ack receipt of 830516 ltr forwarding council Resolution 1443-83 re quality of containment vessel welds Summary rept of 830504 site visit encl Completed rept of review of util commitments expected in Jul 1983
DENTON, H R Office of Nuclear Reactor Regulation, Director 83/06/22 EULER, G A Perry, OH App 19046 290 24X
Fiche 50-440, 83/06/22, 8306290144

I Inspection reports, IE Bulletins & correspondence

8306270112 Ack receipt of 830415 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-440/83-06 & 50-441/83-06
SPESSARD, R L Division of Engineering 83/04/22 EDELMAN, M R
Cleveland Electric Illuminating Co 1p 18988 097 24X
Fiche 50-440, 83/04/22, 8306270112

--8306270115 Responds to NRC 830316 ltr re violations noted in IE Insp Repts 50-440/83-06 & 50-441/83-06 Corrective actions QC insp rept written for each concern identified during LK Comstock Task Force document review
EDELMAN, M R Cleveland Electric Illuminating Co 83/04/15
SPESSARD, R L Division of Engineering 5pp 18988 098 24X
Fiche 50-440, 83/04/22, 8306270112

DOCKETED ITEMS

311

- 8306030149 Forwards IE Insp Repts 50-440/83-08 & 50-441/83-07 on 830301-03 & 11 No noncompliance noted
LITTLE, W S Region 3, Office of Director 83/05/16 EDELMAN, M R
Cleveland Electric Illuminating Co 2pp 18704 253 24X
Fiche 50-440, 83/05/16, 8306030149
- 8306030151 IE Insp Repts 50-440/83-08 & 50-441/83-07 on 830301-03 & 11 No noncompliance noted Major areas inspected LK Comstock personnel qualifications, GA/QC & craft personnel & license actions on previously identified items
BARRETT, P A, NAIDU, K R, PLIKER, P R Region 3, Office of Director 83/05/12 13pp 18704 255 24X Fiche 50-440, 83/05/16, 8306030149
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl
TAYLOR, J H Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458
- 8305110460 IC Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461
- 8306160242 Forwards IE Insp Repts 50-440/83-12 & 50-441/83-11 on 830418-22 & notice of violation
LITTLE, W S Region 3, Office of Director 83/06/03 EDELMAN, M R
Cleveland Electric Illuminating Co 2pp 18861 276 24X
Fiche 50-440, 83/06/03, 8306160242
- 8306160247 Notice of violation from Insp on 830418-22
LITTLE, W S Region 3, Office of Director 83/06/03 1p 18861 228 24X Fiche 50-440, 83/06/03, 8306160242
- 8306160254 IE Insp Repts 50-440/83-12 & 50-441/83-11 on 830418-22 Noncompliance noted Failure to perform routine monthly insp on stored items
HUNT, M D, MERRIWEATHER, N Region 2, Office of Director
CONLON, T E Division of Engineering & Radiological Safety Programs 83/05/11 6pp 18861 227 24X Fiche 50-440, 83/06/03, 8306160242
- 8306130299 Ack receipt of 830531 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-440/83-09 & 50-441/83-08
LITTLE, W S Region 3, Office of Director 83/06/08 EDELMAN, M R
Cleveland Electric Illuminating Co 1p 18823 320 24X
Fiche 50-440, 83/06/08, 8306130299
- 8306130305 Responds to NRC 830401 ltr re violations noted in IE Insp Repts 50-440/83-09 & 50-441/83-08 Corrective actions monitoring program consisting of periodic visual exam of suppression pool welds performed from platform
EDELMAN, M R Cleveland Electric Illuminating Co 83/05/31
KEPPLER, J Q Region 3, Office of Director 2pp 18823 321 24X
Fiche 50-440, 83/06/08, 8306130299
- 8306230267 Forwards IE Insp Repts 50-440/83-14 & 50-441/83-13 on 830425-28 No noncompliance noted
LITTLE, W S Region 3, Office of Director 83/06/08 EDELMAN, M R
Cleveland Electric Illuminating Co 2pp 18745 086 24X
Fiche 50-440, 83/06/08, 8306230267
- 8306230271 IE Insp Repts 50-440/83-14 & 50-441/83-13 on 830426-28 No noncompliance noted Major areas inspected licensee action on deficiency items re RCPB piping work activities & review of quality records
WARD, K D, KEATING, D E, DANIELSON, D H Region 3, Office of Director 83/06/07 14pp 18745 080 24X Fiche 50-440, 83/06/08, 8306230267
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc 117pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470
- 8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010
- 8306300201 Forwards IE Insp Repts 50-440/83-17 & 50-441/83-16 on 830301-0430 No noncompliance noted
KNOP, R C Region 3, Office of Director 83/06/14 EDELMAN, M R
Cleveland Electric Illuminating Co 2pp 19119 359 24X
Fiche 50-440, 83/06/14, 8306300201
- 8306300207 IE Insp Repts 50-440/83-17 & 50-441/83-16 on 830301-0430, No noncompliance noted Major areas inspected safety-related const activities, including 10CFR50 55(e) reportable item followup, housekeeping & preparation for ABLB hearings.
GILDER, M L, KONKLIN, J E Region 3, Office of Director 83/06/14 3pp 19119 361 24X Fiche 50-440, 83/06/14, 8306300201
- 8306300179 Forwards IE Insp Repts 50-440/83-16 & 50-441/83-15 on 830518-19 No noncompliance noted
KNOP, R C Region 3, Office of Director 83/06/15 EDELMAN, M R
Cleveland Electric Illuminating Co 2pp 19119 263 24X
Fiche 50-440, 83/06/15, 8306300179
- 8306300183 IE Insp Repts 50-440/83-16 & 50-441/83-15 on 830518-19, No noncompliance noted Major areas inspected licensee actions on previous insp findings, 10CFR50 55(e) reportable items & IE bulletins
PELKE, P R, KONKLIN, J E Region 3, Office of Director 83/06/15 4pp 19119 265 24X Fiche 50-440, 83/06/15, 8306300179
- 8306300126 Forwards IE Insp Repts 50-440/83-15 & 50-441/83-14 on 830509-13 No noncompliance noted
LITTLE, W S Region 3, Office of Director 83/06/17 EDELMAN, M R
Cleveland Electric Illuminating Co 2pp 19122 323 24X
Fiche 50-440, 83/06/17, 8306300126
- 8306300132 IE Insp Repts 50-440/83-15 & 50-441/83-14 on 830509-13 No noncompliance noted Major areas inspected safety-related cable tray installation, electrical cables & terminations & equipment installation
MERRIWEATHER, N, CONLON, T E Region 2, Office of Director 83/06/02 4pp 19122 325 24X Fiche 50-440, 83/06/17, 8306300126
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 120pp 18977 007 24X Fiche 50-000, 83/06/22, 8305110477
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co. of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479
- 8306270283 Ack receipt of 830609 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-440/83-11 & 50-441/83-10
LITTLE, W S Region 3, Office of Director 83/06/23 EDELMAN, M R
Cleveland Electric Illuminating Co 1p 18996 173 24X
Fiche 50-440, 83/06/23, 8306270283
- 8306270287 Responds to NRC 830609 ltr re violations noted in IE Insp Repts 50-440/83-11 & 50-441/83-10 Corrective actions
Johnson Controls Procedure QAS-1802-RNPP, "Review & Turnover of Records," revised to reflect present document review
EDELMAN, M R Cleveland Electric Illuminating Co 83/06/09
KEPPLER, J Q Region 3, Office of Director 2pp 18996 174 24X
Fiche 50-440, 83/06/23, 8306270283
- 8305110483 IE Info Notice 83-43, "Improper Bettings of Intermediate Range (IR) High Flux Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc 116pp 19046 277 24X Fiche 50-000, 83/06/24, 8305110483

DOCKETED ITEMS

B Reportable occurrences, LERs & related correspondence

B306100119 Fifth interim deficiency rept re rejection of previously accepted containment vessel radiographs Review of radiographs utilizing film overlay techniques being performed Next rept will be submitted by B30930
EDELMAN, M R Cleveland Electric Illuminating Co 83/05/31
KEPPLER, J G Region 3, Office of Director 1p 18802 024 24X
Fiche 50-440, 83/05/31, B306100119

B306220015 Interim deficiency rept re sensitivity & density variations in Borg-Warner valve radiographs Initially reported on B30411 Sampling plan to determine valve acceptability established Final rept by B30710 Also reported per Part 21
EDELMAN, M R Cleveland Electric Illuminating Co 83/06/10
KEPPLER, J G Region 3, Office of Director 2pp 18927 330 24X
Fiche 50-440, 83/06/10, B306220015

B306220058 Final deficiency rept re potentially inadequate cooling of RCIC room during LOCA Initially reported on B30513 AE reviewing RCIC pump/turbine automatic start Review will be completed by B30729 Also reported per Part 21
EDELMAN, M R Cleveland Electric Illuminating Co 83/06/10
KEPPLER, J G Region 3, Office of Director 2pp 18930 034 24X
Fiche 50-440, 83/06/10, B306220058

B306200120 Notifies that rework associated w/potentially significant deficiency re governor drive coupling mfg by Transamerica Delaval in standby diesel generators, scheduled to be completed by B31031 for Unit 1 & B31231 for Unit 2
EDELMAN, M R Cleveland Electric Illuminating Co 83/06/14
KEPPLER, J G Region 3, Office of Director 1p 18903 329 24X
Fiche 50-440, 83/06/14, B306200120

B306220039 Suppls final deficiency rept re matl used in Transamerica Delaval, Inc governor drive coupling in standby diesel generators Due to long storage time, governors will be returned to manufacturers for overhauling & recaliber
EDELMAN, M R Cleveland Electric Illuminating Co 83/06/14
KEPPLER, J G Region 3, Office of Director 1p 18930 174 24X
Fiche 50-440, 83/06/14, B306220039

B306300169 Suppl to B10803 final deficiency rept re Mono-Bol Brand 7-0015-3 COS polyvinyl alcohol film, water soluble purge dam matl mfg by Chris Craft Industries Portions of sys will be flushed prior to fuel loading
EDELMAN, M R Cleveland Electric Illuminating Co 83/06/27
KEPPLER, J G Region 3, Office of Director 3pp 19121 360 24X
Fiche 50-440, 83/06/27, B306300169

F Hearing transcripts on non-antitrust matters

B306010006 Transcript of B30526 hearing in Painesville, OH Pp 1, 227-1, 436
* Atomic Safety and Licensing Board Panel 83/05/25 21pp
18673 093 24X Fiche 50-440, 83/05/25, B306010006

B306010010 Transcript of B30526 hearing in Painesville, OH Pp 1, 437-1, 706 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/05/26 31pp
18671, 224 24X Fiche 50-440, 83/05/26, B306010010

B306010004 Transcript of B30527 hearing in Painesville, OH Pp 1, 707-1, 877 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/05/27 17pp
18665 200 24X Fiche 50-440, 83/05/27, B306010004

B306070149 Transcript of B30531 hearing in Painesville, OH Pp 1, 877-1, 980 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/05/31 127pp
18737, 001 24X Fiche 50-440, 83/05/31, B306070149

DOCKET 50-441 PERRY NUCLEAR POWER PLANT, UNIT 2

A Application/construction stage documents & correspondence

B306060381 Appeals denial of FOIA request for documents re risk to facilities from low trajectory turbine missiles
HIATT, S L Ohio Citizens for Responsible Energy 83/03/03
DIRKSB, H J Office of the Executive Director for Operations 3pp
18750 329 24X Fiche 50-440, 83/03/03, B306060381

B306060384 Responds to appeal re partial denial of FOIA request for documents concerning risks to facilities from low trajectory turbine missiles Appeal denied Documents withheld (ref FOIA Exemption 5)
DIRKSB, H J Office of the Executive Director for Operations 83/04/06, HIATT, S L Ohio Citizens for Responsible Energy 1p
18750 332 24X Fiche 50-440, 83/04/06, B306060384

B306030509 Informs that each LRG-II member must submit numerical value determined by GF for respective plants on fuel assembly lift off displacement, due to error in fuel assembly topical rept re LRG-II Generic Issue 2-CMB
NOVAK, T M Assistant Director for Licensing 83/05/27
HOLTZSCHER, D L Licensing Review Group II 3pp 18735 051 24X
Fiche 50-000, 83/05/23, B306030509

B306060373 Responds to B20903 ltr submitting position papers which included Licensing Review Group II proposed solution for Issue 4-MEB, intended to protect in-core instrument tubes from flow-induced vibration Issue unresolved
YOUNGBLOOD, B J Licensing Branch 1 83/05/26 HOLTZSCHER, D L
Licensing Review Group II HOLTZSCHER, D L Illinois Power Co 4pp
18751 287 24X Fiche 50-000, 83/05/26, B306060373

B306080044 Forwards "Analysis of Inaccessible & Potentially Rejectable Defects in Perry Nuclear Power Plant," per B30474 meeting commitment
EDELMAN, M R Cleveland Electric Illuminating Co 83/05/31
YOUNGBLOOD, B J Licensing Branch 1 1p 18774 115 24X
Fiche 50-440, 83/05/31, B306080044

--B306080048 "Analysis of Inaccessible & Potentially Rejectable Defects in Perry Nuclear Power Plant"
MCNAUGHTON, H P, EGAN, O R, BYRON, J D Aptech Engineering Services 83/05/31 11pp 18774 116 24X Fiche 50-440, 83/05/31, B306080048

B306140661 Forwards response to R Bimber ltr re salt cavity storage area Encl FSAR changes will be incorporated into future FSAR amend
EDELMAN, M R Cleveland Electric Illuminating Co 83/06/01
YOUNGBLOOD, B J Licensing Branch 1 4pp 18834 001 24X
Fiche 50-440, 83/06/01, B306140661

B306100180 Forwards current description of QA program for design & const of facilities Program acceptable, per 10C H90, App B
EDELMAN, M R Cleveland Electric Illuminating Co 83/06/01
KEPPLER, J G Region 3, Office of Director 3pp 18806 024 24X
Fiche 50-440, 83/06/02, B306100180

B306240186 Forwards add info on safety relief valve piping & quencher device & safety-related piping supports, in response to Questions 210 9, 210 10 & 210 11 in NRC Q21714 & B30401 ltr. Lateral instability will not occur
EDELMAN, M R Cleveland Electric Illuminating Co 83/06/21
YOUNGBLOOD, B J Licensing Branch 1 9pp 18901 021 24X
Fiche 50-440, 83/06/21, B306240186

B306240390 Requests submittal of proof & review Tech Specs accompanied by detailed discussion of methodology used in establishing setpoint values for reactor protection sys & CSF instrumentation 6 months prior to Unit 1 licensing.
YOUNGBLOOD, B J Licensing Branch 1 83/06/21 EDELMAN, M R
Cleveland Electric Illuminating Co 3pp 18987 350 24X
Fiche 50-440, 83/06/21, B306240390

B306280161 Responds to Generic ltr B3-1B, "NRC Review of BWR Owners Group Control Room Survey Program" Plant-specific info to be addressed listed
EDELMAN, M R Cleveland Electric Illuminating Co 83/06/21
YOUNGBLOOD, B J Licensing Branch 1 2pp 19015 100 24X
Fiche 50-440, 83/06/21, B306280161

E NRC Safety Evaluation Report (SER), supp & correspondence

B306020694 Submits rept re turbine missile issue Rept completes NRC action requested in ACRS B20713 ltr Results documented in Suppl 3 to SER (NUREG-0887)
NOVAK, T M Assistant Director for Licensing 83/05/23 RAY, P J
ACRS - Advisory Committee on Reactor Safeguards 10pp 18714 231 24X Fiche 50-440, 83/05/23, B306020694

B306010059 Responds to B30506 ltr on procedures generation package per SER Outstanding Issue 21, Dec 1983 scheduled completion date provided in B30415 suppl to Generic ltr B2-35
EDELMAN, M R Cleveland Electric Illuminating Co 83/05/27
YOUNGBLOOD, B J Licensing Branch 1 1p 18674 073 24X
Fiche 50-440, 83/05/27, B306010059

B306080437 Summary of B30526 meeting w/util in Bethesda, MD re present containment purge sys design, Outstanding Issue 10 in SER (NUREG-0887)
STEFANO, J J Licensing Branch 1 83/06/03 YOUNGBLOOD, B J
Licensing Branch 1 12pp 18772 197 24X Fiche 50-440, 83/06/04, B306080437

DOCKETED ITEMS

313

8306200085 Clarifies commitment to perform addl start & load qualification testing on standby diesel generators, as outlined in SER Section B 3.1 Total of 20 addl tests will be conducted
EDELMAN, M R Cleveland Electric Illuminating Co 83/06/15
YOUNGBLOOD, B J Licensing Branch 1 2pp 18903 353 24X
Fiche 50-440, 83/06/15, 8306200085

8306240269 Forwards study results of effects of grating on drywell & containment response, per SER Outstanding Issue 9 re pool dynamic loads App 30 incorporated in Amend II to FSAR providing description of hydrodynamic loads
EDELMAN, M R Cleveland Electric Illuminating Co 83/06/20
YOUNGBLOOD, B J Licensing Branch 1 1pp 18980 078 24X
Fiche 50-440, 83/06/20, 8306240269

8306240064 Notifies that addl info re list of safety-related items in FSAR Table 3.2-1 (QA-list) acceptable Outstanding Issue 23 in Suppl 3 to 5SR (NUREG-0887) will be changed to confirmatory issue per FSAR Amend 12 review
YOUNGBLOOD, B J Licensing Branch 1 83/06/21 EDELMAN, M R
Cleveland Electric Illuminating Co 2pp 18987 134 24X
Fiche 50-440, 83/06/21, 8306240064

8306240288 Requests addl info to resolve SER Confirmatory Issue 10 re fast action hydrodynamic loads on control rod drive sys Response within 7 days of ltr receipt requested
YOUNGBLOOD, B J Licensing Branch 1 83/06/21 EDELMAN, M R
Cleveland Electric Illuminating Co 3pp 18999 167 24X
Fiche 50-440, 83/06/21, 8306240288

8306290137 Submits evaluation findings on outstanding & confirmatory instrumentation & control sys issues documented in SER Addl info requested Response requested within 7 days
YOUNGBLOOD, B J Licensing Branch 1 83/06/22 EDELMAN, M R
Cleveland Electric Illuminating Co 25pp 19046 222 24X
Fiche 50-440, 83/06/22, 8306290137

F Security, medical, emergency & fire protection plans

8306010058 Responds to 830506 ltr on procedures generation package per SER Outstanding Issue 21 Dec 1983 scheduled completion date provided in 830415 suppl to Generic Ltr B2-32
EDELMAN, M R Cleveland Electric Illuminating Co 83/05/27
YOUNGBLOOD, B J Licensing Branch 1 1p 18674 073 24X
Fiche 50-440, 83/05/27, 8306010058

G Adjudicatory correspondence

8306010423 Motion for summary disposition of Issue 13 No genuine issue of matl fact exists & NRC entitled to favorable decision Affidavit, Certificate of Svc & prof qualifications encl
CUTCHIN, J M Hearing Branch 4 83/05/31 Atomic Safety and Licensing Board Panel 11pp 18674 25/ 24X Fiche 50-440, 83/05/31, 8306010423

8306090345 Notice of Ohio Citizens for Responsible Energy 10CIRP 206 petition alleging false util statements in application re use of herbicides to control vegetation along transmission lines
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/06/06 1p 18794 335 24X Fiche 50-440, 83/06/06, 8306090345

8306140706 Forwards NRC answers to two AUIB questions posed during 830509 telephone conference re declaration of sua sponte issue Operators will be trained to differentiate between instrument failures & transients & accidents
CUTCHIN, J M Hearing Branch 4 83/06/13 BLOCH, P D, BRIGHT, O D, KLINE, J R Atomic Safety and Licensing Board Panel 5pp 18841 274 24X Fiche 50-440, 83/06/13, 8306140706

8306160596 Answer opposing Ohio Citizens for Responsible Energy 830510 motion to admit five new contentions on SNM license application Contentions unjustifiably late, outside ASLB jurisdiction or moot Certificate of Svc encl
SILBERG, J E Commonwealth Edison Co SILBERG, J E Shaw, Pittman, Potts & Trowbridge 83/06/13 Atomic Safety and Licensing Board Panel 23pp 18892 286 24X Fiche 50-440, 83/06/13, 8306160596

8306160611 Provides estimate of hearing dates in-core thermocouples & steam erosion issue will be disposed of by summary disposition Standby liquid control sys initiation & hydrogen control issues should be resolved by rulemaking
SILBERG, J E Shaw, Pittman, Potts & Trowbridge SILBERG, J E Cleveland Electric Illuminating Co 83/06/14 BLOCH, P D, KLINE, J R, BRIGHT, O D Atomic Safety and Licensing Board Panel 3pp 18866 097 24X Fiche 50-440, 83/06/14, 8306160611

8306220080 Answer opposing NRC 830531 motion for summary disposition of Issue 13 re adequacy of proposed turbine maint program w/turbine missile probability Statement of matl fact & Certificate of Svc encl Related correspondence
LODGE, T J Sunflower Alliance 83/06/15 Atomic Safety and Licensing Board Panel 3pp 18730 137 24X Fiche 50-440, 83/06/15, 8306220080

8306170399 Advises of incorrect cite in NRC 830713 answer opposing Ohio Citizens for Responsible Energy motion to file contentions on SNM license application
CUTCHIN, J M Hearing Branch 4 83/06/16 BLOCH, P D, BRIGHT, O D, KLINE, J R Atomic Safety and Licensing Board Panel 1p 18880 017 24X Fiche 50-440, 83/06/16, 8306170399

8306270014 Responses to fourth set of interrogatories & request for production of documents Related correspondence
HIATT, S L Ohio Citizens for Responsible Energy 83/06/21
Cleveland Electric Illuminating Co 5pp 18988 050 24X
Fiche 50-440, 83/06/21, 8306270014

--8306270017 Supplemental response to third set of interrogatories Certificate of Svc encl
HIATT, S L Ohio Citizens for Responsible Energy 83/06/21, Cleveland Electric Illuminating Co 3pp 18988 055 24X
Fiche 50-440, 83/06/21, 8306270014

8306290536 Response opposing NRC 830531 motion for summary disposition of Issue 13 re turbine missile hazards Motion premature Valuable evidence would be excluded if motion granted Statement of matl facts encl Related correspondence
HIATT, S L Ohio Citizens for Responsible Energy 83/06/23 Atomic Safety and Licensing Board Panel 7pp 19052 292 24X
Fiche 50-440, 83/06/23, 8306290536

--8306290549 Affidavit of BL Hiatt that Ohio Citizens for Responsible Energy cannot currently present facts to justify opposition to NRC motion for summary disposition of Issue 13 since info still being reviewed Certificate of Svc encl
HIATT, S L Ohio Citizens for Responsible Energy 83/06/23 16pp, 19052 297 24X Fiche 50-440, 83/06/23, 8306290536

8306290214 Answer supporting NRC 830531 motion for summary disposition of Issue 13 No genuine issue of matl fact exists & no good cause provided Certificate of Svc encl Related correspondence
SILBERG, J E Cleveland Electric Illuminating Co SILBERG, J E Shaw, Pittman, Potts & Trowbridge 83/06/27 Atomic Safety and Licensing Board Panel 12pp, 19056 148 24X Fiche 50-440, 83/06/27, 8306290214

--8306290220 Affidavit of DP Timm & LH Johnson, supporting NRC 830531 motion for summary disposition of Issue 13 Prof qualifications encl
TIMM, D P, JOHNSON, L H NRC - No Detailed Affiliation Given, TIMM, D P General Electric Co 83/06/24 35pp 19056 160 24X
Fiche 50-440, 83/06/27, 8306290214

--8306290240 Affidavit of EU Turk, supporting NRC 830531 motion for summary disposition Util will follow GE recommendations re testing of overspeed protection sys Prof qualifications encl
TURK, E J NRC - No Detailed Affiliation Given * Cleveland Electric Illuminating Co 83/06/24 3pp 19056 195 24X
Fiche 50-440, 83/06/27, 8306290214

H General correspondence

8306030288 Notice of change of counsel address Certificate of Svc encl
LODGE, T J Lodge, T J 83/05/31 1p 18703 357 24X
Fiche 50-440, 83/05/31, 8306030288

8306290144 Ack receipt of 830516 ltr forwarding council Resolution 1443-83 re quality of containment vessel welds Summary rept of 830504 site visit encl Completed rept of review of util commitments expected in Jul 1983
DENTON, H R Office of Nuclear Reactor Regulation, Director 83/06/22 EULERT, O A Perry, OH App 19046 250, 24X
Fiche 50-440, 83/06/22, 8306290144

I Inspection reports, IE Bulletins & correspondence

8306270112 Ack receipt of 830415 ltr Informing NRC of steps taken to correct violations noted in IE Insp Repts 50-440/83-05 & 50-441/83-06
SPESERARD, R L Division of Engineering 83/04/22 EDELMAN, M R Cleveland Electric Illuminating Co 1p 18988 097 24X
Fiche 50-440, 83/04/22, 8306270112

DOCKETED ITEMS

- 8306270115 Responds to NRC 830316 ltr re violations noted in IE Insp Repts 50-440/83-06 & 50-441/83-06. Corrective actions QC in progress written for each concern identified during ILC Comstock Task Force document review
EDELMAN, M R Cleveland Electric Illuminating Co 83/04/15
SPESSARD, R L Division of Engineering 5pp 18788 09B 24X
Fiche 50-440, 83/04/22, 8306270115
- 8306030149 Forwards IE Insp Repts 50-440/83-08 & 50-441/83-07 on 830301-03 & 11 No noncompliance noted
LITTLE, W S Region 3, Office of Director 83/05/16 EDELMAN, M R
Cleveland Electric Illuminating Co 2pp 18704 253 24X
Fiche 50-440, 83/05/16, 8306030149
- 8306030151 IE Insp Repts 50-440/83-08 & 50-441/83-07 on 830301 03 & 11 No noncompliance noted Major areas inspected LK Comstock personnel qualifications, QA/QC & craft personnel & licensee actions on previously identified items
BARRETT, P A, NAIDU, K R, PELKE, P R Region 3, Office of Director 83/05/12 13pp 18704 255 24X Fiche 50-440, 83/05/16, 8306030149
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Wall Logging Device " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461
- 8306160242 Forwards IE Insp Repts 50-440/83-12 & 50-441/83-11 on 830418-22 & notice of violation
LITTLE, W S Region 3, Office of Director 83/06/03 EDELMAN, M R
Cleveland Electric Illuminating Co 2pp 18861 226 24X
Fiche 50-440, 83/06/03, 8306160242
- 8306160254 IE Insp Repts 50-440/83-12 & 50-441/83-11 on 830418-22 Noncompliance noted failure to perform routine monthly insp on stored items
HUNT, M D, MERRIWEATHER, N Region 2, Office of Director
CONLON, Y E Division of Engineering & Radiological Safety Programs 83/05/11 6pp 18861 229 24X Fiche 50-440, 83/06/03, 8306160242
- 8306130299 Ack receipt of 830501 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-440/83-07 & 50-441/83-08
LITTLE, W S Region 3, Office of Director 83/06/08 EDELMAN, M R
Cleveland Electric Illuminating Co 1p 18823 320 24X
Fiche 50-440, 83/06/08, 8306130299
- 8306130305 Responds to NRC 830401 ltr re violations noted in IE Insp Repts 50-440/83-07 & 50-441/83-08. Corrective actions monitoring program consisting of periodic visual exam of suppression pool welds performed from platform
EDELMAN, M R Cleveland Electric Illuminating Co 83/05/31
KEPPLER, J O Region 3, Office of Director 2pp 18823 321 24X
Fiche 50-440, 83/06/08, 8306130299
- 8306230267 Forwards IE Insp Repts 50-440/83-14 & 50-441/83-13 on 830425-28 No noncompliance noted
LITTLE, W S Region 3, Office of Director 83/06/08 EDELMAN, M R
Cleveland Electric Illuminating Co 2pp 18945 086 24X
Fiche 50-440, 83/06/08, 8306230267
- 8306230271 IE Insp Repts 50-440/83-14 & 50-441/83-13 on 830426-20 No noncompliance noted Major areas inspected licensee action on deficiency item, re RCPB piping work activities & review of quality records
WARD, K D, KEATING, D E, DANIELSON, D H Region 3, Office of Director 83/06/07 14pp 18945 088 24X Fiche 50-440, 83/06/08, 8306230267
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 117pp 18930 280 24X Fiche 50-000, 83/06/09, 8305110464
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 116pp 18920 227 24X Fiche 50-000, 83/06/13, 8305110470
- 8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection (ables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010
- 8306000201 Forwards IE Insp Repts 50-440/83-17 & 50-441/83-16 on 830301-0430 No noncompliance noted
KNOP, R C Region 3, Office of Director 83/06/14 EDELMAN, M R
Cleveland Electric Illuminating Co 2pp 19119 359 24X
Fiche 50-440, 83/06/14, 8306000201
- 8306300207 IE Insp Repts 50-440/83-17 & 50-441/83-16 on 830301 0430 No noncompliance noted Major areas inspected safety-related const activities, including 10CFR50.55(e) reportable item followup, housekeeping & preparation for ASD hearings
GILNER, M L, KONKLIN, J L Region 3, Office of Director 83/06/14 4pp 19119 361 24X Fiche 50-440, 83/06/14, 8306300207
- 8306300179 Forwards IE Insp Repts 50-440/83-16 & 50-441/83-15 on 830518-19 No noncompliance noted
KNOP, R C Region 3, Office of Director 83/06/15 EDELMAN, M R
Cleveland Electric Illuminating Co 2pp 19119 263 24X
Fiche 50-440, 83/06/15, 8306300179
- 8306300183 IE Insp Repts 50-440/83-16 & 50-441/83-15 on 830518-19 No noncompliance noted Major areas inspected licensee actions on previous insp findings, 10CFR50.55(e) reportable items & IE bulletins
PELKE, P R, KONKLIN, J E Region 3, Office of Director 83/06/15 4pp 19119 265 24X Fiche 50-440, 83/06/15, 8306300179
- 8306300126 Forwards IE Insp Repts 50-440/83-15 & 50-441/83-14 on 830509-13 No noncompliance noted
LITTLE, W S Region 3, Office of Director 83/06/17 EDELMAN, M R
Cleveland Electric Illuminating Co 2pp 19122 327 24X
Fiche 50-440, 83/06/17, 8306300126
- 8306300172 IE Insp Repts 50-440/83-15 & 50-441/83-14 on 830509-13 No noncompliance noted Major areas inspected safety-related cable tray installation, electrical cables & terminations & equipment installation
MERRIWEATHER, N, CONLON, T I Region 3, Office of Director 83/06/02 4pp 19122 325 24X Fiche 50-440, 83/06/17, 8306300126
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 116pp 19021 177 24X Fiche 50-000, 83/06/22, 8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479
- 8306270283 Ack receipt of 830604 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-440/83-11 & 50-441/83-10
LITTLE, W S Region 3, Office of Director 83/06/23 EDELMAN, M R
Cleveland Electric Illuminating Co 1p 18996 173 24X
Fiche 50-440, 83/06/23, 8306270283
- 8306270287 Responds to NRC 830509 ltr re violations noted in IE Insp Repts 50-440/83-11 & 50-441/83-10 Corrective actions Johnson Controls Procedure OAG-1802 PNPP, "Review & Turnover of Records," revised to reflect present document review
EDELMAN, M R Cleveland Electric Illuminating Co 83/06/09
KEPPLER, J O Region 3, Office of Director 2pp 18996 174 24X
Fiche 50-440, 83/06/23, 8306270283
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

S Reportable occurrences, ILRs & related correspondence

8306100119 Fifth interim deficiency rept re rejection of previously accepted containment vessel radiographs Review of radiographs utilizing film overlay techniques being performed Next rept will be submitted by 830930
EDELMAN, M R Cleveland Electric Illuminating Co 83/05/31
KEPPLER, J G Region 3, Office of Director 1p 18802 02/ 24X
Fiche 50-440, 83/05/31, 8306100119

8306220015 Interim deficiency rept re sensitivity & density variations in Borg-Warner valve radiographs Initially reported on 830411 Sampling plan to determine valve acceptability established Final rept by 830710 Also reported per Part 21
EDELMAN, M R Cleveland Electric Illuminating Co 83/06/10
KEPPLER, J G Region 3, Office of Director 2pp 18927 33U 24X
Fiche 50-440, 83/06/10, 8306220015

8306220058 Final deficiency rept re potentially inadequate cooling of RCIC room during LOCA Initially reported on 830513 AE reviewing RCIC pump/turbine automatic start Review will be completed by 830729 Also reported per Part 21
EDELMAN, M R Cleveland Electric Illuminating Co 83/06/10
KEPPLER, J G Region 3, Office of Director 2pp 18930 03A 24X
Fiche 50-440, 83/06/10, 8306220058

83062200120 Notifies that rework associated w/potentially significant deficiency re governor drive coupling mfg by Transamerica Delaval in standby diesel generators scheduled to be completed by 831031 for Unit 1 & 831231 for Unit 2
EDELMAN, M R Cleveland Electric Illuminating Co 83/06/14
KEPPLER, J G Region 3, Office of Director 1p 18903 329 24X
Fiche 50-440, 83/06/14, 83062200120

8306220039 Suppls final deficiency rept re matl used in Transamerica Delaval, Inc governor drive coupling in standby diesel generator Due to long storage time, governors will be returned to manufacturers for overhauling & recalibr
EDELMAN, M R Cleveland Electric Illuminating Co 83/06/14
KEPPLER, J G Region 3, Office of Director 1p 18930 179 24X
Fiche 50-440, 83/06/14, 8306220039

8306300164 Suppl to 810803 final deficiency rept re Mono-Sol Inland 7-0015-3 COB polyvinyl alcohol film, water soluble purge dam matl mfg by Chis Craft Industries Portions of sys will be flushed prior to fuel loading
EDELMAN, M R Cleveland Electric Illuminating Co 83/06/27
KEPPLER, J G Region 3, Office of Director 3pp 19121 360 24X
Fiche 50-440, 83/06/27, 8306300164

T Hearing transcripts on non-antitrust matters

8306010006 Transcript of 830525 hearing in Painesville, OH Pp 1, 427-1, 436
* Atomic Safety and Licensing Board Panel 83/05/25 21pp
18673 053 24X Fiche 50-440, 83/05/25, 8306010006

8306010010 Transcript of 830526 hearing in Painesville, OH Pp 1, 447-1, 706 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/05/26 314pp
18671 224 24X Fiche 50-440, 83/05/26, 8306010010

8306010004 Transcript of 830527 hearing in Painesville, OH Pp 1, 707-1, 877 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/05/27 176pp
18665 200 24X Fiche 50-440, 83/05/27, 8306010004

8306070149 Transcript of 830531 hearing in Painesville, OH Pp 1, 879-1, 900 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/05/31 127pp
18737 001 24X Fiche 50-440, 83/05/31, 8306070149

DOCKET 50-443 SEABROOK NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8306020039 Notification of 830607 significant licensee meeting w/util & Pullman-Higgins in King of Prussia, PA to discuss performance of site contractor
HOLDEN, C Region 1, Office of Director 83/05/25 Region 1, Office of Director 1p 18702 323 24X Fiche 50-443, 83/05/25, 8306020039

8306010448 Application to amend & renew (PWR-135 & CWR-136, extending const completion dates to 841031 & 851031, respectively)
Factors delaying const listed
JOHNSON, W P Yankee Atomic Electric Co JOHNSON, W P Public Service Co of New Hampshire 83/05/26 DENTON, H R Office of Nuclear Reactor Regulation, Director 1pp 18674 309 24X
Fiche 50-443, 83/05/26, 8306010448

8306240462 Summary of 830511 meeting w/util re basis for projecting fuel load date of Sept 1984 for Unit 1
WHEELER, L Licensing Branch 3 83/06/10 Licensing Branch 3 4pp 18998 005 24X Fiche 50-443, 83/06/10, 8306240462

8306230452 Forwards revised response to NUREG-0612, "Control of Heavy Loads" Rev addresses NRC comments contained in draft technical evaluation rept dtd 821123 & supplemented by NRC 821228 11
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 83/06/20 KNIGHTON, G W Licensing Branch 3 2pp 18941 001 24X Fiche 50-443, 83/06/20, 8306230452

--8306230458 "Response to NRC Generic Request for Addl Info Re NUREG-0612, Control of Heavy Loads"
* United Engineers & Constructors, Inc (subs of Raytheon Co) 9763 006-B-N-5 83/05/31 147pp 18941 004 24X
Fiche 50-443, 83/06/20, 8306230458

E NRC Safety Evaluation Report (SER), supls & correspondence

8306030177 Forwards response to request for addl info re open item in SER, Section 7 J 2 B concerning effects of high temps on ref legs of steam generator & pressurized water level measuring instruments after high energy line breaks
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 83/05/31 KNIGHTON, G W Licensing Branch 3 11pp 18703 313 24X Fiche 50-443, 83/05/31, 8306030177

8306080125 Forwards SER open item response to Chemical Engineering Branch request for addl info re NUREG-0737, Item II B 3, "Post-Accident Sampling Capability" Info supls 821201 response & OL application Amend 4B
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 83/05/31 KNIGHTON, G W Licensing Branch 3 21pp 18772 333 24X Fiche 50-443, 83/05/31, 8306080125

8306200236 Forwards "Containment Ultimate Capacity of Seabrook Station Units 1 & 2 for Internal Pressure Loads," in response to Request for Addl Info RAI 220 37 & SER Section 3 B 1 Rept will be referenced in OL application Amend 49
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 83/06/07 KNIGHTON, G W Licensing Branch 3 2pp 18903 001 24X Fiche 50-443, 83/06/07, 8306200236

--8306200242 "Containment Ultimate Capacity of Seabrook Station Units 1 & 2 for Internal Pressure Loads" W/weight oversize figures Aperture cards are available in PDR
* United Engineers & Constructors, Inc (subs of Raytheon Co) 83/02/28 75pp 18903 003 24X Fiche 50-443, 83/06/07, 8306200242

8306200330 Forwards response to Meteorological & Effluent Treatment Sys Branch draft SER open items, per 830518 meeting request Response will be incorporated in Amend 50 to OL application & FSAR
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 83/06/15 KNIGHTON, G W Licensing Branch 3 3pp 18900 350 24X Fiche 50-443, 83/06/15, 8306200330

8306200397 Forwards supplemental response to SER Section II 5 2 re need for gross radioactivity monitor in svc water sys Response will be incorporated in Amend 50 to OL application & FSAR
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 83/06/15 KNIGHTON, G W Licensing Branch 3 4pp 18899 037 24X Fiche 50-443, 83/06/15, 8306200397

G Adjudicatory correspondence

8306150256 Forwards Suppl 1 to SER (NUREG-0896), addressing two outstanding issues re emergency preparedness & secondary water chemistry Corrected page to NRC 820420 joint affidavit & WT LeFave 830511 affidavit encl w/o SER, LEBBY, R P, PATTERSON, W F Hearing Branch 3 83/05/11 HOYT, H, LUECKE, E A, HARBOUR, J Atomic Safety and Licensing Board Panel, 2pp 18849 191 24X Fiche 50-443, 83/05/11, 8306150256

--8306150259 Affidavit of WT LeFave, detailing corrections to NRC joint affidavit of C Liang, WT LeFave & SR Kirsalis, Paragraphs 9 & 10 re environ qualification of nonsafety-related valves Valves not needed for safe shutdown under LOCA conditions
LEFAVE, W T Auxiliary Systems Branch 83/05/11 2pp 18849-193, 24X Fiche 50-443, 83/05/11, 8306150256

--8306150262 Corrected Paragraphs 9 & 10 to joint affidavit of C Liang, WT LeFave & SR Kirsalis re environ qualification of nonsafety-related valves, filed on 830420
LIANG, C, LEFAVE, W T, KIRSALIS, S B NRC - No Detailed Affidavit Given 83/05/11 1p 18949 195 24X Fiche 50-443, 83/05/11, 8306150256

DOCKETED ITEMS

8306150238 Response opposing New England Coalition on Nuclear Pollution
830912 motion to file out-of-time answer to NRC Affidavit re
environ. qualification of electric valve operators
Unavailability of consultant does not justify late response.
PATTERSON, W F., LESSY, R P. Hearing Branch 3 83/05/24 Atomic
Safety and Licensing Board Panel 5pp 18847 263 24X
Fiche 50-443, 83/05/24, 8306150238

--8306150431 Affidavit of C Liang re environ. qualification of electric
valve operators CS-HCV-189, CS-HCV-190 & RC-V81 Valves not
required to be environmentally qualified since letdown sys;
not in use during post-accident operations
LIANG, C. Reactor Systems Branch 83/05/24 5pp 18847 273 24X
Fiche 50-443, 83/05/24, 8306150238

--8306150437 Affidavit of W T Lafave re electric valve operators
SA-BV-4A/4D Operators not important to safety & do not need
to be environmentally qualified No failure mode of valves
exists due to harsh environ that could affect safe shutdown
LEFAVE, W T. Division of Systems Integration (post 81100%)
83/05/24 3pp 18847 278 24X Fiche 50-443, 83/05/24, 8306150238

8306010342 Objection to ASLB 830511 memorandum & order re Contentions
NH-9 & NH-13 & to rationale for granting of summary
disposition on contentions Order should be reconsidered &
contentions readmitted Certificate of Svc encl
BISBEE, G D. New Hampshire, State of 83/05/24 Atomic Safety and
Licensing Board Panel 7pp 18680 084 24X Fiche 50-443, 83/05/26,
8306010342

8306010382 Petition for directed certification of ASLB summary
disposition dismissing Contention II B 4 on QA for
replacement parts ASLB ruling flagrantly illegal & sets
dangerous precedent
CURRAN, D., JORDAN, W S. New England Coalition on Nuclear Pollution
CURRAN, D. Harmon & Weiss 83/05/26 Atomic Safety and Licensing
Appeal Panel 10pp 18682 160 24X Fiche 50-443, 83/05/26,
8306010382

8306010384 Motion for 3-day extension to 830523 for filing objection to
ASLB 830511 memorandum & order Delay due to unexpected
involvement in federal court litigation
BISBEE, G D. New Hampshire, State of 83/05/26 Atomic Safety and
Licensing Board Panel 1p 18682 170 24X Fiche 50-443, 83/05/26,
8306010384.

8306010444 Appeal of dismissal of Class 9 accident Contention 3 on, in
alternative, request for certification per 10CFR2.718(i)
Issue central to determining whether OL should provide for
mitigating features Certificate of Svc encl
BACKUS, R A. Seacoast Anti-Pollution League 83/05/26 Atomic
Safety and Licensing Appeal Panel 9pp 18674 354 24X
Fiche 50-443, 83/05/26, 8306010444

8306010437 Forwards LL Bishop notice of withdrawal as counsel for
New England Coalition on Nuclear Pollution
CURRAN, D. Hutton & Williams 83/05/27 HOYT, H F. Atomic Safety
and Licensing Board Panel 1p 18679 302 24X
Fiche 50-443, 83/05/27, 8306010437

--8306010443 Notice of withdrawal as counsel for New England Coalition
on Nuclear Pollution Certificate of Svc encl
BISHOP, L L. Hutton & Williams 83/05/26 3pp 18679 303 24X
Fiche 50-443, 83/05/27, 8306010437

8306010446 Forwards, under separate cover, exhibit to New England
Coalition on Nuclear Pollution 830526 petition for directed
certification
CURRAN, D. Harmon & Weiss 83/05/27 ROSENTHAL, A S. Atomic Safety
and Licensing Appeal Panel 1p 18674 326 24X
Fiche 50-443, 83/05/27, 8306010446

8306020169 Requests deferral of responses to applicants motion for
summary disposition of New England Coalition on Nuclear
Pollution Contention I D 2 re reactor trip sys until 20 days
after svc of NUREO-1000, Vol 2
PERLIS, R G. Hearing Branch 3 83/05/31 HOYT, H., LUEBKE, E A.,
HARBUR, J. Atomic Safety and Licensing Board Panel 2pp
18690:361 24X Fiche 50-443, 83/05/31, 8306020169

8306020361 Notice of ASLB Constitution AS Rosenthal, chairman, OJ Liles
& HA Wilber, members
SHOEMAKER, C J. Atomic Safety and Licensing Appeal Panel 83/05/31
1p. 18694 330 24X Fiche: 50-443, 83/05/31, 8306020361

8306030355 Forwards New England Coalition on Nuclear Pollution 830601
objection to applicant twenty-first motion for summary
disposition of Contentions III 2 & III 13. Renotarized
affidavit of PD Herr available upon request
CURRAN, D. Hutton & Williams. CURRAN, D. New England Coalition on
Nuclear Pollution 83/06/01 HOYT, H.F. Atomic Safety and Licensing
Board Panel 1p 18705 215 24X Fiche 50-443, 83/06/01, 8306030355

--8306030357 Objection to applicant twenty-first motion for summary
disposition of Contentions III 2 & III 13 Affidavit of
JA MacDonald insufficient or matter of law to support grant
of summary disposition Statement of mit facts encl
CURRAN, D. New England Coalition on Nuclear Pollution (HUTTON, B
Hutton & Williams 83/06/01 Atomic Safety and Licensing Board
Panel 2pp 18705 216 24X Fiche 50-443, 83/06/01, 8306030355

--8306030363 Affidavit of PD Herr on Contentions III 12 & 13 re
documentation in support of applicant 830214 twenty-first
motion for summary disposition Certificate of Svc encl
HERR, P B. New England Coalition on Nuclear Pollution (HUTTON, B
Massachusetts Institute of Technology 83/05/27 287pp
18705 218 24X Fiche 50-443, 83/06/01, 8306030355

8306070411 Advises that Commonwealth of MA Civil Defense Agency unable
to meet 830601 target date for submission of state area
plan to FEMA New target date is 830815
BHOWELL, J A. Massachusetts, Commonwealth of, 83/06/01 HOYT, H.,
PARIS, O H., LUEBKE, E A. Atomic Safety and Licensing Board Panel
2pp 18742 271 24X Fiche 50-443, 83/06/01, 8306070411

8306080053 Response supporting util motion for summary disposition of
New England Coalition on Nuclear Pollution Contentions
III 12 & III 13 & opposing util motion for summary
disposition of State of NH Contention 21
PERLIS, R G., LESSY, R P. Hearing Branch 3 83/06/06 Atomic
Safety and Licensing Board Panel 8pp 18773 176 24X
Fiche 50-443, 83/06/06, 8306080053

--8306080057 Affidavit of JR Sears Util has not provided info necessary
to comply w/onsite protective measure requirements
Evacuation time estimates accurate & useful Certificate of
Svc encl
SEARS, J R. CP Licensing Branch 83/06/03 7pp 18773 184 24X
Fiche 50-443, 83/06/06, 8306080053

8306080088 Response opposing Seacoast Anti-Pollution League 830511
motion to amend intervention petition by adding new
contention re instrumentation for detection of inadequate
core cooling Motion untimely Certificate of Svc encl
PATTERSON, W F., LESSY, R P. Hearing Branch 3 83/06/06 Atomic
Safety and Licensing Board Panel 8pp 18773 255 24X
Fiche 50-443, 83/06/06, 8306080088

8306080166 Order advising that supplemental answers to util motion for
summary disposition of New England Coalition on Nuclear
Pollution Contention I D 2 due 20 days after svc of Vol 2 of
NRC rept on implications of ATWS incident at Salem
HOYT, H.F. Atomic Safety and Licensing Board Panel 83/06/06 7pp
18772 155 24X Fiche 50-443, 83/06/06, 8306080166

8306080176 Order denying New England Coalition on Nuclear Pollution
830912 motion to file out-of-time answer to NRC Affidavit re
environ. qualification of electric valve operators Issue
decided twice & will not be considered again
HOYT, H.F. Atomic Safety and Licensing Board Panel 83/06/06 2pp
18772 276 24X
Fiche 50-443, 83/06/06, 8306080176

8306080186 Memorandum advising that State of NH 830526 objections to
ASLB 830511 order not filed late Objections will be
considered
HOYT, H.F. Atomic Safety and Licensing Board Panel 83/06/06 3pp
18772 258 24X Fiche 50-443, 83/06/06, 8306080186

8306150387 Response opposing New England Coalition on Nuclear Polluti
petition to ASLB for directed certification of ASLB 830511
memorandum & order dismissing Contention II B 4 Petition
should be dismissed Certificate of Svc encl
DIONAN, T O., QAD, R K. Public Service Co. of New Hampshire
DIONAN, T O. Ropes & Gray 83/06/08 Atomic Safety and Licensing
Appeal Panel 9pp 18847 239 24X Fiche 50-443, 83/06/08,
8306150387

8306150388 Response opposing Seacoast Anti-Pollution League appeal of
dismissal of Class 9 accident contention or alternatively,
request for certification Appeal should be dismissed &
directed certification denied Certificate of Svc encl
DIONAN, T O., QAD, R K. Public Service Co. of New Hampshire
DIONAN, T O. Ropes & Gray 83/06/08 Atomic Safety and Licensing
Appeal Panel 8pp 18847 196 24X Fiche 50-443, 83/06/08,
8306150388

8306150357 Ack receipt of 830601 ltr & encls HA Wilber, not Gentry,
assigned to ASLB
GADPAIN, B A. Atomic Safety and Licensing Appeal Panel 83/06/13
QAD, R.K. Ropes & Gray 1p 18847 267 24X Fiche 50-443, 83/06/13,
8306150357

DOCKETED ITEMS

317

8306200173 Response opposing New England Coalition on Nuclear Pollution & Seacoast Anti-Pollution League petitions for directed certification of ASLR B30511 order Petitioners do not meet requirements for discretionary review w/Certificate of Svc LESSY, R P, PATTERSON, W F, MILLIS, R C Hearing Branch 3 83/06/15 Atomic Safety and Licensing Appeal Panel 28pp 18903 145 24X Fiche 50-443, 83/06/15, 8306200173

8306270256 Expresses concern re draft emergency response plan Draft does not accurately reflect or address emergency response plan for West Newbury Related correspondence CHUTE, M West Newbury, MA 83/06/15 LOMASNEY, M Costello, Lomasney & deNapoli, Inc 3pp 10990 217 24X Fiche 50-443, 83/06/15, 8306270256

8306220077 Requests GJ Humphrey be added to svc list LEWIS, D R Atomic Safety and Licensing Board Panel 83/06/16 Office of the Executive Legal Director 1p 18930 141 24X Fiche 50-443, 83/06/16, 8306220077

8306220085 Deletes R Cashman & adds M Pearson to svc list as town of Amesbury, NH representative LEWIS, D R Atomic Safety and Licensing Board Panel 83/06/16 Office of the Executive Legal Director 1p 18927 101 24X Fiche 50-443, 83/06/16, 8306220085

8306220100 Requests RG Miller be deleted & DR Lewis added to svc list COFFELAND, J C Atomic Safety and Licensing Board Panel 83/06/16 Office of the Executive Legal Director 1p 18927 170 24X Fiche 50-443, 83/06/16, 8306220100

8306220079 Memorandum & order denying Seacoast Anti-Pollution League B30516 motion to amend petition to intervene No good cause shown for late filing Admission of Contention Suppl / would not assist in developing sound record HOYT, H F Atomic Safety and Licensing Board Panel 83/06/17 Seacoast Anti-Pollution League 4pp 18927 183 24X Fiche 50-443, 83/06/20, 8306220079

8306220097 Memorandum & Order ALB-731 dismissing Seacoast Anti-Pollution League (SAPL) appeal of & denying request for certification of portion of ASLR B30511 order granting summary disposition of SAPL Supplemental Contention 3 TOMPKINS, B A Atomic Safety and Licensing Appeal Panel 83/06/20 Seacoast Anti-Pollution League 3pp 18927 016 24X Fiche 50-443, 83/06/20, 8306220097

8306220099 Memorandum & order scheduling 830/13 oral argument in Bethesda, MD re New England Coalition on Nuclear Pollution petition for directed certification of ASLR B30511 order granting summary disposition in Contention 31 B 4 TOMPKINS, B A Atomic Safety and Licensing Appeal Panel 83/06/20 7pp 18926 174 24X Fiche 50-443, 83/06/20, 8306220099

8306270249 Memorandum providing schedule of locations & ASLR anticipated hearing & limited appearance session dates HOYT, H F Atomic Safety and Licensing Board Panel 83/06/22 2pp 10990 217 24X Fiche 50-443, 83/06/22, 8306270249

8306270304 Response opposing State of NH B30526 objections to ASLR B30511 memorandum & order ruling on motions for summary disposition No mods to ASLR conclusions warranted Certificate of Svc encl LESSY, R P, PATTERSON, W F Hearing Branch 3 83/06/22 Atomic Safety and Licensing Board Panel 11pp 18995 208 24X Fiche 50-443, 83/06/22, 8306270304

8306280512 Informs that addl work needed in listed areas of draft emergency plan Traffic & access control point section of plan must be completed so entire draft can be analyzed Related correspondence RTEL, G L Newbury, MA 83/06/22 LOMASNEY, M Costello, Lomasney & deNapoli, Inc 2pp 19018 191 24X Fiche 50-443, 83/06/22, 8306280512

8306270521 Contentions on State of NH radiological emergency response plan Certificate of Svc encl BACKUS, R A Seacoast Anti-Pollution League BACKUS, R A Backus, Shea & Meyer 83/06/22 Atomic Safety and Licensing Board Panel 8pp 19052 324 24X Fiche 50-443, 83/06/22, 8306270521

8306280553 Contentions re emergency planning for State of NH Certificate of Svc encl BELLOTTI, F X Texas, State of 83/06/23 Atomic Safety and Licensing Board Panel 36pp 19018 066 24X Fiche 50-443, 83/06/23, 8306280553

8306280543 Response opposing State of NH B30511 Filing Request for reconsideration of ASLR B30511 memorandum & order should be denied Issue in Contention NH-9 not ripe for litigation Certificate of Svc encl DIGNAN, T G, GAD, R K Public Service Co of New Hampshire DIGNAN, T G Ropes & Gray 83/06/24 Atomic Safety and Licensing Board Panel 16pp 19019 327 24X Fiche 50-443, 83/06/24, 8306280543

8306290532 Errata to Seacoast Anti-Pollution League contentions on State of NH radiological emergency response plan Certificate of Svc encl BACKUS, R A Seacoast Anti-Pollution League BACKUS, R A Backus, Shea & Meyer 83/06/24 Atomic Safety and Licensing Board Panel 3pp 19052 324 24X Fiche 50-443, 83/06/24, 8306290532

8306290556 Contentions on State of NH radiological emergency response plan, Vol 1 Certificate of Svc encl CURRAN, D J, JORDAN, W S New England Coalition on Nuclear Pollution CURRAN, D Harmon & Weiss 83/06/27 Atomic Safety and Licensing Board Panel 24pp 19052 217 24X Fiche 50-443, 83/06/27, 8306290556

G Inspection reports, IE Bulletins & correspondence

8306080259 Addl response to FOIA request for nine separate categories of documents re facilities Forwards documents listed in App A App B documents completely & partially withheld (ref FOIA Exemptions 6 & 7) FELTON, J H Division of Rules and Records 83/04/06 KINDER, E T, New Hampshire, State of App 18790 315 24X Fiche 50-443, 83/04/06, 8306080259

--8306080263 Forwards results of licensee investigation of Pullman-Higgins QC inspector allegations re perceived harassment of QC inspectors from within organization & documentation of organization changes CERNE, A C Region 1, Office of Director 82/07/16 Region 1, Office of Director 7pp 18790 319 24X Fiche 50-443, 83/04/06, 8306080259

--8306080264 Discusses QC inspector concerns within Pullman-Higgins organization (facility piping contractor) re perceived harassment of QC inspectors by P-H const personnel Closure of case recommended CERNE, A C Region 1, Office of Director 82/10/13 Region 1, Office of Director 2pp 18790 326 24X Fiche 50-443, 83/04/06, 8306080259

--8306080266 Discusses Pullman-Higgins (P-H) QC inspector concerns re allegations of harassment of QC inspectors by P-H const personnel Personally identifiable info deleted CERNE, A C Region 1, Office of Director 82/06/09 Region 1, Office of Director 2pp 18790 328 24X Fiche 50-443, 83/04/06, 8306080259

--8306080269 Discusses nonspecific allegations re Pullman-Higgins QA/QC inspectors at facilities Personally identifiable info deleted MATAKAS, R A Region 1, Office of Director 82/07/27 GALLIGR, M Division of Project & Resident Programs 2pp 18790 336 24X Fiche 50-443, 83/04/06, 8306080259

8306010442 Ack receipt of B3050P ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-443/83-02 & 50-444/83-02 STAROSTECKI, R Division of Project & Resident Programs 83/05/25 HARRISON, R J Public Service Co of New Hampshire 1p 18674 302 24X Fiche 50-443, 83/05/25, 8306010442

--8306010449 Responds to NRC B30404 ltr re violations noted in IE Insp Repts 50-443/83-02 & 50-444/83-02 Corrective Actions craft personnel reinducted, QC personnel will monitor safety-related supports & site contractor QA audited DEVINCENIS, J Yankee Atomic Electric Co DEVINCENIS, J Public Service Co of New Hampshire 83/05/02 STAROSTECKI, R Division of Project & Resident Programs 6pp 18674 303 24X Fiche 50-443, 83/05/25, 8306010442

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post B30103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18931 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

DOCKETED ITEMS

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at DWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306230399 Forwards IE Insp Repts 50-443/83-06 & 50-444/83-06 on 830411-0523 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/06/08
HARRISON, R J Public Service Co of New Hampshire 2pp 18743 074 24X Fiche 50-443, 83/06/08, 8306230399

--8306230409 IE Insp Repts 50-443/83-06 & 50-444/83-06 on 830411-0523 No noncompliance noted Major areas inspected licensee action on previously identified insp items & work activities, procedures & records re piping & raceway installation
CERNE, A C, GRAMM, R A Region 1, Office of Director GALL, R M Division of Project & Resident Programs 83/06/07 12pp 18743, 078 24X Fiche 50-443, 83/06/08, 8306230399

8305110444 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 117pp 18930 280 24X Fiche 50-000, 83/06/09, 8305110444

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297, 24X Fiche 50-000, 83/06/24, 8305110483

B Reportable occurrences, LERs & related correspondence

8306170169 Interim deficiency rept re suspected quality of NDE performed at facilities initially reported on 830504 Plan established to reexamine 100% of all readily accessible affected work Next rept by 830831
DEVINCENIIS, J Yankee Atomic Electric Co DEVINCENIIS, J Public Service Co of New Hampshire 83/06/03 STAROSTECKI, R Division of Project & Resident Programs 3pp 18878 329 24X Fiche 50-443, 83/06/03, 8306170169

8306280545 Final deficiency rept re potential for certain Westinghouse gate valves to provide closed indication prior to valve disc fully isolating flow Field change notice issued modifying generic wiring specs
DEVINCENIIS, J, Yankee Atomic Electric Co DEVINCENIIS, J Public Service Co of New Hampshire 83/06/10 STAROSTECKI, R Division of Project & Resident Programs 2pp 17019 325 24X Fiche 50-443, 83/06/10, 8306280545

8306210112 Interim Part 21 rept re adequacy of circulating water pump house structure Analysis & design of needed structural mods for svc water pump house being performed & will be completed by 830819
SARSTEN, G E United Engineers & Constructors, Inc (subs of Raytheon Co) 83/06/17 Director's Office, Office of Inspection and Enforcement 3pp 18914 108 24X Fiche 50-443, 83/06/17, 8306210112

V Operator Examinations

8306140518 Extends invitation to attend 830627 meeting in King of Prussia, PA to discuss transfer of reactor operator licensing function from Bethesda, MD to Region 1 aft
STAROSTECKI, R Division of Project & Resident Programs 83/06/09
HARRISON, R J Public Service Co of New Hampshire 2pp 11880 120 24X Fiche 50-443, 83/06/09, 8306140518

DOCKET 50 444 SEABROOK NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8306020039 Notification of 830607 significant licensee meeting w/utl & Pullman-Higgins in King of Prussia, PA to discuss performance of site contractor
HOLDEN, C Region 1, Office of Director 83/05/25 Region 1, Office of Director 1p 18702 323 24X Fiche 50-443, 83/05/25, 8306020039

8306010448 Application to amend & renew CPR-135 & CPR-136, extending const completion dates to 841031 & 881031, respectively
Factors delaying const listed
JOHNSON, W P Yankee Atomic Electric Co JOHNSON, W P Public Service Co of New Hampshire 83/05/26 BENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 18674 309 24X Fiche 50-443, 83/05/26, 8306010448

8306240462 Summary of 830511 meeting w/utl re basis for projecting fuel load date of Sept 1984 for Unit 1
WHEELER, L Licensing Branch 3 83/06/10 Licensing Branch 7 4pp 18798 005 24X Fiche 50-443, 83/06/10, 8306240462

8306230452 Forwards revised response to NUREG-0612, "Control of Heavy Loads " Rev addresses NRC comments contained in draft technical evaluation rept dtd 821123 & supplemented by NRC 821228 ltr
DEVINCENIIS, J Yankee Atomic Electric Co DEVINCENIIS, J Public Service Co of New Hampshire 83/06/20 KNIGHTON, G W Licensing Branch 3 2pp 18941 001 24X Fiche 50-443, 83/06/20, 8306230452

--8306230458 "Response to NRC Generic Request for Addl Info Re NUREG-0612, Control of Heavy Loads "
* United Engineers & Constructors, Inc (subs of Raytheon Co) 9763 006-S-N-5 83/05/31 147pp 18941 004 24X Fiche 50-443, 83/06/20, 8306230452

E NRC Safety Evaluation Report (SER), supp's & correspondence

8306030177 Forwards response to request for addl info re open item in SER, Section 7 3 2 8 concerning effects of high temps on ref legs of steam generator & pressurized water level measuring instruments after high energy line breaks
DEVINCENIIS, J Yankee Atomic Electric Co DEVINCENIIS, J Public Service Co of New Hampshire 83/05/31 KNIGHTON, G W Licensing Branch 3 11pp 18703 313 24X Fiche 50-443, 83/05/31, 8306030177

8306080125 Forwards SER open item response to Chemical Engineering Branch request for addl info re NUREG-0737, Item II B 3, "Post-Accident Sampling Capability " Info supp's 821201 response & OL application Amend 48
DEVINCENIIS, J Yankee Atomic Electric Co DEVINCENIIS, J Public Service Co of New Hampshire 83/05/31 KNIGHTON, G W Licensing Branch 3 21pp 18772 333 24X Fiche 50-443, 83/05/31, 8306080125

8306200236 Forwards "Containment Ultimate Capacity of Seabrook Station Units 1 & 2 For Internal Pressure Loads," in response to Request for Addl Info RAI 220 37 & SER Section 3 B 1 Rept will be referenced in OL application Amend 49
DEVINCENIIS, J Yankee Atomic Electric Co DEVINCENIIS, J Public Service Co of New Hampshire 83/06/07 KNIGHTON, G W Licensing Branch 3 2pp 18903 001 24X Fiche 50-443, 83/06/07, 8306200236

--8306200242 "Containment Ultimate Capacity of Seabrook Station Units 1 & 2 For Internal Pressure Loads " W/weight oversize figures Aperture cards are available in PDR
* United Engineers & Constructors, Inc (subs of Raytheon Co) 83/02/28 75pp 18903 003 24X Fiche 50-443, 83/06/07, 8306200236

8306200330 Forwards response to Meteorological & Effluent Treatment By: Branch draft SER open items per 830518 meeting request Response will be incorporated in Amend 50 to OL application & FSAR
DEVINCENIIS, J Yankee Atomic Electric Co DEVINCENIIS, J Public Service Co of New Hampshire 83/06/15 KNIGHTON, G W Licensing Branch 3 3pp 18900 350 24X Fiche 50-443, 83/06/15, 8306200330

DOCKETED ITEMS

319

8306200397 Forwards supplemental response to GER Section 11.5.2 re need for gross radioactivity monitor in svc water sys Response will be incorporated in Amend 50 to DL application & FBAR DEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of New Hampshire 83/06/15 KNIGHTON, G. W. Licensing Branch 3 4pp 18699 037 24X Fiche 50-443, 83/06/15, 8306200397

G Adjudicatory correspondence

8306150256 Forwards Suppl 1 to GER (NUREG-0896), addressing two outstanding issues re emergency preparedness & secondary water chemistry. Corrected page to NRC B20420 joint affidavit & WT Lefave 830511 affidavit encl W/o GER LESSY, R. P., PATTERSON, W. F. Hearing Branch 3 83/05/11 HOYT, H., LUEBKE, E. A., HARBOUR, J. Atomic Safety and Licensing Board Panel 2pp 18649 171 24X Fiche 50-443, 83/05/11, 8306150256

--8306150259 Affidavit of WT Lefave, detailing corrections to NRC joint affidavit of C Liang, WT Lefave & SS Kirsliis, Paragraphs 9 & 10 re environ qualification of nonsafety-related valves. Valves not needed for safe shutdown under LOCA conditions. LEFAVE, W. T. Auxiliary Systems Branch 83/05/11 2pp 18649 193 24X Fiche 50-443, 83/05/11, 8306150256

--8306150262 Corrected Paragraphs 9 & 10 to joint affidavit of C Liang, WT Lefave & SS Kirsliis re environ qualification of nonsafety-related valves, filed on 83/04/20 LIANG, C., LEFAVE, W. T., KIRSILIS, S. NRC - No Detailed Affidavit Given 83/05/11 1p 18649 195 24X Fiche 50-443, 83/05/11, 8306150256

8306150238 Response opposing New England Coalition on Nuclear Pollution 830512 motion to file out-of-time answer to NRC affidavit re environ qualification of electric valve operators. Unavailability of consultant does not justify late response. PATTERSON, W. F., LESSY, R. P. Hearing Branch 3 83/05/24 Atomic Safety and Licensing Board Panel 5pp 18647 268 24X Fiche 50-443, 83/05/24, 8306150238

--8306150431 Affidavit of C Liang re environ qualification of electric valve operators. CS-HCV-189, CS-HCV-190 & RC-VB1 Valves not required to be environmentally qualified since letdown sys not in use during post-accident operations. LIANG, C. Reactor Systems Branch 83/05/24 5pp 18647 273 24X Fiche 50-443, 83/05/24, 8306150238

--8306150437 Affidavit of WT Lefave re electric valve operators. SA-BV-4A/4B Operators not important to safety & do not need to be environmentally qualified. No failure mode of valves exists due to harsh environ that could affect safe shutdown. LEFAVE, W. T. Division of Systems Integration (post 811005) 83/05/24 3pp 18647 278 24X Fiche 50-443, 83/05/24, 8306150238

8306010342 Objection to ASLB 830511 memorandum & order re Contentions NH-9 & NH-13 & to rationale for granting of summary disposition on contentions. Order should be reconsidered & contentions readmitted. Certificate of Svc encl. B188EE, O. D. New Hampshire, State of 83/05/26 Atomic Safety and Licensing Board Panel 7pp 18680 084 24X Fiche 50-443, 83/05/26, 8306010342

8306010382 Petition for directed certification of ASLB summary disposition dismissing Contention II D 4 on QA for replacement parts ASLB ruling flagrantly illegal & sets dangerous precedent. CURRAN, D., JORDAN, W. S. New England Coalition on Nuclear Pollution. CURRAN, D., Harmon & Weiss 83/05/26 Atomic Safety and Licensing Appeal Panel 10pp 18682 160 24X Fiche 50-443, 83/05/26, 8306010382

8306010384 Motion for 3-day extension to 830523 for filing objection to ASLB 830511 memorandum & order. Delay due to unexpected involvement in federal court litigation. B188EE, O. D. New Hampshire, State of 83/05/26 Atomic Safety and Licensing Board Panel 1p 18682 170 24X Fiche 50-443, 83/05/26, 8306010384

8306010444 Appeal of dismissal of Class 2 accident Contention 3 or in alternative request for certification per 10CFR2.718(i). Issue central to determining whether DL should provide for mitigating features. Certificate of Svc encl. BACKUS, R. A. Seacoast Anti-Pollution League 83/05/26 Atomic Safety and Licensing Appeal Panel 9pp 18674 354 24X Fiche 50-443, 83/05/26, 8306010444

8306010437 Forwards LL Bishop notice of withdrawal as counsel for New England Coalition on Nuclear Pollution. CURRAN, D., HUNTON & WILLIAMS 83/05/27 HOYT, H. F. Atomic Safety and Licensing Board Panel 1p 18677 302 24X Fiche 50-443, 83/05/27, 8306010437

--8306010443 Notice of withdrawal as counsel for New England Coalition on Nuclear Pollution. Certificate of Svc encl. B18HOP, L. L. HUNTON & WILLIAMS 83/05/26 3pp 18679 303. 24X Fiche 50-443, 83/05/27, 8306010437

8306010446 Forwards, under separate cover, exhibit to New England Coalition on Nuclear Pollution 830526 petition for directed certification. CURRAN, D., Harmon & Weiss 83/05/27 ROSENTHAL, A. S. Atomic Safety and Licensing Appeal Panel 1p 18674 326 24X Fiche 50-443, 83/05/27, 8306010446

8306020169 Requests deferral of responses to applicants motion for summary disposition of New England Coalition on Nuclear Pollution Contention I D 2 re reactor trip sys until 20 days after svc of NUREG-1000, Vol 2. PERLIS, R. O. Hearing Branch 3 83/05/31 HOYT, H., LUEBKE, E. A., HARBOUR, J. Atomic Safety and Licensing Board Panel 2pp 18690 361 24X Fiche 50-443, 83/05/31, 8306020169

8306020261 Notice of ASLB constitution. AS Rosenenthal, chairman, OJ Edles & HA Wilber, members. SHOENAKER, C. J. Atomic Safety and Licensing Appeal Panel 83/05/31 1p 18694 330 24X Fiche 50-443, 83/05/31, 8306020261

8306030355 Forwards New England Coalition on Nuclear Pollution 830601 objection to applicant twenty-first motion for summary disposition of Contentions III 2 & III 13. Renotarized affidavit of PB Herr available upon request. CURRAN, D., HUNTON & WILLIAMS CURRAN, D. New England Coalition on Nuclear Pollution 83/06/01 HOYT, H. F. Atomic Safety and Licensing Board Panel 1p 18705 215 24X Fiche 50-443, 83/06/01, 8306030355

--8306030359 Objection to applicant twenty-first motion for summary disposition of Contentions III 2 & III 13. Affidavit of JA MacDonald insufficient as matter of law to support grant of summary disposition. Statement of mat facts encl. CURRAN, D. New England Coalition on Nuclear Pollution. CURRAN, D., HUNTON & WILLIAMS 83/06/01 Atomic Safety and Licensing Board Panel 2pp 18705 216 24X Fiche 50-443, 83/06/01, 8306030355

--8306030363 Affidavit of PB Herr on Contentions III 12 & 13 re documentation in support of applicant 830214 twenty-first motion for summary disposition. Certificate of Svc encl. HERR, P. B. New England Coalition on Nuclear Pollution. HERR, P. B. Massachusetts Institute of Technology 83/05/27 259pp 18705 218 24X Fiche 50-443, 83/06/01, 8306030355

8306070411 Advises that Commonwealth of MA Civil Defense Agency unable to meet 830601 target date for submission of state area plan to FEMA. New target date is 830815. SHOTWELL, J. A. Massachusetts, Commonwealth of 83/06/01 HOYT, H., PARIB, O. H., LUEBKE, E. A. Atomic Safety and Licensing Board Panel 2pp 18742:271 24X Fiche 50-443, 83/06/01, 8306070411

8306080053 Response supporting util motion for summary disposition of New England Coalition on Nuclear Pollution Contentions III, 12 & III, 13 & opposing util motion for summary disposition of State of NH Contention 21. PERLIS, R. O., LESSY, R. P. Hearing Branch 3 83/06/06 Atomic Safety and Licensing Board Panel 8pp 18773 176 24X Fiche 50-443, 83/06/06, 8306080053

--8306080057 Affidavit of JR Sears. Util has not provided info necessary to comply w/onsite protective measure requirements. Evacuation time estimates accurate & useful. Certificate of Svc encl. SEARSB, J. R. EP Licensing Branch 83/06/03 7pp 18773 184 24X Fiche 50-443, 83/06/06, 8306080053

8306080088 Response opposing Seacoast Anti-Pollution League 830516 motion to amend intervention petition by adding new contention re instrumentation for detection of inadequate core cooling. Motion untimely. Certificate of Svc encl. PATTERSON, W. F., LESSY, R. P. Hearing Branch 3 83/06/06 Atomic Safety and Licensing Board Panel 8pp 18773 255 24X Fiche 50-443, 83/06/06, 8306080088

8306080166 Order advising that supplemental answers to util motion for summary disposition of New England Coalition on Nuclear Pollution Contention I D 2 due 20 days after svc of Vol 2 of NRC rept on implications of ATWS incident at Salem. HOYT, H. F. Atomic Safety and Licensing Board Panel 83/06/06 2pp 18772:155 24X Fiche 50-443, 83/06/06, 8306080166

8306080176 Order denying New England Coalition on Nuclear Pollution 830512 motion to file out-of-time answer to NRC affidavit re environ qualification of electric valve operators. Issue decided twice & will not be considered again. HOYT, H. F. Atomic Safety and Licensing Board Panel 83/06/06 New England Coalition on Nuclear Pollution 2pp 18772 276. 24X Fiche 50-443, 83/06/06, 8306080176

DOCKETED ITEMS

- 8306080186 Memorandum advising that State of NH 830526 objections to ASLB 830511 order not filed late Objections will be considered
HOYT, H F Atomic Safety and Licensing Board Panel 83/06/06 2pp
18772 258 24X Fiche 50-443, 83/06/06, 8306080186
- 8306150387 Response opposing New England Coalition on Nuclear Pollution petition to ASLB for directed certification of ASLB 830511 memorandum & order dismissing Contention II B 4 Petition should be dismissed Certificate of Svc encl
DIOMAN, T O, GAD, R K Public Service Co of New Hampshire
DIOMAN, T O Ropes & Gray 83/06/08 Atomic Safety and Licensing Appeal Panel 7pp 18847 239 24X Fiche 50-443, 83/06/08, 8306150387
- 8306150388 Response opposing Seacoast Anti-Pollution League appeal of dismissal of Class 9 accident contention or, alternatively, request for certification Appeal should be dismissed & directed certification denied Certificate of Svc encl
DIOMAN, T O, GAD, R K Public Service Co of New Hampshire
DIOMAN, T O Ropes & Gray 83/06/08 Atomic Safety and Licensing Appeal Panel 8pp 18847 196 24X Fiche 50-443, 83/06/08, 8306150388
- 8306150357 Ack receipt of 830608 ltr & encls HA Wilber, not Botchy, assigned to ASLB
TOMPKINS, B A Atomic Safety and Licensing Appeal Panel 83/06/13
GAD, R K Ropes & Gray 1p 18847 267 24X Fiche 50-443, 83/06/13, 8306150357
- 8306200173 Response opposing New England Coalition on Nuclear Pollution & Seacoast Anti-Pollution League petitions for directed certification of ASLB 830511 order Petitions do not meet requirements for discretionary review W/Certificate of Svc
LESSBY, R P, PATTERSON, W F, PERLIS, R O Hearing Branch 3 83/06/15 Atomic Safety and Licensing Appeal Panel 28pp 16903 145 24X Fiche 50-443, 83/06/15, 8306200173
- 8306270256 Expresses concern re draft emergency response plan Draft does not accurately reflect or address emergency response plan for West Newbury Related correspondence
CHUTE, M West Newbury, MA 83/06/15 LOMASNEY, M Costello, Lomasney & deNapoli, Inc 5pp 18790 212 24X
Fiche 50-443, 83/06/15, 8306270256
- 8306220077 Requests GJ Humphrey be added to svc list
LEWIS, D R Atomic Safety and Licensing Board Panel 83/06/16
Office of the Executive Legal Director 1p 18730 163 24X
Fiche 50-443, 83/06/16, 8306220077
- 8306220085 Deletes R Cashman & adds M Pearson to svc list as Town of Amesbury, NH representative
LEWIS, D R Atomic Safety and Licensing Board Panel 83/06/16
Office of the Executive Legal Director 1p 18727 181 24X
Fiche 50-443, 83/06/16, 8306220085
- 8306220100 Requests RO Miller be deleted & DR Lewis added to svc list
COPELAND, J E Atomic Safety and Licensing Board Panel 83/06/16
Office of the Executive Legal Director 1p 18727 170 24X
Fiche 50-443, 83/06/16, 8306220100
- 8306220079 Memorandum & order denying Seacoast Anti-Pollution League 830516 motion to amend petition to intervene No good cause shown for late filing Admission of Contention Suppl 7 would not assist in developing sound record
HOYT, H F Atomic Safety and Licensing Board Panel 83/06/20
Seacoast Anti-Pollution League 4pp 18927 183 24X
Fiche 50-443, 83/06/20, 8306220079
- 8306220097 Memorandum & Order ALAB-731 dismissing Seacoast Anti-Pollution League (SAPL) appeal of & denying request for certification of portion of ASLB 830511 order granting summary disposition of SAPL Supplemental Contention 3
TOMPKINS, B A Atomic Safety and Licensing Appeal Panel 83/06/20
Seacoast Anti-Pollution League 3pp 18927 016 24X
Fiche 50-443, 83/06/20, 8306220097
- 8306220099 Memorandum & order scheduling 830713 oral argument in Bethesda, MD re New England Coalition on Nuclear Pollution petition for directed certification of ASLB 830511 order granting summary disposition on Contention II B 4
TOMPKINS, B A Atomic Safety and Licensing Appeal Panel 83/06/20
7pp 18926, 174 24X Fiche 50-443, 83/06/20, 8306220099
- 8306270249 Memorandum providing schedule of locations & ASLB anticipated hearing & limited appearance session dates
HOYT, H F Atomic Safety and Licensing Board Panel 83/06/22 2pp
18990, 217, 24X Fiche 50-443, 83/06/22, 8306270249
- 8306270306 Response opposing State of NH 830526 objections to ASLB 830511 memorandum & order ruling on motions for summary disposition No mods to ASLB conclusions warranted
Certificate of Svc encl
LESSBY, R P, PATTERSON, W F Hearing Branch 3 83/06/22 Atomic Safety and Licensing Board Panel 11pp 18995 208 24X
Fiche 50-443, 83/06/22, 8306270306
- 8306280512 Informs that addl work needed in listed areas of draft emergency plan Traffic & access control point section of plan must be completed so entire draft can be analyzed
Related correspondence
RIEL, G L Newbury, MA 83/06/22 LOMASNEY, M Costello, Lomasney & deNapoli, Inc 2pp 19018 191 24X Fiche 50-443, 83/06/22, 8306280512
- 8306290521 Contentions on State of NH radiological emergency response plan Certificate of Svc encl
BACKUS, R A Seacoast Anti-Pollution League BACKUS, R A Backus, Shea & Meyer 83/06/22 Atomic Safety and Licensing Board Panel 8pp 19052 195 24X Fiche 50-443, 83/06/22, 8306290521
- 8306280553 Contentions re emergency planning for State of NH Certificate of Svc encl
BELLOTTI, F X Texas, State of 83/06/23 Atomic Safety and Licensing Board Panel 36pp 19018 046 24X Fiche 50-443, 83/06/23, 8306280553
- 8306280543 Response opposing State of NH 830511 filing Request for reconsideration of ASLB 830511 memorandum & order should be denied Issue in Contention NH-9 not ripe for litigation
Certificate of Svc encl
DIOMAN, T O, GAD, R K Public Service Co of New Hampshire
DIOMAN, T O Ropes & Gray 83/06/24 Atomic Safety and Licensing Board Panel 16pp 19019 327 24X Fiche 50-443, 83/06/24, 8306280543
- 8306290532 Errata to Seacoast Anti-Pollution League contentions on State of NH radiological emergency response plan Certificate of Svc encl
BACKUS, R A Seacoast Anti-Pollution League BACKUS, R A Backus, Shea & Meyer 83/06/24 Atomic Safety and Licensing Board Panel 5pp 19052 324 24X Fiche 50-443, 83/06/24, 8306290532
- 8306290556 Contentions on State of NH radiological emergency response plan, Vol 1 Certificate of Svc encl
CURRAN, D, JORDAN, H S New England Coalition on Nuclear Pollution
CURRAN, D Harmon & Weiss 83/06/27 Atomic Safety and Licensing Board Panel 24pp 19052 217 24X Fiche 50-443, 83/06/27, 8306290556
- 0 Inspection reports, IE Bulletins & correspondence
- 8306080259 Addl response to FOIA request for nine separate categories of documents re facilities Forwards documents listed in App A App B documents completely & partially withheld (re: PFOIA Exemptions 4 & 7)
FELTON, J M Division of Rules and Records 83/04/06 KING, R I New Hampshire, State of 4pp 18790 315 24X Fiche 50-443, 83/04/06, 8306080259
- 8306080263 Forwards results of licensee investigation of Pullman Higgins QC inspector allegations re perceived harassment of QC inspectors from within organization & documentation of organization changes
CERNE, A C Region 1, Office of Director 82/07/16 Region 1, Office of Director 7pp 18790 319 24X Fiche 50-443, 83/04/06, 8306080259
- 8306080264 Discusses QC inspector concerns within Pullman Higgins organization (facility piping contractor) re perceived harassment of QC inspectors by P-H const personnel Closure of case recommended
CERNE, A C Region 1, Office of Director 82/10/13 Region 1, Office of Director 2pp 18790 326 24X Fiche 50-443, 83/04/06, 8306080259
- 8306080266 Discusses Pullman-Higgins (P-H) QC inspector concerns re allegations of harassment of QC inspectors by P-H const personnel Personally identifiable info deleted
CERNE, A C Region 1, Office of Director 82/04/09 Region 1, Office of Director 2pp 18790 328 24X Fiche 50-443, 83/04/06, 8306080259
- 8306080269 Discusses nonspecific allegations re Pullman-Higgins QA/QC inspectors at facilities Personally identifiable info deleted
MATAKAS, R A Region 1, Office of Director 82/09/27 CALLE, R H Division of Project & Resident Programs 2pp 18790 336 24X Fiche 50-443, 83/04/06, 8306080259

DOCKETED ITEMS

321

8306010442 Ack receipt of 830502 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-443/83-02 & 50-444/83-02
STAROSTECKI, R Division of Project & Resident Programs 83/05/25
HARRISON, R J Public Service Co of New Hampshire 1p 18674 302
24X Fiche 50-443,83/05/25,8306010442

--8306010447 Responds to NRC 830404 ltr re violations noted in IE Insp Repts 50-443/83-02 & 50-444/83-02 Corrective actions craft personnel reinducted. GC personnel will monitor safety-related supports & site contractor QA audited
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 83/05/02 STAROSTECKI, R Division of Project & Resident Programs 3pp 18674 303 24X
Fiche 50-443,83/05/25,8306010447

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000,83/05/26,8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche 50-000,83/05/26,8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at WHRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 200 24X Fiche 50-000,83/05/31,8305110461

8306230397 Forwards IE Insp Repts 50-443/83-06 & 50-444/83-06 on 830411-0523 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/06/08
HARRISON, R J Public Service Co of New Hampshire 2pp 18743 076 24X Fiche 50-443,83/06/08,8306230397

--8306230405 IE Insp Repts 50-443/83-06 & 50-444/83-06 on 830411-0523 No noncompliance noted Major areas inspected licensee action on previously identified insp items & work activities, procedures & records re piping & raceway installation
CERNE, A C, GRAMM, R A Region 1, Office of Director, GALLO, R M Division of Project & Resident Programs 83/06/07 12pp 18743 078 24X Fiche 50-443,83/06/08,8306230397

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fiche 50-000,83/06/09,8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225 24X Fiche 50-000,83/06/13,8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000,83/06/13,8306090010

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 115pp 19021 177 24X Fiche 50-000,83/06/22,8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000,83/06/22,8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000,83/06/23,8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000,83/06/24,8305110483

S Reportable occurrences, LERs & related correspondence

8306170169 Interim deficiency rept re suspected quality of NDE performed at facilities Initially reported on 830504 Plan established to reexamine 100% of all readily accessible affected work Next rept by 830831
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 83/06/03 STAROSTECKI, R Division of Project & Resident Programs 3pp 18878 329 24X
Fiche 50-443,83/06/03,8306170169

8306280545 Final deficiency rept re potential for certain Westinghouse gate valves to provide closed indication prior to valve disc fully isolating flow Field change notice issued modifying generic wiring specs
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 83/06/10 STAROSTECKI, R Division of Project & Resident Programs 2pp 19019 325 24X
Fiche 50-443,83/06/10,8306280545

8306210112 Interim Part 21 rept re adequacy of circulating water pump house structure. Analysis & design of needed structural mods for svc water pump house being performed & will be completed by 830819
SARSTEN, O E United Engineers & Constructors, Inc (subs of Raytheon Co) 83/06/17 Director's Office, Office of Inspection and Enforcement 3pp 18914 108 24X Fiche 50-443,83/06/17,8306210112

V Operator Examinations

8306140518 Extends invitation to attend 830627 meeting in King of Prussia, PA to discuss transfer of reactor operator licensing function from Bethesda, MD to Region 1 ofc
STAROSTECKI, R Division of Project & Resident Programs 83/06/09
HARRISON, R J Public Service Co of New Hampshire 2pp 18838 120 24X Fiche 50-443,83/06/09,8306140518

DOCKET 50-445 COMANCHE PEAK STEAM ELECTRIC STA ,UNIT 1

A Application/construction stage documents & correspondence

8306090162 Forwards table providing description of 830510 Amend 40 to FSAR re administrative controls, environ qualification tables & B&F components
MARSHALL, J B Texas Utilities Services, Inc 83/05/11
BURWELL, S B Division of Licensing 7pp 18792 308 24X
Fiche 50-445,83/05/11,8306090162

8306010392 Forwards, for review, revised page from Chapter 17.1 of FSAR, Change (Amend 40) adds more specific commitment re QA programmer encl NRC 830307 request
QARY, R J Texas Utilities Generating Co 83/05/23 COLLINS, J T Region 4, Office of Director, App 18682 227 24X
Fiche 50-445,83/05/23,8306010392

8306210403 Advises that Benjamin May House not eligible for inclusion in Natl Register of Historic Places Determination of eligibility notification encl
YOUNGBLOOD, B J Licensing Branch 1 83/06/03 QARY, R J Texas Utilities Generating Co 3pp 18926 233 24X Fiche 50-445,83/06/03,8306210403

8306100153 Forwards addl info re environ qualification of safety-related mechanical equipment, in response to Equipment Qualification Branch 830426 request W/six oversite drawings. Aperture cards are available in PDR
MARSHALL, J B Texas Utilities Services, Inc 83/06/07
YOUNGBLOOD, B J Licensing Branch 1 12pp 18801 164 24X
Fiche 50-445,83/06/07,8306100153

8306130193 Forwards audit rept re environ qualification verification of installed equipment per request. No model identification indicated on recombiner, however, ratings info on nameplate sufficient to establish model identify
MARSHALL, J B Texas Utilities Services, Inc 83/06/07
YOUNGBLOOD, B J Licensing Branch 1 5pp 18826 298 24X
Fiche 50-445,83/06/07,8306130193

8306130176 Forwards final response to NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants,"
SCHMIDT, H C Texas Utilities Services, Inc 83/06/08
YOUNGBLOOD, B J Licensing Branch 1 153pp 18828 031 24X
Fiche 50-445,83/06/08,8306130176

8306130279 Submits results of testing program re tube vibration in Westinghouse Model D-4 & D-5 steam generators. Mods to steam generators & feedwater sys required to permit unrestricted operation Mods to begin 830615
SCHMIDT, H C Texas Utilities Services, Inc 83/06/09
YOUNGBLOOD, B J Office of Nuclear Reactor Regulation, Director, 37pp 18824 142 24X Fiche 50-445,83/06/09,8306130279

DOCKETED ITEMS

B306130293 Forwards proprietary "Counterflow Preheat Steam Generator Tube Vibration Summary Repts" & "Counterflow Preheat Steam Tube Expansion Rept" Repts withheld (ref 10CFR2 7.0)
SCHMIDT, H C Texas Utilities Services, Inc 83/06/09
EISENHUT, D G Division of Licensing 2pp 18823 275 24X
Fiche 50-445, 83/06/09, B306130293

B306220170 Notification of B30615 meeting w/util in Bethesda, MD to discuss applicant plans for tube expansion in Model D-4 steam generator Meeting will be closed due to proprietary nature of info to be discussed
BURWELL, S B Licensing Branch 1 83/06/13 YOUNGBLOOD, B J
Licensing Branch 1 3pp 18937 289 24X Fiche 50-445, 83/06/13, B306220170

B306220019 Summary of B30331 meeting w/utills & Westinghouse in Bethesda, MD re Westinghouse analysis & evaluation of D4/D5/E steam generator mod
HOPKINS, J B Licensing Branch 4 83/06/14 Licensing Branch 4
22pp 18908 327 24X Fiche 50-000, 83/06/14, B306220019

B306220177 Summary of B30615 meeting w/util & Westinghouse in Bethesda, MD re applicant plans for tube expansion in Model D-4 steam generators
HOPKINS, J B Licensing Branch 4 83/06/16 Licensing Branch 4
4pp 18937 275 24X Fiche 50-445, 83/06/16, B306220177

B306280392 Advises that info submitted by util on B30610 re response to open items from Equipment Qualification Branch SGR1 is nonproprietary
RAHE, E P Westinghouse Electric Corp 83/06/21 YOUNGBLOOD, B J
Licensing Branch 1 1p 19019 008 24X Fiche 50-445, 83/06/21, B306280392

--B306280400 Forwards addl info re unresolved concerns from seismic & dynamic qualification review of safety-related electrical & mechanical equipment
SCHMIDT, H C Texas Utilities Services, Inc 83/06/10
YOUNGBLOOD, B J Licensing Branch 1 164pp 19019 009 24X
Fiche 50-445, 83/06/21, B306280392

B306300120 Advises that info provided in Texas Utils B30610 ltr re open items from NRC Equipment Qualification Branch SGR1 audit of site not Westinghouse proprietary as originally marked
RAHE, E P Westinghouse Electric Corp 83/06/21 YOUNGBLOOD, B J
Licensing Branch 1 1p 19121 077 24X Fiche 50-445, 83/06/21, B306300120

F Security, medical, emergency & fire protection plans

B306010279 Forwards Rev 4 to physical security plan Rev withheld (ref 10CFR73 21)
CLEMENS, B R Texas Utilities Generating Co 83/05/26 DUNTON, H H
Office of Nuclear Reactor Regulation, Director 1p 18672 236
24X Fiche 50-445, 83/05/26, B306010279

B306150101 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/06/06 Document
Management Branch 1p 18872 121 24X Fiche 50-445, 83/06/06, B306150101

--B306150102 Forwards public version of revised emergency plan implementing procedures, including Procedures EPP-101 re preparation of emergency plan procedures, EPP-20B re control of site access & EPP-210 re evacuation w/o encl
SCHMIDT, H C Texas Utilities Services, Inc 83/05/10
COLLINS, J T Region 4, Office of Director 1p 18872 122 24X
Fiche 50-445, 83/06/06, B306150101

G Adjudicatory correspondence

B306030330 Forwards proposed order reflecting ASLB B30516 ruling re consideration of thermal stresses under ASME Code Order incorporates subsequent ruling re inclusion of support frames in ASME Code definition of supports
REYNOLDS, N B Debevoise & Liberman REYNOLDS, N B Texas Utilities Generating Co 83/06/01 BLOCH, P B, JORDAN, W H, MCCOLLUM, K A
Atomic Safety and Licensing Board Panel 7pp 18708 349 24X
Fiche 50-445, 83/06/01, B306030330

B306070304 Fifteenth set of interrogatories & requests to produce
ELLIS, J Citizens Association for Sound Energy 83/06/04 Texas
Utilities Generating Co 3pp 18740 351 24X Fiche 50-445, 83/06/04, B306070304

--B306070306 Fifth set of interrogatories & requests to produce Certificate of Svc encl
ELLIS, J Citizens Association for Sound Energy 83/06/04
Office of the Executive Legal Director 5pp 18740 354, 24X
Fiche 50-445, 83/06/04, B306070304

B306070382 Forwards motion to reopen record re steam generator upper lateral restraint & J Doyle unexecuted affidavit
ELLIS, J Citizens Association for Sound Energy 83/06/04
BLOCH, P B, JORDAN, W H, MCCOLLUM, K A Atomic Safety and Licensing
Board Panel 1p 18741 312 24X Fiche 50-445, 83/06/04, B306070382

--B306070394 Motion to reopen record re steam generator upper lateral restraint Util should be ordered to supply Citizens Assoc for Sound Energy w/info necessary to determine if problem exists Certificate of Svc encl
ELLIS, J Citizens Association for Sound Energy 83/06/04
Atomic Safety and Licensing Board Panel 8pp 18741 313 24X
Fiche 50-445, 83/06/04, B306070394

B306070350 Order extending time until B30706 for Commission to act to review ALAB-714
CNILK, S J Office of the Secretary of the Commission 83/06/06
Commissioners 1p 18742 066 24X Fiche 50-445, 83/06/06, B306070350

B306080218 Forwards testimony of 1E Const Appraisal Team Insp Repts 50-445/B3-1B & 50-446/B3-12
TREBY, S A Hearing Branch 1 83/06/06 BLOCH, P B, JORDAN, W H, MCCOLLUM, K A
Atomic Safety and Licensing Board Panel 2pp 18771 004 24X Fiche 50-445, 83/06/06, B306080218

--B306080222 Answer to ASLB inquiry re iterative sys for pipe design ASLB need not inquire into subj since iterative sys not issue in controversy Evidence in record sufficient to conclude process & piping adequate
MIZUNO, O S Hearing Branch 1 83/06/06 7pp 18771 006 24X
Fiche 50-445, 83/06/06, B306080218

--B306080224 Testimony of AB Beach, DC Ford, RM Compton & WA Hansen re 1L Const Appraisal Team Insp Repts 50-445/B3-1B & 50-446/B3-12 Changes & corrections to repts listed Prof qualifications encl
BEACH, A B, FORD, D C, COMPTON, R M Director's Office, Office of Inspection and Enforcement 83/06/06 10pp 18771 013 24X
Fiche 50-445, 83/06/06, B306080218

--B306080227 Supplemental affidavit of TG Dunning re NRC consideration of voltage spike or pressure surge in piping sys Adequate analysis of control sys failure safety significance conducted w/o considering voltage spikes or pressure surges.
DUNNING, T G Instrumentation & Control Systems Branch 83/06/06
6pp 18771 023 24X Fiche 50-445, 83/06/06, B306080218

B306080239 Forwards testimony & miscellaneous documents on NRC const appraisal team re
REYNOLDS, N J Debevoise & Liberman REYNOLDS, N J Texas Utilities Generating Co 83/06/06 BLOCH, P B, MCCOLLUM, K A, JORDAN, W H
Atomic Safety and Licensing Board Panel 2pp 18771 115 24X
Fiche 50-445, 83/06/06, B306080239

--B306080241 Testimony of CT Brandt, RO Tolson & A Vega re NRC const appraisal team re
BRANDT, C T, TOLSON, R O, VEGA, A Texas Utilities Generating Co 83/06/06 25pp 18771 117 24X Fiche 50-445, 83/06/06, B306080239

--B306080243 Response to ASLB inquiry re iterative piping design process ASLB should not inquire sua sponte into process since record evidence sufficient No basis exists for further inquiry info as-built verification program
REYNOLDS, N B, HORIN, W A Texas Utilities Generating Co
REYNOLDS, N B Debevoise & Liberman 83/06/06 9pp 18771 135
24X Fiche 50-445, 83/06/06, B306080239

--B306080248 Affidavit of JC Finneran re ASLB inquiries on status of pipe support design verification & unstable support design Approx 86% of pipe supports vendor certified Approx 50% of review process for remaining supports complete
FINNERAN, J C Texas Utilities Generating Co 83/06/03 5pp
18771 151 24X Fiche 50-445, 83/06/06, B306080239

B306100223 Motion for stay of ASLB order re LOCA Record on issue should remain open until ASME Code interpretation received & analyzed
ELLIS, J Citizens Association for Sound Energy 83/06/06 Atomic
Safety and Licensing Board Panel 6pp 18807 163 24X
Fiche 50-445, 83/06/06, B306100223

--B306100230 Affidavit of DH Boltz re interpretation of ASME Code Subsection NF-1121(a) Linguistic analysis presented
BOLTZ, D H Citizens Association for Sound Energy 83/06/05
17pp 18807 169 24X Fiche 50-445, 83/06/06, B306100223

--B306100227 Forwards DH Boltz original signed affidavit w/o encl Certificate of Svc encl
ELLIS, J Citizens Association for Sound Energy 83/06/06
Docketing & Services Branch 3pp 18807 186 24X
Fiche 50-445, 83/06/06, B306100223

DOCKETED ITEMS

323

8306080230 Forwards Region IV 830531 ltr & notice of violation re IE Const Appraisal Team Insp Repts 50-445/83-18 & 50-446/83-12 Ltr omitted from 830606 submittal to ASLB
TREBY, S A Hearing Branch 1 83/06/07 BLOCH, P B, JORDAN, W H, MCCOLLUM, K A Atomic Safety and Licensing Board Panel 6pp
18771 080 24X Fiche 50-445, 83/06/07, 8306080230

8306100118 Confirms 830526 telcon discussing conversation between K Ennis & M Walsh re thermal expansion in piping or pipe supports under accident conditions
TREBY, S A, MIZUNO, G S Hearing Branch 1 83/06/08 ENNIS, K American Society of Mechanical Engineers 2pp 18802 027 24X Fiche 50-445, 83/06/08, 8306100118

8306150310 Notice of DH Boltz appearance in proceeding Certificate of Svc encl
ELLIS, J Citizens Association for Sound Energy 83/06/08 3pp
18849 129 24X Fiche 50-445, 83/06/08, 8306150310

8306150380 Forwards miscellaneous ltrs, exhibits & stipulations re IE Insp Repts 50-445/82-26 & 50-446/82-14 w/o encls
ELLIS, J Citizens Association for Sound Energy 83/06/08 HORNIN, W Debevoise & Liberman 1p 18847 257 24X Fiche 50-445, 83/06/08, 8306150380

8306150307 Motion for admission of new contention re adequacy of emergency planning Somervell County & Hood County commitment, expertise & resources inadequate to adopt & implement emergency plans Certificate of Svc encl
MATHIAS, J Texas, State of 83/06/07 Commissioners 7pp
18849 137 24X Fiche 50-445, 83/06/09, 8306150307

8306150406 Forwards cross-examination documents to assist util & NRC in preparing witnesses for questioning
ELLIS, J Citizens Association for Sound Energy 83/06/09 ROTHSCCHILD, M U Hearing Branch 1 REYNOLDS, N S Debevoise & Liberman REYNOLDS, N S Texas Utilities Generating Co 2pp
18847 126 24X Fiche 50-445, 83/06/09, 8306150406

8306150414 Forwards executed J Doyle 830608 affidavit Unexecuted version encl w/Citizens Assoc for Sound Energy 830604 motion to reopen record re steam generator upper lateral restraint issue
ELLIS, J Citizens Association for Sound Energy 83/06/09 Bookletting & Services Branch 1p 18347 091 24X Fiche 50-445, 83/06/09, 8306150414

--8306150415 Affidavit of J Doyle re need to reopen record on steam generator upper lateral restraint issue
DOYLE, J Citizens Association for Sound Energy 83/06/08 3pp
18847 092 24X Fiche 50-445, 83/06/09, 8306150415

8306150425 Forwards updated Somervell County emergency plan w/ Attachment S & Attachment S to Hood County emergency plan w/o encl
REYNOLDS, N S Debevoise & Liberman REYNOLDS, N S Texas Utilities Generating Co 83/06/09 BLOCH, P B, JORDAN, W H, MCCOLLUM, K A Atomic Safety and Licensing Board Panel 1p 18847 090 24X Fiche 50-445, 83/06/09, 8306150425

8306150366 Response opposing Citizens Assoc for Sound Energy (CASE) 830604 motion to reopen record re upper lateral steam generator support CASE should be admonished for raising new issues premised on speculation Certificate of Svc encl
REYNOLDS, N S, HORNIN, W A Texas Utilities Generating Co HORNIN, W A Debevoise & Liberman 83/06/10 Atomic Safety and Licensing Board Panel 7pp 18847 306 24X Fiche 50-445, 83/06/10, 8306150366

8306150390 Forwards documents to assist NRC in cross-examining util panel consisting of CT Brandt, RO Tolson & A Vega
TREBY, S A Hearing Branch 1 82/06/10 ELLIS, J Citizens Association for Sound Energy REYNOLDS, N S Debevoise & Liberman 1p 18847 029 24X Fiche 50-445, 83/06/10, 8306150390

8306150396 Forwards WP Haass supplemental affidavit re ASLB question on NRC position re application of QA/QC to sys important to safety & response to Citizens Assoc for Sound Energy motion to reopen record on upper lateral restraint issue
ROTHSCCHILD, M U Hearing Branch 1 83/06/10 BLOCH, P B, JORDAN, W H, MCCOLLUM, K A Atomic Safety and Licensing Board Panel 1p 18847 075 24X Fiche 50-445, 83/06/10, 8306150396

--8306150400 Affidavit of WP Haass responding to ASLB 830510 question re NRC position on application of QA/QC to sys important to safety NRC position on Comanche Peak consistent w/NRC position on Shoreham
HAASES, W P QA Branch 83/06/10 3pp 18847 076 24X Fiche 50-445, 83/06/10, 8306150396

--8306150403 Response opposing Citizens Assoc for Sound Energy 830604 motion to reopen record re steam generator upper lateral support issue Assertions re placement of snubbers incorrect Certificate of Svc encl
MIZUNO, G S Hearing Branch 1 83/06/10 Atomic Safety and Licensing Board Panel 6pp 18847 079 24X Fiche 50-445, 83/06/10, 8306150396

8306170406 Answer opposing State of TX 830609 motion for admission of new contention re adequacy of emergency planning Proposed contention lacks requisite specificity & bases for late-filed contentions Certificate of Svc encl
REYNOLDS, N S Texas Utilities Generating Co REYNOLDS, N S Debevoise & Liberman 83/06/12 Atomic Safety and Licensing Board Panel 26pp 18880 018 24X Fiche 50-445, 83/06/12, 8306170406

8306150313 Forwards Secretary of Labor 830610 decision & final order in CA Atchison vs Brown & Root, Inc Certificate of Svc encl
ROTHSCCHILD, M U Hearing Branch 1 83/06/13 BLOCH, P B, JORDAN, W H, MCCOLLUM, K A Atomic Safety and Licensing Board Panel 29pp 18849 099 24X Fiche 50-445, 83/06/13, 8306150313

8306150376 Summary of 830609 telcon w/ASLB & parties re util draft order on thermal stress issue
REYNOLDS, N S Texas Utilities Generating Co REYNOLDS, N S Debevoise & Liberman 83/06/13 6pp 18847 282 24X Fiche 50-445, 83/06/13, 8306150376

8306230381 Forwards Secretary of Labor decision & final order re CA Atchison vs Brown & Root, Inc Decision relevant to pending NRC 830311 petition for Commission review of ALAB-714 W/o encl
ROTHSCCHILD, M U Hearing Branch 1 83/06/20 CHILK, B J Office of the Secretary of the Commission 1p 18943 243 24X Fiche 50-445, 83/06/20, 8306230381

8306280556 Memorandum & order denying State of TX 830609 motion for admission of new contention re adequacy of emergency planning Late filing criteria not met
BLOCH, P B, JORDAN, W H, MCCOLLUM, K A Atomic Safety and Licensing Board Panel 83/06/27 Texas, State of 7pp 19018 016 24X Fiche 50-445, 83/06/27, 8306280556

8306300056 Forwards util 811218 ltr to NRC, responding to ACRB 81117 comments re reactor protection sys, util mgt & organizational capabilities & station operations review committee
TREBY, S A Hearing Branch 1 83/06/28 JORDAN, W H Atomic Safety and Licensing Board Panel 1p 19121 012 24X Fiche 50-445, 83/06/28, 8306300056

M Antitrust correspondence

8306230127 Advises that documents produced by Gulf States Utils Co. in response to NRC subpoena, destroyed
VOGLER, B H Hearing Branch 2 83/06/21 CLEMENTS, D M Gulf States Utilities Co 1p 18947 048 24X Fiche 50-000, 83/06/21, 8306230127

Q Inspection reports, IE Bulletins & correspondence

8306080220 Forwards IE Insp Repts 50-445/83-06 & 50-446/83-03 on 830131-0204 No noncompliance noted
MADSEN, O L Region 4, Office of Director 83/04/14 GARY, R J Texas Utilities Generating Co 2pp 18771 189 24X Fiche 50-445, 83/04/14, 8306080220

--8306080221 IE Insp Repts 50-445/83-06 & 50-446/83-03 on 830131-0204 No noncompliance noted Major areas inspected preoperational environ protection programs, organization & administration, audit, training, procedures & site tour
HOLLEY, W L, MURRAY, B, WESTERMAN, T F Region 4, Office of Director 83/04/12 21pp 18771 191 24X Fiche 50-445, 83/04/14, 8306080220

8306130255 Forwards IE Insp Rept 50-445/83-22 on 830401-30 No noncompliance noted
MADSEN, O L Region 4, Office of Director 83/05/25 GARY, R J Texas Utilities Generating Co 2pp 18824 234 24X Fiche 50-445, 83/05/25, 8306130255

--8306130261 IE Insp Rept 50-445/83-22 on 830401-30 No noncompliance noted Major areas inspected, preoperational test results evaluation, fuel receipt preparation, hot functional test, plant tours & plant status
KELLEY, D L, MCCORDY, S L, WESTERMAN, T F Region 4, Office of Director 83/05/24 8pp 18824 236 24X Fiche 50-445, 83/05/25, 8306130255

8306110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8306110458

DOCKETED ITEMS

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8306140370 Forwards IE Insp Repts 50-445/83-19 & 50-446/83-13 on 830420-22, 25, 27 & 0503-05 No noncompliance noted
MADSEN, G. L. Region 4, Office of Director 83/05/27 GARY, R. J. Texas Utilities Generating Co 2pp 18832 123 24X Fiche 50-445, 83/05/27, 8306140370

--8306140374 IE Insp Repts 50-445/83-19 & 50-446/83-13 on 830420-22, 25, 27 & 0503-05 No noncompliance noted Major areas inspected followup of allegations on protective coatings & review of records for safety-related pipe supports
OILBERT, L. D., JOHNSON, C. E., BESS, J. E. Region 4, Office of Director 83/05/24 9pp 18832 125 24X Fiche 50-445, 83/05/27, 8306140370

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306210105 Discusses Const Appraisal Insp Repts 50-445/83-18 & 50-446/83-12 on 830124-0204 & forwards notice of violation
MADSEN, G. L. Region 4, Office of Director 83/05/31 GARY, R. J. Texas Utilities Generating Co 2pp 18914 206 24X Fiche 50-445, 83/05/31, 8306210105

--8306210110 Notice of violation from insp on 830214-0303 Noncompliance noted failure to provide adequate procedures, instructions or drawing for installation of major items of equipment
* Region 4, Office of Director 83/05/31 3pp 18914 208 24X Fiche 50-445, 83/05/31, 8306210110

8306080230 Forwards Region IV 830531 ltr & notice of violation re IE Const Appraisal Team Insp Repts 50-445/83-18 & 50-446/83-12 Ltr omitted from 830606 submittal to ASLB
TREBY, S. A. Hearing Branch 1 83/06/07, BLOCH, P. B., JORDAN, W. H., MCCOLLUM, K. A. Atomic Safety and Licensing Board Panel 6pp 18771 088 24X Fiche 50-445, 83/06/07, 8306080230

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 118pp 18920 229 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc. 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8306160503 Forwards Westinghouse Procedure ISI-154, "Preservice & Inservice Insp of Reactor Vessels" & plant-specific reactor vessel insp program
MARSHALL, J. B. Texas Utilities Services, Inc 83/06/13 BURBELL, B. B. Division of Licensing 1p 18862, 104 24X Fiche 50-445, 83/06/13, 8306160503

--8306160506 "Reactor Vessel Exam Program "
ADAMONIS, D. C., EFTHYMIU, O. C., JOHNSON, R. M. Texas Utilities Services, Inc 83/05/07 52pp 18862 105 24X Fiche 50-445, 83/06/13, 8306160503

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
* (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 11pp 19021:177 24X Fiche 50-000, 83/06/22, 8305110475

41, "Actuation of Fire Suppression System at Equipment " Svc list

paredness & Engineering
Consolidated Edison Co. of New York, Inc. 50-000, 83/06/22, 8305110477

8305110477 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co. of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110477

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

S Reportable occurrences, LLRs & related correspondence

8306090043 Interim deficiency rept re new fuel storage rack support anchors installed w/o proper authorization Initially reported on 830407 Approved anchoring design implemented No evidence that deficiency is generic
GARY, R. J. Texas Utilities Generating Co 83/05/31 MADSEN, G. L. Region 4, Office of Director 2pp 18793 285 24X Fiche 50-445, 83/05/31, 8306090043

8306130440 Interim deficiency rept re shutdown HX anchors Initially reported on 830709 Evaluation continuing investigation will be completed by 830708
GARY, R. J. Texas Utilities Generating Co 83/06/02 MADSEN, G. L. Region 4, Office of Director 1p 18921 211 24X Fiche 50-445, 83/06/02, 8306130440

8306300055 Final deficiency rept re adhesive bond on Westinghouse NIP (loop power supply) printed circuit cards Initially reported on 830601 Condition not reportable under 10CFR50.55(e)
GARY, R. J. Texas Utilities Generating Co 83/06/21 MADSEN, G. L. Region 4, Office of Director 1p 19121 018 24X Fiche 50-445, 83/06/21, 8306300055

8306300074 Final deficiency rept re Class 1 support matl w/o complete NDE required for NF2500 Initially reported on 830525 Item not reportable under 10CFR50.55(e)
GARY, R. J. Texas Utilities Generating Co 83/06/21 MADSEN, G. L. Region 4, Office of Director 1p 19121 002 24X Fiche 50-445, 83/06/21, 8306300074

8306300088 Final deficiency rept re jam nuts on rigid struts not adequately installed to prevent rotation of strut barrel Initially reported on 830526 Item not reportable under 10CFR50.55(e)
GARY, R. J. Texas Utilities Generating Co 83/06/21 MADSEN, G. L. Region 4, Office of Director 1p 19048 345 24X Fiche 50-445, 83/06/21, 8306300088

8306300167 Deficiency rept re nonsafety-related components in cooling water Class V piping Controls will be added to existing level transmitters by 830801 to sense depletion of surge tank
GARY, R. J. Texas Utilities Generating Co 83/06/21 MADSEN, G. L. Region 4, Office of Director 2pp 19122 065 24X Fiche 50-445, 83/06/21, 8306300167

T Hearing transcripts on non-antitrust matters

8306080218 Forwards testimony of IE Const Appraisal Team Insp Repts 50-445/83-18 & 50-446/83-12
TREBY, S. A. Hearing Branch 1 83/06/06 BLOCH, P. B., JORDAN, W. H., MCCOLLUM, K. A. Atomic Safety and Licensing Board Panel 2pp 18771 004 24X Fiche 50-445, 83/06/06, 8306080218

--8306080224 Testimony of AB Beach, DC Ford, RM Compton & WA Hansen re IE Const Appraisal Team Insp Repts 50-445/83-18 & 50-446/83-12 Changes & corrections to repts listed Prof qualifications encl
BEACH, A. B., FORD, D. C., COMPTON, R. M. Director's Office, Office of Inspection and Enforcement 83/06/06 10pp 18771:013 24X Fiche 50-445, 83/06/06, 8306080218

8306080239 Forwards testimony & miscellaneous documents on NRC const appraisal team rept
REYNOLDS, N. J. Debovoise & Liberman REYNOLDS, N. J. Texas Utilities Generating Co 83/06/06 BLOCH, P. B., MCCOLLUM, K. A., JORDAN, W. H. Atomic Safety and Licensing Board Panel 2pp 18771 115 24X Fiche 50-445, 83/06/06, 8306080239

--8306080241 Testimony of CI Brandt, RO Tolson & A Vega re NRC const appraisal team rept
BRANDT, C. T., TOLSON, R. O., VEGA, A. Texas Utilities Generating Co 83/06/06 25pp 18771 117 24X Fiche 50-445, 83/06/06, 8306080239

8306090013 Transcript of 830607 telephone conference in Bethesda, MD Pp 7, 486-7, 535
* Atomic Safety and Licensing Board Panel 83/06/07 51pp 18793 117 24X Fiche 50-445, 83/06/07, 8306090013

DOCKETED ITEMS

325

B306170286 Transcript of B30613 hearing in Ft Worth, TX Pp 7, 536-7, B09
Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/06/13 273pp
18881 272 24X Fiche 50-445, 83/06/13, B306170286

B306210059 Transcript of B30614 hearing in Fort Worth, TX Pp 7, 810-
8, 079
* Commissioners 83/06/14 267pp 10912 001 24X
Fiche 50-445, 83/06/14, B306210059

B306210117 Transcript of B30615 hearing in Ft Worth, TX Pp B, 08-B, 345
Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/06/15 280pp
18917 146 24X Fiche 50-445, 83/06/15, B306210117

B306210222 Transcript of B30616 hearing in Ft Worth, TX Pp B, 346-B, 619
Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/06/16 282pp
18916 063 24X Fiche 50-445, 83/06/16, B306210222

V Operator Examinations

B306090312 Forwards Rev 1 to Training Manual Procedure TRA-204,
"Licensed Operator Requalification Training Program"
CLEMENTS, D R Texas Utilities Generating Co 83/06/06 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 18795 197
24X Fiche 50-445, 83/06/06, B306090312

--B306090315 Rev 1 to Training Manual Procedure TRA-204, "Licensed
Operator Requalification Training Program"
JONES, R A Texas Utilities Generating Co 83/05/13 27pp
18795 200 24X Fiche 50-445, 83/06/06, B306090312

DOCKET 50-446 COMANCHE PEAK STEAM ELECTRIC STA, UNIT 2

A Application/Construction stage documents & correspondence

B306090162 Forwards table providing description of B30510 Amend 40 to
FSAR re administrative controls, environ qualification tables
& ESF components
MARSHALL, J S Texas Utilities Services, Inc 83/05/11
BURNELL, S B Division of Licensing /pp 18792 308 24X
Fiche 50-445, 83/05/11, B306090162

B306010392 Forwards, for review, revised page from Chapter 17.1 of
FSAR Change (Amend 40) adds more specific commitment re QA
program, per encl NRC B3030/ request
GARY, R J Texas Utilities Generating Co 83/05/23 COLLINS, J T
Region 4, Office of Director 4pp 18682 227 24X
Fiche 50-445, 83/05/23, B306010392

B306210403 Advises that Benjamin May House not eligible for inclusion
in Natl Register of Historic Places Determination of
eligibility notification encl
YOUNGBLOOD, B J Licensing Branch 1 83/06/03 GARY, R J Texas
Utilities Generating Co 5pp 18936 273 24X Fiche 50-445,
83/06/03, B306210403

B306100153 Forwards addl info re environ qualification of
safety-related mechanical equipment, in response to Equipment
Qualification Branch B30426 request W/ix oversize drawings
Aperture cards are available in PDR
MARSHALL, J S Texas Utilities Services, Inc 83/06/07
YOUNGBLOOD, B J Licensing Branch 1 12pp 18801 164 24X
Fiche 50-445, 83/06/07, B306100153

B306130193 Forwards audit rept re environ qualification verification
of installed equipment per request No model identification
indicated on recombimer, however, ratings info on nameplate
sufficient to establish model identify
MARSHALL, J S Texas Utilities Services, Inc, 83/06/07
YOUNGBLOOD, B J Licensing Branch 1 5pp 18826 298 24X
Fiche 50-445, 83/06/07, B306130193

B306130176 Forwards final response to NUREG-0612, "Control of Heavy
Loads at Nuclear Power Plants"
SCHMIDT, H C Texas Utilities Services, Inc 83/06/08
YOUNGBLOOD, B J Licensing Branch 1 153pp 18828 031 24X
Fiche 50-445, 83/06/08, B306130176

B306130279 Submits results of testing program re tube vibration in
Westinghouse Model D-4 & D-5 steam generators. Mods to steam
generators & feedwater sys required to permit unrestricted
operation. Mods to begin B30615
SCHMIDT, H C Texas Utilities Services, Inc 83/06/09
YOUNGBLOOD, B J Office of Nuclear Reactor Regulation, Director,
37pp 18824 142 24X Fiche 50-445, 83/06/09, B306130279

B306130293 Forwards proprietary "Counterflow Preheat Steam Generator
Tube Vibration Summary Repts" & "Counterflow Preheat Steam
Tube Expansion Rept" Repts withheld (ref 10CFR2 790)
SCHMIDT, H C Texas Utilities Services, Inc 83/06/09
EISENHUT, D Q Division of Licensing 2pp 18923 275 24X
Fiche 50-445, 83/06/09, B306130293

B306200019 Summary of B30331 meeting w/utls & Westinghouse in
Bethesda, MD re Westinghouse analysis & evaluation of
D4/D5/E steam generator mod
HOPKINS, J B Licensing Branch 4 83/06/14 Licensing Branch 4
22pp 18908 327 24X Fiche 50-000, 83/06/14, B306200019

B306280392 Advises that info submitted by util on B30610 re response to
open items from Equipment Qualification Branch SORT is
nonproprietary
RAHE, E P Westinghouse Electric Corp 83/06/21 YOUNGBLOOD, B J
Licensing Branch 1 1p 19019 008 24X Fiche 50-445, 83/06/21,
B306280392

--B306280400 Forwards addl info re unresolved concerns from seismic &
dynamic qualification review of safety-related electrical
& mechanical equipment.
SCHMIDT, H C Texas Utilities Services, Inc 83/06/10
YOUNGBLOOD, B J Licensing Branch 1 164pp 19019 009 24X
Fiche 50-445, 83/06/21, B306280392

B306300120 Advises that info provided in Texas Utls B30610 ltr re open
items from NRC Equipment Qualification Branch SORT audit of
site not Westinghouse proprietary as originally marked,
RAHE, E P Westinghouse Electric Corp 83/06/21 YOUNGBLOOD, B J
Licensing Branch 1 1p 19121 077 24X Fiche 50-445, 83/06/21,
B306300120

F Security, medical, emergency & fire protection plans

B306010279 Forwards Rev 4 to physical security plan Rev withheld
(ref 10CFR73 21)
CLEMENTS, D R Texas Utilities Generating Co, 83/05/26 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 18672 235
24X Fiche 50-445, 83/05/26, B306010279

B306150101 Releases public version of revised emergency plan
implementing procedures
FELTON, J M Division of Rules and Records 83/06/06 Document
Management Branch 1p 18872 121 24X Fiche 50-445, 83/06/06,
B306150101

--B306150102 Forwards public version of revised emergency plan
implementing procedures, including Procedures EPP-101 re
preparation of emergency plan procedures, EPP-208 re control
of site access & EPP-210 re evacuation W/o encl.
SCHMIDT, H C Texas Utilities Services, Inc, 83/05/10
COLLINS, J T Region 4, Office of Director, 1p 18872 122, 24X
Fiche 50-445, 83/06/06, B306150101

Q Adjudicatory correspondence

B306030330 Forwards proposed order reflecting ASLB B30516 ruling re
consideration of thermal stresses under ASME Code Order
incorporates subsequent ruling re inclusion of support
frames in ASME Code definition of supports.
REYNOLDS, N S Debevoise & Liberman REYNOLDS, N S Texas Utilities
Generating Co 83/06/01 BLOCH, P B, JORDAN, W H, MCCOLLUM, K A,
Atomic Safety and Licensing Board Panel 7pp 18708 349, 24X
Fiche 50-445, 83/06/01, B306030330

B306070304 Fifteenth set of interrogatories & requests to produce
ELLIS, J Citizens Association for Sound Energy 83/06/04 Texas
Utilities Generating Co 3pp 18740 391, 24X Fiche 50-445,
83/06/04, B306070304

--B306070306 Fifth set of interrogatories & requests to produce
Certificate of Evc encl
ELLIS, J Citizens Association for Sound Energy 83/06/04
Office of the Executive Legal Director 5pp, 18740 354, 24X
Fiche 50-445, 83/06/04, B306070304

B306070382 Forwards motion to reopen record re steam generator upper
lateral restraint & J Doyle unexecuted affidavit
ELLIS, J Citizens Association for Sound Energy, 83/06/04,
BLOCH, P B, JORDAN, W H, MCCOLLUM, K A Atomic Safety and Licensing
Board Panel 1p, 18741 312 24X Fiche 50-445, 83/06/04, B306070382

--B306070394 Motion to reopen record re steam generator upper lateral
restraint Util should be ordered to supply Citizens Assoc
for Sound Energy w/info necessary to determine if problem
exists Certificate of Evc encl.
ELLIS, J Citizens Association for Sound Energy 83/06/04
Atomic Safety and Licensing Board Panel 8pp 18741 313 24X
Fiche 50-445, 83/06/04, B306070382

DOCKETED ITEMS

8306070350 Order extending time until 830706 for Commission to act to review ALAB-714
CHILK, S J Office of the Secretary of the Commission 83/06/06
Commissioners 1p 18742 066 24X Fiche 50-445, 83/06/06, 8306070350

8306080218 Forwards testimony of IE Const Appraisal Team Insp Repts 50-445/82-18 & 50-446/83-12
TREBY, S A Hearing Branch 1 83/06/06 BLOCH, P B, JORDAN, W H, MCCOLLOM, K A Atomic Safety and Licensing Board Panel 2pp 18771 004 24X Fiche 50-445, 83/06/06, 8306080218

--8306080222 Answer to ASLB inquiry re iterative sys for pipe design
ASLB need not inquire into subj since iterative sys not issue in controversy Evidence in record sufficient to conclude process & piping adequate
MIZUNO, O S Hearing Branch 1 83/06/06 7pp 18771 006 24X Fiche 50-445, 83/06/06, 8306080218

--8306080227 Supplemental affidavit of T O Dunning re NRC consideration of voltage spike or pressure surge in piping sys Adequate analysis of control sys failure safety significance conducted w/o considering voltage spikes or pressure surges
DUNNING, T O Instrumentation & Control Systems Branch 83/06/06 6pp 18771 023 24X Fiche 50-445, 83/06/06, 8306080218

8306080239 Forwards testimony & miscellaneous documents on NRC const appraisal team rept
REYNOLDS, N J Debevoise & Liberman REYNOLDS, N J Texas Utilities Generating Co 83/06/06 BLOCH, P B, MCCOLLOM, K A, JORDAN, W H Atomic Safety and Licensing Board Panel 2pp 18771 115 24X Fiche 50-445, 83/06/06, 8306080239

--8306080243 Response to ASLB inquiry re iterative piping design process
ASLB should not inquire sua sponte into process since record evidence sufficient No basis exists for further inquiry into as-built verification program
REYNOLDS, N S, HOKIN, W A Texas Utilities Generating Co REYNOLDS, N S Debevoise & Liberman 83/06/06 9pp 18771 135 24X Fiche: 50-445, 83/06/06, 8306080239

--8306080248 Affidavit of JC Finneran re ASLB inquiries on status of pipe support design verification & unstable support design Approx 85% of pipe supports vendor certified Approx 90% of review process for remaining supports complete
FINNERAN, J C Texas Utilities Generating Co 83/06/06 5pp 18771 151 24X Fiche 50-445, 83/06/06, 8306080239

8306100223 Motion for stay of ASLB order re LOCA Record on issue should remain open until ASME Code interpretation received & analyzed.
ELLIS, J Citizens Association for Sound Energy. 83/06/06 Atomic Safety and Licensing Board Panel 6pp 18807 163 24X Fiche 50-445, 83/06/06, 8306100223

--8306100230 Affidavit of DH Boltz re interpretation of ASME Code Subsection NF-1121(a) Linguistic analysis presented
BOLTZ, D H Citizens Association for Sound Energy 83/06/06 17pp 18807 169 24X Fiche 50-445, 83/06/06, 8306100223

--8306100227 Forwards DH Boltz original signed affidavit w/o encl Certificate of Svc encl
ELLIS, J Citizens Association for Sound Energy 83/06/06 Docketing & Services Branch. 3pp 18807 186 24X Fiche 50-445, 83/06/06, 8306100223

8306080230 Forwards Region IV 830531 ltr & notice of violation re IE Const Appraisal Team Insp Repts 50-445/83-18 & 50-446/83-12 Ltr omitted from 830606 submittal to ASLB
TREBY, S A Hearing Branch 1 83/06/07 BLOCH, P B, JORDAN, W H, MCCOLLOM, K A Atomic Safety and Licensing Board Panel 6pp 18771 088 24X Fiche 50-445, 83/06/07, 8306080230

8306100118 Confirms 830526 telcon discussing conversation between & M Walsh re thermal expansion in piping on pipe under accident conditions
MIZUNO, O S Hearing Branch 1 83/06/08 ENNIS, K Society of Mechanical Engineers 2pp 18802 027 24X 45, 83/06/08, 8306100118

Notice of DH Boltz appearance in proceeding Certificate of Citizens Association for Sound Energy 83/06/08 3pp 24X Fiche: 50-445, 83/06/08, 8306150310.

Forwards miscellaneous ltrs, exhibits & stipulations re IE 50-445/82-26 & 50-446/82-14. W/o encls.
Citizens Association for Sound Energy 83/06/08 HOKIN, W & Liberman 1p 18847 257 24X Fiche 50-445, 83/06/08.

8306150307 Motion for admission of new contention re adequacy of emergency planning Somervell County & Hood County commitment, expertise & resources inadequate to adopt & implement emergency plans Certificate of Svc encl
MATHEWS, J Texas, State of 83/06/09 Commissioners 7pp 18849 13/ 24X Fiche 50-445, 83/06/09, 8306150307

8306150406 Forwards cross-examination documents to assist util & NRC in preparing witnesses for questioning
ELLIS, J Citizens Association for Sound Energy 83/06/09 ROTHCHILD, M U Hearing Branch 1 REYNOLDS, N S Debevoise & Liberman REYNOLDS, N S Texas Utilities Generating Co 2pp 18847 126 24X Fiche 50-445, 83/06/09, 8306150406

8306150414 Forwards executed J Doyle 830608 affidavit Unexecuted version encl w/Citizens Assoc for Sound Energy 830604 motion to reopen record re steam generator upper lateral restraint issue
ELLIS, J Citizens Association for Sound Energy 83/06/09 Docketing & Services Branch 1p 18847 091 24X Fiche 50-445, 83/06/09, 8306150414

--8306150415 Affidavit of J Doyle re need to reopen record on steam generator upper lateral restraint issue
DOYLE, J Citizens Association for Sound Energy 83/06/09 3pp 18847 092 24X Fiche 50-445, 83/06/09, 8306150414

8306150429 Forwards updated Somervell County emergency plan w/ Attachment S & Attachment S to Hood County emergency plan w/o encl
REYNOLDS, N S Debevoise & Liberman REYNOLDS, N S Texas Utilities Generating Co 83/06/09 BLOCH, P B, JORDAN, W H, MCCOLLOM, K A Atomic Safety and Licensing Board Panel 1p 18847 090 24X Fiche 50-445, 83/06/09, 8306150429

8306150366 Response opposing Citizens Assoc for Sound Energy (CASE) 830604 motion to reopen record re upper lateral steam generator support CASE should be admonished for raising new issues premised on speculation Certificate of Svc encl
REYNOLDS, N S, HOKIN, W A Texas Utilities Generating Co HOKIN, W A Debevoise & Liberman 83/06/10 Atomic Safety and Licensing Board Panel 7pp 18847 306 24X Fiche 50-445, 83/06/10, 8306150366

8306150390 Forwards documents to assist NRC in cross-examining util panel consisting of CT Brandt, RG Tolson, & A Vega
TREBY, S A Hearing Branch 1 83/06/10 ELLIS, J Citizens Association for Sound Energy REYNOLDS, N S Debevoise & Liberman 1p 18847 029 24X Fiche 50 445, 83/06/10, 8306150390

8306150396 Forwards WP Haass supplemental affidavit re ASLB question on NRC position re application of QA/QC to sys important to safety & response to Citizens Assoc for Sound Energy motion to reopen record on upper lateral restraint issue
ROTHCHILD, M U Hearing Branch 1 83/06/10 BLOCH, P B, JORDAN, W H, MCCOLLOM, K A Atomic Safety and Licensing Board Panel 1p 18847 075 24X Fiche 50-445, 83/06/10, 8306150396

--8306150400 Affidavit of WP Haass responding to ASLB 830510 question re NRC position on application of QA/QC to sys important to safety NRC position on Comanche Peak consistent w/NRC position on Shoshone
HAASS, W P QA Branch 83/06/10 4pp 18847 076 24X Fiche 50-445, 83/06/10, 8306150396

--8306150403 Response opposing Citizens Assoc for Sound Energy 830604 motion to reopen record re steam generator upper lateral support issue Assertions re placement of snubbers incorrect Certificate of Svc encl
MIZUNO, O S Hearing Branch 1 83/06/10 Atomic Safety and Licensing Board Panel 6pp 18847 079 24X Fiche 50-445, 83/06/10, 8306150396

8306170406 Answer opposing State of TX 830609 motion for admission of new contention re adequacy of emergency planning Proposed contention lacks requisite specificity & bases for late-filed contentions Certificate of Svc encl
REYNOLDS, N S Texas Utilities Generating Co REYNOLDS, N S Debevoise & Liberman 83/06/12 Atomic Safety and Licensing Board Panel 26pp 18880 018 24X Fiche 50-445, 83/06/12, 8306170406

8306150313 Forwards Secretary of Labor 830610 decision & final order in CA Atchison vs Brown & Root, Inc Certificate of Svc encl
ROTHCHILD, M U Hearing Branch 1 83/06/13 BLOCH, P B, JORDAN, W H, MCCOLLOM, K A Atomic Safety and Licensing Board Panel 29pp 18849 099 24X Fiche 50-445, 83/06/13, 8306150313

8306150376 Summary of 830609 telcon w/ASLB & parties re util draft order on thermal stress issue
REYNOLDS, N S Texas Utilities Generating Co REYNOLDS, N S Debevoise & Liberman 83/06/13 6pp 18847 282 24X Fiche 50-445, 83/06/13, 8306150376

DOCKETED ITEMS

327

B306230381 Forwards Secretary of Labor decision & final order re
CA Atchison vs Brown & Root, Inc Decision relevant to
pending NRC B30311 petition for Commission review of
ALAB-714 W/a encl
ROTHSCHILD, M U Hearing Branch 1 B3/06/20 CHILK, S J Office of
the Secretary of the Commission 1p 18943 243 24X
Fiche 50-445, B3/06/20, B306230381

B306280556 Memorandum & order denying State of TX B30609 motion for
admission of new contention re adequacy of emergency
planning Late filing criteria not met
BLUCH, P B, JORDAN, W H, MCCOLLON, K A Atomic Safety and Licensing
Board Panel B3/06/27 Texas, State of 7pp 19018 014 24X
Fiche 50-445, B3/06/27, B306280556

B306300056 Forwards until B11218 ltr to NRC, responding to ACRS B1117
comments re reactor protection sys, util mgt & organizational
capabilities & station operations review committee
TREBY, S A Hearing Branch 1 B3/06/28 JORDAN, W H Atomic Safety
and Licensing Board Panel 1p 19121 012 24X
Fiche 50-445, B3/06/28, B306300056

M Antitrust correspondence

B306230127 Advises that documents produced by Gulf States Utils Co in
response to NRC subpoena, destroyed
VOLLER, B H Hearing Branch 2 B3/06/21 CLEMENTS, D M Gulf States
Utilities Co 1p 18947 048 24X Fiche 50-000, B3/06/21, B306230127

Q Inspection reports, IE Bulletins & correspondence

B306080220 Forwards IE Insp Repts 50-445/B3-06 & 50-446/B3-03 on
B30131-0204 No noncompliance noted
MADSEN, G L Region 4, Office of Director B3/04/14 GARY, R J
Texas Utilities Generating Co 2pp 18771 189 24X
Fiche 50-445, B3/04/14, B306080220

--B306080221 IE Insp Repts 50-445/B3-06 & 50-446/B3-03 on B30131-0204 No
noncompliance noted Major areas inspected preoperational
environ protection programs, organization & administration,
audits, training, procedures & site tour
HOLLEY, W L, MURRAY, B, WESTERMAN, T I Region 4, Office of
Director B3/04/12 21pp 18771 191 24X Fiche 50-445,
B3/04/14, B306080220

B305110458 IE Info Notice B3-32, "Ruptured Am-241 Sources Contained in
Well Logging Device " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post
B30103) B3/05/26 Consolidated Edison Co of New York, Inc
125pp 18831 043 24X Fiche 50-000, B3/05/26, B305110458

B305110460 IE Info Notice B3-34, "Event Notification Info Worksheet "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B3/05/26 Consolidated Edison Co of New
York, Inc 116pp 18732 085 24X Fiche 50-000, B3/05/26, B305110460

B306140370 Forwards IE Insp Repts 50-445/B3-19 & 50-446/B3-13 on
B30420-22, 25, 27 & 0503-05 No noncompliance noted
MADSEN, G L Region 4, Office of Director B3/05/27 GARY, R J
Texas Utilities Generating Co 2pp 18832 123 24X
Fiche 50-445, B3/05/27, B306140370

--B306140374 IE Insp Repts 50-445/B3-19 & 50-446/B3-13 on B30420-22, 25, 27
& 0503-05 No noncompliance noted Major areas inspected
followup of allegations on protective coatings & review of
records for safety-related pipe supports
GILBERT, L D, JOHNSON, C E, BESS, J E Region 4, Office of
Director B3/05/24 9pp 18832 125 24X Fiche 50-445, B3/05/27,
B306140370

B305110461 IE Info Notice B3-35, "Fuel Movement W/Control Rods
Withdrawn at QWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B3/05/31 Consolidated Edison Co of New
York, Inc 116pp 18732 208 24X Fiche 50-000, B3/05/31, B305110461

B306210105 Discusses Const Appraisal Insp Repts 50-445/B3-18
& 50-446/B3-12 on B30124-0204 & Forwards notice of
violation
MADSEN, G L Region 4, Office of Director B3/05/31 GARY, R J
Texas Utilities Generating Co 2pp 18914 206 24X
Fiche 50-445, B3/05/31, B306210105

--B306210110 Notice of violation from insp on B30214-0303 Noncompliance
noted Failure to provide adequate procedures, instructions
or drawing for installation of major items of equipment
* Region 4, Office of Director B3/05/31 3pp 18914 208 24X
Fiche 50-445, B3/05/31, B306210110

B306080230 Forwards Region IV B30531 ltr & notice of violation re IE
Const Appraisal Team Insp Repts 50-445/B3-18 & 50-446/B3-12
Ltr omitted from B30604 submittal to ASLB
TREBY, S A Hearing Branch 1 B3/06/07 BLUCH, P B Atomic Safety
and Licensing Board Panel 4pp 18771 088 24X
Fiche 50-445, B3/06/07, B306080230

B305110464 IE Info Notice B3-36, "Impact of Security Practices on Safe
Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B3/06/09 Consolidated Edison Co of New
York, Inc 119pp 18830 280 24X Fiche 50-000, B3/06/09, B305110464

B305110470 IE Info Notice B3-38, "Defective Heat Sink Adhesive &
Seismically Induced Chatter in Relays Within Printed
Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B3/06/13 Consolidated Edison Co of New
York, Inc 118pp 18920 225 24X Fiche 50-000, B3/06/13, B305110470

B306090010 IE Info Notice B3-37, "Transformer Failure Resulting From
Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B3/06/13 Consolidated Edison Co of New
York, Inc 243pp 18921 001 24X Fiche 50-000, B3/06/13, B306090010

B306160503 Forwards Westinghouse Procedure ISI-154, "Preservice &
Inservice Insp of Reactor Vessels" & plant-specific reactor
vessel insp program
MARSHALL, J B Texas Utilities Services, Inc. B3/06/13
BURWELL, B D Division of Licensing 1p 18862 104 24X
Fiche 50-445, B3/06/13, B306160503

B305110475 IE Info Notice B3-40, "Need to Environmentally Qualify
Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B3/06/22 Consolidated Edison Co of New
York, Inc 115pp 19021 179 24X Fiche 50-000, B3/06/22, B305110475

B305110477 IE Info Notice B3-41, "Actuation of Fire Suppression Sys
Causing Inoperability of Safety-Related Equipment " Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B3/06/22 Consolidated Edison Co of New
York, Inc 120pp 18997 007 24X Fiche 50-000, B3/06/22, B305110477

B305110479 IE Info Notice B3-42, "Reactor Mode Switch Malfunctions "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B3/06/23 Consolidated Edison Co of New
York, Inc 116pp 18976 242 24X Fiche 50-000, B3/06/23, B305110479

B305110483 IE Info Notice B3-43, "Improper Settings of Intermediate
Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B3/06/24 Consolidated Edison Co of New
York, Inc 116pp 19046 297 24X Fiche 50-000, B3/06/24, B305110483

S Reportable occurrences, LERs & related correspondence

B306090043 Interim deficiency rept re new fuel storage rack support
anchors installed w/o proper authorization Initially
reported on B30407 Approved anchoring design implemented.
No evidence that deficiency is generic
GARY, R J Texas Utilities Generating Co. B3/05/31. MADSEN, G L
Region 4, Office of Director 2pp 18793 285 24X
Fiche 50-445, B3/05/31, B306090043

B306130440 Interim deficiency rept re latdown HX anchors Initially
reported on B30709 Evaluation continuing Investigation
will be completed by B30708
GARY, R J Texas Utilities Generating Co B3/06/02. MADSEN, G L
Region 4, Office of Director 1p 18821 211 24X
Fiche 50-445, B3/06/02, B306130440

B306300055 Final deficiency rept re adhesive bond on Westinghouse NLP
(loop power supply) printed circuit cards Initially
reported on B30601 Condition not reportable under
10CFR50.55(e)
GARY, R J Texas Utilities Generating Co. B3/06/21 MADSEN, G L
Region 4, Office of Director 1p 19121 018 24X
Fiche 50-445, B3/06/21, B306300055

B306300074 Final deficiency rept re Class 1 support matl w/o complete
NDE required for NF2500 Initially reported on B30525 Item
not reportable under 10CFR50.55(e).
GARY, R J Texas Utilities Generating Co B3/06/21 MADSEN, G L
Region 4, Office of Director 1p 19121 002 24X
Fiche 50-445, B3/06/21, B306300074

DOCKETED ITEMS

8306300088 Final deficiency rept re jam nuts on rigid struts not adequately installed to prevent rotation of strut barrel Initially reported on 830526 Item not reportable under 10CFR50.55(e).

GARY, R J Texas Utilities Generating Co 83/06/21 MADSEN, G L Region 4, Office of Director 1p 1704B 345 24X Fiche 50-445, 83/06/21, 8306300088

8306300167 Deficiency rept re non-safety-related components in cooling water Class V piping Controls will be added to existing level transmitters by 830801 to sense depletion of surge tank

GARY, R J Texas Utilities Generating Co 83/06/21 MADSEN, G L Region 4, Office of Director 2pp 17122 065 24X Fiche 50-445, 83/06/21, 8306300167

T Hearing transcripts on non-antitrust matters

8306080218 Forwards testimony of IE Const Appraisal Team Insp Repts 50-445/83-18 & 50-446/83-12
TREBY, S A Hearing Branch 1 83/06/06 BLOCH, P B Atomic Safety and Licensing Board Panel 2pp 18771 004 24X Fiche 50-445, 83/06/06, 8306080218

--8306080224 Testimony of AB Beach, DC Ford, RM Compton & WA Hansen re IE Const Appraisal Team Insp Repts 50-445/83-18 & 50-446/83-12 Changes & corrections to repts listed. Prof qualifications encl.

BEACH, A B, FORD, D C, COMPTON, R M Director's Office, Office of Inspection and Enforcement 83/06/06 10pp 18771 013 24X Fiche 50-445, 83/06/06, 8306080218

8306080239 Forwards testimony & miscellaneous documents on NRC const appraisal team rept
REYNOLDS, N J Dubevoise & Liberman. 83/06/06 BLOCH, P B Atomic Safety and Licensing Board Panel 2pp 18771 115 24X Fiche 50-445, 83/06/06, 8306080239

--8306080241 Testimony of CT Brandt, RO Tolson & A Vega re NRC const appraisal team rept
BRANDT, C T, TOLSON, R G, VEGA, A Texas Utilities Generating Co 83/06/06 25pp 18771 117 24X Fiche 50-445, 83/06/06, 8306080239

8306090013 Transcript of 830607 telephone conference in Bethesda, MD Pp 7, 48-7, 335.
* Atomic Safety and Licensing Board Panel 83/06/07 51pp 18793 117 24X Fiche 50-445, 83/06/07, 8306090013

8306170286 Transcript of 830613 hearing in Ft Worth, TX Pp 7, 536-7, 807 Supporting documentation encl.
* Atomic Safety and Licensing Board Panel 83/06/13 273pp 18881 272 24X Fiche 50-445, 83/06/13, 8306170286

8306210059 Transcript of 830614 hearing in Fort Worth, TX Pp 7, 810-8, 079
* Commissioners 83/06/14 269pp 18912 001 24X Fiche 50-445, 83/06/14, 8306210059

8306210119 Transcript of 830615 hearing in Ft Worth, TX Pp 8, 08-B, 345 Supporting documentation encl.
* Atomic Safety and Licensing Board Panel 83/06/15 280pp 18917 146 24X Fiche 50-445, 83/06/15, 8306210119

8306210222 Transcript of 830616 hearing in Ft Worth, TX, Pp 8, 346-B, 617 Supporting documentation encl.
* Atomic Safety and Licensing Board Panel 83/06/16 282pp 18916 063 24X Fiche 50-445, 83/06/16, 8306210222

V Operator Examinations

8306090312 Forwards Rev 1 to Training Manual Procedure TRA-204, "Licensed Operator Requalification Training Program"
CLEMENS, B R Texas Utilities Generating Co 83/06/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18795 199 24X Fiche 50-445, 83/06/06, 8306090312

15 Rev 1 to Training Manual Procedure TRA-204, "Licensed Operator Requalification Training Program."
Texas Utilities Generating Co. 83/05/13 27pp 24X Fiche 50-445, 83/06/06, 8306090312

DOCKET STN-50-447 GESSAR-238

A Application/construction stage documents & correspondence

8306080434 Discusses potential for delays in GESSAR-II severe accident review schedule Hoses for delay was development of source term which would not be completed until Feb 1984 Schedule impacts of up to 8 months could be encountered
SCALETTI, D C Standardization & Special Projects Branch 83/06/02
MIRAGLIA, F J Assistant Director for Safety Assessment 1p 18792 193 24X Fiche 50-447, 83/06/02, 8306080434

8306090236 Forwards draft Amend 17 to OLSAR-II re CP/multi-plant licensing & SRP rules
SHERWOOD, G G General Electric Co 83/06/07 EISENHUT, D G Division of Licensing 125pp 18796 239 24X Fiche 50-447, 83/06/07, 8306090236

8306170214 Forwards supplemental response to Question 410 24 of NRC 820825 response & summary of measures taken in GESSAR-II design to avoid intergranular stress corrosion cracking Info will be included in Amend 18 scheduled for Jul 1983
SHERWOOD, G G General Electric Co 83/06/15 EISENHUT, D G Division of Licensing 8pp 18882 306 24X Fiche 50-447, 83/06/15, 8306170214

K Utility Final Safety Analysis Report (FSAR) & amends

8306070105 Forwards Amend 15 to application for review of Amend 15 to GESSAR-II, consisting of proprietary & nonproprietary portions Proprietary portion withheld (ref 10CFR2 790) & submitted under separate cover
SHERWOOD, G G General Electric Co 83/05/24 EISENHUT, D G Division of Licensing 2pp 18744 246 24X Fiche 50-447, 83/05/24, 8306070105

--8306070111 Amend 15 to application for review of Amend 15 to GESSAR II
SHERWOOD, G G General Electric Co 83/05/24 1p 18744 240 24X Fiche 50-447, 83/05/24, 8306070105

--8306070114 Amend 15 to GESSAR II
* General Electric Co 22A7007 83/05/24 515pp 18744 249 24X Fiche 50-447, 83/05/24, 8306070105

8306070201 Forwards proprietary portion Amend 15 to GESSAR-II re human factors sys analysis emergency procedures Info withheld (ref 10CFR2 790)
SHERWOOD, G G General Electric Co 83/05/24 EISENHUT, D G Division of Licensing 6pp 18747 011 24X Fiche 50-447, 83/05/24, 8306070201

8306290481 Forwards proprietary Amend 16 to GESSAR-II, describing design considerations to reduce sabotage risk Amend withheld (ref 10CFR2 790)
SHERWOOD, G G General Electric Co 83/06/15 EISENHUT, D G Division of Licensing 2pp 19049 277 24X Fiche 50-447, 83/06/15, 8306290481

8306290495 Forwards nonproprietary Amend 16 to GESSAR-II, providing assessment of design features which reduce sabotage risk
SHERWOOD, G G General Electric Co 83/06/15 EISENHUT, D G Division of Licensing 1p 19052 333 24X Fiche 50-447, 83/06/15, 8306290495

--8306290500 Nonproprietary Amend 16 to application for review of GESSAR-II Amend provides assessment of design features which reduce sabotage risk
QUIRK, J F General Electric Co 83/06/15 Division of Licensing 1p 19052 336 24X Fiche 50-447, 83/06/15, 8306290495

--8306290504 Nonproprietary Amend 16 to GESSAR-II, providing assessment of design features which reduce sabotage risk
* General Electric Co 83/06/15 27pp 19052 337 24X Fiche 50-447, 83/06/15, 8306290495

8306290507 Forwards Amend 17 to GESSAR-II, furnishing new App 10 & revised Section 1 B & clarifying discrepancies in text
SHERWOOD, G G General Electric Co 83/06/15 EISENHUT, D G Division of Licensing 1p 19050 011 24X Fiche 50-447, 83/06/15, 8306290507

--8306290512 Amend 17 to GESSAR-II, furnishing new App 10 & revised Section 1 B & clarifying discrepancies in text
QUIRK, J F General Electric Co 83/06/15 Division of Licensing 1p 19050 012 24X Fiche 50-447, 83/06/15, 8306290507

--8306290515 Amend 17 to GESSAR-II, furnishing new App 10 & revised Section 1 B & clarifying discrepancies in text
* General Electric Co 83/06/15 174pp 19050 013 24X Fiche 50-447, 83/06/15, 8306290507

DOCKETED ITEMS

329

G Advisory Committee on Reactor Safeguards reports & correspondence

8306290089 Forwards, for info, ACRS 830615 comments on application for final design approval of GESSAR-II
THOMAS, C D Standardization & Special Projects Branch 83/06/23
SHERWOOD, G G General Electric Co 2pp 19046 173 24X
Fiche 50-447, 83/06/23, 8306290089

--8306290122 Summarizes ACRS 278th meeting on 830609-II re limited review of final design approval of GESSAR-II BWR/6 nuclear island design GESSAR-II design can be incorporated in plants w/valid CP that references PDA in CP application
RAY, J J ACRS - Advisory Committee on Reactor Safeguards 83/06/15
FALLADINO, N J Commissioners 3pp 19046 175 24X
Fiche 50-447, 83/06/23, 8306290089

DOCKET 83N-50-454 BYRON STATION, UNIT 1

A Application/construction stage documents & correspondence

8306030417 Requests info re identification of safety-related mechanical equipment located in harsh environ areas, including required operating times & plant location info requested within 30 days of receipt of ltr
YOUNGBLOOD, B J Licensing Branch 1 83/05/20 FARRAR, D L
Commonwealth Edison Co 3pp 18735 359 24X Fiche 50-000, 83/05/20, 8306030417

8306010019 Summary of 830504 meeting w/util, Westinghouse, Sargent & Lundy & Energy, Inc in Bethesda, MD re design verification programs
OLSHAN, L N Licensing Branch 1 83/05/23 Licensing Branch 1
4pp 18687 171 24X Fiche 50-454, 83/05/23, 8306010019

8306010031 Summary of 830513 meeting w/util, Westinghouse & Sargent & Lundy in Bethesda, MD re review of seismic qualification & pump & valve operability
OLSHAN, L N Licensing Branch 1 83/05/23 Licensing Branch 1
4pp 18687 178 24X Fiche 50-454, 83/05/23, 8306010031

8306030517 Board Notification 83-74 submits info re work stoppage on installation of new pipe whip restraints Stop work action related to deficiencies in applicant QA program Work will resume when upgraded program in place
NOVAK, T M Assistant Director for Licensing 83/05/23 Atomic
Safety and Licensing Board Panel 6pp 18735 054 24X
Fiche 50-454, 83/05/23, 8306030517

8306090194 Discusses util interpretation of 10CFR50.49, "Environ Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants" Intent of rulemaking is to require upgrade program for replacement equipment not parts
FARRAR, D L Commonwealth Edison Co 83/06/03, DENTON, H R Office
of Nuclear Reactor Regulation, Director 3pp 18796 090 24X
Fiche 50-000, 83/06/03, 8306090194

8306200019 Summary of 830331 meeting w/util & Westinghouse in Bethesda, MD re Westinghouse analysis & evaluation of D4/D5/E steam generator mod
HOPKINS, J B Licensing Branch 4 83/06/14 Licensing Branch 4
22pp 18708 327 24X Fiche 50-000, 83/06/14, 8306200019

8306230237 Forwards addl info re use of PORVs for venting & depressurizing RCS at facilities & response to FSAR Question 212 159, to be incorporated into future FSAR amend
TRAHM, T R Commonwealth Edison Co 83/06/16 DENTON, H R Office
of Nuclear Reactor Regulation, Director 18pp 18745 235 24X
Fiche 50-000, 83/06/16, 8306230237

8306240379 Summary of Caseload Forecast Panel 830324-25 meetings w/util in Ogle County, IL re independent assessment of applicant fuel load date of 830831 Fuel load will not occur earlier than Nov 1983
OLSHAN, L N Licensing Branch 1 83/06/17 Licensing Branch 1
75pp 18787 059 24X Fiche 50-454, 83/06/17, 8306240379

8306270322 Provides addl details re control of heavy loads during const when new fuel assemblies being stored in spent fuel pit Due to failure of reactor coolant pump at Byron 1, fuel handling bldg crane will be installed
TRAHM, T R Commonwealth Edison Co 83/06/17 DENTON, H R Office
of Nuclear Reactor Regulation, Director 1p 18794 073 24X
Fiche 50-000, 83/06/17, 8306270322

8306240252 Reviews estimated fuel load dates to Oct 1983 for LaSalle County & Dec 1983 & May 1985 for Byron Units 1 & 2, respectively
STIEDE, W L Commonwealth Edison Co 83/06/21 DENTON, H R Office
of Nuclear Reactor Regulation, Director 1p 18781 323 24X
Fiche 50-000, 83/06/21, 8306240252

8306270373 Notifies of change in FSAR distribution All nuclear power plant activities transferred to new IL Dept of Nuclear Safety State copy of FSAR amend should be sent to listed address
TRAHM, T R Commonwealth Edison Co 83/06/21 DENTON, H R Office
of Nuclear Reactor Regulation, Director 1p 18793 313 24X
Fiche 50-000, 83/06/21, 8306270373

8306300032 Reviews estimated fuel load dates, based on const activity & preoperational testing budget review Fuel load scheduled for 831001, Dec 1983 & May 1985 for LaSalle County Unit 2 & Byron Units 1 & 2, respectively
STIEDE, W L Commonwealth Edison Co 83/06/21 KEPLER, J R Region
3, Office of Director 1p 19120 311 24X Fiche 50-000, 83/06/21, 8306300032

E NRC Safety Evaluation Report (SER), supp's & correspondence

8306220001 Forwards addl info re seismic design basis for river screenhouse Review of info should help close Confirmatory Issue 1 of SER Values presented in FSAR are reasonable for mats underlying river screenhouse
TRAHM, T R Commonwealth Edison Co 83/06/15 DENTON, H R Office
of Nuclear Reactor Regulation, Director 15pp 18928 063 24X
Fiche 50-454, 83/06/15, 8306220001

8306270431 Forwards advance copy of rev to Section E 17 of App E to FSAR Section describes safety parameter display sys. Info should close SER Outstanding Item 16.
TRAHM, T R Commonwealth Edison Co 83/06/17 DENTON, H R Office
of Nuclear Reactor Regulation, Director 13pp 19345 353 24X
Fiche 50-000, 83/06/17, 8306270431

8306240070 Requests addl info re moisture separators of heaters in filter sys serving nonaccessible area & fuel handling bldg for SER review Info requested within 30 days to maintain review schedule
YOUNGBLOOD, B J Licensing Branch 1 83/06/21 FARRAR, D L
Commonwealth Edison Co 3pp 18785 028 24X Fiche 50-000, 83/06/21, 8306240070

F Security, medical, emergency & fire protection plans

8306090247 Confirms 830601 telcon re changes to exercise windows for Dresden & Byron Nuclear Power Stations Dresden partial exercise will be conducted during wk of 830912 w/Byron Full-scale exercise beginning wk of 831114
JONES, E E Illinois, State of, 83/06/01 KEPLER, J, Region 3,
Office of Director 1p 18795 319 24X Fiche 50-000, 83/06/01, 8306090247

8306090221 Forwards current versions of all prefire plans, per requirements of 10CFR50, App R, Paragraph 3 K 12 Plans will be continually revised & future revs will not be formally submitted unless specifically requested
TRAHM, T R Commonwealth Edison Co 83/06/02 DENTON, H R Office
of Nuclear Reactor Regulation, Director 1p 18796 119 24X
Fiche 50-454, 83/06/02, 8306090221

--8306090223 Prefire plans
* Commonwealth Edison Co 83/05/18 113pp 18796 120 24X
Fiche 50-454, 83/06/02, 8306090221

8306160214 Submits correction to 830601 ltr Date of reassessment will be made prior to 830801, not 831001
JONES, E E Illinois, State of 83/06/09 KEPLER, J, Region 3,
Office of Director 1p 18861 358 24X Fiche 50-000, 83/06/09, 8306160214

8306230257 Forwards addl info on communications & cable spreading room suppression sys re fire protection program Third radio communication channel being installed. Repeater will be located in turbine bldg.
TRAHM, T R Commonwealth Edison Co 83/06/17 DENTON, H R Office
of Nuclear Reactor Regulation, Director 5pp 18745 016 24X
Fiche 50-000, 83/06/17, 8306230257

8306230412 Provides addl info requested in NRC 830411 ltr re instrumentation used to assure safe shutdown in event of fire Info will be incorporated into FSAR & fire protection rept in future amends
TRAHM, T R Commonwealth Edison Co 83/06/17 DENTON, H R Office
of Nuclear Reactor Regulation, Director 52pp 18943 136 24X
Fiche 50-000, 83/06/17, 8306230412

DOCKETED ITEMS

Q Adjudicatory correspondence

8306010457 Forwards marked-up Joint Intervenor Exhibit 14 re radiological emergency response survey Ambulance medical svcs, indicating stricken portions per ASLB 830426 ruling encl Certificate of Svc encl
COPELAND, V G Isham, Lincoln & Beale COPELAND, V G Commonwealth Edison Co 83/05/26 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 24pp 18674 328 24X
Fiche 50-454, 83/05/26, 8306010457

8306020437 Forwards Rockford League of Women Voters proposed findings of fact & conclusions of law re Contention 106 on seismology, per 820818 stipulation
THOMAS, D C Illinois Institute of Technology. 83/05/31
SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 12pp 18693 228 24X Fiche 50-454, 83/05/31, 8306020437

8306060193 Forwards proposed findings of fact & conclusions of law re seismology, water hammer & ALARA Final agreement not reached re procedural history
COPELAND, V G Isham, Lincoln & Beale COPELAND, V G Commonwealth Edison Co 83/05/31 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 2pp 18718 261 24X
Fiche 50-454, 83/05/31, 8306060193

--8306060196 Proposed findings of fact & conclusions of law re seismology, water hammer & ALARA
MILLER, M I, BIELAWSKI, A P, COPELAND, V G Commonwealth Edison Co 83/05/31. 104pp 18718 263 24X Fiche 50-454, 83/05/31, 8306060193

8306080143 Forwards proposed findings of fact & conclusions of law on Contention 9a re water hammer
CHAVEZ, D Binnississippi Alliance for the Environment (SAFE)
CHAVEZ, D DeKalb Area Alliance for Responsible Energy 83/05/31
Atomic Safety and Licensing Board Panel 1p 18772 290 24X
Fiche 50-454, 83/05/31, 8306080143

--8306080145 Proposed findings of fact & conclusions of law on Contention 9a re water hammer.
* Binnississippi Alliance for the Environment (SAFE) * DeKalb Area Alliance for Responsible Energy 83/05/31 19pp 18772 291 24X
Fiche 50-454, 83/05/31, 8306080143

8306060286 Requests delay of plant licensing & operation until design, QA, waste disposal & emergency procedure problems resolved
PULIDO, M Affiliation Unknown 83/06/03 SMITH, I W Atomic Safety and Licensing Board Panel 1p 18729 038 24X
Fiche 50-454, 83/06/03, 8306060286

8306060302 Complaint filed in Circuit Court of Seventeenth Judicial Circuit, Winnebago County, IL requesting imposition of punitive damages for wrongful diversion of waste water onto plaintiff's property
FEARER, W P Motor Oils Refining Co FEARER, W P Fearer & Nye 83/06/03 Illinois, State of 5pp. 18729 097 24X
Fiche 50-454, 83/06/03, 8306060302

8306090342 Supplementary memorandum opposing intervenor motion to reopen record Neither triable issue nor significant safety issue exists re Hughes allegations Certificate of Svc encl
BECKER, B D Commonwealth Edison Co 83/06/07 Atomic Safety and Licensing Board Panel 12pp. 18794 322 24X Fiche 50-454, 83/06/07, 8306090342

8306100201 Brief supporting motion to admit J Hughes testimony
Intervenor has raised serious & significant safety issues re quality of work at plant Hughes testimony should be considered in ruling on Contention 1A w/ Certificate of Svc
WHICHER, J M League of Women Voters of Rockford, IL. WHICHER, J M DeKalb Area Alliance for Responsible Energy. WHICHER, J M Binnississippi Alliance for the Environment (SAFE) 83/06/07. Atomic Safety and Licensing Board Panel 21pp 18805 230 24X
Fiche 50-454, 83/06/07, 8306100201

8306130445 Forwards proposed findings of fact & conclusions of law re steam generator tube integrity Document should be filed w/830531 proposed findings re seismology, water hammer & ALARA
GOLDFEIN, M R Isham, Lincoln & Beale GOLDFEIN, M R Commonwealth Edison Co. 83/06/07. SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 2pp 18820 319. 24X
Fiche 50-454, 83/06/07, 8306130445

--8306130452 Proposed findings of fact & conclusions of law re steam generator tube integrity Certificate of Svc encl
GALLD, J, GOLDFEIN, M R. Commonwealth Edison Co GALLD, J Isham, Lincoln & Beale. 83/06/07 64pp 18820 321 24X
Fiche 50-454, 83/06/07, 8306130445

8306150402 Informs that radiological emergency exercise moved to wk of 831114, to accommodate Illinois Emergency Svcs & Disaster Agency Svc list encl
BIELAWSKI, A P Isham, Lincoln & Beale BIELAWSKI, A P Commonwealth Edison Co 83/06/07 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 3pp 18847 129 24X
Fiche 50-454, 83/06/07, 8306150402

8306150420 Forwards motion for & amend to consolidate DeKalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ Contention 3 w/Rockford League of Women Voters Contentions 19 & 108
BIELAWSKI, A P Isham, Lincoln & Beale BIELAWSKI, A P Commonwealth Edison Co 83/06/07 Office of the Secretary of the Commission 2pp 18847 095 24X Fiche 50-454, 83/06/07, 8306150420

--8306150436 Motion to amend & consolidate DeKalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ Contention 3 w/Rockford League of Women Voters Contentions 19 & 108
CHAVEZ, D DeKalb Area Alliance for Responsible Energy (SAFE) MORRISON, P Binnississippi Alliance for the Environment (SAFE) MORRISON, P League of Women Voters of Rockford, IL 83/02/21 Atomic Safety and Licensing Board Panel 4pp 18847 097 24X
Fiche 50-454, 83/06/07, 8306150420

--8306150442 Amend & consolidation of DeKalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ Contention 3 & Rockford League of Women Voters Contentions 19 & 108
CHAVEZ, D DeKalb Area Alliance for Responsible Energy (SAFE) MORRISON, P Binnississippi Alliance for the Environment (SAFE) MORRISON, P League of Women Voters of Rockford, IL 83/02/21 Atomic Safety and Licensing Board Panel 8pp 18847 101 24X
Fiche 50-454, 83/06/07, 8306150420

8306150408 Notifies that pending review of NRC-commissioned study of current sabotage problems at nuclear power plants, intervenor may move to reopen evidentiary record to consider ramifications of study Svc list encl
THOMAS, D C Illinois Institute of Technology THOMAS, D C Affiliation Unknown 83/06/07 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 3pp 18847 118 24X
Fiche 50-454, 83/06/07, 8306150408

8306200300 Reply opposing Rockford League of Women Voters proposed findings of fact & conclusions of law re seismology Certificate of Svc encl
GOLDFEIN, M R Commonwealth Edison Co GOLDFEIN, M R Isham, Lincoln & Beale 83/06/09 10pp 18700 176 24X Fiche 50-454, 83/06/09, 8306200300

8306200304 Forwards until reply to Rockford League of Women Voters proposed findings of fact & conclusions of law re seismology Related correspondence w/o encl.
COPELAND, V G Isham, Lincoln & Beale COPELAND, V G Commonwealth Edison Co 83/06/09 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 2pp 18700 170 24X
Fiche 50-454, 83/06/09, 8306200304

8306130361 Proposed findings of fact & conclusions of law in form of partial initial decision on seismology & water hammer
issues Certificate of Svc encl
GOLDBERG, S C Hearing Branch 4 83/06/10 37pp 18822 114 24X
Fiche 50-454, 83/06/10, 8306130361

8306170371 Forwards NRC 830531 ltr transmitting IE Insp Rept 50-454/83-16 & notice of violation Rept supports intervenor position that until unwillling or unable to maintain effective QA/QC program Svc list encl
WHICHER, J M Businessmen for the Public Interest WHICHER, J M League of Women Voters of Rockford, IL. WHICHER, J M Binnississippi Alliance for the Environment (SAFE) 83/06/16 SMITH, I W, CALLIHAN, A D, COLE, R F Atomic Safety and Licensing Board Panel 17pp 18880 294 24X Fiche 50-454, 83/06/16, 8306170371

8306150318 Proposed findings of fact & conclusions of law in form of supplemental partial initial decision on occupational radiation safety & steam generator issues Certificate of Svc encl.
GOLDBERG, S C Hearing Branch 4 RAWSON, R J Hearing Branch 3 83/06/14 120pp 18848 328 24X Fiche 50-454, 83/06/14, 8306150318

8306170378 Advises that NRC will not reply to party 830607 supplemental briefs re intervenor 830427 motion to reopen record NRC position already matter of record
GOLDBERG, S C Hearing Branch 4 83/06/14 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 2pp 18880 248 24X Fiche 50-454, 83/06/14, 8306170378

DOCKETED ITEMS

3

--8306170384 Confirms that JM Whicher will represent J Hughes, former employee of Pittsburgh Testing Labs, per 830427 telcon NRC should not contact Hughes directly Hughes statement, prepared by Region III, requested
WHICHER, J M Businessmen for the Public Interest 83/04/28
LEWIS, S H Region 3, Office of Director 2pp 18880 250 24X
Fiche 50-454, 83/06/14, 8306170378

--8306170389 Advises that author will represent J Hughes, former employee of Pittsburgh Testing Labs & requests Hughes Jan 1983 statements to NRC & documents provided to NRC
WHICHER, J M Businessmen for the Public Interest 83/04/28
PAWLICK, E Region 3, Office of Director 2pp 18880 252 24X
Fiche 50-454, 83/06/14, 8306170378

--8306170392 Responds to 830428 ltr & transmits JM Hughes 830119 statements Other matl/documents being used in ongoing investigation & cannot be provided
PAWLICK, E T Region 3, Office of Director 83/05/13 WHICHER, J
Businessmen for the Public Interest 1p 18880 254 24X
Fiche 50-454, 83/06/14, 8306170378

8306200320 Proposed findings of fact & conclusions of law re ALARA & steam generator tube integrity
THOMAS, D C League of Women Voters of Rockford, IL THOMAS, D C
Thomas, D C 83/06/14 32pp 18899 173 24X Fiche 50-454,
83/06/14, 8306200320

--8306200327 Motion for extension until 830628 to file proposed findings of fact & conclusions of law re Contentions 22 & 9(c)
THOMAS, D C League of Women Voters of Rockford, IL THOMAS, D C
DeKalb Area Alliance for Responsible Energy THOMAS, D C
Sinnissippi Alliance for the Environment (SAFE) 83/06/14
Atomic Safety and Licensing Board Panel 1p 18899 205 24X
Fiche 50-454, 83/06/14, 8306200320

--8306200331 Affidavit of DC Thomas supporting extension until 830628 to file proposed findings of fact & conclusions of law re Contentions 22 & 9(c) Time needed due to heavy trial & teaching schedule Certificate of Svc encl
THOMAS, D C League of Women Voters of Rockford, IL THOMAS, D C
DeKalb Area Alliance for Responsible Energy THOMAS, D C
Sinnissippi Alliance for the Environment (SAFE) 83/06/14 3pp
18899 206 24X Fiche 50-454, 83/06/14, 8306200320

8306200350 Forwards 830406 memorandum & unexecuted stipulations re emergency planning contentions
COPELAND, V O Isham, Lincoln & Beale COPELAND, V O Commonwealth Edison Co 83/06/14 Docketing & Services Branch 47pp
18900 274 24X Fiche 50-454, 83/06/14, 8306200350

8306200294 Certification to Commission of ASLB recommendation that Commission confer continuing jurisdiction to ASLB or clarify ASLB has jurisdiction to resolve specified emergency planning disputes after decision authorizing operation
CALLIHAN, D, COLE, R F, SMITH, I W Atomic Safety and Licensing Board Panel 83/06/17 21pp 18948 008 24X Fiche 50-454, 83/06/17, 8306200294

8306210281 Proposed findings of fact & conclusions of law in form of supplemental partial initial decision on emergency planning issues Certificate of Svc encl
GOLDBERG, S C Hearing Branch 4 83/06/20 63pp 18714 310 24X
Fiche 50-454, 83/06/20, 8306210281

8306270022 Findings of fact & conclusions of law re emergency planning * DeKalb Area Alliance for Responsible Energy * Sinnissippi Alliance for the Environment (SAFE) * League of Women Voters of Rockford, IL 83/06/20 67pp 19012 259 24X
Fiche 50-454, 83/06/20, 8306270022

8306270041 Proposed findings of fact & conclusions of law re emergency planning Certificate of Svc encl
MILLER, M I, BICLAWSKI, A P, COPELAND, V O Commonwealth Edison Co 83/06/20 53pp 19012 326 24X Fiche 50-454, 83/06/20, 8306270041

8306270383 Forwards until proposed findings of fact & conclusions of law re emergency planning, to be incorporated w/830531 & 0607 submittals W/o encl
COPELAND, V O Isham, Lincoln & Beale COPELAND, V O Commonwealth Edison Co 83/06/20 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 1p 18993 165 24X
Fiche 50-454, 83/06/20, 8306270383

8306230352 Requests cooperation of Ofc of Investigations in reopened hearing, in particular, by releasing pertinent Ofc of Investigations documents, insp repts & hearing testimony
SMITH, I W Atomic Safety and Licensing Board Panel 83/04/21
PAWLICK, E T Region 3, Office of Director 1p 18743 287 24X
Fiche 50-454, 83/06/21, 8306230352

8306230355 Memorandum & order reopening record re alleged falsification of GA inspector records by Hatfield Electric Co Evidence should be presented on all pertinent investigations
SMITH, I W Atomic Safety and Licensing Board Panel 83/06/21 5pp
18943 309 24X Fiche 50-454, 83/06/21, 8306230355

8306230362 Memorandum & order ruling on Joint Intervenor 830427 motion to allow J Hughes testimony on GA/OC issue Motion granted in part & denied in part Intervenor to present proposed statement of Hughes testimony by 830701.
COLE, R F, SMITH, I W Atomic Safety and Licensing Board Panel 83/06/21 19pp 18944 100 24X Fiche 50-454, 83/06/21, 8306230362

8306270016 Reply to DeKalb Area Alliance for Responsible Energy/ Sinnissippi Alliance for Environ proposed findings of fact & conclusions of law re water hammer Certificate of Svc encl
GALLD, J, COPELAND, V O Commonwealth Edison Co GALLD, J Isham, Lincoln & Beale 83/06/21 11pp 19012 246 24X
Fiche 50-454, 83/06/21, 8306270016

--8306270020 Motion for leave to file out-of-time reply to proposed findings of fact & conclusions of law on waterhammer. Addl time needed due to demands imposed by preparation of other documents
COPELAND, V O Commonwealth Edison Co COPELAND, V O Isham, Lincoln & Beale 83/06/21 Atomic Safety and Licensing Board Panel 2pp 19012 257 24X Fiche 50-454, 83/06/21, 8306270016

8306270032 Errata to ASLB 830621 memorandum & order ruling on intervenor motion to admit J Hughes testimony Date for intervenor to submit matter for ASLB consideration is 830707, not 830701
MORAN, D M Atomic Safety and Licensing Board Panel 83/06/22 1p
18988 064 24X Fiche 50-454, 83/06/22, 8306270032

8306270393 Advises that Dec 1983 current fuel load data for Unit 1
MILLER, M I Isham, Lincoln & Beale MILLER, M I Commonwealth Edison Co 83/06/22 SMITH, I W Atomic Safety and Licensing Board Panel 1p 18974 137 24X Fiche 50-454, 83/06/22, 8306270393

8306280528 Motion for extension until 830715 to reply to DeKalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ & Rockford League of Women Voters proposed findings of fact & conclusions of law Certificate of Svc encl
COPELAND, V O Commonwealth Edison Co COPELAND, V O Isham, Lincoln & Beale 83/06/23 Atomic Safety and Licensing Board Panel 4pp
19019 262 24X Fiche 50-454, 83/06/23, 8306280528

8306280535 Proposed findings of fact & conclusions of law re liquid pathway Certificate of Svc encl
GALLD, J, FURSE, M C Commonwealth Edison Co GALLD, J Isham, Lincoln & Beale 83/06/24 39pp 19020 005 24X
Fiche 50-454, 83/06/24, 8306280535

8306290508 Informs of correct mailing address for ASLB chairman
MORAN, D N Atomic Safety and Licensing Board Panel 83/06/27 1p
19052 105 24X Fiche 50-454, 83/06/27, 8306290508

8306300215 Motion for extension until 830701 to file remaining proposed findings of fact & conclusions of law for parties.
THOMAS, D C League of Women Voters of Rockford, IL THOMAS, D C
Thomas, D C 83/06/29 Atomic Safety and Licensing Board Panel 2pp 19122 099 24X Fiche 50-454, 83/06/29, 8306300215

J Insurance & indemnity information

8306130231 Forwards NELIA & MAELU Certificates N-93 & M-93, respectively, evidencing secondary financial protection for plant
OSTER, J Commonwealth Edison Co 83/06/03 BALTIMAN, J Assistant Director for State & License Relations 13pp 18826 311 24X
Fiche 50-454, 83/06/03, 8306130231

8306270345 Forwards Endorsement 7 to NELIA Policy NF-277
OSTER, J Commonwealth Edison Co 83/06/16 BALTIMAN, J Assistant Director for State & License Relations 2pp 18993 133 24X
Fiche 50-454, 83/06/16, 8306270345

K Utility Final Safety Analysis Report (FSAR) & amends

8306030272 Forwards Amend 42 to FSAR
TRAMM, T R Commonwealth Edison Co 83/05/31 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 18713 001 24X
Fiche 50-000, 83/05/31, 8306030272

--8306030281 Amend 42 to FSAR
* Commonwealth Edison Co 83/05/31 583pp 18713:005, 24X
Fiche 50-000, 83/05/31, 8306030272

DOCKETED ITEMS

8306210211 Forwards affidavit of distribution for FSAR, Amend 12
TRAMM, T R Commonwealth Edison Co 83/06/14 DCNTDN, H R Office
of Nuclear Reactor Regulation, Director 2pp 18918 117 24X
Fiche 50-000, 83/06/14, 8306210211

0 Inspection reports, IE Bulletins & correspondence

8306100244 Forwards IE Insp Rept 50-454/83-17 & 50-455/83-14 on
830330-0504 & notice of violation.
STREETER, J F Region 3, Office of Director 83/05/24 REED, C
Commonwealth Edison Co 2pp 18807 139 24X Fiche 50-454, 83/05/24,
8306100244

--8306100247 Notice of violation from insp on 830330-0504
STREETER, J F Region 3, Office of Director 83/05/24 2pp
18807 141 24X Fiche 50-454, 83/05/24, 8306100244

--8306100249 IE Insp Repts 50-454/83-17 & 50-455/83-14 on 830330 0504
Noncompliance noted failure to perform adequate test
procedure review & approval & failure to adequately
implement program for maintaining cleanliness
RING, M A, REYES, L A Region 3, Office of Director. 83/05/24
6pp 18807, 143 24X Fiche 50-454, 83/05/24, 8306100244

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in
Well Logging Device " Svc list encl.
TAYLOR, J M Division of Safeguards & Inspection Programs (Post
830103). 83/05/26 Consolidated Edison Co of New York, Inc
125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet "
Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/05/26 Consolidated Edison Co of New
York, Inc 115pp 18732 085 24X Fiche: 50-000, 83/05/26, 8305110460

8306170359 Forwards IE Insp Repts 50-454/83-18 & 50-455/83-15 on
830301-0430 & notice of violation
NORELIUS, C E Division of Project & Resident Programs 83/05/26
REED, C Commonwealth Edison Co 3pp 18880 071 24X
Fiche, 50-454, 83/05/26, 8306170359.

--8306170361 Notice of violation from insp on 830301-0430
NORELIUS, C E Division of Project & Resident Programs 83/05/26
2pp. 18880 074 24X Fiche 50-454, 83/05/26, 8306170359

--8306170364 IE Insp Repts 50-454/83-18 & 50-455/83-15 on 830301-0430
Noncompliance noted operating personnel failed to observe
control bands for RCS pressure & temp during preoperational
testing & precaution re loose parts indication posted
FORNEY, W, CONNAUGHTON, K, HAYES, D W, Region 3, Office of
Director 83/05/25 7pp 18880 076 24X Fiche 50-454, 83/05/26,
8306170359

8306170020 Forwards IE Insp Rept 50-454/83-19 on 830427-29 No
noncompliance noted
NORELIUS, C E Division of Project & Resident Programs 83/05/27
REED, C Commonwealth Edison Co 2pp 18882 252 24X
Fiche, 50-454, 83/05/27, 8306170020

--8306170023 IE Insp Rept 50-454/83-19 on 830427-29 No noncompliance
noted. Major areas inspected: testing of pipe support &
restraint sys
AND, W P, JAPE, F Region 2, Office of Director 83/05/16 5pp
18882, 254, 24X Fiche 50-454, 83/05/27, 8306170020

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods
Withdrawn at DWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/31 Consolidated Edison Co of New
York, Inc. 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306130341 Forwards IE Insp Rept 50-454/83-16 on 830321-25 & 0404-08 &
notice of violation.
LITTLE, W S, Region 3, Office of Director 83/05/31 REED, C,
Commonwealth Edison Co 2pp. 18822, 282 24X Fiche 50-454, 83/05/31,
8306130341

--8306130343 Notice of violation from insp on 830321-25 & 0404-08
LITTLE, W S, Region 3, Office of Director. 83/05/27 1p
18822, 284 24X Fiche: 50-454, 83/05/31, 8306130341

--8306130345 IE Insp Rept 50-454/83-16 on 830321-25 & 0404-08
Noncompliance noted failure to assure that lead auditors
performing Power-A2CO-Pope properly qualified & certified
LOVE, R B, WILLIAMS, C C, Region 3, Office of Director 83/05/27
11pp. 18822, 285 24X Fiche 50-454, 83/05/31, 8306130341

8306070388 Ack receipt of 830516 ltr informing NRC of steps taken to
correct violations noted in II Insp Repts 50-454/83 12 &
50-455/83 10
SPESSARD, R L Region 3, Office of Director 83/06/01 M.F.D, C
Commonwealth Edison Co 1p 18/42 02J 24X Fiche 50-454, 83/06/01,
8306070388

--8306070392 Responds to NRC 830413 ltr re violations noted in II Insp
Repts 50-454/83-12 & 50 455/83-10 Corrective actions FbAR to
be changed to represent accurate design philosophy for RCS
leak detection
FARRAR, D L Commonwealth Edison Co 83/05/16 KEPPLE, J G
Region 3, Office of Director 7pp 18/42 024 24X
Fiche 50-454, 83/06/01, 8306070388

8306230385 Advises that requested cable tray stiffener weld insp
criteria available in Amend 41 to FSAR, revised Page 3 10-6
TRAMM, T R Commonwealth Edison Co 83/06/02 KEPPLE, J G (Region,
3, Office of Director 1p 18943 058 24X Fiche 50-454, 83/06/02,
8306230385

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe
Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/09 Consolidated Edison Co of New
York, Inc 117pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8306230285 Forwards IE Enforcement Conference Rept 50-454/83 23 on
830523
SPESSARD, R L Region 3, Office of Director 83/06/10 M.F.D, C
Commonwealth Edison Co 2pp 18945 150 24X Fiche 50-454, 83/06/10,
8306230285

--8306230290 IE Enforcement Conference Rept 50-454/83-23 on 830523 Major
areas discussed deficiencies identified in preoperational
test program
SPESSARD, R L Division of Engineering REYES, L A, FORNEY, W L
Region 3, Office of Director 83/06/09 4pp 18945 160 24X
Fiche 50-454, 83/06/10, 8306230285

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive &
Seismically Induced Chatter in Relays Within Printed
Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New
York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-3/, "Transformer Failure Resulting From
Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New
York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8306170371 Forwards NRC 830531 ltr transmitting IE Insp Rept
50-454/83 16 & notice of violation Rept supports intervenor
position that until unwilling or unable to maintain effective
QA/QC program Svc list encl
WHICHER, J M Businessmen for the Public Interest WHICHER, J M
League of Women Voters of Rockford, IL WHICHER, J M Mississippi
Alliance for the Environment (SAFE) 83/06/16 SMITH, I W,
CALLAHAN, A D, COLE, R F Atomic Safety and Licensing Board Panel
17pp 18880 294 24X Fiche 50-454, 83/06/13, 8306170371

8306300178 Forwards IE Insp Repts 50-454/83-21 & 50-455/83-16 on
830427 & 0502-03 & 10 No noncompliance noted
KNOP, R C Region 3, Office of Director 83/06/16 REED, C
Commonwealth Edison Co 2pp 19120 02U 24X Fiche 50-454, 83/06/16,
8306300178

--8306300184 IE Insp Repts 50-454/83-21 & 50-455/83 16 on 830427 &
0502-03 & 10 No noncompliance noted Major areas inspected
allegations re safety-related insp activities & electrical
work
HINDS, J M, HAYES, D W, KNOP, R C Region 3, Office of Director
83/06/16 12pp 19120 030 24X Fiche 50-454, 83/06/16, 8306300170

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New
York, Inc. 115pp 19021 177 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys
Causing Inoperability of Safety-Related Equipment " Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co of New
York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110477 IE Info Notice 83-43, "Reactor Mode Switch Malfunctions" Svc list encl
JORDAN, C L Division of Emergency Preparedness & Engineering
Response (Post 830103) 03/06/83 Consolidated Edison Co of New York, Inc 116pp 18996 247 24X Fiche 50-000, 83/06/23, 8305110477

8305110483 IE Info Notice 83-47, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints" Svc list encl
JORDAN, C L Division of Emergency Preparedness & Engineering
Response (Post 830103) 03/06/84 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

S Reportable occurrences, LLRs & related correspondence

8306030225 Interim Deficiency Rept 83-05 re preservice insp weld indications initially reported on 830427 Disposition of weld indications to be finalized within 90 days of completion of hot functional testing scheduled for 03X001
SWARTZ, E D Commonwealth Edison Co 83/05/26 KEPLER, J O Region 3, Office of Director 3pp 18/03 280 24X Fiche 50-454, 83/05/26, 8306030225

8306030229 Final Deficiency Rept 83-04 re structural steel connection rework design inadequacy initially reported on 830429 Jam nuts to be installed on sliding connections by 830801 & 840101 for Byron & 830725 & 11P5 for Hanford
SWARTZ, E D Commonwealth Edison Co 83/05/26 KEPLER, J O Region 3, Office of Director 2pp 18/03 341 24X Fiche 50-000, 83/05/26, 8306030229

8306100170 Inform that final response to 831206 interim deficiency rept re failure of several dc cables in underground duct, will be submitted in Sept 1983 instead of Apr 1983
TRAHM, T R Commonwealth Edison Co 83/06/01 KEPLER, J O Region 3, Office of Director 1p 18906 017 24X Fiche 50-434, 83/06/01, 8306100170

8306100236 Third Interim Deficiency Rept 82-11 & 82-12 re accuracy of Barton electronic instrument transmitter's changes in allowable accuracy of transmitters being evaluated Final rept will be sent by 830831
TRAHM, T R Commonwealth Edison Co 83/06/01 KEPLER, J O Region 3, Office of Director 1p 18905 311 24X Fiche 50-000, 83/06/01, 8306100236

8306100207 Final Deficiency Rept 82-09 re mechanical snubber bracket interference No inspected snubbers require redesign or repair Inps & changes will be completed prior to fuel load
TRAHM, T R Commonwealth Edison Co 83/06/02 KEPLER, J O Region 3, Office of Director 1p 18905 294 24X Fiche 50-000, 83/06/02, 8306100207

8306100246 Final deficiency rept re Westinghouse DB-416 reactor trip switchgear design discrepancy initially reported on 830504 Replacement undervoltage attachments will have modified, widened grooves to accommodate new retaining rings
SWARTZ, E D Commonwealth Edison Co 83/06/03 KEPLER, J O Region 3, Office of Director 3pp 18907 050 24X Fiche 50-000, 83/06/03, 8306100246

8306170045 Interim Deficiency Rept 83-07 re reactor coolant pump 1A bearing failure initially reported on 830503 Defective pump internals returned to Westinghouse to determine cause of failure Damaged internals replaced final rept in 90 days
SWARTZ, E D Commonwealth Edison Co 83/06/09 KEPLER, J O Region 3, Office of Director 3pp 18978 357 24X Fiche 50-454, 83/06/09, 8306170045

8306270282 Potential Part 21 rept re discrepancy in welding of turnbuckle assembly, turnbuckle bolt interface & on top plate assembly variable springs SAKO Grade B bolts not ASME Section IX mat'l investigation underway
KARAGIANIS, J A Licon Metal Products Co 83/06/17 KEPLER, J O Region 3, Office of Director 2pp 18996 207 24X Fiche 50-000, 83/06/17, 8306270282

T Hearing transcripts on non-antitrust matters

8306010023 Transcript of 830526 hearing in Rockford, IL Pp 7, 102-7, 231 Supporting documentation encl.
* Atomic Safety and Licensing Board Panel 83/05/26, 287pp 18668 220 24X Fiche 50-454, 83/05/26, 8306010023.

DOCKET 83N 50-455 BYRON STATION, UNIT 2

A Application/construction stage documents & correspondence

8306030417 Requests info re identification of safety-related mechanical equipment located in harsh environ areas, including required operating times & plant location info requested within 30 days of receipt of ltr
YOUNGLOOD, D J Licensing Branch 1 83/05/20 FARRAR, D L Commonwealth Edison Co 3pp 18/35 377 24X Fiche 50-000, 83/05/20, 8306030417

8306010019 Summary of 830504 meeting w/util, Westinghouse, Bargent & Lundy in Bethesda, MD re design verification programs
OLSHAN, L N Licensing Branch 1 83/05/23 Licensing Branch 1 4pp 18687 171 24X Fiche 50-454, 83/05/23, 8306010019

8306010031 Summary of 830513 meeting w/util, Westinghouse & Bargent & Lundy in Bethesda, MD re review of seismic qualification & pump & valve operability
OLSHAN, L N Licensing Branch 1 83/05/23 Licensing Branch 1 4pp 18687 170 24X Fiche 50-454, 83/05/23, 8306010031

8306030517 Board Notification 83-74 submits info re work stoppage on installation of new pipe whip restraints Stop work action related to deficiencies in applicant QA program Work will resume when upgraded program in place
NOVAK, T M Assistant Director for Licensing 83/05/23 Atomic Safety and Licensing Board Panel 6pp 18735 054 24X Fiche 50-454, 83/05/23, 8306030517

8306090194 Discusses util interpretation of 10CFR50.49, "Environment Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants" Intent of rulemaking is to require upgrade program for replacement equipment not parts
FARRAR, D L Commonwealth Edison Co 83/06/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 18796 090 24X Fiche 50-000, 83/06/03, 8306090194

8306200019 Summary of 830331 meeting w/util & Westinghouse in Bethesda, MD re Westinghouse analysis & evaluation of 04/05/82 steam generator mod
HOPKINS, J B Licensing Branch 4 83/06/14 Licensing Branch 4 22pp 18908 027 24X Fiche 50-000, 83/06/14, 8306200019

8306230237 Forwards addl info re use of PDVs for venting & depressurizing RCS at facilities & response to FBAR Question 212 157, to be incorporated into future FBAR amend
TRAHM, T R Commonwealth Edison Co 83/06/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 10pp 18945 235 24X Fiche 50-000, 83/06/16, 8306230237

8306240379 Summary of Caseload Forecast Panel 830324-25 meetings w/util in Ogle County, IL re independent assessment of applicant fuel load date of 830831 Fuel load will not occur earlier than Nov 1983
OLSHAN, L N Licensing Branch 1 83/06/17 Licensing Branch 1 75pp 18987 037 24X Fiche 50-454, 83/06/17, 8306240379

8306270322 Provides addl details re control of heavy loads during const when new fuel assemblies being stored in spent fuel pit Due to failure of reactor coolant pump at Byron 1 fuel handling bldg crane will be installed
TRAHM, T R Commonwealth Edison Co 83/06/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18994 073 24X Fiche 50-000, 83/06/17, 8306270322

8306240252 Revises estimated fuel load dates to Oct 1983 for LaSalle County & Dec 1983 & May 1985 for Byron Units 1 & 2, respectively
STIEDE, W L Commonwealth Edison Co. 83/06/21, DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18981 323 24X Fiche 50-000, 83/06/21, 8306240252

8306270373 Notifies of change in FBAR distribution All nuclear power plant activities transferred to new IL Dept of Nuclear Safety, State copy of FBAR amend should be sent to listed address
TRAHM, T R Commonwealth Edison Co 83/06/21, DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18993 313 24X Fiche 50-000, 83/06/21, 8306270373

8306300032 Revises estimated fuel load dates, based on const activity & preoperational testing budget review Fuel load scheduled for 831001, Dec 1983 & May 1985 for LaSalle County Unit 2 & Byron Units 1 & 2, respectively
STIEDE, W L Commonwealth Edison Co 83/06/21 KEPLER, J O Region 3, Office of Director 1p 19120 311. 24X Fiche 50-000, 83/06/21, 8306300032

DOCKETED ITEMS

E NRC Safety Evaluation Report (SER), suppls & correspondence

8306220001 Forwards addl info re seismic design basis for river screenhouse. Review of info should help close Confirmatory Issue 1 of SER Values presented in FSAR are reasonable for mats underlying river screenhouse.
TRAMM, T R Commonwealth Edison Co 83/06/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 15pp 18728 063 24X
Fiche 50-454, 83/06/19, 8306220001

8306270431 Forwards advance copy of rev to Section E 17 of App E to FSAR Section describes safety parameter display sys info should close SER Outstanding Item 16.
TRAMM, T R Commonwealth Edison Co 83/06/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 13pp 19345 353 24X
Fiche 50-000, 83/06/17, 8306270431

8306240070 Requests addl info re moisture separators of heaters in filter sys serving nonaccessible area & fuel handling bldg for SER review. Info requested within 30 days to maintain review schedule.
YOUNGBLOOD, B J Licensing Branch 1 83/06/21 FARRAR, D L Commonwealth Edison Co 3pp 18785 026 24X Fiche 50-000, 83/06/21, 8306240070

F Security, medical, emergency & fire protection plans

8306090247 Confirms 830601 telcon re changes to exercise windows for Dresden & Byron Nuclear Power Stations. Dresden partial exercise will be conducted during wk of 830912 w/Byron full-scale exercise beginning wk of 831114.
JONES, E C Illinois, State of 83/06/01 KEPLER, J Region 3, Office of Director 1p 18795 319 24X Fiche 50-000, 83/06/01, 8306090247

8306090221 Forwards current versions of all prefire plans per requirements of 10CFR50, App II, Paragraph 3 K 12. Plans will be continually revised & future revs will not be formally submitted unless specifically requested.
TRAMM, T R Commonwealth Edison Co 83/06/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18796 119 24X
Fiche 50-454, 83/06/02, 8306090221

--8306090223 Prefire plans
* Commonwealth Edison Co 83/05/18 113pp 18796 120 24X
Fiche 50-454, 83/06/02, 8306090223

8306160214 Submits correction to 830601 ltr. Date of reassessment will be made prior to 830801, not 831001.
JONES, E E Illinois, State of 83/06/09 KEPLER, J Region 3, Office of Director 1p 18861 358 24X Fiche 50-000, 83/06/09, 8306160214

8306230257 Forwards addl info on communications & cable spreading room suppression sys for fire protection program. Third radio communication channel being installed. Repeater will be located in turbine bldg.
TRAMM, T R Commonwealth Edison Co 83/06/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 18745 016 24X
Fiche 50-000, 83/06/17, 8306230257

8306230412 Provides addl info requested in NRC 830411 ltr re instrumentation used to assure safe shutdown in event of fire. Info will be incorporated into FSAR & fire protection rept in future amends.
TRAMM, T R Commonwealth Edison Co 83/06/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 52pp 18943 136 24X
Fiche 50-000, 83/06/17, 8306230412

G Adjudicatory correspondence

8306010457 Forwards marked-up Joint Intervenor Exhibit 14 re radiological emergency response survey. Ambulance medical svcs, indicating stricken portions per ASLD 830426 ruling encl Certificate of Svc encl.
COPELAND, V G Isham, Lincoln & Beale COPELAND, V G Commonwealth Edison Co 83/05/26 SMITH, I W, COLLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 24pp 18674-32R 24X
Fiche: 50-454, 83/05/26, 8306010457

8306020437 Forwards Rockford League of Women Voters proposed findings of fact & conclusions of law re Contention 104 on seismology, per 820818 stipulation.
THOMAS, D C Illinois Institute of Technology 83/05/31 SMITH, I W, COLLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 12pp 18693 228 24X Fiche 50-454, 83/05/31, 8306020437,

8306060193 Forwards proposed findings of fact & conclusions of law re seismology, water hammer & ALARA. Final agreement not reached re procedural history.
COPELAND, V G Isham, Lincoln & Beale COPELAND, V G Commonwealth Edison Co 83/05/31 SMITH, I W, COLLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 2pp 18718 261 24X
Fiche 50-454, 83/05/31, 8306060193

--8306060196 Proposed findings of fact & conclusions of law re seismology, water hammer & ALARA.
MILLER, M I, BIELAWSKI, A P, COPELAND, V G Commonwealth Edison Co 83/05/31 104pp 18718 263 24X Fiche 50-454, 83/05/31, 8306060196

8306080143 Forwards proposed findings of fact & conclusions of law on Contention 9a re water hammer.
CHAVEZ, D Mississippi Alliance for the Environment (SAFE) CHAVEZ, D DeKalb Area Alliance for Responsible Energy 83/05/31 Atomic Safety and Licensing Board Panel 1p 18772 290 24X
Fiche 50-454, 83/05/31, 8306080143

--8306080145 Proposed findings of fact & conclusions of law on Contention 9a re water hammer.
* Mississippi Alliance for the Environment (SAFE) * DeKalb Area Alliance for Responsible Energy 83/05/31 19pp 18772 291 24X
Fiche 50-454, 83/05/31, 8306080145

8306060286 Requests delay of plant licensing & operation until design, QA, waste disposal & emergency procedure problems resolved.
PULIDO, M Affiliation Unknown 83/06/03 SMITH, I W Atomic Safety and Licensing Board Panel 1p 18729 038 24X
Fiche 50-454, 83/06/03, 8306060286

8306060302 Complaint filed in Circuit Court of Seventeenth Judicial Circuit, Winnebago County, IL requesting imposition of punitive damages for wrongful diversion of waste water onto plaintiff property.
FEARER, W P Motor Oils Refining Co FEARER, W P Fearer & Nye 83/06/03 Illinois, State of 3pp 18729 097 24X
Fiche 50-454, 83/06/03, 8306060302

8306090342 Supplementary memorandum opposing intervenor motion to reopen record. Neither triable issue nor significant safety issue exists re Hughes allegations. Certificate of Svc encl.
BECKER, B D Commonwealth Edison Co 83/06/07 Atomic Safety and Licensing Board Panel 12pp 18794 322 24X Fiche 50-454, 83/06/07, 8306090342

8306100201 Brief supporting motion to admit J Hughes testimony. Intervenor has raised serious & significant safety issues re quality of work at plant. Hughes testimony should be considered in ruling on Contention 1A w/Certificate of Svc.
WHICHER, J M League of Women Voters of Rockford, IL WHICHER, J M DeKalb Area Alliance for Responsible Energy WHICHER, J M Mississippi Alliance for the Environment (SAFE) 83/06/07 Atomic Safety and Licensing Board Panel 21pp 18805 230 24X
Fiche 50-454, 83/06/07, 8306100201

8306130445 Forwards proposed findings of fact & conclusions of law re steam generator tube integrity. Document should be filed w/830531 proposed findings re seismology, water hammer & ALARA.
GOLDFEIN, M R Isham, Lincoln & Beale GOLDFEIN, M R Commonwealth Edison Co 83/06/07 SMITH, I W, COLLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 2pp 18820 319 24X
Fiche 50-454, 83/06/07, 8306130445

--8306130452 Proposed findings of fact & conclusions of law re steam generator tube integrity. Certificate of Svc encl.
GALLD, J, GOLDFEIN, M R Commonwealth Edison Co, OALLD, J Isham, Lincoln & Beale 83/06/07 64pp 18820 321 24X
Fiche 50-454, 83/06/07, 8306130452

8306150402 Informs that radiological emergency exercise moved to wk of 831114, to accommodate Illinois Emergency Svcs & Disaster Agency Svc list encl.
BIELAWSKI, A P Isham, Lincoln & Beale BIELAWSKI, A P Commonwealth Edison Co 83/06/07 SMITH, I W, COLLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 3pp 18847 129 24X
Fiche 50-454, 83/06/07, 8306150402

8306150420 Forwards motion for & amend to consolidate DeKalb Area Alliance for Responsible Energy/Mississippi Alliance for Environ Contention 3 w/Rockford League of Women Voters Contentions 19 & 10B.
BIELAWSKI, A P Isham, Lincoln & Beale BIELAWSKI, A P Commonwealth Edison Co 83/06/07 Office of the Secretary of the Commission 2pp 18847 095 24X Fiche 50-454, 83/06/07, 8306150420.

--8306150426 Motion to amend & consolidate Dekalb Area Alliance for Responsible Energy/Sinnissippi Alliance for the Environment Contention 3 w/Rockford League of Women Voters Contentions 19 & 108
CHAVEZ, D Dekalb Area Alliance for Responsible Energy (HAVEZ, D Sinnissippi Alliance for the Environment (SAFE) MORRISON, P League of Women Voters of Rockford, IL 83/02/21 Atomic Safety and Licensing Board Panel App 1/14/7 097 24X
Fiche 50-454, 83/06/07, 8306150426

--8306150442 Amend & consolidation of Dekalb Area Alliance for Responsible Energy/Sinnissippi Alliance for the Environment Contention 3 & Rockford League of Women Voters Contentions 19 & 108
CHAVEZ, D Dekalb Area Alliance for Responsible Energy (HAVEZ, D Sinnissippi Alliance for the Environment (SAFE) MORRISON, P League of Women Voters of Rockford, IL 83/02/21 Atomic Safety and Licensing Board Panel App 1/14/7 101 24X
Fiche 50-454, 83/06/07, 8306150442

8306150408 Notifies that pending review of NRC-commissioned study of current sabotage problems at nuclear power plants, intervenor may move to reopen evidentiary record to consider ramifications of study (Svc list encl)
THOMAS, D C Illinois Institute of Technology THOMAS, D C Affiliation Unknown 83/06/09 SMITH, I W, COLE, R F, CALLIHAN, D Atomic Safety and Licensing Board Panel App 1/14/7 118 24X
Fiche 50-454, 83/06/09, 8306150408

8306200300 Reply opposing Rockford League of Women Voters proposed findings of fact & conclusions of law re seismology Certificate of Svc encl
GOLDFEIN, M R Commonwealth Edison Co GOLDFEIN, M R Isham, Lincoln & Beale 83/06/09 10pp 18900 176 24X Fiche 50-454, 83/06/09, 8306200300

8306200304 Forwards util reply to Rockford League of Women Voters proposed findings of fact & conclusions of law re seismology Related correspondence W/o encl
COPELAND, V G Isham, Lincoln & Beale COPELAND, V G Commonwealth Edison Co 83/06/09 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 2pp 18900 170 24X
Fiche 50-454, 83/06/09, 8306200304

8306130361 Proposed findings of fact & conclusions of law in form of partial initial decision on seismology & water hammer issues Certificate of Svc encl
GOLDBERG, S C Hearing Branch 4 81/06/10 39pp 18822 114 24X
Fiche 50-454, 83/06/10, 8306130361

8306170371 forwards NRC 830531 ltr transmitting IE Insp Rept 50-454/GS-16 & notice of violation Rept supports intervenor position that util unwilling or unable to maintain effective GA/GC program Svc list encl
WHICHER, J M Businessmen for the Public Interest WHICHER, J M League of Women Voters of Rockford, IL WHICHER, J M Sinnissippi Alliance for the Environment (SAFE) 83/06/16 SMITH, I W, CALLIHAN, A D, COLE, R F Atomic Safety and Licensing Board Panel 17pp 18880 274 24X Fiche 50-454, 83/06/16, 8306170371

8306150310 Proposed findings of fact & conclusions of law in form of supplemental partial initial decision on occupational radiation safety & steam generator issues Certificate of Svc encl
GOLDBERG, S C Hearing Branch 4 RANKIN, R J Hearing Branch 3 83/06/14 120pp 18848 328 24X Fiche 50-454, 83/06/14, 8306150310

8306170370 Advises that NRC will not reply to party 830607 supplemental briefs re intervenor 830427 motion to reopen record NRC position already matter of record
GOLDBERG, S C Hearing Branch 4 83/06/14 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 2pp 18880 248 24X Fiche 50-454, 83/06/14, 8306170370

8306200320 Proposed findings of fact & conclusions of law re ALARA & steam generator tube integrity
THOMAS, D C League of Women Voters of Rockford, IL THOMAS, D C Thomas, D C 83/06/14 37pp 18899 173 24X Fiche 50-454, 83/06/14, 8306200320

--8306200327 Motion for extension until 830628 to file proposed findings of fact & conclusions of law re Contentions 22 & 9(c)
THOMAS, D C League of Women Voters of Rockford, IL THOMAS, D C Dekalb Area Alliance for Responsible Energy THOMAS, D C Sinnissippi Alliance for the Environment (SAFE) 83/06/14 Atomic Safety and Licensing Board Panel 1p 18899 205 24X
Fiche 50-454, 83/06/14, 8306200327

--8306200371 Affidavit of DC Thomas supporting extension until 830628 to file proposed findings of fact & conclusions of law re Contentions 22 & 9(c) Time needed due to heavy trial & teaching schedule Certificate of Svc encl
THOMAS, D C League of Women Voters of Rockford, IL THOMAS, D C Dekalb Area Alliance for Responsible Energy THOMAS, D C Sinnissippi Alliance for the Environment (SAFE) 83/06/14 3pp 18899 206 24X Fiche 50-454, 83/06/14, 8306200370

8306200350 Forwards 830404 memorandum & unexecuted stipulations re emergency planning contentions
COPELAND, V G Isham, Lincoln & Beale COPELAND, V G Commonwealth Edison Co 83/06/14 Docketing & Services Branch 47pp 18900 274 24X Fiche 50-454, 83/06/14, 8306200350

8306200294 Certification to Commission of ASLB recommendation that Commission confer continuing jurisdiction to ASLB or clarify ASLB has jurisdiction to resolve specified emergency planning disputes after decision authorizing operation
CALLIHAN, D, COLE, R F, SMITH, I W Atomic Safety and Licensing Board Panel 83/06/17 21pp 18948 008 24X Fiche 50-454, 83/06/17, 8306200294

8306210281 Proposed findings of fact & conclusions of law in form of supplemental partial initial decision on emergency planning issues Certificate of Svc encl
GOLDBERG, S C Hearing Branch 4 83/06/20 63pp 18914 310 24X
Fiche 50-454, 83/06/20, 8306210281

8306270022 Findings of fact & conclusions of law re emergency planning * Dekalb Area Alliance for Responsible Energy * Sinnissippi Alliance for the Environment (SAFE) * League of Women Voters of Rockford, IL 83/06/20 67pp 19012 259 24X
Fiche 50-454, 83/06/20, 8306270022

8306270041 Proposed findings of fact & conclusions of law re emergency planning Certificate of Svc encl
MILLER, M I, BIELAWSKI, A P, COPELAND, V G Commonwealth Edison Co 83/06/20 53pp 19012 326 24X Fiche 50-454, 83/06/20, 8306270041

8306270383 Forwards util proposed findings of fact & conclusions of law re emergency planning to be incorporated w/830531 & 0607 submittals W/o encl
COPELAND, V G Isham, Lincoln & Beale COPELAND, V G Commonwealth Edison Co 83/06/20 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 1p 18993 165 24X
Fiche 50-454, 83/06/20, 8306270383

8306230352 Requests cooperation of Ofc of Investigations in reopened hearing, in particular, by releasing pertinent Ofc of Investigations documents, insp repts & hearing testimony
SMITH, I W Atomic Safety and Licensing Board Panel 83/06/21 PAWLICK, E T Region 3, Office of Director 1p 18943 267 24X
Fiche 50-454, 83/06/21, 8306230352

8306230355 Memorandum & order reopening record re alleged falsification of GA inspector records by Hatfield Electric Co Evidence should be presented on all pertinent investigations
SMITH, I W Atomic Safety and Licensing Board Panel 83/06/21 5pp 18943 309 24X Fiche 50-454, 83/06/21, 8306230355

8306230362 Memorandum & order ruling on Joint Intervenor 830427 motion to allow J Hughes testimony on GA/GC issue Motion granted in part & denied in part Intervenor to present proposed statement of Hughes testimony by 830701
COLE, R F, SMITH, I W Atomic Safety and Licensing Board Panel 83/06/21 19pp 18914 100 24X Fiche 50-454, 83/06/21, 8306230362

8306270016 Reply to Dekalb Area Alliance for Responsible Energy/Sinnissippi Alliance for the Environment proposed findings of fact & conclusions of law re water hammer Certificate of Svc encl
GALLO, J, COPELAND, V G Commonwealth Edison Co GALLO, J Isham, Lincoln & Beale 83/06/21 11pp 17012 246 24X
Fiche 50-454, 83/06/21, 8306270016

--8306270020 Motion for leave to file out-of-time reply to proposed findings of fact & conclusions of law on waterhammer Addl time needed due to demands imposed by preparation of other documents
COPELAND, V G Commonwealth Edison Co COPELAND, V G Isham, Lincoln & Beale 83/06/21 Atomic Safety and Licensing Board Panel 2pp 19012 257 24X Fiche 50-454, 83/06/21, 8306270016

8306270032 Errata to ASLB 830621 memorandum & order ruling on intervenor motion to admit J Hughes testimony Date for intervenor to submit matter for ASLB consideration is 830707, not 830701
MORAN, D M Atomic Safety and Licensing Board Panel 83/06/22 1p 18988 064 24X Fiche 50-454, 83/06/22, 8306270032

DOCKETED ITEMS

8306270393 Advises that Dec 1983 current fuel load date for Unit 1 MILLER, M I Isham, Lincoln & Beale MILLER, M I Commonwealth Edison Co 83/06/22 SMITH, I W Atomic Safety and Licensing Board Panel 1p 18994 137 24X Fiche 50-454, 83/06/22, 8306270393

8306280528 Motion for extension until 830715 to reply to Dekalb Area Alliance for Responsible Energy/Sinissippi Alliance for Environ & Rockford League of Women Voters proposed findings of fact & conclusions of law Certificate of Svc encl COPELAND, V G Commonwealth Edison Co COPELAND, V G Isham, Lincoln & Beale 83/06/23 Atomic Safety and Licensing Board Panel 4pp 19019 262 24X Fiche 50-454, 83/06/23, 8306280528

8306280535 Proposed findings of fact & conclusions of law re liquid pathway Certificate of Svc encl GALL, J, FURBE, M C Commonwealth Edison Co GALL, J Isham, Lincoln & Beale 83/06/24 37pp 17020 005 24X Fiche 50-454, 83/06/24, 8306280535

8306290508 Informs of correct mailing address for AGLB chairman MORAN, D H Atomic Safety and Licensing Board Panel 83/06/27 1p 19052 185 24X Fiche 50-454, 83/06/27, 8306290508

8306300215 Motion for extension until 830701 to file remaining proposed findings of fact & conclusions of law for parties THOMAS, D C League of Women Voters of Rockford, IL THOMAS, D C Thomas, D C 83/06/29 Atomic Safety and Licensing Board Panel 2pp 19122 099 24X Fiche 50-454, 83/06/29, 8306300215

J Insurance & indemnity information

8306270345 Forwards Endorsement 7 to NELA Policy NF-277 OSTER, J Commonwealth Edison Co 83/06/16 SALTZMAN, J Assistant Director for State & License Relations 2pp 10993 133 24X Fiche 50-454, 83/06/16, 8306270345

K Utility Final Safety Analysis Report (FSAR) & amends

8306030272 Forwards Amend 42 to FSAR TRAMM, T R Commonwealth Edison Co 83/05/31 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 18113 001 24X Fiche 50-000, 83/05/31, 8306030272

--8306030281 Amend 42 to FSAR * Commonwealth Edison Co 83/05/31 583pp 18713 005 24X Fiche 50-000, 83/05/31, 8306030272

8306210211 Forwards affidavit of distribution for FSAR, Amend 42 TRAMM, T R Commonwealth Edison Co 83/06/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18918 117 24X Fiche 50-000, 83/06/14, 8306210211

G Inspection reports, IE Bulletins & correspondence

8306100244 Forwards IE Insp Rept 50-454/83-17 & 50-455/83-14 on 830330-0504 & notice of violation STREETER, J F Region 3, Office of Director 83/05/24 REED, C Commonwealth Edison Co 2pp 18807 139 24X Fiche 50-454, 83/05/24, 8306100244

--8306100247 Notice of violation from insp on 830330-0504 STREETER, J F Region 3, Office of Director 83/05/24 2pp 18807 141 24X Fiche 50-454, 83/05/24, 8306100244

--8306100249 IE Insp Repts 50-454/83-17 & 50-455/83-14 on 830330-0504 Noncompliance noted failure to perform adequate test procedure review & approval & failure to adequately implement program for maintaining cleanliness RING, M A, REYER, L A Region 3, Office of Director 83/05/24 8pp 18807 143 24X Fiche 50-454, 83/05/24, 8306100244

8305110488 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103), 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche: 50-000, 83/05/26, 8305110488

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc. 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8306170359 Forwards IE Insp Repts 50-454/83-18 & 50-455/83-15 on 830301-0430 & notice of violation. NORELIOUS, C E Division of Project & Resident Programs 83/05/26, REED, C Commonwealth Edison Co 3pp 18880 071 24X Fiche 50-454, 83/05/26, 8306170359

--8306170361 Notice of violation from insp on 830301-0430 NORELIOUS, C E Division of Project & Resident Programs 83/05/26 2pp 18880 074 24X Fiche 50-454, 83/05/26, 8306170359

--8306170364 IE Insp Repts 50-454/83-18 & 50-455/83-15 on 830301-0430 Noncompliance noted operating personnel failed to observe control bands for RCS pressure & temp during preoperational testing & precaution re loose parts indication posted FORNEY, W, CONNAUGHTON, K, HAYES, D W Region 3, Office of Director 83/05/25 7pp 18880 076 24X Fiche 50-454, 83/05/26, 8306170359

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods. Withdrawn at BWRs " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306070388 Ack receipt of 830516 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-454/83-12 & 50-455/83-10. SPESBARD, R L Region 3, Office of Director 83/06/01 REED, C Commonwealth Edison Co 1p 10742 023 24X Fiche 50-454, 83/06/01, 8306070388

--8306070392 Responds to NRC 830413 ltr re violations noted in II Insp Repts 50-454/83 12 & 50-455/83-10 Corrective actions FSAR to be changed to represent accurate design philosophy for R/R leak detection FARRAR, D L Commonwealth Edison Co 83/05/16 KEEPLER, J G Region 3, Office of Director 7pp 18742 024 24X Fiche 50-454, 83/06/01, 8306070388

8306230385 Advises that requested cable tray stiffener weld insp criteria available in Amend 41 to FSAR, revised Page 3 10-6 TRAMM, T R Commonwealth Edison Co 83/06/02 KEEPLER, J G Region 3, Office of Director 1p 18743 030 24X Fiche 50-454, 83/06/02, 8306230385

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 110pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306170371 Forwards NRC 830531 ltr transmitting IE Insp Rept 50-454/83-16 & notice of violation Rept supports intervenor position that util unwilling or unable to maintain effective GAO/C program Svc list encl WHICHER, J M Businessmen for the Public Interest WHICHER, J M Dekalb Area Alliance for Responsible Energy 83/06/16 SMITH, I W Atomic Safety and Licensing Board Panel 17pp 18880 294 24X Fiche 50-454, 83/06/13, 8306170371

8306300178 Forwards IE Insp Repts 50-454/83-21 & 50-455/83-16 on 830427 & 0502-03 & 10 No noncompliance noted KNOP, R C Region 3, Office of Director 83/06/16 REED, C Commonwealth Edison Co 2pp 19120 026 24X Fiche 50-454, 83/06/16, 8306300178

--8306300184 IE Insp Repts 50-454/83-21 & 50-455/83-16 on 830427 & 0502-03 & 10 No noncompliance noted Major areas inspected, allegations re safety-related insp activities & electrical work HINDS, J M, HAYES, D W, KNOP, R C Region 3, Office of Director 83/06/16 12pp 19120 030 24X Fiche 50-454, 83/06/16, 8306300178

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting from Degraded Internal Connection Cables " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc. 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

DOCKETED ITEMS

337

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

B Reportable occurrences, LLRs & related correspondence

8306030229 Final Deficiency Rept 83-04 re structural steel connection rework design inadequacy initially reported on 830429 Jam nuts to be installed on sliding connections by 830801 & 840101 for Byron & 830725 & 1125 for Braidwood
SWARTZ, E D Commonwealth Edison Co 83/05/26 KEPPLER, J Q Region 3, Office of Director 2pp 18703 341 24X Fiche 50-000, 83/05/26, 8306030229

8306100178 Informs that final response to 831206 interim deficiency rept re failure of several dc cables in underground duct, will be submitted in Sept 1983 instead of Apr 1983
TRAHM, T R Commonwealth Edison Co 83/06/01 KEPPLER, J Q Region 3, Office of Director 1p 18806 019 24X Fiche 50 434, 83/06/01, 8306100178

8306100236 Third Interim Deficiency Repts 82-11 & 82-12 re accuracy of Darton electronic instrument transmitters changes in allowable accuracy of transmitters being evaluated Final rept will be sent by 830831
TRAHM, T R Commonwealth Edison Co 83/06/01 KEPPLER, J Q Region 3, Office of Director 1p 18805 311 24X Fiche 50-000, 83/06/01, 8306100236

8306100207 Final Deficiency Rept 82-09 re mechanical snubber bracket interference. No inspected snubbers require redesign or repair. Insps & changes will be completed prior to fuel load
TRAHM, T R Commonwealth Edison Co 83/06/02 KEPPLER, J Q Region 3, Office of Director 1p 18805 294 24X Fiche 50 000, 83/06/02, 8306100207

8306100246 Final deficiency rept re Westinghouse DS-416 reactor trap switchgear design discrepancy initially reported on 830504 Replacement undervoltage attachments will have modified, widened grooves to accommodate new retaining rings
SWARTZ, E D Commonwealth Edison Co 83/06/03 KEPPLER, J Q Region 3, Office of Director 3pp 18807 090 24X Fiche 50-000, 83/06/03, 8306100246

8306170045 Interim Deficiency Rept 83-07 re reactor coolant pump 1A bearing failure initially reported on 830503 Defective pump internals returned to Westinghouse to determine cause of failure Damaged internals replaced Final rept in 90 days
SWARTZ, E D Commonwealth Edison Co 83/06/09 KEPPLER, J Q Region 3, Office of Director 3pp 18878 359 24X Fiche 50-456, 83/06/09, 8306170045

8306270282 Potential Part 21 rept re discrepancy in welding of turnbuckle assembly, turnbuckle-bolt interface & on top plate assembly variable springs SA307 Grade B bolts not ASME Section IX matl Investigation underway
KARAOIANIS, J A Elcon Metal Products Co 83/06/17 KEPPLER, J Q Region 3, Office of Director 2pp 18996 207 24X Fiche 50-000, 83/06/17, 8306270282

T Hearing transcripts on non-antitrust matters

8306010023 Transcript of 830526 hearing in Rockford, IL Pp 7, 102-7, 231 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/05/26 287pp 18668:220 24X Fiche 50-456, 83/05/26, 8306010023

DOCKET BYN-50-456 BRAIDWOOD STATION, UNIT 1

A Application/Construction stage documents & correspondence

8306030417 Requests info re identification of safety-related mechanical equipment located in harsh environ areas, including required operating times & plant location Info requested within 30 days of receipt of ltr
YOUNGBLOOD, B J Licensing Branch 1 83/05/20 FARRAR, D L Commonwealth Edison Co 3pp 18735 359 24X Fiche 50-000, 83/05/20, 8306030417

8306030066 Ask participation in 830503-05 environ site visit Expertise on aquatic biological resources will be particularly valuable as input to environ review
YOUNGBLOOD, B J Licensing Branch 1 83/05/23 BERTRAND, B A Illinois, State of 1p 18733 210 24X Fiche 50-456, 83/05/23, 8306030066

8306030237 Forwards request for addl info re application for DL covering pipe line locations & frequency of munitions shipments FSAR should be amended to include requested info Response required by 830715
YOUNGBLOOD, B J Licensing Branch 1 83/05/24 FARRAR, D L Commonwealth Edison Co 3pp 18734 016 24X Fiche 50-456, 83/05/24, 8306030237

8306090194 Discusses util interpretation of 10CFR50 49, "Environ Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants " Intent of rulemaking is to require upgrade program for replacement equipment not parts
FARRAR, D L Commonwealth Edison Co 83/06/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 18796 090 24X Fiche 50-000, 83/06/03, 8306090194

8306140161 Submits list of endangered species present in proposed const site, in response to 830503 ltr Indiana bat utilizes steam corridors for foraging in summer Bald eagle found in Will County during winter No critical habitat designated
GROUTAGE, T M Interior, Dept of, Fish & Wildlife Service 83/06/09 YOUNGBLOOD, B J Division of Licensing 2pp 18839 071 24X Fiche 50-456, 83/06/09, 8306140161

8306200019 Summary of 830331 meeting w/utills & Westinghouse in Bethesda, MD re Westinghouse analysis & evaluation of D4/DS/E steam generator mod
HOPKINS, J B Licensing Branch 4 83/06/14 Licensing Branch 4 22pp 18908 327 24X Fiche 50-000, 83/06/14, 8306200019

8306200069 Responds to 830414 memo requesting decision under NRC standardization policy re need to perform review of operation QA program Review of plant should be consistent w/standardized review
THOMAS, C O Standardization & Special Projects Branch 83/06/14 HAASB, W P Quality Assurance 1p 18908 173 24X Fiche 50-456, 83/06/14, 8306200069

8306230237 Forwards addl info re use of PDVs for venting & depressurizing RCB at facilities & response to FSAR Question 212 159, to be incorporated into future FSAR amend
TRAHM, T R Commonwealth Edison Co 83/06/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 18pp 18945 235 24X Fiche 50-000, 83/06/16, 8306230237

8306230294 Forwards addl FSAR info re Question 423 40 concerning suction conditions for essential svc water pumps FSAR will be amended to include info contained in encl.
SWARTZ, E D Commonwealth Edison Co 83/06/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18945 167 24X Fiche 50-456, 83/06/17, 8306230294

8306270322 Provides addl details re control of heavy loads during const when new fuel assemblies being stored in spent fuel pit. Due to failure of reactor coolant pump at Byron 1 fuel handling bldg crane will be installed
TRAHM, T R Commonwealth Edison Co 83/06/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18994 073 24X Fiche 50-000, 83/06/17, 8306270322

8306270373 Notifies of change in FSAR distribution All nuclear power plant activities transferred to new IL Dept of Nuclear Safety State copy of FSAR amend should be sent to listed address
TRAHM, T R Commonwealth Edison Co 83/06/21 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18993 313 24X Fiche 50-000, 83/06/21, 8306270373

C Utility Environmental Report (ER), amends & correspondence

8306030232 Forwards request for addl info re environ rept - DL stage. Response required by 830715
YOUNGBLOOD, B J Licensing Branch 1 83/05/24 FARRAR, D L Commonwealth Edison Co 26pp 18733 352 24X Fiche 50-456, 83/05/24, 8306030232

E NRC Safety Evaluation Report (SER), supls & correspondence

8306270431 Forwards advance copy of rev to Section E 17 of App E to FSAR Section describes safety parameter display sys. Info should close SER Outstanding Item 14
TRAHM, T R Commonwealth Edison Co 83/06/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 13pp 19345 353 24X Fiche 50-000, 83/06/17, 8306270431

DOCKETED ITEMS

8306240070 Requests addl info re moisture separators of heaters in filter sys serving nonaccessible area & fuel handling bldg for SER review info requested within 30 days to maintain review schedule
YOUNGBLOOD, B J Licensing Branch 1 83/06/21 FARRAR, D I
Commonwealth Edison Co 3pp 18985 021 24X Fiche 50-000, 83/06/21, 8306240070

F Security, medical, emergency & fire protection plans

8306230257 Forwards addl info on communications & cable spreading room suppression sys re fire protection program Third radio communication channel being installed Repeater will be located in turbine bldg
TRAHM, T R Commonwealth Edison Co 83/06/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 15945 016 24X
Fiche 50-000, 83/06/17, 8306230257

8306230412 Provides addl info requested in NRC 830411 ltr re instrumentation used to assure safe shutdown in event of fire info will be incorporated into FSAR & fire protection rept in future amends
TRAHM, T R Commonwealth Edison Co 83/06/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 52pp 18943 136 24X
Fiche 50-000, 83/06/17, 8306230412

K Utility Final Safety Analysis Report (FSAR) & amends

8306030272 Forwards Amend 42 to FSAR
TRAHM, T R Commonwealth Edison Co 83/05/31 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 18/13 001 24X
Fiche 50-000, 83/05/31, 8306030272

--8306030281 Amend 42 to FSAR
Commonwealth Edison Co 83/05/31 583pp 18713 005 24X
Fiche 50-000, 83/05/31, 8306030272

8306210211 Forwards affidavit of distribution for FSAR, Amend 42
TRAHM, T R Commonwealth Edison Co 83/06/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18918 117 24X
Fiche 50-000, 83/06/14, 8306210211

G Inspection reports, IE Bulletins & correspondence

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl
TAYLOR, J H Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BHRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8306270066 Ack receipt of 830521 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-456/82-08 & 50-457/82-08
NORELIUS, C E Division of Project & Resident Programs 83/06/20 REED, C Commonwealth Edison Co 1p 18988 131, 24X
Fiche 50-456, 83/06/20, 8306270066

--8306270071 Suppls response to NRC 830514 ltr re violations noted in IE Insp Repts 50-456/82-08 & 50-457/82-08 Corrective action date of issuance for FCR L 8344 on drawing M537 located in Area III of auxiliary bldg corrected
FARRAR, D I Commonwealth Edison Co 83/05/24 KEPPLER, J G Region 3, Office of Director 3pp 18988 132 24X
Fiche 50-456, 83/06/20, 8306270066

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

S Reportable occurrences, LERs & related correspondence

8306030229 Final Deficiency Rept 83-04 re structural steel connection rework design inadequacy Initially reported on 830429 Jam nuts to be installed on sliding connections by 830401 & 840101 for Byron & 830725 & 1125 for Braidwood
SWARTZ, E D Commonwealth Edison Co 83/05/26 KEPPLER, J G Region 3, Office of Director 2pp 18703 341 24X Fiche 50-000, 83/05/26, 8306030229

8306100234 Third Interim Deficiency Repts 82-11 & 82-12 re accuracy of Barton electronic instrument transmitters Changes in allowable accuracy of transmitters being evaluated Final rept will be sent by 830831
TRAHM, T R Commonwealth Edison Co 83/06/01 KEPPLER, J G Region 3, Office of Director 1p 18805 311 24X Fiche 50-000, 83/06/01, 8306100234

8306100207 Final Deficiency Rept 82-09 re mechanical snubber bracket interference No inspected snubbers require redesign or repair Insps & changes will be completed prior to fuel load
TRAHM, T R Commonwealth Edison Co 83/06/02 KEPPLER, J G Region 3, Office of Director 1p 18805 294 24X Fiche 50-000, 83/06/02, 8306100207

8306100246 Final deficiency rept re Westinghouse DB-416 reactor trip switchgear design discrepancy Initially reported on 830504 Replacement undervoltage attachments will have modified, widened grooves to accommodate new retaining rings
SWARTZ, E D Commonwealth Edison Co 83/06/03 KEPPLER, J G Region 3, Office of Director 3pp 18807 058 24X Fiche 50-000, 83/06/03, 8306100246

8306270282 Potential Part 21 rept re discrepancy in welding of turnbuckle assembly, turnbuckle-bolt interface & on top plate assembly variable springs 8A307 Grade B bolts not ASME Section IX mat Investigation underway
KARAGIANIS, J A Elcen Metal Products Co 83/06/17 KEPPLER, J G Region 3, Office of Director 2pp 18996 207 24X
Fiche 50-000, 83/06/17, 8306270282

DOCKET BTN-50-457 BRAIDWOOD STATION, UNIT 2

A Application/construction stage documents & correspondence

8306030417 Requests info re identification of safety-related mechanical equipment located in harsh environ areas, including required operating times & plant location info requested within 30 days of receipt of ltr
YOUNGBLOOD, B J Licensing Branch 1 83/05/20 FARRAR, D I Commonwealth Edison Co 3pp 18735 359 24X Fiche 50-000, 83/05/20, 8306030417

8306030066 Ack participation in 830503-05 environ site visit expertise on aquatic biological resources will be particularly valuable as input to environ review
YOUNGBLOOD, B J Licensing Branch 1 83/05/23 BERTRAND, B A Illinois State of 1p 18733 210 24X Fiche 50-456, 83/05/23, 8306030066

DOCKETED ITEMS

339

8306030237 Forwards request for addl info re application for GL covering pipe line locations & frequency of munitions shipments FSAR should be amended to include requested info Response required by 830715
YOUNGBLOOD, B J Licensing Branch 1 03/05/24 FARRAR, D L Commonwealth Edison Co 3pp 18734 01A 24X Fiche 50-456, 83/05/24, 8306030237

8306090194 Discusses util interpretation of 10CFR50.49, "Envision Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants" Intent of rulemaking is to require upgrade program for replacement equipment not parts FARRAR, D L Commonwealth Edison Co 83/06/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 18796 090 24X Fiche 50-000, 83/06/03, 8306090194

8306140161 Submits list of endangered species present in proposed const site in response to 830503 ltr Indiana bat utilizes steam corridors for foraging in summer Bald eagle found in Hill County during winter No critical habitat designated ORGUTAF, T H Interior, Dept of Fish & Wildlife Service 83/06/09 YOUNGBLOOD, B J Division of Licensing 2pp 18839 071 24X Fiche 50-456, 83/06/09, 8306140161

8306200019 Summary of 830331 meeting w/utills & Westinghouse in Bethesda, MD re Westinghouse analysis & evaluation of D4/D5/E steam generator mod HOPKINS, J B Licensing Branch 4 83/06/14 Licensing Branch 4 22pp 18708 327 24X Fiche 50-000, 83/06/14, 8306200019

8306200069 Responds to 830414 memo requesting decision under NRC standardization policy re need to perform review of operation QA program Review of plant should be consistent w/standardized review THOMAS, C O Standardization & Special Projects Branch 83/06/14 HAAES, W P Quality Assurance 1p 18708 173 24X Fiche 50-456, 83/06/14, 8306200069

8306230237 Forwards addl info re use of PURVs for venting & depressurizing RCS at facilities & response to FSAR amend Question 212 157, to be incorporated into future FSAR amend TRAMM, T R Commonwealth Edison Co 83/06/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 18pp 18945 235 24X Fiche 50-000, 83/06/16, 8306230237

8306230294 Forwards addl FSAR info re Question 423 40 concerning suction conditions for essential svc water pumps FSAR will be amended to include info contained in encl SHWARTZ, C D Commonwealth Edison Co 83/06/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18945 167 24X Fiche 50-456, 83/06/17, 8306230294

8306270322 Provides addl details re control of heavy loads during const when new fuel assemblies being stored in spent fuel pit Due to failure of reactor coolant pump at Byron 1, fuel handling bldg crane will be installed TRAMM, T R Commonwealth Edison Co 83/06/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18794 073 24X Fiche 50-000, 83/06/17, 8306270322

8306270373 Notifies of change in FSAR distribution All nuclear power plant activities transferred to new IL Dept of Nuclear Safety State copy of FSAR amend should be sent to listed address TRAMM, T R Commonwealth Edison Co 83/06/21 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18993 313 24X Fiche 50-000, 83/06/21, 8306270373

C Utility Environmental Report (ER), amends & correspondence

8306030232 Forwards request for addl info re environ rept - GL stage Response required by 830715
YOUNGBLOOD, B J Licensing Branch 1 83/05/24 FARRAR, D L Commonwealth Edison Co 26pp 18733 J62 24X Fiche 50-456, 83/05/24, 8306030232

E NRC Safety Evaluation Report (SER), suppls & correspondence

8306270431 Forwards advance copy of rev to Section E 17 of App E to FSAR Section describes safety parameter display sys info should close SER Outstanding Item 16 TRAMM, T R Commonwealth Edison Co 83/06/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 13pp 19345 352 24X Fiche 50-000, 83/06/17, 8306270431

8306240070 Requests addl info re moisture separators of heaters in filter sys serving nonaccessible area & fuel handling bldg for SER review Info requested within 30 days to maintain review schedule YOUNGBLOOD, B J Licensing Branch 1 83/06/21 FARRAR, D L Commonwealth Edison Co 3pp 18988 026 24X Fiche 50-000, 83/06/21, 8306240070

F Security, medical, emergency & fire protection plans

8306230257 Forwards addl info on communications & cable spreading room suppression sys re fire protection program Third radio communication channel being installed Repeater will be located in turbine bldg TRAMM, T R Commonwealth Edison Co 83/06/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 18945 016 24X Fiche 50-000, 83/06/17, 8306230257

8306230412 Provides addl info requested in NRC 830411 ltr re instrumentation used to assure safe shutdown in event of fire Info will be incorporated into FSAR & fire protection rept in future amends TRAMM, T R Commonwealth Edison Co 83/06/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 52pp 18943 136 24X Fiche 50-000, 83/06/17, 8306230412

K Utility Final Safety Analysis Report (FSAR) & amends

8306030272 Forwards Amend 42 to FSAR TRAMM, T R Commonwealth Edison Co 83/05/31 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 18713 001 24X Fiche 50-000, 83/05/31, 8306030272

--8306030281 Amend 42 to FSAR * Commonwealth Edison Co 83/05/31 357pp 18713 005 24X Fiche 50-000, 83/05/31, 8306030281

8306210211 Forwards affidavit of distribution for FSAR, Amend 42 TRAMM, T R Commonwealth Edison Co 83/06/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18918 117 24X Fiche 50-000, 83/06/14, 8306210211

G Inspection reports, IC Bulletins & correspondence

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Wall Logging Device" Svc list encl TAYLOR, J H Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting from Degraded Internal Connection Cables" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8306270066 Ack receipt of 830524 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-456/82-08 & 50-457/82-08 NORELIUB, C E Division of Project & Resident Programs 83/06/20 REED, C Commonwealth Edison Co 1p 18988 131 24X Fiche 50-456, 83/06/20, 8306270066

--8306270071 Suppls response to NRC 830214 ltr re violations noted in IE Insp Repts 50-456/82-08 & 50-457/82-08 Corrective action, date of issuance for FCR L-8344 on drawing M537 located in Area III of auxiliary bldg corrected FARRAR, D L Commonwealth Edison Co 83/05/24 KEPLER, J O Region 3, Office of Director 3pp 18988 132 24X Fiche 50-456, 83/06/20, 8306270066

DOCKETED ITEMS

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 11pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 12pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42 "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 11pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 11pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

B Reportable occurrences, LERs & related correspondence

8306030229 Final Deficiency Rept 83-04 re structural steel connection rework design inadequacy Initially reported on 830429 Jam nuts to be installed on sliding connections by 830801 & 840101 for Byron & 830725 & 1125 for Braidwood
SHARTZ, E D Commonwealth Edison Co 83/05/24 KEPLER, J G Region 3, Office of Director 2pp 18703 341 24X Fiche 50-000, 83/05/26, 8306030229

8306100236 Third Interim Deficiency Repts 82-11 & 82-12 re accuracy of Barton electronic instrument transmitters Changes in allowable accuracy of transmitters being evaluated Final rept will be sent by 830831
TRAHM, T R Commonwealth Edison Co 83/06/01 KEPLER, J G Region 3, Office of Director 1p 18805 311 24X Fiche 50-000, 83/06/01, 8306100236

8306100207 Final Deficiency Rept 82-09 re mechanical snubber bracket interference No inspected snubbers require redesign or repair Insps & changes will be completed prior to fuel load
TRAHM, T R Commonwealth Edison Co 83/06/02 KEPLER, J G Region 3, Office of Director 1p 18805 294 24X Fiche 50-000, 83/06/02, 8306100207

8306100246 Final deficiency rept re Westinghouse DB-416 reactor trip switchgear design discrepancy Initially reported on 830504 Replacement undervoltage attachments will have modified, widened grooves to accommodate new retaining rings
SHARTZ, E D Commonwealth Edison Co 83/06/03 KEPLER, J G Region 3, Office of Director 3pp 18807 058 24X Fiche 50-000, 83/06/03, 8306100246

8306270282 Potential Part 21 rept re discrepancy in welding of turnbuckle assembly, turnbuckle-bolt interface & on top plate assembly variable springs. SA307 Grade B bolts not ABME Section IX matl. Investigation underway
KARAGIANIS, J A Eichen Metal Products Co 83/06/17 KEPLER, J G Region 3, Office of Director 2pp 18796 207 24X Fiche 50-000, 83/06/17, 8306270282

DOCKET 50-458 RIVER BEND STATION, UNIT 1

A Application/construction stage documents & correspondence

8306030509 Informs that each LRQ-II member must submit numerical value determined by GE for respective plants on fuel assembly lift off displacement due to error in fuel assembly topical rept re LRQ-II Generic Issue 2-CPB
NOVAK, T M Assistant Director for Licensing 83/05/23
HOLTZSCHER, D L Licensing Review Group II 3pp 18735 051 24X Fiche 50-000, 83/05/23, 8306030509

8306060373 Responds to 820903 ltr submitting position papers which included Licensing Review Group II proposed solution for Issue 4-MEB, intended to protect in-core instrument tubes from flow-induced vibration Issue unresolved
YOUNGBLOOD, B J Licensing Branch 1 83/05/26 HOLTZSCHER, D L Licensing Review Group II HOLTZSCHER, D L Illinois Power Co 4pp 18751 287 24X Fiche 50-000, 83/05/26, 8306060373

8306090205 Notification of 830607 meeting w/util & S&W in Cherry Hill, NJ to discuss ODC 51 compliance (fracture prevention of containment pressure boundary)
HAUGHEY, M WEINKAM, E Licensing Branch 2 83/06/02 NOVAK, T M Assistant Director for Licensing 4pp 18809 225 24X Fiche 50-000, 83/06/02, 8306090205

8306140417 Notification of 830601 meeting w/util & GE in San Jose, CA to discuss ODC 51 compliance
WEINKAM, E J Licensing Branch 2 83/06/02 SCHWENCER, A Licensing Branch 2 3pp 18854 069 24X Fiche 50-458, 83/06/02, 8306140417

8306150227 Suppls 830523 request for addl info re personnel simulator training, to complete review of DI application Response schedule requested
SCHWENCER, A Licensing Branch 2 83/06/02 CAHILL, W J Gulf States Utilities Co 3pp 18870 063 24X Fiche 50-458, 83/06/02, 8306150227

8306130462 Notification of 830616 meeting w/util in St Francisville, LA to discuss various environ features prior to site tour
WEINKAM, C J Licensing Branch 2 83/06/06 SCHWENCER, A Licensing Branch 2 3pp 18830 171 24X Fiche 50-458, 83/06/06, 8306130462

8306220254 Notification of 830621 meeting w/util & S&W in Bethesda, MD to discuss geosciences open items
WEINKAM, C J Licensing Branch 2 83/06/09 SCHWENCER, A Licensing Branch 2 3pp 18951 063 24X Fiche 50-458, 83/06/09, 8306220254

8306280328 Responds partially to NRC B10330 ltr re ultimate capacity analysis of Mark III containments Rept showing calculated general yielding value for steel containment of 56 psi encl Final results for remaining issues provided by 830930
BOOKER, J E Gulf States Utilities Co 83/06/22 TEDESCO, R I Assistant Director for Licensing 6pp 19001 216 24X Fiche 50-458, 83/06/22, 8306280328

F Security, medical, emergency & fire protection plans

8306150221 Responds to util 830307 & All ltrs re emergency operations facility (EOF) & backup EOF Proposed LOF & backup EOF sites acceptable Addl LOF features & emergency response facilities to be evaluated during post-implementation review
EISENHUT, D O Division of Licensing 83/06/01 CAHILL, W J Gulf States Utilities Co 2pp 18870 061 24X Fiche 50-458, 83/06/01, 8306150221

8306220250 Responds to 830307 ltr submitting Rev 3 to guard training & qualification plan Rev 3 satisfies 10CFR73 & 10CFR73, App B requirements License condition will incorporate 810825 ltr & approved revs
SCHWENCER, A Licensing Branch 2 83/06/09 CAHILL, W J Gulf States Utilities Co 2pp 18791 069 24X Fiche 50-458, 83/06/09, 8306220250

8306220234 Summarizes telephone survey of agencies cited in R Littlel 830603 ltr re whether govt agencies advise witnesses of right to counsel per Advisory Committee on Rights of Licensee Employees Under Investigation
LEVI, R P Office of the General Counsel 83/06/10 Rights of Licensee Employees Under Investigation 4pp 18977 348 24X Fiche 50-458, 83/06/10, 8306220234

G Adjudicatory correspondence

8306100206 Answer opposing Joint Intervenor 830531 first amended & supplemented contentions Unauthorized Filing seeks to add new contentions beyond time prescribed by ASLB Contentions w/o merit Certificate of Svc encl
CONNER, T B Gulf States Utilities Co CONNER, T B Conner & Wetterhahn 83/06/07 Atomic Safety and Licensing Board Panel 11pp 18805 295 24X Fiche 50-458, 83/06/07, 8306100206

8306100041 Response opposing Joint Intervenor 830531 first amended & supplemented contentions Submittal procedurally improper Amends fail to remedy original contention defects Supplemental contentions inadmissible W/Certificate of Svc
REPKA, D A Hearing Branch 3 83/06/09 Atomic Safety and Licensing Board Panel 11pp 18805 117 24X Fiche 50-458, 83/06/09, 8306100041

8306220117 Response to NRC & util answers to first amended & supplemental contentions Contentions filed in timely manner Certificate of Svc encl
FALKENHEIMER, D IRVING, S M Louisiana Consumer's League, Inc, WATKINS, L B Rothschild, O C 83/06/10 Atomic Safety and Licensing Board Panel 4pp 18926 076 24X Fiche 50-458, 83/06/10, 8306220117

8306230003 Forwards NRC 830601 draft SER W/o encl
REPKA, D A Hearing Branch 3 83/06/21 COLE, R F, LINENBERGER, D COTTER, D P Atomic Safety and Licensing Board Panel 1p 18947 079 24X Fiche 50-458, 83/06/21, 8306230003

G Inspection reports, IE Bulletins & correspondence

8306060069 Forwards IE Insp Rept 50-458/B3-10 on 830407-30 No noncompliance noted
MADSEN, O L Region 4, Office of Director 83/05/17 CAHILL, W J
Gulf States Utilities Co 2pp 18719 J19 24X
Fiche 50-458, 83/05/17, 8306060069

--8306060073 IE Insp Rept 50-458/B3-10 on 830407-30 No noncompliance noted Major areas inspected licensee identified const deficiencies, safety-related pipe welding, pipe supports & restraints & electrical sys installation
BROWN, R L, CROSSMAN, W A Region 4, Office of Director 83/05/13
6pp 18719 J21 24X Fiche 50-458, 83/05/17, 8306060069

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 118pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

S Reportable occurrences, LERs & related correspondence

8306010394 Interim Deficiency Rept DR-73 re improperly installed spring nuts in GE power generation control complex termination cabinets Initially reported on 820902 OE evaluation awaited Next rept due by 830405
BOOKER, J E Gulf States Utilities Co 83/05/24 COLLINS, J T
Region 4, Office of Director 1p 18602 234 24X
Fiche 50-458, 83/05/24, 8306010394

8306010423 Interim Deficiency Rept DR-101 re undersized fillet welds on NF pipe supports Initially reported on 830223 Addl info from Util AE awaited Next rept will be submitted by 830808
BOOKER, J E Gulf States Utilities Co 83/05/24 COLLINS, J T
Region 4, Office of Director 1p 18679 311 24X
Fiche 50-458, 83/05/24, 8306010423

8306070265 Interim Deficiency Rept DR-93 re documentation & code stamping of interconnecting piping between reactor water cleanup HXs Util awaiting info from supplier Atlas Industrial Mfg Co Next rept will be submitted by 830708
BOOKER, J E Gulf States Utilities Co 83/05/25 COLLINS, J T
Region 4, Office of Director 1p 18740 336 24X
Fiche 50-458, 83/05/25, 8306070265

8306070195 Interim Deficiency Rept 80 re defective piston skirt castings installed in emergency diesel generator engines supplied by Transamerica Delaval, Inc Initially reported on 821124 Insp of diesel generators underway
BOOKER, J E Gulf States Utilities Co 83/05/27 COLLINS, J T
Region 4, Office of Director 1p 18736 294 24X
Fiche 50-458, 83/05/27, 8306070195

8306070196 Interim Deficiency Rept 89 re malfunction of primary knife-type disconnect mfg by RTE Delta Corp & used in diesel generators Initially reported on 830317 Util awaiting addl info from Transamerica Delaval Next rept expected by 830706
BOOKER, J E Gulf States Utilities Co 83/05/27 COLLINS, J T
Region 4, Office of Director 1p 18736 293 24X
Fiche 50-458, 83/05/27, 8306070196

8306090038 Final Deficiency Rept DR-60 re design of nonseismic pipe sys over Category 1 components in control bldg. Initially reported on 820615 SEM improved basic program for meeting requirements of Reg Guide 1.29
BOOKER, J E Gulf States Utilities Co 83/05/31 COLLINS, J T
Region 4, Office of Director 1p 18793 310 24X
Fiche 50-458, 83/05/31, 8306090038

8306090365 Interim Deficiency Rept DR-74 re incorrect installation of 1/4-inch drilled-in-expansion-type anchor bolts, used to support emergency lighting battery units Addl AE info expected by 830729 Next rept scheduled for 830818
BOOKER, J E Gulf States Utilities Co 83/05/31 COLLINS, J T
Region 4, Office of Director 1p 18795 068 24X
Fiche 50-458, 83/05/31, 8306090365

8306130317 Final Deficiency Rept DR-71 re inconsistencies in QA program at WJ Woolley Co, manufacturer of personnel air locks Initially reported on 820827, No physical hardware changes necessary Item not reportable per 10CFR50.55(e)
BOOKER, J E Gulf States Utilities Co 83/06/03 COLLINS, J T
Region 4, Office of Director 1p 18821 033 24X
Fiche 50-458, 83/06/03, 8306130317

8306130376 Interim Part 21 Rept DR-95 re possible defect in plate & face plate gaskets for Morrison-Knudsen Co hydrogen ignitor, Model 5043 Initially reported on 830204 Evaluation not completed Next rept to be submitted by 830711
BOOKER, J E Gulf States Utilities Co 83/06/06 COLLINS, J T
Region 4, Office of Director 1p 18822 346 24X
Fiche 50-458, 83/06/06, 8306130376

8306160353 Interim Deficiency Rept DR-61 re length of capscrew which holds starting air valve assembly in cylinder head of standby emergency diesel generators supplied by Transamerica Delaval Initially reported on 830406 Next rept by 830725
BOOKER, J E Gulf States Utilities Co 83/06/07 COLLINS, J T
Region 4, Office of Director 1p 18860 123 24X
Fiche 50-458, 83/06/07, 8306160353

8306160520 Interim Deficiency Rept DR-111 re dimensional discrepancy on two small bore pipe support design drawings Initially reported on 830412 Evaluation continuing Next rept will be submitted by 830714
BOOKER, J E Gulf States Utilities Co 83/06/08 COLLINS, J T
Region 4, Office of Director 1p 18863 233 24X
Fiche 50-458, 83/06/08, 8306160520

8306160439 Interim Deficiency Rept DR-115 re tackwelding of heavy hex nuts Initially reported on 830510 Current station design specifies use of locknuts w/heavy hex nuts in lieu of tackwelding Interim or final status rept expected by 830718
BOOKER, J E Gulf States Utilities Co 83/06/09 COLLINS, J T
Region 4, Office of Director 1p 18860 206 24X
Fiche 50-458, 83/06/09, 8306160439

8306160521 Interim Deficiency Rept DR-72 re improper installation, testing & insp of concrete drilled-in-expansion-type anchors Initially reported on 830425 Addl AE info awaited, Next rept due by 830831
BOOKER, J E Gulf States Utilities Co 83/06/10 COLLINS, J T
Region 4, Office of Director 1p 18864 033 24X
Fiche 50-458, 83/06/10, 8306160521

DOCKETED ITEMS

8306160531 Interim Deficiency Rept DR-114 re larger-than-specified gaps in joints connecting RHR HX supports to embedment plates Initially reported on 830511 Next rept to be provided by 830715
BOOKER, J E Gulf States Utilities Co 83/06/10 COLLINS, J T
Region 4, Office of Director 1p 13863 137 24X
Fiche 50-458, 83/06/10, 8306160531

8306170395 Interim Deficiency Rept DR-109 re Velan 3/4-inch socket welded globe valves w/counterbores not concentric to ctr of valves Initially reported on 830408 AE evaluation awaited Next rept will be submitted by 830804
BOOKER, J E Gulf States Utilities Co 83/06/13 COLLINS, J T
Region 4, Office of Director 1p 18880 237 24X
Fiche 50-458, 83/06/13, 8306170395

8306300148 Interim Deficiency Rept DR-107 re Category I air circuit breakers w/trip coils of higher range than shown on Bill of Materials Initially reported on 830404 Util awaiting addl info from AE Next rept by 830719
BOOKER, J E General Public Utilities - GPU Service Corp 83/06/14 COLLINS, J T Region 4, Office of Director 1p 19119 320 24X
Fiche 50-458, 83/06/14, 8306300148

8306280355 Interim Deficiency Rept DR-110 re contamination of stainless steel w/ultrasonic couplant not meeting chemical analysis requirements Initially reported on 830408 Addl info from AE expected Next rept will be provided by 830729
BOOKER, J E Gulf States Utilities Co 83/06/15 COLLINS, J T
Region 4, Office of Director 1p 19014 082 24X
Fiche 50-458, 83/06/15, 8306280355

8306270095 Interim Deficiency Rept DR-118 re insufficient penetration of welds for platform channels on primary shield wall Initially reported on 830517 Investigation incomplete Interim or final rept will be submitted by 830728
BOOKER, J E Gulf States Utilities Co 83/06/16 COLLINS, J T
Region 4, Office of Director 1p 13988 138 24X
Fiche 50-458, 83/06/16, 8306270095

8306270130 Interim Deficiency Rept DR-119 re failure of threaded weld studs during const of cable tray supports Initially reported on 830517 Investigation incomplete Interim or final rept expected by 830802
BOOKER, J E Gulf States Utilities Co 83/06/16 COLLINS, J T
Region 4, Office of Director 1p 18988 093 24X
Fiche 50-458, 83/06/16, 8306270130

8306270391 Interim Deficiency Rept DR-117 re previously unanalyzed scenario which could result in containment negative pressure less than containment design negative pressure Initially reported on 830517 Next rept by 830809
BOOKER, J E Gulf States Utilities Co 83/06/16 COLLINS, J T
Region 4, Office of Director 1p 13994 151 24X
Fiche 50-458, 83/06/16, 8306270391

8306270156 Interim Deficiency Rept DR-104 re linear indications found in lifting lugs on containment dome Initially reported on 830325 Util awaiting addl info from AE Next rept expected by 830811
BOOKER, J E Gulf States Utilities Co 83/06/17 COLLINS, J T
Region 4, Office of Director 1p 17012 147 24X
Fiche 50-458, 83/06/17, 8306270156

8306300121 Interim Deficiency Rept DR-108 re pipe support std components supplied by Bergen-Paterson Pipe Support Corp not conforming to components referenced in design drawings Util awaiting info from AE Interim or final rept by 830810
BOOKER, J E Gulf States Utilities Co 83/06/21 COLLINS, J T
Region 4, Office of Director 1p 19121 074 24X
Fiche 50-458, 83/06/21, 8306300121

T Hearing transcripts on non-antitrust matters

8306170289 Transcript of 830614 prehearing conference in Baton Rouge, LA Pp 1-132
* Atomic Safety and Licensing Board Panel 83/06/14 133pp
18881, 137 24X Fiche 50-458, 83/06/14, 8306170289

RIVER BEND STATION, UNIT 2

'construction stage documents & correspondence

is that each LR0-II member must submit numerical value IE for respective plants on fuel assembly component, due to error in fuel assembly topical Generic Issue 2-CPB
Assistant Director for Licensing 83/05/23,
Licensing Review Group II 3pp 18735 051 24X
1/05/23, 8306030509

8306060373 Responds to 820903 ltr submitting position, papers which included Licensing Review Group II proposed solution for Issue 4-MEB, intended to protect in-core instrument tubes from flow-induced vibration issue unresolved
YOUNGBLOOD, D J Licensing Branch 1 83/05/26 HULTSCHER, D J
Licensing Review Group II 4pp 18751 287 24X
Fiche 50-000, 83/05/26, 8306060373

8306090205 Notification of 830607 meeting w/utls & SAM in Cherry Hill, NJ to discuss ODC 51 compliance (fracture prevention of containment pressure boundary)
HAUGHEY, M, WEINKAM, E Licensing Branch 2 83/06/02 NOVAK, I M
Assistant Director for Licensing 4pp 18809 225 24X
Fiche 50 000, 83/06/02, 8306090205

8306140417 Notification of 830621 meeting w/utl & GF in San Jose, CA to discuss ODC 51 compliance
WEINKAM, E J Licensing Branch 2 83/06/02 SCHWENGER, A Licensing Branch 2 3pp 18854 069 24X Fiche 50-458, 83/06/02, 8306140417

8306150227 Suppls 030523 request for addl info re personnel simulator training, to complete review of DL application Response schedule requested
SCHWENGER, A Licensing Branch 2 83/06/06 CAHILL, W J Gulf States Utilities Co 3pp 18870 063 24X Fiche 50-458, 83/06/06, 8306150227

8306130462 Notification of 830616 meeting w/utl in St Francisville, LA to discuss various environ features prior to site tour
WEINKAM, E J Licensing Branch 2 83/06/06 SCHWENGER, A Licensing Branch 2 3pp 18830 171 24X Fiche 50-458, 83/06/06, 8306130462

8306280328 Responds partially to NRC 810330 ltr re ultimate capacity analysis of Mark III containments Rept showing calculated general yielding value for steel containment of 56 psi encl Final results for remaining issues provided by 830430
BOOKER, J E Gulf States Utilities Co 83/06/22 TEDESCO, R L
Assistant Director for Licensing 4pp 19001 216 24X
Fiche 50-458, 83/06/22, 8306280328

F Security, medical, emergency & fire protection plans

8306150221 Responds to util 830307 & 410 ltrs re emergency operations facility (EOF) & backup EOF Proposed Eur & backup EOF sites acceptable Addl EOF features & emergency response facilities to be evaluated during post-implementation review
EISENHUT, D G Division of Licensing 83/06/01 CAHILL, W J Gulf States Utilities Co 2pp 18870 061 24X Fiche 50-458, 83/06/01, 8306150221

8306220250 Responds to 830307 ltr submitting Rev 3 to guard training & qualification plan Rev 3 satisfies 10CFR73 & 10CFR73, App B requirements License condition will incorporate 810225 ltr & approved revs
SCHWENGER, A Licensing Branch 2 83/06/09 CAHILL, W J Gulf States Utilities Co 2pp 18951 069 24X Fiche 50-458, 83/06/09, 8306220250

8306220234 Summarizes telephone survey of agencies cited in R littell 830603 ltr re whether govt agencies advise witnesses of right to counsel per Advisory Committee on Rights of Licensee Employees Under Investigation
LEVI, R P Office of the General Counsel 83/06/10 Rights of Licensee Employees Under Investigation 4pp 18777 348 24X
Fiche 50-458, 83/06/10, 8306220234

G Adjudicatory correspondence

8306100206 Answer opposing Joint Intervenor 830531 first amended & supplemented contentions Unauthorized filing seeks to add new contentions beyond time prescribed by ASLB Contentions w/o merit Certificate of Svc encl
CONNER, T B Gulf States Utilities Co CONNER, T B Conner & Wetterhahn 83/06/07 Atomic Safety and Licensing Board Panel 11pp 18805 27b 24X Fiche 50-458, 83/06/07, 8306100206

8306100041 Response opposing Joint Intervenor 830531 first amended & supplemented contentions Submittal procedurally improper Amends fail to remedy original contention defects Supplemental contentions inadmissible w/Certificate of Svc.
REPKA, D A Hearing Branch 3 83/06/09 Atomic Safety and Licensing Board Panel 11pp 18805 117 24X Fiche 50-458, 83/06/09, 8306100041

8306220117 Response to NRC & util answers to first amended & supplemental contentions Contentions filed in timely manner Certificate of Svc encl
FALKENHEIMER, D, IRVING, S M Louisiana Consumer's League, Inc. WATKINS, L D Rothschild, G I 83/06/13 Atomic Safety and Licensing Board Panel 4pp 18926 096 24X Fiche 50-458, 83/06/13, 8306220117

DOCKETED ITEMS

343

8306230003 Forwards NRC 830601 draft S/R W/u encl
REPKA, D A Hearing Branch 3 03/06/21 COLE, R F, LINENBERGER, G,
COTTER, J P Atomic Safety and Licensing Board Panel 1p
18947 079 24X Fiche 50-460, 83/06/21, 8306230003

Q Inspection reports, IE Bulletins & correspondence

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in
Well Logging Device " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post
830103) 03/05/26 Consolidated Edison Co of New York, Inc
125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 03/05/26 Consolidated Edison Co of New
York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Reds
Withdrawn at BWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 03/05/31 Consolidated Edison Co of New
York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe
Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 03/06/09 Consolidated Edison Co of New
York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive &
Seismically Induced Chatter in Relays Within Printed
Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 03/06/13 Consolidated Edison Co of New
York, Inc 110pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From
Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 03/06/13 Consolidated Edison Co of New
York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 03/06/22 Consolidated Edison Co of New
York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys
Causing Inoperability of Safety-Related Equipment " Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 03/06/22 Consolidated Edison Co of New
York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 03/06/23 Consolidated Edison Co of New
York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate
Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 03/06/24 Consolidated Edison Co of New
York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

T Hearing transcripts on non-antitrust matters

8306170289 Transcript of 830614 prehearing conference in Baton Rouge,
LA Pg 1-132,
* Atomic Safety and Licensing Board Panel 83/06/14 137pp
18981 139, 24X Fiche 50-460, 83/06/14, 8306170289.

DOCKET 50-460 WPPSS NUCLEAR PROJECT, UNIT 1

A Application/construction stage documents & correspondence

8306080062 Notification of 830608 meeting w/util & United Engineers &
Constructors in Bethesda, MD to discuss ASME Section III, Div
2 addenda articles & code case review
THADANI, M Licensing Branch 4 83/06/06 ADENBAM, E O Licensing
Branch 4, 3pp, 18787 303 24X Fiche 50-460, 83/06/06, 8306080062

8306090262 Forwards discussion of remaining ASME approved code cases &
ASME Code addenda articles utilized during containment
design & const for NRC approval Text of each code case, as
approved by ASME, also encl Reply requested by 830617
BOUCHEY, O D Washington Public Power Supply System 03/06/06
ADENBAM, E O Licensing Branch 4 22pp 18795 257 24X
Fiche 50-460, 83/06/06, 8306090262

8306140612 Forwards addl info requested at 830608 meeting re approval
of ASME Section III, Div 2 Code Cases for containment
in-place concrete strength is greater than design strength
BOUCHEY, O D Washington Public Power Supply System 03/06/10
ADENBAM, E O Licensing Branch 4 4pp 18941 264 24X
Fiche 50-460, 83/06/10, 8306140612

8306240017 Forwards order extending const completion date of CPPR-134
to 910601 Safety evaluation supporting order encl
ADENBAM, E O Licensing Branch 4 83/06/16 FERGUSON, R L
Washington Public Power Supply System 2pp 18987 283 24X
Fiche 50-460, 83/06/16, 8306240017

--8306240025 SER supporting extension of CPPR-134 const completion date
to 910601
* Licensing Branch 4 83/06/16 4pp, 18987 285 24X
Fiche 50-460, 83/06/16, 8306240017

--8306240027 Order extending CPPR-134 const completion date to 910601
EISENHUT, D O Division of Licensing 83/06/16 Washington
Public Power Supply System 3pp 18987 289 24X
Fiche 50-460, 83/06/16, 8306240017

8306210301 Advises that NRC issued order extending CP per Commission
Order CL1-62-29
YOUNG, M A Hearing Branch 4 83/06/17 ORDSSMAN, H, HARBOUR, J,
BRIGHT, G O Atomic Safety and Licensing Board Panel 7pp
18914 025 24X Fiche 50-460, 83/06/17, 8306210301

Q Adjudicatory correspondence

8306010364 Responses to NRC first set of interrogatories Certificate of
Svc encl, Related correspondence
BELL, N Coalition for Safe Power 83/05/24 Office of the
Executive Legal Director 7pp 18681 350 24X
Fiche 50-460, 83/05/24, 8306010364

8306020365 Response supporting State of WA 830523 motion to be
admitted as interested state in OL & CP proceedings
Certificate of Svc encl
REYNOLDS, N S Washington Public Power Supply System REYNOLDS, N S
Debovoise & Liberman 83/05/31 Atomic Safety and Licensing Board
Panel 3pp 18694 262 24X Fiche 50-460, 83/05/31, 8306020365

8306020412 Submits status rept re proposed schedules for remaining
discovery, summary disposition memoranda filing & hearing
commencement Hearing tentatively scheduled for 831104,
WAGNER, M E Hearing Branch 4 83/06/01 ORDSSMAN, H, HARBOUR, J,
BRIGHT, G O Atomic Safety and Licensing Board Panel 3pp
18695 020 24X Fiche 50-460, 83/06/01, 8306020412

8306030347 Status rept & recommendations re future course of
proceeding, per ABLB 830325 memorandum & order Recommended
schedule provided Hearings should not be prolonged
unnecessarily Certificate of Svc encl
REYNOLDS, N S Washington Public Power Supply System REYNOLDS, N S
Debovoise & Liberman 83/06/01 Atomic Safety and Licensing Board
Panel 6pp 18705 001 24X Fiche 50-460, 83/06/01, 8306030347

8306030353 Response in opposition to Coalition for Safe Power 830518
motion to compel licensee to respond to Interrogatories 6, 7,
8 & 9 Intervenor fundamentally misunderstood 830503
objections to interrogatories Certificate of Svc encl
REYNOLDS, N S Washington Public Power Supply System REYNOLDS, N S
Debovoise & Liberman 83/06/01 Atomic Safety and Licensing Board
Panel 9pp 18706 117 24X Fiche 50-460, 83/06/01, 8306030353

8306060308 Discovery status rept & proposed schedule for proceeding
Certificate of Svc encl Related correspondence
BELL, N Coalition for Safe Power 83/06/01 4pp 18729 134 24X
Fiche 50-460, 83/06/01, 8306060308

8306090337 Motion to compel intervenor answers to licensee first set of
interrogatories & requests to produce Responses evasive &
incomplete Certificate of Svc encl
REYNOLDS, N S Washington Public Power Supply System REYNOLDS, N S
Debovoise & Liberman, 83/06/07 Atomic Safety and Licensing Board
Panel 13pp 18795 081 24X Fiche: 50-460, 83/06/07, 8306090337

DOCKETED ITEMS

8306100190 Second memorandum re petitioner standing to intervene
 Requisite interest to support representational standing
 established One litigable contention requirement not met
 Certificate of Svc encl
 REYNOLDS, N S Washington Public Power Supply System * Debevoise &
 Liberman 83/06/08 Atomic Safety and Licensing Board Panel
 7pp 18805 274 24X Fiche 50-460, 83/06/08, 8306100190

8306150302 First set of interrogatories Related correspondence
 ROSOLIE, E Coalition for Safe Power 83/06/09 Office of the
 Executive Legal Director 5pp 18849 162 24X
 Fiche 50-460, 83/06/09, 8306150302

8306150306 Second set of interrogatories Certificate of Svc encl
 Related correspondence
 ROSOLIE, E Coalition for Safe Power 83/06/09 Washington Public
 Power Supply System 6pp 18849 146 24X Fiche 50-460, 83/06/09,
 8306150306

8306170411 Position re Coalition for Safe Power standing to intervene
 Coalition has met interest requirement & should be admitted
 as party if at least one litigable contention submitted
 Certificate of Svc encl
 WAGNER, M E Hearing Branch 4 83/06/16 Atomic Safety and
 Licensing Board Panel 5pp 18890 044 24X Fiche 50-460, 83/06/16,
 8306170411

8306210276 Response supporting State of WA 830509 request to
 participate as interested state in CP extension proceeding
 Certificate of Svc encl
 YOUNG, M A Hearing Branch 4 83/06/16 Atomic Safety and
 Licensing Board Panel 2pp 18915 123 24X Fiche 50-460, 83/06/16,
 8306210276

8306210347 Response supporting State of WA 830609 request to
 participate as interested state in DL proceeding, if
 Coalition for Safe Power petition to intervene granted
 Certificate of Svc encl
 YOUNG, M A Hearing Branch 4 83/06/16 Atomic Safety and
 Licensing Board Panel 2pp 18914 036 24X Fiche 50-460, 83/06/16,
 8306210347

8306210301 Advises that NRC issued order extending CP per Commission
 Order CL1-82-29
 YOUNG, M A Hearing Branch 4 83/06/17 GROSSMAN, H, HARBOUR, J,
 BRIGHT, O D Atomic Safety and Licensing Board Panel 9pp
 18914 025 24X Fiche 50-460, 83/06/17, 8306210301

8306220364 Forwards NRC 830616 order & safety evaluation extending
 const completion date from 820101 to 910101
 REYNOLDS, N S Debevoise & Liberman REYNOLDS, N S Washington
 Public Power Supply System, 83/06/21 GROSSMAN, H, BRIGHT, O D,
 HARBOUR, J Atomic Safety and Licensing Board Panel 7pp
 18944 119 24X Fiche 50-460, 83/06/21, 8306220364

8306240286 Advises that NRC will not respond to licensee 830607 motion to
 compel, directed to Coalition for Safe Power, Discovery
 disputes between licensee & intervenor
 WAGNER, M E Hearing Branch 4 83/06/22 GROSSMAN, H, BRIGHT, O D,
 HARBOUR, J Atomic Safety and Licensing Board Panel 1p 18980 157
 24X Fiche 50-460, 83/06/22, 8306240286

8306290370 Response to licensee 830607 motion to compel to first set of
 interrogatories Updated responses addressed licensee
 concerns thus negating necessity of ASLD ruling Related
 correspondence
 ROSOLIE, E Coalition for Safe Power 83/06/22 Atomic Safety and
 Licensing Board Panel 1p 19055 214 24X Fiche 50-460, 83/06/22,
 8306290370

--8306290375 Updated response to first set of interrogatories Discusses
 decision to defer const & to extend CP Certificate of Svc
 encl Related correspondence
 ROSOLIE, E Coalition for Safe Power 83/06/22 Washington
 Public Power Supply System 5pp 19055 215 24X
 Fiche 50-460, 83/06/22, 8306290370

8306270254 Memorandum holding Coalition for Safe Power meets interest
 requirements for intervenor status ASLD will not rule on
 contentions until State of WA responds to contentions
 GROSSMAN, H Atomic Safety and Licensing Board Panel 83/06/23
 2pp 18990 223 24X Fiche 50-460, 83/06/23, 8306270254

8306270333 Memorandum & order admitting State of WA as interested
 state, to be represented by Energy Facility Site Evaluation
 Council
 GROSSMAN, H Atomic Safety and Licensing Board Panel 83/06/23
 Washington, State of 2pp 18993 155 24X Fiche 50-460, 83/06/23,
 8306270333

8306270348 Memorandum & order admitting State of WA as interested
 state, to be represented by Energy Facility Site Evaluation
 Council State response to petitioner contentions due by
 830712
 GROSSMAN, H Atomic Safety and Licensing Board Panel 83/06/23
 Washington, State of 2pp 18993 141 24X Fiche 50-460, 83/06/23,
 8306270348

8306300047 Response to 830609 second set of interrogatories Certificate
 of Svc encl
 REYNOLDS, N S Washington Public Power Supply System REYNOLDS, N S
 Debevoise & Liberman 83/06/28 Coalition for Safe Power 24pp
 19120 198 24X Fiche 50-460, 83/06/28, 8306300047

8306300127 Memorandum & order granting Coalition for Safe Power 830527
 motion to compel answers to Interrogatories 6, 7, 8 & 9 Info
 sought reasonably calculated to lead to discovery of
 admissible evidence
 GROSSMAN, H Atomic Safety and Licensing Board Panel 83/06/28
 Coalition for Safe Power 4pp 19121 095 24X
 Fiche 50-460, 83/06/28, 8306300127

G Inspection reports, IE Bulletins & correspondence

8306100009 Addl response to FOIA request for documents dtd 820101 or
 after re BALP Forwards App A documents Documents also
 available in PDR
 FELTON, J M Division of Rules and Records 83/04/11 CLARK, R San
 Francisco Examiner 3pp 10815 252 24X Fiche 50-000, 83/04/11,
 8306100009

--8306100014 Submits schedule for Region V BALP Board meetings for
 820928-830523
 ENGELKEN, R H Region 5, Office of Director 82/03/19
 BENTON, H R Office of Nuclear Reactor Regulation, Director 1p
 18815 253 24X Fiche 50-000, 83/04/11, 8306100009

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in
 Well Lifting Device " Svc list encl
 TAYLOR, J M Division of Safeguards & Inspection Programs (Post
 830103) 83/05/26 Consolidated Edison Co of New York, Inc
 129pp 18931 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet "
 Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co of New
 York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods
 Withdrawn at BHRs " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/31 Consolidated Edison Co of New
 York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe
 Operations " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/09 Consolidated Edison Co of New
 York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive &
 Seismically Induced Chatter in Relays Within Printed
 Circuit Cards " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/13 Consolidated Edison Co of New
 York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From
 Degraded Internal Connection Cables " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/13 Consolidated Edison Co of New
 York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
 Epoxy Grouts & Sealers " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co of New
 York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys
 Causing Inoperability of Safety-Related Equipment " Svc list
 encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co of New
 York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions "
 Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/23 Consolidated Edison Co of New
 York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

S Reportable occurrences, LERs & related correspondence

8306070113 Interim deficiency rept re potential failure of reactor vessel internals bolts initially reported on 830502 B&W participating in insp program on operating plants Status rept will be provided upon const restart
DE LORENZO, R A Washington Public Power Supply System 83/05/25
STERNBERG, D M Region 5, Office of Director 2pp 18739 212 24X Fiche 50-460, 83/05/25, 8306070113

8306300159 Part 21 rept re spot welds in Bailey Controls Co cabinets w/smaller diameter than specified Cabinets strengthened by seam & edge welding or bolting
TAYLOR, J H Babcock & Wilcox Co 83/06/23 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 2pp 19119 308 24X Fiche 50-000, 83/06/23, 8306300159

DOCKET 50-461 CLINTON POWER STATION, UNIT 1

A Application/construction stage documents & correspondence

8306160031 Clarifies NRC final response to FDIA request for documents re Zack Co &/or work performed by Zack in const of facilities App D Document 5 deleted since document identical to App A Document 135
FELTON, J M Division of Rules and Records 83/04/14
PRENDERGAST, R Prendergast, R J 1p 18872 356 24X Fiche 50-000, 83/04/14, 8306160031

8306030509 Informs that each LRO-II member must submit numerical value determined by OE for respective plants on fuel assembly lift off displacement due to error in fuel assembly topical rept re LRO-II Generic Issue 2-CPB
HGVAA, T M Assistant Director for Licensing 83/05/23
HOLTZSCHER, D L Licensing Review Group II 3pp 18735 051 24X Fiche 50-000, 83/05/23, 8306030509

8306060373 Responds to 820903 ltr submitting position papers which included Licensing Review Group II proposed solution for Issue 4-MEB, intended to protect in-core instrument tubes from flow-induced vibration issue unresolved
YOUNGBLOOD, B J Licensing Branch I 83/05/26 HOLTZSCHER, D L Licensing Review Group II App 18751 287 24X Fiche 50-000, 83/05/26, 8306060373

8306020620 Informs that fuel load data revised from Jan 1984 to Jan 1986 Press release encl
ABELSON, H Licensing Branch 2 83/05/27 DENTON, H R, CASE, E O, CARTER, J Office of Nuclear Reactor Regulation, Director 2pp 18702 357 24X Fiche 50-461, 83/05/27, 8306020620

8306210231 Forwards Action Plans 1,2,3,4 & 33, in response to Humphrey concerns for NRC review Action 33 re suppression pool temp sensors emergency procedures closed
MULLER, O E Illinois Power Co 83/06/17 SCHWENCER, A Licensing Branch 2 16pp 18916 043 24X Fiche 50-461, 83/06/17, 8306210231

E NRC Safety Evaluation Report (SER), supp's & correspondence

8306060412 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF CLINTON POWER STATION, UNIT NO. 1 Docket No 50-461 (Illinois Power Company, et al)
* Division of Licensing NUREG-0853 902 83/05/31 72pp Available at NRC \$4 50 18747 321 24X Fiche 50-461, 83/05/31, 8306060412

8306070444 Forwards Suppl 2 to SER (NUREG-0853) W/o encl
SCHWENCER, A Licensing Branch 2 83/05/31 MULLER, O Illinois Power Co 1p 18780 351 24X Fiche 50-461, 83/05/31, 8306070444

--8306070446 Forwards Suppl 2 to May 1983 SER (NUREG-0853) W/o encl.
* Office of Nuclear Reactor Regulation, Director 83/05/26, OTTINGER, R. House of Rep, Energy & Commerce 1p 18780 352 24X Fiche 50-461, 83/05/31, 8306070444

--8306070447 Forwards Suppl 2 to May 1983 SER (NUREG-0853) W/o encl.
* Office of Nuclear Reactor Regulation, Director 83/05/26 STIMPSON, A Senate, Environment & Public Works, 1p 18780 353 24X Fiche 50-461, 83/05/31, 8306070444

--8306070451 Forwards Suppl 2 to May 1983 SER (NUREG-0853) W/o encl
* Office of Nuclear Reactor Regulation, Director 83/05/26, UDALL, M. House of Rep, Interior & Insular Affairs 1p 18780 354 24X Fiche 50-461, 83/05/31, 8306070444

F Security, medical, emergency & fire protection plans

8306150285 Responds to util 821203 ltr & May 1982 Amend 16 to FSAR re emergency operations facility (EOF) & backup EOF Proposed site acceptable Add'l EOF features & emergency response facilities to be reviewed during post-implementation review
EISENHUT, D O Division of Licensing 83/06/01 MULLER, O E Illinois Power Co 2pp 18869 318 24X Fiche 50-461, 83/06/01, 8306150285

8306100077 Forwards schedule implementation plan for emergency response capability & list of submittals required by NUREG-0737, Suppl 1, per Generic Ltr 82-33 Procedures generation package will be submitted by 840501
MULLER, O E Illinois Power Co 83/06/06, SCHWENCER, A Licensing Branch 2 5pp 18804 043 24X Fiche 50-461, 83/06/06, 8306100077

8306200409 Forwards "Emergency Response Facilities Design Rept," per NUREG-0737, Suppl 1, in response to Generic Ltr 82-33
MULLER, O E Illinois Power Co 83/06/16 SCHWENCER, A Licensing Branch 2 1p 18704 325 24X Fiche 50-461, 83/06/16, 8306200409

--8306200414 "Emergency Response Facilities Design Rept"
* Illinois Power Co 83/06/16 38pp 18704 326 24X Fiche 50-461, 83/06/16, 8306200409

G Adjudicatory correspondence

8306150226 Response to 830419 questions & document request re Contentions III & IV.
PATTERSON, W F Hearing Branch 3 83/05/23, WILLIAM, P L Illinois, State of 22pp 18846 289 24X Fiche 50-461, 83/05/23, 8306150226

8306080163 Forwards Suppl 2 to SER W/o encl.
ODDARD, R J, Hearing Branch 3 83/06/06 CLARK, H K, PARIS, D H, FERDUSON, O A Atomic Safety and Licensing Board Panel 1p 18772 157 24X Fiche 50-461, 83/06/06, 8306080163

K Utility Final Safety Analysis Report (FSAR) & amends

8306070396 Forwards Amend 25 to FSAR, containing rev to Chapter 17 to resolve SER Outstanding Issue 20 re QA program & SER Confirmatory Issue 6 re containment ultimate strength
HALL, D P Illinois Power Co 83/05/31 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18742 284 24X Fiche 50-461, 83/05/31, 8306070396

--8306070401 Amend 25 to FSAR.
* Illinois Power Co 83/05/31 137pp 18742 285 24X Fiche 50-461, 83/05/31, 8306070396

G Inspection reports, IE Bulletins & correspondence

8306030142 Forwards IE Insp Rept 50-461/83-02 on 830117-21 & 0308-11 & notice of violation
LITTLE, W B Region 3, Office of Director 83/05/16 GERSTNER, W C Illinois Power Co 2pp 18704 268 24X Fiche 50-461, 83/05/16, 8306030142

--8306030144 Notice of violation from insp on 830117-21 & 0308-11
LITTLE, W B Region 3, Office of Director 83/05/16 2pp 18704 270 24X Fiche 50-461, 83/05/16, 8306030142

--8306030147 IE Insp Rept 50-461/83-02 on 830117-21 & 0308-11. Noncompliance noted failure to accomplish activities affecting quality in accordance w/instructions, procedures & drawings
LOVE, R B, WILLIAMS, C C. Region 3, Office of Director 83/05/12 11pp 18704 272 24X Fiche 50-461, 83/05/16, 8306030142

8306220066 Forwards IE Insp Rept 50-461/83-05 on 830318-0315, No noncompliance noted.
KNOP, R C Region 3, Office of Director 83/06/06, GERSTNER, W C, Illinois Power Co 2pp 18928 171 24X Fiche 50-461, 83/06/06, 8306220066

--8306220076 IE Insp Rept 50-461/83-05 on 830318-0315 No noncompliance noted. Major areas inspected: mat'l laydown & storage areas, program control, licensee action on previous insps, welding, heat treat & NDE & stop work recovery activities.
LIVEMORE, H H, HAYES, D W. Region 3, Office of Director, 83/06/03 7pp 18928 173 24X Fiche 50-461, 83/06/06, 8306220066

DOCKETED ITEMS

8306270117 Requests review of util recovery plan to correct deficiencies associated w/NRC 820623 stop work order. Appropriate procedures & instructions revised & training accomplished & documented.
HALL, D P Illinois Power Co 83/06/15 KEPLER, J O Region 3, Office of Director 1p 18788 106 24X Fiche 50-461, 83/06/15, 8306270117

8306270311 Forwards SALP Rept 50-461/82-21 for Oct 1981 - Sept 1982
KEPLER, J O Region 3, Office of Director 83/06/22 GERSTNER, W C Illinois Power Co 2pp 18793 321 24X Fiche 50-461, 83/06/22, 8306270311

--8306270314 SALP Rept 50-461/82-21 for Oct 1981 - Sept 1982 Significant progress in upgrading regulatory performance evident.
* Region 3, Office of Director 83/06/22 27pp 18793 323 24X Fiche 50-461, 83/06/22, 8306270311

--8306270321 Responds to SALP Rept 50-461/82-21 for Oct 1981 - Sept 1982. SM retained as mgt support involved w/const of Facility & increased emphasis placed on hiring & retention of qualified personnel.
GERSTNER, W C Illinois Power Co 83/06/12 KEPLER, J O Region 3, Office of Director 3pp 18793 350 24X Fiche 50-461, 83/06/22, 8306270311

S Reportable occurrences, LERs & related correspondence

8306070289 Interim Deficiency Rept 82-12 re bound sway strut/snubber piping component supports initially reported on 821021 Field Insp of Basic Engineers sway struts & snubbers underway. Next rept expected in 90 days.
HALL, D P Illinois Power Co 83/05/31 KEPLER, J O Region 3, Office of Director 4pp 18776 178 24X Fiche 50-461, 83/05/31, 8306070289

8306070338 Interim rept of Potential Deficiency 83-02 re procedural controls for insp of field counterbolting of safety-related pipe. Initially reported on 830113. Applicable procedures & instructions revised.
HALL, D P Illinois Power Co 83/05/31 KEPLER, J O Region 3, Office of Director 5pp 18742 125 24X Fiche 50-461, 83/05/31, 8306070338

8306100060 Interim rept re vendor shop welding deficiencies on structural steel welds supplied by Rockwell Engineering. Initially reported on 830427. Investigation continuing. Final rept will be submitted in 90 days.
HALL, D P Illinois Power Co 83/05/31 KEPLER, J O Region 3, Office of Director 3pp 18802 172 24X Fiche 50-461, 83/05/31, 8306100060

8306100141 Interim Deficiency Rept 83-01 re qualification of suppliers for measuring & test equipment calibr svcs. Initially reported on 830113. QA instruction for procurement document reviews revised & training provided to QA personnel.
HALL, D P Illinois Power Co 83/05/31 KEPLER, J O Region 3, Office of Director 4pp 18801 255 24X Fiche 50-461, 83/05/31, 8306100141

8306170370 Final Deficiency Rept 82-08 re lack of distribution control for instrument data sheets. Initially reported on 820702. Instrument data sheet books reissued as controlled copies & computer info sys established by Baldwin Assoc.
HALL, D P Illinois Power Co 83/06/06 KEPLER, J O Region 3, Office of Director 7pp 18880 312 24X Fiche 50-461, 83/06/06, 8306170370

8306170383 Final Deficiency Rept 82-07 re breakdown in QA program. Initially reported on 820708. Actions to be taken to ensure timely insps listed.
HALL, D P Illinois Power Co 83/06/06 KEPLER, J O Region 3, Office of Director 7pp 18880 230 24X Fiche 50-461, 83/06/06, 8306170383

8306270334 Interim Deficiency Rept 82-10 re violation of min wall thickness for safety-related piping. Initially reported on 821007. Sargent & Lundy reviewing piping design. Piping lines 1LP21A4 & 1LP21B4 modified. Next rept within 90 days.
HALL, D P Illinois Power Co 83/06/17 KEPLER, J O Region 3, Office of Director 4pp 18793 157 24X Fiche 50-461, 83/06/17, 8306270334

T Hearing transcripts on non-antitrust matters

8306070183 Transcript of 830602 prehearing conference in Urbana, IL. Pg 372-437.
* Atomic Safety and Licensing Board Panel 83/06/02, 66pp 18738 216 24X Fiche 50-461, 83/06/02, 8306070183

DOCKET 50-462 CLINTON POWER STATION, UNIT 2

A Application/construction stage documents & correspondence

8306160031 Clarifies NRC final response to FOIA request for documents re Zack Co &/or work performed by Zack in const of facilities. App D Document 5 deleted since document identical to App A Document 135.
FELTON, J M Division of Rules and Records 83/04/14 PRENDERGAST, R Prendergast, R J 1p 18872 356 24X Fiche 50-000, 83/04/14, 8306160031

DOCKET 50-470 CESSAR SYSTEM 80

A Application/construction stage documents & correspondence

8306090170 Forwards review of CESSAR-F against requirements of 10 CFR rule 10CFR50.34(f) & selective sections of App B & Chapter 3 of CESSAR-F. Only fraction of rule requirements within scope of CESSAR-F. CESSAR-F complies w/rule.
SCHERER, A E Combustion Engineering, Inc 83/05/25 EISENHUT, D O Division of Licensing 103pp 18794 010 24X Fiche 50-470, 83/05/25, 8306090170

8306130428 Summarizes 830425 meeting w/NRC re natural circulation cooldown analysis for CESSAR-F. Reanalysis to be submitted by 830729.

SCHERER, A E Combustion Engineering, Inc 83/06/07 EISENHUT, D O Division of Licensing 1p 18821 229 24X Fiche 50-470, 83/06/07, 8306130428

8306200254 Forwards "Basis for Design of Plant W/o Pipe Whip Restraints for RCS Main Loop Piping," to demonstrate that guillotine-type failure of RCS main loop piping need not be considered in design basis for Sys 80.
SCHERER, A E Combustion Engineering, Inc 83/06/14 EISENHUT, D O Division of Licensing 121pp 18901 202 24X Fiche 50-470, 83/06/14, 8306200254

E NRC Safety Evaluation Report (SER), supp & correspondence

8306200070 Approves request for withholding, per 10CFR2.790, info transmitted by 830228, 0304 & 0503 ltrs re SER Confirmatory Item 7.

THOMAS, C O Standardization & Special Projects Branch 83/06/13 SCHERER, A E Combustion Engineering, Inc 5pp 18708 174 24X Fiche 50-470, 83/06/13, 8306200070

8306200392 Clarifies plant-specific info needed re CESSAR-F supplemental SER, Section 4.4.6, "Statistical Combination of Uncertainties." No plant-specific submittal planned since verification of values to be documented internally.
SCHERER, A E Combustion Engineering, Inc 83/06/15 EISENHUT, D O Division of Licensing 1p 18919 219 24X Fiche 50-470, 83/06/15, 8306200392

DOCKET 50-482 WOLF CREEK GENERATING STATION

A Application/construction stage documents & correspondence

8306060383 Responds to 830509 request for permission to use Paragraph NX-4427 of Winter 1982 Addenda to Section III of ASME Boiler & Pressure Vessel Code re fillet weld requirements. Request acceptable.
YOUNGBLOOD, B J Licensing Branch 1 83/05/26 KOESTER, O L Kansas Gas & Electric Co SCHNELL, D F Union Electric Co 3pp 18748 359 24X Fiche 50-000, 83/05/26, 8306060383

8306080051 Forwards request for addl info re environ qualification plan info requested within 2 wks of receipt of ltr.
YOUNGBLOOD, B J Licensing Branch 1 83/05/31 SCHNELL, D F Union Electric Co KOESTER, O L Kansas Gas & Electric Co 4pp 18787 308 24X Fiche 50-000, 83/05/31, 8306080051

8306080321 Notification of 830620 & 24 meetings w/utls & SNUPPG in Highway, MO & Burlington, KS, respectively, to discuss environ qualification of equipment.
EIDSON, Q E Licensing Branch 1 83/06/02 YOUNGBLOOD, B J Licensing Branch 1 5pp 18787 350 24X Fiche 50-000, 83/06/02, 8306080321

8306080175 Forwards changes to FSAR addendum, Rev 10 re operating QA program (Section 17.2). Updated Table 17.2-1 will be formally incorporated in Rev 11 to FSAR.
KOESTER, O L Kansas Gas & Electric Co 83/06/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 18771 301 24X Fiche 50-482, 83/06/06, 8306080175

DOCKETED ITEMS

347

--8306080178 Changes to FSAR addendum, Rev 10 re operating QA program
 (Section 17.2)
 * Kansas Gas & Electric Co 83/04/30 27pp 18771 304 24X
 Fiche 50-482, 83/06/06, 8306080175

8306140230 Forwards revised pages to design & const QA program &
 revised Page 17 1-15 to SNUPPS Design & Const QA Program
 Pages will be formally incorporated into next rev of SNUPPS
 Design & Const QA Program
 KOESTER, G L Kansas Gas & Electric Co 83/06/10 DENTON, H R
 Office of Nuclear Reactor Regulation, Director COLLINS, J T Region
 4, Office of Director 3pp 18832 296 24X Fiche 50-482, 83/06/10,
 8306140230

--8306140234 Revised pages to design & const QA program
 * Kansas Gas & Electric Co 83/06/10 49pp 18832 299 24X
 Fiche 50-482, 83/06/10, 8306140230

--8306140240 Revised Page 17 1-15 to SNUPPS design & const QA program
 * Standardized Nuclear Unit Power Plant System 83/06/10 3pp
 18832 348 24X Fiche 50-482, 83/06/10, 8306140230

8306220018 Forwards addl info re environ qualification of safety-
 related electrical equipment, in response to NRC 830531 ltr
 FSAR will be updated in next rev to include questions &
 responses
 PETRICK, N A Standardized Nuclear Unit Power Plant System
 83/06/10 DENTON, H R Office of Nuclear Reactor Regulation,
 Director 4pp 18927 318 24X Fiche 50-000, 83/06/10, 8306220018

8306160539 Informs of change in plans for completion of local
 containment leak rate testing Encl info re testing will be
 incorporated into Rev 11 of Wolf Creek FSAR & Rev 12 of
 SNUPPS FSAR
 KOESTER, G L Kansas Gas & Electric Co 83/06/13 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 6pp 18865 043
 24X Fiche 50-482, 83/06/13, 8306160539

8306200312 Forwards until 830523 ltr informing NRC of revised schedule
 for fuel load & commercial operation fuel load scheduled
 for 840815 Commercial operation planned for 850215 Svc
 list encl
 RIDGWAY, D A Shaw, Pittman, Potts & Troubridge RIDGWAY, D A
 Kansas Gas & Electric Co 83/06/15 LAURENSEN, J A , ANDERSON, G C ,
 PAXTON, H C Atomic Safety and Licensing Board Panel 4pp
 18899 300 24X Fiche 50-482, 83/06/15, 8306200312

F Security, medical, emergency & fire protection plans

8306060191 Forwards Rev 10 to radiological emergency response plan
 (filed in PDR Category F)
 KOESTER, G L Kansas Gas & Electric Co 83/05/31 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 10pp 18720 001
 24X Fiche 50-482, 83/05/31, 8306060191

--8306060195 Rev 10 to radiological emergency response plan
 * Kansas Gas & Electric Co 83/04/30 205pp 18721 333 24X
 Fiche 50-482, 83/05/31, 8306060191

8306150482 Releases public version of revised radiological emergency
 response plan.
 FELTON, J M Division of Rules and Records 83/06/06 Document
 Management Branch 1p 18868 039 24X Fiche 50-482, 83/06/06,
 8306150482

--8306150487 Public version of Rev 10 to radiological emergency response
 plan Revised plan will be included in FSAR, Rev 10 W/830429
 ltr
 *, KOESTER, G L Kansas Gas & Electric Co 83/04/30 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 12Bpp 18868 040
 24X Fiche 50-482, 83/06/06, 8306150482

8306220098 Forwards Suppl 2 to GER (NUREG-0881) W/o encl
 YOUNGLODD, B J Licensing Branch 1 83/06/16 KOESTER, G L Kansas
 Gas & Electric Co 2pp 18977 346 24X Fiche 50-482, 83/06/16,
 8306220098

G. Adjudicatory correspondence

8306160593 Forwards collation of intervenor interrogatory responses
 identified in Paragraphs 6(a)-(h) of intervenor 830512
 response to util objections Svc list encl
 SILBERG, J E Shaw, Pittman, Potts & Troubridge SILBERG, J E
 Kansas Gas & Electric Co 83/06/13 LAURENSEN, J A , ANDERSON, G C ,
 PAXTON, H C Atomic Safety and Licensing Board Panel 47pp
 18866 048 24X Fiche 50-482, 83/06/13, 8306160593

8306200318 Forwards "Wyle Research Rept (WR B2-36), Final Design of
 Alert & Notification Sys for Wolf Creek Generating Station"
 Svc list encl Related correspondence W/o rept
 SILBERG, J E Shaw, Pittman, Potts & Troubridge SILBERG, J E,
 Kansas Gas & Electric Co 83/06/13 LAURENSEN, J A , ANDERSON, G C ,
 PAXTON, H C Atomic Safety and Licensing Board Panel 3pp
 18899 209 24X Fiche 50-482, 83/06/13, 8306200318

8306200312 Forwards until 830523 ltr informing NRC of revised schedule
 for fuel load & commercial operation fuel load scheduled
 for 840815 Commercial operation planned for 850215 Svc
 list encl
 RIDGWAY, D A Shaw, Pittman, Potts & Troubridge RIDGWAY, D A
 Kansas Gas & Electric Co 83/06/15 LAURENSEN, J A , ANDERSON, G C ,
 PAXTON, H C Atomic Safety and Licensing Board Panel 4pp
 18899 300 24X Fiche 50-482, 83/06/15, 8306200312

8306220082 Forwards map depicting location & range of warning sirens
 recommended for alert & notification sys, as part of rept
 served on 830613 Svc list encl W/o map
 RIDGWAY, D A Shaw, Pittman, Potts & Troubridge RIDGWAY, D A
 Kansas Gas & Electric Co 83/06/15 LAURENSEN, J A , PAXTON, H C ,
 ANDERSON, G C Atomic Safety and Licensing Board Panel 3pp
 18930 154 24X Fiche 50-482, 83/06/15, 8306220082

8306230358 Forwards revised pages modifying compilation of intervenor
 interrogatory responses Certificate of Svc encl Related
 correspondence
 RIDGWAY, D A Shaw, Pittman, Potts & Troubridge RIDGWAY, D A,
 Kansas Gas & Electric Co 83/06/21 LAURENSEN, J A , ANDERSON, G C ,
 PAXTON, H C Atomic Safety and Licensing Board Panel 12pp
 18943 319 24X Fiche 50-482, 83/06/21, 8306230358

8306290522 Responds to applicant collation of intervenor interrogatory
 responses, submitted in 830613 ltr Some responses will be
 amended Listed amends not agreed upon Svc list encl Related
 correspondence
 SIMPSON, J M Simpson, J M SIMPSON, J M Affiliation Unknown
 83/06/22 LAURENSEN, J A , ANDERSON, G C , PAXTON, H C Atomic Safety
 and Licensing Board Panel 6pp 19052 203 24X
 Fiche 50-482, 83/06/22, 8306290522

8306280514 Forwards Change Page 7, for insertion into 830613
 compilation Svc list encl
 RIDGWAY, D A Shaw, Pittman, Potts & Troubridge 83/06/24,
 LAURENSEN, J A , ANDERSON, G C , PAXTON, H C Atomic Safety and
 Licensing Board Panel 4pp 19017 234 24X Fiche 50-482, 83/06/24,
 8306280514

8306300138 Forwards GER Suppl 2, (NUREG-0881) W/o encl
 KARMAN, M Hearing Branch 1 83/06/28 LAURENSEN, J A , PAXTON, H C ,
 ANDERSON, G C Atomic Safety and Licensing Board Panel 1p
 19168 118 24X Fiche 50-482, 83/06/28, 8306300138

K Utility Final Safety Analysis Report (FSAR) & amends

8306060191 Forwards Rev 10 to FSAR (filed in PDR Category K) & Rev 10
 to radiological emergency response plan (filed in PDR
 Category F) Certificate of Svc encl
 KOESTER, G L Kansas Gas & Electric Co 83/05/31 DENTON, H R,
 Office of Nuclear Reactor Regulation, Director 10pp 18720:001
 24X Fiche 50-482, 83/05/31, 8306060191

--8306060194 Rev 10 to FSAR
 * Kansas Gas & Electric Co 83/04/30 483pp 18720:010 24X
 Fiche 50-482, 83/05/31, 8306060191

Q Inspection reports, IE Bulletins & correspondence

8306140354 Confirms Region IV plan to perform independent NDE
 verification insp on 830606-17 Addl info on documentation
 selected for insp encl
 OAGLIARDO, J E Division of Resident, Reactor Project & Engineering
 Programs 83/05/11 KOESTER, G L Kansas Gas & Electric Co 6pp
 18832 186 24X Fiche 50-482, 83/05/11, 8306140354

8306140245 Forwards IE Insp Rept 50-482/83-08 on 830418-22 No
 noncompliance noted
 SEIDLE, W C Region 4, Office of Director 83/05/13 KOESTER, G L,
 Kansas Gas & Electric Co 2pp 18833 005 24X
 Fiche 50-482, 83/05/13, 8306140245

--8306140249 IE Insp Rept 50-482/83-08 on 830418-22 No noncompliance
 noted Major areas inspected safety-related piping sys for
 selection of welds for NRC independent insp program
 GILBERT, L D, JOHNSON, W D, HUNNICUTT, D M Region 4, Office of
 Director 83/05/13 4pp 18833:007 24X Fiche 50-482, 83/05/13,
 8306140245

DOCKETED ITEMS

8306130393 Responds to NRC 830422 ltr re violations noted in IE Insp Rept 50-482/83-07 Corrective actions listed Daniel Const Co procedures/activities revised to include definite test control criteria per Corrective Action Rept 1-0-0024 KOESTER, O L Kansas Gas & Electric Co 83/05/20 SEIDLE, W C Region 4, Office of Director 3pp 18922 216 24X Fiche 50-482, 83/05/20, 8306130393

8306140207 Forwards IE Insp Rept 50-482/83-11 on 830401-30 & notice of violation SEIDLE, W C Region 4, Office of Director 83/05/20 KOESTER, O L Kansas Gas & Electric Co 2pp 18932 264 24X Fiche 50-482, 83/05/20, 8306140207

--8306140212 Notice of violation from insp on 830401-30. "Region 4, Office of Director 83/05/20 1p 18932 266 24X Fiche 50-482, 83/05/20, 8306140207

--8306140220 IE Insp Rept 50-482/83-11 on 830401-30. Noncompliance noted failure to follow procedures re GC insp checklist for two auxiliary feedwater sys spring hangers SCHUM, W D JOHNSON, W D Region 4, Office of Director 83/05/19 3pp 18932 267 24X Fiche 50-482, 83/05/20, 8306140207

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306270088 Informs that response to notice of violation contained in IE Insp Rept 50-482/83-10 will be submitted by 830624 KOESTER, O L Kansas Gas & Electric Co 83/06/03 SEIDLE, W C Region 4, Office of Director 1p 18773 042 24X Fiche 50-482, 83/06/03, 8306270088

8306080184 Ack receipt of 830520 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-482/83-07 Program to control all aspects of contractor testing should be developed at earliest practicable time SEIDLE, W C Region 4, Office of Director 83/06/06 KOESTER, O L Kansas Gas & Electric Co 1p 18770 359 24X Fiche 50-482, 83/06/06, 8306080184

--8306080188 Responds to NRC 830422 ltr re violations noted in IE Insp Rept 50-482/83-07 Corrective actions/procedures/activities identified will be revised to include definitive test control criteria KOESTER, O L Kansas Gas & Electric Co 83/05/20 SEIDLE, W C Region 4, Office of Director 3pp 18770 360 24X Fiche 50-482, 83/06/06, 8306080184

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

110 IE Info Notice 83-37, "Transformer Failure Resulting From Internal Connection Cables " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8306070010

Environmentally Qualify

ness & Engineering
Consolidated Edison Co. of New
50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

9 Reportable occurrences, LERs & related correspondence

8306230277 Part 21 rept re defect in hoist assembly 7/3/79 Assembly welded w/60-degree rather than 30-degree elbow installed Condition reported to Bechtel SHAFFER, J C Metal Bellows Comp 83/05/09 COLLINS, J T Region 4, Office of Director 4pp 18945 138 24X Fiche 50-000, 83/05/09, 8306230277

8306030220 Final Part 21 rept re deficiency in DS-416 reactor trip switchgear undervoltage attachment (SDR-83-07) Initially reported on 830421 Attachments to be replaced Also reported by Westinghouse per Part 21 SEIKEN, B J Standardized Nuclear Unit Power Plant System 83/03/23 KEPLER, J O Region 3, Office of Director COLLINS, J T Region 4, Office of Director 3pp 18703 287 24X Fiche 50-000, 83/03/24, 8306030220

8306070194 Interim deficiency rept re welds on Bergen - Paterson sway struts Initially reported on 830224 Majority of welds evaluated No adverse safety concerns identified Next rept will be submitted by 830718 KOESTER, O L Kansas Gas & Electric Co 83/05/26 SEIDLE, W C Region 4, Office of Director 1p 18746 295 24X Fiche 50-482, 83/05/26, 8306070194

8306070262 Interim deficiency rept re loose parts in steam generators Initially reported on 830426 Westinghouse evaluation of safety implications underway Status rept will be submitted by 830815 KOESTER, O L Kansas Gas & Electric Co 83/05/26 SEIDLE, W C Region 4, Office of Director 2pp 18740 337 24X Fiche 50-482, 83/05/26, 8306070262

8306070345 Final significant deficiency rept re lockup of RM-23 display in radiation monitoring sys Initially reported on 830223 Circuit boards returned to vendor for mod & testing Modified boards will be installed prior to fuel load. SEIKEN, B J Standardized Nuclear Unit Power Plant System 83/05/27 KEPLER, J O Region 3, Office of Director COLLINS, J T Region 4, Office of Director 7pp 18742 145 24X Fiche 50-482, 83/05/27, 8306070345

8306100183 Final Deficiency Rept 83-01 re faulty Westinghouse CMD gate valve position indication Initially reported on 830121 Valve mods & adjustments to be performed per Westinghouse Field Change Notices SAPM-10605 & SCPM-10602 PETRICK, N A Standardized Nuclear Unit Power Plant System 83/05/31 COLLINS, J T Region 4, Office of Director KEPLER, J O Region 3, Office of Director 3pp 18005 285 24X Fiche 50-000, 83/05/31, 8306100183

8306090231 Interim deficiency rept re inadequate matl control for special scope items Results of numerous insps, tests & document reviews tabulated & will be sent to AE within 2 wks for final evaluation Next rept expected by 830901 KOESTER, O L Kansas Gas & Electric Co 83/06/01 SEIDLE, W C Region 4, Office of Director 1p 18746 238 24X Fiche 50-482, 83/06/01, 8306090231

8306130138 Interim deficiency rept re workmanship on Swagelok fittings Initially reported on 830215 Info obtained from insps & testing of various tubing installations transmitted to AE for evaluation Next rept will be submitted by 830808 KOESTER, O L Kansas Gas & Electric Co 83/06/03 SEIDLE, W C Region 4, Office of Director 1p 18824 281 24X Fiche 50-482, 83/06/03, 8306130138

8306160565 Final deficiency rept re use of Teflon tape in instrument lines Initially reported on 830504 List of sys where use of Teflon tape or compound could have potentially adverse implications being developed KOESTER, O L Kansas Gas & Electric Co 83/06/03 SEIDLE, W C Region 4, Office of Director 2pp 18866 103 24X Fiche 50-482, 83/06/03, 8306160565

DOCKETED ITEMS

349

8306100125 Part 21 rept re incorrect assembly of Vitro Labs 175-volt battery monitor used at site faulty Zener diode will cause monitor to issue battery failure indication
DIXON, D J General Electric Co 83/06/06 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 1p 18802 010 24X
Fiche 50-482, 83/06/06, 8306100125

8306130043 Fourth interim deficiency rept re diesel generator belt torque Initially reported on 820614 Retorquing of diesel studs/nut combinations completed Results forwarded to manufacturer for evaluation Next rept expected by 830801
KOESTER, G L Kansas Gas & Electric Co 83/06/06 SEIDLE, W C Region 4, Office of Director 1p 1884 247 24X
Fiche 50-482, 83/06/06, 8306130043

8306160415 Final deficiency rept re containment spray/RMR motor oil foaming Foaming observed in oil sight gauges determined to be normal Condition not reportable per 10CFR50.55(e)
KOESTER, G L Kansas Gas & Electric Co 83/06/10 SEIDLE, W C Region 4, Office of Director 1p 18859 309 24X
Fiche 50-482, 83/06/10, 8306160415

8306170286 Final deficiency rept re diesel generator thermostatic valves Initially reported on 820622 Valves reworked & found free of potential defect Valves replaced w/unit containing overrun assembly utilizing cotter pin
KOESTER, G L Kansas Gas & Electric Co 83/06/13 SEIDLE, W C Region 4, Office of Director 1p 18860 053 24X
Fiche 50-482, 83/06/13, 8306170286

8306270352 Final deficiency rept re component testing QA program Initially reported on 830209 Revised procedures reviewed No discrepancies identified Component test program resumed Condition withdrawn as potential 10CFR50.55(e) item
KOESTER, G L Kansas Gas & Electric Co 83/06/17 SEIDLE, W C Region 4, Office of Director 2pp 18993 149 24X
Fiche 50-482, 83/06/17, 8306270352

8306280335 Interim deficiency rept re insufficient torque on structural steel bolted connections Initially reported on 830204 Corrective Action Rept 1-C-006 initiated to track evaluation & resolution of problem Next rept by 830909
KOESTER, G L Kansas Gas & Electric Co 83/06/20 SEIDLE, W C Region 4, Office of Director 2pp 19001 310 24X
Fiche 50-482, 83/06/20, 8306280335

DOCKET 87N-50-483 CALLAWAY PLANT, UNIT 1

A Application/construction stage documents & correspondence

8306060383 Responds to 830909 request for permission to use Paragraph NX-4427 of Winter 1982 Addenda to Section III of ASME Boiler & Pressure Vessel Code re fillet weld requirements Request acceptable
YOUNGBLOOD, B J Licensing Branch 1 83/05/26 KOESTER, G L Kansas Gas & Electric Co SCHNELL, D F Union Electric Co 3pp, 18748 359 24X Fiche 50-000, 83/05/26, 8306060383

8306080051 Forwards request for addl info re environ qualification plan Info requested within 2 wks of receipt of ltr
YOUNGBLOOD, B J Licensing Branch 1 83/05/31 SCHNELL, D F Union Electric Co KOESTER, G L Kansas Gas & Electric Co 4pp 18787 308 24X Fiche 50-000, 83/05/31, 8306080051

8306080438 Notification of 830617 meeting w/util in Bethesda, MD to discuss clarifications to QA program
EDISON, O E Licensing Branch 1 83/06/01 YOUNGBLOOD, B J Licensing Branch 1 4pp 18792 209 24X Fiche 50-483, 83/06/01, 8306080438

8306080321 Notification of 830620 & 24 meetings w/util & SNUPPS in Highway, MO & Burlington, KB, respectively, to discuss environ qualification of equipment
EDISON, O E Licensing Branch 1 83/06/02 YOUNGBLOOD, B J Licensing Branch 1 5pp 18789 350 24X Fiche 50-000, 83/06/02, 8306080321

8306100147 Forwards revised draft versions of, "Cultural Resources Mgt Plan for Residual Lands" & "Phase 1 Cultural Resources Survey & Assessment to Residual Lands" & responses to SHPD comments
SCHNELL, D F Union Electric Co, 83/06/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 18807 237, 24X
Fiche 50-483, 83/06/03, 8306100147

8306100148 Revised draft of, "Cultural Resources Mgt Plan for Residual Lands at Union Electric Co"
* Union Electric Co 83/06/03 49pp 18807 281 24X
Fiche 50-483, 83/06/03, 8306100147

8306100152 Revised draft of, "Phase 1 Cultural Resources Survey & Assessment to Residual Lands at Union Electric Co Callaway Nuclear Power Plant"
RAY, J H, MORLIN, E M, MCNERNEY, M J American Resources Group, Ltd 83/04/03 49pp 18807 332 24X Fiche 50-483, 83/06/03, 8306100147

8306220018 Forwards addl info re environ qualification of safety-related electrical equipment, in response to NRC 830531 ltr FSAR will be updated in next rev to include questions & responses
PETRICK, N A Standardized Nuclear Unit Power Plant System 83/06/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 18927 318 24X Fiche 50-000, 83/06/10, 8306220018

F Security, medical, emergency & fire protection plans

8306150454 Releases public version of revised emergency plan administrative procedure
FELTON, J M Division of Rules and Records, 83/06/06 Document Management Branch 1p 18869 148 24X Fiche 50-483, 83/06/06, 8306150454

8306150455 Public version of Rev O to Emergency Plan Administrative Procedure APA-ZZ-00102, "Emergency Operating Procedures Writers Guide." Item numbers an encl correspond to numbers used in Generic Ltr 82-33 W/830511 ltr
SCOTT, W O, SCHNELL, D F Union Electric Co 83/04/07, DENTON, H R Office of Nuclear Reactor Regulation, Director 49pp, 18869 149 24X Fiche 50-483, 83/06/06, 8306150454.

8306170473 Responds to SNUPPS 810601 & util 821203 ltr re primary & backup emergency operations facilities (EOF) Location of primary & backup EOF approved. Approval of addl features to be determined during post-implementation appraisal
EISENHUT, D O Division of Licensing 83/06/06 SCHNELL, D F Union Electric Co 3pp 18894 335 24X Fiche 50-483, 83/06/06, 8306170473

8306230476 Forwards SALP Rept 50-483/83-09 for Oct 1981 - Sept 1982 Overall performance satisfactory Issue re emergency planning zone resolved.
KEPPLER, J O Region 3, Office of Director 83/06/20 SCHNELL, D F Union Electric Co 2pp 18941 160 24X Fiche 50-483, 83/06/20, 8306230476

8306230481 Clarifies Page 9 of SALP Rept 50-483/83-09 transmitted by NRC 830126 ltr re licensing activities to reduce size of emergency planning zone (EPZ) excluding two eastern most counties Reduction of EPZ not formally requested
SCHNELL, D F Union Electric Co 83/02/23 HIND, J A Division of Emergency Preparedness & Operational Support 1p, 18941, 184, 24X Fiche 50-483, 83/06/20, 8306230476.

G Adjudicatory correspondence

8306010146 Informs that author will represent NRC in 830622 oral argument in response to ASLAP 830429 order
PERLIS, R O Hearing Branch 3 83/05/27 SHOEMAKER, C J Atomic Safety and Licensing Appeal Panel, 1p 18674 050 24X
Fiche 50-483, 83/05/27, 8306010146

8306030331 Motion & response to applicant 830520 motion for summary disposition of JO Reed Contentions 1 through 11 & 13 through 20 Applicant motion should be denied since matl facts should be heard w/Certificates of Svc.
REED, J O 83/05/31 Atomic Safety and Licensing Board Panel 17pp 18709 001 24X Fiche 50-483, 83/05/31, 8306030331.

8306100045 Motion for extension until 830617 to respond to util 830520 20 motions for summary disposition Large number of filings creates undue burden Negotiations initiated to dispose of contentions Certificate of Svc encl.
ODDARD, R J Hearing Branch 3 83/06/08 Atomic Safety and Licensing Board Panel 4pp 18802 115 24X Fiche: 50-483, 83/06/08, 8306100045

8306150287 Order granting NRC request for extension until 830617 to file responses to pending motions for summary disposition.
OLEASON, J P Atomic Safety and Licensing Board Panel 83/06/10 Office of the Executive Legal Director 1p, 18849:173, 24X
Fiche 50-483, 83/06/10, 8306150287

8306160314 Answer to JO Reed 830531 motion & response to applicant motion for summary disposition of JO Reed contentions Temporary funding of OH Stanfill position irrelevant & accusation of bias w/o foundation. Certificate of Svc encl.
BAKTER, T A Union Electric Co BAKTER, T A, Shaw, Pittman, Potts & Trowbridge 83/06/13, Atomic Safety and Licensing Board Panel, 4pp 18860 048, 24X Fiche: 50-483, 83/06/13, 8306160314.

DOCKETED ITEMS

--8306160322 Affidavit of WR Beatty informing of erroneous statements in JO Reed 830531 Filing on status of CW Stanfill Stanfill is not until employee Util temporarily funds position but exercises no control over position
BEATY, W R Union Electric Co BEATY, W R Missouri, State of
83/06/10 4pp 18860 052 24X Fiche 50-483,83/06/13,8306160314

8306210266 Advises of partial settlement re Reed contentions on emergency planning Settlement discussions will be held on Contentions 4, 11 & 15 Hearings will be held on Contentions 6 & 16 Remaining contentions will be withdrawn
PERLIS, R G Hearing Branch 3 83/06/17 GLEASON, J P, KLINE, J R, BRIGHT, G D Atomic Safety and Licensing Board Panel 2pp
18919 031 24X Fiche 50-483,83/06/17,8306210266

--8306210271 Settlement agreement re disposition of Reed contentions & util motions for summary disposition Util agrees to withdraw motions re Contentions 6 & 16 Meeting scheduled for 830623 or 24 to settle Contentions 4, 11 & 15 Draft order encl
PERLIS, R G Hearing Branch 3 83/06/16 4pp 18915 033 24X
Fiche 50-483,83/06/17,8306210266

8306220132 Forwards settlement agreement executed by util
BAXTER, T A Shaw, Pittman, Potts & Trowbridge BAXTER, T A Union
Electric Co 83/06/20 GLEASON, J P, BRIGHT, G D, KLINE, J R
Atomic Safety and Licensing Board Panel 1p 18926 152 24X
Fiche 50-483,83/06/20,8306220132

--8306220137 Settlement agreement, executed by util re disposition of J Reed contentions Util will withdraw motion for summary disposition of Reed Contentions 6 & 16 Parties will attempt to settle Contentions 4, 11 & 15 Svc list encl
BAXTER, T A Union Electric Co 83/06/20 3pp 18926 143 24X
Fiche 50-483,83/06/20,8306220132

8306230344 Settlement agreement re disposition of J Reed contentions & util motions for summary disposition Util will withdraw motions for summary disposition of Contentions 6 & 16 Certificate of Svc encl
REED, J O Reed, J O 83/06/20 3pp 18942 276 24X
Fiche 50-483,83/06/20,8306230344

8306270137 Order ratifying settlement agreement of parties Util motion for summary disposition of Reed Contentions 6 & 16 dismissed Reed Contentions 1, 2, 3, 5, 7, 8, 9, 10, 13, 14, 17, 18, 19 & 20 dismissed NRC responses to motions due 830701
GLEASON, J P Atomic Safety and Licensing Board Panel 83/06/23
Union Electric Co 1p 18988 182 24X Fiche 50-483,83/06/23,8306270137

G Inspection reports, IE Bulletins & correspondence

8306030180 Forwards IE Insp Rept 50-483/83-06 on 830411-14 No noncompliance noted.
LITTLE, W B Region 3, Office of Director 83/05/20 SCHNELL, D F
Union Electric Co 2pp 18704 007 24X Fiche 50-483,83/05/20,8306030180

--8306030185 IE Insp Rept 50-483/83-06 on 830411-14 No noncompliance noted Major areas inspected 10CFR50 55(e) items, IE bulletins, 10CFR21 items, circulars, NCRB piping, review of quality records & work activities
WARD, K D, DANIELSON, D H Region 3, Office of Director 83/05/20
12pp 18704 009 24X Fiche 50-483,83/05/20,8306030180

8306060241 Forwards IE Insp Rept 50-483/83-05 on 830301-0415 & notice of violation
KNOP, R C Region 3, Office of Director 83/05/20 SCHNELL, D F
Union Electric Co 2pp 18727 281 24X Fiche 50-483,83/05/20,8306060241

--8306060242 Notice of violation from insp on 830301-0415
KNOP, R C Region 3, Office of Director 83/05/20 2pp
18727 283 24X Fiche 50-483,83/05/20,8306060241

--8306060244 IE Insp Rept 50-483/83-05 on 830301-0415 Noncompliance noted untimely audit response, inadequate procedures & inadequate delineation of authorities & responsibilities
NEIBLER, J H, KONKLIN, J E Region 3, Office of Director 83/05/20 6pp 18727 285 24X Fiche 50-483,83/05/20,8306060241

8306100162 Forwards IE Insp Rept 50-483/83-08 on 830426-28 No noncompliance noted
STREETER, J F Region 3, Office of Director 83/05/23 SCHNELL, D F
Union Electric Co 2pp 18805 128 24X Fiche 50-483,83/05/23,8306100162

--8306100169 IE Insp Rept 50-483/83-08 on 830426-28 No noncompliance noted Major areas inspected preparation & implementation status of licensee operational GA program.
HABBE, R A, HAWKINS, F C Region 3, Office of Director 83/05/23
3pp 18805 130 24X Fiche 50-483,83/05/23,8306100162

8306100165 Forwards IE Insp Rept 50-483/83-07 on 830426-28 No noncompliance noted
PAPERIELI, D C J Region 3, Office of Director 83/05/23
SCHNELL, D F Union Electric Co 2pp 18801 198 24X
Fiche 50-483,83/05/23,8306100165

--8306100167 IE Insp Rept 50-483/83-07 on 830426-28 No noncompliance noted Major areas inspected preoperational radiological environ monitoring program, including mgt controls, QA & site tour
ROZAK, S, OESTHANN, M J, SCHUMACHER, M C Region 3, Office of Director 83/05/25 5pp 18801 200 24X Fiche 50-483,83/05/25,8306100165

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 12pp 18931 043 24X Fiche 50-000,83/05/26,8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 11pp 18732 085 24X Fiche 50-000,83/05/26,8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 11pp 18732 208 24X Fiche 50-000,83/05/31,8305110461

8306070137 Ack receipt of 830510 ltr informing NRC of steps taken to correct violations noted in IL Insp Rept 50-483/83-02
Submitted of test procedures per FSAR (chapter 14 required 60 days prior to test performance)
SPESARD, R L Division of Engineering 83/06/01 SCHNELL, D F
Union Electric Co 1p 18739 216 24X Fiche 50-483,83/06/01,8306070137

--8306070145 Responds to NRC 830418 ltr re violations noted in IF Insp Rept 50-483/83-02 Corrective actions minor change notice added to CS-03EPO1 to ensure recording of accumulator temps in test log prior to repressurization
SCHNELL, D F Union Electric Co 83/05/18 SPESARD, R L
Division of Engineering 2pp 18739 217 24X
Fiche 50-483,83/06/01,8306070137

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 11pp 18830 280 24X Fiche 50-000,83/06/09,8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 11pp 18920 225 24X Fiche 50-000,83/06/13,8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 24pp 18921 001 24X Fiche 50-000,83/06/13,8306090010

8306210187 Ack receipt of 830603 ltr informing NRC of steps taken to correct violations noted in IL Insp Rept 50-483/82-20
SPESARD, R L Division of Engineering 83/06/14 SCHNELL, D F
Union Electric Co 1p 18914 122 24X Fiche 50-483,83/06/14,8306210187

--8306210198 Responds to NRC 830315 ltr re violations noted in IF Insp Rept 50-483/82-20 Corrective actions piping seismic analyzer performed on snubbers to identify ineffective areas & overstressed piping Equipment nozzle acceptable
SCHNELL, D F Union Electric Co 83/06/03 LITTLE, W A Region 3, Office of Director 7pp 18914 123 24X Fiche 50-483,83/06/14,8306210187

8306230476 Forwards SALP Rept 50-483/83-09 for Oct 1981 - Sept 1982 Overall performance satisfactory Issue re emergency planning zone resolved
KEPPLER, J G Region 3, Office of Director 83/06/20 SCHNELL, D F
Union Electric Co 2pp 18941 160 24X Fiche 50-483,83/06/20,8306230476

--8306230477 SALP Rept 50-483/83-09 for Oct 1981 - Sept 1982
* Region 3, Office of Director 83/06/20 17pp 18941 162 24X
Fiche 50-483,83/06/20,8306230476

DOCKETED ITEMS

36

--B306230479 Confirms B30204 meeting to discuss SALP Rept 50-483/83-09 for Oct 1981 - Sept 1982
HIND, J A Division of Emergency Preparedness & Operational Support B3/01/24 SCHNELL, D F Union Electric Co 3pp 18941 181 24X Fiche 50-483, 83/06/20, B306230476

--B306230481 Clarifies Page 9 of SALP Rept 50-483/83-09 transmitted by NRC B30126 ltr re licensing activities to reduce size of emergency planning zone (EPZ) excluding two eastern most counties Reduction of EPZ not formally requested
SCHNELL, D F Union Electric Co B3/02/23 HIND, J A Division of Emergency Preparedness & Operational Support 1p 18941 184 24X Fiche 50-483, 83/06/20, B306230476

B306300170 Forwards IE Insp Rept 50-483/83-11 on B30414-0531 & notice of violation
KNOP, R C Region 3, Office of Director B3/06/20 SCHNELL, D F Union Electric Co 2pp 19122 056 24X Fiche 50-483, 83/06/20, B306300170

--B306300182 Notice of violation from insp on B30416-0531
KNOP, R C Region 3, Office of Director B3/06/17 1p 19122 058 24X Fiche 50-483, 83/06/20, B306300170

--B306300186 IE Insp Rept 50-483/83-11 on B30416-0531 Noncompliance noted failure of insp program to adequately identify broken & missing parts on safety-related pipe supports
NEISLER, J H, KONKALIN, J E Region 3, Office of Director B3/06/17 6pp 19122 059 24X Fiche 50-483, 83/06/20, B306300170

B305110475 IE Info Notice B3-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/06/22 Consolidated Edison Co of New York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, B305110475

B305110477 IE Info Notice B3-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, B305110477

B305110479 IE Info Notice B3-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, B305110477

B305110483 IE Info Notice B3-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, B305110483

B306300084 Ack receipt of B30615 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-483/83-05
KNOP, R C Region 3, Office of Director B3/06/27 SCHNELL, D F Union Electric Co 1p 19048 249 24X Fiche 50-483, 83/06/27, B306300084

--B306300090 Responds to NRC B30520 ltr re violations noted in IE Insp Rept 50-483/83-03 Corrective actions test program surveillance group program being revised to upgrade & establish requirements for witnessing test activities
SCHNELL, D F Union Electric Co B3/06/15 KNOP, R C Region 3, Office of Director 4pp 19048 250 24X Fiche 50-483, 83/06/27, B306300084

B Reportable occurrences, LFNs & related correspondence

B306230277 Part 21 rept re defect in hose assembly 77379 Assembly welded w/60-degree rather 30-degree elbow installed
Condition reported to Bechtel
SHAFFER, J C Metal Bellows Corp B3/05/09 COLLINS, J T Region 4, Office of Director 4pp 18945 138 24X Fiche 50-000, 83/05/09, B306230277

B306030220 Final Part 21 rept re deficiency in D9-416 reactor trip switchgear undervoltage attachment (SDR-83-07) Initially reported on B30421 Attachments to be replaced Also reported by Westinghouse per Part 21
SEIKEN, S J Standardized Nuclear Unit Power Plant System B3/05/23 KEPLER, J G Region 3, Office of Director COLLINS, J T Region 4, Office of Director 3pp 18703 287 24X Fiche 50-000, 83/05/23, B306030220

B306070345 Final significant deficiency rept re lockup of RM-23 display in radiation monitoring sys Initially reported on B30223 Circuit boards returned to vendor for mod & testing Modified boards will be installed prior to fuel load
SEIKEN, S J Standardized Nuclear Unit Power Plant System B3/05/27 KEPLER, J G Region 3, Office of Director COLLINS, J T Region 4, Office of Director 7pp 18742 145 24X Fiche 50-482, 83/05/27, B306070345

B306100183 Final Deficiency Rept B3-01 re faulty Westinghouse EMD gate valve position indication Initially reported on B30121. Valve mods & adjustments to be performed per Westinghouse Field Change Notices SAPH-1060b & SCPM-10602
PETRICK, N A Standardized Nuclear Unit Power Plant System B3/05/31 COLLINS, J T Region 4, Office of Director KEPLER, J G Region 3, Office of Director 3pp 18805 285 24X Fiche 50-000, 83/05/31, B306100183

B306170279 Final deficiency & Part 21 Repts U-53 re defective plastic molding utilized in circuit boards supplied by Forboro Co Initially reported on B30511 Components returned to vendor for rework/replacement
SCHNELL, D F Union Electric Co B3/06/01 KEPLER, J G Region 3, Office of Director 1p 18877 024 24X Fiche 50-483, 83/06/01, B306170279

B306270235 Final Deficiency Rept U-54 & Part 21 rept re failure of closed limit switches to reset on containment isolation valves HV-7126 & HV-7180 Initially reported on B30516 Compensating spring installed on actuating arm
SCHNELL, D F Union Electric Co B3/06/16 KEPLER, J G Region 3, Office of Director 1p 18788 250 24X Fiche 50-483, 83/06/16, B306270235

T Hearing transcripts on non-antitrust matters

B306270074 Transcript of B30622 oral argument in Bethesda, MD Pp 1-B3 + Atomic Safety and Licensing Appeal Panel B3/06/22 83pp, 19013 148 24X Fiche 50-483, 83/06/22, B306270074

DOCKET 50-496 MONTAQUE NUCLEAR POWER STATION, UNIT 1

G Inspection reports, IE Bulletins & correspondence

B305110458 IE Info Notice B3-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post B30103) B3/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000, 83/05/26, B305110458

B305110460 IE Info Notice B3-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, B305110460

B305110461 IE Info Notice B3-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 200 24X Fiche 50-000, 83/05/31, B305110461

B305110464 IE Info Notice B3-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, B305110464

B305110470 IE Info Notice B3-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, B305110470

B306090010 IE Info Notice B3-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, B306090010

B305110475 IE Info Notice B3-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/06/22 Consolidated Edison Co of New York, Inc 115pp, 19021 179 24X Fiche 50-000, 83/06/22, B305110475

DOCKETED ITEMS

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046-297 24X Fiche 50-000, 83/06/24, 8305110483

DOCKET 50-497 MONTAQUE NUCLEAR POWER STATION, UNIT 2

G Inspection reports, IE Bulletins & correspondence

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device." Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831.043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at DHRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830:280 24X Fiche 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 116pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997-007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996-242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046-297 24X Fiche 50-000, 83/06/24, 8305110483

DOCKET STN-50-498 SOUTH TEXAS PROJECT, UNIT 1

A Application/Construction stage documents & correspondence

8306240059 Requests participation in pilot program concept contained in Public Law 97 415 Section 13 re QA limits bases to be used for planning purposes
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/03 OPREA, G A Houston Lighting & Power Co 2pp 18987 057 24X Fiche 50-498, 83/05/03, 8306240059

8306020024 Forwards request for addl info re proposed deletion of emergency duration sys Response should be provided in amend form
KNIGHTON, G W Licensing Branch 3 83/05/12 OPREA, G W Houston Lighting & Power Co 3pp 18715 243 24X Fiche 50-498, 83/05/12, 8306020024

--8112030545 Forwards Div of Sys Integration safety evaluation of Westinghouse 1981 version of large break ECCS evaluation model, per NUREG 0630 Revisions, per 10CFR50, App K requested
SPEIS, T P Assistant Director for Reactor Safety 81/11/02
TEDESCH, R L Division of Licensing 1p 18715 250 24X Fiche 50-498, 83/05/12, 8306020024

8306200122 Forwards Rev 4 to QA program for design & const phase Rev does not reduce commitments contained in Rev 3 submitted on 820309 Affidavit encl
OPREA, G W Houston Lighting & Power Co 83/05/18 COLLINS, J T Region 4, Office of Director 4pp 18704 025 24X Fiche 50-498, 83/05/18, 8306200122

--8306200126 Rev 4 to QA program for design & const phase
* Houston Lighting & Power Co 83/05/18 300pp 18904 029 24X Fiche 50-498, 83/05/18, 8306200126

8306140052 Advises that responses to FSAR Questions 32 42, "Loss of Non-Class 1E Instrument & Control Power Sys Bus During Operation" & 32 44, "Qualification of Control Sys" will be provided by May 1984 Delay due to extensive redesign effort
GOLDBERG, J H Houston Lighting & Power Co 83/06/07 NOVAK, T M Assistant Director for Licensing 2pp 18838 286 24X Fiche 50-498, 83/06/07, 8306140052

8306200019 Summary of 830331 meeting w/utls & Westinghouse in Bethesda, MD re Westinghouse analysis & evaluation of D4/D5/E steam generator mod
HOPKINS, J B Licensing Branch 4 83/06/14 Licensing Branch 4 22pp 18908 317 24X Fiche 50-000, 83/06/14, 8306200019

8306230460 Comments on NRC activities re load combinations & pipe break design Guidance on elimination of double-ended breaks & intermediate break postulations requested Meeting recommended
GOLDBERG, J H Houston Lighting & Power Co 83/06/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 18941 315 24X Fiche 50-498, 83/06/17, 8306230460

F Security, medical, emergency & fire protection plans

8306010350 Forwards IE Mgt Meeting Repts 50-498/83-05 & 50-499/83-05 on 830217-10
MADSEN, G L Region 4, Office of Director 83/05/25 OPREA, G W Houston Lighting & Power Co 2pp 18902 145 24X Fiche 50-498, 83/05/25, 8306010350

--8306010356 IE Mgt Meeting Repts 50-498/83-05 & 50-499/83-05 on 830217-18 Major areas discussed emergency preparedness & tentative date for emergency preparedness appraisal Tour of facilities followed meeting
CROSBMAN, W A Region 4, Office of Director DARGART, R I Division of Vendor & Technical Programs 83/05/25 3pp 18682 147 24X Fiche 50-498, 83/05/25, 8306010356

8306070204 Forwards Amend 3 to security plan Amend withheld (ref 10CFR73 21) Rev 2 to security plan should be disposed of per appropriate safeguards procedure
GOLDBERG, J H Houston Lighting & Power Co 83/05/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 18747 092 24X Fiche 50-498, 83/05/27, 8306070204

G Adjudicatory correspondence

8306080150 Forwards suppl to motion for new contention on utal financial qualifications & response to seventh set of utal interrogatories Related correspondence
SINKIN, L Citizens Concerned About Nuclear Power, Inc 83/06/02
BECHTOLD, C, LAMU, J C, HILL, E E Atomic Safety and Licensing Board Panel 1p 18772 192 24X Fiche 50-498, 83/06/02, 8306080150

DOCKETED ITEMS

353

--8306080155 Suppl to 830318 motion to admit new contention on util financial qualifications Adequate grounds For waiver of rule of financial qualifications review established & good cause shown for late filing
SINKIN, L A Citizens Concerned About Nuclear Power, Inc
83/05/30 Atomic Safety and Licensing Board Panel 14pp
18772 193 24X Fiche 50-498, 83/06/01, 8306080150

--8306080159 Response to motion to compel answers to seventh set of interrogatories, consisting of answers to interrogatories Certificate of Svc encl Related correspondence
SINKIN, L A Citizens Concerned About Nuclear Power, Inc
83/06/02 Houston Lighting & Power Co 14pp 18772 205 24X
Fiche 50-498, 83/06/02, 8306080150

8306100200 Comments on Citizens Concerned About Nuclear Power 830602 ltr & pleadings Certificate of Svc encl
NEWMAN, J R Lowenstein, Newman, Reis, Axelrad & Toll NEWMAN, J R
Houston Lighting & Power Co 83/06/08 DECHHOEFER, C, LANH, J C, .
HILL, E E Atomic Safety and Licensing Board Panel 5pp 18305 306
24X Fiche 50-498, 83/06/08, 8306100200

8306130427 Advises that time for Commission to review Director's Decision DD-83 05 expired Commission declined review Decision became final agency action on 830606
CHILK, S J Office of the Secretary of the Commission 83/06/10
SINKIN, L A Affiliation Unknown 1p 10821 178 24X
Fiche 50-498, 83/06/10, 8306130427

8306220057 Supplemental answer to seventh set of interrogatories & requests for production of documents re site location acceptability W/Certificate of Svc Related correspondence
SINKIN, L A Citizens Concerned About Nuclear Power, Inc 83/06/13
Houston Lighting & Power Co 5pp 18930 029 24X
Fiche 50-498, 83/06/13, 8306220057

8306200308 Advises that applicant does not intend to file motion to compel detailed answers from Citizens Concerned About Nuclear Power to applicant seventh set of interrogatories & requests to produce Effort would be fruitless
NEWMAN, J R Lowenstein, Newman, Reis, Axelrad & Toll NEWMAN, J R
Joint Applicants-Bouth Texas Project 83/06/15 DECHHOEFER, C, LANH, J C, HILL, E E Atomic Safety and Licensing Board Panel 4pp
18900 160 24X Fiche 50-498, 83/06/15, 8306200308

8306270148 Memorandum & order granting util 830418 motion to compel Citizens Concerned About Nuclear Power answers to 830310 sixth set of interrogatories & requests for documents NRC directed to brief issues at earliest convenience
DECHHOEFER, C Atomic Safety and Licensing Board Panel 83/06/22
Houston Lighting & Power Co 8pp 18708 041 24X
Fiche 50-498, 83/06/22, 8306270148

8306280583 Forwards, per request, Reg Guide 1.70 & NUREG-0800, Sections 2.3.1 W/o encls
PEARL, R O Hearing Branch 3 83/06/27 DERWICK, D Texas, State of 1p 19017 324 24X Fiche 50-498, 83/06/27, 8306280583

K Utility Final Safety Analysis Report (FSAR) & amends

8306300077 Forwards effective page listing through Amend 31 for FSAR Listing to be considered formal addition to FSAR
WIGENBURG, M R Houston Lighting & Power Co 83/06/22 NOVAK, T M
Assistant Director for Licensing /Opp 19048 260 24X
Fiche 50-498, 83/06/22, 8306300077

M Antitrust correspondence

8306230127 Advises that documents produced by Gulf States Utils Co, in response to NRC subpoena, destroyed
VOGLER, B M Hearing Branch 2 83/06/21 CLEMENT, D M Gulf States Utilities Co 1p 18947 040 24X Fiche 50-000, 83/06/21, 8306230127

Q Inspection reports, IE Bulletins & correspondence

8306080128 Forwards IE Insp Repts 50-498/83-04 & 50-499/83-04 on 830207-11 No noncompliance noted
MADSEN, O L Region 4, Office of Director 83/04/04 OPREA, O W
Houston Lighting & Power Co 2pp 18772 318 24X
Fiche 50-498, 83/04/04, 8306080128

--8306080133 IE Insp Repts 50-498/83-04 & 50-499/83-04 on 830207-11 No noncompliance noted Major areas inspected environ protection program during const, including organization & administration audits & compliance w/CP & FES
CHANEY, H D, MURRAY, B, CROSSMAN, W A Region 4, Office of Director 83/03/29 13pp 18772 720 24X Fiche 50-498, 83/04/04, 8306080128

8306080277 Addl response to FOIA request for seven categories of records re Brown & Root, Inc & facilities App C Document 1 partially withheld (ref FOIA Exemption 7) App D documents withheld entirely (ref FOIA Exemption b)
FELTON, J M Division of Rules and Records 83/04/12 LINDEMAN, H N
Lowenstein, Newman, Reis, Axelrad & Toll 4pp 18792 156 24X
Fiche 50-498, 83/04/12, 8306080277

--8306080304 "Request for Investigation Concerning Alleged Advanced Notification," investigation rept info partially deleted
SINCLAIR, J R Office of Inspector & Auditor 80/10/23 7pp
18792 160 24X Fiche 50-498, 83/04/12, 8306080277

--8306080308 Forwards rept re alleged advanced notification to util or Brown & Root, Inc of forthcoming Region IV investigation &/or alleged identities No further investigation contemplated W/o encl
CUMMINGS, J J Office of Inspector & Auditor 80/10/24
AHEARNE, J F, GILINSKY, V, HENDRIE, J M Commissioners 1p
18792 169 24X Fiche 50-498, 83/04/12, 8306080277

--8306080310 Forwards "Request for Investigation Concerning Alleged Advanced Notification" (ref 8301024 memo) W/o encl
CUMMINGS, J J Office of Inspector & Auditor, 80/11/10
STELLO, V J Director's Office, Office of Inspection and Enforcement 1p 18792 170 24X Fiche 50-498, 83/04/12, 8306080277

8306060056 Forwards IE Insp Repts 50-498/83-08 & 50-499/83-08 on 830411-15 No noncompliance noted
MADSEN, O L Region 4, Office of Director 83/05/18, OPREA, O W
Houston Lighting & Power Co 2pp 18719 258 24X
Fiche 50-498, 83/05/18, 8306060056

--8306060060 IE Insp Repts 50-498/83-08 & 50-499/83-08 on 830411-15, No noncompliance noted Major areas inspected, const activities including deficient threads on site-fabricated anchor bolts, improper bolt matl & training records
BOARDMAN, J R, CROSSMAN, W A Region 4, Office of Director, 83/05/13 11pp 18719 260 24X Fiche 50-498, 83/05/18, 8306060056

8306060111 Forwards IE Insp Repts 50-498/83-02 & 50-499/83-02 on 830201-28 & notice of violation
MADSEN, O L Region 4, Office of Director 83/05/18 OPREA, O W
Houston Lighting & Power Co 2pp 18719 082 24X
Fiche 50-498, 83/05/18, 8306060111

--8306060116 Notice of violation from insp on 830201-28, * Region 4, Office of Director 83/05/18 2pp, 18719 084 24X
Fiche 50-498, 83/05/18, 8306060111

--8306060122 IE Insp Repts 50-498/83-02 & 50-499/83-02 on 830201-28 Noncompliance noted, licensee unable to retrieve OA records re site fabricated anchor bolts
HILL, W M, BOARDMAN, J R, TOMLINSON, D P Region 4, Office of Director 83/05/13 40pp 18719 086 24X Fiche 50-498, 83/05/18, 8306060111

8306010350 Forwards IE Mgt Meeting Repts 50-498/83-05 & 50-499/83-05 on 830217-10
MADSEN, O L Region 4, Office of Director 83/05/25 OPREA, O W
Houston Lighting & Power Co 2pp 18602 145 24X
Fiche 50-498, 83/05/25, 8306010350

--8306010356 IE Mgt Meeting Repts 50-498/83-05 & 50-499/83-05 on 830217-10 Major areas discussed emergency preparedness & tentative data for emergency preparedness appraisal Tour of facilities followed meeting
CROSSMAN, W A Region 4, Office of Director, BANGART, R L
Division of Vendor & Technical Programs 83/05/25, 3pp
18682 147, 24X Fiche 50-498, 83/05/25, 8306010350

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc.
129pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet," Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co, of New York, Inc 119pp 18732 089 24X Fiche 50-000, 83/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc. 116pp 18732 208, 24X Fiche: 50-000, 83/05/31, 8305110461

DOCKETED ITEMS

8305110464 IE Info Notice 83-26, "Impact of Security Practices on Safe Operations." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/09 Consolidated Edison Co of New
York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New
York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New
York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New
York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New
York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co of New
York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co of New
York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

B Reportable occurrences, LERs & related correspondence

8306070112 Final deficiency rept re inadequate duct layout of reactor containment fan cooler sys Initially reported on 830429
Design of discharge ducts will be modified to prevent water spray into ducts
OPREA, G W Houston Lighting & Power Co 83/05/25 COLLINS, J T
Region 4, Office of Director 4pp 18739 168 24X
Fiche 50-498, 83/05/25, 8306070112

8306130350 Final deficiency rept re breakdown in Brown & Root quality program for procurement cycle of purchased matls Initially reported on 800615 Item not reportable per 10CFR50.55(e) or Part 21
OPREA, G W Houston Lighting & Power Co 83/06/03 COLLINS, J T
Region 4, Office of Director, 11pp 18822 326 24X
Fiche 50-498, 83/06/03, 8306130350

8306170388 Seventh interim deficiency rept re lack of visibility on Brown & Root computer program methods Initially reported on 810508 Further action re codes used by civil disciplines & pipe stress group required Next rept expected by 831014
OPREA, G W Houston Lighting & Power Co 83/06/13 COLLINS, J T
Region 4, Office of Director 5pp 18880 243 24X
Fiche 50-498, 83/06/13, 8306170388

DOCKET STN-50-499 SOUTH TEXAS PROJECT, UNIT 2

A Application/construction stage documents & correspondence

8306240059 Requests participation in pilot program concept contained in Public Law 97-415 Section 13 re QA lists bases to be used for planning purposes
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/03 OPREA, G A Houston Lighting & Power Co 2pp
18978 037 24X Fiche 50-498, 83/05/03, 8306240059

8306020024 Forwards request for addl info re proposed deletion of emergency boration sys Response should be provided in amend form
KNIGHTON, O W Licensing Branch 3 83/05/12 OPREA, G W Houston Lighting & Power Co 5pp, 18715 245 24X Fiche 50-498, 83/05/12, 8306020024

8306200122 Forwards Rev 4 to QA program for design & const phase Rev does not reduce commitments contained in Rev 3 submitted on 820309 Affidavit encl
OPREA, G W Houston Lighting & Power Co 83/05/18 COLLINS, J T
Region 4, Office of Director 4pp 18704 025 24X
Fiche 50-498, 83/05/18, 8306200122

--8306200126 Rev 4 to QA program for design & const phase
* Houston Lighting & Power Co 83/05/18 300pp 18904 029 24X
Fiche 50-498, 83/05/18, 8306200126

8306140052 Advises that responses to FSAR Questions 32 42, "Loss of Non-Class IE Instrument & Control Power Sys Bus During Operation" & 32 44, "Qualification of Control Sys" will be provided by May 1984 Delay due to extensive redesign effort
GOLDBERG, J H Houston Lighting & Power Co 83/06/07 NGVAH, I H
Assistant Director for Licensing 2pp 18838 286 24X
Fiche 50-498, 83/06/07, 8306140052

8306200017 Summary of 830331 meeting w/utls & Westinghouse in Bethesda, MD re Westinghouse analysis & evaluation of B4/D3/E steam generator mod
HOPKINS, J B Licensing Branch 4 83/06/14 Licensing Branch 4
22pp 18908 327 24X Fiche 50 000, 83/06/14, 8306200017

8306230460 Comments on NRC activities re load combinations & pipe break design Guidance on elimination of double-ended breaks & intermediate break postulations requested Meeting recommended
GOLDBERG, J H Houston Lighting & Power Co 83/06/17 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 18941 325 24X Fiche 50-498, 83/06/17, 8306230460

F Security, medical, emergency & fire protection plans

8306010350 Forwards IE Mgt Meeting Repts 50-498/83-05 & 50-499/83-05 on 830217-18
MADSEN, G L Region 4, Office of Director 83/05/25 OPREA, G W
Houston Lighting & Power Co 2pp 18682 145 24X
Fiche 50-498, 83/05/25, 8306010350

--8306010356 IE Mgt Meeting Repts 50-498/83-05 & 50-499/83-05 on 830217-18 Major areas discussed emergency preparedness & tentative date for emergency preparedness appraisal Tour of facilities followed meeting
CROSSMAN, W A Region 4, Office of Director 83/05/25 3pp
18682 147 24X Fiche 50-498, 83/05/25, 8306010350

8306070204 Forwards Amend 3 to security plan Amend withheld (ref 10CFR73.21) Rev 2 to security plan should be disposed of per appropriate safeguards procedures
GOLDBERG, J H Houston Lighting & Power Co 83/05/27 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 18747 092 24X Fiche 50-498, 83/05/27, 8306070204

G Adjudicatory correspondence

8306080150 Forwards suppl to motion for new contention on util financial qualifications & response to seventh set of util interrogatories Related correspondence
SINKIN, L Citizens Concerned About Nuclear Power, Inc 83/06/02
BECHHOEFER, C, LAMB, J C, HILL, C E Atomic Safety and Licensing Board Panel 1p 18772 192 24X Fiche 50-498, 83/06/02, 8306080150

--8306080155 Suppl to 830318 motion to admit new contention on util financial qualifications Adequate grounds for waiver of rule of financial qualifications review established & good cause shown for late filing
SINKIN, L A Citizens Concerned About Nuclear Power, Inc 83/05/30 Atomic Safety and Licensing Board Panel 12pp
18772 193 24X Fiche 50-498, 83/06/02, 8306080150

--8306080159 Response to motion to compel answers to seventh set of interrogatories, consisting of answers to interrogatories Certificate of Svc encl Related correspondence
SINKIN, L A Citizens Concerned About Nuclear Power, Inc 83/06/02 Houston Lighting & Power Co 14pp 18772 205 24X
Fiche 50-498, 83/06/02, 8306080150

8306100200 Comments on Citizens Concerned About Nuclear Power 830602 ltr & pleadings Certificate of Svc encl
NEWMAN, J R Lowenstein, Newman, Reiss, Axelrad & Toll NEWMAN, J R
Houston Lighting & Power Co 83/06/08 BECHHOEFER, C, LAMB, J C, HILL, E E, Atomic Safety and Licensing Board Panel 5pp 18805 306 24X Fiche 50-498, 83/06/08, 8306100200

8306130427 Advises that time for Commission to review Director's Decision DD-83-05 expired Commission declined review Decision became final agency action on 830606
CHILK, S J Office of the Secretary of the Commission 83/06/10
SINKIN, L Affiliation Unknown 1p 18821 178 24X
Fiche 50-498, 83/06/10, 8306130427

DOCKETED ITEMS

355

8306220057 Supplemental answer to seventh set of interrogatories & requests for production of documents re site location acceptability w/certificate of Svc Related correspondence SINKIN, L A Citizens Concerned About Nuclear Power, Inc 83/06/13 Houston Lighting & Power Co 5pp 18790 029 24X Fiche 50-498, 83/06/13, 8306220057

8306200308 Advises that applicant does not intend to file motion to compel detailed answers from Citizens Concerned About Nuclear Power to applicant seventh set of interrogatories & requests to produce EPort would be fruitless NEWMAN, J R Lowenstein, Newman, Reis, Axelrad & Toll NEWMAN, J R Joint Applicants-South Texas Project 83/06/15 DECHHOEFER, C, LAMB, J C, HILL, E E Atomic Safety and Licensing Board Panel 4pp 18900 160 24X Fiche 50-498, 83/06/15, 8306200308

8306270148 Memorandum & order granting until 830418 motion to compel Citizens Concerned About Nuclear Power answers to 830310 sixth set of interrogatories & requests for documents NRC directed to brief issues at earliest convenience DECHHOEFER, C Atomic Safety and Licensing Board Panel 83/06/22 Houston Lighting & Power Co 8pp 18768 041 24X Fiche 50-498, 83/06/22, 8306270148

8306280583 Forwards, per request, Reg Guide 1.70 & NUREG-0800, Sections 2.3.1 w/n encls PERLIS, R G Hearing Branch 3 83/06/27 BERNICK, B Texas, State of 1p 19017 324 24X Fiche 50-498, 83/06/27, 8306280583

K Utility Final Safety Analysis Report (FSAR) & amends

8306300077 Forwards effective page listing through Amend 31 for FSAR Listing to be considered formal addition to FSAR WISENBURG, H R Houston Lighting & Power Co 83/06/22 NOVAK, T M Assistant Director for Licensing 70pp 19048 260 24X Fiche 50-498, 83/06/22, 8306300077

M Antitrust correspondence

8306230127 Advises that documents produced by Gulf States Utils Co, in response to NRC subpoena, destroyed VOGLER, B H Hearing Branch 2 83/06/21 CLEMENTS, D M Gulf States Utilities Co 1p 18947 048 24X Fiche 50-000, 83/06/21, 8306230127

Q Inspection reports, IE Bulletins & correspondence

8306080128 Forwards IE Insp Repts 50-498/83-04 & 50-499/83-04 on 830207-11 No noncompliance noted MADSEN, O L Region 4, Office of Director 83/04/04 OPRCA, O W Houston Lighting & Power Co 2pp 18772 318 24X Fiche 50-498, 83/04/04, 8306080128

--8306080133 IE Insp Repts 50-498/83-04 & 50-499/83-04 on 830207-11 No noncompliance noted Major areas inspected environ protection program during const, including organization & administration audits & compliance w/CP & RES CHANEY, H D, MURRAY, D, CROSSMAN, W A Region 4, Office of Director 83/03/29 13pp 18772 320 24X Fiche 50-498, 83/04/04, 8306080133

8306080277 Addl response to FOIA request for seven categories of records re Brown & Root, Inc & facilities App C Document 1 partially withheld (ref FOIA Exemption 7) App D documents withheld entirely (ref FOIA Exemption 5) FELTON, J M Division of Rules and Records 83/04/12 LINDEMAN, H N Lowenstein, Newman, Reis, Axelrad & Toll 4pp 18792 156 24X Fiche 50-498, 83/04/12, 8306080277

--8306080304 "Request for Investigation Concerning Alleged Advanced Notification," investigation rpt Info partially deleted BINCLAIR, J R Office of Inspector & Auditor 80/10/23 9pp, 18792 160 24X Fiche 50-498, 83/04/12, 8306080277

--8306080308 Forwards rpt re alleged advanced notification to util or Brown & Root, Inc of forthcoming Region IV investigation &/or alleged identities No further investigation contemplated w/o encl CUMMINGS, J J Office of Inspector & Auditor 80/10/24 AHEARN, J F, GILINSKY, V, HENDRIE, J M Commissioners 1p, 18792 169 24X Fiche 50-498, 83/04/12, 8306080277

--8306080310 Forwards "Request for Investigation Concerning Alleged Advanced Notification" (ref 801024 memo) w/o encl CUMMINGS, J J Office of Inspector & Auditor 80/11/10, BTELLO, V J, Director's Office, Office of Inspection and Enforcement 1p 18792 170 24X Fiche 50-498, 83/04/12, 8306080277

8306060056 Forwards IE Insp Repts 50-498/83-08 & 50-499/83-08 on 830411-15 No noncompliance noted MADSEN, O L Region 4, Office of Director 83/05/18 OPRCA, O W Houston Lighting & Power Co 2pp 18719 258 24X Fiche 50-498, 83/05/18, 8306060056

--8306060060 IE Insp Repts 50-498/83-08 & 50-499/83-08 on 830411-15 No noncompliance noted Major areas inspected const activities including deficient threads on site-fabricated anchor bolts, improper bolt matl & training records BOARDMAN, J R, CROSSMAN, W A Region 4, Office of Director 83/05/13 11pp 18719 260 24X Fiche 50-498, 83/05/18, 8306060056

8306060111 Forwards IE Insp Repts 50-498/83-02 & 50-499/83-02 on 830201-28 & notice of violation MADSEN, O L Region 4, Office of Director 83/05/18 OPRCA, O W Houston Lighting & Power Co 2pp 18719 082 24X Fiche 50-498, 83/05/18, 8306060111

--8306060116 Notice of violation from insp on 830201-28 * Region 4, Office of Director 83/05/18 2pp 18719 084 24X Fiche 50-498, 83/05/18, 8306060111

--8306060122 IE Insp Repts 50-498/83-02 & 50-499/83-02 on 830201-28 Noncompliance noted licensee unable to retrieve GA records re site fabricated anchor bolts HILL, W H, BOARDMAN, J R, THOMLINSON, D P Region 4, Office of Director 83/05/13 40pp 18719 086 24X Fiche 50-498, 83/05/18, 8306060111

8306010350 Forwards IE Mgt Meeting Repts 50-498/83-05 & 50-499/83-05 on 830217-18 MADSEN, O L Region 4, Office of Director 83/05/25 OPRCA, O W Houston Lighting & Power Co 2pp 18602 145 24X Fiche 50-498, 83/05/25, 8306010350

--8306010356 IE Mgt Meeting Repts 50-498/83-05 & 50-499/83-05 on 830217-18 Major areas discussed: emergency preparedness & tentative date for emergency preparedness appraisal Tour of facilities followed meeting CROSSMAN, W A Region 4, Office of Director BANGART, R L Division of Vendor & Technical Programs 83/05/25 3pp 18682 147 24X Fiche 50-498, 83/05/25, 8306010350

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 12pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp, 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement w/Control Rods Withdrawal at JWHs." Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp, 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

DOCKETED ITEMS

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18977 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18976 242 24X Fiche 50-000, 83/06/23, 8305110477

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

S Reportable occurrences, LERs & related correspondence

8306070112 Final deficiency rept re inadequate duct layout of reactor containment fan cooler sys Initially reported on 830429
Design of discharge ducts will be modified to prevent water spray into ducts
OPREA, Q W Houston Lighting & Power Co 83/05/25 COLLINS, J T
Region 4, Office of Director App. 18739 168 24X
Fiche 50-498, 83/05/25, 8306070112

8306130350 Final deficiency rept re breakdown in Brown & Root quality program for procurement cycle of purchased matls Initially reported on 830615 Item not reportable per 10CFR50.55(e) or Part 21.
OPREA, Q W Houston Lighting & Power Co 83/06/03 COLLINS, J T
Region 4, Office of Director 11pp 18822 324, 24X
Fiche 50-498, 83/06/03, 8306130350

8306170388 Seventh interim deficiency rept re lack of visibility on Brown & Root computer program methods Initially reported on 830508 Further action re codes used by civil disciplines & pipe stress group required Next rept expected by 831014
OPREA, Q W Houston Lighting & Power Co 83/06/13 COLLINS, J T
Region 4, Office of Director 5pp 18880 243 24X
Fiche 50-498, 83/06/13, 8306170388

DOCKET 83N-50-508 WPPSS NUCLEAR PROJECT, UNIT 3

A Application/construction stage documents & correspondence

8306080378 Summarizes 830112 meeting w/C-E Owners Group in Bethesda, MD re depressurization & DHR capability w/ PORVs. Scenarios should reflect current emergency response guidelines rather than take credit for depressurization w/RCB cooldown
NOVAK, T M Assistant Director for Licensing 83/05/24
FERGUSON, R L Washington Public Power Supply System, App 18789 336, 24X Fiche 50-508, 83/05/24, 8306080378

8306080388 Forwards C-E ltr requesting addl info re rapid depressurization & DHR Responses provided by C-E will be directly applicable to Facility
NOVAK, T M Assistant Director for Licensing, 83/05/24
FERGUSON, R L Washington Public Power Supply System 2pp 18792 218, 24X Fiche 50-508, 83/05/24, 8306080388

--8304090019 Forwards request for addl info re depressurization & decay heat removal capability of CESSAR design
TEDESCHI, R L Assistant Director for Licensing, 82/03/26
SCHERER, A E Combustion Engineering, Inc 7pp 18792 220 24X
Fiche 50-508, 83/05/24, 8306080388

8306170184 Advises that on 830527, until executive board directed immediate slowdown of const, not to exceed 30 days, due to nearly exhausted funds & inability to secure conventional financing. No change to current licensing schedule requested
LEDDICK, R B Washington Public Power Supply System 83/06/01
STERNBERG, D M Region 5, Office of Director, 2pp 18882 300 24X
Fiche: 50-508, 83/06/01, 8306170184

8306100117 Notifies that on 830527, until implemented slowdown of const for period of 30 days Decision based on reduction of funds. Plans being developed for possible 3-yr extension of completion date in case financing cannot be secured
BOUCHEY, Q D Washington Public Power Supply System 83/06/03
DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18801 195, 24X Fiche: 50-508, 83/06/03, 8306100117.

8306230373 Forwards changes to QA program description, re organizational structure per 830110 notice of final rulemaking Program description will be incorporated into FSAR Chapter 17 by future FSAR amend
BOUCHEY, Q D Washington Public Power Supply System 83/06/13
MARTIN, J V Region 5, Office of Director 42pp 18742 304 24X
Fiche 50-508, 83/06/13, 8306230373

8306210154 Forwards responses to Apr & May 1983 acceptance review questions Info covers fire hazard analyses & RHK sys
BOUCHEY, Q D Washington Public Power Supply System 83/06/14
KNIGHTON, Q W Licensing Branch 3 5pp 18916 017 24X
Fiche 50-508, 83/06/14, 8306210154

C Utility Environmental Report (ER), amends & correspondence

8306090207 Forwards responses to 830406 request for info re environ rept - OL stage Site certification agreement w/Energy Facility Site Evaluation Council requires replacement &/or compensation for wildlife losses
BOUCHEY, Q D Washington Public Power Supply System 83/06/07
KNIGHTON, Q W Licensing Branch 3 10pp 18796 093 24X
Fiche 50-508, 83/06/02, 8306090207

E NRC Safety Evaluation Report (SER), supplis & correspondence

8306170079 Forwards request for addl info re FSAR review Response requested by 830712 Draft SER will be prepared following review of response
KNIGHTON, Q W Licensing Branch 3 83/06/01 FERGUSON, R L
Washington Public Power Supply System 13pp 18708 001 24X
Fiche 50-508, 83/06/01, 8306170079

F Security, medical, emergency & fire protection plans

8306210154 Forwards responses to Apr & May 1983 acceptance review questions Info covers fire hazard analyses & RHK sys
BOUCHEY, Q D Washington Public Power Supply System 83/06/15
KNIGHTON, Q W Licensing Branch 3 5pp 18916 013 24X
Fiche 50-508, 83/06/14, 8306210154

G Adjudicatory correspondence

8306020431 Requests special prehearing conference be rescheduled for 830817-18
REYNOLDS, N B Debevoise & Liberman 83/06/01 MARQUILIES, M B
Atomic Safety and Licensing Board Panel 1p 18694 112 24X
Fiche 50-508, 83/06/01, 8306020431

8306150354 Forwards until 830603 ltr re 30-day const slowdown & possible addl const delays
REYNOLDS, N B Debevoise & Liberman REYNOLDS, N B Washington
Public Power Supply System 83/06/10 MARQUILIES, M B, CARPENTER, J H,
BROWN, F J Atomic Safety and Licensing Board Panel 1p 18847 265
24X Fiche 50-508, 83/06/10, 8306150354

8306220129 Suppl to 830218 petition to intervene, consisting of proposed contentions Certificate of Svc encl
BELL, N Condition for Safe Power 83/06/15 Atomic Safety and
Licensing Board Panel 41pp 18926 112 24X Fiche 50-508, 83/06/15, 8306220129

G Inspection reports, IE Bulletins & correspondence

8306100009 Addl response to FOIA request for documents dtd 830301 or after re SALP Forwards App A documents Documents also available in PDR
FELTON, J M Division of Rules and Records 83/04/11 CLARK, R
Francisco Examiner 3pp 18815 252 24X Fiche 50-000, 83/04/11, 8306100009

--8306100014 Submits schedule for Region V SALP Board meetings for 820928-830523
ENGELKEN, R H Region 5, Office of Director 82/03/19
DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18815 255 24X Fiche 50-000, 83/04/11, 8306100009

8306010376 Advises that response to deviation identified in IE Insp Repts 50-508/83-03 & 50-508/83-01 re failure to meet AWS D1.1 weld joint requirements, will be submitted by 830715
LEDDICK, R B Washington Public Power Supply System 83/05/10
STERNBERG, D M Region 5, Office of Director 2pp 18682 103 24X
Fiche, 50-508, 83/05/10, 8306010376

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 122pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

DOCKETED ITEMS

357

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 115pp 18732 089 24X Fiche 50-000, 83/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Electrically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-3/, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8306170216 Ack receipt of 830216 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-508/82-25
STERNBERG, D M Region 5, Office of Director 83/06/13
LEDDICK, R S Washington Public Power Supply System 1p 18882 285 24X Fiche 50-508, 83/06/13, 8306170216

--8306170222 Responds to NRC 830117 ltr re violations noted in IE Insp Rept 50-502/82-25 Util does not concur that activities described in item of noncompliance are in violation of 10CFR50, App D requirements Discussion requested
LEDDICK, R S Washington Public Power Supply System 83/02/16
STERNBERG, D M Region 5, Office of Director 3pp 18882 806 24X Fiche 50-508, 83/06/13, 8306170216

8306170425 Ack receipt of 830601 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-508/82-16
STERNBERG, D M Region 5, Office of Director 83/06/13
LEDDICK, R S Washington Public Power Supply System 1p 18879, 015 24X Fiche 50-508, 83/06/13, 8306170425

--8306170428 Suppls 821124 response to NRC 821227 ltr re violations noted in IE Insp Rept 50-508/82-16 Corrective actions code/code case addenda requested to allow full penetration welds in lieu of double butt welds
LEDDICK, R S Washington Public Power Supply System 83/06/01
STERNBERG, D M Region 5, Office of Director 3pp 18874 014 24X Fiche 50-508, 83/06/13, 8306170425

8306280405 Forwards IE Insp Rept 50-508/83-04 on 830411-15 & 25-29 No noncompliance noted
STERNBERG, D M Region 5, Office of Director 83/06/13
LEDDICK, R S Washington Public Power Supply System 2pp 19001 337 24X Fiche 50-508, 83/06/13, 8306280405

--8306280409 IE Insp Rept 50-508/83-04 on 830411-15 & 25-29 No noncompliance noted Major areas inspected const activities, including installation of pipe support & restraint sys & pressure insp of RCPB
HATST, D P, DODDS, R T Region 5, Office of Director 83/06/09, 12pp 19001 339 24X Fiche, 50-508, 83/06/13, 8306280405

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 120pp 18997, 007, 24X Fiche, 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions, " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103), 83/06/23 Consolidated Edison Co. of New York, Inc 116pp, 18996 242 24X Fiche 50-000, 83/06/23, 8305110477

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

S Reportable occurrences, LERs & related correspondence

8306070254 PND-V-83-023 on 830527, executive board of util passed resolution delaying completion of Project 3 for 3 yrs if addl financing not obtained within 30 days Present employment at project is approx 3,000
STERNBERG, D M, HAIST, D P Region 5, Office of Director 83/05/27 1p 18740 335 24X Fiche 50-508, 83/05/27, 8306070254

8306170296 Interim Deficiency Rept NY-0A-5 re main steam & feedwater penetration anchor stress analyses Initially reported on 830426 Engineering procedure revised & analyses performed Final rept expected by 830729
LEDDICK, R S Washington Public Power Supply System 83/06/09
STERNBERG, D M Region 5, Office of Director 3pp 18878 174 24X Fiche 50-508, 83/06/09, 8306170296

DOCKET BTN-50-509 WPPSS NUCLEAR PROJECT, UNIT 5

G Inspection reports, IE Bulletins & correspondence

8306100009 Addl response to FOIA request for documents dtd 820101 or after re SALP Forwards App A documents Documents also available in PDR
FELTON, J M Division of Rules and Records 83/04/11 CLARK, R San Francisco Examiner 3pp 18815 252 24X Fiche, 50-000, 83/04/11, 8306100009

--8306100014 Submits schedule for Region V SALP Board meetings for 820928-830523
ENGELKEN, R H Region 5, Office of Director 82/03/19
DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18815 255 24X Fiche 50-000, 83/04/11, 8306100009

DOCKET 50-513 WPPSS NUCLEAR PROJECT, UNIT 4

G Inspection reports, IE Bulletins & correspondence

8306100009 Addl response to FOIA request for documents dtd 820101 or after re SALP Forwards App A documents Documents also available in PDR
FELTON, J M Division of Rules and Records 83/04/11 CLARK, R San Francisco Examiner 3pp 18815 252 24X Fiche 50-000, 83/04/11, 8306100009

--8306100014 Submits schedule for Region V SALP Board meetings for 820928-830523
ENGELKEN, R H Region 5, Office of Director 82/03/19
DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18815 255 24X Fiche, 50-000, 83/04/11, 8306100009

S Reportable occurrences, LERs & related correspondence

8306010106 Final deficiency rept re stuck reactor vessel flange stud/ hole-stuck stud Initially reported on 821115 Vendor determined that structural & functional integrity of stud hole acceptable Condition not reportable per 10CFR50.55(e)
DE LORENZO, R A Washington Public Power Supply System 83/05/17
STERNBERG, D M Region 5, Office of Director 2pp 18674 062 24X Fiche 50-513, 83/05/17, 8306010106

8306070113 Interim deficiency rept re potential failure of reactor vessel internals bolts Initially reported on 830502 B&W participating in insp program on operating plants Status rept will be provided upon const restart
DE LORENZO, R A Washington Public Power Supply System 83/05/25
STERNBERG, D M Region 5, Office of Director 2pp 18739 212 24X Fiche 50-460, 83/05/25, 8306070113

DOCKET 50-514 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 1

G Inspection reports, IE Bulletins & correspondence

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device, " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 125pp, 18831 043 24X Fiche, 50-000, 83/05/26, 8305110458

DOCKETED ITEMS

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche 50-000,83/05/26,8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000,83/05/31,8305110461

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18930 280 24X Fiche 50-000,83/06/09,8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225 24X Fiche 50-000,83/06/13,8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000,83/06/13,8306090010

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 115pp 19021 179 24X Fiche 50-000,83/06/22,8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000,83/06/22,8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000,83/06/23,8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000,83/06/24,8305110483

DOCKET 50-515 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 2

Q Inspection reports, IE Bulletins & correspondence

8305110498 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000,83/05/26,8305110498

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche 50-000,83/05/26,8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000,83/05/31,8305110461

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18930 280 24X Fiche 50-000,83/06/09,8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225 24X Fiche 50-000,83/06/13,8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000,83/06/13,8306090010

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 115pp 19021 179 24X Fiche 50-000,83/06/22,8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000,83/06/22,8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000,83/06/23,8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000,83/06/24,8305110483

DOCKET STN-50-517 JAMESPORT NUCLEAR STATION, UNIT 2

Q Inspection reports, IE Bulletins & correspondence

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000,83/06/24,8305110483

DOCKET STN-50-518 HARTSVILLE NUCLEAR PLANT, UNIT 1

S Reportable occurrences, LERs & related correspondence

8306160454 Pt 21 rept re potential defect in transmitter mfg by Rosemount, Inc used in control sys components furnished to listed plants All components involved retrofitted w/new circuit boards Matter closed
GIRDOUX, E J Carrier Corp 83/05/23 STELLD, V Director's Office, Office of Inspection and Enforcement 1p 18863 094 24X Fiche 50-518,83/05/23,8306160454

8306090135 Second interim deficiency rept re Henry Pratt butterfly valve Initially reported on 821109 Valve air-operator yoke mod kits delivered & mod in progress Operators removed & returned to GH Bettis Co Also reported per Part 21
MILLS, L M Tennessee Valley Authority 83/06/02 O'REILLY, J P Region 2, Office of Director 1p 18/95 297 24X Fiche 50-000,83/06/02,8306090135

DOCKET STN-50-519 HARTSVILLE NUCLEAR PLANT, UNIT 2

S Reportable occurrences, LERs & related correspondence

8306160454 Pt 21 rept re potential defect in transmitter mfg by Rosemount, Inc used in control sys components furnished to listed plants All components involved retrofitted w/new circuit boards Matter closed
GIRDOUX, E J Carrier Corp 83/05/23 STELLD, V Director's Office, Office of Inspection and Enforcement 1p 18863 094 24X Fiche 50-518,83/05/23,8306160454

DOCKET STN-50-520 HARTSVILLE NUCLEAR PLANT, UNIT 3

S Reportable occurrences, LERs & related correspondence

8306160454 Pt 21 rept re potential defect in transmitter mfg by Rosemount, Inc used in control sys components furnished to listed plants All components involved retrofitted w/new circuit boards Matter closed
GIRDOUX, E J Carrier Corp 83/05/23 STELLD, V Director's Office, Office of Inspection and Enforcement 1p 18863 094 24X Fiche 50-518,83/05/23,8306160454

8306090135 Second interim deficiency rept re Henry Pratt butterfly valve initially reported on 04/10/97 Valve air-operator yoke mod kits delivered & mod in progress Operators removed & returned to GH Bellis Co Also reported per Part 21
MILLS, L M Tennessee Valley Authority 03/06/02 O'REILLY, J P
Region 2, Office of Director 1p 10/25 297 24X
Fiche 50-000, 03/06/02, 8306090135

DOCKET 83N-50-521 HARTSVILLE NUCLEAR PLANT, UNIT 4

5 Reportable occurrences, LERs & related correspondence

8306160454 Pt 21 rept re potential defect in transmitter mfg by Rosemount, Inc used in control sys of components furnished to listed plants All components involved retrofitted w/new circuit boards Matter closed
GIRoux, E J Carrier Corp 03/05/23 STELLO, V Director's Office,
Office of Inspection and Enforcement 1p 10863 094 24X
Fiche 50 518, 03/05/23, 8306160454

DOCKET 50-522 SKAGIT NUCLEAR POWER PROJECT, UNIT 1

Q Adjudicatory correspondence

8306060285 Memorandum & order extending time until 030930 for parties to answer intervenor 830512 motion for summary disposition of Contention 1 Util considering alternative to terminating licensing efforts
WOLF, J F Atomic Safety and Licensing Board Panel 03/06/02
Puget Sound Power & Light Co 2pp 11/28 361 24X
Fiche 50-522, 03/06/02, 8306060285

8306090234 Response opposing applicant 830525 request for extension until 030930 to answer motion for summary disposition of Contention 1 No good cause demonstrated Certificate of Svc encl
CAVANAGH, R Natural Resources Defense Council 03/06/03 Atomic
Safety and Licensing Board Panel App 18795 336 24X
Fiche 50-522, 03/06/03, 8306090234

Q Inspection reports, IE Bulletins & correspondence

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 03/05/26 Consolidated Edison Co of New York, Inc
125pp 10831 043 24X Fiche 50 000, 03/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 03/05/26 Consolidated Edison Co of New York, Inc
119pp 18732 085 24X Fiche 50-000, 03/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 03/05/31 Consolidated Edison Co of New York, Inc
116pp 18732 208 24X Fiche 50-000, 03/05/31, 8305110461

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 03/06/09 Consolidated Edison Co of New York, Inc
119pp 18830 280 24X Fiche 50-000, 03/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 03/06/13 Consolidated Edison Co of New York, Inc
110pp 18920 225 24X Fiche 50-000, 03/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 03/06/13 Consolidated Edison Co of New York, Inc
243pp 18921 001 24X Fiche 50-000, 03/06/13, 8306090010

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy GROUTS & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 03/06/22 Consolidated Edison Co of New York, Inc
115pp 19021 177 24X Fiche 50-000, 03/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 03/06/22 Consolidated Edison Co of New York, Inc
120pp 18997 007 24X Fiche 50-000, 03/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 03/06/23 Consolidated Edison Co of New York, Inc
116pp 18996 242 24X Fiche 50-000, 03/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Bettings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 03/06/24 Consolidated Edison Co of New York, Inc
116pp 19046 297 24X Fiche 50-000, 03/06/24, 8305110483

DOCKET 50-523 SKAGIT NUCLEAR POWER PROJECT, UNIT 2

Q Adjudicatory correspondence

8306060285 Memorandum & order extending time until 030930 for parties to answer intervenor 830512 motion for summary disposition of Contention 1 Util considering alternative to terminating licensing efforts
WOLF, J F Atomic Safety and Licensing Board Panel 03/06/02
Puget Sound Power & Light Co 2pp 11/28 361 24X
Fiche 50-522, 03/06/02, 8306060285

8306090234 Response opposing applicant 830525 request for extension until 030930 to answer motion for summary disposition of Contention 1 No good cause demonstrated Certificate of Svc encl
CAVANAGH, R Natural Resources Defense Council 03/06/03 Atomic
Safety and Licensing Board Panel App 18795 336 24X
Fiche 50-522, 03/06/03, 8306090234

Q Inspection reports, IE Bulletins & correspondence

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 03/05/26 Consolidated Edison Co of New York, Inc
125pp 10831 043 24X Fiche 50-000, 03/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 03/05/26 Consolidated Edison Co of New York, Inc
115pp 18732 085 24X Fiche 50-000, 03/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 03/05/31 Consolidated Edison Co of New York, Inc
116pp 18732 208 24X Fiche 50-000, 03/05/31, 8305110461

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 03/06/09 Consolidated Edison Co of New York, Inc
119pp 18830 280 24X Fiche 50-000, 03/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 03/06/13 Consolidated Edison Co of New York, Inc
110pp 18920 225 24X Fiche 50-000, 03/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 03/06/13 Consolidated Edison Co of New York, Inc
243pp 18921 001 24X Fiche 50-000, 03/06/13, 8306090010

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy GROUTS & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 03/06/22 Consolidated Edison Co of New York, Inc
115pp 19021 177 24X Fiche 50-000, 03/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 03/06/22 Consolidated Edison Co of New York, Inc
120pp 18997 007 24X Fiche 50-000, 03/06/22, 8305110477

DOCKETED ITEMS

8303110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 114pp 18996 242 24X Fiche 50-000, 83/06/23, 8303110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 114pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

DOCKET STN-50-52B PALO VERDE NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8306080284 FOIA request for documents re R Gunderson & Bechtel senior manager allegations concerning electrical problems & deficiencies at facilities Waiver of fees requested
YOUNG, M C, BERNABEI, L Government Accountability Project
83/03/29 Office of Administration 2pp 18790 757 24X Fiche 50-52B, 83/03/29, 8306080284

8306140225 Forwards Conference Notes CN-E-1255 from 830323 meeting w/uttl, counsel, Bechtel, NRC & C-E in Washington, DC re post-LDCA containment sump
WILSON, W H Bechtel Corp 83/04/14 VAN BRUNT, E E Arizona Public Service Co 3pp 18844 322 24X Fiche 50-52B, 83/04/14, 8306140225

8306080281 Partial response to FOIA request for documents re R Gunderson & Bechtel allegations concerning electrical problems at facilities App A Documents 1 & 2 available in PDR Documents 3, 4 & 5 withheld (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records 83/04/28 YOUNG, M C, BERNABEI, L Government Accountability Project 3pp 18790 354 24X Fiche 50-52B, 83/04/28, 8306080281

8306020627 Notification of 830622-23 & 24 meetings w/uttl in Maricopa & Phoenix, AZ, respectively, to assess current status of const
LICITRA, E A Licensing Branch 3 83/05/24 KNIGHTON, G W Licensing Branch 3 8pp 18716 339 24X Fiche 50-52B, 83/05/24, 8306020627

8306070091 Advises that schedule for responding to five confirmatory items & completion of qualification program for safety-related pumps & valves will be submitted by 830630
VAN BRUNT, E E Arizona Public Service Co 83/05/31 KNIGHTON, G W Licensing Branch 3 1p 18739 141 24X Fiche 50-52B, 83/05/31, 8306070091

8306080097 Summary of 830517 meeting w/uttl, C-E & Bechtel in Bethesda, MD re NRC 830314 requested info on environ qualifications
Licitation, E A Licensing Branch 3 83/06/01 Licensing Branch 3 4pp 18787 327 24X Fiche 50-52B, 83/06/01, 8306080097

8306200051 Notification of 830608 meeting w/uttl in Bethesda, MD to discuss control room design review
LICITRA, E A Licensing Branch 3 83/06/03 KNIGHTON, G W Licensing Branch 3 3pp 18708 286 24X Fiche 50-52B, 83/06/03, 8306200051

8306200053 Notification of 830628-30 & 0701 meetings w/uttl, Bechtel, C-E & EP&Q in Phoenix & Maricopa County, AZ to conduct audit of equipment environ qualification documentation
LICITRA, E A Licensing Branch 3 83/06/03 KNIGHTON, G W Licensing Branch 3 3pp 18708 287 24X Fiche 50-52B, 83/06/03, 8306200053

8306170265 Forwards marked-up Amend 12 to FSAR Section 17.1 re QA program for engineering, design procurement & const of facility, per 10CFR50.55(f)
VAN BRUNT, E E Arizona Public Service Co 83/06/10 STERNBERG, D M Region 5, Office of Director 82pp 18877 274 24X Fiche 50-52B, 83/06/10, 8306170265

Forwards App J to: "Evaluation of Pressurized Thermal Shock to Small Break LDCA's W/Loss of Feedwater for 7, 2 & 3 Reactor Vessels " Rept applies to

Arizona Public Service Co. 83/06/14 KNIGHTON, G W 3pp 18878 197 24X Fiche 50-52B, 83/06/14,

a response to 830503 request for info supplementing SAR Table C 2-1 re quality classification
Arizona Public Service Co 83/06/14, KNIGHTON, G W 3 14pp 18881 005 24X Fiche 50-52B, 83/06/14,

8306240458 Summary of 830608 meeting w/uttl in Bethesda, MD re detailed control room design review
LICITRA, E A Licensing Branch 3 83/06/14 Licensing Branch 3 4pp 18998 001 24X Fiche 50-52B, 83/06/14, 8306240458

8306270143 Forwards schedule for submittal of info required for NRC review of FSAR Schedule covers submittal of revised security plan & add'l CESSAR interface requirements
VAN BRUNT, E E Arizona Public Service Co 83/06/20 KNIGHTON, G W Licensing Branch 3 8pp 18908 001 24X Fiche 50-52B, 83/06/20, 8306270143

8306280436 Forwards Amend 1 to environ qualification rept. per 830314 request & NUREG-0588 requirements
VAN BRUNT, E E Arizona Public Service Co 83/06/24 KNIGHTON, G W Licensing Branch 3 228pp 19016 297 24X Fiche 50-52B, 83/06/24, 8306280436

E NRC Safety Evaluation Report (SER), supp's & correspondence

8306130432 Responds to 830328 request for add'l info re adequacy of electric distribution sys voltages per SER (NUREG-0857)
Response re adequacy of util info requested within 2 wks
VAN BRUNT, E E Arizona Public Service Co 83/06/07 KNIGHTON, G W Licensing Branch 3 8pp 18821 195 24X Fiche 50-52B, 83/06/07, 8306130432

8306160500 Advises that procedures indicating shutdown cooling relief valves armed by manually opening shutdown cooling sys isolation valves will be utilized until operable low temp overpressure alarm available, per NUREG-0857, Suppl 1
VAN BRUNT, E E Arizona Public Service Co 83/06/13 KNIGHTON, G W Licensing Branch 3 1p 18064 156 24X Fiche 50-52B, 83/06/13, 8306160500

8306170326 Forwards proposed amend to Fbmk re CESSAR iodine removal sys & responses to NRC 830422 ltr Proposed FSAR amend combined w/responses closes out sump ph issue in SER Sections 4 & 15.4.8 & TMI Item III D 3.4
VAN BRUNT, E E Arizona Public Service Co 83/06/13 KNIGHTON, G W Licensing Branch 3 8pp 18079 040 24X Fiche 50-52B, 83/06/13, 8306170326

8306270368 Forwards responses to SER, Suppl 4, Sections 13.3.2.1 & 13.3.2.3 (NUREG-0857), re courses of action necessary in unlikely event of emergency at facilities Info will be included in Rev 3 to emergency plan
VAN BRUNT, E E Arizona Public Service Co 83/06/15 KNIGHTON, G W Licensing Branch 3 26pp 18793 214 24X Fiche 50-52B, 83/06/15, 8306270368

8306210287 Forwards program plan issues & areas for outstanding items re NUREG-0737, Item 1 D.1 re detailed control room design review per NUREG-0700 requirements & SER, NUREG-0857 Generic Ltr 82-33 issues addressed
VAN BRUNT, E E Arizona Public Service Co 83/06/17 KNIGHTON, G W Licensing Branch 3 36pp 18714 038 24X Fiche 50-52B, 83/06/17, 8306210287

8306280317 Submits required data to demonstrate that line voltage regulators perform as acceptable isolation device by limiting primary current under short circuit conditions to full-load primary current, per SER (NUREG-0857)
VAN BRUNT, E E Arizona Public Service Co 83/06/23 KNIGHTON, G W Licensing Branch 3 1p 19001 282 24X Fiche 50-52B, 83/06/23, 8306280317

F Security, medical, emergency & fire protection plans

8306170356 Forwards description & list of objectives for 830511 emergency preparedness exercise Scenario will be provided within 30 days Comments requested within 15 days of ltr date
ANDOGNINI, G C Arizona Public Service Co 83/03/02 GRIMES, D K Division of Emergency Preparedness (Pre 830103) 19pp 18880 333 24X Fiche 50-52B, 83/03/02, 8306170356

--8306170360 Forwards description & list of objectives for 830511 emergency preparedness exercise Scenario will be provided within 30 days Comments requested within 15 days of ltr date
ANDOGNINI, G C Arizona Public Service Co 83/03/02 HANFIM, R Region 5, Office of Director 10pp 18880 332 24X Fiche 50-52B, 83/03/02, 8306170360

8306020056 Responds to 830414 ltr re Generic Ltr 82-33 requirements concerning Suppl 1 to NUREG-0737 Portion of response addressing detailed control room design review does not provide all info requested Response requested by 830531
KNIGHTON, G W Licensing Branch 3 83/05/10 VAN BRUNT, E E Arizona Public Service Co 8pp 18701 347 24X Fiche 50-52B, 83/05/10, 8306020056

8306030357 Advises that addl info re detailed control room design review per Generic Ltr 82-33 re emergency response capabilities will be submitted by 830617
VAN BRUNT, E E Arizona Public Service Co 83/04/01 KNIGHTON, G
Licensing Branch 3 1p 18/05 214 24X Fiche 50-528, 83/06/01,
8306030357

8306090273 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/06/03 Document
Management Branch 1p 18810 067 24X Fiche 50-528, 83/06/03,
8306090273

--8306090275 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP-01 re emergency organization, EPIP-02 re emergency classification & EPIP-04 re alert implementing actions
VAN BRUNT, E E Arizona Public Service Co 83/05/23 KNIGHTON, G
Licensing Branch 3 3pp 18810 068 24X Fiche 50-528, 83/06/03,
8306090275

--8306090276 Public version of revised emergency plan implementing procedures, including Procedures EPIP-01 re emergency organization, EPIP-02 re emergency classification & EPIP-04 re alert implementing actions
LUCIA, B Arizona Public Service Co 83/03/30 708pp 18810 071
24X Fiche 50-528, 83/06/03, 8306090276

8306160058 Releases public version of revised emergency plan
FELTON, J M Division of Rules and Records 83/06/06 Document
Management Branch 1p 18872 316 24X Fiche 50-528, 83/06/06,
8306160058

--8306160064 Public version of Rev 3 to emergency plan, changing overall organizing task force & organizational option of corporate emergency planning & preparedness group W/830510 ltr
ANDOGNINI, G C Arizona Public Service Co 83/03/28 KERRIGAN, J
Operating Reactors Branch 3 6pp 18872 317 24X
Fiche 50-528, 83/06/06, 8306160064

8306280515 Forwards IE Insp Rept 50-528/83-21 on 830523-27 Nu noncompliance noted
STERNBERG, D M Region 5, Office of Director 83/06/14
ANDOGNINI, G C Arizona Public Service Co 2pp 19017 199 24X
Fiche 50-528, 83/06/14, 8306280515

--8306280519 IE Insp Rept 50-528/83-21 on 830523-27 No noncompliance noted Major areas inspected fire protection/prevention program & program implementation
SCHWEN, K, YOUNG, T Region 5, Office of Director 83/06/14 6pp
19017 201 24X Fiche 50-528, 83/06/14, 8306280519

8306280371 Forwards responses to open items from NRC 830201-03 fire protection audit
VAN BRUNT, E E Arizona Public Service Co 83/06/15 KNIGHTON, G
Licensing Branch 3 31pp 18899 056 24X Fiche 50-528, 83/06/15,
8306280371

8306270368 Forwards responses to Ser, Suppl 4, Sections 13.3.2.2 & 13.3.2.3 (NUREG-0857), re courses of action necessary in unlikely event of emergency at Facilities Info will be included in Rev 3 to emergency plan
VAN BRUNT, E E Arizona Public Service Co 83/06/15 KNIGHTON, G
Licensing Branch 3 26pp 18993 214 24X Fiche 50-528, 83/06/15,
8306270368

8306270447 Responds to Generic Ltr 82-33 re Suppl 1 to NUREG-0737 concerning requirements for emergency response capability Unit 1 selected as backup emergency operations facility Exemptions from 10-mile criteria requested
VAN BRUNT, E E Arizona Public Service Co 83/06/16 KNIGHTON, G
Licensing Branch 3 3pp 18992 096 24X Fiche 50-528, 83/06/16,
8306270447

8306210287 Forwards program plan issues & areas for outstanding items re NUREG-0737, Item I D 1 re detailed control room design review per NUREG-0700 requirements & SFR, NUREG-085/ Generic Ltr 82-33 issues addressed
VAN BRUNT, E E Arizona Public Service Co 83/06/17 KNIGHTON, G
Licensing Branch 3 36pp 18914 038 24X Fiche 50-528, 83/06/17,
8306210287

8306270143 Forwards schedule for submittal of info required for NRC review of SAR Schedule covers submittal of revised security plan & addl CESSAR interface requirements
VAN BRUNT, E E Arizona Public Service Co 83/06/20 KNIGHTON, G
Licensing Branch 3 6pp 18988 001 24X Fiche 50-528, 83/06/20,
8306270143

Q Adjudicatory correspondence

8306140429 Requests info needed to complete review of util proposed salt deposition & impact monitoring plan
DEWEY, L S Hearing Branch 3 83/06/10 PLATT, W E Snell & Wilmer
PLATT, W E Arizona Public Service Co 2pp 18898 045 24X
Fiche 50-528, 83/06/10, 8306140429

Q Inspection reports, IE Bulletins & correspondence

8306100009 Addl response to FOIA request for documents dtd 82D101 or after re SALP Forwards App A documents Documents also available in PDR
FELTON, J M Division of Rules and Records 83/04/11 CLARK, R. San
Francisco Examiner 3pp 18815 252 24X Fiche 50-000, 83/04/11,
8306100009

--8306100014 Submits schedule for Region V SALP Board meetings for 820928-830523
ENGELKEN, R H Region 5, Office of Director 82/03/19
DENTON, H R Office of Nuclear Reactor Regulation, Director, 1p.
18815.255 24X Fiche 50-000, 83/04/11, 8306100009

8306101363 Requests extension until 830615 to determine suitable time for QA program implementation insp prior to OL issuance, per IE Insp Rept 50-528/83-06
ANDOGNINI, G C Arizona Public Service Co 83/05/13 STERNBERG, D M
Region 5, Office of Director 1p 18681 349 24X
Fiche 50-528, 83/05/13, 8306101363

8306070005 Forwards IE Insp Rept 50-528/83-17 on 830502-06 No noncompliance noted
STERNBERG, D M Region 5, Office of Director 83/05/24 VAN
BRUNT, E E Arizona Public Service Co 2pp 18736 337 24X
Fiche 50-528, 83/05/24, 8306070005

--8306070007 IE Insp Rept 50-528/83-17 on 830502-06 No noncompliance noted Major areas inspected allegations associated w/ electrical & coating activities & licensee action on previous insp findings
NARDUT, P P, BURDOIN, J F, YOUNG, T Region 5, Office of Director
83/05/23 16pp 18736 339 24X Fiche 50-528, 83/05/24, 8306070009

8306070252 Forwards IE Insp Repts 50-528/83-18, 50-529/83-10 & 50-530/83-08 on 830301-0430 & notice of violation.
STERNBERG, D M Region 5, Office of Director 83/05/25 VAN
BRUNT, E E Arizona Public Service Co 2pp 18740 340 24X
Fiche 50-528, 83/05/25, 8306070252

--8306070253 Notice of violation from insp on 830301-0430
VORDBRUEGGEN, Region 5, Office of Director 83/05/25, 2pp
18740 342, 24X Fiche 50-528, 83/05/25, 8306070252,

--8306070256 IE Insp Repts 50-528/83-18, 50-529/83-10 & 50-530/83-08 on 830301-0430 Noncompliance noted: power cables for containment spray pump drive motors w/unsupported lengths longer than 24 inches & cables trays not grounded at both ends.
VORDBRUEGGEN, YOUNG, T Region 5, Office of Director 83/05/24
6pp 18740 344, 24X Fiche 50-528, 83/05/25, 8306070252,

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post
830103) 83/05/26 Consolidated Edison Co. of New York, Inc.
125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co. of New
York, Inc. 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/31 Consolidated Edison Co. of New
York, Inc. 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306280137 Forwards IE Insp Rept 50-528/83-12 on 830424-29 & 0512 No noncompliance noted.
BODK, H E Region 5, Office of Director, 83/06/03 ANDOGNINI, G. C.
Arizona Public Service Co 2pp 19014 333 24X
Fiche 50-528, 83/06/03, 8306280137,

--8306280145 IE Insp Rept 50-528/83-12 on 830424-29 & 0512, No noncompliance noted Major areas inspected. Followup on IE info notices, organization & staffing, environment protection, resolution 10CFR50.55(e) & NUREG-0737, items 11 F.1 & 11.1.3.
SHERMAN, C, NORTH, H B, WENGLAWSKI, F. A. Region 5, Office of
Director 83/06/03, 16pp, 19014 335, 24X Fiche 50-528, 83/06/03,
8306280137

DOCKETED ITEMS

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/09 Consolidated Edison Co of New
York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8306280450 Forwards IE Insp Repts 50-528/83-19 & 50-529/83-11 on
830502-31 No noncompliance noted
STERNBERG, D M Region 5, Office of Director 83/06/09
ANDOGNINI, O C Arizona Public Service Co 2pp 19020 168 24X
Fiche 50-528, 83/06/09, 8306280450

--8306280452 IE Insp Repts 50-528/83-19 & 50-529/83-11 on 830502-31 No
noncompliance noted Major areas inspected startup testing
procedures, plant cleanliness, control room cooler line
rupture & allegation re lifting of leads
FIORILLI, O, JOHNSTON, O, YOUNG, T Region 5, Office of Director
83/06/03 6pp 19020 170 24X Fiche 50-528, 83/06/09, 8306280450

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive &
Seismically Induced Chatter in Relays Within Printed
Circuit Cards " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New
York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From
Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New
York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8306230252 Responds to IE Insp Rept 50-528/83-06 & requests proposed &
alternate dates for Insp of QA program Suggests 830822-26
as Insp date & 830829-0902 as alternate date
ANDOGNINI, O C Arizona Public Service Co 83/06/14 STERNBERG, D M
Region 5, Office of Director 1p 18745 226 24X
Fiche 50-528, 83/06/14, 8306230252

8306280515 Forwards IE Insp Rept 50-528/83-21 on 830523-27 No
noncompliance noted
STERNBERG, D M Region 5, Office of Director 83/06/14
ANDOGNINI, O C Arizona Public Service Co 2pp 19017 199 24X
Fiche 50-528, 83/06/14, 8306280515

--8306280519 IE Insp Rept 50-528/83-21 on 830523-27 No noncompliance
noted Major areas inspected fire protection/prevention
program & program implementation
SCOHN, K, YOUNG, T Region 5, Office of Director 83/06/14 8pp
19017-201 24X Fiche 50-528, 83/06/14, 8306280519

8306280303 Forwards IE Insp Rept 50-528/83-20 on 830524-25 No
noncompliance noted
BOOK, H Region 5, Office of Director 83/06/16 VAN BRUNT, E E
Arizona Public Service Co, 2pp 19014 097 24X
Fiche: 50-528, 83/06/16, 8306280303

--8306280310 IE Insp Rept 50-528/83-20 on 830524-25 No noncompliance
noted Major areas inspected lab capability to perform
chemical & radiochemical analyses
HAMADA, O, WENGLAWSKI, F, BOOK, H E Region 5, Office of Director
83/06/16 3pp 19014 099 24X Fiche 50-528, 83/06/16, 8306280303

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New
York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys
Causing Inoperability of Safety-Related Equipment " Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New
York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc
list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co of New
York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110477

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate
Range (IR) High Flux Trip Setpoints " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co of New
York, Inc 116pp 19046 277 24X Fiche 50-000, 83/06/24, 8305110483

5 Reportable occurrences, LERs & related correspondence

8306010137 Interim Deficiency Rept DER 83-9 re low pressure safety
injection pump A suction strainer containing foreign matl &
pump D w/ torn strainer Initially reported on 830216 Due to
extensive evaluation, final rept will be submitted by 830715
VAN BRUNT, E E Arizona Public Service Co 83/05/11 STERNBERG, D M
Region 5, Office of Director 2pp 18674 042 24X
Fiche 50-528, 83/05/11, 8306010137

8306010289 Interim Deficiency Rept DER 83-22 re failure of ITE Gould
circuit breaker for hydrogen recombiner to function
properly Initially reported on 830413 Dechtel & Rockwell
Intl working on circuit breaker Next rept by 831108
VAN BRUNT, E E Arizona Public Service Co 83/05/11 STERNBERG, D M
Region 5, Office of Director 3pp 18672 195 24X
Fiche 50-528, 83/05/11, 8306010289

8306010076 Interim Deficiency Rept DER 83-10 re main steam relief valve
tests exceeding 5% blowdown limit Initially reported on
830228 Submittal of final rept extended to 830630
VAN BRUNT, E E Arizona Public Service Co 83/05/16 STERNBERG, D M
Region 5, Office of Director 2pp 18674 096 24X
Fiche 50-528, 83/05/16, 8306010076

8306010119 Interim deficiency rept re underground cables to startup
transformers unable to carry full-load current at max site
soil temp Initially reported on 821126 Final rept submittal
extended to 830729 due to extensive investigation
VAN BRUNT, E E Arizona Public Service Co 83/05/16 STERNBERG, D M
Region 5, Office of Director 2pp 18673 360 24X
Fiche 50-528, 83/05/16, 8306010119

8306010272 Rev 2 to Final Deficiency Rept DER 82-78 re improperly
crimped termination lugs in control panels for water
chillers supplied by Carrier, revising panel numbers
Initially reported on 821217 Also reportable under Part 21
VAN BRUNT, E E Arizona Public Service Co 83/05/16 STERNBERG, D M
Region 5, Office of Director 3pp 18672 246 24X
Fiche 50-528, 83/05/16, 8306010272

8306010375 Final Deficiency Rept DER 82-39 re C-C valve limit switches
(Class IE) below max LOCA flood level in containment
Initially reported on 820730 Dechtel review complete
Condition determined not reportable per 10CFR50.55(e)
VAN BRUNT, E E Arizona Public Service Co 83/05/16 23pp
18682 050 24X Fiche 50-528, 83/05/16, 8306010375

8306010055 Final Deficiency Rept 83-24 re diesel generator tube oil &
jacket water heaters not maintaining required temp Initially
reported on 830421 Design Change Packages 25M-DG-029 &
3CM-DG-029 issued to install new heaters
VAN BRUNT, E E Arizona Public Service Co 83/05/18 STERNBERG, D M
Region 5, Office of Director 3pp 18673 330 24X
Fiche 50-528, 83/05/18, 8306010055

8306010072 Rev 1 to Interim Deficiency Rept DER 82-61 re potential for
reactor coolant pump diffuser ring cap screws to fail &
damage pump Initially reported on 821021 C-E reviewed
potential failure mechanisms final rept by 830725
VAN BRUNT, E E Arizona Public Service Co 83/05/18 STERNBERG, D M
Region 5, Office of Director 4pp 18673 274 24X
Fiche 50-528, 83/05/18, 8306010072

--8306010078 "Reactor Coolant Pump Diffuser Bolt Failure Summary "
COLDEN, F P Combustion Engineering, Inc 83-0002 83/04/06 0pp
18673 278 24X Fiche 50-528, 83/05/18, 8306010072

--8306010083 App 1 to, "Metallurgical Investigation of Diffuser/Reactor
Coolant Pump Casing Bolt Failures (7/1350) "
DOLANSKY, K W Combustion Engineering, Inc TR-MCH-112
82/11/24 30pp 18673 286 24X Fiche 50-528, 83/05/18, 8306010072

--8306010087 App 2 to, "Metallurgical Exam of Diffuser/Reactor Coolant
Pump Casing Bolts Returned From AZ Unit 2 (7/1350) "
DOLANSKY, K W Combustion Engineering, Inc TR-V-MCH-003
83/01/25 14pp 18673 316 24X Fiche 50-528, 83/05/18, 8306010072

8306070225 Final Deficiency Rept DER 83-23 re failure of MSIV bypass
valves to close in required time Initially reported on
830419 Solenoid valve replaced Problem investigation request
issued by Bechtel Also reported per Part 21
VAN BRUNT, E E Arizona Public Service Co 83/05/19 STERNBERG, D M
Region 5, Office of Director 5pp 18744 217 24X
Fiche 50-528, 83/05/19, 8306070225

8306100203 Part 21 rept re deficiency in six emergency standby diesel
generator sets mfg by Cooper Energy Svcs Jacket water heater
& lube oil heater will be replaced w/40 kW & 19 kW versions,
respectively, to maintain 120 F standby temp
STOLBA, F B Cooper Industries, Inc 83/05/20 Director's Office
Office of Inspection and Enforcement 2pp 18806 007 24X
Fiche 50-528, 83/05/20, 8306100203

8306070078 Interim Deficiency Rept DER 82-63 re design calculation error in refueling water tank seismic response Initially reported on 821026 Time extension requested until 830624 to submit final rept
VAN BRUNT, E E Arizona Public Service Co 83/05/24 STERNBERG, D M
Region 5, Office of Director 2pp 18739 272 24X
Fiche 50-528, 83/05/24, 8306070078

8306070221 Interim Deficiency Rept DER 82-56 re condensate storage tank design scaled-down w/o new calculations for seismic response Initially reported on 821015 Final rept delayed until 830624 due to extensive investigation & evaluation
VAN BRUNT, E E Arizona Public Service Co 83/05/24 STERNBERG, D M
Region 5, Office of Director 2pp 10746 136 24X
Fiche 50-528, 83/05/24, 8306070221

8306070178 Interim Deficiency Rept DER 82-46 re failure of ITI-Barton pressure transmitters supplied by OE to meet overpressure requirements Initially reported on 820824 Submittal of final rept delayed until 830830 due to extensive investigation
VAN BRUNT, E E Arizona Public Service Co 83/05/25 STERNBERG, D M
Region 5, Office of Director 2pp 10736 327 24X
Fiche 50-528, 83/05/25, 8306070178

8306170240 Interim Deficiency Rept DER 83-26 re balance of ESF actuation sys electronic module Failure in preoperational testing due to overheating Initially reported on 830427 Final evaluation expected by 830825
VAN BRUNT, E E Arizona Public Service Co 83/05/25 STERNBERG, D M
Region 5, Office of Director 3pp 10882 322 24X
Fiche 50-528, 83/05/25, 8306170240

8306170180 Interim Deficiency Rept DER 83-25 re lack of instrumentation tubing boundary class break requirements Initially reported on 830421 Evaluation & final rept will be submitted by 830630
VAN BRUNT, E E Arizona Public Service Co 83/05/26 STERNBERG, D M
Region 5, Office of Director 5pp 18883 258 24X
Fiche 50-528, 83/05/26, 8306170180

8306170244 Final Deficiency Rept DER 83-28 re Pacific Scientific snubbers installed in violation of reserve range requirements Initially reported on 830427 Spec Change Notice 2390 issued to clarify intent of Spec 13-PM-204
VAN BRUNT, E E Arizona Public Service Co 83/06/01 STERNBERG, D M
Region 5, Office of Director 5pp 18883 294 24X
Fiche 50-528, 83/06/01, 8306170244

8306170342 Interim Deficiency Rept 82-51 re Pullman-Kellogg essential cooling water sys pipeline failure Completion date for final rept extended to 830706
VAN BRUNT, E E Arizona Public Service Co 83/06/01 STERNBERG, D M
Region 5, Office of Director 2pp 18880 289 24X
Fiche 50-528, 83/06/01, 8306170342

8306170393 Interim Deficiency Rept DER 82-50 re possibility of damage to flexible conduit couplings between auxiliary & control bldgs if seismic event exceeds 3/4-inch movement Initially reported on 820910 Final rept will be available by 830706
VAN BRUNT, E E Arizona Public Service Co 83/06/01 STERNBERG, D M
Region 5, Office of Director 2pp 18880 238 24X
Fiche 50-528, 83/06/01, 8306170393

8306170366 Interim Deficiency Rept DER 83-31 re temp rise in diesel generator control cabinet potentially exceeding design requirements Initially reported on 830505 Bechtel & Cooper Envrn Svcs evaluating condition Final rept by 830906
VAN BRUNT, E E Arizona Public Service Co 83/06/06 STERNBERG, D M
Region 5, Office of Director 3pp 10880 319 24X
Fiche 50-528, 83/06/06, 8306170366

8306170367 Final Deficiency Rept DER-29 re two pipe hangers in safety injection sys not installed as designed Supports 1-SI-100-H-006 & 1-SI-106-H-007 repaired per design drawings & drawings revised to clarify bar locations
VAN BRUNT, E E Arizona Public Service Co 83/06/06 STERNBERG, D M
Region 5, Office of Director 6pp 18880 220 24X
Fiche 50-528, 83/06/06, 8306170367

8306130150 Part 21 rept re solenoid activated valves, Models 77C-001 & 77C-003 Defects include incorrect valve assembly, significant missing parts, limited switch valve position indication failures & failure of valve to open & close
PUTTARINI, D M Target Rock Corp 83/06/07 DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement 7pp. 18824 267 24X Fiche 50-528, 83/06/07, 8306130150

8306230270 Final Deficiency Rept DER 83-28 re Pacific Scientific snubbers installed in violation of reserve range requirements. Deficiency determined not reportable per 10CFR50.55(e).
VAN BRUNT, E E Arizona Public Service Co 83/06/08 STERNBERG, D M
Region 5, Office of Director 4pp 18745 108 24X
Fiche 50-528, 83/06/08, 8306230270

8306230318 Advises that final Deficiency Rept DER 83-14 re Westinghouse diesel generator protective relay failures due to leaking capacitors will be submitted by 830831 Delay due to extensive investigation & evaluation
VAN BRUNT, E E Arizona Public Service Co 83/06/08 STERNBERG, D M
Region 5, Office of Director 2pp 18744 164 24X
Fiche 50-528, 83/06/08, 8306230318

8306230408 Interim Deficiency Rept DER 83-10 re main steam relief valve test exceeding specified 5X blowdown limit Initially reported on 830228 Submittal of final rept delayed until 830818 due to extensive investigation & evaluation required
VAN BRUNT, E E Arizona Public Service Co 83/06/08 STERNBERG, D M
Region 5, Office of Director 2pp 18743 132 24X
Fiche 50-528, 83/06/08, 8306230408

8306230245 Requests extension until 830714 to submit final deficiency rept re requirements on tagged-out cable terminations, due to extensive investigation & evaluation required
VAN BRUNT, E E Arizona Public Service Co 83/06/15 STERNBERG, D M
Region 5, Office of Director 2pp 18745 231 24X
Fiche 50-528, 83/06/15, 8306230245

DOCKET STN-50-529 PALO VERDE NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8306080284 FOIA request for documents re R Qunderson & Bechtel senior manager allegations concerning electrical problems & deficiencies at facilities Waiver of fees requested.
YOUNG, M C Government Accountability Project 83/03/29 Office of Administration 2pp 18790 357 24X Fiche 50-528, 83/03/29, 8306080284

8306140225 Forwards Conference Notes CN-E-1255 from 830323 meeting w/util, counsel, Bechtel, NRC & C-E in Washington, DC re post-LUCA containment sump
WILSON, W H Bechtel Corp 83/04/14 VAN BRUNT, E E Arizona Public Service Co 3pp 18844 322 24X Fiche 50-528, 83/04/14, 8306140225

8306080281 Partial response to FOIA request for documents re R Qunderson & Bechtel allegations concerning electrical problems at facilities App A Documents 1 & 2 available in PDR Documents 3, 4 & 5 withheld (ref FOIA Exemption 5).
FELTON, J M Division of Rules and Records 83/04/28 YOUNG, M C Government Accountability Project 3pp 18790 354 24X
Fiche 50-528, 83/04/28, 8306080281

8306020627 Notification of 830622-23 & 24 meetings w/util in Maricopa & Phoenix, AZ, respectively, to assess current status of const LICITRA, E A Licensing Branch 3 83/05/24 KNIGHTON, O W Licensing Branch 3 6pp 18716 339 24X Fiche 50-528, 83/05/24, 8306020627

8306070091 Advises that schedule for responding to five confirmatory items & completion of qualification program for safety-related pumps & valves will be submitted by 830630
VAN BRUNT, E E Arizona Public Service Co 83/05/31 KNIGHTON, O W Licensing Branch 3 1p 18739 141 24X Fiche 50-528, 83/05/31, 8306070091

8306080097 Summary of 830517 meeting w/util, C-E & Bechtel in Bethesda, MD re NRC 830314 requested info on environ qualifications Environ qualification audit scheduled during wk of 830627
LICITRA, E A Licensing Branch 3 83/06/01 Licensing Branch 3 4pp 18787 327 24X Fiche 50-528, 83/06/01, 8306080097

8306200051 Notification of 830608 meeting w/util in Bethesda, MD to discuss control room design review
LICITRA, E A Licensing Branch 3 83/06/03 KNIGHTON, O W Licensing Branch 3 3pp 18908 286 24X Fiche 50-528, 83/06/03, 8306200051

8306200053 Notification of 830628-30 & 0701 meetings w/util, Bechtel, C-E & E&O in Phoenix & Maricopa County, AZ to conduct audit of equipment environ qualification documentation.
LICITRA, E A Licensing Branch 3 83/06/03 KNIGHTON, O W Licensing Branch 3 3pp 18908 289 24X Fiche 50-528, 83/06/03, 8306200053

8306170265 Forwards marked-up Amend 12 to FSAR Section 17.1 re QA program for engineering, design procurement & const of facility, per 10CFR50.55(f).
VAN BRUNT, E E Arizona Public Service Co 83/06/10 STERNBERG, D M Region 5, Office of Director 82pp 18877 274 24X
Fiche 50-528, 83/06/10, 8306170265

DOCKETED ITEMS

8306170302 Forwards App J to, "Evaluation of Pressurized Thermal Shock Effects Due to Small Break LOCAs W/Loss of Feedwater for Palo Verde 1 & 2, 2 & 3 Reactor Vessels " Rept applies to only Unit 1
VAN BRUNT, E E. Arizona Public Service Co 83/06/14 KNIGHTON, G
Licensing Branch 3 3pp 18878 197 24X Fiche 50-528, 83/06/14,
8306170302

8306170351 Forwards response to 830503 request for info supplementing 830322 info on FSAR Table 3 2-1 re quality classification of structures, sys & components
VAN BRUNT, E E. Arizona Public Service Co 83/06/14 KNIGHTON, G
Licensing Branch 3 14pp 18881-005 24X Fiche 50-528, 83/06/14,
8306170351

8306240458 Summary of 830608 meeting w/util in Bethesda, MD re detailed control room design review
LICITRA, E A. Licensing Branch 3 83/06/14 Licensing Branch 3
4pp 18998 001 24X Fiche 50-528, 83/06/14, 8306240458

8306280436 Forwards Amend 1 to environ qualification rept. per 830314 request & NUREG-0586 requirements
VAN BRUNT, E E. Arizona Public Service Co 83/06/24 KNIGHTON, G
Licensing Branch 3 228pp. 19016 297 24X Fiche 50-528, 83/06/24,
8306280436

E NRC Safety Evaluation Report (SER), supp's & correspondence

8306130432 Responds to 830328 request for addl info re adequacy of electric distribution sys voltages per SER (NUREG-0857)
Response re adequacy of util info requested within 2 wks
VAN BRUNT, E E. Arizona Public Service Co 83/06/07. KNIGHTON, G
Licensing Branch 3. 6pp 18821:195 24X Fiche 50-528, 83/06/07,
8306130432

8306160500 Advises that procedures indicating shutdown cooling relief valves armed by manually opening shutdown cooling sys isolation valves will be utilized until operable low temp overpressure alarm available. per NUREG-0857, Suppl 1
VAN BRUNT, E E. Arizona Public Service Co 83/06/13 KNIGHTON, G
Licensing Branch 3 1p 18064 154 24X Fiche 50-528, 83/06/13,
8306160500

8306170326 Forwards proposed amend to FSAR re CESSAR iodine removal sys & responses to NRC 830422 ltr Proposed FSAR amend combined w/responses closes out sump ph issue in SER Sections 6.4 & 15.4 B & TMI Item III D 3.4
VAN BRUNT, E E. Arizona Public Service Co 83/06/13 KNIGHTON, G
Licensing Branch 3 8pp 18879 040 24X Fiche 50-528, 83/06/13,
8306170326

8306270368 Forwards responses to SER, Suppl 4, Sections 13.3.2.2 & 13.3.2.3 (NUREG-0857), re courses of action necessary in unlikely event of emergency at facilities info will be included in Rev 3 to emergency plan
VAN BRUNT, E E. Arizona Public Service Co. 83/06/15. KNIGHTON, G
Licensing Branch 3 26pp 18993 214 24X Fiche 50-528, 83/06/15,
8306270368

8306210287 Forwards program plan issues & areas for outstanding items re NUREG-0737, Item I D 1 re detailed control room design review per NUREG-0700 requirements & SER, NUREG-0857 Generic Ltr 82-33 issues addressed
VAN BRUNT, E E. Arizona Public Service Co 83/06/17 KNIGHTON, G
Licensing Branch 3 36pp 18914 038 24X Fiche 50-528, 83/06/17,
8306210287

8306280317 Submits required data to demonstrate that line voltage regulators perform as acceptable isolation device by limiting primary current under short circuit conditions to full-load primary current. per SER (NUREG-0857)
VAN BRUNT, E E. Arizona Public Service Co 83/06/23 KNIGHTON, G
Licensing Branch 3. 1p 19001, 282 24X Fiche 50-528, 83/06/23,
8306280317.

F. Security, medical, emergency & fire protection plans

8306170356 Forwards description & list of objectives for 830511 emergency preparedness exercise Scenario will be provided within 30 days. Comments requested within 15 days of ltr date.
ANDONINI, G C. Arizona Public Service Co 83/03/02 GRIMES, B K
Division of Emergency Preparedness (Pre 830103) 19pp. 18880 333
24X Fiche: 50-528, 83/03/02, 8306170356

--8306170360 Forwards description & list of objectives for 830511 emergency preparedness exercise. Scenario will be provided within 30 days. Comments requested within 15 days of ltr date.
ANDONINI, G C. Arizona Public Service Co 83/03/02 MARTIN, R.
Region 3, Office of Director. 10pp 18880.352. 24X
Fiche. 50-528, 83/03/02, 8306170356

8306020056 Responds to 830414 ltr re Generic Ltr 82-33 requirements concerning Suppl 1 to NUREG-0737 Portion of response addressing detailed control room design review does not provide all info requested Response requested by 830531
KNIGHTON, G W. Licensing Branch 3 83/05/10 VAN BRUNT, E E
Arizona Public Service Co 6pp 18701 349 24X
Fiche 50-528, 83/05/10, 8306020056

8306030357 Advises that addl info re detailed control room design review per Generic Ltr 82-33 re emergency response capabilities will be submitted by 830617
VAN BRUNT, E E. Arizona Public Service Co 83/06/01 KNIGHTON, G
Licensing Branch 3 1p 18705 214 24X Fiche 50-528, 83/06/01,
8306030357

8306090273 Releases public version of revised emergency plan implementing procedures
FELTON, J M. Division of Rules and Records 83/06/03 Document
Management Branch 1p 18810 067 24X Fiche 50-528, 83/06/07,
8306090273

--8306090275 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP-01 re emergency organization, EPIP-02 re emergency classification & EPIP-04 re alert implementing actions.
VAN BRUNT, E E. Arizona Public Service Co 83/05/23 KNIGHTON, G
Licensing Branch 3 3pp 18810 060 24X Fiche 50-528, 83/06/03,
8306090273

--8306090276 Public version of revised emergency plan implementing procedures, including Procedures EPIP-01 re emergency organization, EPIP-02 re emergency classification & EPIP-04 re alert implementing actions
LUCIA, B. Arizona Public Service Co 83/03/30 708pp 18810 071
24X Fiche 50-528, 83/06/03, 8306090276

8306200371 Forwards responses to open items from NRC 830201-03 fire protection audit.
VAN BRUNT, E E. Arizona Public Service Co 83/06/15 KNIGHTON, G
Licensing Branch 3 31pp 18899 056 24X Fiche 50-528, 83/06/15,
8306200371

8306270368 Forwards responses to Ser, Suppl 4, Sections 13.3.2.2 & 13.3.2.3 (NUREG-0857), re courses of action necessary in unlikely event of emergency at facilities info will be included in Rev 3 to emergency plan
VAN BRUNT, E E. Arizona Public Service Co 83/06/15 KNIGHTON, G
Licensing Branch 3 26pp 18993 214 24X Fiche 50-528, 83/06/15,
8306270368

8306270447 Responds to Generic Ltr 82-33 re Suppl 1 to NUREG-0737 concerning requirements for emergency response capability Unit 1 selected as backup emergency operations facility Exemptions from 10-mile criteria requested
VAN BRUNT, E E. Arizona Public Service Co 83/06/16 KNIGHTON, G
Licensing Branch 3 3pp 18992 095 24X Fiche 50-528, 83/06/16,
8306270447

8306210287 Forwards program plan issues & areas for outstanding items re NUREG-0737, Item I D 1 re detailed control room design review per NUREG-0700 requirements & SER, NUREG-0857 Generic Ltr 82-33 issues addressed
VAN BRUNT, E E. Arizona Public Service Co 83/06/17 KNIGHTON, G
Licensing Branch 3 36pp 18914 038 24X Fiche 50-528, 83/06/17,
8306210287

G. Adjudicatory correspondence

8306030333 Response to second set of interrogatories Certificate of Svc encl
BERLIN, K. West Valley Agricultural Protection Council, Inc.
83/06/01 Office of the Executive Legal Director 10pp
18709 018 24X Fiche 50-529, 83/06/01, 8306030333

--8306030334 Request for production of documents identified in response to first & second set of interrogatories & documents requested in interrogatories Certificate of Svc encl
BERLIN, K. West Valley Agricultural Protection Council, Inc.
83/06/01 Arizona Public Service Co 6pp. 18709 028 24X
Fiche 50-529, 83/06/01, 8306030333

--8306030335 Response to second set of interrogatories Certificate of Svc encl.
BERLIN, K. West Valley Agricultural Protection Council, Inc.
83/06/01 Arizona Public Service Co. 42pp 18709 034. 24X
Fiche 50-529, 83/06/01, 8306030333

DOCKETED ITEMS

365

- 8306150398 Stipulation agreeing that motions to compel interrogatory answers due 830715 & supplemental info responding to interrogatories due 830701 Proposed order & Certificate of Svc encl
DEWEY, L. S. Hearing Branch 3 BERLIN, K. West Valley Agricultural Protection Council, Inc. PLATT, W. Joint Applicants-Palo Verde 83/06/01 5pp 18847 140 24X Fiche 50-529, 83/06/01, 8306150398
- 8306090311 Withdrawal of 830526 request to extend time to respond to revised discovery schedule No addl time needed to review schedule Schedule acceptable Certificate of Svc encl
DEWEY, L. S. Hearing Branch 3 83/06/08 Atomic Safety and Licensing Board Panel 3pp 18795 196 24X Fiche 50-529, 83/06/08, 8306090311
- 8306100075 Forwards West Valley Agricultural Protection Council, Inc & Joint Applicants stipulation re discovery schedule mod
ENO, M. B. West Valley Agricultural Protection Council, Inc 83/06/09 LAZO, R. M. Atomic Safety and Licensing Board Panel 1p 18803 164 24X Fiche 50-529, 83/06/09, 8306100075
- 8306100078 Stipulation agreeing to comply w/provisions of proposed order, unless & until further mod requested by parties ASLB should enter encl order re discovery schedule mod
BERLIN, K. West Valley Agricultural Protection Council, Inc PLATT, W. E. Joint Applicants-Palo Verde PLATT, W. E. Snell & Wilmer 83/06/09 6pp 18803 165 24X Fiche 50-529, 83/06/09, 8306100078
- 8306140429 Requests info needed to complete review of util proposed salt deposition & impact monitoring plan
DEWEY, L. S. Hearing Branch 3 83/06/10 PLATT, W. E. Snell & Wilmer PLATT, W. E. Arizona Public Service Co 2pp 18838 045 24X Fiche 50-528, 83/06/10, 8306140429
- 8306150304 Request for production of documents Certificate of Svc encl
CRAWFORD, V. A. Joint Applicants Palo Verde CRAWFORD, V. A. Snell & Wilmer 83/06/10 West Valley Agricultural Protection Council, Inc 10pp 18849 152 24X Fiche 50-529, 83/06/10, 8306150304
- 8306160622 Order directing motions to compel re interrogatory answers be filed by 830715 Supplemental responses to interrogatories to be filed by 830701
LAZO, R. M. Atomic Safety and Licensing Board Panel 83/06/14 1p. 18863 073 24X Fiche 50-529, 83/06/14, 8306160622
- 8306160629 Order delineating schedules for depositions, discovery on crop study & pretrial preparation
LAZO, R. M. Atomic Safety and Licensing Board Panel 83/06/14. App 18866 122 24X Fiche 50-529, 83/06/14, 8306160629
- 8306210264 Request for production of documents Certificate of Svc encl
DEWEY, L. S. Hearing Branch 3 83/06/17 West Valley Agricultural Protection Council, Inc 4pp 18915 027 24X Fiche 50-529, 83/06/17, 8306210264
- 8306210268 Request for production of documents Certificate of Svc encl
DEWEY, L. S. Hearing Branch 3 83/06/17 Arizona Public Service Co 4pp 18914 005 24X Fiche 50-529, 83/06/17, 8306210268
- 8306240284 Forwards util 830426 application for SNM license
DEWEY, L. S. Hearing Branch 3 83/06/21 LAZO, R. M. CALLIHAN, D. COLE, R. F. Atomic Safety and Licensing Board Panel. 149pp. 18979 291 24X Fiche 50-529, 83/06/21, 8306240284
- 0 Inspection reports, IE Bulletins & correspondence
- 8306100009 Addl response to FOIA request for documents dtd 820101 or after re BALP Forwards App A documents Documents also available in PDR
FELTON, J. M. Division of Rules and Records 83/04/11 CLARK, R. San Francisco Examiner 3pp. 18815 232 24X Fiche 50-000, 83/04/11, 8306100009
- 8306100014 Submits schedule for Region V BALP Board meetings for 820928-830523
ENGELKEN, R. H. Region 5, Office of Director 82/03/19. DENTON, H. R. Office of Nuclear Reactor Regulation, Director 1p. 18815 235 24X Fiche 50-000, 83/04/11, 8306100009
- 8306070252 Forwards IE Insp Repts 50-528/83-18, 50-529/83-10 & 50-530/83-08 on 830301-0430 Noncompliance noted power cables for containment spray pump drive motors w/unsupported lengths longer than 24 inches & cables trays not grounded at both ends
VORDERBRUEGGEN, YOUNG, T. Region 5, Office of Director 83/05/24. 6pp 18740 344. 24X Fiche 50-528, 83/05/25, 8306070252
- 830511045B IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Wall Logging Device " Svc list encl.
TAYLOR, J. M. Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 125pp 18831 043. 24X Fiche 50-000, 83/05/26, 830511045B
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460.
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461.
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/09 Consolidated Edison Co. of New York, Inc. 119pp. 18830 280. 24X Fiche 50-000, 83/06/09, 8305110464
- 8306280450 Forwards IE Insp Repts 50-528/83-19 & 50-529/83-11 on 830502-31 No noncompliance noted.
STERNBERG, D. H. Region 5, Office of Director, 83/06/09, ANDOQUINI, O. C. Arizona Public Service Co 2pp 19020 168 24X Fiche 50-528, 83/06/09, 8306280450
- 8306280452 IE Insp Repts 50-528/83-19 & 50-529/83-11 on 830502-31 No noncompliance noted Major areas inspected, startup testing procedures, plant cleanliness, control room cooler line rupture & allegation re lifting of leads.
FIORELLI, G. JOHNSTON, O. YOUNG, T. Region 5, Office of Director, 83/06/03 6pp. 19020 170 24X Fiche 50-528, 83/06/09, 8306280450.
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Electrically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470
- 8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 243pp 18921 001. 24X Fiche 50-000, 83/06/13, 8306090010.
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/22 Consolidated Edison Co. of New York, Inc. 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/22 Consolidated Edison Co. of New York, Inc 120pp. 18997 007 24X Fiche 50-000, 83/06/22, 8305110477.
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co. of New York, Inc. 116pp. 18996 242 24X Fiche 50-000, 83/06/23, 8305110479.
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc. 116pp. 19046 297. 24X Fiche 50-000, 83/06/24, 8305110483.
- 8 Reportable occurrences, IERs & related correspondence
- 8306010289 Interim Deficiency Rept DER 83-22 re failure of ITE Gould circuit breaker for hydrogen recombiner to function properly Initially reported on 830413, Bechtel & Rockwell Intl working on circuit breaker Next rept by 831108
VAN BRUNT, E. E. Arizona Public Service Co 83/05/11. STERNBERG, D. H. Region 5, Office of Director. 3pp 18672 195. 24X Fiche 50-528, 83/05/11, 8306010289
- 8306070253 Notice of Violation from insp on 830301-0430.
VORDERBRUEGGEN, Region 5, Office of Director, 83/05/25. 2pp. 18740 342 24X Fiche 50-528, 83/05/25, 8306070252

DOCKETED ITEMS

8306010341 Rev 1 to Final Deficiency Rept DER 81-29 re failure of ASTM A490 bolts Initially reported on 8/05/11. Defective bolts replaced Insp program implemented to verify bolt tension Also reportable per Part 21
VAN BRUNT, E E Arizona Public Service Co 83/05/11 STERNBERG, D M
Region 5, Office of Director 3pp 18681:289 24X
Fiche: 50-529, 83/05/11, 8306010341

8306010076 Interim Deficiency Rept DER 83-10 re main steam relief valve tests exceeding 5% blowdown limit Initially reported on 830228 Submittal of final rept extended to 830630
VAN BRUNT, E E Arizona Public Service Co 83/05/16 STERNBERG, D M
Region 5, Office of Director 2pp 18674 096 24X
Fiche 50-528, 83/05/16, 8306010076

8306010119 Interim deficiency rept re underground cables to startup transformers unable to carry full-load current at max site soil temp Initially reported on 821126 Final rept submittal extended to 830729 due to extensive investigation
VAN BRUNT, E E Arizona Public Service Co 83/05/16 STERNBERG, D M
Region 5, Office of Director 2pp 18673 360. 24X
Fiche 50-528, 83/05/16, 8306010119.

8306010272 Rev 2 to Final Deficiency Rept DER 82-78 re improperly crimped termination lugs in control panels for water chillers supplied by Carrier, revising panel numbers Initially reported on 821217 Also reportable under Part 21
VAN BRUNT, E E Arizona Public Service Co 83/05/16 STERNBERG, D M
Region 5, Office of Director 3pp 18672-246 24X
Fiche: 50-528, 83/05/16, 8306010272

8306010072 Rev 1 to Interim Deficiency Rept DER 82-61 re potential for reactor coolant pump diffuser ring cap screws to fail & damage pump Initially reported on 821021. C-E reviewed potential failure mechanisms Final rept by 830725
VAN BRUNT, E E Arizona Public Service Co. 83/05/18 STERNBERG, D M
Region 5, Office of Director 4pp. 18673 274 24X
Fiche 50-528, 83/05/18, 8306010072

--8306010087 App 2 to, "Metallurgical Exam of Diffuser/Reactor Coolant Pump Casing Bolts Returned From AZ Unit 2 (791350) "
DOLLANSKY, K W Combustion Engineering, Inc TR-V-MCM-003
83/01/25 14pp 18673 316 24X Fiche 50-528, 83/05/18, 8306010072

8306070225 Final Deficiency Rept DER 83-23 re failure of MSIV bypass valves to close in required time. Initially reported on 830419 Solenoid valve replaced Problem investigation request issued by Bechtel Also reported per Part 21
VAN BRUNT, E E Arizona Public Service Co. 83/05/19 STERNBERG, D M
Region 5, Office of Director 3pp 18744, 217 24X
Fiche: 50-528, 83/05/19, 8306070225

8306100203 Part 21 rept re deficiency in six emergency standby diesel generator sets mfg by Cooper Energy Svcs Jacket water heater & lube oil heater will be replaced w/40 kW & 19 kW versions, respectively, to maintain 120 F standby temp
STOLBA, F B Cooper Industries, Inc 83/05/20 Director's Office,
Office of Inspection and Enforcement 2pp 18806 007. 24X
Fiche: 50-528, 83/05/20, 8306100203

8306070078 Interim Deficiency Rept DER 82-63 re design calculation error in refueling water tank seismic response. Initially reported on 821026 Time extension requested until 830624 to submit final rept
VAN BRUNT, E E Arizona Public Service Co 83/05/24 STERNBERG, D M
Region 5, Office of Director 2pp. 18739-272 24X
Fiche 50-528, 83/05/24, 8306070078.

8306070104 Interim Deficiency Rept DER 83-15 re ASTM A354 anchor bolt supplied by Marathon Steel breaking under installation torque after test acceptance Initially reported on 830318 Alternate column base anchoring detail will be installed.
VAN BRUNT, E E Arizona Public Service Co 83/05/24 STERNBERG, D M
Region 5, Office of Director. 3pp 18739-172 24X
Fiche. 50-529, 83/05/24, 8306070104.

--8306070107 "Failure Analysis of ASTM A-354 Bolt for Palo Verde Nuclear Generating Station "
BINGHAM, W O, GONZALES, J C, SCHMIDT, O R. Bechtel Corp. 0383-03
PA 83/05/24 177. 24X Fiche: 50-529, 83/05/24.

t DER 83-25 re lack of instrumentation
measurements. Initially reported
pt will be submitted by

Service Co. 83/05/26 STERNBERG, D M.
3pp. 18883, 258. 24X
0

8306170341 Interim Deficiency Rept DER 83-30 re broken anchor bolt A354 on feedwater pump during torquing Initially reported on 830505 Test program developed & conducted to assess torque values Final rept expected by 830817
VAN BRUNT, E E Arizona Public Service Co 83/06/06 STERNBERG, D M
Region 5, Office of Director 3pp 18880 286 24X
Fiche 50-529, 83/06/06, 8306170341

8306170366 Interim Deficiency Rept DER 83-31 re temp rise in diesel generator control cabinet potentially exceeding design requirements Initially reported on 830505 Bechtel & Cooper Energy Svcs evaluating condition Final rept by 830906
VAN BRUNT, E E Arizona Public Service Co 83/06/06 STERNBERG, D M
Region 5, Office of Director 3pp 18880 319 24X
Fiche 50-528, 83/06/06, 8306170366

8306130150 Part 21 rept re solenoid activated valves, Models 77C-001 & 77C-003 Defects include incorrect valve assembly, significant missing parts, limited switch valve position indication failures & failure of valve to open & close
PUTTARINI, D M Target Rock Corp 83/06/07 DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement 7pp
18824 267 24X Fiche 50-528, 83/06/07, 8306130150

8306230318 Advises that final Deficiency Rept DER 83-14 re Westinghouse diesel generator protective relay failures due to leaking capacitors will be submitted by 830831 Delay due to extensive investigation & evaluation
VAN BRUNT, E E Arizona Public Service Co 83/06/08 STERNBERG, D M
Region 5, Office of Director 2pp 18944 164 24X
Fiche 50-528, 83/06/08, 8306230318

8306230379 Rev 1 to Interim Deficiency Rept DER 82-73 re excessive gap between pipe & pipe clamp across ITT Grinnell pipe support clamps Initially reported on 821124 Clamps acceptable w/two or four-area contact Final rept to be submitted by 830901
VAN BRUNT, E E Arizona Public Service Co 83/06/08 STERNBERG, D M
Region 5, Office of Director 3pp 18943 244 24X
Fiche 50-529, 83/06/08, 8306230379

DOCKET STN-50-530 PALO VERDE NUCLEAR STATION, UNIT 3

A Application/construction stage documents & correspondence

8306140225 Forwards Conference Notes CN-E-1255 from 830323 meeting w/util, counsel, Bechtel, NRC & C-E in Washington, DC re post-LUCA containment sump
WILSON, W H Bechtel Corp 83/04/14 VAN BRUNT, E E Arizona Public Service Co 3pp 18844 322 24X Fiche 50-528, 83/04/14, 8306140225

8306080281 Partial response to FOIA request for documents re R Gunderson & Bechtel allegations concerning electrical problems at facilities App A Documents 1 & 2 available in PDR Documents 3, 4 & 5 withheld (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records 83/04/28 YOUNG, M C
Government Accountability Project 3pp 18790 354 24X
Fiche 50-528, 83/04/28, 8306080281

8306020627 Notification of 830622-23 & 24 meetings w/util in Maricopa & Phoenix, AZ, respectively, to assess current status of const
LICITRA, E A Licensing Branch 3 83/05/24 KNIGHTON, Q W
Licensing Branch 3 3pp 18716 339 24X Fiche 50-528, 83/05/24, 8306020627

8306070091 Advises that schedule for responding to five confirmatory items & completion of qualification program for safety-related pumps & valves will be submitted by 830630
VAN BRUNT, E E Arizona Public Service Co 83/05/31 KNIGHTON, Q W
Licensing Branch 3 1p 18739 141. 24X Fiche 50-528, 83/05/31, 8306070091

8306080097 Summary of 830517 meeting w/util, C-E & Bechtel in Bethesda, MD re NRC 830314 requested info on environ qualifications
Environ qualification audit scheduled during wk of 830627
LICITRA, E A Licensing Branch 3 83/06/01 Licensing Branch 3
4pp. 18787 327 24X Fiche 50-528, 83/06/01, 8306080097

8306200051 Notification of 830608 meeting w/util in Bethesda, MD to discuss control room design review
LICITRA, E A Licensing Branch 3 83/06/03 KNIGHTON, Q W
Licensing Branch 3 3pp 18908 286 24X Fiche 50-528, 83/06/03, 8306200051

8306200053 Notification of 830628-30 & 0701 meetings w/util, Bechtel, C-E & E&O in Phoenix & Maricopa County, AZ to conduct audit of equipment environ qualification documentation
LICITRA, E A Licensing Branch 3 83/06/03 KNIGHTON, Q W
Licensing Branch 3 3pp 18908 289 24X Fiche 50-528, 83/06/03, 8306200053

8306170265 Forwards marked-up Amend 12 to FSAR Section 17.1 re QA program for engineering, design procurement & const of facility, per 10CFR50.55(f)
VAN BRUNT, E E Arizona Public Service Co 83/06/10 STERNBERG, D M
Region 5, Office of Director 02pp 18877 274 24X
Fiche 50-528, 83/06/10, 8306170265

8306170302 Forwards App J to, "Evaluation of Pressurized Thermal Shock Effects Due to Small Break LOCAs W/Loss of Feedwater For Palo Verde 1 & 2, P & 3 Reactor Vessels " Rept applies to only Unit 1
VAN BRUNT, E E Arizona Public Service Co 83/06/14 KNIGHTON, O
Licensing Branch 3 3pp 18878 197 24X Fiche 50-528, 83/06/14,
8306170302

8306170351 Forwards response to 830503 request for info supplementing 830322 info on FSAR Table 3.2-1 re quality classification of structures, sys & components
VAN BRUNT, E E Arizona Public Service Co 83/06/14 KNIGHTON, O
Licensing Branch 3 14pp 18881 005 24X Fiche 50-528, 83/06/14,
8306170351

8306240458 Summary of 830608 meeting w/util in Bethesda, MD re detailed control room design review
CICITRA, E A Licensing Branch 3 83/06/14 Licensing Branch 3
4pp 18978 001 24X Fiche 50-528, 83/06/14, 8306240458

8306280436 Forwards Amend 1 to environ qualification rept, per 830314 request & NUREG-0858 requirements
VAN BRUNT, E E Arizona Public Service Co 83/06/24 KNIGHTON, O
Licensing Branch 3 228pp 19016 297 24X Fiche 50-528, 83/06/24,
8306280436

E NRC Safety Evaluation Report (SER), suppl & correspondence

8306130432 Responds to 830328 request for addl info re adequacy of electric distribution sys voltages per SER (NUREG-0857)
Response re adequacy of util info requested within 2 wks
VAN BRUNT, E E Arizona Public Service Co 83/06/07 KNIGHTON, O
Licensing Branch 3 6pp 18821 195 24X Fiche 50-528, 83/06/07,
8306130432

8306160500 Advises that procedures indicating shutdown cooling relief valves armed by manually opening shutdown cooling sys isolation valves will be utilized until operable low temp overpressure alarm available, per NUREG-0857, Suppl 1
VAN BRUNT, E E Arizona Public Service Co 83/06/13 KNIGHTON, O
Licensing Branch 3 1p 18864 156 24X Fiche 50-528, 83/06/13,
8306160500

8306170326 Forwards proposed amend to FSAR re CESSAR iodine removal sys & responses to NRC 830428 ltr Proposed FSAR amend combined w/responses closes out sump ph issue in SER Sections 4.4 & 15.4 B & TMI Item III D 3.4
VAN BRUNT, E E Arizona Public Service Co 83/06/13 KNIGHTON, O
Licensing Branch 3 8pp 18879 040 24X Fiche 50-528, 83/06/13,
8306170326

8306270368 Forwards responses to SER, Suppl 4, Sections 13.3.2.2 & 13.3.2.3 (NUREG-0857), re courses of action necessary in unlikely event of emergency at facilities info will be included in Rev 3 to emergency plan
VAN BRUNT, E E Arizona Public Service Co 83/06/15 KNIGHTON, O
Licensing Branch 3 26pp 18993 214 24X Fiche 50-528, 83/06/15,
8306270368

8306210287 Forwards program plan issues & areas for outstanding items re NUREG-0737, Item I.D.1 re detailed control room design review per NUREG-0700 requirements & SER, NUREG-0857 Generic Ltr 82-33 issues addressed
VAN BRUNT, E E Arizona Public Service Co 83/06/17 KNIGHTON, O
Licensing Branch 3 36pp 18914 038 24X Fiche 50-528, 83/06/17,
8306210287

8306280317 Submits required data to demonstrate that line voltage regulators perform as acceptable isolation device by limiting primary current under short circuit conditions to full-load primary current, per SER (NUREG-0857)
VAN BRUNT, E E Arizona Public Service Co 83/06/23 KNIGHTON, O
Licensing Branch 3 1p 19001 282 24X Fiche 50-528, 83/06/23,
8306280317

F Security, medical, emergency & fire protection plans

8306170356 Forwards description & list of objectives for 830511 emergency preparedness exercise Scenario will be provided within 30 days Comments requested within 15 days of ltr date
ANDOGNINI, O C Arizona Public Service Co. 83/03/02 GRIMES, B. K
Division of Emergency Preparedness (Pre 830103) 17pp 18880:333,
24X Fiche: 50-528, 83/03/02, 8306170356

--8306170360 Forwards description & list of objectives for 830511 emergency preparedness exercise Scenario will be provided within 30 days Comments requested within 15 days of ltr date
ANDOGNINI, O C Arizona Public Service Co 83/03/02 MARTIN, R
Region 5, Office of Director 10pp 18880 352. 24X
Fiche 50-528, 83/03/02, 8306170356

8306020056 Responds to 830414 ltr re Generic Ltr 82-33 requirements concerning Suppl 1 to NUREG-0737 Portion of response addressing detailed control room design review does not provide all info requested Response requested by 830531
KNIGHTON, O W Licensing Branch 3 83/05/10 VAN BRUNT, E E
Arizona Public Service Co 6pp 18701 349 24X
Fiche 50-528, 83/05/10, 8306020056

8306030357 Advises that addl info re detailed control room design review per Generic Ltr 82-33 re emergency response capabilities will be submitted by 830617
VAN BRUNT, E E Arizona Public Service Co 83/06/01 KNIGHTON, O
Licensing Branch 3 1p 18705.214 24X Fiche 50-528, 83/06/01,
8306030357

8306090273 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/06/03 Document
Management Branch 1p 18910 067 24X Fiche 50-528, 83/06/03,
8306090273

--8306090275 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP-01 re emergency organization, EPIP-02 re emergency classification & EPIP-04 re alert implementing actions
VAN BRUNT, E E Arizona Public Service Co 83/05/23 KNIGHTON, O
Licensing Branch 3 3pp 18910 068 24X Fiche: 50-528, 83/06/03,
8306090273

--8306090276 Public version of revised emergency plan implementing procedures, including Procedures EPIP-01 re emergency organization, EPIP-02 re emergency classification & EPIP-04 re alert implementing actions
LUCIA, B Arizona Public Service Co 83/03/30 708pp 18910.071
24X Fiche 50-528, 83/06/03, 8306090273

8306200371 Forwards responses to open items from NRC 830201-03 fire protection audit
VAN BRUNT, E E Arizona Public Service Co 83/06/15 KNIGHTON, O
Licensing Branch 3 31pp 18899 056 24X Fiche 50-528, 83/06/15,
8306200371

8306270368 Forwards responses to SER, suppl 4, Sections 13.3.2.2 & 13.3.2.3 (NUREG-0857), re courses of action necessary in unlikely event of emergency at facilities info will be included in Rev 3 to emergency plan
VAN BRUNT, E E Arizona Public Service Co 83/06/15 KNIGHTON, O
Licensing Branch 3 26pp 18993 214 24X Fiche 50-528, 83/06/15,
8306270368

8306270447 Responds to Generic Ltr 82-33 re Suppl 1 to NUREG-0737 concerning requirements for emergency response capability Unit 1 selected as backup emergency operations facility Exemptions from 10-mile criteria requested
VAN BRUNT, E E Arizona Public Service Co 83/06/16 KNIGHTON, O
Licensing Branch 3 3pp 18992 095. 24X Fiche 50-528, 83/06/16,
8306270447

8306210287 Forwards program plan issues & areas for outstanding items re NUREG-0737, Item I.D.1 re detailed control room design review per NUREG-0700 requirements & SER, NUREG-0857 Generic Ltr 82-33 issues addressed
VAN BRUNT, E E Arizona Public Service Co 83/06/17 KNIGHTON, O
Licensing Branch 3 36pp. 18914 038. 24X Fiche, 50-528, 83/06/17,
8306210287.

G Adjudicatory correspondence

8306030333 Response to second set of interrogatories Certificate of Bvc encl
BERLIN, K West Valley Agricultural Protection Council, Inc
83/06/01 Office of the Executive Legal Director, 10pp
18709 018. 24X Fiche 50-529, 83/06/01, 8306030333

--8306030334 Request for production of documents identified in response to first & second set of interrogatories & documents requested in interrogatories, Certificate of Bvc encl.
BERLIN, K West Valley Agricultural Protection Council, Inc.
83/06/01 Arizona Public Service Co 6pp 18709 028 24X
Fiche 50-529, 83/06/01, 8306030333

DOCKETED ITEMS

--8306030335 Response to second set of interrogatories Certificate of
Svc encl
BERLIN, K West Valley Agricultural Protection Council, Inc
83/06/01 Arizona Public Service Co 42pp 18709 034 24X
Fiche 50-529, 83/06/01, 8306030335

8306150398 Stipulation agreeing that motions to compel interrogatory
answers due 830715 & supplemental info responding to
interrogatories due 830701 Proposed order & Certificate of
Svc encl
DEWEY, L S Hearing Branch 3 BERLIN, K West Valley Agricultural
Protection Council, Inc PLATT, W Joint Applicants-Palo Verde
83/06/01 5pp 18847 140 24X Fiche 50-529, 83/06/01, 8306150398

8306090311 Withdrawal of 830526 request to extend time to respond to
revised discovery schedule. No addl time needed to review
schedule. Schedule acceptable Certificate of Svc encl
DEWEY, L S Hearing Branch 3 83/06/08 Atomic Safety and
Licensing Board Panel. 3pp 18775 196 24X Fiche 50-529, 83/06/08,
8306090311

8306100075 Forwards West Valley Agricultural Protection Council, Inc &
Joint Applicants stipulation re discovery schedule mod
ENQ, M B West Valley Agricultural Protection Council, Inc
83/06/09, LAZO, R M Atomic Safety and Licensing Board Panel 1p
18803 164. 24X Fiche 50-529, 83/06/09, 8306100075

--8306100078 Stipulation agreeing to comply w/provisions of proposed
order, unless & until further mod requested by parties ASLB
should enter encl order re discovery schedule mod
BERLIN, K West Valley Agricultural Protection Council, Inc
PLATT, W E Joint Applicants-Palo Verde PLATT, W E Snell & Wilmer
83/06/09 6pp 18803 165 24X Fiche 50-529, 83/06/09,
8306100078

8306140429 Requests info needed to complete review of util proposed
self deposition & impact monitoring plan
DEWEY, L S Hearing Branch 3 83/06/10 PLATT, W E Snell & Wilmer
PLATT, W E Arizona Public Service Co 2pp 18838 045 24X
Fiche 50-528, 83/06/10, 8306140429

8306150304 Request for production of documents. Certificate of Svc encl.
CRAWFORD, V A Joint Applicants-Palo Verde CRAWFORD, V A Snell &
Wilmer. 83/06/10. West Valley Agricultural Protection Council,
Inc. 10pp 18849 152 24X Fiche 50-529, 83/06/10, 8306150304

8306160622 Order directing motions to compel re interrogatory answers
be filed by 830715 Supplemental responses to interrogatories
to be filed by 830701
LAZO, R M Atomic Safety and Licensing Board Panel 83/06/14 1p
18865 073. 24X Fiche 50-529, 83/06/14, 8306160622

8306160629 Order delineating schedules for depositions, discovery on
crop study & pretrial preparation.
LAZO, R M Atomic Safety and Licensing Board Panel 83/06/14 4pp
18866, 122 24X Fiche 50-529, 83/06/14, 8306160629

8306210264 Request for production of documents. Certificate of Svc encl.
DEWEY, L S Hearing Branch 3 83/06/17 West Valley Agricultural
Protection Council, Inc. 4pp. 18915 027. 24X Fiche 50-529,
83/06/17, 8306210264.

8306210268 Request for production of documents Certificate of Svc
encl
DEWEY, L S Hearing Branch 3 83/06/17 Arizona Public Service
Co. 4pp. 18914 005. 24X Fiche 50-529, 83/06/17, 8306210268.

8306240284 Forwards util 830426 application for SNM license.
DEWEY, L S Hearing Branch 3 83/06/21 LAZO, R M, CALLIHAN, D.
COLE, R F Atomic Safety and Licensing Board Panel 149pp
18977, 291. 24X Fiche 50-529, 83/06/21, 8306240284

G Inspection reports, IE Bulletins & correspondence

109 Addl response to FOIA request for documents dtd 820101 or
re BALP Forwards App A documents Documents also
in PDR.
Division of Rules and Records. 83/04/11. CLARK, R San
vaminar. 3pp. 18815:252. 24X Fiche 50-000, 83/04/11,

for Region V BALP Board meetings for

fice of Director. 82/03/19
near Reactor Regulation, Director 1p.
0. 83/04/11, 8306100009

8306070252 Forwards IE Insp Repts 50-528/83-18, 50-529/83-10 &
50-530/83-08 on 830301-0430 & notice of violation
STERNBERG, D M Region 5, Office of Director 83/05/25 VAN
BRUNT, E E Arizona Public Service Co 2pp 18740 340 24X
Fiche 50-528, 83/05/25, 8306070252

--8306070256 IE Insp Repts 50-528/83-18, 50-529/83-10 & 50-530/83-08 on
830301-0430 Noncompliance noted power cables for containment
spray pump drive motors w/unsupported lengths longer than
24 inches & cables trays not grounded at both ends
VORDERBURG, G, YOUNG, T Region 5, Office of Director 83/05/24
6pp 18740 344 24X Fiche 50-528, 83/05/25, 8306070252

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in
Wall Logging Device " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post
830103) 83/05/26 Consolidated Edison Co of New York, Inc
125pp. 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet "
Svc list encl
JORDAN, C L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New
York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods
Withdrawn at BWRs " Svc list encl
JORDAN, C L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/31 Consolidated Edison Co of New
York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe
Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/09 Consolidated Edison Co of New
York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive &
Seismically Induced Chatter in Relays Within Printed
Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New
York, Inc 118pp 18920 225. 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From
Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New
York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
Epoxy Grouts & Sealers." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New
York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys
Causing Inoperability of Safety-Related Equipment " Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New
York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co of New
York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate
Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co of New
York, Inc 116pp 19046:297 24X Fiche 50-000, 83/06/24, 8305110483

S Reportable occurrences, LERs & related correspondence

8306010289 Interim Deficiency Rept DER 83-22 re Failure of ITE Could
circuit breaker for hydrogen recombiner to function
properly Initially reported on 830413, Bechtel & Rockwell
Intl working on circuit breaker Next rept by 831108
VAN BRUNT, E E Arizona Public Service Co 83/05/11. STERNBERG, D M
Region 5, Office of Director 3pp. 18672 195 24X
Fiche 50-528, 83/05/11, 8306010289.

8306010341 Rev 1 to final Deficiency Rept DER 81-29 re Failure of ASTM
A490 bolts Initially reported on 810521. Defective bolts
replaced. Insp program implemented to verify bolt tension
Also reportable per Part 21
VAN BRUNT, E E Arizona Public Service Co 83/05/11. STERNBERG, D M
Region 5, Office of Director. App. 18681 289 24X
Fiche 50-529, 83/05/11, 8306010341

DOCKETED ITEMS

369

8306010076 Interim Deficiency Rept DER 83-10 re main steam relief valve tests exceeding 5% blowdown limit Initially reported on 830228 Submittal of final rept extended to 830630
VAN BRUNT, E E Arizona Public Service Co 83/05/16 STERNBERG, D M
Region 5, Office of Director 2pp 18674 096 24X
Fiche 50-528, 83/05/16, 8306010076

8306010119 Interim deficiency rept re underground cables to startup transformers unable to carry full-load current at max site soil temp Initially reported on 821126 Final rept submittal extended to 830729 due to extensive investigation
VAN BRUNT, E E Arizona Public Service Co 83/05/16 STERNBERG, D M
Region 5, Office of Director 2pp 18673 360 24X
Fiche 50-528, 83/05/16, 8306010119

8306010272 Rev 2 to Final Deficiency Rept DFR 82-78 re improperly crimped termination lugs in control panels for water chillers supplied by Carrier, revising panel numbers Initially reported on 821217 Also reportable under Part 21
VAN BRUNT, E E Arizona Public Service Co 83/05/16 STERNBERG, D M
Region 5, Office of Director 3pp 18672 246 24X
Fiche 50-528, 83/05/16, 8306010272

8306010072 Rev 1 to Interim Deficiency Rept DER 82-61 re potential for reactor coolant pump diffuser ring cap screws to fail & damage pump Initially reported on 821021 C-E reviewed potential failure mechanisms final rept by 830725
VAN BRUNT, E E Arizona Public Service Co 83/05/10 STERNBERG, D M
Region 5, Office of Director 4pp 18673 274 24X
Fiche 50-528, 83/05/10, 8306010072

8306070225 Final Deficiency Rept DER 83-23 re failure of MSIV bypass valves to close in required time Initially reported on 830419 Solenoid valve replaced Problem investigation request issued by Bechtel Also reported per Part 21
VAN BRUNT, E E Arizona Public Service Co 83/05/19 STERNBERG, D M
Region 5, Office of Director 9pp 10744 217 24X
Fiche 50-528, 83/05/19, 8306070225

8306100203 Part 21 rept re deficiency in six emergency standby diesel generator sets mfg by Cooper Energy Svcs Jacket water heater & lube oil heater will be replaced w/40 kW & 19 kW versions, respectively, to maintain 120 F standby temp
STOLBA, F D Cooper Industries, Inc 83/05/20 Director's Office,
Office of Inspection and Enforcement 2pp 18806 007 24X
Fiche 50-528, 83/05/20, 8306100203

8306070078 Interim Deficiency Rept DER 82-63 re design calculation error in refueling water tank seismic response Initially reported on 821026 Time extension requested until 830624 to submit final rept
VAN BRUNT, E E Arizona Public Service Co 83/05/24 STERNBERG, D M
Region 5, Office of Director 2pp 10739 272 24X
Fiche 50-528, 83/05/24, 8306070078

8306170180 Interim Deficiency Rept DER 83-25 re lack of instrumentation tubing boundary class break requirements Initially reported on 830421 Evaluation & final rept will be submitted by 830630
VAN BRUNT, E E Arizona Public Service Co 83/05/26 STERNBERG, D M
Region 5, Office of Director 5pp 18883 258 24X
Fiche 50-528, 83/05/26, 8306170180

8306170366 Interim Deficiency Rept DER 83-31 re temp rise in diesel generator control cabinet potentially exceeding design requirements Initially reported on 830505 Bechtel & Cooper Energy Svcs evaluating condition Final rept by 830906
VAN BRUNT, E E Arizona Public Service Co 83/06/06 STERNBERG, D M
Region 5, Office of Director 3pp 18880 319 24X
Fiche 50-528, 83/06/06, 8306170366

8306130150 Part 21 rept re solenoid activated valves, Models 77C-001 & 77C-003 Defects include incorrect valve assembly, significant missing parts, limited switch valve position indication failures & failure of valve to open & close
PUTARINI, D M Target Rock Corp. 83/06/07 DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement 9pp 18824 247 24X Fiche 50-528, 83/06/07, 8306130150

DOCKET 50-537 CLINCH RIVER BREEDER REACTOR

A Application/construction stage documents & correspondence

8306060203 Submits agreements reached at 830524 meeting w/CRBR project re PRA Description of addl tasks needed to integrate Plan I & II efforts encl.
LONGENECKER, J Energy, Dept of 83/05/27 GRACE, J N Clinch
River Breeder Reactor Program Office 11pp 18727, 328, 24X
Fiche 50-537, 83/05/27, 8306060203

8306070436 Notification of 830606 meeting w/DOE, Project Mgt Corp & TVA in Bethesda, MD to discuss schedule for completion of confirmatory items
STARK, R M Clinch River Breeder Reactor Program Office 83/05/27,
GRACE, J N Clinch River Breeder Reactor Program Office 3pp,
18776 354 24X Fiche 50-537, 83/05/27, 8306070436

8306130403 Forwards "CRBR Erosion & Sediment Control Plan Rept," providing implementation status of control plan measures currently utilized
GROSS, P J Energy, Dept of 83/05/27 JOHNSTON, W Assistant
Director for Matis, Chem & Environ Technology (Post 830201),
MCKINNEY, A D Tennessee, State of TRAINA, P J Environmental
Protection Agency 2pp 18823 047 24X Fiche 50-537, 83/05/27,
8306130403

--8306130407 "CRBR Erosion & Sediment Control Plan Rept "
* Energy, Dept of. 83/05/27 15pp 18823 049. 24X
Fiche 50-537, 83/05/27, 8306130403

8306070462 Notification of 830610 meeting w/DOE & Project Mgt Corp in Bethesda, MD to discuss CRBR programmatic objectives.
STARK, R M Clinch River Breeder Reactor Program Office 83/06/01
GRACE, J N Clinch River Breeder Reactor Program Office 3pp,
18780 315 24X Fiche 50-537, 83/06/01, 8306070462

8306220048 Informs of planned optional use of mechanical couplers for reinforcing bar splice sys in nuclear island mat QA program will be established. Exception to ASME Code, Section III & Reg Guide 1.136 requirements encl
LONGENECKER, J Energy, Dept of 83/06/20 GRACE, J N Clinch
River Breeder Reactor Program Office 3pp 18930, 020 24X
Fiche 50-537, 83/06/20, 8306220048

8306290570 Notification of 830628 meeting w/DOE, Project Mgt Corp & util in Bethesda, MD to discuss applicant radiological calculations
STARK, R M Clinch River Breeder Reactor Program Office 83/06/21,
GRACE, J N Clinch River Breeder Reactor Program Office. 3pp
19047 190 24X Fiche 50-537, 83/06/21, 8306290570

8306240233 Summarizes 830606 meeting w/CRBR project personnel re schedule for resolution of confirmatory items All identified items & preliminary schedule info discussed List of attendees encl
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant
83/06/23 GRACE, J N Clinch River Breeder Reactor Program Office,
2pp 18980 185 24X Fiche 50-537, 83/06/23, 8306240233

E NRC Safety Evaluation Report (SER), supp's & correspondence

8306150616 SAFETY EVALUATION REPORT RELATED TO THE CONSTRUCTION OF THE CLINCH RIVER BREEDER REACTOR PLANT Docket No 50-537,
(U S Department of Energy, Tennessee Valley Authority
And Project Management Corporation)
* Clinch River Breeder Reactor Program Office NUREG-0968 802
83/05/31 19pp Available at NRC. 43 00 18854, 231 24X
Fiche 50-537, 83/05/31, 8306150616

8306170482 Forwards Suppl 2 to DFR (NUREG-0968) re const of Facility. Suppl provides evaluation of addl info received on previously identified outstanding review items w/o encl
GRACE, J N Clinch River Breeder Reactor Program Office 83/06/13
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant,
2pp 18894 303 24X Fiche 50-537, 83/06/13, 8306170482

8306200325 Summarizes programmatic objectives 830610 meeting re failbacks identified in Chapter 4 of SER & impact on CRBR project Viewgraphs & supporting documentation encl.
LONGENECKER, J Energy, Dept of 83/06/17 GRACE, J N Clinch
River Breeder Reactor Program Office 17pp 18901:001 24X
Fiche 50-537, 83/06/17, 8306200325

G Adjudicatory correspondence

8306070037 Forwards util analysis re seismic qualification of small diameter piping in response to ASLB 830513 inquiry, NRC analysis forthcoming.
TURK, B E Hearing Branch I. 83/06/03. MILLER, M., LINENBERGER, O.,
HAND, C H Atomic Safety and Licensing Board Panel 1p. 18739:334.
24X Fiche 50-537, 83/06/03, 8306070037

8306100043 Answer supporting util 830517 motion for summary disposition of intervenor Contention 9(g), Contention 9(g) fails to raise litigable issue of fact that will not be litigated under other subparts of Contention 9 Certificate of Svc encl.
TURK, B E Hearing Branch I 83/06/08. Atomic Safety and
Licensing Board Panel 4pp 18882 111. 24X Fiche: 50-537, 83/06/08,
8306100043

DOCKETED ITEMS

8306150311 Confirms understanding re NRC production of documents identified in NRC 830520 response to CP interrogatories (third set) Documents will be available in Bethesda, MD on 830616
 TURK, B E Hearing Branch 1 83/06/10 FINAMORE, B A Natural Resources Defense Council 1p 18849 128 24X
 Fiche 50-537, 83/06/10, 8306150311

8306150317 Confirms 830610 telcon re NRC deposition of T Cochran Deposition continued on 830512 NRC will adjourn deposition, sub j to listed conditions
 TURK, B E Hearing Branch 1 83/06/10 FINAMORE, B A Natural Resources Defense Council 2pp 18849 088 24X
 Fiche 50-537, 83/06/10, 8306150317

8306150315 Answer supporting until 830523 motion for partial summary disposition of intervenor Contentions 7(c) & 9(f) Intervenor fails to provide any factual basis that 10-mile emergency planning zone inappropriate Certificate of Svc encl
 TURK, B E Hearing Branch 1 83/06/13 Atomic Safety and Licensing Board Panel 9pp 18849 090 24X Fiche 50-537, 83/06/13, 8306150315

8306200302 Advises that DOE addressees include TJ Garrish, L Silverstrom & WD Luck RT Johnson & WE Bergholz should be deleted from svc list Certificate of Svc encl
 LUCK, W D Energy, Dept of 83/06/16 MILLER, M C, HAND, C H, LINENBERGER, Q Atomic Safety and Licensing Board Panel 4pp 18900 172 24X Fiche 50-537, 83/06/16, 8306200302

8306220146 Motion to withdraw Contentions 1, 3, 9(c), 9(g) from consideration at Jul 1983 CP hearings & request for leave to submit written statement on issues raised Limited resources prohibit continued full participation
 FINAMORE, B A, WEISS, E R, GREENBERG, E V Natural Resources Defense Council 83/06/21 Atomic Safety and Licensing Board Panel 3pp 18926 181 24X Fiche 50-537, 83/06/21, 8306220146

8306220193 Response opposing applicant 830519 & 23 motions for summary disposition of Contentions 7(g), 7(c) & 9(f) Motions moot since intervenors moved to withdraw contentions from consideration
 FINAMORE, B A, WEISS, E R Natural Resources Defense Council WEISS, E R Sierra Club 83/06/21 Atomic Safety and Licensing Board Panel 2pp 18926 184 24X Fiche 50-537, 83/06/21, 8306220146

8306220157 Lists typographical & transcription errors in 830519 deposition Certificate of Svc encl
 COCHRAN, T B Natural Resources Defense Council 83/06/21 TURK, B E Hearing Branch 1 4pp 18926 186 24X
 Fiche 50-537, 83/06/21, 8306220146

8306270317 Response to intervenor 830621 motion to withdraw Contentions 1, 3, 9(c), 7(f) & 7(g) from consideration at Jul 1983 CP hearings intervenors should be dismissed as parties Certificate of Svc encl
 EDGAR, Q L Project Management Corp LUCK, W D Energy, Dept of 83/06/22 Atomic Safety and Licensing Board Panel 9pp 18994 030 24X Fiche 50-537, 83/06/22, 8306270317

Q Inspection reports, IE Bulletins & correspondence

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl
 TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

83/06/06 on 830502-05 No

esident Programs 83/06/07
 hority 2pp 19056 123 24X

n 830502-05 No noncompliance
 t surveillance of

, Office of Director
 he 50-537, 83/06/07, 8306270227

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/07 Consolidated Edison Co of New York, Inc 117pp 18830 280 24X Fiche 50-000, 83/06/07, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/11 Consolidated Edison Co of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/11, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 115pp 19021 177 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety Related Equipment " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

DOCKET STN-50-546 MARBLE HILL NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8306060039 Forwards "Audit of Jul 1981 Cost Estimate for Marble Hill Nuclear Project," in support of util petition to increase existing rates & changes for retail electric svc & for approval of new rate schedules, rules & regulations
 SHIELDS, S W Public Service Co of Indiana, Inc 83/05/31 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18723 300 24X Fiche 50-546, 83/05/31, 8306060039

8306060043 "Audit of Jul 1982 Cost Estimate for Marble Hill Nuclear Project " Apps 1-5 encl
 * O'Brien-Kreitberg & Associates, Inc 83/05/23 1107pp 18723 302 24X Fiche 50-546, 83/05/31, 8306060039

8306140596 Forwards scheduler commitments for submittal of environ qualification program in response to Questions M270 2 & M270 3, per 830510 request for addl info re environ qualification of electrical & mechanical equipment
 SHIELDS, S W Public Service Co of Indiana, Inc 83/06/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 18833 138 24X Fiche 50-546, 83/06/09, 8306140596

8306200019 Summary of 830331 meeting w/utills & Westinghouse in Bethesda, MD re Westinghouse analysis & evaluation of D4/D5/E steam generator mod
 HOPKINS, J B Licensing Branch 4 83/06/14 Licensing Branch 4 22pp 18908 327 24X Fiche 50 000, 83/06/14, 8306200019

8306200097 Informs that area proposed by util for const of transmission lines within range of state endangered bobcat, badger, indianabat & within seasonal migration route of bald eagle
 TURNER, D Indiana, State of 83/06/14 YOUNGBLOOD, B J Licensing Branch 1 1p 18903 339 24X Fiche 50-546, 83/06/14, 8306200097

8306220101 Forwards notice of 830712 public meeting in Madison, IN to discuss recent application submitted by util & Wabash Valley Power Assoc, Inc for OLRs to be published in local newspapers
 YOUNGBLOOD, B J Licensing Branch 1 83/06/14 SHIELDS, S W Public Service Co of Indiana, Inc 3pp 13977 343 24X
 Fiche 50-546, 83/06/14, 8306220101

- 8306210127 Informs that site or associated transmission line impact on natl forest lands & program described in 830608 ltr will be forwarded to Forest Supervisor H Godlevsky for response
SMUTLEWORTH, W Agriculture, Dept of 83/06/15 YOUNGBLOOD, B J
Licensing Branch 1 1p 18710 131 24X Fiche 50-546, 83/06/15, 8306210127
- 8306270219 Amend 24 to CP & UL applications, consisting of Byron Amend 41 to FSAR, Suppl 2 to environ rept & revs to training & qualification plan section of safeguards vol Revs withheld (ref 10CFR2 790) W/o encls
SHIELDS, S W Public Service Co of Indiana, Inc 83/06/24 6pp
DENTON, H R Office of Nuclear Reactor Regulation, Director 18991 219 24X Fiche 50-546, 83/06/24, 8306270219
- C Utility Environmental Report (IER), amends & correspondence
- 8306270138 forwards Suppl 2 to environ rept - UL stage
SHIELDS, S W Public Service Co of Indiana, Inc 83/06/24 6pp
DENTON, H R Office of Nuclear Reactor Regulation, Director 18990 242 24X Fiche 50-546, 83/06/24, 8306270138
- 8306270149 Suppl 2 to environ rept - UL stage
Public Service Co of Indiana, Inc 83/06/30 4pp
18990 248 24X Fiche 50-546, 83/06/24, 8306270138
- D NRC Draft/Final Environmental Statements, suppl & correspondence
- 8306170470 Requests info re environ impact of station operation to assist in EIS preparation Notification re participation in 830711-12 site visit due by 830630
YOUNGBLOOD, B J Licensing Branch 1 83/06/08 SMITH, P H Advisory Council on Historic Preservation 9pp 18894 347 24X Fiche 50-546, 83/06/08, 8306170470
- 8306280382 Comments on EIS re water quality, in response to 830600 request CP re construction off & sedimentation pond issued on 760209
BOHNER, E A Indiana, State of 83/06/24 YOUNGBLOOD, B J
Licensing Branch 1 1p 19001 281 24X Fiche 50-546, 83/06/24, 8306280382
- F Security, medical, emergency & fire protection plans
- 8306270219 Amend 24 to CP & UL applications, consisting of Byron Amend 41 to FSAR, Suppl 2 to environ rept & revs to training & qualification plan section of safeguards vol Revs withheld (ref 10CFR2 790) W/o encls
SHIELDS, S W Public Service Co of Indiana, Inc 83/06/24 6pp
DENTON, H R Office of Nuclear Reactor Regulation, Director 18991 219 24X Fiche 50-546, 83/06/24, 8306270219
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8306270178 Application for amend to CIPR 170 & CIPR-171, including Amend 24 to FSAR, rev to training & qualification plan section of safeguards vol 1 & Suppl 2 to environ rept - UL stage (filed in PDR Category C) Safeguards vol withheld (ref 10CFR2 790)
SHIELDS, S W Public Service Co of Indiana, Inc 83/06/24 6pp
DENTON, H R Office of Nuclear Reactor Regulation, Director 18990 242 24X Fiche 50-546, 83/06/24, 8306270178
- 8306270192 Amend 24 to FSAR
Public Service Co of Indiana, Inc 83/06/30 254pp
18990 316 24X Fiche 50-546, 83/06/24, 8306270192
- G Inspection reports, IE Bulletins & correspondence
- 8306030144 Forwards IE Insp Repts 50-546/83-05 & 50-547/83-05 on 830330-0401 No noncompliance noted
LITTLE, W S Region 3, Office of Director 83/05/17 SHIELDS, S W Public Service Co of Indiana, Inc 2pp 18704 028 24X Fiche 50-546, 83/05/17, 8306030144
- 8306030148 IE Insp Repts 50-546/83-05 & 50-547/83-05 on 830330-0401 No noncompliance noted Major areas inspected followup on allegations/concerns re const deficiencies in Svc Level 1 protective coatings area Rept addresses technical aspects
NORTON, J R WILLIAMS, C C Region 3, Office of Director 83/05/16 4pp 18704 030 24X Fiche 50-546, 83/05/17, 8306030148
- 8306030198 Forwards IE Insp Repts 50-546/83-03 & 50-547/83-03 on 830411-15 No noncompliance noted
LITTLE, W S Region 3, Office of Director 83/05/10 SHIELDS, S W Public Service Co of Indiana, Inc 2pp 18703 302 24X Fiche 50-546, 83/05/18, 8306030198
- 8306030202 IE Insp Repts 50-546/83-03 & 50-547/83-03 on 830411-15 No noncompliance noted Major areas inspected licensee progress on recovery program in electrical area
LOVE, R S WILLIAMS, C C Region 3, Office of Director 83/05/16 5pp 18703 304 24X Fiche 50-546, 83/05/18, 8306030198
- 8305110458 IE Info Notice 83-34, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWHs " Svc list encl
JORDAN, C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461
- 8306070137 Ack receipt of 830527 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-546/83-01 & 50-547/83-01
SPESSARD, R L Division of Engineering 83/06/01 SHIELDS, S W Public Service Co of Indiana, Inc 1p 18739 219 24X Fiche 50-546, 83/06/01, 8306070137
- 8306070144 Responds to NRC 830425 ltr re violations noted in IE Insp Repts 50-546/83-01 & 50-547/83-01 Corrective actions cable tray to hanger attachments & cable tray splice plate bolting identified as safety-related on design drawings
SHIELDS, S W Public Service Co of Indiana, Inc 83/05/24 KEPPLE, J G Region 3, Office of Director 6pp 18739 220 24X Fiche 50-546, 83/06/01, 8306070139
- 8306070147 Requests inspector verification that program for improved control over electrical const adequate per 830202 confirmatory action ltr, Items 2-6 re electrical cable tray hanger installation
SHIELDS, S W Public Service Co of Indiana, Inc 83/04/08 KEPPLE, J G Region 3, Office of Director 1p 18739 226 24X Fiche 50-546, 83/06/01, 8306070137
- 8306270201 Forwards IE Insp Repts 50-546/83-06 & 50-547/83-06 on 830401-0511 No noncompliance noted
KNOPF, R C Region 3, Office of Director 83/06/08 SHIELDS, S W Public Service Co of Indiana, Inc 2pp 18991 270, 24X Fiche 50-546, 83/06/08, 8306270201
- 8306270205 IE Insp Repts 50-546/83-06 & 50-547/83-06 on 830401-0511 No noncompliance noted Major areas inspected allegations of cracked welds in electrical cable tray & conduit support hangers & review of training activities
SCHAPIKER, J F, KONKLIN, J E Region 3, Office of Director 83/06/08 0pp 18991 272 24X Fiche 50-546, 83/06/08, 8306270201
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470
- 8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010
- 8306210006 Responds to util request for partial release of electrical conduit & conduit hanger installation activities. Util program addressing confirmatory action ltr, Items 2-6 adequate for resumption of electrical work activities.
KEPPLE, J G Region 3, Office of Director 83/06/15 SHIELDS, S W Public Service Co of Indiana, Inc 2pp 18911 355 24X Fiche 50-546, 83/06/15, 8306210006
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

DOCKETED ITEMS

8305110477 IE Info Notice 83-41, "Actuation of Fare Suppression Sys Causing Inoperability of Safety-Related Equipment" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/05/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

B Reportable occurrences, LERs & related correspondence

8306070377 Final deficiency rept re mechanically cracked embedded box beam plate Initially reported on 830503 Alternative welding methods investigated Similar embedded plate welds
SHIELDS, S W Public Service Co of Indiana, Inc 83/05/31
KEPPLER, J G Region 3, Office of Director 2pp 18741 344 24X Fiche 50-546, 83/05/31, 8306070377

8306170182 Interim deficiency rept re separation of deformed wire anchors from embedded plate in containment Initially reported on 821020 Investigation re source of axial tensile stress applied to welds underway Next rept due 830702
SHIELDS, S W Public Service Co of Indiana, Inc 83/06/09
KEPPLER, J G Region 3, Office of Director 2pp 18883 254 24X Fiche 50-546, 83/06/09, 8306170182

8306270375 Interim deficiency rept re design changes not shown on detail drawings used by primary civil contractor (Newberg-Marble Hill) Initially reported on 830622 Drawing review continuing Next rept by 830826
SHIELDS, S W Public Service Co of Indiana, Inc 83/06/16
KEPPLER, J G Region 3, Office of Director 2pp 18993 212 24X Fiche 50-546, 83/06/16, 8306270375

DOCKET 83N-50-547 MARBLE HILL NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8306060039 Forwards "Audit of Jul 1982 Cost Estimate for Marble Hill Nuclear Project," in support of util petition to increase existing rates & changes for retail electric svc & for approval of new rate schedules, rules & regulations
SHIELDS, S W Public Service Co of Indiana, Inc 83/05/31
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18723 300 24X Fiche 50-546, 83/05/31, 8306060039

--8306060043 "Audit of Jul 1982 Cost Estimate for Marble Hill Nuclear Project" Apps 1-5 encl
* O'Brien-Kreitzberg & Associates, Inc 83/05/23 1107pp
18723 302 24X Fiche 50-546, 83/05/31, 8306060039

8306140596 Forwards scheduler commitments for submittal of environ qualification program, in response to Questions M270 P & M270 G, per 830510 request for addl info re environ qualification of electrical & mechanical equipment
SHIELDS, S W Public Service Co of Indiana, Inc 83/06/09
DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 18833 138 24X Fiche 50-546, 83/06/09, 8306140596

8306200019 Summary of 830331 meeting w/utis & Westinghouse in Bethesda, MD re Westinghouse analysis & evaluation of D4/D5/E steam generator mod.
HOPKINS, J B Licensing Branch 4 83/06/14, Licensing Branch 4 22pp 18708 327 24X Fiche 50-000, 83/06/14, 8306200019

8306200097 Informs that area proposed by util for const of transmission lines within range of state endangered bobcat, badger, Indiana bat & within seasonal migration route of bald eagle.
TURNER, D Indiana, State of 83/06/14 YOUNGBLOOD, B J, Licensing Branch 1 1p 18903 339 24X Fiche 50-546, 83/06/14, 8306200097

8306220101 Forwards notice of 830712 public meeting in Madison, IN to discuss recent application submitted by util & Wabash Valley Power Assoc, Inc for OLE to be published in local newspapers
YOUNGBLOOD, B J, Licensing Branch 1 83/06/14 SHIELDS, S W Public Service Co of Indiana, Inc 3pp 18977 343 24X Fiche 50-546, 83/06/14, 8306220101

8306210127 Informs that site or associated transmission line impact on natl forest lands & program described in 830608 ltr will be forwarded to forest supervisor H Godlevske for response
SHUTTLEWORTH, W Agriculture, Dept of 83/06/15 YOUNGBLOOD, B J Licensing Branch 1 1p 18918 131 24X Fiche 50-546, 83/06/15, 8306210127

8306270219 Amend 26 to CP & OL applications, consisting of Byron Amend 41 to FSAR, Suppl 2 to environ rept & revs to training & qualification plan section of safeguards vol Revs withheld (ref 10CFR2 790) W/o encl
SHIELDS, S W Public Service Co of Indiana, Inc 83/06/24
DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp 18791 219 24X Fiche 50-546, 83/06/24, 8306270219

C Utility Environmental Report (ER), amend & correspondence

8306270138 Forwards Suppl 2 to environ rept - OL stage
SHIELDS, S W Public Service Co of Indiana, Inc 83/06/24
DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp 18790 262 24X Fiche 50-546, 83/06/24, 8306270138

--8306270149 Suppl 2 to environ rept - OL stage
* Public Service Co of Indiana, Inc 83/06/30 46pp
18790 268 24X Fiche 50-546, 83/06/24, 8306270138

D NRC Draft/Final Environmental Statements, suppls & correspondence

8306170470 Requests info re environ impact of station operation to assist in CIS preparation Notification re participation in 830711-13 site visit due by 830630
YOUNGBLOOD, B J Licensing Branch 1 83/06/08 SMITH, P H Advisory Council on Historic Preservation 7pp 18894 347 24X Fiche 50-546, 83/06/08, 8306170470

8306280382 Comments on CIS re water quality, in response to 830608 request CP re const run off & sedimentation pond issued on 760209
BOHNER, E A Indiana, State of 83/06/24 YOUNGBLOOD, B J Licensing Branch 1 1p 19001 281 24X Fiche 50-546, 83/06/24, 8306280382

F Security, medical, emergency & fire protection plans

8306270219 Amend 26 to CP & OL applications, consisting of Byron Amend 41 to FSAR, Suppl 2 to environ rept & revs to training & qualification plan section of safeguards vol Revs withheld (ref 10CFR2 790) W/o encl
SHIELDS, S W Public Service Co of Indiana, Inc 83/06/24
DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp 18791 219 24X Fiche 50-546, 83/06/24, 8306270219

K Utility Final Safety Analysis Report (FSAR) & amends

8306270138 Application for amend to CPPR-170 & CPPR-171, including Amend 26 to FSAR, rev to training & qualification plan section of safeguards vol & Suppl 2 to environ rept - OL stage (Filed in PDR Category C) Safeguards vol withheld (ref 10CFR2 790)
SHIELDS, S W Public Service Co of Indiana, Inc 83/06/24
DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp 18790 262 24X Fiche 50-546, 83/06/24, 8306270138

--8306270152 Amend 26 to FSAR
* Public Service Co of Indiana, Inc 83/06/30 294pp
18790 316 24X Fiche 50-546, 83/06/24, 8306270138

Q Inspection reports, IE Bulletins & correspondence

8306030146 Forwards IE Insp Repts 50-546/83-05 & 50-547/83-05 on 830330-0401 No noncompliance noted
LITTLE, W S Region 3, Office of Director 83/05/17 SHIELDS, S W Public Service Co of Indiana, Inc 2pp 18704 029 24X Fiche 50-546, 83/05/17, 8306030146

--8306030148 IE Insp Repts 50-546/83-05 & 50-547/83-05 on 830330 0401 No noncompliance noted. Major areas inspected followup on allegations/concerns re const deficiencies in Svc Level 1 protective coatings area. Rept addresses technical aspects
NORTON, J F, WILLIAMS, C C Region 3, Office of Director 83/05/16 4pp 18704 030 24X Fiche 50-546, 83/05/17, 8306030146

8306030198 Forwards IE Insp Repts 50-546/83-03 & 50-547/83-03 on 830411-15 No noncompliance noted
LITTLE, W S Region 3, Office of Director 83/05/10 SHIELDS, S W Public Service Co of Indiana, Inc 2pp 18703 302 24X Fiche 50-546, 83/05/18, 8306030198

--8306030202 IE Insp Repts 50-546/83-03 & 50-547/83-03 on 830411-15 No noncompliance noted Major areas inspected licensee programs on recovery program in electrical area
LOVE, R S, WILLIAMS, C C Region 3, Office of Director 83/05/16
5pp 18703 304 24X Fiche 50-000, 83/05/16, 8306030170

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8306070137 Ack receipt of 83052/ ltr informing NRC of steps taken to correct violations noted in IL Insp Repts 50-546/83-01 & 50-547/83-01
SPESARD, R L Division of Engineering 83/06/01 SHIELDS, S W Public Service Co. of Indiana, Inc 1p 18739 219 24X Fiche 50-546, 83/06/01, 8306070137

--8306070144 Responds to NRC 830425 ltr re violations noted in IL Insp Repts 50-546/83-01 & 50-547/83-01 Corrective actions cable tray to hanger attachments & cable tray splice plate bolting identified as safety-related on design drawings
SHIELDS, S W Public Service Co. of Indiana, Inc 83/05/24 KEPLER, J Q Region 3, Office of Director 6pp 18739 220 24X Fiche 50-546, 83/06/01, 8306070137

--8306070147 Requests inspector verification that program for improved control over electrical const adequate per 830202 confirmatory action ltr, items 2-6 re electrical cable tray hanger installation
SHIELDS, S W Public Service Co. of Indiana, Inc 83/04/08 KEPLER, J Q Region 3, Office of Director 1p 18739 226 24X Fiche 50-546, 83/06/01, 8306070137

8306270201 forwards IE Insp Repts 50-546/83-06 & 50-547/83-06 on 830401-0511 No noncompliance noted
KNOPF, R C Region 3, Office of Director 83/06/08 SHIELDS, S W Public Service Co. of Indiana, Inc 2pp 18991 270 24X Fiche 50-546, 83/06/08, 8306270201

--8306270205 IE Insp Repts 50-546/83-06 & 50-547/83-06 on 830401-0511 No noncompliance noted Major areas inspected allegations of cracked welds in electrical cable tray & conduit support hangers & review of training activities
SCHAPKER, J F, KONKLIN, J E Region 3, Office of Director 83/06/08 8pp 18991 2/2 24X Fiche 50-546, 83/06/08, 8306270201

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 110pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 243pp 18921 001 24X Fiche 50-000, 83/06/13, 8306090010

8306210006 Responds to util request for partial release of electrical conduit & conduit hanger installation activities Util program addressing confirmatory action ltr, items 2-6 adequate for resumption of electrical work activities
KEPLER, J Q Region 3, Office of Director 83/06/15 SHIELDS, S W Public Service Co. of Indiana, Inc 2pp 18911 355 24X Fiche 50-546, 83/06/15, 8306210006

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 120pp 18977 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co. of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

S Reportable occurrences, LERs & related correspondence

8306270375 Interim deficiency rept re design changes not shown on detail drawings used by primary civil contractor (Newberg-Marble Hill) Initially reported on 830622 Drawing review continuing Next rept by 830826
SHIELDS, S W Public Service Co. of Indiana, Inc 83/06/16 KEPLER, J Q Region 3, Office of Director 2pp 18993 212 24X Fiche 50-546, 83/06/16, 8306270375

DOCKET STN-50-553 PHIPPS BEND NUCLEAR STATION, UNIT 1

S Reportable occurrences, LERs & related correspondence

8306160454 Pt 21 rept re potential defect in transmitter afg by Rosemount, Inc used in control sys of components furnished to listed plants All components involved retrofitted w/new circuit boards Matter closed
QIROUX, E J Carrier Corp 83/05/23 STELLO, V Director's Office, Office of Inspection and Enforcement 1p 18863 094 24X Fiche 50-518, 83/05/23, 8306160454

DOCKET STN-50-554 PHIPPS BEND NUCLEAR STATION, UNIT 2

S Reportable occurrences, LERs & related correspondence

8306160454 Pt 21 rept re potential defect in transmitter afg by Rosemount, Inc used in control sys of components furnished to listed plants All components involved retrofitted w/new circuit boards Matter closed
QIROUX, E J Carrier Corp 83/05/23 STELLO, V Director's Office, Office of Inspection and Enforcement 1p 18863 094 24X Fiche 50-518, 83/05/23, 8306160454

DOCKET STN-50-556 BLACK FOX STATION, UNIT 1

A Application/construction stage documents & correspondence

8306290128 Forwards FR notice of withdrawal of application for CPs & revocation of LWA & ABLB 830707 order & ABLB 830414 order re termination of appellate jurisdiction retained in ALAB-573 re radon issue
DENTON, H R Office of Nuclear Reactor Regulation, Director 83/06/22 WEST, J B Public Service Co. of Oklahoma 3pp 19046 180 24X Fiche 50-556, 83/06/22, 8306290128

--8306290135 Notice of withdrawal of application for CPs & revocation of LWA
ADENSAH, E O Licensing Branch 4 83/06/22 3pp 19046, 183 24X Fiche 50-556, 83/06/22, 8306290128

Q Inspection reports, IE Bulletins & correspondence

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

DOCKETED ITEMS

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BHRs " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc 116pp 18732 208 24X Fiche 50-000,83/05/31,8305110461

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc 119pp 18830 280 24X Fiche 50-000,83/06/09,8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 118pp 18920 225 24X Fiche 50-000,83/06/13,8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 243pp 18921 001 24X Fiche 50-000,83/06/13,8306090010

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 115pp 19021 179 24X Fiche 50-000,83/06/22,8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 120pp 18997 007 24X Fiche 50-000,83/06/22,8305110477.

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co. of New York, Inc 116pp 18996 242 24X Fiche 50-000,83/06/23,8305110479

8305110483 IE Info Notice 83-43, "Improper Bettings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc 116pp 19046 297 24X Fiche 50-000,83/06/24,8305110483

DOCKET 87N-50-557 BLACK FOX STATION, UNIT 2

A Application/construction stage documents & correspondence

8306290128 Forwards FR notice of withdrawal of application for CPs & revocation of LMA & ASLB 830307 order & ASLAB 830414 order re termination of appellate jurisdiction retained in ALAB-373 re radon issue
DENTON, H R Office of Nuclear Reactor Regulation, Director
83/06/22 WEST, J B. Public Service Co of Oklahoma 3pp
19046 160 24X Fiche 50-556,83/06/22,8306290128

--8306290135 Notice of withdrawal of application for CPs & revocation of LMA
ADENSAH, E G, Licensing Branch 4 83/06/22, 3pp 19046, 183 24X
Fiche 50-556,83/06/22,8306290128.

G Inspection reports, IE Bulletins & correspondence

8305110458 IE Info Notice 83-32, "Ruptured An-241 Sources Contained in Well Logging Device " Svc list encl
TAYLOR, J.M. Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 123pp 18831 043 24X Fiche:50-000,83/05/26,8305110458.

Event Notification Info Worksheet "

Preparedness & Engineering
Consolidated Edison Co. of New York, Inc
Fiche 50-000,83/05/26,8305110460

Movement W/Control Rods

Preparedness & Engineering
Consolidated Edison Co. of New York, Inc
Fiche 50-000,83/05/31,8305110461.

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc 119pp 18830 280 24X Fiche 50-000,83/06/09,8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 118pp 18920 225 24X Fiche 50-000,83/06/13,8305110470

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 243pp 18921 001 24X Fiche 50-000,83/06/13,8306090010

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 115pp 19021 179 24X Fiche 50-000,83/06/22,8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 120pp 18997 007 24X Fiche 50-000,83/06/22,8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co. of New York, Inc 116pp 18996 242 24X Fiche 50-000,83/06/23,8305110479

8305110483 IE Info Notice 83-43, "Improper Bettings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc 116pp 19046 297 24X Fiche 50-000,83/06/24,8305110483

DOMESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL

DOCKET 70-000B BATTELLE MEMORIAL INSTITUTE, COLUMBUS, OH

8306230129 Responds to FOIA request for five categories of documents re spent fuel at facilities App A & B documents respond to Items 1,2,4 & 5 Forwards App B Documents 1 & 5-11 No documents located for Item 3
FELTON, J M Division of Rules and Records 83/04/13 AUI)1N,1
Affiliation Unknown 3pp 18982 047 24X Fiche 50-014,83/04/13,8306230129

--8306230137 Part 21 rept re employee receiving dose of 30 /10 rems to right hand on 800720 while removing particulate cartridge from water filter subsequent to cask flushing operation
TOY, H L Battelle Memorial Institute, Pacific Northwest Laboratory 80/08/19 KEPLER, J Q Region 3, Chicago, Office of the Director 4pp 18982 060

--8306230139 Forwards data sheet for Part 21 Rept 80-256-000 re defect in spent fuel cask unloading procedures, per T1109/P(Rev 1)
FISHER, W L Region 3, Chicago, Office of the Director 00/10/71 HIGGINBOTHAM, L Region 3, Chicago, Fuel Facility & Materials Safety Branch 1p 18982 066

--8306230144 Forwards data sheet for Part 21 Rept 80-256-000 re defect in spent fuel unloading procedures Completed data sheet should be returned by 801001 Comments on Part 21 rept encl
HIGGINBOTHAM, L Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/08/27 DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 4pp 18982 067

--8306230149 Forwards request for addl info re IE Insp Repts 70-000B 82-02,30-05728/80-02 & 50-006/80-01 concerning problems w/NFS-4 (NAC-IE) cask, per 810226 telcon
CARLSON, R T Region 1, Philadelphia, Office of the Director, 81/02/27 FISCHER, W L Region 3, Chicago, Office of the Director 4pp 18982 071 24X Fiche 50-006,83/04/13,8306230129

--8306230153 Forwards addl info re IE Insp Rept 70-000B/80-02 re overviews through vent tubing, means of floor surfaces & radiation levels w/portable instrument & removal of fuel assembly
FISCHER, W L Technical Inspection Branch 81/03/25 CARLSON, R T Director's Office, Office of Inspection and Enforcement 3pp 18982 075

DOCKETED ITEMS

375

DOCKET 70-0025 ROCKWELL INTERNATIONAL CORP , CANOGA PARK, CA

8306060274 Order CLI-83-15, requesting potential intervenors to file statement setting forth certain facts, within 45 days of order Parties to informal adjudication are licensee & persons filing intervention statement Addl views encl CHILK, S J Office of the Secretary of the Commission 83/06/02 8pp 18730 027

8306060307 Forwards Commission order re request for hearing on license renewal Addressee of signatories to 821124 ltr requested STUCKY, S W Docketing & Services Branch 83/06/03 MICHAELS, A Affiliation Unknown 1p 18729 130

--8306060309 Request for public hearing on license renewal WILLIAMS, R K , WOLLIN, J , ZEIDLER, Z Affiliation Unknown 82/11/24 PAGE NRC - No Detailed Affiliation Given 3pp 18729 131

8306060185 Notice of appointment of RM Lazo as presiding officer to conduct informal proceeding re Rockwell Intl Energy Sys Group application to renew License GNM-21 COTTER, D P Atomic Safety and Licensing Board Panel 83/06/06 1p 18772 260

8306290343 Demands public hearing on license renewal & opposes response to ASLB questions on financial interests of individuals requesting hearings COOK, L Affiliation Unknown 83/06/21 PALLADINO, N J NRC - No Detailed Affiliation Given 2pp 19055 243

DOCKET 70-0084 IOWA STATE UNIV , AMES, IA

8306100275 Submits corrected date for application to renew License R-59 & advises that computer printout records summarizing GNM inventory results for 1981 & 1982 corrected, in response to IE Insp Repts 50-116/83-01 & 70-0084/83-01 HENDRICKSON, R Iowa State Univ 83/05/19 PIRTLE, O L Region 3, Office of Director 2pp 18805 142 24X Fiche 50-116, 83/05/19, 8306100275

DOCKET 70-0115 WASHINGTON, UNIV OF, SEATTLE, WA

8306280458 Discusses IE insp of License GNM-108 on 830517 & forwards notice of violation SCARANO, R A Division of Radiological Safety & Safeguards Program 83/06/07 CHALK, W S Washington, Univ of, Seattle, WA 2pp 19020 135

--8306280458 Notice of violation from insp on 830517 Noncompliance noted five Pu/De sources not leak tested within required 6-month interval THOMAS, R D Region 5, Office of Director 83/06/07 1p 19020 137

DOCKET 70-0121 INTERIOR, DEPT OF, DENVER, CO

8306240140 Forwards IE Safeguards Insp Repts 50-274/83-02 & 70-0121/83-02 on 830418-20 No noncompliance noted MADSEN, O L Region 4, Office of Director 83/06/20 MILLARD, II Interior, Dept of, Geological Survey 2pp 18980 162 24X Fiche 50-274, 83/06/20, 8306240140

--8306240148 IE Safeguards Insp Repts 50-274/83-02 & 70-0121/83-02 on 830418-20 No noncompliance noted Major areas inspected nuclear matl control & accountability, including facility organization & operations Details withheld (ref 10CFR2 790). CALDWELL, R A , KELLY, J A F , WESTERMAN, T F Region 4, Office of Director 83/06/15 1p 18980 164 24X Fiche 50-274, 83/06/15, 8306240140

DOCKET 70-0124 TELEDYNE ISOTOPE, INC , WESTWOOD, NJ

8306020019 Application to amend License GNM-107, reducing possession limit of U-235 from 235 to 225 g BLACK, S A Teledyne Isotopes 83/03/24 PAGE, R, O Uranium Fuel Licensing Branch 1p 18702 343

DOCKET 70-0134 WISCONSIN, UNIV OF, MADISON, WI

8306270162 Forwards IE Insp Repts 50-154/83-03 & 70-0134/83-01 on 830519-20 No noncompliance noted PAPERIELLO, C J Region 3, Office of Director 83/06/08 CASHMELL, R J Wisconsin, Univ of, Madison 2pp 18992 026 24X Fiche 50-156, 83/06/08, 8306270162

--8306270167 IE Insp Repts 50-154/83-03 & 70-0134/83-01 on 830519-20 No noncompliance noted Major areas inspected radiation protection & radwaste mgmt program, including organization & qualifications & logs & records PAUL, R A , GREGER, L R Region 3, Office of Director 83/06/08 6pp 18992 026 24X Fiche 50-156, 83/06/08, 8306270162

DOCKET 70-0135 BABCOCK & WILCOX CO , APOLLO, PA

8306200020 Notifies of 830423 accident Truck carrying 48 packages containing low enriched U dioxide powder, 36 empty 55 gallon drums & two boxes of low enriched U lab samples overturned in Lynchburg, VA No radioactive matl released AUSTIN, R A , Babcock & Wilcox Co 83/05/19 Office of Nuclear Material Safety & Safeguards, Director 1p 18908 350

DOCKET 70-0143 NUCLEAR FUEL SERVICES, INC., ERWIN, TN

8306030283 Repts on airborne radioactivity concentrations released from plant stacks for Apr 1983 GUINN, F K Nuclear Fuel Services, Inc (subs of Getty Oil Co) 83/05/13 O'REILLY, J P Region 2, Office of Director 6pp 18734 078

8306080381 Act receipt of IE Insp Rept 70-0143/83-15 No proprietary info GUINN, F K Nuclear Fuel Services, Inc (subs of Getty Oil Co) 83/05/23 STORR, J P Division of Project & Resident Programs 1p 18789 360

8306030175 Trip rept of 830418-22 meetings w/Nuclear Fuel Svcs in Erwin, TN re health-physics insp of facility BODNO, A L Uranium Fuel Licensing Branch 83/05/26 Uranium Fuel Licensing Branch 2pp 18733 318

8306140700 Forwards IE Safeguards Insp Rept 70-0143/83-18 on 830411-15 No noncompliance noted STORR, J P Division of Emergency Preparedness & Materials Safety, 83/06/02 MANSER, W C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 2pp 18840 207

--8306140713 IE Safeguards Insp Rept 70-0143/83-18 on 830411-15 No noncompliance noted Major areas inspected MC-B52068 measurement & statistical controls, MC-B52138 & inventory verification Details withheld (ref 10CFR2 790) BABADDIS, J W Region 2, Office of Director MCALPINE, E J Division of Emergency Preparedness & Materials Safety 83/06/02 1p 18840 209

8306150264 Act receipt of 830407 ltr informing NRC of steps taken to correct violation noted in IE Safeguards Insp Rept 70-0143/83-08 STORR, J P Division of Emergency Preparedness & Materials Safety 83/06/02 MANSER, W C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 1p 18848 326

--8306150269 Responds to NRC 830310 ltr re violation noted in IE Safeguards Insp Rept 70-0143/83-08 Corrective actions withheld (ref 10CFR2 790) MANSER, W C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 83/04/07 STORR, J P Division of Emergency Preparedness & Materials Safety 1p 18848 327

8306160658 Responds to 830407 questions re proposed groundwater monitoring program, Depth of proposed wells expected to be similar to existing wells or approx 20 ft Agrees to comply w/lower limits of detection specified GUINN, F K Nuclear Fuel Services, Inc (subs of Getty Oil Co) 83/06/03 CROHN, W T Uranium Fuel Licensing Branch 6pp 18884 346

8306210436 Issues Amend 20 to License GNM-124, authorizing installation of nonfavorable geometry pits in Bldg 302 & 303, SER supporting licensing action & review of license amend application encl PAGE, R O Uranium Fuel Licensing Branch 83/06/10 IDEKER, R, Nuclear Fuel Services, Inc, (subs. of Getty Oil Co), 4pp 18936 270

DOCKETED ITEMS

--B306210440 SER supporting Amend 20 to license SNM-124, authorizing installation of nonfavorable geometry pits in floor beneath furnaces in Bldgs 302 & 303 Pits in floor needed for installation & maint of equipment for improved operation
BIDINGER, G H , CROW, W T Uranium Fuel Licensing Branch 03/06/10 2pp 18935 273

B306170345 PNO-II-B3-046 on B30613, fire identified in high-enriched U incinerator ventilation duct Cause not determined No indications of personnel exposure or contamination noted Downwind radiation monitoring devices being analyzed
WRAY, J R , BARR, K Region 2, Office of Director 03/06/14 1p 18880.293

B306290572 Ack receipt of IE Insp Rept 70-0143/83-20 No proprietary info
OUIHNN, F K Nuclear Fuel Services, Inc (subs of Getty Oil Co) 03/06/15 STOHR, J P Division of Emergency Preparedness & Materials Safety 1p 19047 193

B306270240 PNO-II-B3-050 on B30620, bimonthly inventory difference resulting from B30420 physical inventory reported inventory difference was accounting gain greater than calculated error limit. Investigation initiated by licensee
MCALPINE, E J Region 2, Office of Director 03/06/21 1p 18988.269

DOCKET 70-0258 ILLINOIS, UNIV OF, URBANA, IL

B306090023 Responds to violation noted in IE insp rept Forwards data showing that calibr checks performed on dosimeters on B30616
BECK, G P, Illinois, Univ of, Urbana-Champaign 03/05/31 GRANT, W B, Region 3, Office of Director 2pp 18792-356 24X Fiche 50-151, 03/05/31, B306090023

DOCKET 70-0267 NEW YORK, STATE UNIV OF, BUFFALO, NY

B306170050 Ack receipt of B30511 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-057/82-01 & 70-0267/82-01
MARTIN, T T Division of Engineering & Technical Programs 03/06/01 HENRY, L G, New York, State Univ of, Buffalo, 2pp 18882 210 24X Fiche 50-057, 03/06/01, B306170050

--B306170052 Responds to NRC B30427 ltr re violations noted in IE Insp Repts 50-057/82-01 & 70-0267/82-01 Corrective actions new reactor engineer added to assume responsibility for accountability actions & records Fuel burnup code modified
HENRY, L G, New York, State Univ of, Buffalo 03/05/11. MARTIN, T T, Division of Engineering & Technical Programs 1p 18882 212. 24X Fiche 50-057, 03/06/01, B306170050

DOCKET 70-0364 BABCOCK & WILCOX CO , APOLLO, PA

B306060163 Forwards IE Insp Rept 70-0364/83-02 on B30321-23 & notice of violation
STAROSTECKI, R, Division of Project & Resident Programs 03/05/23 COLEMAN, W L Babcock & Wilcox Co 2pp 18728 105

--B306060173 Notice of violation from insp on B30321-23
Region 1, Office of Director 03/05/23 2pp 18728 107

--B306060176 IE Insp Rept 70-0364/83-02 on B30321-23 Noncompliance noted Failure to maintain air flow from areas of low contamination potential to high contamination & Failure to take corrective actions when smear survey exceeded 100 dpm/100cm
ROTH, J , ELGABSER, T C Region 1, Office of Director 03/05/18 9pp 18728 109.

B306280473 Responds to B30310 ltr re cancellation of Pu decommissioning fundamental nuclear matl control plan for License SNM-414 & submittal of control plan for low enriched U decontamination activities under License SNM-145
ALLAN, J M Region 1, Office of Director 03/06/16 COLEMAN, W L Babcock & Wilcox Co 2pp 18997 127.

IC , UNCASVILLE, CT

to Page 10.0-7C re wet & dry

5/12 BIDINGER, G. Fuel
1p 18734 362

B306010148 Forwards IE Safeguards Insp Rept 70-0371/83-03 on B30321-25 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 03/05/17 AMY, G O United Nuclear Corp 2pp 18674 051

--B306010153 IE Safeguards Insp Rept 70-0371/83-03 on B30321-25 No noncompliance noted Major areas inspected measurement control program, shipper-receiver verification, inventory difference & associated limit of error verification
ZIBULSKY, H , KENT, J , GODY, A T Region 1, Office of Director 03/05/13 4pp 18674 053

B306030238 Forwards IE Safeguards Insp Rept 70-0371/83-05 on B30411 15 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 03/05/20 AMY, G O United Nuclear Corp 2pp 18708 271

--B306030324 IE Safeguards Insp Rept 70-0371/83-05 on B30411-15 No noncompliance noted Major areas inspected inventory verification
ZIBULSKY, H , DELLA RATTIA, A , GODY, A T Region 1, Office of Director 03/05/10 2pp 18708 271

B306030314 Forwards IE Safeguards Insp Rept 70-0371/83-06 on B30503-06 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 03/05/20 AMY, G O United Nuclear Corp 2pp 18708 275

--B306030317 IE Safeguards Insp Rept 70-0371/83-06 on B30503 06 No noncompliance noted Major areas inspected security program audit, testing & maint, locks, keys & combinations & security sys power supply
SMITH, G C , DUNLAP, J M , GODY, A T Region 1, Office of Director 03/05/10 3pp 18708 277

B306170241 Forwards IE Safeguards Insp Rept 70-0371/83-07 on B30509-14 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 03/06/01 AMY, G O United Nuclear Corp 2pp 18878 280

--B306170245 IE Safeguards Insp Rept 70-0371/83-07 on B30509 13 No noncompliance noted Major areas inspected physical inventory reconciliation & records & tests
RATTA, A B , WOLTNER, E , GODY, A T Region 1, Office of Director 03/05/31 2pp 18878 282

B306210449 Forwards request for addl info in order to proceed w/1A associated w/renewal of License SUB-1010, during B30518 site visit
RHODES, M J Uranium Fuel Licensing Branch 03/06/10, United Nuclear Corp 6pp 18935 345

B306280095 Trip rept of B30517-18 meetings & site tour w/ORNL & State of CT in Uncasville, CT re environ review for United Nuclear Corp Naval Products license renewal application
RHODES, M J Uranium Fuel Licensing Branch 03/06/16 Uranium Fuel Licensing Branch 2pp 19042 361

DOCKET 70-0498 EASTERN MICHIGAN UNIV , YPSILANTI, MI

B306170077 QA program W/B30531 ltr
KOEHL, K M Gearheart-Owen Industries, Inc 03/05/31 MACDONALD, C E Transportation Branch 4pp 18907 359

DOCKET 70-0687 UNION CARBIDE CORP , TUXEID, NY

B306030064 Describes present monitoring sys to replace old sys detailed on Page 33 of rept discussed on B30510
VOTH, M H Union Carbide Corp 03/05/11 CLARK, I NRC - No Detailed Affiliation Given 1p 18733 208

B306010338 Forwards IE Safeguards Insp Repts 70-0687/83 01 on B30425-29 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 03/05/17 MCCOVERN, J J Union Carbide Corp 2pp 18680 079

--B306010339 IE Safeguards Insp Rept 70-0687/83-01 on B30425-29, No noncompliance noted Major areas inspected nuclear matl control & accounting including shipper/receiver verification, physical inventory & verification
DELLA RATTIA, A , ZIBULSKY, H , GODY, A T Region 1, Office of Director 03/05/13 3pp 18680 081

DOCKETED ITEMS

377

DOCKET 70-0698 WESTINGHOUSE ELECTRIC CORP., PITTSBURGH, PA

8306020387 Forwards IE Insp Rept 70-0698/B3-01 on B30308 & 10 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs 83/05/20
WARD, A J Westinghouse Electric Corp 2pp 18695 001

--8306020391 Notice of violation from insp on B30308 & 10
* Region 1, Office of Director 83/05/20 1p 18695 003

--8306020392 IE Insp Rept 70-0698/B3-01 on B30308 & 10 Noncompliance noted licensee transferred licensed matl in form which recipient not authorized to receive
NICOLISI, J. KINNEMAN, J Region 1, Office of Director 83/05/20 2pp 18695 004

DOCKET 70-0734 GA TECHNOLOGIES, INC., SAN DIEGO, CA

8306100005 Forwards requested info re 1963 shipping plan for HTGR fuel elements. Tri-State escorts will assume responsibility at GA Co protected area & relinquish responsibility at plant site
HOWRY, W GA Technologies, Inc /General Atomic Co 83/05/19
HILLMAN, C Division of Safeguards 4pp 18815 317

8306200379 Forwards IE Safeguards Insp Rept 70-0734/B3-07 on B30410-0513 No noncompliance noted
NORDERHAUG, L R Region 5, Office of Director 83/06/15
PARKER, J W GA Technologies, Inc /General Atomic Co 2pp 18897 001

--8306200383 IE Safeguards Insp Rept 70-0734/B3-07 on B30410-0513 No noncompliance noted Major areas inspected independent safeguards efforts, measurement controls & physical inventory details withheld (ref 10CFR 790)
NELSON, G D, WIEDER, A V, NORDERHAUG, L R Region 5, Office of Director 83/06/15 1p 18897 003

8306290082 Forwards negative declaration & EIA (NUREG-0994) re renewal of License GNM-696 W/O CIA
PAGE, R O Uranium Fuel Licensing Branch 83/06/21 HOWRY, W R GA Technologies, Inc /General Atomic Co 1p 19046 167

--8306290083 Negative declaration supporting renewal of License GNM-696
PAGE, R O Uranium Fuel Licensing Branch 83/06/21 2pp 19046 168

DOCKET 70-0754 GENERAL ELECTRIC CO., PLEASANTON, CA

8306020234 Advises of shipment of 12 irradiated fuel rods from Monticello, MN to BHI Schedule withheld (ref 10CFR 73.21)
KIRKLAND, M W General Electric Co 83/04/26, Region 3, Office of Director 3pp 18700 352

DOCKET 70-0820 UNITED NUCLEAR CORP., WOOD RIVER JCT., RI

8306080098 Discusses 830502-04 & 06 meetings w/United Nuclear, Naval Products Div & C-E in Montville, CT & Windsor, CT, respectively, re safeguards program & other safeguards, classified & licensee proprietary info
JACKSON, R L Material Control Licensing Branch 83/05/19
BROWN, B B Fuel Facility Safeguards Licensing Branch 1p 18787 362

8306130450 Forwards list of rejected concrete grid blocks replaced per Oak Ridge Assoc Univs Apr 1983 contamination level survey
HELGESON, K A United Nuclear Corp 83/05/31, CROW, W T Office of Nuclear Material Safety & Safeguards, Director 5pp 18830 179

8306170433 Summary of 830425-27 meetings w/licensee & ORNL in Wood River Junction, RI to observe ORNL performance of main process bldg radiological survey
EDDING, A L Uranium Fuel Licensing Branch 83/06/09 Uranium Fuel Licensing Branch 2pp 18907 333

8306230114 Forwards IE Insp Rept 70-0820/B3-03 on B30418-0506 No noncompliance noted
STAROSTECKI, R. Division of Project & Resident Programs 83/06/09, AMY, G O United Nuclear Corp 2pp 18747 057

--8306230118 IE Insp Rept 70-0820/B3-03 on B30418-0506 No noncompliance noted Major areas inspected decommissioned processing areas
ROTH, J, CLEMONS, P., ELBASER, T C Region 1, Office of Director, 83/06/07 13pp 18947 057

8306290577 Forwards revised Subsection 2 to Section 1 of final survey rept re description of methodology
HELGESON, K A United Nuclear Corp 83/06/16 CROW, W T Office of Nuclear Material Safety & Safeguards, Director 2pp. 19047 195

DOCKET 70-0824 BABCOCK & WILCOX CO., LYNCHBURG, VA

8306140609 Forwards IE Insp Rept 70-0824/B3-03 on B30427-29. No noncompliance noted
STOHR, J P Division of Emergency Preparedness & Materials Safety 83/05/18 ENGELDER, T C Babcock & Wilcox Co 2pp 18834 351.

--8306140617 IE Insp Rept 70-0824/B3-03 on B30427-29 No noncompliance noted Major areas inspected organization, facility changes & mods, internal review, safety committee operations & criticality safety
CORVELL, G P. Region 2, Office of Director MCALPINE, E J Division of Emergency Preparedness & Materials Safety 83/05/17, 4pp 18834 353

8306220131 Submits info re planned shipments of BNH of moderate strategic significance
REGAN, N A Babcock & Wilcox Co 83/05/30 O'REILLY, J P. Region 2, Office of Director 2pp. 18937 357

DOCKET 70-1113 GENERAL ELECTRIC CO., WILMINGTON, NC

8306140122 Ack receipt of IE Insp Rept 70-1113/B3-08 on B30307-11 No proprietary info
VAUGHAN, C M General Electric Co. 83/04/15 STOHR, J.P. Division of Emergency Preparedness & Materials Safety. 1p. 18839:100.

8306140072 Confirms 830518 enforcement conference at facility to discuss improper shipments of radioactive matl to Chem-Nuclear site at Barnwell, SC, per 830511 telcon
O'REILLY, J P Region 2, Office of Director 83/05/13 LONG, J A General Electric Co 1p 18838 341

8306140317 Ack receipt of 830509 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 70-1113/B3-06
STOHR, J P Division of Emergency Preparedness & Materials Safety. 83/05/26 LONG, J A General Electric Co 1p. 18832:192.

--8306140338 Responds to NRC 830411 ltr re violation noted in IE Insp Rept 70-1113/B3-06 Corrective actions: internal WHD procedures modified to require surveys during roof scrubber filter changes following unusual incidents
VAUGHAN, C M General Electric Co 83/05/09 STOHR, J.P. Division of Emergency Preparedness & Materials Safety 3pp 18832 193

--8306140342 Forwards IE Insp Rept 70-1113/B3-06 on B30307-11 & notice of violation
STOHR, J P Division of Emergency Preparedness & Materials Safety. 83/04/11 LONG, J A General Electric Co 2pp. 18832:196.

--8306140348 Notice of violation from insp on B30307-11
* Region 2, Office of Director, 83/04/11 1p 18832:198.

--8306140387 IE Insp Rept 70-1113/B3-06 on B30307-11 Noncompliance noted: failure to perform airborne radioactivity surveys during removal of contaminated high efficiency particulate air filters on 830204
HOBSEY, C H Region 2, Office of Director. BARR, K P. Division of Engineering & Radiological Safety Programs 83/04/07. 8pp. 18832 199

8306140576 Forwards IE Safeguards Insp Rept 70-1113/B3-14 on B30502-06. No noncompliance noted.
STOHR, J P Division of Emergency Preparedness & Materials Safety. 83/06/01 LONG, J A General Electric Co 2pp. 18834 357.

--8306140582 IE Safeguards Insp Rept 70-1113/B3-14 on B30502-06 No noncompliance noted Major areas inspected: physical inventory on previous insp findings (MC-85213) Details withheld (ref 10CFR 790)
BABADOSS, J W. Region 2, Office of Director. MCALPINE, E J. Division of Emergency Preparedness & Materials Safety. 83/06/01, 1p 18834:359

8306140568 Forwards IE Safeguards Insp Rept 70-1113/B3-13 on B30425-29. No noncompliance noted
STOHR, J P Division of Emergency Preparedness & Materials Safety. 83/06/02 LONG, J A General Electric Co. 2pp. 18834:338

DOCKETED ITEMS

--B306140975 IE Insp Rept 70-1113/B3-13 on B30425-29 No noncompliance noted Major areas inspected verification of export shipment & measurement control program Rept details withheld (ref 10CFR2 790)
BATES, J. H. Region 2, Office of Director MCALPINE, E. J. Division of Emergency Preparedness & Materials Safety 83/06/02 1p 18834 340

B306210444 Submits items of interest re B30603 meeting w/OE to discuss supplemental info needed for license renewal application & notice of availability of Kerr-McGee IE9 NMSS div meeting notices & info on Canonsburg, PA site encl
PAGE, R. G. Uranium Fuel Licensing Branch 83/06/08 DAVIS, J. G. Office of Nuclear Material Safety & Safeguards, Director 3pp 18935-056

DOCKET 70-1143 WESTINGHOUSE ELECTRIC CORP., PITTSBURGH, PA

B3062000221 Forwards IE Insp Rept 70-1143/03-01 on B30325-2B & notice of violation
STAROSTECKI, R. Division of Project & Resident Programs 83/06/06 JACOBI, W. M. Westinghouse Electric Corp 2pp 18902 288

--B306200222 Notice of violation from insp on B30323-25
* Region 1, Office of Director 83/06/06 1p 18902 290

--B306200225 IE Insp Rept 70-1143/B3-01 on B30323-25 Noncompliance noted failure to initiate special air investigation repts when three stack air samples exceeded action level
ROTH, J., ELBASSER, T. C. Region 1, Office of Director 83/05/20 8pp. 18902 291

B306150001 Notification of B30429 significant licensee meeting w/vendor in King of Prussia, PA to discuss status of plant decommissioning activities
ROTH, J., Region 1, Office of Director 83/06/10 Region 1, Office of Director 1p 18846 318

DOCKET 70-1151 WESTINGHOUSE ELECTRIC CORP., PITTSBURGH, PA

B304040114 Ack receipt of B30228 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 70-1151/B3-02
STOHR, J. P. Division of Emergency Preparedness & Materials Safety 83/04/06 D'AMORE, M. Westinghouse Electric Corp 1p 18728 092

--B304040118 Responds to NRC B30215 ltr re violation noted in IE Safeguards Insp Rept 70-1151/B3-02 Corrective actions withheld (ref 10CFR2 790)
D'AMORE, M. Westinghouse Electric Corp 83/02/28 O'REILLY, J. P. Region 2, Office of Director 3pp 18728 093

--B304040124 Forwards IE Safeguards Insp Rept 70-1151/B3-02 on B30125-2B & notice of violation, Encls withheld (ref 10CFR2 790)
STOHR, J. P. Division of Emergency Preparedness & Materials Safety 83/02/15 D'AMORE, M. Westinghouse Electric Corp 2pp 18728-095

B306080021 Forwards application for renewal of License SNM-1107, for 20-yr period, authorizing use of SNM at Columbia, SC site
NARDI, A. J. Westinghouse Electric Corp 83/04/29 PAGE, R. G. Uranium Fuel Licensing Branch 2pp 18786 001

--B306080023 Application for renewal of License SNM-1107, authorizing use of SNM at Columbia, SC site
* Westinghouse Electric Corp 83/04/30 496pp 18786 003.

B306140179 Ack receipt of B30429 application for renewal of License SNM-1107 Existing license will not expire until application for renewal has been determined by Commission
PAGE, R. G. Uranium Fuel Licensing Branch 83/06/06 NARDI, A. J. Westinghouse Electric Corp 1p 18844 186.

B306290433 Forwards IE Safeguards Insp Rept 70-1151/B3-10 on B30606-0B No noncompliance noted
STOHR, J. P. Division of Emergency Preparedness & Materials Safety 83/06/22 BRITTON, W. H. Westinghouse Electric Corp 2pp 19049 279.

--B306290436 IE Safeguards Insp Rept 70-1151/B3-10 on B30606-0B No noncompliance noted Major areas inspected physical protection of SNM of low strategic significance at fixed site Details withheld (ref 10CFR2 790)
HALL, B. L. Region 2, Office of Director MCQUIRE, D. R. Division of Emergency Preparedness & Materials Safety 83/06/20 1p 19049 281.

DOCKET 70-1201 BABCOCK & WILCOX CO., LYNCHBURG, VA

B306140674 Rev 1 to application for Amend B3-1 to License SNM 1168, allowing receipt of reactor insp equipment for storage & maint Revised & add'l pages of license & check for minor amend fee encl
FORD, J. T. Babcock & Wilcox Co 83/03/09 PAGE, R. G. Uranium Fuel Licensing Branch 11pp 18854 004

B306200020 Notifies of B3042J accident Truck carrying 45 packages containing low enriched U dioxide powder, 36 empty 55 gallon drums & two boxes of low enriched U lab samples overturned in Lynchburg, VA No radioactive mat'l released
AUSTIN, M. A. Babcock & Wilcox Co 83/05/19 Office of Nuclear Material Safety & Safeguards, Director 1p 18908 350

B306270121 Forwards revised pages to fundamental nuclear matls control plan, incorporating personnel reorganization, revised facility layout & Part 4 1 2 clarification Pages withheld (ref 10CFR2 790)
FORD, J. T. Babcock & Wilcox Co 83/05/23 O'REILLY, J. P. Region 2, Office of Director 1p 18788 063

B306140527 Forwards IE Insp Rept 70-1201/B3-06 on B30426 No noncompliance noted
STOHR, J. P. Division of Emergency Preparedness & Materials Safety 83/05/25 ALTU, R. A. Babcock & Wilcox Co 2pp 18840 180

--B306140529 IE Insp Rept 70-1201/B3-06 on B30426 & 27 No noncompliance noted Major areas inspected organization, facility mode, internal review & audit safety committees & nuclear criticality safety & operations
CORVELL, G. P. Region 2, Office of Director MCALPINE, E. J. Division of Emergency Preparedness & Materials Safety 83/05/24 4pp 18840 182

B306030152 Forwards negative declaration & EIA re renewal of license SNM-1168 for continued operation of plant w/o supporting EIA
PAGE, R. G. Uranium Fuel Licensing Branch 83/05/27 FORD, J. T. Babcock & Wilcox Co 1p 18733 310

--B306030179 Negative declaration re renewal of License SNM-1168 for continued operation of plant
PAGE, R. G. Uranium Fuel Licensing Branch 83/05/29 2pp 18733 311

B306020112 ENVIRONMENTAL IMPACT APPRAISAL FOR RENEWAL OF SPECIAL NUCLEAR MATERIAL LICENSE NO SNM-1168 Docket No 70-1201 (Babcock & Wilcox Company Commercial Nuclear Fuel Plant)
* Office of Nuclear Material Safety & Safeguards, Director NUREG-0987 83/05/31 141pp Available at NRC \$6.50 18698 271

DOCKET 70-1207 NAVY, DEPT OF, SILVER SPRING, MD

B306160313 Discusses IE Insp Repts 70-1207/B3-01, 30-08422/B3-01 & 30-10712/B3-01 on B30412-14 & forwards notice of violation
MARTIN, T. T. Division of Engineering & Technical Programs 83/06/01 FERNANDES, J. E. Navy, Dept of 3pp 18860 184

--B306160321 Notice of violation from insp on B30412-14 Noncompliance noted survey meters not calibr at 6-month intervals & refresher training not provided to individuals using licensed mat'l during CY81-83
* Region 1, Office of Director 83/06/01 2pp 18860 187

DOCKET 70-1224 TELEFLEX, INC., NORTH WALKER, PA

B306020408 Ack request of B30517 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-1224/B3-01
MARTIN, T. T. Division of Engineering & Technical Programs 83/05/31 ALBOM, I. Teleflex, Inc 1p 18693 205

--B306020415 Responds to NRC B30421 ltr re violation noted in IE Insp Rept 70-1224/B3-01 Corrective actions separate inventory listings will be maintained, plant engineer will post new deliveries & quarterly inventory count will be verified
DEAN, J. P. Teleflex, Inc 83/05/17 MARTIN, T. T. Region 1, Office of Director 2pp 18693 206

DOCKETED ITEMS

379

DOCKET 70-1257 EXXON NUCLEAR CO , INC , RICHLAND, WA

8306130493 Advises that fee not received for 830103 application to amend License SNM-1227 for const & operation of chemical process waste treatment facilities
WEISS, D License Fee Management Branch 83/02/28 MALODY, C W
Exxon Nuclear Co , Inc (subs of Exxon Corp) 1p 18830 271

--8306130500 Application to amend License SNM-1227 providing for const & operation of chemical process waste treatment facilities
Minor amend fee encl
MALODY, C W Exxon Nuclear Co , Inc (subs of Exxon Corp)
83/01/03 CROW, W T Uranium Fuel Licensing Branch 6pp
18870 272

8306240394 Application to amend License SNM-1227, allowing const & operation of solids holding & leaching basin & permitting cleanout of solids from lagoons
MALODY, C W Exxon Nuclear Co , Inc (subs of Exxon Corp)
83/05/04 CROW, W T Division of Fuel Cycle & Material Safety 6pp

8306190332 Issues Amend 10 to Exxon Nuclear Co, Inc license, authorizing const & operation of solids basin SER encl
PAGE, R Q Uranium Fuel Licensing Branch 83/06/07 MALODY, C W
Exxon Nuclear Co , Inc (subs of Exxon Corp) 1p 18870 007

--8306150335 SER supporting Amend 10 to License SNM-1227, authorizing const & operation of solids holding & leaching basin
DIDINGER, O H , CROW, W T Uranium Fuel Licensing Branch 83/06/07
2pp 18870 008

8306200406 Forwards IE Safeguards Insp Rept 70-1257/83-03 on 830523-27 No noncompliance noted
NORDERHAUG, L R Region 5, Office of Director 83/06/15 NELSON, R
Exxon Nuclear Co , Inc (subs of Exxon Corp) 2pp 18919 220

--8306200410 IE Safeguards Insp Rept 70-1257/83-03 on 830523-27 No noncompliance noted Major areas inspected facility organization & operations & shipper-receiver verification
Details withheld (ref 10CFR 290)
NELSON, R & , WIEBER, A V , NORDERHAUG, L R Region 5, Office of Director 83/06/15 1p 18919 222

DOCKET 70 1308 GENERAL ELECTRIC CO , SAN JOSE, CA

8306030426 Submits annual consolidated SAR update
DAWSON, D M General Electric Uranium Management Corp 83/05/13
CUNNINGHAM, R E Division of Fuel Cycle & Material Safety 2pp
18735 346

8306240484 Suggests withdrawal of rev to GA Plan NEDO-20776, for further editing before resubmission Response by 830708 requested
ROBERTS, J P Advanced Fuel & Spent Fuel Licensing Branch 83/06/20
DAWSON, D M General Electric Co 1p 18978 047

DOCKET 70-1402 ABINGTON MEMORIAL HOSP , ABINGTON, PA

8306280429 Ack receipt of 830517 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-02948/83-01, 30-00453/83-01 & 70-1402/83-01 on 830315
MARTIN, T T Division of Engineering & Technical Programs 83/06/22
CANDIA, Q Abington Memorial Hosp Abington, PA 1p 19020 324

--8306280433 Responds to NRC 830421 ltr re violations noted in IE Insp Repts 30-02948/83-01, 30-00453/83-01 & 70-1402/83-01 on 830315
Corrective actions, 3-month interval calibr check of survey meters reinstituted
CANDIA, Q R Abington Memorial Hosp Abington, PA 83/09/17
MARTIN, T T Division of Engineering & Technical Programs 2pp
19020 325

DOCKET 70-1549 NUCLEAR FUEL SERVICES, INC., ERWIN, TN

8306170024 Notifies of 830517-20 meetings w/vendor at Erwin, TN re safeguards program & other classified, proprietary & safeguards info
GUNDERSEN, O Fuel Facility Safeguards Licensing Branch 83/05/24
BROWN, W B Fuel Facility Safeguards Licensing Branch 1p
18907 348

DOCKET 70-1739 TRI-STATE MOTOR TRANSIT CO , JOPLIN, MO

8306200115 Forwards route overview depicting planned check call frequency for forthcoming shipment, w/o encl
RUTENKROGER, E Tri-State Motor Transit Co 83/05/19 HILLMAN, C
NRC - No Detailed Affiliation Given 2pp 18908 236

DOCKET 70-1764 NUCLEAR FUEL SERVICES, INC , ERWIN, TN

8306170024 Notifies of 830517-20 meetings w/vendor at Erwin, TN re safeguards program & other classified, proprietary & safeguards info
GUNDERSEN, O Fuel Facility Safeguards Licensing Branch 83/05/24
BROWN, W B Fuel Facility Safeguards Licensing Branch 1p
18907 348

DOCKET 70-2375 PACIFIC GAS & ELECTRIC CO , SAN FRANCISCO, CA

8306240398 Application to renew License SNM-1667, extending expiration date to 840630
SCHUYLER, J O Pacific Gas & Electric Co 83/05/11 PAGE, R Q
Uranium Fuel Licensing Branch 1p 18997 354

8306290682 Amend 9 to License SNM-1667, extending expiration date to 840630 or upon conversion of CFRP-69 to OL
PAGE, R Q Uranium Fuel Licensing Branch 83/06/16 SCHUYLER, J O
Pacific Gas & Electric Co 1p 19047 102

--8306290687 SER supporting Amend 9 to License SNM-1667
DIDINGER, O H , CROW, W T Uranium Fuel Licensing Branch 83/06/16
1p 19047 103

DOCKET 70-2548 DOVER GENERAL HOSP , DOVER, NJ

8306020399 Ack receipt of 830330 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-2548/82-01, 30-00374/82-01 & 30-02576/82-01
MARTIN, T T Division of Engineering & Technical Programs 83/05/31
LOVELL, R Dover General Hosp Dover, NJ 1p 18695 013

--8306020405 Responds to NRC 830324 ltr re violations noted in IE Insp Repts 70-2548/82-01, 30-00374/82-01 & 30-02576/82-01 Exhibits A, B, C & D re Co-60 teletherapy forwarded
LOVELL, R M Dover General Hosp Dover, NJ 83/03/30 MARTIN, T T
Division of Engineering & Technical Programs 16pp 18695 014

DOCKET 70-2669 ROBERT PACKER HOSP , SAYRE, PA

8306150156 Ack receipt of 830418 ltr informing NRC of steps taken to correct violations noted in IE Insp of License SNM-1758
License should be retired
MARTIN, T T Division of Engineering & Technical Programs 83/06/08
MORRISON, O B Robert Packer Hosp Sayre, PA 1p 18846 001

--8306150163 Informs that License SNM-1758 expired on 820831 No renewal application received licensee never received or possessed
licensed matl Termination requested per 830418 ltr
KINNEMAN, J D Region 1, Office of Director 83/06/08
WALKER, L E Material Control Licensing Branch 1p 18846 002

--8306150166 Responds to NRC 830331 ltr re License SNM-1758 No matls procured or expected under license, Cancellation of license requested
MORRISON, O B Robert Packer Hosp Sayre, PA 83/04/18 Region 1, Office of Director 1p 18846 003

--8306150169 Certificate of disposition of matls: no matls procured by licensee under License SNM-1758
MORRISON, O B Robert Packer Hosp Sayre, PA 83/04/18 1p
18846 004

DOCKET 70-2838 CINCINNATI GAS & ELECTRIC CO , CINCINNATI, OH

8306080393 Issues Amend 8 to License SNM-1823, extending expiration date to 850731 or upon conversion of CFRP-88 to OL
PAGE, R Q Uranium Fuel Licensing Branch 83/05/31 FLYNN, J D
Cincinnati Gas & Electric Co 1p 18792 174

--8306080396 Safety evaluation supporting Amend 8 to License SNM-1823
DIDINGER, O H , CROW, W T Uranium Fuel Licensing Branch 83/05/31
1p 18792 175

DOCKETED ITEMS

DOCKET 70-2850 WEBER STATE COLLEGE, OODEN, UT

8306090065 Submits notice of violation re expiration of License SNM-1819 Discusses actions to be taken by licensee
Radioactive matl must be placed in secure storage until valid license issued
BROWN, D. Region 4, Office of Director 83/06/03 TRIPP, D Weber State College 2pp 18793 26B

DOCKET 70-2892 AUXILIARY HOSP, HATO REY, PR

8306020312 Application for renewal of License SNM-1823, revising expiration date to 830731 or upon conversion of CPR-88 to OL
FLYNN, J D Cincinnati Gas & Electric Co 83/02/12 PAGE, R O Division of Fuel Cycle & Material Safety 1p. 18715 280

DOCKET 70-2910 TENNESSEE VALLEY AUTHORITY, CHATTANOOGA, TN

8306030504 Application for extension of License SNM-1841 to 840331 due to const delays
MILLS, L M Tennessee Valley Authority 83/05/02 CROW, W T Division of Fuel Cycle & Material Safety 1p. 18735 002

8306080082 Informs that License SNM-1841 has been amended, extending expiration date to 840331 or upon conversion of CPR-91 to OL BCR encl
PAGE, R O Uranium Fuel Licensing Branch 83/06/01. MILLS, L M Tennessee Valley Authority 1p 18787 306

--8306080084 Recommends approval of 830502 application to amend License SNM-1841 extending expiration until 840331 or upon conversion of CPR-91 to OL
BIDINGER, G H, CROW, W T Uranium Fuel Licensing Branch 83/06/01 Uranium Fuel Licensing Branch 1p 18787 307.

8306090255 Issues Amend 5 to License SNM-1841, changing expiration date to 840331 or upon conversion of CPR-91 to OL
PAGE, R O Uranium Fuel Licensing Branch 83/06/01. MILLS, L M Tennessee Valley Authority 1p 18777 043

--8306090259 Safety evaluation supporting 830502 amend application to extend license expiration date to 840331 due to const delays
PAGE, R O Uranium Fuel Licensing Branch 83/06/01 1p 18777:044

DOCKET 70-2926 DETROIT EDISON CO, DETROIT, MI

8306090022 Unexecuted Amend 25 to Indemnity Agreement B-20, deleting items 3 & 4 re license numbers & location, respectively
BALTZMAN, J. Assistant Director for State & Licensee Relations 83/05/31 1p 18797 361 24X Fiche 50-016, 83/05/31, 8306090022

8306090039 Unexecuted Amend 24 to Indemnity Agreement B-20, adding Wolverine Power Supply Cooperative as licensee
BALTZMAN, J Assistant Director for State & Licensee Relations 83/05/31. 1p 18797 360 24X Fiche 50-016, 83/05/31, 8306090039

8306090265 Forwards Matls License SNM-1915 authorizing receipt, possession, insp & storage of enriched U-235 contained in fuel assemblies, for eventual use at Enrico Fermi, Unit 2
Indemnity Agreement B-20 & BCR also encl.
PAGE, R O. Uranium Fuel Licensing Branch. 83/05/31 TAUBER, H Detroit Edison Co 2pp 18810 047

--8306090269 Matls License SNM-1915 authorizing receipt, possession, insp & storage of enriched U-235 contained in fuel assemblies for use at Enrico Fermi, Unit 2
PAGE, R O Uranium Fuel Licensing Branch. 83/05/31 3pp 18810:051

--8306090274 Safety evaluation supporting issuance of Matls License SNM-1915 re 821109 application for storage of enriched fuel assemblies at Enrico Fermi, Unit 2
BERINI, B L Uranium Fuel Licensing Branch. 83/05/31. 13pp. 18810:054

929 ARMY, DEPT. OF, FT MCCELLAN, AL

R Insp Findings & Licensee Ack dtd 830407 of License nsp findings no violations observed
2, Office of Director. 83/04/07. 1p 18839.070

DOCKET 70-2945 UNION ELECTRIC CO, ST LOUIS, MO

8306010110 Application to amend License SNM-1901 permitting restricted use of cranes in proximity of fuel bldg cranes, when not in use, will be placed in safe configuration
SCHNEEL, D F Union Electric Co 83/05/16 KEPPLER, J O Region 3, Office of Director 5pp 18686 343

8306290585 Notifies that either operating supervisor or shift supervisor will verify trolley placement & replacement of crane stops during & after use of cask handling crane over spent fuel pool, per 830516 ltr
SCHNEEL, D F Union Electric Co 83/06/17 DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director 2pp 19282 021

DOCKET 70-2947 ILLINOIS POWER & LIGHT CO, DECATUR, IL

8306020203 Application to renew License SNM-1886, extending license to 840831 or upon conversion of CPR-137 to OL Amend authorizing possession of two neutron calibr stds consisting of max of 20 Ci Pu-238 requested
WOLLER, G E Illinois Power Co 83/04/25 CUNNINGHAM, R E Division of Fuel Cycle & Material Safety 2pp 18701 062

DOCKET 70-2950 WASHINGTON PUBLIC POWER SUPPLY SYSTEM, RICHLAND, WA

8306080026 Application to amend License SNM-1890, changing present curie limit from 1,200 Ci/source to 3,000 Ci/source
BOUCHEY, G D Washington Public Power Supply System 83/04/15 Office of Nuclear Material Safety & Safeguards, Director 1p 18787 312

8306240339 Application for amend to License SNM-1890 increasing possession limit to 3,000 Ci/source
BOUCHEY, G D Washington Public Power Supply System 83/04/15 Office of Nuclear Material Safety & Safeguards, Director 5pp 18999:235

8306240460 Application for amend to License SNM-1890, deleting ref to warehouse storage
BOUCHEY, G D Washington Public Power Supply System 83/06/16 Office of Nuclear Material Safety & Safeguards, Director 5pp 18998 108

DOCKET 70-2953 CONNECTICUT, UNIV OF, STORRS, CT

8306020025 Ack receipt of 830503 ltr informing NRC of steps taken to correct violations noted in IF Insp Repts 30-10576/83-01, 30-11727/83-01 & 70-2953/83-01
MARTIN, T T Division of Engineering & Technical Programs 83/05/18 VAN GELDER, A Connecticut, Univ of 1p 18702 333

--8306020032 Responds to NRC 830411 ltr re violations noted in IF Insp Repts 30-10576/83-01, 30-11727/83-01 & 70-2953/83-01
Corrective actions room locked, proper posting maintained & updated Form NRC-3 posted
HARSHAW, F. Connecticut, Univ of 83/05/03 MARTIN, T T Division of Engineering & Technical Programs 2pp 18702 334

DOCKET 70-2968 CLEVELAND ELECTRIC ILLUMINATING CO, CLEVELAND, OH

8306240344 Amend 2 to application for SNM license, changing requested effective date of license to 840810
EDELMAN, M R Cleveland Electric Illuminating Co 83/05/27 DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director 10pp 18999 171

DOCKET 70-2982 ROCHESTER, UNIV OF, ROCHESTER, NY

8306030456 Application for license authorizing possession only of 455 g U hexafluoride stored in metal cylinder, for use in animal inhalation experiments
O'REGORY, M D Rochester, Univ of, 83/04/28 COOL, D A Office of Nuclear Material Safety & Safeguards, Director 2pp 18735 275

DOCKET 70-2984 ARIZONA PUBLIC SERVICE CO, PHOENIX, AZ

8306070432 Application for SNM license, authorizing storage of unirradiated reactor fuel & associated radioactive matl
Supporting documentation encl
ANDONINI, G C Arizona Public Service Co 83/04/26 Office of Nuclear Material Safety & Safeguards, Director 151pp 18776 182

DOCKETED ITEMS

381

B306240284 Forwards until B30426 application for BNM license
DEWEY, L. B. Hearing Branch 3 83/06/21 LAZOR, M., CALLIHAN, D.,
COLE, R. F. Atomic Safety and Licensing Board Panel 149pp
18979 291 24X Fiche 50-529, 83/06/21, B306240284

DOCKET 70-2985 DUKE POWER CO., CHARLOTTE, NC

B306020638 Forwards application for BNM license
TUCKER, H. D. Duke Power Co 83/05/17 DAVIS, J. O. Office of Nuclear
Material Safety & Safeguards, Director PAGE, R. G. Uranium Fuel
Licensing Branch 2pp 18716 304

--B306020646 Application for BNM license, authorizing receipt, possession,
insp, use & storage of U enriched in U-235 isotope, contained
in fuel assemblies & in fission chambers, Pu-238 contained
in Pu/Be neutron source & Pu-239 alpha source
* Duke Power Co 83/05/17 24pp 18716 306

PACKAGING OF RADIOACTIVE MATERIAL FOR TRANSPORT AND TRANSPORTATION OF RADIOACTIVE MATERIAL UNDER CERTAIN CONDITIONS

DOCKET 71-0002 ATCOR ENGINEERED SYSTEMS, INC

B306090030 Forwards IE Insp Rept 71-0002/83-61 on B30427 of activities
associated w/periodic maint of transport packages No
noncompliance noted
MARTIN, T. T. Division of Engineering & Technical Programs 83/05/25
BROWNSTEIN, M. ATCOR 2pp 18792 358

--B306090036 IE Insp Rept 71-0002/83-61 on B30427 No noncompliance noted
Major areas inspected periodic maint of transport packages,
including QA manual & interviews w/personnel
CLEMONS, P., SHANBAKY, M. Region 1, Office of Director 83/05/24
2pp 18792 360

B306230473 Clarifies IE Insp Rept 71-0002/83-61 transmitted by B30525
ltr re maint activities for transport packages at alternate
facility
MARTIN, T. T. Division of Engineering & Technical Programs 83/06/20
BROWNSTEIN, M. ATCOR 1p 18941 301

DOCKET 71-0086 ALPHA-OMEGA SERVICES, INC

B306160649 Forwards "QA Plan for Shipping Packages," for approval Plan
is not rev
SOUTHERN, R. L. Alpha-Omega Services, Inc 83/05/25 GORDON, L.
Transportation Branch 2pp 18884 250

--B306160652 "QA Plan for Shipping Packages"
* Alpha-Omega Services, Inc 83/05/25 30pp 18884 252

B306240483 Forwards QA program approval for Radioactive Matl Package
0086, Rev 1
MACDONALD, C. E. Transportation Branch 83/06/16 SOUTHERN, R. L.
Alpha-Omega Services, Inc 1p 18997 361

--B306240489 QA Program approval for Radioactive Matl Package 0086, Rev 1
MACDONALD, C. E. Transportation Branch 83/06/16 1p 18997 362

DOCKET 71-0210 GULF NUCLEAR, INC

B306060394 QA program for Gulf Nuclear, Inc W/B30504 ltr
HOPCRAFT, C. P. Gulf Nuclear, Inc 83/03/01 MACDONALD, C. E.
Transportation Branch 36pp 18750 216

B306220203 Requests addl info re B30504 application for approval of
revised QA program applicable to design, fabrication & use of
packaging containing special form radioactive matl W/o encl
Reg Guide 7.10
MACDONALD, C. E. Transportation Branch 83/06/13 HOPCRAFT, C. P.
Gulf Nuclear, Inc 2pp 18751 036

DOCKET 71 0250 TRANSNUCLEAR, INC

B306020258 Forwards IE Insp Repts 71-0250/83-61 on B30426 No
noncompliance noted
MARTIN, T. T. Division of Engineering & Technical Programs 83/05/20
MACKLIN, L. Transnuclear, Inc. 2pp 18690 275

--B306020264 IE Insp Rept 71-0250/83-61 on B30426 No noncompliance noted
Major areas inspected periodic maint of transport packages,
including QA manual, procedures & personnel interviews
CLEMONS, P., SHANBAKY, M. Region 1, Office of Director 83/05/18
2pp 18690 277

DOCKET 71-0302 ASSOCIATED PIPING & ENGINEERING CORP

B306020585 Forwards, for approval, QA for Radioactive Matl Package 0302
Rev 0 Requests registration as user of Model 6717-B W/o
encl
JONES, K. C. Associated Piping & Engineering Corp (subs of Johnson
Controls, Inc.) 83/05/19 MACDONALD, C. E. Transportation Branch
1p 18715 061

DOCKET 71-0367 NAVY, DEPT OF

B306220231 Responds to B30503 request for rev to QA Program approval
for Certificate of Compliance 0367 to include SNAP-23A
radioisotope thermoelectric generator (RTG) QA program
administrative & mgt controls applicable to all RTGs
MACDONALD, C. E. Transportation Branch 83/06/13 SHOENAKER, D.
Navy, Dept of 1p 18977 352

DOCKET 71-0498 GEARHART-OWEN INDUSTRIES

B306220172 Forwards QA program approval for Radioactive Matl Package
0498, Rev 0
MACDONALD, C. E. Transportation Branch 83/06/13 KOEHL, K. M.
Gearhart-Owen Industries, Inc 1p 18937 279

--B306220178 QA program approval for Radioactive Matl Package 0498,
Rev 0,
MACDONALD, C. E. Transportation Branch 83/06/13 1p 18937 280

DOCKET 71-4909 MODEL GE 21PF-1, GENERAL ELECTRIC CO

B306080341 Discusses proposed design fixes for U hexafluoride 30-inch
diameter overpacks to correct water leakage problem Fixes
include mods to existing overpacks & to current DOT Spec
21PF-1 W/three oversize drawings Aperture cards are in PDR
PRICHARD, R. P. Transportation, Dept of 83/05/12 ROBERTS, A. I.
Transportation, Dept of 15pp 18770 250

--B306080348 "U Hexafluoride Product Cylinder - Overpack Insulation"
FRAZIER, J. L. Union Carbide Corp W-7405 K/TL/89-88 83/02/28
11pp 18790 266

--B306080358 Rev 1 to "BAR for Modified U Hexafluoride Cylinder Shipping
Package, DOT Spec 21 PF-1"
* Union Carbide Corp K/D-5400 R01 83/03/30 17pp 18790 277

B306020493 Notification of registration as user of Model GE-21PF-1
in response to B30310 request
MACDONALD, C. E. Transportation Branch. 83/05/25 TAYLOR, J. C. Union
Carbide Corp 1p 18715 194

B306080327 Forwards three oversize revised drawings, including one
proprietary, in response to NRC B30224 request for addl info
re B30119 request for amend to Certificate of Compliance
4909, Aperture cards in PDR & Central Files
NARDI, A. J. Westinghouse Electric Corp 83/05/31, MACDONALD, C. E.
Transportation Branch 1p. 18791 217

B306220195 Forwards request for addl info re B30119 & 0531 application
& suppl for approval of Model W-21PF-1 packaging Info should
be submitted as revised pages
MACDONALD, C. E. Transportation Branch 83/06/16 NARDI, A. J.
Westinghouse Electric Corp. 2pp 18751 043

DOCKET 71-4960 MODEL LLD-1, ENERGY, DEPT. OF

B306200022 Submits lists of BAR packages for which DOE no longer
intends to pursue certificates of compliance Also lists
BARPs for which DOE intends to pursue issuance of
certificates of compliance
PRICHARD, R. P. Energy, Dept. of. 83/05/31 MACDONALD, C. Division
of Fuel Cycle & Material Safety. 2pp 18908 352

DOCKET 71-5026 MODEL: CNS 14-190, CHEM-NUCLEAR SYSTEMS, INC.

B306090014 Forwards Rev 7 to Certificate of Compliance 5026 for Model
CNS 14-190
MACDONALD, C. E. Transportation Branch. 83/05/31 DEAL, R.
Chem-Nuclear Systems, Inc 3pp 18798 001

--B306090017 Certificate of Compliance 5026, Rev 7, for Model CNS 14-190
MACDONALD, C. E. Transportation Branch 83/05/31 4pp 18798 004.

DOCKETED ITEMS

DOCKET 71-5097 MODEL 44, ENERGY, DEPT OF

8306200022 Submits lists of SAR packages for which DOE no longer intends to pursue certificates of compliance Also lists SARPs for which DOE intends to pursue issuance of certificates of compliance
 PRICHARD, R P Energy, Dept of 83/05/31 MACDONALD, C Division of Fuel Cycle & Material Safety 2pp 18908 352

DOCKET 71-5170 MODEL STEEL INGOOT SKID & BOX 37, ENERGY, DEPT OF

8306200022 Submits lists of SAR packages for which DOE no longer intends to pursue certificates of compliance Also lists SARPs for which DOE intends to pursue issuance of certificates of compliance
 PRICHARD, R P Energy, Dept of 83/05/31 MACDONALD, C Division of Fuel Cycle & Material Safety 2pp 18908 352

DOCKET 71-5364 MODEL NPI-67-0442, NEUTRON PRODUCTS, INC

8306202048B Notification of registration as user of Models DT-14B & NPI-67-0442 in response to 830218 & 0322 requests
 MACDONALD, C E Transportation Branch 83/05/25 ANSELINO, A A E&O, Inc 1p 18715 200

8306240341 Informs of inadvertent overloading of shipping cask under Certificate of Compliance 536. On 830222, 407,300 Ci shipped in container licensed for 400,000 Ci. Caused by miscalculations of generation rate of first Co-60 targets
 SMEDIRA, C Neutron Products, Inc 83/06/03 MACDONALD, C E Transportation Branch 2pp 18999-231

DOCKET 71-5450 MODEL RCC, -1, -2, -3, -4, WESTINGHOUSE ELECTRIC CORP

8306290561 Forwards listing of applicable shipping packages for continued registration as user Encl also identifies packages to be removed from user list
 STEWART, W L Virginia Electric & Power Co 83/06/06 MACDONALD, C E Transportation Branch 4pp 19047 181

DOCKET 71-5467 MODEL MARK VR, VE & MARK 15, ENERGY, DEPT OF

8306200022 Submits lists of SAR packages for which DOE no longer intends to pursue certificates of compliance Also lists SARPs for which DOE intends to pursue issuance of certificates of compliance
 PRICHARD, R P Energy, Dept of 83/05/31 MACDONALD, C Division of Fuel Cycle & Material Safety 2pp 18908 352

DOCKET 71-5469 MODEL HNPB SPENT FUEL SHIPPING CASK, ENERGY, DEPT OF

8306200022 Submits lists of SAR packages for which DOE no longer intends to pursue certificates of compliance Also lists SARPs for which DOE intends to pursue issuance of certificates of compliance
 PRICHARD, R P Energy, Dept of 83/05/31 MACDONALD, C Division of Fuel Cycle & Material Safety 2pp 18908 352

DOCKET 71-5507 MODEL HFIR SPENT FUEL ELEMENT SHIPPING CASK, ENERGY,

8306200022 Submits lists of SAR packages for which DOE no longer intends to pursue certificates of compliance Also lists SARPs for which DOE intends to pursue issuance of certificates of compliance
 PRICHARD, R P Energy, Dept of 83/05/31 MACDONALD, C Division of Fuel Cycle & Material Safety 2pp 18908 352

DOCKET 71-5552 MODEL GAS CYLINDER FIRE IMPACT SHIELD, ENERGY, DEPT.

8306200022 Submits lists of SAR packages for which DOE no longer intends to pursue certificates of compliance Also lists SARPs for which DOE intends to pursue issuance of certificates of compliance
 PRICHARD, R P Energy, Dept of 83/05/31 MACDONALD, C Division of Fuel Cycle & Material Safety. 2pp 18908 352

DOCKET 71-5595 MODEL L&M ORNL URANIUM SHIELDED CASK, ENERGY, DEPT OF

8306200022 Submits lists of SAR packages for which DOE no longer intends to pursue certificates of compliance Also lists SARPs for which DOE intends to pursue issuance of certificates of compliance
 PRICHARD, R P Energy, Dept of 83/05/31 MACDONALD, C Division of Fuel Cycle & Material Safety 2pp 18908 352

8306240033 Advises that questions re structural integrity of Model L casks resolved by replacing stainless steel closure bolts w/ASIC 4340 quenched & tempered steel bolts Questions re containment & testing resolved w/issuance of revised SARP
 TRAVIS, W H Energy, Dept of 83/06/10 MACDONALD, C E Transportation Branch 2pp 18987 270

--8306240044 Certificate of Compliance 5575, Rev 4, For Models L & M
 TRAVIS, W H Energy, Dept of 83/06/10 46pp 18987 232

DOCKET 71-5597 MODEL TUNGSTEN SHIELDED CASK, ENERGY, DEPT OF

8306200022 Submits lists of SAR packages for which DOE no longer intends to pursue certificates of compliance Also lists SARPs for which DOE intends to pursue issuance of certificates of compliance
 PRICHARD, R P Energy, Dept of 83/05/31 MACDONALD, C Division of Fuel Cycle & Material Safety 2pp 18908 352

DOCKET 71-5607 MODEL T-2, ENERGY, DEPT OF

8306290610 Notifies that registration for Model OE T-2 still valid, in response to 830502 ltr Registration for Model HFIR not yet issued by NRC
 MACDONALD, C E Transportation Branch 83/06/21 DEIGL, H J Texas A&M Univ, College Station, TX 1p 19047 082

DOCKET 71-5608 MODEL BR 63 0101, ENERGY, DEPT OF

8306200022 Submits lists of SAR packages for which DOE no longer intends to pursue certificates of compliance Also lists SARPs for which DOE intends to pursue issuance of certificates of compliance
 PRICHARD, R P Energy, Dept of 83/05/31 MACDONALD, C Division of Fuel Cycle & Material Safety 2pp 18908 352

DOCKET 71-5641 MODEL UNC-2500, UNITED NUCLEAR CORP

8306080022 Application to amend Certificate of Compliance 5641 incorporating listed changes re stated dry & wet safe quantities per Amend 19
 KIRK, W F United Nuclear Corp 83/04/25 MACDONALD, C E Transportation Branch 2pp 18787 317

8306140790 Forwards request for addl info re 830425 application for amend to Model UNC-2500 packaging contents Response schedule requested within 30 days
 MACDONALD, C E Transportation Branch 83/05/31 KIRK, W F United Nuclear Corp 2pp 18845 325

8306170447 Forwards request for addl info re 830425 supplemented application for amend to Model UNC-2500 Response schedule requested within 30 days
 MACDONALD, C E Transportation Branch 83/06/08 KIRK, W F United Nuclear Corp 2pp 18907 326

DOCKET 71-5645 MODEL AL-L B, ENERGY, DEPT OF

8306200022 Submits lists of SAR packages for which DOE no longer intends to pursue certificates of compliance Also lists SARPs for which DOE intends to pursue issuance of certificates of compliance
 PRICHARD, R P Energy, Dept of 83/05/31 MACDONALD, C Division of Fuel Cycle & Material Safety 2pp 18908 352

DOCKET 71-5753 MODEL ORNL LOOP TRANSPORT CASK, ENERGY, DEPT OF

8306200022 Submits lists of SAR packages for which DOE no longer intends to pursue certificates of compliance Also lists SARPs for which DOE intends to pursue issuance of certificates of compliance
 PRICHARD, R P Energy, Dept of 83/05/31 MACDONALD, C Division of Fuel Cycle & Material Safety 2pp 18908 352

DOCKETED ITEMS

383

DOCKET 71-5795 MODEL NONE, ENERGY, DEPT OF

8306200022 Submits lists of SAR packages for which DOE no longer intends to pursue certificates of compliance Also lists SARPs for which DOE intends to pursue issuance of certificates of compliance
PRICHARD, R P Energy, Dept of 83/05/31 MACDONALD, C Division of Fuel Cycle & Material Safety 2pp 18908 352

DOCKET 71-5796 MODEL 181375, 181361, ADVANCED MEDICAL SYSTEMS, INC

830620046B Forwards Change 3, consisting of revised pages & drawings, to Certificate of Compliance 5796 showing four bolts on each side of tie down assembly bolt into machine irradiator head, in response to 821229 & 830225 ltrs
IRWIN, H R ATC Medical Technology, Inc 83/05/03 MACDONALD, C Transportation Branch 24pp 18719 210

8306210445 Requests revised analysis showing internal support sys capable of withstanding 30 ft corner drop per 821101 application for amend to Model 181375 packaging
MACDONALD, C E Transportation Branch 83/06/15 IRWIN, H R Advanced Medical Systems, Inc 1p 18735 355

DOCKET 71-5828 MODEL TREAT, ENERGY, DEPT OF

8306220184 Forwards Rev 2 to Certificate of Compliance 5828 for Model TREAT
MACDONALD, C E Transportation Branch 83/06/09 BARRACLAUGH, E Energy, Dept of 1p 18977 334

--8306220190 Certificate of Compliance 5828, Rev 2, for Model TREAT
Approval record encl
MACDONALD, C E Transportation Branch 83/06/09 3pp 18977 335

DOCKET 71-5885 MODEL AL-L 11, ENERGY, DEPT OF

8306200022 Submits lists of SAR packages for which DOE no longer intends to pursue certificates of compliance Also lists SARPs for which DOE intends to pursue issuance of certificates of compliance
PRICHARD, R P Energy, Dept of 83/05/31 MACDONALD, C Division of Fuel Cycle & Material Safety 2pp 18908 352

DOCKET 71-5907 MODEL ORNL IN PILE CAPSULE, ENERGY, DEPT OF

8306200022 Submits lists of SAR packages for which DOE no longer intends to pursue certificates of compliance Also lists SARPs for which DOE intends to pursue issuance of certificates of compliance
PRICHARD, R P Energy, Dept of 83/05/31 MACDONALD, C Division of Fuel Cycle & Material Safety 2pp 18908 352

DOCKET 71-5957 MODEL BMT-1, BATTELLE COLUMBUS LABORATORY

8306030045 Requests registration as user of Model BMT
DEIOL, H J Texas A&M Univ, College Station, TX 83/05/13
MACDONALD, C E Transportation Branch 1p 18733 190

DOCKET 71-5971 MODEL OE-200, GENERAL ELECTRIC CO

8306030029 Requests registration as user of Model OE-200
MILLER, R I Sacramento Municipal Utility District 83/05/08
MACDONALD, C E Transportation Branch 1p 18733 172

DOCKET 71-6003 MODEL M-130, ENERGY, DEPT OF

8306030087 Forwards Rev 4 to Certificate of Compliance 6003 for Model M-130
MACDONALD, C E Transportation Branch 83/05/25 ENGEL, W P Energy, Dept of 1p 18733 273

--8306030090 Certificate of Compliance 6003, Rev 4, for Model M-130.
MACDONALD, C E Transportation Branch 83/05/25 4pp 18733 274.

8306140787 Forwards request for addl info re 810911 application for amend to Certificate of Compliance 6003 to include light water breeder reactor seed modules in Model M-130 Addl info should be submitted in form of revised pages
MACDONALD, C E Transportation Branch 83/05/27. ENGEL, W P Energy, Dept of 2pp 18845 329

DOCKET 71-6080 MODEL D-38, OAK RIDGE NATIONAL LAB

8306200022 Submits lists of SAR packages for which DOE no longer intends to pursue certificates of compliance Also lists SARPs for which DOE intends to pursue issuance of certificates of compliance
PRICHARD, R P Energy, Dept of 83/05/31 MACDONALD, C Division of Fuel Cycle & Material Safety 2pp 18908 352

DOCKET 71-6104 MODEL ANL-390-BPM, ENERGY, DEPT OF

8306200022 Submits lists of SAR packages for which DOE no longer intends to pursue certificates of compliance Also lists SARPs for which DOE intends to pursue issuance of certificates of compliance
PRICHARD, R P Energy, Dept of 83/05/31 MACDONALD, C Division of Fuel Cycle & Material Safety 2pp 18908 352

DOCKET 71-6115 MODEL R1010-0032, ENERGY, DEPT OF

8306200022 Submits lists of SAR packages for which DOE no longer intends to pursue certificates of compliance Also lists SARPs for which DOE intends to pursue issuance of certificates of compliance.
PRICHARD, R P Energy, Dept of 83/05/31 MACDONALD, C Division of Fuel Cycle & Material Safety 2pp 18908 352

DOCKET 71-6142 MODEL BETTIS WASTE, ENERGY, DEPT. OF

8306030022 Forwards Rev 1 to Certificate of Compliance 6142 for Model B-2
MACDONALD, C E Transportation Branch 83/05/25 ENGEL, W P Energy, Dept of 1p 18733 160

--8306030027 Certificate of Compliance 6142, Rev 1, for Model Bettis Disposable Waste
MACDONALD, C E Transportation Branch 83/05/25 3pp. 18733 169

DOCKET 71-6244 MODEL 6244, CHEM-NUCLEAR SYSTEMS, INC

8306090070 Forwards Rev 4 to Certificate of Compliance 6244 for Model 6244
MACDONALD, C E Transportation Branch 83/05/31. DEAL, R Chem-Nuclear Systems, Inc 3pp 18797 351

--8306090074 Certificate of Compliance 6244, Rev 4 for Model 6244
MACDONALD, C E Transportation Branch 83/05/31. 4pp 18797 354

DOCKET 71-6272 MODEL 6272, U S ECOLOGY

8306200022 Submits lists of SAR packages for which DOE no longer intends to pursue certificates of compliance Also lists SARPs for which DOE intends to pursue issuance of certificates of compliance
PRICHARD, R P Energy, Dept of 83/05/31 MACDONALD, C Division of Fuel Cycle & Material Safety. 2pp 18908 352

DOCKET 71-6345 MODEL ANL-402-BPM & 403-BPM, E I DU PONT DE NEMOURS

8306200022 Submits lists of SAR packages for which DOE no longer intends to pursue certificates of compliance Also lists SARPs for which DOE intends to pursue issuance of certificates of compliance
PRICHARD, R P Energy, Dept of 83/05/31 MACDONALD, C Division of Fuel Cycle & Material Safety 2pp 18908 352

DOCKETED ITEMS

DOCKET 71-6346 MODEL FSV-1, GENERAL ATOMIC CO

8306210408 Application for amend to Certificate of Compliance 6346 to allow use of lead shielded pig within generic burial liners used w/FSV-1 cask, per JOCFR71 & IE Notice 83-10 QADR 55 safety analysis suppl, Addendum III & fee encl MOHRY, W R GA Technologies, Inc /General Atomic Co 83/05/18 MACDONALD, C E Division of Fuel Cycle & Material Safety App 18948 030

--8306210415 "Consolidated Design Rept for Fort St Vrain Fuel Shipping Cask," QADR-55 Addendum III for May 1983 MOORE, R L, LABAR, M P, MOHRY, W R GA Technologies, Inc /General Atomic Co 83/05/31 72pp 18948 029

8306210447 Forwards request for addl info re 830518 application requesting amend to Model FSV-1 packaging Response within 30 days requested MACDONALD, C E Transportation Branch 83/06/16 MOHRY, W R GA Technologies, Inc /General Atomic Co 3pp 18935 351

DOCKET 71-6357 MODEL NNFD-10, DARCOCK & WILCOX CO

8306290588 Requests registration as user of Model NNFD-10. IDEKER, R L Nuclear Fuel Services, Inc (subs of Getty Oil Co) 83/06/18 MACDONALD, C E Transportation Branch 1p 19047 198

DOCKET 71-6400 MODEL 6400, WESTINGHOUSE ELECTRIC CORP

8306010001 Forwards Rev 3 to SAR for packaging Super Tiger shipping container as adapted for light-water breeder reactor-type fuel rods Concurrence requested by 830704 ENGEL, W P Energy, Dept of 83/04/28 MACDONALD, C E Transportation Branch 2pp 18687 192

--8306010085 Rev 3 to SAR for packaging Super Tiger shipping container as adapted for light-water breeder reactor-type fuel rods PLUMMER, D E, ZUCKER, C E Energy, Dept of WAPD-LP(FE)-220 R03 83/02/28 120pp 18687 184

8306200022 Submits lists of SAR packages for which DOE no longer intends to pursue certificates of compliance Also lists SARPs for which DOE intends to pursue issuance of certificates of compliance PRICHARD, R P Energy, Dept of 83/05/31. MACDONALD, C Division of Fuel Cycle & Material Safety 2pp 18908 352

DOCKET 71-6421 MODEL CBE-14, ENERGY, DEPT OF

8306200022 Submits lists of SAR packages for which DOE no longer intends to pursue certificates of compliance Also lists SARPs for which DOE intends to pursue issuance of certificates of compliance PRICHARD, R P Energy, Dept of 83/05/31 MACDONALD, C Division of Fuel Cycle & Material Safety 2pp 18908 352

DOCKET 71-6550 MODEL 6-06-1, ENERGY, DEPT OF

8306170465 Requests for Model 6-6-5-1, documents referenced by Certificate of Compliance 6550 within 45 days of ltr date, to complete review of LBL 830503 renewal application MACDONALD, C E Transportation Branch 83/06/08 JACKSON, C D Energy, Dept of 1p 18894 362

DOCKET 71-6553 MODEL PADUCAH TIGER, ENERGY, DEPT OF

8306140744 Forwards Rev 1 to Certificate of Compliance 6553 for Model Paducah Tiger, MACDONALD, C E Transportation Branch 83/06/03 BLALOCK, L Energy, Dept of 2pp 18845 345

--8306140750 Certificate of Compliance 6553, Rev 1, for Model Paducah Tiger MACDONALD, C E Transportation Branch. 83/06/03 4pp 18845 347.

DOCKET 71-6574 MODEL HN-200, HITTMAN NUCLEAR & DEVELOPMENT CORP

8306020626 Notification of registration as user of Models HN-100S, HN-100, Series 1, HN-100, Series 3 & HN-100 in response to 830330 request MACDONALD, C E Transportation Branch 83/05/23 FAY, C W Wisconsin Electric Power Co 1p 18716 345

DOCKET 71-6601 MODEL CNS B-120, CHEM-NUCLEAR SYSTEMS, INC

8306240372 Corrects util name & address on list of registered users of Rev 10 to Certificate of Compliance 6601 for Model CNS B-120 packaging SAURY, R D Consolidated Edison Co of New York, Inc 83/05/24 MACDONALD, C E Transportation Branch 3pp 18987 359

8306090004 Forwards Rev 11 to Certificate of Compliance 6601 for Model CNS B-120 MACDONALD, C E Transportation Branch 83/05/31 DEAL, R Chem-Nuclear Systems, Inc 4pp 18798 245

--8306090006 Certificate of Compliance 6601, Rev 11 for Model CNS B-120 MACDONALD, C E Transportation Branch 83/05/31 3pp 18748 249

DOCKET 71-6613 MODEL 702, TECHNICAL OPERATIONS, INC

8306240440 Requests issuance of IAEA certificate of competent authority for Certificate of Compliance 6613 for Type B(u) packaging, Model 702, for use in conjunction w/Model 849 special form source assembly MUNRO, J J Technical Operations, Inc 83/05/16 RAWL, R Transportation, Dept of 1p 18997 273

DOCKET 71-6639 MODEL MH-1A, ENERGY, DEPT OF

8306200022 Submits lists of SAR packages for which DOE no longer intends to pursue certificates of compliance Also lists SARPs for which DOE intends to pursue issuance of certificates of compliance PRICHARD, R P Energy, Dept of 83/05/31 MACDONALD, C Division of Fuel Cycle & Material Safety 2pp 18908 352.

DOCKET 71-6679 MODEL 6679, U S ECOLOGY

8306030105 Requests extension until 830701 to submit addl info re consolidated application for Certificate of Compliance 6679 WALLER, N K US Ecology, Inc (formerly Nuclear Engineering) 83/05/18 MACDONALD, C E Transportation Branch 1p 18793 296

DOCKET 71-6698 MODEL NFB-4, NUCLEAR FUEL SERVICES, INC

8306230123 FOIA request for five categories of documents re spent fuel at facilities AUDIN, L Affiliation Unknown 83/03/05 Office of Administration 2pp 18982 045 24X Fiche 50-014, 83/03/05, 8306230123

8306230129 Responds to FOIA request for five categories of documents re spent fuel at facilities App A & B documents respond to Items 1, 2, 4 & 5 Forwards App B Documents 1 & 5-11. No documents located for Item 3 FELTON, J H Division of Rules and Records 83/04/13 AUDIN, L Affiliation Unknown 3pp 18982 047 24X Fiche 50-014, 83/04/13, 8306230129

DOCKET 71-6717 MODEL 6717-B, GAMMA INDUSTRIES

8306020585 Forwards, for approval, GA for Radioactive Matl Package 0302 Rev 0 Requests registration as user of Model 6717-B W/o encl JONES, K C Associated Piping & Engineering Corp (subs. of Johnson Controls, Inc) 83/05/19 MACDONALD, C E Transportation Branch 1p 18715 061.

DOCKETED ITEMS

385

DOCKET 71-9006 MODEL 500-SU, AUTOMATION INDUSTRIES, INC.

8306240430 Ack receipt of 830517 ltr requesting amend to Certificate of Compliance 9006 Minor amend fee required
JACKSON, Q License Fee Management Branch 83/06/07 SANTORO, M P
Automation Industries, Inc 2pp 18797 174

--8306240441 Forwards amend fee per 830517 request for addition of shielding plates to Model 500-SU, Ir-192 source changer, under Certificate of Compliance 9006
MAYBERRY, O B Automation Industries, Inc 83/06/02
MACDONALD, C L Transportation Branch 2pp 18797 176

--8306240445 Application for amend to Certificate of Compliance 9006, adding shielding plates to Model 500-SU, Ir-192 source changer w/two oversize drawings Aperture cards are available in PDR
SANTORO, M P Automation Industries, Inc 83/05/19
MACDONALD, C L Transportation Branch 2pp 18797 178

DOCKET 71-9010 MODEL NLI-1/2, NI INDUSTRIES, INC

8306240447 Application for amend to Rev 9 to Certificate of Compliance 9010 to allow transport of PWR fuel assembly w/max average burnup of 56,000 MWD/MTU & min cooling time of 450 days prior to shipment
JOHNSON, C R Nuclear Assurance Corp 83/05/24 MACDONALD, C L
Transportation Branch 2pp 18798 114

8306090034 Forwards Rev 10 to Certificate of Compliance 9010 for Model NLI-1/2
MACDONALD, C E Transportation Branch 83/05/27 JOHNSON, C R
Nuclear Assurance Corp 3pp 18798 011

--8306090037 Certificate of Compliance 9010, Rev 10, for Model NLI-1/2
MACDONALD, C E Transportation Branch 83/05/27 6pp 18798 014

DOCKET 71-9015 MODEL TN-B, OL, NO USERS

8306240375 Requests rev to Certificates of Compliance 9015 & 9016 to allow use of component spacers to properly position fuel within fuel compartments of TN-B, TN-B1 & TN-9 packagings
GOLDMANN, K Transnuclear, Inc 83/05/27 MACDONALD, C E
Transportation Branch 3pp 18787 314

8306090278 Forwards Rev 5 to Certificate of Compliance 9015 for Models TN-B & TN-B1
MACDONALD, C E Transportation Branch 81/06/03 GOLDMANN, K
Transnuclear, Inc 1p 18810 040

--8306090277 Certificate of Compliance 9015, Rev 5, for Models TN-B & TN-B1
MACDONALD, C L Transportation Branch 83/06/03 6pp 18810 041

DOCKET 71-9016 MODEL TN-9, NO USERS

8306240375 Requests rev to Certificates of Compliance 9015 & 9016 to allow use of component spacers to properly position fuel within fuel compartments of TN-B, TN-B1 & TN-9 packagings
GOLDMANN, K Transnuclear, Inc 83/05/27 MACDONALD, C E
Transportation Branch 3pp 18787 355

8306090408 Forwards Rev 3 to Certificate of Compliance 9016 for Model TN-9
MACDONALD, C E Transportation Branch 83/06/03 GOLDMAN, K
Transnuclear, Inc 1p 18792 176

--8306090411 Certificate of Compliance 9016, Rev 3, for Model TN-9
MACDONALD, C E Transportation Branch 83/06/03 5pp 18792 177

DOCKET 71-9017 MODEL SNAP-23A 1000, NAVY, DEPT OF

8306080326 Requests renewal of Certificate of Compliance 9017 for SNAP-23A Model 1000 shipping package w/expiration date of 830331 Amend to GA program to include Certificate of Compliance 9017 for SNAP-23A also requested
SHOEMAKER, B Navy, Dept of 83/05/03 ODEGAARDEN, R
Transportation Branch 2pp 18791 001

--8306080334 Forwards Certificate of Compliance 9017, Rev 1, for SNAP-23A Model 1000 shipping package
MACDONALD, C E Transportation Branch 77/03/29 HENDRIX, Q W
Navy, Dept of 2pp 18791 004

--8306080336 Certificate of Compliance 9017, Rev 1, for SNAP-23A Model 1000 shipping package
MACDONALD, C E Transportation Branch 77/03/29 3pp 18791 006

--8306080339 SER supporting use of SNAP-23A Model 1000 shipping package by Dept of Navy Supporting documentation encl W/15 oversize drawings Aperture cards are available in PDR
MACDONALD, C E Atomic Energy Commission, Directorate of Licensing
74/09/30 4pp 18791 009

--8306080340 Application for Certificate of Compliance 9017 for SNAP-23A Model 1000
* Hittman Nuclear & Development Corp (subs Hittman Corp),
74/04/19 12pp 18791 013

--8306080342 Supplemental application for Certificate of Compliance 9017 for SNAP-23A Model 1000
* Hittman Nuclear & Development Corp (subs Hittman Corp)
74/08/28 76pp 18791 141

8306150239 Forwards Rev 2 to Certificate of Compliance 9017 for Model SNAP-23A
MACDONALD, C E Transportation Branch 83/06/03 Navy, Dept of
1p 18870 050

--8306150240 Certificate of Compliance 9017, Rev 2, for Model SNAP-23A
MACDONALD, C E Transportation Branch 83/06/03 4pp 18870 051

DOCKET 71-9029 MODEL 676 & 676E, TECHNICAL OPERATIONS, INC

8306030041 Notification of registration as user of Models 676, 676E, 650, 660, 660E, 680, 715, 920, B50 & MRC-20WC in response to 830412 request
MACDONALD, C E Transportation Branch 83/05/23 KRUZIC, R W
Chicago Bridge & Iron Co 1p 18733 187

DOCKET 71-9032 MODEL 650, TECHNICAL OPERATIONS, INC

8306030041 Notification of registration as user of Models 676, 676E, 650, 660, 660E, 680, 715, 920, B50 & MRC-20WC in response to 830412 request
MACDONALD, C E Transportation Branch 83/05/23 KRUZIC, R W
Chicago Bridge & Iron Co 1p 18733 187

DOCKET 71-9033 MODEL 660 & 660L, TECHNICAL OPERATIONS, INC

8306240401 Requests registration as user of Model 660
NEAL, T P Consumers Power Co 83/05/26 MACDONALD, C E
Transportation Branch 1p 18797 353

DOCKET 71-9035 MODEL 680 & 680E, TECHNICAL OPERATIONS, INC

8306030041 Notification of registration as user of Models 676, 676E, 650, 660, 660E, 680, 715, 920, B50 & MRC-20WC in response to 830412 request
MACDONALD, C E Transportation Branch 83/05/23 KRUZIC, R W
Chicago Bridge & Iron Co 1p 18733 187

DOCKET 71-9039 MODEL 715, TECHNICAL OPERATIONS, INC

8306030041 Notification of registration as user of Models 676, 676E, 650, 660, 660E, 680, 715, 920, B50 & MRC-20WC in response to 830412 request
MACDONALD, C E Transportation Branch 83/05/23 KRUZIC, R W
Chicago Bridge & Iron Co 1p 18733 187

DOCKET 71-9056 MODEL SPEC 2-T, SOURCE PRODUCTION & EQUIPMENT CO

8306030053 Informs that 830419 application for amend to Certificate of Compliance 9056 requires Fee Request classified as minor amend
JACKSON, Q License Fee Management Branch 83/05/05 DICARRRY, R F
Source Production & Equipment Co, Inc, 2pp 18733 199

--8306030057 Requests amend to Certificate of Compliance 9056, requiring use of overpack, consisting of 12 gallon, 24 gauge drum fitted w/lock ring top
DICARRRY, R F Source Production & Equipment Co, Inc 83/04/19
MACDONALD, C E Transportation Branch 1p 18733 201

DOCKETED ITEMS

8306170464 Requests addl info re 830419 application for amend to Model SPEC 2-T Unique model number should be designated for overpack & contents Response schedule requested within 30 days of ltr date
 MACDONALD, C E Transportation Branch 83/06/08 DICHARRY, R F
 Source Production & Equipment Co., Inc 1p 18906 348

DOCKET 71-9070 MODEL N-55, ENERGY, DEPT OF

8306080382 Issues amend to Certificate of Compliance 9070 for Model N-55, authorizing one-time shipment of Pu fluoride neutron source containing 35 Ci Pu-238
 MACDONALD, C E Transportation Branch 83/06/03 NARDI, A J
 Westinghouse Electric Corp 2pp 18785 360

DOCKET 71-9080 MODEL 9080, HITTMAN NUCLEAR & DEVELOPMENT CORP

8306020528 Advises that encl Hittman Nuclear & Development Corp 830422 application for renewal of Certificate of Compliance 9080 & associated proprietary SARs & drawings should be placed in PDR
 MACDONALD, C E Transportation Branch 83/05/13 SCOTT, S. Document Management Branch 1p 18702 001

--8306020533 Forwards application for renewal of Certificate of Compliance 9080, authorizing use of HN-600 & NUPAC 7-100 casks.
 MALLORY, C W Hittman Nuclear & Development Corp (subs Hittman Corp) 83/04/22 MACDONALD, C Transportation Branch 2pp 18702-002

--8306020540 Application for renewal of Certificate of Compliance 9180, authorizing use of HN-600 & NUPAC 7-100 casks w/seven oversize drawings Aperture cards are available in PDR
 * Hittman Nuclear & Development Corp (subs Hittman Corp) 83/04/22 4pp 18702-004

--8306020592 Rev 0 to "SAR for 9080 Radwaste Shipping Cask"
 PETTIGREW, M Hittman Nuclear & Development Corp (subs Hittman Corp) STD-R-02-011 R00 83/04/22 76pp 18702 012

8306020635 Informs that Rev 6 to Certificate of Compliance 9080 for Model 9080 will not expire until determination made by Commission Application for renewal should be submitted in timely manner.
 MACDONALD, C E Transportation Branch 83/05/23 ROWE, B S Hittman Nuclear & Development Corp (subs Hittman Corp) 4pp 18716 334

8306290601 Forwards request for addl info in response to 830422 application for renewal of Certificate of Compliance 9080 for Model 9080. Info should be submitted within 60 days
 MACDONALD, C E Transportation Branch 83/06/20 MALLORY, C W Hittman Nuclear & Development Corp (subs Hittman Corp) 3pp. 19047-092

DOCKET 71-9086 MODEL HN-100, SERIES 1, HITTMAN NUCLEAR & DEV CORP.

8306020626 Notification of registration as user of Models HN-100S, HN-100, Series 1, HN-100, Series 3 & HN-200 in response to 830330 request.
 MACDONALD, C E Transportation Branch 83/05/23 FAY, C W Wisconsin Electric Power Co 1p 18716 345

DOCKET 71-9089 MODEL HN-100S, HITTMAN NUCLEAR & DEVELOP CORP

8306020626 Notification of registration as user of Models HN-100S, HN-100, Series 1, HN-100, Series 3 & HN-200 in response to 830330 request
 MACDONALD, C E Transportation Branch 83/05/23 FAY, C W Wisconsin Electric Power Co 1p. 18716 345.

8306130177 Advises that encl Hittman Nuclear & Development Corp 830514 application for renewal of Certificate of Compliance 9089 & associated proprietary SARs & drawings should be placed in PDR
 MACDONALD, C E Transportation Branch 83/06/03 SCOTT, S Document Management Branch 1p 18930 184.

--8306130185 Forwards application for renewal of Certificate of Compliance 9089, authorizing use of Model HN-100S
 MALLORY, C W Hittman Nuclear & Development Corp (subs Hittman Corp) 83/05/16 MACDONALD, C Transportation Branch 1p 18930-185

--8306130198 Application for renewal of Certificate of Compliance 9089, authorizing use of Model HN 100S W/Rev 0 to "SAR for HN-100S Radwaste Shipping Cask" & two oversize drawings Aperture cards are available in PDR
 * Hittman Nuclear & Development Corp (subs Hittman Corp) 83/05/16 4pp 18930 184

--8306130212 Rev 0 to "SAR for HN 100S Radwaste Shipping Cask"
 PETTIGREW, M Hittman Nuclear & Development Corp (subs Hittman Corp) STD R-02-012 R00 83/05/16 78pp 18930 192

DOCKET 71-9096 MODEL CNS 21-300, (CHEM-NUCLEAR SYSTEMS, INC

8306090202 Advises that response to 830503 request for addl info re Model CNS-21-300 amend request will be submitted by 830701
 POPPE, L K Chem-Nuclear Systems, Inc 83/05/27 MACDONALD, C Transportation Branch 1p 18809 234

8306280101 Summary of 830614 meeting w/Chem-Nuclear, Inc in Silver Spring, MD re proposed use of temporary shielding in Model CNS 21-300
 ODEGAARDEN, R H Transportation Branch 83/06/20 Transportation Branch 2pp 19042 300

DOCKET 71-9100 MODEL KKP-20-4940, KERR NUGEL NUCLEAR CORP

8306240459 Notification of registration as user of Model KKP 20 4950, in response to 830414 request
 MACDONALD, C E Transportation Branch 83/06/20 O'HARA, P D Rhone-Poulenc, Inc 1p 18997 255

DOCKET 71-9108 MODEL CNS 6-75, CHEM-NUCLEAR SYSTEMS, INC

8306210290 Application for renewal of Certificate of Compliance 9100, authorizing use of CNS 6-75 cask for shipment of radwaste
 Rev 1 to "SAR for Chem-Nuclear Sys, Inc Model CNS 6-75 Type A Radwaste Shipping Cask" encl
 POPPE, L K Chem-Nuclear Systems, Inc 83/05/31 MACDONALD, C Transportation Branch 1p 18921 244

--8306210256 Rev 1 to "SAR for Chem-Nuclear Sys, Inc Model CNS 6-75 Type A Radwaste Shipping Cask"
 * Chem-Nuclear Systems, Inc 83/05/20 53pp 18921 245

DOCKET 71-9110 MODEL MX-IC-100, MAGNAFLUX CORP

8306240342 Application for renewal of Certificate of Compliance 9110, Rev 0, for Model MX-IC-100
 ROSAUER, P J Affiliation Unknown 83/06/02 MACDONALD, C Transportation Branch 2pp 18999 114

8306170455 Forwards Rev 1 to Certificate of Compliance 9110 for Model MX-IC-100
 MACDONALD, C E Transportation Branch 83/06/09 ROSAUER, P J Magnaflux Corp (subs of Peabody Gation Corp) 2pp 18901 311

--8306170456 Certificate of Compliance 9110, Rev 1, for Model MX-IC 100 Approval record encl
 MACDONALD, C E Transportation Branch 83/06/09 3pp 18707 319

DOCKET 71-9111 MODEL CNS 6-80-2, CHEM-NUCLEAR SYSTEMS, INC

8306020040 Requests addl info re 830303 amend application for Model CNS6-80-2 Response requested in 30 days of receipt of ltr
 MACDONALD, C E Transportation Branch 83/05/25 DEAL, R Chem-Nuclear Systems, Inc 2pp 18702 321

8306090001 Forwards Rev 6 to Certificate of Compliance 9111 for Model CNS 6-80-2
 MACDONALD, C E Transportation Branch 83/05/31 SIMCHUK, J D Nuclear Packaging, Inc 3pp 18798 142

--8306090002 Certificate of Compliance 9111, Rev 6, for Model CNS 6-80-2
 MACDONALD, C E Transportation Branch 83/05/31 4pp 18798 255

8306170458 Requests consolidated application w/drawings, incorporating previous submittals, within 30 days of expiration date of Certificate of Compliance 9111 for Model CNS 6-80-2
 MACDONALD, C E Transportation Branch 83/06/08 SIMCHUK, J D Nuclear Packaging, Inc 1p 18906 359

DOCKETED ITEMS

387

DOCKET 71-9132 MODEL T-3, ENERGY, DEPT OF

8306170462 Requests registration as user of Model T-3 in response to 830602 request
PRICHARD, R P Energy, Dept of 83/06/02 MACDONALD, C E
Transportation Branch 1p 18706 351

8306240455 Notification of registration as user of Model T-3, in response to 830602 request
MACDONALD, C E Transportation Branch 83/06/20 Energy, Dept of 1p 18797 257

8306240485 Notification of registration as user of Model T-3, in response to 830602 request
MACDONALD, C E Transportation Branch 83/06/20 TERRY, W E Union Carbide Corp 1p 18798 060

DOCKET 71-9133 MODEL C-10, GAMMA INDUSTRIES

8306030038 Requests registration as user of Model C-10
EVANS, W A Capitol Steel Corp 83/05/05 MACDONALD, C E
Transportation Branch 1p 18733 179

DOCKET 71-9134 MODEL ETR, EXXON NUCLEAR IDAHO CO

8306160664 Requests Certificate of Compliance 9134 be revised to permit shipment of unirradiated reactor fuel other than ETR & QTR fuel elements Technical evaluation encl
PRICHARD, R P Energy, Dept of 83/06/02 MACDONALD, C E
Transportation Branch 5pp 10092 002

--8306160667 Certificate of Compliance 5/05, Rev 2, for Models ATR & ETH fuel element shipping containers
WILLIAMS, C E Energy, Dept of 82/10/25 4pp 10092 007

--8306160670 "ETR Fuel Element Shipping Container Addendum to PR-T-79-011 (TR-466)," internal technical report
SMITH, M L EG&O, Inc PR-T-79-012 R01 82/12/02 33pp
10084 217

DOCKET 71-9135 MODEL CENTURY 8 & 8A, CLN UNIV 8 & 8A, GAMMA IND

8306240381 Requests registration as user of Models Century 8A, IR-50 & IR-100
CORBESIA, D M Cherne Contracting Corp 83/06/06 MACDONALD, C E
Transportation Branch 1p 18787 354

DOCKET 71-9141 MODEL 900, TECHNICAL OPERATIONS, INC

8306160639 Informs that Model MRC-20WC vs. Package Number USA/9141/B in error Model number should be 900 Requests issuance of confirmation ltr covering model number
KRUZIC, R W Chicago Bridge & Iron Co 83/06/02 MACDONALD, C E
Transportation Branch 2pp 18804 342

8306240454 Notification of registration as user of Model 900, in response to 830602 request
MACDONALD, C E Transportation Branch 83/06/20 KRUZIC, R W
Chicago Bridge & Iron Co 1p 18997 256

DOCKET 71-9142 MODEL MRC-20WC, MONSANTO RESEARCH CORP

8306030041 Notification of registration as user of Models 676, 676E, 650, 660, 660E, 680, 715, 920, 850 & MRC-20WC in response to 830412 request
MACDONALD, C E Transportation Branch 83/05/23 KRUZIC, R W
Chicago Bridge & Iron Co 1p 18733 187

DOCKET 71-9143 MODEL 920, TECHNICAL OPERATIONS, INC.

8306030041 Notification of registration as user of Models 676, 676E, 650, 660, 660E, 680, 715, 920, 850 & MRC-20WC in response to 830412 request
MACDONALD, C E Transportation Branch 83/05/23 KRUZIC, R W
Chicago Bridge & Iron Co 1p 18733 107

DOCKET 71-9147 MODEL 850, TECHNICAL OPERATIONS, INC

8306030041 Notification of registration as user of Models 676, 676E, 650, 660, 660E, 680, 715, 920, 850 & MRC-20WC in response to 830412 request
MACDONALD, C E Transportation Branch 83/05/23 KRUZIC, R W
Chicago Bridge & Iron Co 1p 18733 187

DOCKET 71-9151 MODEL HN-100, SERIES 3, HITTHAN NUCLEAR & DEV CORP

8306020626 Notification of registration as user of Models HN-100B, HN-100, Series 1, HN-100, Series 3 & HN-200 in response to 830330 request
MACDONALD, C E Transportation Branch 83/05/23 FAY, C W
Wisconsin Electric Power Co 1p 18716 345

8306150143 Notification of registration as user of Models HN-100 Series 3 & CNS 14-170 Series III in response to 830228 request
MACDONALD, C E Transportation Branch 83/06/09 MUROLF, D
Northern States Power Co 1p 18872 071

DOCKET 71-9152 MODEL CNS 1-13C11, CHEM-NUCLEAR SYSTEMS, INC

8306020711 Notification of registration as user of Model CNS 1-13C 11 in response to 830309 request
MACDONALD, C E Transportation Branch 83/05/23 BRACKEN, K W
Energy, Dept of 1p 18715 319

DOCKET 71-9156 MODEL IR-50, INDUSTRIAL NUCLEAR CO

8306170461 Forwards info on IAEA B(U) certification of devices, per request. Requirements listed in IAEA Safety Std & adequately addressed in application
GAINEB, T H Industrial Nuclear Co 83/05/31 RAWL, R
Transportation, Dept of 2pp 18706 352

8306240381 Requests registration as user of Models Century 8A, IR-50 & IR-100
CORBESIA, D M Cherne Contracting Corp 83/06/06 MACDONALD, C E
Transportation Branch 1p 18787 354

DOCKET 71-9157 MODEL IR-100, INDUSTRIAL NUCLEAR CO

8306170461 Forwards info on IAEA B(U) certification of devices, per request. Requirements listed in IAEA Safety Std & adequately addressed in application
GAINEB, T H Industrial Nuclear Co 83/05/31 RAWL, R
Transportation, Dept of 2pp 18706 352

8306240381 Requests registration as user of Models Century 8A, IR-50 & IR-100
CORBESIA, D M Cherne Contracting Corp 83/06/06 MACDONALD, C E
Transportation Branch 1p 18787 354

DOCKET 71-9159 MODEL; NUPAC SERIES A, NUCLEAR PACKING, INC.

8306030135 Expresses appreciation to Transportation Certification Branch for cooperation & assistance during licensing process
SINCHUK, J D Nuclear Packaging, Inc. 83/05/04 MACDONALD, C E
Transportation Branch 1p 18733 308

DOCKET 71-9163 MODEL QN0-20, GULF NUCLEAR, INC

8306210305 Forwards pertinent drawings of shipping shield, insert & plug
HOPCRAFT, C P Gulf Nuclear, Inc 83/06/03 MACDONALD, C E
Division of Fuel Cycle & Material Safety. 12pp 18720:351

DOCKET 71-9165 MODEL 855, TECHNICAL OPERATIONS, INC.

8306030489 Forwards addl info on Model 855 Type B package in response to 820729 request
MUNRO, J J Technical Operations, Inc 83/05/12 MACDONALD, C E
Transportation Branch. 13pp 18735 270

DOCKETED ITEMS

--B306030492 Forward request for addl info re B20521 application for Certificate of Compliance 9163 for Model B55 packaging. Addl info should be submitted in form of revised pages. MACDONALD, C E Transportation Branch 82/07/29 MUNRO, J J Technical Operations, Inc 2pp 18745 244

B306220199 Forwards request for addl info re B20521 application & B30512 supp. For approval of Model B55 packaging Submittal schedule requested in 30 days. MACDONALD, C E Transportation Branch 83/06/16 MUNRO, J J Technical Operations, Inc 2pp 18751 038

DOCKET 71-9174 MODEL F-147, ATOMIC ENERGY OF CANADA, LTD

B306220185 Forwards request for addl info re B30224 application for approval of Model F-147 packaging Submittal schedule requested within 30 days. MACDONALD, C E Transportation Branch 83/06/15 RIDOUT, E F Canada, Atomic Energy Control Board 2pp 18777 332

DOCKET 71-9176 MODEL NUPAC 14/210L & 14/210H, NUCLEAR PACKAGING, INC

B306030135 Expresses appreciation to Transportation Certification Branch for cooperation & assistance during licensing process. SIMCHUK, J D Nuclear Packaging, Inc 83/05/04 MACDONALD, C E Transportation Branch 1p 18733 308

B306030042 Requests registration as user of Model NUPAC 14/210H. NIX, H C Georgia Power Co 83/05/13 MACDONALD, C E Transportation Branch 1p 18733 188

B306080345 Requests registration as user of Model 14-210H. EBENHACK, D G Chem-Nuclear Systems, Inc 83/05/26 MACDONALD, C E Transportation Branch 1p 18787 362

DOCKET 71-9178 MODEL NUPAC 7/100, NUCLEAR PACKAGING, INC

B306030135 Expresses appreciation to Transportation Certification Branch for cooperation & assistance during licensing process. SIMCHUK, J D Nuclear Packaging, Inc 83/05/04 MACDONALD, C E Transportation Branch 1p 18733 308

DOCKET 71-9179 MODEL NUPAC 6/100L & 6/100 H, NUCLEAR PACKAGING, INC

B306030135 Expresses appreciation to Transportation Certification Branch for cooperation & assistance during licensing process. SIMCHUK, J D Nuclear Packaging, Inc 83/05/04 MACDONALD, C E Transportation Branch 1p 18733 308

DOCKET 71-9182 MODEL HUSMAN IRRADIATOR, AGRICULTURE, DEPT OF

B306070453 Forwards "SAR for Husman Irradiator to 10CFR71 Type B Packaging Requirements " Packaging to be used by USDA. STREUTKER, B R Nuclear Packaging, Inc 83/05/16 MACDONALD, C E Transportation Branch 1p 18781 001

--B306070455 "SAR For Husman Irradiator to 10CFR71 Type B Packaging Requirements " * Nuclear Packaging, Inc 83/05/16 129pp 18781 002

--B306070458 Advises that Nuclear Packaging, Inc will be forwarding, under separate cover, SAR for new Husman Irradiator Request for issuance of license & IAEA Certificate of Competent Authority for shipment of radioactive material. JARRETT, R D Agriculture, Dept of 83/04/27 WEISS, D License Fee Management Branch 3pp 18781 131

DOCKET 71-9508 MODEL DOT SPEC 6M, ENERGY, DEPT OF

B306150326 Forwards list of addl info required re B00005 application requesting Certificate of Compliance authorizing shipment of polystyrene PU compacts in Model 6M packaging. MACDONALD, C E Transportation Branch 83/06/06 PRICHARD, R P Energy, Dept of 2pp 18867 357

DOCKET 71-9510 MODEL GPHS, ENERGY, DEPT OF

B306200022 Submits lists of SAR packages for which DOE no longer intends to pursue certificates of compliance. Also lists SARs for which DOE intends to pursue issuance of certificates of compliance. PRICHARD, R P Energy, Dept of 83/05/31 MACDONALD, C E Division of Fuel Cycle & Material Safety 2pp 18908 352

DOCKET 71-9851 MODEL LITHIUM HYDROXIDE FIRE/IMPACT SHIELD, ENERGY,

B306200022 Submits lists of SAR packages for which DOE no longer intends to pursue certificates of compliance. Also lists SARs for which DOE intends to pursue issuance of certificates of compliance. PRICHARD, R P Energy, Dept of 83/05/31 MACDONALD, C E Division of Fuel Cycle & Material Safety 2pp 18908 352

DOCKET 71-9852 MODEL DT-14, ENERGY, DEPT OF

B306020488 Notification of registration as user of Models DT-14B & NF1-67-0442 in response to B30218 & 0572 requests. MACDONALD, C E Transportation Branch 83/05/25 ANSELINO, A A EG&G, Inc 1p 18719 200

LICENSING OF INDEPENDENT SPENT FUEL STORAGE

DOCKET 72-0001 MORRIS OPERATIONS, GENERAL ELECTRIC CO

B306030426 Submits annual consolidated SAR update. DAWSON, D M General Electric Uranium Management Corp 83/05/13 CUNNINGHAM, R E Division of Fuel Cycle & Material Safety 2pp 18735 346

B306240484 Suggests withdrawal of rev to QA Plan NEDO-20776, for further editing before resubmission. Response by B30708 requested. ROBERTS, J P Advanced Fuel & Spent Fuel Licensing Branch 83/06/20 DAWSON, D M General Electric Co 1p 18978 067

NONDOCKETED ITEMS

10CFR COMMISSION MEETING RECORDS

8305110499 Board Notification 83-87 forwards info item re design verification program
EISENHUT, D G Division of Licensing 83/06/27 PALLADINO, N J,
QILINSKY, V, ROBERTS, T M Commissioners 2pp 19053 035 24X
Fiche 50-275, 83/06/27, 8305110499

--8306290470 Transcript of 830617 public meeting in Bethesda, MD re design verification program Pp 1-45
* Commissioners 83/06/17 48pp 24X Fiche 50-275, 83/06/27, 8305110499

8306020371 Transcript of Commission 830527 public briefing in Washington, DC re plant reliability data sys Pp 1-60
Supporting documentation encl
* Commissioners 83/05/27 116pp 18714 247

8306020700 Transcript of Commission 830527 discussion & possible vote in Washington, DC on full power OL Pp 1-83 Supporting documentation encl
* Commissioners 83/05/27 112pp 18717 046 24X
Fiche 50-370, 83/05/27, 8306020700

8306020709 Transcript of Commission 830526 meeting in Washington, DC, re emergency planning & preparedness Pp 1-117 Supporting documentation encl
* Commissioners 83/05/26 236pp 18716 001 24X
Fiche 50-247, 83/05/26, 8306020709

8306030157 Staff requirements memo informing of Commission 830513 briefing in Washington, DC on NUREG-1000, "Generic Implications of ATWS Events at Salem Nuclear Power Plant" Operating criteria requested
CHILK, S J Office of the Secretary of the Commission 830518
83/05/27 DIRCKS, W J Office of the Executive Director for Operations 1p 18733 313 24X Fiche 50-272, 83/05/27, 8306030157

8306030259 Staff requirements memo re 830527 discussion/possible vote in Washington, DC on full power OL authorization License amend to be modified re maint of circuit breakers Meeting requested w/breaker mfg
CHILK, S J Office of the Secretary of the Commission 830527A
83/05/27 DIRCKS, W J Office of the Executive Director for Operations 1p 18734 071 24X Fiche 50-370, 83/05/27, 8306030259

8306030499 Staff requirements memo re Commission 830527 briefing in Washington, DC on status of nuclear plant reliability data sys Staff responded to questions on status rept. per SECY-83-4
CHILK, S J Office of the Secretary of the Commission 830527B
83/05/27 Office of the Secretary of the Commission 1p.
18735 246

8306030501 Staff requirements memo re Commission 830523 briefing in Washington, DC on SECY-83-195, "Staff Comments on EPA Proposed Stds for U & Thorium Mill Tailings at Licensed Commercial Processing Site" Comment deadline is 830614
CHILK, S J Office of the Secretary of the Commission 830523B
83/05/27 Office of the Secretary of the Commission 1p.
18734 361

8306060369 Transcript of Commission 830531 affirmation/discussion & vote in Washington, DC re SECY-83-128 on renewal of Rockwell Intl Energy Sys Group SNM license Pp 1-2
* Commissioners 83/05/31 5pp 18748 349.

8306060389 Staff requirements memo re 830523 affirmation/discussion & vote in Washington, DC on SECY-83-117 review of ALAB-701 & 10CFR60, "Disposal of High Level Wastes in Geologic Repositories"
CHILK, S J Office of the Secretary of the Commission 830523C
83/05/27 DIRCKS, W J Office of the Executive Director for Operations PLAINE, H Office of the Executive Legal Director 2pp
18748 362

8306080331 Staff requirements memo re Commission 830524 briefing on NRC revalidation of mgt competence identified in insps on 830518 & 19
CHILK, S J Office of the Secretary of the Commission 830524A
83/06/02 DIRCKS, W J Office of the Executive Director for Operations 1p 18789 355 24X Fiche 50-320, 83/06/02, 8306080331

8306080439 Forwards Commission determination statement withholding transcript of 830224 meeting from public disclosure
CHILK, S J Office of the Secretary of the Commission 83/05/18
Public Document Branch 1p 18792 213 24X Fiche 50-322, 83/05/18, 8306080439

--8306080442 Commission determination statement withholding transcript of 830224 meeting from public disclosure
CHILK, S J Office of the Secretary of the Commission 83/05/18
Office of the Secretary of the Commission 1p 18792 214 24X
Fiche 50-322, 83/05/18, 8306080439.

8306130516 Staff requirements memo re 830331 affirmation/discussion & vote in Washington, DC re concerning renewal of Rockwell Intl SNM license
CHILK, S J Office of the Secretary of the Commission 830531C
83/06/03 PLAINE, H E Office of the General Counsel 1p
18830 270

8306150206 Staff requirements memo re 830526 oral presentations in Bethesda, MD re emergency planning & preparedness at Indian Point List of participants encl
CHILK, S J Office of the Secretary of the Commission 83/06/07
Office of the Secretary of the Commission 2pp. 18870 045 24X
Fiche 50-247, 83/06/07, 8306150206

8306150500 Transcript of 830609 Commission discussion & vote on emergency planning deficiencies at Indian Point in Washington, DC Pp 1-24
* Commissioners 83/06/09 30pp 18868:249 24X
Fiche 50-247, 83/06/09, 8306150500

8306160073 Addl response to FOIA request for documents re IAEA nuclear natl safeguards program. Forwards App A documents App B Documents 1-8 entirely withheld & Documents 9-16 partially withheld (w/ FOIA Exemptions 1, 3 & 5).
FELTON, J M Division of Rules and Records 83/04/01.
GREENBERG, E V Tuttle & Taylor 5pp. 18892 011

--8306160211 Forwards partially released transcript of 820602 briefing on efforts to improve IAEA safeguards in Washington, DC. Withheld portions per 10CFR9.104(a)(1) listed
CHILK, S J Office of the Secretary of the Commission 82/08/03.
Office of the Secretary of the Commission 2pp 18892:187

8306160673 Transcript of Commission 830610 meeting re discussion & possible vote on full-power OL in Washington, DC. Pp 1-90
Supporting documentation encl
* Commissioners 83/06/10 150pp 18884 045. 24X
Fiche: 50-389, 83/06/10, 8306160673

8306170450 Transcript of Commission 830615 briefing in Washington, DC re status of certification in THM-1 restart proceeding Pp 1-36 Supporting documentation encl
* Commissioners 83/06/15. 80pp 18906:234 24X
Fiche 50-289, 83/06/15, 8306170450

8306200016 Transcript of Commission 830615 briefing in Washington, DC re status of GA & soil settlement at facility Pp 1-64
Supporting documentation encl.
* Commissioners 83/06/15. 76pp 18909:238. 24X
Fiche 50-329, 83/06/15, 8306200016

NONDOCKETED ITEMS

8306200026 Staff requirements memo re 830610 discussion & possible vote in Washington, DC on full power OL Commission voted 5-0 to authorize full power operation License amend to be modified re post-trip procedures
CHILK, S J Office of the Secretary of the Commission M830610A
83/06/13 DIRCKS, W J Office of the Executive Director for Operations 1p 18908 355 24X Fiche 50-389, 83/06/13, 8306200026

8306200030 Staff requirements memo re 830609 discussion & vote in Washington, DC on continued operation of Indian Point Commission agreed by vote of 3-2 to allow continued operation
CHILK, S J Office of the Secretary of the Commission M830609B
83/06/14 Office of the Secretary of the Commission 1p
18908 356 24X Fiche 50-247, 83/06/14, 8306200030

8306240018 Transcript of Commission 830617 briefing on Indian Point labor issues in Washington, DC Pp 1-44
* Commissioners 83/06/17 47pp 18987 293 24X
Fiche 50-247, 83/06/17, 8306240018

8306290562 Transcript of Commission 830617 public meeting in Washington, DC re addl budgetary needs to fulfill requirements of Nuclear Waste Policy Act Pp 1-72
* Commissioners 83/06/17 76pp 19047 105

ACRS ADVISORY COMMITTEE ON REACTOR SAFEGUARDS

8306010002 Transcript of ACRS Subcommittee on Electrical Sys 830526 meeting in Washington, DC Pp 1-177 Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards 83/05/26 190pp 18664 001

8306010064 Transcript of ACRS Subcommittee on ECCS 830524 meeting in Denver, CO Pp 1-338
* ACRS - Advisory Committee on Reactor Safeguards 83/05/24 597pp 18666 167

8306010075 Transcript of ACRS Subcommittee on ATWS 830527 meeting in Washington, DC Pp 1-173
* ACRS - Advisory Committee on Reactor Safeguards 83/05/27 176pp 18668 044

8306010082 Transcript of ACRS Joint Subcommittee on Metal Components/Reactor Fuels 830527 meeting in Washington, DC Pp 219-366
* ACRS - Advisory Committee on Reactor Safeguards 83/05/27 151pp 18666 016

8306010199 Summaries ACRS 277th meeting on 830512-14 re SEP review of plant. Defers review of full-term OL application until NRC completes action on remaining SEP topics, unresolved safety issues & TMI action items.
EBERSOLE, J. C. ACRS - Advisory Committee on Reactor Safeguards 83/05/17 PALLADINO, J. Commissioners 3pp 18696 197 24X
Fiche 50-409, 83/05/17, 8306010199

8306020095 Discusses ACRS 277th meeting on 830512-14 re results of Phase II of SEP as applied to facility issue re protection against extreme external events requires resolution
EBERSOLE, J. C. ACRS - Advisory Committee on Reactor Safeguards 83/05/17 PALLADINO, N. J. Commissioners 3pp 18701 283 24X
Fiche 50-213, 83/05/17, 8306020095

8306020098 Discusses ACRS 277th meeting on 830512-14 re proposed final rules on immediate notification requirements (10CFR50.72) & LER sys (10CFR50.73) Implementation of rules would greatly improve current reporting requirements
EBERSOLE, J. C. ACRS - Advisory Committee on Reactor Safeguards 83/05/16 PALLADINO, N. J. Commissioners 2pp 18701 281

8306020386 Transcript of ACRS Subcommittee on ECCS 830525 meeting in Denver, CO Pp 337-600 Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards 83/05/25 422pp 18689.168

8306090003 Transcript of ACRS Subcommittee on Advanced Reactors 830607 in Washington, DC Pp 1-101 Supporting documentation
Advisory Committee on Reactor Safeguards 83/06/07 193 169

ript of ACRS Subcommittee on Qualification Program for Equipment 830607 meeting in Washington, DC
ting documentation encl
ory Committee on Reactor Safeguards 83/06/07 13

8306090011 Transcript of ACRS Subcommittee on Plant Features Important to Safety 830607 meeting in Washington, DC Pp 1-80 Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards 83/06/07 116pp 18793 001

8306100073 Transcript of ACRS Subcommittee on Regulatory Policy & Procedures 830608 meeting in Washington, DC Pp 1-81 Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards 83/06/08 89pp 18803 075

8306100076 Transcript of ACRS Subcommittee on Safety Research Program 830608 meeting in Washington, DC Pp 1-214 Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards 83/06/08 232pp 18803 171

8306130208 Transcript of ACRS 278th meeting on 830609 in Washington, DC Pp 1-255 Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards 83/06/09 466pp 18829 001

8306170322 Transcript of ACRS 278th general meeting on 830610 in Washington, DC Pp 256-349
* ACRS - Advisory Committee on Reactor Safeguards 83/06/10 73pp 18878 058

8306170438 Summary of ACRS Subcommittee on Catawba Nuclear Station 830304-05 meetings in Charlotte, NC re OL application review
* ACRS - Advisory Committee on Reactor Safeguards 83/05/11 ACRS - Advisory Committee on Reactor Safeguards 39pp 18908 017
24X Fiche 50-413, 83/05/11, 8306170438

8306200095 Minutes of ACRS Waste Mgt Subcommittee 830318 meeting in Washington, DC re DOE proposed general guidelines for recommendation of nuclear waste repository sites - 10CFR60 Proposed agenda, summary comments & attendance list encl
* ACRS - Advisory Committee on Reactor Safeguards 83/03/02 ACRS - Advisory Committee on Reactor Safeguards 25pp 18908 206

8306200096 Submits corrections to Low Level Waste Licensing Branch technical position paper re radwaste classification, to maintain scientific accuracy
ORTM, D. A. ACRS - Advisory Committee on Reactor Safeguards 83/05/18 TANG, R. C. ACRS - Advisory Committee on Reactor Safeguards 1p 18908 231

8306200119 Minutes of ACRS ECCS Subcommittee 830512 meeting in Washington, DC re proposed GE SAFER/GESTR ECCS licensing codes & status of other NRC licensing actions Schedules for completing Unresolved Safety Issues A-43 & A-1 encl
* ACRS - Advisory Committee on Reactor Safeguards 83/05/12 ACRS - Advisory Committee on Reactor Safeguards 29pp 18908 279

8306200153 Minutes of ACRS Subcommittee on SEP on Haddam Neck Nuclear Plant 830407 meeting in Washington, DC re integrated plant safety assessment Proposed agenda & attendance list encl
* ACRS - Advisory Committee on Reactor Safeguards 83/05/14 ACRS - Advisory Committee on Reactor Safeguards 14pp 18909 190
24X Fiche 50-213, 83/05/14, 8306200153

8306200163 Minutes of ACRS Joint Class 9 Accidents & Reactor Radiological Effects Subcommittee 830222 meeting in Washington, DC re severe accident source term program Attendance list & agenda encl
* ACRS - Advisory Committee on Reactor Safeguards 83/05/10 ACRS - Advisory Committee on Reactor Safeguards 22pp 18907 128

8306200168 Comments on NUREG-0963, Items 10.6.2.c & 10.6.2.d re waste mgt research program, in view of NRC request for clarification of ACRS recommendations per 830429 meeting Recommendations appropriate
FOSTER, R. F. Foster, R. F. ACRS - Advisory Committee on Reactor Safeguards 83/05/02 MOELLER, D. TANG, R. C. ACRS - Advisory Committee on Reactor Safeguards 2pp 18909 124

8306200440 Comments on Reliability & Probabilistic Assessment & Extreme External Phenomena Subcommittees 830413 meeting re Charleston earthquake & licensing implications
POMEROY, P. W. Roundout Associates POMEROY, P. W. ACRS - Advisory Committee on Reactor Safeguards 83/04/25 OKRENT, D. ACRS - Advisory Committee on Reactor Safeguards 2pp 18920 012

8306200444 Responds to P. Sheumon questions re cracks in BWR primary piping Meaningful NDE can be conducted if Weldcap designed correctly
BUSH, S. H. Battelle Memorial Institute, Pacific Northwest Laboratory BUSH, S. H. ACRS - Advisory Committee on Reactor Safeguards 83/04/29 IGNE, E. O. ACRS - Advisory Committee on Reactor Safeguards 3pp 18920 008

NONDOCKETED ITEMS

391

8306200443 Comments on IDCOR & NRC severe accident research program
IDCOR is worthwhile endeavor which should have positive &
long lasting results NRC programs lack strong centralized
mgt & prioritization structure
DAVIS, P R Affiliation Unknown DAVIS, P R ACRS - Advisory
Committee on Reactor Safeguards 83/05/02 KERR, W ACRS - Advisory
Committee on Reactor Safeguards 3pp 18920 005

8306210007 Transcript of ACRS Metal Components Subcommittee on
Pressurized Thermal Shock Research Program 830615 meeting in
Oak Ridge, TN Pp 1-199 Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards 83/06/15
300pp 18910 001

8306210398 Comments on Class 9 Subcommittee 830425-26 meetings Severe
accident research plan could be more useful to NRR if plan
focused on prioritization of research results already
gathered
CORRADINI, M Wisconsin, Univ of Madison CORRADINI, M ACRS -
Advisory Committee on Reactor Safeguards 83/05/04 WANG, A ACRS -
Advisory Committee on Reactor Safeguards 4pp 18935 285

8306210410 Comments on ACRS Subcommittee on Human Factors 830519
meeting Addl funds should be added to human factors research
budget for FY83
PEARSON, D North Carolina State Univ PEARSON, D ACRS - Advisory
Committee on Reactor Safeguards 83/05/20 WARD, D ACRS - Advisory
Committee on Reactor Safeguards 2pp 18937 070

8306210422 Comments on ACRS ECCS Subcommittee 830510 meeting in
Washington, DC Planned B&W integral sys may be inadequate to
achieve stated goals
CATTON, I ACRS - Advisory Committee on Reactor Safeguards
83/05/23 BOEHNERT, P ACRS - Advisory Committee on Reactor
Safeguards 3pp 18937 045

8306210442 Summary of joint ACRS Subcommittees on Metal Components &
Combination of Dynamic Loads 830329 meeting in Washington, DC
re reevaluation of double-ended guillotine pipe leak break
for Westinghouse PWR plants
* ACRS - Advisory Committee on Reactor Safeguards 83/05/18
ACRS - Advisory Committee on Reactor Safeguards 28pp 18936 239

8306210446 Expresses concern re combined legal & best estimate
approaches to SAFER/GESTER ECCB methodology Addl statistical
analysis required to justify calculated App K value
ZUDANS, Z Franklin Institute/Franklin Research Center ZUDANS, Z
ACRS - Advisory Committee on Reactor Safeguards 83/05/13
BOEHNERT, P A ACRS - Advisory Committee on Reactor Safeguards 1p
18935 354

8306210453 Comments on Class 9 Accidents Subcommittee 830425 & 26
meetings NUREG-0700 fails to answer how regulatory needs
for degraded core accidents could be met by severe accident
research plan
LEE, J C Michigan, Univ of LEE, J C ACRS - Advisory Committee on
Reactor Safeguards 83/05/05 WANG, A ACRS - Advisory Committee on
Reactor Safeguards 2pp 18935 338

8306220290 Comments on GE SAFER/GESTER evaluation model & NRC & GE
presentation at 830217-18 & 0510 subcommittee meetings ACRS
endorsement of evaluation model recommended
SCHROCK, V E California, Univ of Berkeley SCHROCK, V E ACRS -
Advisory Committee on Reactor Safeguards 83/05/17 WARD, D,
BOEHNERT, P ACRS - Advisory Committee on Reactor Safeguards 3pp
18940 347

ADVCM NRC ADVISORY COMMITTEE

8306060331 Transcript of Advisory Committee on Rights of Licensee
Employees Under Investigation 830526 hearing in
Washington, DC Pp 1-206
* Rights of Licensee Employees Under Investigation 83/05/26
207pp 18751 046

8306080092 Forwards charter for Advisory Committee for Review of
Ofc of Investigation Policy on Rights of Licensee Employees
Under Investigation
HOYLE, J C Office of the Secretary of the Commission 83/02/23
HOWTON, C National Archives & Records Service 3pp 18787 356

8306080093 Meeting agenda for Advisory Committee on Ofc of
Investigation Policy on Rights of Licensee Employees Under
Investigation 830526 meeting
* Rights of Licensee Employees Under Investigation 83/05/26
Rights of Licensee Employees Under Investigation 1p 18787 355

8306080095 Statement of P Shoop re grievance/arbitration procedures,
presented before Advisory Committee for Review of Ofc of
Investigation Policy on Rights of Employees Under
Investigation
SHOOP, P International Brotherhood of Electrical Workers 83/05/26
6pp 18787 339

8306080096 Charter for Advisory Committee for Review of Ofc of
Investigation Policy on Rights of Licensee Employees Under
Investigation
HOYLE, J C Rights of Licensee Employees Under Investigation
83/02/23 2pp 18787 337

8306080101 Ack receipt of 830217 ltr expressing interest in Advisory
Committee for Review of Ofc of Investigation Policy on
Rights of Licensee Employees Under Investigation Press
release naming members & charter encl
HOYLE, J C Office of the Secretary of the Commission 83/03/01
WETTERHAHN, M J Conner & Wetterhahn 4pp 18787 320

--8306080107 Expresses interest in new Advisory Committee for Review of
Ofc of Investigation Policy on Rights of Licensee Employees
Under Investigation Requests info re meetings & other
activities & membership
WETTERHAHN, M J Conner & Wetterhahn 83/02/17 HOYLE, J C
Rights of Licensee Employees Under Investigation 3pp 18787 324

8306080337 Forwards transcript of statement before Advisory Committee
on Ofc of Investigation Policy on Rights of Licensee
Employees Under Investigation on 830526 W/o encl.
LEVI, R P Rights of Licensee Employees Under Investigation
83/05/04 SHOOP, P Affiliation Unknown 1p 18787 361

8306080385 Submits comments responding to Commissioner Palladino 830411
ltr re Advisory Committee on Ofc of Investigation Policy on
Rights of Licensee Employees Under Investigation Grants of
confidentiality should be used sparingly
BURNS, J B Isham, Lincoln & Beale 83/06/03 SILBERT, E J
Schwalb, Donnenfeld, Bray & Silbert 7pp 18790 296

8306080429 Delegates authority as acting director of IE to JA
Fitzgerald
PALLADINO, N J Commissioners 82/07/16 FITZGERALD, J A
Director's Office, Office of Inspection and Enforcement 2pp
18792 186

8306090450 Requests clarification of 830511 FR notice re text of "Ofc
of Investigation Policy on Rights of Licensee Employees
Under Investigation" & statutory authority of policy
HOODAN, J P OA Technologies, Inc /General Atomic Co 83/05/20
LEVI, R P Office of the General Counsel 1p 18812 061

8306090501 Responds to 830501 ltr re establishment of advisory
committee on investigative procedures DDJ & NRC should
jointly review violations prior to adoption of mods to
investigative procedures
OLSEN, R M Justice, Dept of, Attorney General, Office of
83/05/20 SILBERT, E J Schwalb, Donnenfeld, Bray & Silbert 1p
18812 069

8306100006 Submits response to N Palladino 830411 ltr re rights of
employees under investigation Comments will be discussed at
830526 meeting NRC should recognize that public policy
favors liberal right to counsel for all interviewees
LITTELL, R Debevoise & Liberman 83/05/25 SILBERT, E J Schwalb,
Donnenfeld, Bray & Silbert 5pp 18815 314

8306130501 Responds to Advisory Committee on Ofc of Investigation
Policy on Rights of Licensee Employees Under Investigation
question re govt agencies advising witnesses about right to
counsel during informal interviews
LITTELL, R Debevoise & Liberman 83/06/03 SILBERT, E J Schwalb,
Donnenfeld, Bray & Silbert 2pp 18830 278

8306140229 Forwards transcript of Advisory Committee on Ofc of
Investigation Policy on Rights of Licensee Employees Under
Investigation 830413 meeting; committee charter &
questions for 830526 meeting
LEVI, R P Office of the General Counsel 83/04/29 DEVINE, T
Government Accountability Project 1p 18844 331

8306140270 Confirms commitment to appear at Advisory Committee on Ofc
of Investigation Policy on Rights of Licensee Employees
Under Investigation 830526 meeting W/o encl
LEVI, R P NRC - No Detailed Affiliation Given, 83/05/04 SHOOP, P
Affiliation Unknown 1p 18844 208

8306140329 Forwards corrected Page 143 to transcript of Advisory
Committee on Ofc of Investigation Policy on Rights of
Licensee Employees Under Investigation 830526 meeting
LEVI, R NRC - No Detailed Affiliation Given 83/06/07 MCKINIGHT, J.
Document Management Branch 1p 18854 118

NONDOCKETED ITEMS

--8306140337 Corrected Pages 143-144 to transcript of 830526 meeting of Advisory Committee on Dfc of Investigation Policy on Rights of Licensee Employees Under Investigation
* Rights of Licensee Employees Under Investigation 83/06/07
2pp 18854 119

8306140509 Submits info on effective establishment date & background info on Advisory Committee on Dfc of Investigation Policy on Rights of Licensee Employees Under Investigation
LEVI, R P Office of the General Counsel 83/02/28 SILBERT, E Schwalb, Donnenfeld, Bray & Silbert 9pp 18854 015

--8306140513 Submits info re creation of NRC advisory committee to obtain expert advice on rights of licensee employees under investigation Prompt reply assessing merit of committee requested
PALLADINO, N J Commissioners 83/01/10 CARMEN, O P General Services Administration 4pp 18854 024

--8306140517 Advises that QSA concurred in establishment of Advisory Committee for Review of Dfc of Investigation Policy on Rights of Licensee Employees Under Investigation
HOYLE, J C Rights of Licensee Employees Under Investigation 83/02/03 Rights of Licensee Employees Under Investigation 3pp 18854 028

--8306140521 Forwards charter for Advisory Committee for Review of Dfc of Investigation Policy on Rights of Licensee Employees Under Investigation
KAMMERER, C Office of Congressional Affairs 83/02/24, OTTINGER, R L House of Rep, Energy & Commerce 3pp 18854 031

8306140681 Requests Commission directly consult DOJ re mods to investigative & insp procedures Consultant svcs to E Silbert withdrawn Procedures inconsistent w/judicial authority
JENSEN, D L Justice, Dept of Attorney General, Office of 83/05/02 PALLADINO, N J Commissioners 2pp 18845 354

8306140726 Forwards MJ Wetterhahn 830217 ltr re Advisory Committee for Review of Dfc of Investigation Policy on Rights of Licensee Employees Under Investigation
LEVI, R P Office of the General Counsel 83/03/03 SILBERT, E J Schwalb, Donnenfeld, Bray & Silbert 1p 18845 351

--8306140734 Ack receipt of 830217 ltr expressing interest in Advisory Committee for Review of Dfc of Investigation Policy on Rights of Licensee Employees Under Investigation Ltr forwarded to EJ Silbert Press release naming members encl
HOYLE, J C Rights of Licensee Employees Under Investigation 83/03/01 WETTERHAHN, M J Conner & Wetterhahn 1p 18845 352

--8306140740 Expresses interest re nomination & selection procedure & matters associated w/formation & operation of Advisory Committee for Review of Dfc of Investigation Policy on Rights of Licensee Employees Under Investigation
WETTERHAHN, M J Conner & Wetterhahn 83/02/17 HOYLE, J C Rights of Licensee Employees Under Investigation 1p 18845 353

8306140756 Forwards response to 820520 request re Advisory Committee for Review of Dfc of Investigation Policy on Rights of Licensee Employees Under Investigation & statutory authority for adoption of propositions before Committee w/o encl
LEVI, R P NRC - No Detailed Affiliation Given 83/06/03 HOGAN, J P QA Technologies, Inc /General Atomic Co 1p 18845 338

8306140789 Notices of 830526 meeting of Advisory Committee on Dfc of Investigation Policy on Rights of Licensee Employees Under Investigation Recommendations of individuals to contact to appear before committee or submitting views requested
SILBERT, E J Schwalb, Donnenfeld, Bray & Silbert 83/05/03, FITZGERALD, J A Office of Investigation REARHAUSEN, O Debevoise & Plimpton SPRITZER, R B Pennsylvania, Univ of 2pp 18845 327

8306170310 Informs that Federal Aviation Administration does not generally advise witnesses of right to counsel, per 830526 meeting of Advisory Committee on Dfc of Investigation Policy on Rights of Licensee Employees Under Investigation
LEVI, R P Rights of Licensee Employees Under Investigation 83/06/03 Rights of Licensee Employees Under Investigation 1p 18908 016

8306170476 Forwards proposed form of "Advice to interviewees" for use by NRC investigators, per Advisory Committee on Dfc of Investigation Policy on Rights of Licensee Employees Under Investigation
CHARNOFF, O, Charnoff, O 83/06/03, SILBERT, E J Schwalb, Donnenfeld, Bray & Silbert 3pp 18974 329

8306200045 Forwards packet of matis describing reasons for creation of Advisory Committee on Dfc of Investigation Policy on Rights of Licensee Employees Under Investigation & formal charter Meeting on 830412 or 13 requested
SILBERT, E J Schwalb, Donnenfeld, Bray & Silbert 83/03/07 FITZGERALD, J A Office of Investigation REARHAUSEN, O Debevoise & Plimpton SCOTT, J B Kator, Scott & Heller 3pp 18909 066

--8212020236 "I&E Conflict or Cooperation," presented to 1982 AIF annual conference
CHARNOFF, O Affiliation Unknown 82/11/17 18pp 18909 069

--8306200048 Submits discussion items for Subcommittee on NRC Investigations 821020 meeting in Washington, DC Items include initiation of investigation, availability of counsel & debriefing employees post-NRC interview
CHARNOFF, O Charnoff, O 82/10/20 Office of Inspector & Auditor 3pp 18909 087

COMMISSION NRC COMMISSIONERS

8305240605 Responds to 830324 & 0411 ltrs re next generation of LWRs NRC has on going program w/EPRI in identifying unresolved generic safety issues which impact design of plant & could affect cost & const time
PALLADINO, N J Commissioners 83/05/09 AMORSI, A Argonne National Laboratory 1p 18716 356

--8305240612 Requests that 830324 ltr be made available to all Commissioners re study of LWRs Study would take advantage of worldwide experience w/LWRs, including EPRI evaluation, emphasizing basic changes in design
AMORSI, A Argonne National Laboratory 83/04/11 PALLADINO, N J Commissioners 1p 18716 357

--8305240624 Comments on development of next generation of LWRs for US & foreign use NRC & nuclear industry collaboration in defining safety criteria & evaluating safety improvements recommended
AMORSI, A Argonne National Laboratory 83/03/24 PALLADINO, N J Commissioners 3pp 18716 358

8306020229 Forwards answer to Subcommittee on Nuclear Regulation Question 7, in response to 830411 ltr on FY82-83 Authorization Act, Section 5 re current offsite emergency planning controversy
PALLADINO, N J Commissioners 83/05/09 OTTINGER, R L House of Rep 1p 18701 001 24X Fiche 50-322, 83/05/09, 8306020229

--8306020242 Forwards answer to Subcommittee on Nuclear Regulation Question 7, in response to 830411 ltr on FY82-83 Authorization Act, Section 5 re current offsite emergency planning controversy
PALLADINO, N J Commissioners 83/05/09 DOWNEY, T J House of Rep 6pp 18701 002 24X Fiche 50-322, 83/05/09, 8306020229

--8306020248 Emphasizes that NRC must not take undue liberties w/1982 Authorization Act, Section 5 re offsite emergency preparedness NRC cannot consider local govt plan developed by util if plan officially approved by local govt
DOWNEY, T J, OTTINGER, R L House of Rep 83/04/11 PALLADINO, N J Commissioners 3pp 18701 008 24X Fiche 50-322, 83/05/09, 8306020229

8306020710 Weekly info rept for wk ending 830520
REHM, T A Office of the Executive Director for Operations 83/05/23 45pp 18717 001

8306030156 Responds to 830506 request for clarification of 830503 order re consideration of views of public & parties to special proceeding in 830609 decision Comments from licensees, govt agencies & public invited
PALLADINO, N J Commissioners 83/05/12 OTTINGER, R L House of Rep, Energy & Commerce 2pp 18733 326 24X Fiche 50-247, 83/05/12, 8306030156

--8306030158 Requests Commission 830503 order be revised to stress need for parties to safety investigation views on shutdown Rev requested by 830311
OTTINGER, R L House of Rep, Energy & Commerce 83/05/06 PALLADINO, N J Commissioners 2pp 18733 328 24X Fiche 50-247, 83/05/12, 8306030156

8306030159 Discusses efforts to consolidate NRC activities in one location since TMI-2 accident
PALLADINO, N J Commissioners 83/05/10 HATFIELD, H D Senate Appropriations 2pp 18733 330,

NONDOCKETED ITEMS

383

8306030164 Submits status rept re Commission activities concerning allegations raised by GPU employees & former employees on mods to plant sys & components w/o proper review, tests & approval
PALLADINO, N J Commissioners 83/05/12 MINNICH, J Advisory Council for Decontamination of TMI Unit 2 1p 18733 332 24X Fiche 50-320, 83/05/12, 8306030164

8306030170 Designates WJ Dircks, Executive Director for Operations, as representative to fact finding panel on Facility per 830422 request
PALLADINO, N J Commissioners 83/05/10 CUOMO, M M New York, State of 2pp 18733 333 24X Fiche 50-322, 83/05/10, 8306030170

--8306030176 Requests assistance & participation in fact finding panel re scientific & economic issues surrounding debate on proposed nuclear power plant
CUOMO, M M New York, State of 83/04/22 Commissioners 1p 18733 334 24X Fiche 50-322, 83/05/10, 8306030170

8306030369 Forwards "NRC Eighth Annual Rept on Domestic Safeguards (U), for Oct 1981 - Sept 1982," in response to 740427 NSDM-254, "Domestic Safeguards" re safeguards sys established under NRC purview
PALLADINO, N J Commissioners 83/05/11 President of US & Executive Offices 1p 18734 333

--8306030371 "NRC Eighth Annual Rept on Domestic Safeguards (U), for Oct 1981 - Sept 1982"
* Commissioners 83/05/11 6pp 18714 247

--8306030375 Advises that "NRC Eighth Annual Rept on Domestic Safeguards (U), for Oct 1981 - Sept 1982" submitted to President Reagan Approval to discontinue annual safeguards rept submission requested since info duplicates annual rept
PALLADINO, N J Commissioners 83/05/11 CLARK, W P President of US & Executive Offices 1p 18734 360

8306040369 Responds to 830511 ltr, inviting Commission testimony at joint hearing on proposed amends to 10CFR110 re licensing of nuclear exports Commission testimony should be delayed until proposed mods reviewed & reexamined
PALLADINO, N J Commissioners 83/05/16 OTTINGER, R L House of Rep, Energy & Commerce 1p 18750 347

--8306060374 Responds to RL Ottinger 830511 ltr, inviting Commission testimony at joint hearing on proposed amends to 10CFR110 re licensing of nuclear exports Commission testimony should be delayed until proposed mods reviewed & reexamined
PALLADINO, N J Commissioners 83/05/16 DONKER, D House of Rep, Foreign Affairs 1p 18750 348

--8306060380 Notifies of 830525 joint hearing on prospective amends to 10CFR110 re licensing of nuclear exports Present status of proposed amends requested Commission invited to appear & testify at hearing Summary statements requested by 830520.
OTTINGER, R L House of Rep, Energy & Commerce 83/05/11 PALLADINO, N J Commissioners 3pp 18750 349

8306060388 Responds to 830407 ltr re ATWS events & reactor trip breaker malfunctions Language used in IE bulletins revised to ensure specific & general responses
PALLADINO, N J Commissioners 83/05/16 MARKEY, E J House of Rep, Interior & Insular Affairs 24pp 18752 349 24X Fiche 50-272, 83/05/16, 8306060388

--8306060392 Requests info re unreported breaker failures, reporting requirements & reliability of 25 cycle pre-startup testing to better understand LER sys
MARKEY, E J House of Rep, Interior & Insular Affairs 83/04/07 PALLADINO, N J Commissioners 2pp 18753 018 24X Fiche 50-272, 83/05/16, 8306060388

8306070426 Weekly info rept for wk ending 830527
REHM, T A Office of the Executive Director for Operations 83/06/03 43pp 18782 313

8306140501 Forwards response to 830425 request for clarification of allegations re illegal procedures & faulty welds at nuclear power plants.
DIRCKS, W J Office of the Executive Director for Operations 83/05/18 HATCH, D Q Senate, Labor & Human Resources 6pp 18834 049

--8306140505 Requests clarification of procedures responding to G Boring allegations re illegal procedures & faulty welds at nuclear power plants.
NEWMAN, D Senate, Labor & Human Resources 83/04/25 KAMMERER, C Office of Congressional Affairs 2pp 18854 035

8306150146 Weekly info rept for wk ending 830603
REHM, T A Office of the Executive Director for Operations 83/06/09 43pp 18872 048

8306150533 Responds to 830304 ltr requesting info & responses to questions re 830222 & 25 events Failures of safety sys & broader implications for nuclear power industry discussed
PALLADINO, N J Commissioners 83/06/02 BIDEN, J R Senate, 27pp 18866 334 24X Fiche 50-272, 83/06/02, 8306150533

--8306150543 Expresses concern re 830222 & 25 events when manual shutdown of reactor required Following failures of automatic safety sys Investigation by NRC requested prior to restart Questions encl for NRC response.
BIDEN, J R Senate 83/03/04 PALLADINO, N J Commissioners 3pp 18867 023 24X Fiche 50-272, 83/06/02, 8306150533

8306160093 Addl response to FOIA request for documents re IAEA nuclear mail safeguards program Forwards App A documents App B Documents 1-8 entirely withheld & Documents 9-16 partially withheld (ref FOIA Exemptions 1, 3 & 5)
FELTON, J M Division of Rules and Records 83/04/01 GREENBERG, E V Tuttle & Taylor 5pp 18892 011

--8306160118 Forwards undisputed portion of response to 811125 ltr re IAEA safeguards sys, supplementing Commission 820302 ltr
BRADFORD, P A Commissioners. 82/03/04 OTTINGER, R L House of Rep, Energy & Commerce HART, G Senate DINGELL, J D House of Rep 2pp 18892 042

8306170449 Forwards NRC rept on ADs at licensed nuclear facilities (NUREG-0090, Vol 3, Number 4), for Fourth Quarter CY82 W/o encl.
AHEARNE, J F Commissioners 83/06/02 O'NEILL, T P House of Rep BUSH, G H Senate 3pp 18907 322

--8306170451 Forwards FR notice & ltr forwarding AQ rept to Congress (NUREG-0090, Vol 3, Number 4), Medical misadministration event, discussed in BECY-83-92, upgraded to App C item W/o encl.
DIRCKS, W J Office of the Executive Director for Operations, 83/06/02 CHILK, S J Office of the Secretary of the Commission 1p 18907 325

8306220198 Forwards Vol 3, Number 4 to NUREG-0090, "Rept to Congress on ADs," for Fourth Quarter CY82 One AQ reported at NRC licensees re inoperability of containment spray sys Agreement states reported no ADs
AHEARNE, J F Commissioners. 83/06/02 O'NEILL, T P. House of Rep BUSH, G H W Senate 2pp 18940 024 24X Fiche 50-000, 83/06/02, 8306220198

--8306220264 Agrees w/830223 view that B&W/util litigation should be carefully reviewed Responses to Questions 2 through 3 raised in 830223 ltr encl
AHEARNE, J F Commissioners 83/06/01 UDALL, M K House of Rep., Interior & Insular Affairs 3pp 18940 107, 24X Fiche 50-000, 83/06/02, 8306220198

--8306220268 Discusses importance of carefully analyzing 830222 record of hearing on util/B&W litigation to determine whether record contains info bearing on questions of competence & character requirements of DL holder Questions per TMI-2 accident encl
UDALL, M K House of Rep, Interior & Insular Affairs 83/02/23 PALLADINO, N J Commissioners 2pp 18940 112 24X Fiche 50-000, 83/06/02, 8306220198

8306230221 Weekly info rept for wk ending 830610.
REHM, T A Office of the Executive Director for Operations 83/06/15 41pp. 18931 315

8306240328 Requests encl 830105 memo re IE investigation of Automation Industries be placed in PDR
MANNING, W J Commissioners 83/06/13 CHILK, S J Office of the Secretary of the Commission 1p 18999 191

--8306240330 Express outrage re IE investigation of Automation Industries Employees received overdose of thousands of rads, suffered extensive visible damage & reported injuries.
QILINSKY, V Commissioners 83/01/05 Commissioners 3pp, 18999 192

--8306240331 Discusses investigation of AD at Automation Industries. Serious violations & attempted coverups must be penalized swiftly & severely if NRC regulatory policies are to be respected.
HUTCHINS, G H NRC - No Detailed Affiliation Given. 81/07/14 QILINSKY, V. Commissioners 11pp. 18999 193

NONDOCKETED ITEMS

40333 Requests restoration of \$14,000,000 cut from NRC budget
 uss Deferral of work from FY83 plus FY84 cuts would
 stantially delay programs scheduled to resolve many
 nificant issues
 ERTS, T M Commissioners 83/06/13 HATFIELD, M O Senate
 ropriations 2pp 18999 207

40335 Forwards "Annual Rept for 1982 on Administration of Govt in
 shine Act of 1976 " W/o encl
 ERTS, T M Commissioners 83/06/13 BUSH, G H Senate 1p
 99 209

6240336 Forwards "Annual Rept for 1982 on Administration of Govt in
 unshine Act of 1976 "
 DBERTS, T M Commissioners 83/06/13 O'NEILL, T P House of
 ep 1p 18999 210

6240337 "Annual Rept for 1982 on Administration of Govt in Sunshine
 ct of 1976 "
 Commissioners 82/12/31 20pp 18999 211

80008 Submits monthly rept on status of offsite emergency
 paredness for OL reviews for May 1983
 CKS, W J Office of the Executive Director for Operations
 06/14 PALLADINO, N J Commissioners 6p 19046 098

ACT NRC CONTRACTS AND MODIFICATIONS

40657 Notification of contract execution "EIS Sys Drawings,"
 rded to TVA
 ES, E B Administrative Contracts Branch FIN B-8841 83/04/28
 ELSON, C Director's Office HEDDON, F NRC - No Detailed
 iliation Given 1p 18327 197

1190510 Executed Interagency Agreement NRC-ADH-83-441, "EIS Sys
 awings "
 ITIA, M J NRC - No Detailed Affiliation Given FIN B-8841
 IC-26-83-441 83/04/13 6pp 18327 198

10708 Notification of contract execution, Mod 2 to "Radionuclide
 ation Around U Ore Bodies - Analogue of Radwaste
 isitorias " Contractor Australian AEC
 .ETT, S Research Contracts Branch FIN B-6661 NRC-04-B1-172
 14/20 BATSON, W Office of Nuclear Regulatory Research,
 ictor BIRCHARD, G NRC - No Detailed Affiliation Given 1p
 11,311

1040713 Mod 2, increasing funds, to "Radionuclide Migration Around
 ore Bodies - Analogue of Radwaste Repositories "
 TGLIFF, W H Australia GUSTAVE, R P Research Contracts Branch
 IN B-6661 NRC-04-B1-172 83/04/20 1p 18351 310

0022 Notification of contract execution, Mod 3 to "Task Analysis
 Nuclear Power Plant Control Room Crews " Contractor
 ral Physics Corp
 HATCH, V Technical Assistance Contracts Branch FIN B-7491
 04-82-005 83/05/09, FOREHAND, W Office of Nuclear Regulatory
 arch, Director JENKINS, J NRC - No Detailed Affiliation Given
 18687 175

010077 Mod 3, extending period of performance to 830609, to "Task
 alysis of Nuclear Power Plant Control Room Crews "
 ITNEY, J W General Physics Corp GUSTAVE, R P Division of
 ntracts FIN B-7491, NRC-04-82-005 83/05/09 1p 18687 176

0117 Notification of contract execution, Mod 7 to "Fission Product
 port Analysis " Contractor Battelle Columbus Labs
 ETT, S Technical Assistance Contracts Branch FIN B-8992
 04-80-177 83/05/11 BATSON, W Office of Nuclear Regulatory
 arch, Director WALKER, T NRC - No Detailed Affiliation Given
 18686, 338

010129 Mod 7, adding Task B & providing funding, to "Fission Product
 nsport Analysis "
 KZ, F J Battelle Memorial Institute, Columbus Laboratories
 RTON, K V Division of Contracts FIN B-8992 NRC-04-80-177
 705/11, 4pp 18686 339

0327 Notification of contract execution, Mod 2 to "Technical &
 neering Support Svcs for Radio Communications " Contractor DOI
 AREN, T Administrative Contracts Branch NRC-10-83-352
 5/26 CORLEY, J Division of Facilities & Operations COHEN, S,
 ILLE, T NRC - No Detailed Affiliation Given 1p 18715 310

020329 Mod 2, increasing ceiling amount for FY83 & total amount
 ligated, to "Technical & Engineering Support Svcs for Radio
 mmunications "
 RCIVALL, R M Interior, Dept of HAGAN, T F Division of
 ntracts NRC-10-83-352 83/05/26 1p 18715 311

8306020333 Notification of contract execution, Mod 1 to "Technical &
 Engineering Support Svcs for Radio Communications " Contractor DOI
 MCLEAREN, T Administrative Contracts Branch NRC-10-83-352
 83/05/26 CORLEY, J Division of Facilities & Operations
 MELVILLE, T, COHEN, S NRC - No Detailed Affiliation Given 1p
 18715 312

--8306020336 Mod 1, defining statement of work deliverables required &
 eliminating requirement for issuance of task orders under
 agreement, to "Technical & Engineering Support Svcs for Radio
 Communications " Contractor DOI
 WILSON, J F Interior, Dept of HAGAN, T F Division of
 Contracts NRC-10-83-352 83/05/26 3pp 18715 313

8306020459 Notification of contract execution to "Radiation Monitoring
 Program Requirements " Contractor State of NE
 MCDERMOTT, D Technical Assistance Contracts Branch FIN B-8508
 NRC-31-83-670 83/05/16 MEYERS, D M Region 4, Office of Director
 NICHOLAS, J B NRC - No Detailed Affiliation Given 1p 18715 234

--8306020463 Contract "Radiation Monitoring Program Requirements,"
 awarded to State of NE
 SMITH, H D Nebraska, State of MORTON, K V Division of
 Contracts FIN B-8508 NRC-31-83-670 83/05/16 10pp
 18715 235

8306020480 Notification of contract execution, Mod 21 to "Local ECCS
 Support Studies " Contractor MPR Assoc, Inc
 WOLLETT, S Technical Assistance Contracts Branch FIN B-5537
 NRC-04-75-183 83/05/20 BATSON, W Office of Nuclear Regulatory
 Research, Director RHEE, O NRC - No Detailed Affiliation Given
 1p 18715 201

--8306020482 Mod 21, extending period of performance to 831105 &
 increasing funding, to "Local ECCS Support Sys "
 HANDIL, I H MPR Associates, Inc MORTON, K V Division of
 Contracts FIN B-5537 NRC-04-75-183 83/05/20 3pp
 18715 202

8306020506 Notification of contract execution, Mod 1 to "Licensing
 Assistance/Geotechnical & Hydrological Evaluation " Contractor EBASCO Svcs, Inc
 FIELDS, J A Technical Assistance Contracts Branch
 NRC-02-80-033-08 83/05/20 DAVIS, J Division of Safeguards
 GARCIA, P NRC - No Detailed Affiliation Given 1p 18715 146

--8306020513 Mod 1, extending period of performance to 830930, to
 "Licensing Assistance/Geotechnical & Hydrological
 Evaluation " Contractor EBASCO Services, Inc (subs of Enserch Corp)
 GUSTAVE, R P Division of Contracts NRC-02-80-033-08 83/05/20
 1p 18715 147

8306030048 Notification of contract execution "Orisance Review
 Examiner," awarded to BA Theeman
 HOYLE, A Administrative Contracts Branch NRC-10-83-360 83/05/17
 BIRD, P E Division of Organization and Personnel EDWARDS, R NRC
 - No Detailed Affiliation Given 1p 18733 191

--8306030054 Contract "Orisance Review Examiner" awarded to BA Theeman
 THEEMAN, B A Theeman, B A REBELLO, J E Division of Contracts
 NRC-10-83-360, 83/05/17 3pp 18733 192

8306030252 Notification of contract execution, Mod 16 to "Performance
 Testing for Personnel Dosimetry " Contractor Univ of
 Michigan
 WOLLETT, S Technical Assistance Contracts Branch FIN B-1049
 NRC-01-77-180 83/04/06 FOREHAND, W Office of Nuclear Regulatory
 Research, Director ROECKLEIN, R NRC - No Detailed Affiliation
 Given 1p 18734 065

--8306030256 Mod 16, extending period of performance through 830429,
 to "Performance Testing for Personnel Dosimetry "
 STEMPLE, P J Michigan, Univ of GUSTAVE, R P Division of
 Contracts FIN B-1049 NRC-01-77-180 83/04/06 1p 18734 066

8306030254 Corrected notification of contract execution, Mod 4 to
 "Canadian Seismic Agreement " Contractor Canadian
 Commercial Corp.
 WOLLETT, S Technical Assistance Contracts Branch FIN B-6275
 NRC-04-79-180 83/05/26 BATSON, W Office of Nuclear Regulatory
 Research, Director MURPHY NRC - No Detailed Affiliation Given
 1p 18734 070

8306030263 Notification of contract execution, Mod 2 to "Multiple Award
 Task Order Contract for ADP Development " Contractor Boeing
 Computer Svcs Co
 PERLMAN, J Administrative Contracts Branch FIN B-8166
 NRC-33-83-452 83/05/23 BASSETT, H S, HARVES, J Office of
 Resource Management, Director 1p 18734 072

NONDOCKETED ITEMS

395

- 8306030246 Mod 2, correcting subcontractor wage rate, to "Multiple Award Task Order Contract for ADP Development " HOPKINS, H R Boeing Computer Services, Inc (subs of Boeing Co) SMITH, P A Division of Contracts FIN B-8166 NRC-33-83-452 83/05/25 1p 18734 073
- 8306030268 Notification of contract execution, Mod 1 to "Electrostatic Copying & Related Svcs " Contractor Literature Research Co PERLMAN, J Administrative Contracts Branch NRC-10-83-318 83/05/19 BESAW, W J, BAGGETT, M Division of Technical Information & Document Control 1p 18734 074
- 8306030271 Mod 1, adding funds, to "Electrostatic Copying & Related Svcs " * Literature Research Corp SMITH, P A Division of Contracts NRC-10-83-318 83/05/19 1p 18734 075
- 8306030277 Notification of contract execution, Mod 1 to "Radiation Monitoring Program Requirements " Contractor State of AR MCDERMOTT, D Technical Assistance Contracts Branch FIN B-8500 NRC-31-83-667 83/05/20 MEYERS, D M Region 4, Office of Director NICHOLAS, J B NRC - No Detailed Affiliation Given 1p 18733 324
- 8306030284 Mod 1, increasing funding to FY83 levels, to "Radiation Monitoring Program Requirements " * Arkansas, State of MORTON, K V Division of Contracts FIN B-8500 NRC-31-83-667 83/05/20 1p 18733 325
- 8306030400 Notification of contract execution "Hypocenter Determination of Regional Earthquakes" awarded to Univ of KY MURPHY, L O Purchasing Section FIN B-9000 NRC-04-83-024 83/05/27 ARSENAULT, F J Division of Health, Siting & Waste Management MURPHY, A J NRC - No Detailed Affiliation Given 1p 18747 117
- 8306030402 Contract "Hypocenter Determination of Regional Earthquakes," awarded to Univ of KY McDONALD, J Y Kentucky, Univ of * Division of Contracts FIN B-9000 NRC-04-83-024 83/05/27 6pp 18747 118
- 8306060391 Notification of contract execution "11th Water Reactor Safety Research Info Meeting," awarded to SA Szaulewicz MCDERMOTT, D Technical Assistance Contracts Branch FIN B-8943 NRC-04-83-005 83/04/28 BASSETT, O E Division of Accident Evaluation SULLIVAN, H NRC - No Detailed Affiliation Given 1p 18750 293
- 8306060395 Contract "11th Water Reactor Safety Research Info Meeting," awarded to SA Szaulewicz SZAWLEWICZ, S A Szaulewicz, S A MORTON, K V Division of Contracts FIN B-8943 NRC-04-83-005 83/04/28 3pp 18750 294
- 8306060399 Solicits proposals for 11th water reactor research meeting Summary, instructions & solicitation package encl MORTON, K V Technical Assistance Contracts Branch RS-RE8-83-005 83/02/16 Affiliation Unknown 77pp 18750 257
- 8306070464 Notification of contract execution, Mod 4 to "Definition of Bounding Physical Tests Representative of Transport Accidents Air & Marine " Contractor IIT Research Inst WOLLETT, S Technical Assistance Contracts Branch FIN B-7570 NRC-04-81-203 83/05/18 FOREHAND, B, Office of Nuclear Regulatory Research, Director LAHS, W NRC - No Detailed Affiliation Given 1p 18780 333
- 8306070465 Mod 4, extending period of performance to 830921, to "Definition of Bounding Physical Tests Representative of Transport Accidents Air & Marine " FLOWERS, T R IIT Research Inst GUSTAVE, R P Division of Contracts FIN B-7570 NRC-04-81-203 83/05/18 1p 18780 334
- 8306080067 Notification of contract execution, Mod 2 to "Audit of NRC Supergrade Positions " Contractor Damans & Assoc SMITH, P A Division of Contracts NRC-10-77-140 83/06/02 BIRD, P E Division of Organization and Personnel 1p 18787 295
- 8306080072 Mod 2, finalizing final indirect rates & incorporating rates into contract per General Provisions Clause 34 & deobligating unliquidated balance, to "Audit of NRC Supergrade Positions," CASANAVE, M Damans & Associates SMITH, P A Division of Contracts NRC-10-77-140 83/06/02 2pp, 18787 296
- 8306080413 Notification of contract execution, Mod 2 to "Word Processing Svcs " Contractor Keyboard Communications, Inc MCLEAREN, T Administrative Contracts Branch NRC-10-83-296 83/06/01 STEELE, M Division of Technical Information & Document Control JOHANSEN, J Cross Branch 1p 18792, 182
- 8306080417 Mod 2, increasing funding ceiling, to "Word Processing Svcs " * Keyboard Communications, Inc SMITH, P A Division of Contracts NRC-10-83-296 83/06/01 1p 18792 183
- 8306080419 Notification of contract execution, Mod 20, to "FLECHT-SEASET " Contractor Westinghouse/EPRI WOLLETT, S Technical Assistance Contracts Branch FIN B-6204, NRC-04-77-127 83/05/24 BATSON, W Office of Nuclear Regulatory Research, Director LEE, R NRC - No Detailed Affiliation Given 1p 18792 184
- 8306080427 Ltr contract, Mod 20, changing ceiling amounts, to "FLECHT-SEASET " GUSTAVE, R P Technical Assistance Contracts Branch. FIN B-6204 NRC-04-77-127 83/05/19 ROSENBLATT, H Westinghouse Electric Corp 1p 18792 185
- 8306090277 Notification of contract execution, Mod 1 to "Oregg Shorthand Theory Review " Contractor Montgomery County, MD Public Schools SMITH, P A Division of Contracts NRC-10-79-665 83/05/09 DORRIS, W M Office of Administration VAN SANTEN, L NRC - No Detailed Affiliation Given 1p 18810, 047
- 8306090280 Mod 1, deobligating funds to enable final contract closeout, to "Oregg Shorthand Theory Review " PASCOE, S Maryland, State of SMITH, P A Division of Contracts NRC-10-79-665 83/05/09 1p 18810, 048
- 8306090282 Notification of contract execution, Mod 2 to "Records Holding Area Support Svcs," Contractor SBA Subcontractor Maxima Corp MCLEAREN, T Administrative Contracts Branch NRC-10-82-396 83/06/02 BESAW, W J Division of Technical Information & Document Control SCOTT, R S NRC - No Detailed Affiliation Given 1p 18810 032
- 8306090284 Mod 2, extending period of performance to 840613 & increasing funding, to "Records Holding Area Support Svcs " * Small Business Administration * Maxima Corp SMITH, P A Division of Contracts NRC-10-82-396 83/06/02 2pp 18810, 033.
- 8306090447 Notification of contract execution, Mod 1 to "Licensing Technical Assistance " Contractor Science Applications, Inc FLYNN, M J Technical Assistance Contracts Branch FIN B-7339-3, NRC-02-83-035 83/05/27 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director LOYSEN, P, NRC - No Detailed Affiliation Given 1p 18815, 145
- 8306090452 Mod 1, issuing fully definitized Task Order 004 & increasing funding to "Licensing Technical Assistance," FINDLEY, D E Science Applications, Inc. GUSTAVE, R P, Division of Contracts FIN B-7339-3, NRC-02-83-035 83/05/27 6pp 18815 146
- 8306090467 Notification of contract execution, Mod 16 to "Improved Ultrasonic NDT of Pressure Vessels " Contractor, Univ of MI FLYNN, M J Technical Assistance Contracts Branch NRC-04-75-182 83/05/25 FOREHAND, W Office of Nuclear Regulatory Research, Director MUSCARA, J NRC - No Detailed Affiliation Given 1p 18815 154
- 8306090470 Mod 16, changing period of performance to 830228 & adding paragraph to Article IV, to "Improved Ultrasonic NDT of Pressure Vessels " DALRYMPLE, J T Michigan, Univ of. GUSTAVE, R P, Technical Assistance Contracts Branch NRC-04-75-182 83/05/25 2pp, 18815, 155
- 8306090484 Notification of contract execution, Mod 5 to "Benchmarking of Computer Codes & Licensing Assistance " Contractor, Tektron Research, Inc. FLYNN, M J Technical Assistance Contracts Branch FIN B-6985, NRC-02-81-026 83/05/25 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director. FEHRINGER, D J NRC - No Detailed Affiliation Given. 1p. 18815, 159
- 8306090488 Mod 5, exercising option for performance of Tasks 4 & 5, providing incremental funding & substituting key personnel, to "Benchmarking of Computer Codes & Licensing Assistance," VOGT, D, K Tektron Research, Inc GUSTAVE, R P, Technical Assistance Contracts Branch FIN B-6985 NRC-02-81-026, 83/05/25 4pp 18815 160
- 8306140228 Notification of contract execution, "BWR Nuclear Engineering Courses," awarded to OE. MCDERMOTT, D Technical Assistance Contracts Branch FIN B-8710, NRC-05-83-217, 83/05/18 BLAHA, J L Program Support Branch. HAVENS, D H NRC - No Detailed Affiliation Given 1p, 18844 325

NONDOCKETED ITEMS

- 8306140238 Contract "BWR Nuclear Engineering Courses," awarded to GE
PIERCE, R C General Electric Co MORTON, K V Division of
Contracts FIN B-8710. NRC-05-B3-219 83/05/18 5pp
18844 326
- 8306140421 Notification of contract execution, Mod 9 to "Study of
Chemical Toxicity of Low Level Waste " Contractor General
Research Corp
SILVER, R M Technical Assistance Contracts Branch FIN B-6127
NRC-02-77-183 83/06/03 DAVIS, J G Office of Nuclear Material
Safety & Safeguards, Director JOHNSON, T NRC - No Detailed
Affiliation Given 1p 18854 062
- 8306140426 Mod 9, deobligating unliquidated balance, to "Study of
Chemical Toxicity of Low Level Waste "
ANDERSON, D J General Research Corp GUSTAVE, R P Division of
Contracts FIN B-6127 NRC-02-77-183 83/06/03 1p 18854 063
- 8306140433 Notification of contract execution, Mod 2 to "Reviewing
Hydrogeologic Investigations of Nevada Test Site - Project
C " Contractor Williams-Robinette & Assoc, Inc
SILVER, R M. Technical Assistance Contracts Branch FIN B-7377-2
NRC-02-82-446 83/06/03 DAVIS, J G Office of Nuclear Material
Safety & Safeguards, Director. POHLE, J A NRC - No Detailed
Affiliation Given 1p 18854 064
- 8306140438 Mod 2, adjusting consulting hours of svc. to "Reviewing
Hydrogeologic Investigations of Nevada Test Site - Project
C."
WILLIAMS, R E. Williams-Robinette & Associates, Inc GUSTAVE, R P
Division of Contracts. FIN B-7377-2 NRC-02-82-046 83/06/03
1p 18854 045
- 8306150246 Notification of grant execution "Criteria & Procedures for
Low Level Radwaste Mgt." awarded to Conference of Radiation
Control Program Directors, Inc.
MCDERMOTT, D. Technical Assistance Contracts Branch FIN Q-1049
NRC-Q-04-B3-003 83/06/07 BATSON, W Office of Nuclear Regulatory
Research, Director. KIM, K NRC - No Detailed Affiliation Given
1p 18870 047
- 8306150251 Grant "Criteria & Procedures for Low Level Radwaste Mgt.,"
awarded to Conference of Radiation Control Program
Directors, Inc.
SHEALY, M O Conference of Radiation Control Program Directors,
Inc MORTON, K V. Technical Assistance Contracts Branch FIN
Q-1049 NRC-Q-04-B3-003 83/06/07 2pp. 18870 048.
- 8306150485 Notification of contract execution "Radiation Monitoring
Program Requirements," awarded to State of LA
MCDERMOTT, D. Technical Assistance Contracts Branch FIN B-8902
NRC-31-B3-669 83/06/01. MEYERS, D M Region 4, Office of Director
NICHOLAS, J B NRC - No Detailed Affiliation Given 1p 18868 001
- 8306150488 Contract: "Radiation Monitoring Program Requirements,"
awarded to State of LA
SIBONEAUX, F P. Louisiana, State of MORTON, K V Administrative
Contracts Branch FIN B-8902 NRC-31-B3-669. 83/06/01 18pp
18868 002
- 8306150506 Notification of contract execution "Investigation of
Alternative Means to Accomplish Goals of Biennial Calibr
of Ionization Chambers," awarded to Univ of WI
MCDERMOTT, D K Technical Assistance Contracts Branch FIN B-8906
NRC-04-B3-002 83/06/01. BATSON, W Office of Nuclear Regulatory
Research, Director. RODENBECK, E. NRC - No Detailed Affiliation
Given. 1p. 18866.295.
- 8306150521 Contract "Investigation of Alternative Means to Accomplish
Goals of Biennial Calibr of Ionization Chambers,"
awarded to Univ of WI
ERICKSON, R W Wisconsin, Univ. of, Madison MORTON, K V. Division
of Contracts FIN B-8906 NRC-04-B3-002 83/06/01 17pp
18866.296
- 8306150560 Notification of contract execution, Mod 10 to "Site
Suitability Assessments Based on Seepage & Groundwater
Conditions Associated w/U Recovery Operations " Contractor
Williams Robinette & Assoc.
DELOATCH, V. Technical Assistance Contracts Branch. NRC-02-B1-039
83/06/03. DAVIS, J. G. Office of Nuclear Material Safety &
Safeguards, Director SIEFKEN NRC - No Detailed Affiliation Given
1p. 18854.360.
- 8306150570 Mod 10, modifying period of performance, to "Site Suitability
Assessments Based on Seepage & Groundwater Conditions
Associated w/U Recovery Operations "
WILLIAMS, R E. Williams-Robinette & Associates, Inc GUSTAVE, R P
Administrative Contracts Branch. NRC-02-B1-039 83/06/03 1p
18854:361
- 8306160040 Notification of contract execution, Mod 4 to "Followon
Earthquake Ground Motion " Contractor Univ of California at
San Diego
MURPHY, L G Administrative Contracts Branch FIN B-6898
NRC-03-B0-143 83/06/06 VOLLMER, R Division of Engineering
JACKSON, R NRC - No Detailed Affiliation Given 1p 18892 336
- 8306160045 Mod 4, deleting reporting requirements, to "Followon
Earthquake Ground Motion "
* California, Univ. of, San Diego REBELLO, J Division of
Contracts FIN B-6898 NRC-03-B0-143 83/06/06 1p 18892 337
- 8306160239 Notification of contract execution, Mod 9 to "Memphis Area
Regional Seismic Network " Contractor Memphis State Univ.
FIELDS, J A Technical Assistance Contracts Branch NRC-04-78-200
83/05/27 BATSON, W Office of Nuclear Regulatory Research,
Director JOHNSON, A C NRC - No Detailed Affiliation Given 1p
18893 020
- 8306160273 Mod 9, incorporating App A to modify govt property, to
"Memphis Area Regional Seismic Network "
CARPENTER, T G Memphis State Univ GUSTAVE, R P Division of
Contracts. NRC-04-78-200 83/05/27 4pp 18893 021
- 8306170026 Notification of contract execution "A/E Design Svcs for
Installation of Shielded Encl," awarded to EK Fox & Assoc,
Ltd
BAZIN, J P Administrative Contracts Branch NRC-10-B3-334
83/04/08 CORLEY, J H Division of Facilities & Operations
FISHER, L NRC - No Detailed Affiliation Given 1p 18907 349
- 8306170029 Contract "A/E Design Svcs for Installation of Shielded
Encl," awarded to EK Fox & Assoc, Ltd
FOX, E K E K Fox & Associates, Ltd MATTIA, M J Division of
Contracts NRC-10-B3-334 83/04/08 9pp 18907 350
- 8306170253 Notification of contract execution, Mod 5 to "Licensing
Assistance/Tailings Mgt Program Technical Evaluation "
Contractor-Geotechnical Engineers, Inc
FIELDS, J A Research Contracts Branch NRC-02-79-031-01 83/05/27
DAVIS, J Office of Nuclear Material Safety & Safeguards, Director
ROSSBACH, L NRC - No Detailed Affiliation Given 1p 18908 014
- 8306170259 Mod 5, extending period of performance to 830930 at no
add cost, to "Licensing Assistance/Tailings Mgt Program
Technical Evaluation "
CASTRO, Q Geotechnical Engineers, Inc GUSTAVE Administrative
Contracts Branch NRC-02-79-031-01 83/05/27 1p 18908 015
- 8306170463 Notification of contract execution, Mod 6 to "Career
Counseling " Contractor Binder, Elster, Mendelson & Wheeler
PERLMAN, J Administrative Contracts Branch NRC-10-B2-350
83/06/15 DORIE, W Office of Administration VAN SANTEN, L W NRC
- No Detailed Affiliation Given 1p 18906 349
- 8306170466 Mod 6, allowing for quarterly payments for regional
liaison svcs, to "Career Counseling "
MENDELSON, I N Binder, Elster, Mendelson & Wheeler, Inc
SMITH, P A Administrative Contracts Branch NRC-10-B2-350
83/06/15 1p 18906 350
- 8306170480 Notification of contract execution, Mod 1 to "Environ
Assessments & Impact Statements for Low Level Waste Disposal
Facilities " Contractor Battelle Columbus Labs
FLEENOR, C Technical Assistance Contracts Branch NRC-02-B2-026-10
83/05/27 DAVIS, J Office of Nuclear Material Safety &
Safeguards, Director. NEUDER, S M NRC - No Detailed Affiliation
Given 1p 18874 317
- 8306170482 Mod 1, extending period of agreement to 850930, incorporating
microfiche requirements & project officer, to "Environ
Assessment & Impact Statements for Low Level Waste
Disposal Facilities "
LUKZ, F J Battelle Memorial Institute, Columbus Laboratories
GUSTAVE, R P Administrative Contracts Branch NRC-02-B2-026-10
83/05/27 3pp 18894 318
- 8306170484 Notification of contract execution, Mod 3 to "Environ
Assessments & Impact Statements for Low Level Waste
Disposal Facilities." Contractor Versar, Inc
FLEENOR, C. Technical Assistance Contracts Branch NRC-02-B2-026-04
83/06/03 DAVIS, J Office of Nuclear Material Safety &
Safeguards, Director. NEUDER, S M NRC - No Detailed Affiliation
Given 2pp. 18894 305
- 8306170485 Mod 3, extending period of agreement to 850930 &
incorporating project officer, to "Environ Assessments &
Impact Statements for Low Level Waste Disposal Facilities,"
ROGERS, W H Versar, Inc GUSTAVE, R P Administrative Contracts
Branch NRC-02-B2-026-04 83/06/03 1p 18894 306

NONDOCKETED ITEMS

397

830620012B Notification of contract execution, Mod 2 to "Audiovisual Consultant Svcs " Contractor N Hall
PERLMAN, J Administrative Contracts Branch FIN B-8181
NRC-17-83-398 83/06/07 CHILK, S , MAGEE, W Office of the
Secretary of the Commission 1p 18908 268

--8306200134 Mod 2, extending period of performance to 830930, to
"Audiovisual Consultant Svcs "
HALL, N M Hall, N SMITH, P A Division of Contracts FIN
B-8181 NRC-17-83-398 83/06/07 1p 18908 269

8306200224 Notification of contract execution, Mod 6 to "Statistical Analysis Study " Contractor S Wolfbein
GILDENHORN, A Administrative Contracts Branch NRC-10-80-694
83/06/06 DORIE, W Office of Administration DAMBLEY, D Office of
the Executive Legal Director 1p 18909 355

--8306200289 Mod 6, extending period of performance to 840601 at no addl
cost, to "Statistical Analysis Study "
WOLFBEIN, S L Wolfbein, S L SMITH, P A Division of Contracts
NRC-10-80-694 83/06/06 1p 18909 356

8306210339 Notification of contract execution, Mod 11 to "Evaluation of
Matl Accounting Performance at Nuclear Fuel Cycle
Facilities " Contractor NUSAC, Inc
FIELD, J A Technical Assistance Contracts Branch NRC-02-81-028
83/06/03 DAVIS, J Office of Nuclear Material Safety &
Safeguards, Director MILLER, M NRC - No Detailed Affiliation Given
1p 18921 332

--8306210344 Mod 11, correcting Mod 8 numbering to Mod 10, to "Evaluation
of Matl Accounting Performance at Nuclear Fuel Cycle
Facilities "
* NUSAC, Inc GUSTAVE, R P Division of Contracts,
NRC-02-81-028 83/06/03 1p 18921 333

8306210364 Notification of contract execution, Mod 5 to "Personnel
Neutron Dosimetry for Nuclear Power Plants " Contractor
Rensselaer Polytechnic Inst
SILVIG, R M Technical Assistance Contracts Branch FIN B-6651
NRC-04-78-263 83/03/31, FOREHAND, W Office of Nuclear Regulatory
Research, Director FOULKE, J NRC - No Detailed Affiliation Given
1p 18937 094

--8306210371 Mod 5, extending period of performance to 830228, to
"Personnel Dosimetry for Nuclear Power Plants "
LOOUDICE, J M Rensselaer Polytechnic Inst GUSTAVE, R P
Division of Contracts FIN B-6651 NRC-04-78-263 83/03/31
2pp 18937 095

8306210370 Notification of contract execution, Mod 4 to "Licensing
Assistance/Geotechnical & Hydrological Evaluations "
Contractor Intl Engineering Co
FIELD, J A Technical Assistance Contracts Branch
NRC-02-80-033-04 83/06/03 DAVIS, J Office of Nuclear Material
Safety & Safeguards, Director GARCIA, P NRC - No Detailed
Affiliation Given 1p 18937 086

--8306210375 Mod 4, extending period of performance to 830930, to
"Licensing Assistance/Geotechnical & Hydrological
Evaluations "
CHRISTENSEN, R International Generation & Transmission Co, Inc
GUSTAVE, R P Division of Contracts NRC-02-80-033-04 83/06/03
1p 18937 087

8306210376 Notification of contract execution, Mod 1 to "Advisory
Committee for Const During Adjudication " Contractor Berle,
Buttel, Kass & Case
SMITH, P A Division of Contracts FIN B-1560 NRC-17-79-701
83/06/16 HOYLE, J C Office of the Secretary of the Commission
BERSON, B NRC - No Detailed Affiliation Given 1p 18937 088

--8306210384 Mod 1, deobligating funds for closeout, to "Advisory
Committee for Const During Adjudication "
* Berle, Buttel, Kass & Case SMITH, P A Division of Contracts
FIN B-1560 NRC-17-79-701 83/06/16 1p 18937 089

8306210381 Notification of contract execution, Mod 2 to "Licensing
Assistance/Tailings Mgt Program Technical Evaluation "
Contractor Simons, Li & Assoc, Inc
FIELD, J A Technical Assistance Contracts Branch
NRC-02-79-031-06 83/03/27 DAVIS, J Office of Nuclear Material
Safety & Safeguards, Director GILDEN, D NRC - No Detailed
Affiliation Given 1p 18937 082

--8306210386 Mod 2, extending period of performance to 830930, to
"Licensing Assistance/Tailings Mgt Program Technical
Evaluation "
SIMONS, D B Simons, Li & Associates, Inc. GUSTAVE, R. P. Division
of Contracts NRC-02-79-031-06, 83/03/27 1p 18937 083.

8306210391 Notification of contract execution, Mod 1 to "Lab Studies
Dynamic Response of Prototypical Piping Sys " Contractor
Anco Engineers, Inc & EPRI
BAIDEN, L Technical Assistance Contracts Branch FIN B-8907
NRC-04-82-025 83/06/10 FOREHAND, W Office of Nuclear Regulatory
Research, Director O'BRIEN, J NRC - No Detailed Affiliation Given
1p 18935 289

--8306210397 Ltr Contract Mod 1 to NRC-04-82-025, increasing funds, to
"Lab Studies Dynamic Response of Prototypical Piping Sys "
MORTON, K V Technical Assistance Contracts Branch FIN B-8907
NRC-04-82-025 83/06/10 HOWARD, G E ANCO Engineers, Inc 1p.
18935 290

8306210421 Notification of contract execution "Radiation Monitoring
Program Requirements," awarded to Environ Surveillance Lab
MCDERMOTT, D Technical Assistance Contracts Branch FIN B-8550
NRC-32-83-681 83/06/16 ALEXANDER, I Division of Resource
Management & Administration. HAMADA, G NRC - No Detailed
Affiliation Given 1p. 18937 048

--8306210432 Contract "Radiation Monitoring Program Requirements,"
awarded to Environ Surveillance Lab
TEDFORD, C F Environmental Surveillance Laboratory. MORTON, K V.
Division of Contracts. FIN B-8850 NRC-32-83-681 83/06/16
16pp 18937 049

8306220073 Notification of contract execution "Autoprint F Microfiche
Printer," awarded to Dybell/Ware & Assoc, Inc
COLEMAN, R Administrative Contracts Branch NRC-10-83-340
83/06/02 BESA, W Division of Technical Information & Document
Control 8KDC2LAB, J NRC - No Detailed Affiliation Given 1p
18947 311

--8306220091 Solicitation, offer & award of "Autoprint F Microfiche
Printer" to Dybell/Ware & Assoc, Inc
WARE, J T Dybell/Ware & Associates, Inc MATTIA, M J Division of
Accounting & Finance NRC-10-83-340 83/06/02 59pp 18947 312

8306220133 Notification of contract execution, Mod 7 to "Computer
Time-Sharing & Related Svcs," Contractor NIH.
PERLMAN, J Administrative Contracts Branch FIN B-1666.
NRC-25-82-312 83/06/06 BASSETT, H B , KIRK, I., BANDINI, B. Office
of Resource Management, Director 1p 18948 087

--8306220138 Mod 7, designating JA Shields as project officer, to "Computer
Time-Sharing & Related Svcs "
* HHS, Dept. of, US Public Health Service SMITH, P A Division
of Contracts. FIN B-1666 NRC-25-82-312 83/06/06, 1p.
18948 088

8306220151 Notification of contract execution, Mod 7 to "Licensing
Review of OL Applications." Contractor, Naval Surface Weapons
Ctr
SILVIG, R M Technical Assistance Contracts Branch. FIN B-6878
NRC-03-80-109, 83/06/10. VOLLMER, R Division of Engineering
RINALDI, F NRC - No Detailed Affiliation Given 1p 18937 339.

--8306220158 Mod 7, extending period of performance to 830930, modifying
statement of work & obligating addl funds, to "Licensing
Review of OL Applications "
ROBERTS, E. S Navy, Dept of. GUSTAVE, R. P. Technical Assistance
Contracts Branch FIN B-6878 NRC-03-80-109, 83/06/10 2pp.
18937 340

8306220166 Notification of contract execution "Radiation Monitoring
Program Requirements," awarded to State of MD
MCDERMOTT, D. Technical Assistance Contracts Branch FIN B-8353.
NRC-28-83-608 83/06/16 MCBOCAR, J. Region 1, Office of Director
COSTELLO, F. NRC - No Detailed Affiliation Given 1p 18937 305.

--8306220168 Contract, "Radiation Monitoring Program Requirements,"
awarded to State of MD.
RESH, D L Maryland, State of * NRC - No Detailed Affiliation
Given FIN B-8353, NRC-28-83-608 83/06/16, 13pp. 18937 306.

8306220186 Notification of contract execution, Mod 26 to "Review &
Evaluation of Approx 500 Pending Operating Reactors
Licensing Actions " Contractor, Franklin Inst.
FLYNN, M Technical Assistance Contracts Branch. FIN B-6590.
NRC-03-79-118 83/06/15, EISENHUT, D G., BAJWA, S. Division of
Licensing 1p 18951 045.

--8306220192 Mod 26, extending period of performance for 30 days at no
addl cost & deobligating funds from residual fee, to "Review
& Evaluation of Approx 500 Pending Operating Reactors
Licensing Actions "
ASHTON, A. M, Franklin Institute/Franklin Research Center
GUSTAVE, R. P. Division of Contracts. FIN B-6590, NRC-03-79-118
83/06/15, 3pp. 18951 046

NONDOCKETED ITEMS

- 8306220217 Notification of contract execution, Mod 6 to "Eastern Tennessee/Western North Carolina Regional Seismic Network " Contractor Memphis State Univ
STLVIS, R M Technical Assistance Contracts Branch FIN B-6675
NRC-04-79-214 83/09/31 BATSON, W Office of Nuclear Regulatory Research, Director MURPHY, A NRC - No Detailed Affiliation Given
ip 18950 359
- 8306220222 Mod 6, vesting title to property in NRC, to "Eastern Tennessee/Western North Carolina Regional Seismic Network " * Tennessee, State of GUSTAVE, R P Technical Assistance Contracts Branch FIN B-6675 NRC-04-79-214 83/05/31 2pp
18950 360
- 8306220220 Notification of contract execution, Mod 3 to "Environ Assessments & EIS for Low Level Waste Disposal Facilities " Contractor Engineering-Science, Inc
FLEENOR, C Technical Assistance Contracts Branch NRC-02-82-026-08 83/06/10 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director NEUDER, S NRC - No Detailed Affiliation Given
ip 18950 355
- 8306220227 Mod 3, extending period of performance to 850930 & incorporating new project officer, to "Environ Assessments & EIS for Low Level Waste Disposal Facilities " TISCHLER, L F Engineering Science GUSTAVE, R P Division of Contracts NRC-02-82-026-08 83/06/10 ip 18950 356
- 8306220229 Notification of contract execution, Mod 8 to "Fuel Cycle Project Review " Contractor Science Applications, Inc
WOLLETT, B Technical Assistance Contracts Branch FIN B-6694
NRC-04-80-178 83/06/10 FOREHAND, W Office of Nuclear Regulatory Research, Director ENG, C NRC - No Detailed Affiliation Given
ip 18977 353
- 8306220233 Mod 8, extending period of performance to 830530, to "Fuel Cycle Project Review " FELDMAN, S A Science Applications, Inc GUSTAVE, R P Division of Contracts FIN B-6694 NRC-04-80-178 83/06/10 ip 18977 354
- 8306220238 Notification of contract execution, Mod 2 to "Licensing Assistance/Tailings Mgt Program Technical Evaluation " Contractor Energy Resources Co
FIELDS, J A Technical Assistance Contracts Branch NRC-02-79-031-07 83/06/15 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director GILLEN, D NRC - No Detailed Affiliation Given ip 18977 032
- 8306220241 Mod 2, extending period of performance to 830930, to "Licensing Assistance/Tailings Mgt Program Technical Evaluation " * Energy Resources Co., Inc. GUSTAVE, R P Division of Contracts NRC-02-79-031-07 83/06/15 ip 18977 033
- 8306220244 Notification of contract execution, Mod 1 to "California Offshore Radiological Licensee Survey " Contractor State of CA
HOYLE, A Administrative Contracts Branch FIN B-8705
NRC-05-82-254 83/06/10 BLAHA, J L Program Support Branch YACKO, G T NRC - No Detailed Affiliation Given ip 18951 114
- 8306220246 Mod 1, extending period of performance to 830630, to "California Offshore Radiological Licensee Survey " * California, State of REBELLO, J E Division of Contracts FIN B-8705 NRC-05-82-254 83/06/10 ip 18951 115
- 8306220249 Notification of contract execution, Mod 3 to "Environ Assessments & EIS for Low Level Waste Disposal Facilities," Contractor Kaman Tempo
FLEENOR, C Technical Assistance Contracts Branch NRC-02-82-026-05 83/06/10 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director NEUDER, S NRC - No Detailed Affiliation Given
ip 18951 071
- 8306220255 Mod 3, extending period of performance to 850930 & incorporating new project officer, to "Environ Assessments & EIS for Low Level Waste Disposal Facilities " FOXWELL, D Q Kaman Tempo GUSTAVE, R P Division of Contracts NRC-02-82-026-05 83/06/10 ip 18951 072
- 8306220253 Notification of contract execution, Mod 2 to "Reviewing Hydrologic Investigations of Basalt Waste Isolation " Contractor Williams-Robinette & Assoc
FLEENOR, C Technical Assistance Contracts Branch NRC-02-82-044 83/06/03 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director LOGBDON, M NRC - No Detailed Affiliation Given ip 18951 066
- 8306220259 Mod 2, revising indirect rates & designating new project officer, to "Reviewing Hydrologic Investigations of Basalt Waste Isolation " WILLIAMS, R. Williams-Robinette & Associates, Inc GUSTAVE, R P Division of Contracts NRC-02-82-044. 83/06/03, 2pp 18951 067
- 8306220267 Notification of contract execution, Mod 3 to "Environ Assessments & EIS for Low Level Waste Disposal Facilities " Contractor EnviroSphere Co
FLEENOR, C Technical Assistance Contracts Branch NRC-02-82-026-09 83/06/10 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director NEUDER, S NRC - No Detailed Affiliation Given
ip 18951 052
- 8306220266 Mod 3, extending period of performance to 850930 & incorporating new project officer, to "Environ Assessments & EIS for Low Level Waste Disposal Facilities " O'DONNELL, E P EnviroSphere Co GUSTAVE, R P Division of Contracts NRC-02-82-026-09 83/06/10 ip 18951 053
- 8306220267 Notification of contract execution, Mod 13 to "Transport/Fixed Site Vulnerability Analysis " Contractor US Army JF Kennedy Ctr
FIELDS, J A Technical Assistance Contracts Branch NRC-02-76-311 83/06/03 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director CANLEY, J NRC - No Detailed Affiliation Given
ip 18951 050
- 8306220272 Mod 13, extending period of performance to 831231, to "Transport/Fixed Site Vulnerability Analysis " WEBB, D Army, Dept of GUSTAVE, R P Division of Contracts NRC-02-76-311 83/06/03 ip 18951 051
- 8306220269 Notification of contract execution, Mod 3 to "Environ Assessment & EIS for Low Level Waste Disposal Facilities " Contractor Science Applications, Inc
FLEENOR, C Technical Assistance Contracts Branch NRC-02-82-026-07 83/06/10 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director NEUDER, S NRC - No Detailed Affiliation Given
ip 18977 165
- 8306220276 Mod 3, extending period of performance to 850930 & incorporating new project officer, to "Environ Assessments & EIS for Low Level Waste Disposal Facilities " PASQUA, M P Science Applications, Inc GUSTAVE, R P Division of Contracts NRC-02-82-026-07 83/06/10 ip 18977 166
- 8306220277 Notification of contract execution, Mod 4 to "Demographic Projections & Regional Economic Impacts of Accidents " Contractor Dept of Commerce
FIELDS, J A Technical Assistance Contracts Branch FIN B-8044
NRC-03-82-112 83/06/06 VOLLMER, R H Division of Engineering SINSALLI, A NRC - No Detailed Affiliation Given ip 18940 356
- 8306220282 Mod 4, revising reporting requirements, extending period of performance to 830930 & modifying funding, to "Demographic Projections & Regional Economic Impacts of Accidents " Draft monthly business ltr rept encl
TROTTE, E Commerce, Dept of, GUSTAVE, R P Division of Contracts FIN B-8044 NRC-03-82-112 83/06/06 4pp
18940 357
- 8306220284 Notification of contract execution, Mod 3 to "Maint of Data General Computers & Peripheral Equipment " Contractor Data Consultants, Inc
PERLMAN, J Administrative Contracts Branch FIN B-1663
NRC-25-82-311 83/05/31 BASSETT, H R Office of Resource Management, Director JOHNSON, C R NRC - No Detailed Affiliation Given ip 18940 353
- 8306220289 Mod 3, adding funds, to "Maint of Data General Computers & Peripheral Equipment " * Data Consultants, Inc SMITH, P A Division of Contracts FIN B-1663 NRC-25-82-311 83/05/31 ip 18940 354
- 8306220302 Notification of contract execution, Mod 4 to "Licensing Assistance/Geotechnical & Hydrological Evaluations " Contractor Geotechnical Engineers, Inc
FIELDS, J A Technical Assistance Contracts Branch NRC-02-80-033-01. 83/06/03 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director GARCIA, P NRC - No Detailed Affiliation Given, ip 18940 299
- 8306220305 Mod 4, extending period of performance to 830930, to "Licensing Assistance/Geotechnical & Hydrological Evaluations " CASTRO, G. Geotechnical Engineers, Inc GUSTAVE, R P Division of Contracts NRC-02-80-033-01 83/06/03 ip 18940 300
- 8306220316 Notification of contract execution, Mod 3 to "Environ Assessments & Impact Statements for Low Level Waste Disposal Facilities " Contractor H & R Technical Assoc, Inc
FLEENOR, C Technical Assistance Contracts Branch NRC-02-82-026-01 83/06/03 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director NEUDER, S M NRC - No Detailed Affiliation Given ip. 18940 297

--B306220320 Mod 3, extending period of performance to 830930 & designating project officer, to "Environ Assessments & Impact Statements for Low Level Waste Disposal Facilities" RHYME, W R H&R Technical Associates, Inc GUSTAVE, R P Division of Contracts NRC-02-82-026-01 83/06/03 1p 18940 298

B306220324 Notification of contract execution, Mod 1B to "Reactor Effluent & Environ Radioactivity Stds " Contractor NBS MOLLETT, S A Technical Assistance Contracts Branch FIN B-5118 NRC-03-72-100 83/05/27 BLAHA, J L Director's Office, Office of Inspection and Enforcement COHEN, L NRC - No Detailed Affiliation Given 1p 18977 147

--B306220327 Mod 1B, providing scope of work for FY83, extending period of performance to 830930 & increasing Commission support, to "Reactor Effluent & Environ Radioactivity Stds " SHREVE, D B Commerce, Dept of, National Bureau of Standards GUSTAVE, R P Division of Contracts FIN B-5118 NRC-05-72-100 83/05/27 2pp 18977 148

B306230041 Notification of contract execution "Technical Assistance in Defense of Appeal of TERA Advanced Svcs Corp (TASC) Before GSA Board of Contract Appeals Analyse Technical Aspects of TASC Case " awarded to Dataflow Sys, Inc TOMMSEN, B L Administrative Contracts Branch NRC-10-83-368 83/06/07 NORRY, P Q Office of Administration AVERY, R E NRC - No Detailed Affiliation Given 1p 18934 344

--B306230048 Contract "Technical Assistance in Defense of Appeal of TERA Advanced Svcs Corp (TASC) Before GSA Board of Contract Appeals Analyse Technical Aspects of TASC Case " awarded to Dataflow Sys, Inc Statement of work encl GUDNINOFF, B Dataflow Systems, Inc REDELL, J E Division of Contracts NRC-10-83-368 83/06/07 4pp 18934 345

B306230054 Notification of contract execution, Mod 3 to "Licensing Assistance/Geotechnical & Hydrological Evaluations " Contractor Converse Ward Davis Dixon, Inc FIELDS, J A Technical Assistance Contracts Branch NRC-02-80-033-07 83/05/27 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director GARCIA, P NRC - No Detailed Affiliation Given 1p 18982 184

--B306230059 Mod 3, extending period of performance to 830930, to "Licensing Assistance/Geotechnical & Hydrological Evaluations " LEBAY, A G Converse, Ward, Davis, Dixon, Inc GUSTAVE, R P Division of Contracts NRC-02-80-033-07 83/05/27 1p 18982 185

B306230192 Notification of contract execution, Mod 4 to "Licensing Assistance/Geotechnical & Hydrological Evaluations " Contractor Leeds, Hill & Jewett, Inc FIELDS, J A Technical Assistance Contracts Branch NRC-02-80-033-02 83/06/14 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director GARCIA, P NRC - No Detailed Affiliation Given 1p 18954 335

--B306230198 Mod 4, extending period of performance to 830930, to "Licensing Assistance/Geotechnical & Hydrological Evaluations " Leeds, Hill & Jewett, Inc GUSTAVE, R P Division of Contracts NRC-02-80-033-02 83/06/14 1p 18954 336

B306230218 Notification of contract execution "Foreign Fuel Cycle Data," awarded to Nuclear Assurance Corp WIGGINS, E J FIELDS, J Division of Contracts FIN B-7382-3 NRC-02-83-036 83/03/31 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director THOMAS, B NRC - No Detailed Affiliation Given 1p 18981 324

--B306230220 Contract "Foreign Fuel Cycle Data," awarded to Nuclear Assurance Corp DQIRON, D G Nuclear Assurance Corp MORTON, K V Division of Contracts FIN B-7382-3 NRC-02-83-036 83/03/31 63pp 18981 325

B306230485 Notification of contract execution, Mod 1 to "Radiation Monitoring Program Requirements " Contractor State of TX SILVIS, R M Technical Assistance Contracts Branch FIN B-8504 NRC-31-83-671 83/06/14 MEYERS, D M Region 4, Office of Director NICHOLAS, J B NRC - No Detailed Affiliation Given 1p 18982 040

--B306230491 Mod 1, providing CY83 funding & changing B&R number to 94-19-30-02, to "Radiation Monitoring Program Requirements " MACLEAN, R Texas, State of GUSTAVE, R P Technical Assistance Contracts Branch FIN B-8504 NRC-31-83-671 83/06/14 1p 18982 041

B306230494 Notification of contract execution, Mod 2 to "Radiation Monitoring Program Requirements " Contractor State of NE SILVIS, R M Technical Assistance Contracts Branch FIN B-8503 NRC-31-83-670 83/06/14 MEYERS, D M Region 4, Office of Director NICHOLAS, J B NRC - No Detailed Affiliation Given 1p 18982 038

--B306230496 Mod 2, providing CY83 funds, to "Radiation Monitoring Program Requirements " BECK, R H Nebraska, State of GUSTAVE, R P Technical Assistance Contracts Branch FIN B-8503 NRC-31-83-670 83/06/15 1p 18982 039

B306230497 Notification of contract execution, Mod 1 to "Provision of Technical Assistance to Assess Psychological Stress Related to Decontamination & Disposal of Radwaste at TMI Unit 2 " Contractor Human Design Group SMITH, P A Administrative Contracts Branch FIN B-7538 NRC-03-81-097 83/05/13 DENTON, H R Office of Nuclear Reactor Regulation, Director CLEARV, D P NRC - No Detailed Affiliation Given 1p 18982 035 24X Fiche 50-320, 83/05/13, B306230497

--B306230501 Mod 1, deobligating balance of funds, to "Provision of Technical Assistance to Assess Psychological Stress Related to Decontamination & Disposal of Radwaste at TMI Unit 2." BAUM, A S Human Design Group SMITH, P A Administrative Contracts Branch FIN B-7538 NRC-03-81-097, 83/05/13 1p 18982 036 24X Fiche 50-320, 83/05/13, B306230497

B306230503 Notification of contract execution, Mod 20 to "Steam-Water Mixing & Steam Hydrodynamics " Contractor BMI, SILVIS, R M Technical Assistance Contracts Branch FIN A-4048 NRC-04-76-293 83/06/15 BATSON, W Office of Nuclear Regulatory Research, Director REYES, J NRC - No Detailed Affiliation Given 1p 18982 031

--B306230505 Mod 20, providing addl work scope & FY83 funding, to "Steam-Water Mixing & Steam Hydrodynamics." LUKIZ, F J Battelle Memorial Institute, Columbus Laboratories MORTON, K V Division of Contracts FIN A-4048 NRC-04-76-293 83/06/15 3pp 18982 032.

B306230507 Notification of contract execution, Mod 1 to "Radiation Monitoring Program Requirements " Contractor State of OR SILVIS, R M Technical Assistance Contracts Branch FIN B-8554 NRC-32-83-685 83/06/15 ALEXANDER, I Office of Resource Management, Director HAMADA, G NRC - No Detailed Affiliation Given 1p 18982 029

--B306230509 Mod 1, providing funds for CY83, to "Radiation Monitoring Program Requirements " Oregon, State of GUSTAVE, R P Division of Contracts FIN B-8554 NRC-32-83-685 83/06/15 1p 18982 030.

B306240031 Notification of contract execution, Mod 6 to "Geotechnical Assistance " Contractor Dept of Army, Corps of Engineers. FLEENOR, C Division of Contracts, NRC-02-81-036 83/06/15 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director PREBTHOLT, P NRC - No Detailed Affiliation Given 1p 18987 280.

--B306240034 Mod 6, deobligating unexpended travel funds for FY82, obligating travel funds for FY83 & extending period of performance to 840930, to "Geotechnical Assistance " RYAN, R H Army, Dept of, Corps of Engineers GUSTAVE, R P Division of Contracts, NRC-02-81-036 83/06/15 2pp 18987 281.

B306240055 Notification of contract execution, Mod 2 to "Licensing Assistance/Tailings Mgt Program Technical Evaluation " Contractor Weston Designers Consultants. FIELDS, J A Technical Assistance Contracts Branch NRC-02-79-031-08 83/06/15 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director ROSSBACH, L NRC - No Detailed Affiliation Given 1p 18979 188

--B306240057 Mod 2, extending period of performance to 830930, to "Licensing Assistance/Tailings Mgt Program Technical Evaluation " THOMPSON, A F Roy F. Weston, Inc. GUSTAVE, R P Division of Contracts, NRC-02-79-031-08 83/06/15 1p 18979 189

B306240353 Notification of contract execution, Mod 1 to "Field Experiment Determinations of Distribution Coefficients of Actinide Elements in Aquatic Environs." Contractor, Columbia Univ, FIELDS, J A Technical Assistance Contracts Branch NRC-04-81-217 83/06/15 BATSON, W Office of Nuclear Regulatory Research, Director BIRCHARD, O. NRC - No Detailed Affiliation Given 1p 18979 160

NONDOCKETED ITEMS

--830624035B Mod 1, modifying govt property & definition of purchased equipment, to "Field Experiment Determinations of Distribution Coefficients of Actinide Elements in Aquatic Environments" ISRAEL, B H Columbia Univ GUSTAVE, R P Division of Contracts NRC-04-81-217 83/06/13 2pp 18999 161

830627041 Notification of contract execution "Maint for IBM Mag Cards & Memory Typewriters," awarded to Technical Specialties, Inc COLEMAN, R Administrative Contracts Branch NRC-33-83-459 83/06/03 BASSETT, H Office of Resource Management, Director JOHNSON, C NRC - No Detailed Affiliation Given 1p 18999 350

--830627046 Contract "Maint for IBM Mag Cards & Memory Typewriters," awarded to Technical Specialties, Inc MATTIA, M J Division of Contracts NRC-33-83-459 83/06/03 18pp 18999 351

8306280050 Notification of contract execution, Mod 2 to "Licensing Technical Assistance" Contractor Science Application, Inc FLYNN, M Technical Assistance Contracts Branch FIN B-7391-3 NRC-02-83-035 83/05/27 DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director LOYSEN, P NRC - No Detailed Affiliation Given 1p 19042 303

--8306280057 Mod 2, increasing funds & definitizing Task Order 2, to "Licensing Technical Assistance" FINDLEY, D E Science Applications, Inc GUSTAVE, R P Division of Contracts FIN B-7391-3 NRC-02-83-035 83/05/27 6pp 19042 304

8306280113 Notification of contract execution, Mod 3 to "Licensing Technical Assistance" Contractor Science Application, Inc FLYNN, M Technical Assistance Contracts Branch FIN B-7392-3 NRC-02-83-035 83/06/03 DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director LOYSEN, P NRC - No Detailed Affiliation Given 1p 19056 259

--8306280118 Mod 3, increasing funds & definitizing Task Order 2, to "Licensing Technical Assistance" FINDLEY, D E Science Applications, Inc GUSTAVE, R P Division of Contracts FIN B-7392-3 83/06/03 5pp 19056 260

8306280115 Notification of contract execution "FSARS," awarded to Info Handling Svcs COLEMAN, R Administrative Contracts Branch NRC-10-83-341 83/06/13 BESAM, W Division of Technical Information & Document Control BRONCZLAS, J NRC - No Detailed Affiliation Given 1p 19056 265

--8306280122 Contract "FSARS," awarded to Info Handling Svcs * Information Handling Services, MATTIA, M J Division of Contracts NRC-10-83-341 83/06/13 23pp 19056 266

8306280127 Notification of contract execution, Mod 10 to "Word Processing Svcs" Contractor Automated Correspondence Sys DORSEY, M, SMITH, P A Administrative Contracts Branch NRC-10-80-702 83/05/06 SPRINGER, M L Office of Administration JOHANSEN, J NRC - No Detailed Affiliation Given 1p 19056 289

8306280141 Notification of contract execution, Mod 4 to "Licensing Technical Assistance" Contractor Science Application, Inc FLYNN, M Technical Assistance Contracts Branch FIN B-7393-3 NRC-02-83-035 83/06/03 DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director LOYSEN, P NRC - No Detailed Affiliation Given 1p 19043 353

--8306280147 Mod 4, increasing funds & definitizing Task Order 3, to "Licensing Technical Assistance" FINDLEY, D E Science Applications, Inc GUSTAVE, R P Division of Contracts FIN B-7393-3 NRC-02-83-035 83/06/03 5pp 19043 354

8306280152 Notification of contract execution, Mod 5 to "Seismicity & Earthquake Hazard Research in Northern AL" Contractor Geological Survey of AL WOLLETT, S Technical Assistance Contracts Branch FIN B-6674 NRC-04-80-220 83/03/16 BATSON, W Office of Nuclear Regulatory Research, Director MURPHY, A NRC - No Detailed Affiliation Given 1p 19069 359

--8306280159 Mod 5, extending period of performance to 840516 & increasing funds, to "Seismicity & Earthquake Hazard Research in Northern AL" MANCINI, E A Alabama, State of GUSTAVE, R P Administrative Contracts Branch FIN B-6674 NRC-04-80-220 83/03/16 2pp 19069 360

8306290268 Notification of contract execution "Provide Necessary Support for Brown to Present Paper Entitled 'Biaxial Loading Effects on Growth of Cracks' at Seventh Intl Conference", awarded to Sheffield Univ TOMSEND, B L Administrative Contracts Branch FIN B-8993 NRC-04-83-166 83/06/20 BASSETT, D Division of Accident Evaluation WALKER, J NRC - No Detailed Affiliation Given 1p 19046 127

--8306290281 Contract "Provide Necessary Support for Brown to Present Paper Entitled 'Biaxial Loading Effects on Growth of Cracks' at Seventh Intl Conference on Structural Mechanics", awarded to Sheffield Univ BROWN, M W Sheffield, Univ of REBELLO, J E Division of Contracts FIN B-8993 NRC-04-83-166 83/06/20 4pp 19046 128

8306290385 Notification of contract execution, Mod 4 to "Task Analysis of Nuclear Power Plant Control Room Crews" Contractor General Physics Corp DEODAT, V Technical Assistance Contracts Branch FIN B-7491 NRC-04-82-005 83/06/15 FOREHAND, W Office of Nuclear Regulatory Research, Director JENKINS, J NRC - No Detailed Affiliation Given 1p 19046 140

--8306290633 Mod 4, extending period of performance to 830709, to "Task Analysis of Nuclear Plant Control Room Crews" WHITNEY, J W General Physics Corp GUSTAVE, R P Division of Contracts FIN B-7491 NRC-04-82-005 83/06/15 1p 19046 141

8306290597 Notification of contract execution, revised Mod 4, to "Presentation of GE BWR/6 Design & Operation Courses" Contractor GE WOLLETT, S Technical Assistance Contracts Branch FIN B-1224 NRC-05-80-282 83/06/15 BLAHA, J Program Support Branch HAVEN, G NRC - No Detailed Affiliation Given 1p 19047 095

--8306290625 Revised Mod 4, canceling Mods 4 & 5 & setting new course schedule, to "Presentation of GE BWR/6 Design & Operation Courses" DUNN, M O General Electric Co GUSTAVE, R P Division of Contracts FIN B-1224 NRC-05-80-282 83/06/15 2pp 19047 096

8306280133 Mod 10, deobligating balance of funds remaining, to "Word Processing Svcs" SPAISHAN, B H Automated Correspondence Systems, Inc SKITTE, P A Division of Contracts NRC-10-80-702 83/05/06 1p 19056 290

FOIA FREEDOM OF INFORMATION ACT REQUESTS AND RELEASES

8306030007 FOIA request for rept or memo to Commissioners reviewing evidence in recently-terminated lawsuit between OPU & B&W in federal court, Southern District of NY WEISS, E R Union of Concerned Scientists 83/02/23 FELTON, J Division of Rules and Records 1p 18733 043 24X Fiche 30-320, 83/02/23, 8306030007

8306030010 Responds to FOIA request for rept or memo to Commissioners reviewing evidence in recently-terminated lawsuit between OPU & B&W in federal court, Southern District of NY Rept available in PDR FELTON, J M Division of Rules and Records 83/04/01, WEISS, E R Union of Concerned Scientists 1p 18733 044 24X Fiche 30-320, 83/04/01, 8306030010

8306030039 Appeals denial of FOIA request for NRC General Counsel B10923 memo re interim licensing legislation HAFNER, B Affiliation Unknown 83/02/28 Office of the Secretary of the Commission 2pp 18733 181

8306030046 Responds to appeal of denial of FOIA request for NRC General Counsel B10923 memo re interim licensing legislation Requested document not incorporated into final decision & remains predecisional & withholdable (ref FOIA Exemption 3) CHILK, S J Office of the Secretary of the Commission 83/04/01 HAFNER, B Affiliation Unknown 1p 18733 183

8306030366 Addl response to FOIA request for SECY-82-368, SECY-82-475 & SECY-82-509, SECY-82-475 available in PDR SECY-82-368 withheld entirely (ref FOIA Exemption 3) FELTON, J M Division of Rules and Records 83/04/01 SUCHLICK, R Affiliation Unknown 2pp 18734 290

--8306030370 SECY-82-475
Informs of resolution of reactor coolant pump trip issue (TMI Action Plan Item 11.K 3 5)
DIRCKS, W J Office of the Executive Director for Operations 82/11/30 5pp 18734 292

NONDOCKETED ITEMS

401

8306030373 FOIA request for two categories of address labels for listed US & foreign codes
AGN1HQTR1:N K Nuclear Plant Safety 83/03/04 FELTON,J M
Division of Rules and Records 2pp 18734 330

8306030376 Responds to FOIA request for two categories of address labels Forwards Labels W/o encl
FELTON,J M Division of Rules and Records 83/04/01
AGN1HQTR1:N K Nuclear Plant Safety 1p 18734 332

8306030379 FOIA request for NURE0-0945, "Final EIS on 10CFR61
'Licensing Requirements for Land Disposal of Radwaste'"
JOHNSON,B J Minnesota Project 83/03/22 Division of Rules and
Records 1p 18734 348

8306030382 Responds to FOIA request for NURE0-0945, "Final EIS on
10CFR61 'Licensing Requirements for Land Disposal of
Radwaste'" Forwards NURE0-0945, Vols 1-3 W/o encls
FELTON,J M Division of Rules and Records 83/04/01 JOHNSON,B J
Minnesota Project 1p 18734 349

8306030383 Responds to FOIA request for documents re exploration,
mining or milling of U in specific areas in State of NE
Forwards documents listed in app
FELTON,J M Division of Rules and Records 83/04/01 REID,A B
Broken Plow Law Office 2pp 18747 149

--8204070018 SECY-82-127
Recommends Commission reassert regulatory authority over
State of NE U mining & milling activities to protect public
health & safety, per Governor Thone request
DIRCKS,W J Office of the Executive Director for Operations
82/03/23 2pp 18747 153

--8306030388 Approves encl draft FR notice re reassertion of certain
regulatory authority in State of NE (SECY-82-127)
CHILK,B J Office of the Secretary of the Commission 82/04/20.
DIRCKS,W J Office of the Executive Director for Operations 4pp
18747 159

--8306030390 Forwards notice of issuance & availability of reassertion of
certain regulatory authority in State of NE
KERR,G W Office of State Programs, Director 82/04/26
COMBS,T R Correspondence & Records Branch 1p 18747 163

--8306030395 Notice of issuance & availability of reassertion of certain
regulatory authority in State of NE
KERR,G W Office of State Programs, Director 82/04/26 3pp.
18747 164

8306030448 Addl response to FOIA request for three documents re Univ of
KS Research Reactor (License R-78) Forwards GL Madsen 830324
ltr transmitting notice of violation & IE Insp Rept
30-148/83-01
FELTON,J M Division of Rules and Records, 83/04/19 BARNES,C
Affiliation Unknown 1p 18735 329 24X Fiche 30-148/83/04/19,
8306030448

8306030449 FOIA request for results of insp & investigation performed
by R Brown & D Murphy on 821130-31
RAE,R M Laboratory of Clinical Medicine, Sioux Falls, SD.
83/03/18 Division of Rules and Records 1p 18735 344.

8306030450 Responds to FOIA request for results of insp & investigation
performed by R Brown & D Murphy on 821130-31 Requested rept
will not be completed until end of Jul 1983
FELTON,J M Division of Rules and Records 83/04/19 RAE,R M
Laboratory of Clinical Medicine, Sioux Falls, SD 1p 18735 345

8306030451 FOIA request for Matl/Byproduct License 37-21226-01 granted
to Swank-Metacon Sys Co
ROBBINS,M C Republic Steel Corp 83/03/30. GRIMSLEY,D.H.
Division of Rules and Records 1p 18735:270

8306030454 Responds to FOIA request for Matl/Byproduct License
37-21226-01 granted to Swank-Metacon Sys Co Forwards
requested license
FELTON,J M Division of Rules and Records 83/04/19 ROBBINS,M C
Republic Steel Corp, 1p 18735 271

--8306030455 Matl/Byproduct License 37-21226-01 for Swank-Metacon Sys Co,
authorizing Co-60 & Cs-137 sealed sources for use in
installation, relocation, repair & servicing of Berthold
devices
GUINN,P R Division of Fuel Cycle & Material Safety, 83/01/31.
3pp 18735 272

8306030459 FOIA request for study & recommendation paper by Commission
Ofc of Policy Evaluation re replacement of highly enriched
U w/low enriched U in research reactors Paper referred to in
encl CP Woodland 830213 ltr
AFTERGOOD,B Committee to Bridge the Gap 83/03/18 Office of
Administration 1p 18747 124

8306030461 Responds to FOIA request for study & recommendation paper by
Commission Ofc of Policy Evaluation re replacement of highly
enriched U w/low enriched U in research reactors Forwards
JE Zerbe 830301 memo to Commission Ahearne
FELTON,J M Division of Rules and Records 83/04/19 AFTERGOOD,B
Committee to Bridge the Gap 1p 18747 126

8306040002 FOIA request for info re four listed corporations &
individuals & all info concerning facilities licensed for
use of 2 to 3 million curies near residential area.
CLARK,R I Dolan & Dolan 83/02/09 Office of Administration.
2pp 18752 212.

8306040003 Responds to FOIA request for info re four listed
corporations & individuals & all info concerning facilities
licensed for use of 2 to 3 million curies near residential
areas Forwards documents listed in App A
FELTON,J M Division of Rules and Records 83/03/21 CLARK,R I
Dolan & Dolan 4pp 18752 114.

--8006200486 Matl/Byproduct License 29-02786-03 for Ethicon, Inc. is
amended in its entirety per 790426 application Amend 23
authorizes use of Co-60 in sealed sources for
sterilization of medical & pharmaceuticals products
BROWN,J M Licensing Management Branch, 80/03/27. 3pp
18752 302

--8007160084 Matl/Byproduct License 29-15364-01 for Isomedix, Inc. is
amended per 790629 application. Amend 19 authorizes use of
Co-60 & Cs-137 in sealed sources for irradiating matls
GUINN,P R Licensing Management Branch 80/06/17. 3pp
18752 295

--8306060004 Notifies that source discovered leaking on 740611-14 during
transfer of Co-60 from old to new source holder Insp field
notes for Insp Rept 7401 encl.
O'SULLIVAN,E T RBA Corp 74/07/03 Atomic Energy Commission.
17pp 18752 218

--8306060005 Responds to NRC 740711 ltr re violations noted in insp rept.
Corrective actions separate log book established to record
all routine & nonroutine surveys Proper notices posted
stating where license document posted.
STEIN,M H RBA Corp 74/07/29 Region 1, Philadelphia, Office
of the Director 1p. 18752 235

--8306060006 Ack receipt of 740729 ltr informing AEC of steps taken to
correct violations noted in insp rept Related info encl.
NELSON,P.R. Region 1, Philadelphia, Office of the Director
74/08/02 STEIN,M H RBA Corp 8pp 18752 236

--8306060007 Discusses Insp Rept 30-07026/75-01 on 751023 & forwards
notice of violation Corrective actions re radiation surveys
per 740711 ltr verified
NELSON,P R Region 1, Philadelphia, Office of the Director
75/11/06 STEIN,M H RBA Corp. 2pp 18752 244.

--8306060009 Notice of violation from insp on 751023. Noncompliance noted
failure to submit annual rept of radiation exposure incurred
by personnel & to submit required repts re radiation
exposure of terminated employees
* Region 1, Philadelphia, Office of the Director 75/11/06 Bpp.
18752 246.

--8306060012 Responds to AEC 751106 ltr re violations noted in insp rept.
Corrective actions: ltr reporting annual exposures sent to
Executive Director of Regulations on 751027. Ltrs to
terminated employees sent on 751113
O'SULLIVAN,E.T. RBA Corp 75/11/14. NELSON,P.R. Region 1,
Philadelphia, Fuel Facility & Materials Safety Branch, 1p
18752 254.

--8306060013 Ack receipt of 751114 ltr informing AEC of steps taken to
correct violations noted in Insp Rept 30-07026/75-01. Insp
field notes encl
NELSON,P R Region 1, Philadelphia, Fuel Facility & Materials
Safety Branch 75/11/21 STEIN,M H RBA Corp. 11pp. 18752 255.

--8306060017 Notification of 761202 significant licensee meeting w/
Radiation Svc Assoc Corp in King of Prussia, PA to discuss
results of 761116 & 23 insps & inadequacies observed in
licensee mpt control sys
OLENN,J Region 1, Philadelphia, Office of the Director.
76/11/30 Region 1, Philadelphia, Office of the Director, 1p.
18752 266

NONDOCKETED ITEMS

- 8306060019 Discusses agenda for mgt meeting w/Radiation Svc Assoc Corp on 761202 Commitments needed from licensee include health physics audits, survey program & method & date of leaking source disposal
HCCINTOCK, R O Region 1, Philadelphia, Office of the Director
76/11/30 O'REILLY, J P Region 1, Philadelphia, Office of the Director 3pp 18752 267
- 8306060020 Confirms 761202 meeting at Region 1 ofc to discuss results of 761116 & 23 insps & items of noncompliance Outline of corrective actions & improvements in mgt control sys requested
O'REILLY, J P Region 1, Philadelphia, Office of the Director
76/11/30 STEIN, M RSA Corp 1p 18752 270
- 8306060022 Submits agenda for 761209 mgt meeting w/Radiation Svc Assoc Corp to discuss detailed plan & time table for achieving compliance w/NRC rules & regulations per 761202 mgt meeting
NELSON, P R Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 76/12/03 O'REILLY, J P Region 1, Philadelphia, Office of the Director 2pp 18752 271
- 8306060024 Confirms 761209 meeting at Region 1 ofc to discuss detailed plans resulting from 761202 meeting re assurance of future compliance w/NRC regulations & conditions of license
O'REILLY, J P Region 1, Philadelphia, Office of the Director
76/12/04 STEIN, M RSA Corp 1p 18752 273
- 8306060025 Commits to comply w/NRC rules & regulations re upgrade of radiological health & control stds in response to noncompliance noted during insp
STEIN, M H RSA Corp 76/12/09 O'REILLY, J P Region 1, Philadelphia, Office of the Director 1p 18752 274
- 8306060026 Discusses implementation of radiation protection program per 761214 meeting re control of radioactive matls
O'REILLY, J P Region 1, Philadelphia, Office of the Director
76/12/16 STEIN, M RSA Corp 2pp 18752 275
- 8306060028 Discusses 761123 insp of Radiation Svc Assoc Corp smear for removable radiation contamination revealed higher than reported concentration in samples drawn during 761116 insp
OLENN, J E Region 1, Philadelphia, Office of the Director
77/01/03 Region 1, Philadelphia, Office of the Director 2pp 18752 277
- 8306060030 Discusses insp of Licenses 29-13848-01 & 29-13848-02 on 761116 & 23 & 1213 & 14 & 761202, 09 & 14 meetings & forwards notice of violation
THOMPSON, D Office of Inspection & Enforcement, Office of the Director 77/01/31 STEIN, M H RSA Corp 3pp 18752 279
- 8306060031 Notice of violation from insp on 761116 Noncompliance noted radiation levels in unrestricted ofc bldg exceeded allowable limit & contaminated underwater light stored in unrestricted machine shop
Office of Inspection & Enforcement, Office of the Director
77/01/31 3pp 18752 282
- 8306060033 Responds to NRC 770131 ltr re violations noted in IE insp re: corrective actions: leaking broken source storage container removed from pool & placed in shielded storage cask for disposal.
O'BULLIVAN, E T RSA Corp 77/02/17 THOMPSON, D Office of Inspection & Enforcement, Office of the Director 4pp 18752 287
- 8306060035 Ack receipt of 770217 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 30-07026/75-01
VOLGENAU, E Office of Inspection & Enforcement, Office of the Director 77/02/17 STEIN, M H RSA Corp 1p 18752:291
- 8306060038 Forwards proposed enforcement ltr in response to Radiation Svc Assoc Corp 770217 ltr Corrective actions adequate.
O'REILLY, J P Region 1, Philadelphia, Office of the Director
77/03/04 THOMPSON, D Office of Inspection & Enforcement, Office of the Director 1p 18752 292
- 8306060041 Amend 12 to Matl Byproduct License 20-00315-03 for Dept of Army, authorizing use of Co-60 sealed source in irradiation of nonexplosive matl
CORNB, F Division of Fuel Cycle & Material Safety 78/11/15 2pp 18752 293
- 8306060053 Amend 16 to Matl/Byproduct License 29-13613-02, authorizing use of Co-60 sealed sources for Radiation Technology Model 2102 irradiator for surface irradiation, R&D & storage in receiving pool
QUINN, P R Division of Fuel Cycle & Material Safety 81/08/17 4pp. 18752 298.
- 8306060008 FOIA request for list of 1982 & 83 SECY papers
BROLIN, M A KLM Engineering, Inc 83/04/05 Division of Rules and Records 1p 18751 258
- 8306060010 FOIA request for documents re investigation of L Berstler allegations concerning Facility
HODAS, D R Potter & Carmine 83/03/18 Office of Administration 1p 18752 305 24X Fiche 50-354, 83/03/18, 8306060010
- 8306060011 Responds to FOIA request for list of 1982 & 83 SECY papers Forwards requested list SECYs available in PDR
FELTON, J M Division of Rules and Records 83/04/19 BROLIN, M A KLM Engineering, Inc 1p 18751 259
- 8306060014 Publicly available 1982 & 83 SECY papers
* NRC - No Detailed Affiliation Given 83/04/19 8pp 18751 260
- 8306060013 Responds to FOIA request for documents re investigation of L Berstler allegations concerning Facility Forwards listed documents
FELTON, J M Division of Rules and Records 83/04/15 HODAS, D R Potter & Carmine 2pp 18752 306 24X Fiche 50-354, 83/04/15, 8306060013
- 8306060016 IE inquiry re:pt on 820819 Major area investigated L Berstler allegations re deficiencies in installation & testing of HVAC sys at Facility Inquiry closed
SHEPHERD, R E, CHRISTOPHER, R Region 1, Office of Director
82/11/22 14pp 18752 308 24X Fiche 50-354, 83/04/15, 8306060013
- 8306060018 Statement of LR Berstler alleging deficiencies in installation & testing of HVAC sys at Facility Leak test re:pt forms for nongas-tight ductwork & worksheet encl
BERSTLER, L R Affiliation Unknown 82/04/13 8pp 18752 322 24X Fiche 50-354, 83/04/15, 8306060013
- 8306060021 Discusses L Berstler, former Willard & Hirsch, Arkin, Herberman (W-H) QC inspector, allegations re HVAC installation at Facility Bechtel preliminary review indicated minor hardware deficiencies & QC paperwork problem
TRIPP, L E Division of Project & Resident Programs 82/03/04 Division of Project & Resident Programs 2pp 18752 328 24X Fiche 50-354, 83/04/15, 8306060013
- 8306060023 Discusses L Berstler, former Willard & Hirsch, Arkin, Herberman (W-H) QC inspector, allegations re deficiencies in installation & testing of HVAC sys at Facility
SHEPHERD, R E Region 1, Office of Director 82/12/16 Region 1, Office of Director 1p 18752 330 24X Fiche 50-354, 83/04/15, 8306060013
- 8306060027 Forwards matl discussed on 820819, per request Further discussion of matl will be arranged w/o encl
SHEPHERD, R E, Region 1, Office of Director 83/08/23 BERSTLER, L Affiliation Unknown 1p 18752 333
- 8306060032 Partial response to FOIA request for two categories of labels Forwards labels responsive to first category Second category labels will be forwarded when available w/o encl
FELTON, J M Division of Rules and Records 83/04/01 AGNIHOTRI, N K Nuclear Plant Safety 1p 18751 270
- 8306060034 FOIA request for documents re US approvals of reprocessing of US-supplied nuclear fuel abroad & transfer & use of Pu derived from fuel
LEVENTHAL, P Nuclear Club, Inc, The 83/06/10 MACHAK, F, State Dept of 1p 18751 268
- 8306060037 Responds to FOIA request for documents re US approvals of reprocessing of US-supplied nuclear fuel abroad & transfer & use of Pu derived from fuel Documents withheld (ref FOIA Exemption 1).
FELTON, J M Division of Rules and Records 83/04/08 LEVENTHAL, P Nuclear Club, Inc., The 1p 18751 269
- 8306060051 Addl response to FOIA request for three categories of documents re PRA of reactor safety study methodology application program repts & interim reliability evaluation program repts Forwards App A documents, Search continuing
FELTON, J M Division of Rules and Records 83/04/07 SHOLLY, S C FICHE 50-000, 83/04/07, 8306060051 3pp 18752 001 24X
- 8109210318 Responds to 810820 memo re transmittal of NUREG/CR-1659, Vol 2, to licensee for comments Util comments on re:pt already requested
BERNERO, R M Division of Risk Analysis 81/08/28 NOVAK, T M Assistant Director for Operating Reactors, 2pp 18752 018 24X Fiche. 50-000, 83/04/07, 8306060051

NONDOCKETED ITEMS

403

- B204120488 Discusses results of Sandia Natl Labs Study, "Reactor Safety Study Methodology Application Program Grand Gulf 1 BWR Power Plant (NUREG/CR-1659, Vol 4) " ERNST, M L Assistant Director for Technology Review 82/04/06 TEDESCO, R L Assistant Director for Licensing 2pp 18752 067 24X Fiche 50-000, 83/04/07, 8306060051
- B207280024 Discusses NUREG/CR-2787, "Interim Reliability Evaluation Program Analysis of AR Nuclear One-Unit 1 Nuclear Power Plant," first final rept on four integrated reliability evaluation program Phase II studies BERNERD, R M Division of Risk Analysis 82/06/24 HANAVER, S H Division of Human Factors Safety 3pp 18752 074 24X Fiche 50-000, 83/04/07, 8306060051
- B211220332 Forwards "Effect of Resolution of Millstone Unit 1 SEP Issues on Probabilistic Calculations of Risk" & risk-based perspective of selected SEP issues ERNST, M L Assistant Director for Technology Review 82/11/15 MIRAGLIA, F Assistant Director for Safety Assessment 12pp 18752 079 24X Fiche 50-000, 83/04/07, 8306060051
- B211220337 SAND82-2429 "Effect of Resolution of Millstone Unit 1 SEP Issues on Probabilistic Calculations of Risk " SPULAK, R G , STACK, D , AMICO, P Science Applications, Inc 82/11/15 NRC - No Detailed Affiliation Given 108pp 18752 091. 24X Fiche 50-000, 83/04/07, 8306060051
- B306060058 Requests meeting w/NRC to discuss concerns re reactor safety study methodology application program Conservative rather than realistic assumptions & calculations used in analysis DALE, L F Mississippi Power & Light Co AECM-B1/18A 81/07/23 BERNERD, R M Division of Risk Analysis 2pp 18752 016 24X Fiche 50-000, 83/04/07, 8306060051
- B306060061 Statement on background, issues, current status & future action re interim & natl reliability evaluation programs * NRC - No Detailed Affiliation Given 82/12/31 2pp 18752 099 24X Fiche 50-000, 83/04/07, 8306060051
- B306060066 Requests review of listing of all PRA-type studies performed on plants (both operating & under const) Listing does not include SEP Phase III/natl reliability evaluation program plants EIBENHUT, D G Division of Licensing 82/06/01 HANAVER, S H Division of Safety Technology 2pp 18752 069
- B306060076 Discusses interim actions taken to reduce impact of turbine bldg flooding Doors between turbine & auxiliary bldgs at basement level sealed shut, component cooling water crossover valves closed & condensate cooler isolated TUCKER, H D Duke Power Co 82/12/01 O'REILLY, J P Region 2, Office of Director 2pp 18752 190 24X Fiche 50-000, 83/04/07, 8306060051
- B306060080 Forwards background info re PRA studies Review of Sandia Natl Labs interim reliability evaluation program studies discussed W/o encl BTOLZ, J Operating Reactors Branch 4 TAC 47491 83/01/19 LAINAB, G C Assistant Director for Operating Reactors 2pp 18752 200 24X Fiche 50-000, 83/04/07, 8306060051
- B306060085 Provides info on boron precipitation clogging HPI lines & failure of operator to switch to hot leg injection in order to flush out boron residue from core during recirculation Info obtained from PRA's DAVIS, S NRC - No Detailed Affiliation Given 83/02/24 THADANI, A NRC - No Detailed Affiliation Given 6pp 18752 206 24X Fiche 50-000, 83/04/07, 8306060051
- B306060094 FOIA request for BECY-B1-645, BECY-B1-654 & BECY-B2-162A GRABER, L Affiliation Unknown 83/01/31 Division of Rules and Records 1p 18750 352
- B306060104 Responds to FOIA request for BECY-B1-645, BECY-B1-654 & BECY-B2-162A BECY-B1-645 & BECY-B1-654 pertain to AOs noticed in 46FR61020 Forwards BECY-B2-162A FELTON, J M Division of Rules and Records 83/03/29 GRABER, L Affiliation Unknown 1p 18750 353
- B306060108 BECY-B2-162A Forwards integrated plan for development of rule for shift crew qualifications, DIRCKS, W J Office of the Executive Director for Operations 82/08/26 9pp 18750 354
- B306060381 Appeals denial of FOIA request for documents re risk to facilities from low trajectory turbine missiles HIATT, S L Ohio Citizens for Responsible Energy 83/03/03 DIRCKS, W J Office of the Executive Director for Operations. 3pp 18750 329 24X Fiche, 50-440, 83/03/03, 8306060381
- B306060384 Responds to appeal re partial denial of FOIA request for documents concerning risks to facilities from low trajectory turbine missiles Appeal denied Documents withheld (ref FOIA Exemption 5) DIRCKS, W J Office of the Executive Director for Operations 83/04/06 HIATT, S L Ohio Citizens for Responsible Energy 1p 18750 332 24X Fiche 50-440, 83/04/06, 8306060384
- B306060393 Final response to FOIA request for five listed documents re guide tube support pin failures Forwards Documents 2 & 3 & related meeting minutes Document 3 incorrectly identified as B20320 ltr Ltr coded NS-EPR-2351 actually dtd 820128 FELTON, J M Division of Rules and Records 83/04/05 MCNAHAN, J Francis & McGinnis Associates 1p 18753 021
- B306060396 Summary of B20602 meeting w/Westinghouse re control rod drive guide tube support pin failures List of attendees & viewpoints encl HOLLAND, R A Director's Office, Office of Inspection and Enforcement 82/06/02 MILLS, W R Events Analysis Branch 49pp 18753 029
- B306060398 FOIA request for lists of people in emergency planning dept & instrumentation & control dept of nuclear plants & in state depts of health physics/radiology WEST, D K Affiliation Unknown 83/02/28 Division of Rules and Records 1p 18751 291
- B306060400 Responds to FOIA request for lists of personnel in specified depts of nuclear plants & in state depts of health physics/radiology Forwards listed documents. Document partially withheld (ref FOIA Exemption 6) FELTON, J M Division of Rules and Records 83/04/06 WEST, D K Affiliation Unknown 2pp 18751 292 24X Fiche 50-312, 83/04/06, 8306060400
- B306060402 "Directory of Personnel Responsible for Radiological Health Programs " Organization charts of NC, FL, AL, GA, KY, MS, SC & TN & list of state contacts for emergency preparedness w/ info partially deleted encl. * HHS, Dept of, US Public Health Service 82/10/08 56p 18751 294
- B306070018 FOIA request for insp, surveillance & radiological monitoring repts re Westinghouse Cheswick Div, License 37-05809-01 JOHNSON, C Behrand, Aramson & Morraus 83/03/03 ALLAN, J M Region 1, Office of Director 2pp. 18780 360
- B306070019 Final response to FOIA request for documents re current efforts by NRC to upgrade earthquake resistance at facility Forwards documents listed in app. Handwritten document withheld (ref FOIA Exemption 5) FELTON, J M Division of Rules and Records 83/04/03 WHARTON, R J San Diego, Univ of, San Diego, CA 2pp 18781 343 24X Fiche 50-206, 83/04/03, 8306070019
- B205170474 Forwards B20506 memo w/Systematic Evaluation Program Branch recommendations re seismic reanalysis program DIRCKS, W J Office of the Executive Director for Operations 82/03/07 PALLADINO, N J , OILINSKY, V , AHEARNE, J F Commissioners 2pp 18781 352 24X Fiche 50-206, 83/04/03, 8306070019
- B208050024 Forwards response to B20618 request for comments on Director's Decision 81-19 denying 10CFR2 206 relief re restart & emergency planning DIRCKS, W J Office of the Executive Director for Operations, DD-81-19 82/07/22 AHEARNE, J Commissioners 6pp. 18781 354 24X Fiche 50-206, 83/04/03, 8306070019
- B306070021 Requests meeting to discuss encl questions on BECY-B2-63 re Director's Decision denying 10CFR2, 206 relief concerning interim seismic adequacy AHEARNE, J Commissioners 82/04/20, Office of Policy Evaluations. 3pp. 18781 347 24X Fiche: 50-206, 83/04/03, 8306070019
- B306070028 Approves BECY-B2-63 re Director's Decisions 81-19 & 81-20 denying request for 10CFR2 206 relief. Comments on BECY-B2-63 re misclassification of turbine bldg complex encl AHEARNE, J F Commissioners, DD-81-19 82/05/03 CHILK, S J Office of the Secretary of the Commission 2pp 18782 008 24X Fiche, 50-206, 83/04/03, 8306070019
- B306070020 Responds to FOIA request for insp, surveillance & radiological monitoring repts re Westinghouse Cheswick Div, License 37-05809-01 Forwards App A documents Search for addl documents continuing. W/o encls FELTON, J M Division of Rules and Records 83/03/16 JOHNSON, C Behrand, Aramson & Morraus 2pp. 18780 362

NONDOCKETED ITEMS

- 8306070023 FOIA request for documents re proposals submitted under RFP RS-SECY-82-473, including proposal revs & review of proposals & negotiations between NRC & any entity submitting proposals
SHARP, I H Alderson Reporting 83/03/21 FELTON, J M Division of Rules and Records 1p. 18782 270
- 8306070025 Addl response to FOIA request for proposals submitted under RFP RS-SECY-82-473, including proposal revs, review of proposals & negotiations between NRC & any entity submitting proposals Nonproprietary portions of proposals encl
FELTON, J M Division of Rules and Records 83/03/03 SHARP, I H Alderson Reporting. 1p 18782 271
- 8306070026 Solicitation, offer & award to Mohick Reporting Co.
MEHLICK, J J. Monick Reporting Co FLYNN, M Division of Contracts RS-SECY-82-473 82/09/13. 3pp 18782 272
- 8306070027 Requests that encl response to RFP RS-SECY-82-473 be withheld. Info partially deleted
MEHLICK, J J. Monick Reporting Co 82/09/13 Division of Contracts 25pp 18782-277.
- 8306070439 Responds to FOIA request for 790328 original petition for rulemaking filed by Q Taplin Forwards document W/o encl
FELTON, J M Division of Rules and Records 83/04/05 KRONZEK, A L FOI Services 1p. 18776 357
- 8306070441 FOIA request for 790328 original petition for rulemaking filed by Q Taplin.
KRONZEK, A L. FOI Services 2724. 83/03/29 FELTON, J M Division of Rules and Records 1p 18776 358
- 8306080028 FOIA request for ORNL/TM-8275, "Technical Considerations re Interim Source Term Assumption for Equipment Qualification & Emergency Planning."
SHOLLY, S C Union of Concerned Scientists 83/03/14 FELTON, J M Division of Rules and Records 1p 18784 148.
- 8306080031 Responds to FOIA request for ORNL/TM-8275, "Technical Considerations re Interim Source Term Assumptions for Equipment Qualification & Emergency Planning." ORNL/TM-8275 encl
FELTON, J M. Division of Rules and Records 83/03/25 SHOLLY, S C Union of Concerned Scientists 1p 18784 049
- 8306080041 ORNL/TM-8275
"Technical Considerations re Interim Source Term Assumptions for Emergency Planning & Equipment Qualification"
NIEMCZYK, S J., MCDOWELL-BDYER Oak Ridge National Laboratory 82/09/30 NRC - No Detailed Affiliation Given 312pp 18784 150.
- 8306080046 Responds to FOIA request for current roster of utility list Document available in PDR
FELTON, J M. Division of Rules and Records 83/04/04 SANDRY, W A Professional Reactor Operator Society 1p 18787 298
- 8306080070 FOIA request for current roster of utility list
SANDRY, W. A. Professional Reactor Operator Society. 83/03/28 CARR, J. Division of Rules and Records 1p 18787 299.
- 8306080235 Responds to FOIA request for names, addresses, license numbers & insp priorities & subpriorities for licenses in nine states Forwards computer printout W/o encl
FELTON, J M Division of Rules and Records 83/04/11 TEKIN, J V Radiat Research 1p 18785 349
- 8306080256 FOIA request for names, addresses, license numbers & insp priorities & subpriorities for licenses in nine listed states
TEKIN, J V. Radiat Research. 83/03/23 Office of Administration 1p. 18785 350
- 8306080297 Responds to FOIA request for info on fraudulent practices of Ray Miller, Inc. App A documents available in PDR
FELTON, J M Division of Rules and Records 83/04/11. STECKEL, A Union of Concerned Scientists. 4pp. 18785 351.
- - - fraudulent
1/15. FELTON, J M
- to categories
7 App
FOIA
- KINDER, E. T.
Enc. 30-443.
- 8306080263 Forwards results of licensee investigation of Pullman-Higgins QC inspector allegations re perceived harassment of QC inspectors from within organization & documentation of organization changes
CERNE, A C Region 1, Office of Director 82/07/16 Region 1, Office of Director 7pp 18790 319 24X Fiche 30-443, 83/04/06. 8306080259
- 8306080264 Discusses QC inspector concerns within Pullman-Higgins organization (facility piping contractor) re perceived harassment of QC inspectors by P-H const personnel Closure of case recommended
CERNE, A C Region 1, Office of Director 82/10/13 Region 1, Office of Director 2pp 18790 326 24X Fiche 30-443, 83/04/06. 8306080259
- 8306080266 Discusses Pullman-Higgins (P-H) QC inspector concerns re allegations of harassment of QC inspectors by P-H const personnel Personally identifiable info deleted
CERNE, A C Region 1, Office of Director 82/06/09 Region 1, Office of Director 2pp 18790 328 24X Fiche 30-443, 83/04/06. 8306080259
- 8306080267 Discusses QC inspector concerns, per AC Cerne 820609 memo Handwritten notes encl Memo contents deleted
SHEPHERD, R E Region 1, Office of Director 82/06/17 BRUNHNER, E J Division of Project & Resident Programs 6pp 18790 330
- 8306080269 Discusses nonspecific allegations re Pullman-Higgins QA/QC inspectors at facilities Personally identifiable info deleted
MATAKAS, R A Region 1, Office of Director 82/09/27 OALLO, R M Division of Project & Resident Programs 2pp 18790 336 24X Fiche 30-443, 83/04/06, 8306080259
- 8306080261 FOIA request for R Parks 56-page affidavit sent to US Dept of Labor
ROMANO, F R Air and Water Pollution Patrol 83/03/31 Division of Rules and Records 1p 18787 177 24X Fiche 30-320, 83/03/31. 8306080261
- 8306080262 Responds to FOIA request for R Parks 56-page affidavit sent to US Dept of Labor Forwards T Devine 830323 ltr transmitting RD Parks 830321 affidavit & RD Parks 830316 ltr to Bechtel
FELTON, J M Division of Rules and Records 83/04/12 ROMANO, F R Air and Water Pollution Patrol 1p 18787 178 24X Fiche 30-320, 83/04/12, 8306080262
- 8306080265 FOIA request for SECY-83-22
KNIGHT, N L General Physics Corp 83/03/18 Division of Rules and Records 1p 18787 239
- 8306080268 Responds to FOIA request for SECY-83-22 Forwards publicly available portions of paper per telcon w/N Toms
FELTON, J M Division of Rules and Records 83/04/11 KNIGHT, N L General Physics Corp 1p 18787 240
- 8306080270 "Statement of policy Further Commission Guidance on Emergency Response Capability." draft 10CFR50 effective rule Suppl issued to NUREG-0737, "Clarification of TMI Action Plan Requirements"
CHILK, B J Office of the Secretary of the Commission 83/04/11 3pp 18787 241
- 8306080272 Addl response to FOIA request for documents re meeting between ABEA-ATOM (Sweden) & NRC concerning PIUS reactor & documents regarding PIUS reactor No addl documents available
FELTON, J M. Division of Rules and Records 83/05/03 SHOLLY, S C Union of Concerned Scientists 1p 18790 350
- 8306080275 Responds to FOIA request for lists of people in nuclear industry Forwards requested lists except for list of expired reactor operator licenses List of reactor & senior reactor operators also encl W/o encls
FELTON, J M Division of Rules and Records 83/04/25. SCUDDER, J Affiliation Unknown 1p. 18790 352
- 8306080276 FOIA request for lists of people in nuclear industry
SCUDDER, J Affiliation Unknown 83/04/15 FELTON, J Division of Rules and Records. 1p 18790 353
- 8306080277 Addl response to FOIA request for seven categories of records re Brown & Root, Inc & facilities App C Document 1 partially withheld (ref FOIA Exemption 7) App D documents withheld entirely (ref FOIA Exemption 3)
FELTON, J M. Division of Rules and Records 83/04/12 LINDEMAN, H M Lowenstein, Newman, Reis, Axelrad & Toll 4pp 18792.156 24X Fiche. 30-498, 83/04/12, 8306080277

NONDOCKETED ITEMS

405

--B306080304 "Request for Investigation Concerning Alleged Advanced Notification," investigation rept info partially deleted
SINCLAIR, J R Office of Inspector & Auditor 80/10/23 9pp
18792 160 24X Fiche 50-498, 83/04/12, B306080277

--B306080308 Forwards rept re alleged advanced notification to util or Brown & Root, Inc of forthcoming Region IV investigation &/or alleged identities No further investigation contemplated
W/o encl
CUMMINGS, J J Office of Inspector & Auditor 80/10/24
AHEARNE, J F, OILINSKY, V, HENDRIE, J M Commissioners 1p
18792 169 24X Fiche 50-498, 83/04/12, B306080277

--B306080310 Forwards "Request for Investigation Concerning Alleged Advanced Notification" (ref 801024 memo) W/o encl
CUMMINGS, J J Office of Inspector & Auditor 80/11/10
STELLO, V J Director's Office, Office of Inspection and Enforcement 1p 18792 170 24X Fiche 50-498, 83/04/12, B306080277

B306080281 Partial response to FOIA request for documents re R Gunderson & Bechtel allegations concerning electrical problems at facilities App A Documents 1 & 2 available in PDR Documents 3, 4 & 5 withheld (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records 83/04/28 YOUNG, M C BERNABEI, L Government Accountability Project 3pp 18790 354 24X Fiche 50-528, 83/04/28, B306080281

B306080284 FOIA request for documents re R Gunderson & Bechtel senior manager allegations concerning electrical problems & deficiencies at facilities Waiver of fees requested
YOUNG, M C, BERNABEI, L Government Accountability Project 83/03/29 Office of Administration 2pp 18790 357 24X Fiche 50-528, 83/03/29, B306080284

B306080288 FOIA request for list of NRC licensed contractors &/or subcontractors performing HVAC sheet metal work at nuclear plants currently operating & under const in US
WEST, D K Affiliation Unknown 83/02/28 Office of Administration 1p 18790 360

B306080291 Responds to FOIA request for list of NRC licensed contractors &/or subcontractors performing HVAC sheet metal work at nuclear plants currently operating & under const in US
FELTON, J M Division of Rules and Records 83/03/23 WEST, D K Affiliation Unknown 1p 18790 359

B306080293 FOIA request for list of addressees receiving DEB re decommissioning of Rare Earths Facility, West Chicago, IL subsequent to May 1982
SPELMAN, H J Harold J Spelman & Associates 83/03/23 Division of Rules and Records 2pp 18792 145

B306080296 Responds to FOIA request for documents re licensee (Radiation Technology, Inc) & other licenses dealing w/ MA Welt Prior insp repts & transcript of hearing involving licensee will be provided, per B30425 conference call
FELTON, J M Division of Rules and Records 83/04/27 HILL, R Riverside County, CA 1p 18790 361

B306080297 Responds to FOIA request for list of addressees receiving DES re decommissioning of Rare Earths Facility, West Chicago, IL subsequent to May 1982 Forwards mailing list for DES Addressees receiving DES after May 1982 not identified
FELTON, J M Division of Rules and Records 83/04/06 SPELMAN, H J Harold J Spelman & Associates 1p 18792 147

--B306080302 "Distribution List, Kerr-McGee West Chicago DES"
* NRC - No Detailed Affiliation Given 83/04/06 8pp
18792 148

B306080301 FOIA request for documents re licensee (Radiation Technology, Inc) & other licenses dealing w/ MA Welt
HILL, B, Riverside County, CA 83/03/31 Office of Administration 1p 18790 362

B306080305 Responds to FOIA request for info re safety & const violations at facility info available in LPDR, per B30407
FELTON, J M Division of Rules and Records 83/04/08 BADINO, A Affiliation Unknown 1p 18792 216 24X Fiche 50-35B, 83/04/08, B306080305

B306080307 FOIA request for info re safety & const violations at facility
BADINO, A Affiliation Unknown 83/04/01 Division of Rules and Records 1p 18792 217 24X Fiche 50-35B, 83/04/01, B306080307

B306080309 FOIA request for three documents re Univ of KB Research Reactor
BARNES, C Affiliation Unknown 83/03/08 FELTON, J M Division of Rules and Records 1p 18790 303 24X Fiche 50-14B, 83/03/08, B306080309

B306080313 Responds to FOIA request for three documents re Univ of KB Research Reactor Forwards documents responsive to items 1 & 2 of request Releasability determination for item 3 re insp rept under review
FELTON, J M Division of Rules and Records 83/04/06 BARNES, C Affiliation Unknown 1p 18790 304 24X Fiche 50-14B, 83/04/06, B306080313

--B306080316 Forwards responses to 731106 questions, indicating specified locations on floor plan
SMITH, W P Kansas, Univ of 8759 73/12/06 ZIEHANN, D L Atomic Energy Commission, Directorate of Licensing 8pp.
18790 305 24X Fiche 50-14B, 83/04/06, B306080313

B306080320 FOIA request for info re safety requirements of nuclear power plants
MARTIN, C Affiliation Unknown 83/04/25 NRC - No Detailed Affiliation Given 1p. 18789 336

B306080322 Responds to FOIA request for info re safety requirements of nuclear power plants Forwards App A documents W/o encl
FELTON, J M Division of Rules and Records 83/05/03 MARTIN, C Affiliation Unknown 2pp 18789 337

B306090373 FOIA request for winning technical proposal & any mgt proposals submitted by Computer Data Sys, Inc to provide publication distribution & inventory svcs.
SEMINARA, C Science Management Corp 83/02/09 Division of Contracts 1p 18815 171

B306090376 Responds to FOIA request for winning technical proposal & any mgt proposals submitted by Computer Data Sys, Inc to provide publication distribution & inventory svcs Forwards nonproprietary version of requested proposal
FELTON, J M Division of Rules and Records 83/04/13 SEMINARA, C Science Management Corp 1p 18815 172

--B306090379 Nonproprietary version of "Proposal to Provide Publication Distribution & Inventory Sys for NRC"
* Computer Data Systems, Inc 82/08/20 44pp. 18815 173

B306090381 Responds to FOIA request for documents released under Request FOIA Request 82-315 & NRC response & all encls Documents available in PDR Status of administration of FOIA for wk ending 821105 encl
FELTON, J M Division of Rules and Records 83/04/13 KRONZEK, A L FOI Services 2pp 18815 168

B306100009 Addl response to FOIA request for documents dtd B20101 or after re SAMP Forwards App A documents Documents also available in PDR
FELTON, J M Division of Rules and Records 83/04/11 CLARK, R San Francisco Examiner 3pp 18815 252 24X Fiche 50-000, 83/04/11, B306100009

--B306100014 Submits schedule for Region V SAMP Board meetings for 820928-B30523
ENDELKEN, R H Region 5, Office of Director 82/03/19.
DENTON, H R Office of Nuclear Reactor Regulation, Director
DAVIS, J Q Office of Nuclear Material Safety & Safeguards, Director MICELSON, C Director's Office 1p.
18815 255 24X Fiche 50-000, 83/04/11, B306100009.

--B306100032 Requests brief performance analysis & recommended conclusion for each functional area inspected, based on review of summary of insp activities & analyses of LERS & noncompliance items issued from Jul 1981 - Sept 1982.
STERNBERG, D M Region 5, Office of Director. 82/03/23 YOUNG, T., CANTER, H, O'BRIEN, J Region 5, Office of Director 1p.
18815 256 24X Fiche 50-000, 83/04/11, B306100009

--B306100036 Discusses assignment of SAMP coordinators for Reactor Operations Projects Branch facilities Coordinators will be responsible for preparing input data used by board members in analyzing functional areas Draft note from B Miner encl.
STERNBERG, D M Region 5, Office of Director. 82/03/24 Region 5, Office of Director 11pp 18815 257 24X Fiche 50-000, 83/04/11, B306100009.

--B306100038 Forwards input to SAMP rept
CHOKENI, N. Structural Engineering Branch 82/10/18 MINER, B NRC - No Detailed Affiliation Given 3pp 18815 271. 24X Fiche 50-000, 83/04/11, B306100009

NONDOCKETED ITEMS

- 8306100039 Forwards evaluation of licensee performance for safeguards licensing portion of SALP review per Sternberg 821014 memo. Util has responded quickly & accurately to NRC-initiated comments & suggestions. MCCORMACK, O W Power Reactor Safeguards Licensing Branch 82/11/04 NORDERHAUG, L Region 5, Office of Director 3pp 18815 288 24X Fiche 50-000, 83/04/11, 8306100009
- 8306100040 Forwards brief description of investigative activities of seven cases re SALP during Jul 1981 - Sept 1982 Allegation against contract personnel using controlled drugs during outages still pending. SHACKLETON, O C Region 5, Office of Director 82/11/10 WILLETT, D Region 5, Office of Director 2pp 18815 291 24X Fiche 50-000, 83/04/11, 8306100009
- 8306100044 Comments on 821014 memo re SALP Board review of facility NORTH, H Region 5, Office of Director 82/11/10 WILLETT, D Region 5, Office of Director 2pp 18815 293 24X Fiche 50-000, 83/04/11, 8306100009
- 8306100047 Forwards SALP rept inadvertently omitted from 821202 ltr & revised agenda for SALP 830105 meeting. STERNBERG, D M Region 5, Office of Director 82/12/13 MATTHEW, J J Sacramento Municipal Utility District 1p 18815 304 24X Fiche 50-000, 83/04/11, 8306100009
- 8306160013 Responds to FOIA request for grant applications, grant awards, contracts & cooperative agreements to League of Cities & Conference of Mayors over last 10 yrs Div of Contracts has no records subj to request. FELTON, J M Division of Rules and Records 83/04/14. HOUSTON, J C Fairness Committee Against Tax Funded Politics 1p 18872, 217
- 8306160015 FOIA request for grant applications, grant awards, contracts & cooperative agreements to League of Cities & Conference of Mayors over last 10 yrs. HOUSTON, J C Fairness Committee Against Tax Funded Politics 83/04/04 PALLADINO, N J Commissioners 1p 18872, 218
- 8306160019 Responds to FOIA request for four categories of documents re suspected teratogens & birth defects as result of nuclear power plant operation NRC has no records subj to request. FELTON, J M Division of Rules and Records 83/04/15 MARSHALL, C Foundation for National Progress 1p 18872 291
- 8306160024 FOIA request for four categories of documents re suspected teratogens & birth defects as result of nuclear power plant operation. MARSHALL, C Foundation for National Progress 83/03/16 CARR, J C NRC - No Detailed Affiliation Given 3pp 18872 292
- 8306160026 Responds to FOIA request for four documents re Saxton Test Reactor Requested ltrs available in PDR Saxton 741124 ltr to NRC not located. FELTON, J M Division of Rules and Records 83/04/20 GRABER, L D NUS Corp 1p 18872 314 24X Fiche 50-146, 83/04/20, 8306160026
- 8306160030 FOIA request for four documents re Saxton Test Reactor. GRABER, L D NUS Corp CP-LIS-9104 83/04/12 Division of Rules and Records 1p 18872, 315 24X Fiche 50-146, 83/04/12, 8306160030
- 8306160031 Clarifies NRC final response to FOIA request for documents re Zack Co k/or work performed by Zack in const of facilities App D Document 5 deleted since document identical to App A Document 135. FELTON, J M Division of Rules and Records 83/04/14 PRENDERGAST, R J 1p 18872 336 24X Fiche 50-000, 83/04/14, 8306160031
- 8306160033 Responds to FOIA request for documents re Jul 1982 stop work order issued to util Request withdrawn, per 830414 telcon between requester & N Tom Case closed. FELTON, J M Division of Rules and Records 83/04/14 GARDE, B Government Accountability Project 1p 18892, 333 24X Fiche 50-329, 83/04/14, 8306160033
- 8306160035 FOIA request, on behalf of EE Kent, for documents re Jul 1982 stop work order issued to util. GARDE, B Government Accountability Project 83/02/16 Office of Administration 1p 18892, 334, 24X Fiche 50-329, 83/02/16, 8306160035
- 8306160041 FOIA request for AEDD Engineering Evaluation Rept AEDD/N301 re I-125/I-131 effluent releases by licensees & documents re Ray Miller, Inc. KRANISH, A Trends Publishing, Inc 83/04/06 Division of Rules and Records, 1p 18892 328
- 8306160046 FOIA request, on behalf of EE Kent, for records prepared by US govt employees re Alliance for Survival, T Carpenter &/or ongoing NRC investigation of facilities. CARPENTER, T Orange County Alliance for Survival 83/03/14 Office of Administration 1p 18893 031 24X Fiche 50-206, 83/03/14, 8306160046
- 8306160050 Responds to FOIA request for AEDD Engineering Evaluation Rept AEDD/N301 re I-125/I-131 effluent releases by licensees & documents re Ray Miller, Inc Forwards AEDD rept Ltr sent to UCS re Ray Miller, Inc practices will be provided. FELTON, J M Division of Rules and Records 83/04/21 KRANISH, A Trends Publishing, Inc 1p 18892 329
- 8306160057 AEDD/N301 AEDD engineering evaluation rept re I-125/I-131 effluent releases by licensees Issuance of IE info notice recommended to clarify 10CFR20 201(b) requirement that licensees make physical measurements to verify compliance w/10CFR20 106(a) * Director's Office 83/03/18 3pp 18892 330
- 8306160052 Responds to FOIA request for records prepared by US govt employees re Alliance for Survival, T Carpenter &/or ongoing NRC investigation of facilities Forwards App A documents Search for addl documents in progress. FELTON, J M Division of Rules and Records 83/04/14 CARPENTER, T Orange County Alliance for Survival 2pp 18893 032 24X Fiche 50-206, 83/04/14, 8306160052
- 821160565 Forwards Community Energy Action Network 821018 ltr & Los Angeles Times article re potential problem w/weeds at facilities. CRANSTON, A Senate 82/10/29 KRAMMERER, C Office of Congressional Affairs 3pp 18893 036 24X Fiche 50-206, 83/04/14, 8306160052
- 8306160069 FOIA request for Chairman Palladino 810930 memo referenced in 821210 FR notice of proposed rulemaking 47FR2876 & 2877, "Environ Qualification of Electrical Equipment for Nuclear Power Plants". NEWMAN, K A Debevoise & Liberman 83/03/28 FELTON, J M Division of Rules and Records 1p 18872 357
- 8306160070 Addl response to FOIA request for records prepared by US govt employees re Alliance for Survival, T Carpenter &/or ongoing NRC investigation of facilities IE Insp Repts 50-206/82-31, 50-361/82-31 & 50-362/82-27 available in PDR. FELTON, J M Division of Rules and Records 83/04/28 CARPENTER, T Orange County Alliance for Survival 2pp 18892 338 24X Fiche 50-206, 83/04/28, 8306160070
- 8306160073 Responds to FOIA request for Chairman Palladino 810930 memo referenced in 821210 FR notice of proposed rulemaking 47FR2876 & 2877, "Environ Qualification of Electrical Equipment for Nuclear Power Plants" Forwards memo. FELTON, J M Division of Rules and Records 83/04/25 NEWMAN, K A Debevoise & Liberman 1p 18872 360
- 8306160078 FOIA request for eight categories of records re certain sys in C-E designed nuclear power plants. BELL, N Coalition for Safe Power 83/03/31 Office of Administration 4pp 18893 203
- 8306160081 Responds to FOIA request for eight categories of records re certain sys in C-E designed nuclear power plants forwards App A documents identified in Categories 5 & 6 Category B document not located Remaining documents filed in NRR. FELTON, J M Division of Rules and Records 83/04/19 BELL, N Coalition for Safe Power 4pp 18893 204 24X Fiche 50-317, 83/04/19, 8306160081
- 8203090638 Advises that three listed accident classes may each be more frequent than Commission safety goal in C-E designs that lack capability for core cooling via HPI injection & venting of RCS absence of feedwater replenishment. ROHSOME, F Division of Risk Analysis MURPHY, J A Reactor Risk Branch 82/01/29 TEDESCO, R Assistant Director for Licensing SPEIR, T Assistant Director for Reactor Safety 23pp 18894 200
- 8306160083 Submits daily highlight re diesel generator failures at facility on 820603 Incident caused by paralleling of diesel generators w/buses powered from offsite source licensee investigating incident. JAFFE, D H Operating Reactors Branch 3 82/06/04 DENTON, H R, CARTER, J, EISENHUT, D O NRC - No Detailed Affiliation Given 1p 18894 229 24X Fiche 50-317, 83/04/19, 8306160083
- 8306160093 Addl response to FOIA request for documents re IAEA nuclear mat'l safeguards program Forwards App A documents App B Documents 1-8 entirely withheld & Documents 9-16 partially withheld (ref FOIA Exemptions 1, 3 & 5). FELTON, J M Division of Rules and Records 83/04/01 GREENBERG, E V Tuttle & Taylor 3pp 18892 011

NONDOCKETED ITEMS

407

- 8306160107 Forwards suggested questions & answers for 811202 hearing re IAEA safeguards, per request
SHEA, J R Office of International Programs, Director 81/12/01
QILINSKY, V Commissioners 7pp 18892 018
- 8306160112 Advises that Congressmen Dingell, Ottinger & Hart 811125 ltr classified as "SECRET-NSI" & 811130 ltr unclassified, per 811130 request Draft response to 811125 ltr will be forwarded separately W/o encl marked-up 811125 ltr
REHM, T A NRC - No Detailed Affiliation Given 81/12/08
REARER, C W NRC - No Detailed Affiliation Given 1p 18892 025
- 8306160115 Draft Commission paper proposing ltr from Chairman thanking TE Shea for suggestions on improving IAEA safeguards & informing Commission that TE Shea ltr sent to State Dept
DIRCKS, W J Office of the Executive Director for Operations 82/01/27 16pp 18892 026
- 8306160118 Forwards undisputed portion of response to 811125 ltr re IAEA safeguards sys, supplementing Commission 820302 ltr
BRADFORD, P A Commissioners 82/03/04 OTTINGER, R L House of Rep , Energy & Commerce HART, G Senate DINGELL, J D House of Rep 2pp 18892 042
- 8306160125 Forwards Q Hart, MB Kratzer, L Scheinman, P Leventhal & HD Sokolski testimonies & prepared statements at 830303 joint hearing of Committee on Foreign Affairs re IAEA safeguards
KAMMERER, C Office of Congressional Affairs 82/03/09
PALLADINO, N J , QILINSKY, V , BRADFORD, P A Commissioners 4pp 18892 044
- 8306160131 Testimony of Q Hart before Subcommittee on Intl Economic Policy & Trade, Committee on Foreign Affairs, US House of Representatives re IAEA safeguards Committee 820301 revised meeting notice encl
HART, G Senate 82/03/03 4pp 18892 048
- 8306160134 Statement of MB Kratzer before Subcommittees on Intl Security & Scientific Affairs & Intl Economic Policy & Trade, Committee on Foreign Affairs, US House of Representatives re IAEA safeguards
KRATZER, M D International Energy Associates, Ltd 82/03/03 35pp 18892 052
- 8306160138 Prepared statement of L Scheinman before Subcommittee on Intl Economic Policy & Trade, Committee on Foreign Affairs, US House of Representatives re IAEA safeguards
SCHEINMAN, L Cornell Univ 82/03/03 17pp 18892 087
- 8306160143 Testimony of P Leventhal before Committee on Foreign Relations, US House of Representatives re IAEA safeguards
LEVENTHAL, P Nuclear Club, Inc , The 82/03/03 10pp 18892 110
- 8306160148 Prepared Statement of HD Sokolski before Subcommittee on Intl Security & Scientific Affairs & Subcommittee on Intl Economic Policy & Trade, Committee on Foreign Affairs, US House of Representatives re IAEA safeguards
SOKOLSKI, H D Heritage Foundation 82/03/03 10pp 18892 120
- 8306160153 Responds to 820420 ltr re IAEA safeguards NRC actively examining effective ways & means to continue support for IAEA safeguards
PALLADINO, N J Commissioners 82/06/10 BLIX, H International Atomic Energy Agency (Austria), 1p 18892 130
- 8306160156 Forwards summary of IAEA safeguards sys US support for IAEA safeguards crucially important
BLIX, H International Atomic Energy Agency (Austria) 82/04/20
PALLADINO, N J Commissioners 4pp 18892 131
- 8306160162 Comments on proposed Commission paper & ltr to Dept of State re classification of Morgan rept Proposed Commission paper unnecessary Proposed ltr to Dept of State should be modified W/o encl redraft ltr
BRADY, R J Division of Security 82/04/26 SHEA, J R Office of International Programs, Director 1p 18892 135
- 8306160166 Forwards draft Romania safeguards analysis for review & comment Response requested by 820524 W/o encl
SHERR, T S Material Transfer Safeguards Licensing Branch 82/05/19
ZIMMERMAN, J Office of International Programs, Director BURNETT, B., MCCORKLE, G Division of Safeguards. 1p 18892 136
- 8306160175 Forwards draft safeguards country analysis for Pakistan Analysis based on unclassified & foreign intelligence info provided by State Dept CIA or DOE repts not included W/o encl
DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director 82/05/24 PALLADINO, N J , QILINSKY, V , AHEARNE, J F Commissioners 1p 18892 137
- 8306160178 Forwards revised safeguards country analysis for Romania, including changes to reflect JQ Davis comments Section 3.3 on nuclear trade w/other countries changed in response to comments from Ofc of Intl Programs W/o encl
BURNETT, R F Division of Safeguards 82/06/16 DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director 1p 18892 138
- 8306160182 Forwards draft safeguards analysis for Romania, incorporating comments from Ofc of Intl Programs Updated analysis will be provided after receipt of comments from State Dept W/o encl
DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director 82/06/30 DIRCKS, W J Office of the Executive Director for Operations 1p 18892 139
- 8306160185 Forwards draft safeguards analysis for Romania, incorporating comments from Ofc of Intl Programs Analysis based on unclassified info & classified foreign intelligence info provided by State Dept W/o encl
DIRCKS, W J Office of the Executive Director for Operations 82/07/12 PALLADINO, N J , QILINSKY, V , AHEARNE, J F Commissioners 1p 18892 140
- 8306160190 Forwards revised draft safeguards analysis for Romania for transmission to State Dept No sensitive foreign intelligence info employed W/o encl Partially deleted answers & questions re IAEA safeguards encl
BURNETT, R F Division of Safeguards 82/07/15 SHEA, J R Office of International Programs, Director 5pp 18892 141
- 8306160193 SECY-82-025
Forwards H Gruemm preliminary comments on Morgan memo re IAEA safeguards for 81117 press conference SECY title & other safeguards info deleted
DIRCKS, W J Office of the Executive Director for Operations 82/01/19 8pp 18892 146
- 8306160198 SECY-82-046
Informs Commission of existing interagency groups involved in US efforts to upgrade IAEA safeguards & provides brief rept on status of activities W/o encl outline & status of action plan
DIRCKS, W J Office of the Executive Director for Operations 82/02/02 13pp 18892 154
- 8306160203 Discusses implications of R Richter testimony before Senate Foreign Relations Committee & House Foreign Affairs Committee re Iraqi nuclear program & weaknesses in IAEA safeguards Safeguards info deleted
DIRCKS, W J Office of the Executive Director for Operations 82/03/09 BRADFORD, P A Commissioners 3pp 18892 167
- 8306160208 SECY-82-210
Forwards summary of significant NRC & Executive Branch efforts to improve IAEA safeguards & estimate of expended resources Safeguards info deleted W/o encl rept on US assistance to IAEA & outline of areas needing improvements
DIRCKS, W J Office of the Executive Director for Operations 82/05/26, 17pp 18892 170
- 8306160211 Forwards partially released transcript of 820602 briefing on efforts to improve IAEA safeguards in Washington, DC Withheld portions per 10CFR9 104(a)(1) listed
CHILK, S J Office of the Secretary of the Commission. 82/08/03
Office of the Secretary of the Commission 2pp 18892 187
- 8306160216 SECY-82-313
Informs Commission of receipt of Dept of State 820702 ltr re classification of Morgan rept, State agrees that rept should be classified "secret" Safeguards info deleted W/o listed encls
DIRCKS, W J Office of the Executive Director for Operations 82/07/26 2pp 18892 282
- 8306160222 Draft Commission paper recommending Commission approval of proposed responses to Senator Hart & Representatives Dingell & Ottinger 821125 & 30 ltrs re IAEA safeguards Safeguards info deleted W/o encl proposed ltrs
DIRCKS, W J Office of the Executive Director for Operations 81/12/31, 1p 18892 284
- 8306160098 FDIA request for insp repts & responses to insp repts for all Pharmatopes, Inc nuclear pharmacies licensed by NRC.
MCDONALD, D D Nuclear Pharmacy, Inc DDM 383-12 83/03/16
FELTON, J M Division of Rules and Records 1p 18891 244

NONDOCKETED ITEMS

- 8306160110 Partial response to FOIA request for insp repts & responses to insp repts for all Pharmatopes, Inc nuclear pharmacies licensed by NRC Forwards App A documents Search for other related documents continuing
FELTON, J M Division of Rules and Records 83/04/14 DESSEL, B Nuclear Pharmacy, Inc 4pp 18891 243
- 8306160124 IE Insp Rept 30-18918/81-01 on 810720 Noncompliance noted possession of Xe-133 not authorized by Doctors Hosp license, CRN signs not posted on premises & survey matls disposal not recorded
CAIN, C L Region 4, Dallas, Office of the Director (81/03/01) 81/09/01 9pp 18891 249
- 8306160132 Forwards IE Insp Findings & Licensee Act of License 33-19583-01MD Signature required agreeing to correction of violations within 30 days W/o encl
CAIN, C L Technical Inspection Branch 81/07/30 LAHN, J M Pharmatopes, Inc 1p 18891 258
- 8306160139 Responds to NRC 801215 ltr re violations noted in IE Insp Rept 30-14826/80-01 Corrective actions individual receiving overexposure to hands terminated & overexposure reprimand submitted Protests imposition of civil penalties
HEBNER, M T, IRWIN, R Pharmatopes, Inc 81/01/06 Region 1, Philadelphia, Office of the Director 33pp 18891 281
- 8306160149 FOIA request for SECY-82-499
COMER, E Edison Electric Institute, 83/04/04 FELTON, J M Division of Rules and Records 1p 18893 198
- 8306160151 Responds to FOIA request for SECY-82-499 Forwards transmittal memo attached to SECY paper Requested document available in PDR W/o encl
FELTON, J M Division of Rules and Records 83/04/28 COMER, E Edison Electric Institute 1p 18893 199
- 8306160155 FOIA request for four categories of documents re McRae-Edison Co, Worthington Compressors, Inc, Worthington Svc Corp & Edison Intl
ADRAGNA, J M Spiegel & McDiarmid 83/04/04 FELTON, J M Division of Rules and Records 2pp 18893 200
- 8306160160 Responds to FOIA request for four categories of documents re McRae-Edison Co, Worthington Compressors, Inc, Worthington Svc Corp & Edison Intl, Inc NRC has no documents subj to request
FELTON, J M Division of Rules and Records 83/04/27, ADRAGNA, J M Spiegel & McDiarmid 1p 18893 202
- 8306160171 Final response to FOIA request for documents concerning NRC policy re issuance of press releases in connection w/ enforcement & licensing activities Forwards partial Document 2 listed in app Document 1 available in PDR
FELTON, J M Division of Rules and Records 83/04/27 HARTMAN, B Debevoise & Liberman, 2pp 18892 347
- 8306160173 Discusses specific guidelines for release of info to news media by Ofc of Investigation personnel. Instructions should not be construed as contradicting any other stated NRC policy Info partially deleted
* Office of Investigation 83/04/27 Office of Investigation 2pp 18892 350
- 8306160174 FOIA request for all correspondence from RO McClintock to NRC since 830314.
MCDONALD, D D Nuclear Pharmacy, Inc DDM 483-B 83/04/06 FELTON, J M Division of Rules and Records 1p 18892 352
- 8306160177 Responds to FOIA request for all correspondence from RO McClintock to NRC since 830314 Forwards RO McClintock 830411 ltr
FELTON, J M Division of Rules and Records 83/04/25 MCDONALD, D D Nuclear Pharmacy, Inc 1p 18892 353
- 8306160179 Advises that author no longer responsible for radiation safety & regulatory affairs program for Nuclear Pharmacy, Inc as of 830317.
MCDONALD, R O, Affiliation Unknown 83/04/11 DELMEDICO, J Office of Fuel Cycle & Material Safety 1p 18892 354
- re SECY-82-306 & SECY-82-499
*, Leiby & MacRae 83/03/24 FELTON, J M 1p 18876 297.
- West for SECY-82-306 & Y-82-499 published available in PDR Forwards notes.
ords 83/04/28 DIBBLE, C B 8876 298
- 8209210593 Requests proposed reg guide re nuclear energy liability policy & related rule mod be prepared in final form, pointing out potential for protracted licensing hearings resulting from deletion of 10CFR140, App A
DIRCKS, W J Office of the Executive Director for Operations 82/09/15 KERR, W G Office of State Programs, Director 1p 18876 299
- 8306160192 FOIA request for documents re FOIA Request 82-6189 Requests fees be waived
GARDE, B P Government Accountability Project 83/03/24 Office of Administration 2pp 18893 123
- 8306160197 Responds to FOIA request for documents re FOIA Request 82-618 Forwards App A documents Documents 18 & 19(d) partially deleted (ref FOIA Exemption 4)
FELTON, J M Division of Rules and Records 83/04/25 GARDE, B P Government Accountability Project 4pp 18893 125 24X Fiche 50-206, 83/04/25, 8306160197
- 8306160200 Forwards FOIA request Releasability determinations indicated in response ltrs to requester No action required
FELTON, J M Division of Rules and Records 83/03/24 DIETCH, R Southern California Edison Co 1p 18893 129 24X Fiche 50-206, 83/04/25, 8306160197
- 8306160200 Forwards FOIA request Releasability determinations indicated in response ltrs to requester No action required
FELTON, J M Division of Rules and Records 83/03/24 DIETCH, R Southern California Edison Co 1p 18893 129 24X Fiche 50-206, 83/04/25, 8306160197
- 8306160204 Requests disclosure determination for listed document subj to FOIA Request 82-618 by noon on 830314
GRIMSLEY, D H Division of Rules and Records 83/03/11 ALEXANDER, I Region 5, Office of Director 1p 18893 140
- 8306160209 Requests disclosure determination for listed documents subj to FOIA Request 82-618
GRIMSLEY, D H Division of Rules and Records 83/02/07 ALEXANDER, I Region 5, Office of Director 2pp 18893 148 24X Fiche 50-206, 83/04/25, 8306160197
- 8306160218 Forwards documents re B Garde FOIA request, on behalf of EE Kent, for documents regarding 821120 IE rept "Special NRC Insp of San Onofre 1, 2 & 3 (FOIA-82-618)" W/o encl
FORTUNA, R A Office of Investigation 83/01/24 CARR, J C Division of Rules and Records 3pp 18893 150 24X Fiche 50-206, 83/04/25, 8306160197
- 8306160223 Request disclosure determination for document originated by Ofc re FOIA Request 82-618 by noon on 830119
CARR, J C Division of Rules and Records 83/01/12 WILSON, V Office of Nuclear Reactor Regulation, Director 2pp 18893 157 24X Fiche 50-206, 83/04/25, 8306160197
- 8306160230 Submits list of Region V Ofc of Investigation File Serials 26-42, "BONOB-Allegations Re Welding of Piping by EE Kent," Case 3-82-021 Serials 1-23 previously provided in response to FOIA Request 82-328
SHACKLETON, D C Office of Investigation 83/01/03 FORTUNA, R A Office of Investigation 3pp 18893 159 24X Fiche 50-206, 83/04/25, 8306160197
- 8306160243 Forwards list of documents available at Region V re B Garde FOIA Request 82-618 on EE Kent behalf, for documents concerning 821130 IE rept "Special NRC Insp of San Onofre 1, 2 & 3"
ALEXANDER, I Region 5, Office of Director 83/12/28 REED, C A Division of Rules and Records 3pp 18893 162 24X Fiche 50-206, 83/04/25, 8306160197
- 8306160253 Forwards DC Shackleton 821109 memo transmitting documents subj to FOIA Request 82-328 Review of Documents 1, 2, 10 & 19 by Region V recommended Confidentiality not sought by EE Kent
FORTUNA, R A Office of Investigation 82/12/10 CARR, J C Division of Rules and Records 1p 18893 165 24X Fiche 50-206, 83/04/25, 8306160197
- 8306160263 Forwards list of documents responsive to FOIA Request 82-328 re EE Kent allegations concerning facilities from Oct 1980 to present Region V not aware of allegation until Oct 1982
SHACKLETON, D C Region 5, Office of Director 82/11/09 FORTUNA, R A Office of Investigation 3pp 18893 166 24X Fiche 50-206, 83/04/25, 8306160197

NONDOCKETED ITEMS

409

- 8306160276 Requests info responsive to FOIA Request 82-528 for documents re EE Kent allegation concerning facilities from Oct 1980 to present be forwarded to Div of Rules & Records by 821116
CARR, J C Division of Rules and Records 82/11/04 KINE, C Director's Office, Office of Inspection and Enforcement ALEXANDER, I Region 5, Office of Director BOWERS, H Office of Inspector & Auditor 1p 18893 171 24X Fiche 50-206, 83/04/25, 8306160197
- 8306160281 Forwards list of documents responsive to FOIA Request 82-528 re EE Kent allegations concerning facilities from Oct 1980 to present, per 821104 memo Related info encl ENGELKEN, R H Region 5, Office of Director 82/11/17 CARR, J C Division of Rules and Records 5pp 18893 174 24X Fiche 50-206, 83/04/25, 8306160197
- 8306160292 FOIA request for tape recording & NRC transcript of meeting w/D Hirsch, O Shackleton & P Joukoff at Dana Point, CA KENT, E E Affiliation Unknown 82/11/08 Office of Administration 8pp 18893 187
- 3306160301 Forwards FOIA Request 82-618 for documents re 821130 IE rept "Special NRC Insp of San Onofre 1, 2 & 3" Documents responsive to request should be forwarded to Div of Rules & Records by 830104
CARR, J C Division of Rules and Records 82/12/22 FORTUNA, R Office of Inspector & Auditor ALEXANDER, I Region 5, Office of Director 1p 18893 193 24X Fiche 50-206, 83/04/25, 8306160197
- 6170084 FOIA request for five categories of documents re Matl/Byproduct License 20-00297-53 Fee waiver requested
RICE, J C Affiliation Unknown 83/03/18 Office of Administration 2pp 18908 056
- 6170089 Responds to FOIA request for five categories of documents re Matl/Byproduct License 20-00297-53 Forwards listed documents License Amend 18 & documents identified by Items 2 & 3 cannot be located
ELTON, J M Division of Rules and Records 83/04/14 RICE, J C Affiliation Unknown 1p 18908 058
- 009030104 Application for amend of Matl/Byproduct License 20-00297-53 Amend authorizes individuals approved by radiation safety committee to use or supervise use of Cm-244 in sealed sources for surface analysis & calibr
SHAPIRO, J Harvard Univ 80/07/10 3pp 18908 115
- 310070140 Matl/Byproduct License 20-00297-53 for President & Fellows of Harvard College is amended per 800710 application Amend 32 adds 50 mCi of Pu-244 sealed sources for R&D defined in 10CFR30.4(g)
LAMASTRA, M A Licensing Management Branch 80/09/04 1p 18908 062
- 106170097 Amend 34 to Matl/Byproduct License 20-00297-53, changing license name & address, per 821119 ltr
GLENN, J E Region 1, Office of Director 82/11/30 1p 18908 059
- 06170099 Amend 33 to Matl/Byproduct License 20-00297-53, changing Items 4, 7 & 8, authorizing use of listed matl & revising Condition 19 re possession & use of licensed matl, per 810710 ltr
4 Division of Fuel Cycle & Material Safety 81/09/04, 2pp 82908 060
- 06170152 Amend 31 to Matl/Byproduct License 20-00297-53, changing Condition 20, authorizing use of 15 mCi Ni-63 at research lab at Harvard Forest, per 771118 ltr
MADE, I Radioisotopes Licensing Branch (Pre 790501) 77/12/01 1p 18908 063
- 76170155 Amend 30 to Matl/Byproduct License 20-00297-53, changing Condition 10 re use of licensed matl, per 770614 ltr
BOWYER, J E Radioisotopes Licensing Branch (Pre 790301) 77/06/30 1p 18908 064
- 76170157 Amend 29 to Matl/Byproduct License 20-00297-53, changing Condition 10 re use of licensed matl, per 791107 ltr
MVIS, F C Division of Fuel Cycle & Material Safety 75/12/22 p 18908, 065
- 16170160 Amend 28 to Matl/Byproduct License 20-00297-53, adding Cm-244 sealed sources for R&D use, per 750110 application
MVIS, F C NRC - No Detailed Affiliation Given 75/03/26 1p 8908 066
- 8306170167 Amend 27 to Matl/Byproduct License 20-00297-53, changing license in entirety, per 740222 ltr & 740409 application Amend authorizes use of any byproduct matl between Atomic Numbers 3-83, tritium, Po-210, Th-228, Am-241 & Cf-252
BOWYER, J E Atomic Energy Commission, Directorate of Licensing 74/03/02 5pp 18908 067
- 8306170170 Amend 26 to Matl/Byproduct License 20-00297-53, changing Condition 10 re use of byproduct matl, per 720907 ltr
BOWYER, J E Atomic Energy Commission, Directorate of Licensing 73/03/13 1p 18908 072
- 8306170174 Amend 25 to Matl/Byproduct License 20-00297-53, changing Subitems 7 F & 8 F, authorizing use of 5.6 mCi sealed sources (ORNL platinum foil & SRD type ALC or SACL), per 710427 ltr
BOWYER, J E Atomic Energy Commission 71/03/21 1p 18908 073
- 8306170178 Amend 24 to Matl/Byproduct License 20-00297-53, adding Condition 23, authorizing use of C-14 at Lynn Harbor, MA, per 701022 & 1103 ltrs
BOWYER, J E Atomic Energy Commission 70/11/27 1p 18908 074
- 8306170185 Amend 23 to Matl/Byproduct License 20-00297-53, changing Condition 20 re possession & use of byproduct matl & adding Condition 22, authorizing burial of byproduct matl at Primate Ctr in Southboro, MA, per 690305 ltr
BOWYER, J E Atomic Energy Commission 69/07/08 1p 18908 075
- 8306170190 Amend 22 to Matl/Byproduct License 20-00297-53, changing license in entirety, per 690130 application Amend authorizes any byproduct matl between Atomic Numbers 3-83, tritium, Po-210, Th-228, Am-241 & Cf-252 for R&D
BOWYER, J E Atomic Energy Commission 69/03/24 6pp 18908 076
- 8306170194 Amend 21 to Matl/Byproduct License 20-00297-53, changing Subitem 8 F to read 55.9 uCi
BUCHANAN, C R Atomic Energy Commission 68/07/18 1p. 18908 082
- 8306170198 Amend 20 to Matl/Byproduct License 20-00297-53, adding Cf-252 platinum foil for R&D, per 680701 telegram
BOWYER, J E Atomic Energy Commission 68/07/03 1p 18908 083
- 8306170203 Amend 19 to Matl/Byproduct License 20-00297-53, changing Condition 18, authorizing disposal of licensed matl w/ listed exception & revising Condition 20 re possession & use of byproduct matl, per 680506 & 15 ltrs
BOWYER, J E Atomic Energy Commission 68/06/27 2pp 18908 084
- 8306170208 Amend 17 to Matl/Byproduct License 20-00297-53, changing license in entirety, per 670223 application Amend authorizes any byproduct matl between Atomic Numbers 3-83 inclusive, tritium, Po-210, Th-228 & Am-241 for R&D use
BOWYER, J E Atomic Energy Commission 67/03/30 5pp 18908 086
- 8306170212 Amend 16 to Matl/Byproduct License 20-00297-53, adding Condition 23 authorizing use of 1 mCi C-14 source at Youngstown Sheet & Tube Co. Campbell Works in Youngstown, OH, per 670216 ltr
BOWYER, J E Atomic Energy Commission 67/03/03 1p 18908 091
- 8306170220 Amend 15 to Matl/Byproduct License 20-00297-53, changing Condition 11, authorizing use of byproduct matl at specified locations, per 660606 ltr
BOWYER, J E Atomic Energy Commission 66/07/11 1p 18908 092
- 8306170225 Amend 14 to Matl/Byproduct License 20-00297-53, changing Condition 21 re transportation vehicle of licensed matl, per 660415 ltr
BOWYER, J E Atomic Energy Commission 66/03/16 1p 18908 093
- 8306170229 Amend 13 to Matl/Byproduct License 20-00297-53, adding Am-241 in any form for R&D, per 651130 ltr
BUCHANAN, C R Atomic Energy Commission 65/12/08 1p. 18908 094
- 8306170235 Amend 12 to Matl/Byproduct License 20-00297-53, adding Condition 22, authorizing use of 1 mCi C-14 source at Pittsburgh Steel Co. Monessen Works in Monessen, PA, per 651020 ltr
BOWYER, J E Atomic Energy Commission 65/11/08 1p 18908 095
- 8306170238 Amend 11 to Matl/Byproduct License 20-00297-53, changing license in entirety, per 650730 ltr Amend authorizes any byproduct matl between Atomic Numbers 3-83 inclusive, tritium, Po-210 & Th-228 for R&D
BOWYER, J E Atomic Energy Commission 65/09/17 6pp. 18908 096

NONDOCKETED ITEMS

- 8306170242 Amend 10 to Matl/Byproduct License 20-00297-53, adding Condition 24, authorizing use of 1 mCi C-14 source at Jones Laughlin Steel Corp, South Works in Pittsburgh, PA, per 650709 & 21 ltrs
BOHYER, J E Atomic Energy Commission 65/07/28 1p 18908 102
- 8306170244 Amend 9 to Matl/Byproduct License 20-00297-53, changing Condition 17, authorizing disposal of licensed matl w/ listed exception, per 650325 ltr
BOHYER, J E Atomic Energy Commission 65/03/07 1p 18908 103
- 8306170248 Amend 8 to Matl/Byproduct License 20-00297-53, changing symbol below license number to C67, extending expiration date to 670331 & revising Item 9 A-9 D, per 650217 ltr & application
BOHYER, J E Atomic Energy Commission 65/03/31 1p 18908 104
- 8306170252 Amend 7 to Matl/Byproduct License 20-00297-53, changing Condition 11, authorizing use of byproduct matl at specified locations, per 650125 application & ltr
BOHYER, J E Atomic Energy Commission 65/03/09 1p 18908 105
- 8306170258 Amend 6 to Matl/Byproduct License 20-00297-53, changing Item 8 A re possession limit of byproduct matl, per 641106 ltr
BOHYER, J E Atomic Energy Commission 64/12/01 1p 18908 106
- 8306170262 Amend 5 to Matl/Byproduct License 20-00297-53, changing Condition 11, authorizing use of byproduct matl at specified locations, per 641015 ltr
BOHYER, J E Atomic Energy Commission 64/11/04 1p 18908 107
- 8306170267 Amend 4 to Matl/Byproduct License 20-00297-53, changing Condition 21 re possession & use of byproduct matl, per 640901 ltr
BOHYER, J E Atomic Energy Commission 64/09/30 1p 18908 108
- 8306170269 Amend 3 to Matl/Byproduct License 20-00297-53, adding Condition 23, authorizing use of P-32 at Drumlin Farm in Lincoln, MA to study habitat selection of queen ants & foraging patterns of worker ants, per 640624 & 0803 ltrs
BOHYER, J E Atomic Energy Commission 64/08/25 1p 18908 109
- 8306170272 Amend 2 to Matl/Byproduct License 20-00297-53, adding Condition 22 re transportation of byproduct matl, per 640326, 0611 & 16 ltrs
BOHYER, J E Atomic Energy Commission 64/08/04 1p 18908 110
- 8306170274 Amend 1 to Matl/Byproduct License 20-00297-53, adding Condition 18, authorizing use of byproduct matl at specified locations, changing Condition 17 re disposal of radwastes & deleting Conditions 18 & 19, per 631108 ltr
BOHYER, J E Atomic Energy Commission 63/12/06 1p 18908 111
- 8306170280 Matl/Byproduct License 20-00297-53 for President & Fellows of Harvard College, authorizing any byproduct matl between Atomic Numbers 3-83, inclusive in any form for R&D
BOHYER, J E Atomic Energy Commission 63/06/19 3pp 18908 112
- 8306170284 Returns application for renewal of Matl/Byproduct License 20-00297-53 for signature
BOHYER, J E Atomic Energy Commission, Directorate of Licensing 43606 74/04/02 SHAPIRO, J Harvard Univ 1p 18908 118
- 8306170288 Ack receipt of application for renewal of Matl/Byproduct License 20-00297-53 License will not expire until final action taken by AEC
BOHYER, J E Atomic Energy Commission, Directorate of Licensing 74/03/21, JOHNSON, R U Harvard Univ 1p 18908 119
- 8306170291 Forwards application for renewal of Matl/Byproduct License 20-00297-53 for use of radioisotopes
JOHNSON, R U Harvard Univ 43606 74/02/22 BOHYER, J E Atomic Energy Commission 1p 18908 120
- 8306170295 Application for renewal of Matl/Byproduct License 20-00297-53, authorizing individuals approved by radioisotope committee to use any byproduct matl between Atomic Numbers 3-83, tritium, Po-210, Am-241, Th-228, Cf-252 for R&D
SHAPIRO, J Harvard Univ 43606 74/04/09 22pp 18908 121
- 8306170298 "Regulations for Use of Radioisotopes at Harvard Univ" Related info encl.
* Harvard Univ 43606 74/04/09 28pp 18908 143
- 8306200035 FOIA request for blueprints & explanations of assorted power plants
SPECTOR, B. Affiliation Unknown, 83/03/08 NRC - No Detailed Affiliation Given 1p 18919 319
- 8306200037 Responds to FOIA request for blueprints & explanations of assorted power plants Forwards documents describing safety & NRC licensing process for reactors Drawings & design details available in listed LPDRs in NY
FELTON, J M Division of Rules and Records 83/05/18 SPECTOR, B Affiliation Unknown 2pp 18919 320
- 8306200040 WASH-1250
Excerpt from WASH-1250, "Safety of Nuclear Power Reactors (Light Water-Cooled) & Related Facilities"
* NRC - No Detailed Affiliation Given 83/05/18 39pp 18919 322
- 8306200041 "Reactor Licensing Process"
* Office of Public Affairs 80/11/30 6pp 18919 361
- 8306200273 FOIA request for records re Book Mart Intl, Inc & DL Hall
TRUITT, M O, DANA, J T Wilner, Cutler & Pickering 83/04/13 Office of Administration 3pp 18919 223
- 8306200277 Responds to FOIA request for records re Book Mart Intl, Inc & DL Hall Forwards documents listed in app Documents also available in PDR
FELTON, J M Division of Rules and Records 83/04/28 TRUITT, M O, DANA, J T Wilner, Cutler & Pickering 2pp 18919 226
- 8306200280 Discusses corporate structure & svcs provided by Book Mart Intl, Inc Related info encl
HALL, D L Book Mart International, Inc 83/04/28 NRC No Detailed Affiliation Given 9pp 18919 228
- 8306200282 Ack NRC interest in Book Mart Intl, Inc Brochures & newsletter encl
HALL, D L Book Mart International, Inc 83/04/28 NRC No Detailed Affiliation Given 4pp 18919 237
- 8306200284 Requests execution of blanket purchase order w/Book Mart Intl, Inc for scientific texts & medical books
HAMILTON, M, DEVINE, B NRC - No Detailed Affiliation Given 80/09/01 1p 18919 241
- 8306200286 Requests availability of funds for library book acquisitions from Book Mart Intl, Inc Related info encl
MURPHY, L G Administrative Contracts Branch 80/10/30 COOPER, L P Administrative Contracts Branch 16pp 18919 242
- 8306200287 Requests cancellation of Blanket Purchase Agreement DR-B1-0181 w/Book Mart Intl Company apparently out of business Related info encl
DEVINE, R E NRC - No Detailed Affiliation Given 81/04/28 2pp 18919 258
- 8306200288 Discusses corporate structure & svcs provided by Book Mart Intl, Inc Related info encl
HALL, D L Book Mart International, Inc 83/04/28 NRC No Detailed Affiliation Given 9pp 18919 228
- 8306200289 Ack NRC interest in Book Mart Intl, Inc Brochures & newsletter encl
HALL, D L Book Mart International, Inc 83/04/28 NRC No Detailed Affiliation Given 4pp 18919 237
- 8306200284 Requests execution of blanket purchase order w/Book Mart Intl, Inc for scientific texts & medical books
HAMILTON, M, DEVINE, B NRC - No Detailed Affiliation Given 80/09/01 1p 18919 241
- 8306200286 Requests availability of funds for library book acquisitions from Book Mart Intl, Inc Related info encl
MURPHY, L G Administrative Contracts Branch 80/10/30 COOPER, L P Administrative Contracts Branch 16pp 18919 242
- 8306200287 Requests cancellation of Blanket Purchase Agreement DR-B1-0181 w/Book Mart Intl Company apparently out of business Related info encl
DEVINE, R E NRC - No Detailed Affiliation Given 81/04/28 2pp 18919 258
- 8306200291 Informs that response to Seacoast Anti-Pollution League 830328 FOIA request has not been received Statute requires response within 10 working days Prompt attention appreciated
BACKUS, R A Backus, Shea & Meyer 83/05/06 Division of Rules and Records 1p 18920 027
- 8306200293 FOIA request on behalf of Seacoast Anti-Pollution League. G Speth ltr to Commissioner Ahearne on or about 800320 concerning NRC treatment of Class 9 accidents in EIS
BACKUS, R A Backus, Shea & Meyer 83/03/28 Division of Rules and Records 3pp 18920 028

NONDOCKETED ITEMS

411

8306200295 FOIA request for eight categories of documents re facility
JOHNSTON, M M Affiliation Unknown 83/04/11 Division of Rules
and Records 2pp 18920 222 24X Fiche 50-341, 83/04/11, 8306200295

8306200296 Partial response to FOIA request for ltr from G Speth to
Commissioner Ahearne on or about 860320 concerning NRC
treatment of Class 9 accidents in EIS Forwards documents
listed in app Review continuing
FELTON, J M Division of Rules and Records 83/05/16 BACKUS, R A
Bactus, Shea & Meyer 2pp 18920 031

8306200299 Partial response to FOIA request for eight categories of
documents re facility Copies of listed documents will be
provided NUREG available from NTIS
FELTON, J M Division of Rules and Records 83/05/06 JOHNSTON, M M
Affiliation Unknown 1p 18920 224 24X Fiche 50-341, 83/05/06,
8306200299

8306200434 Responds to FOIA request for NRC Investigation Rept 1-83-003
re facilities Rept withheld (ref FOIA Exemptions 5 & 7)
FELTON, J M Division of Rules and Records 83/05/02 KILCOYNE, J J
Kilcoyne, J J 1p 18920 017 24X Fiche 50-289, 83/05/02,
8306200434

8306200438 FOIA request for NRC Investigation Rept 1-83-003 re
facilities
KILCOYNE, J J Kilcoyne, J J 83/03/28 FELTON, J Division of
Rules and Records 1p 18920 018 24X Fiche 50 289, 83/03/28,
8306200438

8306210289 Responds to FOIA request for documents re NRC current,
potential or future use of line of business data published
by Federal Trade Commission No records subj to request
available
FELTON, J M Division of Rules and Records 83/04/05 BILEK, M L
Paul, Weiss, Rifkind, Wharton & Garrison 1p 18925 326

8306210293 FOIA request for documents re NRC current, potential or
future use of line of business data published by Federal
Trade Commission
BILEK, M L Paul, Weiss, Rifkind, Wharton & Garrison 83/03/29
Office of Administration 2pp 18925 327

8306210297 FOIA request for part number & pricing on recent order
awarded to Federal Sales Svc for 67 HELKO work stations
HEATH, R C Data Stor, Inc 83/03/21 MCNULTY, A Division of
Contracts 1p 18925 323

8306210300 Responds to FOIA request for part number & pricing on
recent order awarded to Federal Sales Svc for 67 HELKO work
stations Forwards NRC Purchase Order DR-83-0727
FELTON, J M Division of Rules and Records 83/04/11 HEATH, R C
Data Stor, Inc 1p 18925 324

--8306210303 Purchase Order DR-83-0727 awarded to Federal Sales Svc for
67 HELKO work stations
REBELLO, J E Administrative Contracts Branch 83/02/25 1p
18925 329

8306210306 Partial response to FOIA request for NRC records re security
violations & safeguards events at nuclear facilities Repts
listed on App A available in PDR Search for addl documents
subj to request continuing
FELTON, J M Division of Rules and Records 83/05/16 GOLDENBERG, G
Scripps-Howard Newspapers 2pp 18925 196 24X
Fiche 50-000, 83/05/16, 8306210306

8306210312 Responds to FOIA request for info re NRC involvement in
activities occurring at US Army Matl Command Firing range
NRC has no documents subj to request Request referred to DOD
for direct response
FELTON, J M Division of Rules and Records 83/05/16 HARVEY, P W
Underhill Range Committee 1p 18922 358

8306210313 FOIA request for info re NRC involvement w/activities within
 confines of US Matl Command Firing range
HARVEY, P W Underhill Range Committee 83/04/27 Office of
Administration 1p 18922 359

8306210314 FOIA request for NRC records re security violations &
safeguards events at nuclear facilities
GOLDENBERG, G Scripps-Howard Newspapers 83/04/22 FELTON, J M
Office of Administration 2pp 18925 198 24X
Fiche 50 000, 83/04/22, 8306210314

8306210318 FOIA request for all documents re proposals & revs to
proposals submitted under RFP RS-SECY-82-473
SHARP, I H Alderson Reporting 83/03/21 FELTON, J M Division of
Rules and Records 1p 18921 301

8306210320 Responds to FOIA request for all documents re proposals &
revs to proposals submitted under RFP RS-SECY-82-473
Forwards nonproprietary version of technical proposal &
certain RFP pages
FELTON, J M Division of Rules and Records 83/04/07 SHARP, I H
Alderson Reporting 1p 18921 302

--8306210323 Nonproprietary version of Proposal RS-SECY-82-473,
"Stenographic Reporting Svcs"
* Interstate Court Reporters, Inc 83/04/07 22pp 18921 303

--8306210326 Solicitation, offer & award of "Stenographic Reporting
Svcs," to Interstate Court Reporters, Inc
JACKSON, B M Interstate Court Reporters, Inc 82/08/06 5pp.
18921 325

8306210327 FOIA request for final rept on probability & consequences
of highway & rail hazardous matl accidents published Dec
1982
RESNICKOFF, M Council on Economic Priorities 83/02/21 Division
of Rules and Records 1p 18923 001

8306210327 Responds to 830221 FOIA request for final rept, "Definition
of Bounding Physical Test Representative of Transport
Accidents - Rail & Truck," & 830406 appeal re NRC lack of
response to initial request Forwards requested rept
FELTON, J M Division of Rules and Records 83/04/22 RESNICKOFF, M
Council on Economic Priorities 1p 18923 002

--8306210332 Draft Vol I to "Final Rept on Severe Rail & Truck Accidents
Toward Definition of Bounding Environments for Transportation
Packages"
* Ridihalgh, Eggers & Associates NRC-04-80-182 82/12/31
NRC - No Detailed Affiliation Given 250pp 18923 004

--8306210336 PLQ-0207 DRFT
Draft "Analysis of Severe Transportation Accident Environ
Frequencies"
SIU, N O, GARRICK, B J Pickard, Lowe & Garrick, Inc 81/09/30
81pp 18923 280

--8306210332 Draft Vol I to "Final Rept on Severe Rail & Truck Accidents
Toward Definition of Bounding Environments for Transportation
Packages"
* Ridihalgh, Eggers & Associates NRC-04-80-182 82/12/31
NRC - No Detailed Affiliation Given 250pp 18923 004

--8306210336 PLQ-0207 DRFT
Draft "Analysis of Severe Transportation Accident Environ
Frequencies"
SIU, N O, GARRICK, B J Pickard, Lowe & Garrick, Inc 81/09/30
81pp 18923 280

8306210330 Appeals NRC lack of response to & denial of FOIA request for
final rept, "Definition of Bounding Physical Test
Representative of Transport Accidents - Rail & Truck"
RESNICKOFF, M Council on Economic Priorities 83/04/06 Office of
the Executive Director for Operations 1p 18923 003

8306210340 Responds to FOIA request for names & locations of various
nuclear facilities licensed by NRC Forwards NUREG-0871,
"Summary Info Rept" W/o encl
FELTON, J M Division of Rules and Records 83/04/08 THOMAS, D M
Overseas Packing, Inc 1p 18921 330

8306210342 FOIA request for names & locations of various nuclear
facilities licensed by NRC
THOMAS, D M Overseas Packing, Inc 83/03/15 NRC - No Detailed
Affiliation Given 1p 18921 331

8306230005 Addl response to FOIA request for all drafts, insp evaluation
repts & comments on J Keppier 820719 rept re special safety
insp during May-Jul 1982 of activities at Unit 1 Forwards
documents listed in App B, Addl records under review
FELTON, J M Division of Rules and Records 83/03/25 GARDE, B
Government Accountability Project 3pp 18932 001 24X
Fiche 50-373, 83/03/25, 8306230005

--8306230012 Insp Evaluation Rept 82-35 re allegations of drilling &
const deficiencies at site Concerns resolved effectively
by licensee & NRC Related draft info encl
* NRC - No Detailed Affiliation Given RP 1206 83/03/25
265pp 18932 004, 24X Fiche 50-373, 83/03/25, 8306230005

--8306230015 Evaluation Rept on Atty General of IL allegations re
drilling & const deficiencies at site Allegations w/o merit
* Structural Engineering Branch 83/03/25 4pp 18932 269 24X
Fiche 50-373, 83/03/25, 8306230005.

NONDOCKETED ITEMS

- 8306230019 Summary of B20611 mgt meeting at site re ongoing investigation of Abt General of IL allegations concerning drilling & const problems
DAVIS, A B Region 3, Office of Director 82/06/17 Region 3, Office of Director 3pp 18952 280 24X Fiche 50-373, 83/03/25, 8306230005
- 8306230022 Discusses readiness of facility to receive DL per request initial recommendation or issuance of DL withdrawn pending further quantification & clarification of const GC issues insp evaluation & related info encl
REIMANN, F H Region 3, Office of Director 82/06/28 JACKIN, I H, WALKER, R D Region 3, Office of Director 74pp 18952 283 24X Fiche 50-373, 83/03/25, 8306230005
- 8306230024 "Assessment of Effects of Nicked Reinforcing Steel," technical rept evaluation
CHAN, B P Systematic Evaluation Program Branch 82/06/15 4pp 18952 357
- 8306230028 Forwards trip rept of 820625-26 visit to Region III & site re containment bolt installation problem Engineering discussion, recommendations & exam conclusion included HQDB, A C SPS Technologies 82/06/28 JACKIN, I H NRC - No Detailed Affiliation Given 16pp 18952 361 24X Fiche 50-373, 83/03/25, 8306230005
- 8306230031 Comments on agenda items for 820625 site meeting re technical aspects of torque wrench calibr Motor operator/ valve connection tightness check, torque wrench calibr accuracy & expansion anchor installation discussed RODABAUGH, E C E C Rodabaugh Associates, Inc 82/06/26 TERAQ, D Mechanical Engineering Branch 6pp 18953 015 24X Fiche 50-373, 83/03/25, 8306230005
- 8306230037 Forwards QA Manual 1B-1 2 audit rept Plant const satisfactory
REED, C Commonwealth Edison Co 82/07/08 KEPPLER, J D Region 3, Office of Director 1p 18953 021 24X Fiche 50-373, 83/03/25, 8306230005
- 8306230039 QA Manual 1B-1 2 audit rept Related correspondence encl HANBING, H J Commonwealth Edison Co 81/08/04 60pp 18953 022 24X Fiche 50-373, 83/03/25, 8306230005
- 8306230043 Discusses 820630, 0707 & 08 telcons re investigations of allegations concerning facilities Allegations not properly investigated & could result in "whitewash",
CUMMINGS, J J Office of Inspector & Auditor 82/07/15 DIRCKS, W Office of the Executive Director for Operations 2pp 18953 083 24X Fiche 50-373, 83/03/25, 8306230005
- 8306230051 Discusses changes in Section X of util rept resulting from consultant concerns re bolting issue Rept revised to reflect verification of procedures & data
NORELIOUS, C E Division of Engineering 82/07/19 JOBLONSKI, F J KNICELEY, J, REIMANN, F Region 3, Office of Director 3pp 18953 085 24X Fiche 50-373, 83/03/25, 8306230005
- 8306230056 Discusses results of insp of allegations considered to have potential effect on facility operation No reason evident to limit power operation at facility
KEPPLER, J D Region 3, Office of Director 82/07/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18953 088 24X Fiche 50-373, 83/03/25, 8306230005
- 8306230061 Discusses concurrence w/Section X of IE Insp Repts 50-373/82-35 & 50-374/82-06 re allegation that Morrison Co torque wrench calibr records falsified Audit not sufficiently comprehensive to draw meaningful conclusions
REIMANN, F H Region 3, Office of Director 82/07/21 Region 3, Office of Director 1p 18953 089 24X Fiche 50-373, 83/03/25, 8306230005
- 8306230065 Summarizes 820811 meeting w/N Jacklin, R Lipinski & representatives of public interest groups re affidavits submitted by bricklayers subsequent to completion of initial special insp of facility insp evaluation repts encl
NORELIOUS, C E Region 3, Office of Director 82/08/18 Region 3, Office of Director 15pp 18953 090 24X Fiche 50-373, 83/03/25, 8306230005
- 8306230006 FOIA request for 28 administrative tort claims for damage filed w/NRC by residents of Canonsburg, PA area
MONTANGE, C H Covington & Burling 83/04/29 FELTON, J, Division of Rules and Records, 2pp 18982 279
- 8306230009 Responds to FOIA request for 28 administrative tort claims for damage filed w/NRC by residents of Canonsburg, PA area Forwards requested claims & physician affidavit Documents also available in PDR
FELTON, J M Division of Rules and Records 83/05/06 MONTANGE, C H Covington & Burling 1p, 18982 281
- 8306230016 Claim for damage, injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Gofman affidavit encl
AMOROSE, M L Affiliation Unknown 83/02/20 3pp 18982 282
- 8306230018 Claim for damage, injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Gofman affidavit encl
AMOROSE, A A Affiliation Unknown 83/02/20 3pp 18982 284
- 8306230020 Claim for damage, injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Gofman affidavit encl
BADIA, A Affiliation Unknown 83/03/14 3pp 18982 287
- 8306230025 Claim for damage, injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Gofman affidavit encl,
BADIA, A Affiliation Unknown 83/03/14 3pp 18982 289
- 8306230035 Claim for damage, injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Gofman affidavit encl
BROWN, E Affiliation Unknown 83/02/21 3pp 18982 291
- 8306230038 Claim for damage, injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Gofman affidavit encl
BROWN, S H Affiliation Unknown 83/02/21 3pp 18982 294
- 8306230042 Claim for damage, injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Gofman affidavit encl
DAVIS, H H Affiliation Unknown 83/02/22 3pp 18982 297
- 8306230053 Claim for damage, injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Gofman affidavit encl
DAVIS, L K Affiliation Unknown 83/02/22 3pp 18982 300
- 8306230058 Claim for damage, injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Gofman affidavit encl
DELOST, J Affiliation Unknown 83/02/21 3pp 18982 303
- 8306230060 Claim for damage, injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Gofman affidavit encl
DELOST, T Affiliation Unknown 83/02/21 3pp 18982 306
- 8306230063 Claim for damage, injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Gofman affidavit encl
DUNN, D C Affiliation Unknown 83/02/21 3pp 18982 309
- 8306230064 Claim for damage, injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Gofman affidavit encl
DUNN, D C Affiliation Unknown 83/02/23 3pp 18982 312
- 8306230066 Claim for damage, injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Gofman affidavit encl
DUNN, K Affiliation Unknown 83/02/20 3pp 18982 315
- 8306230067 Claim for damage, injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Gofman affidavit encl
DUNN, R E Affiliation Unknown 83/02/21 3pp 18982 318
- 8306230069 Claim for damage, injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Gofman affidavit encl
DUNN, R W Affiliation Unknown 83/02/20 3pp 18982 321
- 8306230071 Claim for damage, injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Gofman affidavit encl
DUNN, W J Affiliation Unknown 83/02/23 3pp 18982 324
- 8306230072 Claim for damage, injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Gofman affidavit encl,
HERRON, M M Affiliation Unknown 83/02/22 3pp 18982 327
- 8306230076 Claim for damage, injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Gofman affidavit encl
MALARDIE, P J Affiliation Unknown 83/02/21 3pp 18982 330

NONDOCKETED ITEMS

413

- B306230077 Claim for damage, injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Gofman affidavit encl
HARTON, E J Affiliation Unknown 83/02/26 3pp 18982 333
- B306230078 Claim for damage, injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Gofman affidavit encl
HARTON, J Affiliation Unknown 83/02/16 3pp 18982 336
- B306230080 Claim for damage, injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Gofman affidavit encl
PROWITT, B M Affiliation Unknown 83/02/22 3pp 18982 339
- B306230084 Claim for damage, injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Gofman affidavit encl
SPINDOSA, E Affiliation Unknown 83/02/28 3pp 18982 342
- B306230085 Claim for damage, injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Gofman affidavit encl
SPINDOSA, I Affiliation Unknown 83/02/28 3pp 18982 345
- B306230091 Claim for damage, injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Gofman affidavit encl
TOMECSKO, M Affiliation Unknown 83/02/23 3pp 18982 348
- B306230094 Claim for damage, injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Gofman affidavit encl
TOMECSKO, P Affiliation Unknown 83/02/23 3pp 18982 351
- B306230098 Claim for damage, injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Gofman affidavit encl
WAGNER, G M Affiliation Unknown 83/02/21 3pp 18982 354
- B306230105 Claim for damage, injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Gofman affidavit encl
WAGNER, R M Affiliation Unknown 83/02/21 3pp 18982 357
- B306230109 Claim for damage, injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Gofman affidavit encl
WINSECK, S Affiliation Unknown 83/02/22 3pp 18982 360
- B306230123 FOIA request for five categories of documents re spent fuel at facilities
AUDIN, L Affiliation Unknown 83/03/05 Office of Administration 2pp 18982 045 24X Fiche 50-014, 83/03/05, B306230123
- B306230129 Responds to FOIA request for five categories of documents re spent fuel at facilities App A & B documents respond to Items 1, 2, 4 & 5 Forwards App B Documents 1 & 3-11 No documents located for Item 3
FELTON, J M Division of Rules and Records 83/04/13 AUDIN, L Affiliation Unknown 3pp 18982 047 24X Fiche 50-014, 83/04/13, B306230129
- B306230137 Part 21 rept re employee receiving dose of 30 710 rems to right hand on 800720 while removing particulate cartridge from water filter subsequent to cask flushing operation
TOY, H L Battelle Memorial Institute, Pacific Northwest Laboratory 80/08/19 KEPPLER, J O Region 3, Chicago, Office of the Director 4pp, 18982 060
- B306230139 Forwards data sheet for Part 21 Rept 80-256-000 re defect in spent fuel cask unloading procedures, per T1103/2 (Rev 1)
FISHER, W L Region 3, Chicago, Office of the Director, 80/10/21 HIGGINSBOOTHAM, L Region 3, Chicago, Fuel Facility & Materials Safety Branch 1p 18982 066
- B306230144 Forwards data sheet for Part 21 Rept 80-256-000 re defect in spent fuel unloading procedures Completed data sheet should be returned by 801001 Comments on Part 21 rept encl
HIGGINSBOOTHAM, L Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/08/27, DAVIES, A H Region 3, Chicago, Fuel Facility & Materials Safety Branch 4pp 18982 067
- B306230149 Forwards request for addl info re IE Insp Repts 70-0008/82-02, 30-05728/80-02 & 30-006/80-01 concerning problems w/NFB-4 (NAC-1E) cask, per B10226 telcon
CARLSON, R T Region 1, Philadelphia, Office of the Director 81/02/27 FISCHER, W L Region 3, Chicago, Office of the Director, 4pp 18982 071 24X Fiche 50-006, 83/04/13, B306230129.
- B306230153 Forwards addl info re IE Insp Rept 70-0008/80-02 re overflow through vent tubing, smears of floor surfaces & radiation levels w/portable instrument & removal of fuel assembly
FISCHER, W L Technical Inspection Branch 81/03/23 CARLSON, R T Director's Office, Office of Inspection and Enforcement, 3pp 18982 075
- B306230157 Forwards ANI complaint against BMI, Northeast Utils Svc Co & Connecticut Yankee Atomic Power Co re damage to shipping cask due to contamination during spent fuel shipment
SALTZMAN, J Assistant Director for State & Licensee Relations 82/03/04 CUNNINGHAM, G Office of the Executive Legal Director 1p 18982 086
- B306230161 Discusses Nuclear Assurance Corp suit against Connecticut Yankee Atomic Power Co, Northeast Utils Svc Co & BMI re damage to shipping cask due to contamination during spent fuel shipment
HARWARD, J E American Nuclear Insurers 82/02/10 SALTZMAN, J Assistant Director for State & Licensee Relations 2pp, 18982 087
- B306230166 Compliant against BMI, Connecticut Yankee Atomic Power Co & Northeast Utils Svc Co re damage to shipping cask due to contamination during spent fuel shipment
CROFT, T L, ANDERSON, A S Nuclear Assurance Corp CROFT, T L Affiliation Unknown C82-53 A 82/01/15 Unknown Affiliation 20pp 18982 089
- B306240003 FOIA request for all NRC draft & final comments or memoranda re DOE proposed general guidelines for recommendation of sites for nuclear waste repositories (48FR5670)
TOUSLEY, D R Harmon & Weiss 83/04/05 FELTON, J M Division of Rules and Records 1p 18984 050
- B306240007 Responds to FOIA request for all NRC draft & final comments or memoranda on DOE proposed general guidelines for recommendation of sites for nuclear waste repositories (48FR5670) Forwards documents listed in App A.
FELTON, J M Division of Rules and Records 83/04/25 TOUSLEY, D R Harmon & Weiss 3pp, 18984 051
- B306240011 Forwards DOE draft "Nuclear Waste Policy Act of 1982, Proposed General Guidelines for Recommendation of Sites for Nuclear Waste Repositories " Technical review initiated to provide basis for NRC concurrence/nonconcurrence
BELL, M J High Level Waste Licensing Management Branch 83/01/27 KERR, G W Office of State Programs, Director, 66pp 18984 054
- B306240016 Forwards proposed DOE Regulation 10CFR960, "Proposed General Guidelines for Recommendation of Sites for Nuclear Waste Repositories," & briefing package Comments requested by 830222 W/o encls
BELL, M J High Level Waste Licensing Management Branch 83/02/14 COMELLA, P A Division of Health, Siting & Waste Management 2pp 18984 120
- B306240020 Forwards briefing re proposed DOE Regulation 10CFR960, "Proposed General Guidelines for Recommendation of Sites for Nuclear Waste Repositories " DOE requests concurrence w/ guidelines by 830603 Comments required by 830222
BELL, M J High Level Waste Licensing Management Branch 83/02/14 BUNTING, J O Licensing Process & Integration Branch 16pp 18984 122
- B306240024 Forwards draft DOE Regulation 10CFR960, "Proposed General Guidelines for Recommendation of Sites for Nuclear Waste Repositories " W/o encl State Working Group on High Level Radwaste Mgt recommendations to DOE encl
BELL, M J High Level Waste Licensing Management Branch, 83/02/14 MILLER, H J High Level Waste Technical Development Branch, 10pp 18984 138
- B306240028 Forwards general comments re proposed DOE Regulation 10CFR960, "Proposed General Guidelines for Recommendation of Sites for Nuclear Waste Repositories," per 830214 memo
MILLER, H J High Level Waste Technical Development Branch, 83/02/24 BELL, M J High Level Waste Licensing Management Branch, 4pp 18984 150
- B306240036 Summary of 830209 meeting w/Natl Governors Assoc State Working Group re DOE proposed guidelines for siting of high level waste repositories Guidelines technically deficient.
MACDOUGALL, R D Licensing Process & Integration Branch, 83/03/02, BUNTING, J O Licensing Process & Integration Branch 3pp 18984 154
- B306240039 Comments on DOE draft siting guidelines re nomination of sites for site characterization Pending legal determination, guidelines do not fulfill requirements of Nuclear Waste Policy Act, W/stated encls.
BUNTING, J O Licensing Process & Integration Branch, 83/03/03 BELL, M J High Level Waste Licensing Management Branch, 10pp 18984 159

NONDOCKETED ITEMS

- 8306240043 Trip rept of 830304 visit to Chicago, IL for DOE public hearing on proposed general guidelines for siting high level waste repository. List of speakers & statements of chairperson & DOE representative encl
REHFELDT, W R High Level Waste Licensing Management Branch
83/03/11 BOYLE, R R High Level Waste Licensing Management Branch 15pp 18984 169
- 8306240047 Submits addl proposed guidelines to be added to DOE draft site selection guidelines w/emphasis on disqualifying factors, per 830309 telcon Backup point paper for discussion encl
BUNTING, J O Licensing Process & Integration Branch 83/03/15
BELL, M J High Level Waste Licensing Management Branch 5pp 18984 184
- 8306240051 Comments on DOE proposed general guidelines for recommendation of sites for nuclear waste repositories, per 830214 memo Guidelines generally acceptable Specific comments encl
COMELLA, P A Division of Health, Siting & Waste Management 83/03/15 BELL, M J High Level Waste Licensing Management Branch 4pp 18984 189
- 8306240053 Discusses review of tectonic environ technical guidelines in draft DOE proposed general guidelines for recommendation of sites for nuclear waste repositories. Guidelines would be difficult to apply rigorously in licensing action
SCHMITT, T J Earth Sciences Branch 83/03/11 COMELLA, P Division of Health, Siting & Waste Management 2pp 18984 193
- 8306240084 Summarizes DOE 830310 public hearing on proposed general guidelines for siting high level waste repository in Washington, DC Draft briefing & prepared statements encl
PFLUM, C O High Level Waste Licensing Management Branch
83/03/16 BOYLE, R R High Level Waste Licensing Management Branch 18pp 18984 195
- 8306240094 Trip rept of 830307 visit to New Orleans, LA for DOE public hearing on proposed general guidelines for siting high level waste repositories. Prepared statements encl
PFLUM, C O High Level Waste Licensing Management Branch
83/03/23 BOYLE, R R High Level Waste Licensing Management Branch 10pp 18984 229
- 8306240096 Forwards "Comments on Proposed General Guidelines for Recommendation of Sites for Nuclear Waste Repositories per Nuclear Waste Policy Act of 1982 before DOE," presented on 830321
SAMPSON, M R Yakima Indian Nation 83/03/24 MILLER, H J High Level Waste Technical Development Branch 1p 18984 244
- 8306240101 "Comments on Proposed General Guidelines for Recommendation of Sites for Nuclear Waste Repositories per Nuclear Waste Policy Act of 1982 before DOE"
SAMPSON, M Yakima Indian Nation 83/03/21 11pp 18984 245
- 8306240106 Trip rept of 830321 visit to Seattle, WA for DOE public hearing on proposed general guidelines for siting high level waste repository. List of scheduled speakers encl
REHFELDT, W R High Level Waste Licensing Management Branch
83/03/30 BOYLE, R R High Level Waste Licensing Management Branch 8pp 18984 256
- 8306240109 Forwards ACRS Waste Mgt Subcommittee 830318 comments on DOE proposed guidelines for recommendation of sites for nuclear waste repositories (10CFR960) & S Philbrick 830316 comments on NRC proposed rule 10CFR60
TANO, R C ACRS - Advisory Committee on Reactor Safeguards
83/04/01 BELL, M J High Level Waste Licensing Management Branch 8pp 18984 264
- 8306240112 Comments on NRC proposed rule 10CFR60 re high level waste disposal. Listed mods should be incorporated
PHILBRICK, S B Philbrick, S B 83/03/16 MOELLER, D ACRS - Advisory Committee on Reactor Safeguards 2pp 18984 272
- 8306240116 Summarizes DOE 830314 public hearing on proposed general guidelines for siting high level waste repository in Salt Lake City, UT. List of panel members, statements of chairperson & DOE representative & list of speakers encl
BOYLE, R R High Level Waste Licensing Management Branch
83/04/03 BELL, M J High Level Waste Licensing Management Branch 18pp 18984 274
- 8306240119 Summary of 830228 meeting w/DOE in Germantown, MD re 10CFR960, "Proposed General Guidelines for Recommendation of Sites for Nuclear Waste Repositories." List of attendees encl
PFLUM, C O High Level Waste Licensing Management Branch
83/04/03 BOYLE, R R High Level Waste Licensing Management Branch 6pp 18984 272
- 8306240128 Forwards Yakima Indian Nation comments on DOE proposed guidelines for recommendation of sites for repositories & requests Reg Guide 4.17, "Std Form & Content of Site Characterization for High Level Waste Geologic"
HGVIS, J B Hovic, Cockrill, Weaver & Bjor 83/04/06 KRIGHI, R J Basalt Waste Isolation Project 2pp 18984 298
- 8306240131 "Written Comments on Proposed General Guidelines for Recommendation of Sites for Nuclear Waste Repositories, per Nuclear Waste Policy Act of 1982 Before DOE"
* Yakima Indian Nation 83/04/07 19pp 18984 300
- 8306240151 Summary of 830404 meeting w/DOE in Germantown, MD re staff comments on 10CFR960 concerning DOE proposed guidelines for recommendation of sites for nuclear waste repositories
PFLUM, C O High Level Waste Licensing Management Branch
83/04/06 BOYLE, R R High Level Waste Licensing Management Branch 2pp 18984 319
- 8306240155 Forwards comments on 10CFR960 re DOE proposed general guidelines for recommendations of sites for nuclear waste repositories, in response to 830207 FR notice
BROWNING, R E Division of Waste Management 83/04/07
MORGAN, R L Energy, Dept of 12pp 18984 321
- 8306240158 Forwards comments re transportation aspects of DOE proposed general guidelines for recommendation of sites for nuclear waste repositories
TROSTEN, L H LeBouff, Lamb, Leiby & MacRae 83/04/07 DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director 12pp 18984 333
- 8306240160 Summary of 830120 meeting w/OMB & DOE re proposed DOE guidelines for siting repositories required by Nuclear Waste Policy Act of 1982
BELL, M J High Level Waste Licensing Management Branch 83/04/07
High Level Waste Licensing Management Branch 2pp 18984 345
- 8306240163 Forwards comments on draft DOE guidelines for recommendation of sites for repositories (10CFR960), in response to Request 2 of 830324 telcon
BROWNING, R E Division of Waste Management 83/04/11
KAMMERER, C C Office of Congressional Affairs 1p 18984 347
- 8306240168 Forwards viewgraphs used in ACRS presentation on DOE siting guidelines & comments sent to DOE, per 830407 request
BELL, M J High Level Waste Licensing Management Branch 83/04/11
BUDNITZ, R Affiliation Unknown 1p 18984 361
- 8306240347 FOIA request for winning technical proposal under NRC-03-83-107
THURMOND, P NUS Corp SE-3006 83/04/18 CARR, J O Office of Administration 1p 18997 180
- 8306240352 Responds to FOIA request for winning technical proposal under NRC-03-83-107 Forwards nonproprietary version of proposal document also available in PDR
FELTON, J M Division of Rules and Records 83/05/06 THURMOND, P NUS Corp 1p 18997 181
- 8306240356 "Technical Proposal for Development of Reg Guide & Regulatory Analyses"
* Analysis & Technology, Inc NRC-03-83-107 RS-NRR-83-107
83/03/07 35pp 18997 182
- 8306280182 Partial response to FOIA request for all documents made available per FOIA Request 83-153 re consultations w/EPA concerning development of stds for remedial actions at inactive U processing sites. Documents available in PDR
FELTON, J M Division of Rules and Records 83/05/11 KAPPEL, B Hamel, Park, McCabe & Saunders 1p 19043 210
- 8306280186 FOIA request for all documents made available per FOIA Request 83-153 re consultations w/EPA concerning development of stds for remedial actions at inactive U processing sites
KAPPEL, B Hamel, Park, McCabe & Saunders 83/04/12 NORMAN, P B Office of Administration 1p 19043 211
- 8306280193 FOIA request for DOE/NRC Forms 741 filed since Jan 1982 re movement of South African origin matl from DOE U enrichment facilities to any US fuel fabricator
KNAPIK, M McGraw-Hill Publications Co 82/12/21 CARR, J Division of Rules and Records 1p 19043 212
- 8306280198 Responds to FOIA request for DOE/NRC Forms 741 filed since Jan 1982 re movement of South African origin matl from DOE U enrichment facilities to any US fuel fabricator Forms withheld (ref FOIA Exemption 4)
FELTON, J M Division of Rules and Records 83/05/12 KNAPIK, M McGraw-Hill Publications Co 1p 19043 213

NONDOCKETED ITEMS

41

8306280202 FOIA request for copies of all permits allowing radioactive mats in sewage or sewage sludge from plants or sanitary landfills since 820101 or any repts from TMI concerning levels of radiation or radionuclide contamination
HUNT, B D Three Mile Island Alert 83/04/07 Office of Administration 1p 19043 214 24X Fiche 50-320, 83/04/07, 8306280202

8306280206 Partial response to FOIA request for copies of permits allowing radioactive mats in sewage or sewage sludge from TMI plant transported to area sewage treatment plants or landfills Forwards App A documents Search continuing
FELTON, J M Division of Rules and Records 83/05/06 HUNT, B D Three Mile Island Alert 2pp 19043 215 24X Fiche 50-320, 83/05/06, 8306280206

--8306280211 Submits evaluation results of contaminated sewage in Gate 7 sewage holding tank Concentrations of radionuclides in sewage in accordance w/10CFR20 303 Cs-137 & tritium concentrations 0.023% mpc & 0.0057% mpc, respectively
LAZARSKI, R F Region 1, Office of Director 83/01/27 BARRETT, L H TMI Program Office 4pp 19043 261 24X Fiche 50-320, 83/05/06, 8306280206

--8306280216 Forwards info re Gate 7 sewage holding tank, located outside west entrance to turbine bldg Info consists of effluent & waste disposal & liquid effluent to summation of all releases
BYRNE, J J Region 1, Office of Director 4410-83-M-0134 83/02/04 BARRETT, L H TMI Program Office 33pp 19043 265 24X Fiche 50-320, 83/05/06, 8306280206

--8306280220 Forwards GPU 830331 memo & related info re contamination in Gate 7 sewage holding tanks Info results of King NY Times article & Gischel affidavit
BARRETT, L H TMI Program Office 83/04/06 WARD, B Region 1, Office of Director 49pp 19043 299 24X Fiche 50-320, 83/05/06, 8306280206

8306280224 Addl response to FOIA request for insp, surveillance & radiological monitoring repts re Westinghouse Cheswick Div from 1963-1970 Addl documents not located
FELTON, J M Division of Rules and Records 83/06/02 JOHNSON, C obsolete code 1p 19043 330

8306280230 FOIA request for insp, surveillance & radiological monitoring repts re Westinghouse Cheswick Div from 1963-1970
JOHNSON, C Behrman, Aramson & Morris 83/05/03 ALLAN, J N Region 1, Office of Director 2pp 19043 331

GEN TEC IS GENERIC TECHNICAL ISSUES

8306010052 NUREG/CR-3224
STATION BLACKOUT ACCIDENT ANALYSES (PART OF NRC TASK ACTION PLAN A-44)
KOLACZKOWSKI, A, PAYNE, A C Sandia Laboratories FIN A-1302
84ND82-2450 83/05/31 Division of Safety Technology 279pp Available at NRC \$8 00 18683 232

8306010065 Forwards "Control of Heavy Loads (C-10), Kewaunee Nuclear Power Plant," draft technical evaluation rept for review & comment Conference call to discuss rept scheduled for wk of 830610
VARSA, S A Operating Reactors Branch 1 83/05/16 GIESLER, C W Wisconsin Public Service Corp 2pp 18695 332 24X Fiche 50-303, 83/05/16, 8306010065

--8305200714 TER-C5506-363 DRFT
"Control of Heavy Loads (C-10), Kewaunee Nuclear Power Plant," draft technical evaluation rept.
VOGBURY, F W, BOMBERGER, C Franklin Institute/Franklin Research Center NRC-03-81-130 TAC 46747 83/04/29 BARGENT, I H NRC - No Detailed Affiliation Given 38pp 18696 001 24X Fiche 50-303, 83/05/16, 8306010065

8306010166 NUREG-0869 FC ERR
USI A-43 RESOLUTION POSITIONS
SPEIS, T P Division of Safety Technology 83/05/12 3pp 18686 322.

8306010236 Clarifies responses to NUREG-0612, "Control of Heavy Loads" Turbine Crane MT-CRA-1 meets guidelines of NUREG
DOUCHEY, G D Washington Public Power Supply System 602-83-337, 83/04/13 SCHWENGER, A Licensing Branch 2 1p 18673 001 24X Fiche 50-397, 83/04/13, 8306010236

8306010316 Advises that performance of load test in excess of 100% of max load unnecessary since crane operator training & safety programs ensure safest possible operations, in response to 801222 ltr re control of heavy loads (NUREG-0612)
WITHERS, B D Portland General Electric Co 83/05/24 EIBENHUT, D O Division of Licensing 3pp 18682 138 24X Fiche 50-344, 83/05/24, 8306010316

8306020015 Requests performance or documentation of completion of load test of reactor vessel head lifting fixture for control of heavy loads, Phase I within 120 days Guidelines for response & complete draft technical evaluation rept encl
CLARK, R A Operating Reactors Branch 3 83/05/24 GARRITY, J H Maine Yankee Atomic Power Co 16pp 18701 146 24X Fiche 50-309, 83/05/24, 8306020015

--8306020037 TER-C5506-365 DRFT
"Control of Heavy Loads (C-10), Maine Yankee Atomic Power Co, Main Yankee Nuclear Power Station," draft technical evaluation rept
VITO, D J, BOMBERGER, C, BARGENT, I H Franklin Institute/Franklin Research Center NRC-03-81-130 TAC-08059, 82/12/30, CLEMENSON, F NRC - No Detailed Affiliation Given 26pp 18701 162, 24X Fiche 50-309, 83/05/24, 8306020015

8306020134 NUREG/CR-2837 801
PNL TECHNICAL REVIEW OF PRESSURIZED THERMAL SHOCK ISSUES, Technical Critique Of The NRC Near-Term Screening Criteria, PEDERSON, L T, APLEY, W J, BIAN, S H Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2510 PNL-4327 83/05/31 Division of Safety Technology 36pp Available at NRC \$4 75 18698 168

8306020188 Forwards Franklin Research Ctr draft technical evaluation rept, "Control of Heavy Loads (C-10), Florida Power Co, Crystal River Unit 3," Guidance document, "Synopsis of Issues Associated w/NUREG-0612," also encl
STOLZ, J F Operating Reactors Branch 4 83/05/19 WILCOX, W G Florida Power Corp 2pp 18701 072 24X Fiche 50-302, 83/05/19, 8306020188

--8306020196 TER-C5506-347 DRFT
"Control of Heavy Loads (C-10), Florida Power Co, Crystal River Unit 3," draft technical evaluation rept.
BOMBERGER, C, VOGBURY, F W Franklin Institute/Franklin Research Center NRC-03-81-130 83/01/28 CLEMENSON, F NRC - No Detailed Affiliation Given 39pp 18701 074 24X Fiche 50-302, 83/05/19, 8306020188

8306020524 Discusses status of 820827 commitment to perform comprehensive stress analyses of reactor vessel closure head & internal lifting rigs to provide scope & schedule of effort Results scheduled for submittal by 830831.
GARRITY, J H Maine Yankee Atomic Power Co MN-83-115 83/05/27 CLARK, R A Operating Reactors Branch 3 2pp 18693 241 24X Fiche 50-309, 83/05/27, 8306020524

8306030020 Forwards "Control of Heavy Loads at Nuclear Power Plants, Washington Nuclear Project 2 (Phase II - Interim)," technical evaluation rept
SCHWENGER, A Licensing Branch 2 83/05/24 FERGOUSON, R L Washington Public Power Supply System 2pp 18733 146 24X Fiche 50-397, 83/05/24, 8306030020

--8306030088 "Control of Heavy Loads at Nuclear Power Plants, Washington Nuclear Project 2 (Phase II - Interim)," draft technical evaluation rept.
DIXON, B W, STICKLEY, T H E&G, Inc FIN A-6457 83/05/24 NRC - No Detailed Affiliation Given 20pp 18733 148 24X Fiche 50-397, 83/05/24, 8306030020

8306030067 Forwards synopsis of issues to resolve conformance w/NUREG-0612 re control of heavy loads (Phase I) & draft technical evaluation rept.
CLARK, R A Operating Reactors Branch 3 83/05/17 STEWART, W L Virginia Electric & Power Co 13pp 18733 211 24X Fiche 50-338, 83/05/17, 8306030067

--8306030070 TER-C5506-372/373 DR
"Control of Heavy Loads (C-10), Virginia Electric Power Co, North Anna Power Station Units 1 & 2," draft technical evaluation rept
BOMBERGER, C R Franklin Institute/Franklin Research Center NRC-03-81-130 TAC 47112 83/02/22 NRC - No Detailed Affiliation Given 25pp 18733 224, 24X Fiche 50-338, 83/05/17, 8306030067

8306030290 Forwards addl guidance on acceptable solutions to open items re control of heavy loads in compliance w/NUREG-0612 & draft "Control of Heavy Loads (C-10), Donald C Cook Nuclear Plant Units 1 & 2," technical evaluation rept.
VARSA, S A Operating Reactors Branch 1 83/05/16 BOLAN, J Indiana & Michigan Electric Co 14pp 18734 086 24X Fiche 50-315, 83/05/16, 8306030290

NONDOCKETED ITEMS

--B306030299 TER-C5506-344/345 DR
Draft "Control of Heavy Loads (C-10), Donald C Cook Nuclear Power Plant Units 1 & 2," technical evaluation rept
VOBBURY, F W Franklin Institute/Franklin Research Center
NRC-03-B1-130 TAC 07981 83/02/24 CLEMENSON, F NRC - No
Detailed Affiliation Given 33pp 18734 100 24X
Fiche 50-315, 83/05/16, B306030299

B306030441 Forwards "Control of Heavy Loads (C-10), Surry Power Station Units 1 & 2," draft technical evaluation rept & summary of addl info required to complete review Response requested within 60 days
VARQA, S A Operating Reactors Branch 1 83/05/16 STEWART, W L
Virginia Electric & Power Co 2pp 18735 287 24X
Fiche 50-280, 83/05/16, B306030441

--B306030446 TER-C5506-395/396 DR
"Control of Heavy Loads (C-10), Surry Power Station Units 1 & 2," draft technical evaluation rept
VOBBURY, F W, SARGENT, I H Franklin Institute/Franklin Research Center
NRC-03-B1-130 TAC 08084 83/01/14 NRC - No Detailed
Affiliation Given 40pp 18735, 289 24X Fiche 50-280, 83/05/16, B306030441

B306030508 Forwards draft "Control of Heavy Loads (C-10), Zion Station Units 1 & 2," per responses to NRC 800731 request for review of provisions for handling & control of heavy loads in conformance w/NUREG-0612 Addl guidance encl.
VARQA, S A Operating Reactors Branch 1 83/05/19 FARRAR, D L
Commonwealth Edison Co 15pp 18735-006 24X Fiche 50-295, 83/05/19, B306030508

--B306030512 TER-C5506-403/404 DR
Draft "Control of Heavy Loads (C-10), Zion Station Units 1 & 2," technical evaluation rept
SARGENT, I H Franklin Institute/Franklin Research Center
NRC-03-B1-130 TAC 08093 82/11/30 CLEMENSON, F NRC - No
Detailed Affiliation Given 30pp. 18735 021 24X
Fiche 50-295, 83/05/19, B306030508

B306060121 Forwards evaluations submitted re NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants " Handling shielded shipping casks over spent fuel pool will be prohibited until measures taken to reduce probability of cask drop
BAYNE, J Power Authority of the State of New York JPN-B3-49
83/06/02 VASSALLO, D B Operating Reactors Branch 2 14pp
18722 275 24X Fiche 50-333, 83/06/02, B306060121.

B306060413 NUREG-0927 FC
EVALUATION OF WATER HAMMER EXPERIENCE IN NUCLEAR POWER PLANTS Technical Findings Relevant To Unresolved Safety Issue A-1
BERKIL, A W Division of Safety Technology 83/05/31 78pp
18748-076

B306060418 NUREG-0993 FC
VALUE-IMPACT ANALYSIS FOR USI A-1, "WATER HAMMER"
BERKIL, A W Division of Safety Technology 83/05/31 29pp.
18747, 293

B306070427 Notification of B30601 meeting w/util, E&G, DRNL & C-E in Bethesda, MD to review control sys on plant design for resolution of Unresolved Safety Issue A-47, "Safety Implications of Control Sys."
SZUMIEWICZ, A J Generic Issues Branch 83/05/26, KNIEL, K, Generic
Issues Branch 3pp 18780, 348 24X Fiche 50-317, 83/05/26, B306070427.

B306070449 Summary of B30322 meeting w/util & consultants in Bethesda, MD re reactor vessel belline weld (WF-70) anomaly (Unresolved Safety Issue A-11) Attendance list encl
HERNAN, R W Licensing Branch 4 83/05/25, Licensing Branch 4, 4pp. 18780, 355 24X Fiche 50-329, 83/05/25, B306070449

B306070460 Requests concurrence w/encl package & comments re resolution of Generic Issue B-10, "Behavior of BWR Mark III Containment"
NOVAK, T M Assistant Director for Operating Reactors 83/05/27
EISENHUT, D G Division of Licensing. 3pp. 18780 312

B306080102 Forwards response to questions asked at mid-yr program review, per B30506 memo.
REHM, T A Office of the Executive Director for Operations, 83/05/31, CHILKIS, J Office of the Secretary of the Commission 6pp. 18787, 331.

B306080137 Forwards "WH Zimmer Nuclear Power Station, Unit 1, Heavy Loads Rept" in response to supplemental SER (NUREG-0528, Suppl 3) & NUREG-0612 re control of heavy loads.
WILLIAMS, J, Cincinnati Gas & Electric Co. 83/06/02 DENTON, H
Office of Nuclear Reactor Regulation, Director. 87pp 18768, 275, 24X Fiche 50-358, 83/06/02, B306080137.

--B306080140 "WH Zimmer Nuclear Power Station, Unit 1, Heavy Loads Rept"
* Cincinnati Gas & Electric Co 83/06/01 108pp 18768 277
24X Fiche 50-358, 83/06/02, B306080137

B306080143 Forwards proposed findings of fact & conclusions of law on Contention 9a re water hammer
CHAVEZ, D Mississippi Alliance for the Environment (SAFE)
CHAVEZ, D DeKalb Area Alliance for Responsible Energy ISSUANCES
QL 83/05/31 Atomic Safety and Licensing Board Panel 1p
18772 290 24X Fiche 50-454, 83/05/31, B306080143

--B306080145 Proposed findings of fact & conclusions of law on Contention 9a re water hammer
* Mississippi Alliance for the Environment (SAFE) * DeKalb Area
Alliance for Responsible Energy 83/05/31 19pp 18772 291 24X
Fiche 50-454, 83/05/31, B306080143

B306080207 Summary of CROR Meeting 38 on B30518 re presentation of proposed rule on pressurized thermal shock of reactor pressure vessels Committee supports proposed rule
STELLER, V Regional Operations & Generic Requirements 83/05/31
DIRCKS, W J Office of the Executive Director for Operations 3pp
18771 267

B306080213 Informs that station blackout procedure approved & available for NRC review, per NUREG-0528, Suppl 3, Subsection B 1 2
WILLIAMS, J Cincinnati Gas & Electric Co 83/06/01 DENTON, H
Office of Nuclear Reactor Regulation, Director 1p 18771 185 24X
Fiche 50-358, 83/06/01, B306080213

B306080218 Forwards testimony of IE Const Appraisal Team Insp Repts 50-445/B3-18 & 50-446/B3-12
TREBY, S A Hearing Branch 1 83/06/06 BLOCH, P B Atomic Safety
and Licensing Board Panel 2pp 18771 004 24X
Fiche 50-445, 83/06/06, B306080218

B306080251 Forwards "Control of Heavy Loads (C-10) St Lucie Unit 1," draft technical rept, per util response to Section 2 1 of 801222 generic ltr re NUREG-0612 Completion of review by B30617 requested
CLARK, R A Operating Reactors Branch 2 83/05/24 UHRIG, H L
Florida Power & Light Co 2pp 18787 139 24X
Fiche 50-335, 83/05/24, B306080251

--B306080252 TER-C5506-394 DRFT
"Control of Heavy Loads (C-10) St Lucie Unit 1," draft technical evaluation rept
BOMBERGER, C, AHMED, N Franklin Institute/Franklin Research Center
NRC-03-B1-130 TAC 08083 83/04/29 CLEMENSON, F NRC -
No Detailed Affiliation Given 36pp 18787 141 24X
Fiche 50-335, 83/05/24, B306080251

B306090386 Forwards request for addl info re response to encl "Control of Heavy Loads at Nuclear Power Plants, Phase 1, Nebraska Public Power District, Cooper Nuclear Station " Draft technical evaluation rept encl Info requested in 60 days.
VASSALLO, D B Operating Reactors Branch 2 83/05/26 PILANT, J H
Nebraska Public Power District 13pp 18814 042 24X
Fiche 50-298, 83/05/26, B306090386

--B306090388 TER-C5506-346 DRFT
"Control of Heavy Loads (C-10), Nebraska Public Power District, Cooper Nuclear Station," draft technical evaluation rept
VOBBURY, F W, VITO, D J, SARGENT, I H Franklin Institute/Franklin Research Center
NRC-03-B1-130 TAC 07982 82/12/30, CLEMENSON, F NRC - No Detailed Affiliation Given 29pp
18814 055 24X Fiche 50-298, 83/05/26, B306090386

B306090393 Forwards request for addl info re three open items concerning controls for handling heavy loads Franklin Research Ctr draft technical evaluation encl Response requested within 60 days of receipt of ltr
STOLZ, J F Operating Reactors Branch 4 83/05/31 RODRIGUEZ, R J
Sacramento Municipal Utility District 13pp. 18815 037. 24X
Fiche 50-312, 83/05/31, B306090393

--B306090397 TER-C5507-388 DRFT
"Control of Heavy Loads, Sacramento Municipal Util District, Rancho Seco Nuclear Generating Station," draft technical evaluation rept
VOBBURY, F W, VITO, D J, SARGENT, I H Franklin Institute/Franklin Research Center
NRC-03-B1-130 TAC 08079 83/01/13, CLEMENSON, F NRC - No Detailed Affiliation Given 28pp.
18815 050 24X Fiche 50-312, 83/05/31, B306090393

B306090426 Forwards safety evaluation & technical evaluation rept, "Control of Heavy Loads " Guidelines of NUREG-0612 satisfied
CLARK, R A Operating Reactors Branch 3 83/05/27 LUNDVALL, A E
Baltimore Gas & Electric Co 2pp 18809 107 24X
Fiche 50-317, 83/05/27, B306090426

NONDOCKETED ITEMS

417

--8306090492 Safety evaluation accepting util response to "Control of Heavy Loads Phase I" Item resolved
a NRC - No Detailed Affiliation Given 83/05/27 2pp
18809 109 24X Fiche 50-317, 83/05/27, 8306090426

--8306030310 TER-C5506-342
"Control of Heavy Loads (C-10) Calvert Cliffs Nuclear Power Plants Units 1 & 2," technical evaluation rept
BOMBERGER, C Franklin Institute/Franklin Research Center
NRC-03-81-130 TAC 07978 83/05/31 CLEMENSON, F NRC - No
Detailed Affiliation Given 28pp 18809 111 24X
Fiche 50-317, 83/05/27, 8306090426

8306130176 Forwards final response to NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants"
SCHMIDT, H C Texas Utilities Services, Inc TTX-3659 83/06/08
YOUNGBLOOD, D J Licensing Branch 1 153pp 18828 031 24X
Fiche 50-445, 83/06/08, 8306130176

8306130356 Forwards safety evaluation supporting util decision not to reroute reactor water cleanup sys return line per
NUREG-0619 Decision based on value-impact analysis & sleeve leakage measurements
SHEA, J J Operating Reactors Branch 5 L805-83-06-024 83/06/09
COUNSELL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 18822 153 24X Fiche 50-245, 83/06/09, 8306130356

--8306130358 Safety evaluation supporting util decision not to reroute reactor water cleanup sys return line per NUREG-0619
Decision based on value-impact analysis & sleeve leakage measurements
a Office of Nuclear Reactor Regulation, Director TAC 08412
83/06/09 2pp 18822 155 24X Fiche 50-245, 83/06/09, 8306130356

8306130495 Forwards synopsis of resolutions to open items re control of heavy loads at nuclear power plants, per NUREG-0612
guidelines Draft final technical evaluation rept & request for addl info encl
VASSALLO, D D Operating Reactors Branch 2 83/05/26 SINGLAIR, J B
Vermont Yankee Nuclear Power Corp 13pp 18830 107 24X
Fiche 50-271, 83/05/26, 8306130495

8306140198 Notification of 830601-02 meetings w/Sandia, Alden Research Lab, Burns & Roe, Creare, AIF, B&W, Queens Corning & EPRI in Bethesda, MD to discuss proposed resolution of Unresolved Safety Issue A-43, "Containment Emergency Sump Performance"
BERKIZ, A W Generic Issues Branch 83/05/31 KNIEL, K Generic Issues Branch 3pp 18844 209

8306140305 Forwards draft task action plan, Rev 2 under Task A-45 re shutdown DHR requirements & A Marchese paper, presented before Swiss Federal Inst for Reactor Research in Switzerland in late Apr 1983 W/o encls
MORAN, D H Standardization & Special Projects Branch 83/05/25
NEILLS, G H Public Service Electric & Gas Co of New Jersey 1p.
18844 348

8306140500 Forwards response to 801222 ltr re NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants" Info addresses overhead handling sys for fuel storage pool
CRDUSE, R P Toledo Edison Co 952 83/06/10 STOLZ, J F
Operating Reactors Branch 4 142pp 18843 096 24X
Fiche 50-346, 83/06/10, 8306140500

8306140715 Response to first set of interrogatories on pressurized thermal shock, Contention I-62 Certificate of Svc encl
HODDODON, A F Hearing Branch 2 83/06/10 Lewis, M 27pp
18841 276 24X Fiche 50-352, 83/06/10, 8306140715

8306140792 Forwards draft task action plan, Rev 2 for Task A-45 re shutdown DHR requirements & A Marchese paper on same subj, presented before Swiss Federal Inst for Reactor Research in late Apr 1983 W/o encls
MORAN, D H Standardization & Special Projects Branch 83/05/25.
BERGA, J O Electric Power Research Institute 1p 18834 078

8306140797 Forwards draft task action plan, Rev 2 for Task A-45 re shutdown DHR requirements & A Marchese paper on same subj, presented before Swiss Federal Inst for Reactor Research in late Apr 1983 W/o encls
MORAN, D H Standardization & Special Projects Branch 83/05/25
MITTLER, R Public Service Electric & Gas Co of New Jersey 1p.
18845 324

8306140814 Forwards draft task action plan, Rev 2 for Task A-45 re shutdown DHR requirements & A Marchese paper on same subj, presented before Swiss Federal Inst for Reactor Research in late Apr 1983 W/o encls.
MORAN, D H Standardization & Special Projects Branch 83/05/25
NICKELL, R E Electric Power Research Institute 1p 18845 323

8306150019 Forwards draft task action plan, Rev 2 under Task A-45 re shutdown DHR requirements & A Marchese paper on same subj, presented before Swiss Federal Inst for Reactor Research in late Apr 1983 W/o encls
MORAN, D H Standardization & Special Projects Branch 83/05/25
MATTIMOE, J Sacramento Municipal Utility District 1p.
18872 047

8306150022 Forwards draft task action plan, Rev 2 for Task A-45 re shutdown DHR requirements & A Marchese paper on same subj, presented before Swiss Federal Inst for Reactor Research in late Apr 1983 W/o encls
MORAN, D H Standardization & Special Projects Branch 83/05/25.
PATTERSON, D R Tennessee Valley Authority 1p 18872 046

8306150112 Forwards draft task action plan, Rev 2 for Task A-45 re shutdown DHR requirements & A Marchese paper on same subj, presented before Swiss Federal Inst for Reactor Research in late Apr 1983 W/o encls.
MORAN, D H Standardization & Special Projects Branch 83/05/25
BURSTEIN, S Wisconsin Electric Power Co 1p 18872 120

8306150260 Forwards "Control of Heavy Loads (C-10), TVA, Browns Ferry Nuclear Power Station, Units 1, 2 & 3," draft technical evaluation rept Conference call requested within 4 to 5 wks to discuss review results
VASSALLO, D D Operating Reactors Branch 2 83/05/26 FARRIS, H O
Tennessee Valley Authority 2pp 18869-322 24X
Fiche 50-259, 83/05/26, 8306150260

--8306150266 TER-C5506-337/338/33
"Control of Heavy Loads (C-10), TVA, Browns Ferry Nuclear Power Station, Units 1, 2 & 3," draft technical evaluation rept
BOMBERGER, C Franklin Institute/Franklin Research Center
NRC-03-81-130 TAC 07975 83/04/03 CLEMENSON, F. NRC - No
Detailed Affiliation Given 23pp 18869-324 24X
Fiche 50-259, 83/05/26, 8306150260.

--8306150272 "Synopsis of Issues Associated w/NUREG-0612"
a Operating Reactors Branch 2 83/05/26 11pp 18869 349. 24X
Fiche 50-259, 83/05/26, 8306150260

8306160034 Forwards draft task action plan, Rev 2 for Task A-45 re shutdown DHR requirements & A Marchese paper same subj, presented before Swiss Federal Inst for Reactor Research in late Apr 1983 W/o encls.
MORAN, D H Standardization & Special Projects Branch 83/05/25.
TAYLOR, J J Electric Power Research Institute 1p 18892-335.

8306160277 Forwards synopsis of issues & Franklin Research Ctr draft technical evaluation rept re NUREG-0612, "Control of Heavy Loads, Phase I," W/o encls
ADENBAM, E G. Licensing Branch 4. 83/06/10 TUCKER, H. B. Duke Power Co 2pp 18872 170 24X Fiche: 50-369, 83/06/10, 8306160277.

8306160310 Forwards final response to NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants-Resolution of TAP A-36"
Response includes analyses for loads handled over reactor vessel
KEPNER, J B Philadelphia Electric Co 83/06/13. EISENHUT, D O
Division of Licensing. 126pp 18860, 243 24X Fiche: 50-352, 83/06/13, 8306160310

8306160603 Forwards util answer to HI Lewis first set of interrogatories on pressurized thermal shock contention.
WETTERHAHN, M J. Conner & Wetterhahn WETTERHAHN, M J Philadelphia Electric Co. 83/06/13 LEWIS, M I Lewis, M. 1p. 18866:144. 24X
Fiche 50-352, 83/06/13, 8306160603

--8306160609 Answers to first set of interrogatories on pressurized thermal shock contention Certificate of Svc encl.
BOYER, V B Philadelphia Electric Co. 83/06/09. LEWIS, M I Lewis, M. 16pp 18866 143 24X Fiche 50-352, 83/06/13, 8306160603.

8306160630 Forwards draft "Control of Heavy Loads at Nuclear Power Plants, St Lucie Plant, Unit 2 (Phase I)," & synopsis of NRC interpretation of guidelines of NUREG-0612 for use in resolving open items.
KNIIGHTON, G W. Licensing Branch 3 TAC 47015. 83/05/31. UHRIG, R. E. Florida Power & Light Co. 14pp. 18884 283 24X
Fiche: 50-389, 83/05/31, 8306160630

--8306160641 EQQ-HS-6263 DRFT
Draft "Control of Heavy Loads at Nuclear Power Plants, St Lucie Plant, Unit 2 (Phase I)," technical evaluation rept.
SHABER, C. R. E&G, Inc. FIN A-6457 TAC 47015. 83/04/30. NRC
- No Detailed Affiliation Given. 16pp. 18884:297 24X
Fiche 50-369, 83/05/31, 8306160630

NONDOCKETED ITEMS

8306170053 Concurs w/ findings contained in technical evaluation rept.
 "Control of Heavy Loads " Guidelines in NUREG-0612, Section
 5.1.1 satisfied, per util 810402, 0713, 0831 & 1209, 820203 &
 1108 & 830408 submittals.
 CLARK, R A Operating Reactors Branch 3 83/06/06 MUSOLF, D M
 Northern States Power Co 2pp 18906 314 24X
 Fiche 50-282, 83/06/06, 8306170053

--8306170058 Safety evaluation supporting util Phase I actions re control
 of heavy loads NUREG-0612, Section 5.1.1 guidelines
 satisfied
 * Office of Nuclear Reactor Regulation, Director 83/06/06 1p
 18906 316 24X Fiche 50-282, 83/06/06, 8306170053

--8305230021 TER-C5506-384/385
 "Control of Heavy Loads (C-10), Prairie Island Nuclear
 Generating Plant, Units 1 & 2," technical evaluation rept
 VOSBURY, F W. Franklin Institute/Franklin Research Center
 NRC-03-81-130 TAC 08073 83/05/17 NRC - No Detailed
 Affiliation Given 31pp 66794 188 24X Fiche 50-282, 83/06/06,
 8306170053

8306170302 Forwards App J to, "Evaluation of Pressurized Thermal Shock
 Effects Due to Small Break LOCAs W/Loss of Feedwater for
 Palo Verde 1 & 2, 2 & 3 Reactor Vessels " Rept applies to
 only Unit 1
 VAN BRUNT, E E Arizona Public Service Co ANPP-24608-WF0/
 83/06/14 KNIGHTON, G. Licensing Branch 3, 3pp 18978-197 24X
 Fiche 50-528, 83/06/14, 8306170302

8306170453 Forwards draft task action plan, Rev 2, for Task A-43.
 "Shutdown DHR Requirements" & A Marchess paper presented
 before Swiss Federal Inst for Reactor Research, during Apr
 1983, w/o encls
 MORAN, D H Standardization & Special Projects Branch 83/05/31
 STAHLKOPF, K Electric Power Research Institute 1p 18906 360

8306200119 Minutes of ACRS ECCS Subcommittee 830512 meeting in
 Washington, DC re proposed GE SAFER/OESTR ECCS licensing
 codes & status of other NRR licensing actions Schedules for
 completing Unresolved Safety Issues A-43 & A-1 encl
 * ACRS - Advisory Committee on Reactor Safeguards 83/05/12
 ACRS - Advisory Committee on Reactor Safeguards 29pp 18908 239

8306210007 Transcript of ACRS Metal Components Subcommittee on
 Pressurized Thermal Shock Research Program 830615 meeting in
 Oak Ridge, TN, Pp 1-199 Supporting documentation encl
 * ACRS - Advisory Committee on Reactor Safeguards 83/06/15
 300pp 18910 001

8306220043 Answer to first set of interrogatories re pressurized
 thermal shock in BWRs
 LEWIS, M 83/06/15, Philadelphia Electric Co 2pp
 18926 255 24X Fiche 50-352, 83/06/15, 8306220043

8306220074 Forwards safety evaluation & technical evaluation rept re
 util response to 801222 generic ltr, "Control of Heavy
 Loads " Guidelines in NUREG-0612 satisfied & Phase
 acceptable
 CRUTCHFIELD, D Operating Reactors Branch 3 LE05-83-06-045
 83/06/21 FIEDLER, P.B. General Public Utilities - GPU Service Corp
 2pp 18926 060. 24X Fiche 50-219, 83/06/21, 8306220074

--8306220083 Safety evaluation re util response to Generic Technical
 Issue A-36, "Control of Heavy Loads " NUREG-0612 guidelines
 satisfied, Phase 1 acceptable
 * Office of Nuclear Reactor Regulation, Director 83/06/21, 2pp
 18926 062 24X Fiche 50-219, 83/06/21, 8306220074

--8306140424 TER-C5506-377
 "Control of Heavy Loads (C-10), JCP&L Oyster Creek Nuclear
 Power Plant," technical evaluation rept
 BOMBERGER, C. Franklin Institute/Franklin Research Center
 NRC-03-81-130 TAC 47128 83/06/10 BINGH, A NRC - No Detailed
 Affiliation Given. 32pp 18926-064 24X Fiche: 50-219, 83/06/21,
 8306220074

8306230348 Forwards response to NRC 830428 request for addl info re
 Mark I containment long-term program NUTECH rept "Mark I
 Containment Ring Girder Modelling & Stress Evaluation
 Utilizing Eccentric Beams" encl.
 MCOWHUGH, R W. Iowa Electric Light & Power Co NO-83-2073
 83/06/20 DENTON, H Office of Nuclear Reactor Regulation, Director.
 6pp, 18943 011. 24X Fiche: 50-331, 83/06/20, 8306230348.

--8306230351 MKI-03-008
 "Mark I Containment Ring Girder Modelling & Stress
 Evaluation Utilizing Eccentric Beams,"
 CHANO, D K, STURKEY, J. J., BALLARD, T A NUTECH Engineers, Inc
 NO-83-2093, 80/04/30 41pp, 18943 017. 24X
 Fiche: 50-331, 83/06/20, 8306230348.

8306230452 Forwards revised response to NUREG-0612, "Control of Heavy
 Loads " Rev addresses NRC comments contained in draft
 technical evaluation rept 810 821223 & supplemented by NRC
 821228 ltr
 DEVINCENTIS, J Yankee Atomic Electric Co SBN-521 83/06/20
 KNIGHTON, G H Licensing Branch 3 2pp 18941 001 24X
 Fiche 50-443, 83/06/20, 8306230452

--8306230458 9763 006-S-N-5
 "Response to NRC Generic Request for Addl Info Re
 NUREG-0612, Control of Heavy Loads "
 * United Engineers & Constructors, Inc (subs of Raytheon Co)
 83/05/31 147pp 18941 004 24X Fiche 50-443, 83/06/20,
 8306230452

8306240290 Response to ASLB consultant P Amico rept re addl testimony
 on Commission Question 1 No addl testimony necessary for
 complete record
 MOORE, J, MCOURRAN, H J Hearing Branch 1 ISSUANCES SP 83/06/20
 15pp 18979 241 24X Fiche 50-247, 83/06/20, 8306240290

--8306240305 Affidavit of HW Woods re ASLB consultant PJ Amico 830601
 rept Testimony on conditional probability of core melt &
 release due to pressurized thermal shock event unavailable
 W/prof qualifications & Certificate of Svc
 WOODS, H W NRC - No Detailed Affiliation Given ISSUANCES SP
 83/06/16 7pp 18979 272 24X Fiche 50-247, 83/06/20, 8306240290

8306270016 Reply to Dekalb Area Alliance for Responsible Energy/
 Mississippi Alliance for Environ proposed findings of fact &
 conclusions of law re water hammer Certificate of Svc encl
 GALLO, J, COPELAND, V G Commonwealth Edison Co GALLO, J Ishaq,
 Lincoln & Beale ISSUANCES DL 83/06/21 11pp 19012 246 24X
 Fiche 50-454, 83/06/21, 8306270016

--8306270020 Motion for leave to file out-of-time reply to proposed
 findings of fact & conclusions of law on waterhammer Addl
 time needed due to demands imposed by preparation of other
 documents
 COPELAND, V G Commonwealth Edison Co COPELAND, V G Ishaq,
 Lincoln & Beale ISSUANCES DL 83/06/21 Atomic Safety and
 Licensing Board Panel 2pp 19012 257 24X Fiche 50-454,
 83/06/21, 8306270016

8306270225 Forwards results of plant-unique calculations which form
 bases for mod program in response to Generic Ltr 83-08,
 "Mod of Mark I Containment Vacuum Breakers "
 ZIMMERMAN, S R Carolina Power & Light Co GL-83-08 83/06/23
 VASSALLO, D B Operating Reactors Branch 2 85pp 18988 293 24X
 Fiche 50-324, 83/06/23, 8306270225

--8306270230 82-31 R00
 Rev 0 to "Mark I Vacuum Breaker Improved Valve Dynamic
 Model - Model Development & Validation "
 SULLIVAN, J M Continuum Dynamics, Inc 82/08/31 40pp
 18989 043 24X Fiche 50-324, 83/06/23, 8306270225

8306270322 Provides addl details re control of heavy loads during const
 when new fuel assemblies being stored in spent fuel pit Due
 to failure of reactor coolant pump at Byron 1, fuel handling
 bldg crane will be installed
 TRAMM, T R Commonwealth Edison Co 6794N 83/06/17 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 1p 18994 073 24X
 Fiche 50-000, 83/06/17, 8306270322

8306280003 Informs of progress made since 820719 meeting re Unresolved
 Safety Issue A-47, "Safety Implications of Control Sys "
 Task Action Plan for A-47 completed Sept 1982 & EQ&O
 contracted for plant design review List of info needed encl
 EISENHUT, D O Division of Licensing 83/06/20 UTLEY, E E
 Carolina Power & Light Co 34pp 19044 043 24X
 Fiche 50-261, 83/06/20, 8306280003

8306280089 NUREG/CR-2789
 PRESSURE VESSEL THERMAL SHOCK AT U S PRESSURIZED-WATER
 REACTORS EVENTS AND PRECURSORS 1963-1981
 PHUNG, D L Oak Ridge National Laboratory FIN D-0435
 ORNL/NBIC-210 83/05/31 Division of Risk Analysis 251pp
 19045 185

8306280138 Forwards "Control of Heavy Loads, Philadelphia Electric Co.
 Peach Bottom Atomic Power Station, Units 2 & 3," draft
 technical evaluation rept
 STOLZ, J F Operating Reactors Branch 4 83/06/14 BAUER, E O
 Philadelphia Electric Co 2pp 19043 339 24X
 Fiche 50-277, 83/06/14, 8306280138

--8306060329 TER-C5506-379/380
 "Control of Heavy Loads, Peach Bottom Atomic Power Station,
 Units 2 & 3," draft technical evaluation rept
 BOMBERGER, C R Franklin Institute/Franklin Research Center
 NRC-03-81-130 TAC 08070 83/05/17 NRC - No Detailed
 Affiliation Given 45pp 19043 361 24X Fiche 50-277, 83/06/14,
 8306280138

NONDOCKETED ITEMS

411

8306280502 Forwards supplemental response to E&G, Phase I, Apr 1983 rept re NUREG-0612, "Control of Heavy Loads," reflecting areas of concern addressed during 830614 telcon
SWARTZ, E. D. Commonwealth Edison Co. 83/06/22 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 26pp 19019 236 24X
Fiche 50-373, 83/06/22, 8306280502

8306300027 Forwards safety evaluation of util responses to NRC 781129 ltr re Generic Item B-24, "Containment Purging/Venting During Normal Operations." Radiological consequences of LOCA during purging acceptable Item closed
CRUTCHFIELD, D. Operating Reactors Branch 3 83/06/28 VANDEHALL, D. J. Consumers Power Co 5pp 19120 238 24X
Fiche 50-155, 83/06/28, 8306300027

--8306300034 Safety evaluation of util responses to NRC 781129 ltr re Generic Item B-24, "Containment Purging/Venting During Normal Operations." Issues of purge & vent valve operability resolved except for two open items
* Office of Nuclear Reactor Regulation, Director 83/06/28 9pp 19120 243 24X Fiche 50-159, 83/06/28, 8306300027

FILE INSPECTION AND ENFORCEMENT

8304110279 PNO-I-83-025A on 830404, Region I notified that 330 mCi Xe-133 package reported missing on 830401 & recovered 830402 by Delta Airlines in Miami, FL. Package returned to Fort Lauderdale by contract carrier
DEWNIEN, N. JOYNER, J. Region I, Office of Director 83/04/05 1p 17912 260

8304110289 PNO-I-83-028 on 830327, radioactive shipment of 15 mCi Tl-201 reported lost when shipment did not arrive on direct-flight to San Juan, PR. State of NY & Region II notified
DEWNIEN, N. JOYNER, J. Region I, Office of Director 83/04/05 1p 17915 114

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device." Svc list encl
TAYLOR, J. M. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 115pp 18732 089 24X Fiche 50-000, 83/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co. of New York, Inc 116pp 18996, 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483

8306010066 EN-83-037 on 830601, notice of violation & proposed imposition of civil penalty in amount of \$40,000 to be issued Action based on failure to control access into protected area & to properly handle intrusion alarms
ROSAND, R. AXELRAD, J. Director's Office, Office of Inspection and Enforcement 83/05/26 1p 18674 088 24X Fiche 50-219, 83/05/26, 8306010066

8306010183 EN-83-036 notice of violation & proposed imposition of civil penalty in amount of \$1,000 to be issued on 830602 for failure to secure licensed mail from unauthorized removal during storage in unrestricted area
FLACK, E. AXELRAD, J. Director's Office, Office of Inspection and Enforcement 83/05/26 1p 18673 002

8306010262 PNO-IV-83-019A on 830517, licensee committed to perform insp of recirculation sys piping welds, including RHR sys inlet & outlet T connections. Four welds in need of repair, due to intergranular stress corrosion cracking
DUBOIS, D. WESTERMAN, T. F. Region 4, Office of Director 83/05/27, 1p 18672 288 24X Fiche 50-298, 83/05/27, 8306010262

8306010310 EN-83-038 notice of violation & proposed imposition of civil penalties in amount of \$180,000 to be issued on 830602 Action based on three Severity Level III violations re failure to maintain primary containment integrity
BARBER, O. AXELRAD, J. Director's Office, Office of Inspection and Enforcement 83/05/27 1p 18672 317 24X Fiche 50-269, 83/05/27, 8306010310

8306020179 EN-83-039 notice of violation & proposed imposition of civil penalty in amount of \$40,000 will be issued in May 1983 Proposed action based on licensee failure to ensure restoration of electrical cable tray sys
BARBER, O. AXELRAD, J. Director's Office, Office of Inspection and Enforcement 83/05/31 1p 18691 092 24X Fiche 50-321, 83/05/31, 8306020179

8306070043 PNO-II-83-044: util announced scheduling of enforcement conference w/NRC for 830601 to discuss offloading of 130 fuel bundles into high density fuel rack not verified for boral content
BUTCHER, R. C. CANTRELL, F. S. Region 2, Office of Director 83/06/02 2pp 18739 361 24X Fiche 50-259, 83/06/02, 8306070043

8306070100 PNO-I-83-053, on 830601, licensee reported 225 uCi Ba-133 source lost. Thorough search of facility conducted w/negative results. Source & storage "Pig" missing since Nov 1982. Search efforts continuing.
FRIEDMAN, L. F. GLENN, J. Region 1, Office of Director 83/06/02 1p 18739 310

8306070191 PNO-II-83-043 on 830602, initial criticality achieved w/actual parameters in close agreement w/predicted conditions. Low power testing began immediately & scheduled to be completed within 5 days
JULIAN, C. A. DANCE, H. C. Region 2, Office of Director 83/06/02, 1p 18736 298 24X Fiche 50-389, 83/06/02, 8306070191

8306070234 PNO-V-83-023 on 830527, executive board of util passed resolution delaying completion of Project 3 for 3 yrs if addl financing not obtained within 30 days. Present employment at project is approx 3,000
STERNBERG, D. M. HAIST, D. P. Region 5, Office of Director 83/05/27 1p 18740, 335 24X Fiche 50-508, 83/05/27, 8306070234

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 243pp 18921, 001 24X Fiche 50-000, 83/06/13, 8306090010

8306090174 PNO-V-83-020 on 830504, 100 uCi Cs-137 check source found missing from gas decay tank discharge monitor RE-22. Licensee believes source stolen. On 830415, 9 uCi Cs-137 source found missing. All sources removed from monitors
OARCIA, E. WENSLAWSKI, F. Region 5, Office of Director 10CFR 20.402B, 83/05/04 1p 18792 270 24X Fiche 50-275, 83/05/04, 8306090174

8306100176 PNO-II-83-045 on 830608, Cardox carbon dioxide fire protection sys in diesel room inadvertently activated. Precautionary evacuation conducted. No serious injuries reported
IGNATONIS, A. BROWNLEE, V. Region 2, Office of Director 83/06/08, 2pp 18903 262 24X Fiche 50-413, 83/06/08, 8306100176

NONDOCKETED ITEMS

- 8306130263 PNO-III-83-041 on 830608, personnel from NRC Ofc of State Programs informed Region III that well-logger in Council Bluffs, IA possessed 2 250 mCi sealed sources of Am-241/Ba w/o license Meeting w/individual scheduled for 830609
BRENIAMSKI, D., MILLER, J. Region 3, Office of Director 83/06/09
1p 18824 190
- 8306130327 PNO-III-83-040 on 830605, licensee noticed increase in chloride concentration in reactor cooling water from leak or leaks in main condenser tubes Condenser tubes repaired or plugged. Chlorine level reduced.
CLARDY, L., JORDAN, M., SHAFER, W. Region 3, Office of Director 83/06/07 1p 18822 355 24X Fiche 50-331, 83/06/07, 8306130327
- 8306140022 PNO-I-83-056 on 830606, chlorine gas released into atmosphere for approx 15 minutes Caused by leak in 3/4-inch plastic pipe on outlet of chlorination evaporator All fuel removed from vessel & vessel drained
CONNOR, L., CONNER Region 1, Office of Director 83/06/07 1p 18838 234 24X Fiche 50-219, 83/06/07, 8306140022
- 8306140080 PNO-I-83-057 on 830607, while preparing weld on 3-inch control rod drive (CRD) return header for ultrasonic exam, through wall crack found in weld 4 ft from reactor pressure vessel CRD return nozzle. Header cut out
KISTER, H., KEIMIG, R. Region 1, Office of Director 83/06/08 1p 18838 346 24X Fiche 50-333, 83/06/08, 8306140080
- 8306140194 PNO-I-83-054 on 830604, ECCS actuation signal caused HPCI & RCIC sys to actuate, but sys failed due to lack of steam (reactor temp at 185 F). Open RCIC & HPCI lines created depressurization
HOLDEN, ALLO, KEIMIG Region 1, Office of Director 83/06/06 2pp 18839:029. 24X Fiche 50-271, 83/06/06, 8306140194
- 8306140269 PNO-I-83-055 on 830604, Region I received rept that five children in Philadelphia area had played w/vials labeled radioactive matl found in vacant lot Assistance requested in determining whether children were contaminated
KINNEHAN, J. Region 1, Office of Director 83/06/06 1p 18832 221
- 8306140416 EN-83-042 on 830610, order to show cause & order temporarily suspending license issued to American Testing Labs, based on noncompliance w/NRC requirements & willful false statements re use of licensed matl
FLACK, E., AXELRAD, J. Director's Office, Office of Inspection and Enforcement 83/06/10 1p 18838 052
- 8306140476 PNO-I-83-058 on 830608, Yankee Atomic Electric Corp notified licensee of two support problems w/ECCS suction piping attached to torus & svc water piping for cooling water to uninterruptible power supplies
HOLDEN, KISTER Region 1, Office of Director 83/06/09 1p 18834 335 24X Fiche 50-271, 83/06/09, 8306140476
- 8306140690 PNO-I-83-059 on 830608, several trips experienced during startup Caused by feedwater flow inconsistency w/steam generator level demand Secondary boron soak performed.
KENNY, T., COLLINS, B. Region 1, Office of Director 83/06/09 1p 18841:343. 24X Fiche 50-286, 83/06/09, 8306140690
- 8306140696 EN-83-041 on 830613, notice of violation & proposed imposition of civil penalty in amount of \$40,000 will be issued Action based on util failure to control access to vital area Licensee may respond within 30 days.
ROBANO, R., AXELRAD, J. Director's Office, Office of Inspection and Enforcement 83/06/08 1p 18841:343 24X Fiche 50-416, 83/06/08, 8306140696
- 8306160169 PNO-III-83-043 on 830610, while removing filter from reactor water cleanup sample panel, radiation protection technician received eye contamination from dry matl adhering to filter. Eye flushing reduced contamination to 30,000 dpm.
MUETTER, L., MILLER, J. Region 3, Office of Director 83/06/10 1p 18861:272 24X Fiche 50-373, 83/06/10, 8306160169
- 8306160264 PNO-III-83-042 on 830608, unit shut down to investigate source of RCB leakage. Source of leakage determined to be from four steam generator manways Repairs expected to take 3 to 5 days.
JACKIN, I., SHAFER, W. Region 3, Office of Director 83/06/10 1p 18861:266 24X Fiche 50-306, 83/06/10, 8306160264
- 8306160317 PNO-IV-83-020A on 830609, reactor tripped Cause undetermined. Trip breaker AK2A failed to close due to personnel failure to follow procedure. Closing procedure revised & operations personnel trained.
HUNNICUTT, D. M., CALLAN, L. J. Region 4, Office of Director 83/06/10 1p 18866:143. 24X Fiche 50-313, 83/06/10, 8306160317
- 8306160644 PNO-IV-83-020 on 830609, unit tripped from 99% power from unknown cause Reactor will remain in cold shutdown until cause determined On 830610, two ac-supplied reactor trip breakers failed to close Cause under investigation
HUNNICUTT, D. M., CALLAN, L. J. Region 4, Office of Director 83/06/10 1p 18866 100 24X Fiche 50-313, 83/06/10, 8306160644
- 8306170294 PNO-II-83-047 on 830613, standby gas treatment sys train B declared inoperable due to problems w/filter heaters Cause not stated Event involved no equipment damage, no personnel error or injury & no radioactive releases
BUTCHER, R. C., VERRELLI, D. M. Region 2, Office of Director 83/06/15 2pp 18879 048 24X Fiche 50-260, 83/06/15, 8306170294
- 8306170332 PNO-I-83-061 on 830615, while conducting mod to reactor water level sensing lines, false low reactor water & low-low reactor water level signals generated, initiating ECCS & starting emergency diesel generators
ALLO, KISTER Region 1, Office of Director 83/06/15 1p 18880 362 24X Fiche 50-271, 83/06/15, 8306170332
- 8306170343 PNO-I-83-060 on 830614, reactor tripped from 100% power due to high radiation signal sensed in main steam lines Caused by air pocket in steam lines Safety relief valve cycled & RCIC manually restarted
RHODAS, G., GREENMAN, E. Region 1, Office of Director 83/06/14 1p 18880 083 24X Fiche 50-387, 83/06/14, 8306170343
- 8306170345 PNO-II-83-046 on 830613, fire identified in high-enriched U incinerator ventilation duct Cause not determined No indications of personnel exposure or contamination noted Downwind radiation monitoring devices being analyzed
WRAY, J. R., BARR, K. Region 2, Office of Director 83/06/14 1p 18880 293
- 8306200149 EN-83-043 on 830621, notice of violation & proposed imposition of civil penalties in amount of \$150,000 will be issued re Security Level III violations concerning shutting down reactor by inserting control rods in reverse order
BARBER, Q., AXELRAD, J. Director's Office, Office of Inspection and Enforcement 83/06/16 1p 18903 120 24X Fiche 50-254, 83/06/16, 8306200149
- 8306200203 PNO-II-83-048 on 830615, facility automatically shut down due to turbine trip caused by loss of power to electro-hydraulic control sys Facility to be down until 830620 for replacement of safety relief valves
ROGGE, J., DANCE, H. C. Region 2, Office of Director 83/06/16 2pp 18903 206 24X Fiche 50-321, 83/06/16, 8306200203
- 8306210131 EN-83-013A on 830318, notice of violation & proposed civil penalty in amount of \$2,000 to be issued to licensee Actions based on violation re unauthorized persons performing maint on hosp teletherapy unit
FLACK, E., AXELRAD, J. Director's Office, Office of Inspection and Enforcement EA-83-013A 83/06/17 1p 18914.204
- 8306210148 PNO-III-83-046 on 830610, contaminated water from Halden Spring Chemical Plant appeared to be draining into site sewage sys due to dislodged mechanical plug Cause unknown Plug replaced
NICHOLSON, N., SCHUMACHER, M. Region 3, Office of Director 83/06/15 2pp 18915 246
- 8306210237 PNO-I-83-062 on 830609, extremity TLD ring badge, used by employee during recovery of 40 Ci Ir-192 source from radiography device, indicated overexposure. Region I will review & evaluate incident on 830620
DAVIS, KINNEHAN, JOYNER Region 1, Office of Director 83/06/16 2pp 18916 041.
- 8306210242 PNO-III-83-045 on 830614, bomb threat received from male caller complaining of increased electric rates & state & federal economic policies Sheriff & FBI notified
CHRISTOFFER, Q., CREED, J. Region 3, Office of Director 83/06/15 1p 18916 351 24X Fiche 50-331, 83/06/15, 8306210242
- 8306210248 PNO-I-83-014 on 830615, control room received low seal flow alarm & lost indication of seal leak-off flow on reactor coolant pump IC Valve CH210 found closed Licensee interviewing personnel working in containment area
MCKEDOWN, M., QODDY, JOYNER Region 1, Office of Director 83/06/16 2pp 18915 251 24X Fiche 50-334, 83/06/06, 8306210248
- 8306220060 PNO-III-83-044 on 830614, radiation chemistry lab foreman found shot twice No known connection exists between apparent murder & employment
BYDD, D., SHAFER, W. Region 3, Office of Director 83/06/15 1p 18930 174 24X Fiche 50-299, 83/06/15, 8306220060

NONDOCKETED ITEMS

421

8306230001 PNS-I-83-015 on 830616,unannounced narcotics search of site initiated & one marijuana cigarette found in pocketbook belonging to contract security watchperson Individuals employment terminated
MADDEN, W. , GOODY, A. , JOYNER, J. Region 1, Office of Director 83/06/17 1p 18947 077 24X Fiche 50-243,83/06/17,8306230001

8306230002 PNO-I-83-064 on 830618,electrical generator/turbine trip caused reactor to trip investigation revealed fault originated within main generator End turns on some windings melted & portions of internals covered w/carbon
GREENMAN, E. Q. Region 1, Office of Director 83/06/20 1p 18947 078 24X Fiche 50-286,83/06/20,8306230002

8306230246 PNO-III-83-047 on 830615,two radiography workers received apparent whole body overexposures to radiation Caused by failure of radiographers to adequately secure radiation source in shielded position
SHENIAHSKI, D. , SLAWINSKI, W. Region 3, Office of Director 83/06/17 1p 18945 230

8306230248 PNO-II-83-049 on 830616,licensee shut reactor down in compliance w/plant operating requirements because one of two emergency power diesel generators was inoperable Caused by cooling water leak into cylinders
JACKMAN, C. A. , VERRELLI, D. M. Region 2, Office of Director 83/06/17 2pp 18945 228 24X Fiche 50-339,83/06/17,8306230248

8306230263 PNO-I-83-043 on 830617,licensee reported that during lodination on 830610,approx 1.25 mCi I-125 released from hood at Yale medical ctr All activities in affected lodination facility suspended No press release planned
FRIEDMAN, L. , JOYNER, J. Region 1, Office of Director 83/06/17 1p 18945 075

8306230330 PNO-III-83-050 on 830617,w/circuit breakers for core spray valves closed,core spray valves opened Approx 400 gallons lake water injected into reactor vessel,raising chloride concentration Event not reported within 1 h
HOLZMER, M. , JACKMAN, W. L. Region 3, Office of Director 83/06/17 1p 18942 274 24X Fiche 50-135,83/06/17,8306230330

8306230334 PNO-I-83-066 on 830620,fire discovered in 480-volt vital switchgear room Source of fire was phase C of 2B 480 transformer Fire extinguished Cause of fire under investigation
SUMMERS, R. , COLLINS, S. Region 1, Office of Director 83/06/20 1p 18942 348 24X Fiche 50-311,83/06/20,8306230334

8306230347 PNO-I-83-065 on 830617,contract between util & Util Workers of America Local 1-2 expired Union/mgmt turnover conducted w/o incident Reverification of sys lineups & insp of equipment completed Media attention evident
GREENMAN, E. Q. Region 1, Office of Director 83/06/20 1p 18943 280 24X Fiche 50-247,83/06/20,8306230347

8306230398 PNO-V-83-024 on 830616,while increasing condenser vacuum & resetting trip setpoint,low vacuum turbine trip occurred followed by reactor trip from 100% power Caused by low primary plant pressure
ECKHARDT, J. H. , KIRSCH, D. F. Region 3, Office of Director 83/06/16 1p 18943 075 24X Fiche 50-361,83/06/16,8306230398

8306230438 PNO-III-83-048 on 830615,contractor employee reentered plant unescorted after triggering contamination monitor on existing plant Employee instructed to proceed to radiation protection ofc located in vital area for decontamination
CREED, J. , MILLER, J. , HIND, J. Region 3, Office of Director 83/06/17 1p 18942 078 24X Fiche 50-295,83/06/17,8306230438

8306230462 PNS-I-83-014A updates PNS-I-83-014 re possible equipment tampering on 830615 On 830617,FBI concluded no evidence of deliberate equipment tampering evident Valve probably inadvertently closed
BAILEY Region 1, Office of Director 83/06/20 1p 18941 328. 24X Fiche. 50-334,83/06/20,8306230462

8306270181 PNO-III-83-051, on 830621,util authorized to proceed w/installation of electrical penetration area temporary support beams & excavation under auxiliary bldg Workers laid off 830617 & 18 recalled
LANDSMAN, R. , HARRISON, J. Region 3, Office of Director 83/06/21. 1p. 18991 344. 24X Fiche 50-329,83/06/21,8306270181

8306270240 PNO-II-83-050 on 830620,bimonthly inventory difference resulting from 830420 physical inventory reported inventory difference was accounting gain greater than calculated error limit Investigation initiated by licensee
MCALPINE, E. J. Region 2, Office of Director 83/06/21 1p 18988 269.

8306270279 PNO-III-83-052 on 830620,electrical fire occurred in generator exciter,forcing shutdown of unit for 2-3 hrs Storing process caused short in rings/brush manifold assembly Damage extensive
TONGUE, T. , SHAFER, W. Region 3, Office of Director 83/06/21 1p 18996 172 24X Fiche 50-237,83/06/21,8306270279

8306280017 PNO-V-83-022A on 830622, personnel determined that RCB piping in areas of welds other than reported on 830510 may be less than min wall thickness Reduction in wall thickness occurred during original preservice exam
KIRSCH, D. F. Region 3, Office of Director 83/06/23 1p 19001 119 24X Fiche 50-275,83/06/23,8306280017

8306280203 PNO-I-83-067 on 830622,Tristate tractor trailer carrying radwaste struck near rear axle by passenger car Five passengers in car injured.Truck driver not injured & radioactive mail not damaged Mail transferred to new truck
KINNEHAN, J. , BRENNEMAN, F. Region 1, Office of Director 83/06/23. 1p 19013 073

8306280337 PNO-I-83-063A on 830621,licensee rept received that several hoods exhaust through same duct as one through which I-125 released Concentration estimated at 57.8 times max permissible concentration All activities suspended
FRIEDMAN, L. , JOYNER, J. Region 1, Office of Director. 83/06/23 1p 19020 002

8306280382 PNS-I-83-016 on 830622,bomb threat by unidentified male caller received at plant site & TV station Reactor & turbine bldgs evacuated & search procedures initiated,per emergency & safeguards contingency plans.Results negative.
MADDEN, W. , GOODY, A. Region 1, Office of Director 83/06/23. 2pp. 19017 328 24X Fiche. 50-387,83/06/23,8306280382

8306300026 PNO-III-83-053 on 830621,one of two manual isolation valves for vacuum breakers D found closed,rendering vacuum breaker inoperable Cause being reviewed Appropriate enforcement action to be initiated
JORGENSEN, B. L. , SHAFER, W. D. Region 3, Office of Director 83/06/24 2pp 19120 313 24X Fiche 50-373,83/06/24,8306300026

8306300106 EN-83-011A on 830218,notice of violation & proposed imposition of civil penalties will be issued in amount of \$600,000 Action based on failure to perform Tech Spec surveillances on safety sys & components.
BARBER, Q. , AXELRAD, J. Director's Office, Office of Inspection and Enforcement 83/06/28. 1p 19048 216 24X Fiche 50-324,83/06/28, 8306300106

8306300115 EN-83-044 on 830701,notice of violation & proposed imposition of civil penalties will be issued based on licensee failure to adequately control access to high radiation area & to unlocked radiography device.
FLACK, E. , AXELRAD, J. Director's Office, Office of Inspection and Enforcement 83/06/28 1p 19121 075

MISC PUBLIC DOCUMENT ROOM MISCELLANEOUS

8306030215 Response to 830306 memo re followup on AEOB recommendations Formal tracking & followup sys acceptable,NRR contact designated as T Ippolito.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 83/05/24 HELTEMES, C. J. Director's Office 1p 18733 345.

8306030348 Provides justification for removal of company name from list of companies receiving fraudulent mails from Ray Miller, Inc.
KEMP, R. D. FBI Industries. 83/05/26 JORDAN, E. L. Director's Office, Office of Inspection and Enforcement. 2pp. 18704 358.

8306070186 Responds to 830518 request for interpretation of 10CFR21 re supplier of commercial-grade product While manufacturer/supplier not subj to Part 21 regulations,manufacturer/supplier must rept known defects or failures
POTAPDOVB, U. Region 4, Office of Director. 83/06/02 HENGBELI, S. Special-T-Metals Co., Inc. 2pp 18736 301

--8306070189 Requests 10CFR21 interpretation for supplier of commercial-grade product,per 830517 telcon.
HENGBELI, S. Special-T-Metals Co., Inc. 83/05/18. POTAPDOVB, U. Region 4, Office of Director 1p 18736 303

8306070318 Forwards RH Brickley survey of QA procedures applied by BNL to computer code activities re NRC-funded programs Series of natl lab surveys complete
BANGART, R. L. Division of Vendor & Technical Programs. 83/06/02. MATTHEW, R. J. Division of Systems Integration,NRR (post 811005). 2pp. 18746 057

NONDOCKETED ITEMS

- 8306070466 Forwards rept on feasibility of one megawatt TRIGA Reactor at Univ of Colombo & summary of 830425 meeting w/Japanese Ministry of Intl Trade & Industry, Sri Lanka Atomic Energy Authority & utility in Tokyo, Japan
THOMAS, C D Standardization & Special Projects Branch 83/05/25
DENTON, H R, EISENHUT, D O, MIRAGLIA, F J NRC - No Detailed Affiliation Given 2pp 18780 335
- 8306070468 "Rept on Feasibility of One Megawatt TRIGA Reactor at Univ of Colombo Campus"
THOMAS, C D Standardization & Special Projects Branch 83/05/25 7pp 18780 337
- 8306080077 Concurs w/revised surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys per Generic Ltr 83-13 Use of ANSI/ASME N510 1975 edition questioned Updating ref will eliminate errors
JACOBI, J H Nuclear Consulting Services, Inc GL-83-13 83/06/01
EISENHUT, D O Division of Licensing 1p 18773 263
- 8306080087 Approves priority ranking of medium for Generic Issue 51, "Proposed Requirements for Improving Reliability of Open Cycle Svc Water Sys." Schedule for completing issue should be consistent w/FY84-86 NRR budget request
DENTON, H R Office of Nuclear Reactor Regulation, Director 83/06/03
MATTHEWSON, R J Division of Systems Integration (post 811005) 10pp 18787 345
- 8306090200 Forwards users manual for dual porosity pipe flow code, GNET/DVM NRC received mod to GNET/DVM on 830931 from Sandia which permits use of dual porosities in first flow leg downstream of repository. W/o encl
BELL, H J High Level Waste Licensing Management Branch 83/06/01
BROWNING, R E Division of Waste Management 1p 18809 251
- 8306090323 Comments on proposed Commission paper re severe accident research program, per 830509 request Proposed outline should be modified to recognize early issuance of final severe accident policy statement
EISENHUT, D O Division of Licensing 83/05/31
EPEIS, T P Division of Safety Technology 2pp 18797 111
- 8306090371 Responds to 830505 request NRR concurs w/proposed Commission paper re immediate notification requirement for operating nuclear power reactors (10CFR50 72)
DENTON, H R Office of Nuclear Reactor Regulation, Director 83/05/31
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 1p 18815 158
- 8306090438 Responds to 830505 request to review proposed reportable scope for NRRDS Comments on failure rate data submitted
DENTON, H R Office of Nuclear Reactor Regulation, Director 83/06/03
HELMES, C J Director's Office 2pp 18809 138
- 8306090474 Ack receipt of 830506 memo itemizing all ongoing studies being performed by AEDD Encl memo distributed throughout NRR to solicit comments W/o encl
DENTON, H R Office of Nuclear Reactor Regulation, Director 83/05/31
HELMES, C J Director's Office 1p 18815 157
- 8306130353 Forwards fuel cycle & matls LER summary for Mar 1983
BROWN, G D Region 4, Office of Director 83/06/07
DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director
MICHELSON, C Director's Office 3pp 18822 317
- 8306140202 Offers no comments in response to 830518 memo re draft NRC manual chapter on security of shared logic word processing sys
THOMAS, C D Standardization & Special Projects Branch 83/06/02
WILLIAMS, M Division of Licensing 1p 18844 212
- 8306140294 Submits followup to 830408 memo requesting review of proposed rules to implement hybrid hearing process required in Section 134 of Nuclear Waste Policy Act of 1982
DENTON, H R Office of Nuclear Reactor Regulation, Director 83/05/23
CUNNINGHAM, G H Office of the Executive Legal Director 1p 18844 200
- 8306140668 Responds to inquiry re color vision criteria for NRC operator license exams Applicant generally required to pass practical test in nuclear plant control room to determine ability to operate plant safely & competently
GIBSON, A F Region 2, Office of Director 83/04/08
HOLMES, K R Affiliation Unknown 1p 18841 262
- 8306140675 Requests interpretation of color blindness requirement for senior reactor operator license exam
HOLMES, K R Affiliation Unknown. 83/04/08 Region 2, Office of Director 1p 18841-263
- 8306200435 Recommends integrated assessment of all access controls on plant safety for three facilities, to determine scope of potential safety problems re locked doors & barriers
Response within 10 days requested
EISENHUT, D O Division of Licensing 83/05/31
MATTHEWSON, R J Division of Systems Integration (post 811005)
THOMPSON, H L Division of Human Factors Safety
VOLLMEYER, R H Division of Engineering 3pp 18920 014
- 8306210239 Comments on Commission 830413 memo denying issuance of proposed rulemaking on third-party accreditation of labs, per 10CFR50 49 (SECY-82-153) Clarification & enforcement of NRC responsibility recommended
BANGART, R L Division of Vendor & Technical Programs 83/06/17
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 7pp 18919 012
- 8306210291 Advises that status rept on QA reviews re change to 10CFR50 will be issued on or about 13th of each month Summary of activities to date provided All Region IV licensee programs will be submitted by Jul 1983
HALC, C J Division of Vendor & Technical Programs 83/06/17
COLLINS, J T Region 4, Office of Director 2pp 18914 022
- 8306240264 Responds to 830606 request for opinion re criteria for employment as security personnel Past use of marijuana w/o evidence of current usage should not disqualify individual from consideration as security officer
LIEBERMAN, J Regional Operations & Enforcement Division 83/06/14
PULCINI, R A National Labor Relations Board 2pp 18980 108
- 8306280125 Comments on AEOD Apr 1983 rept on failures of Class IE safety-related switchgear circuit breakers to close on demand Periodic testing & rigorous main procedures, instead of design changes recommended
DENTON, H R Office of Nuclear Reactor Regulation, Director 83/06/17
HELMES, C J Director's Office 3pp 19056 292
- 8310290150 Disagrees w/conclusion in rept on failures of Class IE safety-related switchgear circuit breakers to close on demand re need to make design changes in Class IE breaker surveillance circuits
DENTON, H R Office of Nuclear Reactor Regulation, Director 82/09/23
MICHELSON, C Director's Office 3pp 66406 300
- NUREG NUREG REPORTS AND RELATED CORRESPONDENCE
- 8305170121 NUREG/CR-3173
NEW MADRID SEISMOTECTONIC STUDY Summary Of Activities 1977-1981
BUSCHBACH, T C St Louis Univ, St Louis, MO 83/03/31
Division of Health, Siting & Waste Management 214pp Available at NRC \$7 00 18480 209
- 8305240436 Forwards addl info on implementation of Rev 1 to NUREG-0313, in response to NRC 830408 request Wtwo oversize drawings
Aperture cards are available in PDR
HARRINGTON, W D Boston Edison Co 83-133 83/05/20
VASSALLO, D B Operating Reactors Branch 2 8pp 18573 224 24X
Fiche 50-293, 83/05/20, 8305240436
- 8305240443 Rev 4 to Procedure 22 A 16, "Ultrasonic Exam of Piping Welds"
DEEDS, P E Peabody International Corp 80/02/22 24pp 18573 232 24X Fiche 50-293, 83/05/20, 8305240436
- 8305240448 Rev 33 to Procedure SWRI-NDT-600-3, "Manual Ultrasonic Exam of Pressure Piping Welds"
* Southwest Research Institute 79/07/31 41pp 18573 256 24X
Fiche 50-293, 83/05/20, 8305240436
- 8305240455 Rev 3 to Procedure SWRI-NDT-700-5, "Mechanized Exam of Vessel Components, Vessel Welds & Piping Welds"
* Southwest Research Institute 79/09/30 20pp 18573 297 24X
Fiche 50-293, 83/05/20, 8305240436
- 8305240461 Rev 6 to Procedure SWRI-NDT-700-5, "Mechanized Ultrasonic Exam of Vessel Components, Vessel Welds & Piping Welds"
* Southwest Research Institute 81/02/28 28pp 18573 317 24X
Fiche 50-293, 83/05/20, 8305240436
- 8305310226 NUREG/CR-3085 V01
INTERIM RELIABILITY EVALUATION PROGRAM ANALYSIS OF THE MILLSTONE POINT UNIT I NUCLEAR POWER PLANT Docket No 50-245 (Northeast Utilities)
CURRY, J J, O'LAGHER, D W, MODARRES, M Sandia Laboratories FIN A-1241
SAND82-7212 83/04/30 Division of Risk Analysis 201pp 18682 277 24X Fiche 50-245, 83/04/30, 8305310226

1306010018 NUREQ-0979
SIZEMELL, D-ANALYSIS OF BRITISH APPLICATION OF US PWR
TECHNOLOGY
EDISON, G E Division of Licensing 83/05/31 95pp Available at
NRC \$5 50 18684 226

1306010039 NUREQ/CR-3012 V01
INTERACTIVE RAPID DOSE ASSESSMENT MODEL (IRDA) Volume 1
Users Guide
POETON, R W, MOELLER, M P, LAUGHLIN, G J Battelle Memorial
Institute, Pacific Northwest Laboratory FIN B-2311 PNL-4510
83/05/31 Division of Emergency Preparedness & Engineering
Response (Post 830103) 14pp Available at NRC \$3 25 18684 048

1306010041 NUREQ/CR-2843 V02
THERMAL/HYDRAULIC ANALYSIS RESEARCH PROGRAM QUARTERLY
REPORT APRIL - JUNE 1982
THOMPSON, S L Sandia Laboratories FIN A-1205 SAND82-1788
83/04/30 Division of Accident Evaluation 68pp 18687 104

1306010043 NUREQ-0892 803
SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF WPPSS
NUCLEAR PROJECT NO 2 Docket No 50-397 (Washington Public
Power Supply System)
* Division of Licensing 83/05/31 46pp Available at NRC
\$4 75 18684 082 24X Fiche 50-397, 83/05/31, 8306010043

1306010046 NUREQ-0936 V02 N01
NRC REGULATORY AGENDA Quarterly Report January - February
1983
* Division of Rules and Records 83/04/30 192pp 18685 060

1306010052 NUREQ/CR-3226
STATION BLACKOUT ACCIDENT ANALYSES (PART OF NRC TASK ACTION
PLAN A-44)
KOLACZKOWSKI, A, PAYNE, A C Sandia Laboratories FIN A-1302
SAND82-2450 83/05/31 Division of Safety Technology 279pp
Available at NRC \$8 00 18685 252

1306010057 NUREQ-0843 802
SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF ST
LUCIE PLANT, UNIT NO 2 Docket No 50-389 (Florida Power and
Light Company, And Orlando Utilities Commission Of The City
Of Orlando, Florida)
* Office of Nuclear Reactor Regulation, Director 82/07/30 99pp
Available at NRC \$5 50 18684 321 24X Fiche 50-389, 82/07/30,
8306010057

1306010063 Submits clarification to 830425 response to Item 7 of
Generic Ltr 83-02 re NUREQ-0737 Tech Specs Failures of
valves to close & challenges to valves to be reported per
Tech Spec 6.9.2 & 6.9.16, respectively
MANNAN, C V Niagara Mohawk Power Corp GL-83-02 83/05/26
VASSALLO, D B Operating Reactors Branch 2 1p 18674 087 24X
Fiche 50-220, 83/05/26, 8306010063

1306010065 Forwards "Control of Heavy Loads (C-10), Kewaunee Nuclear
Power Plant," draft technical evaluation report for review &
comment Conference call to discuss report scheduled for wk of
830610
VARGA, S A Operating Reactors Branch 1 83/05/16 GIESLER, C W
Wisconsin Public Service Corp 2pp 18693 332 24X
Fiche 50-305, 83/05/16, 8306010065

13060100714 TER-C9504-363 DRFT
"Control of Heavy Loads (C-10), Kewaunee Nuclear Power
Plant," draft technical evaluation report
WOSBURY, F W, DOMBERGER, C Franklin Institute/Franklin Research
Center NRC-03-81-130 TAC 46747 83/04/29 SARGENT, I H NRC -
No Detailed Affiliation Given 38pp 18696 001 24X
Fiche 50-305, 83/05/16, 8306010065

1306010072 NUREQ/CR-3012 V02
INTERACTIVE RAPID DOSE ASSESSMENT MODEL (IRDA) Volume 2
Accident Assessment Methods
POETON, R W, MOELLER, M P, LAUGHLIN, G J Battelle Memorial
Institute, Pacific Northwest Laboratory FIN B-2311 PNL-4510
83/05/31 Division of Emergency Preparedness & Engineering
Response (Post 830103) 88pp Available at NRC \$5 50 18684 138

1306010073 NUREQ/CR-3012 V03
INTERACTIVE RAPID DOSE ASSESSMENT MODEL (IRDA) Volume 3
Scenarios For Comparing Dose Assessment Models
POETON, R W, MOELLER, M P, LAUGHLIN, G J Battelle Memorial
Institute, Pacific Northwest Laboratory FIN B-2311 PNL-4510
83/05/31 Division of Emergency Preparedness & Engineering
Response (Post 830103) 151pp Available at NRC \$6 50,
18686 171

8306010081 NUREQ/CR-3191
TARGET ASSIGNMENTS FOR SECURITY OFFICERS TO K TARGETS
(TASK)
ROWLAND, J R, SHELTON, K W, STUNKEL, C B Oklahoma, Univ of FIN
A-1060 SAND83-7012 83/04/30 Division of Accident Evaluation
59pp 18687 024

8306010086 NUREQ/CR-2839
SURVEY OF ERROR PROPAGATION IN SYSTEMS
UPPULURI, V R, KUD, W Oak Ridge National Laboratory FIN B-0444
ORNL/CSD-TM-190 83/04/30 Division of Risk Analysis 24pp
18687 001

8306010088 NUREQ/CR-2785
IRRADIATION OF ZEOLITE ION-EXCHANGE MEDIA
SNYLER, K J, BARLETTA, R E Brookhaven National Laboratory FIN
A-3162 BNL-NUREG-51551 83/05/31 Division of Waste Management
68pp Available at NRC \$5 00 18684 001

8306010094 NUREQ/CR-3207
GEOLOGIC AND HYDROLOGIC RESEARCH AT THE WESTERN NEW YORK
NUCLEAR SERVICE CENTER, WEST VALLEY, NEW YORK Annual Report
August 1981 - July 1982
ALBANESE, J R, ANDERSON, B L, DUNNE, L A New York, State of FIN
B-6350 83/05/31 Division of Health, Siting & Waste Management
414pp Available at NRC \$8 50 18687 304 24X
Fiche 50-201, 83/05/31, 8306010094

8306010138 NUREQ/BR-0015
DOCUMENT CONTROL SYSTEM NEWSLETTER
* Division of Technical Information & Document Control 83/04/29,
6pp 18686 332

8306010144 NUREQ/CR-2767 ERR
X-RAY MEASUREMENTS OF WATER FOAM DENSITY
CAMP, A L Sandia Laboratories FIN A-1246 SAND82-1292 83/02/21
Office of Nuclear Regulatory Research, Director 2pp 18686 329

8306010158 NUREQ-0800 R04 ERR
STANDARD REVIEW PLAN Proposed Revision 4 To & 2.2,
Containment Heat Removal Systems
* Office of Nuclear Reactor Regulation, Director 83/05/12 2pp
18686 327

8306010166 NUREQ-0869 FC ERR
USI A-43 RESOLUTION POSITIONS
SPEIS, T P Division of Safety Technology, 83/05/12 5pp
18686 322

8306010236 Clarifies responses to NUREQ-0612, "Control of Heavy Loads"
Turbine Crane MT-CRA-1 meets guidelines of NUREQ
DOUCHEY, G D Washington Public Power Supply System 002-83-337
83/04/13 SCHWENGER, A Licensing Branch 2 1p 18673 001, 24X
Fiche 50-397, 83/04/13, 8306010236

8306010266 NUREQ/CR-3164
SUBSURFACE MONITORING PROGRAMS AT SITES FOR DISPOSAL OF
LOW-LEVEL RADIOACTIVE WASTE
LITTON, R J, STROHM, W E, STRONG, A B Army, Dept of, Army Engineer
Waterways Experiment Station FIN B-7324 83/04/30 Division of
Waste Management 100pp Available at NRC \$5 50 18693 232

8306010316 Advises that performance of load test in excess of 100% of
max load unnecessary since crane operator training & safety
programs ensure safest possible operations in response to
801222 ltr re control of heavy loads (NUREG-0612)
WITHERS, B D Portland General Electric Co 83/05/24 EISENHUT, D O,
Division of Licensing 3pp 18682 138 24X Fiche 50-344, 83/05/24,
8306010316

8306010331 Submits list of post-trip review procedures to be modified
following review of results of NUREQ-0977 (Balem event) &
discussion w/NRC Mods will be made within 30 days
CLAYTON, F L Alabama Power Co 83/05/24 VARGA, S A Office of
Nuclear Reactor Regulation, Director 1p 18681 278 24X
Fiche 50-348, 83/05/24, 8306010331

8306010334 Submits response to Generic Ltr 83-02 re implementation
of NUREQ-0737 items No Tech Spec changes required for
Items I A 1.1.3, I A 1.3, II E 4.1, II E 4.2.3, II E 4.2.6,
II E 4.2.7, II K.3.3, II K 3.13, II K 3.22 & II K 3.15
HARRINGTON, W D, Boston Edison Co GL-83-02 83/05/24
EISENHUT, D O, Division of Licensing 2pp 18672 315 24X
Fiche, 50-293, 83/05/24, 8306010334

8306010399 Informs that add'l clad swell & rupture model calculations in
progress, per NUREQ-0630 implementation schedule Final report
will be issued by 830620
RODRIGUEZ, R J Sacramento Municipal Utility District RJR 83-434
83/05/23 STOLZ, J F Operating Reactors Branch 4 1p 18682:240
24X Fiche 50-312, 83/05/23, 8306010399

NONDOCKETED ITEMS

8306010400 Forwards proposed schedule re current status of emergency response capability per Region V 830301 meeting (Generic Ltr 82-33 & Suppl 1 to NUREG-0737)
BOKUCHEY, D D Washington Public Power Supply System 002-83-346
83/04/15 SCHWENGER, A Licensing Branch 2 4pp 18682 241 24X
Fiche 50-397, 83/04/15, 8306010400

8306010413 Forwards descriptions of responsibilities of nuclear safety assurance group, in confirmation of 830209 meeting Encl provides revised response to TH1 Items I B 1 2 & I C 3
BOKUCHEY, D D Washington Public Power Supply System 002-83-345
83/04/15 SCHWENGER, A Licensing Branch 2 6pp 18674 244 24X
Fiche 50-397, 83/04/15, 8306010413

8306010428 Advises of failure to complete installation & place in operation portions of radioactive monitoring equipment for compliance w/NUREG-0737, Item II F 1.1, "Noble Gas Monitoring." Completion expected by 830630
FAY, C W Wisconsin Electric Power Co 83/05/25 DENTON, H R Office of Nuclear Reactor Regulation, Director. CLARK, R A Operating Reactors Branch 3 5pp 18679 321 24X
Fiche 50-266, 83/05/25, 8306010428

8306010441 Submits response to 10CFR50.49, "Environmental Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants." Master list of safety-related electrical equipment encl
MUSOLF, D M Northern States Power Co IEB-79-018 83/05/19 Office of Nuclear Reactor Regulation, Director 30pp 18674:272 24X Fiche 50-263, 83/05/19, 8306010441

8306010477 Informs that NUREG-0737, Item III A 2.1, "Emergency Preparedness, Upgrade Emergency Plans to App E, 10CFR50," completed item closed.
CLARK, R A Operating Reactors Branch 3 83/05/11 LUNDVALL, A E Baltimore Gas & Electric Co 3pp 18688 399 24X
Fiche 50-317, 83/05/11, 8306010477.

8306020007 NUREG/CR-2841
LIGHT WATER REACTOR SAFETY RESEARCH PROGRAM SEMIANNUAL REPORT, OCTOBER 1981 - MARCH 1982.
BERMAN, M Sandia Laboratories FIN A-1019 SAND82-1572. 83/05/31 Division of Accident Evaluation. 302pp 18700 014

8306020011 NUREG/CR-3210
LOW-LEVEL WASTE RISK METHODOLOGY DEVELOPMENT
COX, N D, FALCONER, K L, ROPE, B. K. EQ&G, Inc FIN A-6310
EQ&G-2247. 83/05/31 Division of Risk Analysis 54pp 18698 218

8306020015 Requests performance or documentation of completion of load test of reactor vessel head lifting fixture for control of heavy loads, Phase I within 120 days Guidelines for response & complete draft technical evaluation rept encl.
CLARK, R A Operating Reactors Branch 3 83/05/24 GARRITY, J H Maine Yankee Atomic Power Co 16pp 18701 146 24X
Fiche 50-309, 83/05/24, 8306020015.

--8306020037 TER-C5306-365 DRAFT
"Control of Heavy Loads (C-10), Maine Yankee Atomic Power Co, Main Yankee Nuclear Power Station," draft technical evaluation rept
VITO, D. J., BOMBERGER, C., SARGENT, I H Franklin Institute/Franklin Research Center NRC-03-81-130 TAC-08059. 82/12/30
CLEMENSSEN, F. NRC - No Detailed Affiliation Given 26pp. 18701 162. 24X Fiche 50-309, 83/05/24, 8306020037.

8306020016 NUREG/CR-3189
LARGE SCALE EXPLORATORY TESTS OF SODIUM MAGNETITE CONCRETE INTERACTIONS.
RANDICH, E., ACTON, R U Sandia Laboratories FIN A-1034
SAND83-0336 83/05/31. Office of Nuclear Regulatory Research, Director. 72pp. 18702:235.

8306020020 Informs that, based on review of BWR Owners Group 801230 response to NUREG-0737, Item II K 3.43, "Depressurization W/ Other Than Automatic Depressurization Sys.," complete.
VASSALLO, D. B. Operating Reactors Branch 2 83/05/18 UTLEY, E E 7pp. 18702 336 24X
020

IR EMERGENCY CONDITIONS AT

OETON, R W Battelle Memorial
ratory FIN-84491 PNL-4491
-V Preparedness & Engineering
Available at NRC. 86 50

8306020056 Responds to 830414 ltr re Generic Ltr 82-33 requirements concerning Suppl 1 to NUREG-0737 Portion of response addressing detailed control room design review does not provide all info requested Response requested by 830531
KNIGHTON, G W Licensing Branch 3 GL-82-33 83/05/10 VAN
BRUNT, E E Arizona Public Service Co 6pp 18701 349 24X
Fiche 50-328, 83/05/10, 8306020056

8306020066 NUREG/CR-2949
SOLIDIFICATION OF IRRADIATED EPICOR-II WASTE PRODUCTS
BARLETTA, R E., SHYLER, K J., CHAN, S F Brookhaven National Laboratory FIN A-3162 BNL-NUREG-51590 83/05/31 Division of Waste Management 141pp Available at NRC 86 50 18699 032

8306020072 NUREG/CR-2006
MODELING AND ANALYSIS OF LOW HEAT FLUX NATURAL CONVECTION SODIUM BOILING IN LMFBRS
KHATIB-RAHDAR, CAZZOLI, E O Brookhaven National Laboratory FIN A-3013 BNL-NUREG-51541 83/05/31 Division of Accident Evaluation 68pp 18698 103

8306020080 NUREG/CR-3131 V01
CONTAINMENT INTEGRITY PROGRAM FY82 ANNUAL REPORT
BLEJWAS, T. E., WOODFIN, R L., DENNIS, A W Sandia Laboratories FIN A-1249 SAND83-0417 83/05/31 Division of Engineering Technology. 55pp 18701 286

8306020112 NUREG-0987
ENVIRONMENTAL IMPACT APPRAISAL FOR RENEWAL OF SPECIAL NUCLEAR MATERIAL LICENSE NO SNM-1168 Docket No. 70-1201 (Babcock & Wilcox Company Commercial Nuclear Fuel Plant)
* Office of Nuclear Material Safety & Safeguards, Director 83/05/31 141pp Available at NRC 86 50 18698 271

8306020122 NUREG/CR-3245
METABOLIC DATA AND RETENTION FUNCTIONS FOR THE INTRACELLULAR ALKALI METALS
LEOGETT, R W Oak Ridge National Laboratory FIN B-0480-2 ORNL/TM-8630 83/05/31 Division of Facility Operations 93pp 18701 188

8306020131 NUREG/CR-2800 801
GUIDELINES FOR NUCLEAR POWER PLANT SAFETY ISSUE PRIORITIZATION INFORMATION DEVELOPMENT
ANDREWS, W B., GALLUCCI, R H., KONZEK, G J Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2507 PNL-4297 83/05/31 Division of Safety Technology 235pp Available at NRC 87 50. 18697 230

8306020134 NUREG/CR-2837 801
PNL TECHNICAL REVIEW OF PRESSURIZED THERMAL SHOCK ISSUES
Technical Critique of the NRC Near-Term Screening Criteria
PEDERSON, L T., APLEY, W J., BIAN, S H Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2510 PNL-4327 83/05/31 Division of Safety Technology 54pp Available at NRC 84 75 18698 168

8306020144 NUREG-0485 V05 N04
SYSTEMATIC EVALUATION PROGRAM STATUS SUMMARY REPORT Data As of April 30, 1983 (Buff Book)
* Division of Data Automation & Management Information 83/05/31 70pp 18697 128

8306020146 Forwards info supporting post-implementation review of post-accident sampling sys Eleven criteria from NUREG-0737, Item II B 3 addressed Description of reactor coolant & containment air post-accident sampling sys encl
GARRITY, J H Maine Yankee Atomic Power Co MN-83-97 83/05/26
CLARK, R A Operating Reactors Branch 3 28pp 18694 130 24X
Fiche 50-309, 83/05/26, 8306020146

8306020169 Requests deferral of responses to applicants motion for summary disposition of New England Coalition on Nuclear Pollution Contention I D 2 re reactor trip sys until 20 days after svc of NUREG-1000, Vol 2
PERLIS, R O Hearing Branch 3. ISSUANCES OL 83/05/31. HOYT, H, LUESKE, E A, HARBOUR, U, Atomic Safety and Licensing Board Panel 2pp 18690 361. 24X Fiche 50-443, 83/05/31, 8306020169

8306020188 Forwards Franklin Research Ctr draft technical evaluation rept, "Control of Heavy Loads (C-10), Florida Power Co, Crystal River Unit 3." Guidance document, "Synopsis of Issues Associated w/NUREG-0612," also encl
STOLZ, J F Operating Reactors Branch 4 83/05/19 WILGUS, W S Florida Power Corp. 2pp 18701, 072 24X Fiche 50-302, 83/05/19, 8306020188

--8306020196 TER-C5306-347 DRAFT
"Control of Heavy Loads (C-10), Florida Power Co, Crystal River Unit 3," draft technical evaluation rept
BOMBERGER, C., VOSBURY, F W Franklin Institute/Franklin Research Center NRC-03-81-130 83/01/28 CLEMENSSEN, F NRC - No Detailed Affiliation Given 39pp 18701 074 24X Fiche 50-302, 83/05/19, 8306020188

8306020193 NUREG/CR-2814 V03
NUCLEAR REACTOR SAFETY July - October 1982
STEVENSON, M G Los Alamos Scientific Laboratory FIN A-7420
LA-9649-PR 83/04/30 Division of Accident Evaluation 31pp
18677 199

8306020232 Forwards Rev 0 to Salem Generating Station Emergency
Operating Procedures Generation Package, per Suppl 1 to
NUREG-0737 (Generic Ltr 82-33)
LIDEN, E A Public Service Electric & Gas Co of New Jersey
GL-82-33 83/05/20 VARGA, S A Operating Reactors Branch 1 1p
18689 001 24X Fiche 50-272, 83/05/20 8306020232

--8306020240 Rev 0 to "Salem Generating Station Emergency Operating
Procedures Generation Package"
GUELLER, J, FRY, L, BERKLEY, J Public Service Electric & Gas Co
of New Jersey GL-82-33 83/04/20 166pp 18689 002 24X
Fiche 50-272, 83/05/20, 8306020232

8306020281 Responds to 830510 ltr requesting addl info re status of
NUREG-0737, Item II F 1 Installation of Unit 2 high range
containment monitor trending & recording function completed
Monitor operational
MUNTER, R S Indiana & Michigan Electric Co HEP NRC 0678F
83/05/27 DENTON, H R Office of Nuclear Reactor Regulation,
Director 3pp 18690 315 24X Fiche 50-315, 83/05/27, 8306020281

8306020283 Forwards rev to 801219 response to NUREG-0737, Item I C 6,
"Guidance on Procedures for Verifying Correct Performance of
Operating Activities," per 821222 Tech Spec change re shift
technical advisor
BORRINE, T C Consumers Power Co 83/05/23 CRUTCHFIELD, D
Operating Reactors Branch 5 2pp 18690 318 24X
Fiche 50-155, 83/05/25, 8306020283

8306020524 Discusses status of 820827 commitment to perform
comprehensive stress analyses of reactor vessel closure head
& internals lifting rigs to provide scope & schedule of
effort Results scheduled for submittal by 830831
GARRITY, J H Maine Yankee Atomic Power Co MM-83-115 83/05/27
CLARK, R A Operating Reactors Branch 3 2pp 18693 241 24X
Fiche 50-309, 83/05/27, 8306020524

8306020570 Comments on NUREG-0737, Item III A 2 1, "Emergency
Preparedness, Upgrade Emergency Plans to App E, 10CFR50,"
Onsite & offsite emergency preparedness adequate Item
closed
VARGA, S A Operating Reactors Branch 1 83/05/24 CLAYTON, F L
Alabama Power Co 2pp 18715 066 24X Fiche 50-348, 83/05/24,
8306020570

8306020598 Forwards draft SER, NUREG-0422, Suppl 7 & "Evaluation of
McGuire Units 1 & 2 Undervoltage Trip Attachment Failures,"
Interim technical evaluation rept & draft full power DL
asend
NOVAK, T M Assistant Director for Licensing 83/05/24 TUCKER, H B
Duke Power Co 44pp 18718 001 24X Fiche 50-369, 83/05/24,
8306020598

8306020601 Forwards briefing package for forthcoming Commission
meeting re full power operation Package includes briefing
slides, SER Suppl 7, DL issued on 830303 & proposed amend
DIRCKS, W J Office of the Executive Director for Operations
83/05/24 PALLADINO, N, GILINSKY, V, AHFARNE, J Commissioners
147pp 18717 198 24X Fiche 50-370, 83/05/24, 8306020601

8306020604 Confirms NRC caseload forecast panel findings resulting from
830302-04 site visit to assess complet completion schedules
[issuance of suppl] to SER (NUREG-0847) scheduled for Nov
1983
NOVAK, T M Assistant Director for Licensing 83/05/24 PARRIS, H O
Tennessee Valley Authority 3pp 18715 050 24X
Fiche 50-390, 83/05/24, 8306020604

8306020676 Informs that NUREG-0737, Items II F 1 4, "Containment
Pressure Monitor," & II F 1 5, "Containment Hydrogen
Monitor" completed Items closed
VARGA, S A Operating Reactors Branch 1 83/05/17 CAREY, J J
Duquesne Light Co. 6pp 18716 249 24X Fiche 50-334, 83/05/17,
8306020676

8306020694 Submits rept re turbine missile issue Rept completes NRR
action requested in ACRS 820713 ltr Results documented in
Suppl 3 to SER (NUREG-0887)
NOVAK, T M Assistant Director for Licensing 83/05/23 RAY, J J
ACRS - Advisory Committee on Reactor Safeguards 10pp 18716 237
24X Fiche 50-440, 83/05/23, 8306020694

8306030009 NUREG/CR-3217
NEAR-TERM IMPROVEMENTS FOR NUCLEAR POWER PLANT CONTROL ROOM
ANNUNCIATOR SYSTEMS
RANKIN, W L, ANES, K R Battelle Memorial Institute, Pacific
Northwest Laboratory DUVENNOY, E O Battelle Human Affairs Research
Centers FIN D-2360 PNL-4662 83/04/30 Division of Human
Factors Safety 65pp Available at NRC #5 00 18733 073

8306030020 Forwards "Control of Heavy Loads at Nuclear Power Plants,
Washington Nuclear Project 2 (Phase II - Interim),"
technical evaluation rept
SCHWENGER, A Licensing Branch 2 83/05/24 FERGUSON, R L
Washington Public Power Supply System 2pp 18733 146 24X
Fiche 50-397, 83/05/24, 8306030020

--8306030088 "Control of Heavy Loads at Nuclear Power Plants, Washington
Nuclear Project 2 (Phase II - Interim)," draft technical
evaluation rept
DIXON, B W, STICKLEY, T H EG&G, Inc FIN A-6457 83/05/24
NRC - No Detailed Affiliation Given 20pp 18733 148 24X
Fiche 50-397, 83/05/24, 8306030088

8306030067 Forwards synopsis of issues to resolve conformance
w/NUREG-0612 re control of heavy loads (Phase I) & draft
technical evaluation rept
CLARK, R A Operating Reactors Branch 3 83/05/17 STEWART, W L
Virginia Electric & Power Co 13pp 18733 211 24X
Fiche 50-358, 83/05/17, 8306030067

--8306030070 TER-C5506-372/373 DR
"Control of Heavy Loads (C-10), Virginia Electric Power Co,
North Anna Power Station Units 1 & 2," draft technical
evaluation rept
BORBERGER, C R, VOSBURY, F W, SARGENT, I H Franklin
Institute/Franklin Research Center NRC-03-81-130 TAC 47112
83/02/22 NRC - No Detailed Affiliation Given 25pp
18733 224 24X Fiche 50-358, 83/05/17, 8306030067

8306030089 Informs that onsite & offsite emergency preparedness
adequate & emergency plans upgraded per NUREG-0737, Item
III A 2 1 Item complete.
CLARK, R A Operating Reactors Branch 3 83/05/20 GARRITY, J H
Maine Yankee Atomic Power Co 3pp 18733 280 24X
Fiche 50-309, 83/05/20, 8306030089

8306030096 Informs that NUREG-0737, Item III A 2 1, "Emergency
Preparedness, Upgrade Emergency Plans to App E, 10CFR50,"
complete Item closed
STOLZ, J F Operating Reactors Branch 4 83/05/18 BAUER, E O
Philadelphia Electric Co 3pp 18733 293 24X
Fiche 50-277, 83/05/18, 8306030096

8306030110 Forwards safety evaluation re BWR Owners Group 801230
response to NUREG-0737, Item II K 3 45, "Depressurization
W/Other Than Automatic Depressurization Sys." No mod to
plant design or operation required
STOLZ, J F Operating Reactors Branch 4 83/05/18 BAUER, E O
Philadelphia Electric Co 2pp 18733 297 24X
Fiche 50-277, 83/05/18, 8306030110

8306030122 Forwards addl info to aid in completion of review re NUREG-
0737, Items II F 1 4, II F 1 5 & II F 1 6, per 830110 ltr
request & justification concerning Item II F 1 5 Amend to
830318 confirmatory order requested
TUCKER, H B Duke Power Co 83/05/31 DENTON, H R Office of
Nuclear Reactor Regulation, Director 15pp 18704 302 24X
Fiche 50-269, 83/05/31, 8306030122

8306030132 Ack receipt of 830325 ltr requesting waiver of 3 month
 hiatus between submittal of procedures generation package
& initiation of training on upgraded emergency procedures
Waiver granted
STOLZ, J F Operating Reactors Branch 4 83/05/17 WILGUS, W S
Florida Power Corp 2pp 18733 306 24X Fiche 50-302, 83/05/17,
8306030132

8306030157 Staff requirements memo informing of Commission 830313
briefing in Washington, DC on NUREG-1000, "Generic
Implications of ATWS Events at Salem Nuclear Power Plant"
Operating criteria requested
CHILK, S J Office of the Secretary of the Commission MB30318
83/05/27 DIRCKS, W J Office of the Executive Director for
Operations 1p 18733 313 24X Fiche 50-272, 83/05/27, 8306030157

8306030253 Informs that NUREG-0737, Item III A 2 1, "Emergency
Preparedness, Upgrade Emergency Plans to App E, 10CFR50,"
completed Item closed
STOLZ, J F Operating Reactors Branch 4 83/05/17 WILGUS, W S
Florida Power Corp 3pp 18734 067 24X Fiche 50-302, 83/05/17,
8306030253

NONDOCKETED ITEMS

8306030290 Forwards addl guidance on acceptable solutions to open items re control of heavy loads in compliance w/NUREG-0612 & draft "Control of Heavy Loads (C-10), Donald C Cook Nuclear Plant Units 1 & 2," technical evaluation rept
VARGA, S A Operating Reactors Branch 1 83/05/16 DOLAN, J
Indiana & Michigan Electric Co 14pp 18734 086 24X
Fiche 50-315, 83/05/16, 8306030290

--8306030299 TER-C5506-344/345 DR
Draft "Control of Heavy Loads (C-10), Donald C Cook Nuclear Power Plant Units 1 & 2," technical evaluation rept
VOSBURY, F W Franklin Institute/Franklin Research Center
NRC-03-B1-130 TAC 07980 83/02/24 CLEMENSON, F NRC - No
Detailed Affiliation Given 33pp 18734 100 24X
Fiche 50-315, 83/05/16, 8306030290

8306030300 Forwards Vols 1 & 2 to Rev 1 to "Duke Power Co Response to Suppl 1 to NUREG-0737 for Catauba Nuclear Station"
TUCKER, H B Duke Power Co 83/06/01 DENTON, H R Office of
Nuclear Reactor Regulation, Director ADENSAH, E G Licensing Branch
4 215pp 18704 038 24X Fiche 50-413, 83/06/01, 8306030300

8306030352 Advises that backup meteorological instrumentation will not be installed at facility, per NUREG-0737, Suppl 1 Software problems w/meteorological dispersion modeling unresolved
Interim sys described in B20401 ltr utilized
LEMPGEB, T E Niagara Mohawk Power Corp 83/05/27 VASSALLO, D B
Operating Reactors Branch 2 1p 18706 126 24X
Fiche 50-220, 83/05/27, 8306030352

8306030379 FOIA request for NUREG-0945, "Final EIS on 10CFR61
"Licensing Requirements for Land Disposal of Radwaste"
JOHNSON, B J Minnesota Project 83/03/22 Division of Rules and
Records 1p 18734 348

8306030382 Responds to FOIA request for NUREG-0945, "Final EIS on 10CFR61
"Licensing Requirements for Land Disposal of Radwaste"
"Forwards NUREG-0945, Vols 1-3 w/o encls
FELTON, J M Division of Rules and Records 83/04/01 JOHNSON, B J
Minnesota Project 1p 18734 349

8306030412 Forwards final schedule for satisfying requirements of
Generic Ltr 82-33, Suppl 1 to NUREG-0737 "Requirements for
Emergency Response Capability"
YOUNGBLOOD, B J Licensing Branch 1 GL-B2-33 83/05/18
WILLIAMS, J Cincinnati Gas & Electric Co 4pp 18747 141 24X
Fiche 50-358, 83/05/18, 8306030412

8306030441 Forwards "Control of Heavy Loads (C-10), Surry Power Station
Units 1 & 2," draft technical evaluation rept & summary of
addl info required to complete review Response requested
within 60 days
VARGA, S A Operating Reactors Branch 1 83/05/16 STEWART, H L
Virginia Electric & Power Co 2pp 18735 287 24X
Fiche 50-280, 83/05/16, 8306030441

--8306030446 TER-C5506-393/396 DR
"Control of Heavy Loads (C-10), Surry Power Station Units 1 &
2," draft technical evaluation rept
VOSBURY, F W Franklin Institute/Franklin Research Center
NRC-03-B1-130 TAC 08085 83/01/14 NRC - No Detailed
Affiliation Given 40pp 18735 289 24X Fiche 50-280, 83/05/16,
8306030441

8306030489 NUREG/CR-3027 ERR
OVERLAND EROSION OF URANIUM MILL TAILINGS IMPOUNDMENTS
PHYSICAL PROCESSES AND COMPUTATIONAL METHODS
* Battelle Memorial Institute, Pacific Northwest Laboratory
* Division of Technical Information & Document Control PNL-4523
83/05/04 Division of Health, Safety & Waste Management 1p
18735 268

8306030488 NUREG-0304 VOB NO1
REGULATORY AND TECHNICAL REPORTS Compilation For First
Quarter 1983
* Division of Technical Information & Document Control 83/05/31
44pp 18735 067

8306030503 Forwards safety evaluation supporting response to TMI Items
1 A 2.1.4 & 11 B 2 Requirements satisfied
DEA0AZ10, A Operating Reactors Branch 4 83/05/13 CROUSE, R P
Toldeo Edison Co 4pp 18747 167 24X Fiche 50-346, 83/05/13,
8306030503

--8209030323 BAI-186-029-28
"Improvements in Training & Requalification Programs As
Required By TMI Action Items 1 A 2.1 & 11 B 4 for
Davis-Besse Nuclear Power Station," technical evaluation
rept.
* Science Applications, Inc NRC-03-B2-096 82/08/31 NRC -
No Detailed Affiliation Given 15pp 18747 172 24X
Fiche 50-346, 83/05/13, 8306030503

8306030508 Forwards draft "Control of Heavy Loads (C-10), Zion Station
Units 1 & 2," per responses to NRC B00731 request for review
of provisions for handling & control of heavy loads in
conformance w/NUREG-0612 Addl guidance encl
VARGA, S A Operating Reactors Branch 1 83/05/19 FARRAR, D L
Commonwealth Edison Co 15pp 18735 006 24X Fiche 50-295,
83/05/19, 8306030508

--8306030512 TER-C5506-403/404 DR
Draft "Control of Heavy Loads (C-10), Zion Station Units 1 &
2," technical evaluation rept
SARGENT, I H VITO, D J Franklin Institute/Franklin Research
Center NRC-03-B1-130 TAC 08092 82/11/30 CLEMENSON, F NRC
No Detailed Affiliation Given 30pp 18735 021 24X
Fiche 50-295, 83/05/19, 8306030508

8306060036 Specifies provisions incorporated into procedures re NRC
positions for SEP Topic 111-3 C, "Inservice Insp of
Water-Control Structures" Topic detailed in final
integrated plant SAR, NUREG-0821
MAIER, J E Rochester Gas & Electric Corp 83/05/26 CRUTCHFIELD, D
Operating Reactors Branch 5 2pp 18723 298 24X
Fiche 50-244, 83/05/26, 8306060036

8306060051 Addl response to FOIA request for three categories of
documents re PRA of reactor safety study methodology
application program repts & interim reliability evaluation
program repts Forwards App A documents Search continuing
FELTON, J M Division of Rules and Records 83/04/07 SMOLL, S C
Union of Concerned Scientists 3pp 18752 001 24X
Fiche 50-000, 83/04/07, 8306060051

--8109210318 Responds to B10820 memo re transmittal of NUREG/CR-1659,
Vol 2, to licensee for comments Util comments on rept already
requested
BERNERD, R M Division of Risk Analysis 81/08/28 NOVAK, T M
Assistant Director for Operating Reactors 2pp 18752 018 24X
Fiche 50-000, 83/04/07, 8306060051

--8204120488 Discusses results of Sandia Natl Labs Study, "Reactor Safety,
Study Methodology Application Program Grand Gulf 1 BWR
Power Plant (NUREG/CR-1639, Vol 4)"
ERNST, M L Assistant Director for Technology Review 82/04/06
TEDESCO, R L Assistant Director for Licensing 2pp 18752 067
24X Fiche 50-000, 83/04/07, 8306060051

--8207280024 Discusses NUREG/CR-2787, "Interim Reliability Evaluation
Program Analysis of AR Nuclear One-Unit 1 Nuclear Power
Plant," first final rept on four integrated reliability
evaluation program Phase II studies
BERNERD, R M Division of Risk Analysis 82/06/24 HANAUER, S H
Division of Human Factors Safety 5pp 18752 074 24X
Fiche 50-000, 83/04/07, 8306060051

8306060092 Advises that requirements of NUREG-0737, Item 11 B 2 re plant
shielding for vital areas will be met when mods described in
encl safety evaluation implemented Review of corrective
actions completed
CLARK, R A Operating Reactors Branch 3 83/05/24 COUNSILL, W G
Northeast Nuclear Energy Co (subs of Northeast Utilities) 5pp
18751 253 24X Fiche 50-336, 83/05/24, 8306060092

8306060099 Forwards Rev 4 to "Transport of Toxic Chemicals & Control
Room Habitability Study," in response to NRC request & in
conjunction w/Suppl 3 to SER
WILLIAMS, J Cincinnati Gas & Electric Co 83/06/01 DENTON, H
Office of Nuclear Reactor Regulation, Director 1p 18731 301 24X
Fiche 50-358, 83/06/01, 8306060099

--8306060101 Rev 4 to "Transport of Toxic Chemicals & Control Room
Habitability Study" One oversize graph encl Aperture card
is available in PDR
BUGEN, P E Cincinnati Gas & Electric Co 83/05/18 116pp
18731 303 24X Fiche 50-358, 83/06/01, 8306060099

8306060121 Forwards evaluations submitted re NUREG-0612, "Control of
Heavy Loads at Nuclear Power Plants" Handling shielded
shipping casks over spent fuel pool will be prohibited until
measures taken to reduce probability of cask drop
BAYNE, J P Power Authority of the State of New York JPN-B3-49
83/06/02 VASSALLO, D B Operating Reactors Branch 2 14pp
18722 275 24X Fiche 50-333, 83/06/02, 8306060121

8306060200 Forwards IE Insp Rept 50-334/83-08 on 830405-0302 & notice
of violation
STAROSTECKI, R Division of Project & Resident Programs, 83/05/23
CAREY, J J Duquesne Light Co 2pp 18727 256 24X
Fiche 50-334, 83/05/23, 8306060200

NONDOCKETED ITEMS

427

--B306060714 IE Insp Rept 90-334/83-08 on B30405-0502 Noncompliance noted failure to demonstrate ECCS valve operability within specified surveillance interval
TROSKOSKI, W M, TRIPP, L E Region 1 Office of Director
IEB-87-01 83/05/17 22pp 18727 259 24X Fiche 50-334, 83/05/23, B306060200

B306060207 Notifies that Apr 1983 rept "Shaking-Table Testing for Seismic Evaluation of Electrical Raceway Sys." applicable to facilities for SEP Topic III-6 re seismic design NUREG-0824 & NUREG-0826 commitments partially satisfied
COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W G Connecticut Yankee Atomic Power Co
COUNCIL, W G Northeast Utilities 810798 83/05/26
CRUTCHFIELD, D Operating Reactors Branch 5 1p 18727 295 24X
Fiche 50-000, 83/05/26, B306060207

B306060236 Forwards qualification status & compliance summary on environ qualification of electrical equipment important to safety, per 10CFR50.49
DALE, L F Mississippi Power & Light Co IEB-79 01R 83/05/20
DENTON, H R Office of Nuclear Reactor Regulation, Director 62pp 18728 278 24X Fiche 50-416, 83/05/20, B306060236

B306060265 Forwards IE Insp Rept 50-322/83-14 on B30427-29 & 0506 No noncompliance noted
STAROSTICKI, R Division of Project & Resident Programs 83/05/25
POLLOCK, M S Long Island Lighting Co 2pp 18727 033 24X
Fiche 50-322, 83/05/25, B306060265

--B306060268 IE Insp Rept 50-322/83-14 on B30427-29 & 0506 No noncompliance noted Major areas inspected licensee actions taken to comply w/requirements in NUREG-0737, Item II B 2, "Design Review of Plant Shielding"
KELLY, E Region 1, Office of Director GALLO, R M Division of Project & Resident Programs 83/05/23 8pp 18727 035 24X
Fiche 50-322, 83/05/25, B306060265

B306060303 Notification of CRGR Meeting 41 on B30608 to review draft (NUREG-0801, "Evaluation Criteria for Detailed Control Room Design Reviews" & draft NUREG-0835, "Human Factors Review Guidelines for Safety Parameter Display Sys"
STELL, V Regional Operations & Generic Requirements 83/06/02
MATSON, R J Office of Nuclear Reactor Regulation, Director
JORDAN, F L Director's Office, Office of Inspection and Enforcement
CUNNINGHAM, R E Office of Nuclear Material Safety & Safeguards, Director 121pp 18729 202

B306060366 NUREG/CR-3228 V01
STRUCTURAL INTEGRITY OF WATER REACTOR PRESSURE BOUNDARY COMPONENTS Annual Report For 1982
* Materials Engineering Associates, Inc * ENSA, Inc FIN 0-8133
MEA-2012 83/04/30 Division of Engineering Technology 106pp
Available at NRC \$5 50 18747 187

B306060377 Advises that NUREG-0737, Items II F 1 4, "Containment Pressure Monitor, II F 1 5, "Containment Water Level Monitor" & II F 1 6, "Containment Hydrogen Monitor," resolved, per B21217 submittal Safety evaluation encl
CLARK, R A Operating Reactors Branch 3 83/05/24 WITHERS, B D
Portland General Electric Co 9pp 18730 338 24X
Fiche 50-344, 83/05/24, B306060377

B306060410 NUREG/CR-3089
SPECIMEN GEOMETRY AND EXTENDED CRACK GROWTH EFFECTS ON J1-R CURVE CHARACTERISTICS FOR HY-130 AND ASTM A533B STEELS
DAVIS, D A, VASSILAROS, M O, QUDAS, J P David W Taylor Naval Research & Development Center FIN 0-6290 83/05/31 Division of Engineering Technology 55pp Available at NRC \$4 75 18748 021

B306060412 NUREG-0853 802
SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF CLINTON POWER STATION, UNIT NO 1 Docket No 50-461 (Illinois Power Company, et al)
* Division of Licensing 83/05/31 72pp Available at NRC \$4 50 18747 321 24X Fiche 50-461, 83/05/31, B306060412

B306060413 NUREG-0927 FC
EVALUATION OF WATER HAMMER EXPERIENCE IN NUCLEAR POWER PLANTS Technical Findings Relevant To Unresolved Safety Issues A-1
SERKIZ, A W Division of Safety Technology 83/05/31 78pp 18748 076

B306060418 NUREG-0993 FC
VALUE-IMPACT ANALYSIS FOR USI A-1, "WATER HAMMER"
SERKIZ, A W Division of Safety Technology 83/05/31 29pp 18747 293

B306060419 NUREG-0940 V03 N02
TITLE LIST OF DOCUMENTS MADE PUBLICLY AVAILABLE February 1983
* Division of Technical Information & Document Control 83/05/31 575pp 18749 001

B306070013 Responds to request for environ qualification status of reactor bldg flood level alarms, per SER Open Item 41 re scram discharge vol (NUREG-0803) Testing program completed Documentation available for onsite review in approx 2 wks
SMITH, J L Long Island Lighting Co SNRC-900 83/06/03
DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 18736 359 24X Fiche 50-322, 83/06/03, B306070013

B306070015 Forwards IE Insp Rept 50-344/83-11 on B30328-0429 No noncompliance noted
STERNBERG, D M Region 3, Office of Director 83/05/23
WITHERS, B D Portland General Electric Co 2pp 18737 339 24X
Fiche 50-344, 83/05/23, B306070015

--B306070017 IE Insp Rept 50-344/83-11 on B30328-0429 No noncompliance noted Major areas inspected plant operations, surveillance testing, security, maint, refueling & followup on corrective action to NUREG-0737 items
MALMROS, M H, DODDS, R T Region 3, Office of Director 83/05/19 6pp 18737 341 24X Fiche 50-344, 83/05/23, B306070015

B306070016 NUREG-0748 V03 N04
OPERATING REACTORS LICENSING ACTIONS SUMMARY Data As Of April 30, 1983 (Orange Book)
* Management Information Branch 83/05/31 319pp 18783 189

B306070045 Clarifies misconception in B30513 safety evaluation submitted in response to NUREG-0737, Item II F 1-3 re containment high-range radiation monitors High-range drywell radiation monitors & procedures in place when response sent
HARRINGTON, W D Boston Edison Co 83-141 83/06/01 VASSILAROS, D B, Operating Reactors Branch 2 1p 18739 343 24X
Fiche 50-293, 83/06/01, B306070045

B306070047 Discusses reactor coolant pump seal ability to perform adequately after extended loss of component cooling water, per NUREG-0737, Item II K 3 25 "Effect of Loss of Alternating Current Power on Pump Seals" Item resolution requested.
OLSON, R C Baltimore Gas & Electric Co 83/05/25 CLARK, R A Operating Reactors Branch 3 2pp 18740 003 24X
Fiche 50-317, 83/05/25, B306070047

B306070062 Forwards safety evaluation of proposed resolution of integrated plant SAR Section 4 27 re svc & cooling water sys Mods acceptable
WAMBACH, T V Operating Reactors Branch 5 L805-83-05-070, 83/05/31 VANDEWALLE, D J Consumers Power Co 2pp 18740 100, 24X Fiche 50-255, 83/05/31, B306070062

--B306070063 Safety evaluation on integrated plant SAR Section 4 27 re svc & cooling water sys
* Operating Reactors Branch 5 83/05/31 3pp 18740 102 24X
Fiche 50-255, 83/05/31, B306070062

B306070079 Forwards schedule for completion of full-term license SEP commitments contained in NUREG-0827 Three items resolved after issuance of draft NUREG-0827 listed
LINDER, F Dairyland Power Cooperative L-9124 83/06/02
CRUTCHFIELD, D Operating Reactors Branch 5 10pp 18738 206 24X
Fiche 50-409, 83/06/02, B306070079

B306070086 Provides results of chlorine, boron & pH analyses performed for chemical test matrix, per NUREG-0737, Item II B 3, Criterion 10, to demonstrate analytical capabilities in presence of interfering ion concentrations
FAY, C W Wisconsin Electric Power Co 83/06/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18737 350 24X Fiche 50-266, 83/06/03, B306070086

B306070125 Submits revs to B30525 augmented RCS leak detection submittal & inservice insp program commitment incorporating surveillance frequencies per NUREG-0313, Rev 1 Insp &/or mod plans for recirculation & RHR sys piping forthcoming
QUCHAL, T Georgia Power Co NED-83-332 83/06/02 STOLZ, J F Operating Reactors Branch 4 2pp 18739 266 24X
Fiche 50-366, 83/06/02, B306070125

B306070133 Responds to B21013 ltr finding util position on NUREG-0737, Item II K 3 25 re power on pump seals acceptable Addl info re component cooling water pumps B & C clarified. Both pumps automatically tripped by containment spray sys
ZIMMERMAN, S R Carolina Power & Light Co 83/05/31 VARGA, B A Operating Reactors Branch 1 2pp 18736 241 24X
Fiche 50-261, 83/05/31, B306070133

NONDOCKETED ITEMS

8306070177 Requests 30-day extension for response to 830505 notice of violation & proposed imposition of civil penalties Delay due to complexity of issues & consideration of available options
UDERITZ, R A Public Service Electric & Gas Co of New Jersey
83/06/01 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 2pp 18736 329 24X Fiche 50-272, 83/06/01, 8306070177

8306070189 Forwards application to amend License DPR-64 to conform requirements of OL-82-16 concerning NUREG-0737 Tech Specs
BAYNE, J P Power Authority of the State of New York IPN-83-49
83/06/01 EISENHUT, D G Division of Licensing 2pp 18736 304
24X Fiche 50-286, 83/06/01, 8306070189

--8306070197 Application to amend License DPR-64 changing Tech Specs in accordance w/requirements of Generic Ltr 82-16 re NUREG-0737 items
BAYNE, J P Power Authority of the State of New York OL-82-16
83/06/01 12pp 18736 306 24X Fiche 50-286, 83/06/01, 8306070189

8306070193 Responds to 830322 ltr re open issues of NUREG-0737, Item II E 1 i, "Auxiliary Feedwater Sys Evaluation," Review of Recommendations OL-2 re environ qualification & OL-4 re flow test to be completed by 830731
MARSHALL, J R Arkansas Power & Light Co ICAN058307 83/05/31
STOLZ, J F Operating Reactors Branch 4 2pp 18736 296 24X
Fiche 50-313, 83/05/31, 8306070193

8306070208 Responds to 830208 Generic Ltr 83-10D on plans & schedule for resolving NUREG-0737, Item II K 3 5 re trip criteria for reactor coolant pumps Util will follow guidance provided by Westinghouse & Westinghouse Owners Group
ALEXICH, M P Indiana & Michigan Electric Co OL-83-10D 83/06/02
EISENHUT, D G Division of Licensing 11pp 18747 054 24X
Fiche 50-315, 83/06/02, 8306070208

8306070239 Forwards revised draft response to Question 410 17 re CP application compliance w/NUREG-0800 per 830330 meeting w/NRC Changes will be incorporated in FSAR rev scheduled for June 1983
BRADLEY, E J Philadelphia Electric Co 83/06/03 SCHWENCER, A
Licensing Branch 2 3pp 18747 048 24X Fiche 50-352, 83/06/03, 8306070239

8306070300 Forwards proposed schedule for completing requirements of NUREG-0737, Suppl 1, "Emergency Response Capability," per 830510 meeting Commitments from 830415 ltr remain unchanged
WILGUS, W S Florida Power Corp 3F-0383-24 83/05/31 STOLZ, J F
Operating Reactors Branch 4 8pp 18740 305 24X
Fiche 50-302, 83/05/31, 8306070300

8306070303 Advises that individual program plan will be submitted by 831019 referencing BWR Owners Group generic program plan re NRC 830419 Generic Ltr 83-18, Suppl 1 to NUREG-0737, Item I D 1, "Control Room Design Review"
BAYNE, J P Power Authority of the State of New York OL-83-18
83/06/03 VASSALLO, D B Operating Reactors Branch 2 2pp 18740 301 24X Fiche 50-333, 83/06/03, 8306070303

8306070343 Responds to Generic Ltr 82-16 re NUREG-0737 Tech Specs for listed TMI items Some Tech Specs incorporated, some not applicable & some unnecessary.
O'TOOLE, J D Consolidated Edison Co of New York, Inc OL-82-16
83/05/31 EISENHUT, D G, Division of Licensing 6pp 18742 031
24X Fiche 50-247, 83/05/31, 8306070343

8306070363 Responds to 830202 request for addl info re NUREG-0737, Item II K 3 2B, "Verify Qualification of Accumulators on Automatic Depressurization Sys Valves" W/one oversize drawing. Aperture card is available in PDR.
DALTROFF, B L Philadelphia Electric Co 83/06/02 STOLZ, J F
Operating Reactors Branch 4 11pp 18743 075 24X
Fiche 50-277, 83/06/02, 8306070363

8306070437 NUREG-0800 FC
PROPOSED REVISIONS TO STANDARD REVIEW PLAN, PSRP 3 4 & Rev 3, PSRP 5 4 7, Rev 3/PSRP 6 3, Rev 2/PSRP 7 2 1, Rev 3/PSRP 9 2 2, Rev 2/PSRP 10 3, Rev 3 & PSRP 10 4 7, Rev 3
* Office of Nuclear Reactor Regulation, Director 83/06/06 87pp
18783 102

8306070444 Forwards Suppl 2 to SER (NUREG-0853), W/o encl
SCHWENCER, A Licensing Branch 2 83/05/31 WULLER, G Illinois
Power Co 1p, 18780 351 24X Fiche 50-461, 83/05/31, 8306070444

--8306070446 Forwards, Suppl 2 to May 1983 SER (NUREG-0853), W/o encl
* Office of Nuclear Reactor Regulation, Director 83/05/26
OTTINGER, R House of Rep, Energy & Commerce 1p 18780 352
24X Fiche 50-461, 83/05/31, 8306070444

--8306070447 Forwards Suppl 2 to May 1983 SER (NUREG-0853) W/o encl
* Office of Nuclear Reactor Regulation, Director 83/05/26
STIMPSON, A Senate, Environment & Public Works 1p 18780 353
24X Fiche 50-461, 83/05/31, 8306070444

--8306070451 Forwards Suppl 2 to May 1983 SER (NUREG-0853) W/o encl
* Office of Nuclear Reactor Regulation, Director 83/05/26
UDALL, M House of Rep, Interior & Insular Affairs 1p
18780 354 24X Fiche 50-461, 83/05/31, 8306070444

8306070452 NUREG/CR-3290
FEASIBILITY STUDY ON THE DEVELOPMENT OF A NON-INVASIVE LIQUID LEVEL GAUGE FOR NUCLEAR POWER REACTORS
BARATTA, A J, JESTER, W A, IMEL, G R Pennsylvania State Univ FIN
Q-1029 83/05/31 Division of Accident Evaluation 84pp
Available at NRC #4 50 18782 020

8306070471 NUREG/CR-3248
STUDIES OF FISSION PRODUCT SCRUBBING WITHIN ICE COMPARTMENTS
WINEGARDNER, W Battelle Memorial Institute, Pacific Northwest
Laboratory POSTMA, A K Benton City Technology JANKOWSKI, H W
Office of Nuclear Regulatory Research, Director FIN D-2444
PNL-4691 83/05/31 Division of Engineering Technology 57pp
Available at NRC #4 25 18782 103

8306070473 NUREG/CR-3291
AN ANALYSIS OF BOILING WATER NUCLEAR REACTOR STABILITY
MARGIN
BALARAM, J, SHEN, C N, LAHEY, R T Rensselaer Polytechnic Inst FIN
8-7230 83/05/31 Division of Accident Evaluation 235pp
Available at NRC #7 50 18753 182

8306080125 Forwards SER open item response to Chemical Engineering Branch request for addl info re NUREG-0737, Item II B 3, "Post-Accident Sampling Capability" Info suppls 821201 response & DL application Amend 48
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
Service Co of New Hampshire BBN-514 83/05/31 KNIIGHTON, G W
Licensing Branch 3 21pp 18772 333 24X Fiche 50-443, 83/05/31, 8306080125

8306080137 Forwards "WH Zimmer Nuclear Power Station, Unit 1, Heavy Loads Rept," in response to supplemental SER (NUREG-0528, Suppl 3) & NUREG-0612 re control of heavy loads
WILLIAMS, J Cincinnati Gas & Electric Co 83/06/02 DENTON, H
Office of Nuclear Reactor Regulation, Director 87pp 18760 275
24X Fiche 50-358, 83/06/02, 8306080137

--8306080140 "WH Zimmer Nuclear Power Station, Unit 1, Heavy Loads Rept"
* Cincinnati Gas & Electric Co 83/06/01 108pp 18760 277
24X Fiche 50-358, 83/06/02, 8306080137

8306080146 NUREG-0904
FINAL ENVIRONMENTAL STATEMENT RELATED TO THE DECOMMISSIONING OF THE RARE EARTHS FACILITY, WEST CHICAGO, ILLINOIS Docket No 40-2061
* Division of Fuel Cycle & Material Safety 83/05/31 522pp
Available at NRC #10 00 18788 001

8306080158 NUREG-0880 R01 FC
SAFETY GOALS FOR NUCLEAR POWER PLANT OPERATION
* Office of Policy Evaluations 83/05/31 116pp 18789 163

8306080168 NUREG/CR-3174 V01
GEOPHYSICAL-GEOLOGICAL STUDIES OF POSSIBLE EXTENSIONS OF THE NEW MADRID FAULT ZONE Annual Report for 1982
HINZE, W J, BRAILE, L W, KELLER, G R Purdue Univ FIN D-8077
83/05/31 Division of Health, Siting & Waste Management 101pp
Available at NRC #4 75 18790 001

8306080198 Informs that requirements of TMI Item II B 2 2, "Design Review of Plant Shielding & Environ Qualification of Equipment for Spaces/Sys Which May Be Used in Post-Accident Operations," met
CRUTCHFIELD, D Operating Reactors Branch 5 L605-83-06-011
83/06/07 COUNSIL, W G Northeast Nuclear Energy Co (subs of
Northeast Utilities) 6pp 18772 233 24X Fiche 50-245, 83/06/07, 8306080198

8306080213 Informs that station blackout procedure approved & available for NRC review, per NUREG-0528, Suppl 3, Subsection 8 1 2
WILLIAMS, J Cincinnati Gas & Electric Co 83/06/01 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 18771 182 24X
Fiche 50-358, 83/06/01, 8306080213

8306080251 Forwards "Control of Heavy Loads (C-10) St Lucie Unit 1," draft technical rept, per util response to Section 2 1 of 801222 generic ltr re NUREG-0612 Completion of review by 830617 requested
CLARK, R A Operating Reactors Branch 2 83/05/24 UHRIG, R E
Florida Power & Light Co 2pp 18787 139 24X
Fiche 50-335, 83/05/24, 8306080251

NONDOCKETED ITEMS

429

--8306080252 TCR-C5506-394 DRFT
"Control of Heavy Loads (C-10) St Lucie Unit 1," draft
technical evaluation rept
BOMBERGER, C., AHMED, N Franklin Institute/Franklin Research
Center NRC-03-B1-130 TAC 08083 83/04/29 CLEMENSON, F NRC -
No Detailed Affiliation Given 3pp 18787 141 24X
Fiche 50-325, 83/05/24, 8306080251

8306080268 Responds to FOIA request for SCCY-83-22 Forwards publicly
available portions of paper per telcon w/N Toms
FELTON, J M Division of Rules and Records 83/04/11 KNIGHT, N L
General Physics Corp 1p 18787 240

--8306080270 "Statement of policy Further Commission Guidance on
Emergency Response Capability," draft 10CFR50 effective
rule Suppl issued to NUREG-0737, "Clarification of TMI
Action Plan Requirements"
CHILK, S J Office of the Secretary of the Commission 83/04/11
3pp 18787 241

8306080375 Forwards review of "Reactor Safety Study Methodology
Applications Program Ocone 3 PWR Power Plant
(NUREG/CR-1659, 2 of 4) " Review identified dominant core
melt sequences & required licensing actions
STOLZ, J F Operating Reactors Branch 4 83/06/01 TUCKER, H B
Duke Power Co 14pp 18787 279 24X Fiche 50-287, 83/06/01,
8306080375

8306080437 Summary of 830526 meeting w/util in Bethesda, MD re present
containment purge sys design, Outstanding Issue 10 in SER
(NUREG-0887)
STEFANO, J J Licensing Branch 1 83/06/03 YOUNGBLOOD, B J
Licensing Branch 1 12pp 18792 197 24X Fiche 50-440, 83/06/03,
8306080437

8306090067 Forwards IE Insp Rept 50-322/83-10 on 830401-0509 & notice
of violation
STAROSTECKI, R Division of Project & Resident Programs 83/05/27
FOLLOCK, M S Long Island Lighting Co 2pp 18793 290 24X
Fiche 50-322, 83/05/27, 8306090067

--8306090076 IE Insp Rept 50-322/83-10 on 830401-0509 Noncompliance
noted failure to assure that changes to emergency diesel
generator test procedures distributed & used
HIGGINS, J C., MCCLANE, E C., KUNKLE, G L Region 1, Office of
Director 18B-00-15 83/05/25 14pp 18793 293 24X
Fiche 50-322, 83/05/27, 8306090067

8306090118 Advises of approval of emergency response plan for facility,
subj to verification of adequacy of public alerting &
notification sys
MCLOUGHLIN, D Federal Emergency Management Agency 83/05/16
DICKS, W J Office of the Executive Director for Operations 1p
18793 329 24X Fiche 50-155, 83/05/16, 8306090118

8306090170 Forwards review of CESSAR-F against requirements of CP/ML
rule 10CFR50.34(f) & selective sections of App B & Chapter
3 of CESSAR-F Only fraction of rule requirements within
scope of CESSAR-F CESSAR-F complies w/rule
SCHERER, A C Combustion Engineering, Inc LD-83-049 83/05/25
EISENHUT, D G Division of Licensing 103pp 18794 010 24X
Fiche 50-470, 83/05/25, 8306090170

8306090194 Discusses util interpretation of 10CFR50.49, "Environ
Qualification of Electrical Equipment Important to Safety
for Nuclear Power Plants " Intent of rulemaking is to
require upgrade program for replacement equipment not parts
FARRAR, D L Commonwealth Edison Co 6702N 83/06/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 18796 090
24X Fiche 50-000, 83/06/03, 8306090194

8306090229 Approves State of MI emergency response plan & associated
local plans w/condition that adequacy of public alerting &
notification sys be verified per FEMA/NRC joint criteria
listed in NUREG-0654/FEMA-REP-1, Rev 1, App 3
PAPERELLO, C J Region 3, Office of Director 83/06/06
DEWITT, R B Consumers Power Co 2pp 18796 235 24X
Fiche 50-155, 83/06/06, 8306090229

8306090232 Advises that NUREG-0824, Section 4 i & concerns resolved,
based on util 830113 response, per SEP Topic II-3 B 1,
"Capability of Operating Plant to Cope W/Design Basis
Flooding Conditions " Procedure OP 514A revised by 830729
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast
Utilities) COUNSIL, W G Northeast Utilities 810799 83/06/03
CRUTCHFIELD, D Operating Reactors Branch 3 2pp 18795 344 24X
Fiche 50-245, 83/06/03, 8306090232

8306090233 Provides info for resolution of NUREG-0737, Item II E 1 i
open items re review of upgraded auxiliary feedwater sys
RODRIGUEZ, R J Sacramento Municipal Utility District 83/06/03
STOLZ, J F Operating Reactors Branch 4 2pp 18795 342 24X
Fiche 50-312, 83/06/03, 8306090233

8306090237 Forwards "Emergency Operating Procedures Generation
Package," in response to Generic Ltr 82-33, Suppl 1 to
NUREG-0737
MUSOLF, D Northern States Power Co GL-82-33 83/05/31 Office
of Nuclear Reactor Regulation, Director 1p 18797 001 24X
Fiche 50-282, 83/05/31, 8306090237

--8306090237 "Emergency Operating Procedures Generation Package "
Northern States Power Co GL-82-33 83/05/31 16pp
18797 002 24X Fiche 50-282, 83/05/31, 8306090237

8306090267 Forwards safety evaluation of BWR Owners Group response to
NUREG-0737, Item II K 3 1B, "Mod of Automatic
Depressurization Sys Logic " Acceptable options include
elimination of high drywell pressure permissive
CRUTCHFIELD, D Operating Reactors Branch 3 LSO3-83-06-016
83/06/08 COUNSIL, W G Northeast Nuclear Energy Co (subs of
Northeast Utilities) 2pp 18795 280 24X Fiche 50-245, 83/06/08,
8306090267

--8306090272 Safety evaluation of BWR Owners Group response to
NUREG-0737, Item II K 3 1B, "Mod of Automatic
Depressurization Sys Logic " Acceptable options include
elimination of high drywell pressure permissive
Office of Nuclear Reactor Regulation, Director 83/06/08 5pp
18795 282 24X Fiche 50-245, 83/06/08, 8306090267

8306090361 Forwards request for exemption from emergency operations
facility (EDF) location requirements per Generic Ltr 82-33,
Proposed EDF to be located 125 air miles from facility, w/
joint news ctr remaining in Oconee, NC
TUCKER, H B Duke Power Co GL-82-33 83/06/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director 28pp 18795 039
24X Fiche 50-269, 83/06/03, 8306090361

8306090369 Forwards comments on CRGR review package re NUREG-0666,
"Probabilistic Safety Analysis of DC Power Supply
Requirements for Nuclear Power Plants " Assistance of lead
project manager offered
EISENHUT, D G Division of Licensing 83/06/02 MATTSON, R J
Division of Systems Integration (post 811003) 2pp 18814 016

8306090386 Forwards request for addl info re response to encl "Control
of Heavy Loads at Nuclear Power Plants, Phase I, Nebraska
Public Power District, Cooper Nuclear Station " Draft
technical evaluation rept encl info requested in 60 days
VASSALL, D B Operating Reactors Branch 2 83/05/26 PILANT, J M
Nebraska Public Power District 13pp 18814 042 24X
Fiche 50-298, 83/05/26, 8306090386

--8306090388 TER-C5506-246 DRFT
"Control of Heavy Loads (C-10), Nebraska Public Power
District, Cooper Nuclear Station," draft technical evaluation
rept
VOSSBURY, F., VITO, D., SARGENT, I H Franklin Institute/Franklin
Research Center NRC-03-B1-130 TAC 07982 82/12/30
CLEMSON, F NRC - No Detailed Affiliation Given 27pp
18814 055 24X Fiche 50-298, 83/05/26, 8306090386

8306090393 Forwards request for addl info re three open items
concerning controls for handling heavy loads Franklin
Research Ctr draft technical evaluation encl Response
requested within 60 days of receipt of ltr
STOLZ, J F Operating Reactors Branch 4 83/05/31 RODRIGUEZ, R J
Sacramento Municipal Utility District 13pp 18815 037 24X
Fiche 50-312, 83/05/31, 8306090393

--8306090397 TER-C5257-388 DRFT
"Control of Heavy Loads, Sacramento Municipal Util District,
Rancho Seco Nuclear Generating Station," draft technical
evaluation rept
VOSSBURY, F W., VITO, D J., SARGENT, I H Franklin Institute/Franklin
Research Center NRC-03-B1-130 TAC 08079 83/01/13
CLEMSON, F NRC - No Detailed Affiliation Given 28pp
18815 050 24X Fiche 50-312, 83/05/31, 8306090393

8306090426 Forwards safety evaluation & technical evaluation rept,
"Control of Heavy Loads " Guidelines of NUREG-0612
satisfies
CLARK, R A Operating Reactors Branch 3 83/05/27 LUNDVALL, A E
Baltimore Gas & Electric Co 2pp 18809 107 24X
Fiche 50-317, 83/05/27, 8306090426

--8306090492 Safety evaluation accepting util response to "Control of
Heavy Loads Phase I " Item resolved
NRC - No Detailed Affiliation Given, 83/05/27 2pp
18809 107 24X Fiche 50-317, 83/05/27, 8306090426

8306100018 Requests route approval for irradiated fuel shipments from
West Valley, NY to Two Rivers, WI
DANESE, F L Nuclear Assurance Corp 22352 83/05/26 HILLMAN, C
Division of Safeguards 3pp 18815 306 24X Fiche 50-246, 83/05/26,
8306100018

NONDOCKETED ITEMS

8306100055 Describes integrated assessment of open issues & schedule for issue resolution & documents util response to environ equipment qualification & Generic Ltr 82-33 re NUREG-0737
TOMER, K A Consumers Power Co GL-82-33 83/06/01 CRUTCHFIELD, D
Operating Reactors Branch 5 113pp 18804 048 24X
Fiche 50-155, 83/06/01, 8306100055

8306100059 "Control Room Design Review Plan, Prairie Island Nuclear Generating Plant," response to Generic Ltr 82-33, Suppl 1 to NUREG-0737 W/830527 ltr
MUSOLF, D Northern States Power Co GL-82-33 83/05/27 47pp
18802 123 24X Fiche 50-282, 83/05/27, 8306100059

8306100097 Forwards schedule implementation plan for emergency response capability & list of submittals required by NUREG-0737, Suppl 1, per Generic Ltr 82-33 Procedures generation package will be submitted by 840501
MULLER, G E Illinois Power Co GL-82-33 83/06/06 SCHWENGER, A
Licensing Branch 2 5pp 18804 043 24X Fiche 50-461, 83/06/06, 8306100097

8306100113 Forwards addl info re time frame for providing access to hydrogen recombiner panel area per 830215 commitment to NUREG-0737, Item II B 2, "Plant Shielding " Hydrogen recombiner panel access time of 5 days appropriate
BAYNE, J P Power Authority of the State of New York IPN-83-52
83/06/03 EISENHUT, D O Division of Licensing 5pp 18802 018
24X Fiche 50-286, 83/06/03, 8306100113

8306100114 Forwards listing of scheduled completion dates for SEP integrated assessment open issues requiring addl action by util Each issue resolution documented in draft NUREG-0826 Topic VI-7 C 1 resolution outlined
COUNSEL, W O Connecticut Yankee Atomic Power Co 810806 83/06/02
CRUTCHFIELD, D Operating Reactors Branch 5 19pp 18802 186 24X
Fiche 50-213, 83/06/02, 8306100114

8306100132 Forwards Rev 0 to "Design Rept For Weld Overlay Repairs & Flaw Evaluations in Recirculation & RHR Sys " Sensor check will be performed every 4 hours in addition to interval required by Tech Specs, effective at restart
GUCHA, L T Georgia Power Co NED-83-341 83/06/08 STOLZ, J F
Operating Reactors Branch 4 2pp 18801 262 24X
Fiche 50-366, 83/06/08, 8306100132

8306100147 Forwards revised draft versions of: "Cultural Resources Mgt Plan for Residual Lands" & "Phase 1 Cultural Resources Survey & Assessment to Residual Lands" & responses to SHPD comments
SCHNELL, D F Union Electric Co ULNRC-634 83/06/03 BENTON, H R
Office of Nuclear Reactor Regulation, Director 44pp 18807 237
24X Fiche 50-483, 83/06/03, 8306100147

8306100184 Forwards comments on draft NUREG-0827, "Integrated Plant Safety Assessment, SEP," to help improve rept accuracy
LINDER, F Dairyland Power Cooperative LAC-9126 83/06/02
CRUTCHFIELD, D Operating Reactors Branch 5, 5pp 18806 024 24X
Fiche 50-407, 83/06/02, 8306100184

8306100189 Restates previous commitment to install redundant radiation monitor in control room HVAC sys, per NUREG-0737, Item III D 3 4, "Control Room Habitability," in response to 830401 request
QIESLER, C W Wisconsin Public Service Corp NRC-83-116 83/06/06
VARGA, S A Operating Reactors Branch 1 5pp 18805 257 24X
Fiche 50-305, 83/06/06, 8306100189

8306130176 Forwards final response to NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants "
SCHMIDT, H C Texas Utilities Services, Inc TXX-3659 83/06/08
YOUNGBLOOD, B J Licensing Branch 1 153pp 18828 031 24X
Fiche 50-445, 83/06/08, 8306130176

8306130260 Comments on NUREG/CR-2337, Vols 1 & 4, "Aquatic Impacts From Operation of Three Midwestern Nuclear Power Stations " Author evaluation & conclusions differ from util understanding gained in studies Supporting info encl
JONES, W C Omaha Public Power District LIC-83-130 83/06/06
VOLLMER, R H Division of Engineering 40pp 18824 194 24X
Fiche 50-285, 83/06/06, 8306130260

8306130334 Forwards "Suppl 1 to NUREG-0737, Milestone Activity - Submittal of Updated Detailed Control Room Design Review Program Plan "
TOMER, K A Consumers Power Co 83/06/07 CRUTCHFIELD, D Operating
Reactors Branch 5, 1p 18822 197, 24X Fiche 50-255, 83/06/07, 8306130334

--8306130335 "Suppl 1 to NUREG-0737, Milestone Activities - Submittal of Updated Detailed Control Room Design Review Program Plan "
* Consumers Power Co 83/06/07 12pp 18822 198 24X
Fiche 50-255, 83/06/07, 8306130335

8306130336 Forwards safety evaluation supporting util decision not to reroute reactor water cleanup sys return line per NUREG-0619 Decision based on value-impact analysis & sleeve leakage measurements
SHEA, J J Operating Reactors Branch 5 LS05-83-06-024 83/06/07
COUNSEL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 18822 153 24X Fiche 50-245, 83/06/07, 8306130336

--8306130338 Safety evaluation supporting util decision not to reroute reactor water cleanup sys return line per NUREG-0619 Decision based on value-impact analysis & sleeve leakage measurements
* Office of Nuclear Reactor Regulation, Director TAC 08412
83/06/07 2pp 18822 153 24X Fiche 50-245, 83/06/07, 8306130338

8306130342 Forwards revised response to NUREG-0737, Item II F 1, committing to install GA Co Model RD-23 high-range gas monitors by fuel load
MILLER, L M Tennessee Valley Authority 83/06/07 ADENHAM, E
Licensing Branch 4 4pp 18822 157 24X Fiche 50-370, 83/06/07, 8306130342

8306130385 Advises of cancellation of CRGR Meeting 41 to permit NRC to reevaluate NUREG-0801, "Evaluation Criteria for Detailed Control Room Design " & NUREG-0835, "Human Factors Review Guidelines for Safety Parameter Display Sys "
STELLER, V Regional Operations & Generic Requirements 83/06/08
MATSON, R J Office of Nuclear Reactor Regulation, Director
JORDAN, E L Director's Office, Office of Inspection and Enforcement
CUNNINGHAM, R E Office of Nuclear Material Safety & Safeguards, Director 1p 18822 215

8306130415 Requests exemption from 10CFR50 48(c) schedule requirements per 10CFR50 12, for completion of fire protection mods at fuel & auxiliary bldg 45-ft elevations Deferral requested due to const manpower commitment
WITHERS, B D Portland General Electric Co 83/06/07 CLARK, R A
Operating Reactors Branch 3 2pp 18823 136 24X
Fiche 50-344, 83/06/07, 8306130415

8306130429 Application for amend to Licenses NPF-2 & NPF-D, changing Tech Specs re operating personnel, per NUREG-0737, Item I A 1 3 & Generic Ltrs 82-02 & 82-12, to incorporate current practices
CLAYTON, F L Alabama Power Co GL-82-02 83/06/06 VARGA, S A
Office of Nuclear Reactor Regulation, Director 3pp 18821 223
24X Fiche 50-348, 83/06/06, 8306130429

8306130431 Forwards SER re compliance w/NUREG-0737, Item III A 1 J, "Min Staffing Levels for Emergency Situations " Provisions for onshift staffing & augmentation acceptable
HIND, J A Division of Radiological & Materials Safety Programs
83/06/10 BURSTEIN, S Wisconsin Electric Power Co 8pp
18821 215 24X Fiche 50-266, 83/06/10, 8306130431

8306130432 Responds to 830328 request for addl info re adequacy of electric distribution sys voltages per SER (NUREG-0857) Response re adequacy of util info requested within 2 wks
VAN BRUNT, E E Arizona Public Service Co ANPP-23991-ACR/
83/06/07 KNIIGHTON, O Licensing Branch 3 6pp 18821 195 24X
Fiche 50-528, 83/06/07, 8306130432

8306130493 Forwards synopsis of resolutions to open items re control of heavy loads at nuclear power plants, per NUREG-0612 guidelines Draft final technical evaluation rept & request for addl info encl
VASSALLO, D J Operating Reactors Branch 2 83/05/26 SINCLAIR, J B
Vermont Yankee Nuclear Power Corp 13pp 18830 107 24X
Fiche 50-271, 83/05/26, 8306130493

8306140208 Application for amend to Licenses NPF-4 & NPF-7, adding addl accident monitoring instrumentation & instrumentation for detection of inadequate core cooling per requirements of NUREG-0737, Items II F 1 & II F 2
STEWART, W L Virginia Electric & Power Co 333 83/06/03
BENTON, H R Office of Nuclear Reactor Regulation, Director
CLARK, R A Operating Reactors Branch 3 4pp 18841 169 24X
Fiche 50-338, 83/06/03, 8306140208

--8306140222 Proposed changes to Tech Specs adding addl accident monitoring instrumentation & instrumentation for detection of inadequate core cooling per requirements of NUREG-0737, Items II F 1 & II F 2
* Virginia Electric & Power Co 83/06/03 22pp 18841 169 24X
Fiche 50-338, 83/06/03, 8306140222

8306140277 Informs that analysis of inlet & discharge piping for relief & safety valves refined to reflect more realistic conditions, per 830215 ltr & TMI Action Item II D 1 Listed options will be considered if overstress condition revealed
BAYNE, J P Power Authority of the State of New York IPN-83-55
83/06/08 VARGA, S A Operating Reactors Branch 1 2pp 18834 223
24X Fiche 50-286, 83/06/08, 8306140277

8306140315 NUREG/CR-2766
DESIGN BASIS FOR THE NRC OPERATIONS CENTER
DESROSIERS, A E, MEITZLER, W D Battelle Memorial Institute, Pacific
Northwest Laboratory LINDELL, M K Battelle Human Affairs Research
Centers FIN D-2182 83/05/31 Division of Emergency
Preparedness & Engineering Response (Post 830103) 108pp Available
at NRC #4 75 18852 166

8306140318 Informs that addl info requested on 830511 re NUREG-0737,
Item II K 3 2B, "Qualification of Automatic Depressurization
Sys Accumulators," will be provided by 830930
BAYNE, J P Power Authority of the State of New York JPN-83-53
83/06/09 VASSALLO, D B Operating Reactors Branch 2 3pp
18832 207 24X Fiche 50-333, 83/06/09, 8306140318

8306140324 NUREG-0090 V03 N04
REPORT TO CONGRESS ON ABNORMAL OCCURRENCES October -
December 1982
* Director's Office 83/05/31 36pp 18854 080

8306140402 NUREG/CR-3087
INCINERATION OF A TYPICAL LWR COMBUSTIBLE WASTE AND ANALYSIS
OF THE RESULTING ASH
TREAT, R L, LOKKEN, R O, SCHLIEBE, M J Battelle Memorial Institute,
Pacific Northwest Laboratory FIN D-2401 PNL-4563 83/05/31
Division of Health, Siting & Waste Management 70pp Available at
NRC #4 50 18845 248

8306140407 NUREG/CR-3219 V02
DRAFT TECHNICAL POSITION Subtask 1 2 Post Emplacement
Monitoring
FANNING, S V Brookhaven National Laboratory FIN A-3168
BRL-NUREG-51658 83/05/31 Division of Waste Management 121pp
Available at NRC #5 00 18845 061

8306140408 Forwards evaluation of BWR Owners Group generic response to
NUREG-0737, Item II K 3 1B, "Mod of Automatic
Depressurization Sys Logic-Feasibility for Increased
Diversity for Some Event Sequences " Two options listed
CRUTCHFIELD, D Operating Reactors Branch 5 83/06/03 FARRAR, D L
Commonwealth Edison Co 2pp 18837 354 24X Fiche 50-237, 83/06/03,
8306140408

8306140414 Informs that interim plan to reduce blocked position from
50 to 140 degrees acceptable pending review of 830715 rept
re cut of plane upstream elbow SRP 6 2 4 & Positions 6 & 7
of THI Action Item II E 4 2 closed
CLARK, R A Operating Reactors Branch 3 83/05/27 UHRIG, R E
Florida Power & Light Co 6pp 18854 072 24X
Fiche 50-335, 83/05/27, 8306140414

8306140480 Forwards revised schedule for post-accident instrumentation
transmitted by 830520 ltr re environ qualification of
electrical equipment (10CFR50.49) Data of referenced ltr
corrected Original encl should be replaced
MUKILL, H D General Public Utilities - GPU Service Corp
5211-83-173 83/06/08 DENTON, H A Office of Nuclear Reactor
Regulation, Director 2pp 18843 279 24X Fiche 50-269, 83/06/08,
8306140480

8306140500 Forwards responses to 801222 ltr re NUREG-0612, "Control of
Heavy Loads at Nuclear Power Plants " Info addresses
overhead handling sys for fuel storage pool
CROUSE, R P Toledo Edison Co 752 83/06/10 STOLZ, J F
Operating Reactors Branch 4 142pp 18843 076 24X
Fiche 50-346, 83/06/10, 8306140500

8306140538 Forwards IE Insp Repts 50-335/83-06 & 50-389/83-20 on
830314-18 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/05/18
UHRIG, R E Florida Power & Light Co 2pp 18834 163 24X
Fiche 50-335, 83/05/18, 8306140538

--8306140541 IE Insp Repts 50-335/83-06 & 50-389/83-20 on 830314-18 No
noncompliance noted Major areas inspected emergency
planning
HUFFMAN, G N Region 2, Office of Director 50-389/83-20
83/05/17 6pp 18834 167 24X Fiche 50-335, 83/05/18, 8306140538

8306140562 Forwards IE Insp Repts 50-390/83-15 & 50-391/83-11 on
830321-0422 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/05/20
FARRIS, H O Tennessee Valley Authority 2pp 18844 129 24X
Fiche 50-390, 83/05/20, 8306140562

--8306140580 IE Insp Repts 50-390/83-15 & 50-391/83-11 on 830321-0422
No noncompliance noted Major areas inspected plant tour,
operating, maint & emergency procedure insps, preoperational
test procedure review & observation of structural concrete
HEATHERLY, T L, SWAN, W Region 2, Office of Director QUICK, D R
Division of Project & Resident Programs 50-391/83-11 83/05/20
18pp 18844 131 24X Fiche 50-390, 83/05/20, 8306140562

8306140631 Forwards IE Emergency Preparedness Appraisal Rept
50-382/83-08 on 830222-0304 No noncompliance noted Schedule
for completing corrective actions for deficiency noted in
App A requested within 30 days of receipt of ltr
MADSEN, G L Region 4, Office of Director 83/05/27 MAURIN, L V
Louisiana Power & Light Co 16pp 18837 281 24X
Fiche 50-382, 83/05/27, 8306140631

--8306140636 IE Emergency Preparedness Appraisal Rept 50-382/83-08 on
830222-0304 No noncompliance noted Major areas inspected
administration, emergency organization, training & retraining
& emergency facilities
HACKNEY, C A, PERROTTI, D J, WISNER, C E Region 4, Office of
Director 83/05/21 37pp 18837 297 24X Fiche 50-382, 83/05/27,
8306140631

8306140642 Forwards evaluation of BWR Owners Group generic response to
NUREG-0737, Item II K 3 1B, "Automatic Depressurization Sys
Logic Mods " Two of seven BWR Owners Group alternatives
acceptable Selection of option within 43 days requested
CRUTCHFIELD, D Operating Reactors Branch 5 83/06/03 FIEDLER, P B
General Public Utilities - GPU Service Corp 2pp 18833 264 24X
Fiche 50-219, 83/06/03, 8306140642

8306140691 NUREG/CR-3308 V01
EVALUATION OF ECOSYSTEM MODELS IN POWER PLANT IMPACT
ASSESSMENT A CASE STUDY USING LAKE ONTARIO Description of
Alternative Process Equations And Documentation of Parameter
Values
KALUZYNY, S P, ROSE, K A, SULLIVAN, P J Washington, Univ of,
Seattle, WA FIN D-7018 83/05/31 Division of Health, Siting &
Waste Management 68pp Available at NRC #4 50 18845 182

8306140707 Forwards addl info re NUREG-0737, Items II F 1 4, II F 1 5 &
II F 1 6 Due to small reactor size & low population density,
existing equipment adequate for safe operation
LINDER, F Dairyland Power Cooperative LAC-9127 83/06/03
CRUTCHFIELD, D Operating Reactors Branch 5 7pp 18841 279 24X
Fiche 50-409, 83/06/03, 8306140707

8306140716 Submits followup response to 14 of 19 open items identified
in NRC 830217 ltr re IE Emergency Preparedness Appraisal
Rept 50-298/82-34 on 821206-10
PILANT, J M Nebraska Public Power District 50-298/82-34
83/05/13 MADSEN, G L Region 4, Office of Director 9pp
18841 323 24X Fiche 50-298, 83/05/13, 8306140716

8306140738 Forwards topical repts, "Boundary Analytical Assessment of
NUREG-0630 on LOCA & Operating kW/Ft Limits," per 830602
request
TUCKER, H B Duke Power Co 83/06/26 DENTON, H R Office of
Nuclear Reactor Regulation, Director 1p 18845-001 24X
Fiche 50-269, 83/06/06, 8306140738

--8306140746 77-1141256-00
"Boundary Analytical Assessment of NUREG-0630 on LOCA &
Operating kW/Ft Limits "
* Babcock & Wilcox Co 83/06/06 29pp 18845 002 24X
Fiche 50-269, 83/06/06, 8306140738

--8306140752 77-1140895-00
"Bounding Analytical Assessment of NUREG-0630 on LOCA &
Operating kW/Ft Limits "
* Babcock & Wilcox Co 83/06/06 29pp 18845 032 24X
Fiche 50-269, 83/06/06, 8306140738

8306140774 NUREG/CR-3239
COMPRN-A COMPUTER CODE FOR MODELING COMPARTMENT FIRES
BIJUN D California, Univ of, Los Angeles FIN B-0493
UCLA-ENG-8237 83/05/31 Division of Risk Analysis 91pp
Available at NRC #4 73 18853 115

8306150011 Forwards detailed design description of implementation of
NUREG-0737, Item II F 1 6, "Containment Atmospheric Monitor,"
per 830411 request Test to be completed by 840601
HARRINGTON, W D Boston Edison Co 83-145 83/06/09 VASSALLO, D N
Operating Reactors Branch 2 14pp 18846 334 24X
Fiche 50-293, 83/06/09, 8306150011

8306150044 NUREG/CR-2963
COPPER IN THE INTAKE AND DISCHARGE ZONES OF THE SURRY
AND SALEM NUCLEAR POWER STATIONS
HARRISON, F L, KNEZOVICH, J F Lawrence Livermore Laboratory, FIN
A-0119 UCRL-53325 83/05/31 Division of Health, Siting & Waste
Management 31pp Available at NRC. #4 00 18869 221 24X
Fiche 50-000, 83/05/31, 8306150044

NONDOCKETED ITEMS

- 8306150081 NUREG/CP-0044 V02
PROCEEDINGS OF THE INTERNATIONAL ATOMIC ENERGY AGENCY
SPECIALISTS' MEETING ON SUBCRITICAL CRACK GROWTH Sessions
III, IV And V Held At Freiburg, Federal Republic Of Germany,
May 13-15, 1981
CULLEN, W H Materials Engineering Associates, Inc * ENSA, Inc
FIN B-8133 MEA-2014 83/05/31 Division of Engineering
Technology 434pp Available at NRC \$9 00 18870 097
- 8306150161 Requests extension of implementation date for torus mods
to 90 days following startup from current refueling outage
All internal mods & all torus-related mods complete
Extension applies only to torus-attached piping
HEIDER, L H Vermont Yankee Nuclear Power Corp FVY 83-35
83/06/13 EISENHUT, D G Division of Licensing 2pp 18846 319
24X Fiche 50-271, 83/06/13, 8306150161
- 8306150256 Forwards Suppl 1 to SER (NUREG-0896), addressing two
outstanding issues re emergency preparedness & secondary
water chemistry. Corrected page to NRC 820420 joint
affidavit & WT LeFave 830511 affidavit encl W/o SER
LEBBY, R P, PATTERSON, W F Hearing Branch 3 ISSUANCES OL
83/05/11 HOYT, H, LUEBKE, E A, HARBOUR, J Atomic Safety and
Licensing Board Panel. 2pp 18849 191 24X Fiche 50-443, 83/05/11,
8306150256
- 8306150260 Forwards "Control of Heavy Loads (C-10), TVA, Browns Ferry
Nuclear Power Station, Units 1, 2 & 3," draft technical
evaluation rept Conference call requested within 4 to 5
wks to discuss review results
VASSALLO, D B Operating Reactors Branch 2 83/05/26 PARRIS, H G
Tennessee Valley Authority 2pp 18869 322 24X
Fiche 50-259, 83/05/26, 8306150260
- 8306150266 TER-C5506-337/338/33
"Control of Heavy Loads (C-10), TVA, Browns Ferry Nuclear
Power Station, Units 1, 2 & 3," draft technical evaluation
rept
BOMBERGER, C Franklin Institute/Franklin Research Center
NRC-03-B1-130 TAC 07975 83/04/05 CLENNISON, F NRC - No
Detailed Affiliation Given 25pp 18869 324 24X
Fiche 50-259, 83/05/26, 8306150266
- 8306150272 "Synopsis of Issues Associated w/NUREG-0612,"
* Operating Reactors Branch 2. 83/05/26 11pp 18869 349 24X
Fiche 50-259, 83/05/26, 8306150266
- 8306150321 Forwards request for addl info re FSAR Design Criteria
Summary, Item 260.56 reflecting requirements of NUREG-0737,
"Clarification of TMI Action Plan Requirements,"
SCHWENCER, A Licensing Branch 2 83/06/07, BAUER, E O,
Philadelphia Electric Co 7pp 18870 010 24X
Fiche 50-352, 83/06/07, 8306150321
- 8306150391 Forwards supplemental SER, NUREG-0882 re NRC review of
licensee emergency plan, W/o encl
BACHMANN, R G Hearing Branch 1. 83/06/10 HOYT, H, HILL, E E,
SCHINK, D R Atomic Safety and Licensing Board Panel 1p
18847 028 24X Fiche 50-170, 83/06/10, 8306150391
- 8306150454 Releases public version of revised emergency plan
administrative procedure.
FELTON, J M Division of Rules and Records 83/06/06 Document
Management Branch 1p 18869 148, 24X Fiche 50-483, 83/06/06,
8306150454
- 8306150455 Public version of Rev D to Emergency Plan Administrative
Procedure APA-21-00102, "Emergency Operating Procedures
Writers Guide " Item numbers on encl correspond to numbers
used in Generic Ltr 82-33 W/830311 ltr.
SCOTT, W O, SCHNELL, D F Union Electric Co ULNRC-627 83/04/07
DENTON, H R Office of Nuclear Reactor Regulation, Director
49pp. 18869 149 24X Fiche 50-483, 83/06/06, 8306150454
- 8306150466 Forwards safety evaluation of util submittals on NUREG-0737
Items 1 A 2 1 4, "Upgrading Reactor Operator & Senior
Reactor Operator Training" & 11 B 4, "Training for
Mitigating Core Damage." Items resolved
VASSALLO, D B Operating Reactors Branch 2 83/06/03. MUSOLF, D M
Northern States Power Co 5pp 18869 214, 24X
Fiche 50-263, 83/06/03, 8306150466
- 8306150508 Forwards SER supporting 830128 submittal re TMI Action Plan
Items II F 1 4, "Containment Pressure Monitor," II F 1 5,
"Containment Water Level Monitor," & II F 1 6,
"Containment Hydrogen Monitor " Requirements met.
BDLZ, J F Operating Reactors Branch 4 83/05/24 CROUSE, R P
Toledo Edison Co 2pp 18866 313, 24X Fiche 50-346, 83/05/24,
8306150508
- 8306150515 Safety evaluation supporting licensee 830128 submittal re
NUREG-0737, Items II F 1 4, "Containment Pressure Monitor,"
II F 1 5, "Containment Water Level Monitor," & II F 1 6,
"Containment Hydrogen Monitor " Requirements met
* Office of Nuclear Reactor Regulation, Director 83/05/24 5pp
18866 313 24X Fiche 50-346, 83/05/24, 8306150508
- 8306150552 Forwards assessment of "Quick Look" rept in response to
830304 & 30 ltrs re submittal of initial evaluation of
safety relief valve in-plant test results Addl info
requested
SCHWENCER, A Licensing Branch 2 83/06/07 FARRAR, D L
Commonwealth Edison Co 5pp 18867 029 24X Fiche 50-373, 83/06/07,
8306150552
- 8306150574 NUREG/SR-0025 V09 N5
INFORMATION REPORT ON STATE LEGISLATION
KERR, O W, LANDAU, M Office of State Programs, Director 83/06/30
11pp. 18854 326
- 8306150576 Forwards safety evaluation of util submittals re NUREG-0737,
Item II B 2 on plant shielding mods Item resolved
VASSALLO, D B Operating Reactors Branch 2 83/05/23 MUSOLF, D M
Northern States Power Co 4pp 18867 034 24X
Fiche 50-263, 83/05/23, 8306150576
- 8306150584 NUREG/CR-3119 V02
NUCLEAR POWER SAFETY REPORTING SYSTEM Concept Description
FINLAYSON, F C Aerospace Corp FIN B-8255 ATR-83(3018)-1N
83/05/31 Division of Facility Operations 43pp Available at
NRC 3 75 18854 321
- 8306150588 NUREG-0910 R01
NRC COMPREHENSIVE RECORDS DISPOSITION SCHEDULE
* Division of Technical Information & Document Control 83/05/31
149pp Available at NRC \$7 00 18867 062
- 8306150602 NUREG/CR-2786
BWR REFILL-REFLOOD PROGRAM TASK 4 4 - CCFL/REFILL SYSTEM
EFFECTS TESTS (30 DEGREE SECTOR) EVALUATION OF ECCS MIXING
PHENOMENA
FINDLAY, J A General Electric Co FIN B-5877 EPRI NP-2542
83/05/31 Division of Accident Evaluation 69pp Available at
NRC \$4 50 18854 249
- 8306150616 NUREG-0968 S02
SAFETY EVALUATION REPORT RELATED TO THE CONSTRUCTION OF THE
CLINCH RIVER BREEDER REACTOR PLANT Docket No 50-537
(U S Department of Energy, Tennessee Valley Authority
And Project Management Corporation)
* Clinch River Breeder Reactor Program Office 83/05/31 19pp
Available at NRC \$3 00 18854 231 24X Fiche 50-537, 83/05/31,
8306150616
- 8306150619 NUREG/CR-3225
DATA ANALYSIS OF THE LLNL HYDROGEN IONITER EXPERIMENTS
ALTENBACH, T J, DAVIS, B W, MARTIN, R W Lawrence Livermore
Laboratory FIN A-0422 UCRL-53049 83/05/31 Division of
Systems Integration (post 811003) 63pp Available at NRC \$4 30
18854 164
- 8306160009 Forwards B Hawley & H Bernard testimony, completing NRC
testimony filing for Jul 1983 hearing
WOODHEAD, C P Hearing Branch 4 83/06/14 FRYE, J H, BRIDIT, G O,
LUEBKE, E A Atomic Safety and Licensing Board Panel 1p
18861 176 24X Fiche 50-142, 83/06/14, 8306160009
- 8306160010 Testimony of B Hawley explaining & clarifying analytical
bases for conclusion in NUREG/CR-2079, "Analysis of
Credible Accidents for Argonaut Reactors " Prof
qualifications encl
HAWLEY, B C NRC - No Detailed Affiliation Given HAWLEY, B C
Battelle Memorial Institute, Pacific Northwest Laboratory
83/06/14 20pp 18861 177 24X Fiche 50-142, 83/06/14, 8306160009
- 8306160017 Testimony of H Bernard explaining & clarifying bases &
assumptions used in SER, Section 14 re analysis of
consequences of postulated accidents Prof qualifications
encl
BERNARD, H Standardization & Special Projects Branch 83/06/14
14pp 18861 197 24X Fiche 50-142, 83/06/14, 8306160009
- 8306160206 Advises recipients of comments on proposed rule re safety
goal development program that two comments marked 1
received Comment docketed 830502 will be 1A
* Docketing & Services Branch 48FR10772 83/06/13 Docketing &
Services Branch 1p 18861 359
- 8306160210 Comments on proposed rule re safety goals concerning
evaluation plan for nuclear power plants Supports rule
WERNER, T A, Energy, Dept of 48FR10772 005 83/06/08 CHILK, S J
Office of the Secretary of the Commission 5pp 18861 267

NONDOCKETED ITEMS

433

8306160224 Package of three comments supporting proposed rule re safety goals development program, policy statement & evaluation plan
RAHE, E P Westinghouse Electric Corp FARRAR, D L Commonwealth Edison Co EDELMAN, M Atomic Industrial Forum 48FR10772
83/06/09 CHILK, B J Office of the Secretary of the Commission 9pp 18861 241

8306160249 Suppl to application for amend to Licenses NPF-4 & NPF-7, providing Tech Specs for NUREG-0737, Item 11 B 1, "Reactor Vessel Head Vent " No addl license amend fee required
STEWART, W L Virginia Electric & Power Co 333A 83/06/09
DENTON, H R Office of Nuclear Reactor Regulation, Director
CLARK, R A Operating Reactors Branch 3 2pp 18861 211 24X
Fiche 50-338, 83/06/09, 8306160249

--8306160266 Tech Specs re NUREG-0737, Item 11 B 1, "Reactor Vessel Head Vent " Discussion of proposed Tech Spec change also encl
* Virginia Electric & Power Co 83/06/09 11pp 18861 214 24X
Fiche 50-338, 83/06/09, 8306160249

8306160277 Forwards synopsis of issues & Franklin Research Ctr draft technical evaluation re NUREG-0612, "Control of Heavy Loads, Phase 1 " W/o encls
ADENSAH, E O Licensing Branch 4 83/06/10 TUCKER, H B Duke Power Co 2pp 18872 170 24X Fiche 50-369, 83/06/10, 8306160277

8306160284 Forwards Westinghouse Owners Group steam generator tube rupture (SOTR) emergency contingency guidance approved for high pressure version of emergency response guideline set Three SOTR guidelines, ECA-7, B & 9 provided
SHEPARD, J J Westinghouse Operating Plants Owners Group
SHEPARD, J J Carolina Power & Light Co 00-92 83/03/16
EISENHUT, D O Division of Licensing 4pp 18861 013

8306160310 Forwards final response to NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants-Resolution of TAP A-36 "
Response includes analyses for loads handled over reactor vessel
HEMPER, J S Philadelphia Electric Co 83/06/13 EISENHUT, D O Division of Licensing 126pp 18860 243 24X Fiche 50-352, 83/06/13, 8306160310

8306160339 Forwards response to 830422 request for addl info re Criteria 2.10 & 11 of NUREG-0737, Item 11 B 3, "Post-Accident Sampling " Interim core damage estimate guidelines will be submitted by 830630
WHIRLO, R C Florida Power & Light Co L-83-358 83/06/10
VARROA, S A Operating Reactors Branch 1 3pp 18861 171 24X
Fiche 50-250, 83/06/10, 8306160335

8306160337 Comments on proposed rule 10CFR50 re NRC policy statement on severe accidents & proposed rule re safety goals development program UCS comments on proposed rules will be consolidated & filed in early Jul
CURRAN, D Harmon & Weiss 48FR16014 001 83/06/08 STUCKY, B Docketing & Services Branch 1p 18860 124

8306160347 Comments on NRC policy statement on evaluation plan for safety goals Supports statement Evaluation period should be extended beyond 2 yrs Mechanism should be developed to allow public to assess progress
BRADBURY, R D Stone & Webster Engineering Corp 48FR10772 004 83/06/00 Docketing & Services Branch 3pp 18861 126

8306160357 Forwards "Enrico Fermi Atomic Power Plant, Unit 2, Plant-Unique Analysis Rept for Torus Attached Piping & Suppression Chamber Penetrations " Submittal responds to 820526 ltr & BER (NUREG-0798) requirements
TAUBER, H Detroit Edison Co EF2-63, 923, 83/06/10
YOUNGBLOOD, D J Licensing Branch 1 2pp 18859 247 24X
Fiche 50-341, 83/06/10, 8306160357

--8306160366 DET-19-076-6 ROD
Rev O to "Enrico Fermi Atomic Power Plant, Unit 2, Plant-Unique Analysis Rept for Torus Attached Piping & Suppression Chamber Penetrations "
HIGGINS, A J, YOSHIDA, D K NUTECH Engineers, Inc 83/06/30 192pp 18858 247 24X Fiche 50-341, 83/06/10, 8306160357

8306160401 Package of two comments on NRC policy statement on evaluation plans for safety goals for nuclear power plant operation
BLAND, W M System Safety Society CASTERLINO, R O Affiliation Unknown 48FR10772, 83/06/06 CHILK, B J Office of the Secretary of the Commission 9pp 18860 108

8306160493 Forwards "Bounding Analytical Assessment of NUREG-0630 Models on LOCA kW/ft Limits," reflecting use of FLECHET heat transfer correlation as compensating model to reduce impact of NUREG-0630 models
MARSHALL, J R Arkansas Power & Light Co 1CAN068301 83/06/08 STOLZ, J F Operating Reactors Branch 4 1p 18862 083 24X
Fiche 50-313, 83/06/08, 8306160493

--8306160497 77-1143707-00
"Bounding Analytical Assessment of NUREG-0630 Models on LOCA kW/ft Limits "
* Babcock & Wilcox Co 83/06/08 20pp 18862 083 24X
Fiche 50-313, 83/06/08, 8306160493

8306160500 Advises that procedures indicating shutdown cooling relief valves armed by manually opening shutdown cooling sys isolation valves will be utilized until operable low temp overpressure alarm available, per NUREG-0857, Suppl 1
VAN BRUNT, E E Arizona Public Service Co ANPP-24058-WFQ/ 83/06/13 KNIGHTON, G Licensing Branch 3 1p 18864 136 24X
Fiche 50-328, 83/06/13, 8306160500

8306160537 Responds to 821025 IE Insp Repts 50-313/82-14 & 50-369/82-11, Item 8 re control room dose calculations item re NUREG-0737, Item 11 B 2, "Plant Shielding," closed
MARSHALL, J R Arkansas Power & Light Co 0CAN068301 83/03/24 COLLINS, J T Region 4, Office of Director 2pp 18863 115 24X
Fiche 50-313, 83/03/24, 8306160537

8306160630 Forwards draft "Control of Heavy Loads at Nuclear Power Plants-St Lucie Plant, Unit 2 (Phase 1)" & synopsis of NRC interpretation of guidelines of NUREG-0612 for use in resolving open items
KNIGHTON, G Licensing Branch 3 TAC 47015 83/05/31 WHIRLO, R E Florida Power & Light Co 14pp 18884 283 24X
Fiche 50-389, 83/05/31, 8306160630

--8306160641 EOO-HB-6263 DRFT
Draft "Control of Heavy Loads at Nuclear Power Plants, St Lucie Plant, Unit 2 (Phase 1)," technical evaluation re SHADER, C R EGO, Inc FIN A-6457 TAC 47015 83/04/30 NRC
- No Detailed Affiliation Given 16pp 18884 297 24X
Fiche 50-389, 83/05/31, 8306160630

8306160645 NUREG-0422 807
SAFETY EVALUATION REPORT RELATED TO OPERATION OF MCQUIRE NUCLEAR STATION, UNITS 1 AND 2 Docket Nos 50-369 And 50-370 (Duke Power Company)
* Division of Licensing 83/05/31 100pp 18876 164 24X
Fiche 50-369, 83/05/31, 8306160645

8306170033 Concurs w/ findings contained in technical evaluation re "Control of Heavy Loads " Guidelines in NUREG-0612, Section 5 1 1 satisfied, per util 810402, 0715, 0831 & 1209, 820203 & 1108 & 830408 submittals
CLARK, R A Operating Reactors Branch 3 83/06/06 MUEBOLD, D M Northern States Power Co 2pp 18706 314 24X
Fiche 50-282, 83/06/06, 8306170033

--8306170038 Safety evaluation supporting util Phase 1 actions re control of heavy loads NUREG-0612, Section 5 1 1 guidelines satisfied
* Office of Nuclear Reactor Regulation, Director 83/06/06 1p, 18706 314 24X Fiche 50-282, 83/06/06, 8306170033

--8306170051 TER-C5506-384/385
"Control of Heavy Loads (C-10), Prairie Island Nuclear Generating Plant, Units 1 & 2," technical evaluation rept VOBURRY, F W Franklin Institute/Franklin Research Center, NRC-03-81-130 TAC 08073 83/05/17 NRC - No Detailed Affiliation Given 31pp 66794 188 24X Fiche 50-282, 83/06/06, 8306170053

8306170202 Forwards addl info to justify 820701 10CFR50 4B & App R schedule exemption requests discussed at 830330 meeting Plan being developed to complete maint & design changes W/ two oversize drawings Aperture cards available in PDR OUCHA, L T Georgia Power Co IEB-79-01B 83/06/14 STOLZ, J F Operating Reactors Branch 4 4pp 18882, 277 24X
Fiche 50-321, 83/06/14, 8306170202

8306170263 NUREG/CP-0044 V01
PROCEEDINGS OF THE INTERNATIONAL ATOMIC ENERGY AGENCY SPECIALIST MEETING ON SUBCRITICAL CRACK GROWTH, Sessions 1 And II Held At Freiburg, Federal Republic Of Germany, May 13-15, 1981
CULLEN, W H Materials Engineering Associates, Inc * ENBA, Inc FIN D-8133 HEA-2014 83/05/31 Division of Engineering Technology 328pp 18707 001

8306170281 Advises that 821227 commitment to complete installation & testing of post-accident sampling sys per NUREG-0737, Item 11 B 3 by 830601 has been met Final procedures for sys will be complete by 830701
STEWART, W L Virginia Electric & Power Co 332 83/06/14, DENTON, H R Office of Nuclear Reactor Regulation, Director EISENHUT, D O Division of Licensing, 2pp 18877 025 24X
Fiche 50-280, 83/06/14, 8306170281

NONDOCKETED ITEMS

8306170302 Forwards App J to, Evaluation of Pressurized Thermal Shock Effects Due to Small Break LOCAs W/Loss of Feedwater for Palo Verde 1 & 2, 2 & 3 Reactor Vessels " Rept applies to only Unit 1
VAN BRUNT, E E Arizona Public Service Co ANPP-24608-WFQ/
83/06/14 KNIGHTON, G Licensing Branch 3 3pp 18878 197 24X
Fiche 50-528, 83/06/14, 8306170302

8306170326 Forwards proposed amend to FSAR re CESSAR iodine removal sys & responses to NRC 830422 ltr Proposed FSAR amend combined w/responses closes out sump pH issue in SER Sections 5.4 & 15.4.8 & TMI Item III D 3.4
VAN BRUNT, E E Arizona Public Service Co ANPP-24059-WFQ/
83/06/13 KNIGHTON, G Licensing Branch 3 8pp 18879 040 24X
Fiche 50-528, 83/06/13, 8306170326

8306170333 Comments on proposed rule re NRC policy statement on development program & evaluation of safety goals Supports statement
TAYLOR, J J Electric Power Research Institute 48FR10772 008
83/06/13 Docketing & Services Branch 12pp 18880 054

8306170334 Package of five comments on proposed rule re plan to evaluate safety goal policy statement
REYNOLDS, N S, MCGARRY, J M Debevoise & Liberman FISHER, C R GA
Technologies, Inc /General Atomic Co 48FR10772 83/06/13
CHILK, S J Office of the Secretary of the Commission 16pp
18881 025

8306170408 Documents commitment to administratively impose temporary restrictions on plant operating LOCA limits as result of NUREG-0630, per 830608 telcon Review of PLFCSET data requested
MARSHALL, J R Arkansas Power & Light Co 1CAN068308 83/06/10
STOLZ, J F Operating Reactors Branch 4 3pp 18879 022 24X
Fiche 50-313, 83/06/10, 8306170408

8306170449 Forwards NRC rept on ADs at licensed nuclear facilities (NUREG-0090, Vol 3, Number 4), for Fourth Quarter CY82 W/o encl
AHEARN, J F Commissioners 83/06/02 O'NEILL, T P House of Rep
BUSH, G H Senate 3pp 18907 322

--8306170451 Forwards FR notice & ltr forwarding AO rept to Congress (NUREG-0090, Vol 3, Number 4) Medical misadministration event, discussed in SECY-83-92, upgraded to App C item W/o encl
DIRCKS, M J Office of the Executive Director for Operations
83/06/02 CHILK, S J Office of the Secretary of the Commission
1p 18907 325

8306170452 Forwards Suppl 2 to SER (NUREG-0968) re const of facility Suppl provides evaluation of addl info received on previously identified outstanding review items W/o encl
GRACE, J N Clinch River Breeder Reactor Program Office 83/06/13
LONCENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant
2pp 18894 303 24X Fiche 50-537, 83/06/13, 8306170452

8306170471 Forwards evaluation of BWR Owners Group generic response to NUREG-0737, Item II K 3.18 "Automatic Depressurization Sys Logic Modt" Two of seven alternatives acceptable One alternative should be chosen for facility mod
STOLZ, J F Operating Reactors Branch 4 83/06/03 BAUER, E G
Philadelphia Electric Co 9pp 18894 338 24X
Fiche 50-277, 83/06/03, 8306170471

8306200018 Notification of 830624 meeting w/util in Bethesda, MD to discuss & schedule multi-plant actions, NUREG-0737 & plant-specific open items
REGUVA, O Operating Reactors Branch 1 83/06/14 VARGA, S A
Operating Reactors Branch 1 3pp 18909 121 24X
Fiche 50-241, 83/06/14, 8306200018

8306200059 Advises that NUREG-0737, Items II F 1.4, II F 1.5 & II F 1.6 requirements resolved per 801219, 820726 & 830408 submittals Environ qualification of equipment will be reviewed separately, SER encl
STOLZ, J F Operating Reactors Branch 4 CLARK, R A Operating
Reactors Branch 3 83/06/04 GRIFFIN, J M Arkansas Power & Light
Co 7pp 18908 302 24X Fiche 50-313, 83/06/06, 8306200059

8306200069 Responds to 830414 memo requesting decision under NRC policy re need to perform review of
an Review of plant should be consistent
w/
refitization & Special Projects Branch 83/06/14
Assurance 1p 18909 173 24X
14, 8306200069

8306200102 Submits schedule for resolution of TMI Action Plan Item II K 3.5 "Automatic Trip of Reactor Coolant Pumps," in response to Generic Ltr 83-10D Pump trip setpoint procedures will be implemented by end of 1985 refuel outage
GIESLER, C W Wisconsin Public Service Corp GL-83-10D 83/06/15
EISENHUT, D G Division of Licensing 4pp 18903 330 24X
Fiche 50-303, 83/06/15, 8306200102

8306200108 Informs of change in design of control room ventilation sys smoke detection & isolation sys to upgrade control room ventilation sys to satisfy NUREG-0737, Item III D 3.4 requirements
MUSOLF, D Northern States Power Co 83/06/13 Office of Nuclear
Reactor Regulation, Director 1p 18903 238 24X
Fiche 50-263, 83/06/13, 8306200108

8306200119 Minutes of ACRS ECCS Subcommittee 830312 meeting in Washington, DC re proposed GE SAFER/GESTR ECCS licensing codes & status of other NRR licensing actions Schedules for completing Unresolved Safety Issues A-43 & A-1 encl
* ACRS - Advisory Committee on Reactor Safeguards 83/05/12
ACRS - Advisory Committee on Reactor Safeguards 29pp 18900 239

8306200168 Comments on NUREG-0963, Items 10.6.2.c & 10.6.2.d re waste mgmt research program, in view of NRC request for clarification of ACRS recommendations per 830429 meeting Recommendations appropriate
FOSTER, R F Foster, R FOSTER, R F ACRS - Advisory Committee on
Reactor Safeguards 83/05/02 MOELLER, D, TANG, R C ACRS -
Advisory Committee on Reactor Safeguards 2pp 18909 124

8306200204 Submits steps taken to satisfy Items 1.C.3 of License NPF-13 re control room envelope leak tightness test Control room leakage reduced Allowable leakage increased & analysis performed verifying SRP (NUREG-0800) conformance
DALE, L F Mississippi Power & Light Co AECM-83/0333 83/06/16
DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp
18903 236 24X Fiche 50-416, 83/06/16, 8306200204

8306200246 Forwards list of procedures reviewed, changed if appropriate & typical examples of controls that exist to assure equipment returned to svc, per NUREG-0608, Suppl 1
HUXILL, H D General Public Utilities - OPU Service Corp
5211-83-090 83/06/01 Region 1, Office of Director 15pp
18901 187 24X Fiche 50-289, 83/06/01, 8306200246

8306200260 Informs of further delay in implementing post-TMI-related issues due to delay in shipment of auxiliary safety instrumentation panels from vendor, in response to 830314 order
FAY, C W Wisconsin Electric Power Co 83/06/16 DENTON, H R
Office of Nuclear Reactor Regulation, Director CLARK, R A
Operating Reactors Branch 3 App 18901 173 24X
Fiche 50-246, 83/06/16, 8306200260

8306200409 Forwards "Emergency Response Facilities Design Rept," per NUREG-0737, Suppl 1, in response to Generic Ltr 82-33
WULLER, G E Illinois Power Co U-0643 83/06/16 SCHWENGER, A
Licensing Branch 2 1p 18904 325 24X Fiche 50-461, 83/06/16, 8306200409

--8306200414 "Emergency Response Facilities Design Rept"
* Illinois Power Co U-0643 83/06/16 38pp 18904 326 24X
Fiche 50-461, 83/06/16, 8306200409

8306200429 Forwards Suppl 4 to SER, NUREG-0831 W/o encl
SCHWENGER, A Licensing Branch 2 83/06/13 MCGAUGHY, J P
Mississippi Power & Light Co App 18920 019 24X
Fiche 50-416, 83/06/13, 8306200429

8306210025 Forwards QA Program Insp Rept 99900060/83-01 on 830314-18 No noncompliance noted
POTAPOV, U Region 4, Office of Director 83/05/27 PATTARINI, D H
Target Rock Corp 2pp 18911 249

--8306210031 QA Program Insp Rept 99900060/83-01 on 830314-18 No noncompliance noted Major areas inspected TVA Part 21 rept on safety relief valve failure at Browns Ferry Unit 2
KELLEY, W D, BARNES, I Region 4, Office of Director 83/05/26
10pp 18911 251

8306210058 Interim deficiency rept for Item 8-11 re inadequacy of structural steel bolting program to assure compliance w/design spec & FSAR criteria Initially reported on 830313 Followup rept expected by 830912
WILLIAMS, J Cincinnati Gas & Electric Co IOCFR 050 55E 83/06/10
KEPPLER, J G Region 3, Office of Director 2pp 18911 224 24X
Fiche 50-358, 83/06/10, 8306210058

NONDOCKETED ITEMS

435

8306210073 Suppls B30513 ltr re NUREG-0737, Item II F 1 5, "Containment Water Level Monitoring Sys " Lower value of transmitter error should be used for calculating of overall loop uncertainties
LENTINE, G G Commonwealth Edison Co 676JN 83/06/15 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 18912 291
24X Fiche 50-295, 83/06/15, 8306210073

8306210144 Suppls B21012 & B30510 responses to NUREG-0737, Item II B 3, "Post-Accident Sampling Sys " Commitment to Criterion 9(b)
re background radiation levels Fulfills item requirement
BAYNE, J P Power Authority of the State of New York 1PN-83-63
83/06/17 EISENHUT, D G Division of Licensing 4pp 18914 092
24X Fiche 50-286, 83/06/17, 8306210144

8306210158 Forwards order confirming commitment to implement post-TMI-related items II D 3, "Post-Accident Sampling" & II E 4 2 7, "Isolate Purge & Vent Valves on Radiation Signal"
CRUTCHFIELD, D Operating Reactors Branch 5 LS05-83-06-039
83/06/17 FIELDER, P B General Public Utilities - GPU Service Corp
3pp 18916 392 24X Fiche 50-219, 83/06/17, 8306210158

--8306210166 Order confirming licensee commitments on post-TMI-related items II D 3, "Post-Accident Sampling" & II E 4 2, "Isolate Purge & Vent Valves on Radiation Signal"
EISENHUT, D G Division of Licensing GL-82-05 83/06/17
General Public Utilities - GPU Service Corp 8pp 18916 395 24X
Fiche 50-219, 83/06/17, 8306210158

8306210287 Forwards program plan issues & areas for outstanding items re NUREG-0737, Item I D 1 re detailed control room design
review per NUREG-0700 requirements & SER, NUREG-0857 Generic
Ltr 82-33 issues addressed
VAN BRUNT, E E Arizona Public Service Co GL-82-33 83/06/17
KNOX, G Licensing Branch 3 36pp 18914 038 24X
Fiche 50-52B, 83/06/17, 8306210287

8306210294 Interim deficiency rept, Item B-9 re soil structure compaction outside power area not per design spec & FAR criteria Initially reported on B30513 All safety-related structures & sys will be identified
WILLIAMS, J Cincinnati Gas & Electric Co 10CFR 050 55E 83/06/13
MEPLER, J G Region 3, Office of Director 2pp 18915 147 24X
Fiche 50-35B, 83/06/13, 8306210294

8306210317 NUREG-0982
SAFETY EVALUATION REPORT RELATED TO RENEWAL OF THE OPERATING LICENSE FOR THE RESEARCH REACTOR AT THE STATE UNIVERSITY OF NEW YORK AT BUFFALO Docket No 50-57
* Division of Licensing 83/05/31 89pp Available at NRC
\$4 50 18924 282 24X Fiche 50-057, 83/05/31, 8306210317

8306210324 NUREG/CR-2044
REACTOR OPERATING EXPERIENCES 1978 - 1980
MAYS, O T, WINTON, M L Oak Ridge National Laboratory FIN A-9135
ORNL/NSIC-194 83/05/31 Director's Office 1p Available at
NRC \$6 00 18922 001

8306210331 NUREG-0831 804
SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF GRAND GULF NUCLEAR STATION, UNITS 1 & 2 Docket Nos 50-416 & 50-417 (Mississippi Power And Light Company)
* Division of Licensing 83/05/31 156pp Available at NRC
\$5 50 18922 197 24X Fiche 50-416, 83/05/31, 8306210331

8306210340 Responds to FOIA request for names & locations of various nuclear facilities licensed by NRC Forwards NUREG-0871, "Summary Info Rept " W/o encl
FELTON, J M Division of Rules and Records 83/04/08 THOMAS, D M
Overseas Packing, Inc 1p 18921 330

8306210350 NUREG/CR-3287
A GUIDE FOR THE TACT III COMPUTER CODE Final Report
KILLOUGH, G O, BEGOVICH, C L, SJOREN, A L Oak Ridge National
Laboratory FIN D-0774 ORNL/IM-8763 83/05/31 Division of
Systems Integration (post 811005) 290pp Available at NRC \$7 00
18924 001

8306210354 NUREG-0992
REPORT OF THE COMMITTEE TO REVIEW SAFEGUARDS REQUIREMENTS
AF POWER REACTORS
HAYNE, R C, BURNETT, R F, MIRAGLIA, F J Safety/Safeguards Review
Group 83/05/31 184 Available at NRC \$6 00 18925 008

8306210362 NUREG-0939
EXAMPLE CALCULATIONS ILLUSTRATING METHODS FOR ANALYZING
DUCTILE FLAW STABILITY IN NUCLEAR PRESSURE VESSELS
MERKLE, J O, JOHNSON, R E Division of Safety Technology 83/05/31
26pp Available at NRC \$3 50 18937 233

8306210378 NUREG-0882 501
SAFETY EVALUATION REPORT RELATED TO THE RENEWAL OF THE
OPERATING LICENSE FOR THE RESEARCH REACTOR AT THE ARMED
FORCES RADIOBIOLOGY RESEARCH INSTITUTE Docket No 50-170
* Division of Licensing 83/05/31 11pp Available at NRC
\$3 00 18937 261 24X Fiche 50-170, 83/05/31, 8306210378

8306210383 NUREG-0606 V05 N02
UNRESOLVED SAFETY ISSUES SUMMARY Data As Of May 27, 1983
(Aqua Book)
* Management Information Branch 83/06/30 49pp 18935 233

8306210401 NUREG-0020 V07 N02
LICENSED OPERATING REACTORS STATUS SUMMARY REPORT Data As Of
January 31, 1983 (Grey Book)
* Management Information Branch 83/06/30 391pp 18934 199

8306210453 Comments on Class 7 Accidents Subcommittee 830425 & 26
meetings NUREG-0900 fails to answer how regulatory needs
for degraded core accidents could be met by severe accident
research plan
LEE, J C Michigan, Univ of LEE, J C ACRS - Advisory Committee on
Reactor Safeguards 83/05/05 WANG, A ACRS - Advisory Committee on
Reactor Safeguards 2pp 18935 338

8306210463 Forwards comments on draft AD rept to Congress for First
Quarter CY83 Comments in 830415 memo adequately addressed.
Subj to resolution of comments, concurs w/proposed Commission
paper
DENTON, H R Office of Nuclear Reactor Regulation, Director
83/06/07 HELTEMES, C J Director's Office 3pp 18925 329

--8306020498 Forwards draft Commission paper re AD rept to Congress for
First Quarter CY83 based on NRC response to AEOD 830318
memo, for review, comments & concurrence
HELTENES, C J Director's Office 83/05/17 DENTON, H R Office
of Nuclear Reactor Regulation, Director 46pp 18926 001

8306220005 Documents 830606 telcon re util 830209 response to NUREG-
0737, Item II E 1 2, "Auxiliary Feedwater Sys Automatic
Initiation & Flow Indication " Bypass signals do not block
indicator, annunciator or reactor trip signals
ZIMMERMAN, S R Carolina Power & Light Co LAP-83-228 83/06/17
VAROA, B A Operating Reactors Branch 1 2pp 18927 360 24X
Fiche 50-261, 83/06/17, 8306220005

8306220033 Application to amend Licenses DPR-32 & DPR-37, changing Tech
Specs by adding addl accident monitoring instrumentation &
reactor vessel head vents per NUREG-0737, Items II F 1 &
II D 1, respectively
STEWART, W L Virginia Electric & Power Co 330 83/06/16
DENTON, H R Office of Nuclear Reactor Regulation, Director
VAROA, B A Operating Reactors Branch 1 3pp 18927 233, 24X
Fiche 50-280, 83/06/16, 8306220033

--8306220047 Proposed Tech Specs adding addl accident monitoring
instrumentation & reactor vessel head vents, per NUREG-0737,
Items II F 1 & II D 1, respectively
* Virginia Electric & Power Co 83/06/16 23pp 18927 237 24X
Fiche 50-280, 83/06/16, 8306220033

8306220040 Notifies of error in 830506 ltr re containment
instrumentation upgrades per NUREG-0737, Items II F 1 4,
II F 1 5 & II F 1 6 Existing instrument display is indicator
not recorder
RODRIGUEZ, R J Sacramento Municipal Utility District RJR 83-504
83/06/17 BTOLZ, J F Operating Reactors Branch 4 2pp 18928 208
24X Fiche 50-312, 83/06/17, 8306220040

8306220049 Forwards Vols 3 & 4 to "Environ Qualification of Class IE
Equipment " Data combined w/830320 response to NRC 830111
SER, provides complete response to NUREG-0508, IE Bulletin
79-018 & recently published rule 10CFR90.49
WESTAFER, O R Florida Power Corp 3F-0683-07 83/06/15
BTOLZ, J F Operating Reactors Branch 4 2pp 18928 231 24X
Fiche 50-302, 83/06/15, 8306220049

8306220074 Forwards safety evaluation & technical evaluation rept re
util response to 801222 generic ltr, "Control of Heavy
Loads " Guidelines in NUREG-0612 satisfied & Phase
acceptable
CRUTCHFIELD, D Operating Reactors Branch 5 LS05-83-06-045
83/06/21 FIELDER, P B General Public Utilities - GPU Service Corp
2pp 18926 060 24X Fiche 50-219, 83/06/21, 8306220074

--8306220083 Safety evaluation re util response to Generic Technical
Issue A-36, "Control of Heavy Loads " NUREG-0612 guidelines
satisfied Phase 1 acceptable
* Office of Nuclear Reactor Regulation, Director 83/06/21 2pp
18926 062 24X Fiche: 50-219, 83/06/21, 8306220074.

NONDOCKETED ITEMS

- 8306140424 YER-C5506-377
"Control of Heavy Loads (C-10), JCP&L Oyster Creek Nuclear Power Plant," technical evaluation rept
BOMBERGER, C Franklin Institute/Franklin Research Center
NRC-03-81-130 TAC 47128 83/06/10 SINGH, A NRC - No Detailed Affiliation Given 32pp 18926 044 24X Fiche 50-219, 83/06/21, 8306220074
- 8306220075 Clarifies info provided in 830502 ltr re NUREG-0737, Item II B 3 "Post-Accident Sampling Sys (PASS)," per 830926 request Equipment ordered to allow powering of analyzer & solenoid valves from reliable source within 3 h
RODRIGUEZ, R J Sacramento Municipal Utility District RWR-83-312 83/06/17 STOLZ, J F Operating Reactors Branch 4 6pp 18930 164 24X Fiche 50-312, 83/06/17, 8306220075
- 8306220087 Forwards description of program approved by Westinghouse Owners Group to address NUREG-0737, Item II B 3 re post-accident core damage assessment, per 830428 meeting Project to be completed by end of yr
SHEPPARD, J J Westinghouse Operating Plants Owners Group
SHEPPARD, J J Carolina Power & Light Co 83/06/16 NORRIS, J A Operating Reactors Branch 1 7pp 18926 203
- 8306220098 Forwards Suppl 2 to SER (NUREG-0881) W/o encl
YOUNGBLOOD, D J Licensing Branch 1 83/06/16 KOESTER, G L Kansas Gas & Electric Co 2pp 18977 346 24X Fiche 50-482, 83/06/16, 8306220098
- 8306220198 Forwards Vol 5, Number 4 to NUREG-0090, "Rept to Congress on AOs," for Fourth Quarter CY82 One AO reported at NRC licensees re inoperability of containment spray sys Agreement states reported no AOs
AHEARNE, J F Commissioners 83/06/02 O'NEILL, T P House of Rep 2pp 18940 024 24X Fiche 50-000, 83/06/02, 8306220198
- 8306220219 Presents alternatives to automatic depressurization sys logic to eliminate need for manual actuation for core coverage per TMI Item II K 3 18 Implementation schedule & proposed Tech Specs requested within 45 days of ltr receipt
STOLZ, J F Operating Reactors Branch 4 83/06/03 BECKHAM, J T Georgia Power Co 2pp 18951 001 24X Fiche 50-321, 83/06/03, 8306220219
- 8306220224 Forwards draft tables reflecting status of NUREG-0752, NUREG-0737, NUREG-0680 & NUREG-0746 restart certification items Meeting proposed for 830614 to discuss status of items listed in encl
STOLZ, J F Operating Reactors Branch 4 83/06/09 HUKILL, H D General Public Utilities - GPU Service Corp 35pp 18930 312 24X Fiche 50-289, 83/06/09, 8306220224
- 8306220245 NUREG/CP-0043 ERR
PROCEEDINGS OF THE JOINT NRC/ANS MEETING ON BASIC THERMAL HYDRAULIC MECHANISMS IN LWR ANALYSIS Held At Bethesda, Maryland, September 14-15, 1982
* American Nuclear Society 83/06/02 Office of Nuclear Regulatory Research, Director 43pp 18931 073
- 8306220275 Informs that 830310 proposed wide-range hot leg level/reactor vessel head monitoring satisfactory Evaluation & addl info request re conformance of addl inadequate core cooling instrumentation sys components to NUREG-0737, encl
STOLZ, J F Operating Reactors Branch 4 83/06/08 YUCKER, H B Duke Power Co 10pp 18977 155 24X Fiche 50-269, 83/06/08, 8306220275
- 8306230047 Forwards safety evaluation of emergency response guidelines Guidelines acceptable for implementation & will provide improved guidance for emergency operating procedure development Response schedule requested within 90 days
EISENHUT, D O Division of Licensing 83/06/01 SHEPPARD, J J Westinghouse Operating Plants Owners Group 2pp 18982 109
- 8306230052 Safety evaluation re Westinghouse Owners Group generic emergency guidelines for mitigating transients & accidents, per NUREG-0737, Item I, C 1
* Office of Nuclear Reactor Regulation, Director 83/06/01 73pp 18982 111
- 8306230089 Interim deficiency rept re Item M-87, inadequacy of design control process to assure design output documents contain adequate erection & insp criteria. Initially reported on 830513, Item not reportable under 10CFR50.55(e)
WILLIAMS, J Cincinnati Gas & Electric Co, 10CFR 050 35E 83/06/15 KEPLER, J O Region 3, Office of Director 2pp 18947 074 24X Fiche 50-358, 83/06/15, 8306230089
- 8306230195 Forwards IE Insp Rept 50-244/83-11 on 830502-06 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/06/08 MAIER, J E Rochester Gas & Electric Corp 2pp 18946 392 24X Fiche 50-244, 83/06/08, 8306230195
- 8306230199 IE Insp Rept 50-244/83-11 on 830502-06 No noncompliance noted Major areas inspected actions taken to comply w/ NUREG-0737, Item II B 2 re design review of plant shielding
BAUNACK, W H, EAPEN, R K Region 1, Office of Director KISTER, H B Division of Project & Resident Programs 83/06/07 7pp 18946 354 24X Fiche 50-244, 83/06/08, 8306230195
- 8306230203 Forwards IE Insp Rept 50-247/83-12 on 830503-31 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/06/10 TUDOLE, J D Consolidated Edison Co of New York, Inc 2pp 18945 283 24X Fiche 50-247, 83/06/10, 8306230203
- 8306230212 IE Insp Rept 50-247/83-12 on 830503-31 No noncompliance noted Major areas inspected licensee action on previously identified insp findings, facility operations review, plant trips, TMI action items & surveillance
FOLLEV, F Region 1, Office of Director 01-82-12 83/06/07 14pp 18945 283 24X Fiche 50-247, 83/06/10, 8306230203
- 8306230259 Forwards Rev 0 to "Detailed Control Room Design Review (DCRR) Program Plan for Davis Besse Nuclear Power Plant," in response to NRC 821217 ltr & commitments per util 830415 ltr
CROUSE, R P Toledo Edison Co 959 83/06/15 STOLZ, J F Operating Reactors Branch 4 1p 18945 021 24X Fiche 50-346, 83/06/15, 8306230259
- 8306230262 Rev 0 to "Detailed Control Room Design Review (DCRR) Program Plan for Davis Besse Nuclear Power Plant"
* Toledo Edison Co 83/06/15 50pp 18945 022 24X Fiche 50-346, 83/06/15, 8306230259
- 8306230274 Responds to NRC 830523 request for proposed resolution to TMI Item II K 3 18, "Mod of Automatic Depressurization Sys Logic." Justification for bypass timer setting will be provided prior to implementation of mod
KEMPER, J S Philadelphia Electric Co 83/06/20 SCHWENGER, A Licensing Branch 2 3pp 18945 135 24X Fiche 50-352, 83/06/20, 8306230274
- 8306230342 Comments on proposed rule re safety goal development program
SCHERER, A E Combustion Engineering, Inc 48FR10772 016 83/06/17 Docketing & Services Branch 2pp 18943 059
- 8306230409 Comments on proposed rule re NRC policy statement on safety goals Policy inadequate for dealing w/safety problems
PUROY, O J Affiliation Unknown 48FR10772 017 83/06/16 NRC - No Detailed Affiliation Given 2pp 18943 203
- 8306230413 Supplements 830202 ltr discussing alternative to automatic isolation of V-79 exhaust sys when radiation detected, per NUREG-0737, Item II F 1.1 Explanation of why alternatives to proposed mod investigated discussed
JOHNSON, B D Consumers Power Co 83/06/17 KEPLER, J O Region 1 Office of Director 3pp 18941 340 24X Fiche 50-235, 83/06/17, 8306230413
- 8306230428 Advises recipients of comments on proposed rule re safety goal development program that two comments both numbered 7 received Comment docketed 830613 will be 14
* Docketing & Services Branch 48FR10772 83/06/21 Docketing & Services Branch 1p 18943 232
- 8306230432 Advises recipients of comments on proposed rule re safety goal development program that two comments both numbered 6 received Comment docketed 830613 will be 13
* Docketing & Services Branch 48FR10772 83/06/21 Docketing & Services Branch 1p 18941 359
- 8306230433 Advises recipients of comments on proposed rule re safety goal development program that two comments both numbered 5 received Comment docketed 830613 will be 12
* Docketing & Services Branch 48FR10772 83/06/21 Docketing & Services Branch 1p 18942 076
- 8306230434 Advises recipients of comments on proposed rule re safety goal development program that two comments both numbered 4 received Comment docketed 830613 will be 11
* Docketing & Services Branch 48FR10772 83/06/21 Docketing & Services Branch 1p 18943 242
- 8306230436 Advises recipients of comments on proposed rule re safety goal development program that two comments both numbered 3 received Comment docketed 830613 will be 10
* Docketing & Services Branch 48FR10772 83/06/21 Docketing & Services Branch 1p 18942 087

NONDOCKETED ITEMS

437

8306230437 Forwards Rev 3 to "Corporate Operations Manual, Part IV- Functional Manuals, Section I Nuclear QA Manual" Revs reflect organizational changes & clarify items modified in Rev 2 to SRP (NUREG-0800)
RAUSCH, W P Burns & Roe Co 83/06/07 HAASS, W P Quality Assurance Branch 1p 18944 023

8306230439 Advises recipients of comments on proposed rule re safety goal development program that two separate comments both indicate number 8 Comment docketed 830615 will be 15
* Docketing & Services Branch 48FR10772 83/06/21 Docketing & Services Branch 1p 18944 022

8306230447 Responds to NRC 830603 & 10 telcon requests for addl info re NUREG-0737, Item II D 2, "Plant Shielding"
RODRIGUEZ, R J Sacramento Municipal Utility District RJR 83-303 83/06/17 MARTIN, J B Region 5, Office of Director App 18942 083 24X Fiche 50-312, 83/06/17, 8306230447

8306230452 Forwards revised response to NUREG-0612, "Control of Heavy Loads" Rev addresses NRC comments contained in draft technical evaluation rept dtd 821123 & supplemented by NRC 821228 ltr
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire SBN-521 83/06/20 KNIGHTON, G W Licensing Branch 3 2pp 18941 001 24X Fiche 50-443, 83/06/20, 8306230452

--8306230458 9743 006-S-N-5
"Response to NRC Generic Request for Addl Info Re NUREG-0612, Control of Heavy Loads"
* United Engineers & Constructors, Inc (subs of Raytheon Co) 83/05/31 147pp 18941 004 24X Fiche 50-443, 83/06/20, 8306230452

8306230474 Submits addl info re radiation filtration sys for emergency control ctr (ECC), per NUREG-0737, Suppl 1 on emergency response Radiation Filtration sys designed to be manually activated Sketch of ECC filtration sys encl
MARSHALL, J R Arkansas Power & Light Co OCAHO68310 83/06/17 STOLZ, J F Operating Reactors Branch 4 3pp 18941 307 24X Fiche 50-313, 83/06/17, 8306230474

8306230517 NUREG 0750 V16 N01
NUCLEAR REGULATORY COMMISSION ISSUANCES July 1982
* Division of Technical Information & Document Control 82/07/31 409pp 18983 001

8306230521 Advises that mod of Model B2/D3 steam generators acceptable & modified steam generators can be operated at 100% of design capacity w/mod in place
DIRCKS, W J Office of the Executive Director for Operations 83/06/14 PALLADINO, N J, GILINSKY, V, AHEARNE, J Commissioners 3pp 18991 387 24X Fiche 50-395, 83/06/14, 8306230521

8306240004 Forwards vendor info rept, "Containment Water Level Monitoring," in response to 830415 request for addl info re NUREG-0737, Items II F 1.4 & II F 1.5, "Containment Pressure Monitor" & "Containment Water Level Monitor"
BORDINE, T C Consumers Power Co 83/06/20 CRUTCHFIELD, D Operating Reactors Branch 5 16pp 18991 293 24X Fiche 50-155, 83/06/20, 8306240004

8306240048 NUREG-0580 V12 N05
REGULATORY LICENSING STATUS SUMMARY REPORT Data As Of May 31, 1983 (Blue Book)
* Management Information Branch 83/06/30 47pp 18986 352

8306240050 NUREG/CR-3047
CLOSEOUT OF IE BULLETIN 80-14 POTENTIAL MISAPPLICATION OF ROSEMOUNT PRESSURE TRANSMITTERS
DEAN, R S, FOLEY, W J, HENNICK, A Parameter, Inc FIN B-1013 PARAMETER IE-12 83/06/30 Division of Emergency Preparedness (Pre 830103) 42pp Available at NRC \$3 75 18986 309

8306240052 NUREG/CR-2460
EXPERIMENT OPERATION PLAN FOR THE TH-3 EXPERIMENT IN THE NRU REACTOR
RUSSCHER, O C, WILSON, C L, PARCHEN, L J Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2277 PNL-4232 83/06/30 Division of Accident Evaluation 35pp Available at NRC \$3 75 18986 272

8306240056 NUREG-0843 S04
SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF ST LUCIE PLANT, UNIT NO 2 Docket No 50-389 (Florida Power and Light Company And Orlando Utilities Commission Of The City Of Orlando, Florida)
* Division of Licensing 83/06/30 26pp 18986 245 24X Fiche 50-389, 83/06/30, 8306240056

8306240058 NUREG/CR-3254
LICENSEE PROGRAMS FOR MAINTAINING OCCUPATIONAL EXPOSURE TO RADIATION AS LOW AS IS REASONABLY ACHIEVABLE
MUNSON, L H Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2427 PNL-4683 83/06/30 Division of Facility Operations 39pp Available at NRC \$3 75 18986 203

8306240060 NUREG-0856
FINAL TECHNICAL POSITION ON DOCUMENTATION OF COMPUTER CODES FOR HIGH-LEVEL WASTE MANAGEMENT
SILLING, S A Division of Waste Management 83/06/30 20pp Available at NRC \$3 00 18986 182

8306240062 NUREG/CR-3294
FATIGUE CRACK GROWTH RATES OF A 508-2 STEEL IN PRESSURIZED, HIGH TEMPERATURE WATER
CULLEN, W H Materials Engineering Associates, Inc * ENSA, Inc. FIN B-B133 MEA-2016 83/06/30 Division of Engineering Technology 33pp Available at NRC \$3 75 18986 148

8306240063 NUREG-0986
RCS/KS REACTOR COOLANT SYSTEM LEAK RATE DETERMINATION FOR PWRB User's Guide
KIRKPATRICK, O, WOODRUFF, R W Division of Emergency Preparedness (Pre 830103) 83/06/30 103pp Available at NRC \$4 75, 18986 043

8306240064 Notifies that addl info re list of safety-related items in FSAR Table 3.2-1 (QA-list) acceptable Outstanding Issue 23 in Suppl 3 to SER (NUREG-0807) will be changed to conformity issue per FSAR Amend 12 review
YOUNGBLOOD, D J Licensing Branch 1 83/06/21 EDELMAN, M R Cleveland Electric Illuminating Co 2pp 18987 134 24X Fiche 50-440, 83/06/21, 8306240064

8306240070 Requests addl info re moisture separators of heaters in filter sys serving nonaccessible area & fuel handling bldg for SER review Info requested within 30 days to maintain review schedule
YOUNGBLOOD, D J Licensing Branch 1 83/06/21 FARRAR, D L Commonwealth Edison Co 3pp 18985 028 24X Fiche 50-000, 83/06/21, 8306240070

8306240073 NUREG/CR-3183
LOCA SIMULATION IN NRU PROGRAM THE CONTINUOUS MEASUREMENT OF COOLANT LIQUID LEVEL DURING THE HT-4 EXPERIMENT IN THE NRU REACTOR
MARSHALL, R K, MOHR, C L, MCDOUFFIE, P N Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2381 PNL-7650 83/06/30 Division of Accident Evaluation 32pp Available at NRC \$3 75 18986 016

8306240078 NUREG/CR-3194
IMPROVED BENEFIT-COST TECHNIQUES IN THE U S NUCLEAR REGULATORY COMMISSION
CRONIN, F J, MCGEE, R J, VAETH, M Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2381 PNL-7650 83/06/30 Office of Nuclear Regulatory Research, Director 109pp, Available at NRC \$5 00 18985 247

8306240145 Application to amend License DPR-71, changing Tech Specs re snubber listings, drywell sump instrumentation numbers, remote shutdown panel instrumentation numbers & installation of NUREG-0737 mods for startup
HOWE, P W Carolina Power & Light Co LAP-83-236 83/06/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp, 18981 041 24X Fiche 50-325, 83/06/20, 8306240145

--8306240149 Revised Tech Spec re snubber listings, drywell sump instrumentation numbers, remote shutdown panel instrumentation numbers & installation of NUREG-0737 mods for startup
* Carolina Power & Light Co 83/06/20 44pp 18981 043 24X Fiche 50-325, 83/06/20, 8306240145

8306240177 Responds to SEP Topic III-5 B, "Pipe Break Outside Containment" Installation of jet impingement shields to protect main steam safety & relief valves not needed, item resolved
MATER, J E Rochester Gas & Electric Corp 83/06/16 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 18981 030 24X Fiche 50-244, 83/06/16, 8306240177

8306240256 Requests reconsideration of denial of exemption request in SECY-83-199 re primary emergency operations facility (EOF) Current EOF location found acceptable by Region V, FEMA & state & local govts
WITHERS, D D Portland General Electric Co 83/06/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 18981 315 24X Fiche 50-344, 83/06/17, 8306240256

NONDOCKETED ITEMS

8306240274 Forwards response to criteria for resolution of NUREG-0737, Item II K 3 5. "Automatic Trip of Reactor Coolant Pumps," stated in NRC B30208 Generic Ltr B3-10C Westinghouse Owners Group program addressing criteria will be evaluated. FOSTER, D O Georgia Power Co FOSTER, D O Southern Co Services, Inc QL-B3-10C B3/06/16 ADENSAM, E G Licensing Branch 4 3pp 18980 126 24X Fiche 50-424, B3/06/16, B306240274

8306240288 Requests addl info to resolve SER Confirmatory Issue 10 re fast scram hydrodynamic loads on control rod drive sys. Response within 7 days of ltr receipt requested. YOUNG, B J Licensing Branch 1 B3/06/21 EDELMAN, M R Cleveland Electric Illuminating Co 3pp 18999 167 24X Fiche 50-440, B3/06/21, B306240288

8306240373 NUREG/CR-2954 RADIOLOGICAL SURVEYS OF PROPERTIES CONTAMINATED BY RESIDUAL RADIOACTIVE MATERIAL FROM URANIUM PROCESSING SITES. YOUNG, Y A, JACKSON, P O, THOMAS, W V Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2216 PNL-4264 B3/06/30 Division of Waste Management 142pp Available at NRC \$5 50 18985 031

8306240384 NUREG/CR-3296 A REVIEW OF THE CURRENT DEFICIENCIES IN PERSONNEL BETA DOSIMETRY, WITH RECOMMENDATIONS. SHERBINI, S, PORTER, S W Porter Consultants, Inc FIN B-8096 PCI-TR-224 B3/05/31 Division of Facility Operations 83pp Available at NRC \$4 50 18985 179

8306240413 NUREG/CR-3281 INVESTIGATION OF THE SHELL CRACKING ON THE STEAM GENERATORS OF INDIAN POINT NO 3 Docket No 50-286 (Consolidated Edison Company). CIAJIKOWSKI, C Brookhaven National Laboratory FIN A-3400 BNL/NUREG-51670 B3/06/30 Division of Engineering 51pp Available at NRC \$4 00 18998 273 24X Fiche 50-286, B3/06/30, B306240413

8306270008 IE Insp Findings & Licensee Act 4db B30614 of License 34-15634-01 Insp findings 48 hr dose calibrator linearity tests not performed per NUREG-0338, App D, Section 2 & wipe tests not performed on incoming packages. * Region 3, Office of Director B3/06/14 1p 18988 137

8306270133 Forwards addl info re NUREG-0737, Item II E 1 i, "Auxiliary Feedwater Sys Upgrade Review," per B30502 & 0603 ltrs, in response to NRC B20407 Ltr Condensate storage tank not damaged by wind loads generated by 175 mph winds. RODRIGUEZ, R J Sacramento Municipal Utility District RJR B3-507 B3/06/21 STOLZ, J F Operating Reactors Branch 4 3pp 18988 011 24X Fiche 50-312, B3/06/21, B306270133

8306270141 NUREG/CR-2962 THERMALLY STIMULATED CURRENT CHARACTERIZATION OF THE DEGRADATION OF POLY (VINYL CHLORIDE) CABLE MATERIAL IN RADIATION AND THERMAL ENVIRONMENT. KURTZ, S R Sandia Laboratories FIN A-1091 SAND82-2164 B3/05/31 Division of Engineering Technology 23pp 18999 320

8306270143 Forwards schedule for submittal of info required for NRC review of PSAR Schedule covers submittal of revised security plan & addl CESSAR interface requirements. VAN BRUNT, E E Arizona Public Service Co ANPP 24126-WF0/ B3/06/20 KNIGHTON, O Licensing Branch 3 8pp 18988 001 24X Fiche 50-528, B3/06/20, B306270143

8306270146 NUREG/CR-2809 V04 AEROSOL RELEASE AND TRANSPORT PROGRAM QUARTERLY PROGRESS REPORT FOR OCTOBER-DECEMBER 1982. ADAMS, R E, TOBIAS, M L Argonne National Laboratory FIN B-0121 DRNL/TK-B397 B3/05/31 Division of Accident Evaluation 35pp 19021 142

8306270191 NUREG/CR-3156 A SURVEY OF STATE-OF-THE-ART IN AGING OF ELECTRONICS WITH APPLICATION TO NUCLEAR POWER PLANT INSTRUMENTATION. JOHNSON, R T, THOME, F J, CRAFT, C M Sandia Laboratories FIN A-1091 SAND82-2539 B3/05/31 Division of Engineering Technology 67pp, 19021 072

8306270197 NUREG/CR-1599 IODINE, KRYPTON AND XENON RETENTION EFFICIENCIES OF SILVER IMPREGNATED SILICA GEL MEDIA WITH DIFFERENT SILVER LOADINGS AND UNDER DIFFERENT TEST CONDITIONS. MOTES, B O, FERNANDEZ, S J, TKACHYK, J W Idaho National Engineering Laboratory, FIN A-6287, EN1CO-1049 B3/05/31, Division of Health, Biting & Waste Management 106pp 19020 329

8306270260 Forwards "Bounding Analytical Assessment of NUREG-0630 Models on LOCA W/Ft Limits." RODRIGUEZ, R J Sacramento Municipal Utility District RJR B3-505 B3/06/20 STOLZ, J F Operating Reactors Branch 4 2pp 18990 231 24X Fiche 50-312, B3/06/20, B306270260

8306270285 Clarifies capabilities of hydrogen ignition sys under all circumstances, per Schwencer B11106 ltr to NUREG/CR-2486 Under worst case conditions, min voltage required would be 10 0B volts. DALE, L F Mississippi Power & Light Co AECM-B3/03J9 B3/06/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18996 196 24X Fiche 50-416, B3/06/23, B306270285

8306270306 Response opposing State of NH B30526 objections to ASLB B30511 memorandum & order ruling on motions for summary disposition. No mods to ASLB conclusions warranted. Certificate of Svc encl. LESSY, R P, PATTERSON, W F Hearing Branch 3 ISSUANCES QL B3/06/22 Atomic Safety and Licensing Board Panel 11pp 18995 208 24X Fiche 50-443, B3/06/22, B306270306

8306270312 Forwards info re reactor vessel level instrumentation sys, in response to Generic Ltr B2-28 concerning inadequate core cooling instrumentation in-core thermocouple sys will be upgraded to NUREG-0737, Item II F 2 requirements. HERING, R F Indiana & Michigan Electric Co GL-B2-28 B3/06/22 EISENHUT, D G Division of Licensing 19pp 18993 353 24X Fiche 50-315, B3/06/22, B306270312

8306270322 Provides addl details re control of heavy loads during coast when new fuel assemblies being stored in spent fuel pit. Due to failure of reactor coolant pump at Byron 1, fuel handling bldg crane will be installed. TRAMM, T R Commonwealth Edison Co 6794N B3/06/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18994 073 24X Fiche 50-000, B3/06/17, B306270322

8306270360 Forwards addl info requested B30407 re containment pressure monitor, containment water level monitor & containment hydrogen monitors installed per requirements of IMI Items II F 1 4, II F 1 5 & II F 1 6, respectively. MAIER, J E Rochester Gas & Electric Corp B3/06/20 CRUTCHFIELD D Operating Reactors Branch 5 10pp 18993 176 24X Fiche 50-244, B3/06/20, B306270360

8306270368 Forwards responses to SER, suppl 4, Sections 13 3 2 2 h 13 3 2 3 (NUREG-0857), re courses of action necessary in unlikely event of emergency at facilities. Info will be included in Rev 3 to emergency plan. VAN BRUNT, E E Arizona Public Service Co ANPP-24103-WF0 B3/06/15 KNIGHTON, O Licensing Branch 3 26pp 18993 214 24X Fiche 50-528, B3/06/15, B306270368

8306270376 Submits addl info re Generic Ltr B1-03 concerning implementation of NUREG-0313, "Intergranular Stress Corrosion Cracking of Pressure Boundary Piping & Safe Ends" per B30415 request. Inservice insp program not appropriate. BORDINE, T C Consumers Power Co GL B1-03 B3/06/22 CRUTCHFIELD, D Operating Reactors Branch 5 5pp 18993 308 24X Fiche 50-155, B3/06/22, B306270376

8306270413 Advises that util does not object to Limerick Ecology Action position in B30610 ltr on contentions related to NUREG-0737. WETTERHAHN, M J Conner & Wetterhahn WETTERHAHN, M J Philadelphia Electric Co B3/06/23 BRENNER, L, MORRIS, P A, COLE, R F Atomic Safety and Licensing Board Panel 2pp 18994 146 24X Fiche 50-352, B3/06/23, B306270413

8306280013 NUREG/CR-3263 A COMPARISON OF METHODS FOR UNCERTAINTY ANALYSIS OF NUCLEAR POWER PLANT SAFETY SYSTEM FAULT TREE MODELS. MARTZ, H F, BECKMAN, R J, CAMPBELL, K Los Alamos Scientific Laboratory FIN A-7725 LA-9729-MS B3/06/30 Division of Risk Analysis 181pp 19044 101

8306280033 NUREG/CR-2607 FIRE PROTECTION RESEARCH PROGRAM FOR THE U S NUCLEAR REGULATORY COMMISSION 1975-1981. DURE, H Sandia Laboratories FIN A-1010 SAND82-0431 B3/06/30 Division of Engineering Technology 106pp 19042 087

8306280036 Forwards evaluation & request for addl info on responses to B21210 order re NUREG-0737, Item II F 2, "Detection of Inadequate Core Cooling." Clarification requested within 30 days. Digital indicators acceptable. STOLZ, J F Operating Reactors Branch 4 B3/06/14 HUXILL, H D General Public Utilities - GPU Service Corp Bpp 19042 348 24X Fiche 50-289, B3/06/14, B306280036

8306280044 NUREG/CR-2906 SENSITIVITY OF RISK PARAMETERS COMPONENT UNAVAILABILITY IN REACTOR SAFETY STUDY (PSAP/PSAB COMPUTER CODES). AZARM, M, FARAHZAD, P, TINGLE, A Brookhaven National Laboratory FIN A-3235 BNL-NUREG-51980 B3/05/31 Division of Risk Analysis 167pp 19044 284

NONDOCKETED ITEMS

43

8306280049 NUREG/CR-3163
RELAP5 ASSESSMENT LOFT SMALL BREAK L3-6/L8-1
KMEFYK, L N Sandia Laboratories FIN A-1205 SAND83-0245
03/06/30 Division of Accident Evaluation 94pp 19045 090

8306280080 NUREG/CR-2973
LOSS OF DNR SEQUENCES AT BROWNS FERRY UNIT ONE - ACCIDENT
SEQUENCE ANALYSIS
COOK, D H, GREENE, S R, HARRINGTON, R M Oak Ridge National
Laboratory FIN B-0452 ORNL/TM-8532 83/06/30 Division of
Accident Evaluation 180pp 19068 295 24X Fiche 50-259, 83/06/30,
8306280080

8306280085 NUREG/CR-3267
SIMILARITY ANALYSIS AND SCALING CRITERIA FOR LWR'S UNDER
SINGLE-PHASE AND TWO-PHASE NATURAL CIRCULATION
ISHIJ, M, KATACKA, I Argonne National Laboratory FIN A-2026
ANL-83-32 03/03/31 Division of Accident Evaluation 46pp
19069 283

8306280089 NUREG/CR-2789
PRESSURE VESSEL THERMAL SHOCK AT U S PRESSURIZED-WATER
REACTORS EVENTS AND PRECURSORS 1963-1981
PHUNG, D L Oak Ridge National Laboratory FIN B-0435
ORNL/NSIC-210 83/05/31 Division of Risk Analysis 251pp
19045 185

8306280093 NUREG/CR-2874 V03
HIGH-TEMPERATURE GAS-COOLED REACTOR SAFETY STUDIES FOR THE
DIVISION OF ACCIDENT EVALUATION QUARTERLY PROGRESS REPORT,
JULY 1 - SEPTEMBER 30, 1982
BALL, J C, CLAPP, N E, CONKLIN, J C Oak Ridge National Laboratory
FIN B-0122 ORNL/TM-8443/V3 83/06/30 Division of Accident
Evaluation 27pp 19069 331

8306280096 NUREG/CR-3292
ENVIRONMENTAL ASSISTED CRACKING IN LIGHT WATER REACTORS
Annual Report, October 1981 - September 1982
SHACK, W J, KASSNER, T F, KUPPERMAN, D S Argonne National
Laboratory FIN A-2212 ANL-83-27 83/06/30 Division of
Engineering Technology 101pp 19042 196

8306280137 Forwards IE Insp Rept 50-528/83-12 on 830424-29 & 0312 No
noncompliance noted
BODK, H C Region 5, Office of Director 83/06/03 ANDOGNINI, O C
Arizona Public Service Co 2pp 19014 333 24X
Fiche 50-528, 83/06/03, 8306280137

--8306280145 IE Insp Rept 50-528/83-12 on 830424-29 & 0312 No
noncompliance noted Major areas inspected followup on IE
info notices, organization & staffing, environ protection,
resolution 10CFR50 55(e) & NUREG-0737, Items II F 1 & II B 3
SHERMAN, C, NORTH, H B, WENSLAWSKI, F A Region 5, Office of
Director 83/06/03 16pp 19014 339 24X Fiche 50-528, 83/06/03,
8306280137

8306280138 Forwards "Control of Heavy Loads, Philadelphia Electric Co.
Peach Bottom Atomic Power Station, Units 2 & 3," draft
technical evaluation rept
BTOLZ, J F Operating Reactors Branch 4 83/06/14 BAUER, E O
Philadelphia Electric Co 2pp 19043 339 24X
Fiche 50-277, 83/06/14, 8306280138

--8306040324 TER-C5506-379/380
"Control of Heavy Loads, Peach Bottom Atomic Power Station,
Units 2 & 3," draft technical evaluation rept
BOMBERGER, C R Franklin Institute/Franklin Research Center
NRC-03-B1-130 1AC 08070 83/05/17 NRC - No Detailed
Affiliation Given 43pp 19043 361 24X Fiche 50-277, 83/06/14,
8306280138

8306280155 Informs that 830606 response to open item in integrated
plant SAR (NUREG-0822) re flooding elevation acceptably
resolves item Corrective actions re diesel generator 146g
enfranchises also acceptable
CRUTCHFIELD, D Operating Reactors Branch 5 1805-83-06-054
83/06/23 FIEDLER, P B General Public Utilities - GPU Service Corp
2pp 19014 316 24X Fiche 50-219, 83/06/23, 8306280155

8306280190 NUREG/CR-3185
CRITICAL REVIEW OF THE REACTOR SAFETY STUDY RADIOLOGICAL
HEALTH EFFECTS MODEL
COOPER, D W, JACOB, N, KASE, K R Harvard Univ FIN A-1042
BAND82-7081 83/05/31 180pp 19069 111

8306280197 Forwards safety evaluation of 1411 design review of TMI
Action Item II B 2 2, "Plant Shielding " Plant shielding
adequate to assure post-accident access to vital areas
CRUTCHFIELD, D Operating Reactors Branch 5 1805-83-06-034
83/06/27 LINDER, F Dairyland Power Cooperative 3pp 19015 074
24X Fiche 50-409, 83/06/27, 8306280197

8306280233 Forwards correct version of App A, "Mechanical Errors From
NUREG/CR-2337, Vol 1, Aquatic Impacts From Operation of Three
Midwestern Nuclear Power Plants " Draft version
inadvertently attached to 830606 submittal
JONES, W C Omaha Public Power District LIC-83-148 83/06/22
VOLLMER, R H Division of Engineering 10pp 19015 088 24X
Fiche 50-285, 83/06/22, 8306280233

8306280317 Submits required data to demonstrate that line voltage
regulators perform as acceptable isolation devices by
limiting primary current under short circuit conditions to
full-load primary current, per SER (NUREG-0857)
VAN BRUNT, E E Arizona Public Service Co ANPP-24155-JYB/
83/06/23 KNIGHTON, O Licensing Branch 3 1p 19001 282 24X
Fiche 50-528, 83/06/23, 8306280317

8306280321 Discusses impact of NUREG-0824, SER Topic III-4 B, "Turbine
Missiles," on control valve surveillance testing program No
changes to current testing program warranted Item closed,
COUNSIL, W O Northeast Nuclear Energy Co (subs of Northeast
Utilities) COUNSIL, W O Northeast Utilities 810819 83/06/22
CRUTCHFIELD, D Operating Reactors Branch 5 2pp 19001 312 24X
Fiche 50-245, 83/06/22, 8306280321

8306280371 Forwards IE Insp Rept 50-397/83-20 on 830516-20. No
noncompliance noted
STERNBERG, D M Region 5, Office of Director, 83/06/15,
CARLBLE, C S Washington Public Power Supply System, 2pp
19001 323 24X Fiche 50-397, 83/06/15, 8306280371

--8306280380 IE Insp Rept 50-397/83-20 on 830516-20 No noncompliance
noted Major areas inspected QA program, THI (NUREG-0737)
activities, including Confirmatory Issue 22 & Independent
Insp
WILLETT, D J, DODDS, R T Region 5, Office of Director IE8-79-05
83/06/15 7pp 19001 325 24X Fiche 50-397, 83/06/15, 8306280371

8306280386 Clarifies 830422 response to request for addl info re
NUREG-0737, Item II B 3, "Post-Accident Sampling Sys," per
NRC 830531 telcon in-core temp indicators not in use at
plant per Reg Guide 1.97 & Generic Ltr 82-33
PILANT, J M Nebraska Public Power District LQAB300161 83/06/21
VASSALLO, D B Operating Reactors Branch 2 2pp 19014 085 24X
Fiche 50-298, 83/06/21, 8306280386

8306280412 Forwards response to 830422 request for addl info re Rev 1
to NUREG-0313 concerning leakage detection sys
COUNSIL, W O Northeast Nuclear Energy Co (subs of Northeast
Utilities) COUNSIL, W O Northeast Utilities A03200 83/06/21,
CRUTCHFIELD, D Operating Reactors Branch 5 93pp 19020 188 24X
Fiche 50-245, 83/06/21, 8306280412

8306280415 Suppls B21220 response to NUREG-0313 request for addl info
Ferrite content of cast austenitic stainless steel ranges
from 15 to 20% Valves highly resistant to intergranular
stress corrosion cracking
MILLER, L M Tennessee Valley Authority 83/06/22 DENTON, H R
Office of Nuclear Reactor Regulation, Director, 2pp 19018 351
24X Fiche 50-259, 83/06/22, 8306280415

8306280436 Forwards Amend 1 to environ qualification rept, per 830314
request & NUREG-0588 requirements
VAN BRUNT, E E Arizona Public Service Co ANPP-24107-WFG/
83/06/24 KNIGHTON, O Licensing Branch 3 120pp 19016 297 24X
Fiche 50-320, 83/06/24, 8306280436

8306280442 Advises that, based on review of 801219 submittal re
NUREG-0737, Item II K 3 21, "Restart of Core Spray & LPCI
Sys," issue resolved
CRUTCHFIELD, D Operating Reactors Branch 5 1805-83-06-056
83/06/27 VANDEWALLE, D J Consumers Power Co 4pp 19020 184,
24X Fiche 50-155, 83/06/27, 8306280442

8306280444 Requests 60-day extension for responding to 830511 request
for addl info re NUREG-0737, Item II K 3 28, "Qualification
of Automatic Depressurization Sys Accumulators " Extension
due to personnel changes & addl time needed by AE
PILANT, J M Nebraska Public Power District, LQAB300163 83/06/21,
VASSALLO, D B Operating Reactors Branch 2 2pp 19020 176 24X
Fiche 50-298, 83/06/21, 8306280444

8306280445 Forwards General Physics Corp evaluation results of items
in corporate scope of review info should be sufficient to
close SER open items
SMITH, J L Long Island Lighting Co 8NRC-912 83/06/23,
DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp
19020 178 24X Fiche, 50-322, 83/06/23, 8306280445

NONDOCKETED ITEMS

8306280459 Informs that operational data for completion of HEPA filtration sys extended to 831001 due to difficulty in adopting ventilation sys to accommodate demands of HEPA filtration per Suppl 1 to NUREG-0737
MUSOLF, D. Northern States Power Co 83/06/20 Office of Nuclear Reactor Regulation, Director 1p 19018 328 24X
Fiche 50-000, 83/06/20, 8306280459

8306280478 Provides info re SEP Topic VI-4, "Containment Isolation Sys." to resolve concern raised by NUREG-0824, "Integrated Plant Safety Assessment," for which NRC unable to determine adequacy of penetrations X-211A & X-204
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 810816 83/06/22 CRUTCHFIELD, D Operating Reactors Branch 3 2pp 19018 313 24X
Fiche 50-245, 83/06/22, 8306280478

8306280487 Discusses problems w/post-accident sampling sys (PASS) microprocessor, on-line pH meter sample flow & ion chromatograph Proposed PASS completion per NUREG-0737, Item II B 3, scheduled for 830930
JONES, W C Omaha Public Power District LLC-83-147 83/06/23 CLARK, R A Operating Reactors Branch 3 3pp 19019 186 24X
Fiche 50-285, 83/06/23, 8306280487

8306280489 Lists commitments to implement addl monitoring & restrictive limits on unidentified RCS leakage per NUREG-0313, Rev 1, in response to IE Bulletin 83-02 Plans to be submitted to NRC 3 months prior to next refueling outage
HOME, P W Carolina Power & Light Co IEB-83-02 83/06/24, VASSALLO, D B Operating Reactors Branch 2 2pp 19018 311 24X
Fiche 50-325, 83/06/24, 8306280489

8306280502 Forwards supplemental response to EG&O, Phase I, Apr 1983 rept re NUREG-0612, "Control of Heavy Loads," reflecting areas of concern addressed during 830614 telcon
SWARTZ, E D Commonwealth Edison Co 6773N. 83/06/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 24pp 19019 236 24X
Fiche 50-373, 83/06/22, 8306280502

8306280508 Forwards addl info re compliance w/NUREG-0737, Items II F 1 4, "Containment Pressure Monitor" & II F 1 5, "Containment Water Level Monitor," per 830408 commitment
BAYNE, J P Power Authority of the State of New York JPN-83-58 83/06/23 VASSALLO, D B Operating Reactors Branch 2 7pp 19017 288 24X
Fiche 50-333, 83/06/23, 8306280508

8306280524 Supplemental application for amend to Licenses DPR-71 & DPR-62, revising Tech Specs re RCIC sys actuation instrumentation per Generic Ltr 83-02 & NUREG-0737 Items
HOME, P W Carolina Power & Light Co LAP-83-227 83/06/23 VASSALLO, D B Operating Reactors Branch 2 4pp 19019 290, 24X
Fiche 50-324, 83/06/23, 8306280524

--8306280544 Revised Tech Specs re RCIC sys actuation instrumentation
* Carolina Power & Light Co GL-83-02 83/06/23 21pp 19019 294 24X
Fiche 50-324, 83/06/23, 8306280544

8306280559 Forwards documents to assist w/evaluation of 830601 submittal re integrated assessment of open issues Results of primary coolant sys safety relief valve test, in response to NUREG-0737, Item II D 1, provided in util 811001 ltr w/o encl
BLANCHARD, D P Carolina Power & Light Co 83/06/20 RUBIN, M NRC - No Detailed Affiliation Given 4pp 19017 310 24X
Fiche 50-155, 83/06/20, 8306280559

8306280583 Forwards, per request, Reg Guide 1.70 & NUREG-0800, Sections 2.3.1, w/o encls
PERLIS, R O Hearing Branch 3 83/06/27 BERNICK, B Texas, State of 1p. 19017 324 24X
Fiche 50-498, 83/06/27, 8306280583

8306280585 Responds to Generic Ltr 82-33 (NUREG-0737, Suppl 1) re requirements for emergency response capability Proposed completion dates encl
TAUBER, H Detroit Edison Co EFR - 62,262 83/06/23 YOUNGBLOOD, B J Licensing Branch 1 2pp 19018 026 24X
Fiche 50-341, 83/06/23, 8306280585

8306290082 Forwards negative declaration & EIA (NUREG-0994) re renewal of License BNM-696 w/o EIA
PAOE, R O Uranium Fuel Licensing Branch 83/06/21 HOWRY, W R OA Technologies, Inc./General Atomic Co 1p 19046 167

8306290131 NUREG/BR-0051 V04 N7
POWER REACTOR EVENTS November-December 1982
MARBARD, S A, TRENER, B E Director's Office 83/06/30 35pp 19046 186

8306290146 Informs that util response to NUREG-0737, Items II F 1 4, II F 1 5 & II F 1 6 acceptable re installation of containment pressure, water level & hydrogen monitoring sys
SER encl
CLARK, R A Operating Reactors Branch 3 83/06/21 FAY, C W Wisconsin Electric Power Co 8pp 19046 298 24X
Fiche 50-266, 83/06/21, 8306290146

8306290158 Forwards safety evaluation concluding that requirements of TMI Items II F 1 4, II F 1 5 & II F 1 6 re containment pressure, water level & hydrogen monitors met Items resolved
CLARK, R A Operating Reactors Branch 3 83/06/17 JONES, W C Omaha Public Power District 9pp 19046 271 24X
Fiche 50-285, 83/06/17, 8306290158

8306290190 Requests proposed Tech Specs re limiting overtime for staff personnel which comply w/guidelines furnished in 820615 ltr Proposal dtd 830121 unacceptable
CLARK, R A Operating Reactors Branch 3 83/06/21 GARRITY, J H Maine Yankee Atomic Power Co 3pp 19046 287 24X
Fiche 50-309, 83/06/21, 8306290190

8306290241 Forwards safety evaluation conditionally approving licensee 830310 request from relief from Generic Ltr 82-28 & NUREG-0737, Item II F 2 requirements to install reactor vessel level sys Addl info needed within 30 days
CRUTCHFIELD, D Operating Reactors Branch 5 LS05-83-06-05B 83/06/27 KAY, J A Yankee Atomic Electric Co 11pp 19056 247 24X
Fiche 50-029, 83/06/27, 8306290241

8306290249 Advises that methodology used to calculate beta dose for radiation profile for equipment qualification not acceptable Resubmittal of beta analysis based upon methodology in NUREG-058B required by 830630
CLARK, R A Operating Reactors Branch 3 83/06/17 UHRIG, R E Florida Power & Light Co 2pp 19046 116 24X
Fiche 50-335, 83/06/17, 8306290249

8306290311 Forwards final seismic input for SEP Topic III-6, "Seismic Design Considerations" NUREG-0825 conclusions valid based on conservative structural analysis methods & linear elastic analysis
CRUTCHFIELD, D Operating Reactors Branch 5 LS05-83-06-047 83/06/22 KAY, J A Yankee Atomic Electric Co 35pp 19055 316 24X
Fiche 50-029, 83/06/22, 8306290311

8306290323 Forwards safety evaluation of proposed resolution of classification of structures, sys & components issue in Section 4.5 of integrated plant safety assessment rept (NUREG-0820) info acceptable to resolve open items
WAMBACH, T Operating Reactors Branch 5 LS05-83-06-055 83/06/27 VANDEWALLE, D J Consumers Power Co 7pp 19055 306 24X
Fiche 50-255, 83/06/27, 8306290323

8306290377 Forwards IE Insp Rept 50-302/83-15 on 830502-06 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/05/27 WILCOX, W S Florida Power Corp 2pp 19055 192 24X
Fiche 50-302, 83/05/27, 8306290377

--8306290380 IE Insp Rept 50-302/83-15 on 830502-06 No noncompliance noted Major areas inspected refueling outage radiation protection organization, procedures, advanced planning (ALARA), exposure control & respiratory protection program
KAHLE, J B Region 2, Office of Director DARR, K P Division of Engineering & Radiological Safety Programs 83/05/26 8pp 19055 194 24X
Fiche 50-302, 83/05/27, 8306290377

8306290400 Application to amend Licenses DPR-33, DPR-52 & DPR-68, changing Tech Specs to require annual rept of main steam safety/relief valve actuations, in response to NUREG-0737, Item II K 3 3 & Generic Ltr 83-02
HILLS, L M Tennessee Valley Authority GL-83-02 83/06/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 19053 133 24X
Fiche 50-259, 83/06/20, 8306290400

--8306290408 Proposed Tech Spec revs, requiring annual rept of main/steam safety/relief valve actuations, in response to NUREG-0737, Item II K 3 3 & Generic Ltr 83-02
* Tennessee Valley Authority GL-83-02 83/06/20 3pp 19053 133 24X
Fiche 50-259, 83/06/20, 8306290400

8306290406 Forwards safety evaluation of licensee compliance w/NUREG-0737, Item II B 1, "RCS Vents," based on review of encl LLL technical evaluation rept High point vents on primary coolant side of isolation condenser not required
CRUTCHFIELD, D Operating Reactors Branch 5 LS05-83-06-037 83/06/27 COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 6pp 19053 140 24X
Fiche 50-245, 83/06/27, 8306290406

NONDOCKETED ITEMS

441

--8306290413 TF-382/0823A

"Selected Operating Reactor Issues Program (I RCS Vents
NUREG 0737, Item II B 1), " Final technical evaluation rept
HELD, J T Energy Incorporated * Lawrence Livermore Laboratory
FIN A-0250 TAC 44384 83/04/06 ALBERTHAL, G Division of
Licensing App 19093 146 24X Fiche 50-245, 83/06/27, 8306290406

8306290538 Requests methodology & acceptance criteria to be used in
evaluating anchorage of 4,160-volt switchgear panels by
831130 Review will be included in integrated plant
SAR suppl
CRUTCHFIELD, D Operating Reactors Branch 5 L505-83-06-053
83/06/24 FIEDLER, P B General Public Utilities - GPU Service Corp
2pp 19093 029 24X Fiche 50-217, 83/06/24, 8306290538

8306300120 Comments on NRC plan for evaluating safety goals Environ &
geological effects missing from design objective
SACHNOFF, S WILLHOITE, D League of Women Voters 18FR10772 020
83/06/27 Office of the Secretary of the Commission 5pp
19120 008

8306300131 Comments on NRC safety goal development program Vendor
generally agrees w/safety goals
SHERWOOD, G O General Electric Co 48FR10772 021 83/06/20
Docketing & Services Branch 2pp 19122 331

8306300133 forwards draft revised response to TMI Item I O 1, "Training
During Low-Power Testing," per 830627 conference call info
contained in draft revised response will be incorporated
into FSAR rev scheduled for Aug 1983
BRADLEY, F J Philadelphia Electric Co 83/06/28 SCHWENCER, A
Licensing Branch 2 5pp 19122 311 24X Fiche 50-352, 83/06/28,
8306300133

8306300138 Forwards SER Suppl 2, (NUREG-0881) W/o encl
KARMAH, M Hearing Branch 1 ISSUANCES OL 83/06/28
LAURENSON, J A, PAXTON, H C, ANDERSON, G C Atomic Safety and
Licensing Board Panel 1p 19168 118 24X Fiche 50-482, 83/06/28,
8306300138

8306300140 Informs that addl nondegree personnel will be assigned to
shift technical advisor position per NUREG-0737, Item
I A 1 Info re experience, college educ & current operator
licenses encl
COUNSIL, W O Northeast Nuclear Energy Co (subs of Northeast
Utilities) COUNSIL, W O Northeast Utilities R108P3 83/06/22
CRUTCHFIELD, D Operating Reactors Branch 5 CLARK, R A Operating
Reactors Branch 3 3pp 19122 320 24X Fiche 50-245, 83/06/22,
8306300140

8306300146 Comments on safety goals policy statement & evaluation plan
Supports plan
WINCK, W European Communities, Commission of 48FR10772 018
83/06/10 LAFLEUR, J D Office of International Programs, Director
18pp 19117 321

8306300166 Forwards supplemental description of CE Owners Group program
& schedule in response to Generic Ltr 83/10A re guidance
for closing out NUREG-0737, Item II K 3 5, "Automatic Trip
of Reactor Coolant Pumps"
DRAUMOND, F J Louisiana Power & Light Co W3P83-2115 83/06/27
KNIGHTON, O H Licensing Branch 3 4pp 19119 2/3 24X
Fiche 50-382, 83/06/27, 8306300166

8306300172 Comments on NRC safety goal evaluation plan Supports plan
QFI BY, E V Gilby Associates 48FR10772 022 83/04/16 DIRCKS, W J
Office of the Executive Director for Operations 6pp 19168 111

8306300173 Comments on plan to evaluate Commission safety goal policy
statement NRC should provide periodic updates of plant
analyses
HICENBURG, M R Houston Lighting & Power Co 48FR10772 019
83/06/22 CHILK, S J Office of the Secretary of the Commission
2pp 19168 109

8306300213 Responds to 820/30 ltr re emergency preparedness appraisal
rept & 820630 notice of violation Adequate performance
demonstrated during 821021 exercise Exam of
representation of facts in progress
KEPPLER, J O Region 3, Office of Director 01 82-33 83/06/09
DOLAN, J C American Electric Power Service Corp 3pp 19122 101
24X Fiche 50 315, 83/06/09, 8306300213

8306300226 Forwards IE Insp Rept 50-409/83-07 on 830516-18 No noncompliance noted
PAPERIELLO, C J Region 3, Office of Director 83/06/14
LINDER, F W Dairyland Power Cooperative 2pp 19119 173 24X
Fiche 50-409, 83/06/14, 8306300226

--8306300231 IE Insp Rept 50-409/83-07 on 830516-18 No noncompliance
noted Major areas inspected status of post-TMI
requirements
PAUL, R A, GREGER, L R Region 3, Office of Director 83/06/14
3pp 19119 173 24X Fiche 50-409, 83/06/14, 8306300226

8306300241 Forwards diagram depicting proposed location of new
training ctr per Suppl 1 to NUREG-0737 Ctr will house new
emergency operations facility & is tentatively scheduled for
completion in Spring 1984
MANOAN, C V Niagara Mohawk Power Corp 83/06/24 VASSBALLO, D B
Operating Reactors Branch 2 2pp 19122 309 24X
Fiche 50-220, 83/06/24, 8306300241

8306300251 Forwards IE Insp Rept 50-346/83-14 on 830524-26 No
noncompliance noted
LITTLE, W S Region 3, Office of Director 83/06/17 CROUBE, R P
Toledo Edison Co 2pp 19119 343 24X Fiche 50-346, 83/06/17,
8306300251

--8306300252 IE Insp Rept 50-346/83-14 on 830524-26 No noncompliance
noted Major areas inspected licensee action on previous insp
findings
MENDEZ, R, WILLIAMS, C C Region 3, Office of Director 83/06/17
3pp 19119 343 24X Fiche 50-346, 83/06/17, 8306300251

ORG CORRESPONDENCE WITH OTHER ORGANIZATIONS

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in
Well Logging Device " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post
830103) 83/05/26 Consolidated Edison Co of New York, Inc
125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New
York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods
Withdrawn at BWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/31 Consolidated Edison Co of New
York, Inc 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe
Operations " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/09 Consolidated Edison Co of New
York, Inc 117pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive &
Seismically Induced Chatter in Relays Within Printed
Circuit Cards " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/13 Consolidated Edison Co of New
York, Inc 118pp 18920 225 24X Fiche 50-000, 83/06/13, 8305110470

8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
Epoxy Grouts & Sealers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New
York, Inc 119pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475

8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys
Causing Inoperability of Safety-Related Equipment " Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/22 Consolidated Edison Co of New
York, Inc 120pp 18977 007 24X Fiche 50-000, 83/06/22, 8305110477

8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/23 Consolidated Edison Co of New
York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479

8305110487 IE Info Notice 83-43, "Improper Settings of Intermediate
Range (IR) High Flux Trip Setpoints " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/06/24 Consolidated Edison Co of New
York, Inc 116pp 19046 277 24X Fiche 50-000, 83/06/24, 8305110483

8306010241 Provides addl info re Yakima Indian Nation, per verbal
request State of WA utilities law enforcement teletype sys
to notify contiguous counties of event w/potential offsite
consequences Yakima County would notify tribal police
DONOVAN, R W Federal Emergency Management Agency 83/05/19
AULUCK, R Licensing Branch 2 1pp 18673 009 24X
Fiche 50-377, 83/05/19, 8306010241

NONDOCKETED ITEMS

8306070233 "Zion Nuclear Generating Station," second evaluation
* Institute of Nuclear Power Operations 83/04/30 38pp
18741 117 24X Fiche 50-295,83/04/30,8306070233

8306070475 Responds to approval request for info collection re generic
clearance of IE bulletin, "Failure of Reactor Trip Breakers
(Hestingshouse DB-30) to Open on Automatic Trip Signal"
Request approved through 830430 under OMB Number 3150-0012
SCURRY, N Office of Management & Budget OMB 3150-0012 83/03/26
SCOTT, S Document Management Branch 2pp 18776 333

8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From
Degraded Internal Connection Cables" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/13 Consolidated Edison Co of New
York, Inc 243pp 18921 001 24X Fiche 50-000,83/06/13,8306090010

8306090114 Forwards consolidated Regional Assistance Committee comments
for five unrated planning elements Comments should be part
of initial FEMA findings & determination of effectiveness of
offsite emergency planning
MCLUGHLIN, D Federal Emergency Management Agency 83/05/18
DIRCKS, W J Office of the Executive Director for Operations 5pp
18793 324 24X Fiche 50-329,83/05/18,8306090114

8306090118 Advises of approval of emergency response plan for facility,
subj to verification of adequacy of public alerting &
notification sys
MCLUGHLIN, D Federal Emergency Management Agency 83/05/16
DIRCKS, W J Office of the Executive Director for Operations 1p
18793 329 24X Fiche 50-155,83/05/16,8306090118

8306090229 Approves State of MI emergency response plan & associated
local plans w/condition that adequacy of public alerting &
notification sys be verified per FEMA/NRC joint criteria
listed in NUREG-0654/FEMA-REP-1, Rev 1, App 3
PAPERILL, C J Region 3, Office of Director 83/06/06
DEWITT, R B Consumers Power Co 2pp 18796 235 24X
Fiche 50-155,83/06/06,8306090229

8306130294 Forwards FEMA final exercise evaluations of offsite
emergency preparedness exercise conducted on 810729, 1007
& 830118 No major exercise deficiencies noted
HIND, J A Region 3, Office of Director 83/06/09 RCED, C
Commonwealth Edison Co 2pp 18823 334 24X Fiche 50-295,83/06/09,
8306130294

8306130081 NUREG/CP-0044 V02
PROCEEDINGS OF THE INTERNATIONAL ATOMIC ENERGY AGENCY
SPECIALISTS' MEETING ON SUBCRITICAL CRACK GROWTH Sessions
VII, IV And V Held At Freiburg, Federal Republic Of Germany,
May 13-15, 1981
CULLEN, W H Materials Engineering Associates, Inc * ENSA, Inc
FIN B-8133 MEA-2014 83/05/31 Division of Engineering
Technology 434pp Available at NRC \$9 00 18870 097

8306150263 Forwards State of ME plans to correct emergency preparedness
deficiencies identified by FEMA, per 830311 site meeting
Addl info on radiological exposure control will be submitted
to FEMA within 1 wk
GARRITY, J H Maine Yankee Atomic Power Co MN-83-118 83/06/06
ALLAN, J M Region 1, Office of Director 15pp 18849 176 24X
Fiche 50-309,83/06/06,8306150263

8306160093 Addl response to FOIA request for documents re IAEA nuclear
matl safeguards program Forwards App A documents App B
Documents 1-B entirely withheld & Documents 9-16 partially
withheld (ref FOIA Exemptions 1,3 & 5)
FELTON, J M Division of Rules and Records 83/04/01
GREENBERG, E V Tuttle & Taylor 5pp 18892 011

--8306160107 Forwards suggested questions & answers for 811202 hearing re
IAEA safeguards, per request
SHEA, J R Office of International Programs, Director 81/12/01
GILINSKY, V Commissioners 7pp 18892 018

--8306160115 Draft Commission paper proposing ltr from Chairman thanking
TE Shea for suggestions on improving IAEA safeguards &
informing Commission that TE Shea ltr sent to State Dept
DIRCKS, W J Office of the Executive Director for Operations
82/01/27, 16pp 18892 026

--8306160118 Forwards undisputed portion of response to 811215 ltr re
IAEA safeguards sys, supplementing Commission 820302 ltr
BRADFORD, P A Commissioners 82/03/04 OTTINGER, R L House of
Rep, Energy & Commerce HART, G Senate DINGELL, J D House of
Rep. 2pp. 18892 042

--8306160129 Forwards G Hart, MB Kratzer & Scheinman, P Leventhal &
HD Sokolski testimonies & prepared statements at 810303
joint hearing of Committee on Foreign Affairs re IAEA
safeguards
KAMMERER, C Office of Congressional Affairs 82/03/04
PALLADINO, N J, GILINSKY, V, BRADFORD, P A Commissioners 4pp
18892 044

--8306160131 Testimony of G Hart before Subcommittee on Intl Economic
Policy & Trade, Committee on Foreign Affairs, US House of
Representatives re IAEA safeguards Committee 820301 revised
meeting notice encl
HART, G Senate 82/03/03 4pp 18892 048

--8306160134 Statement of MB Kratzer before Subcommittees on Intl
Security & Scientific Affairs & Intl Economic Policy &
Trade, Committee on Foreign Affairs, US House of
Representatives re IAEA safeguards
KRATZER, M B International Energy Associates, Ltd 82/03/03
33pp 18892 052

--8306160138 Prepared statement of L Scheinman before Subcommittee on
Intl Economic Policy & Trade, Committee on Foreign Affairs,
US House of Representatives re IAEA safeguards
SCHEINMAN, L Cornell Univ 82/03/03 17pp 18892 087

--830616014J Testimony of P Leventhal before Committee on Foreign
Relations, US House of Representatives re IAEA safeguards
LEVENTHAL, P Nuclear Club, Inc, The 82/07/03 10pp
18892 110

--8306160148 Prepared Statement of HD Sokolski before Subcommittee on
Intl Security & Scientific Affairs & Subcommittee on Intl
Economic Policy & Trade, Committee on Foreign Affairs, US
House of Representatives re IAEA safeguards
SOKOLSKI, H D Heritage Foundation 82/03/03 10pp 18892 120

--8306160153 Responds to 820420 ltr re IAEA safeguards NRC actively
examining effective ways & means to continue support for
IAEA safeguards
PALLADINO, N J Commissioners 82/06/10 BLIX, H International
Atomic Energy Agency (Austria) 1p 18892 130

--8306160156 Forwards summary of IAEA safeguards sys US support for IAEA
safeguards crucially important
BLIX, H International Atomic Energy Agency (Austria) 82/04/20
PALLADINO, N J Commissioners 4pp 18892 131

--8306160190 Forwards revised draft safeguards analysis for Romania for
transmission to State Dept No sensitive foreign intelligence
info employed w/o encl Partially deleted answers & questions
re IAEA safeguards encl
BURNETT, R F Division of Safeguards 82/07/15 SHEA, J R Office
of International Programs, Director 3pp 18892 141

--8306160193 SECY-82-025
Forwards H Gruemm preliminary comments on Morgan memo re
IAEA safeguards for 811119 press conference GILCY title &
other safeguards info deleted
DIRCKS, W J Office of the Executive Director for Operations
82/01/19 8pp 18892 146

--8306160198 SECY-82 046
Informs Commission of existing interagency groups involved
in US efforts to upgrade IAEA safeguards & provides brief
rept on status of activities w/o encl outline & status of
action plan
DIRCKS, W J Office of the Executive Director for Operations
82/02/02 13pp 18892 154

--8306160203 Discusses implications of R Richter testimony before Senate
Foreign Relations Committee & House Foreign Affairs
Committee re Iraqi nuclear program & weaknesses in IAEA
safeguards Safeguards info deleted
DIRCKS, W J Office of the Executive Director for Operations
82/03/09 BRADFORD, P A Commissioners 3pp 18892 167

--8306160208 SECY-82-210
Forwards summary of significant NRC & Executive Branch
efforts to improve IAEA safeguards & estimate of expended
resources Safeguards info deleted w/o encl rept on US
assistance to IAEA & outline of areas needing improvements
DIRCKS, W J Office of the Executive Director for Operations
82/05/26 17pp 18892 170

--8306160211 Forwards partially released transcript of 820602 briefing on
efforts to improve IAEA safeguards in Washington, DC Withhold
portions per 10CFR99.104(a)(1) listed
CHILK, S J Office of the Secretary of the Commission 82/08/03
Office of the Secretary of the Commission 2pp 18892 187

NONDOCKETED ITEMS

443

--8306160222 Draft Commission paper recommending Commission approval of proposed responses to Senator Hain & Representatives Dingell & Ottinger 8/11/25 & 30 ltrs re IAEA safeguards Safeguards info deleted w/o encl proposed ltrs
BIRKENS,W J Office of the Executive Director for Operations
8/12/31 1p 18892 284

8306170396 Forwards FEMA 830608 ltr to NRC providing current evaluation of plant offsite emergency planning
HASSELL,D F Hearing Branch 2 ISSUANCES SP 83/06/09
GLEASON,J P Atomic Safety and Licensing Board Panel 46pp
18979 333 24X Fiche 50-247 83/06/09,8306170396

8306220245 NUREG/CP-0043 ERR
PROCEEDINGS OF THE JOINT NRC/ANS MELTING ON BASIC THERMAL HYDRAULIC MECHANISMS IN LWR ANALYSIS Held At Bethesda Maryland, September 14-15, 1982
American Nuclear Society 83/06/02 Office of Nuclear Regulatory Research, Director 43pp 18991 0/3

8306230523 Discusses ATF proposal detailing info in one-step license application proposal in form of rewrite of Reg Guide 1.70, "Std Format & Content of SARs for Nuclear Power Plants" will illustrate level of design detail required
BIRKENS,W J Office of the Executive Director for Operations
830311 83/06/16 CHILK,S J Office of the Secretary of the Commission 1p 18751 356

8306240308 Forwards "1982 Trojan Nuclear Power Plant Exercise" based on 821118 exercise State & local plans & preparedness adequate
WRIGHT,R W Federal Emergency Management Agency 83/05/18
JORDAN,F L Division of Emergency Preparedness & Engineering Response (Post 830103) 1p 18979 0/5 24X fiche 50-344,83/05/18, 8306240308

--8306240310 "1982 Trojan Nuclear Power Plant Exercise"
Federal Emergency Management Agency 82/12/10 80pp
18979 076 24X Fiche 50-344,83/05/18,8306240308

8306270309 Forwards ANL rept, "Element-By-Element Review of LILCO Transition Module of Shoreham Nuclear Power Station Offsite Radiological Emergency Response Plan," in response to 830601 request
WRIGHT,R W Federal Emergency Management Agency 83/06/23
JORDAN,F L Division of Emergency Preparedness & Engineering Response (Post 830103) 2pp 18975 264 24X Fiche 50-322,83/06/23, 8306270309

8306280506 Forwards FFMA 830623 findings on util transition plan for offsite emergency preparedness
REPMAN,D A Hearing Branch 3 83/06/24 LAURENSEN,J A,
LIVINGTON,H S, KLINE,J R Atomic Safety and Licensing Board Panel 22pp 19017 212 24X Fiche 50-322,83/06/24,8306280506

FR PROPOSED RULE

8306300423 Comments on proposed rules 10CFR2 & 50 re granting temporary OLs Commission should not utilize temporary OL as mechanism to avoid rapid & expeditious issuance of full-term OL
PARKYN,J D Affiliation Unknown 48FR14926 001 83/04/19
Docketing & Services Branch 1p 18306 264

8306050091 Responds to 830415 request for acceptance of proposed IER rulemaking package 10CFR50 73 Concurrence submitted on 830216 Certification of acceptable NPPRB performance before rule becomes effective recommended
DENTON,H R Office of Nuclear Reactor Regulation, Director
83/05/20 HEITMES,C J Director's Office 3pp 18696 073

--8306020555 Forwards draft Commission paper forwarding final 10CFR50 73 "LER Sys," incorporating comments from previous review Requests concurrence on Commission paper by 830423 for submission to Commission no later than 830430
HEITMES,C J Director's Office 83/04/15 DENTON,H R Office of Nuclear Reactor Regulation, Director 7pp 18696 076

8306020424 Comments on proposed rule re NRC policy statement on regionalization Power reactor licensing should not be candidate for transfer
STEWART,W L Virginia Electric & Power Co 48FR12619 060
83/05/20 Docketing & Services Branch 2pp 18694 123

8306020449 Package of three comments on proposed rule re NRC policy statement on regionalization
FARRAR,B L Commonwealth Edison Co MAIER,J E Rochester Gas & Electric Corp COUNCIL,W G Northeast Utilities 48FR12619
83/05/23 Docketing & Services Branch 10pp 18693 338

8306020451 Package of four comments opposing proposed rule re NRC policy statement on regionalization
JENKS,L L Affiliation Unknown PATTON,S D Three Mile Island Alert NILSON,R Exxon Nuclear Co, Inc (subs of Exxon Corp)
48FR12619 83/05/13 Office of the Secretary of the Commission 7pp 18693 294

8306060226 Package of two comments opposing proposed rule 10CFR20 re elimination of licensee judgment in reporting theft or loss of licensed matl
WRIGHT,D J Geisinger Medical Center Danville,PA SCHIAGER,K J Utah, Univ of 48FR20721 83/05/23 Docketing & Services Branch 2pp 18727 254

8306060228 Advises recipients of comments on proposed rule 10CFR30 re group licensing for certain medical uses that Comment 12 was misused & will not be used again
Docketing & Services Branch 48FR13189 83/06/01 Docketing & Services Branch 1p 18728 291

8306060229 Comments on proposed rule re planned studies of QA programs for const of nuclear power plants Existing regulatory framework should not be encumbered by mandating addl layers of overview or prescriptive criteria
KEARNEY,J J Edison Electric Institute 48FR9106 032 83/05/20
CHILK,S J Office of the Secretary of the Commission 2pp 18727 252

8306060231 Package of two comments supporting proposed rules 10CFR2 & 50 re issuing temporary OLs
COTTER,W D New York, State of KUBINAK,R A Long Island Lighting Co 48FR14926 83/05/23 Docketing & Services Branch 4pp 18728 292

8306060233 Comments on proposed rule 10CFR50 re significant hazards considerations & on state notice & consultation Supports rule
COTTER,W D New York, State of 48FR14864 020 83/05/16 Office of the Secretary of the Commission 2pp 18728 296

8306060249 Comments on proposed rule re QA programs for const of nuclear power plants Supports rule Recommends comprehensive & frequent NRC or NRC-contracted audits of licensee QA programs recommended
BULLOCK,S V Affiliation Unknown 48FR9106 033 83/05/26
Docketing & Services Branch 2pp 18727 233

8306080268 Responds to FOIA request for SECY-83-22 Forwards publicly available portions of paper per telcon w/N Toms
FELTON,J M Division of Rules and Records 83/04/11 KNIGHT,N L General Physics Corp 1p 18787 240

--8306080270 "Statement of policy Further Commission Guidance on Emergency Response Capability," draft 10CFR50 effective rule Suppl issued to NUREG-0737, "Clarification of TMI Action Plan Requirements"
CHILK,S J Office of the Secretary of the Commission 83/04/11 3pp 18787 241

8306140712 Concurs w/830510 memo re insider safeguards rule package, subj to appropriate consideration of comments Encl comments also address concerns contained in RF Burnett 830416 memo re protection of vital areas/islands
DENTON,H R Office of Nuclear Reactor Regulation, Director 83/06/01 DAVIS,J O Office of Nuclear Material Safety & Safeguards, Director 3pp 18852 274

--8306140718 Forwards revised insider safeguards rule package containing encl action plan to implement recommendations of Committee to Review Safeguards Requirements at Power Reactors Concurrence requested by 830527
DAVIS,J O Office of Nuclear Material Safety & Safeguards, Director 83/05/10 DENTON,H R Office of Nuclear Reactor Regulation, Director CUNNINGHAM,G H Office of the Executive Legal Director MINOUE,R B Office of Nuclear Regulatory Research, Director 196pp 18852 279

8306160201 Comments on proposed rule 10CFR50 re Tech Specs for nuclear power plants Tech Spec rulemaking should be reopened in light of restrictive interpretation to utils w/STB
DAUSER,M A Lowenstein, Newman, Reis, Axelrad & Toll 48FR14864 021 83/06/09 Docketing & Services Branch 4pp 18862 001

8306160245 Advises recipients of comments on proposed rule 10CFR50 re stds for determining whether license amend involves no significant hazards considerations that two comments marked 18 received SF Flynn comment will be 18A
Docketing & Services Branch 48FR14864 83/06/13 Docketing & Services Branch 1p 18861 225

NONDOCKETED ITEMS

- 8306160334 Comments on proposed rule 10CFR50 re NRC policy statement on severe accidents & related views on reactor regulation Supports statement
REED, C Atomic Industrial Forum 48FR16014 002 83/06/07
Docketing & Services Branch 2pp 18860 090
- 8306160337 Comments on proposed rule 10CFR50 re NRC policy statement on severe accidents & proposed rule re safety goals development program UCS comments on proposed rules will be consolidated & filed in early Jul
CURRAN, D Harmon & Weiss 48FR16014 001 83/06/08 STUCKY, S
Docketing & Services Branch 1p 18860 124
- 8306160467 Comments on proposed rule re planned studies of QA programs for const of nuclear power plants Present QA requirements adequate, but commitment, implementation & timeliness need addl emphasis
WEINMAN, S American Society of Mechanical Engineers 48FR9106 034 83/06/01
Docketing & Services Branch 3pp 18863 108
- 8306220285 Forwards results of Divs of Licensing, Sys Integration & Human Factors Safety review of insider safeguards rule package & rept by Committee to Review Safeguards Requirements at Power Reactors w/o encl
EISENHUT, D G Division of Licensing 83/05/31 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 18940 351
- 8306230323 Comments on proposed rule 10CFR53 re criteria & procedures for determining adequacy of available spent nuclear fuel storage capacity Opposes rule
WITHERS, B D Portland General Electric Co 48FR19382 001 83/06/08 Office of the Secretary of the Commission 1p 18944 143
- 8306230328 Comments on proposed rule 10CFR53 re criteria & procedures for determining adequacy of available spent nuclear fuel storage capacity Supports rule
WALSHE, C Atomic Industrial Forum 48FR19382 002 83/06/14
Docketing & Services Branch 4pp 18942 270
- 8306230331 Comments on proposed rule 10CFR40 re proposal to suspend certain regulations that could have significant cost impact on licensees if implemented before conformance to EPA stds Opposes rule
FREUDENTHAL, N Wyoming, State of 48FR23649 001 83/06/17
Docketing & Services Branch 1p 18942 275
- 8306230339 Comments on proposed rule 10CFR50 re severe accidents & related views on nuclear reactor regulation Focus must shift from std designs to std design processes Supporting repts encl.
WHITE, W Burns & Roe Co 48FR16014 003 83/06/15 Docketing & Services Branch 22pp 18942 351
- 8306230340 Comments on proposed rule 10CFR20 re elimination of licensee judgement in reporting theft or loss of licensed mat'l NRC should modify judgemental part of rule to define substantial hazard
WISSINK, R O 3M Co Minnesota Mining & Mfg Co 48FR20721 003 83/06/16 Docketing & Services Branch 2pp 18941 151
- 8306230445 Comments on proposed rule 10CFR50 re stds for determining whether license amendments involve no significant hazards consideration Opposes rule Comment period insufficient
WITHERS, B D Portland General Electric Co 48FR14864 021 83/06/15 Docketing & Services Branch 1p 18941 153
- 8306230450 Advises that encl 820909 petition to extend time for public comments on proposed rule 10CFR50 re personnel w/unescorted access to protected areas not answered by NRC Response requested
COOPER, J H Affiliation Unknown 47FR33980 83/05/26 Office of the Secretary of the Commission 1p 18942 079
- 8306280047 Informs that proposed changes in reporting criteria re selection of medical misadministration events for AD reporting appear reasonable NRR not responsible for regulatory matters re medical misadministration events
DENTON, H R Office of Nuclear Reactor Regulation, Director 83/06/17 HELTEMBER, C J Director's Office 2pp
- 8306280056 Proposes that future AD determinations be based primarily on severe adverse health effects, regardless of part of body involved, per review of guidelines requested on 830512 by Commission Draft Commission paper encl
HELTEMBER, C J Director's Office 83/06/01 DENTON, H R Office of Nuclear Reactor Regulation, Director DEYOUNG, R C Director's Office, Office of Inspection and Enforcement DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director 12pp 86859 068
- 8306290242 Comments on proposed rule 10CFR50 re stds for determining whether license amendments involve no significant hazards consideration Opposes rule
WITHERS, B D Portland General Electric Co 48FR14864 022 83/06/15 Docketing & Services Branch 1p 19056 052
- 8306290270 Advises recipients of comments on proposed rule 10CFR50 for determining whether license amendments involve no significant hazards considerations that Comment 21 used twice Portland General comment changed to 22
* Docketing & Services Branch 48FR14864 83/06/27
Services Branch 1p 19056 073
- 8306300103 Comments on proposed rule 10CFR20 re repts of theft of licensed mat'l Opposes rule
SHELLEY, W J Kerr-McGee Corp 48FR20721 004 83/06/21
Docketing & Services Branch 2pp 19121 070
- 8306300110 Comments on proposed rule 10CFR50 re qualification equipment important to safety in nuclear power plants Opposes rule
MORFARTY, J M Colt Industries, Inc 47FR2876 089 83/05
Docketing & Services Branch 2pp 19048 217
- 8306300124 Comments on proposed rule 10CFR53 re criteria & procedures for determining adequacy of available spent nuclear fuel storage capacity Definition of diligence unclear
EDDLEMAN, W Eddleman, W 48FR19382 006 83/06/22 Docketing & Services Branch 1p 19168 131
- 8306300137 Comments on proposed suspension of selected provisions of 10CFR40 re U mill tailings disposal Opposes suspension
PERICK, D Environmental Policy Institute 48FR23649 003 83/06/17
Office of the Secretary of the Commission 2pp 19169 11
- 8306300142 Package of five comments on proposed rule 10CFR53 re criteria & procedures for determining adequacy of available spent nuclear fuel storage capacity
RILEY, R W South Carolina, State of JORDAN, W S Harmon & Co 83/06/28 PALLADINO, J
YEAGER, H B Sierra Club 48FR19382 003/06/28 Commissioners 36pp 19119 214
- 8306300150 Comments on proposed rule 10CFR53 re criteria & procedures for determining adequacy of available spent nuclear fuel storage capacity Opposes rule
LEWIS, M I Lewis, M 48FR19382 003 83/06/03 Office of the Secretary of the Commission 2pp 19119 318
- 8306300152 Comments on proposed rule 10CFR53 re criteria & procedures for determining adequacy of available spent nuclear fuel storage capacity Opposes rule
BERNDT, J Snake River Alliance 48FR19382 014 83/06/27
No Detailed Affiliation Given 2pp 19048 359
- 8306300154 Comments on proposed rule 10CFR53 re procedures & criteria for determining adequacy of available spent nuclear fuel storage capacity Util agrees w/general approach of rule
VHRIE, R E Florida Power & Light Co 48FR19382 005 83/06/21
Docketing & Services Branch 3pp 19048 351
- 8306300155 Package of three comments on proposed rule 10CFR40 re suspension of selected provisions of NRC U mill tailings requirements
OVERTON, J A American Mining Congress * Sierra Club
SHELLEY, W J Kerr-McGee Chemical Corp (subs of Kerr-McGee) 48FR23649 83/06/27 CHILK, S J Office of the Secretary of the Commission 26pp 19122 067
- 8306300157 Comments on proposed rule 10CFR53 re criteria & procedures for determining adequacy of available spent nuclear fuel storage capacity Opposes rule
ONCAVAGE, M P Floridians United for Safe Energy 48FR19382 83/06/26 NRC - No Detailed Affiliation Given 6pp 19122 067
- 8306300158 Comments on proposed rule 10CFR53 re criteria & procedures for determining adequacy of available spent nuclear fuel storage capacity Proposed rule does not provide for public participation
DIALIK, C I New York, State of 48FR19382 004 83/06/21
Docketing & Services Branch 2pp 19119 310
- 8306300161 Comments on proposed rule 10CFR50 re NRC policy statement on severe accidents & related views on nuclear reactor regulation Opposes rule
ONCAVAGE, M P Floridians United for Safe Energy 48FR16014 83/06/26 NRC - No Detailed Affiliation Given 2pp 19122 067
- 8306300165 Comments on proposed rule 10CFR20 re repts of theft of licensed mat'l GE concurs w/NRC conclusions that reporting requirements need reevaluation & rev
VAUGHAN, C M General Electric Co 48FR20721 005 83/06/23
Docketing & Services Branch 5pp 19122 292

8306300176 Comments proposed rules 10CFR50 & 51 re requirements for licensee actions or disposition of spent fuel upon expiration of reactor DIs Opposes rules
BIALIK, E. New York, State of 48FR22730 001 83/06/23
Docketing & Services Branch 3pp 1916B 125

8306300180 Comments on proposed rule 10CFR20 re repts of theft or loss of licensed matl Conflict exists re hazards of loss of
10.12 5 mCi Cs-137 sources
COLSMANN, P Affiliation Unknown 48FR20721 006 83/06/23
Docketing & Services Branch 1p 1904B 361

8306300195 Comments on proposed suspension of 10CFR40, App A re portions of regulations dealing w/disposal of U mill tailings Opposes
suspension
FRISCO, D C Coalition for Nuclear Power Plant Postponement
48FR23649 007 83/06/26 NRC - No Detailed Affiliation Given
1p 1916B 108

8306300209 Comments on proposed rule 10CFR53 re criteria & procedures for determining adequacy of available spent nuclear fuel storage capacity Recommended changes to Sections 53.11, 53.12(b) & 53.28 listed
CAREY, J J Duquesne Light Co 48FR19382 013 83/06/27
Docketing & Services Branch 1p 19122 117

8306300219 Package of two comments on proposed suspension of 10CFR40, App A re portions of regulations dealing w/disposal of U mill tailings
JACOBI, W Colorado, State of 8HUCY, C, SOUSA, M Southwest Research and Information Center 48FR23649 83/06/29 Docketing & Services Branch 10pp 1916B 09B

8306300223 Package of two comments on proposed rule 10CFR53 re criteria & procedures for determining adequacy of available spent nuclear fuel storage capacity at civilian nuclear power reactors Supports rule
MORAN, R L Energy, Dept of KCARNEY, J J Edison Electric Institute 48FR19382 83/06/29 CHILK, S J Office of the Secretary of the Commission 25pp 19119 125

8306300227 Comments on proposed rules 10CFR50 & 51 re requirements for licensee actions on disposition of spent fuel upon expiration of reactor DIs Opposes rules
OMCAVAGE, M P Floridians United for Safe Energy 48FR22730 002 83/06/27 NRC - No Detailed Affiliation Given 4pp 1916B 094

PRM PETITION FOR RULEMAKING

8306400246 Forwards motion to dismiss Union Carbide Corp petition for rulemaking PRM-40-24
BERICK, D M Environmental Policy Institute 47FR53889 83/04/27
CHILK, S J Office of the Secretary of the Commission 1p 18727 240

--8306400248 Motion to dismiss Union Carbide Corp petition for rulemaking PRM-40-24 Made proposed contrary to requirements at U Mill Tailings Control Act & Atomic Energy Act
BERICK, D M Environmental Policy Institute 47FR53889 83/04/27 Commissioners 8pp 18727 241

8306400313 Petition for rulemaking PRM-50-36 requesting NRC amend 10CFR50 54(e), 50 54(f), 50 55(e), 50 59(h), 50 72(a), Part 50, App E, Section V, Section 73.71 & NUREGs on STS re reporting requirements
REYNOLDS, H S, COTTINGHAM, A Debevoise & Liberman 83/04/20 26pp 18729 137

8306400465 Comments on petition for rulemaking PRM-40-24 re operation of U mills & disposition of U mill tailings Recommends petition be denied or postponed
SHUCY, C Southwest Research and Information Center 47FR53889 010 83/03/02 CHILK, S J Office of the Secretary of the Commission 89pp 18862 317

PROJ PROJECTS - PREDOCKET LICENSING

8306400471 Summary of 830513 meeting w/C-C, VCPCO & Science Applications, Inc Silver Spring, MD to discuss submittal & rev to topical rept re dry cask spent fuel storage 18FSI
(CENPO-270)
ROBERTS, J P Advanced Fuel & Spent Fuel Licensing Branch 83/05/18
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 3pp 18715 207

8306400210 Forwards copyright notices to be posted in Topical Rept "REA 2023 Dry Storage Cask for DWR Spent Fuel " w/o encl
TRAPP, D Ridihaigh, Eggers & Associates 22299 83/05/16
ROUSE, L Office of Nuclear Material Safety & Safeguards, Director 3pp 18844 224

8306400167 Forwards application for withholding & proprietary repts, "Westinghouse Advanced PWR General Design Description" & "Westinghouse Advanced PWR Preliminary Ref Std Plant Primary Side Safeguards Sys " Repts withheld (ref 10CFR2 790)
RAHE, E P Westinghouse Electric Corp NS-EPR-2776 83/06/13
EISENHUT, D G Division of Licensing 3pp 18850 040

--8306400172 Application for withholding proprietary "Westinghouse Advanced PWR Preliminary Ref Std Plant Primary Side Safeguards Sys Module "
WIESEMANN, R A Westinghouse Electric Corp AW-83-46 83/06/13
EISENHUT, D G Division of Licensing 1p 18850 043

8306400216 Trip rept of site visit to observe test equipment operation & discuss waste mgt techniques w/DOE personnel & Dupont Corp List of participants encl
BOYLE, R High Level Waste Licensing Management Branch CLARK, A T NRC - No Detailed Affiliation Given 83/05/23 ROUSE, L C NRC - No Detailed Affiliation Given BELL, M J High Level Waste Licensing Management Branch 9pp 18870 036 24X Fiche 50-201, 83/05/23, 8306150216

8306220165 Summarizes 830608 meeting w/DOE in West Valley, NY re methods used by Dames & Moore to develop realistic seismic basis for design of structures & equipment for solidification of high level wastes at site List of attendees & agenda encl.
CLARK, A T Advanced Fuel & Spent Fuel Licensing Branch 83/06/15
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 3pp 18937 322

8306230213 Notification of 830606-10 meetings w/Gesellschaft fur Nuklear BvG in Essen, West Germany to discuss topical rept on Model CASTOR 1c 18FSI & to visit machining & foundry facilities for CASTOR-type casks
ROBERTS, J P Advanced Fuel & Spent Fuel Licensing Branch 83/06/15.
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 2pp 18934 359

8306240369 Forwards notice of withdrawal of application for CP for publication in FR
REGAN, W H Sitting Analysis Branch ISSUANCES A 83/06/15.
COMBS, T Docketing & Services Branch 1p 18999 136

--8306240380 Notice of withdrawal of application for CP
REGAN, W H Sitting Analysis Branch ISSUANCES A 83/06/15 1p 18999 138

8306240370 Withdraws applications for copyright registration of topical repts for DWR & PWR spent fuel per 830524 & 25 telcon requests
TRAPP, D Ridihaigh, Eggers & Associates 1098/83/106 83/03/25
ROBERTS, J P Office of Nuclear Material Safety & Safeguards, Director 1p 18999 134

8306240443 Forwards GA plan for design & fabrication of Ridihaigh Eggers & Assoc 2023 dry storage casks for spent fuel & Rev 1 to plan
PARKER, P E Ridihaigh, Eggers & Associates 83/06/03 ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 3pp 18999 001

--8306240446 Rev 1 to GA plan for design & fabrication of Ridihaigh, Eggers & Assoc 2023 dry storage casks for spent fuel pool.
* Ridihaigh, Eggers & Associates 22329 83/04/04 21pp 18999 004

--8306240450 GA plan for design & fabrication of Ridihaigh, Eggers & Assoc 2023 dry storage casks for spent fuel pool
* Ridihaigh, Eggers & Associates 22329 82/05/06 76pp 18999 025

8306270355 Forwards proprietary viewgraphs used at 830517 meeting w/NRC re review of design process for advanced control room for Westinghouse Advanced PWR Meeting agenda provided. Viewgraphs withheld
RAHE, E P Westinghouse Electric Corp NS-EPR-2776 83/06/03
EISENHUT, D G Division of Licensing 2pp 18993 306

8306270434 Provides addl justification re proprietary classification of Westinghouse Advanced PWR licensing control document Overall concept of licensing control document considered Westinghouse proprietary info
WIESEMANN, R A Westinghouse Electric Corp NB-RAW-83-477 83/06/21 MEYER, O C Standardization & Special Projects Branch 2pp 18993 117

8306280132 Expresses appreciation for T Clark & R Boyle cooperation & assistance in reviewing & evaluating processing & disposal of high level waste under West Valley Demonstration Project Act
DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director 83/06/15 HINDMAN, T B Energy, Dept of, Savannah River Operations 1p 19056 291

NONDOCKETED ITEMS

8306290366 Advises that DOE has selected borosilicate glass as waste form for immobilizing West Valley high level wastes
Appropriate tests of wastes required
HANNUH, W. H. Energy, Dept. of 22337 83/06/17 CLARK, A. T. 19047 188 24X
Advanced Fuel & Spent Fuel Licensing Branch 1p
Fiche 50-201, 83/06/17, 8306290366

8306290620 Forwards "Analysis of Terminal Waste Form Selection For West Valley Demonstration Project" Rept discusses basis for selection of borosilicate glass
COFFMAN, F. E. Energy, Dept. of 22338 83/06/14 DAVIS, J. G. 19047 035 24X
Office of Nuclear Material Safety & Safeguards, Director 2pp
19047 035 24X Fiche 50-201, 83/06/14, 8306290620

--8306290626 WVDF-100

"Analysis of Terminal Waste Form Selection for West Valley Demonstration Project"
Energy, Dept. of 22338 83/06/14 24pp 19047 037 24X
Fiche 50-201, 83/06/14, 8306290620

PT21 NONCOMPLIANCE REPORTS AND RELATED CORRESPONDENCE

8306010053 Final Deficiency Rept 83-24 re diesel generator lube oil & jacket water heaters not maintaining required temp. Initially reported on 830421 Design Change Packages 25M-00-029 & 25M-00-029 issued to install new heaters
VAN BRUNT, E. E. Arizona Public Service Co. 10CFR 050 55E 83/05/18
STERNBERG, D. M. Region 5, Office of Director 3pp 18673 330 24X
Fiche 50-528, 83/05/18, 8306010053

8306010218 Part 21 rept re screw-clamp type lugs which may not form adequate connection when used w/14 SIS stranded wire
Defective lugs identified as ILSCO Corp SLUH-70 ILSCO lugs replaced w/proper sized crimped connection ring lugs
KENYON, B. D. Pennsylvania Power & Light Co. PT21 83-880-000
83/05/25 ALLAN, J. M. Region 1, Office of Director 2pp
18673 003 24X Fiche 50-387, 83/05/25, 8306010218

8306010272 Rev 2 to Final Deficiency Rept DER 82-78 re improperly crimped termination lugs in control panels for water chillers supplied by Carrier, revising panel numbers
Initially reported on 821217 Also reportable under Part 21
VAN BRUNT, E. E. Arizona Public Service Co. DER 82-78 83/05/16
STERNBERG, D. M. Region 5, Office of Director 3pp 18672 246 24X
Fiche 50-528, 83/05/16, 8306010272

8306010274 Third interim deficiency rept re sheared motor pinion keys in Limitorque motor operators Initially reported on 820830
Field change notices issued to replace keys Next rept will be sent by 830922 Also reportable per Part 21
MILLS, L. M. Tennessee Valley Authority 10CFR 050 55E 83/05/25
O'REILLY, J. P. Region 2, Office of Director 2pp 18674 322 24X
Fiche 50-000, 83/05/25, 8306010274

8306010341 Rev 1 to final Deficiency Rept DER 81-29 re Failure of ASTM A490 bolts Initially reported on 810521 Defective bolts replaced Insp program implemented to verify bolt tension
Also reportable per Part 21
VAN BRUNT, E. E. Arizona Public Service Co. 10CFR 050 55E 83/05/11
STERNBERG, D. M. Region 5, Office of Director 4pp 18681 289 24X
Fiche 50-529, 83/05/11, 8306010341

8306010403 Fourth interim deficiency rept re failure of B1F butterfly valve seats Initially reported on 820511 Valves returned to B1F & tested satisfactorily Final rept by 830801 Also reportable per Part 21
MILLS, L. M. Tennessee Valley Authority 10CFR 050 55E 83/05/25
O'REILLY, J. P. Region 2, Office of Director 2pp 18679 328 24X
Fiche 50-438, 83/05/25, 8306010403

8306010422 Interim deficiency rept re Gould, Inc Class IE 480-volt motor control ctr protective ground Initially reported on 830425 Work underway to implement listed corrective actions
Next rept by 831216 Also reportable per Part 21
PARSONS, R. M. Carolina Power & Light Co. 10CFR 050 55E 83/05/25
O'REILLY, J. P. Region 2, Office of Director 4pp 18679 324 24X
Fiche 50-400, 83/05/25, 8306010422

8306030220 Final Part 21 rept re deficiency in DS-416 reactor trip switchgear undervoltage attachment (SDR-83-07). Initially reported on 830421 Attachments to be replaced Also reported by Westinghouse per Part 21
SEIKEN, S. J. Standardized Nuclear Unit Power Plant System PT21 83-882-000, 83/05/23 KEPPeler, J. O. Region 3, Office of Director
COLLINS, J. T. Region 4, Office of Director 3pp 18703 287 24X
Fiche 50-000, 83/05/23, 8306030220

8306070049 Part 21 rept re defective Woodward governor/activator, type EGR-13C Pointer discs machined to remove 1/16 inch from diameter Activator overhauled Util will replace brushes when spare parts available
RODRIGUEZ, R. J. Sacramento Municipal Utility District PT21 83-897-000 83/05/27 MARTIN, J. B. Region 5, Office of Director 3pp 18776 175 24X Fiche 50-312, 83/05/27, 8306070049

8306070148 Deficiency rept re narrow range resistance temp detectors installed to meet license condition failing to operate Cause under investigation Detectors replaced Testing modified until design revised Also reportable per Part 21
STEWART, W. L. Virginia Electric & Power Co. 10CFR 050 55E 83/05/27 BENTON, H. R. Office of Nuclear Reactor Regulation, Director CLARK, R. A. Operating Reactors Branch 3 2pp 18736 266 24X Fiche 50-339, 83/05/27, 8306070148

8306070160 Fifth interim deficiency rept re defects in reactor protection & ESF actuation sys modules supplied by Bailey Meter Co Initially reported on 820414 BMA investigating use of yellowish bonding agent Also reportable per Part 21
MILLS, L. M. Tennessee Valley Authority 10CFR 050 55E 83/05/26
O'REILLY, J. P. Region 2, Office of Director 3pp 18736 288 24X
Fiche 50-438, 83/05/26, 8306070160

8306070225 Final Deficiency Rept DER 83-23 re failure of MSIV bypass valve to close in required time Initially reported on 830419 Solenoid valve replaced Problem investigation request issued by Dechtel Also reported per Part 21
VAN BRUNT, E. E. Arizona Public Service Co. DER 83-23 83/05/19
STERNBERG, D. M. Region 5, Office of Director 5pp 18744 217 24X
Fiche 50-528, 83/05/19, 8306070225

8306070231 Interim deficiency rept re main reactor trip breakers design discrepancy Initially reported on 830427 Westinghouse will replace undervoltage attachments to accommodate new retaining ring Also reportable per Part 21
PARSONS, R. M. Carolina Power & Light Co. 10CFR 050 55E 83/05/26
O'REILLY, J. P. Region 2, Office of Director 4pp 18746 105 24X
Fiche 50-400, 83/05/26, 8306070231

8306090135 Second interim deficiency rept re Henry Pratt butterfly valve Initially reported on 821109 Valve air-operator yoke mod kits delivered & mod in progress Operators removed & returned to OH Battis Co Also reported per Part 21
MILLS, L. M. Tennessee Valley Authority 10CFR 050 55E 83/06/02
O'REILLY, J. P. Region 2, Office of Director 1p 18793 297 24X
Fiche 50-000, 83/06/02, 8306090135

8306090180 Third interim deficiency rept re reactor protection sys failure following secondary high energy line rupture Initially reported on 800707 Insulation of steam generator ref leg underway Also reportable per Part 21
PARSONS, R. M. Carolina Power & Light Co. 10CFR 050 55E 83/06/01
O'REILLY, J. P. Region 2, Office of Director 4pp 18792 271 24X
Fiche 50-400, 83/06/01, 8306090180

8306090191 Third interim deficiency rept re potential damage to safety injection charging pump following secondary side high energy line rupture (Item 3B) Initially reported on 800707 Resolution under review Also reportable per Part 21
PARSONS, R. M. Carolina Power & Light Co. 10CFR 050 55E 83/06/01
O'REILLY, J. P. Region 2, Office of Director 4pp 18796 086 24X
Fiche 50-400, 83/06/01, 8306090191

8306090242 Second interim rept, Item 117, re welding deficiencies on Class IE 6 9 kV circuit breakers Initially reported on 830211 All breakers returned to vendor for fabrication Also reportable under Part 21
PARSONS, R. M. Carolina Power & Light Co. 10CFR 050 55E 83/05/31
O'REILLY, J. P. Region 2, Office of Director 4pp 18795 332 24X
Fiche 50-400, 83/05/31, 8306090242

8306090306 Part 21 rept re defective Woodward Governor Co activator, Type EGR-13C Pointer discs machined to reduce disc diameter Commission notified of potential generic problem Brushes in 125-volt dc motor found worn after overhaul by manufacturer
RODRIGUEZ, R. J. Sacramento Municipal Utility District RJR 83-465 83/05/27 MARTIN, J. B. Region 5, Office of Director 4pp 18795 187 24X Fiche 50-312, 83/05/27, 8306090306

8306090310 Second interim deficiency rept re tube leaks in component cooling water HXs Initially reported on 830218 Corrosion pitting revealed by metallurgical exam Alloys investigated for replacement
MILLS, L. M. Tennessee Valley Authority 10CFR 050 55E 83/06/03
O'REILLY, J. P. Region 2, Office of Director 3pp 18795 193 24X
Fiche 50-438, 83/06/03, 8306090310

NONDOCKETED ITEMS

447

8306100090 Part 21 rept re abnormal indications in upper core barrel bolting identified during ultrasonic testing Initially reported on 830328 Samples to be removed from internals & examined
TAYLOR, J. H. Babcock & Wilcox Co PT21 83-872-000 83/04/11
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 3pp 18802 095 24X Fiche 50-312, 83/04/11, 8306100090

8306100092 Part 21 rept re potential inconvert interface w/reactor pressure vessel instrument piping Caused by error on four local instrument panel piping diagrams field deviation disposition requests issued No operating plants affected
SHERWOOD, G. O. General Electric Co PT21 83-801-000 82/11/18
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 3pp 18802 224 24X Fiche 50-352, 82/11/18, 8306100092

8306100121 Part 21 status summary rept re GE activities Defects identified in Rosemount instrumentation, electrical separation & CR2940 switch tandem blocks
CAPERON, C. A. General Electric Co IFN 085/83 83/05/13
MILLS, W. R. Director's Office, Office of Inspection and Enforcement 3pp 18802 193

8306100122 Part 21 Rept 82-10 re path of in-leakage in MSIV leakage control sys Path exists because valve not powered from critical bus Valve MS-V-146 will be powered from critical bus to assure that MSIV-1CS can perform intended function
COHEN, H. G. Burns & Roe Co PT21 83-888-000 82/11/09
ENCKELKEN, R. H. Region 3, Office of Director 4pp 18802 031 24X Fiche 50-377, 82/11/09, 8306100122

8306100125 Part 21 rept re incorrect assembly of Vitro Labs 125-volt battery monitor used at site Faulty Zener diode will cause monitor to issue battery failure indication
O'CONNOR, D. J. General Electric Co PT21 83-095-000 83/06/06
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 1p 18802 010 24X Fiche 50-482, 83/06/06, 8306100125

8306100203 Part 21 rept re deficiency in six emergency standby diesel generator sets mfg by Cooper Energy Svcs Jacket water heater & tube oil heater will be replaced w/40 kW & 19 kW versions, respectively, to maintain 120 F standby temp
STOLBA, F. D. Cooper Industries, Inc GCO 332 83/05/20
Director's Office, Office of Inspection and Enforcement 2pp 18806 007 24X Fiche 50-528, 83/05/20, 8306100203

8306100219 Sixth Interim Deficiency Rept PRD-82/14 re sheared bolts on diesel generator rear crankcase cover Initially reported on 820322 Deficiency reportable under 10CFR70 55(e) & Part 21 for Unit 1, Div II diesel generator only
MCQUAGHY, J. P. Mississippi Power & Light Co 10CFR 050 55E 83/06/01
O'REILLY, J. P. Region 2, Office of Director 6pp 18805 193 24X Fiche 50-416, 83/06/01, 8306100219

8306100231 Interim deficiency rept re use of defective matl for pinion keys in Limitorque motor operators Initially reported on 820827 Also reportable per Part 21 Rept contains no proprietary info
FOSTER, D. O. Georgia Power Co 10CFR 050 55E 83/06/01
O'REILLY, J. P. Region 2, Office of Director 3pp 18807 189 24X Fiche 50 424, 83/06/01, 8306100231

8306100233 Final Deficiency Rept PRD-83/06 re failure to provide corrosion-resistant matl in carbon steel instrument air penetration Initially reported on 830319 Util preparing design change package Also reportable per Part 21
MCQUAGHY, J. P. Mississippi Power & Light Co 10CFR 050 55E 83/06/06
O'REILLY, J. P. Region 2, Office of Director 4pp 18807 193 24X Fiche 50-416, 83/06/06, 8306100233

8306100238 Interim deficiency rept re Item 127, shop weld defects in ITT Hammel Dahl chilled water valve Item also reportable under Part 21 Valve returned to manufacturer Final rept expected by 830701
PARSONS, R. H. Carolina Power & Light Co 10CFR 050 55E 83/06/03
O'REILLY, J. P. Region 2, Office of Director 4pp 18807 154 24X Fiche 50-400, 83/06/03, 8306100238

8306100251 Final Deficiency Rept PRD-82/27 re potential for plant flooding based on PMP flood level Watertight door seals, toe plate & curb to be installed & two penetrations raised Also reportable under Part 21
MCQUAGHY, J. P. Mississippi Power & Light Co 10CFR 050 55E 83/05/31
O'REILLY, J. P. Region 2, Office of Director 3pp 18807 149 24X Fiche 50-416, 83/05/31, 8306100251

8306130150 Part 21 rept re solenoid activated valves, Models 77C-001 & 77C-003 Defects include incorrect valve assembly, significant missing parts, limited switch valve position indication failures & failure of valve to open & close
PUTTARINI, D. M. Target Rock Corp PT21 83-901-000 83/06/07
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 9pp 18824 267 24X Fiche 50-528, 83/06/07, 8306130150

8306130376 Interim Part 21 Rept DR-95 re possible defect in plate & face plate gaskets for Morrison-Knudsen Co hydrogen ignitor, Model 6043 Initially reported on 830204 Evaluation not completed Next rept to be submitted by 830711
BOOKER, J. C. Gulf States Utilities Co PT21 83-896-000 83/06/06
COLLINS, J. T. Region 4, Office of Director 1p 18822 346 24X Fiche 50-458, 83/06/06, 8306130376

8306140435 First interim deficiency rept re DB-16 reactor trip breaker design error identified by Westinghouse Initially reported on 830505 Undervoltage component Ultrasonic exam shows rept by 830926 Also reported per Part 21
MILLS, L. M. Tennessee Valley Authority 10CFR 050 55E 83/06/06
O'REILLY, J. P. Region 2, Office of Director 2pp, 18838 035 24X Fiche 50-390, 83/06/06, 8306140435

8306140683 Part 21 rept supplementing 830306 notification of potential significant safety hazard re matl defects in stainless steel tubing pressure boundary component Ultrasonic exam shows assemblies acceptable per ASME Code, Section III
SCHERER, A. E. Combustion Engineering, Inc PT21 83-911-000, 83/06/07
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 1p 18842 066 24X Fiche 50-335, 83/06/07, 8306140683

8306160433 Part 21 rept re heat sinks on MLP card & NTC card relay Heat sinks will be replaced per encl drawing Replacement relay being developed & tested
RAHE, E. P. Westinghouse Electric Corp PT21 83-902-000, 83/06/01, 83/06/07
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 9pp 18860 217

8306160454 Pt 21 rept re potential defect in transmitter mfg by Rosemount, Inc used in control sys of components furnished to listed plants All components involved retrofitted w/new circuit boards Matter closed
DIRoux, E. J. Carrier Corp PT21 83-878-000 83/05/23
STELLO, V. Director's Office, Office of Inspection and Enforcement 1p 18863 094 24X Fiche 50-518, 83/05/23, 8306160454

8306160470 Part 21 rept re broken spring-steel bands on 60 amp fuse clips ILSCO Corp requested to determine cause of breakage
DE metallurgically testing broken bands
Dwyer, P. W. General Electric Co PT21 83-893-000 83/05/10
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 7pp 18862 253 24X Fiche 50-070, 83/05/10, 8306160470

8306160316 Part 21 rept re 60 ampere ILSCO fuse holders All fuse clips subjected to 1 wt stress test & followup insp prior to installation of equipment
Dwyer, P. W. General Electric Co PT21 83-894-000 83/06/08
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 6pp 18864 164

8306170250 Interim deficiency rept re potential excessive offsite dose concerning feedwater containment penetrations not maintaining water seal for 30 days post-LQCA Also reportable under Part 21
CURTIS, N. W. Pennsylvania Power & Light Co 10CFR 050 55E 83/05/31
ALLAN, J. M. Region 1, Office of Director 4pp 18878 276 24X Fiche 50-368, 83/05/31, 8306170250

8306170279 Final deficiency & Part 21 Repts U-53 re defective plastic molding utilized in circuit boards supplied by Foxboro Co Initially reported on 830311 Components returned to vendor for rework/replacement
SCHNELL, D. F. Union Electric Co 10CFR 050 55E 83/06/01
KEPPLER, J. O. Region 3, Office of Director 1p 18877 024 24X Fiche 50-483, 83/06/01, 8306170279

8306200133 Interim Deficiency Rept 3 re Nelson stud failures on Type 86 embed plates Initially reported on 821221 Unit 1 embed plates replaced w/surface mounted plates Final rept to be submitted by 830705 Also reported per Part 21
MCQUAGHY, J. P. Mississippi Power & Light Co 10CFR 050 55E, 83/06/07
O'REILLY, J. P. Region 2, Office of Director 6pp, 18903 285 24X Fiche 50-416, 83/06/07, 8306200133

8306200141 Sixth interim deficiency rept re Viking flow control valves in fire protection sys Initially reported on 811124 Drawing rev review continuing Next rept to be submitted by 830809 Also reportable per Part 21
MILLS, L. M. Tennessee Valley Authority 10CFR 050 55E 83/06/07
O'REILLY, J. P. Region 2, Office of Director 1p, 18903, 264, 24X Fiche 50-438, 83/06/07, 8306200141

8306210005 First interim deficiency rept re max temp inside containment Initially reported on 830513, Util requested BkW to respond to nonconformance rept by 830715 Next rept to be submitted by 830826 Also reported per Part 21
MILLS, L. M. Tennessee Valley Authority 10CFR 050 55E, 83/06/13, 83/06/07
O'REILLY, J. P. Region 2, Office of Director 2pp 18912 283 24X Fiche 50-438, 83/06/13, 8306210005

NONDOCKETED ITEMS

8306210079 Interim deficiency rept re lack of movement in ITF Grinnell snubber brackets Initially reported on 830429 All snubbers will be reinspected & design & installation processes under review Final rept due Oct 1983 Also reported per Part 21 CURTIS, N W Pennsylvania Power & Light Co IOCFR 050 55E 83/05/31. ALLAN, J M Region 1, Office of Director 4pp 18911 241 24X Fiche 50-388, 83/05/31, 8306210079

8306210112 Interim Part 21 rept re adequacy of circulating water pump house structure Analysis & design of needed structural mods for svc water pump house being performed & will be completed by 830819 BARSTEN, O E United Engineers & Constructors, Inc (subs of Raytheon Co) PT21 83-907-000 83/06/17 Director's Office, Office of Inspection and Enforcement 3pp 18914 108 24X Fiche 50-443, 83/06/17, 8306210112

8306210116 Final deficiency rept re solid state protection sys test procedures. Initially reported on 820831 Procedural change initiating use of test probe w/indicator lamp connected to ground implemented Also reportable under Part 21 MILLS, L M Tennessee Valley Authority IOCFR 050 55E 83/06/15 O'REILLY, J P Region 2, Office of Director 4pp 18914 078 24X Fiche 50-390, 83/06/15, 8306210116

8306220007 Part 21 rept re adequacy of fittings supplied by Tube-Line Corp through Capitol Pipe & Steel Products Co for use on new auxiliary feedwater headers of steam generators Flanges not heat-treated as required by matl specs TAYLOR, J H Babcock & Wilcox Co PT21 83-906-000 83/06/17 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 4pp. 18927 354 24X Fiche 50-000, 83/06/17, 8306220007

8306220015 Interim deficiency rept re sensitivity & density variations in Borg-Warner valve radiographs Initially reported on 830411 Sampling plan to determine valve acceptability established Final rept by 830710 Also reported per Part 21 EDELMAN, M R Cleveland Electric Illuminating Co IOCFR 050 55E 83/06/10 KEPLER, J G Region 3, Office of Director 2pp 18927 338 24X Fiche 50-440, 83/06/10, 8306220015

8306220038 Final deficiency rept re potentially inadequate cooling of RCIC room during LOCA Initially reported on 830513 AE reviewing RCIC pump/turbine automatic start Review will be completed by 830729 Also reported per Part 21 EDELMAN, M R Cleveland Electric Illuminating Co IOCFR 050 55E 83/06/10 KEPLER, J G Region 3, Office of Director 2pp 18930 034 24X Fiche 50-440, 83/06/10, 8306220038

8306230139 Forwards data sheet for Part 21 Rept 80-256-000 re defect in spent fuel cask unloading procedures per T1105/2 (Rev 1) FISHER, W L Region 3, Chicago, Office of the Director 80/10/21 HIGGINSBOTHAM, L Region 3, Chicago, Fuel Facility & Materials Safety Branch 1p 18982-066

--8306230144 Forwards data sheet for Part 21 Rept 80-256-000 re defect in spent fuel unloading procedures. Completed data sheet should be returned by 801001 Comments on Part 21 rept encl HIGGINSBOTHAM, L Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/08/27 DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 4pp 18982 067

--8306230137 Part 21 rept re employee receiving dose of 30 710 rems to right hand on 800720 while removing particulate cartridge from water filter subsequent to cask flushing operation TOY, H L Battelle Memorial Institute, Pacific Northwest Laboratory 80/08/19 KEPLER, J G Region 3, Chicago, Office of the Director 4pp 18982 060

8306230277 Part 21 rept re defect in hose assembly 77379 Assembly welded w/60-degree rather 30-degree elbow installed SHAFER, J C Metal Bellows Corp PT21 83-903-000 83/05/09 COLLINGS, J T Region 4, Office of Director 4pp 18945 138 24X Fiche 50-000, 83/05/09, 8306230277

8306230372 Part 21 rept re Brand-Rex Co Type 3/C 12 wire cable deficiency Initially reported on 830613 Six suspect wire reels quarantined. Records researched to insure suspect cable not used in Class I areas. RODRIGUEZ, R J Sacramento Municipal Utility District, PT21 83-903-000, 83/06/16 MARTIN, J B Region 5, Office of Director 4pp. 18942:300. 24X Fiche 50-312, 83/06/16, 8306230372

8306240191 Part 21 Evaluation Rept 83-07 re improperly sized overcurrent fuses in dc motor feeders. Initially reported on 830603 Fuses sized for 225X of full load current will be provided for jogging pump. VANDERBER, J J Burns & Roe Co PT21 83-904-000, 83/06/06 COLLINGS, J T Region 4, Office of Director 16pp 18981 003. 24X Fiche 50-397, 83/06/06, 8306240191.

8306240196 Ack receipt of 830174 0211, 0322 & 0425 ltrs informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900377/82-01 POTAPOVS, U Region 4, Office of Director 83/06/17 ASHE, J Victoreen, Inc (subs of Sheller-Globe Corp) 1p 18980 265

--8306240204 Agrees w/Victoreen Part 21 evaluation of deficiencies in radiation modules, per 830413 request Position does not reflect addl discrepancies identified in CPC IOCFR50 55(e) rept BANGARI, R L Division of Vendor & Technical Programs 83/05/03 HIND, J A Division of Radiological & Materials Safety Programs 1p 18980 268

--8306240219 Responds to NRC 830119 ltr re nonconformance noted in QA Program Insp Rept 99900377/82-01 Corrective actions all outstanding purchase orders for printed circuit boards will be reviewed for inclusion of Part 21 requirements ZIMMERMAN, R Victoreen, Inc (subs of Sheller-Globe Corp) 83/02/11 POTAPOVS, U Region 4, Office of Director 4pp 18980 274

--8306240224 Forwards addl support & background info re Victoreen workmanship & Part 21 Review & evaluation by K Stafford revealed defect not apparent in workmanship & notification to NRC not required ZIMMERMAN, R Victoreen, Inc (subs of Sheller-Globe Corp) 83/02/11 POTAPOVS, U Region 4, Office of Director 83pp 18980 278

8306270223 Interim deficiency & Part 21 repts re boric acid transfer pumps, Westinghouse Shop Order 203, Item 113 Initially reported on 830113 Support bolting will be replaced & gusset stiffener spot welds supplemented by 830901 PARSONS, R M Carolina Power & Light Co PT21 83-919-000 83/06/14 O'REILLY, J P Region 2, Office of Director 4pp 18990 227 24X Fiche 50-400, 83/06/14, 8306270223

8306270228 Part 21 rept re improper latching between control rod drive shafts & control rod cluster assemblies in reactor vessel Initially reported on 830620 Insp underway COUNSILL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) PT21 83-913-000 83/06/22 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 3pp 18988 237 24X Fiche 50-213, 83/06/22, 8306270228

8306270235 Final Deficiency Rept U-54 & Part 21 rept re failure of closed limit switches to rest on containment isolation valves HV-7126 & HV-7150 Initially reported on 830516 Compensating spring installed on actuating arm SCHMELT, D F Union Electric Co IOCFR 050 55E 83/06/16 KEPLER, J G Region 3, Office of Director 1p 18988 230 24X Fiche 50-483, 83/06/16, 8306270235

8306270282 Potential Part 21 rept re discrepancy in welding of turnbuckle assembly, turnbuckle-bolt interface & on top plate assembly variable springs 5A307 Grade B bolts not ASME Section IX matl Investigation underway KARAGIANIS, J A Elcen Metal Products Co PT21 83-922-000 83/06/17 KEPLER, J G Region 3, Office of Director 2pp 18996 207 24X Fiche 50-000, 83/06/17, 8306270282

8306270289 Part 21 rept re heat sink adhesive bond failures & NTC card relay problems within Westinghouse 7300 process sys Investigation underway to determine number of cards requiring heat sink replacement DIXON, D W South Carolina Electric & Gas Co PT21 83-912-000 83/06/17 O'REILLY, J P Region 2, Office of Director 4pp 18996 178 24X Fiche 50-395, 83/06/17, 8306270289

8306270346 Final Deficiency Rept PRD-83/07 re two Div II cables improperly routed outside scheduled conduit Initially reported on 830412 Design change package issued to rework cables Also reportable per Part 21 for Unit 1 MCGAUGHY, J P Mississippi Power & Light Co AECM-83/0332 83/06/14 O'REILLY, J P Region 2, Office of Director 4pp 18996 222 24X Fiche 50-416, 83/06/14, 8306270346

8306270439 Second Interim Part 21 Rept PRD-83/08 re inability to maintain pressurized water supply to RHR pumps & discharge piping Initially reported on 830413 Final rept expected by 840201 MCGAUGHY, J P Mississippi Power & Light Co PT21 83-917-000 83/06/13 O'REILLY, J P Region 2, Office of Director 3pp 18992 067 24X Fiche 50-416, 83/06/13, 8306270439

8306280222 Revised final deficiency rept re DHR valve. Initially reported on 820212 Lower stem valve plug & lock pin replaced Control valve design sold to company not qualified as nuclear industry supplier Also reportable per Part 21 MILLS, L M Tennessee Valley Authority IOCFR 050 55E 83/06/20 O'REILLY, J P Region 2, Office of Director 2pp 19014 185 24X Fiche 50-439, 83/06/20, 8306280222

NONDOCKETED ITEMS

449

8306280417 Part 21 Deficiency Rept 80 re damaged insulation on MCC Powers Co shielded multiconductor cable on HVAC control panels Also reported by MCC Power
KEMPER, J S Philadelphia Electric Co PT21 83-916-000 83/06/01
MURLEY, T E Region 1, Office of Director 1p 19020 296 24X
Fiche 30-352, 83/06/01, 8306280417

8306280429 Fourth interim deficiency rept re B&W design of RCS supports & restraints Initially reported on 820601 Majority of blocks installed Shear bar evaluation expected by
830801 Also reported per Part 21
MILLS, L M Tennessee Valley Authority 10CFR 050 35E 83/06/20
O'REILLY, J P Region 2, Office of Director 2pp 19020 300 24X
Fiche 30-438, 83/06/20, 8306280429

8306280426 Supplemental deficiency rept re post-accident readings from containment sump level transmitters Initially reported on 820708 Fuel load date rescheduled to Jan 1984 Also reportable per Part 21
MILLS, L M Tennessee Valley Authority 10CFR 050 35E 83/06/17
O'REILLY, J P Region 2, Office of Director 1p 19018 350 24X
Fiche 30-390, 83/06/17, 8306280426

8306280463 Interim deficiency rept re Item 121, welding deficiencies in main steam/feedwater support frames Initially reported on 830318 Extension requested until 830715 to submit complete evaluation Also reportable per Part 21
PARSONS, R M Carolina Power & Light Co 10CFR 050 35E 83/06/17
O'REILLY, J P Region 2, Office of Director 1p 19018 294 24X
Fiche 30-400, 83/06/17, 8306280463

8306280479 Final deficiency rept re improperly welded chiller unit piping components Initially reported on 820111 Radiographic exam to be performed on all safety-related chiller piping Also reportable per Part 21
MILLS, L M Tennessee Valley Authority 10CFR 050 35E 83/06/17
O'REILLY, J P Region 2, Office of Director 3pp 19020 116 24X
Fiche 30-438, 83/06/17, 8306280479

8306300018 Final Part 21 evaluation rept re potential failure of Brown Boveri Model HPL-C speed switches for component cooling pump & svc water pump motors Initially reported on 830624 Failed motor replaced & defective motors repaired
DIXON, D H South Carolina Electric & Gas Co 83/06/24
O'REILLY, J P Region 2, Office of Director 3pp 19120 234 24X
Fiche 30-393, 83/06/24, 8306300018

8306300031 Sixth interim deficiency rept re failure of Limitorque motor operators during valve closure Initially reported on 820126 Westinghouse & Limitorque determining cause of failures Next rept expected by 830928 Also reportable per Part 21
MILLS, L M Tennessee Valley Authority 10CFR 050 35E 83/06/22
O'REILLY, J P Region 2, Office of Director 2pp 19120 193 24X
Fiche 30-390, 83/06/22, 8306300031

8306300159 Part 21 rept re spot welds in Bailey Controls Co cabinets w/smaller diameter than specified Cabinets strengthened by seam & edge welding or bolting
TAYLOR, J H Babcock & Wilcox Co 83/06/23 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 2pp 19119 308 24X Fiche 30-000, 83/06/23, 8306300159

8306300192 Final Part 21 rept on Item 133 re safety injection valves made of carbon steel instead of stainless steel Initially reported on 830524 Valves of correct matl reordered & incorrect valves retagged
PARSONS, R M Carolina Power & Light Co PT21 83-920-000, 83/06/22
O'REILLY, J P Region 2, Office of Director 4pp 19122 187 24X
Fiche 30-400, 83/06/22, 8306300192

8306300202 Part 21 rept re short-term reliability problem w/position indicating mechanism in solenoid valve used to control PORV 3750010 Magnet position indicating mechanism replaced on 830307 Corrective action in progress
JOHNSON, V M Garrett Corp PT21 83-891-000 83/03/09
Director's Office, Office of Inspection and Enforcement 3pp 19122 123 24X Fiche 30-389, 83/03/09, 8306300202

8306300220 Part 21 rept re loose locking clips used to secure terminal boards to rear terminal panels of safety-related instrument cabinets Initially reported on 821203 All B&W plants notified
TAYLOR, J H Babcock & Wilcox Co PT21 83-908-000 82/12/03
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 4pp 19121 356 24X Fiche 30-269, 82/12/03, 8306300220

QA799 QUALITY ASSURANCE INSPECTIONS

8306070108 Ack receipt of 830407 & 0519 ltrs informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900793/83-01.
POTAPOV, U Region 4, Office of Director 83/06/02 MACBRYDE, M B Unibraz Corp 1p 18739 158

--8306070109 Submits revised response to NRC 830228 ltr re Section II, Item B nonconformance noted in QA Program Insp Rept 99900793/83-01 Corrective actions Section 4 & 2 of identification & verification manual rewritten
MACBRYDE, M B Unibraz Corp 83/05/19 POTAPOV, U Region 4, Office of Director 2pp 18739 159

--8306070110 Responds to NRC 830228 ltr re nonconformances noted in QA Program Insp Rept 99900793/83-01 Corrective actions 10CFR21 posted on employee bulletin board, new Procedure GCP-3-83-1 implemented & tags prepared for incoming welding matl
MACBRYDE, M B Unibraz Corp 83/04/07 POTAPOV, U Region 4, Office of Director 7pp 18739 161

8306070158 Ack receipt of 830512 ltr informing NRC of steps taken to correct nonconformances noted in QA Program Insp Rept 99900796/82-01
POTAPOV, U Region 4, Office of Director 83/06/02 AMBIELLI, J Custom Alloy Corp 1p 18736 211

--8306070163 Responds to NRC 831223 ltr re nonconformances noted in QA Program Insp Rept 99900796/82-01 Corrective actions QA vendor audit rept files will be reviewed upon completion of audit & weekly audits of completed travelers conducted
BAXTER, B Custom Alloy Corp 83/05/12 CONWAY, J T Region 4, Office of Director 5pp 18736 212

8306070168 Ack receipt of 830421 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900403/83-01
POTAPOV, U Division of Vendor & Technical Programs 83/06/02 BRUGGEMAN, W H General Electric Co 1p 18739 001.

--8306070171 Responds to NRC 830328 ltr re nonconformance noted in QA Program Insp Rept 99900403/83-01 Corrective actions: component procedure delineating requirements per design memo will be issued by 830601 QA newsletter will be issued
BOHL, L B General Electric Co 83/04/21 POTAPOV, U Region 4, Office of Director 2pp 18739 002

8306070288 Ack receipt of 830518 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900387/83-01
POTAPOV, U Region 4, Office of Director 83/06/02 BISSONNETTE, P QA Technologies, Inc /General Atomic Co 1p 18741 173

--8306070294 Responds to NRC 830420 ltr re nonconformance noted in QA Program Insp Rept 99900387/83-01 Corrective actions: product quality dept manager replaced Training, production & product quality operating procedures strengthened
BISSONNETTE, P QA Technologies, Inc /General Atomic Co 83/05/18 COLLINS, J T Region 4, Office of Director, 12pp 18741 174.

8306070305 Ack receipt of 830210 & 0301 ltrs informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900792/82-01
POTAPOV, U Region 4, Office of Director 83/06/02 HARRINGTON, G W Greenville Metal Manufacturing, Inc. 1p. 18740 319

--8306070308 Responds to NRC 830110 ltr re nonconformance noted in QA Program Insp Rept 99900792/82-01 Addl info not available when 830210 response to notice of nonconformance formulated.
HARRINGTON, G W Greenville Metal Manufacturing, Inc 83/03/01, POTAPOV, U Region 4, Office of Director, 3pp. 18740 320.

--8306070312 Responds to NRC 830110 ltr re nonconformance noted in QA Program Insp Rept 99900792/82-01 Corrective actions: condition re induced shear wave angle not considered nonconformance based on insp findings
HARRINGTON, G W Greenville Metal Manufacturing, Inc. 83/02/10 POTAPOV, U Region 4, Office of Director 2pp 18740 323.

8306070331 Ack receipt of 830516 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900002/83-01
POTAPOV, U Region 4, Office of Director 83/06/02 LICHTENBERGER Combustion Engineering, Inc 1p. 18741 074.

--8306070336 Responds to NRC 830421 ltr re nonconformance noted in QA Program Insp Rept 99900002/83-01 Corrective actions: travelers will have matl release numbers recorded prior to issuance & sign off individual reinstructions
LICHTENBERGER Combustion Engineering, Inc NQA 83-008 83/05/16 POTAPOV, U Region 4, Office of Director 2pp. 18741 075.

8306130113 Advises that insp results re significant corrections & changes to ADLPIPE computer code documented in encl QA Program Insp Rept 99900535/83-01, Paragraph D.2, Item closed.
W/O encl
POTAPOV, U Division of Vendor & Technical Programs, VITS 83-46 83/06/08, MERRILL, O, Events Analysis Branch 1p 18824 298.

NONDOCKETED ITEMS

- 8306130194 Forwards QA Program Insp Rept 99900522/83-01 on 830314-18 & notice of violation
POTAPQVS,U Region 4, Office of Director 83/05/23 STATTON,C D
Bechtel Corp 2pp 18826 274
- 8306130216 Notice of violation from insp on 830314-18
* Division of Vendor & Technical Programs 83/05/23 1p
18826 274
- 8306130224 QA Program Insp Rept 99900522/83-01 on 830314-18
Noncompliance noted Part 21 not specified on safety-related
matl requisition & procurement agreement did not incorporate
matl requisition requirement
COSTELLO,J R , BEAUX,D G , HALE,C J Region 4, Office of Director
83/05/17 20pp 18826 277
- 8306130397 Forwards QA Program Insp Rept 99900535/83-01 on 830328-30
& notice of violation
POTAPQVS,U Region 4, Office of Director 83/05/23 DINGWELL, I W
DIB/ADLPIPE, Inc 3pp 18822 219
- 8306130402 Notice of violation from insp on 830328-30
* Region 4, Office of Director 83/05/23 1p 18822 222
- 8306130410 QA Program Insp Rept 99900535/83-01 on 830328-30
Noncompliance noted failure to notify users of ADLPIPE Code
error yielding nonconservative stress values
Noncompliance reported per Part 21 by B&R
BRICKLEY,R H , HALE,C J Division of Vendor & Technical Programs
83/05/06 10pp 18822 223
- 8306130413 Forwards QA Program Insp Rept 99900906/83-01 on 830314-17
& notice of nonconformance
POTAPQVS,U Region 4, Office of Director 83/05/23 MOLNAR,J
American Environments Co 3pp 18823 117
- 8306130416 Notice of nonconformance from insp on 830314-17
* Region 4, Office of Director 83/05/23 1p 18823 120
- 8306130422 QA Program Insp Rept 99900906/83-01 on 830314-17
Noncompliance noted QA procedures not type appropriate
to fully or completely describe activities affecting quality
& duties of data manager not established
SMITH,A L , PHILLIPS,H S Region 4, Office of Director 83/05/02
15pp 18823 121
- 8306140548 Ack receipt of 830510 & 27 ltrs informing NRC of steps taken
to correct nonconformance noted in QA Program Insp Rept
99900053/83-01
POTAPQVS,U Region 4, Office of Director 83/06/13 CAROD,A E
Anchor/Darling Valve (subs Anchor/Darling Industries) 1p
18845 060
- 8306140556 Responds to NRC 830412 ltr re nonconformance noted in QA
Program Insp Rept 99900053/83-01 Corrective actions sys
being developed to insure qualification repts are reviewed
for adequacy & completeness Sys to be implemented by 830601
KNIESER,G W Anchor/Darling Valve (subs Anchor/Darling
Industries), 83/05/27 POTAPQVS,U Region 4, Office of Director
1p 18845 061
- 8306140578 Responds to NRC 830412 ltr re nonconformance noted in QA
Program Insp Rept 99900053/83-01 Corrective actions
waterford valves fitted w/shrouds & heaters to maintain
actuator ambient temp & mods to feedwater valve reconciled
KNIESER,G W Anchor/Darling Valve (subs Anchor/Darling
Industries) 83/05/10 POTAPQVS,U Region 4, Office of Director
2pp 18845 062
- 8306210001 Confirms QA program insp on 830620-24 at Waltham,MA plant
per 830517 telcon
POTAPQVS,U Region 4, Office of Director 83/05/26 SPRAGERS,C O
Teledyne Engineering Services 1p 18911 359
- 8306210013 Forwards QA Program Insp Rept 99900902/83-01 on 830330-0401
No noncompliance noted
POTAPQVS,U Region 4, Office of Director 83/05/27 HOLBROOK,W H
Wyle Laboratories 2pp 18910 337
- 8306210020 QA Program Insp Rept 99900902/83-01 on 830330-0401.No
noncompliance noted Major areas inspected QA program manual.
QA program implementation & action on previous insp items
JOHNSON,A R , PHILLIPS,H S Region 4, Office of Director
SALAZAR,E A Sandia Laboratories 83/05/26 10pp 18910 339
- 8306210023 Ack receipt of 830510 ltr informing NRC of steps taken to
correct nonconformances noted in QA Program Insp Rept
99900911/83-01.
POTAPQVS,U Region 4, Office of Director 83/06/03 BRUGGEMAN,W H
General Electric Co. 1p 18911 245
- 8306210028 Responds to NRC 830413 ltr re nonconformances noted in QA
Program Insp Rept 99900911/83-01 Corrective actions
Engineering Work Authorization EAW08-22 issued on 821101 &
Engineering Review Memorandum DMD-4025 issued on 821222
BOHL,L S General Electric Co 83/05/10 POTAPQVS,U Region 4,
Office of Director 3pp 18911 246
- 8306210029 Forwards QA Program Insp Rept 99900060/83-01 on 830314-18
No noncompliance noted
POTAPQVS,U Region 4, Office of Director 83/05/27 PATTARINI,D M
Target Rock Corp 2pp 18911 249
- 8306210031 QA Program Insp Rept 99900060/83-01 on 830314-18 No
noncompliance noted Major areas inspected TVA Part 21 rept
on safety relief valve failure at Browns Ferry Unit 2
KELLEY,W D , BARNES,I Region 4, Office of Director 83/05/26
10pp 18911 251
- 8306210030 Ack receipt of 830513 ltr informing NRC of steps taken to
correct nonconformance noted in QA Program Insp Rept
99900799/83-01
POTAPQVS,U Region 4, Office of Director 83/06/17 LOTT,J E
E L Manufacturing Peebles, Inc 1p 18912 292
- 8306210033 Responds to NRC 830421 ltr re nonconformance noted in QA
Program Insp Rept 99900799/83-01 Corrective actions 10CFR21
subscription ordered on 830510 Current issue, dtd 821230,
posted on 830323
PLANK,R A E L Manufacturing Peebles, Inc 83/05/13
POTAPQVS,U Region 4, Office of Director 3pp 18912 293
- 8306210069 Confirms QA program insp on 830627-30 at Acton,MA facility,
per 830512 telcon
POTAPQVS,U Region 4, Office of Director 83/06/06 CHODREY,R S
Acton Environ Testing Corp 1p 18912 310
- 8306210172 Confirms QA program insp on 830606-10 at Oradell,NJ plant,
per 830429 telcon
POTAPQVS,U Region 4, Office of Director 83/05/26 HENDRICKSON,T
Burns & Roe Co 1p 18913 242
- 8306210185 Confirms QA program insp on 830620-24 at Canton,OH plant
per 830531 telcon
POTAPQVS,U Region 4, Office of Director 83/06/03 O'DEAY,C A
Hootley Manufacturing Div 1p 18914 130
- 8306210215 Provides status rept of open item identified in QA
Program Insp Rept 99900060/83-01 Modified pilot valve must
be tested & safety/relief valves must operate within design
pressure tolerance W/o encl
POTAPQVS,U Division of Vendor & Technical Programs FO2700282
83/06/17 LEWIS,R C Division of Project & Resident Programs 1p
18918 119
- 8306210230 Forwards QA Program Insp Rept 99900104/83-01 on 830329-31
& notice of nonconformance
POTAPQVS,U Region 4, Office of Director 83/05/27 MILLER,T D
Westinghouse Electric Corp 2pp 18915 218
- 8306210233 Notice of nonconformance from insp on 830329-31
* Region 4, Office of Director 83/05/27 2pp 18915 220
- 8306210238 QA Program Insp Rept 99900104/83-01 on 830329-31
Noncompliance noted Inconel weld band detail for primary
nozzle const not identified in technical manual & customer
drawing
OLLER,R E , POTAPQVS,U , BARNES,I Region 4, Office of Director
83/05/26 17pp 18915 222
- 8306210244 Discusses QA Program Insp Rept 99900104/83-01 on 830329-31
Failure to depict Inconel weld band on steam generator
nozzles limited to technical manual & drawings furnished to
specific facility W/o encl insp rept
POTAPQVS,U Division of Vendor & Technical Programs 83/06/17
MARTIN,T T Division of Engineering & Technical Programs 1p
18916 350
- 8306210272 Forwards QA Program Insp Rept 99900921/83-01 on 830425-29
notice of violations & nonconformance
POTAPQVS,U Region 4, Office of Director 83/06/01 SAOQI,MH,A J
Franklin Institute/Franklin Research Center 3pp 18914 280
- 8306210274 Notice of violation from insp on 830425-29
* Region 4, Office of Director 83/06/01 1p 18914 283
- 8306210282 Notice of nonconformance from insp on 830425-29
* Region 4, Office of Director 83/06/01 3pp 18914 284

NONDOCKETED ITEMS

451

--8306210286 QA Program Insp Rept 99900921/83-01 on 830425-29 Noncompliance noted failure to develop procedures for training record maint, QA responsibilities & identification of deviations from approved test procedures HUBBARD, G T, PHILLIPS, H S Region 4, Office of Director 83/05/25 22pp 18914 287

8306210278 Confirms QA program insp at Cleveland, OH plant on 830627-0701, per 830531 telcon POTAPOVS, U Region 4, Office of Director 83/06/08 ASHE, J Victoreen, Inc (subs of Sheller-Globe Corp) 1p 18914 309

8306230401 Responds to 830506 ltr re QA program Any changes to NRC approved topical rept QA program must be reported & approved prior to implementation POTAPOVS, U Region 4, Office of Director 83/06/08 BOBTRON, D O Anaconda Co (subs of Atlantic-Richfield Co) 2pp 18943 126

--8306230404 Requests info re NRC approved QA programs per 830405 meeting BOSIRICH, D O Anaconda Co (subs of Atlantic-Richfield Co) 83/05/06 BELKE, W Region 4, Office of Director 1p 18943 128

8306240180 Submits findings of recent QA program insp of Sargent & Lundy design activities re mechanical snubber problems Review of piping design criteria requested BANGART, R L Division of Vendor & Technical Programs 83/06/17 VOLLMER, R H Division of Engineering 2pp 18981 033

8306240196 Ack receipt of 830124, 0211, 0322 & 0425 ltrs informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900377/82-01 POTAPOVS, U Region 4, Office of Director 83/06/17 ASHE, J Victoreen, Inc (subs of Sheller-Globe Corp) 1p 18980 265

--8306240201 Responds to NRC 830317 ltr re nonconformance noted in QA Program Insp Rept 99900377/82-01 Corrective actions std operating procedures rewritten re printed circuit boards & purchasing documents updated ZIMMERMAN, R D Victoreen, Inc (subs of Sheller-Globe Corp) 83/04/25 POTAPOVS, U Region 4, Office of Director 2pp 18980 266

--8306240204 Agrees w/Victoreen Part 21 evaluation of deficiencies in radiation modules, per 830413 request Position does not reflect addl discrepancies identified in CPC 10CFR50 35(e) rept BANGART, R L Division of Vendor & Technical Programs 83/05/05 HIND, J A Division of Radiological & Materials Safety Programs 1p 18980 268

--8306240207 Ack receipt of 830317 ltr re QA Program Insp Rept 99900377/82-01 R Zimmerman will respond to issues raised STEWART, E C Victoreen, Inc (subs of Sheller-Globe Corp) 83/03/22 POTAPOVS, U Region 4, Office of Director 1p 18980 269

--8306240209 Ack receipt of 830211 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900377/82-01 Addl info required re actions taken to prevent recurrence of obsolete documents on purchase orders POTAPOVS, U Region 4, Office of Director 83/03/17 ASHE, J Victoreen, Inc (subs of Sheller-Globe Corp) 1p 18980 270

--8306240214 Ack receipt of QA Program Insp Rept 99900377/82-01 No proprietary info ZIMMERMAN, R Victoreen, Inc (subs of Sheller-Globe Corp) 83/02/11 POTAPOVS, U Region 4, Office of Director 1p 18980 273

--8306240219 Responds to NRC 830119 ltr re nonconformance noted in QA Program Insp Rept 99900377/82-01 Corrective actions all outstanding purchase orders for printed circuit boards will be reviewed for inclusion of Part 21 requirements ZIMMERMAN, R Victoreen, Inc (subs of Sheller-Globe Corp.) 83/02/11 POTAPOVS, U Region 4, Office of Director 4pp 18980 274

--8306240224 Forwards addl support & background info re Victoreen workmanship & Part 21 Review & evaluation by K Stafford revealed defect not apparent in workmanship & notification to NRC not required ZIMMERMAN, R Victoreen, Inc (subs of Sheller-Globe Corp) 83/02/11, POTAPOVS, U Region 4, Office of Director 85pp 18980 278

--8306240229 Responds to NRC 830119 ltr re nonconformance noted in QA Program Insp Rept 99900377/82-01 Extension requested for response to permit review of data as to appropriateness of release of ltr to PDR ASHE, J Victoreen, Inc (subs of Sheller-Globe Corp) 83/01/24 POTAPOVS, U Region 4, Office of Director 1p, 18981, 002

8306240237 Ack receipt of 830426 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900310/83-01, POTAPOVS, U Region 4, Office of Director 83/05/26 CURRANE, R A United Engineers & Constructors, Inc (subs of Raytheon Co) 1p 18980 178

--8306240243 Responds to NRC 830331 ltr re nonconformance noted in QA Program Insp Rept 99900510/83-01 Corrective actions procedures reviewed to ensure consistency & QA audit frequency increased CURRANE, R A United Engineers & Constructors, Inc (subs of Raytheon Co) 83/02/02 POTAPOVS, U Region 4, Office of Director 2pp 18980 179

--8306240245 Suppl 830202 response to NRC 830331 ltr re nonconformance noted in QA Program Insp Rept 99900510/83-01 Corrective actions calculation review program instituted & procedures to be revised by 830527 CURRANE, R A United Engineers & Constructors, Inc (subs of Raytheon Co.) 83/04/26 COLLINS, J T Region 4, Office of Director 4pp 18980, 181

8306240289 Ack receipt of 830516 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900769/83-01 POTAPOVS, U Region 4, Office of Director, 83/06/03 HEBB, L R, Pacific Air Products Co 1p 18979 227

--8306240293 Responds to NRC 830415 ltr re nonconformance noted in QA Program Insp Rept 99900769/83-01 Corrective actions tab folding problem resolved, dampers corrected & stricter insp processes instituted by Air Balance, Inc DODDSON, J P Pacific Air Products Co 83/05/16 POTAPOVS, U Region 4, Office of Director 13pp 18979 228

8306270452 Forwards QA Program Insp Rept 99900356/83-01 on 830321-24 & 0414 & notice of nonconformance POTAPOVS, U Region 4, Office of Director 83/06/01, ROSE, P, Husky Products, Inc 2pp 18992 098

--8306270453 Notice of nonconformance from insp on 830321-24 * Division of Vendor & Technical Programs 83/06/01 1p 18992 100

--8306270456 QA Program Insp Rept 99900356/83-01 on 830321-24 & 0414 Noncompliance noted current organization does not conform to requirements & engineering personnel performed insps on operations affecting quality on three Class 1E jobs. BUTTON, J H, BARNES, I Region 4, Office of Director 83/05/26 12pp 18992 101

8306280129 Confirms QA program insp at Oakland, CA plant on 830711-15 per 830523 telcon, POTAPOVS, U Region 4, Office of Director, 83/06/22 BOYER, R E, Transamerica Delaval, Inc 1p 19018 184

8306280404 Summary of 830502 mgt meeting w/Intl Nutronics in Dover, NJ re NRC equipment qualification program PHILLIPS, H S Region 4, Office of Director 83/06/22 Region 4, Office of Director 2pp 19001 335

8306280579 Summary of 830525 mgt meeting & site tour w/ANCO Engineering in Culver City, CA re equipment qualification program PHILLIPS, H S Region 4, Office of Director 83/06/22 Region 4, Office of Director 2pp 19017 322

REGGD REGULATORY GUIDES

8306020420 Comments on draft Reg Guide IC 127-5, "Criteria for Programmable Digital Computer Sys Software in Safety Sys of Nuclear Power Generating Stations," Option A & reg guide will benefit public VIVIRITO, M A Gibbs & Hill, Inc (subs of Dravo Corp) 83/05/20, Docketing & Services Branch 1p 18693 204

8306130004 Requests authorization to use encl ASME Code Case N-343, "Alternative Scope of Exam of Attachment Welds for Exam Categories B-H-B-K-I & CC Section XI, Div 1 " Rev 2 to Reg Guide 1 147 will include code case w/no addl requirements. BODUCHEY, O D Washington Public Power Supply System 002-83-482 83/06/02 SCHWENCER, A Licensing Branch 2 2pp 18824-248, 24X Ficher 30-397, 83/06/02, 8306130004,

8306140712 Concurs w/830310 memo re insider safeguards rule package, sub j to appropriate consideration of comments, Encl comments also address concerns contained in RF Burnett 830414 memo re protection of vital areas/islands. BENTON, H R Office of Nuclear Reactor Regulation, Director, 83/06/01 DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director 3pp 18832-274

NONDOCKETED ITEMS

--B306140718 Forwards revised insider safeguards rule package containing
encl action plan to implement recommendations of Committee
to Review Safeguards Requirements at Power Reactors
Concurrence requested by B30927
DAVIE, J. Q. Office of Nuclear Material Safety &
Safeguards, Director 83/05/10 DENTON, H. R. Office of Nuclear
Reactor Regulation, Director CUNNINGHAM, G. H. Office of the
Executive Legal Director MINOQUE, R. B. Office of Nuclear
Regulatory Research, Director 196pp 18852 279

B306140443 Comments on draft Reg Guide IC 127-5, "Criteria for
Programmable Digital Computer Sys Software in Safety Sys of
Nuclear Generating Stations " Endorses use of IEEE Std 730 &
ANSI/IEEE-ANS-7-4 3 2
BUDZIK, D. M. Consumers Power Co DMB 24-83 83/06/09 Docketing
& Services Branch 3pp 18840 207

B306140446 Comments on Reg Guide 1 36, "Chemical Analysis of Thermal
Insulation Matl for Leachable Chloride, Fluoride, Silicate &
Sodium Ions "
WHITAKER, T. E. American Society for Testing & Materials 83/05/31
Office of the Secretary of the Commission 2pp 18863 113

B306140451 Comments on draft Reg Guide IC 127-5, "Criteria for
Programmable Digital Computer Sys Software in Safety Sys of
Nuclear Generating Stations " Suggests Option A be selected
MALLAV, J. F. American Nuclear Society 83/06/01 Docketing &
Services Branch 2pp 18863 111

B306140460 Package of three comments on draft Reg Guide IC 127-5,
"Criteria for Programmable Digital Computer Sys Software in
Safety Sys of Nuclear Power Generating Stations "
ELLIOTT, J. L. , RONLAND, G. D. Duke Power Co BURSTEIN, S. Wisconsin
Electric Power Co 83/06/09. Docketing & Services Branch 7pp.
18863 051

B306140468 Package of two comments on draft Reg Guide IC 127-5,
"Criteria for Programmable Digital Computer Sys Software in
Safety Sys of Nuclear Generating Stations "
BUDZIK, D. M. Consumers Power Co ALLEN, R. E. Power Engineering
Society 83/06/13 Docketing & Services Branch 5pp 18863 234

B306170254 Package of two comments on draft Reg Guide IC-127-5,
"Criteria for Programmable Digital Computer Sys Software in
Safety Sys of Nuclear Power Generating Stations "
RAHE, E. P. Westinghouse Electric Corp NILSON, R. Exxon Nuclear Co ,
Inc. (subs of Exxon Corp) NB-EPR-2779 83/06/13 CHILK, S. J
Office of the Secretary of the Commission 3pp 18877 271

B306200334 Advises that implementation date for Reg Guide 1.137, "Fuel
Oil Sys for Standby Diesel Generators," delayed until
840201 Revised schedule necessary due to excavation
required to install new fuel oil tank, per DCP 390
CAREY, J. J. Duquesne Light Co 83/06/09 VAROA, S. A. Operating
Reactors Branch 1 1p 18919 214 24X Fiche 30-334, 83/06/09,
B306200334.

B306220143 Reg Guide 4 1B Task WM 013-4, "Std Format & Content of
Environ Repts for Near-Surface Disposal of Radwaste "
* Office of Nuclear Regulatory Research, Director 83/06/30 40pp
18977:096

--B306220148 Value/Impact assessment of Reg Guide 4 1B Task WM 013-4,
"Std Format & Content of Environ Repts for Near-Surface
Disposal of Radwaste "
* Office of Nuclear Regulatory Research, Director. 83/06/30
2pp 18977:136

B306220182 Draft Rev 2 to Reg Guide MS 901-4 & value impact statement,
"Identification of Valves for Inclusion in Inservice Testing
Programs "
* Office of Nuclear Regulatory Research, Director 83/03/31 74pp
18947 175.

B306230414 Comments on draft Reg Guide IC 127-5, "Criteria for
Programmable Digital Computer Sys Software in Safety Sys of
Nuclear Power Generating Sys "
BROEHL, D. J. Portland General Electric Co 83/06/10 Docketing &
Services Branch 2pp 18943 188

B306230419 Comments on draft Reg Guide IC 127-5, "Criteria for
Programmable Digital Computer Sys Software in Safety Sys of
Nuclear Power Generating Sys " Recommends Option B
SCHERER, A. E. Combustion Engineering, Inc LD-83-055 83/06/16,
Docketing & Services Branch 1p 18943 205

B306230425 Comments on draft Reg Guide IC 127-5, "Criteria for
Programmable Digital Computer Sys Software in Safety Sys of
Nuclear Power Generating Sys." Recommends Option A.
FARRAR, D. L. Commonwealth Edison Co. 672BN 83/06/07, Docketing
& Services Branch 1p. 18943-214

B306230523 Discusses AIF proposal detailing info in one-step license
application Proposal in form of rewrite of Reg Guide 1 70,
"Std Format & Content of SARs for Nuclear Power Plants" will
illustrate level of design detail required
DIRCKS, W. J. Office of the Executive Director for Operations
M830311 83/06/16 CHILK, S. J. Office of the Secretary of the
Commission 1p 18951 356

B306240043 Reg Guide 1 147, Rev 2, "Inservice Insp Code Case
Acceptability, ASME Section XI, Div 1 "
* Office of Nuclear Regulatory Research, Director 83/06/30 6pp
18985 173

B306240115 "For Comment" issue of draft Reg Guide ES 114-4, "Guidelines
for Groundwater Monitoring at In Situ U Solution Mines "
* Office of Nuclear Regulatory Research, Director 83/06/30 33pp
18998 233

--B306240118 Draft value/impact assessment of proposed Reg Guide ES
114-4, "Guidelines for Groundwater Monitoring at In Situ
U Solution Mines " Reg Guide establishes technical guidance
on hydrologic monitoring
* Office of Nuclear Regulatory Research, Director 83/06/30
6pp 18998 266

B306300100 Comments on draft Reg Guide IC 127-5, "Criteria for
Programmable Digital Computer Sys Software in Safety Sys of
Nuclear Power Generating Sys " Recommends use of
ANSI/IEEE-ANS-7-4 3 2-1982 be limited
KOESTER, G. L. Kansas Gas & Electric Co KMLNRC 83-075 83/06/17
Docketing & Services Branch 1p 19121 072

RES RESEARCH AND TECHNICAL ASSISTANCE REPORTS

B306010478 "Evaluation of Methods for Reducing Pressure Vessel
Fluence," monthly rept for Mar 1983
ARONSON, A. L. Battelle Memorial Institute, Pacific Northwest
Laboratory CAREW, J. F., COKINGS, D. M. Brookhaven National
Laboratory BNL-NUREQ-32876 83/03/31 LOIS, L., DUNENFELD, H.
Division of Systems Integration (post 811005) 51pp 18693 171

B306020048 "Reliability Assessment of Nuclear Structural Sys "
REICH, H., HWANG, H. Brookhaven National Laboratory BNL-NUREQ-32748
83/06/01 NRC - No Detailed Affiliation Given 14pp 18702 307

B306020683 "Seismic Qualification of Nuclear Plant Mechanical &
Electrical Equipment," Monthly Progress Ltr 16 for Apr 1983
KANA, D. D. Southwest Research Institute NRC-04-81-185 83/05/11
CAMPELL, W. E. Office of Nuclear Regulatory Research, Director 8pp
18715 332

B306030435 "Ranking of Environs in Stress-Corrosion Cracking "
NEWMAN, R. C., BANDY, R. Brookhaven National Laboratory
BNL-NUREQ-32824 83/03/31 NRC - No Detailed Affiliation Given
9pp 18735 330

B306070422 "Investigation of Accident-Induced Flow & Matl Transport in
Nuclear Facilities," monthly progress rept for Apr 1983
MARTIN, R. A., OREGORY, W. S. Los Alamos Scientific Laboratory FIN
A-7029 83/05/27 Transportation & Materials Risk Branch 8pp
18782 012

B306080229 "Matls Properties Data for Fusion Reactor Analysis,"
internal technical rept
HAGRMAN, D. L. EQ&O, Inc 83/04/30 NRC - No Detailed Affiliation
Given 219pp 18785 102

B306170205 "Ranking Safe Shutdown Readiness for FY83, 84 & 85 Reactor
Safe Shutdown Insps "
THOMAS, H. J., MACDOUGALL, E. Brookhaven National Laboratory FIN
A-3133 83/05/31 NRC - No Detailed Affiliation Given 96pp
18881 043

B306240241 "HAARM-3 Users Manual "
QIESEKE, J. A., LEE, K. W., REED, L. D. Battelle Memorial Institute,
Columbus Laboratories NRC-04-76-273-07 BNL-NUREQ-1991 78/01/05
Division of Reactor Safety Research 72pp Available at NTIS
18987 139.

REVIEW ORP NRC RESEARCH REVIEW GROUPS

B306030509 Informs that each LRO-II member must submit numerical value
determined by GE for respective plants on fuel assembly
lift off displacement due to error in fuel assembly topical
rept re LRO-II Generic Issue 2-CPB
NOVAK, T. M. Assistant Director for Licensing 83/05/23
HOLTZSCHER, D. L. Licensing Review Group II 3pp 18735 051 24X
Fiche 50-000, 83/05/23, B306030509.

NONDOCKETED ITEMS

453

B306060303 Notification of CRGR Meeting 41 on B30608 to review draft NUREG-0801, "Evaluation Criteria for Detailed Control Room Design Reviews" & draft NUREG-0835, "Human Factors Review Guidelines for Safety Parameter Display Sys"
STELLO, V Regional Operations & Generic Requirements B3/06/02
MATTSO, R J Office of Nuclear Reactor Regulation, Director
JORDAN, E L Director's Office, Office of Inspection and Enforcement
CUNNINGHAM, R E Office of Nuclear Material Safety & Safeguards, Director 121pp 18729 202

B306060373 Responds to B20903 ltr submitting position papers which included Licensing Review Group II proposed solution for Issue 4-MER, intended to protect in-core instrument tubes from flow-induced vibration issue unresolved
YOUNGBLOOD, B J Licensing Branch 1 B3/05/26 HOLTZSCHER, D L
Fiche 50-Q00, B3/05/26, B306060373

B306060414 Transcript of Ad Hoc Committee for Review of Nuclear Reactor Licensing Reform Proposals B30525 meeting in Washington, DC
Pp 1-167 Supporting documentation encl
* Commissioners B3/05/25 190pp 18748 159

B306070460 Requests concurrence w/encl package & comments re resolution of Generic Issue B-10, "Behavior of BWR Mark III Containment"
KOVAK, T M Assistant Director for Operating Reactors B3/03/27
EISENHUT, D G Division of Licensing 3pp 18780 312

B306080158 NUREG-0880 R01 FC
SAFETY GOALS FOR NUCLEAR POWER PLANT OPERATION
* Office of Policy Evaluations B3/09/31 116pp 18789 163

B306080207 Summary of CRGR Meeting 38 on B30918 re presentation of proposed rule on pressurized thermal shock of reactor pressure vessels Committee supports proposed rule
STELLO, V Regional Operations & Generic Requirements B3/05/31
DIRCKS, W J Office of the Executive Director for Operations 5pp 18771 269

B306130233 Forwards: "Shaking Table Testing for Seismic Evaluation of Electrical Raceway Sys," in response to BEP Topic III-06, "Seismic Design Considerations" Rept must be referenced on individual dockets to apply to specific plants
KACICH, R M BEP Owners Group KACICH, R M Northeast Utilities
B3/04/29 RUSSELL, W T Systematic Evaluation Program Branch 1p 18827 268

--B306130238 URB/JAB 8090
"Shaking Table Testing for Seismic Evaluation of Electrical Raceway Sys"
* URB Corp * John A Blume & Associates, Engineers (subs URB Corp) B3/04/30 122pp 18827 269

B306130383 Advises of cancellation of CRGR Meeting 41 to permit NRR to reevaluate NUREG-0801, "Evaluation Criteria for Detailed Control Room Design" & NUREG-0835, "Human Factors Review Guidelines for Safety Parameter Display Sys"
STELLO, V Regional Operations & Generic Requirements B3/06/08
MATTSO, R J Office of Nuclear Reactor Regulation, Director
JORDAN, E L Director's Office, Office of Inspection and Enforcement
CUNNINGHAM, R E Office of Nuclear Material Safety & Safeguards, Director 1p 18822 215

B306160680 Clarifies B30516 article from Inside NRC, in response to B30516 request Views expressed in presentation considered views of author & not necessarily views of Commission
TOURTELL OTTE, J Regulatory Reform Task Force B3/06/14 WEISS, E R
Union of Concerned Scientists 2pp 18884 357

B306280370 Summary of CRGR Meeting 39 on B30525 re proposed overall rev to 10CFR71 on packaging of radioactive matl for transport & transportation of radioactive matl under certain conditions
Attendance list encl
STELLO, V Regional Operations & Generic Requirements B3/06/20
DIRCKS, W J Office of the Executive Director for Operations 8pp 19001 232

B306290564 Responds to B30419 memo re potential safety problems in use of health physics barriers Integrated assessment of all access controls recommended
DENTON, H R Office of Nuclear Reactor Regulation, Director
B3/06/07 DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director 1p 19047 186

--B306290567 Discusses Committee to Review Safeguards B30228 rept identifying use of barriers established for health physics & fire protection as potential safety problem Action requested
DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director B3/04/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 19047 187

SECY POSITION PAPERS BEFORE THE COMMISSION

B306030366 Addl response to FOIA request for SECY-B2-36B, SECY-B2-475 & SECY-B2-509 SECY-B2-475 available in PDR SECY-B2-36B withheld entirely (ref FOIA Exemption 3)
FELTON, J M Division of Rules and Records B3/04/01 BUCKLER, R
Affiliation Unknown 2pp 18734 290

--B306030370 SECY-B2-475
Informs of resolution of reactor coolant pump trip issue (TMI Action Plan Item II K 3 5)
DIRCKS, W J Office of the Executive Director for Operations B2/11/30 53pp 18734 292

B306030383 Responds to FOIA request for documents re exploration, mining or milling of U in specific areas in State of NE
Forwards documents listed in app
FELTON, J M Division of Rules and Records B3/04/01 REID, A B
Broken Bow Law Office 2pp 18747 149

--B204070018 SECY-B2-127
Recommends Commission reassert regulatory authority over State of NE U mining & milling activities to protect public health & safety, per Governor Thorne request
DIRCKS, W J Office of the Executive Director for Operations, B2/03/23 2pp 18747 153

B306060104 Responds to FOIA request for SECY-B1-645, SECY-B1-654 & SECY-B2-162A SECY-B1-645 & SECY-B1-654 pertain to AOs noticed in 46FR61020 Forwards SECY-B2-162A
FELTON, J M Division of Rules and Records B3/03/29 GRABER, L
Affiliation Unknown 1p 18750 353

--B306060108 SECY-B2-162A
Forwards integrated plan for development of rule for shift crew qualifications.
DIRCKS, W J Office of the Executive Director for Operations B2/08/26 9pp 18750 354

B306160093 Addl response to FOIA request for documents re IAEA nuclear matl safeguards program Forwards App A documents App B Documents 1-B entirely withheld & Documents 7-16 partially withheld (ref FOIA Exemptions 1, 3 & 5)
FELTON, J M Division of Rules and Records B3/04/01 GREENBERG, E V Tuttle & Taylor 5pp 18892 011

--B306160193 SECY-B2-025
Forwards H Gruemm preliminary comments on Morgan memo re IAEA safeguards for B11119 press conference SECY title & other safeguards info deleted
DIRCKS, W J Office of the Executive Director for Operations B2/01/19 8pp 18892 146

--B306160198 SECY-B2-046
Informs Commission of existing interagency groups involved in US efforts to upgrade IAEA safeguards & provides brief rept on status of activities W/o encl outline & status of action plan
DIRCKS, W J Office of the Executive Director for Operations B2/02/02 13pp 18892 154

--B306160208 SECY-B2-210
Forwards summary of significant NRC & Executive Branch efforts to improve IAEA safeguards & estimate of expended resources Safeguards info deleted W/o encl rept on US assistance to IAEA & outline of areas needing improvements
DIRCKS, W J Office of the Executive Director for Operations B2/03/26 17pp 18892 170

--B306160216 SECY-B2-313
Informs Commission of receipt of Dept of State B20702 ltr re classification of Morgan rept State agrees that rept should be classified "secret" Safeguards info deleted, W/o listed encl
DIRCKS, W J Office of the Executive Director for Operations, B2/07/26 2pp 18892 282

B306240403 SECY-B3-219
Provides status rept on LWR accident source term reassessment, including revised schedule & milestones for source term & severe accident research program
DIRCKS, W J Office of the Executive Director for Operations B3/06/06 14pp 18997 339

NONDOCKETED ITEMS

STATE PROG STATE PROGRAMS

8306020035 Speech entitled, "Rept on NRC Activities," presented at 5th Annual Natl Conference on Radiation Control in Reno, NV on 8/30/16
KERR, O W Office of State Programs, Director 83/03/16 6pp
18702 326

8306020366 Confirms discussion W/JO Lubenau, DA Nussbaumer & JW Horner following review & evaluation of State of AZ radiation control program. Significant problems re technical quality of licensing actions & status of regulations identified.
MARTIN, J B Region 5, Office of Director 83/05/25 TEDFORD, C E Arizona, State of 17pp 18694 331

8306020459 Notification of contract execution to "Radiation Monitoring Program Requirements" Contractor State of NE
MCDERMOTT, D Technical Assistance Contracts Branch FIN B-8508
NRC-31-83-670 83/03/16 MEYERS, D M Region 4, Office of Director
NICHOLAS, J B NRC - No Detailed Affiliation Given 1p 18715 234

--8306020463 Contract "Radiation Monitoring Program Requirements," awarded to State of NE
SMITH, H D Nebraska, State of MORTON, K V Division of Contracts FIN B-8508 NRC-31-83-670 83/03/16 10pp
18715 235

8306020496 Speech entitled "Radiation & Regulation," presented at 830523 annual meeting of Assoc of State & Territorial Health Officials in Washington, DC
KERR, O W Office of State Programs, Director 83/05/23 8pp
18715-184

8306030277 Notification of contract execution, Mod 1 to "Radiation Monitoring Program Requirements" Contractor State of AR
MCDERMOTT, D Technical Assistance Contracts Branch FIN B-8500
NRC-31-83-667 83/05/20 MEYERS, D M Region 4, Office of Director
NICHOLAS, J B NRC - No Detailed Affiliation Given 1p 18733 324

--8306030284 Mod 1, increasing funding to FY83 levels, to "Radiation Monitoring Program Requirements"
* Arkansas, State of MORTON, K V Division of Contracts FIN B-8500 NRC-31-83-667 83/05/20 1p 18733 325

8306030383 Responds to FOIA request for documents re exploration, mining or milling of U in specific areas in State of NE
Forwards documents listed in app
FELTON, J M Division of Rules and Records 83/04/01 REID, A B Broken Plow Law Office 2pp 18747 149

--8306030388 Approves encl draft FR notice re reassertion of certain regulatory authority in State of NE (SECY-82-127)
CHILK, B J Office of the Secretary of the Commission 82/04/20
DIRCKS, W J Office of the Executive Director for Operations 4pp
18747 159

--8306030390 Forwards notice of issuance & availability of reassertion of certain regulatory authority in State of NE
KERR, O W Office of State Programs, Director 82/04/26
COMBS, T R Correspondence & Records Branch 1p 18747 163

--8306030395 Notice of issuance & availability of reassertion of certain regulatory authority in State of NE
KERR, O W Office of State Programs, Director 82/04/26 3pp
18747 164

8306060222 Requests 830722 meeting to discuss results of 830718-22 regulatory review of radiation control program. Review will cover principal administrative & technical aspects of program
ALLAN, J M Region 1, Office of Director 83/03/27 CANNON, J E Rhode Island, State of 1p 18728 012

8306060417 Forwards draft version of proposed 80/DQE cooperative agreement. Agreement formally initiates efforts to implement remedial actions to stabilize & control U tailings
ROTHWASSER, R G Energy, Dept of 83/05/20 JANKLOW, W South Dakota, State of 45pp 18751 001

8306130336 Responds to 830905 ltr re radiation control program. Staff instructed to dispatch enforcement ltrs within 2 wks of insp & radiation control section manager will review all insp rpts
SPELL, W H Louisiana, State of 83/06/02 COLLINS, J T Region 4, Office of Director 2pp 18822 361

8306140185 Summarizes 830105 discussion w/D Nussbaumer & K Schneider re Agreement State compatibility concerning financial assurance requirements for long-term care at low level radwaste burial sites. Proposed criteria changes to be finalized
LOHMEYER, P H Low Level Waste Licensing Branch 83/05/18
HIOGINTHAM, L Low Level Waste Licensing Branch 2pp 18844 187

8306140331 Forwards Waste Mgt Group, Inc (WMO) response to 8 NRC & States of NV & SC comments on State of NV Consumer Health Svcs comments re WMO topical rept concerning RADMAN Code to document low level waste input needed by 830527 W/O encl
NUSSBAUMER, D Assistant Director for State Agreements Programs 83/05/12 VADEN, J Nevada, State of 1p 18854 121

8306150485 Notification of contract execution "Radiation Monitoring Program Requirements," awarded to State of LA
MCDERMOTT, D Technical Assistance Contracts Branch FIN B-8502
NRC-31-83-669 83/06/01 MEYERS, D M Region 4, Office of Director
NICHOLAS, J B NRC - No Detailed Affiliation Given 1p 18868 001

--8306150488 Contract "Radiation Monitoring Program Requirements," awarded to State of LA
SIMONCAUX, F P Louisiana, State of MORTON, K V Administrative Contracts Branch FIN B-8502 NRC-31-83-669 83/06/01 18pp
18868 002

8306190574 NUREG/BR-0025 V09 N5
INFORMATION REPORT ON STATE LEGISLATION
KERR, O W, LANDAU, M Office of State Programs, Director 83/06/30
11pp 18854 336

8306160691 Forwards in-process OL amend requests currently being evaluated by NRC in response to final rules, effective 830506, specifying that when licensees request amend to OL, licensees must notify appropriate State designee
TOURIGNY, E G Operating Reactors Branch 3 83/06/06 SIMMONS, H E North Dakota, State of 2pp 18876 288 24X Fiche 50-285-83/06/06, 8306160691

8306200101 Requests 830902 meeting to discuss results of State of NH radiation control program meeting scheduled for wk of 830802 Adequacy & compatibility of program will be evaluated
ALLAN, J M Region 1, Office of Director 83/06/10 WALLACE, W Y New Hampshire, State of 2pp 18903 334

8306220166 Notification of contract execution "Radiation Monitoring Program Requirements," awarded to State of MD
MCDERMOTT, D Technical Assistance Contracts Branch FIN B-8353
NRC-28-83-608 83/06/16 MCSHAR, J Region 1, Office of Director
COSTELLO, F NRC - No Detailed Affiliation Given 1p 18937 309

--8306220168 Contract "Radiation Monitoring Program Requirements," awarded to State of MD
RESH, D L Maryland, State of * NRC - No Detailed Affiliation Given FIN B-8353 NRC-28-83-608 83/06/16 13pp 18937 306

8306220244 Notification of contract execution, Mod 1 to "California Offshore Radiological Licensee Survey" Contractor State of CA
HOYLE, A Administrative Contracts Branch FIN B-8705
NRC-05-82-254 83/06/10 BLAHA, J L Program Support Branch
YACZKO, C T NRC - No Detailed Affiliation Given 1p 18951 114

--8306220246 Mod 1, extending period of performance to 830630, to "California Offshore Radiological Licensee Survey"
* California, State of REBELLO, J E Division of Contracts FIN B-8705 NRC-05-82-254 83/06/10 1p 18951 115

8306230485 Notification of contract execution, Mod 1 to "Radiation Monitoring Program Requirements" Contractor State of TX
SILVIER, R M Technical Assistance Contracts Branch FIN B-8504
NRC-31-83-671 83/06/14 MEYERS, D M Region 4, Office of Director
NICHOLAS, J B NRC - No Detailed Affiliation Given 1p 18982 040

--8306230491 Mod 1, providing CY83 funding & changing B&R number to 94-19-30-02, to "Radiation Monitoring Program Requirements"
MACLEAN, R Texas, State of GUSTAVE, P Technical Assistance Contracts Branch FIN B-8504 NRC-31-83-671 83/06/14 1p 18982 041

8306230494 Notification of contract execution, Mod 2 to "Radiation Monitoring Program Requirements" Contractor State of NE
SILVIER, R M Technical Assistance Contracts Branch FIN B-8503
NRC-31-83-670 83/06/15 MEYERS, D M Region 4, Office of Director
NICHOLAS, J B NRC - No Detailed Affiliation Given 1p 18982 038

NONDOCKETED ITEMS

455

--8306230496 Mod 2, providing CY83 funds, to "Radiation Monitoring Program Requirements " Contractor State of OR
BECK, R H Nebraska, State of GUSTAVE, R P Technical Assistance
Contracts Branch FIN B-8503 NRC-31-83-670 83/06/15 1p
18982 039

8306230507 Notification of contract execution, Mod 1 to "Radiation Monitoring Program Requirements " Contractor State of OR
SILVJIS, R M Technical Assistance Contracts Branch FIN B-8554
NRC-32-83-685 83/06/15 ALEXANDER, I Office of Resource
Management, Director HAMADA, G NRC - No Detailed Affiliation
Given 1p 18982 029

--8306230509 Mod 1, providing funds for CY83, to "Radiation Monitoring Program Requirements "
Oregon, State of GUSTAVE, R P Division of Contracts FIN
B-8554 NRC-32-83-685 83/06/15 1p 18982 030

8306270372 Responds to 830104 ltr expressing NRC concern over technical quality of State of NH licensing program for radioactive materials New comprehensive forms, associated licensing guides & checklists will ease review process
WALLACE, W T New Hampshire, State of 83/04/29 HAYNES, R C
Region 1, Office of Director 2pp 18993 206

8306280242 Ack receipt of 830301 ltr & confirms RS Hoyer 830511 discussions w/Graham & Simmons re State of NE radiation control program Significant compliance problems identified at Univ of NE at Lincoln
COLLINS, J T Region 4, Office of Director 83/06/21 SMITH, H D
Nebraska, State of 2pp 19014 195

TOPREP VENDOR REPORTS AND RELATED CORRESPONDENCE

8304110936 Forwards financial info for Connecticut Light & Power Co & Western Massachusetts Electric Co for 1982 Rept for Northeast Nuclear Energy Co will be available on or about 830415
BIGDOP, R W Northeast Utilities 83/04/05 Office of Nuclear
Reactor Regulation, Director 71pp 17716 P48 24X
Fiche 50-245, 83/04/05, 8304110936

8306010314 Submits update on B&W Owners Group plans to install shunt trip feature to Reactor trip sys scram breakers Arkansas Power & Light Co will submit design info during wk of 830530 Owners group endorses facility shunt trip design
WALLACE, E O Babcock & Wilcox Operating Plants Owners Group
WALLACE, E O General Public Utilities - GPU Service Corp 83/05/27
EISENHUT, D O Division of Licensing 1p 18672 310 24X
Fiche 50-313, 83/05/27, 8306010314

8306020364 Forwards Amend 2 to Rev 3 to "Ederer Nuclear Safety-Related Extra-Safety & Monitoring (X-SAM) Cranes " Rept withheld (ref 10CFR2 790)
CLARK, C W Ederer, Inc 83/05/27 THOMAS, C Standardization &
Special Projects Branch 2pp 18693 185

8306020471 Summary of 830513 meeting w/C-E, VEPCO & Science Applications, Inc Silver Spring, MD to discuss submittal & rev to topical rept re dry cask spent fuel storage 18FBI (CENPD-270)
ROBERTS, J P Advanced Fuel & Spent Fuel Licensing Branch 83/05/18
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 3pp
18715 207

8306020492 Requests payment for review of QA program, Rev 6 Invoice will be sent
MILLER, W D License Fee Management Branch 83/05/20
McFARLAND, J E Sargent & Lundy, Inc 1p 18715 325

--8306020496 Requests billing for review of QA program, Rev 6
MILLER, W D License Fee Management Branch 83/05/20 MANION, W E
Financial Operations Branch 1p 18715 326

8306030338 Endorsement 62 to MAELU Policy MF-54
Nuclear Energy Liability Insurance Association HUGHES, R J
Marsh & McLennan, Inc 83/04/21 1p 18703 020

--8306030339 Endorsement 76 to NELIA Policy NF-187
Nuclear Energy Liability Insurance Association HUGHES, R J
Marsh & McLennan, Inc 83/04/21 1p 18703 021

8306030476 Forwards draft Sections 1 & 2 of May 1983 revised RADMAN topical rept Views on Section 2 requested w/o encl
TUSITE, P T Waste Management Group, Inc 83/05/12 ROLES, G Low
Level Waste Licensing Branch 1p 18735 247

8306030509 Informs that each LRO-II member must submit numerical value determined by GE for respective plants on fuel assembly lift off displacement, due to error in fuel assembly topical rept re LRO-II Generic Issue 2-CPB
NOVAK, T M Assistant Director for Licensing 83/05/23
HOLTZSCHER, D L Licensing Review Group II 3pp 18735 051 24X
Fiche 50-000, 83/05/23, 8306030509

8306060174 Summary of 830518 meeting w/Westinghouse re review of Westinghouse generic safety parameter display sys concerning WCAP-10170, "Emergency Response Facility Design & V&V Process " Vendor will append man-in-the loop results
DICK, G F Operating Reactors Branch 5 LS05-83-06-007 83/06/02
CRUTCHFIELD, D Operating Reactors Branch 5 17pp 18728 164 24X
Fiche 50-244, 83/06/02, 8306060174

8306070167 Application to amend License DPR-35, revising Tech Specs to expand operating region of power/flow map & provide associated changes in average power range monitor flux scram & rod block trip settings (Proposed Change 83-05)
HARRINGTON, W D Boston Edison Co 83-139 83/05/31 VASSALLO, D B
Operating Reactors Branch 2 1p 18739 004 24X
Fiche 50-293, 83/05/31, 8306070167

--8306070174 NEDE-22198
"GE BWR Extended Load Line Limit Analysis for Pilgrim Nuclear Power Station Unit 1 Cycle 6 "
FISCHER, D L, GRIDLEY, R L General Electric Co 82NED084
82/09/30 21pp 18739 016 24X Fiche 50-293, 83/05/31, 8306070167

8306070272 Forwards BAW-1784, "B&W Owners Group Bolting Task Force Summary Rept of NRC/B&W Owners Group 830506 Meeting on Reactor Vessel Internals Bolting " Agrees w/overall findings, w/exception re neutron noise surveillance
TUCKER, H B Duke Power Co 83/05/31 DENTON, H R Office of
Nuclear Reactor Regulation, Director 2pp 18744 086 24X
Fiche 50-269, 83/05/31, 8306070272

--8306070280 Forwards BAW-1784, "B&W Owners Group Bolting Task Force Summary Rept of NRC/B&W Owners Group 830506 Meeting on Reactor Vessel Internals Bolting "
TAYLOR, J H Babcock & Wilcox Operating Plants Owners Group
83/05/20 MINER, S NRC - No Detailed Affiliation Given 1p
18744 088 24X Fiche 50-269, 83/05/31, 8306070272

--8306070286 BAW-1784
"B&W Owners Group Bolting Task Force Summary Rept of NRC/B&W Owners Group 830506 Meeting on Reactor Vessel Internals Bolting "
Babcock & Wilcox Co 83/05/31 124pp 18744 089 24X
Fiche 50-269, 83/05/31, 8306070272

8306080105 Requests generic approval of NEDE-22290 "Safety Evaluation of OE Type 1 Hybrid Control Rod Assembly " Requests issuance of generic SER by 830729
KLAPPROTH, J F General Electric Co MFN 096-83 83/05/20
THOMAS, C NRC - No Detailed Affiliation Given 1p 18773 054

8306090045 Forwards proprietary Rev 1 to XN-NF-524(P), "Exxon Nuclear Critical Power Methodology for BWRs," per GF Oswlwy 800530 ltr
CHANDLER, J C Exxon Nuclear Co, Inc (subs of Exxon Corp.)
JCC 067 83 83/06/06 THOMAS, C O Standardization & Special
Projects Branch 1p 18792 345

8306090154 Forwards proprietary version of Suppl 2 to Rev 2 to "RODCX2 Fuel Rod Thermal Mechanical Response Evaluation Model " Rept provides sample calculation of BWR fuel performance parameters Rept withheld (ref 10CFR2 790)
CHANDLER, J C Exxon Nuclear Co, Inc (subs of Exxon Corp)
JCC 065 83 83/06/02 THOMAS, C O Standardization & Special
Projects Branch 1p 18792 344

8306090267 Forwards safety evaluation of BWR Owners Group response to NUREG-0737, Item II K 3 1B, "Mod of Automatic Depressurization Sys Logic " Acceptable options include elimination of high drywell pressure permissive
CRUTCHFIELD, D Operating Reactors Branch 5 LS05-83-06-016
83/06/08 COUNSIL, W O Northeast Nuclear Energy Co (subs. of
Northeast Utilities) 2pp 18793 280 24X Fiche 50-245, 83/06/08,
8306090267

--8306090272 Safety evaluation of BWR Owners Group response to NUREG-0737, Item II K 3 1B, "Mod of Automatic Depressurization Sys Logic " Acceptable options include elimination of high drywell pressure permissive
Office of Nuclear Reactor Regulation, Director 83/06/08 3pp
18793 282, 24X Fiche 50-245, 83/06/08, 8306090267

NONDOCKETED ITEMS

- 8306090363 Notification of 830607 meeting w/Westinghouse Owners Group in Bethesda, MD to discuss generic design incorporating shunt trip into automatic reactor protection function in reactor trip breakers
IPOLITO, T A Operating Reactors Assessment Branch 83/05/27
HIRAGLJA, F J Assistant Director for Safety Assessment 1p
19046 114
- 8306090457 Forwards request for addl info re WCAP-8375, "Augmented Startup & Cycle 1 Physics Program" Response requested by 830722
THOMAS, C D Standardization & Special Projects Branch TAC 1882
83/06/02 RAHE, E P Westinghouse Electric Corp 2pp 18815 152
- 8306130444 Forwards mgt review committee const implementation overview observations re bulk hanger organization Review of documentation supporting established criteria needed
BARANOW, S W Stone & Webster, Inc 83/06/09 KEPLER, J Q Region 3, Office of Director 2pp 18821 201
- 8306140109 Confirms IE mgt 830405 meeting to discuss recent insp findings re nondestructive assay of waste mats & to review applicable regulatory requirements.
STOHM, J P Division of Emergency Preparedness & Materials Safety 83/04/20 ALTO, R A Babcock & Wilcox Co 1p 18839 096
- 8306140377 Forwards revised Table D-1, "Preliminary Stress Level Comparison," showing value of stress concentration factor & higher calculated peak stresses. Higher peak stresses do not affect conclusions from 830306 meeting Meeting summary encl
TAYLOR, J H Babcock & Wilcox Co 83/06/07 MINER, S NRC - No Detailed Affiliation Given 2pp 18844 001 24X
Fiche: 50-000, 83/06/07, 8306140377
- 8306140738 Forwards topical repts, "Boundary Analytical Assessment of NUREG-0630 on LOCA & Operating kW/Ft Limits," per 830602 request
TUCKER, H B Duke Power Co 83/06/26 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 1p 18845 001 24X Fiche 50-269, 83/06/06, 8306140738
- 8306140746 77-1141256-00
"Boundary Analytical Assessment of NUREG-0630 on LOCA & Operating kW/Ft Limits."
* Babcock & Wilcox Co. 83/06/06 29pp 18845 002 24X
Fiche 50-269, 83/06/06, 8306140738
- 8306140752 77-1140895-00
"Boundary Analytical Assessment of NUREG-0630 on LOCA & Operating kW/Ft Limits"
* Babcock & Wilcox Co 83/06/06 29pp 18845 032 24X
Fiche 50-269, 83/06/06, 8306140738
- 8306150121 Forwards SER of OE proprietary & nonproprietary NEDE-24284-P & NEDO-24284, "Assessment of Fuel Rod Bowing in OE BWRs" Repts acceptable ref in license applications under delineated conditions
THOMAS, C D Standardization & Special Projects Branch 83/05/31
QUIRK, J F General Electric Co 2pp. 18870 068
- 8306150124 SER of OE proprietary & nonproprietary NEDE-24284-P & NEDO-24284, "Assessment of Fuel Rod Bowing in OE BWRs" Repts acceptable ref in license applications w/NRC supporting documentation
* Standardization & Special Projects Branch 83/05/31 9pp 18870:070
- 8303220403 "Technical Evaluation of OE Fuel Rod Bowing Topical Rept NEDE-24284-P"
CAREW, J F Brookhaven National Laboratory 82/08/31 NRC - No Detailed Affiliation Given 6pp 18870 079
- 8306160284 Forwards Westinghouse Owners Group steam generator tube rupture (SOTR) emergency contingency guidance approved for high pressure version of emergency response guideline set Three SOTR guidelines, ECA-7, 8 & 9 provided
SHEPPARD, J J Westinghouse Operating Plants Owners Group
SHEPPARD, J J Carolina Power & Light Co DG-92 83/03/16
EISENHUT, D Q Division of Licensing 4pp 18861 013
- 8306160291 Procedure ECA-7:HP-Basic "Combined SOTR & LOCA"
* Westinghouse Operating Plants Owners Group 83/04/18 23pp. 18861 017.
- 8306160300 Procedure ECA-8 HP-Basic "Unisolatable SOTR"
* Westinghouse Operating Plants Owners Group 83/04/18, 20pp 18861 040
- 8306160303 Procedure ECA-9 HP-Basic "SOTR W/O Pressurizer Pressure Control."
* Westinghouse Operating Plants Owners Group. 83/04/18 14pp 18861:060
- 8306160412 Forwards draft Rev 5 to "GA Program Topical Rept" COUNSEL, W O Northeast Utilities Service Co A03039 83/06/09
MURLEY, T F Region, Office of Director 6pp 18859 090 24X
Fiche 50-000, 83/06/09, 8306160412
- 8306160424 Draft Rev 5 to "GA Program Topical Rept"
* Northeast Utilities 83/06/09 135pp 18859 096 24X
Fiche 50-000, 83/06/09, 8306160412
- 8306160493 Forwards "Bounding Analytical Assessment of NUREG-0630 Models on LOCA kW/Ft Limits," reflecting use of FLECEY heat transfer correlation as compensating model to reduce impact of NUREG-0630 models
MARSHALL, J R Arkansas Power & Light Co 1CAN068301 83/06/08
STOLZ, J F Operating Reactors Branch 4 1p 18862 083 24X
Fiche 50-313, 83/06/08, 8306160493
- 8306160497 77-1143707-00
"Bounding Analytical Assessment of NUREG-0630 Models on LOCA kW/Ft Limits"
* Babcock & Wilcox Co 83/06/08 20pp 18862 085 24X
Fiche 50-313, 83/06/08, 8306160493
- 8306160541 Forwards GA Co Repts 706505, 706577 & GA-A16829 describing results of exams on fuel elements w/cracked webs Repts convey belief that cracks in fuel block graphite webbing do not intersect fuel holes
BREY, H L Public Service Co of Colorado P-83169 83/06/02
COLLINS, J T Region 4, Office of Director 1p 18865 148 24X
Fiche 50-267, 83/06/02, 8306160541
- 8306160564 GA-A16829
"NDE of 54 Fuel & Reflector Elements From Fort St Vrain Core Segment 2"
SAURWICIN, J J GA Technologies, Inc /General Atomic Co UC-77 82/10/31, 196pp 18865 179 24X Fiche 50-267, 83/06/02, 8306160541
- 8306170318 Forwards "Assessment of Conservatism in Mark I Downcomer Chugging Lateral Load," documenting presentation during 830311 meeting
PFEEFERLEN, H C General Electric Co MFN-107-83 83/06/08
VASSALLO, D B Operating Reactors Branch 2 1p 18877 237
- 8306170320 M1-LR-83-01
"Assessment of Conservatism in Mark I Downcomer Chugging Lateral Load"
* EDS Nuclear, Inc * General Electric Co 83/05/31 33pp 18877 238
- 8306200019 Summary of 830331 meeting w/utills & Westinghouse in Bethesda, MD re Westinghouse analysis & evaluation of D4/D3/E steam generator mod
HOPKINS, J D Licensing Branch 4 83/06/14 Licensing Branch 4 22pp 18908 327 24X Fiche 50-000, 83/06/14, 8306200019
- 8306200255 Responds to HR Denton 830513 telcon re identification of plants using reactor steam condensation function in RHR sys Mark I owners accept generic response re Humphrey concerns on ECCS relief line discharge loads
SHERWOOD, O O General Electric Co MFN-106-83 83/06/08
EISENHUT, D Q Division of Licensing 2pp 18901 184
- 8306210093 Provides update of three Salem-related issues previously discussed Broader range of Salem issues being addressed by B&W Owners Group, ATWS Standing Committee & will be discussed at 830630 meeting
ENOS, J T Babcock & Wilcox Operating Plants Owners Group ENOS, J T Arkansas Power & Light Co 1CAN068310 83/06/14 MATTHEW, R J Division of Systems Integration (post B11005) 2pp 18914 237
- 8306210146 Forwards NEDO-22215, "Procedures for Determination of Extent of Core Damage Under Accident Conditions," & "Integration of Other Plant Parameters Into Core Damage Estimate," per NRC request
DENTE, T J BWR Owners Group BWR00-8324 83/06/17 EISENHUT, D Q Division of Licensing 20pp 18919 129
- 8306210153 NEDO-22215, "Procedures for Determination of Extent of Core Damage Under Accident Conditions"
LIN, C C, COWAN, R L, KISSE General Electric Co 82NED090 82/08/31 39pp. 18919 149
- 8306210165 Forwards license operator training segment (Pages 49-79) of revised Procedure N7BA13, "Nuclear Operator Training Program," per 10CFR55, App A
GREEN, H J Tennessee Valley Authority 83/06/17 THOMPSON, H L Division of Human Factors Safety 33pp 18915 237

NONDOCKETED ITEMS

457

8306210295 Informs of results of exam of steam generator internal auxiliary feedwater header designs & intentions to replace internal header 203FA w/external header. Ltr completes info re disposition of all B&W-designed headers
TAYLOR, J H Babcock & Wilcox Co 83/06/16 DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement 3pp
18914 010

8306220087 Forwards description of program approved by Westinghouse Owners Group to address NUREG-0737, Item 11 B 3 re post-accident core damage assessment, per 830428 meeting Project to be completed by end of yr
SHEPPARD, J J Westinghouse Operating Plants Owners Group
SHEPPARD, J J Carolina Power & Light Co 83/06/16 NORRIS, J A
Operating Reactors Branch 1 7pp 18926 203

8306220258 Notification of 830629 meeting w/BWR-Hydrogen Control Owners Group in Bethesda, MD to discuss hydrogen control program
HOUSTON, D Licensing Branch 2 83/06/09 SCHWENGER, A Licensing
Branch 2 9pp 18951 034 24X Fiche 50-416, 83/06/09, 8306220258

8306220300 Notification of 830630 meeting w/B&W Owners Group in Bethesda, MD to discuss organizational structure established to deal w/generic issues & group activities during last 6 months
LAINAS, G C Assistant Director for Operating Reactors 83/06/09
EISENHUT, D O Division of Licensing MATTSOHN, R Division of
Systems Integration (post 811003) VOLLMER, R Division of
Engineering 2pp 18940 301

--8306220703 Designates G Lainas as licensing contact w/overall responsibility for staff interaction coordination & mgt
Encl identifies technical contacts for each B&W Owners Group subcommittee Agenda for 830630 meeting encl
DENTON, H R Office of Nuclear Reactor Regulation, Director
83/06/01 CROUSE, R P Babcock & Wilcox Operating Plants Owners
Group CROUSE, R P Toledo Edison Co 3pp 18940 303

8306230047 Forwards safety evaluation of emergency response guidelines Guidelines acceptable for implementation & will provide improved guidance for emergency operating procedure development Response schedule requested within 90 days
EISENHUT, D O Division of Licensing 83/06/01 SHEPPARD, J J
Westinghouse Operating Plants Owners Group 2pp 18982 109

--8306230052 Safety evaluation re Westinghouse Owners Group generic emergency guidelines for mitigating transients & accidents, per NUREG-0737, Item 1 C 1
* Office of Nuclear Reactor Regulation, Director 83/06/01
73pp 18982 111

8306230167 Forwards addl info re Hydrogen Control Owners Group program, per NRC 830203 request Proprietary & nonproprietary versions of "Grand Gulf Drywell Break Sensitivity Summary" encl
Proprietary rept withheld (ref 10CFR2 790)
DALE, L F Mississippi Power & Light Co AECH-83/0212 83/06/16
DENTON, H R Office of Nuclear Reactor Regulation, Director 11pp
18945 299 24X Fiche 50-416, 83/06/16, 8306230167

--8306230167 8FB-39A82 RA
Nonproprietary version of "Grand Gulf Drywell Break Sensitivity Summary"
QUINTER, A D Offshore Power Systems (subs of Westinghouse Electric Corp) 83/05/11 397pp 18945 311 24X Fiche 50-416, 83/06/16, 8306230167

8306230324 Forwards technical rept, "Generic Control Rod Drive Sys Study for BWR 2 Through BWR-9 Plant Designs"
DENTON, H R BWR Owners Group BWR00-8323 83/06/02 EISENHUT, D O
Division of Licensing 1p 18942 229

--8306230326 TR-5709-1
"Generic Control Rod Drive Sys Study for BWR-2 Through BWR-9 Plant Designs," technical rept
* Teledyne Engineering Services 83/05/31 NRC - No Detailed
Affiliation Given 44pp 18942 226

8306230386 Forwards revised App E to WCAP-10170, "Application of Safety Parameter Display Evaluation Project to Design of Westinghouse Safety Parameter Display Sys"
RAHE, E P Westinghouse Electric Corp NS-EPR-2779 83/06/08
THOMAS, C O Standardization & Special Projects Branch 1p
18943 061

--8306230391 WCAP-10170 APP E
Revised App F to "Application of Safety Parameter Display Evaluation Project to Design of Westinghouse Safety Parameter Display Sys"
MOORE, D B Westinghouse Electric Corp 42320 83/06/08 13pp
18943 062

8306230437 Forwards Rev 3 to "Corporate Operations Manual, Part IV-Functional Manuals, Section I Nuclear QA Manual" Revs reflect organizational changes & clarify items modified in Rev 2 to SRP (NUREG-0800)
RAUSCH, W P Burns & Roe Co 83/06/09 HAASS, W P Quality
Assurance Branch 1p 18944 023

--8306230443 84ROE-COM4-1-NP R03
Rev 3 to "Corporate Operations Manual, Part IV-Functional Manuals, Section I Nuclear QA Manual"
ROE, K A Burns & Roe Co 83/06/09 73pp 18944 024

8306240205 Provides info re DS-416 undervoltage trip attachments to be utilized in NRC evaluation of facility, per B Wright request
RAHE, E P Westinghouse Electric Corp NS-EPR-2767 83/06/17
DENTON, H Office of Nuclear Reactor Regulation, Director 4pp
18980 246 24X Fiche 50-369, 83/06/17, 8306240205

8306240262 Forwards revised responses to RETRAN computer code review, per NRC 830202 request Draft SER requested prior to official release Also forwards "RETRAN-02 Program for Transient Thermal-Hydraulic Analysis of Complex Fluid Flow Sys"
SCHNATZ, T W Middle South Services, Inc 83/06/09 THOMAS, C O
Standardization & Special Projects Branch 25pp 18978 009

--8306240263 EPR1 NP-1830-CCM V04
"RETRAN-02 - Program for Transient Thermal-Hydraulic Analysis of Complex Fluid Flow Sys, Vol 4 Applications"
PETERSON, C E, OOSE, O C, MCFADDEN, J H Energy Incorporated
83/01/31 250pp 18978 034

8306240313 Forwards proprietary & nonproprietary responses to NRC request for addl info on WCAP-8720, Addendum 2, "Revised PAD Code Thermal Safety Model" Proprietary responses withheld (ref 10CFR2 790)
RAHE, E P Westinghouse Electric Corp NS-EPR-2773 83/06/02
THOMAS, C O Standardization & Special Projects Branch 2pp
18997 142

--8306240314 Requests withholding of proprietary response to NRC request for addl info on WCAP-8720, Addendum 2, "Revised PAD Code Thermal Safety Model," per 10CFR2 790 Affidavit encl
WIESEMANN, R A Westinghouse Electric Corp AW-83-45 83/06/02
THOMAS, C O Standardization & Special Projects Branch 9pp
18997 144

--8306240315 Nonproprietary response to NRC request for addl info on WCAP-8720, Addendum 2, "Revised PAD Code Thermal Safety Model"
* Westinghouse Electric Corp 83/06/02 10pp 18997 153

8306270260 Forwards "Bounding Analytical Assessment of NUREG-0630 Models on LOCA 14/15 Limits"
RODRIGUEZ, R J Sacramento Municipal Utility District RJR 83-505
83/06/20 STOLZ, J F Operating Reactors Branch 4 2pp 18990 231
24X Fiche 50-312, 83/06/20, 8306270260

8306270355 Forwards proprietary viewgraphs used at 830517 meeting w/NRC re review of design process for advanced control room for Westinghouse Advanced PWR Meeting agenda provided Viewgraphs withheld
RAHE, E P Westinghouse Electric Corp NS-EPR-2776 83/06/03
EISENHUT, D O Division of Licensing 2pp 18993 306

8306270434 Provides addl justification re proprietary classification of Westinghouse Advanced PWR licensing control document Overall concept of licensing control document considered Westinghouse proprietary info
WIESEMANN, R A Westinghouse Electric Corp NS-RAW-83-477
83/06/21 MEYER, G C Standardization & Special Projects Branch,
2pp 18993 117

8306280240 Forwards proprietary Suppl 1 to "Stability Evaluation of BWR Cores Benchmark Analyses," Rept addresses addl generic issues of BWR stability & provides addl benchmarking calculations Rept withheld (ref 10CFR2 790)
COPELAND, R A Exxon Nuclear Co, Inc (subs of Exxon Corp)
RAC 024 83 83/06/21 THOMAS, C O Standardization & Special
Projects Branch 1p 19015 029

8306280337 Forwards responses to NRC 830331 questions on topical rept BAW-10153P, "Extended Burnup Evaluation" Conservatism in dose calculations sufficient to accommodate expected effects of iodine spiking
TAYLOR, J H Babcock & Wilcox Co 83/06/21 MORAN, D H
Standardization & Special Projects Branch 11pp, 19001:299.

8306280392 Advises that info submitted by util on 830610 re response to open items from Equipment Qualification Branch BQRT is nonproprietary
RAHE, E P Westinghouse Electric Corp NS-EPR-2791, 83/06/21
YOUNGBLOOD, B J Licensing Branch 1 1p 19019 008 24X
Fiche 50-445, 83/06/21, 8306280392

NONDOCKETED ITEMS

8306280449 Discusses concerns re NRC consideration that diverse scram
sys be required on Westinghouse plants PWR inherent design
characteristics adequately address performance criteria for
ATWS events Meeting requested
RAHE, E P Westinghouse Electric Corp NS-EPR-2787 83/06/22
DENTON, H R Office of Nuclear Reactor Regulation, Director App
19019 179

8306280534 Forwards proprietary Suppl 7 to "STR Bundle Submittal
Millstone-1, Segmented Test Rod Bundle," updating 741003
rept, per Reload 2 license amend GO Sherwood affidavit encl
Rept withheld (ref 10CFR2 790)
COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast
Utilities) COUNCIL, W O Northeast Utilities 810727 83/06/17
CRUTCHFIELD, D Operating Reactors Branch 3 5pp 19016 292 24X
Fiche 50-243, 83/06/17, 8306280534

8306300037 Forwards G-E repts, "Depressurization & DHR Responses to NRC
Questions," Suppl 1 to "PRA of Effects of PORVs on
Depressurization & DHR" & "Responses to Plant-Specific
Questions on Depressurization," per 820327 request
BASKIN, K P Southern California Edison Co 83/06/22 KNIGHTON, G W
Licensing Branch 3 3pp 19117 062 24X Fiche 50-361, 83/06/22,
8306300037

--8306300125 CEN-239
"Depressurization & DHR Responses to NRC Questions"
* Combustion Engineering, Inc 83/06/30 390pp 19117 065 24X
Fiche 50-361, 83/06/22, 8306300037

--8306300136 CEN-239 601
Suppl 1 to CEN-239, "PRA of Effects of PORVs on
Depressurization & DHR, San Onofre Nuclear Generating
Station, Units 2 & 3"
* Combustion Engineering, Inc 83/06/30 363pp 19118 083 24X
Fiche 50-361, 83/06/22, 8306300037

8306300116 Endorsement 33 to MAELU Policy MF-96
* Nuclear Energy Liability Insurance Association 83/06/01 2pp
19121 066

WASH REGULATORY PUBLICATIONS - PRE-NUREG SERIES

8306200037 Responds to FOIA request for blueprints & explanations of
assorted power plants Forwards documents describing safety &
NRC licensing process for reactors Drawings & design details
available in listed LPDRs in NY
FELTON, J M Division of Rules and Records 83/05/18 SPECTOR, B
Affiliation Unknown 2pp 18919 320

--8306200040 WASH-1250
Excerpt from WASH-1250, "Safety of Nuclear Power Reactors
(Light Water-Cooled) & Related Facilities"
* NRC - No Detailed Affiliation Given 83/05/18 39pp
18919 322

WASTE MGT NUCLEAR WASTE MANAGEMENT

8306020192 Forwards updated EIS schedule for UMTRAP as of 830501
ARTHUR, J Energy, Dept of 83/05/01 MARTIN, A Low Level Waste
Licensing Branch 2pp, 18701 071

8306020194 Forwards updated environ assessment schedule for UMTRAP as
of 830510
ARTHUR, J Energy, Dept of 83/05/10 MARTIN, D NRC - No Detailed
Affiliation Given 2pp 18701 070

8306020217 Forwards best available sorption info on Columbia Plateau
basalt alteration products & interbed matl
SERNER, J Battelle Memorial Institute, Pacific Northwest
Laboratory 83/05/13 MILLER, A B Sandia Laboratories 33pp
18701 015

8306020220 Forwards proposed agenda for 830527 meeting re UMTRAP
implementation
PAGE, R O NRC - No Detailed Affiliation Given 83/05/18
CUNNINGHAM, R E, BROWNING, R, HIGGINBOTHAM, L NRC - No Detailed
Affiliation Given 3pp 18701 054

8306020228 Designates 24 contaminated Edgemont vicinity properties for
remedial action, identified in encl list of radiological
assessment repts UMTRAP authorized to bring properties in
conformance w/final EPA stds (40CFR192)
COFFMAN, F E Energy, Dept of NE-24 83/05/04 ROMATOWSKI, P O
Energy, Dept of 2pp 18701 012

8306020231 Forwards info re U mill tailings remedial action vicinity
properties status, plans & schedule, including data used in
preparing project schedule & cost estimate rept
BALL, D M Energy, Dept of 83/05/17 BRAZLE, C Energy, Dept
of 3pp 18700 355

8306020252 Forwards 24 radiological assessment repts for properties in
Edgemont, SD where presence of residual radiological matl
detected Remedial action recommended for properties
reporting residual matl levels above EPA stds w/o encl
MARTIN, D F Low Level Waste Licensing Branch FIN B-2217
83/04/21 BAUBLITZ, J Energy, Dept of 2pp 18700 344

8306020255 Forwards, for comment, draft general protocol for
identification, characterization & inclusion/designation of
vicinity properties proposed for remedial action under
Public Law 95-604
BAUBLITZ, J E Energy, Dept of 83/05/13 HIGGINBOTHAM, L Low
Level Waste Licensing Branch 14pp 18700 329

8306030200 Summary of 830419 meeting w/Marlene U Corp in Silver Spring,
MD re status of proposed U project in Danville, VA
KALMAN, K L Uranium Recovery Licensing Branch 83/05/06
HIGGINBOTHAM, L Low Level Waste Licensing Branch 2pp 18733 340

8306030210 Trip rept of attendance at Committee E-5 & Low Level Waste
Mgt Committee 830514-15 meetings & Conference of Radiation
Control Program Directors 830516-17 meeting
HAWKINS, E F Low Level Waste Licensing Branch 83/05/23
HIGGINBOTHAM, L Low Level Waste Licensing Branch 3pp 18731 747

8306030244 Summary of 830511 DOE consultation meeting w/states, USGS &
CEB at Dallas-FT Worth, TX airport re proposed siting
guidelines
BOYLE, R R High Level Waste Licensing Management Branch 83/05/19
BELL, M J High Level Waste Licensing Management Branch 29pp
18734 033

8306030273 Summary of 830516 meeting w/DOE in Gaithersburg, MD re
siting guidelines DOE should make same version available to
public by issuing FR notice of availability
PFLUM, C G High Level Waste Licensing Management Branch 83/05/20
BOYLE, R R High Level Waste Licensing Management Branch 2pp
18734 076

8306030430 Comments on 830415 info re 20 properties in Grand Junction,
CO to be included in UMTRAP Portions of Properties not
scheduled for remedial action under site program should be
included
MARTIN, D C Low Level Waste Licensing Branch 83/05/06
BAUBLITZ, J E Energy, Dept of 1p 18747 116

8306030431 Requests steps vendor must take to deliver 1982 & 83
radioactive shipping records data on magnetic computer tape
for use in DOE low level waste data base
JACKSON, K C Low Level Waste Licensing Branch 83/05/05 CRASE, H
US Ecology, Inc (formerly Nuclear Engineering) 2pp 18735 348

8306030432 Comments on Apr 1983 rev of remedial action concept papers
for Gunnison inactive U Mill Tailings Site issuance of paper
acceptable
HIGGINBOTHAM, L Low Level Waste Licensing Branch 83/05/11
MORLEY, J A Energy, Dept of 1p 18735 362

8306030438 Requests assistance in establishing coordination procedure
re NRC contractors requesting site-specific samples from
high level radioactive sites Meeting requested
BROWNING, R E Division of Waste Management 83/05/04 BENNETT, J W
Energy, Dept of 4pp 18747 145

8306030442 Requests info re steps vendor must take to deliver 1982 & 83
radioactive shipping records data on magnetic computer tape
for use in DOE low level waste data base
JACKSON, K C Low Level Waste Licensing Branch 83/05/05
WHITTAKER, M Chem-Nuclear Systems, Inc 2pp 18735 285

8306030470 Forwards generic comments on 30 Durango & Salt Lake City
property repts No generic protocol agreed on for designation
of vicinity properties Plans for aerial or ground monitoring
requested
MARTIN, D E Low Level Waste Licensing Branch 83/05/26
BAUBLITZ, J E Energy, Dept of 4pp 18735 278

8306030476 Forwards draft Sections 1 & 2 of May 1983 revised RADMAN
topical rept Views on Section 2 requested w/o encl
TUIE, P T Waste Management Group, Inc 83/05/12 ROLES, G Low
Level Waste Licensing Branch 1p 18735 247

NONDOCKETED ITEMS

459

8306030477 Ack receipt of quarterly progress rept on hydrogeochemical studies at Riverton & Maybell sites Supports change in direction of project from field data gathering to modeling
FENNIFILL, R A Low Level Waste Licensing Branch 83/05/24
BARBER, W Jacobs Engineering Group, Inc 1p 18735 267

8306060417 Forwards draft version of proposed SD/DOE cooperative agreement Agreement formally initiates efforts to implement remedial actions to stabilize & control U tailings
ROMATOWSKI, R O Energy, Dept of 83/05/20 JANKLOW, W South Dakota, State of 43pp 18791 001

8306080148 Forwards review draft of "Remedial Action Plan for Stabilization of Inactive U Mill Tailings Site at Canonsburg, PA " Comments requested by 830624
MORLEY, J A Energy, Dept of 83/05/26 NIXON, W A Office of Nuclear Material Safety & Safeguards, Director 1p 18790 102

--8306080153 UMTRA-DOE/AL-140 DR
"Remedial Action Plan for Stabilization of Inactive U Mill Tailings Site at Canonsburg, PA," review draft
* Energy, Dept of. 83/05/31 147pp 18790 103

8306090033 Summary of 830509 meeting w/DOE remedial action contractors in Silver Spring, MD re preliminary sections of Canonsburg, PA remedial action plan & generic health & safety plan for UMTRAP.
FLORY, C A Low Level Waste Licensing Branch 83/05/26
HIGGINSBOTHAM, L Low Level Waste Licensing Branch 2pp 18798 020

8306090353 Forwards seismic study rept for Salt Lake City prepared for inclusion in EIS Rept evaluates effects of probable seismic events on vitro tailings pile in South Salt Lake Rept will undergo format changes & become App I to DLS & EIS
MORLEY, J A Energy, Dept of 83/05/31 MARTIN, D NRC - No Detailed Affiliation Given 44pp 18797 069

8306090357 "Edgemont Remedial Action Program," ltr rept for Feb, Mar & Apr 1983
JACKSON, P G, PERKINS, R W, WOODMAN, N A Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2217 83/05/13 FLORY, C A Low Level Waste Licensing Branch 10pp 18797 046

8306090372 Submits eighth status rept on Edgemont offsite cleanup action program
FLORY, C A Low Level Waste Licensing Branch FIN B-2217 83/06/01
HIGGINSBOTHAM, L Low Level Waste Licensing Branch 4pp 18814 031

8306140185 Summarizes 830405 discussion w/D Nussbaumer & K Schneider re Agreement State compatibility concerning financial assurance requirements for long-term care at low level radwaste burial sites Proposed criteria changes to be finalized
LOHMEYER, P H Low Level Waste Licensing Branch 83/05/10
HIGGINSBOTHAM, L Low Level Waste Licensing Branch 2pp 18844 187

8306140187 Trip rept of 830228-0301 visit to Tucson, AZ to attend waste mgmt conference, ASME radwaste committee meeting & ANS 40 35 vol reduction std committee meeting Meeting summaries encl
JOHNSON, F C Low Level Waste Licensing Branch 03/05/24
LOHMEYER, P H Low Level Waste Licensing Branch 11pp 18844 189

8306140193 Forwards comments on NRC - WSP draft, "Study of Isolation Sys for Geologic Disposal of Radwaste" re hydrology, geology, geochemistry, design, waste package & performance assessment
MILLER, H J High Level Waste Licensing Management Branch 83/05/11.
BELL, M J High Level Waste Licensing Management Branch 17pp 18844. 164

8306140203 Submits specific questions & answers discussed by NRC, OAI & Geo Trans, Inc during 830307 & 08 hydrogeology modeling meetings re implementation of SWIFT (Version 4 B1)
WEBER, M F High Level Waste Licensing Management Branch 83/05/11
KNAFF, M R High Level Waste Licensing Management Branch 11pp 18844 213

8306140203 Forwards first 11 radiological assessment repts for properties in Edgemont, SD where presence of residual radiological matls detected NRC concurrence should be obtained on properties which DOE decides not to designate
HAWKINS, E F High Level Waste Licensing Management Branch 83/03/22 BAUBLITZ, J Energy, Dept of 2pp 18844 206

8306140289 Comments on monthly rept for Feb-Apr 1982 for Edgemont cleanup action program No repts received since 830421 Repts must be submitted as expeditiously as possible
FLORY, C A Low Level Waste Licensing Branch FIN B-2217 83/06/03
WOODMAN, N A Battelle Memorial Institute, Pacific Northwest Laboratory 3pp 18844 203

8306140325 Comments on draft UMTRAP technology development plan, received on 830504 Plan provides good general description of UMTRAP R&D program
GRUGNOLI, O N Low Level Waste Licensing Branch 83/05/13
MATTHEWS, M L Energy, Dept of 2pp 18854 116

8306140331 Forwards Waste Mgt Group, Inc (WMO) response to & NRC & States of NV & SC comments on State of NV Consumer Health Svcs comments re WMO topical rept concerning RADMAN Code to document low level waste input needed by 830527 W/o encl
NUSSBAUMER, D Assistant Director for State Agreements Programs 83/05/12 VADEN, J Nevada, State of 1p 18854 121

8306140333 Forwards radiological assessment repts for 11 remedial action designated properties in Edgemont, SD per 830328 memo. Engineering design repts available from ARIX, Inc W/o encl
MARTIN, D E Low Level Waste Licensing Branch 83/05/19 TUCKER, M Energy, Dept of 1p 18854 122

8306140336 Forwards initial comments on Yuba City, AZ environ assessment of remedial actions on U mill tailings Add info needed to demonstrate that EPA regulations re protection of groundwater met
MARTIN, D E Low Level Waste Licensing Branch 83/05/20
MORLEY, J A Energy, Dept of 6pp 18854 123

8306140351 Forwards radiological assessment repts for 11 remedial action designated properties in Edgemont, SD per 830328 memo Engineering design repts available from ARIX, Inc W/o encl
MARTIN, D E Low Level Waste Licensing Branch 83/05/20,
THIELIS, J Energy, Dept of 1p 18844 337

8306140364 Forwards comments on working copy of environ assessment of remedial action on U mill tailings at Naturita site Compliance w/EPA stds for groundwater impossible to assess
MARTIN, D E Low Level Waste Licensing Branch, 83/05/20,
MORLEY, J A Energy, Dept of 6pp 18854 152

8306140695 Responds to 830622 comments on Green River remedial action concept paper Revised paper will be submitted
MORLEY, J A Energy, Dept of 83/05/25 MARTIN, D E Low Level Waste Licensing Branch 3pp 18854 001

8306150229 Forwards 830525 ltr requesting determination of new technical & economic data significance & draft outline of DES suppl for South Salt Lake tailings
MATTHEWS, M L Energy, Dept of 83/05/26 MARTIN, D NRC - No Detailed Affiliation Given 3pp 18870 035

8306150233 Forwards comments on Apr 1983 draft, "Surface Gamma Ray Measurement Protocol for Small Parcels on Open Lands," Opportunity to review & concur w/final version prior to issuance requested
MARTIN, D E, Low Level Waste Licensing Branch 83/05/31 WHITE, M O Energy, Dept of 3pp. 18870 038

8306160642 Forwards environ assessment & action description memo for remedial action activities planned for vicinity properties in Edgemont, SD Proposed action will remove U mill tailings & return tailings to TVA millsite or disposal site
TUCKER, M K Energy, Dept of. 83/06/06 BAUBLITZ, J E Energy, Dept of 9pp 18876 263

8306170446 Forwards radiological assessment repts for 15 properties in Edgemont, SD where residual radiological matl detected Remedial action needed for properties w/residual matl levels above applicable EPA stds
MARTIN, D E Low Level Waste Licensing Branch 03066. 83/06/06.
BAUBLITZ, J Energy, Dept of 2pp 18907.328

8306200012 Forwards "Economic Impact of Remedial Action Options, Vitro Tailings Site, City of South Salt Lake, UT " Rept will be included in suppl to DES & FES Comments requested by 830617
MATTHEWS, M L Energy, Dept of 83/06/08 MARTIN, D NRC - No Detailed Affiliation Given 1p 18909 001

--8306200013 "Economic Impact of Remedial Action Options, Vitro Tailings Site, City of South Salt Lake, UT "
* Jacobs Engineering Group, Inc 83/06/06 60pp 18909.002

8306200415 Notice of availability of draft technical position on "Solubility & Speciation of Radionuclide Compounds for High Level Waste Repository Safety Assessments "
MILLER, H J High Level Waste Technical Development Branch 83/05/23. 2pp. 18919 268

--8306200419 "Assessment of Radionuclide Solubilities by Conservative Estimation of Concentration NRC Technical Position "
* High Level Waste Technical Development Branch. 83/05/23 33pp 18919 270

NONDOCKETED ITEMS

8306210423 Forwards K Hamill casework status summary rept on Rifle, CO UHTRAP site Removal of milestone for providing comments on DOE notice of intent to publish EIS requested w/o encl
MARTIN, D E Low Level Waste Licensing Branch 83/05/27
BROWNING, R E Division of Waste Management 1p 18936 362

8306210428 Discusses license amend & other documentation necessary to accommodate disposal of vicinity property matls
TUCKER, M K Energy, Dept of 83/06/01 SMITH, D Uranium Recovery Field Office 2pp 18937 031

8306220164 Forwards DOE 830517 response & 830503 request for clarification of DOE position on use of disposal sites by commercial waste generators
BROWNING, R E Division of Waste Management 83/06/13 KERR, G W Office of State Programs, Director CUNNINGHAM, R Division of Fuel Cycle & Material Safety 1p 18937 325

--8306220173 Responds to request for clarification of DOE position on use of disposal sites by commercial waste generators Details of testimony presented at Senate Judiciary Committee 830302 hearing submitted
COFFMAN, F E Energy, Dept of 83/05/17 BROWNING, R E Division of Waste Management 1p 18937 324

--8306220176 Requests clarification of DOE position presented at Senate Judiciary Committee 830302 hearing re use of disposal sites by commercial waste generators
BROWNING, R E Division of Waste Management 83/05/03
COFFMAN, F E Energy, Dept. of 1p 18937 327

8306220169 Forwards info on six Grand Junction site properties designated for remedial action due to contamination w/ residual radioactive matl Properties outside Grand Junction site being identified & radiologically examined
BAUBLITZ, J E Energy, Dept of 83/06/10 HIGGINBOTHAM, L Low Level Waste Licensing Branch 13pp 18937 292

8306220208 Forwards 830603 updated UHTRAP environ assessment schedule
ARTHUR, J Energy, Dept of 83/06/08 MARTIN, D NRC - No Detailed Affiliation Given 2pp 18931 021

8306220211 Advises that NRC comments on draft remedial action concept paper (RACP) for Riverton, WY, incorporated into revised RACP
MORLEY, J A Energy, Dept of 83/06/08 MARTIN, D Low Level Waste Licensing Branch 1p 18931 020

8306220287 Forwards listing of UHTRAP documentation delivered to U Fuel Licensing Branch on 830606
KALHAN, K L Low Level Waste Licensing Branch 83/06/11
MARTIN, D E Low Level Waste Licensing Branch 9pp 18977 309

8306240179 Forwards, for review, Salt Lake City, UT EIS section on public & agency comments & responses to comments Seismic, land value & hydrology addendum sections should receive review priority
MATTHEWS, M L Energy, Dept of 83/06/17 MARTIN, D NRC - No Detailed Affiliation Given 77pp 18999 241

8306240297 Designates 15 Edgemont vicinity properties as contaminated areas needing remedial action Total number of Edgemont vicinity properties so designated is 30 Remedial action should be completed during 1983 const season
COFFMAN, F E Energy, Dept of NE-24 83/06/15 ROMATOWSKI, R D Energy, Dept of 1p 18999 187

8306240385 Discusses requirements for waste classification & waste form published in FR Technical position papers on radwaste classification & waste form encl
HIGGINBOTHAM, L Low Level Waste Licensing Branch 83/05/11 Low Level Waste Licensing Branch 27pp 18998 329

8306240398 Concurs w/issuance of Mar 1983 versions of remedial action concept papers for Grand Junction & Rifle inactive U mill tailings sites
HIGGINBOTHAM, L Low Level Waste Licensing Branch 83/04/21
MORLEY, J A Energy, Dept of 1p 18987 353

8306240482 Forwards 830601 updated schedule for UHTRAP EIS
ARTHUR, J Energy, Dept of 83/06/15 MARTIN, D NRC - No Detailed Affiliation Given 2pp 18998 069

8306240486 Trip rept of attendance at American Chemical Soc 830320-25 meetings in Seattle, WA re geochemical behavior of disposed radwaste
STARMER, R J., BROOKS, D J High Level Waste Technical Development Branch 83/04/20 JUBTUS, P S High Level Waste Technical Development Branch, 7pp 18998 073

8306280098 Notification of 830421 meeting w/Harline Oil Co in Bethesda, MD to discuss potential U mine & mill complex in
Pittsylvania County, VA
MARTIN, D E Low Level Waste Licensing Branch 83/04/20
DAVIS, J G, MAUSSHARDT, D, BROWNING, R E NRC No Detailed Affiliation Given 2pp 19036 360

8306280280 Forwards notice of availability of NRC draft technical position "Solubility & Specification of Radionuclide Compounds for High Level Waste Repository Safety Assessments"
MILLER, H J High Level Waste Technical Development Branch 83/05/26
FELTON, J M Division of Rules and Records 1p 19327 001

--8306280291 "Solubility & Specification of Radionuclide Compounds for High Level Waste Repository Safety Assessments," draft technical position
* High Level Waste Technical Development Branch 83/06/30 21pp 19327 004

XPORTLIC EXPORT AND IMPORT LICENSES

8306020580 Application to amend export license changing quantity to 703 047 kg U-235, contained in 26,007 kg U & O 162 kg U-235, contained in 5.0 kg U & reflecting that matl is of Australian origin
HANNETT, B A Transnuclear, Inc RBU-395 83/05/17 MOORE, H Office of International Programs, Director 1p 18715 065

8306020593 License for Transnuclear, Inc to export 593 200 kg U-235, contained in 19,793 kg U & O 243 kg U-235, contained in 6 kg U, to Sweden
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards RBU-433 83/05/23 2pp 18715 059

8306020597 Amend 2 to GA Co export license, changing name of licensee & ultimate consignee & extending expiration date to 861201
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards IEL-1013 83/05/24 1p 18715 058

8306020615 Executive Branch position re Milco Intl, Inc application to export 440,000 lb greensalt to Israel Application should be returned w/o action
DEVINE, J B State, Dept of 83/05/18 SHEA, J R Office of International Programs, Director 1p 18715 049

8306020623 Amend 2 to GA Co export license, changing name of licensee & ultimate consignee & extending expiration date to 861201
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards IEL-980 83/05/25 1p 18702 356

8306020628 Amend 3 to Edlow Intl Co license, increasing quantity of bulk tritium gas exported to 40,000 Ci, for export to United Kingdom
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/05/23 1p 18716 338

8306020645 Executive Branch position re Reactor Experiments, Inc amend application to export 11.5 mg Pu-239, as metal disks encapsulated in nickel to Japan License should be granted
DEVINE, J B State, Dept of 83/05/16 SHEA, J R Office of International Programs, Director 1p 18716 277

8306020653 Forwards Exxon Nuclear Corp request for amend to export license increasing quantity of matl exported to West Germany
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/05/19 RAYMOND, J Energy, Dept of 1p 18716 269

--8306020659 Application to amend license, increasing quantity of U hexafluoride for export to West Germany
KIEL, G R Exxon Nuclear Co, Inc (subs of Exxon Corp) 83/05/10
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 1p 18716 270

8306020663 Informs that C Itoh & Co 830510 application for license to export 200 guide thimble tubes to Japan meets requirements of Atomic Energy Act License issued w/o 15 day waiting period
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/05/13 Assistant Director for Export/Import & International Safeguards 1p 18716 255

8306020670 Application to amend export licenses extending expiration date to 861201 & changing ultimate consignee
MCWRY, W R GA Technologies, Inc /General Atomic Co IEL-4078 83/05/17
ZIMMERMAN, J Assistant Director for Export/Import & International Safeguards 2pp 18716 247

NONDOCKETED ITEMS

461

- 830602067 Requests formal action re issuance or denial of export license applications
SCHIMMEL, R L Monsanto Research Corp RLS-2160 83/01/10
Office of Nuclear Material Safety & Safeguards, Director 3pp
18715 340
- 830602068 Informs that License XSNM-2028 may be issued No matl changed circumstances since issuance of License XSNM-1912
MOORE, R N Assistant Director for Export/Import & International Safeguards 83/05/19 Assistant Director for Export/Import & International Safeguards 1p 18715 327
- 8306030011 Executive Branch position re Edlow Intl Co application for amend to export license, increasing quantity of bulk tritium gas Amend should be issued
DEVINE, J B State, Dept of, Bureau of Oceans & Intl Environ & Scientific Affairs 83/05/16 SHEA, J R Office of International Programs, Director 1p 18733 140
- 8306030051 Forwards application for license to export nuclear fuel elements to Taiwan
KIEL, G R Exxon Nuclear Co, Inc (subs of Exxon Corp) 83/05/06
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 1p 18733 197
- 8306030060 Application for license to export 3,163 kg U-235, contained in 76,762 kg U in fuel assemblies, to Taiwan
KIEL, G R Exxon Nuclear Co, Inc (subs of Exxon Corp) 83/05/06 1p 18733 190
- 8306030083 Application to amend license to export, incorporating listed info & components & extending expiration date to 830630
WILSON, B D General Electric Co BOW-059-83 83/05/11
WRIGHT, B L Assistant Director for Export/Import & International Safeguards 2pp 18733 267
- 8306030117 Informs that Amend 2 to License XSNM-1977 may be issued No matl changed circumstances since issuance of Amend 1 to License XSNM-1912
MOORE, R N Assistant Director for Export/Import & International Safeguards 83/05/23 Assistant Director for Export/Import & International Safeguards 1p 18733 303
- 8306030160 Application to amend export license, extending expiration date to 840630
BRUSH, P N Hoke, Inc 83/05/23 HEMBRY, E NRC - No Detailed Affiliation Given 1p 18733 314
- 8306030165 Application to amend export license, adding listed ultimate consignees for Zircaloy 4 tube shells
BUONOCORE, J A Mitsui & Co (USA), Inc (subs of Mitsui & Co, Ltd) 83/05/20 NRC - No Detailed Affiliation Given 1p 18733 315
- 8306030169 Telescope application to amend export license, changing address of ultimate & intermediate consignees
FOSTER, C M Edlow International Co 83/05/24 WRIGHT, B Assistant Director for Export/Import & International Safeguards 1p 18733 316
- 8306030174 Amend 1 to OE & OE Technical Svcs Co, Inc export license, deleting two intermediate consignees, changing address of remaining intermediate consignee, adding two parties to export & extending expiration date to 840630
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards BOW-059-83 83/05/26 1p 18733 317
- 8306030219 License for M&T Chemical, Inc to export 1000 kg natural thorium to Australia, Canada, France, Japan, The Netherlands, United Kingdom & West Germany
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards ROB 83/05/26 1p 18733 346
- 8306030276 License for Exxon Nuclear Co, Inc to export miscellaneous parts & components for use in nuclear reactors to France
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/05/26, 1p 18733 347
- 8306030247 Amend 1 to Exxon Nuclear Co, Inc license, increasing valve of export to West Germany
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/05/24 1p 18734 044
- 8306030474 Forwards FR notice re "Applications for Licenses to Import/Export Nuclear Facilities or Matls," for publication in FR
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/05/23 COMBS, T R Office of the Secretary of the Commission 1p 18735 282
- 8306030478 Notice of applications for licenses to import/export nuclear facilities or matls
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/05/23 2pp 18735 283
- 8306060354 Application for license to import 500,000 kg U, enriched to 4% U-235
HARKON, D W Braunkohle Transport & Storage, Inc 83/05/10
MOORE, R N Assistant Director for Export/Import & International Safeguards 1p 18748 335
- 8306090008 Amend 1 to Edlow Intl Co export license, changing ultimate & intermediate consignee addresses
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards HSA-JA-2 (KLK-1) 83/05/31 1p 18798 010
- 8306090009 Amend 1 to Westinghouse export license, adding intermediate consignee
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards ZE0257 83/05/26 1p 18798 009
- 8306090012 Application to amend export license increasing max U enrichment to 3.55%, increasing U-235 to 2,944 kg, changing U hexafluoride to U dioxide sintered pellets & adding party to export
HERSCH, M M Westinghouse Electric Corp MMH-376, 83/05/25
ZIMMERMAN, J V Office of International Programs, Director 1p 18798 008
- 8306090181 License for Westinghouse to export three electrical penetration feed-through assembly parts, including support matl, to Switzerland
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards ZE 10503 83/05/31 1p 18797 113
- 8306140260 Application for license to export two Zircaloy tube shells to Japan End use statement encl
BUONOCORE, J A Mitsui & Co, Ltd 136300 83/05/25 3pp 18844 300
- 8306140267 Amend 8 to Edlow Intl Co export license, authorizing retransfer of 200 uCi Cf-252 source from United Kingdom to Israel
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards TRC-4 83/06/01 1p 18844 303
- 8306140271 Amend 2 to Hoke, Inc export license, extending expiration date until 840630
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards HNL-101 83/06/01 1p 18844 304
- 8306140274 License for Transnuclear, Inc to import 17,000 kg U, enriched to 0.8% U-235, from France
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/05/31 1p 18844 305
- 8306140281 Advises that proposed import of 17,000 kg U, enriched to 0.8% U-235, from France conforms w/std shipping provisions & will not be inimical to common defense & security & does not constitute undue risk to public health & safety
MOORE, R N Office of International Programs, Director 83/06/01
Director's Office, Office of Inspection and Enforcement 1p 18844 309
- 8306140288 Application for license to import 52,000 kg U, enriched to 3.85% U-235, from France
KIEL, G R Exxon Nuclear Co, Inc (subs of Exxon Corp), 83/05/20,
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 2pp 18844 313
- 8306140290 Application for license to import test specimens, in form of solid oxides or fluorides securely bonded to metal backings, from Belgium Fissionable deposits will be used for fission rate measurements to test nuclear data
PEVEY, L E Commerce, Dept of, National Bureau of Standards 83/05/25 Assistant Director for Export/Import & International Safeguards 1p 18844 308
- 8306140298 Application for license to import test specimens, in form of solid oxides or fluorides securely bonded to metal backings, from Belgium Fissionable deposits will be used for fission rate measurements to test nuclear data
PEVEY, L E Commerce, Dept of, National Bureau of Standards, 83/05/25 Assistant Director for Export/Import & International Safeguards 1p 18844 332
- 8306140309 Requests Executive Branch position re Westinghouse application for license to export BNM to Yugoslavia
Westinghouse 830525 ltr superseded 830311 request
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/06/01 STOIBER, C R State, Dept of, Bureau of Oceans & Intl Environ & Scientific Affairs 1p 18854 079

NONDOCKETED ITEMS

8306140374 Application for license to import 19.9 kg U-enriched to 5/ U-235, from France
STEVENSON, R L Ledoux & Co, Inc 83/05/24 WRIGHT, B L Assistant Director for Export/Import & International Safeguards 2pp 18844 353

--8111040442 Amend 3 to License 29-01442-01, authorizing use of Pu & U-235 for instrument calibr & lab sample analysis
WRIGHT, E G Division of Fuel Cycle & Material Safety 78/05/19 2pp 18844 355

8306150271 License for NBS to export Cf-252, as ceramic oxide pellets, to Peoples Republic of China
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/06/02 1p 18869 361

8306150337 Application to amend export license changing ultimate consignee
HANNETT, B A Transnuclear, Inc TNP-429 83/06/03 MOORE, N Office of International Programs, Director 1p 18868 347

8306150340 Application to amend export license increasing quantity of U-235 to 1,513 kg, contained in 44,900 total U, to West Germany
MARCHEL, J European Communities, Commission of 83/06/01 GRIFFIN, J A Energy, Dept of 1p 18868 348

8306150343 Application to amend export license extending license to 840701
WONIAK, D R Carpenter Technology Corp 83/06/01 HENBY, E Assistant Director for Export/Import & International Safeguards 1p 18868 349.

8306150345 Application to amend export license extending license to 840630
BRUSH, P N Hoke, Inc 83/06/02 HENBY, E NRC - No Detailed Affiliation Given 1p 18868 350

8306150348 Application to amend license to export in-core detectors, control rod drive parts & miscellaneous unspecified parts for replacing existing items in Tarapur reactor to India
WILSON, B D General Electric Co BDW-066-83 83/06/03 HENBY, E O NRC - No Detailed Affiliation Given 2pp 18868 351

8306150424 Application for amend to import license, increasing quantity to 18,700 kg U-enriched to 1.0% U-235
HANNETT, B A Transnuclear, Inc, INP-434 83/05/26 MOORE, N Office of International Programs, Director 1p 18868 357

8306150451 Amend 1 to Nuclear Metals, Inc export license, increasing quantity of matl authorized to 40,000 kg depleted U for export to United Kingdom
PETERSON, M R Assistant Director for Export/Import & International Safeguards 83/06/07 1p 18868 358

8306150493 Application for license to export miscellaneous fuel hardware to West Germany
* General Electric Co BDW-067-83 83/06/03 1p 18868 359

8306150457 Amend 1 to Mitsui & Co, Inc export license, adding Ohi Unit 2 & Genkai Unit 2 as facilities authorized to receive Zircaloy 2 & 4 tube shells
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/06/01 1p 18868 360

8306150458 Application for license to export two Zircaloy tube shells to Japan
BUONOCORE, J A Mitsui & Co, Ltd 126300 83/05/25 3pp 18869 001

8306150459 Application for license to export 803 kg U-235, contained in 26,185 kg U, to Japan
OKADA, B Mitsui & Co, Ltd MBK-01-R1 83/06/01 1p 18868 361

8306150462 Application for license to export proportional counter, Model RB-P1-0809-101 & compensated ionization chamber, Model RS-C1-2314-113 to South Korea
SKARUPA, J D Reuter-Stokes, Inc. A-9507 83/06/03 5pp 18869 201

8306150463 Forwards application for license to export enriched U hexafluoride to Japan
NEKI, M Marubeni America Corp (subs of Marubeni Corp.) 83/06/03 WRIGHT, B L Assistant Director for Export/Import & International Safeguards 1p 18869 212

--8306150465 Application for license to export 723 kg U-235, as U hexafluoride, to Japan
* Marubeni America Corp (subs of Marubeni Corp.), ZH0298-1W 83/06/03, 1p 18869 213

8306150467 Application for license to export Pu-242, contained in 5 g solution of 5 molar nitric acid, to Japan
FOSTER, C M Edlow International Co SM18-13 83/06/06 1p 18869 219

8306150468 Ltr of assurance re export of 695 kg U-235, contained in 23,714 kg U, to Japan
SHIRAKAWA, T Japan, Govt of 83/05/25 GRIFFIN, J A Energy, Dept of 1p 18869 220

8306150470 Forwards FR notice of applications for licenses to export nuclear facilities or matls
PETERSON, M R Assistant Director for Export/Import & International Safeguards 83/06/08 COMBS, T R Correspondence & Records Branch 1p 18854 333

--8306150475 Notice of applications for licenses to export nuclear facilities or matls
PETERSON, M R Assistant Director for Export/Import & International Safeguards 83/06/08 2pp 18854 334

8306160285 License for Exxon Nuclear Co to import 26,000 kg U-enriched to 3.30% U-235, from France
ZIMMERMAN, J V Office of International Programs, Director 83/06/13 1p 18893 025

8306160290 Forwards applications for export licenses for minor nuclear export Ltr of assurance required W/o encl
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/06/13 RAYMOND, J J Energy, Dept of 2pp 18892 361

8306160624 Application for license to export 156 kg U-235, contained in 5,171 U, to Japan
OKADA, B Mitsui & Co (USA), Inc (subs of Mitsui & Co, Ltd) MBK-HI-R9 (B) 83/06/07 1p 18884 314

8306160628 Application to amend license to export, increasing quantity to 12,270 kg U-235, contained in 27,026 kg U, to Japan
MARCHEL, J European Communities, Commission of 83/06/01 GRIFFIN, J A Energy, Dept of 1p 18884 313

8306160636 Amend 1 to Nuclear Metals, Inc export license, increasing quantity of matl to 1,000 kg depleted U, contained in U blanks
PETERSON, M R Assistant Director for Export/Import & International Safeguards I-201-71 83/06/10 1p 18884 345

8306160640 Amend 1 to Carpenter Technology Corp export license, extending expiration date to 840701
PETERSON, M R Assistant Director for Export/Import & International Safeguards CARTECH-SPD 102 83/06/07 1p 18884 341

8306160646 Application for license to export 10 pieces Zircaloy-4 guide thimble tubes to Japan
BANGERTER, D H Sandvik Special Metals Corp SSM-31014 83/06/07 1p 18884 282

8306160653 Application for license to export 790 pieces Zircaloy-4 guide thimble tubes to Japan
BANGERTER, D H Sandvik Special Metals Corp SSM-31012 83/06/07 1p 18884 356

8306160659 Application for license to export 10 pieces Zircaloy-4 guide thimble tubes to Japan
BANGERTER, D H Sandvik Special Metals Corp SSM-31013 83/06/07 1p 18884 352

8306160661 Application for license to export 340 pieces Zircaloy-4 guide thimble tubes to Japan
BANGERTER, D H Sandvik Special Metals Corp SSM-31009 83/06/07 1p 18884 361

8306160668 Application for license to export 300 pieces zirconium tubing to West Germany
WILSON, B D General Electric Co BDW-068-83 83/06/06 1p 18884 360

8306160672 Application for license to export 1.68 g U, contained in 1.8065 g U-235, to Japan
POCHAL, W F Westinghouse Electric Corp ZE-60272 83/06/10 1p 18884 359

8306160684 Forwards application for license to export enriched U hexafluoride to Japan
NEKI, M Marubeni America Corp (subs of Marubeni Corp.) 83/06/03 WRIGHT, B L Assistant Director for Export/Import & International Safeguards 1p 18876 291.

NONDOCKETED ITEMS

--8306160615 Application for license to export 181 kg U-235, as enriched U hexafluoride to Japan
NAKAMURA N Marubeni America Corp (subs of Marubeni Corp)
ZHO298 TW 83/06/03 2pp 18976 192

8306160617 Application for license to export two U-238 calibr plates, contained in wood case to Peoples Republic of China
* Teledyne Isotopes 83/06/07 1p 18876 290

8306160716 Application to amend export license, adding addl ultimate consignee
MARCHAL J European Communities, Commission of 83/06/07
GRIFFIN, J A Energy, Dept of 1p 18876 287

8306160720 Application to amend license to export, increasing quantity to 25 049 kg U-235, contained in 55 174 kg U, to Japan
MARCHAL J European Communities, Commission of 83/06/01
GRIFFIN J A Energy, Dept of 1p 18876 286

8306160723 Forwards application for export license for minor nuclear export Ltr of assurance required
PETERSON, M R Assistant Director for Export/Import & International Safeguards 83/06/13 RAYMOND, J J Energy, Dept of 1p 18876 284

--8306160724 Application for license to export 803 kg U-235, contained in 26 187 kg U, to Japan
OKADA, S Mitsui & Co (USA), Inc (subs of Mitsui & Co, Ltd)
MRK-01-R1 83/06/01 1p 18876 285

8306200063 forwards Transnuclear, Inc application for export license for minor nuclear export Ltr of assurance required
ZIMMERMAN J V Assistant Director for Export/Import & International Safeguards 83/06/13 RAYMOND, J J Energy, Dept of 1p 18908 307

8306210374 license for GE to export one specially designed automatic pellet insp sys to West Germany
PETERSON, M R Assistant Director for Export/Import & International Safeguards 8306-83-008 83/06/07 1p 18937 085

8306210380 license for GE to export one specially designed automatic pellet insp sys to Belgium
PETERSON, M R Assistant Director for Export/Import & International Safeguards 8306-83-007 83/06/07 1p 18937 084

8306210414 Amend 3 to Hoke, Inc export license, extending expiration date to 840630
PETERSON, M R Assistant Director for Export/Import & International Safeguards 1126-R1 83/06/09 1p 18937 067

8306210431 Ltr of assurance correcting export license application number license number should be XU 896B rather than XU 886B
LEE, S T Korea, Republic of (South Korea) 83/06/01 GRIFFIN, J A Energy, Dept of 2pp 18936 360

8306220270 License for Reuter-Stokes, Inc to export one proportional counter, Model RS-P1-0809-101 & one compensated ionization chamber, Model RS-C1-2314-113, to South Korea
PETERSON, M R Assistant Director for Export/Import & International Safeguards A-9207 83/06/09 1p 18931 049

8306230023 Advises of issuance of license for Reuter-Stokes, Inc to export two neutron monitoring devices to South Korea w/o 15-day waiting period
PETERSON, M R Assistant Director for Export/Import & International Safeguards 83/06/09 Assistant Director for Export/Import & International Safeguards 1p 18982 027

8306240019 Application for license to export two fulljet stainless steel nozzles to Japan
SAITO, T Mitsubishi International Corp (subs of Mitsubishi Corp)
64-7764-83 83/06/08 1p 18987 292

8306240061 Submits Ofc of Intl Programs findings re 8306160724 application to import 25 2 kg U-enriched to 93 16% U-235, from Canada License should be issued
MOORE, R N Office of International Programs, Director 83/06/13 Office of International Programs, Director 1p 18999 190

8306240325 Requests Executive Branch position re GE 830603 application for license amend to export replacement components to India
PETERSON, M R Assistant Director for Export/Import & International Safeguards 83/06/09 STOIDER, C R State, Dept of, Bureau of Oceans & Intl Environ & Scientific Affairs 1p 18999 206

8306240362 license for Transnuclear, Inc to import 18,700 kg U-enriched to 1 10% U-235, from France
ZIMMERMAN, J V Office of International Programs, Director 83/06/13 1p 18998 361

8306280027 License for B&W to import 25 2 kg U, containing up to 23 5 kg U-235, from Canada
ZIMMERMAN, J V Office of International Programs, Director 83/06/14 2pp 19042 356

8306280258 forwards application for license to export 25,000 kg U depleted U tails, in form of U hexafluoride, to Taiwan
MACNAB, W V NUS Corp MP-WUM-83-050 83/06/10 HEMBY, E Office of International Programs, Director 1p

--8306280261 Application for license to export 25,000 kg U depleted U tails, in form of U hexafluoride, to Taiwan End use statement encl
MCLEOD, N B NUS Corp NUS-2793 83/06/13 3pp

PERSONAL AUTHOR INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
AAMODT, M	8306090297	50-289 G	ALBANESE, J R	8306010094	50-201 P	ANDONINI, O C	8306160064*	50-528
AAMODT, M	8306150427	50-289 G	ALDEN, W M	8306160379	50-277 R	ANDONINI, O C	8306170356	50-528
AAMODT, M H	8306060190	50-289 G	ALDEN, W M	8306170163	50-277 R	ANDONINI, O C	8306170360*	50-528
AAMODT, M M	8306220068	50-289 G	ALDEN, W M	8306210076	50-277 R	ANDONINI, O C	8306230292	50-528
AAMODT, M H	8306220147	50-289 G	ALEXANDER, I	8306160243*	50-206 G	ANDREWS, W B	8306020131	NUREQ
AAMODT, N O	8306070420	50-289 G	ALEXANDER, J F	8306150381*	50-322 G	ANDRUB, N J	8306200067	40-4492
AAMODT, N O	8306220142	50-289 G	ALEXICH, M P	8306070208	50-315 P	ANO, H P	8306170023*	50-389
AARON, J	8306170423	50-276 B	ALEXICH, M P	8306170129	50-315 G	ANO, H P	8306290424*	50-389
ABELSON, H	8306020620	50-461 A	ALEXICH, M P	8306210068*	50-315 G	ANTHONY, R C	8306270038	50-352
ABELSON, H	8306240138	50-352 A	ALEXICH, M P	8306210167	50-315 P	ANTHONY, R C.	8306270038	50-352
ACTON, R U	8306020016	NUREQ	ALEXICH, M P	8306230333	50-315 F	APLEY, W J	8306020134	NUREQ
ADAMETZ, J M	8306060097*	50-244 P	ALLAN, J M	8306060222	State Prog	ARAND, J	8306210089	50-373
ADAMONIS, D C	8306160906*	50-145 G	ALLAN, J M	8306060287	50-412 G	ARAND, J J	8306210192	50-373
ADAMS, L T	8306130370*	50-331 B	ALLAN, J M	8306090041	50-219 G	ARAND, J J	8306210263	50-373
ADAMS, R E	8306270146	NUREQ	ALLAN, J M	8306140632	50-273 G	ARCHITZEL, R E	8306010324*	50-317
ADAMS, R H	8306140549*	50-324 G	ALLAN, J M	8306140658	50-412 G	ARIAS, J	8306210177	50-251
ADAMS, S R	8306020011	NUREQ	ALLAN, J M	8306170008	50-244 F	ARIAS, J	8306270200	50-251
ADENBAM, C G	8306020062	50-329 E	ALLAN, J M	8306170038	50-333 F	ARIAS, J	8306280168	50-250
ADENBAM, E G	8306020601	50-329 A	ALLAN, J M	8306170260	50-309 F	ARLOTTI, M G.	8306140598	50-286
ADENBAM, E G	8306030910	50-329 C	ALLAN, J M	8306200101	State Prog	ARLOTTI, M G.	8306200402*	50-286
ADENBAM, E G	8306070428	50-370 P	ALLAN, J M	8306210145	50-219 G	ARNOLD, R C	8306140600	50-320
ADENBAM, E G	8306070433	50-369 F	ALLAN, J M	8306210149*	50-219 G	ARNOLD, A L	8306010478	RES
ADENBAM, E G	8306070434*	50-370 P	ALLAN, J M	8306220149	50-410 G	ARTHUR, J	8306020192	HABTE MO
ADENBAM, E G	8306140287	50-390 A	ALLAN, J M	8306220154*	50-410 G	ARTHUR, J	8306020194	HABTE MO
ADENBAM, E G	8306140299	50-328 P	ALLAN, J M	8306220155	50-387 G	ARTHUR, J	8306220208	HABTE MO
ADENBAM, E G	8306150510	50-327 F	ALLAN, J M	8306220157*	50-387 G	ARTHUR, J.	8306240482	HABTE MO
ADENBAM, E G	8306160277	50-369 P	ALLAN, J M	8306280473	70-364	AGHE, J	8306240229*	04997
ADENBAM, E G	8306210406	50-369 P	ALLEN, R E	8306160468	REGO	ABITON, A H	8306220192*	CONTRACT
ADENBAM, E G	8306240017	50-460 A	ALLING, M E	8306020184*	50-271 P	ABELSTINE, D	8306270278*	50-289
ADENBAM, E G	8306280029	50-369 P	ALTENBACH, T J	8306150617	NUREQ	ATWOOD, M D	8306130243	40-8722
ADENBAM, E G	8306280064	50-329 E	AMADON, P W	8306080215	50-358 G	AU, T Y	8306010372	50-352
ADENBAM, C G	8306290135*	50-356 A	AMADON, P W	8306080250	50-358 G	AU, T Y	8306010380*	50-352
ADLER, R W	8306070271	50-289 G	AMES, K R	8306030000	NUREQ	AUDIN, L	8306230123	50-14
ADLER, R W	8306070407*	50-289 G	AMICO, P	8211220337*	50-245 P	AULUCK, R	8306070481	50-397
ADLER, R W	8306220046	50-289 G	AMICO, P J	8306020440*	50-247 G	AUSTIN, O	8306140412	50-295
ADRAGNA, J M	8306160155	FOIA	AMICO, P J	8306020452*	50-247 G	AUSTIN, M A	8306200020	70-135
AFTERGOOD, B	8306030459	FOIA	AMOROSE, A A	8306230018*	FOIA	AUTIO, H A	8306170033	50-29
AFTERGOOD, B	8306170379*	50-142 T	AMOROSE, M L	8306230016*	FOIA	AUTIO, H A	8306170418	50-29
AFTERGOOD, B	8306170390*	50-142 T	AMOROSE, A	8305240612*	COMMISSION	AUTIO, H A	8306280107	50-29
AFTERGOOD, B	8306170417*	50-142 T	AMOROSE, A	8305240624*	COMMISSION	AUTIO, H A	8306280144	50-29
AFTERGOOD, B	8306170426*	50-142 T	AMSTUTZ, S	8306060095	50-155 R	AUTIO, H H	8306170339	50-29
AGNIHOTRI, N K	8306030373	FOIA	AMSTUTZ, S	8306140564	50-155 R	AXELRAD, J	8306010066	50-219
AHEARNE, J	8306070021*	50-206 P	ANANDAPPA, A	8306070279	50-249 S	AXELRAD, J	8306010183	I&E
AHEARNE, J	8306270281*	50-289 G	ANDERSEN, M	8306200223	50-331 R	AXELRAD, J	8306010310	50-269
AHEARNE, J F.	8306070028*	50-206 P	ANDERSON, A B	8306230166*	FOIA	AXELRAD, J	8306020179	50-221
AHEARNE, J F.	8306170449	COMMISSION	ANDERSON, A B	8306230166*	FOIA	AXELRAD, J	8306140416	I&E
AHEARNE, J F	8306220198	50-272 P	ANDERSON, C	8306020376	50-354 G	AXELRAD, J	8306140696	50-416
AHEARNE, J F	8306220264*	50-320 P	ANDERSON, C	8306060170*	50-277 G	AXELRAD, J	8306200149	50-254
AHMED, I	8306100266*	50-374 G	ANDERSON, C	8306200086*	50-423 G	AXELRAD, J	8306210131	I&E
AHMED, N	8306080252*	50-335 P	ANDERSON, C R	8306240302*	50-244 P	AXELRAD, J	8306300106	50-324
AHMED, N	8306150266*	50-259 P	ANDERSON, D J	8306140426*	CONTRACT	AXELRAD, J	8306300115	I&E
AHRENS, P	8306090218	50-309 G	ANDERSON, R L	8306140583*	50-416 G	AXELRAD, J A.	8306150278	50-387
AHRENS, P	8306100193	50-309 G	ANDERSON, S L	8306010094	50-201 P	AXELRAD, J A	8306210430	50-219
AHRENS, P	8306100205*	50-309 G	ANDONINI, O C	8306010363	50-528 G	AXELRAD, J A	8306220135	50-298
AKERS, D W.	8306080161	50-335 P	ANDONINI, O C	8306070432	70-2784	AXELRAD, J A	8306220137	50-361

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
AXELRAD, J A	8306220144	50-237 G	BARRETT, L H	8306160643	50-320 R	BAYNE, J P	8306210144	50-286 P
AXELRAD, J A	8306220204	50-313 G	BARRETT, L H	8306160682	50-320 P	BAYNE, J P	8306210170	50-286 P
AXELRAD, J A	8306220218	50-237 G	BARRETT, L H	8306200031	50-320 R	BAYNE, J P	8306230170	50-333 P
AXELRAD, J A	8306220271	40-8698	BARRETT, L H	8306200044	50-320 R	BAYNE, J P	8306280508	50-333 P
AXELRAD, J A	8306220274	40-8681	BARRETT, L H	8306280220*	50-320 P	BEACH, J P	8306090325	50-247 F
AXELSON, W	8306100212*	50-341 G	BARRETT, L H	8306280658	50-320 R	BEATY, W R	8306160322*	50-483 G
AXELSON, W L	8306130412*	50-254 G	BARRETT, P A	8306030151*	50-440 G	BEATY, W R	8306160322*	50-483 G
AZARM, H	8306280044	NUREQ	BASKIN, K P	8306060138*	50-358 G	BECK, O P	8306270140	50-498 G
BACHMANN, R G	8306080081	50-155 G	BASKIN, K P	8306200033	50-358 G	BECK, R H	8306230494*	CONTRACT
BACHMANN, R G	8306150391	50-170 G	BASKIN, K P	8306240267	50-358 G	BECKER, D D	8306090342	50-454 G
BACHMANN, R G	8306170363	50-155 G	BASKIN, K P	8306280090	50-400 G	BECKER, M	8306070473	NUREQ
BACKUS, R A	8306010444	50-443 G	BASKIN, K P	8306070313	50-361 P	BECKHAM, J T	8306010367	50-366 P
BACKUS, R A	8306200291	FOIA	BASKIN, K P	8306080020	50-361 P	BECKHAM, J T	8306010367	50-366 P
BACKUS, R A	8306200293*	FOIA	BASKIN, K P	8306090156	50-361 P	BECKHAM, J T	8306140493*	50-321 V
BACKUS, R A	8306290521	50-443 G	BASKIN, K P	8306130386	50-206 P	BECKHAM, J T	8306140563	50-366 G
BACKUS, R A	8306290521	50-443 G	BASKIN, K P	8306140444	50-361 P	BECKHAM, J T	8306140743*	50-321 G
BACKUS, R A	8306290532	50-443 G	BASKIN, K P	8306140444	50-361 P	BECKHAM, J T	8306220002	50-321 P
BACKUS, R A	8306290532	50-443 G	BASKIN, K P	8306150303	50-206 P	BECKHAM, J T	8306270120	50-366 P
BADIA, A	8306230020*	FOIA	BASKIN, K P	8306200156	50-206 P	BECKHAM, J T	8306290264	50-321 G
BADIA, A	8306230025*	FOIA	BASKIN, K P	8306270362	50-361 P	BECKHAM, J T	8306290265*	50-321 G
BADINO, A	8306080307	50-358 A	BASKIN, K P	8306270415	50-206 P	BECKHAM, J T	8306290455	50-321 G
BAER, R E	8306080079*	50-382 G	BASKIN, K P	8306270415	50-361 P	BECKHAM, J T	8306300085	50-321 G
BAILEY	8306230452	50-334 S	BASS, O W	8306090157	50-259 G	BECKHAM, J T	8306300085	50-321 G
BAILEY, R J	8306070044*	50-219 G	BASSO, L F	8306010277	50-317 S	BECKHAM, J T	8306300085	50-321 G
BAIR, O G	8306070071	50-344 S	BASSO, L F	8306210046	50-318 S	BECKHAM, J T	8306300085	50-321 G
BAIR, O G	8306170193	50-344 S	BASSO, L F	8306210086	50-317 S	BECKHAM, J T	8306300085	50-321 G
BAIR, O G	8306170317	50-344 S	BASSO, L F	8306210097	50-318 S	BECKHAM, J T	8306300085	50-321 G
BAIRDEN, L	8306210391	CONTRACT	BASSO, L F	8306210101	50-317 S	BECKHAM, J T	8306300085	50-321 G
BAKER, T	8306060307*	70-25	BASSO, L F	8306210159	50-318 S	BECKHAM, J T	8306300085	50-321 G
BALARAM, J	8306070473	NUREQ	BATES, J W	8306140575*	70-1113	BECKHAM, J T	8306300085	50-321 G
BALL, D M	8306020231	WASTE MGT	BATTERSON, S	8306020139	50-29 R	BECKHAM, J T	8306300085	50-321 G
BALL, J C	8306280093	NUREQ	BATTERSON, S	8306020152	50-309 R	BECKHAM, J T	8306300085	50-321 G
BALLARD, T A	8306220351*	50-331 P	BATTERSON, S	8306160382	50-29 R	BECKHAM, J T	8306300085	50-321 G
BALLINGER, P L	8306020148	50-298 R	BATTERSON, S	8306160444	50-309 R	BECKHAM, J T	8306300085	50-321 G
BALLINGER, P L	8306130339	50-298 S	BATY, D	8306140604	50-272 H	BECKHAM, J T	8306300085	50-321 G
BALLINGER, P L	8306160477	50-298 R	BAUBLITZ, J E	8306010103	40-84	BECKHAM, J T	8306300085	50-321 G
BALLINGER, P L	8306160480	50-298 R	BAUBLITZ, J E	8306020255	WASTE MGT	BECKHAM, J T	8306300085	50-321 G
BALLINGER, P L	8306160494	50-298 S	BAUBLITZ, J E	8306220169	WASTE MGT	BECKHAM, J T	8306300085	50-321 G
BANDY, R	8306030435	REB	BAUER, E G	8306010239*	50-352 A	BECKHAM, J T	8306300085	50-321 G
BANGART, R L	8306010107*	50-313 G	BAUER, E G	8306140606	50-352 E	BECKHAM, J T	8306300085	50-321 G
BANGART, R L	8306010356*	50-498 G	BAUER, E G	8306270264*	50-277 P	BECKHAM, J T	8306300085	50-321 G
BANGART, R L	8306070318	MISC	BAUER, R H	8306020117	50-373 F	BECKHAM, J T	8306300085	50-321 G
BANGART, R L	8306140636*	50-382 G	BAUM, A S	8306230501*	50-320 P	BECKHAM, J T	8306300085	50-321 G
BANGART, R L	8306210239	MISC	BAUNACK, W H	8306230199*	50-244 G	BECKHAM, J T	8306300085	50-321 G
BANGART, R L	8306240180	QA999	BAUSER, D B	8306220108	50-400 G	BECKHAM, J T	8306300085	50-321 G
BANGART, R L	8306240204*	QA999	BAUSER, D B	8306220111*	50-400 G	BECKHAM, J T	8306300085	50-321 G
BANGERTER, D H	8306160646	XPORTLIC	BAUSER, D B	8306220111*	50-400 G	BECKHAM, J T	8306300085	50-321 G
BANGERTER, D H	8306160653	XPORTLIC	BAUSER, D B	8306220111*	50-400 G	BECKHAM, J T	8306300085	50-321 G
BANGERTER, D H	8306160659	XPORTLIC	BAUSER, D B	8306220111*	50-400 G	BECKHAM, J T	8306300085	50-321 G
BANGERTER, D H	8306160661	XPORTLIC	BAUSER, D B	8306220111*	50-400 G	BECKHAM, J T	8306300085	50-321 G
BARAN, R	8306020090	50-219 R	BAUSER, D B	8306220111*	50-400 G	BECKHAM, J T	8306300085	50-321 G
BARANOW, S W	8306130308	50-329 A	BAUSER, D B	8306220111*	50-400 G	BECKHAM, J T	8306300085	50-321 G
BARANOW, S W	8306130444	TOPREP	BAUSER, D B	8306220111*	50-400 G	BECKHAM, J T	8306300085	50-321 G
BARANOW, S W	8306230121	50-329 A	BAUSER, D B	8306220111*	50-400 G	BECKHAM, J T	8306300085	50-321 G
BARANOW, S W	8306270262	50-329 A	BAUSER, D B	8306220111*	50-400 G	BECKHAM, J T	8306300085	50-321 G
BARANOW, S W	8306270271	50-329 V	BAUSER, D B	8306220111*	50-400 G	BECKHAM, J T	8306300085	50-321 G
BARANOW, S W	8306270309	50-329 A	BAUSER, D B	8306220111*	50-400 G	BECKHAM, J T	8306300085	50-321 G
BARATTA, A J	8306070452	NUREQ	BAUSER, D B	8306220111*	50-400 G	BECKHAM, J T	8306300085	50-321 G
BARBER, O	8306010310	50-269 G	BAUSER, D B	8306220111*	50-400 G	BECKHAM, J T	8306300085	50-321 G
BARBER, O	8306020179	50-321 G	BAUSER, D B	8306220111*	50-400 G	BECKHAM, J T	8306300085	50-321 G
BARBER, O	8306200149	50-254 G	BAUSER, D B	8306220111*	50-400 G	BECKHAM, J T	8306300085	50-321 G
BARBER, O	8306300106	50-324 S	BAUSER, D B	8306220111*	50-400 G	BECKHAM, J T	8306300085	50-321 G
BARHAM, C D	8306210082	50-324 J	BAUSER, D B	8306220111*	50-400 G	BECKHAM, J T	8306300085	50-321 G
BARHAM, C W	8306210109	50-324 J	BAUSER, D B	8306220111*	50-400 G	BECKHAM, J T	8306300085	50-321 G
BARLETTA, R E	8306010088	NUREQ	BAUSER, D B	8306220111*	50-400 G	BECKHAM, J T	8306300085	50-321 G
BARLETTA, R E	8306020066	NUREQ	BAUSER, D B	8306220111*	50-400 G	BECKHAM, J T	8306300085	50-321 G
BARNES, C	8306080309	50-148 P	BAUSER, D B	8306220111*	50-400 G	BECKHAM, J T	8306300085	50-321 G
BARNES, I	8306210031*	QA999	BAUSER, D B	8306220111*	50-400 G	BECKHAM, J T	8306300085	50-321 G
BARNES, I	8306210238*	QA999	BAUSER, D B	8306220111*	50-400 G	BECKHAM, J T	8306300085	50-321 G
BARNES, I	8306270456*	QA999	BAUSER, D B	8306220111*	50-400 G	BECKHAM, J T	8306300085	50-321 G
BARNES, P L	8306100094	50-237 G	BAUSER, D B	8306220111*	50-400 G	BECKHAM, J T	8306300085	50-321 G
BARNES, P L	8306170380	50-237 G	BAUSER, D B	8306220111*	50-400 G	BECKHAM, J T	8306300085	50-321 G
BARNES, P L	8306280377	50-304 G	BAUSER, D B	8306220111*	50-400 G	BECKHAM, J T	8306300085	50-321 G
BARNETT, T	8306010450	50-247 G	BAUSER, D B	8306220111*	50-400 G	BECKHAM, J T	8306300085	50-321 G
BARR, K	8306150008*	50-289 G	BAUSER, D B	8306220111*	50-400 G	BECKHAM, J T	8306300085	50-321 G
BARR, K	8306170345	70-143	BAUSER, D B	8306220111*	50-400 G	BECKHAM, J T	8306300085	50-321 G
BARR, K P	8306140357*	70-1113	BAUSER, D B	8306220111*	50-400 G	BECKHAM, J T	8306300085	50-321 G
BARR, K P	8306140477*	50-348 G	BAUSER, D B	8306220111*	50-400 G	BECKHAM, J T	8306300085	50-321 G
BARR, K P	8306270228*	50-259 G	BAUSER, D B	8306220111*	50-400 G	BECKHAM, J T	8306300085	50-321 G
BARR, K P	8306290244*	50-416 G	BAUSER, D B	8306220111*	50-400 G	BECKHAM, J T	8306300085	50-321 G
BARR, K P	8306290297*	50-259 G	BAUSER, D B	8306220111*	50-400 G	BECKHAM, J T	8306300085	50-321 G
BARR, K P	8306290380*	50-302 G	BAUSER, D B	8306220111*	50-400 G	BECKHAM, J T	8306300085	50-321 G
BARR, K R	8306060266*	50-320 G	BAUSER, D B	8306220111*	50-400 G	BECKHAM, J T	8306300085	50-321 G
BARRETT, L H	8306020008	50-320 G	BAUSER, D B	8306220111*	50-400 G	BECKHAM, J T	8306300085	50-321 G
BARRETT, L H	8306020654	50-320 R	BAUSER, D B	8306220111*	50-400 G	BECKHAM, J T	8306300085	50-321 G

PERSONAL AUTHOR INDEX

46

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
BIAN, S H	8306020134	MUREQ	BOMBERGER, C	8305200714*	50-305 P	BOUCHEY, Q D	8306010413	50-397
BIBB, H E	8306290225*	50-389 Q	BOMBERGER, C	8306020037*	50-309 P	BOUCHEY, Q D	8306080026	70-2950
BIBB, H E	8306290379*	50-335 Q	BOMBERGER, C	8306020196*	50-302 P	BOUCHEY, Q D	8306080039	50-397
BIDEN, J R	8306190543*	50-272 U	BOMBERGER, C	8306030310*	50-317 P	BOUCHEY, Q D	8306090207	50-508
BIDINGER, Q H	8306080056*	70-2910	BOMBERGER, C	8306080252*	50-335 P	BOUCHEY, Q D	8306090262	50-460
BIDINGER, Q H	8306080396*	70-2838	BOMBERGER, C	8306110424*	50-219 P	BOUCHEY, Q D	8306100117	50-508
BIDINGER, Q H	8306190335*	70-1257	BOMBERGER, C	8306190266*	50-289 P	BOUCHEY, Q D	8306130004	50-397
BIDINGER, Q H	8306210440*	70-143	BOMBERGER, C R	8306030070*	50-338 P	BOUCHEY, Q D	8306140612	50-460
BIDINGER, Q H	8306290687*	70-2375	BOMBERGER, C R	8306060329*	50-277 P	BOUCHEY, Q D	8306200243	50-397
BIELAWSKI, A P.	8306060196*	50-454 Q	BOOK, H	8306280303	50-528 Q	BOUCHEY, Q D	8306210120	50-397
BIELAWSKI, A P	8306060196*	50-454 Q	BOOK, H	8306280507*	50-397 Q	BOUCHEY, Q D	8306210184	50-508
BIELAWSKI, A P	8306190402	50-454 Q	BOOK, H E	8306010159	50-361 Q	BOUCHEY, Q D	8306230373	50-508
BIELAWSKI, A P	8306190402	50-454 Q	BOOK, H E	8306070009	50-344 Q	BOUCHEY, Q D	8306240339	70-2950
BIELAWSKI, A P	8306190420	50-454 Q	BOOK, H E	8306070011*	50-344 Q	BOUCHEY, Q D	8306240460	70-2950
BIELAWSKI, A P	8306190420	50-454 Q	BOOK, H E	8306070176*	50-312 Q	BOUCHEY, Q D	8306270347	50-397
BIELAWSKI, A P	8306270041	50-454 Q	BOOK, H E	8306070285	50-243 Q	BOUCHEY, Q D	8306280453	50-397
BIELAWSKI, A P	8306270041	50-454 Q	BOOK, H E	8306070287*	50-243 Q	BOUKNIGHT, R J	8306070202	50-395
BIER, J	8306080232	50-155 Q	BOOK, H E	8306070333	50-206 Q	BOUKNIGHT, R J	8306100163	50-395
BIER, J A	8306080235*	50-155 Q	BOOK, H E	8306070339*	50-206 Q	BOUKNIGHT, R J	8306100261	50-395
BILEK, N L	8306210293	FOIA	BOOK, H E	8306280137	50-528 Q	BOUKNIGHT, R J	8306210021	50-395
BINGHAM, W G	8306070107*	50-529 S	BOOK, H E	8306280145*	50-528 Q	BOUKNIGHT, R J	8306210209	50-395
BISBEE, Q D	8306010342	50-443 Q	BOOK, H E	8306280171	50-89 Q	BOUKNIGHT, R J	8306300156	50-395
BISBEE, Q D	8306010384	50-443 Q	BOOK, H E	8306280185*	50-89 Q	BURNIA, A	8306240406	50-370
BISHOP, D J	8306190064	50-272 P	BOOK, H E	8306280310*	50-528 Q	BOUTROS, F O.	8306140737*	50-289
BISHOP, L L	8306010443*	50-443 Q	BOOK, H E	8306280503	50-397 Q	BOWMAKER, N J	8306070229	50-317
BISHOP, R H	8304110936	50-245 I	BOOK, H E	8306280620	50-344 Q	BOWMAKER, N J	8306280465*	50-317
BISHOP, T W	8306070093	50-275 Q	BOOK, H E	8306280632*	50-344 Q	BOWMAN, H E	8306070077	50-317
BISHOP, T W	8306070240	50-206 Q	BOOK, H E	8306290080*	50-141 W	BOHYER, J E	8306170155*	FOIA
BISHOP, T W	8306070251	50-206 Q	BOOKER, J E	8306010394	50-458 S	BOHYER, J E.	8306170147*	FOIA
BISHOP, T W	8306070360	50-275 Q	BOOKER, J E	8306010423	50-458 S	BOHYER, J E	8306170170*	FOIA
BISHOP, T W	8306070361	50-361 Q	BOOKER, J E	8306070195	50-458 S	BOHYER, J E	8306170174*	FOIA
BISHOP, T W	8306270342*	50-275 Q	BOOKER, J E	8306070196	50-458 S	BOHYER, J E	8306170178*	FOIA
BISHOP, T W	8306280187	50-275 Q	BOOKER, J E	8306070265	50-458 S	BOHYER, J E	8306170185*	FOIA
BISHOP, T W	8306280477	50-206 Q	BOOKER, J E	8306090038	50-458 S	BOHYER, J E	8306170190*	FOIA
BISHOP, T W	8306280490	50-361 Q	BOOKER, J E	8306090365	50-458 S	BOHYER, J E	8306170198*	FOIA
BISHOP, T W	8306280546	50-361 Q	BOOKER, J E	8306130317	50-458 S	BOHYER, J E.	8306170203*	FOIA
BISHOP, T W	8306300083	50-275 Q	BOOKER, J E	8306130376	50-458 S	BOHYER, J E.	8306170208*	FOIA
BISSONNETTE, P	8306070294*	0A999	BOOKER, J E	8306160353	50-458 S	BOHYER, J E.	8306170212*	FOIA
BLACK, G A	8306020017	70-124	BOOKER, J E	8306160439	50-458 S	BOHYER, J E	8306170220*	FOIA
BLACKBURN, T A	8306240208*	50-206 P	BOOKER, J E	8306160520	50-458 S	BOHYER, J E	8306170225*	FOIA
BLAIR, Q O	8306010073	50-344 S	BOOKER, J E	8306160521	50-458 S	BOHYER, J E	8306170235*	FOIA
BLAKE, E L	8306010454	50-289 Q	BOOKER, J E	8306160531	50-458 S	BOHYER, J E	8306170238*	FOIA
BLAKE, E L	8306010454	50-289 Q	BOOKER, J E	8306170395	50-458 S	BOHYER, J E	8306170242*	FOIA
BLAKE, E L	8306030327	50-289 Q	BOOKER, J E	8306270095	50-458 S	BOHYER, J E	8306170244*	FOIA
BLAKE, E L	8306070211	50-289 Q	BOOKER, J E	8306270130	50-458 S	BOHYER, J E	8306170248*	FOIA
BLAKE, E L	8306090211	50-289 Q	BOOKER, J E	8306270156	50-458 S	BOHYER, J E	8306170252*	FOIA
BLAKE, E L	8306130390	50-289 Q	BOOKER, J E	8306270391	50-458 S	BOHYER, J E	8306170258*	FOIA
BLAKE, E L	8306150410	50-289 Q	BOOKER, J E	8306280328	50-458 A	BOHYER, J E.	8306170262*	FOIA
BLAKE, E L	8306150410	50-289 Q	BOOKER, J E	8306280335	50-458 S	BOHYER, J E.	8306170267*	FOIA
BLAKE, E L	8306220071	50-209 Q	BOOKER, J E	8306300121	50-458 S	BOHYER, J E.	8306170269*	FOIA
BLAKE, E L	8306220071	50-289 Q	BOOKER, J E	8306300148	50-458 S	BOHYER, J E	8306170272*	FOIA
BLAKE, E L	8306300087	50-289 Q	BOOKER, J M	8306280013	MUREQ	BOHYER, J E	8306170274*	FOIA
BLAKE, E L	8306300087	50-289 Q	BORCHERT, R	8306280430	50-336 B	BOHYER, J E	8306170280*	FOIA
BLAKE, J J	8306140139*	50-438 Q	BORDENICK, B M.	83062002181	50-322 Q	BOHYER, J E	8306170284*	FOIA
BLAKE, J J	8306140349*	50-335 Q	BORDENICK, B M.	8306060312	50-322 Q	BOHYER, J E	8306170288*	FOIA
BLAKE, J J	8306140439*	50-424 Q	BORDENICK, B M.	83061100240	50-322 Q	BOYD, D	8306220040	50-295
BLAKE, J J.	8306140511*	50-413 Q	BORDENICK, B M.	83061100242*	50-322 Q	BOYD, D C.	8306060221*	50-295
BLAKE, J J	8306140522*	50-321 Q	BORDENICK, B M.	8306130387	50-322 Q	BOYD, D C	8306300021*	50-255
BLAKE, J J	8306140652*	50-338 Q	BORDENICK, B M.	8306150211	50-322 Q	BOYER, V B.	8306060157	50-277
BLAKE, J J	8306290192*	50-413 Q	BORDENICK, B M.	8306150214*	50-322 Q	BOYER, V B	8306160609*	50-352
BLAKE, J J	8306290235*	50-438 Q	BORDENICK, B M.	8306150250	50-322 Q	BOYLE, R	8306150216	50-201
BLAKE, J J	8306290332*	50-321 Q	BORDENICK, B M.	8306230004	50-322 Q	BOYLE, R	8306030244	HASTE M9
BLAKE, J J	8306290357*	50-250 Q	BORDENICK, B M	8306240273	50-410 Q	BOYLE, R	8306240116*	FOIA
BLAKE, J J	8306290424*	50-389 Q	BORDENICK, B M	8306240278	50-410 Q	BRADBURY, R. B.	8306160347	MUREQ
BLANCHARD, D P.	8306280559	50-155 P	BORDENICK, B M.	8306240355	50-410 Q	BRADFORD, P. A.	8306160118*	FOIA
BLAND, W M	8306160401	MUREQ	BORDENICK, B M	8306300070	50-322 Q	BRADFORD, W H	8306290222*	50-348
BLENNER, E B	8306130398	50-322 Q	BORDINE, T	8306010362	50-155 P	BRADLEY, E. J.	8306010233	50-352
BLENNER, T E	8306020080	MUREQ	BORDINE, T C	8305260226	50-155 R	BRADLEY, E. J.	8306010292	50-352
BLETZACKER, R. W	8306070352*	50-413 F	BORDINE, T C	8305260265	50-155 R	BRADLEY, E. J	8306070239	50-352
BLIX, H	8306160156*	FOIA	BORDINE, T C	8306020283	50-155 P	BRADLEY, E. J.	8306070330	50-352
BLOCH, P B	8306280552	50-155 Q	BORDINE, T C	8306060144	50-155 P	BRADLEY, E. J.	8306100065	50-352
BLOCH, P B	8306280556	50-445 Q	BORDINE, T C	8306190003	50-155 P	BRADLEY, E. J.	8306100109	50-352
BLOUGH, A R	8306030312*	50-277 Q	BORDINE, T C	8306160380	50-155 P	BRADLEY, E. J.	8306100110	50-352
BLOUGH, A R	8306070226*	50-277 Q	BORDINE, T C	8306210173	50-155 F	BRADLEY, E. J.	8306100241	50-352
BLOUGH, R E	8306200107	40-3453	BORDINE, T C	8306230241	50-155 S	BRADLEY, E. J.	8306140395	50-352
BOARDMAN, J R	8306060060*	50-498 Q	BORDINE, T C	8306240004	50-155 P	BRADLEY, E. J.	8306140545	50-352
BOARDMAN, J R	8306060122*	50-498 Q	BORDINE, T C	8306270123	50-155 P	BRADLEY, E. J.	8306140624	50-352
BOGART, D. S	8306230447	50-302 R	BORDINE, T C	8306270376	50-155 Q	BRADLEY, E. J.	8306160001	50-352
BOGDEN, G.	8306200074	40-1162	BORN, Q S	8306230282	50-182 S	BRADLEY, E. J.	8306160371	50-352
BOGDEN, G.	8306230032	40-8684	BORYSIAK, M	8306210084	50-346 S	BRADLEY, E. J.	8306160377	50-352
BOGEN, P. E.	8306060101*	50-358 E	BOSTROM, D D	8306230404*	0A999	BRADLEY, E. J.	8306160537	50-352
BOHL, L S	8306070171*	0A999	BOUCHEY, Q D	8306280556*	50-397 A	BRADLEY, E. J.	8306160572	50-352
BOHL, L S	8306210028*	0A999	BOUCHEY, Q D	8306010236	50-397 A	BRADLEY, E. J.	8306170210	50-352
BOHNER, E A	8306280382	50-546 D	BOUCHEY, Q D	8306010249	50-397 A	BRADLEY, E. J.	8306170309	50-352
BOLTZ, D H	8306100230*	50-445 Q	BOUCHEY, Q D.	8306010400	50-397 F	BRADLEY, E. J.	8306170369	50-352

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
RADLEY, E. J.	8306200117	50-352 A	BROWN, G. D.	8306090172	40-8663	CAIN, C. L.	8306090138*	40-8698
RADLEY, E. J.	8306200183	50-352 F	BROWN, G. D.	8306130353	MISC	CAIN, C. L.	8306090175*	40-8698
RADLEY, E. J.	8306200317	50-352 E	BROWN, G. D.	8306160362*	50-298 0	CAIN, C. L.	8306160124*	FOIA
RADLEY, E. J.	8306210283	50-352 E	BROWN, H. H.	8306060184	50-322 0	CAIN, C. L.	8306160132*	FOIA
RADLEY, E. J.	8306270086	50-352 E	BROWN, H. H.	8306060184	50-322 0	CAIN, J. M.	8306060120*	50-382 I
RADLEY, E. J.	8306270212	50-352 A	BROWN, H. H.	8306080169	50-322 0	CALDWELL, R. A.	8306240148*	50-274 0
RADLEY, E. J.	8306270261	50-277 P	BROWN, H. H.	8306080169	50-322 0	CALLAN, L. J.	8306140363*	50-313 0
RADLEY, E. J.	8306270264*	50-277 P	BROWN, H. H.	8306090216	50-322 0	CALLAN, L. J.	8306160317	50-313 8
RADLEY, E. J.	8306270340	50-352 E	BROWN, H. H.	8306090216	50-322 0	CALLAN, L. J.	8306160644	50-313 5
RADLEY, E. J.	8306270365	50-352 A	BROWN, H. H.	8306150397	50-322 0	CALLIHAN, D.	8306200294	50-454 0
RADLEY, E. J.	8306270423	50-352 A	BROWN, H. H.	8306150397	50-322 0	CAMERON, C. A.	8306100121	PT21
RADLEY, E. J.	8306270459	50-352 A	BROWN, J. M.	8306200486*	FOIA	CAMP, A. L.	8306010144	NUREQ
RADLEY, E. J.	8306280389	50-352 A	BROWN, K. J.	8306130367	40-8745	CAMPBELL, D. R.	8306240312*	50-244 P
RADLEY, E. J.	8306300016	50-352 E	BROWN, M. W.	8306270281*	CONTRACT	CAMPBELL, D. R.	8306200139	50-259 S
RADLEY, E. J.	8306300024	50-352 A	BROWN, P.	8306010107*	50-313 0	CAMPBELL, K.	8306280013	NUREQ
IRADLEY, E. J.	8306300133	50-352 A	BROWN, R. L.	8306060073*	50-458 0	CAMPBELL, L. D.	8306210277	50-373 8
IRADLEY, E. J.	8306300200	50-352 E	BROWN, S. W.	8306230038*	FOIA	CANDIA, G. R.	8306280433*	70-1402
IRADLEY, E. J.	8306300221	50-352 A	BROWNING, R. E.	8306030438	WASTE MGT	CANTRELL, F. S.	8306070043	50-259 8
IRADY, J. A.	8306220298*	50-289 F	BROWNING, R. E.	8306220164	WASTE MGT	CANTRELL, F. S.	8306140297*	50-259 0
IRADY, R. J.	8306160162*	FOIA	BROWNING, R. E.	8306220176*	WASTE MGT	CANTRELL, F. S.	8306140383*	50-416 0
IRAGO, J. B.	8306100086	50-247 0	BROWNING, R. E.	8306240155*	FOIA	CANTRELL, F. S.	8306290222*	50-348 0
IRADLE, L. W.	8306080168	NUREQ	BROWNING, R. E.	8306240163*	FOIA	CANTWELL, P. F.	8306210234	50-304 8
IRAMLETT, L. B.	8306020150	50-348 R	BROWNLEE, V. L.	8306100176	50-413 8	CANTWELL, P. F.	8306270168	50-295 8
IRAMLETT, L. B.	8306160474	50-348 R	BROWNLEE, V. L.	8306140469*	50-302 0	CAPHTON, D. L.	8306070146*	50-317 0
IRANCH, M. W.	8306270289*	50-409 0	BROWNLEE, V. L.	8306290293*	50-321 0	CAREW, J. F.	8306220403*	TOPREF
IRAND, D. A.	8306210080	50-133 0	BROWNLEE, V. L.	8306290305*	50-413 0	CAREW, J. F.	8306010478	RES
IRAND, D. A.	8306210162	50-275 R	BRUGGER, R.	8306150165	50-186 F	CAREY, J. J.	8306020218	50-334 R
IRANDENBURG, B.	8306270414	50-247 0	BRUSH, P. N.	8306030160	XPORTLIC	CAREY, J. J.	8306030303*	50-334 0
IRANDENBURG, B.	8306150429	50-247 0	BRUSH, P. N.	8306150345	XPORTLIC	CAREY, J. J.	8306070076	50-334 F
IRANDENBURG, B.	8306200342	50-247 T	BUCHANAN, C. R.	8306170194*	FOIA	CAREY, J. J.	8306070264	50-334 F
IRANDENBURG, B.	8306230376	50-247 0	BUCHANAN, C. R.	8306170229*	FOIA	CAREY, J. J.	8306090189	50-334 F
IRANDENBURG, B.	8306270160	50-247 0	BUDZIK, D. M.	8306160443	REGOD	CAREY, J. J.	8306090368	50-334 P
IRANDT, C. T.	8306080241*	50-443 0	BUDZIK, D. M.	8306160468	REGOD	CAREY, J. J.	8306140620	50-334 0
IRANNEN, W. A.	8306140737*	50-289 F	BUE, J. L.	8306070273	50-302 8	CAREY, J. J.	8306140639	50-334 P
IRANNIN, J. F.	8306210081	50-389 S	BULLOCK, S. V.	8306060249	PR	CAREY, J. J.	8306160476	50-334 R
IRANNIN, J. P.	8306010116	50-389 S	BUNTING, J. D.	8306240039*	FOIA	CAREY, J. J.	8306200334	50-334 P
IRANNIN, J. P.	8306070058	50-389 S	BUNTING, J. D.	8306240047*	FOIA	CAREY, J. J.	8306280435	50-334 0
IRANNIN, J. P.	8306070181	50-389 S	BUNNOCORE, J. A.	8306030165	XPORTLIC	CAREY, J. J.	8306280495*	50-334 0
IRANNIN, J. P.	8306220014	50-389 S	BUNNOCORE, J. A.	8306140260	XPORTLIC	CAREY, J. J.	8306300209	PR
IRANIZER, J. B.	8306140005	50-462 8	BUNNOCORE, J. A.	8306150458	XPORTLIC	CARLISLE, C. B.	8306010220	50-397 8
IRENNEMAN, F.	8306280203	1&E	BURDOIN, J. F.	8306070007*	50-528 0	CARLISLE, C. B.	8306010368	50-397 0
IRENNER, L.	8306020351	50-352 0	BURDOIN, J. F.	8306070367*	50-276 0	CARLISLE, C. B.	8306020104*	50-397 0
IRENNER, L.	8306030286	50-352 0	BURDOIN, J. F.	8306280226*	50-312 0	CARLISLE, C. B.	8306070095	50-397 8
IRENNER, L.	8306080151	50-352 0	BURGER, F. J.	8306170068	50-271 R	CARLISLE, C. B.	8306270333*	50-397 8
IRENNER, L.	8306080167	50-352 0	BURKE, D. J.	8306140627*	50-280 0	CARLBON, J. D.	8306280194*	50-275 0
IRENNER, L.	8306100195	50-352 0	BURNETT, P. T.	8306290319*	50-369 0	CARLBON, R. T.	8306230147*	50-6 0
IRENNER, L.	8306270144	50-322 0	BURNETT, R. F.	8306160178*	FOIA	CARPENTER, J. H.	8306010439	50-400 0
IREY, H. L.	8306070103	50-267 P	BURNETT, R. F.	8306160190*	FOIA	CARPENTER, J. H.	8306220090	50-400 0
IREY, H. L.	8306160286	50-267 0	BURNETT, R. F.	8306210354	NUREQ	CARPENTER, T.	8306080215	50-358 0
IREY, H. L.	8306160541	50-267 P	BURNS, J. B.	8306080385	ADVCM	CARPENTER, T.	8306080250	50-358 0
IREY, H. L.	8306210011	50-267 0	BURNS, R.	8306010237	50-260 8	CARPENTER, T.	8306160046	50-204 0
IREY, H. L.	8306280334	50-267 P	BURNS, S. O.	8306240261	50-338 V	CARPENTER, T. O.	8306160273*	CONTRACT
IRICKLEY, R. H.	8306130410*	0A799	BURNS, S. O.	8306240422*	50-135 0	CARR, A. V.	8306100197	50-413 0
IRIDENBAUGH, D.	8306220141*	50-322 0	BURRIS, B. E.	8306080294*	50-410 A	CARR, A. V.	8306100197	50-413 0
IRIGOR, J. B.	8306020011	NUREQ	BURSTEIN, C. H.	8306280541*	50-382 0	CARR, A. V.	8306220092	50-413 0
IRIGHT, G. D.	8306010439	50-400 0	BURSTEIN, C. H.	8306280541*	50-382 0	CARR, A. V.	8306290459	50-413 0
IRIGHT, G. D.	8306160616	50-142 0	BURSTEIN, S.	8306020208	50-266 8	CARR, A. V.	8306290461*	50-413 0
IRIGHT, G. D.	8306220090	50-400 0	BURSTEIN, S.	8306130146	50-266 0	CARR, A. V.	8306290464*	50-413 0
IRIBBT, G. E.	8306170011	50-317 S	BURSTEIN, S.	8306160460	REGOD	CARR, J. C.	8306160223*	50-204 0
IRODFELD, B.	8306080312*	50-410 A	BURSTEIN, S.	8306210207	50-301 8	CARR, J. C.	8306160276*	50-204 0
IROEHL, D. J.	8306070207	50-344 P	BURSTEIN, S.	8306280397	50-266 P	CARR, J. C.	8306160301*	50-204 0
IROEHL, D. J.	8306070211*	50-344 P	BURWELL, S. B.	8306220170	50-445 A	CARROW, H.	8306220125	50-400 0
IROEHL, D. J.	8306230414	REGOD	BUSCHBACH, T. C.	8305170121	NUREQ	CARRWEAUX, A. R.	8306140532*	50-329 A
IROEHL, D. J.	8306280613	50-344 P	BUSH, S. H.	8306200444	ACRS	CARTEAUX, P.	8306060185*	50-315 8
IROLIN, M. A.	8306060008	FOIA	BUSH, S. H.	8306200444	ACRS	CARTEAUX, P.	8306060273*	50-316 8
IRONB, J. C.	8306010346	50-286 8	BUTCHER, R. C.	8306070043	50-289 8	CARTER, H. L.	8306070385*	50-312 0
IRONB, J. C.	8306020430	50-286 8	BUTCHER, R. C.	8306170294	50-260 8	CARTER, R. B.	8306020454	PR
IRONB, J. C.	8306030345*	50-286 0	BUTLER, S. D.	8306140162*	50-327 0	CARTER, S.	8306130163	50-294 8
IRONB, J. C.	8306160385	50-286 R	BUTLER, S. D.	8306140390*	50-327 0	CARTER, S.	8306300181	50-260 8
IRONB, J. C.	8306200403	50-286 F	BYRD, R.	8306010244	50-416 8	CARTER, S.	8306300224	50-260 8
IRONB, J. C.	8306200411*	50-286 F	BYRD, R.	8306070004	50-416 8	CARTWRIGHT, W. B.	8306020467	50-317 8
IRONB, J. C.	8306210068	50-286 0	BYRD, R.	8306140046	50-416 8	CARTWRIGHT, W. B.	8306200089	50-317 8
IROOKS, D. J.	8306240486	WASTE MGT	BYRD, R.	8306140084	50-416 8	CARTWRIGHT, W. B.	8306200118	50-318 8
IROOKS, E.	8306270212*	50-230 0	BYRD, R.	8306140384	50-416 8	CARTWRIGHT, W. B.	8306200208	50-317 8
IROOKS, E.	8306270511*	50-390 0	BYRD, R.	8306140611	50-416 8	CARUSO, R.	8306020495	50-322 A
IROOKS, E. H.	8306140400*	50-280 0	BYRD, R.	8306200142	50-416 8	CARUSO, R.	8306130418*	50-322 0
IROPHY, J. J.	8306160194*	50-72 F	BYRD, R.	8306280471	50-416 8	CARUSO, R.	8306130477	50-322 A
IRONN, C. H.	8306060231*	50-263 0	BYRNE, J. J.	8306280355	50-416 8	CARUSO, R.	8306140118	50-322 A
IRONN, E.	8306230035*	FOIA	BYRON, J. D.	8306280216*	50-320 P	CARUSO, R.	8306290673	50-322 F
IRONN, G. D.	8306080119	40-8722	BYRON, J. D.	8306080048*	50-440 A	CARVER, A. M.	8306010014	50-328 8
IRONN, G. D.	8306080152	40-8027	BYRON, J. D.	8306290496*	50-329 A	CARVER, A. M.	8306010020	50-327 8
IRONN, G. D.	8306080181	40-8681	BYRON, P. H.	8306170035*	50-341 0	CABANAVE, M.	8306080072*	CONTRACT
IRONN, G. D.	8306090065	70-2890	CAIN, C. L.	8306080190*	40-8681	CASHATT, M. E.	8306140423*	50-324 0
IRONN, G. D.	8306090127	40-8698	CAIN, C. L.	8306080193*	40-8681	CASHATT, M. E.	8306140583*	50-416 0
IRONN, G. D.	8306090163	40-8084	CAIN, C. L.	8306090132*	40-8698	CASHWELL, R. J.	8306060272*	50-186 0

PERSONAL AUTHOR INDEX

469

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
CASTRO, O	8306170259*	CONTRACT	CHRISTEL, B	8306070246	50-237 S	CLARK, R A	8306290249	50-335 P
CASTRO, O	8306220305*	CONTRACT	CHRISTEL, B	8306130325	50-249 S	CLARK, R A	8306290249	50-339 P
CATTON, I	8306210422	ACRS	CHRISTENSEN, R	8306210375*	CONTRACT	CLARK, R A	8306290302	50-339 P
CAUSEY, J C	8306270170	50-366 P	CHRISTIANSON, W	8306230359*	50-358 Q	CLARK, R A	8306060002	FOIA
CAVANAGH, R	8306090234	50-522 Q	CHRISTMAN, J N	8306070405	50-322 Q	CLAYTON, F L	8306010331	50-348 P
CAZZOLI, E Q	8306020072	NUREG	CHRISTMAN, J N	8306160287	50-322 Q	CLAYTON, F L	8306010426	50-364 P
CERNE, A C	8306040215*	50-322 Q	CHRISTMAN, J N	8306160287	50-322 Q	CLAYTON, F L	8306030307	50-348 P
CERNE, A C	8306080263*	50-443 Q	CHRISTOFFER, Q	8306100093*	50-315 Q	CLAYTON, F L	8306060113	50-364 P
CERNE, A C	8306080264*	50-443 Q	CHRISTOFFER, Q	8306100273*	50-315 Q	CLAYTON, F L	8306060201	50-348 P
CERNE, A C	8306080264*	50-443 Q	CHRISTOFFER, Q	8306210242	50-331 S	CLAYTON, F L	8306070326	50-364 P
CERNE, A C	8306230405*	50-443 Q	CHRISTOPHER, R	8306060016*	50-354 Q	CLAYTON, F L	8306090302*	50-348 Q
CHAFFEE, A	8306280561*	50-361 Q	CHRISTOPHER, W	8306070266	50-296 S	CLAYTON, F L	8306160119	50-348 P
CHAFFEE, A E	8306280511*	50-361 Q	CHUNG, J W	8306200136*	50-387 Q	CLAYTON, F L	8306130429	50-348 P
CHAMBERS, O T	8306070084	50-260 S	CHURCHILL, B W	8306070419	50-382 Q	CLAYTON, F L	8306140071	50-348 Q
CHAMBERS, O T	8306100192	50-296 S	CHURCHILL, B W	8306070419	50-382 Q	CLAYTON, F L	8306140593	50-348 P
CHAMBERS, O T	8306210136	50-260 S	CHUTE, E	8306270256	50-443 Q	CLAYTON, F L	8306140610	50-348 P
CHAN, S F	8306020045	FOIA	CHIN, J H	8306240232*	50-322 E	CLAYTON, F L	8306160119	50-364 R
CHAN, S P	8306230024*	TOPREP	CHILTS, M	8306070176*	50-312 Q	CLAYTON, F L	8306160278	50-348 R
CHANDLER, J C	8306090045	TOPREP	CHILTS, M	8306280632*	50-344 Q	CLAYTON, F L	8306160327	50-348 Q
CHANDLER, J C	8306090154	TOPREP	CIPOLLA, A J	8306080406	40-3392	CLAYTON, F L	8306170357	50-348 Q
CHANDLER, L J	8306150230	50-275 Q	CLAPP, N E	8306280093	NUREG	CLAYTON, F L	8306280216	50-348 S
CHANDLER, L J	8306210288	50-361 Q	CLARRY, L	8306130327	50-331 S	CLAYTON, F L	8306280336	50-348 P
CHANDLER, L J	8306240275	50-275 Q	CLARK, A T	8306150216	50-201 P	CLAYTON, F L	8306280376	50-348 P
CHANDLER, L J	8306300064	50-275 Q	CLARK, A T	8306220165	PROJ	CLAYTON, F L	8306280400	50-348 P
CHANEY, H D	8306080074*	50-382 Q	CLARK, C W	8306020364	TOPREP	CLAYTON, F L	8306280429	50-348 S
CHANEY, H D	8306080133*	50-498 Q	CLARK, D	8306230201	50-259 F	CLAYTON, F L	8306280507*	50-348 Q
CHANEY, H D	8306080238*	50-313 Q	CLARK, D	8306240354	50-259 F	CLAYTON, F L	8306280966	NUREG
CHANEY, H D	8306090354*	50-285 Q	CLARK, D D	8306140253*	50-97 Q	CLAYTON, F L	8306102779	50-445 F
CHANG, D K	8306230331*	50-331 P	CLARK, D D	8306230238	50-97 F	CLEMENTS, B R	8306090312	50-445 V
CHARNLEY, J C	8306100136*	50-366 P	CLARK, L	8306200345*	50-358 Q	CLEMENTS, B R	8306090312	50-445 V
CHARNLEY, J C	8306140549*	50-324 Q	CLARK, L	8306200359*	50-258 Q	CLEMENTS, P	8306020264*	71-250
CHARNOFF, O	8306200236*	ADVCM	CLARK, L	8306290351*	50-329 Q	CLEMENTS, P	8306040267*	50-286 Q
CHARNOFF, O	8306170476	ADVCM	CLARK, P R	8306090271*	50-289 F	CLEMENTS, P	8306090336*	71-2
CHARNOFF, O	8306200048*	ADVCM	CLARK, R A	8306010003	50-285 P	CLEMENTS, P	8306230118*	70-820
CHARTERINA, J	8306020353	50-219 S	CLARK, R A	8306010036	50-317 P	CLEVELAND, J C	8306280093	NUREG
CHAUDHARY, B K	8306090151*	50-352 Q	CLARK, R A	8306010477	50-317 F	CLINE, W E	8306140244*	50-416 Q
CHAUDHARY, B K	8306150247*	50-352 Q	CLARK, R A	8306020015	50-309 P	CLINE, W E	8306270426*	50-261 Q
CHAVEZ, D	8306080143	50-454 Q	CLARK, R A	8306020805	50-309 P	CLOBIUS	8306270361	50-213 S
CHAVEZ, D	8306080143	50-454 Q	CLARK, R A	8306030012	50-336 P	CLOBIUS, G J	8306160053	50-213 F
CHAVEZ, D	8306150436*	50-454 Q	CLARK, R A	8306030067	50-338 P	CLOBIUS, G J	8306170051	50-213 S
CHAVEZ, D	8306150436*	50-454 Q	CLARK, R A	8306030073	50-313 F	CLOBIUS, G J	8306170301	50-213 S
CHAVEZ, D	8306150442*	50-454 Q	CLARK, R A	8306030089	50-309 F	CLOBIUS, G J	8306170347	50-213 S
CHAVEZ, D	8306150442*	50-454 Q	CLARK, R A	8306030231	50-309 P	COCHRAN, T B	8306220157*	50-337 Q
CHEN, C	8306200316*	50-244 P	CLARK, R A	8306030241	50-344 P	COCHRAN, T B	8306270370	50-289 H
CHENG, T M	8306170478	50-409 P	CLARK, R A	8306060092	50-336 P	COHEN, R	8306030218	50-227 S
CHIANG, N J	8306070251	50-400 S	CLARK, R A	8306060357	50-344 P	COFFEY, J A	8306070059	50-296 S
CHIANG, N J	8306280080	50-400 S	CLARK, R A	8306060371	50-317 Q	COFFEY, J A	8306160482	50-259 R
CHILDS, V	8306010312	50-333 S	CLARK, R A	8306060377	50-344 P	COFFEY, F E	8306020228	WASTE MOT
CHILK, B J	8306020343	40-2061	CLARK, R A	8306080094	50-335 P	COFFMAN, F E	8306220173*	WASTE MOT
CHILK, B J	8306020441	50-289 Q	CLARK, R A	8306080249	50-285 P	COFFMAN, F E	8306240227	WASTE MOT
CHILK, B J	8306030046	FOIA	CLARK, R A	8306080251	50-335 P	COFFMAN, F E	8306290620	50-201 P
CHILK, B J	8306030157	50-272 S	CLARK, R A	8306080332	50-344 P	COHLEN, P F	8306090258	50-322 Q
CHILK, B J	8306030239	50-370 A	CLARK, R A	8306080431	50-336 P	COHEN, I	8306010100*	50-29 Q
CHILK, B J	8306030388*	FOIA	CLARK, R A	8306070377	50-309 P	COHEN, I	8306010304*	50-271 Q
CHILK, B J	8306030499	10CFR	CLARK, R A	8306090426	50-317 P	COHEN, I	8306020389*	50-244 Q
CHILK, B J	8306030501	10CFR	CLARK, R A	8306130491	50-336 P	COLKINS, D M	8306010478	RES
CHILK, B J	8306060274	70-25	CLARK, R A	8306140352	50-336 P	COLARULLI, P F	8306070414	50-247 Q
CHILK, B J	8306060287	50-70 Q	CLARK, R A	8306140414	50-335 P	COLARULLI, P F	8306070414	50-247 Q
CHILK, B J	8306060389	10CFR	CLARK, R A	8306160197	50-285 P	COLARULLI, P F	8306150429	50-247 Q
CHILK, B J	8306070350	50-445 Q	CLARK, R A	8306160253	50-344 P	COLARULLI, P F	8306150429	50-247 Q
CHILK, B J	8306070390	50-289 Q	CLARK, R A	8306160283	50-245 P	COLARULLI, P F	8306200342	50-247 T
CHILK, B J	8306080157	50-361 Q	CLARK, R A	8306160288	50-335 P	COLARULLI, P F	8306200342	50-247 T
CHILK, B J	8306080270*	FOIA	CLARK, R A	8306160645	50-344 P	COLARULLI, P F	8306230376	50-247 Q
CHILK, B J	8306080331	50-320 Q	CLARK, R A	8306170013	50-301 Q	COLARULLI, P F	8306230376	50-247 Q
CHILK, B J	8306080439	50-322 T	CLARK, R A	8306170019*	50-301 Q	COLARULLI, P F	8306270160	50-247 Q
CHILK, B J	8306080442*	50-322 T	CLARK, R A	8306170083	50-282 P	COLARULLI, P F	8306270160	50-247 Q
CHILK, B J	8306090298	50-266 Q	CLARK, R A	8306170469	50-309 Q	COLE, R F	8306220024	50-454 Q
CHILK, B J	8306090301	50-352 Q	CLARK, R A	8306200055	50-368 P	COLE, R F	8306230362	50-454 Q
CHILK, B J	8306130427	50-498 Q	CLARK, R A	8306200059	50-313 P	COLEMAN, L S	8306200047*	50-320 H
CHILK, B J	8306130516	10CFR	CLARK, R A	8306200065	50-285 P	COLEMAN, R	8306220073	CONTRACT
CHILK, B J	8306150206	50-247 F	CLARK, R A	8306200078	50-336 P	COLEMAN, R	8306270441	CONTRACT
CHILK, B J	8306150299	50-309 Q	CLARK, R A	8306200281	50-282 P	COLEMAN, R	8306280115	CONTRACT
CHILK, B J	8306160211*	FOIA	CLARK, R A	8306210311	50-335 P	COLLINS, D J	8306200460*	50-244 Q
CHILK, B J	8306160632	50-358 Q	CLARK, R A	8306220223	50-309 P	COLLINS, D J	8306230388*	50-317 Q
CHILK, B J	8306160635	50-361 Q	CLARK, R A	8306240347	50-285 P	COLLINS, J T	8306010273	50-267 F
CHILK, B J	8306200026	50-389 P	CLARK, R A	8306240469	50-313 F	COLLINS, J T	8306270208	50-298 P
CHILK, B J	8306200030	50-247 F	CLARK, R A	8306280075*	50-285 P	COLLINS, J T	8306280242	State Proc
CHILK, B J	8306230367	50-289 Q	CLARK, R A	8306290081	50-285 P	COLLINS, S	8306140690	50-286 S
CHILK, B J	8306270265	50-289 Q	CLARK, R A	8306290086	50-339 Q	COLLINS, S	8306230212*	50-247 Q
CHILK, B J	8306270273	50-289 Q	CLARK, R A	8306290146	50-266 P	COLLINS, S	8306230334	50-311 S
CHILK, B J	8306270320	50-289 Q	CLARK, R A	8306290152	50-336 P	COLLINS, S J	8306160006*	50-271 Q
CHILK, B J	8306300143	50-352 Q	CLARK, R A	8306290158	50-285 P	COLLINS, T R	8306290244*	50-416 Q
CHIN, R Y	8306130351	50-295 S	CLARK, R A	8306290190	50-309 P	COLMBQ, R	8306210056	50-312 H
CHOKSHI, N	8306100038*	50-312 Q	CLARK, R A	8306290194	50-317 P	COLMBQ, R W	8306070067	50-312 S
CHOLEB, N C	8306130273*	50-315 Q	CLARK, R A	8306290202*	50-317 P	COLMBQ, R W	8306170293	50-312 S

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
COLONBO, R. W.	8306170359	50-312 S	COPELAND, V. G.	8306200350	50-454 Q	COUNCIL, W. G.	8306280321	50-245 P
COLONBO, R. W.	8306230396	50-312 S	COPELAND, V. G.	8306270016	50-454 Q	COUNCIL, W. G.	8306280346	50-423 S
COLONBO, R. W.	8306230410	50-312 S	COPELAND, V. G.	8306270016	50-454 Q	COUNCIL, W. G.	8306280346	50-423 S
COLON, F. P.	8306010078*	50-528 S	COPELAND, V. G.	8306270020*	50-454 Q	COUNCIL, W. G.	8306280412	50-245 P
COLMANN, P.	8306300180	PR	COPELAND, V. G.	8306270020*	50-454 Q	COUNCIL, W. G.	8306280412	50-245 P
COMBS, F.	8306060041*	FOIA	COPELAND, V. G.	8306270041	50-454 Q	COUNCIL, W. G.	8306280414	50-336 Q
COMELLA, P. A.	8306240051*	FOIA	COPELAND, V. G.	8306270173	50-155 Q	COUNCIL, W. G.	8306280414	50-336 Q
COMER, E.	8306140149	FOIA	COPELAND, V. G.	8306270173	50-155 Q	COUNCIL, W. G.	8306280478	50-245 P
COMPTON, R. M.	8306080224*	50-445 Q	COPELAND, V. G.	8306270383	50-454 Q	COUNCIL, W. G.	8306280478	50-245 P
CONKLIN, J. C.	8306280093	NUREG	COPELAND, V. G.	8306270383	50-454 Q	COUNCIL, W. G.	8306280482	50-423 S
CONLON, T. E.	8306140671*	50-413 Q	COPELAND, V. G.	8306280528	50-454 Q	COUNCIL, W. G.	8306280534	50-245 P
CONLON, T. E.	8306140180*	50-389 Q	COPELAND, V. G.	8306280528	50-454 Q	COUNCIL, W. G.	8306280534	50-245 P
CONLON, T. E.	8306140375*	50-400 Q	CORBESIA, D. M.	8306240381	71-9135	COUNCIL, W. G.	8306300140	50-245 P
CONLON, T. E.	8306140474*	50-416 Q	CORE, H. R.	8306060299	50-285 S	COUNCIL, W. G.	8306300140	50-245 P
CONLON, T. E.	8306140520*	50-389 Q	CORMIER, W. H.	8306070399	50-142 Q	COUNCIL, W. G.	8306300140	50-245 P
CONLON, T. E.	8306140692*	50-259 Q	CORMIER, W. H.	8306070416	50-142 Q	COUTURE, C.	8306170299*	50-389 P
CONLON, T. E.	8306140254*	50-440 Q	CORMIER, W. H.	8306280528	50-142 Q	COHAN, K.	83062140534*	50-329 A
CONLON, T. E.	8306290221*	50-335 Q	CORRADINI, M.	8306210398	ACRS	COHAN, R. L.	8306210153*	TOPREP
CONLON, T. E.	8306290328*	50-390 Q	CORRADINI, M.	8306210398	ACRS	COHILL, C.	8306140022	50-219 S
CONLON, T. E.	8306290371*	50-416 Q	CORT, G. E.	8306130377*	50-142 T	COHILL, C.	8306060220*	50-219 P
CONLON, T. E.	8306300132*	50-440 Q	CORT, G. E.	8306130377*	50-142 T	COX, H. T.	8306070161	50-261 S
CONN, W. Q.	8306140122	50-397 S	CORWIN, B.	8306070299	50-247 F	COX, H. T.	8306070182	50-261 S
CONNAUGHTON, K.	8306170364*	50-454 Q	CORVELL, G. P.	8306140329*	70-1201	COX, H. T.	8306200002	50-261 S
CONNER	8306140022	50-219 S	CORVELL, G. P.	8306140617*	70-824	COX, H. T.	8306200109	50-261 S
CONNER, E. L.	8306130247*	50-352 Q	COSTELLO, J. R.	8306130224*	0A999	COX, H. T.	8306200188	50-261 S
CONNER, T. B.	8306060322	50-352 Q	COSTER, W. F.	8306130398	50-322 Q	COX, N. D.	8306020011	NUREG
CONNER, T. B.	8306060322	50-352 Q	COTTER, B. P.	8306060325	50-409 Q	COYLE, L. H.	8306060040	50-237 S
CONNER, T. B.	8306070373	50-358 Q	COTTER, B. P.	8306080185	70-25	CRAFT, C. H.	8306270151	NUREG
CONNER, T. B.	8306070373	50-358 Q	COTTER, B. P.	8306220070	50-410 Q	CRAIGIN, J. G.	8306170313	50-275 P
CONNER, T. B.	8306100206	50-458 Q	COTTER, W. D.	8306060231	PR	CRAIGIN, J. G.	8306170328	50-275 P
CONNER, T. B.	8306100206	50-458 Q	COTTER, W. D.	8306060233	PR	CRANE, P. A.	8306010347	50-275 R
CONNER, T. B.	8306270294	50-410 Q	COTTINGHAM, A.	8306060313	PRM	CRANE, P. A.	8306280522	50-275 Q
CONNER, T. B.	8306270294	50-410 Q	COTTON, G. D.	8306130002	50-361 K	CRANE, P. A.	8306300041	50-275 Q
CONNER, T. B.	8306280530	50-410 Q	COUNCIL, W. G.	8306010340	50-213 P	CRANE, P. A.	8306300089*	50-275 Q
CONSTABLE, G. L.	8306130129*	50-382 Q	COUNCIL, W. G.	8306010340	50-213 P	CRANE, P. A.	8306300093*	50-275 Q
CONTE, R.	8306150008*	50-289 Q	COUNCIL, W. G.	8306010340	50-213 P	CRAWFORD, V. A.	8306150304	50-229 Q
CONWAY, J. T.	8306070359	50-247 Q	COUNCIL, W. G.	8306020449	PR	CRAWFORD, V. A.	8306150304	50-229 Q
COOK, D.	8306300043	50-254 S	COUNCIL, W. G.	8306060090	50-213 H	CREED, J.	8306210242	50-331 S
COOK, D. H.	8306280080	50-259 P	COUNCIL, W. G.	8306060090	50-213 H	CREED, J.	8306230438	50-295 S
COOK, J.	8306100017	50-333 R	COUNCIL, W. G.	8306060090	50-213 H	CREED, J.	8306230438	50-295 S
COOK, J. W.	8306030172	50-329 R	COUNCIL, W. G.	8306060098	50-336 P	CREED, J. R.	8306100093*	50-155 Q
COOK, J. W.	8306060035*	50-329 Q	COUNCIL, W. G.	8306060098	50-336 P	CREED, J. R.	8306100273*	50-315 Q
COOK, J. W.	8306070242	50-329 S	COUNCIL, W. G.	8306060143	50-423 A	CREED, J. R.	8306130319*	50-346 Q
COOK, J. W.	8306100268	50-329 A	COUNCIL, W. G.	8306060143	50-423 A	CREED, J. R.	8306210075*	50-263 Q
COOK, J. W.	8306130281	50-329 S	COUNCIL, W. G.	8306060184	50-336 F	CRENJAK, R. V.	8306290293*	50-321 Q
COOK, J. W.	8306140524	50-329 A	COUNCIL, W. G.	8306060184	50-336 F	CROCKER, H. W.	8306010100*	50-297 Q
COOK, J. W.	8306150346*	50-329 F	COUNCIL, W. G.	8306060207	50-213 P	CROCKER, H. W.	8306010304*	50-271 Q
COOK, J. W.	8306210302	50-329 S	COUNCIL, W. G.	8306060207	50-213 P	CROCKER, H. W.	8306010306*	50-213 Q
COOK, J. W.	8306300103*	50-329 A	COUNCIL, W. G.	8306060207	50-213 P	CROCKER, H. W.	8306020389*	50-244 Q
COOK, L.	8306290343	70-25	COUNCIL, W. G.	8306060243	50-213 P	CROCKER, H. W.	8306280210*	50-213 Q
COLE, D. A.	8306290611	40-6940	COUNCIL, W. G.	8306060243	50-213 P	CROFT, T. L.	8306230166*	FOIA
CONLEY, M. J.	8306010438	50-278 S	COUNCIL, W. G.	8306060263	50-245 R	CROFT, T. L.	8306230166*	FOIA
CONLEY, M. J.	8306010443*	50-278 S	COUNCIL, W. G.	8306060263	50-245 R	CROWIN, F. J.	8306280078	NUREG
CONLEY, M. J.	8306020277	50-277 S	COUNCIL, W. G.	8306070136	50-245 F	CROSSMAN, W. A.	8306010356*	50-498 Q
CONLEY, M. J.	8306020396	50-277 S	COUNCIL, W. G.	8306070136	50-245 F	CROSSMAN, W. A.	8306060060*	50-498 Q
CONLEY, M. J.	8306160379	50-277 R	COUNCIL, W. G.	8306080058	50-245 P	CROSSMAN, W. A.	8306060073*	50-458 Q
CONLEY, M. J.	8306170017	50-277 S	COUNCIL, W. G.	8306080058	50-245 P	CROSSMAN, W. A.	8306060122*	50-498 Q
CONLEY, M. J.	8306170278	50-277 S	COUNCIL, W. G.	8306090232	50-245 P	CROSSMAN, W. A.	8306060133*	50-112 Q
CONLEY, M. J.	8306200144	50-277 S	COUNCIL, W. G.	8306090232	50-245 P	CROSSMAN, W. A.	8306080074*	50-382 Q
CONLEY, M. J.	8306210076	50-277 R	COUNCIL, W. G.	8306100114	50-213 P	CROSSMAN, W. A.	8306080079*	50-382 Q
CONLEY, M. J.	8306210076	50-277 R	COUNCIL, W. G.	8306100114	50-213 P	CROSSMAN, W. A.	8306080079*	50-382 Q
COOPER, D. W.	8306280190	NUREG	COUNCIL, W. G.	8306100114	50-213 P	CROSSMAN, W. A.	8306080133*	50-498 Q
COOPER, J. H.	8306230450	PR	COUNCIL, W. G.	8306130398	50-213 F	CROSSMAN, W. A.	8306130129*	50-382 Q
COOPER, J. H.	8306010317	50-275 R	COUNCIL, W. G.	8306160412	50-213 P	CROSSMAN, W. A.	8306140636*	50-382 Q
COOPER, W. E.	8306100130	50-275 R	COUNCIL, W. G.	8306160412	50-213 P	CROSSMAN, W. A.	8306210070*	50-382 Q
COOPER, W. E.	8306170270	50-275 R	COUNCIL, W. G.	8306160412	50-213 P	CROUSE, R. P.	8306070166*	50-346 Q
COOPER, W. E.	8306170270	50-275 R	COUNCIL, W. G.	8306170231	50-213 P	CROUSE, R. P.	8306070397	50-346 Q
COOPER, W. E.	8306170312	50-275 R	COUNCIL, W. G.	8306170391	50-213 Q	CROUSE, R. P.	8306140448	50-346 Q
COOPER, W. E.	8306170310	50-275 P	COUNCIL, W. G.	8306170391	50-213 Q	CROUSE, R. P.	8306140500	50-346 Q
COOPER, W. E.	8306170328	50-275 P	COUNCIL, W. G.	8306200104	50-336 S	CROUSE, R. P.	8306170027	50-346 P
COOPER, W. E.	8306200249	50-275 R	COUNCIL, W. G.	8306200104	50-336 S	CROUSE, R. P.	8306170075	50-346 F
COOPER, W. E.	8306270416	50-275 R	COUNCIL, W. G.	8306200313*	50-245 Q	CROUSE, R. P.	8306200393	50-346 P
COOPER, W. E.	8306280449	50-275 R	COUNCIL, W. G.	8306200313*	50-245 Q	CROUSE, R. P.	8306210026	50-346 P
COOPER, W. E.	8306280483	50-275 R	COUNCIL, W. G.	8306200322*	50-245 Q	CROUSE, R. P.	8306210170*	50-346 P
COOPER, W. E.	8306220100	50-443 Q	COUNCIL, W. G.	8306200322*	50-245 Q	CROUSE, R. P.	8306220257*	50-346 P
COOPER, W. E.	8306280240	TOPREP	COUNCIL, W. G.	8306200391*	50-213 Q	CROUSE, R. P.	8306220259	50-346 F
COOPER, W. G.	8306010457	50-454 Q	COUNCIL, W. G.	8306200391*	50-213 Q	CROUSE, R. P.	8306270204	50-346 Q
COOPER, W. G.	8306010457	50-454 Q	COUNCIL, W. G.	8306230289	50-245 P	CROUSE, R. P.	8306270379	50-346 Q
COOPER, W. G.	8306020339	50-155 Q	COUNCIL, W. G.	8306230426	50-213 F	CROW, W. T.	8306060416	40-8035
COOPER, W. G.	8306020339	50-155 Q	COUNCIL, W. G.	8306240200	50-213 P	CROW, W. T.	8306080056*	70-2910
COOPER, W. G.	8306060193	50-454 Q	COUNCIL, W. G.	8306240200	50-213 P	CROW, W. T.	8306080396*	70-2838
COOPER, W. G.	8306060193	50-454 Q	COUNCIL, W. G.	8306240200	50-213 P	CROW, W. T.	8306140446*	40-8794
COOPER, W. G.	8306060196*	50-454 Q	COUNCIL, W. G.	8306270228	50-213 S	CROW, W. T.	8306150335*	70-1257
COOPER, W. G.	8306200304	50-454 Q	COUNCIL, W. G.	8306270255	50-336 P	CROW, W. T.	8306210434	40-6264
COOPER, W. G.	8306200304	50-454 Q	COUNCIL, W. G.	8306270255	50-336 P	CROW, W. T.	8306210440*	70-143
COOPER, W. G.	8306200350	50-454 Q	COUNCIL, W. G.	8306280321	50-245 P	CROW, W. T.	8306210443	50-329 P

PERSONAL AUTHOR INDEX

47

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
CROW, W T	8306290687*	70-2375	DALE, L F	8306010074	50-416 P	DAVIS, J Q	8306160175*	FOIA
CROWLEY, B R	8306140522*	50-321 Q	DALE, L F	8306060058*	50-416 A	DAVIS, J Q	8306160182*	FOIA
CROWLEY, B R	8306290192*	50-413 Q	DALE, L F	8306060079	50-416 F	DAVIS, J Q	8306280132	PROJ
CRUTCHFIELD, D	8306010308	50-237 P	DALE, L F	8306060236	50-416 P	DAVIS, J Q	8306290567*	REVIEW OR
CRUTCHFIELD, D	8306060044	50-255 P	DALE, L F	8306140724	50-416 P	DAVIS, L K	8306230053*	FOIA
CRUTCHFIELD, D	8306060047*	50-255 P	DALE, L F	8306160271	50-416 P	DAVIS, M	8306200351*	50-358
CRUTCHFIELD, D	8306060296	50-244 P	DALE, L F	8306200204	50-416 P	DAVIS, M J	8306140627*	50-280
CRUTCHFIELD, D	8306080198	50-245 P	DALE, L F	8306200412	50-416 F	DAVIS, P R	8306200445	ACRS
CRUTCHFIELD, D	8306090267	50-245 P	DALE, L F	8306210140	50-416 F	DAVIS, P R	8306200445	ACRS
CRUTCHFIELD, D	8306090320	50-219 Q	DALE, L F	8306230167	50-416 P	DAVIS, R E	8306200066	NUREQ
CRUTCHFIELD, D	8306100128	50-237 P	DALE, L F	8306270077	50-416 P	DAVIS, S	8306060085*	50-249
CRUTCHFIELD, D	8306100129	50-155 P	DALE, L F	8306270116	50-416 Q	DAVIS, S M	8306020423	50-317
CRUTCHFIELD, D	8306140408	50-237 P	DALE, L F	8306270285	50-416 P	DAVIS, S M	8306020430	50-318
CRUTCHFIELD, D	8306140642	50-219 P	DALE, L F	8306280505	50-416 P	DAVIS, S M	8306020433	50-317
CRUTCHFIELD, D	8306150013	50-244 Q	DALRYMPLE, J T	8306090470*	CONTRACT	DAVIS, S M	8306200089	50-317
CRUTCHFIELD, D	8306150088	50-255 F	DALTROFF, B L	8306020299	50-277 P	DAVIS, W E	8306230030*	40-8481
CRUTCHFIELD, D	8306150218	50-155 Q	DALTROFF, B L	8306020378	50-277 P	DAMSON, D M	8306030426	70-1308
CRUTCHFIELD, D	8306150253	50-29 J	DALTROFF, B L	8306070363	50-277 P	DE LORENZO, R A	8306010106	50-318
CRUTCHFIELD, D	8306160549	50-155 P	DALTROFF, S L	8306090219	50-277 P	DE LORENZO, R A	8306070113	50-460
CRUTCHFIELD, D	8306160625	50-155 P	DALTROFF, S L	8306140391*	50-277 F	DEAGAZIO, A	8306030503	50-346
CRUTCHFIELD, D	8306200192	50-155 P	DALTROFF, B L	8306160340	50-352 A	DEAN, J P	8306020415*	70-1224
CRUTCHFIELD, D	8306200197*	50-155 P	DALTROFF, B L	8306160486*	50-277 Q	DEAN, R G	8306240050	NUREQ
CRUTCHFIELD, D	8306200235	50-244 P	DALTROFF, B L	8306200165*	50-277 Q	DEARDORFF, D.	8306130453	50-358
CRUTCHFIELD, D	8306210158	50-219 P	DANA, J T	8306200273	FOIA	DEBBAGE, A Q	8306140471*	50-393
CRUTCHFIELD, D	8306210292	50-409 F	DANCE, H C	8306070050	50-250 Q	DEBIEUX, R B	8306070090	50-382
CRUTCHFIELD, D	8306210424	50-111 P	DANCE, H C	8306070191	50-389 B	DEBB, B T	8306140477*	50-348
CRUTCHFIELD, D	8306220074	50-219 P	DANCE, H C	8306140127	50-250 V	DEBB, B T	8306290228*	50-259
CRUTCHFIELD, D	8306240234	50-219 P	DANCE, H C	8306140135	50-395 V	DEBB, B T	8306150360*	50-259
CRUTCHFIELD, D	8306280155	50-219 P	DANCE, H C	8306140174	50-389 Q	DECKER, T R.	8306290426*	50-261
CRUTCHFIELD, D	8306280176	50-219 P	DANCE, H C	8306140186	50-389 Q	DEEDS, P E	8306240443*	50-293
CRUTCHFIELD, D	8306280197	50-409 P	DANCE, H C	8306140190	50-335 Q	DEIGL, H. Q	8306010389	50-128
CRUTCHFIELD, D	8306280442	50-155 P	DANCE, H C	8306140302	50-335 Q	DEIGL, H. J.	8306030045	71-5957
CRUTCHFIELD, D	8306280564	50-237 P	DANCE, H C	8306140343	50-335 Q	DELAWARENCE, J. L	8306270004*	50-213
CRUTCHFIELD, D	8306290068	50-141 W	DANCE, H C	8306140346	50-369 V	DELLA RATTI, A	8306010339*	70-687
CRUTCHFIELD, D	8306290241	50-29 P	DANCE, H C	8306140347	50-302 V	DELLA RATTI, A	8306030324*	70-371
CRUTCHFIELD, D	8306290311	50-29 P	DANCE, H C	8306140353	50-302 V	DELLAVECCHIA, M.	8306130398	50-322
CRUTCHFIELD, D	8306290406	50-245 P	DANCE, H C	8306140397	50-280 Q	DELATCH, V.	8306010622	CONTRACT
CRUTCHFIELD, D	8306290538	50-219 P	DANCE, H C	8306140432	50-424 Q	DELATCH, V.	8306150360*	CONTRACT
CRUTCHFIELD, D	8306300027	50-155 P	DANCE, H C	8306140447	50-302 Q	DELATCH, V.	8306290385	CONTRACT
CRY, K D	8306240266	50-341 Q	DANCE, H C	8306140455*	50-302 Q	DELOST, J	8306230058*	FOIA
CULLEN, W H	8306150081	NUREQ	DANCE, H C	8306140486	50-321 V	DELOST, T.	8306230040*	FOIA
CULLEN, W H	8306170263	NUREQ	DANCE, H C	8306140497	50-413 Q	DENISON, E.	8306170308	50-275
CULLEN, W H	8306240062	NUREQ	DANCE, H C	8306140304	50-389 Q	DENNIS, A. W	8306020080	NUREQ
CUMMINGS, J J	8306080308*	50-498 Q	DANCE, H C	8306140306*	50-413 Q	DENNIS, C.	8306060309*	70-25
CUMMINGS, J J	8306080310*	50-498 Q	DANCE, H C	8306140515	50-321 Q	DENNIS, N.	8304110279	I&E
CUMMINGS, J J	8306230043*	50-373 Q	DANCE, H C	8306140530	50-369 Q	DENNIS, N	8304110289	I&E
CUMMINGS, J E	8306140363*	50-313 Q	DANCE, H C	8306140538	50-335 Q	DENNY, I L	8306080399	40-2061
CUNNINGHAM, O H	8306150174	50-289 H	DANCE, H C	8306140608	50-338 Q	DENTE, T J	8306210146	TOPREP
CUNNINGHAM, O H	8306240281*	50-289 Q	DANCE, H C	8306140621	50-280 Q	DENTE, T J	8306230324	TOPREP
CUNNINGHAM, R Q	8306240157	50-5 P	DANCE, H C	8306140641	50-338 Q	DENTON, H R.	8210290150*	MISC
CUDMO, M M	8306030176*	50-322 U	DANCE, H C	8306140644	50-413 Q	DENTON, H R.	8306010091	PR
CURRANE, R A	8306240243*	QA999	DANCE, H C	8306170151	50-369 Q	DENTON, H R.	8306020443	50-320
CURRANE, R A	8306240245*	QA999	DANCE, H C	8306170285	50-269 Q	DENTON, H R.	8306030213	MISC
CURRAN, D	8306010382	50-443 Q	DANCE, H C	8306200203	50-321 S	DENTON, H R.	8306080687	MISC
CURRAN, D	8306010382	50-443 Q	DANCE, H C	8306290186	50-413 Q	DENTON, H R.	8306090371	MISC
CURRAN, D	8306010437	50-443 Q	DANCE, H C	8306290204	50-250 Q	DENTON, H R.	8306090458	MISC
CURRAN, D	8306010446	50-443 Q	DANCE, H C	8306290209	50-335 Q	DENTON, H R.	8306090474	MISC
CURRAN, D	8306030335	50-443 Q	DANCE, H C	8306290217	50-389 Q	DENTON, H R.	8306130455	50-272
CURRAN, D	8306030335	50-443 Q	DANCE, H C	8306290227	50-537 Q	DENTON, H R.	8306140294	MISC
CURRAN, D	8306030359*	50-443 Q	DANCE, H C	8306290300	50-413 Q	DENTON, H R.	8306140712	PR
CURRAN, D	8306030359*	50-443 Q	DANCE, H C	8306290327	50-335 Q	DENTON, H R.	8306210463	NUREQ
CURRAN, D	8306160337	PR	DANCE, H C	8306290349*	50-250 Q	DENTON, H R.	8306220215	50-346
CURRAN, D	8306290556	50-443 Q	DANCE, H C	8306290359*	50-335 Q	DENTON, H R.	8306230303*	TOPREP
CURRAN, D	8306290556	50-443 Q	DANCE, H C	8306290377	50-302 Q	DENTON, H R.	8306240405	50-155
CURRIE, J W	8306240078	NUREQ	DANCE, H C	8306290396	50-413 Q	DENTON, H R.	8306240410*	50-155
CURRY, J J	8305310226	50-245 P	DANCE, H C	8306290421	50-389 Q	DENTON, H R.	8306240415*	50-155
CURTIS, N W	8306010330	50-387 P	DANCE, H C	8306290517	50-369 Q	DENTON, H R.	8306240419*	50-155
CURTIS, N W.	8306020429	50-387 P	DANESE, F L	8306020199	50-266 F	DENTON, H R.	8306240421*	50-155
CURTIS, N W.	8306090021*	50-387 F	DANESE, F L	8306100018	50-266 F	DENTON, H R.	8306240452	50-272
CURTIS, N W	8306140648	50-387 E	DANIELSON, D H	8306030185*	50-483 Q	DENTON, H R.	8306280047	PR
CURTIS, N W.	8306170250	50-388 S	DANIELSON, D H	8306030213*	50-374 Q	DENTON, H R.	8306280125	MISC
CURTIS, N W	8306210079	50-388 S	DANIELSON, D H	8306060138*	50-358 Q	DENTON, H R.	8306290128	50-556
CURTIS, N W	8306230297	50-387 P	DANIELSON, D H	8306230271*	50-440 Q	DENTON, H R.	8306290144	50-440
CURTIS, N W	8306230430	50-387 E	DANIELSON, D H	8306230440*	50-155 Q	DENTON, H R.	8306290564	REVIEW OR
CURTIS, N W	8306230466	50-387 E	DANIELSON, D H	8306300029*	50-346 Q	DERKS, P. B.	8306020309	50-133
CURTIS, N W.	8306280368	50-387 P	DANIELSON, D H	8306300218*	50-358 Q	DERKS, P. B.	8306160461	50-133
CURTIS, N W.	8306300092	50-387 F	DANIELSON, D H	8306300246*	50-227 Q	DESLANDER, K. D.	8306170042	50-336
CURTIS, N W	8306300185	50-387 P	DAVIS	8306210237	I&E	DESLANDER, K. D.	8306170042	50-336
CUTCHIN, J.	8306010433	50-440 Q	DAVIS, A. B.	8306230019*	50-373 Q	DESBROBIERS, A.	8306010031	NUREQ
CUTCHIN, J M	8306140706	50-440 Q	DAVIS, B W.	8306150619	NUREQ	DESBROBIERS, A. E	8306010039	NUREQ
CUTCHIN, J M	8306170399	50-440 Q	DAVIS, D. A.	8306060410	NUREQ	DESBROBIERS, A. E	8306010067	NUREQ
CUTCHIN, J M	8306290372	50-289 Q	DAVIS, F. C	8306170157*	FOIA	DESBROBIERS, A. E.	8306020053	NUREQ
CAJAJIKOWSKI, C	8306240413	50-286 P	DAVIS, F. C	8306170160*	FOIA	DESBROBIERS, A. E.	8306140315	NUREQ
D'AMORE, M	83060600118*	70-1151	DAVIS, H H	8306230042*	FOIA	DEVINCENTIS, J	8306010447*	50-443
D'ARCY, P F	8306150179*	50-289 H	DAVIS, J Q	8306140718*	PR	DEVINCENTIS, J	8306010447*	50-443

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
DEVINCENTIS, J	8306030177	50-443 E	DIETZ, C R	8306270199	50-324 S	DIXON, O W	8306140388*	50-395 Q
DEVINCENTIS, J	8306030177	50-443 E	DIETZ, C R	8306270245	50-324 S	DIXON, O W	8306140437*	50-395 Q
DEVINCENTIS, J	8306080125	50-443 E	DIETZ, C R	8306270277	50-324 S	DIXON, O W	8306140670	50-395 S
DEVINCENTIS, J	8306080125	50-443 E	DIETZ, C R	8306270291	50-325 S	DIXON, O W	8306160570	50-395 R
DEVINCENTIS, J	8306170169	50-443 S	DIETZ, C R	8306300012	50-324 S	DIXON, O W	8306210021	50-395 S
DEVINCENTIS, J	8306170169	50-443 S	DIETZ, C R	8306300031	50-324 S	DIXON, O W	8306210209	50-395 S
DEVINCENTIS, J	8306200236	50-443 E	DIETZ, C R	8306300193	50-324 S	DIXON, O W	8306230086	50-395 P
DEVINCENTIS, J	8306200236	50-443 E	DIETZ, C R	8306300203	50-325 S	DIXON, O W	8306270136	50-395 S
DEVINCENTIS, J	8306200330	50-443 E	DIETZ, C R	8306300242	50-324 S	DIXON, O W	8306270289	50-395 S
DEVINCENTIS, J	8306200330	50-443 E	DIGGS, R M	8306300056	50-250 P	DIXON, O W	8306270356	50-395 P
DEVINCENTIS, J	8306200397	50-443 E	DIGGS, R M	8306303285	50-369 P	DIXON, O W	8306280067	50-395 S
DEVINCENTIS, J	8306200397	50-443 E	DIGGS, R M	8306309328	50-369 P	DIXON, O W	8306280084	50-395 S
DEVINCENTIS, J	8306230452	50-443 A	DIGGS, R M	8306309341	50-267 P	DIXON, O W	8306290088	50-395 Q
DEVINCENTIS, J	8306230452	50-443 A	DIGGS, R M	8306300157	50-219 P	DIXON, O W	8306300118	50-395 S
DEVINCENTIS, J	8306280345	50-443 S	DIGGS, R M	8306210315	50-298 P	DIXON, O W	8306300049	50-395 S
DEVINCENTIS, J	8306280345	50-443 S	DIGGS, R M	8306230498	50-361 P	DIXON, O W	83063300122	50-395 S
DEVINE, B	8306200284*	FOIA	DIGGS, R M	8306230512	50-155 Q	DIXON, O W	83063300156	50-395 S
DEVINE, J B	8306020615	XPORTLIC	DIGGS, R M	8306230514	50-313 P	DIXON, O W	83063300196	50-395 S
DEVINE, J B	8306020645	XPORTLIC	DIGGS, R M	8306240038	50-269 F	DJEMAL, A	8306020318	50-247 J
DEVINE, J B	8306030011	XPORTLIC	DIGGS, R M	8306280077	50-373 P	DODDS, R T	8306070017*	50-344 Q
DEVINE, R E	8306200287*	FOIA	DIGNAN, T Q	8306060305	50-309 Q	DODDS, R T	8306070083*	50-344 Q
DEVINE, T	8306200075	50-358 Q	DIGNAN, T Q	8306060305	50-309 Q	DODDS, R T	8306210245*	50-397 Q
DEWEY, L B	8306090311	50-529 Q	DIGNAN, T Q	8306060332	50-309 Q	DODDS, R T	8306280215*	50-397 Q
DEWEY, L B	8306140429	50-528 Q	DIGNAN, T Q	8306060332	50-309 Q	DODDS, R T	8306280031*	50-397 Q
DEWEY, L B	8306150398	50-529 Q	DIGNAN, T Q	8306070290	50-309 Q	DODDS, R T	8306280380*	50-397 Q
DEWEY, L B	8306210264	50-529 Q	DIGNAN, T Q	8306070290	50-309 Q	DODDS, R T	8306280409*	50-398 Q
DEWEY, L B	8306210268	50-529 Q	DIGNAN, T Q	8306070296	50-309 Q	DODDS, R T	8306280521*	50-397 Q
DEWEY, L B	8306240284	50-529 Q	DIGNAN, T Q	8306070296	50-309 Q	DODSON, J P	8306240293*	QA999
DEWITT, R B	8306290493	50-329 A	DIGNAN, T Q	8306130387	50-443 Q	DOERFLEIN, L T	8306060227*	50-220 Q
DEYOUNG, R C	8306090345	50-440 Q	DIGNAN, T Q	8306130387	50-443 Q	DOERFLEIN, L T	8306060237*	50-333 Q
DEYOUNG, R C	8306240046	50-272 Q	DIGNAN, T Q	8306130388	50-443 Q	DOIRON, D G	8306230220*	CONTRACT
DEYOUNG, R C	8306240049*	50-272 Q	DIGNAN, T Q	8306130388	50-443 Q	DOLLANSKY, K W	8306010083*	50-528 S
DEYOUNG, R C	8306300102	50-324 Q	DIGNAN, T Q	8306280343	50-443 Q	DOLLANSKY, K W	8306010087*	50-528 S
DEYOUNG, R C	8306300108*	50-324 Q	DIGNAN, T Q	8306280343	50-443 Q	DONOVAN, R W	8306010241	50-397 F
DEBLE, C B	8306160183	FOIA	DIMARIA, D	8306080194	50-322 H	DOOLITTLE, E L	8306020069	50-423 A
DICHARRY, R F	8306030057*	71-9056	DIMEGLIO, A F	8306080329	50-193 F	DOOLITTLE, E L	8306080433	50-423 A
DICK, Q F	8306060174	50-244 F	DINITZ, I	8306220288	50-111 J	DOOLITTLE, E L	8306220167	50-423 A
DICK, Q F	8306060255	50-244 P	DIRCKS, W J	8204070018*	FOIA	DOOLITTLE, E L	8306230141	50-423 A
DICKERSON, M. H.	8306060126*	50-267 Q	DIRCKS, W J	8203170474*	50-206 P	DOOLITTLE, E L	8306230145	50-423 A
DICKKAMP, H.	8306010351	50-289 Q	DIRCKS, W J	8208050024*	50-206 P	DOROSHOW, J	8306020355	50-289 Q
DICKKAMP, H.	8306130395*	50-289 Q	DIRCKS, W J	8209210553*	FOIA	DOROSHOW, J	8306060279	50-289 Q
DIEDERICH, Q J	8306060206	50-373 S	DIRCKS, W J	8306020603	50-370 P	DOROSHOW, J	8306030095	50-289 Q
DIEDERICH, Q J	8306130349	50-373 S	DIRCKS, W J	8306030370*	FOIA	DORSEY, J A	8306030280	50-392 Q
DIEDERICH, Q J	8306130352	50-373 S	DIRCKS, W J	8306060108*	FOIA	DORSEY, J A	8306030280	50-392 Q
DIEDERICH, Q J	8306210043	50-373 S	DIRCKS, W J	8306060384	50-440 A	DORSEY, J A	8306150362	50-392 Q
DIEDERICH, Q J	8306210089	50-373 S	DIRCKS, W J	8306070463	50-275 P	DORSEY, J A	8306150362	50-392 Q
DIEDERICH, Q J	8306210192	50-373 S	DIRCKS, W J	8306140316	50-322 H	DORSEY, J A	8306270297	50-392 Q
DIEDERICH, Q J	8306210263	50-373 S	DIRCKS, W J	8306140501	COMMISSION	DORSEY, M	8306280127	CONTRACT
DIEDERICH, Q J	8306210277	50-373 S	DIRCKS, W J	8306150330	50-409 Q	DOUDNIKOFF, B	8306230048*	CONTRACT
DIEDERICH, Q J	8306210308	50-373 S	DIRCKS, W J	8306150490	50-213 Q	DOUGHERTY, J R	8306150377	50-322 Q
DIEDERICH, Q J	8306220019	50-373 S	DIRCKS, W J	8306160115*	FOIA	DOWNNEY, T J	8306020248*	50-322 U
DIEDERICH, Q J	8306220064	50-373 S	DIRCKS, W J	8306160185*	FOIA	DOWNING, G	8306160690*	50-346 F
DIEDERICH, Q J	8306270002	50-373 S	DIRCKS, W J	8306160192*	FOIA	DOYLE, J	8306150415*	50-445 Q
DIEDERICH, Q J	8306270302	50-373 S	DIRCKS, W J	8306160198*	FOIA	DOYLE, W E	8306020230	40-8794
ETCH, R	8306140019	50-206 P	DIRCKS, W J	8306160203*	FOIA	DRUGA, R J	8304110827*	50-334 S
ETCH, R	8306150002	50-361 K	DIRCKS, W J	8306160208*	FOIA	DRUMMOND, F J	8306010084	50-382 B
ETCH, R	8306220095	50-206 P	DIRCKS, W J	8306160216*	FOIA	DRUMMOND, F J	8306060117	50-382 I
ETCH, R	8306240002	50-362 Q	DIRCKS, W J	8306160222*	FOIA	DRUMMOND, F J	8306070133	50-382 B
ETRICH, J.	8306130398	50-322 Q	DIRCKS, W J	8306160606	50-289 P	DRUMMOND, F J	8306070169	50-382 B
ETZ, C R	8306010105	50-324 S	DIRCKS, W J	8306170431*	COMMISSION	DRUMMOND, F J	8306070274	50-382 B
ETZ, C R	8306010109	50-324 S	DIRCKS, W J	8306220207	50-289 P	DRUMMOND, F J	8306070307	50-382 B
ETZ, C R	8306010118	50-325 S	DIRCKS, W J	8306230351	50-395 P	DRUMMOND, F J	8306070317	50-382 B
ETZ, C R	8306010388	50-324 S	DIRCKS, W J	8306230353	REGARD	DRUMMOND, F J	8306130280	50-382 E
ETZ, C R	8306070053	50-325 S	DIRCKS, W J	8306240279	50-289 Q	DRUMMOND, F J	8306160002	50-382 E
ETZ, C R	8306070081	50-325 S	DIRCKS, W J	8306240403	SECY	DRUMMOND, F J	8306170268*	50-382 Q
ETZ, C R	8306070097	50-324 S	DIRCKS, W J	8306280008	COMMISSION	DRUMMOND, F J	8306210124	50-382 A
ETZ, C R	8306070102	50-324 S	DISE, D P	8306140564*	50-410 Q	DRUMMOND, F J	8306270092	50-382 B
ETZ, C R	8306070141	50-324 S	DISE, D P	8306210182	50-410 S	DRUMMOND, F J	8306270127	50-382 B
ETZ, C R	8306070235	50-324 S	DISE, D P	8306280255	50-410 S	DRUMMOND, F J	8306270206	50-382 A
ETZ, C R	8306070342	50-324 S	DISE, D P	8306280597	50-410 S	DRUMMOND, F J	8306270213	50-382 B
ETZ, C R	8306090136	50-325 S	DIXON, B. W	8306030088*	50-397 A	DRUMMOND, F J	8306270310	50-382 B
ETZ, C R	8306100127	50-325 S	DIXON, D J	8306100125	50-462 S	DRUMMOND, F J	8306270330	50-382 B
ETZ, C R	8306100177	50-324 S	DIXON, D J	8306100325	50-395 Q	DRUMMOND, F J	8306300097	50-382 S
ETZ, C R	8306140214	50-324 R	DIXON, O W	8306020142	50-395 R	DRUMMOND, F J	8306300166	50-382 A
ETZ, C R	8306140214	50-324 Q	DIXON, O W	8306020385	50-395 S	DRUMMOND, F J	8306300188	50-382 S
			DIXON, O W	8306070128	50-395 S	DUBE, H.	8306280033	NUREG
			DIXON, O W	8306070202	50-395 S	DUBOIS, D	8306010262	50-298 S
			DIXON, O W	8306070402	50-395 P	DUBOIS, D L	8306210129*	50-298 Q
			DIXON, O W	8306100142	50-395 S	DUBRY, N. E	8306270387*	50-407 Q
			DIXON, O W	8306100163	50-395 S	DUCE, S W	8306080161	50-333 P
			DIXON, O W	8306100208	50-395 S	DUCK, J R	8306010398	50-250 J
			DIXON, O W	8306100213	50-395 S	DUCK, J R	8306230125	50-250 J
			DIXON, O W	8306100261	50-395 S	DUGGINS, G E	8306200167	50-282 S
			DIXON, O W	8306130417	50-395 P	DUGSTAD, D.	8306020167	50-282 R
			DIXON, O W	8306140088	50-395 S	DUGSTAD, D.	8306140002	50-282 R

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
DUNAWAY, F. R.	8306060221*	50-295 Q	EDELMAN, M. R.	8306240269	50-440 E	ELBASSER, T. C.	8306060211*	50-423
DUNDAS, W. J.	8306070404	50-266 J	EDELMAN, M. R.	8306240344	70-296B	ELBASSER, T. C.	8306070241*	50-245
DUNLAP, J. M.	8306200403*	50-244 Q	EDELMAN, M. R.	8306270115*	50-440 Q	ELBASSER, T. C.	8306160246*	50-193
DUNLAP, J. M.	8306030317*	70-371	EDELMAN, M. R.	8306270287*	50-440 Q	ELBASSER, T. C.	8306200225*	70-1143
DUNN, D. C.	8306230063*	FOIA	EDELMAN, M. R.	8306280161	50-440 A	ELBASSER, T. C.	8306230118*	70-820
DUNN, D. C.	8306230064*	FOIA	EDELMAN, M. R.	8306300169	50-440 S	ELY, J. O.	8306070087	50-259
DUNN, K.	8306230066*	FOIA	EDGAR, G. L.	8306270317	50-537 Q	ELY, J. O.	8306070241*	50-259
DUNN, M. O.	8306290629*	CONTRACT	EDISON, G. E.	8306010018	NUREQ	ELY, J. O.	8306300066	50-259
DUNN, R. E.	8306230067*	FOIA	EDISON, G. E.	8306080321	50-482 A	EMBREY, B.	8306090203*	50-255
DUNN, R. W.	8306230069*	FOIA	EDISON, G. E.	8306080438	50-483 A	EMBREY, B.	8306090287*	50-255
DUNN, W. J.	8306230071*	FOIA	EDLEMAN, M. R.	8306140661	50-440 A	EMBREY, B.	8306140831*	50-255
DUNNE, L. A.	8306010094	50-201 P	EDSBALL, J.	8306080194	50-322 H	EMCH, R. L.	8306100224	50-155
DUNNING, T. C.	8306080227*	50-445 Q	EFTHYIQU, Q. C.	8306160506*	50-445 Q	EMCH, R. L.	8306150152	50-155
DUPONT, D.	8306170377*	50-142 T	EGAN, O. R.	8306080048*	50-440 A	ENGEL, W. P.	8306010001	71-6400
DUPONT, D.	8306170390*	50-142 T	EGAN, O. R.	8306290476*	50-329 A	ENGELKEN, R. H.	8306100014*	50-275
DUPONT, D.	8306170417*	50-142 T	EICH, E.	8306020276	50-247 R	ENGELKEN, R. H.	8306160281*	50-206
DUPONT, D.	8306170426*	50-142 T	EICH, E.	8306160462	50-247 R	ENGELMANN, R.	8306200179	40-8584
DUPONT, S. O.	8306100175*	50-373 Q	EICHENHOLZ, H.	8306160006*	50-271 Q	ENGELMANN, R.	8306280104	40-8348
DUPREE, D. C.	8306020197	50-327 R	EICHENHOLZ, H.	8306200166*	50-293 Q	ENNIS, J.	8306170307*	50-269
DURAND, R. J.	8306140539*	50-329 A	EISELE, P. J.	8306080351*	50-410 A	END, M. B.	8306100075	50-529
DURAND, R. J.	8306140540*	50-329 A	EISENHUT, D.	8306280181*	50-219 P	ENDS, J. T.	8306210093	TOPREP
DURAND, R. J.	8306140544*	50-329 A	EISENHUT, D. O.	8306080366	50-387 P	ENDS, J. T.	8306210093	TOPREP
DURAND, R. J.	8306140546*	50-329 A	EISENHUT, D. O.	8305110468	50-275 P	ENGLISH, E. B.	8306060316	50-170
DURAND, R. J.	8306140548*	50-329 A	EISENHUT, D. O.	8305110471	50-275 P	ERICKSON, P.	8306270318	50-213
DURAND, R. J.	8306140552*	50-329 A	EISENHUT, D. O.	8305110481	50-275 P	ERICKSON, R. W.	8306150521*	CONTRACT
DURAND, R. J.	8306140573*	50-329 A	EISENHUT, D. O.	8305110486	50-275 S	ERNST, M. L.	8306120488*	50-416
DURAND, R. J.	8306140579*	50-329 A	EISENHUT, D. O.	8305110488	50-275 S	ERNST, M. L.	8306122032*	50-245
DURAND, R. J.	8306140587*	50-329 A	EISENHUT, D. O.	8305110489	50-275 P	EURY, L. W.	8306070101	50-261
DURAND, R. J.	8306140597*	50-329 A	EISENHUT, D. O.	8305110492	50-275 Q	EURY, L. W.	8306080122	50-261
DURAND, R. J.	8306140605*	50-329 A	EISENHUT, D. O.	8305110495	50-275 R	EURY, L. W.	8306290555*	50-261
DURR, J. P.	8306210107*	50-322 Q	EISENHUT, D. O.	8305110498	50-275 R	EVANS, J. B.	8306280190	NUREQ
DURVOY, E. O.	8306030009	NUREQ	EISENHUT, D. O.	8305110499	50-275 T	EVANS, W. A.	8306030038	71-9133
DWYER, P. W.	8306180470	50-70 B	EISENHUT, D. O.	8305110500	50-275 P	EVERETT, R. J.	8306080165*	40-8027
DWYER, P. W.	8306180516	P121	EISENHUT, D. O.	8306060066*	FOIA	EVERETT, R. J.	8306080190*	40-8681
DYKERS, L. O.	8306020500	40-8584	EISENHUT, D. O.	8306070216	50-312 P	EVERETT, R. J.	8306080193*	40-8681
DYNNER, A. R.	8306130423	50-322 Q	EISENHUT, D. O.	8306070431*	50-370 P	EVERETT, R. J.	8306090132*	40-8698
DYNNER, A. R.	8306130423	50-322 Q	EISENHUT, D. O.	8306080199	50-275 P	EVERETT, R. J.	8306090138*	40-8698
DYNNER, A. R.	8306150214*	50-322 Q	EISENHUT, D. O.	8306080201*	50-275 P	EVERETT, R. J.	8306090175*	40-8084
DYNNER, A. R.	8306200337	50-322 Q	EISENHUT, D. O.	8306090323	MISC	EVERETT, R. J.	8306090179*	40-8663
DYNNER, A. R.	8306290480	50-322 Q	EISENHUT, D. O.	8306090369	NUREQ	FAIRFIELD, M. B.	8306010049	50-302
DYNNER, A. R.	8306290480	50-322 Q	EISENHUT, D. O.	8306090401	50-412 C	FALCONER, K. L.	8306020011	NUREQ
DYNNER, A. R.	8306290485*	50-322 Q	EISENHUT, D. O.	8306130497	50-267 F	FALKENHEIMER, D.	8306220117	50-458
DYNNER, A. R.	8306290485*	50-322 Q	EISENHUT, D. O.	8306150221	50-458 F	FALKENHEIMER, D.	8306220117	50-458
DYNNER, A. R.	8306290492*	50-322 Q	EISENHUT, D. O.	8306150285	50-461 F	FARAHZAD, P.	8306280044	NUREQ
DYNNER, A. R.	8306300081	50-322 Q	EISENHUT, D. O.	8306150404	50-322 Q	FARRAR, D. L.	8305260238	50-237
DYNNER, A. R.	8306300081	50-322 Q	EISENHUT, D. O.	8306170473	50-483 F	FARRAR, D. L.	8306020449	PR
DYNNER, A. R.	8306130111	50-286 T	EISENHUT, D. O.	8306170475	50-289 P	FARRAR, D. L.	8306070392*	50-454
DYNNER, A. R.	8306130398	50-322 Q	EISENHUT, D. O.	8306200034	50-390 F	FARRAR, D. L.	8306090194	50-237
EAOLE, J.	8306170344	50-265 B	EISENHUT, D. O.	8306200439	MISC	FARRAR, D. L.	8306100218	50-10
EAPEN, P. K.	8306230199*	50-244 Q	EISENHUT, D. O.	8306210166*	50-219 P	FARRAR, D. L.	8306100250*	50-373
EARLEY, A. F.	8306150214*	50-322 Q	EISENHUT, D. O.	8306210297*	50-409 F	FARRAR, D. L.	8306160224	NUREQ
EASTERLING, R. O.	8306160401	NUREQ	EISENHUT, D. O.	8306220283	PR	FARRAR, D. L.	8306160225	50-373
EBENHACK, D. O.	8306080345	71-9176	EISENHUT, D. O.	8306230047	TOPREP	FARRAR, D. L.	8306160435*	50-373
EBENHACK, D. O.	8306240394	27-47	EISENHUT, D. O.	8306240027*	50-460 A	FARRAR, D. L.	8306230425	REPOD
EBERBOLE, J. C.	8306010199	50-409 Q	EISENHUT, D. O.	8306240474	50-275 P	FARRAR, D. L.	8306270071*	50-456
EBERBOLE, J. C.	8306010208*	50-213 Q	EISENHUT, D. O.	8306280003	50-261 P	FARRAR, D. L.	8306300073*	50-373
EBERBOLE, J. C.	8306020095	50-213 Q	EISENHUT, D. O.	8306280570*	50-237 P	FARRAR, D. L.	8306300216*	50-295
EBERBOLE, J. C.	8306020098	ACRS	EISENHUT, D. O.	8306270073*	50-141 W	FARRELL, E. V.	8306010264	50-317
ECKENRODE, R. J.	8306030009	NUREQ	EISENHUT, F. T.	8306280510	50-387 S	FARRELL, R. E.	8306300063*	50-346
ECKERT, E. C.	8306280456*	50-397 E	EL-ASHRY, M. T.	8306140526	50-327 R	FARRAD, A.	8306060266*	50-320
ECKHARDT, J. H.	8306230398	50-361 B	ELIN, J. P.	8306280215*	50-397 Q	FAW, R. E.	8306160229	50-188
ECONOMOS, M.	8306140652*	50-338 B	ELLENBERGER, B.	8306240208*	50-206 P	FAY, C. W.	8305020231*	50-266
EDDINGS, M.	8306020197	50-327 R	ELLIDY, J. L.	8306160460	REPOD	FAY, C. W.	8306010428	50-266
EDDELMAN, W.	8306010355	50-400 Q	ELLIS, J.	8306070330	50-445 Q	FAY, C. W.	8306060078	50-266
EDDELMAN, W.	8306010359	50-400 Q	ELLIS, J.	8306070306*	50-445 Q	FAY, C. W.	8306060156	50-266
EDDELMAN, W.	8306030337	50-400 Q	ELLIS, J.	8306070382	50-445 Q	FAY, C. W.	8306070086	50-266
EDDELMAN, W.	8306090222	50-400 Q	ELLIS, J.	8306070394*	50-445 Q	FAY, C. W.	8306090189*	50-266
EDDELMAN, W.	8306270307	50-400 Q	ELLIS, J.	8306100223	50-445 Q	FAY, C. W.	8306200137	50-266
EDDELMAN, W.	8306270313*	50-400 Q	ELLIS, J.	8306100227*	50-445 Q	FAY, C. W.	8306200260	50-266
EDDELMAN, W.	8306270402	50-400 Q	ELLIS, J.	8306150310	50-445 Q	FAY, C. W.	8306200267	50-266
EDDELMAN, W.	8306290361	50-400 Q	ELLIS, J.	8306150380	50-445 Q	FAY, C. W.	8306210100	50-266
EDDELMAN, W.	8306290381	50-400 Q	ELLIS, J.	8306150404	50-445 Q	FAY, C. W.	8306210207	50-301
EDDELMAN, W.	8306300124	PR	ELLIS, J.	8306150414	50-445 Q	FAY, C. W.	8306230261*	50-266
EDELMAN, M.	8306160224	NUREQ	ELLIS, T. S.	8306080171	50-322 Q	FAY, C. W.	8306230356	50-266
EDELMAN, M. R.	8306010058	50-440 E	ELLIS, T. S.	8306080171	50-322 Q	FAY, C. W.	8306280443	50-266
EDELMAN, M. R.	8306080044	50-440 A	ELLIS, T. S.	8306080177*	50-322 Q	FAY, C. W.	8306300058	50-266
EDELMAN, M. R.	8306100119	50-440 S	ELLIS, T. S.	8306080177*	50-322 Q	FEARER, W. P.	8306040302	50-454
EDELMAN, M. R.	8306100180	50-440 A	ELLIS, T. S.	8306220017	50-322 Q	FEARER, W. P.	8306040302	50-454
EDELMAN, M. R.	8306130308*	50-440 Q	ELLIS, T. S.	8306220017	50-322 Q	FEDERICK, H. C.	8306170336*	50-390
EDELMAN, M. R.	8306200085	50-440 E	ELMS, A.	8306020268	50-213 R	FEIL, R. A.	8306280341*	50-397
EDELMAN, M. R.	8306200120	50-440 S	ELMS, A.	8306160459	50-213 R	FEIL, R. A.	8306280341*	50-397
EDELMAN, M. R.	8306220013	50-440 S	ELMOD, S. A.	8306290379*	50-335 Q	FEINBERG, J. D.	8306290393	50-322
EDELMAN, M. R.	8306220039	50-440 S	ELMOD, S. A.	8306200166*	50-293 Q	FEINBERG, J. D.	8306290393	50-322
EDELMAN, M. R.	8306220058	50-440 S	ELMOD, S. A.	8306060171*	50-245 Q	FEITKNECHT, C.	8306070120	50-334
EDELMAN, M. R.	8306240186	50-440 A	ELMOD, S. A.	8306060176*	70-364	FEITKNECHT, C.	8306300210	50-334

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
FELDMAN, B A	8306220233*	CONTRACT	FELTON, J M	8306160043	50-305 F	FIELDS, J A	8306210370	CONTRACT
FELTON, J M	8306200277	FOIA	FELTON, J M	8306160050	FOIA	FIELDS, J A	8306210381	CONTRACT
FELTON, J M	8306030448	50-320 Q	FELTON, J M	8306160052	50-206 Q	FIELDS, J A	8306220238	CONTRACT
FELTON, J M	8306030366	FOIA	FELTON, J M	8306160058	50-228 F	FIELDS, J A	8306220267	CONTRACT
FELTON, J M	8306030376	FOIA	FELTON, J M	8306160070	50-206 Q	FIELDS, J A	8306220277	CONTRACT
FELTON, J M	8306030382	FOIA	FELTON, J M	8306160071	50-254 F	FIELDS, J A	8306220302	CONTRACT
FELTON, J M	8306030383	FOIA	FELTON, J M	8306160072	50-322 F	FIELDS, J A	8306230054	CONTRACT
FELTON, J M	8306030448	50-148 Q	FELTON, J M	8306160073	FOIA	FIELDS, J A	8306230192	CONTRACT
FELTON, J M	8306030450	FOIA	FELTON, J M	8306160081	50-317 S	FIELDS, J A	8306240055	CONTRACT
FELTON, J M	8306030454	FOIA	FELTON, J M	8306160093	FOIA	FIELDS, J A	8306240353	CONTRACT
FELTON, J M	8306030461	FOIA	FELTON, J M	8306160096	50-322 F	FIELDS, J B	8306270253*	50-387 R
FELTON, J M	8306060003	FOIA	FELTON, J M	8306160110	FOIA	FIELDS, J S	8306280006	50-387 S
FELTON, J M	8306060011	FOIA	FELTON, J M	8306160151	FOIA	FINAMORE, B A	8306220146	50-537 Q
FELTON, J M	8306060013	50-354 Q	FELTON, J M	8306160160	FOIA	FINAMORE, B A	8306220153*	50-537 Q
FELTON, J M	8306060032	FOIA	FELTON, J M	8306160171	FOIA	FINAMORE, B A	8306270370	50-289 H
FELTON, J M	8306060037	FOIA	FELTON, J M	8306160177	FOIA	FINDLAY, J A	8306150602	NUREG
FELTON, J M	8306060051	50-245 P	FELTON, J M	8306160186	FOIA	FINDLEY, D E	8306090452*	CONTRACT
FELTON, J M	8306060104	FOIA	FELTON, J M	8306160189	50-72 F	FINDLEY, D E	8306280057*	CONTRACT
FELTON, J M	8306060393	FOIA	FELTON, J M	8306160197	50-206 Q	FINDLEY, D E	8306280110*	CONTRACT
FELTON, J M	8306060400	50-312 F	FELTON, J M	8306160200*	50-206 Q	FINDLEY, D E	8306280147*	CONTRACT
FELTON, J M	8306070019	50-206 P	FELTON, J M	8306160200*	50-206 Q	FINKEL, A E	8306200086*	50-423 Q
FELTON, J M	8306070020	FOIA	FELTON, J M	8306160249	50-409 F	FINLAYSON, F C	8306150584	NUREG
FELTON, J M	8306070025	FOIA	FELTON, J M	8306160346	50-285 F	FINNAN, C F	8306290092*	50-409 P
FELTON, J M	8306070439	FOIA	FELTON, J M	8306160660	50-389 F	FINNERAN, J C	8306080248*	50-445 Q
FELTON, J M	8306080031	FOIA	FELTON, J M	8306160676	50-346 F	FINSTON, R	8306170379*	50-142 T
FELTON, J M	8306080066	FOIA	FELTON, J M	8306160686	50-346 F	FINSTON, R	8306170426*	50-142 T
FELTON, J M	8306080255	FOIA	FELTON, J M	8306170089	FOIA	FIORELLI, O	8306280452*	50-528 Q
FELTON, J M	8306080257	FOIA	FELTON, J M	8306200014	50-155 F	FISCHER, D L	8306070174*	50-293 P
FELTON, J M	8306080259	50-443 Q	FELTON, J M	8306200037	FOIA	FISCHER, W L	8306230153*	70-B
FELTON, J M	8306080262	50-320 Q	FELTON, J M	8306200036	50-313 F	FISCHER, C R	8306170334	NUREG
FELTON, J M	8306080268	FOIA	FELTON, J M	8306200296	FOIA	FISHER, W L	8306230139*	70-B
FELTON, J M	8306080272	FOIA	FELTON, J M	8306200299	50-341 A	FITZGERALD, J A	8306230368	50-367 Q
FELTON, J M	8306080275	FOIA	FELTON, J M	8306200434	50-289 Q	FUELDAL, O	8306080194	50-322 H
FELTON, J M	8306080277	50-498 Q	FELTON, J M	8306210289	FOIA	FLACK, E	8306010183	1&E
FELTON, J M	8306080281	50-528 A	FELTON, J M	8306210300	FOIA	FLACK, E	8306140416	1&E
FELTON, J M	8306080291	FOIA	FELTON, J M	8306210306	50-10 F	FLACK, E	8306210131	1&F
FELTON, J M	8306080296	FOIA	FELTON, J M	8306210312	FOIA	FLACK, E	8306300115	1&E
FELTON, J M	8306080297	40-2061	FELTON, J M	8306210320	FOIA	FLANAGAN, D D	8306150370	50-322 Q
FELTON, J M	8306080305	50-358 A	FELTON, J M	8306210327	FOIA	FLANAGAN, D D	8306150370	50-322 Q
FELTON, J M	8306080313	50-148 P	FELTON, J M	8306210340	FOIA	FLEENOR, C	8306170480	CONTRACT
FELTON, J M	8306080322	FOIA	FELTON, J M	8306210355	50-10 F	FLEENOR, C	8306170484	CONTRACT
FELTON, J M	8306090018	50-387 F	FELTON, J M	8306210357	50-285 F	FLEENOR, C	8306220220	CONTRACT
FELTON, J M	8306090024	50-219 F	FELTON, J M	8306210363	50-348 F	FLEENOR, C	8306220249	CONTRACT
FELTON, J M	8306090029	50-285 F	FELTON, J M	8306210368	50-267 F	FLEENOR, C	8306220253	CONTRACT
FELTON, J M	8306090057	50-346 F	FELTON, J M	8306210382	50-389 F	FLEENOR, C	8306220262	CONTRACT
FELTON, J M	8306090201	50-255 F	FELTON, J M	8306220225	50-335 F	FLEENOR, C	8306220267	CONTRACT
FELTON, J M	8306090204	50-348 F	FELTON, J M	8306220232	50-346 F	FLEENOR, C	8306220316	CONTRACT
FELTON, J M	8306090254	50-282 F	FELTON, J M	8306220287	50-413 F	FLEISCHAKER, D	8306240051	CONTRACT
FELTON, J M	8306090268	50-289 F	FELTON, J M	8306220293	50-289 F	FLEISCHMANN, R	8306040415	50-279 Q
FELTON, J M	8306090273	50-520 F	FELTON, J M	8306220307	50-321 F	FLEISCHMANN, R	8306170163	50-277 R
FELTON, J M	8306090281	50-346 F	FELTON, J M	8306230005	50-373 Q	FLEISHER, Z B	8306080200	50-247 Q
FELTON, J M	8306090283	50-255 F	FELTON, J M	8306230009	FOIA	FLIPPID, T A	8306130129*	50-382 Q
FELTON, J M	8306090289	50-29 F	FELTON, J M	8306230073	50-282 F	FLORY, C A	8306090033	WASTE HOT
FELTON, J M	8306090370	50-346 F	FELTON, J M	8306230092	50-213 F	FLORY, C A	8306090372	WASTE HOT
FELTON, J M	8306090374	FOIA	FELTON, J M	8306230129	50-14 P	FLORY, C A	8306140289	WASTE HOT
FELTON, J M	8306090381	FOIA	FELTON, J M	8306240007	FOIA	FLYNN, J D	8306020312	70-2892
FELTON, J M	8306090391	50-261 F	FELTON, J M	8306240352	FOIA	FLYNN, J D	8306210267	50-358 H
FELTON, J M	8306090406	50-382 F	FELTON, J M	8306280034	50-322 F	FLYNN, J D	8306230435	50-358 H
FELTON, J M	8306100009	50-312 Q	FELTON, J M	8306280182	FOIA	FLYNN, M	8306070026*	FOIA
FELTON, J M	8306140023	50-338 F	FELTON, J M	8306280190	FOIA	FLYNN, M	8306220186	CONTRACT
FELTON, J M	8306140217	50-155 F	FELTON, J M	8306280206	50-320 P	FLYNN, M	8306280050	CONTRACT
FELTON, J M	8306140237	50-321 F	FELTON, J M	8306280224	FOIA	FLYNN, M	8306280113	CONTRACT
FELTON, J M	8306140265	50-309 F	FELTON, J M	8306010298*	50-128 H	FLYNN, M	8306280141	CONTRACT
FELTON, J M	8306140381	50-277 F	FELTON, J M	8306010358	50-128 P	FLYNN, M	8306090447	CONTRACT
FELTON, J M	8306140828	50-255 F	FELTON, J M	8306060213	50-128 P	FLYNN, M	8306090467	CONTRACT
FELTON, J M	8306150025	50-289 F	FERNANDEZ, S J	8306270157	NUREG	FLYNN, M	8306090484	CONTRACT
FELTON, J M	8306150032	50-313 F	FEY, F L	8306090261*	50-282 F	FLYNN, B F	8306080149	50-400 Q
FELTON, J M	8306150037	50-321 F	FIEDLER, P B	8306090261*	50-219 I	FLYNN, B F	8306080160	50-400 Q
FELTON, J M	8306150082	50-317 F	FIEDLER, P B	8306090261*	50-219 R	FODDERO, A H	8306070452	NUREG
FELTON, J M	8306150091	50-327 F	FIEDLER, P B	8306090261*	50-219 Q	FODARTY, D J	8306010164*	50-361 Q
FELTON, J M	8306150101	50-445 F	FIEDLER, P B	8306090261*	50-219 B	FODARTY, D J	8306200381*	50-361 Q
FELTON, J M	8306150133	50-321 F	FIEDLER, P B	8306090261*	50-219 B	FOLEY, J M	8306140063*	50-272 F
FELTON, J M	8306150290	50-271 F	FIEDLER, P B	8306090261*	50-219 F	FOLEY, T	8306010378*	50-247 Q
FELTON, J M	8306150334	50-213 F	FIEDLER, P B	8306090261*	50-219 R	FOLEY, J M	8306230212*	50-247 Q
FELTON, J M	8306150344	50-329 F	FIEDLER, P B	8306090261*	50-219 P	FOLEY, W J	8306240050	NUREG
FELTON, J M	8306150454	50-483 F	FIEDLER, P B	8306160258*	50-219 Q	FORAT, H	8306280572	50-322 Q
FELTON, J M	8306150482	50-482 F	FIEDLER, P B	8306200340	50-219 F	FORCHT, K A	8306070210*	50-413 F
FELTON, J M	8306150609	50-322 F	FIEDLER, P B	8306210085	50-219 Q	FORD, D C	8306080224*	50-445 Q
FELTON, J M	8306150632	50-373 F	FIEDLER, P B	8306280406	50-219 P	FORD, E J	8306140162*	50-327 Q
FELTON, J M	8306160013	FOIA	FIEDLER, P B	8306100208	50-395 S	FORD, E J	8306140390*	50-327 Q
FELTON, J M	8306160019	FOIA	FIELDS, J	8306230218	CONTRACT	FORD, J T	8306140674	70-1201
FELTON, J M	8306160026	50-146 P	FIELDS, J A	8306020506	CONTRACT	FORD, J T	8306270121	70-1201
FELTON, J M	8306160027	50-348 F	FIELDS, J A	8306160259	CONTRACT	FORNEY, W	8306170364*	50-454 Q
FELTON, J M	8306160031	50-329 A	FIELDS, J A	8306170253	CONTRACT	FORNEY, W L	8306230290*	50-454 Q
FELTON, J M	8306160033	50-329 A	FIELDS, J A	8306210239	CONTRACT	FORST, H	8306270390	50-322 Q

PERSONAL AUTHOR INDEX

476

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
FORTUNA, R A	8306040156	50-358 A	GAD, R K	8306150387	50-443 Q	GIESLER, C W	8306170056	50-305 Q
FORTUNA, R A	8306160218*	50-204 G	GAD, R K	8306150387	50-443 Q	GIESLER, C W	8306200102	50-305 P
FORTUNA, R A	8306160253*	50-204 G	GAD, R K	8306150388	50-443 Q	GIESLER, C W	8306210041*	50-305 Q
FOSTER, C M	8306030169	XPORTLIC	GAD, R K	8306150388	50-443 Q	GIESLER, C W	8306270110	50-305 S
FOSTER, C M	8306150467	XPORTLIC	GAD, R K	8306280543	50-443 Q	GIESLER, C W	8306280373	50-305 P
FOSTER, D O	8306100221	50-424 S	GAD, R K	8306280543	50-443 Q	GILBERT, L D	8306140249*	50-482 Q
FOSTER, D O	8306100231	50-424 S	GAGE, K	8306160594	50-289 Q	GILBERT, L D	8306140374*	50-445 Q
FOSTER, D O	8306100259	50-424 S	GAGLIARDI, J E	8306140354	50-482 Q	GILBY, E V	8306300172	NUREG
FOSTER, D O	8306100264	50-424 A	GAJNES, T M	8306170461	71-9156	GILCHRIST, C W	8306220056	50-170 Q
FOSTER, D O	8306100265*	50-424 A	GAJIC, Z	8306270221	50-304 S	GILCHRIST, J E	8306060318	40-8064
FOSTER, D O	8306100274	50-424 B	GALLAGHER, D W	8305310226	50-245 P	GILCHRIST, J E	8306200421	40-8064
FOSTER, D O	8306240274	50-424 A	GALLAGHER, J W	8306140262*	50-277 Q	GILDENHORN, A	8306200224	CONTRACT
FOSTER, D O	8306240274	50-424 A	GALLAGHER, J W	8306280235	50-277 Q	GILDNER, M L	8306300207*	50-440 Q
FOSTER, D O	8306270166	50-424 S	GALLO	8306140154	50-271 S	GILINSKY, V	8306090339	50-289 Q
FOSTER, D O	8306270166	50-424 S	GALLO	8306170333	50-271 S	GILINSKY, V	8306100237	50-289 H
FOSTER, E R	8306280353	50-336 S	GALLO, J	8306130452*	50-454 Q	GILINSKY, V	8306240330*	COMMISSION
FOSTER, L	8306170377*	50-142 T	GALLO, J	8306130452*	50-454 Q	GILINSKY, V	8306270323*	50-289 Q
FOSTER, L	8306170426*	50-142 T	GALLO, J	8306150405	50-155 Q	GILLEN, D M	8306202028*	40-8681
FOSTER, L E	8306140471*	50-395 Q	GALLO, J	8306150405	50-155 Q	GILLEN, D M	8306090489	40-8681
FOSTER, R F	8306200160	ACRS	GALLO, J	8306220023	50-155 Q	GIRARD, E H	8306290332*	50-321 Q
FOSTER, R F	8306200168	ACRS	GALLO, J	8306220023	50-155 Q	GIROUX, E J	8306160454	50-518 S
FOX, C	8306130398	50-322 Q	GALLO, J	8306220065	50-155 Q	GLEASON, J P	8306200443	50-247 Q
FOX, C	8306270390	50-322 Q	GALLO, J	8306220065	50-155 Q	GLEASON, J P	8306300209	50-247 Q
FOX, E K	8306170029*	CONTRACT	GALLO, J	8306220102	50-155 Q	GLEASON, J P	8306130434	50-247 Q
FOXWELL, D O	8306220255*	CONTRACT	GALLO, J	8306220102	50-155 Q	GLEASON, J P	8306150287	50-483 Q
FRAHM, R	8306020406	50-311 B	GALLO, J	8306270016	50-454 Q	GLEASON, J P	8306270137	50-483 Q
FRAHM, R	8306030188	50-311 B	GALLO, J	8306270016	50-454 Q	GLEASON, J P	8306270140	50-247 Q
FRAHM, R	8306030301	50-311 B	GALLO, J	8306280535	50-454 Q	GLEASON, J P	8306270267	50-247 Q
FRAHM, R	8306030344	50-311 B	GALLO, J	8306280535	50-454 Q	GLENN, J	8306060017*	FOIA
FRAHM, R	8306170021	50-311 S	GALLO, R M	8306030316*	50-309 Q	GLENN, J	8306070100	1&E
FRAHM, R	8306170144	50-272 R	GALLO, R M	8306060215*	50-322 Q	GLENN, J E	8306060028*	FOIA
FRAHM, R	8306170153	50-311 S	GALLO, R M	8306060268*	50-322 Q	GLENN, J E	8306170097*	FOIA
FRAHM, R	8306170207	50-311 S	GALLO, R M	8306070333*	50-271 Q	GLOERSEN, N W	8306130412*	50-254 Q
FRAHM, R	8306170330	50-272 S	GALLO, R M	8306090076*	50-322 Q	GNUNOLLI, G N	8306140325	WASTE MGT
FRAHM, R	8306170362	50-311 S	GALLO, R M	8306090366*	50-271 Q	GODDARD, R J	8306080163	50-461 Q
FRAHM, R	8306170381	50-272 S	GALLO, R M	8306160006*	50-271 Q	GODDARD, R J	8306090296	50-309 Q
FRAHM, R	8306210187	50-272 S	GALLO, R M	8306200181*	50-271 Q	GODDARD, R J	8306100045	50-483 Q
FRAHM, R	8306270180	50-311 S	GALLO, R M	8306230405*	50-443 Q	GODDARD, R J	8306150236	50-309 Q
FRAHM, R	8306270267	50-272 S	GALLUCCI, R II	8306020131	NUREG	GODDARD, R J	8306150241	50-309 Q
FRAHM, R	8306270343	50-272 S	GARCIA, E	8306070339*	50-206 Q	GODDARD, R J	8306170363	50-155 Q
FRAHM, R	8306280256	50-272 S	GARCIA, E	8306090174	50-275 S	GODDARD, R J	8306230007	50-155 Q
FRAHM, R	8306280480	50-272 S	GARCIA, E M	8306070287*	50-242 Q	GODDARD, R J	8306230011	50-309 Q
FRAZIER, J L	8306080340*	71-4909	GARCIA, P	8306200437	40-3453	GODDARD, R J	8306290306	50-155 Q
FREMONT, S	8306080815	50-358 Q	GARDE, B	8306160035	50-329 A	GODY	8306210248	50-334 S
FREMONT, S	8306080820	50-358 Q	GARDE, B P	8306160192	FOIA	GODY, A.	8306230001	50-245 S
FRENCH, J F	8306080191	50-247 H	GARNER, L W	8306140705*	50-324 Q	GODY, A	8306280582	50-387 S
FRENCH, L D	8306170339	50-29 S	GARRETT, C A	8306280269	50-400 D	GODY, A T	8306010133*	70-371
FRENCH, L D	8306280144	50-29 S	GARRICK, B J	8306210336*	FOIA	GODY, A T	8306010327*	50-334 Q
FRESHLEY, M D	8306240032	NUREG	GARRITY, J H	8306020146	50-309 P	GODY, A T	8306010339*	70-687
FREUDENTHAL, N	8306020294	40-8064	GARRITY, J H	8306020352	50-309 R	GODY, A T	8306020403*	50-244 Q
FREUDENTHAL, N	8306210454	40-8064	GARRITY, J H	8306020425	50-309 S	GODY, A T	8306030317*	70-371
FREUDENTHAL, N	8306220113	40-8584	GARRITY, J H	8306020524	50-309 P	GODY, A T	8306030324*	70-371
FREUDENTHAL, N	8306220121	40-2259	GARRITY, J H	8306030341	50-309 S	GODY, A T	8306090844*	50-219 Q
FREUDENTHAL, N	8306220126	40-8728	GARRITY, J H	8306060310	50-309 P	GODY, A T	8306170248*	70-371
FREUDENTHAL, N	8306230331	PR	GARRITY, J H	8306150263	50-309 F	GODY, A T	8306230475*	50-272 Q
FREUDENTHAL, N	8306240444	40-8768	GARRITY, J H	8306170166	50-309 F	GOLDBERG, J H	8306070204	50-498 F
FRIEDMAN, L	8306030263	1&E	GARRITY, J H	8306170166	50-309 S	GOLDBERG, J H	8306140052	50-498 A
FRIEDMAN, L	8306280837	1&E	GARRITY, J H	8306170430	50-309 S	GOLDBERG, J H	8306230460	50-498 A
FRIEDMAN, L I	8306070100	1&E	GARRITY, J H	8306270295	50-309 S	GOLDBERG, J R	8306090338	50-289 Q
FRISBEE, D	8306200213*	50-344 I	GARY, R J	8306010392	50-445 A	GOLDBERG, J R	8306140702	50-275 Q
FRISCO, D C	8306300195	PR	GARY, R J	8306090043	50-445 B	GOLDBERG, J R	8306150845	50-289 Q
FRONFELKER, R	8306210151	50-255 J	GARY, R J	8306130440	50-445 B	GOLDBERG, S C	8306130361	50-454 Q
FRUCCI, E L	8306150416	50-322 Q	GARY, R J	8306300055	50-445 B	GOLDBERG, S C	8306130318	50-454 Q
FRY, L	8306020240*	50-372 F	GARY, R J	8306300074	50-445 B	GOLDBERG, S C	8306170378	50-454 Q
FRYE, J H	8306030321	50-358 Q	GARY, R J	8306300088	50-445 B	GOLDBERG, S C	8306210281	50-454 Q
FRYE, J H	8306060282	50-142 Q	GARY, R J	8306300167	50-445 S	GOLDEN, J C	8306220086	50-237 R
FRYE, J H	8306080162	50-358 Q	GAUNY, R D	8306240372	71-6601	GOLDENBERG, O	8306210314	50-10 F
FRYE, J H	8306160581	50-358 Q	GEARS, O	8306020360	50-278 P	GOLDFEIN, H R	8306130445	50-454 Q
FRYE, J H	8306160616	50-142 Q	GERDEMAN, F W	8306130347	40-7869	GOLDFEIN, H R	8306130445	50-454 Q
FURMAN, O R	8306020436	50-317 S	GERDEMAN, F W	8306140356	40-8698	GOLDFEIN, H R	8306130452*	50-454 Q
FUJITA, N	8306210024*	50-29 P	GERDEMAN, F W	8306220311	40-8674	GOLDFEIN, H R	8306200300	50-454 Q
FULLER, C H	8306160434	50-267 R	GERRETS, T F	8306130206	50-382 A	GOLDFEIN, H R	8306200300	50-454 Q
FULTON, J F	8306200316*	50-244 P	GERSTNER, W C	8306270321*	50-461 Q	GOLDHANN, K	8306240375	71-9013
FURR, B J	8306140264	50-261 Q	GIBBONS, T D	8306140375*	50-400 Q	GOLDMITH, M W	8306060188*	50-322 Q
FURR, B J	8306270247	50-261 Q	GIBSON, A F	8306140668	MISC	GOLDMITH, M W	8306060188*	50-322 Q
FURSE, M C	8306280535	50-454 Q	GIBSON, J	8306020077	50-336 R	GOLDMITH, M W	8306070386*	50-322 Q
FURSE, M C	8306280535	50-454 Q	GIBSON, R L	8306270340	50-413 Q	GOLDMITH, M W	8306070386*	50-322 Q
GAD, R K	8306060305	50-309 Q	GIESEKE, J A	8306240241	REG	GOLDMITH, M W	8306170377	50-289 H
GAD, R K	8306060305	50-309 Q	GIEBLER, C W	8306020395	50-305 P	GONZALES, J C	8306070107*	50-529 S
GAD, R K	8306060332	50-309 Q	GIEBLER, C W	8306070070	50-305 J	GOOD, R	8306200335	50-358 Q
GAD, R K	8306060332	50-309 Q	GIEBLER, C W	8306100189	50-305 P	GOOD, R	8306200335	50-358 Q
GAD, R K	8306070290	50-309 Q	GIEBLER, C W	8306140001	50-305 R	GOOD, R	8306200341*	50-358 Q
GAD, R K	8306070290	50-309 Q	GIEBLER, C W	8306140048	50-305 P	GOOD, R	8306200341*	50-358 Q
GAD, R K	8306070296	50-309 Q	GIEBLER, C W	8306160048*	50-305 F	GOOD, R	8306300076	50-289 Q
GAD, R K	8306070296	50-309 Q	GIEBLER, C W	8306160617	50-305 Q	GOODMAN, L S	8306020291	50-409 R

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
GOODMAN, L S	8306160378	50-409 R	GREENE, S R	8306280080	50-259 P	GUSTAVE, R P	8306220150*	CONTRACT
GOODMAN, L S	8306170376	50-409 S	GREENMAN, E	8306170343	50-307 S	GUSTAVE, R P	8306220192*	CONTRACT
GOODMAN, L S	8306270337	50-409 S	GREENMAN, E G	8306030316*	50-309 Q	GUSTAVE, R P	8306220222*	CONTRACT
GOODWIN, D C	8306070099	50-260 S	GREENMAN, E G	8306230002	50-286 S	GUSTAVE, R P	8306220227*	CONTRACT
GOODWIN, D C	8306210226	50-260 S	GREENMAN, E G	8306230349	50-247 S	GUSTAVE, R P	8306220233*	CONTRACT
GOODIN, C	8306010100*	50-29 Q	GREGOR, L R	8306100220*	50-151 Q	GUSTAVE, R P	8306220241*	CONTRACT
GOODIN, C	8306010304*	50-271 Q	GREGOR, L R	8306100229*	50-155 Q	GUSTAVE, R P	8306220255*	CONTRACT
GOSE, D C	8306240263*	TOPREP	GREGOR, L R	8306100258*	50-373 Q	GUSTAVE, R P	8306220259*	CONTRACT
GOTZMEN, G	8306060309*	70-25	GREGOR, L R	8306130333*	50-305 Q	GUSTAVE, R P	8306220266*	CONTRACT
GRABER, L	8306060096	FOIA	GREGOR, L R	8306270167*	50-156 Q	GUSTAVE, R P	8306220272*	CONTRACT
GRABER, L D	8306160030	50-146 P	GREGOR, L R	8306270187*	50-2 Q	GUSTAVE, R P	8306220276*	CONTRACT
GRACE, J N	8306170432	50-537 E	GREGOR, L R	8306300231*	50-409 Q	GUSTAVE, R P	8306220282*	CONTRACT
GRACE, R H	8306160444	50-309 R	GREGO, H I	8306020376*	50-354 Q	GUSTAVE, R P	8306220295*	CONTRACT
GRACE, R H	8306280009	50-309 P	GREGORY, W D	8306030436	70-2982	GUSTAVE, R P	8306220320*	CONTRACT
GRACE, R H	8306280009	50-309 P	GREGORY, W S	8306070422	REF	GUSTAVE, R P	8306220327*	CONTRACT
GRABER, K L	8306060148	50-304 S	GRICE, J C	8306170084	FOIA	GUSTAVE, R P	8306230059*	CONTRACT
GRABER, K L	8306060230	50-304 S	GRIDLEY, R L	8306070174*	50-293 P	GUSTAVE, R P	8306230198*	CONTRACT
GRABER, K L	8306100064	50-295 S	GRIFFIN, B N	8306140315	NUREG	GUSTAVE, R P	8306230491*	CONTRACT
GRABER, K L	8306130307	50-295 S	GRIFFIN, J	8306130409	50-313 S	GUSTAVE, R P	8306230496*	CONTRACT
GRABER, K L	8306130381	50-295 S	GRIFFEY, R A	8306020011	NUREG	GUSTAVE, R P	8306230509*	CONTRACT
GRABER, K L	8306140412	50-295 R	GRIMSLEY, D H	8306160204*	FOIA	GUSTAVE, R P	8306240034*	CONTRACT
GRABER, K L	8306210234	50-304 S	GRIMSLEY, D H	8306160209*	50-206 Q	GUSTAVE, R P	8306240057*	CONTRACT
GRABER, K L	8306270168	50-295 S	GRICE, R H	8306020192	50-309 R	GUSTAVE, R P	8306240350*	CONTRACT
GRABER, K L	8306270221	50-304 S	GRICE, R H	8306230361	50-309 F	GUSTAVE, R P	8306280057*	CONTRACT
GRAHAM, E T	8306010322	50-293 S	GRIBSCH, G L	8306150360	50-302 Q	GUSTAVE, R P	8306280110*	CONTRACT
GRAHAM, R A	8306230405*	50-443 Q	GROSS, P J	8306130403	50-537 A	GUSTAVE, R P	8306280147*	CONTRACT
GRANT, J	8306060211*	50-423 Q	GROSSMAN, H	8306160571	50-244 Q	GUSTAVE, R P	8306280159*	CONTRACT
GRANT, J M	8306150247*	50-352 Q	GROSSMAN, H	8306270254	50-460 Q	GUSTAVE, R P	8306290625*	CONTRACT
GRANT, W B	8306100220*	50-151 Q	GROSSMAN, H	8306270333	50-460 Q	GUSTAVE, R P	8306290633*	CONTRACT
GRANT, W B	8306130333*	50-305 Q	GROSSMAN, H	8306270340	50-460 Q	GUSTIN, H L	8306100136*	50-366 P
GRANT, W B	8306270187*	50-2 Q	GROSSMAN, H	8306300127	50-460 Q	GUYMON, R H	8306160631*	50-153 P
GRAVES, R H	8306020260	50-213 R	GROUTENHUIS, M	8306020648	50-305 P	GWYNN, T P	8306230359*	50-350 Q
GRAVES, R H	8306160459	50-213 R	GROUTAGE, T M	8306140161	50-456 A	HAASS, W P	8306150400*	50-445 Q
GRAVES, R H	8306170331	50-213 S	GUCHA, L T	8306030233	50-321 F	HACKNEY, C A	8306010107*	50-313 Q
GRAVES, R H	8306170301	50-213 S	GUCHA, L T	8306070123	50-321 I	HACKNEY, C A	8306140636*	50-302 Q
GRAVES, R H	8306170347	50-213 S	GUCHA, L T	8306070125	50-366 Q	HAER, D I	8306140737*	50-289 F
GRAVES, R H	8306270001	50-213 Q	GUCHA, L T	8306070129	50-321 P	HAERER, B	8306030039	FOIA
GRAVES, R H	8306270361	50-213 Q	GUCHA, L T	8306070224	50-321 P	HAQAN, T F	8306020329*	CONTRACT
GRAY, J R	8306130408	50-289 Q	GUCHA, L T	8306100132	50-366 P	HAQAN, T F	8306020336*	CONTRACT
GREEN, A M	8306010020	50-327 S	GUCHA, L T	8306140075	50-321 P	HAER, C	8306020339*	50-219 S
GREEN, H J	8306010014	50-328 S	GUCHA, L T	8306150220	50-366 P	HAARMAN, D L	8306080229	RLS
GREEN, H J	8306010169	50-328 S	GUCHA, L T	8306160267	50-321 P	HAIRSTON, W G	8306100270	50-340 S
GREEN, H J	8306010237	50-260 S	GUCHA, L T	8306160397	50-366 P	HAIRSTON, W G	8306160119	50-364 R
GREEN, H J	8306010396	50-327 S	GUCHA, L T	8306170202	50-321 F	HAIRSTON, W G	8306160327	50-348 R
GREEN, H J	8306070039	50-327 S	GUCHA, L T	8306290303*	50-321 Q	HAIRSTON, W G	8306200220*	50-348 S
GREEN, H J	8306070084	50-260 S	GUDAS, J P	8306060410	NUREG	HAIRSTON, W G	8306200227*	50-348 S
GREEN, H J	8306070087	50-259 S	GUELLER, J	8306020240*	50-272 F	HAIRSTON, W G	8306200233*	50-348 S
GREEN, H J	8306070092	50-259 S	GUILD, R	8306150385	50-413 Q	HAIRSTON, W G	8306200336	50-348 S
GREEN, H J	8306070099	50-260 S	GUILD, R	8306150385	50-413 Q	HAIRSTON, W G	8306270232*	50-348 S
GREEN, H J	8306070218	50-328 S	GUILD, R	8306150385	50-413 Q	HAIRSTON, W G	8306270236*	50-348 S
GREEN, H J	8306070241	50-259 S	QUIMOND, P J	8306210024*	50-29 P	HAIST, D P	8306070254	50-508 S
GREEN, H J	8306070266	50-296 S	QUINN, F K	8306030283	70-143 Q	HAIST, D P	8306280409*	50-508 Q
GREEN, H J	8306070284	50-327 S	QUINN, F K	8306080381	70-143 Q	HALE, C J	8306130224*	04999
GREEN, H J	8306090157	50-259 S	QUINN, F K	8306140658	70-143 Q	HALE, C J	8306130410*	04999
GREEN, H J	8306100173	50-328 S	QUINN, F K	8306290572	70-143 Q	HALE, C J	8306210231	NISC
GREEN, H J	8306100192	50-296 S	QUINN, P R	8007160084*	FOIA	HALL, D L	8306010333*	50-348 Q
GREEN, H J	8306130163	50-296 S	QUINN, P R	8306030435*	FOIA	HALL, D L	8306290436*	70-1151
GREEN, H J	8306130242	50-328 S	QUINN, P R	8306060053*	FOIA	HALL, D L	8306200280*	FOIA
GREEN, H J	8306170423	50-296 S	QUINDEMOND, W	8306270222*	50-373 Q	HALL, D L	8306200282*	FOIA
GREEN, H J	8306200167	50-327 S	QUINDEMOND, W	8306300141*	50-373 Q	HALL, D P	8306070289	50-461 S
GREEN, H J	8306200332	50-327 S	QUINDEMOND, W	8306010346	50-286 S	HALL, D P	8306070338	50-461 S
GREEN, H J	8306210090	50-328 S	QUINDEMOND, W	8306020430	50-286 S	HALL, D P	8306070396	50-461 S
GREEN, H J	8306210106	50-328 S	QUINDEMOND, W	8306170024	70-1349	HALL, D P	8306100060	50-461 S
GREEN, H J	8306210136	50-260 S	QUINDEMOND, W	8306070452	NUREG	HALL, D P	8306100141	50-461 S
GREEN, H J	8306210165	TOPREP	QUINDEMOND, W	8306230169*	50-416 P	HALL, D P	8306170370	50-461 S
GREEN, H J	8306210218	50-327 S	GUSTAVE, R P	8306170259*	CONTRACT	HALL, D P	8306170383	50-461 S
GREEN, H J	8306210226	50-260 S	GUSTAVE, R P	8306040713*	CONTRACT	HALL, D P	8306270117	50-461 Q
GREEN, H J	8306210270	50-259 S	GUSTAVE, R P	8306010077*	CONTRACT	HALL, D P	8306270334	50-461 S
GREEN, H J	8306210290	50-328 S	GUSTAVE, R P	8306020513*	CONTRACT	HALL, N M	8306200134*	CONTRACT
GREEN, H J	8306270090	50-260 S	GUSTAVE, R P	8306030256*	CONTRACT	HALL, N M	8306210392*	50-309 F
GREEN, H J	8306270250	50-327 S	GUSTAVE, R P	8306070465*	CONTRACT	HAMADA, G	8306280310*	50-528 Q
GREEN, H J	8306270274	50-296 S	GUSTAVE, R P	8306080427*	CONTRACT	HAMADA, G H	8306070011*	50-344 Q
GREEN, H J	8306270327	50-260 S	GUSTAVE, R P	8306090452*	CONTRACT	HAMADA, G H	8306070339*	50-206 Q
GREEN, H J	8306270371	50-296 S	GUSTAVE, R P	8306090470*	CONTRACT	HAMADA, G H	8306280507*	50-397 Q
GREEN, H J	8306280192	50-327 S	GUSTAVE, R P	8306090488*	CONTRACT	HAMEL, M A	8306240391	77-39
GREEN, H J	8306280375	50-260 S	GUSTAVE, R P	8306140426*	CONTRACT	HAMILTON, M	8306200284*	FOIA
GREEN, H J	8306300066	50-259 S	GUSTAVE, R P	8306140438*	CONTRACT	HAND	8306160666*	50-389 F
GREEN, H J	8306300139	50-259 S	GUSTAVE, R P	8306130370*	CONTRACT	HANNETT, B A	8306020580	XPORTLIC
GREEN, H J	8306300181	50-260 S	GUSTAVE, R P	8306150273*	CONTRACT	HANNETT, B A	8306150333	XPORTLIC
GREEN, H J	8306300208	50-259 S	GUSTAVE, R P	8306170482*	CONTRACT	HANNETT, B A	8306150426	XPORTLIC
GREEN, H J	8306300224	50-260 S	GUSTAVE, R P	8306170485*	CONTRACT	HANNUM, W H	8306290566	50-201 P
GREENBERG, E. V.	8306220146	50-537 Q	GUSTAVE, R P	8306210344*	CONTRACT	HANSEN, K A	8306080224*	50-445 Q
GREENBERG, E. V.	8306220146	50-537 Q	GUSTAVE, R P	8306210371*	CONTRACT	HANSON, K J	8306230039*	50-373 A
GREENBLATT, D	8306090225	50-400 Q	GUSTAVE, R P	8306210375*	CONTRACT	HARDROVE, T W	8306160234	40-2259
GREENBLATT, D	8306090225	50-400 Q	GUSTAVE, R P	8306210388*	CONTRACT	HARDING, M R	8306010014	50-328 S

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
HARDING, M R	8306010020	50-327 S	HARVEY, F W	8306210313	FOIA	HIATT, S L	8306270017*	50-440
HARDING, M R	8306010169	50-328 S	HARVEY, S	8306110372*	50-329 A	HIATT, S L	8306270036*	50-440
HARDING, M R	8306010396	50-327 S	HARWARD, J E	8306230161*	FOIA	HIATT, S L	8306270037*	50-440
HARDING, M R	8306070039	50-327 S	HASSE, R A	83061100169*	50-403 Q	HICKEY, E E	8306140636*	50-382
HARDING, M R	8306070210	50-328 S	HASSE, R A	8306230279*	50-266 Q	HICKEY, M	8306080194	50-322
HARDING, M R	8306070284	50-327 S	HASSELL, D F	8306010348	50-247 Q	HIETALA, J J	8306060206	50-373
HARDING, M R	83061100173	50-328 S	HASSELL, D F	8306110396	50-247 Q	HIGGINBOTHAM, A	8306160366*	50-341
HARDING, M R	8306130242	50-328 S	HAUGHEY, M	8306090205	50-410 A	HIGGINBOTHAM, L	8306030432	WASTE M
HARDING, M R	8306200167	50-327 S	HAUGHEY, M F	8306240367	50-352 A	HIGGINBOTHAM, L	8306230144*	70-B
HARDING, M R	8306200332	50-327 S	HAUS, A	8306060309*	70-25	HIGGINBOTHAM, L	8306240385	WASTE M
HARDING, M R	8306210090	50-328 S	HAVIAN, E	8306150314	50-275 Q	HIGGINBOTHAM, L	8306240388	WASTE M
HARDING, M R	8306210106	50-328 S	HAVIAN, E	8306150314	50-275 Q	HIGGINS, J C	8306090076*	50-322
HARDING, M R	8306210210	50-327 S	HAWKINS, E F	8306030210	WASTE MGT	HIGGINS, J C	8306130391*	50-322
HARDING, M R	8306210270	50-328 S	HAWKINS, E F	8306140283	WASTE MGT	HILL, B	8306230144*	FOIA
HARDING, M R	8306270250	50-327 S	HAWKINS, F C	83061100169*	50-403 Q	HILL, W H	8306060122*	50-498
HARDING, M R	8306280192	50-327 S	HAWKINS, F C	8306130273*	50-315 Q	HILLMAN, R E	8306060282	50-219
HARDY, B L	8306200171	40-8084	HAWKINS, F C	8306230279*	50-266 Q	HILLMAN, R E	8306090235	50-219
HARDY, R W	8306130331*	50-327 F	HAWKINS, F C	8306230423*	50-374 Q	HILTUNEN, E	8306270110	50-305
HARMON, D W	8306060354	XPORTRIC	HAWKINS, F C	8306300063*	50-346 Q	HIND, J	8306230438	50-295
HARRAN, Q	8306020088	50-245 R	HAWLEY, S C	8306160010*	50-142 T	HIND, J A	8306100210	50-341
HARRAN, Q	8306160388	50-245 R	HAWLEY, S C	8306160010*	50-142 T	HIND, J A	8306130294	50-295
HARRELL, C W	8306070173	50-338 S	HAYES, D W	8306404022	50-388 Q	HIND, J A	8306070230	50-346
HARRELL, E W	8306070249	50-339 S	HAYES, D W	8306170364*	50-434 Q	HIND, J A	8306130363	50-331
HARRELL, E W	8306070276	50-339 S	HAYES, D W	8306220076*	50-461 Q	HIND, J A	8306130431	50-266
HARRELL, C W	8306070281	50-338 S	HAYES, D W	8306300184*	50-454 Q	HIND, J A	8306130447	50-266
HARRELL, C W	8306070137	50-338 S	HAYNES, J O	8306070029	50-361 Q	HIND, J A	8306230479*	50-403
HARRELL, E W	8306090138	50-338 S	HAYNES, J O	8306110011	50-206 Q	HINDS, J M	8306300184*	50-454
HARRELL, E W	8306090314	50-339 S	HAYNES, J O	8306230211	50-361 Q	HINKLE, L B	8306010297	50-318
HARRELL, E W	8306090318	50-338 S	HAYNES, R C	8306210354	NUREQ	HINKLE, L B	8306280332	50-318
HARRELL, E W	8306200114	50-339 S	HAYNES, R C	8306220181	50-277 Q	HINRICH, O	8306170405	50-247
HARRELL, E W	8306200209	50-339 S	HAYNES, R C	8306220191*	50-277 Q	HINRICH, O	8306170044	50-247
HARRELL, E W	8306200232	50-338 S	HEAD, J O	8306010389	50-128 R	HINRICH, O	8306170189	50-247
HARRELL, C W	8306270104	50-338 S	HEATH, R C	8306210297	FOIA	HINRICH, O	8306170197	50-247
HARRELL, E W	8306270142	50-339 S	HEATHERLY, T L	8306140434*	50-390 Q	HINRICH, O	8306170200	50-247
HARRELL, E W	8306270183	50-339 S	HEATHERLY, T L	8306140580*	50-390 Q	HINRICH, O	8306170271	50-247
HARRELL, C W	8306270316	50-339 S	HEBNER, M T	8306160139*	FOIA	HINRICH, O	8306170410	50-247
HARRELL, C W	8306270366	50-338 S	HEHL, C W	8306140423*	50-324 Q	HINZE, W J	8306080160	NUREQ
HARRELL, C W	8306270430	50-338 S	HEHL, C W	8306140580*	50-416 Q	HIPBER, H M	8306210423	27-48
HARRELL, E W	8306280560	50-338 S	HEIDEL, C M	8306010174*	50-341 K	HIRECH, D	8306150382	50-142
HARRELL, C W	8306300020	50-338 S	HEIDER, L H	8306010165*	50-27 Q	HIRECH, D	8306150392	50-142
HARRINGTON, Q W	8306070300*	0A999	HEIDER, L H	8306010246	50-271 P	HIRECH, D	8306170373	50-142
HARRINGTON, Q W	8306070312*	0A999	HEIDER, L H	8306010379	50-271 P	HIRECH, D	8306170377*	50-142
HARRINGTON, R M	8306280080	50-259 P	HEIDER, L H	8306010435	50-271 P	HIRECH, D	8306170390*	50-142
HARRINGTON, R M	8306280093	NUREQ	HEIDER, L H	8306020139	50-27 R	HIRECH, D	8306170417*	50-142
HARRINGTON, W D	8306240436	50-293 P	HEIDER, L H	8306020337	50-27 Q	HIRECH, D	8306170426*	50-142
HARRINGTON, W D	8306010060	50-293 S	HEIDER, L H	8306070302	50-29 Q	HICHENDONER, L.	8306160600	50-289
HARRINGTON, W D	8306010157	50-293 S	HEIDER, L H	8306070303	50-271 P	HODAS, D R.	8306060010	50-394
HARRINGTON, W D	8306010275	50-293 S	HEIDER, L H	8306150161	50-271 P	HODDON, A P	8306140676	50-352
HARRINGTON, W D	8306010332	50-293 S	HEIDER, L H	8306160382	50-29 H	HODDON, A P	8306140715	50-352
HARRINGTON, W D	8306010334	50-293 P	HEIDER, L H	8306200365*	50-29 Q	HODDON, A P	8306140722	50-352
HARRINGTON, W D	8306010386	50-293 S	HEIDER, L H	8306200369*	50-29 Q	HODDON, A P	8306280566	50-352
HARRINGTON, W D	8306010393	50-293 S	HEITNER, K L	8306210304	50-309 P	HODGE, S A	8306280080	50-259
HARRINGTON, W D	8306020154	50-293 R	HEITNER, K L	8306240397	50-309 P	HOFFMAN, D P	8306060095	50-155
HARRINGTON, W D	8306020419	50-293 S	HELD, J T	8306290413*	50-245 P	HOFFMAN, D P	8306160566	50-155
HARRINGTON, W D	8306020456	50-293 S	HELGESON, K A	8306130430	70-820	HOFFMAN, P	8306080306*	50-410
HARRINGTON, W D	8306070045	50-293 P	HELOESON, K A	8306290577	70-820	HOFFMAN, P.	8306080320*	50-410
HARRINGTON, W D	8306070167	50-293 P	HELLER, J K	8306300021*	50-255 Q	HOFFMAN, P.	8306080351*	50-410
HARRINGTON, W D	8306070348	50-293 P	HELMES, C J	8306020555*	FR	HOGAN, J P	8306090450	ADVCH
HARRINGTON, W D	8306140613	50-293 P	HELMES, C J	8306020490*	NUREQ	HOLDEN	8306140184	50-271
HARRINGTON, W D	8306140662*	50-293 Q	HELMES, C J	8306070461	50-272 S	HOLDEN	8306140476	50-271
HARRINGTON, W D	8306150011	50-293 P	HELMES, C J	8306280056*	FR	HOLDEN, C	8306020039	50-443
HARRINGTON, W D	8306210184	50-293 S	HENDRICKS, M	8306150461*	50-320 H	HOLDEN, C F	8306160006*	50-271
HARRINGTON, W D	8306210205	50-293 S	HENDRICKSON, R	8306100275	50-116 Q	HOLDEN, C F.	8306200181*	50-271
HARRINGTON, W D	8306220003	50-293 P	HENDEL, B	8306070189*	MISC	HOLDER, E T	8306070092	50-259
HARRINGTON, W D	8306240172	50-293 Q	HENNICK, A	8306240030	NUREQ	HOLDER, E T	8306270271	50-296
HARRINGTON, W D	8306280072	50-293 S	HENRY, A	8306080194	50-327 H	HOLDER, E T	8306270327	50-260
HARRINGTON, W D	8306280331	50-293 P	HENRY, L O	8306170052*	50-87 Q	HOLLAND, P.	8306070234	50-249
HARRINGTON, W D	8306280350	50-293 S	HERBERT, R J	8306010434	50-245 S	HOLLAND, R A	8306060376*	FOIA
HARRIS, J R	8306270320*	50-390 Q	HERBERT, R J	8306010434	50-245 S	HOLLEY, W L	8306010107*	50-313
HARRIS, J R	8306270371*	50-416 Q	HERBERT, R J	8306020397	50-245 S	HOLLEY, W L	8306080221*	50-446
HARRISON, F	8306140214	50-324 R	HERBERT, R J	8306020397	50-245 S	HOLMES, K R	8306140675*	MISC
HARRISON, F L	8306150044	50-272 P	HERING, R F	8306270312	50-315 P	HOLMES-RAY, P	8306270293*	50-321
HARRISON, J J	8306270181	50-329 S	HERMAN, R	8306150282	50-302 P	HOLT, J	8306070421	50-247
HARRISON, J J	8306060189	50-329 A	HERMAN, R W	8306030191	50-329 A	HOLT, J.	8306090308	50-247
HARRISON, J J	8306090245*	50-329 Q	HERMAN, R W	8306070449	50-329 A	HOLT, J.	8306090380	50-247
HARRISON, J J	8306270336	50-329 A	HERMAN, R W	8306070454	50-329 A	HOLT, J	8306230346	50-247
HARRISON, J J	8306270337	50-329 A	HERMANDEZ, G H	8306270350*	50-325 A	HOLTZ, J. L.	8306020218	50-334
HARRISON, J J	8306270367	50-329 A	HERR, J C	8306200316*	50-244 P	HOLTZ, J. L.	8306160476	50-334
HARB, B	8306060309*	70-25	HERR, P. D.	8306030363*	50-443 Q	HOLZNER, M	8306230330	50-155
HARBHAM, F	8306020032*	70-2953	HERR, P. D.	8306030363*	50-443 Q	HODD, A. C	8306230028*	50-373
HART, Q	8306160131*	FOIA	HERRINGTON, W N	8306140636*	50-382 Q	HODD, D	8306070425	50-329
HARTMANN, P. L	8306060221*	50-295 Q	HERRON, M M	8306230072*	FOIA	HODD, D.	8306170477	50-329
HARTZMAN, R. M	8306160024	50-247 Q	HERSCH, M H	8306090012	XPORTRIC	HOPKRAFT, C. P	8306060394	71-210
HARTZMAN, R. M	8306200324	50-247 Q	HIATT, B. L	8306060381	50-440 A	HOPKRAFT, C. P	8306210305	71-9163
HARTZMAN, R. M	8306200324	50-247 Q	HIATT, B. L	8306270014	50-440 Q	HOPKINS, H. R.	8306030266*	C*

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
HOPKINS, J B	8306020661	50-375 P	HUSEBY, D E	8306210246	50-318 S	JOHNSON, C E	8306210070*	50-381 Q
HOPKINS, J B	8306160299	50-395 P	HUTCHINS, O H	8306240331*	COMMISSION	JOHNSON, C R	8306240457	71-7010
HOPKINS, J B	8306160725	50-369 P	HWANG, H	8306020048	RC5	JOHNSON, O E	8306060072	50-413 G
HOPKINS, J B	8306200019	50-400 A	IDEKER, R L	8306270588	71-6357	JOHNSON, O E	8306070041	50-413 G
HOPKINS, J B	8306220177	50-445 A	IGNATONIS, A	8306100176	50-413 S	JOHNSON, G E	8306090305	50-413 G
HOPKINS, J B	8306240351	50-395 P	IMEL, O R	8306070452	NUREG	JOHNSON, O E	8306170365	50-413 G
HOPKINS, J B	8306290573	50-369 P	IPPOLITO, T A	8306090363	10PRCP	JOHNSON, O E	8306210294	50-413 G
HOPKINS, J M	8306270177	40-8584	IRBY, B J	8306300208	50-259 S	JOHNSON, O E	8306280084	50-413 G
HORDIS, B A	8306170387	50-352 H	IRVING, S M	8306220117	50-458 G	JOHNSON, J	8306280166*	50-293 G
HORIN, W A	8306080243*	50-445 G	IRWIN, H R	8306020468	71-5796	JOHNSON, L H	8306290220*	50-440 G
HORIN, W A	8306150366	50-445 G	IRWIN, R	8306160137*	FOIA	JOHNSON, L H	8306290220*	50-440 G
HORIN, W A	8306150366	50-445 G	ISHII, M	8306280085	NUREG	JOHNSON, R M	8306210362	NUREG
HORSCHTEL, D S	8306020080	NUREG	ISRAEL, B H	8306240358*	CONTRACT	JOHNSON, R M	8306160506*	50-445 G
HOSSEY, C M	8306140357*	70-1113	JABBOUR, K N	8306210427*	50-369 P	JOHNSON, R T	8306270151	NUREG
HOSSEY, C M	8306140477*	50-348 G	JACKI, I	8306160264	50-304 S	JOHNSON, R T	8306170291*	FOIA
HOUSTON, D	8306220250	50-416 P	JACKI, I	8306220330	50-155 S	JOHNSON, T C	8306140189	WASTE MOI
HOUSTON, J C	8306160015	FOIA	JACKI, I N	8306220050*	50-346 G	JOHNSON, T L	83062020331*	40-8584
HOUSTON, R W	8306220064	50-373 S	JACKI, I N	8306270341*	50-305 G	JOHNSON, V M	8306300202	50-389 S
HOYT, J B	8306240120*	FOIA	JACKSON, B M	8306270389*	50-409 G	JOHNSON, W	8306080230*	50-313 G
HOME, P. W	8306140547	50-324 G	JACKSON, G	8306210326*	FOIA	JOHNSON, W D	8306010107*	50-313 G
HOME, P. W	8306240145	50-325 P	JACKSON, G	8306030053	71-7056	JOHNSON, W D	8306080211*	50-285 G
HOME, P. W	8306240246	50-324 P	JACKSON, O	8306240430	71-9006	JOHNSON, W D	8306090354*	50-285 G
HOME, P. W	8306280489	50-325 G	JACKSON, K C	8306030431	WASTE MGT	JOHNSON, W D	8306140197*	50-407 G
HOME, P. W	8306280524	50-324 P	JACKSON, L H	8306030442	WASTE MGT	JOHNSON, W D	8306140320*	50-483 G
HOME, P. W	8306290402	50-324 G	JACKSON, L H	8306140512*	50-400 G	JOHNSON, W D	8306140336*	50-72 G
HOYLE, A	8306030048	CONTRACT	JACKSON, P D	8306270233*	50-537 G	JOHNSON, W D	8306140247*	50-482 G
HOYLE, A	8306220244	CONTRACT	JACKSON, P D	8306090337	WASTE MGT	JOHNSON, W D	8306140363*	50-313 G
HOYLE, J C	8306080092	ADVCM	JACKSON, R L	8306240373	NUREG	JOHNSON, W P	8306010448	50-443 G
HOYLE, J C	8306080096	ADVCM	JACKSON, T J	8306080098	70-820	JOHNSON, W P	8306010448	50-443 G
HOYLE, J C	8306080101	ADVCM	JACOB, N	8306280484*	50-293 G	JOHNSON, G	8306280452*	50-528 G
HOYLE, J C	8306140517*	ADVCM	JACOB, N	8306280190	NUREG	JOHNSTON, M M	8306220029	50-341 G
HOYLE, J C	8306140734*	ADVCM	JACOB, N	8306300219	PR	JONES, E E	8306090247	50-10 F
HOYT, H F	8306080166	50-443 G	JACOBSON, R L	8306270237*	40-8610	JONES, E E	8306160214	50-10 F
HOYT, H F	8306080176	50-443 G	JACOBSON, R L	8306270237*	40-8610	JONES, K C	8306020585	71-302
HOYT, H F	8306080186	50-443 G	JACOBSON, R L	8306080077	MISC	JONES, R A	8306090315*	50-445 G
HOYT, H F	8306220079	50-443 G	JAFFE, D H	8306160083*	50-317 G	JONES, V	8306020162*	50-280 R
HOYT, H F	8306270249	50-443 G	JAMISON, J D	8306140436*	50-382 G	JONES, V	8306140375	50-280 R
HUBBARD, G T	8306210286*	0A979	JANDOVITZ, J B	8306150413*	50-155 G	JONES, W C	8306060153	50-285 F
HUBBARD, R B	8306220052*	50-275 G	JANG, J C	8306020407*	50-317 G	JONES, W C	8306060299	50-285 F
HUBSON, S D	8306060227*	50-220 G	JANKOWSKI, H W	8306070471	NUREG	JONES, W C	8306080236*	50-285 G
HUDSPETH, J B	8306070208*	50-348 F	JANUSKA, A G	8306270174*	50-155 G	JONES, W C	8306090032*	50-285 F
HUDSPETH, J B	8306160032*	50-348 F	JAPE, F	8306140191*	50-389 G	JONES, W C	8306100102	50-285 F
HUDSPETH, J B	8306210365*	50-348 F	JAPE, F	8306140195*	50-390 G	JONES, W C	8306130130*	50-285 G
HUETER, L	8306160169	50-373 B	JAPE, F	8306140362*	50-390 G	JONES, W C	8306130260	50-285 G
HUFFMAN, O N	8306140310*	50-335 G	JAPE, F	8306140400*	50-280 G	JONES, W C	8306130364	50-285 G
HUFFMAN, O N	8306140541*	50-335 G	JAPE, F	8306140537*	50-369 G	JONES, W C	8306160354*	50-285 F
HUGHES, R J	8306030338	TOPREP	JAPE, F	8306170023*	50-454 G	JONES, W C	8306200358	50-285 R
HUGHES, R J	8306030339*	TOPREP	JAPE, F	8306290212*	50-250 G	JONES, W C	8306210360*	50-285 F
HUKILL, H D	8306010404	50-219 P	JAPE, F	8306290285*	50-389 G	JONES, W C	8306270105	50-285 F
HUKILL, H D	8305060487	50-289 P	JAPE, F	8306290404*	50-413 G	JONES, W C	8306280232	50-285 F
HUKILL, H D	8306010353	50-289 S	JAPE, F	8306270511*	50-390 G	JONES, W C	8306280464	50-285 F
HUKILL, H D	8306010407	50-289 R	JAPE, F	8306290517*	50-369 G	JONES, W C	8306280487	50-285 F
HUKILL, H D	8306060181	50-289 P	JARRETT, R D	8306070458*	71-9182	JONES, W C	8306300069	50-285 F
HUKILL, H D	8306100120	50-289 F	JENKINS, O R	8306140244*	50-416 G	JORDAN, E D	8306280351*	50-77 G
HUKILL, H D	8306140014	50-289 P	JENKINS, O R	8306140310*	50-335 G	JORDAN, E L	8305110460	50-3 G
HUKILL, H D	8306140480	50-289 P	JENKINS, O R	8306140541*	50-335 G	JORDAN, E L	8305110461	50-3 G
HUKILL, H D	8306140586	50-289 P	JENKINS, O R	8306140542*	50-327 G	JORDAN, E L	8305110464	50-3 G
HUKILL, H D	8306140623	50-289 P	JENKINS, O R	8306140655*	50-348 G	JORDAN, E L	8305110470	50-3 G
HUKILL, H D	8306140732	50-289 F	JENKINS, O R	8306290426*	50-261 G	JORDAN, E L	8305110475	50-3 G
HUKILL, H D	8306170256	50-289 P	JENKINS, L L	8306020454	PR	JORDAN, E L	8305110477	50-3 G
HUKILL, H D	8306200127	50-289 S	JENNINGS, F	8306010361*	50-128 P	JORDAN, E L	8305110479	50-3 G
HUKILL, H D	8306200246	50-289 S	JENNINGS, R T	8306170031	50-317 S	JORDAN, E L	8305110483	50-3 G
HUKILL, H D	8306210247	50-289 S	JENSEN, D L	8306140681	ADVCM	JORDAN, E L	8306090010	50-3 G
HUKILL, H D	8306210247	50-289 S	JESTER, W A	8306070452	NUREG	JORDAN, M	8306130327	50-331 G
HUKILL, H D	8306270231	50-289 P	JOHANSEN, E	8306030293	50-344 J	JORDAN, W H	8306280554	50-446 G
HUKILL, H D	8306270233*	50-289 P	JOHNSON, A R	8306210020*	0A979	JORDAN, W S	8306010382	50-443 G
HUKILL, H D	8306280365	50-289 G	JOHNSON, B D	8306070068	50-255 G	JORDAN, W S	8306010382	50-443 G
HUKILL, H D	8306280366	50-289 G	JOHNSON, B D	8306070236	50-255 S	JORDAN, W S	8306290554	50-443 G
HUKILL, H D	8306300078	50-289 G	JOHNSON, B D	8306070240	50-255 S	JORDAN, W S	8306290554	50-443 G
HUNNICUTT, D M	8306060122*	50-478 G	JOHNSON, B D	8306070282	50-255 S	JORDAN, W S	8306300142	PR
HUNNICUTT, D M	8306140249*	50-482 G	JOHNSON, B D	8306100179	50-255 R	JORGENSEN, B L	8306300021*	50-255 G
HUNNICUTT, D M	8306140374*	50-445 G	JOHNSON, B D	8306130374	50-255 S	JORGENSEN, B L	8306300026	50-373 S
HUNNICUTT, D M	8306160317	50-313 S	JOHNSON, B D	8306170335	50-155 G	JOYNER, P H	8306060297	50-413 G
HUNNICUTT, D M	8306160644	50-313 S	JOHNSON, B D	8306220013	50-255 S	JOYNER	8306210237	J&F
HUNNICUTT, D M	8306210070*	50-382 G	JOHNSON, B D	8306220236	50-255 S	JOYNER	8306210240	50-334 B
HUNT, B D	8306280202	50-320 P	JOHNSON, B D	8306230287	50-255 R	JOYNER, J	8306110279	J&F
HUNT, M D	8306160254*	50-440 G	JOHNSON, B D	8306230374	50-255 P	JOYNER, J	8306110289	J&F
HUNT, M D	8306290221*	50-335 G	JOHNSON, B D	8306230413	50-255 P	JOYNER, J	8306230001	50-245 G
HUNTER, D R	8306060138*	50-358 G	JOHNSON, B D	8306270043	50-255 S	JOYNER, J	8306230263	J&F
HUNTER, D R	8306070042*	50-358 G	JOHNSON, B D	8306270432	50-255 S	JOYNER, J	8306280537	J&F
HUNTER, D R	8306230359*	50-358 G	JOHNSON, B D	8306270435	50-255 S	JULIAN, C	8306140627*	50-280 G
HUNTER, R. S.	8306020281	50-315 P	JOHNSON, B J	8306030379	FOIA	JULIAN, C	8306140647*	50-338 G
HURFORD, W. J.	8306220273	50-261 F	JOHNSON, C	8306070018	FOIA	JULIAN, C A	8306070191	50-389 G
HURST, A.	8306100311*	50-289 H	JOHNSON, C	8306280230	FOIA	JULIAN, C A	8306230248	50-339 G
HUSEBY, D E	8306010273	50-318 S	JOHNSON, C E	8306140374*	50-445 G	JULIAN, C A	8306290379*	50-335 G

PERSONAL AUTHOR INDEX

479

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
JUNGE, M A	8306010273	50-318 S	KEISER, H W	8306020401	50-387 S	KERR, O W	8306030390*	FOIA
JUNGE, M A	8306010307	50-317 S	KEISER, H W	8306090246	50-387 S	KERR, O W	8306030395*	FOIA
JUNGE, M A	8706170420	50-318 S	KEISER, H W	8306170015	50-387 S	KERR, O W	8306150974	NUREQ
JUNGE, M A	8306210159	50-318 S	KEISER, H W	8306170191*	50-387 P	KETTEVER, J W	8306160560*	50-267
JUNGE, M A	8306280462	50-318 S	KEISER, H W	8306170217	50-387 S	KEY, W J	8306030213*	50-374
KACICH, R M	8306130233	REVIEW GRP	KEISER, H W	8306170413	50-387 S	KHATIB-RAHBAR	8306020072	NUREQ
KACICH, R M	8306130233	REVIEW GRP	KEISER, H W	8306210050	50-387 S	KIBLER, D R	8306060209	50-331
KADAMBI, N P	8306200017	50-400 A	KEISER, H W	8306210212	50-387 S	KIBLER, D R	8306270290	50-331
KADAMBI, N P	8306270012	50-400 A	KEISER, H W	8306280140	50-387 S	KIEL, O R	8306020659*	XPORTLIC
KAHLE, J D	8306290380*	50-302 Q	KEISER, H W	8306280340	50-387 S	KIEL, O R	8306030051	XPORTLIC
KAKU, M	8306170377*	50-142 T	KEISER, H W	8306280399	50-387 S	KIEL, O R	8306030060*	XPORTLIC
KAKU, M	8306170390*	50-142 T	KEISER, H W	8306280434	50-387 S	KIEL, O R	8306140280	XPORTLIC
KAKU, M	8306170417*	50-142 T	KEISER, H W	8306280510	50-387 S	KIESER, H W	8306170037	50-387
KAKU, M	8306170426*	50-142 T	KEISER, H W	8306280518	50-387 S	KILCOYNE, J J	8306280438	50-289
KALIVIANAKIS, N	8306130329	50-254 S	KEISER, H W	8306280548	50-387 S	KILLOUGH, O G	8306210350	NUREQ
KALIVIANAKIS, N	8306130337	50-254 S	KELLER, O R	8306080148	NUREQ	KING, W	8306270390	50-322
KALIVIANAKIS, N	8306130314	50-254 S	KELLER, O R	8306020042	50-334 V	KINNEMAN	8306210237	14E
KALIVIANAKIS, N	8306170344	50-266 S	KELLEY, D L	8306130261*	50-445 Q	KINNEMAN, J	8306020392*	70-698
KALIVIANAKIS, N	8306270252	50-254 S	KELLEY, J L	8306010439	50-400 Q	KINNEMAN, J	8306060172*	40-672
KALIVIANAKIS, N	8306300043	50-254 S	KELLEY, J L	8306070393	50-400 Q	KINNEMAN, J	8306060177*	40-672
KALMAN, K L	8306030200	WASTE MGT	KELLEY, J L	8306160612	50-413 Q	KINNEMAN, J	8306060179*	40-672
KALMAN, K L	8306220287	WASTE MGT	KELLEY, J L	8306220042	50-413 Q	KINNEMAN, J	8306140269	14E
KALMON, K	8306270302	50-373 S	KELLEY, J L	8306220090	50-400 Q	KINNEMAN, J	8306280203	14E
KALUZYNY, B P	8306140691	NUREQ	KELLEY, W D	8306210031*	Q4999	KINNEMAN, J D	8306010263	40-84
KAMMER, D B	8306140041	50-260 Q	KELLY, B	8306080194	50-322 H	KINNEMAN, J D	8306150163*	70-2669
KAMMER, D B	8306140266*	50-259 Q	KELLY, E	8306060260*	50-322 Q	KINNEY, W W	8306160246*	50-193
KAMMER, D B	8306140420*	50-370 Q	KELLY, J A	8306160362*	50-298 Q	KINNEY, W W	8306280353*	50-77
KAMMER, D B	8306150094*	50-327 F	KELLY, J A F	8306240140*	50-274 Q	KINSTON, P B	8306200247*	50-397
KAMMER, D B	8306210010	50-259 F	KELLY, L	8306160385	50-286 R	KIRK, W F	8306030502	70-371
KAMMER, D B	8306210217	50-370 E	KELLY, W J	8306020214	50-275 R	KIRK, W F	8306080022	71-5641
KAMMER, D B	8306290203*	50-259 Q	KELLY, W J	8306100067	50-275 S	KIRKLAND, M W	8306020234	70-754
KAMMERER, C	8306140521*	ADVCM	KELLY, W J	8306100082	50-275 S	KIRKPATRICK, D	8306240063	NUREQ
KAMMERER, C	8306160125*	FOIA	KELLY, W J	8306160535	50-275 R	KIRSCH, D F	8306070098*	50-275
KAMMEYER, D J	8306020119	50-344 R	KELLY, W J	8306210044	50-275 S	KIRSCH, D F	8306070244*	50-206
KAMMEYER, D J	8306160392	50-344 R	KELLY, W J	8306210070	50-275 S	KIRSCH, D F	8306070255*	50-206
KANA, D D	8306020683	RES	KELLY, W J	8306210114	50-275 S	KIRSCH, D F	8306070261*	50-206
KANE, R S	8306280387	50-199 H	KELLY, W J	8306230365	50-275 S	KIRSCH, D F	8306070368*	50-361
KANO, P	8306220226*	50-309 P	KELLY, W J	8306230422	50-275 S	KIRSCH, D F	8306230398	50-361
KANGA, B K	8306010329	50-320 S	KELLY, W J	8306280421	50-275 S	KIRSCH, D F	8306270344*	50-275
KANGA, B K	8306020096	50-320 P	KELLY, W J	8306280523	50-275 S	KIRSCH, D F	8306270350*	50-275
KANGA, B K	8306130137	50-320 Q	KELLY, W J	8306280526	50-275 S	KIRSCH, D F	8306280017	50-275
KANGA, D K	8306170025	50-320 S	KELMER, A D	8306280093	NUREQ	KIRSCH, D F	8306280194*	50-275
KANGA, D K	8306170282	50-320 P	KEMP, R D	8306030340	HIBC	KIRSCH, D F	8306280480*	50-206
KANGA, B K	8306200357	50-320 P	KEMPER, J B	8306160310	50-352 A	KIRSCH, D F	8306280511*	50-361
KANGA, B K	8306220035	50-320 P	KEMPER, J B	8306230276	50-352 A	KIRSCH, D F	8306280551*	50-361
KANGA, B K	8306220054	50-320 P	KEMPER, J B	8306270315	50-352 E	KIRSCH, D F	8306280561*	50-361
KAPPEL, B	8306280186	FOIA	KEMPER, J B	8306280381	50-352 E	KIRSLIS, B S	8306150262*	50-443
KARAGIANTIS, J A	8306270282	50-10 S	KEMPER, J B	8306280417	50-352 S	KISH, J M	8306230423*	50-374
KARMAN, M	8306160007	50-261 Q	KENDALL, J M	8306210024*	50-29 P	KISS, E	8306210153*	TOPREP
KARMAN, M	8306300138	50-482 G	KENNEDY, D M	8306130310	50-255 R	KISTER	8306140476	50-271
KARR, J W	8306290498	50-329 Q	KENNEY, E S	8306070452	NUREQ	KISTER	8306170332	50-271
KARR, J W	8306290490	50-329 Q	KENNY, T	8306140690	50-286 S	KISTER, H	8306070052*	50-286
KARR, J W	8306290530	50-327 Q	KENNY, T J	8306070052*	50-286 Q	KISTER, H	8306140080	50-333
KASE, K R	8306280190	NUREQ	KENT, B	8306060309*	70-25	KISTER, H B	8306010378*	50-247
KASSNER, T F	8306280096	NUREQ	KENT, E E	8306160292*	FOIA	KISTER, H B	8306020074	50-244
KATAOKA, I	8306280085	NUREQ	KENT, O J	8306200152	50-344 R	KISTER, H B	8306060227*	50-220
KAUFMAN, P H	8306220045	50-275 Q	KENT, J	8306010153*	70-371	KISTER, H B	8306060237*	50-333
KAY, H B	8306140039	50-361 S	KENYON, B D	8306010177*	50-387 Q	KISTER, H B	8306160372*	50-244
KAY, J A	8306140067	50-29 Q	KENYON, B D	8306010210	50-387 S	KISTER, H B	8306230199*	50-244
KAY, J A	8306170390	50-29 P	KENYON, B D	8306020223	50-387 R	KISTER, H B	8306230322*	50-244
KAY, J A	8306210017	50-29 P	KENYON, B D	8306020444*	50-387 Q	KLAPPROTH, J F	8306080105	TOPREP
KEANE, M C	8306090380*	50-309 P	KENYON, B D	8306070214	50-387 F	KLEINGORGE, W P	8306140349*	50-335
KEARNEY, J J	8306060229	PR	KENYON, B D	8306140482	50-387 Q	KLEINGORGE, W P	8306290337*	50-250
KEARNEY, J J	8306300223	PR	KENYON, B D	8306140472	50-387 R	KLINBERG, S B	8306220123	50-410
KEATING, D E	8306230271*	50-440 Q	KENYON, B D	8306170180	50-387 P	KLINE, J R	8306150422	50-338
KEATING, D E	8306230359*	50-358 Q	KENYON, B D	8306210143	50-387 F	KLING, C L	8306070159*	50-317
KEATING, L A	8306150615*	50-322 F	KENYON, B D	8306270240	50-387 R	KLUGELEIN, J	8306080194	50-322
KEITHIO	8306140154	50-271 G	KENYON, T J	8306020604	50-390 A	KMETYK, L N	8306280049	NUREQ
KEITHIO, R	8306140080	50-333 S	KEPPLER, J Q	8306060129	50-358 Q	KNAPIK, H	8306280193	FOIA
KEITHIO, R	8306150008*	50-289 Q	KEPPLER, J Q	8306060132*	50-358 Q	KNEZDOVICH, J P	8306150044	50-272
KEITHIO, R R	8306060220*	50-219 Q	KEPPLER, J Q	8306070033	50-358 Q	KNICOLEY, J R	8306210075*	50-263
KEITHIO, R R	8306150615*	50-352 Q	KEPPLER, J Q	8306070094	50-409 Q	KNIEBER, O W	8306160556*	Q4999
KEISER, H	8306090026*	50-387 F	KEPPLER, J Q	8306090125	50-295 Q	KNIEBER, O W	8306160578*	Q4999
KEISER, H W	8306010061	50-387 S	KEPPLER, J Q	8306210006	50-546 Q	KNIIGHT, N L	8306080265	FOIA
KEISER, H W	8306010068	50-387 S	KEPPLER, J Q	8306210177	50-263 Q	KNIIGHTON, O W	8306020013	50-412
KEISER, H W	8306010070	50-387 S	KEPPLER, J Q	8306220025	50-255 F	KNIIGHTON, O W	8306020024	50-498
KEISER, H W	8306010077	50-387 S	KEPPLER, J Q	8306220028	50-254 Q	KNIIGHTON, O W	8306020056	50-528
KEISER, H W	8306010150	50-387 S	KEPPLER, J Q	8306230056*	50-373 Q	KNIIGHTON, O W	8306020487	50-382
KEISER, H W	8306010270	50-387 S	KEPPLER, J Q	8306230476	50-483 Q	KNIIGHTON, O W	8306030062	50-361
KEISER, H W	8306010309	50-387 S	KEPPLER, J Q	8306270293	50-254 Q	KNIIGHTON, O W	8306080064	50-400
KEISER, H W	8306010313	50-387 S	KEPPLER, J Q	8306270298*	50-254 Q	KNIIGHTON, O W	8306140784	50-335
KEISER, H W	8306010323	50-387 S	KEPPLER, J Q	8306270311	50-461 Q	KNIIGHTON, O W	8306150149	50-412
KEISER, H W	8306020367	50-387 S	KEPPLER, J Q	8306020213	50-315 Q	KNIIGHTON, O W	8306150150*	50-412
KEISER, H W	8306020382	50-387 S	KERR, O W	8306020035	State Prog	KNIIGHTON, O W	8306160011	50-206
KEISER, H W	8306020394	50-387 S	KERR, O W	8306020496	State Prog	KNIIGHTON, O W	8306160272	50-400

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
KNIGHTON, Q W	8306160630	50-389 P	KRUIG, H E	8306290225*	50-389 Q	LEDDICK, R S	8306170296	50-508 B
KNIGHTON, Q W	8306160657	50-400 A	KRUZIC, R W	8306160639	71-9141	LEDDICK, R S	8306170420*	50-508 B
KNIGHTON, Q W	8306170079	50-508 E	KUBINAK, R A	8306060231	PR	LEE, J	8306130389	50-269 M
KNIGHTON, Q W	8306220291	50-206 F	KUCZYNSKI, L A	8306010150	50-387 S	LEE, J	8306170385	50-269 M
KNIGHTON, Q W	8306220294	50-206 F	KUCZYNSKI, L A	8306010278	50-387 S	LEE, J C	8306210453	ACRS
KNIGHTON, Q W	8306230520	50-206 F	KUCZYNSKI, L A	8306020223	50-387 R	LEE, J C	8306210453	ACRS
KNIGHTON, Q W	8306240463	50-400 E	KUCZYNSKI, L A	8306020382	50-387 S	LEE, K W	8306240241	RES
KNIGHTON, Q W	8306240464	50-275 P	KUCZYNSKI, L A	8306020394	50-387 S	LEE, O R	8306010335	50-267 P
KNIGHTON, Q W	8306240465	50-275 V	KUCZYNSKI, L A	8306160472	50-387 R	LEE, O R	8306010343	50-267 P
KNIGHTON, Q W	8306240466	50-389 P	KUCZYNSKI, L A	8306170217	50-387 S	LEE, O R	8306010344*	50-267 P
KNIGHTON, Q W	8306240467	50-400 E	KUCZYNSKI, L A	8306170413	50-387 S	LEE, O R	8306010411	50-267 P
KNIGHTON, Q W	8306240468	50-400 E	KUCZYNSKI, L A	8306210212	50-387 S	LEE, O R	8306010416*	50-267 P
KNIGHTON, Q W	8306240479*	50-361 P	KUCZYNSKI, L A	8306280348	50-387 S	LEE, O R	8306280343	50-267 P
KNOP, R C	8306060241	50-483 Q	KUHLUM, W	8306060309*	70-25	LEE, O R	8306300104	50-267 Q
KNOP, R C	8306060242*	50-483 Q	KUKIELKA, C	8306160631*	50-155 P	LEE, S T	8306210433	XPORTRLIC
KNOP, R C	8306170049	50-341 Q	KULP, C J	8306140365	50-412 C	LEECH, P H	8306020642	50-336 P
KNOP, R C	8306210291	50-341 Q	KUNIHITO, D H	8306280081*	50-206 Q	LEFAVE, W T	8306150259*	50-443 Q
KNOP, R C	8306220066	50-461 Q	KUNITA, R K	8306080083*	50-324 P	LEFAVE, W T	8306150262*	50-443 Q
KNOP, R C	8306270201	50-546 Q	KUNKLE, Q L	8306090076*	50-322 Q	LEFAVE, W T	8306150437*	50-443 Q
KNOP, R C	8306300084	50-483 Q	KUO, W	8306010086	NUREQ	LEQUETT, R W	8306020122	NURCO
KNOP, R C	8306300170	50-483 Q	KUPPERMAN, D S	8306280096	NUREQ	LEMPGES, T E	8306010250	50-220 I
KNOP, R C	8306300178	50-454 Q	KURTZ, S R	8306280141	NUREQ	LEMPGES, T E	8306010412*	50-220 R
KNOP, R C	8306300179	50-440 Q	KUCZYNSKI, L A	8306210050	50-387 S	LEMPGES, T E	8306280094	50-220 R
KNOP, R C	8306300182*	50-483 Q	LABAR, H P	8306210415*	71-6346	LEMPGES, T E	8306030352	50-220 I
KNOP, R C	8306300184*	50-454 Q	LABARGE, F	8306220116	40-299	LEMPGES, T E	8306060179	50-220 S
KNOP, R C	8306300201	50-440 Q	LABARGE, F	8306220118	40-299	LENAHAN, J J	8306140180*	50-389 Q
KOEHL, K M	8306170077	70-498	LACEY, W S	8306110818	50-334 S	LENAHAN, J J	8306140474*	50-416 Q
KOEBSTER, Q L	8306060191	50-482 K	LACEY, W S	8306010295	50-334 S	LENAHAN, J J	8306140520*	50-389 Q
KOEBSTER, Q L	8306070194	50-482 S	LACEY, W S	8306010302	50-334 S	LENAN, J J	8306140672*	50-259 Q
KOEBSTER, Q L	8306070262	50-482 S	LACEY, W S	8306020324	50-334 S	LENT, N F	8306140323	50-322 JI
KOEBSTER, Q L	8306080175	50-482 A	LACEY, W S	8306020383	50-334 S	LENTINE, F O	8306210073	50-295 P
KOEBSTER, Q L	8306080188*	50-482 Q	LACEY, W S	8306020440	50-334 S	LENTINE, F O	8306230217	50-295 P
KOEBSTER, Q L	8306090231	50-482 S	LACEY, W S	8306170030	50-334 S	LENTINE, F O	8306270329	50-295 P
KOEBSTER, Q L	8306130043	50-482 S	LACEY, W S	8306280382	50-334 S	LEONARD, M	8306080194	50-322 H
KOEBSTER, Q L	8306130138	50-482 S	LACEY, W S	8306280139	50-334 S	LERMAN, D H	8306160305	50-322 H
KOEBSTER, Q L	8306130393	50-482 Q	LAFLEH, S J	8306170186	50-309 S	LESKY, A G	8306230039*	CONTRACT
KOEBSTER, Q L	8306140230	50-482 A	LAFLEH, S J	8306010277	50-317 S	LESSOR, L C	8306020140	50-293 R
KOEBSTER, Q L	8306150487*	50-482 F	LAFLEH, S J	8306010299	50-318 S	LESSY, R P	8306080093	50-443 Q
KOEBSTER, Q L	8306160415	50-482 S	LAFLEH, S J	8306010300	50-317 S	LESSY, R P	8306080088	50-443 Q
KOEBSTER, Q L	8306160539	50-482 A	LAFLEH, S J	8306200110	50-318 S	LESSY, R P	8306090276	50-309 Q
KOEBSTER, Q L	8306160565	50-482 S	LAFLEH, S J	8306200208	50-317 S	LESSY, R P	8306150230	50-443 Q
KOEBSTER, Q L	8306170386	50-482 S	LAFLEH, S J	8306210108	50-317 S	LESSY, R P	8306150256	50-443 Q
KOEBSTER, Q L	8306270088	50-482 Q	LAFLEH, S J	8306210246	50-318 S	LESSY, R P	8306200173	50-443 Q
KOEBSTER, Q L	8306270352	50-482 S	LAFLEH, S J	8306070473	NUREQ	LESSY, R P	8306270306	50-443 Q
KOEBSTER, Q L	8306280335	50-482 B	LAFLEH, S J	8306220300	TOPREP	LETSCH, K J	8306280601	50-322 Q
KOEBSTER, Q L	8306300100	REGD	LAHASTRA, H A	8306070140*	FOIA	LETSCH, K J	8306280601	50-322 Q
KOHN, R	8306170379*	50-142 T	LAND, R J	8306010389	50-128 R	LETSCH, K J	8306300094	50-322 Q
KOHN, R	8306170390*	50-142 T	LANDAU, H	8306150574	NUREQ	LETSCH, K J	8306300094	50-322 Q
KOHN, R	8306170417*	50-142 T	LANDGRAF, L C	8306010168	50-341 K	LEUTSCH, R	8306130372*	50-329 A
KOHN, R	8306170426*	50-142 T	LANDGRAF, L C	8306010168	50-341 K	LEVENTHAL, P	8306060034	FOIA
KOLACZKOWSKI, A	8306010052	NUREQ	LANDHMAN, R	8306270181	50-329 B	LEVENTHAL, P	8306160143*	FOIA
KOLB, L E	8306280504	50-395 S	LAND, O E	8306070210*	50-413 E	LEVI, R	8306140329	ADVCM
KOLB, L E	8306300049	50-395 S	LANDE, O	8306210122*	50-409 P	LEVI, R P	8306080337	ADVCM
KOLTA, P	8306010378*	50-247 Q	LANKSBURY, R D	8306100175*	50-373 Q	LEVI, R P	8306140229	ADVCM
KOLTA, P	8306230212*	50-247 Q	LANKPHER, L C	8306060292	50-322 Q	LEVI, R P	8306140270	ADVCM
KONKLIN, J E	8306060244*	50-483 Q	LANKPHER, L C	8306060292	50-322 Q	LEVI, R P	8306140509	ADVCM
KONKLIN, J E	8306170055	50-341 Q	LANKPHER, L C	8306220134	50-322 Q	LEVI, R P	8306140726	ADVCM
KONKLIN, J E	8306210298*	50-341 Q	LANKPHER, L C	8306220134	50-322 Q	LEVI, R P	8306140756	ADVCM
KONKLIN, J E	8306270205*	50-546 Q	LANKPHER, L C	8306230337	50-312 Q	LEVI, R P	8306170310	ADVCM
KONKLIN, J E	8306300183*	50-440 Q	LARIZZA, Q F	8306210034	50-244 B	LEVI, R P	8306220234	50-458 F
KONKLIN, J E	8306300186*	50-483 Q	LARSEN, J	8306080303*	50-410 A	LEVIN, H A	8306270067	50-329 R
KONKLIN, J E	8306300207*	50-440 Q	LARSEN, J	8306080343*	50-410 A	LEVINE, J M	8306150034*	50-313 I
KONZEK, Q J	8306020131	NUREQ	LARSEN, C E	8305060453	50-263 Q	LEVINE, J M	8306200060*	50-313 I
KOBLA, B M	8306140767	40-8027	LARSEN, C E	8306170134	50-263 Q	LEVINE, J M	8306270192	50-368 B
KOTTAN, J J	8306020407*	50-317 Q	LARSEN, C E	8306170232	50-282 Q	LEVINSON, C D	8306240012*	50-324 JI
KOTTAN, J J	8306230397*	50-293 Q	LARSEN, C E	8306270399	50-322 Q	LEWIS, D R	8306220077	50-443 Q
KRAMER, E W	8306140063*	50-272 P	LARSEN, C E	8306130398	50-322 Q	LEWIS, D R	8306220085	50-443 Q
KRANISH, A	8306160041	FOIA	LAUFER-COVITZ	8306160398	50-322 Q	LEWIS, F W	8306060225*	50-302 I
KRATZER, M B	8306160134*	FOIA	LAUGHLIN, Q J	8306010039	NUREQ	LEWIS, M I	8306020380	50-352 H
KRAUS, Q	8306080203	50-358 Q	LAUGHLIN, Q J	8306010067	NUREQ	LEWIS, M I	8306220043	50-352 H
KRAUS, Q	8306080205*	50-358 Q	LAUGHLIN, Q J	8306010071	NUREQ	LEWIS, M I	8306300150	PR
KRAUS, T	8306080215	50-358 Q	LAURENSEN, J A	8306150292	50-322 Q	LEWIS, R C	8306090319	50-348 Q
KRAUS, T	8306080250	50-358 Q	LAURENSEN, J A	8306150300	50-322 Q	LEWIS, R C	8306090329	50-348 Q
KRAUS, D F	8306270161	50-316 S	LAWTON, M D	8306200285*	40-8084	LEWIS, R C	8306140045	50-395 Q
KRECHTING, J E	8306100168	50-275 R	LAZARSKI, R F	8306220211*	50-320 P	LEWIS, R C	8306140107	50-259 F
KRECHTING, J E	8306170350	50-275 R	LAZARUS, W J	8306010027	50-410 A	LEWIS, R C	8306140137	50-327 Q
KRICH, R M	8306220029	50-255 B	LATO, L	8306020491	50-412 A	LEWIS, R C	8306140145*	50-327 Q
KRIEGER, R W	8306010142	50-206 F	LATO, L	8306030034	50-412 A	LEWIS, R C	8306140157	50-424 A
KRIEGER, R W	8306220004	50-206 P	LATO, R M	8306160622	50-599 Q	LEWIS, R C	8306140201*	50-324 Q
KRIEGER, R W	8306240203	50-206 P	LATO, R M	8306160627	50-599 Q	LEWIS, R C	8306140251	50-259 Q
KRIEGER, R W	8306280466	50-206 P	LE, H	8306130332*	50-322 E	LEWIS, R C	8306140272	50-389 Q
KRIEGER, R W	8306240308	50-344 F	LEASE, R B	8306020186	50-316 R	LEWIS, R C	8306140276*	50-259 Q
KRIEGER, R W	8306270305	50-322 F	LEDDICK, R S	8306010376	50-508 Q	LEWIS, R C	8306140303	50-416 E
KRONZEK, A L	8306070441	FOIA	LEDDICK, R S	8306170184	50-508 A	LEWIS, R C	8306140382	50-395 Q
KRUIG, H E	8306140191*	50-389 Q	LEDDICK, R S	8306170222*	50-508 Q	LEWIS, R C	8306140399	50-261 Q

PERSONAL AUTHOR INDEX

481

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
LEWIS, R C	8306140415	50-390 Q	LINDER, F	8306270382	50-409 Q	LYNCH, M D	8306010321	50-341 F
LEWIS, R C	8306140422	50-259 Q	LINDER, F	8306300006	50-409 Q	LYNCH, M D	8306080435	50-341 A
LEWIS, R C	8306140425*	50-390 Q	LINDHOLM, U S	8306270003*	50-237 P	LYNDE, H V	8306170334	NUREQ
LEWIS, R C	8306140452	50-395 Q	LINEHAN, J J	8306020328*	40-B681	LYONS, J E	8306200326	50-29 P
LEWIS, R C	8306140461*	50-395 Q	LINEHAN, J J	8306020477	40-B786	LYONS, P J	8306020198	40-299
LEWIS, R C	8306140495*	50-400 Q	LINEHAN, J J	8306210431	40-B084	LYONS, P J	8306020201*	40-299
LEWIS, R C	8306140503*	50-400 Q	LINGLE, J W	8306210091	50-266 P	LYONS, P J	8306070467	40-299
LEWIS, R C	8306140514*	50-389 Q	LINGLE, J W	8306270275	50-266 P	LYONS, W T	8306010270	50-318 B
LEWIS, R C	8306140543	50-259 Q	LINVILLE, J C	8306060237*	50-333 Q	MACBRYDE, M B	8306070109*	0A999
LEWIS, R C	8306140556	50-200 Q	LIPINSKI, D R	83060601171*	50-245 Q	MACBRYDE, M B	8306070110*	0A999
LEWIS, R C	8306140559	50-416 Q	LIPINSKI, D R	8306070241*	50-245 Q	MACDONALD, C E	8306020040	71-9111
LEWIS, R C	8306140561	50-416 Q	LISENO, R T	8306010112	50-333 S	MACDONALD, C E	8306020488	71-5364
LEWIS, R C	8306140567*	50-416 Q	LITTELL, R	8306100006	ADVCH	MACDONALD, C E	8306020493	71-4909
LEWIS, R C	8306140618	50-438 Q	LITTELL, R	8306130501	ADVCH	MACDONALD, C E	8306020528	71-9060
LEWIS, R C	8306140633	50-389 Q	LITTLE, B H	8306170055*	50-341 Q	MACDONALD, C E	8306020626	71-6374
LEWIS, R C	8306140634	50-416 Q	LITTLE, W B	8306030139	50-254 Q	MACDONALD, C E	8306020635	71-9080
LEWIS, R C	8306140637	50-395 Q	LITTLE, W B	8306030142	50-461 Q	MACDONALD, C E	8306020711	71-9182
LEWIS, R C	8306140650	50-309 Q	LITTLE, W B	8306030144*	50-461 Q	MACDONALD, C E	8306030032	71-6142
LEWIS, R C	8306140666	50-416 A	LITTLE, W B	8306030146	50-461 Q	MACDONALD, C E	8306030027*	71-6142
LEWIS, R C	8306140690	50-261 Q	LITTLE, W B	8306030149	50-440 Q	MACDONALD, C E	8306030041	71-9029
LEWIS, R C	8306140711	50-321 Q	LITTLE, W B	8306030180	50-483 Q	MACDONALD, C E	8306030087	71-6003
LEWIS, R C	8306140717*	50-321 Q	LITTLE, W B	8306030198	50-546 Q	MACDONALD, C E	8306030090*	71-6003
LEWIS, R C	8306140721	50-424 A	LITTLE, W B	8306030209	50-374 Q	MACDONALD, C E	8306030492*	71-9165
LEWIS, R C	8306210174	50-259 Q	LITTLE, W B	8306070175	50-254 Q	MACDONALD, C E	8306080334*	71-9017
LEWIS, R C	8306210213*	50-259 Q	LITTLE, W B	8306100101	50-237 Q	MACDONALD, C E	8306080336*	71-9017
LEWIS, R C	8306290195	50-259 Q	LITTLE, W B	8306100263	50-374 Q	MACDONALD, C E	8306080339*	71-9017
LEWIS, R C	8306290198	50-348 Q	LITTLE, W B	8306130299	50-440 Q	MACDONALD, C E	8306080382	71-9070
LEWIS, R C	8306290213	50-348 Q	LITTLE, W B	8306130341	50-454 Q	MACDONALD, C E	8306080408	71-9016
LEWIS, R C	8306290218	50-259 Q	LITTLE, W B	8306130343*	50-454 Q	MACDONALD, C E	8306080411*	71-9016
LEWIS, R C	8306290254	50-321 Q	LITTLE, W B	8306160242*	50-440 Q	MACDONALD, C E	8306090001	71-9111
LEWIS, R C	8306290272	50-259 Q	LITTLE, W B	8306160247*	50-440 Q	MACDONALD, C E	8306090002*	71-9111
LEWIS, R C	8306290277	50-259 Q	LITTLE, W B	8306230253	50-346 Q	MACDONALD, C E	8306090004	71-6601
LEWIS, R C	8306290270*	50-321 Q	LITTLE, W B	8306230267	50-440 Q	MACDONALD, C E	8306090006*	71-6601
LEWIS, R C	8306290288*	50-259 Q	LITTLE, W B	8306230411	50-409 Q	MACDONALD, C E	8306090014	71-8026
LEWIS, R C	8306290298	50-321 Q	LITTLE, W B	8306230431	50-135 Q	MACDONALD, C E	8306090017*	71-8026
LEWIS, R C	8306290312*	50-321 Q	LITTLE, W B	8306270283	50-440 Q	MACDONALD, C E	8306090034	71-9010
LEWIS, R C	8306290341	50-250 Q	LITTLE, W B	8306300022	50-346 Q	MACDONALD, C E	8306090037*	71-9010
LEWIS, R C	8306290383	50-338 Q	LITTLE, W B	8306300053	50-341 Q	MACDONALD, C E	8306090070	71-6244
LEWIS, R C	8306290490*	50-259 Q	LITTLE, W B	8306300061*	50-341 Q	MACDONALD, C E	8306090074*	71-6244
LEWIS, R C	8306290531*	50-261 Q	LITTLE, W B	8306300126	50-440 Q	MACDONALD, C E	8306090078	71-9015
LEWIS, S H	8306270438	50-329 A	LITTLE, W B	8306300212	50-358 Q	MACDONALD, C E	8306090279*	71-9015
LIANO, C	8306130262*	50-443 Q	LITTLE, W B	8306300235	50-237 Q	MACDONALD, C E	8306130177	71-9089
LIANO, C	8306130431*	50-443 Q	LITTLE, W B	8306300238*	50-237 Q	MACDONALD, C E	8306140744	71-6533
LICHTENBERGER	8306070336*	0A999	LITTLE, W B	8306300251	50-346 Q	MACDONALD, C E	8306140750*	71-6533
LICITRA, E A	8306020627	50-528 A	LITTON, R J	8306010266	NUREQ	MACDONALD, C E	8306140787	71-6003
LICITRA, E A	8306080097	50-528 A	LIU, W C	8306140139*	50-438 Q	MACDONALD, C E	8306140790	71-5641
LICITRA, E A	8306200051	50-528 A	LIVERMORE, H H	8306220076*	50-461 Q	MACDONALD, C E	8306150143	71-9151
LICITRA, E A	8306200053	50-528 A	LOCHBAUM, D	8306270090	50-260 B	MACDONALD, C E	8306150239	71-9017
LICITRA, E A	8306240458	50-528 A	LODGE, T J	8306030288	50-440 H	MACDONALD, C E	8306150240*	71-9017
LIDEN, E A	8306020232	50-272 F	LODGE, T J	8306220080	50-440 Q	MACDONALD, C E	8306150326	71-9508
LIDEN, E A	8306070130	50-272 F	LODIUDICE, J M	8306210371*	CONTRACT	MACDONALD, C E	8306170447	71-5641
LIDEN, E A	8306070144	50-272 F	LOHAUS, P H	8306140185	WASTE HOT	MACDONALD, C E	8306170455	71-9110
LIDEN, E A	8306070167	50-272 F	LOKKEN, R	8306140402	NUREQ	MACDONALD, C E	8306170456*	71-9110
LIDEN, E A	8306140036	50-272 V	LOMO, J	8306060137	50-346 B	MACDONALD, C E	8306170458	71-9111
LIDEN, E A	8306140043	50-272 H	LONGENECKER, J	8306060203	50-327 A	MACDONALD, C E	8306170464	71-9056
LIDEN, E A	8306140059	50-272 P	LONGENECKER, J	8306200325	50-537 E	MACDONALD, C E	8306170465	71-6550
LIDEN, E A	8306150267	50-272 R	LONGENECKER, J	8306220048	50-537 A	MACDONALD, C E	8306210445	71-8796
LIDEN, E A	8306150270*	50-272 R	LONGENECKER, J	8306240233	50-537 A	MACDONALD, C E	8306210447	71-6346
LIDEN, E A	8306160438	50-272 P	LOTITO, E M	8306170018	50-317 R	MACDONALD, C E	8306220172	71-498
LIDEN, E A	8306200240	50-272 R	LOVE, R S	8306030147*	50-461 Q	MACDONALD, C E	8306220178*	71-498
LIDEN, E A	8306210176	50-272 Q	LOVE, R S	8306030202*	50-546 Q	MACDONALD, C E	8306220184	71-5828
LIDEN, E A	8306270299	50-272 P	LOVE, R S	8306130345*	50-434 Q	MACDONALD, C E	8306220185	71-9174
LIDEN, E A	8306290313	50-272 P	LOVELL, R M	8306020405*	70-2548	MACDONALD, C E	8306220190*	71-5828
LIDEN, E A	8306300190	50-272 P	LOVENDALE, P C	8306100227*	50-155 Q	MACDONALD, C E	8306220195	71-4909
LIDIAK, E O	8306080168	NUREQ	LUCIA, B	8306090276*	50-528 F	MACDONALD, C E	8306220199	71-9165
LIEBERMAN, J	8306240264	MISC	LUCK, W D	8306200302	50-537 Q	MACDONALD, C E	8306220203	71-210
LIN, C C	8306210153*	TOPREP	LUCK, W D	8306270317	50-537 Q	MACDONALD, C E	8306220231	71-367
LINDBLAD, W J	8306200210*	50-344 I	LUDWIG, W C	8306070039	50-327 B	MACDONALD, C E	8306240455	71-9132
LINDELL, M K	8306140315	NUREQ	LUDWIG, W C	8306070218	50-328 B	MACDONALD, C E	8306240456	71-9141
LINDEMER, T D	8306280093	NUREQ	LUDWIG, W C	8306070284	50-327 B	MACDONALD, C E	8306240459	71-9100
LINDER, F	8306020291	50-409 R	LUDWIG, W C	8306200332	50-327 B	MACDONALD, C E	8306240485	71-9132
LINDER, F	8306070040	50-409 S	LUDWIG, W C	8306210218	50-527 B	MACDONALD, C E	8306240488	71-86
LINDER, F	8306070079	50-409 F	LUEBKE, E A	8306160616	50-142 Q	MACDONALD, C E	8306240489*	71-86
LINDER, F	8306070311	50-409 F	LUJANAC, P L	8306300097*	50-289 Q	MACDONALD, C E	8306290601	71-9080
LINDER, F	8306070332	50-409 F	LUKZ, F J	8306010129*	CONTRACT	MACDONALD, C E	8306290610	71-5607
LINDER, F	8306100184	50-409 P	LUKZ, F J	8306170482*	CONTRACT	MACDONALD, C E	8306170205*	REB
LINDER, F	8306130314*	50-409 Q	LUKZ, F J	8306230505*	CONTRACT	MACDONALD, R D.	8306240036*	FOIA
LINDER, F	8306140707	50-409 P	LUNDVALL, A E	8306060105	50-317 P	MACLEAN, R	8306230491*	CONTRACT
LINDER, F	8306150277	50-409 P	LUNDVALL, A E	8306070136	50-317 Q	MACLEOD, B.	8306020347	50-322 H
LINDER, F	8306160279*	50-409 F	LUNDVALL, A E	8306130001	50-317 Q	MACNABB, W V	8306280258	XPORTLIC
LINDER, F	8306160378	50-409 R	LUNDVALL, A E	8306160330*	50-317 Q	MADDEN, W	8306230001	50-245 B
LINDER, F	8306170376	50-409 B	LUNDVALL, A E	8306210121	50-317 Q	MADDEN, W	8306280582	50-387 B
LINDER, F	8306210066	50-409 F	LUNDA, C K	8306160048*	50-305 F	MADISON, A	8306270222*	50-373 Q
LINDER, F	8306210132	50-409 P	LURIA, N	8306130331*	50-322 E	MADISON, A	8306300141*	50-373 Q
LINDER, F	8306270337	50-409 B	LUTKIN, M H	8306080350	40-299	MADSEN, Q. L.	8306010132	50-267 Q

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MADSEN, Q L	8306010152	50-382 Q	MANN, S F	8306210200	50-410 Q	MARTIN, R E	8306240418	50-352 F
MADSEN, Q L	8306010296	50-128 H	MANN, S F	8306280605	50-410 S	MARTIN, R W	8306150617	NUREQ
MADSEN, Q L	8306010350	50-498 Q	HANSEN, W C	8306150269*	70-143	MARTIN, T	8306060309*	70-25
MADSEN, Q L	8306060056	50-498 Q	MARCHALL, J	8306150340	XPORTLIC	MARTIN, T J	8306280590*	50-354 Q
MADSEN, Q L	8306060069	50-498 Q	MARCHALL, J	8306160620	XPORTLIC	MARTIN, T	8306280610	40-6940
MADSEN, Q L	8306060111	50-498 Q	MARCHALL, J	8306160716	XPORTLIC	MARTIN, T T	8306010096	50-29 Q
MADSEN, Q L	8306060125	50-267 Q	MARCHALL, J	8306160720	XPORTLIC	MARTIN, T T	8306010115	50-247 Q
MADSEN, Q L	8306060128	50-112 Q	MARKEE, E	8306140636*	50-382 Q	MARTIN, T T	8306010148	70-371
MADSEN, Q L	8306060137	50-267 P	MARKEY, E J	8306060392*	50-272 U	MARTIN, T T	8306010160	50-29 Q
MADSEN, Q L	8306070317	50-267 P	MARXT, D	8306090291*	50-29 F	MARTIN, T T	8306010171	50-30/ Q
MADSEN, Q L	8306080042	50-267 Q	MARXT, D	8306150293*	50-271 F	MARTIN, T T	8306010227	50-333 Q
MADSEN, Q L	8306080069	50-382 Q	MARXT, D	8306150297*	50-271 F	MARTIN, T T	8306010301	50-271 Q
MADSEN, Q L	8306080078	50-382 Q	MARSHALL, C	8306160024	FOIA	MARTIN, T T	8306010303	50-213 Q
MADSEN, Q L	8306080120	50-498 Q	MARSHALL, J R	8306010024	50-313 P	MARTIN, T T	8306010326	50-334 Q
MADSEN, Q L	8306080217	50-298 Q	MARSHALL, J R	8306010267	50-313 P	MARTIN, T T	8306010337	50-309 P
MADSEN, Q L	8306080220	50-445 Q	MARSHALL, J R	8306020081	50-313 R	MARTIN, T T	8306010338	70-407
MADSEN, Q L	8306130118	50-382 Q	MARSHALL, J R	8306020135	50-313 P	MARTIN, T T	8306010402	50-220 Q
MADSEN, Q L	8306130255	50-445 Q	MARSHALL, J R	8306020150	50-368 R	MARTIN, T T	8306020025	70-2953
MADSEN, Q L	8306140370	50-445 Q	MARSHALL, J R	8306020466	50-368 P	MARTIN, T T	8306020258	71-250
MADSEN, Q L	8306140631	50-382 Q	MARSHALL, J R	8306030294	50-313 J	MARTIN, T T	8306020375	50-354 Q
MADSEN, Q L	8306160220	50-267 P	MARSHALL, J R	8306060067*	50-313 Q	MARTIN, T T	8306020381	50-244 Q
MADSEN, Q L	8306160351	50-298 Q	MARSHALL, J R	8306060253	50-313 R	MARTIN, T T	8306020387	70-498
MADSEN, Q L	8306170266	50-382 Q	MARSHALL, J R.	8306070034	50-368 P	MARTIN, T T	8306020399	70-2548
MADSEN, Q L	8306170346	50-382 Q	MARSHALL, J R	8306070193	50-313 P	MARTIN, T T	8306020400	50-244 Q
MADSEN, Q L	8306210009	50-298 Q	MARSHALL, J R	8306070298	50-313 Q	MARTIN, T T	8306020402	50-317 Q
MADSEN, Q L	8306210061	50-382 Q	MARSHALL, J R.	8306070384*	50-313 Q	MARTIN, T T	8306020408	70-1224
MADSEN, Q L	8306210105	50-445 Q	MARSHALL, J R.	8306080012	50-313 F	MARTIN, T T	8306020409	50-271 Q
MADSEN, Q L	8306210114	50-298 Q	MARSHALL, J R.	8306090248	50-313 F	MARTIN, T T	8306020427	50-244 Q
MADSEN, Q L	8306220140	50-274 Q	MARSHALL, J R.	8306090313	50-313 P	MARTIN, T T	8306020442	50-307 Q
MADSEN, Q L	8306270236	50-298 Q	MARSHALL, J R	8306130057	50-313 R	MARTIN, T T	8306020445	50-219 Q
MADSEN, Q L	8306300130	50-267 Q	MARSHALL, J R	8306130222	50-313 Q	MARTIN, T T	8306020458	50-244 Q
MAIER, J E	8306020079	50-244 P	MARSHALL, J R	8306130270	50-368 S	MARTIN, T T	8306030238	70-371
MAIER, J E	8306020449	PR	MARSHALL, J R	8306130421	50-368 S	MARTIN, T T	8306030314	70-371
MAIER, J E	8306020451	50-244 R	MARSHALL, J R	8306140030	50-313 Q	MARTIN, T T	8306030343	50-286 Q
MAIER, J E	8306020453	50-244 R	MARSHALL, J R	8306140135	50-313 F	MARTIN, T T	8306060162	50-277 Q
MAIER, J E	8306060036	50-244 Q	MARSHALL, J R	8306160324	50-313 P	MARTIN, T T	8306060167	40-678
MAIER, J E	8306060057	50-244 P	MARSHALL, J R	8306160355	50-368 S	MARTIN, T T	8306060264	50-286 Q
MAIER, J E	8306070258	50-244 F	MARSHALL, J R	8306160469	50-313 S	MARTIN, T T	8306070140	50-317 Q
MAIER, J E	8306140025	50-244 Q	MARSHALL, J R	8306160474	50-368 R	MARTIN, T T	8306090030	71-2
MAIER, J E	8306140410	50-244 Q	MARSHALL, J R	8306160479	50-368 S	MARTIN, T T	8306090128	50-322 Q
MAIER, J E	8306140595	50-244 P	MARSHALL, J R	8306160493	50-313 P	MARTIN, T T	8306140258	50-277 Q
MAIER, J E	8306150309	50-244 Q	MARSHALL, J R	8306160499	50-368 S	MARTIN, T T	8306150156	70-2669
MAIER, J E	8306170032	50-244 P	MARSHALL, J R	8306160537	50-313 Q	MARTIN, T T	8306160313	70-1207
MAIER, J E	8306170201	50-244 S	MARSHALL, J R	8306160561	50-313 R	MARTIN, T T	8306160323	50-317 Q
MAIER, J E	8306200314	50-244 P	MARSHALL, J R	8306160577	50-368 S	MARTIN, T T	8306160341	50-220 Q
MAIER, J E	8306210015	50-244 Q	MARSHALL, J R.	8306160614	50-313 S	MARTIN, T T	8306160440	50-272 Q
MAIER, J E	8306210034	50-244 S	MARSHALL, J R	8306170275	50-313 P	MARTIN, T T	8306170050	50-57 Q
MAIER, J E	8306220022	50-244 Q	MARSHALL, J R	8306170408	50-313 P	MARTIN, T T	8306170204	50-219 F
MAIER, J E	8306240177	50-244 P	MARSHALL, J R	8306210003	50-313 S	MARTIN, T T	8306170241	70-371
MAIER, J E	8306240298	50-244 P	MARSHALL, J R	8306210125	50-313 R	MARTIN, T T	8306200082	50-423 Q
MAIER, J E	8306240311	50-244 P	MARSHALL, J R	8306210181	50-368 S	MARTIN, T T	8306200125	50-277 Q
MAIER, J E	8306270257	50-244 P	MARSHALL, J R	8306210229	50-368 P	MARTIN, T T	8306200139	50-307 Q
MAIER, J E	8306270360	50-244 P	MARSHALL, J R	8306220062	50-313 V	MARTIN, T T	8306200159	50-277 Q
MATYA, P B	8306280096	NUREQ	MARSHALL, J R	8306230474	50-313 F	MARTIN, T T	8306200307	50-245 Q
MALARDIE, P J	8306230076*	FOIA	MARSHALL, J R	8306230487	50-368 P	MARTIN, T T	8306200387	50-213 Q
MALETESKOB, C J	8306280190	NUREQ	MARSHALL, J R	8306300079*	50-313 Q	MARTIN, T T	8306210098	50-213 Q
MALLAY, J F	8306160481	REQD	MARSHALL, J S	8306090162	50-445 A	MARTIN, T T	8306210104	50-322 Q
MALLORY, C W	8306020533	71-9080	MARSHALL, J S	8306100193	50-445 A	MARTIN, T T	8306230215	50-336 Q
MALLORY, C W	8306130188*	71-9089	MARSHALL, J S	8306130193	50-445 A	MARTIN, T T	8306230383	50-317 Q
MALLORY, M H	8306070017*	50-344 Q	MARSHALL, J S	8306160503	50-445 Q	MARTIN, T T	8306230389	50-273 Q
MALODY, C W	8306130500*	70-1257	MARSHALL, R K	8306240073	NUREQ	MARTIN, T T	8306230456	50-333 Q
MALODY, C W	8306240396	70-1257	MARSHALL, H H	8306080206	50-329 Q	MARTIN, T T	8306230497*	50-333 Q
MANCINI, E A	8306280159*	CONTRACT	MARSTON, R R	8306140542*	50-327 Q	MARTIN, T T	8306230471	50-272 Q
MANDIL, I H	8306020482*	CONTRACT	MARSTON, R R	8306140655*	50-348 Q	MARTIN, T T	8306230473	71-2
MANDLER, J W	8306080161	50-335 P	MARTIN, C	8306080320	FOIA	MARTIN, T T	8306270238	40-8610
MANGAN, C V	8306010063	50-220 P	MARTIN, D E	8306020252	WASTE HOT	MARTIN, T T	8306280204	50-213 Q
MANGAN, C V	8306010360	50-220 F	MARTIN, D E	8306030430	WASTE HOT	MARTIN, T T	8306280337	50-293 Q
MANGAN, C V	8306070034	50-220 P	MARTIN, D E	8306030470	WASTE HOT	MARTIN, T T	8306280429	70-1402
MANGAN, C V	8306080273	50-410 A	MARTIN, D E	8306140333	WASTE HOT	MARTIN, T T	8306280461	50-317 Q
MANGAN, C V	8306100143	50-220 P	MARTIN, D E	8306140336	WASTE HOT	MARTIN, T T	8306280472	50-271 Q
MANGAN, C V	8306140440	50-410 A	MARTIN, D E	8306140351	WASTE HOT	MARTON, E J	8306230077*	FOIA
MANGAN, C V	8306140445*	50-410 Q	MARTIN, D E	8306140364	WASTE HOT	MARTON, J	8306230078*	FOIA
MANGAN, C V	8306200214	50-220 R	MARTIN, D E	8306150233	WASTE HOT	MARTZ, H F	8306280013	NUREQ
MANGAN, C V	8306200258	50-410 K	MARTIN, D E	8306170446	WASTE HOT	MASON, C C	8306020197	50-327 R
MANGAN, C V	8306220096	50-410 K	MARTIN, D E	8306210423	WASTE HOT	MASON, J M	8306130453	50-358 Q
MANGAN, C V	8306220422	50-220 Q	MARTIN, D E	8306280098	WASTE HOT	MASBARD, B A	8306290131	NUREQ
MANGAN, C V	8306280509	50-220 F	MARTIN, J B	8306020366	State Prog	MASBEY, F K.	8306220127	50-361 Q
MANGAN, C V	8306300241	50-220 F	MARTIN, J B	8306100095	50-263 Q	MATBERSON, V V	8306130352	50-373 Q
MANN, J	8306010107*	50-313 Q	MARTIN, J B	8306200378	50-361 Q	MATKAS, R A	8306080267*	50-443 Q
MANNING, W J	8306240328	COMMIBBIDN	MARTIN, R A	8306070422	REB	MATTHEY, D L	8306080330*	50-410 A
MANN, B F	8306010453	50-410 S	MARTIN, R E	8306020649	50-352 A	MATERS, B R.	8306140614	50-341 A
MANN, B F	8306140558*	50-410 Q	MARTIN, R E	8306030066	50-352 A	MATHEWS, J	8306150307	50-445 Q
MANN, B F	8306140564*	50-410 Q	MARTIN, R E	8306090194	50-352 A	MATHIS, J.	8306290511*	50-370 Q
MANN, B F	8306200242	50-410 S	MARTIN, R E	8306210418	50-352 A	MATHIS, J L	8306140362*	50-390 Q
MANN, B F	8306210195	50-410 S	MARTIN, R E	8306240412	50-352 A	MATLOCK, R Q	8306170215	50-397 R

PERSONAL AUTHOR INDEX

483

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MATTHEWS, D D	8306080216*	50-361 G	MCFADDEN, J H	8306240263*	TOPREP	MCNURRAY, C M	8306150401*	50-322 Q
MATTHEWS, M I	8306150229	WASTE MGT	MCFARLAND, C R	8306140512*	50-400 Q	MCNURRAY, C M	8306290333	50-322 Q
MATTHEWS, M L	8306200012	WASTE MGT	MCARRY, J M	8306060301	50-413 Q	MCNAMARA, A E	8306020274	50-244 R
MATTHEWS, M L	8306240179	WASTE MGT	MCARRY, J M	8306060301	50-413 Q	MCNAMARA, A E	8306160465	50-244 R
MATTHEWS, T P	8306200358	50-285 R	MCARRY, J M	8306080170	50-413 Q	MCNAUGHTON, W P	8306080048*	50-440 A
MATTIA, M J	8306190510*	CONTRACT	MCARRY, J M	8306080170	50-413 Q	MCNEILL, C A	8306010112	50-333 B
MATTIA, M J	8306170029*	CONTRACT	MCARRY, J M	8306100199*	50-413 Q	MCNEILL, C A	8306010312	50-333 B
MATTIA, M J	8306220091*	CONTRACT	MCARRY, J M	8306100199*	50-413 Q	MCNEILL, C A	8306100017	50-333 R
MATTIA, M J	8306270446*	CONTRACT	MCARRY, J M	8306170334	50-413 Q	MCNEILL, C A	8306140153*	50-333 Q
MATTIA, M J	8306280122*	CONTRACT	MCARRY, J M	8306010244	50-416 S	MCNEILL, C A	8306140159*	50-333 Q
MAURA, F A	8306060130*	50-358 Q	MCARRY, J M	8306010244	50-416 S	MCNEILL, C A	8306200139	50-333 B
MAURA, F A	8306300067*	50-341 Q	MCARRY, J M	8306010244	50-416 S	MCNEILL, C A	8306200344*	50-333 Q
MAURIN, L V	8306010223	50-382 Q	MCARRY, J M	8306010244	50-416 S	MCNEILL, C A	8306200375	50-333 B
MAURIN, L V	8306010297	50-382 R	MCARRY, J M	8306010244	50-416 S	MCNEILL, C A	8306210156	50-333 Q
MAURIN, L V	8306090411*	50-382 F	MCARRY, J M	8306010244	50-416 S	MCNEILL, C A	8306280486	50-333 B
MAURIN, L V	8306170349*	50-382 Q	MCARRY, J M	8306010244	50-416 S	MCNERNEY, M J	8306100152*	50-483 A
MAURIN, L V	8306280342	50-382 R	MCARRY, J M	8306010244	50-416 S	MEDFORD, M O	8306140178	50-361 P
MAXWELL, D	8306130439	50-237 S	MCARRY, J M	8306010244	50-416 S	MEDFORD, M O	8306160275	50-361 K
MAXWELL, D C	8306170409	50-249 S	MCARRY, J M	8306010244	50-416 S	MEHOLICK, J J	8306070026*	FOIA
MAY, E L	8306170033	50-29 S	MCARRY, J M	8306010244	50-416 S	MEHOLICK, J J	8306070027*	FOIA
MAY, E L	8306280107	50-29 S	MCARRY, J M	8306010244	50-416 S	MEILYON, S L	8306280387	50-320 Q
MAYBERRY, G B	8306240441*	71-9006	MCARRY, J M	8306010244	50-416 S	MEITZLER, W D	8306140313	NUREQ
MAYS, G T	8306160631*	50-195 P	MCARRY, J M	8306010244	50-416 S	MENDELSON, I N	8306170466*	CONTRACT
MAYS, G T	8306210324	NUREQ	MCARRY, J M	8306010244	50-416 S	MENDEZ, R	8306230235*	50-346 Q
MAYWEATHER, L	8306160489	50-361 R	MCARRY, J M	8306010244	50-416 S	MENDEZ, R	8306200292*	50-346 Q
MCALLISTER, S A	8306170430	50-309 S	MCARRY, J M	8306010244	50-416 S	MENDONCA, M M	8306270350*	50-275 Q
MCALPINE, E J	8306140529*	70-1201	MCARRY, J M	8306010244	50-416 S	MENDONCA, M M	8306280194*	50-275 Q
MCALPINE, E J	8306140575*	70-1113	MCARRY, J M	8306010244	50-416 S	MENINICK, J	8306020225	27-48
MCALPINE, E J	8306140582*	70-1113	MCARRY, J M	8306010244	50-416 S	MERCIER, A	8306080215	50-358 Q
MCALPINE, E J	8306140617*	70-824	MCARRY, J M	8306010244	50-416 S	MERCIER, A	8306080250	50-358 Q
MCALPINE, E J	8306140713*	70-143	MCARRY, J M	8306010244	50-416 S	MERKLE, J O	8306210362	NUREQ
MCALPINE, E J	8306270240	70-143	MCARRY, J M	8306010244	50-416 S	MERRITT, B	8306130346	50-249 B
MCBREARTY, R A	8306060227*	50-220 Q	MCARRY, J M	8306010244	50-416 S	MERRITT, B	8306270111	50-249 B
MCBREARTY, R A	8306070226*	50-277 Q	MCARRY, J M	8306010244	50-416 S	MERRIWEATHER, N	8306030131*	50-440 Q
MCBREARTY, R A	8306160006*	50-271 Q	MCARRY, J M	8306010244	50-416 S	MERRIWEATHER, N	8306160254*	50-440 Q
MCBRIDE, M	8306060267*	50-286 Q	MCARRY, J M	8306010244	50-416 S	MERRIWEATHER, N	8306300132*	50-440 Q
MCBRIDE, M H	8306020447*	50-219 Q	MCARRY, J M	8306010244	50-416 S	MEYER, O	8306070146*	50-317 Q
MCBRIDE, M H	8306230469*	50-333 Q	MCARRY, J M	8306010244	50-416 S	MEYER, J F	8306240295*	50-247 Q
MCBRIDE, M H	8306280474*	50-271 Q	MCARRY, J M	8306010244	50-416 S	MEYER, T A	8306170201	50-244 B
MCCABE, E C	8306010134*	50-387 Q	MCARRY, J M	8306010244	50-416 S	MICHAELS, S	8306060309*	70-25
MCCABE, E C	8306010324*	50-317 Q	MCARRY, J M	8306010244	50-416 S	MIGHT, A	8306020111*	50-315 R
MCCABE, E C	8306020071	50-322 Q	MCARRY, J M	8306010244	50-416 S	MIGHT, A	8306020118*	50-315 R
MCCABE, E C	8306030312*	50-277 Q	MCARRY, J M	8306010244	50-416 S	MIGHT, A	8306020186	50-316 R
MCCABE, E C	8306070076*	50-322 Q	MCARRY, J M	8306010244	50-416 S	MIGHT, A	8306160338*	50-315 R
MCCANN, J	8306010134*	50-387 Q	MCARRY, J M	8306010244	50-416 S	MILES, E D	8306040657	CONTRACT
MCCLESKEY, K E	8306070295	50-322 Q	MCARRY, J M	8306010244	50-416 S	MILLER, D	8306060309*	70-25
MCCLESKEY, K E	8306070295	50-322 Q	MCARRY, J M	8306010244	50-416 S	MILLER, D B	8306130368	50-329 A
MCCINTOCK, R O	8306060019*	FOIA	MCARRY, J M	8306010244	50-416 S	MILLER, D E	8306100258*	50-373 Q
MCCINTOCK, R O	8306160179*	FOIA	MCARRY, J M	8306010244	50-416 S	MILLER, D S	8306010391	50-309 Q
MCCINTOCK, R O	8306080195	50-361 Q	MCARRY, J M	8306010244	50-416 S	MILLER, D S	8306020358	50-309 Q
MCCLEUNG, C E	8306080195	50-361 Q	MCARRY, J M	8306010244	50-416 S	MILLER, D W	8306270253*	50-387 R
MCCOLLOM, K A	8306280556	50-445 Q	MCARRY, J M	8306010244	50-416 S	MILLER, F O	8306290550	50-247 Q
MCCORMICK, G W	8306100039*	50-312 Q	MCARRY, J M	8306010244	50-416 S	MILLER, G E	8306210186	50-326 S
MCCRORY, B L	8306130261*	50-445 Q	MCARRY, J M	8306010244	50-416 S	MILLER, H J	8306140195	WASTE MGT
MCDERMOTT, D	8306020459	CONTRACT	MCARRY, J M	8306010244	50-416 S	MILLER, H J	8306200415	WASTE MGT
MCDERMOTT, D	8306030277	CONTRACT	MCARRY, J M	8306010244	50-416 S	MILLER, H J	8306240028*	FOIA
MCDERMOTT, D	8306060391	CONTRACT	MCARRY, J M	8306010244	50-416 S	MILLER, H J	8306280290	WASTE MGT
MCDERMOTT, D	8306140228	CONTRACT	MCARRY, J M	8306010244	50-416 S	MILLER, J	8306130265	1&E
MCDERMOTT, D	8306150246	CONTRACT	MCARRY, J M	8306010244	50-416 S	MILLER, J	8306160169	50-373 B
MCDERMOTT, D	8306150485	CONTRACT	MCARRY, J M	8306010244	50-416 S	MILLER, J	8306230438	50-295 B
MCDERMOTT, D	8306210421	CONTRACT	MCARRY, J M	8306010244	50-416 S	MILLER, J H	8306070130*	50-321 I
MCDERMOTT, D	8306220166	CONTRACT	MCARRY, J M	8306010244	50-416 S	MILLER, J R	8306060270	50-156 Q
MCDERMOTT, D K	8306150506	CONTRACT	MCARRY, J M	8306010244	50-416 S	MILLER, J R	8306100088	50-155 Q
MCDONALD, D D	8306160098	FOIA	MCARRY, J M	8306010244	50-416 S	MILLER, J R	8306100371	50-315 Q
MCDONALD, D D	8306160174	FOIA	MCARRY, J M	8306010244	50-416 S	MILLER, J R	8306210072	50-263 Q
MCDONALD, J Y	8306030402*	CONTRACT	MCARRY, J M	8306010244	50-416 S	MILLER, L	8306070244*	50-206 Q
MCDONELL-BOYER	8306080041*	FOIA	MCARRY, J M	8306010244	50-416 S	MILLER, L	8306280480*	50-206 Q
MCDUFFIE, M A	8306060152	50-400 C	MCARRY, J M	8306010244	50-416 S	MILLER, L F	8306280311*	50-361 Q
MCDUFFIE, M A	8306060202	50-400 E	MCARRY, J M	8306010244	50-416 S	MILLER, L K	8306200132	50-311 R
MCDUFFIE, M A	8306070122	50-400 E	MCARRY, J M	8306010244	50-416 S	MILLER, L K	8306200226	50-272 R
MCDUFFIE, M A	8306080032	50-400 E	MCARRY, J M	8306010244	50-416 S	MILLER, L K	8306280542	50-272 R
MCDUFFIE, M A	8306100189	50-400 E	MCARRY, J M	8306010244	50-416 S	MILLER, M	8306240366	50-390 A
MCDUFFIE, M A	8306160116	50-400 E	MCARRY, J M	8306010244	50-416 S	MILLER, M A	8306160060	50-390 A
MCDUFFIE, M A	8306170224	50-400 E	MCARRY, J M	8306010244	50-416 S	MILLER, M I	8306060196*	50-454 Q
MCDUFFIE, M A	8306200083	50-400 E	MCARRY, J M	8306010244	50-416 S	MILLER, M I	8306060196*	50-454 Q
MCDUFFIE, M A	8306200309	50-400 E	MCARRY, J M	8306010244	50-416 S	MILLER, M I	8306270041	50-454 Q
MCDUFFIE, M A	8306210002	50-400 A	MCARRY, J M	8306010244	50-416 S	MILLER, M I	8306270393	50-454 Q
MCDUFFIE, M A	8306210204	50-400 A	MCARRY, J M	8306010244	50-416 S	MILLER, M I	8306270393	50-454 Q
MCDUFFIE, M A	8306270100	50-400 E	MCARRY, J M	8306010244	50-416 S	MILLER, M I	8306070381	50-322 Q
MCDUFFIE, M A	8306270113	50-400 A	MCARRY, J M	8306010244	50-416 S	MILLER, M B	8306070381	50-322 Q
MCDUFFIE, M A	8306270217	50-400 E	MCARRY, J M	8306010244	50-416 S	MILLER, M B	8306070381	50-322 Q
MCDUFFIE, M A	8306270241	50-400 E	MCARRY, J M	8306010244	50-416 S	MILLER, M B	8306070381	50-322 Q
MCDUFFIE, M A	8306270292	50-400 E	MCARRY, J M	8306010244	50-416 S	MILLER, M B	8306070381	50-322 Q
MCDUFFIE, M A	8306270448	50-400 E	MCARRY, J M	8306010244	50-416 S	MILLER, M B	8306070381	50-322 Q
MCDUFFIE, P N	8306240073	NUREQ	MCARRY, J M	8306010244	50-416 S	MILLER, M B	8306070381	50-322 Q

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MILLER, W O	8306020696*	TOPREP	MILLS, L M	8306280415	50-259 P	MOORE, R N	8306240061	XPORLTC
MILLER, W O	8306090498	50-361 P	MILLS, L M	8306280425	50-438 S	MOORE, T L	8306060059*	50-244 P
MILLER, W O	8306090502	50-361 P	MILLS, L M	8306280426	50-390 S	MORAN, D H	8306140305	GEN TEC 15
MILLER, W O	8306140279	50-267 P	MILLS, L M	8306280479	50-438 S	MORAN, D H	8306140792	GEN TEC 15
MILLER, W O	8306150516	50-338 P	MILLS, L M	8306280567	50-259 P	MORAN, D H	8306140797	GEN TEC 15
MILLER, W O	8306200279	50-333 F	MILLS, L M	8306280573	50-390 S	MORAN, D H	8306140814	GEN TEC 15
MILLIGAN, H H	8306060352*	50-322 A	MILLS, L M	8306280570	50-390 S	MORAN, D H	8306150019	GEN TEC 15
MILLS, L	8306230011	50-390 E	MILLS, L M	8306280612	50-390 R	MORAN, D H	8306150022	GEN TEC 15
MILLS, L M	8306010113	50-390 S	MILLS, L M	8306280619	50-438 S	MORAN, D H	8306150112	GEN TEC 15
MILLS, L M	8306010136	50-390 S	MILLS, L M	8306270246*	50-438 Q	MORAN, D H	8306160031	GEN TEC 15
MILLS, L M	8306010143	50-390 S	MILLS, L M	8306290250	50-259 Q	MORAN, D H	8306170433	GEN TEC 15
MILLS, L M	8306010251	50-438 S	MILLS, L M	8306290275*	50-259 Q	MORAN, D H	8306270032	50-454 Q
MILLS, L M	8306010269	50-259 S	MILLS, L M	8306290283*	50-259 Q	MORAN, D M	8306290500	50-454 Q
MILLS, L M	8306010274	50-390 S	MILLS, L M	8306290316*	50-390 Q	MORGAN, R L	8306270032	50-454 Q
MILLS, L M	8306010283	50-390 S	MILLS, L M	8306290319*	50-438 Q		8306300223	PR
MILLS, L M	8306010405	50-438 S	MILLS, L M	8306290388	50-327 Q	MORGENSTERN, M	8306030009	NURFO
MILLS, L M	8306010421	50-390 S	MILLS, L M	8306290400	50-259 P	MORIARTY, J M	8306300110	PR
MILLS, L M	8306030504	70-2910	MILLS, L M	8306290510*	50-259 Q	MORLEY, J A	8306080148	WASTE MGT
MILLS, L M	8306060102	50-259 X	MILLS, L M	8306300008	50-438 S	MORLEY, J A	8306090335	WASTE MGT
MILLS, L M	8306070049	50-390 S	MILLS, L M	8306300013	50-390 S	MORLEY, J A	8306140675	WASTE MGT
MILLS, L M	8306070064	50-390 S	MILLS, L M	8306300033	50-390 S	MORLEY, J A	8306220211	WASTE MGT
MILLS, L M	8306070072	50-390 S	MILLS, L M	8306300038	50-390 S	MORLEY, J A	8306100152*	50-454 Q
MILLS, L M	8306070074	50-390 S	MILLS, L M	8306300051	50-390 S	MORRILL, P J	8306070098*	50-275 Q
MILLS, L M	8306070121	50-438 S	MILLS, L M	8306300054	50-390 S	MORRISON, O B	8306150166*	70-2669
MILLS, L M	8306070132	50-327 F	MILLS, L M	8306300082	50-390 S	MORRISON, O B	8306150169*	70-2669
MILLS, L M	8306070138	50-390 S	MILLS, L M	8306300177	50-259 P	MORRISON, P	8306150436*	50-454 Q
MILLS, L M	8306070160	50-438 S	MILLS, L M	8306300205	50-390 S	MORRISON, P	8306150448*	50-454 Q
MILLS, L M	8306070188	50-438 S	MILLS, L M	8306300214	50-390 S	MORTON, K L	8306020081	50-313 R
MILLS, L M	8306080006	50-390 A	MILLS, L M	8306300228	50-390 S	MORTON, K V	8306010129*	CONTRACT
MILLS, L M	8306080071	50-390 A	MILLS, L M	8306300245	50-438 S	MORTON, K V	8306020463*	CONTRACT
MILLS, L M	8306080208	50-327 P	MILLS, L M	8306300254	50-438 S	MORTON, K V	8306020482*	CONTRACT
MILLS, L M	8306080212	50-327 P	MINECK, D L	8306060209	50-331 S	MORTON, K V	8306030264*	CONTRACT
MILLS, L M	8306090135	50-390 S	MINECK, D L	8306100103	50-331 S	MORTON, K V	8306060395*	CONTRACT
MILLS, L M	8306090142	50-390 S	MINECK, D L	8306170337	50-331 S	MORTON, K V	8306060399*	CONTRACT
MILLS, L M	8306090310	50-438 S	MINECK, D L	8306200223	50-331 R	MORTON, K V	8306140238*	CONTRACT
MILLS, L M	8306090322	50-390 S	MINECK, D L	8306270089	50-331 Q	MORTON, K V	8306150291*	CONTRACT
MILLS, L M	8306090331	50-259 Q	MINECK, D L	8306270290	50-331 S	MORTON, K V	8306150488*	CONTRACT
MILLS, L M	8306100123	50-438 S	MINECK, D L	8306220206	50-312 P	MORTON, K V	8306150521*	CONTRACT
MILLS, L M	8306100239	50-390 Q	MINECK, J R	8306270218	50-341 Q	MORTON, K V	8306160561	50-313 R
MILLS, L M	8306130340	50-438 A	MINECK, J R	8306270218	50-341 Q	MORTON, K V	8306210397*	CONTRACT
MILLS, L M	8306130362	50-390 A	MIRALLO, F J	8306210157	50-244 P	MORTON, K V	8306210432*	CONTRACT
MILLS, L M	8306140125*	50-438 Q	MIRALLO, F J	8306210354	NURFO	MORTON, K V	8306230220*	CONTRACT
MILLS, L M	8306140142*	50-327 Q	MIRALLO, F J	8306280296	50-410 A	MORTON, K V	8306230505*	CONTRACT
MILLS, L M	8306140150*	50-438 Q	MIRALLO, F J	8306170314	50-254 R	MOBLAK, T A	8306060266*	50-320 Q
MILLS, L M	8306140427	50-390 S	MIRALLO, F J	8306200423	40-8594	MOTES, B Q	8306270157	NURFO
MILLS, L M	8306140435	50-390 S	MITCHELL, D H	8306290409	50-354 X	MOHRY, W	8306100005	70-724
MILLS, L M	8306140466	50-390 S	MITCHELL, D H	8306200011	NURFO	MOHRY, W R	8306020670	XPORLTC
MILLS, L M	8306140556	50-259 P	MITCHELL, D H	8306080222*	50-445 Q	MOHRY, W R	8306210408	71-6246
MILLS, L M	8306150245	50-259 P	MITCHELL, D H	8306100118	50-445 Q	MOHRY, W R	8306210415*	71-6246
MILLS, L M	8306160453	50-260 P	MITCHELL, D H	8306150403*	50-445 Q	MROCKA, E J	8306010434	50-245 S
MILLS, L M	8306160507	50-259 P	MITCHELL, D H	8306060307*	70-25	MROCKA, E J	8306010434	50-245 S
MILLS, L M	8306160533	50-390 A	MITCHELL, D H	8306060307*	70-25	MROCKA, E J	8306020077	50-336 R
MILLS, L M	8306170324	NURFO	MITCHELL, D H	8306060307*	70-25	MROCKA, E J	8306020077	50-336 R
MILLS, L M	8306170335	50-390 A	MITCHELL, D H	8306130270	50-368 S	MROCKA, E J	8306020084	50-245 R
MILLS, L M	8306200141	50-438 S	MITCHELL, D H	8306160355	50-368 S	MROCKA, E J	8306020084	50-245 R
MILLS, L M	8306200143	50-438 S	MITCHELL, D H	8306160469	50-313 S	MROCKA, E J	8306020084	50-245 R
MILLS, L M	8306200143	50-390 S	MITCHELL, D H	8306160479	50-368 S	MROCKA, E J	8306020397	50-245 S
MILLS, L M	8306200155	40-1341	MITCHELL, D H	8306160499	50-368 S	MROCKA, E J	8306020397	50-245 S
MILLS, L M	8306200169	50-390 S	MITCHELL, D H	8306160577	50-368 S	MROCKA, E J	8306030319	50-245 S
MILLS, L M	8306210004	50-438 S	MITCHELL, D H	8306160614	50-313 S	MROCKA, E J	8306030319	50-245 S
MILLS, L M	8306210005	50-438 S	MITCHELL, D H	8306010039	NURFO	MROCKA, E J	8306030326	50-245 S
MILLS, L M	8306210014	50-259 P	MITCHELL, D H	8306010067	NURFO	MROCKA, E J	8306030326	50-245 S
MILLS, L M	8306210014	50-259 P	MITCHELL, D H	8306010071	NURFO	MROCKA, E J	8306160380	50-245 R
MILLS, L M	8306210018	50-438 S	MITCHELL, D H	8306240073	NURFO	MROCKA, E J	8306160380	50-245 R
MILLS, L M	8306210027	50-327 P	MITCHELL, D H	8306130446	50-322 Q	MROCKA, E J	8306170042	50-336 S
MILLS, L M	8306210039	50-390 S	MITCHELL, D H	8306130446	50-322 Q	MROCKA, E J	8306170042	50-336 S
MILLS, L M	8306210042	50-438 S	MITCHELL, D H	8306230006	FOIA	MROCKA, E J	8306170046	50-245 S
MILLS, L M	8306210051	50-390 S	MITCHELL, D H	8306170415	50-247 S	MROCKA, E J	8306170046	50-245 S
MILLS, L M	8306210087	50-390 S	MITCHELL, D H	8306060192*	50-329 A	MROCKA, E J	8306170300	50-245 S
MILLS, L M	8306210088	50-390 S	MITCHELL, D H	8306090321	50-329 A	MROCKA, E J	8306170300	50-245 S
MILLS, L M	8306210113	50-327 P	MITCHELL, D H	8306160235	50-329 A	MROCKA, E J	8306270129	50-245 S
MILLS, L M	8306210116	50-390 S	MITCHELL, D H	83062300250	50-329 A	MROCKA, E J	8306270129	50-245 S
MILLS, L M	8306210130	50-390 S	MITCHELL, D H	8306270242	50-329 A	MROCKA, E J	8306280231	50-336 S
MILLS, L M	8306210180	50-327 P	MITCHELL, D H	8306270349*	50-329 A	MROCKA, E J	8306280231	50-336 S
MILLS, L M	8306210203*	50-259 Q	MITCHELL, D H	8306300065	50-247 S	MROCKA, E J	8306280353	50-336 S
MILLS, L M	8306210252	50-438 S	MITCHELL, D H	8306170323	50-247 S	MROCKA, E J	8306280353	50-336 S
MILLS, L M	8306230178	50-390 F	MITCHELL, D H	8306170397	50-247 S	MROCKA, E J	8306280430	50-336 S
MILLS, L M	8306230272	50-328 P	MITCHELL, D H	8306090324*	50-348 Q	MROCKA, E J	8306280430	50-336 S
MILLS, L M	8306230444	50-328 P	MITCHELL, D H	8306210224*	50-259 Q	MULLAHEY, R P	8306200375	50-323 S
MILLS, L M	8306270007	50-259 F	MITCHELL, D H	8306010357*	50-375 Q	MULLIKIN, R P	8306140374*	50-445 Q
MILLS, L M	8306270354	50-390 S	MITCHELL, D H	8306240290	50-247 Q	MUNRO, J F	8306140423*	50-324 Q
MILLS, L M	8306270386	50-390 S	MITCHELL, D H	8306170372	50-247 Q	MUNRO, J F	8306140583*	50-416 Q
MILLS, L M	8306280092	50-438 S	MITCHELL, D H	8306210415*	71-6346	MUNRO, J J	8306030489	71-7165
MILLS, L M	8306280178	50-327 P	MITCHELL, D H	8306020688	XPORLTC	MUNRO, J J	8306240440	71-6613
MILLS, L M	8306280222	50-439 S	MITCHELL, D H	8306030117	XPORLTC	MUNRO, L H	8306240058	NURFO
MILLS, L M	8306280369	50-438 S	MITCHELL, D H	8306140281	XPORLTC	MURLEY, T E	8306280490	50-324 Q

PERSONAL AUTHOR INDEX

485

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MURPHY, C E	8306210284*	50-315 S	NARDOCCI, P B	8306090147	50-369 S	NIX, H C	8306200004	50-366 S
MURPHY, J	8306090325	50-247 F	NARDOCCI, P B	8306100138	50-370 S	NIX, H C	8306200202	50-321 S
MURPHY, J A	8203090638*	FOIA	NARDOCCI, P B	8306100164	50-370 S	NIX, H C	8306200205	50-366 S
MURPHY, L O	8306030400	CONTRACT	NARDOCCI, P B	8306100185	50-370 S	NIX, H C	8306200261	50-321 S
MURPHY, L O	8306160040	CONTRACT	NARDOCCI, P B	8306100216	50-370 S	NIX, H C	8306200374	50-321 S
MURPHY, L O	8306200286*	FOIA	NARDOCCI, P B	8306100243	50-370 S	NIX, H C	8306220310*	50-321 F
MURPHY, M E	8306140197*	50-407 Q	NARDOCCI, P B	8306130316	50-370 S	NIX, H C	8306220313*	50-321 F
MURPHY, M E	8306140236*	50-72 Q	NARDOCCI, P B	8306130342	50-369 S	NIX, H C	8306270328	50-366 S
MURPHY, W P	8306080076	50-271 Q	NARDOCCI, P B	8306130448	50-369 S	NIX, H C	8306280331	50-321 S
MURPHY, W P	8306140489	50-271 Q	NARDOCCI, P B	8306200212	50-369 S	NIX, H C	8306280468	50-366 S
MURPHY, W P	8306170068	50-271 R	NARDOCCI, P B	8306200237	50-369 S	NIXON, W A	8306060367*	40-2061
MURPHY, W P	8306200388	50-271 Q	NARDOCCI, P B	8306200238	50-370 S	NOBLES, L M	8306150098*	50-327 F
MURPHY, W P	8306210118	50-271 Q	NARDOCCI, P B	8306200245	50-369 S	NORDERHAU, L	8306280076	50-206 Q
MURPHY, W P	8306210223	50-271 Q	NARDOCCI, P B	8306200264	50-369 S	NORDERHAU, L R	8306100146	50-344 Q
MURPHY, W P	8306280112	50-271 F	NARDOCCI, P B	8306270227	50-369 S	NORDERHAU, L R	8306170148	50-344 F
MURPHY, W P	8306280173*	50-271 Q	NARDOCCI, P B	8306270301	50-369 S	NORDERHAU, L R	8306170196	50-275 F
MURRAY, B	8306080046*	50-267 Q	NARDOCCI, P B	8306280427	50-369 S	NORDERHAU, L R	8306170305	50-275 F
MURRAY, B	8306080074*	50-307 Q	NARDOCCI, P B	8306300114	50-370 S	NORDERHAU, L R	8306170375	50-312 F
MURRAY, B	8306080079*	50-302 Q	NARDOCCI, P B	8306300189	50-370 S	NORDERHAU, L R	8306200377	70-734
MURRAY, B	8306080133*	50-498 Q	NARDOCCI, P B	8306300198*	50-369 S	NORDERHAU, L R	8306200383*	70-734
MURRAY, B	8306080211*	50-285 Q	NARDOCCI, P B	8306300204*	50-369 S	NORDERHAU, L R	8306200406	70-1257
MURRAY, B	8306080231*	50-445 Q	NARDOCCI, P B	8306300232	50-370 S	NORDERHAU, L R	8306200410*	70-1257
MURRAY, B	8306080238*	50-313 Q	NARDON, L	8306210107*	50-322 Q	NORDERHAU, L R	8306230455	50-266 F
MURRAY, B	8306090354*	50-285 Q	NEAL, T P	8306240401	71-9033	NORDERHAU, L R	8306280131	50-344 Q
MURRAY, B	8306270237*	50-298 Q	NEIGHBOR, D	8306200211	50-286 P	NORDERHAU, L R	8306280175	50-312 Q
MURRAY, J D	8306100124	50-346 S	NEILL, J M	8306010369	50-352 Q	NORELIUS, C C.	8306070082	50-341 Q
MURRAY, T	8306220260*	50-346 F	NEILS, O H	8306060084	50-263 Q	NORELIUS, C E	8306070134	50-331 Q
MURRAY, T	8306220263*	50-346 F	NEISLER, J H	8306060241*	50-483 Q	NORELIUS, C E	8306070324	50-266 Q
MURRAY, T D	8306020129	50-346 R	NEISLER, J H	8306300186*	50-483 Q	NORELIUS, C E	8306100145	50-409 Q
MURRAY, T D	8306060137	50-346 S	NEKI, M	8306150463	XPORTLIC	NORELIUS, C E	8306130254	50-249 P
MURRAY, T D	8306090283*	50-346 F	NEKI, M	8306160684	XPORTLIC	NORELIUS, C E	8306130338	50-237 Q
MURRAY, T D	8306090375*	50-346 F	NELSON, O B	8306200393*	70-734	NORELIUS, C E	8306170020	50-454 Q
MURRAY, T D	8306160540	50-346 R	NELSON, O B	8306200410*	70-1257	NORELIUS, C E	8306170359	50-454 Q
MURRAY, T D	8306160679*	50-346 F	NELSON, M A	8306150030*	50-289 F	NORELIUS, C E	8306170361*	50-454 Q
MURRAY, T D	8306170142	50-346 S	NELSON, P R	8306060006*	FOIA	NORELIUS, C E	8306210037	50-305 Q
MURRAY, T D	8306170276	50-346 R	NELSON, P R	8306060007*	FOIA	NORELIUS, C E	8306220037	50-346 Q
MURRAY, T D	8306170414	50-346 S	NELSON, P R	8306060015*	FOIA	NORELIUS, C E	8306220041*	50-346 Q
MURRAY, T D	8306170427	50-346 S	NELSON, P R	8306060022*	FOIA	NORELIUS, C E	8306230051*	50-373 A
MURRAY, T D	8306210084	50-346 S	NELSON, R L	8306270341*	50-305 Q	NORELIUS, C E	8306230063*	50-373 Q
MURRAY, T D	8306210262	50-346 S	NEOGY, P	8306130379*	50-142 T	NORELIUS, C E	8306230260	50-266 Q
MUSELER, W J	8306140358*	50-322 Q	NEOGY, P	8306130379*	50-142 T	NORELIUS, C E	8306270066	50-456 Q
MUSOLF, D	8306020088	50-263 R	NESBE, R J	8306240078	NUREO	NORELIUS, C E	8306270329	50-305 Q
MUSOLF, D	8306020167	50-202 R	NEUMANN, H R	8306070450	40-8697	NORELIUS, C E	8306270335*	50-305 Q
MUSOLF, D	8306090230	50-202 F	NEUVILLE, C L	8306130372*	50-329 A	NORELIUS, C E	8306300044	50-346 Q
MUSOLF, D	8306090237	50-202 F	NEWMAN, B.	8306140505*	COMMISSION	NORRHLIN, L J	8306160144*	50-272 Q
MUSOLF, D	8306090263	50-202 F	NEWMAN, J R	8306100200	50-498 Q	NORRIS, E B	8306270003*	50-237 F
MUSOLF, D	8306100059	50-202 F	NEWMAN, J R	8306100200	50-498 Q	NORRIS, E B	8306140405	50-261 R
MUSOLF, D	8306130438	50-263 S	NEWMAN, J R	8306200300	50-498 Q	NORRIS, H R	8306160420	50-261 R
MUSOLF, D	8306140002	50-202 R	NEWMAN, J R	8306200308	50-498 Q	NORTH, H	8306100044*	50-312 Q
MUSOLF, D	8306140430	50-263 F	NEWMAN, K A	8306160069	FOIA	NORTH, H S	8306280145*	50-528 Q
MUSOLF, D	8306170353	50-263 P	NEWMAN, R C	8306030435	REG	NORTH, H S	8306280183*	50-312 Q
MUSOLF, D	8306200105	50-263 R	NEYLAN, A J	8306070354	50-358 R	NORTON, B	8306060275	50-275 Q
MUSOLF, D	8306200108	50-263 F	NEYLAN, A J	8306070357	50-358 A	NORTON, B	8306060275	50-275 Q
MUSOLF, D	8306200390	50-202 P	NEYLAN, A J	8306200070	50-358 A	NORTON, B	8306160579	50-275 Q
MUSOLF, D	8306210094	50-263 F	NEYLAN, A J	8306230131	50-358 R	NORTON, B	8306160579	50-275 Q
MUSOLF, D	8306280340	50-202 Q	NICHOLAS, H H	8306090131*	50-322 Q	NORTON, B	8306160584*	50-275 Q
MUSOLF, D	8306280459	50-263 F	NICHOLAS, H H	8306090151*	50-322 Q	NORTON, B	8306160584*	50-275 Q
MUSOLF, D M	8306010349	50-202 P	NICHOLAS, J D.	8306080046*	50-267 Q	NORTON, B	8306160595*	50-275 Q
MUSOLF, D M	8306010441	50-263 P	NICHOLAS, F A	8306280096	NUREO	NORTON, B	8306160595*	50-275 Q
MUSALLI, Y O	8306080298*	50-410 A	NICHOLSON, N	8306210148	40-8631	NORTON, B	8306170379*	50-142 T
MUSALLI, Y O	8306080303*	50-410 A	NICOLARAS, H	8306020523	50-263 P	NORTON, B	8306170390*	50-142 T
MUSALLI, Y O	8306080306*	50-410 A	NICOLARAS, H	8306230034	50-263 P	NORTON, B	8306170417*	50-142 T
MUSALLI, Y O	8306080320*	50-410 A	NICLOSTI, J	8306020392*	70-698	NORTON, B	8306170426*	50-142 T
MUSALLI, Y O	8306080360*	50-410 A	NICLOSTI, J	8306060172*	40-672	NORTON, B	8306280320	50-275 Q
MYERS, D O	8306140705*	50-324 Q	NICLOSTI, J	8306060177*	40-672	NORTON, J F	8306030143*	50-234 Q
MYRABO, A L	8306020088	50-263 R	NICLOSTI, J	8306060179*	40-672	NORTON, J F	8306030148*	50-234 Q
MYRABO, A L	8306200105	50-263 R	NICOTERA, C	8306080194	50-322 H	NORTON, J F	8306070190*	50-234 Q
NAAP, D E	8306170334*	50-263 F	NIENCTYK, S J	8306080041*	FOIA	NORTON, J F	8306100105*	50-237 Q
NAIDU, K R	8306030191*	50-440 Q	NIHTYNGALE, E	8306230359*	50-358 Q	NORTON, J F	8306230420*	50-409 Q
NAIDU, K R	8306100266*	50-374 Q	NILSON, R	8306020454	PR	NOVACHEN, F	8306300098	50-267 S
NAKAMURA, N	8306160685*	XPORTLIC	NILSON, R	8306170254	REG	NOVAK, T M	8306020045	50-423 C
NARBUT, P P	8306070007*	50-528 Q	NIMITZ, R L	8306020434*	50-244 Q	NOVAK, T M	8306020598	50-369 P
NARDACCI, G A	8306070217*	50-289 R	NIMITZ, R L	8306160348*	50-220 Q	NOVAK, T M	8306020606	50-390 A
NARDACCI, G A	8306300164*	50-289 R	NIMITZ, R L	8306230216*	50-336 Q	NOVAK, T M	8306020611	50-329 A
NARDI, A J	8306080021	70-1161	NIX, H C	8306310144	50-321 S	NOVAK, T M	8306020694	50-440 E
NARDI, A J	8306080327	71-4909	NIX, H C	8306030042	71-9176	NOVAK, T M	8306030509	50-440 A
NARDOCCI, P B	8306010015	50-370 S	NIX, H C	8306070080	50-321 S	NOVAK, T M	8306030517	50-454 A
NARDOCCI, P B	8306010098	50-369 S	NIX, H C	8306070259	50-366 S	NOVAK, T M	8306060349	50-322 A
NARDOCCI, P B	8306010104	50-370 S	NIX, H C	8306070347	50-321 S	NOVAK, T M	8306070460	REVIEW ORP
NARDOCCI, P B	8306010123	50-369 S	NIX, H C	8306130264	50-366 S	NOVAK, T M	8306080378	50-508 A
NARDOCCI, P B	8306010256	50-369 S	NIX, H C	8306140246*	50-321 F	NOVAK, T M	8306080388	50-508 A
NARDOCCI, P B	8306010401	50-369 S	NIX, H C	8306150041*	50-321 F	NOVAK, T M	8306170448	50-329 S
NARDOCCI, P B	8306070143	50-369 S	NIX, H C	8306150044*	50-321 F	NOVAK, T M	8306220221	50-395 Q
NARDOCCI, P B	8306090015	50-370 S	NIX, H C	8306150137*	50-321 F	NOVAK, T M	8306230482	50-369 E
NARDOCCI, P B	8306090040	50-370 S	NIX, H C	8306170382	50-321 R	NOVAK, T M	8306240077	50-423 D

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
NOVAK, T. H.	8306280070	50-329 A	OKADA, S.	8306140624	XPORTLIC	PAOLINO, R.	8306020376*	50-354 Q
NOVAK, T. H.	8306290163	50-390 A	OKADA, S.	8306140724*	XPORTLIC	PAOLINO, R.	8306150000*	50-209 Q
NOVAK, T. H.	8306290595	50-352 A	OKYERE, E. W.	8306070452	NUREQ	PAOLINO, R. J.	8306090151*	50-352 Q
NUSSBAUMER, D.	8306140331	WASTE MGT	OLLER, R. E.	8306210236*	NA999	PAPERIELLO, C. J.	8306090177	50-266 Q
O'BRIEN, J. P.	8306070385*	50-312 Q	OLSEN, R. H.	8306090501	ADVCH	PAPERIELLO, C. J.	8306090229	50-155 F
O'CONNOR, B.	8306170142	50-346 S	OLSHAN, L. N.	8306010019	50-454 A	PAPERIELLO, C. J.	8306100165	50-403 Q
O'CONNOR, D. H.	8306210220	50-322 A	OLSHAN, L. N.	8306010031	50-454 A	PAPERIELLO, C. J.	8306100212*	50-341 Q
O'DONNELL, E. P.	8306220266*	CONTRACT	OLSHAN, L. N.	8306240379	50-454 A	PAPERIELLO, C. J.	8306100217	50-151 Q
O'NEILL, B.	8306060266*	50-320 Q	OLSON, R. C.	8306070047	50-317 P	PAPERIELLO, C. J.	8306100226	50-155 Q
O'NEILL, J.	8306070372	50-155 Q	ONCAVAGE, H. P.	8306300157	PR	PAPERIELLO, C. J.	8306100252	50-373 Q
O'NEILL, J.	8306070375*	50-155 Q	ONCAVAGE, H. P.	8306300161	PR	PAPERIELLO, C. J.	8306100255*	50-373 Q
O'NEILL, J.	8306070424	50-155 Q	ONCAVAGE, H. P.	8306300227	PR	PAPERIELLO, C. J.	8306130285	50-341 Q
O'NEILL, J. H.	8306010390	50-400 Q	OPREA, Q. W.	8306070112	50-498 S	PAPERIELLO, C. J.	8306130306	50-303 F
O'NEILL, J. H.	8306010390	50-400 Q	OPREA, Q. W.	8306130350	50-498 S	PAPERIELLO, C. J.	8306130311	50-409 Q
O'NEILL, J. H.	8306010395*	50-400 Q	OPREA, Q. W.	8306170388	50-498 S	PAPERIELLO, C. J.	8306130330	50-305 Q
O'NEILL, J. H.	8306010395*	50-400 Q	OPREA, Q. W.	8306200122	50-498 A	PAPERIELLO, C. J.	8306130396	50-255 Q
O'NEILL, J. H.	8306030336	50-400 Q	ORTH, D. A.	8306200094	ACRS	PAPERIELLO, C. J.	8306130405	50-254 Q
O'NEILL, J. H.	8306030336	50-400 Q	OSTER, J.	8306020183	50-373 J	PAPERIELLO, C. J.	8306170277	50-275 Q
O'NEILL, J. H.	8306070291	50-400 Q	OSTER, J.	8306130231	50-454 J	PAPERIELLO, C. J.	8306210161	50-346 Q
O'NEILL, J. H.	8306070291	50-400 Q	OSTER, J.	8306140003	50-10 J	PAPERIELLO, C. J.	8306220026	50-295 Q
O'REILLY, J. P.	8306060020*	FOIA	OSTER, J.	8306170283	50-373 J	PAPERIELLO, C. J.	8306270162	50-156 Q
O'REILLY, J. P.	8306060024*	FOIA	OSTER, J.	8306270345	50-454 J	PAPERIELLO, C. J.	8306270167	50-155 Q
O'REILLY, J. P.	8306060026*	FOIA	OTTINGER, R. L.	8306020240*	50-322 U	PAPERIELLO, C. J.	8306270185	50-2 Q
O'REILLY, J. P.	8306060038*	FOIA	OTTINGER, R. L.	8306030156*	50-247 U	PAPERIELLO, C. J.	8306300068	50-373 Q
O'REILLY, J. P.	8306080003	50-250 Q	OTTINGER, R. L.	8306060380*	COMMISSION	PAPERIELLO, C. J.	8306300226	50-409 Q
O'REILLY, J. P.	8306140028	50-416 Q	OURB, R. P.	8306210056	50-312 R	PARCHEN, L. J.	8306240052	NUREQ
O'REILLY, J. P.	8306140040	50-302 Q	OVERTON, J. A.	8306300155	PR	PARIS, D. H.	8306280552	50-155 Q
O'REILLY, J. P.	8306140072	70-1113	PAGE, P. L.	8306020216	50-250 R	PARK, J. Y.	8306280096	NUREQ
O'REILLY, J. P.	8306140078	50-261 Q	PAGE, P. L.	8306140638	50-250 R	PARKER, J. E.	8306200251*	50-397 E
O'REILLY, J. P.	8306140116	50-321 Q	PAGE, R. Q.	8306010479	40-6500	PARKER, M. C.	8306210290*	50-341 Q
O'REILLY, J. P.	8306140194	50-324 Q	PAGE, R. Q.	8306020220	WASTE MGT	PARKER, P. E.	8306240443	PROJ
O'REILLY, J. P.	8306140328	50-280 Q	PAGE, R. Q.	8306030152	70-1201	PARKS, B.	8306280476	50-309 E
O'REILLY, J. P.	8306140366	50-309 A	PAGE, R. Q.	8306030179*	70-1201	PARKYN, J. D.	8306300423	PR
O'REILLY, J. P.	8306140393	50-250 Q	PAGE, R. Q.	8306060362	40-2061	PARSONS, R. M.	8306010128	50-400 B
O'REILLY, J. P.	8306140487	50-395 Q	PAGE, R. Q.	8306070430	40-6500	PARSONS, R. M.	8306010422	50-400 B
O'REILLY, J. P.	8306140519	50-416 Q	PAGE, R. Q.	8306070435	40-2061	PARSONS, R. M.	8306070217	50-400 E
O'REILLY, J. P.	8306140533	50-324 F	PAGE, R. Q.	8306070442*	40-2061	PARSONS, R. M.	8306070231	50-400 S
O'REILLY, J. P.	8306140550	50-280 F	PAGE, R. Q.	8306080052	70-2910	PARSONS, R. M.	8306070366	50-400 S
O'REILLY, J. P.	8306140565	50-413 Q	PAGE, R. Q.	8306080393	70-2838	PARSONS, R. M.	8306070389	50-400 S
O'REILLY, J. P.	8306140570	50-438 Q	PAGE, R. Q.	8306090255	70-2910	PARSONS, R. M.	8306070400	50-400 S
O'REILLY, J. P.	8306140577	50-250 Q	PAGE, R. Q.	8306090259*	70-2910	PARSONS, R. M.	8306090046	50-400 S
O'REILLY, J. P.	8306140602	50-416 Q	PAGE, R. Q.	8306090265*	70-2926	PARSONS, R. M.	8306090180	50-400 Q
O'REILLY, J. P.	8306140622	50-335 Q	PAGE, R. Q.	8306090269*	70-2926	PARSONS, R. M.	8306090191	50-400 S
O'REILLY, J. P.	8306140629	50-324 S	PAGE, R. Q.	8306140179	70-1151	PARSONS, R. M.	8306090242	50-400 S
O'REILLY, J. P.	8306140640	50-335 Q	PAGE, R. Q.	8306140442	40-8794	PARSONS, R. M.	8306100230	50-400 S
O'REILLY, J. P.	8306140646	50-335 F	PAGE, R. Q.	8306150332	70-1257	PARSONS, R. M.	8306100254	50-400 S
O'REILLY, J. P.	8306140659	50-400 A	PAGE, R. Q.	8306170479	40-6264	PARSONS, R. M.	8306140490*	50-400 Q
O'REILLY, J. P.	8306140710	50-280 Q	PAGE, R. Q.	8306210434	40-6264	PARSONS, R. M.	8306200116	50-400 R
O'REILLY, J. P.	8306140735	50-324 Q	PAGE, R. Q.	8306210436	70-143	PARSONS, R. M.	8306200200	50-400 Q
O'REILLY, J. P.	8306210236	50-416 Q	PAGE, R. Q.	8306210444	70-1113	PARSONS, R. M.	8306270223	50-400 B
O'REILLY, J. P.	8306210243*	50-416 Q	PAGE, R. Q.	8306280030	40-6500	PARSONS, R. M.	8306280463	50-400 R
O'REILLY, J. P.	8306220171	50-269 Q	PAGE, R. Q.	8306290082	70-734	PARSONS, R. M.	8306300192	50-400 B
O'REILLY, J. P.	8306220175*	50-269 Q	PAGE, R. Q.	8306290083*	70-734	PARTLOW, J. Q.	8306210354	NUREQ
O'REILLY, J. P.	8306240006	50-321 Q	PAGE, R. Q.	8306290101	40-6800	PASCIAK, W.	8306230397*	50-293 Q
O'REILLY, J. P.	8306240014*	50-321 Q	PAGE, R. Q.	8306290682	70-2375	PASCIAK, W.	8306280484*	50-273 Q
O'REILLY, J. P.	8306290483	50-259 Q	PALLADINO, N. J.	8305240605	COMMISSION	PASCIAK, W. J.	8306020407*	50-317 Q
O'REILLY, J. P.	8306290524	50-261 Q	PALLADINO, N. J.	8306020227	50-322 U	PASCOE, S.	8306090280*	CONTRACT
O'BHAUGHNESSY	8306010451	50-247 Q	PALLADINO, N. J.	8306020242*	50-322 U	PASQUA, H.	8306220276*	CONTRACT
O'SULLIVAN, E. T.	8306080004*	FOIA	PALLADINO, N. J.	8306030156	50-247 U	PASTVA, M. J.	8306010105	50-324 E
O'SULLIVAN, E. T.	8306080012*	FOIA	PALLADINO, N. J.	8306030159	COMMISSION	PASTVA, M. J.	8306010107	50-324 H
O'SULLIVAN, E. T.	8306080033*	FOIA	PALLADINO, N. J.	8306030164	50-320 P	PASTVA, M. J.	8306010118	50-325 H
O'TOOLE, J. D.	8306010126*	50-247 Q	PALLADINO, N. J.	8306030170	50-322 U	PASTVA, M. J.	8306070081	50-325 H
O'TOOLE, J. D.	8306020276	50-247 R	PALLADINO, N. J.	8306030369	COMMISSION	PASTVA, M. J.	8306070097	50-324 H
O'TOOLE, J. D.	8306070343	50-247 F	PALLADINO, N. J.	8306030375*	COMMISSION	PASTVA, M. J.	8306070102	50-324 H
O'TOOLE, J. D.	8306160462	50-247 R	PALLADINO, N. J.	8306060369	COMMISSION	PASTVA, M. J.	8306070235	50-324 H
O'TOOLE, J. D.	8306170044	50-247 S	PALLADINO, N. J.	8306060374*	COMMISSION	PASTVA, M. J.	8306100127	50-325 H
O'TOOLE, J. D.	8306170189	50-247 S	PALLADINO, N. J.	8306060388	50-272 U	PASTVA, M. J.	8306200003	50-324 H
O'TOOLE, J. D.	8306170197	50-247 S	PALLADINO, N. J.	8306080429	ADVCH	PASTVA, M. J.	8306210096	50-324 S
O'TOOLE, J. D.	8306170200	50-247 S	PALLADINO, N. J.	8306140513	ADVCH	PASTVA, M. J.	8306210174	50-323 H
O'TOOLE, J. D.	8306170230*	50-247 Q	PALLADINO, N. J.	8306150533	50-272 U	PASTVA, M. J.	8306270061	50-324 S
O'TOOLE, J. D.	8306170271	50-247 S	PALLADINO, N. J.	8306160193*	FOIA	PASTVA, M. J.	8306270199	50-324 S
O'TOOLE, J. D.	8306170323	50-247 S	PALLADINO, N. J.	8306270270*	50-289 Q	PASTVA, M. J.	8306270277	50-324 S
O'TOOLE, J. D.	8306170397	50-247 S	PALLADINO, N. J.	8306060186*	50-315 S	PASTVA, M. J.	8306300012	50-324 F
O'TOOLE, J. D.	8306170405	50-247 S	PALLADINO, N. J.	8306060271*	50-316 S	PASTVA, M. J.	8306300203	50-325 B
O'TOOLE, J. D.	8306170410	50-247 S	PALLADINO, N. J.	8306210134*	50-315 S	PATE, R. J.	8306070368*	50-361 Q
O'TOOLE, J. D.	8306170415	50-247 S	PALLADINO, N. J.	8306210142*	50-315 S	PATE, R. J.	8306280511*	50-361 Q
O'TOOLE, J. D.	8306200257	50-247 P	PALLADINO, N. J.	8306210267*	50-315 S	PATTERSON, J. P.	8306100212*	50-341 Q
O'TOOLE, J. D.	8306240225	50-247 Q	PALLADINO, N. J.	8306210273*	50-315 S	PATTERSON, W. F.	8306080088	50-443 Q
O'TOOLE, J. D.	8306270171	50-3 R	PALLADINO, N. J.	8306270158	50-316 S	PATTERSON, W. F.	8306150226	50-461 Q
OBERG, C. R.	8306210070*	50-382 Q	PALLADINO, N. J.	8306270436*	50-315 S	PATTERSON, W. F.	8306150238	50-443 Q
ODEGAARDEN, R. H.	8306280101	71-9096	PALLADINO, N. J.	8306270444*	50-315 S	PATTERSON, W. F.	8306150256	50-443 Q
ODEGARD, R. J.	8306280011	NUREQ	PALLADINO, N. J.	8306270449*	50-315 S	PATTERSON, W. F.	8306200173	50-443 Q
ODETMANN, M. J.	8306100167*	50-483 Q	PALLADINO, N. J.	8306090228*	40-8452	PATTERSON, W. F.	8306270306	50-443 Q
ODETMANN, M. J.	8306270174*	50-155 Q	PALLADINO, N. J.	8306210437	27-47	PATTON, S. D.	8306020454	PR
OKADA, S.	8306150459	XPORTLIC	PALLADINO, N. J.	8306140407	NUREQ	PAUL, R. A.	8306130333*	50-305 Q

PERSONAL AUTHOR INDEX

487

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
PAUL, R. A.	8306270167*	50-156 G	PFLUM, C. G.	8306240151*	FOIA	POTAPPOVS, U.	8306210023	0A999
PAUL, R. A.	8306300231*	50-409 Q	PHILBRICK, S. S.	8306240112*	FOIA	POTAPPOVS, U.	8306210025	0A999
PAULK, O. L.	8306140297*	50-259 Q	PHILLIPS, H. S.	8306130422*	0A999	POTAPPOVS, U.	8306210030	0A999
PAULSON, W. A.	8306070049	50-206 P	PHILLIPS, H. S.	8306210020*	0A999	POTAPPOVS, U.	8306210069	0A999
PAULSON, W. A.	8306080209	50-206 P	PHILLIPS, H. S.	8306210286*	0A999	POTAPPOVS, U.	8306210172	0A999
PAULSON, W. A.	8306210168*	50-244 P	PHILLIPS, H. S.	8306280404	0A999	POTAPPOVS, U.	8306210185	0A999
PAULSON, W. A.	8306240175	50-206 P	PHILLIPS, H. S.	8306280579	0A999	POTAPPOVS, U.	8306210215	0A999
PAVIS, O. S.	8306170072	50-318 S	PHILLIPS, H. S.	8306130412*	50-254 Q	POTAPPOVS, U.	8306210230	0A999
PAVIS, O. S.	8306210099	50-318 S	PHUNG, D. L.	8306280087	NUREQ	POTAPPOVS, U.	8306210238*	0A999
PAWLIK, E. T.	8306170392*	50-454 Q	PIEMONTESE, A. P.	8306010323	50-387 S	POTAPPOVS, U.	8306210244	0A999
PAYNE, A. C.	8306010052	NUREQ	PIEMONTESE, A. P.	8306020369	50-387 S	POTAPPOVS, U.	8306210272	0A999
PEARSON, D.	8306210410	ACRS	PIEMONTESE, A. P.	8306020401	50-387 S	POTAPPOVS, U.	8306210278	0A999
PEARSON, D.	8306210410	ACRS	PIEMONTESE, A. P.	8306170015	50-387 S	POTAPPOVS, U.	8306230401	0A999
PEDERSON, L. T.	8306020134	NUREQ	PIEMONTESE, A. P.	8306170037	50-387 S	POTAPPOVS, U.	8306240176	0A999
PEEBLES, T. A.	8306220050*	50-346 Q	PIEMONTESE, A. P.	8306280140	50-387 S	POTAPPOVS, U.	8306240207*	0A999
PELIZZA, M. S.	8306090028	40-8786	PIEMONTESE, A. P.	8306280158	50-387 S	POTAPPOVS, U.	8306240237	0A999
PELIZZA, M. S.	8306210425	40-8786	PIERCE, J. W.	8306220117	50-458 Q	POTAPPOVS, U.	8306240289	0A999
PELIZZA, M. S.	8306210451	40-8786	PIERCE, R. C.	8306140238*	CONTRACT	POTAPPOVS, U.	8306270452	0A999
PELKE, P. R.	8306030151*	50-440 Q	PIERINGER, P.	8306170031	50-317 S	POTAPPOVS, U.	8306280129	0A999
PELKE, P. R.	8306300183*	50-440 Q	PIERINGER, P. A.	8306010270	50-318 S	POTAPPOVS, U.	8306070053	50-325 B
PELLETIER, J. P.	8306170039	50-271 S	PIERINGER, P. A.	8306280152	50-318 S	POWELL, D. C.	8306020053	NUREQ
PELLETIER, J. P.	8306170264	50-271 S	PIERINGER, P. A.	8306280372	50-318 S	POWELL, T.	8306080203	50-358 Q
PELLIZZA, M. S.	8306220130	40-8786	PIGOTT, D. R.	8306220084	50-361 Q	POWELL, T.	8306080205*	50-358 Q
PELTO, P. J.	8306020134	NUREQ	PIGOTT, D. R.	8306220084	50-361 Q	POYSER, R. W.	8306160656	40-2259
PEMBERTON, H. R.	8306160275	50-361 K	PILANT, J. M.	8306060261	50-298 J	PRELL, J.	8306070146*	50-317 Q
PENNIFILL, R. A.	8306030477	WASTE MGT	PILANT, J. M.	8306080061	50-298 F	PRESBER, H. A.	8306130437	50-413 Q
PERCH, R.	8306170445	50-387 P	PILANT, J. M.	8306080219*	50-298 Q	PRESBER, H. A.	8306290461*	50-413 Q
PERCH, R. L.	8306150275	50-387 P	PILANT, J. M.	8306100139	50-298 P	PRICE, W.	8306130398	50-322 Q
PERCIVAL, R. M.	8306020329*	CONTRACT	PILANT, J. M.	8306140716	50-298 Q	PRICHARD, R. P.	8306080341	71-4909
PERKINS, R. W.	8306090357	WASTE MGT	PILANT, J. M.	8306160464	50-298 P	PRICHARD, R. P.	8306160664	71-9134
PERLIS, R. Q.	8306010146	50-483 Q	PILANT, J. M.	8306160466	50-298 P	PRICHARD, R. P.	8306170462	71-9132
PERLIS, R. Q.	8306200167	50-443 Q	PILANT, J. M.	8306200104	50-298 F	PRICHARD, R. P.	8306200022	71-4960
PERLIS, R. Q.	8306080053	50-443 Q	PILANT, J. M.	8306280384	50-298 P	PROCTOR, S.	8306220006	50-329 Q
PERLIS, R. Q.	8306200173	50-443 Q	PILANT, J. M.	8306280444	50-298 P	PROCTOR, S. D.	8306060313	50-329 Q
PERLIS, R. Q.	8306210266	50-483 Q	PIRTLE, O. L.	8306130319*	50-346 Q	PROCTOR, S. D.	8306200306	50-329 Q
PERLIS, R. Q.	8306210271*	50-483 Q	PLAINE, H. H.	8306090343	50-289 Q	PROCTOR, S. D.	8306220069	50-329 Q
PERLIS, R. Q.	8306200167	50-410 Q	PLAINE, H. H.	8306220063*	50-170 Q	PROWITT, B. M.	8306230080*	FOIA
PERLIS, R. Q.	8306280583	50-498 Q	PLAINE, H. H.	8306230360	50-289 Q	PULIDO, M.	8306060266	50-454 Q
PERLMAN, J.	8306030263	CONTRACT	PLANK, R. A.	8306210033*	0A999	PULIDO, M.	8306170379*	50-142 T
PERLMAN, J.	8306030268	CONTRACT	PLATT, W.	8306150398	50-529 Q	PULIDO, M.	8306170390*	50-142 T
PERLMAN, J.	8306170463	CONTRACT	PLATT, W.	8306150398	50-529 Q	PULIDO, M.	8306170417*	50-142 T
PERLMAN, J.	8306200128	CONTRACT	PLATT, W. E.	8306100078*	50-529 Q	PULIDO, M.	8306170426*	50-142 T
PERLMAN, J.	8306220133	CONTRACT	PLATT, W. E.	8306100078*	50-529 Q	PULLANI, S. V.	8306200130*	50-277 Q
PERLMAN, J.	8306220281	CONTRACT	PLONIS, T. R.	8306070465*	CONTRACT	PURDY, O. J.	8306230409	NUREQ
PERROTTI, D. J.	8306140636*	50-382 Q	PLONIS, T. R.	8306130412*	50-254 Q	PURPLE, R. A.	8306150257*	50-29 J
PETERS, R.	8306280486	50-333 S	PLOTKIN, S.	8306170379*	50-142 T	PURPLE, R. A.	8306150628*	50-220 F
PETERSON, C. E.	8306240263*	50-255 R	PLOTKIN, S.	8306170417*	50-142 T	PURPLE, R. A.	8306210426*	50-111 P
PETERSON, D. A.	8306130310	XPORTLIC	PLOTKIN, S.	8306170426*	50-142 T	PUTTARINI, D. M.	8306130130	50-528 B
PETERSON, M. R.	8306150451	XPORTLIC	PLUMLEE, O. L.	8306060126*	50-267 Q	QUICK, D. P.	8306210354	NUREQ
PETERSON, M. R.	8306150470	XPORTLIC	PLUMMER, D. E.	8306010085*	71-4400	QUICK, D. R.	8306140162*	50-327 Q
PETERSON, M. R.	8306150475*	XPORTLIC	POCHAL, W. F.	8306160672	XPORTLIC	QUICK, D. R.	8306140390*	50-327 Q
PETERSON, M. R.	8306160636	XPORTLIC	POETON, R. W.	8306010039	NUREQ	QUICK, D. R.	8306140434*	50-390 Q
PETERSON, M. R.	8306160640	XPORTLIC	POETON, R. W.	8306010067	NUREQ	QUICK, D. R.	8306140580*	50-390 Q
PETERSON, M. R.	8306160723	XPORTLIC	POETON, R. W.	8306010071	NUREQ	QUICK, D. R.	8306140583*	50-416 Q
PETERSON, M. R.	8306210374	XPORTLIC	POETON, R. W.	8306020053	NUREQ	QUICK, D. R.	8306290334*	50-438 Q
PETERSON, M. R.	8306210380	XPORTLIC	POLK, H.	8305230345*	50-275 P	QUINTON, H. D.	8306010357*	50-395 Q
PETERSON, M. R.	8306210414	XPORTLIC	POLK, H. E.	8305230135*	50-275 P	QUIRK, J. F.	8306290500*	50-447 K
PETERSON, M. R.	8306220270	XPORTLIC	POLLOCK, M. S.	8306140498*	50-322 Q	QUIRK, J. F.	8306290512*	50-447 K
PETERSON, M. R.	8306230023	XPORTLIC	POLLOCK, M. S.	8306140615*	50-322 Q	RABY, J.	8306060199	50-220 B
PETERSON, M. R.	8306240325	XPORTLIC	POMEROY, P. W.	8306200440	ACRS	RADDER, J. A.	8306310226	50-245 P
PETIT, M. R.	8306130390	50-322 Q	POMEROY, P. W.	8306200440	ACRS	RAE, R. M.	8306030449	FOIA
PETIT, M. R.	8306130401	50-322 H	POPE, M. A.	8306080083*	50-324 P	RAE, R. M.	8306140423*	50-324 Q
PETRIK, N. A.	8306100180	50-482 B	POPE, L. K.	8306090202	71-9096	RAHE, E. P.	8306150167	PROJ
PETRICK, N. A.	8306220010	50-482 A	POPE, L. K.	8306210250	71-9108	RAHE, E. P.	8306160224	NUREQ
PETRONC, C. D.	8306210103*	50-213 Q	PORT, E. A.	8306010069	40-2061	RAHE, E. P.	8306160433	PTR1
PETROWSKI, S. E.	8306040148	50-304 B	PORTER, S. W.	8306240384	NUREQ	RAHE, E. P.	8306170254	REQ00
PETTENHILL, H. J.	83060200437	40-2453	PORTHEMORE, W.	8306280538	50-289 Q	RAHE, E. P.	8306230386	TOPREP
PETTENHILL, H. J.	8306020257	40-299	POSENER, P.	8306060180	50-247 Q	RAHE, E. P.	8306240205	50-369 P
PETTENHILL, H. J.	8306020308*	40-8681	POSENER, P.	8306070471	NUREQ	RAHE, E. P.	8306240313	TOPREP
PETTENHILL, H. J.	8306020334*	40-8586	POSTHA, A. K.	8306070471	NUREQ	RAHE, E. P.	8306270355	PROJ
PETTENHILL, H. J.	8306020340	40-299	POTAPPOVS, U.	8306070066	50-413 S	RAHE, E. P.	8306280392	50-445 A
PETTENHILL, H. J.	8306090228*	40-8452	POTAPPOVS, U.	8306070108	0A999	RAHE, E. P.	8306280449	TOPREP
PETTENHILL, H. J.	8306090409	40-8681	POTAPPOVS, U.	8306070158	0A999	RAHE, E. P.	8306300120	50-445 A
PETTENHILL, H. J.	8306090495	40-8585	POTAPPOVS, U.	8306070168	0A999	RAMADAS, E. B.	8306130328*	50-322 E
PETTENHILL, H. J.	8306130406	40-2259	POTAPPOVS, U.	8306070186	MISC	RAMSDELL, J. V.	8306020053	NUREQ
PETTIKREW, M.	8306020592*	71-9080	POTAPPOVS, U.	8306070288	0A999	RAMSEY, C. B.	8306300067*	50-341 Q
PETTIKREW, M.	8306130212*	71-9089	POTAPPOVS, U.	8306070305	0A999	RAMSEY, C. B.	8306100276	50-309 Q
PETTY, J. C.	8306210190	50-287 B	POTAPPOVS, U.	8306070331	0A999	RANDAZZA, J. B.	8306210175	50-309 Q
PEVEY, L. E.	8306140290	XPORTLIC	POTAPPOVS, U.	8306130113	0A999	RANDAZZA, J. B.	8306290486	50-309 Q
PEVEY, L. E.	8306140298	XPORTLIC	POTAPPOVS, U.	8306130194	0A999	RANDICH, E.	8306020016	NUREQ
PFEFFERLEN, H. C.	8306170318	TOPREP	POTAPPOVS, U.	8306130397	0A999	RANGANATH, S.	8306020379*	50-277 P
PFLUM, C. G.	8306030273	WASTE MGT	POTAPPOVS, U.	8306130413	0A999	RANIN, W. L.	8306030009	NUREQ
PFLUM, C. G.	8306240084*	FOIA	POTAPPOVS, U.	8306160548	0A999	RASILE, J. A.	8306020513*	CONTRACT
PFLUM, C. G.	8306240094*	FOIA	POTAPPOVS, U.	8306210001	0A999	RATCLIFF, W. H.	8306040713*	CONTRACT
PFLUM, C. G.	8306240119*	FOIA	POTAPPOVS, U.	8306210013	0A999	RATHBUN, L. A.	8306270324	50-254 P

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
RATTA, A. D.	8306170245*	70-371	REPKA, D. A.	8306300071	50-322 Q	RIDGWAY, D. A.	8306220082	50-482 Q
RAUMONDO, C.	8306130398	50-322 Q	REQUA, Q.	8306170440	50-261 P	RIDGWAY, D. A.	8306230350	50-482 Q
RAUSCH, W. F.	8306230437	TOPREP	REQUA, Q.	8306200018	50-261 P	RIDGWAY, D. A.	8306230350	50-482 Q
RAWSON, R. J.	8306020446	50-322 Q	RESH, D. L.	8306230168*	CONTRACT	RIDGWAY, D. A.	8306280514	50-482 Q
RAWSON, R. J.	8306080173	50-289 Q	RESNIKOFF, H.	8306210322	FOIA	RIEL, G. L.	8306280512	50-443 Q
RAWSON, R. J.	8306150318	50-454 Q	RESNIKOFF, H.	8306210330	FOIA	RIOERT, J. A.	8306150373*	50-322 Q
RAY, H. B.	8306100054	50-361 S	RESSER, W. C.	8306070215	50-209 H	RILEY, J. L.	8306270284	50-413 Q
RAY, H. B.	8306100067	50-361 S	RESSER, W. C.	8306300162	50-209 R	RILEY, R. W.	8306300142	PR
RAY, H. B.	8306100072	50-361 S	REUSCHAEFER, E.	8306170221	50-302 R	RING, M. A.	8306100247*	50-454 Q
RAY, H. B.	8306100098	50-361 S	REVELEY, W. T.	8306130404	50-322 Q	RING, M. A.	8306230290*	50-454 Q
RAY, H. B.	8306100115	50-361 S	REVELEY, W. T.	8306130411	50-322 Q	RIVENBARK, G.	8306210335	50-321 P
RAY, H. B.	8306140007	50-361 S	REVELEY, W. T.	8306130411	50-322 Q	RIVENBARK, G. W.	8306030082	50-366 P
RAY, H. B.	8306140029	50-362 S	REVELEY, W. T.	8306130411	50-322 Q	RIVENBARK, G. W.	8306150470	50-366 P
RAY, H. B.	83061400250	50-361 S	REVELEY, W. T.	8306300147	50-322 Q	ROBBINS, M. C.	8306030451	FOIA
RAY, H. B.	8306140084	50-361 S	REVELEY, W. T.	8306300147	50-322 Q	ROBBINS, M. J.	8306210070*	50-302 Q
RAY, H. B.	8306160455	50-206 R	REYES, L. A.	8306100175*	50-373 Q	ROBERTS, E. S.	8306220158*	CONTRACT
RAY, H. B.	8306160489	50-361 R	REYES, L. A.	8306100247*	50-454 Q	ROBERTS, H. R.	8306230027	40-8681
RAY, H. B.	8306160113	50-361 S	REYES, L. A.	8306230290*	50-454 Q	ROBERTS, J. P.	8306020471	PROJ
RAY, H. B.	8306210352	50-361 S	REYNOLDS, J. R.	8306010336	50-275 H	ROBERTS, J. P.	8306230213	PROJ
RAY, H. B.	8306230266	50-361 S	REYNOLDS, J. R.	8306010336	50-275 H	ROBERTS, J. P.	8306240484	70-1308
RAY, H. B.	8306230369	50-362 S	REYNOLDS, J. R.	8306060182	50-275 Q	ROBERTS, T. M.	8306240333	COMMISSION
RAY, H. B.	8306230467	50-362 S	REYNOLDS, J. R.	8306060182	50-275 Q	ROBERTS, T. M.	8306240333	COMMISSION
RAY, H. B.	8306280252	50-361 S	REYNOLDS, J. R.	8306070406	50-275 Q	ROBERTS, T. H.	8306240336*	COMMISSION
RAY, H. B.	8306280267	50-361 S	REYNOLDS, J. R.	8306110435	50-275 Q	ROBERTSON, J. B.	8306280190	NUREC
RAY, H. B.	8306280273	50-361 S	REYNOLDS, J. R.	8306110435	50-275 Q	ROBINSON, D.	8306210279*	50-315 S
RAY, H. B.	8306280330	50-361 S	REYNOLDS, J. R.	8306220030	50-275 Q	ROCCO, J.	8306270172	50-206 J
RAY, H. B.	8306280410	50-361 S	REYNOLDS, J. R.	8306220038	50-275 Q	RODABABUSH, C. C.	8306230023*	50-373 A
RAY, J. H.	8306100152	50-493 A	REYNOLDS, J. R.	8306280365	50-275 P	RODRIGUEZ, R. J.	8306010397	50-312 P
RAY, J. J.	8306290122*	50-447 Q	REYNOLDS, J. R.	8306280365	50-275 P	RODRIGUEZ, R. J.	8306070067	50-312 P
RAYMON, M. R.	8306060309*	70-25	REYNOLDS, J. R.	8306290335	50-275 Q	RODRIGUEZ, R. J.	8306070067	50-312 P
RAYMOND, W. J.	8306070353*	50-271 Q	REYNOLDS, J. R.	8306290335	50-275 Q	RODRIGUEZ, R. J.	8306090233	50-312 P
RAYMOND, W. J.	8306160006	50-271 Q	REYNOLDS, N. J.	8306080237	50-445 Q	RODRIGUEZ, R. J.	8306090306	50-312 P
RAYMOND, W. J.	8306200181*	50-271 Q	REYNOLDS, N. J.	8306080237	50-445 Q	RODRIGUEZ, R. J.	8306140126	50-312 P
RAYMON, J. W.	8306010300	50-317 S	REYNOLDS, N. S.	8306020365	50-460 Q	RODRIGUEZ, R. J.	8306140591	50-312 P
RAYMON, J. W.	8306010307	50-317 S	REYNOLDS, N. S.	8306020365	50-460 Q	RODRIGUEZ, R. J.	8306170223	50-312 P
RAYMON, J. W.	8306170420	50-318 S	REYNOLDS, N. S.	8306020431	50-508 Q	RODRIGUEZ, R. J.	8306170290	50-312 P
REAVIS, J. A.	8306170297	50-269 R	REYNOLDS, N. S.	8306030330	50-445 Q	RODRIGUEZ, R. J.	8306170358	50-312 P
REAVIS, J. A.	8306170311	50-369 R	REYNOLDS, N. S.	8306030330	50-445 Q	RODRIGUEZ, R. J.	8306170402	50-312 P
REBELLO, J. E.	8306160045*	CONTRACT	REYNOLDS, N. S.	8306030347	50-460 Q	RODRIGUEZ, R. J.	8306210048	50-312 P
REBELLO, J. E.	8306030054*	CONTRACT	REYNOLDS, N. S.	8306030347	50-460 Q	RODRIGUEZ, R. J.	8306220040	50-312 P
REBELLO, J. E.	8306210303*	FOIA	REYNOLDS, N. S.	8306030353	50-460 Q	RODRIGUEZ, R. J.	8306220075	50-312 P
REBELLO, J. E.	8306220246*	CONTRACT	REYNOLDS, N. S.	8306030353	50-460 Q	RODRIGUEZ, R. J.	8306220150	50-312 P
REBELLO, J. E.	8306230048*	CONTRACT	REYNOLDS, N. S.	8306060313	PRM	RODRIGUEZ, R. J.	8306230372	50-312 P
REBELLO, J. E.	8306290281*	CONTRACT	REYNOLDS, N. S.	8306080243*	50-445 Q	RODRIGUEZ, R. J.	8306230393	50-312 P
REBELLOSKI, T.	8306060211*	50-423 Q	REYNOLDS, N. S.	8306080243*	50-445 Q	RODRIGUEZ, R. J.	8306230396	50-312 P
REDAND, R. T.	8306010141*	50-267 Q	REYNOLDS, N. S.	8306090337	50-460 Q	RODRIGUEZ, R. J.	8306230410	50-312 P
REDAND, R. T.	8306060133*	50-112 Q	REYNOLDS, N. S.	8306090337	50-460 Q	RODRIGUEZ, R. J.	8306230447	50-312 P
REDAND, R. T.	8306210012*	50-298 Q	REYNOLDS, N. S.	8306100190	50-460 Q	RODRIGUEZ, R. J.	8306270133	50-312 P
REDMANZ, F. J.	8306170382	50-321 R	REYNOLDS, N. S.	8306110334	50-508 Q	RODRIGUEZ, R. J.	8306270260	50-312 P
REED, C.	8306140334	PR	REYNOLDS, N. S.	8306110334	50-508 Q	RODRIGUEZ, R. J.	8306270325	50-312 P
REED, C.	8306220034*	50-254 Q	REYNOLDS, N. S.	8306150366	50-445 Q	RODRIGUEZ, R. J.	8306300011*	50-312 Q
REED, C.	8306230037*	50-373 A	REYNOLDS, N. S.	8306150366	50-445 Q	RDE, K. A.	8306230443*	TOPREP
REED, J. Q.	8306030331	50-483 Q	REYNOLDS, N. S.	8306150376	50-445 Q	ROGAN, R. E.	8306240317	50-209 P
REED, J. Q.	8306230344	50-483 Q	REYNOLDS, N. S.	8306150376	50-445 Q	ROGERS, H. H.	8306010167	50-378 S
REED, L. D.	8306240241	RES	REYNOLDS, N. S.	8306150425	50-445 Q	ROGERS, H. R.	8306010396	50-377 S
REEVES, P. E.	8306140549*	50-324 Q	REYNOLDS, N. S.	8306150425	50-445 Q	ROGERS, H. R.	8306100173	50-328 S
REGAN, N. A.	8306220131	70-824	REYNOLDS, N. S.	8306170334	NUREC	ROGERS, H. R.	8306130242	50-328 S
REGAN, W. H.	8306030242	50-329 M	REYNOLDS, N. S.	8306170406	50-445 Q	ROGERS, H. R.	8306210090	50-328 S
REGAN, W. H.	8306030246*	50-329 M	REYNOLDS, N. S.	8306170406	50-445 Q	ROGERS, H. R.	8306210106	50-328 S
REGAN, W. H.	8306140345	50-329 M	REYNOLDS, N. S.	8306230364	50-460 Q	ROGERS, H. R.	8306210290	50-328 S
REGAN, W. H.	8306140350*	50-329 M	REYNOLDS, N. S.	8306230364	50-460 Q	ROGERS, H. R.	8306270250	50-327 P
REGAN, W. H.	8306140360	50-329 M	REYNOLDS, N. S.	8306300047	50-460 Q	ROGERS, H. R.	8306280192	50-327 P
REGAN, W. H.	8306240369	PROJ	REYNOLDS, N. S.	8306300047	50-460 Q	ROGERS, P.	8306130421	50-368 S
REGAN, W. H.	8306240380*	PROJ	RHOADS, Q.	8306010134*	50-387 Q	ROGERS, P.	8306210003	50-313 S
REHFELDT, W. R.	8306240043*	FOIA	RHOADS, Q.	8306170343	50-387 S	ROGERS, P.	8306210181	50-368 S
REHFELDT, W. R.	8306240106*	FOIA	RHOADS, Q. M.	8306170336*	50-390 A	ROGERS, W. Q.	8306220050*	50-346 Q
REHM, T. A.	8306020710	COMMISSION	RHOADS, M. J.	8306020213	40-8027	ROGERS, W. H.	8306170485*	CONTRACT
REHM, T. A.	8306070426	COMMISSION	RHOADS, M. J.	8306030186	40-8027	ROGERS, W. H.	8306220310*	50-321 P
REHM, T. A.	8306080102	GEN TEC IS	RHOADS, M. J.	8306030467	40-7580	ROGERS, J.	8306220203	50-321 P
REHM, T. A.	8306150146	COMMISSION	RHOADS, M. J.	8306210447	70-371	ROHRER, M. V.	8306070237	50-416 S
REHM, T. A.	8306160112*	FOIA	RHOADS, M. J.	8306280095	70-371	ROHRER, M. V.	8306140667	50-416 S
REHM, T. A.	8306230221	COMMISSION	RHYNE, W. R.	8306220320*	CONTRACT	ROKLIKOFF, M. I.	8306080309*	70-25
REICH, M.	8306020048	RES	RICE, D. A.	8306170410	50-29 S	ROKLINE, S. J.	8306080194	50-322 H
REIMANN, F. W.	8306230022*	50-373 Q	RICE, D. W.	8306150064	50-272 P	ROMAN, T. W.	8306020094	50-220 P
REIMANN, F. W.	8306230061*	50-373 Q	RICHARD, J. B.	8306090134	50-416 S	ROMAN, T. W.	8306200214	50-220 P
REIMER, Q. A.	8306170354*	50-263 P	RICHARD, J. B.	8306290211	50-416 Q	ROMANO, F. R.	8306010464	50-352 Q
REITER, R.	8306080215	50-358 Q	RICHARDS, S.	8306060170*	50-277 Q	ROMANO, F. R.	8306080261	50-352 Q
REITER, R.	8306080250	50-358 Q	RICHARDS, S.	8306150008*	50-289 Q	ROMANO, F. R.	8306290364	50-352 Q
REITTER, T. A.	8306150619	NUREC	RICHARDSON, C.	8306210029	50-271 H	ROMANO, F. R.	8306290509	50-352 Q
REKTO, W. A.	8306010231*	50-333 Q	RICHARDSON, J. D.	8306200412	50-416 R	ROMATOWSKI, R. G.	8306060417	WASTE MGT
REPKA, D. A.	8306100041	50-458 Q	RICHTER, L.	8306170429	50-346 S	ROOD, H.	8306240477	50-361 P
REPKA, D. A.	8306130414	50-322 Q	RICHTER, L.	8306210262	50-346 S	ROOF, L. D.	8306070326*	50-331 Q
REPKA, D. A.	8306230003	50-458 P	RIDGWAY, D. A.	8306200312	50-482 Q	ROPE, S. K.	8306020011	NUREC
REPKA, D. A.	8306230008	50-322 Q	RIDGWAY, D. A.	8306200312	50-482 Q	ROBAND, R.	8306010066	50-219 Q
REPKA, D. A.	8306280506	50-322 Q	RIDGWAY, D. A.	8306220082	50-482 Q	ROBAND, R.	8306140696	50-416 S

PERSONAL AUTHOR INDEX

489

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
ROBAUER, P J	B306240342	71-9110	RYBAK, B	B306160233	50-237 P	SCHROEDER, B A	B306140084	50-237 R
ROSE, K A	B306140691	NURCQ	RYBAK, B	B306200265	50-237 P	SCHROEDER, C	B306100234	50-374 S
ROSEN, R A	B306200290	50-247 Q	RYBAK, B	B306220067	50-254 Q	SCHROEDER, C W	B306190370	50-373 P
ROSOLIE, E	B306150302	50-460 Q	RYBAK, B	B306240030	50-237 P	SCHROEDER, C W	B306060146	50-373 P
ROSOLIE, E	B306150306	50-460 Q	RYBAK, B	B306270108	50-254 P	SCHROEDER, C W	B306060238	50-373 P
ROSOLIE, E	B306290370	50-460 Q	RYBAK, B	B306270247	50-237 P	SCHROEDER, C W	B306070334	50-374 A
ROSOLIE, E	B306290375	50-460 Q	RYBAK, B	B306300237	50-254 P	SCHROEDER, C W	B306070355	50-373 F
ROSS, W J	B306290332	50-321 Q	SABADOS, J W	B306140582	70-1113	SCHROEDER, C W	B306100062	50-373 P
ROSSBACH, L W	B306070092	50-286 Q	SABADOS, J W	B306140713	70-143	SCHROEDER, C W	B3060210205	50-373 F
ROTH, J	B306060176	70-364	SACHNOFF, S	B3062300128	NURCQ	SCHROEDER, C W	B306280323	50-373 P
ROTH, J	B306150001	70-1143	SAITO, T	B306240019	XPORTLIC	SCHUELKE, D A	B306230087	50-282 F
ROTH, J	B306230225	70-1143	SALAZAR, E A	B306210020	GA999	SCHUM, W B	B306140220	50-482 Q
ROTH, J	B306230118	70-020	SALTZMAN, J	B306090020	50-16 J	SCHUMACHER, M	B306210148	40-8631
ROTHSCHILD, M U	B306020175	50-400 Q	SALTZMAN, J	B306090039	50-16 J	SCHUMACHER, M C	B306100167	50-483 Q
ROTHSCHILD, M U	B306150313	50-445 Q	SALTZMAN, J	B306220286	50-0 J	SCHUMACHER, M C	B306270174	50-158 Q
ROTHSCHILD, M U	B306150396	50-445 Q	SALTZMAN, J	B306230157	F01A	SCHUSTER, M D	B306280081	50-206 Q
ROTHSCHILD, M U	B306230381	50-445 Q	SALTZMAN, J	B306270103	50-335 J	SCHUSTER, M D	B306280136	50-344 Q
ROUSE, E A	B306270394	50-344 H	SALTZMAN, J	B306270120	50-335 J	SCHUSTER, M D	B306280183	50-312 Q
ROWLAND, O D	B306160460	RECOG	SALTZMAN, J	B306270210	50-335 J	SCHUYLER, J O	B306030162	50-275 P
ROWLAND, J R	B306010081	NURCQ	SAMPSON, N	B306240101	F01A	SCHUYLER, J O	B306060155	50-275 F
ROWLAND, M	B306170414	50-346 S	SAMPSON, N R	B306240096	F01A	SCHUYLER, J O	B306070036	50-133 H
ROWLAND, F	B306030968	F01A	SANDQUIST, G M	B306160194	50-72 F	SCHUYLER, J O	B306070270	50-275 P
ROZAK, S	B306100167	50-483 Q	SANDRY, W A	B306080070	F01A	SCHUYLER, J O	B306070275	50-275 P
RUBY, O T	B306130430	50-263 S	SANTORO, M P	B306240445	71-9006	SCHUYLER, J O	B306070292	50-275 R
RUDY, C R	B306010095	40-6500	SARGENT, I H	B306020037	50-309 P	SCHUYLER, J O	B306140031	50-275 P
RUDY, C R	B306030194	40-6500	SARGENT, I H	B306030070	50-338 P	SCHUYLER, J O	B306160526	50-275 R
RUDY, C R	B306030506	40-6500	SARGENT, I H	B306030446	50-280 P	SCHUYLER, J O	B306210111	50-275 P
RUFF, A B	B306140671	50-113 Q	SARGENT, I H	B306030512	50-295 P	SCHUYLER, J O	B306240398	70-2373
RUITER, G F	B306140001	50-305 R	SARGENT, I H	B306090380	50-298 P	SCHUYLER, J O	B306280332	50-275 P
RULAN, Y	B306060309	70-25	SARGENT, I H	B306090397	50-312 P	SCHUYLER, J O	B306280388	50-275 P
RULAND, W H	B306290228	50-348 Q	SARGENT, I H	B306150266	50-259 P	SCHUYLER, J O	B306280394	50-275 P
RUSHMORE, J W	B306020188	50-220 J	SARGOUR, B	B306020129	50-346 R	SCHUYLER, J O	B306280451	50-275 P
RUSHMORE, J W	B306020187	50-220 J	SARGOUR, B	B306160340	50-346 R	SCHUYLER, J O	B306300041	50-275 Q
RUSCHER, G C	B306240052	NURCQ	SARTEN, G E	B306210112	50-443 S	SCHUYLER, J O	B306300211	50-275 P
RUSSELL, J B	B306270164	50-317 F	SATHER, A	B306090245	50-329 Q	SCHWENGER, A	B306030020	50-397 A
RUSSELL, J B	B306270195	50-317 F	BAUER, J R	B306150179	50-209 H	SCHWENGER, A	B306070440	50-322 Q
RUSSELL, J E	B306140168	40-6622	BAURHEIN, J J	B306160545	50-267 P	SCHWENGER, A	B306070444	50-461 E
RUSSELL, L D	B306010264	50-317 S	BAURHEIN, J J	B306160544	50-267 P	SCHWENGER, A	B306150227	50-458 A
RUSSELL, L D	B306010270	50-318 S	SCALET, D C	B306080434	50-447 A	SCHWENGER, A	B306150321	50-382 A
RUSSELL, L D	B306010273	50-318 S	SCARAND, R A	B306070152	50-312 Q	SCHWENGER, A	B306150552	50-373 P
RUSSELL, L D	B306010277	50-317 S	SCARAND, R A	B306080123	50-312 F	SCHWENGER, A	B306150579	50-352 E
RUSSELL, L D	B306010297	50-318 S	SCARAND, R A	B306280455	70-115	SCHWENGER, A	B306200429	50-416 E
RUSSELL, L D	B306010300	50-317 S	SCHAPKIN, J F	B306230357	50-358 Q	SCHWENGER, A	B306220250	50-458 F
RUSSELL, L D	B306010307	50-317 S	SCHAPKIN, J F	B306270205	50-546 Q	SCHWENGER, A	B306270559	50-416 P
RUSSELL, L D	B306020374	50-318 S	SCHETINMAN, L	B306160138	F01A	SCOTT, D J	B306240073	NURCQ
RUSSELL, L D	B306020423	50-317 S	SCHERER, A E	B306090170	50-470 A	SCOTT, D J	B306030218	50-237 S
RUSSELL, L D	B306020430	50-318 S	SCHERER, A E	B306130428	50-470 A	SCOTT, D J	B306060040	50-237 S
RUSSELL, L D	B306020433	50-317 S	SCHERER, A E	B306140683	50-325 S	SCOTT, D J	B306060232	50-237 S
RUSSELL, L D	B306020438	50-318 S	SCHERER, A E	B306200234	50-470 A	SCOTT, D J	B306070234	50-249 S
RUSSELL, L D	B306020467	50-317 S	SCHERER, A E	B306200392	50-470 E	SCOTT, D J	B306070246	50-237 S
RUSSELL, L D	B306070077	50-317 S	SCHERER, A E	B306230342	NURCQ	SCOTT, D J	B306070277	50-249 R
RUSSELL, L D	B306150086	50-317 F	SCHERER, A E	B306230419	RECOG	SCOTT, D J	B306130275	50-10 B
RUSSELL, L D	B306170011	50-317 S	SCHERER, P R	B306200253	50-397 E	SCOTT, D J	B306130325	50-249 S
RUSSELL, L D	B306170031	50-317 S	SCHERER, P R	B306280436	50-397 F	SCOTT, D J	B306130346	50-249 S
RUSSELL, L D	B306170072	50-318 S	SCHERER, R W	B306070130	50-321 I	SCOTT, D J	B306130348	50-237 S
RUSSELL, L D	B306170420	50-318 S	SCHIAERLO, K J	B306060226	PR	SCOTT, D J	B306130374	50-237 S
RUSSELL, L D	B306200087	50-317 S	SCHIERLING, H	B306020619	50-275 P	SCOTT, D J	B306130382	50-237 S
RUSSELL, L D	B306200118	50-318 S	SCHIERLING, H	B306240473	50-275 P	SCOTT, D J	B306130439	50-237 S
RUSSELL, L D	B306200200	50-317 S	SCHIERLING, H	B306290466	50-275 T	SCOTT, D J	B306140086	50-237 R
RUSSELL, L D	B306200268	50-317 S	SCHIMMEL, R L	B306020677	XPORTLIC	SCOTT, D J	B306210357	50-10 F
RUSSELL, L D	B306210046	50-318 S	SCHLIEDE, H J	B306140402	NURCQ	SCOTT, D J	B306270083	50-249 B
RUSSELL, L D	B306210086	50-317 S	SCHMIDT, R	B306060309	70-25	SCOTT, D J	B306270111	50-249 S
RUSSELL, L D	B306210097	50-318 S	SCHMIDT, G R	B306070107	50-529 S	SCOTT, D J	B306270387	50-237 Q
RUSSELL, L D	B306210101	50-317 S	SCHMIDT, H C	B306130176	50-445 A	SCOTT, W Q	B306150455	50-483 F
RUSSELL, L D	B306210108	50-317 S	SCHMIDT, H C	B306130279	50-445 A	SCOTT, W Q	B306280519	50-328 Q
RUSSELL, L D	B306210159	50-318 S	SCHMIDT, H C	B306130293	50-445 A	SCOTT, W Q	B306070341	50-206 Q
RUSSELL, L D	B306210246	50-318 S	SCHMIDT, H C	B306150102	50-445 F	SCUDDER, J	B306080276	F01A
RUSSELL, L D	B306280172	50-318 S	SCHMIDT, H C	B306280400	50-445 A	SCULL, D L	B306220054	50-170 Q
RUSSELL, L D	B306280352	50-318 S	SCHMITTENDORF, G	B306020092	50-338 R	SCHURRY, N	B306070475	ORO
RUSSELL, L D	B306280447	50-317 S	SCHMITTENDORF, G	B306160532	50-338 R	SEARS, C F	B306010340	50-213 P
RUSSELL, L D	B306280462	50-318 S	SCHMITT, T J	B306240053	F01A	SEARS, C F	B306010340	50-213 P
RUSTICK, R	B306270252	50-254 S	SCHMITT, T W	B306240262	TOPREP	SEARS, C F	B306060098	50-326 P
RUTENKROGER, F	B306200115	70-1739	SCHNELL, D F	B306010110	70-2745	SEARS, C F	B306060243	50-213 P
RUTHER, W E	B306280096	NURCQ	SCHNELL, D F	B306070145	50-483 Q	SEARS, C F	B306080058	50-245 P
RUTLEDGE, C	B306130248	40-8502	SCHNELL, D F	B306100147	50-483 A	SEARS, C F	B306080058	50-245 P
RUTLEDGE, C	B306160215	40-8502	SCHNELL, D F	B306150455	50-483 F	SEARS, C F	B306080058	50-245 P
RUTLEDGE, C	B306200182	40-8502	SCHNELL, D F	B306170279	50-483 B	SEARS, J R	B306080057	50-443 Q
RUTLEDGE, C	B306240436	40-8502	SCHNELL, D F	B306210198	50-483 Q	SEIDLE, W C	B306010101	50-313 Q
RUTLEDGE, C	B306090364	50-34 P	SCHNELL, D F	B306230481	50-483 Q	SEIDLE, W C	B306060063	50-313 Q
RYAN, R H	B306240034	CONTRACT	SCHNELL, D F	B306270235	50-483 B	SEIDLE, W C	B306070380	50-313 Q
RYBAK, B	B306060212	50-254 Q	SCHNELL, D F	B306290585	70-2745	SEIDLE, W C	B306080109	50-285 Q
RYBAK, B	B306070227	50-237 P	SCHNELL, D F	B306300090	50-483 Q	SEIDLE, W C	B306080184	50-482 Q
RYBAK, B	B306100147	50-237 Q	SCHODENBERGER, I	B306200098	50-247 H	SEIDLE, W C	B306080192	50-313 Q
RYBAK, B	B306130226	50-249 P	SCHROCK, V E	B306220290	ACRS	SEIDLE, W C	B306080231	50-285 Q
RYBAK, B	B306130425	50-237 P	SCHROCK, V E	B306220290	ACRS	SEIDLE, W C	B306070349	50-285 Q

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
SEIDLE, W C	8306130117	50-285 G	SHELOSKEY, J I	8306040171	50-245 G	SILBERG, J E	8306200310	50-487 C
SEIDLE, W C	8306140189	50-407 G	SHELOSKEY, J I	8306090241	50-245 G	SILBERG, J E	8306270214	50-440 G
SEIDLE, W C	8306140207	50-482 G	SHELLEY, W J	8306130344	40-8027	SILBERG, J E	8306270211	50-440 G
SEIDLE, W C	8306140224	50-72 G	SHELLEY, W J	8306220140	40-8768	SILBERT, E J	8306140789	ADVCH
SEIDLE, W C	8306140245	50-482 G	SHELLEY, W J	8306240343	10-8047	SILBERT, E J	8306200045	ADVCH
SEIDLE, W C	8306140359	50-317 G	SHELLEY, W J	8306300103	PR	SILLING, S A	8306240066	NUREG
SEIDLE, W C	8306160354	50-313 G	SHELLEY, W J	8306300155	PR	SILVIS, R M	8306140421	CONTRACT
SEIDLE, W C	8306300075	50-313 G	SHELTON, K W	8306010081	NUREG	SILVIS, R M	8306140437	CONTRACT
SEIFFERT, S G	8306220136	40-1162	SHEN, C N	8306070473	NUREG	SILVIS, R M	8306210364	CONTRACT
SEIKEN, S J	8306030220	50-482 S	SHEPHERD, R L	8306060164	10-354 G	SILVIS, R M	8306220151	CONTRACT
SEIKEN, S J	8306070345	50-482 S	SHEPHERD, R L	8306060023	50-354 G	SILVIS, R M	8306220217	CONTRACT
SELAN, J C	8304070100	50-277 P	SHEPHERD, R L	8306060027	FOIA	SILVIS, R M	8306230185	CONTRACT
SELAN, J C	8306100135	50-237 P	SHEPHERD, R L	8306060027	FOIA	SILVIS, R M	8306230474	CONTRACT
SELLS, D E	8306020046	50-335 P	SHEPHERD, J J	8306160284	TOPREF	SILVIS, R M	8306230503	CONTRACT
SEMINARA, C	8306090373	FOIA	SHEPHERD, J J	8306160284	TOPREF	SILVIS, R M	8306230507	CONTRACT
SEMMEI, H	8306010450	50-155 G	SHEPPARD, J J	8306220087	TOPREF	SIMAN-TOV, J	8306220097	NUREG
SEMMEI, H	8306240423	50-155 G	SHEPPARD, J J	8306220087	TOPREF	SIMCHUK, J D	8306030135	71-9159
SEMMEI, H	8306240423	50-155 G	SHERIN, W C	8306130331	50-321	SIMON, J A	8306070245	50-329
SERINT, B L	8306070274	70-2926	SHERINT, S	8306240384	NUREG	SIMONEAUX, F P	8306150484	CONTRACT
SERKIL, A W	8306060418	NUREG	SHERMAN, C	8306260145	50-528 G	SIMONEN, C P	8306020134	NUREG
SERKIZ, A W	8306060413	NUREG	SHERR, T S	8306140218	50-264 F	SIMONS, D D	8306210386	CONTRACT
SERKIZ, A W	8306140198	GEN TEC IS	SHERR, T S	8306160164	FOIA	SIMPSON, F B	8306080161	50-335 P
SERNE, R J	8306020217	WASTE MGT	SHERR, T S	8306210349	50-171 F	SIMPSON, R M	8306290827	50-482 C
SERRANO, H	8306080161	50-335 P	SHERWOOD, G G	8306070105	50-447 K	SIMPSON, J H	8306290522	50-482 C
SESTAK, F	8306100171	50-275 R	SHERWOOD, G G	8306070111	50-447 K	SINCLAIR, J H	8306020174	50-271 P
SESTAK, F	8306290397	50-275 R	SHERWOOD, G G	8306070201	50-447 K	SINCLAIR, J H	8306030112	50-271 P
SESTAK, F	8306290401	50-275 R	SHERWOOD, G G	8306070236	50-447 A	SINCLAIR, J H	8306140285	50-271 P
SESTAK, F	8306290545	50-275 R	SHERWOOD, G G	8306100092	50-351 S	SINCLAIR, J H	8306290247	50-271 P
SETKA, Q E	8306170354	50-243 S	SHERWOOD, G G	8306170214	50-447 A	SINCLAIR, J H	8306220044	50-271 P
SEWELL, R B	8112090561	50-255 S	SHERWOOD, G G	8306220255	TOPREF	SINCLAIR, J H	8306240170	50-271 P
SHABER, C R	8306160641	50-389 P	SHERWOOD, G G	8306290481	50-447 K	SINCLAIR, J H	8306080304	50-490 J
SHACK, W J	8306280096	NUREG	SHERWOOD, G G	8306290495	50-447 K	SINISI, J M	8306020129	70-444 J
SHACKLETON, D C	8306100040	50-312 G	SHERWOOD, G G	8306290507	50-447 K	SINISI, J M	8306230293	50-277 J
SHACKLETON, D C	8306160230	50-206 G	SHERWOOD, G G	8306300131	NUREG	SINKIN, I	8306080150	50-498 G
SHACKLETON, D C	8306160263	50-206 G	SHERWOOD, G G	8306060037	50-546 A	SINKIN, I	8306080155	50-498 G
SHAFFER, J C	8306230277	50-482 S	SHIELDS, S W	8306070144	50-546 G	SINKIN, L A	8306080159	50-498 G
SHAFFER, W	8306130327	50-331 S	SHIELDS, S W	8306070144	50-546 G	SINKIN, L A	8306220057	50-498 G
SHAFFER, W	8306160264	50-306 S	SHIELDS, S W	8306070377	50-546 G	SITLER, P	8306220094	50-322 G
SHAFFER, W	8306220060	50-295 S	SHIELDS, S W	8306140396	50-546 A	SITLER, P	8306290326	50-322 G
SHAFFER, W	8306270277	50-237 G	SHIELDS, S W	8306170182	50-546 G	SITLER, P	8306140774	NUREG
SHAFFER, W D	8306060210	50-295 G	SHIELDS, S W	8306270138	50-546 K	SIV, N D	8306210336	FOIA
SHAFFER, W D	8306060217	50-295 G	SHIELDS, S W	8306270219	50-546 G	SJOGREN, A L	8306210330	NUREG
SHAFFER, W D	8306060247	50-263 G	SHIELDS, S W	8306270375	50-546 G	SKARITKA, J	8306140590	50-486 P
SHAFFER, W D	8306090316	50-331 G	SHIFFER, J D	8306100067	50-275 G	SKARITKA, J	8306200402	50-486 P
SHAFFER, W D	8306210057	50-315 G	SHIFFER, J D	8306100082	50-275 G	SKARUPA, J D	8306150462	XPURTLIC
SHAFFER, W D	8306210095	50-155 G	SHIFFER, J D	8306210044	50-275 G	SKINNER, P H	8306140471	50-395 G
SHAFFER, W D	8306270215	50-373 G	SHIFFER, J D	8306210070	50-275 G	SLAMINSKI, W	8306230246	70-371 G
SHAFFER, W D	8306270220	50-373 G	SHIFFER, J D	8306230365	50-275 G	SLCUM, L	8306060307	70-45
SHAFFER, W D	8306270381	50-409 G	SHIFFER, J D	8306230422	50-275 G	SLEDIRAL, C	8306240341	71-9344
SHAFFER, W D	8306270385	50-409 G	SHIFFER, J D	8306280042	50-275 G	SLEDLEY, R	8306270388	50-289 G
SHAFFER, W D	8306300014	50-255 G	SHIFFER, J D	8306280523	50-275 G	SMITH, A L	8306130422	NAVY
SHAFFER, W D	8306300026	50-373 S	SHIFFER, J D	8306280526	50-275 G	SMITH, B	8306060307	70-25
SHAFFER, W D	8306300127	50-373 G	SHIFFER, J D	8306280164	50-275 G	SMITH, D	8306202324	40-8681
SHAFFER, W D	8306300135	50-373 G	SHINGLETON, H	8306140046	50-416 G	SMITH, D G	8306200190	NUREG
SHAFFER, W D	8306300197	50-375 G	SHINGLETON, H	8306200121	50-416 G	SMITH, G C	8306010327	50-334 G
SHAFFER, J D	8306240318	50-275 S	SHINGLETON, H	8306140667	50-416 G	SMITH, G C	8306030317	70-371
SHAFFER, R	8306200276	40-8380	SHIRAKAWA, T	8306150468	XPURTLIC	SMITH, G C	8306230475	50-372 G
SHANBAKY, M	8306060264	71-290	SHOENAKER, B	8306080326	71-9017	SMITH, H D	8306020463	CONTRACT
SHANBAKY, M	8306060267	50-286 G	SHOENAKER, C J	8306020361	50-441 G	SMITH, I W	8306200294	50-454 G
SHANBAKY, M	8306090036	71-2	SHOENAKER, C J	8306060276	50-341 G	SMITH, I W	8306220392	50-454 G
SHANBAKY, M	8306230469	50-333 G	SHOENAKER, C J	8306060330	50-351 G	SMITH, I W	8306230355	50-454 G
SHANBAKY, M	8306280474	50-271 G	SHOENAKER, C J	8306070396	50-409 G	SMITH, I W	8306230362	50-454 G
SHANBAKY, M M	8306020416	50-293 G	SHOENAKER, C J	8306090307	50-275 G	SMITH, J L	8306010011	50-322 S
SHANBAKY, M M	8306020434	50-244 G	SHOENAKER, C J	8306270288	50-289 G	SMITH, J L	8306010432	50-322 S
SHANBAKY, M M	8306020447	50-219 G	SHOENAKER, C J	8306300052	50-275 G	SMITH, J L	8306020455	50-322 S
SHANBAKY, M M	8306020460	50-244 G	SHOENAKER, C J	8306300134	50-409 G	SMITH, J L	8306070013	50-322 L
SHANBAKY, M M	8306160340	50-220 G	SHOLLY, B C	8306080028	FOIA	SMITH, J L	8306070030	50-322 G
SHANBAKY, M M	8306230216	50-334 G	SHON, R J	8306280552	50-156 G	SMITH, J L	8306070321	50-322 A
SHANBAKY, M M	8306230388	50-317 G	SHOOD, P	8306080079	ADVCH	SMITH, J L	8306170236	50-322 G
SHANK, K E	8306270253	50-387 R	SHOPENN, N H	8306080165	40-8027	SMITH, J L	8306130326	50-322 E
SHANNON, J B	8306070456	40-8064	SHORT, R H	8306200210	50-344 I	SMITH, J L	8306140607	50-322 G
SHAPIRO, J	830609030104	FOIA	SHOTWELL, J A	8306070411	50-443 G	SMITH, J L	8306140607	50-322 G
SHAPIRO, J	8306170295	FOIA	SHREVE, D B	8306220327	CONTRACT	SMITH, J L	8306160087	50-322 F
SHAPIRO, J	8306150378	50-322 G	SHUEY, C	8306160465	PRM	SMITH, J L	8306160100	50-322 F
SHARP, I H	8306070023	FOIA	SHUEY, C	8306300217	PR	SMITH, J L	8306240230	50-322 E
SHARP, I H	8306210310	FOIA	SHUTTLEWORTH, W	8306210127	50-546 A	SMITH, J L	8306240250	50-322 F
SHEA, J F	8306280608	50-322 G	SHUTLOCK, M D	8306140647	50-331 G	SMITH, J L	8306280042	50-322 F
SHEA, J F	8306280608	50-322 G	SIEBER, J D	8306100104	50-334 G	SMITH, J L	8306280265	50-322 G
SHEA, J J	8306130356	50-245 P	SILBERG, J E	8306160593	50-482 G	SMITH, J L	8306280445	50-322 E
SHEA, J R	8306160107	FOIA	SILBERG, J E	8306160593	50-482 G	SMITH, J L	8306280347	50-322 E
SHEA, K H	8306030167	50-331 J	SILBERG, J E	8306140596	50-440 G	SMITH, M	8306020274	40-8064
SHEALY, H G	8306190251	CONTRACT	SILBERG, J E	8306160596	50-440 G	SMITH, M	8306130412	50-254 G
SHEARER, L N	8306130347	50-373 R	SILBERG, J E	8306160611	50-440 G	SMITH, M L	8306160670	71-9134
SHEARER, V M	8306080203	50-358 G	SILBERG, J E	8306160611	50-440 G	SMITH, P A	8306030264	CONTRACT
SHEARER, V M	8306080203	50-358 G	SILBERG, J E	8306200310	50-482 G	SMITH, P A	8306030271	CONTRACT

PERSONAL AUTHOR INDEX

49

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
SMITH, P A	030600006	CONTRACT	SPITZBERG, D B	0306080175*	40-8027	STAROSTECKI, R	0306140617	50-309
SMITH, P A	0306000072*	CONTRACT	SPITZBERG, D B	0306090175*	40-8084	STAROSTECKI, R	0306140625	50-199
SMITH, P A	0306000417*	CONTRACT	SPITZBERG, D B	0306090179*	40-8643	STAROSTECKI, R	0306140628	50-170
SMITH, P A	0306090277	CONTRACT	SPULAK, R G	0211220337*	50-245 P	STAROSTECKI, R	0306140630	50-134
SMITH, P A	0306090280*	CONTRACT	SQUIER, S	0306080194	50-322 H	STAROSTECKI, R	0306140635	50-223
SMITH, P A	0306090284*	CONTRACT	SRENIAWSKI, D	0306130265	1&F	STAROSTECKI, R	0306140651	50-54
SMITH, P A	0306170466*	CONTRACT	SRENIAWSKI, D	0306230246	1&F	STAROSTECKI, R	0306140657	50-293
SMITH, P A	0306200174*	CONTRACT	STACK, D	0211220337*	50-245 P	STAROSTECKI, R	0306140663*	50-412
SMITH, P A	0306200289*	CONTRACT	STARPLETON, D W	0306100097*	50-155 G	STAROSTECKI, R	0306140665	50-333
SMITH, P A	0306210376	CONTRACT	STARPLETON, D W	0306210075*	50-263 G	STAROSTECKI, R	0306140673	50-423
SMITH, P A	0306210384*	CONTRACT	STARKE, R M	0306070436	50-537 A	STAROSTECKI, R	0306140697	50-220
SMITH, P A	0306220130*	CONTRACT	STARKE, R M	0306070462	50-537 A	STAROSTECKI, R	0306140714	50-317
SMITH, P A	0306220280*	CONTRACT	STARKE, R M	0306290570	50-537 A	STAROSTECKI, R	0306140741	50-57
SMITH, P A	0306230497	50-320 P	STARKEY, R B	0306070161	50-261 G	STAROSTECKI, R	0306150005	50-289
SMITH, P A	0306230501*	50-320 P	STARKEY, R B	0306070182	50-261 S	STAROSTECKI, R	0306150237	50-332
SMITH, P A	0306280127	CONTRACT	STARKEY, R B	0306140405	50-261 R	STAROSTECKI, R	0306150349	50-412
SMITH, P A	0306280133*	CONTRACT	STARKEY, R B	0306160420	50-261 R	STAROSTECKI, R	0306160003	50-271
SMITH, R D	0306020305	40-0681	STARKEY, R B	0306200002	50-261 S	STAROSTECKI, R	0306160130	50-272
SMITH, R D	0306020331	40-0586	STARKEY, R B	0306200109	50-261 S	STAROSTECKI, R	0306160238	50-193
SMITH, R D	0306020333	40-0502	STARKEY, R B	0306200188	50-261 S	STAROSTECKI, R	0306160250	50-219
SMITH, R D	0306020503	40-1341	STARNER, R J	0306240406	WASTE MGT	STAROSTECKI, R	0306160361	50-244
SMITH, R D	0306020515	40-0585	STAROSTECKI, R	0306010121	50-307 G	STAROSTECKI, R	0306160483	50-277
SMITH, R D	0306170466	40-3453	STAROSTECKI, R	0306010310	50-317 G	STAROSTECKI, R	0306170226	50-247
SMITH, R H	0306010306*	50-213 G	STAROSTECKI, R	0306010365	50-247 G	STAROSTECKI, R	0306170235	50-293
SMITH, R H	0306200210*	50-213 G	STAROSTECKI, R	0306010442	50-443 G	STAROSTECKI, R	0306200158	50-293
SMITH, R D	0306090224	40-8452	STAROSTECKI, R	0306030282	50-309 G	STAROSTECKI, R	0306200174	50-271
SMITH, W G	0306020107	50-315 R	STAROSTECKI, R	0306030291	50-277 G	STAROSTECKI, R	0306200221	70-1143
SMITH, W G	0306030186	50-316 R	STAROSTECKI, R	0306030298	50-334 G	STAROSTECKI, R	0306200330	50-333
SMITH, W G	0306060183	50-315 S	STAROSTECKI, R	0306060160	50-245 G	STAROSTECKI, R	0306200343	50-77
SMITH, W G	0306060267	50-316 S	STAROSTECKI, R	0306060163	70-364	STAROSTECKI, R	0306200361	50-29
SMITH, W G	0306160343	50-315 R	STAROSTECKI, R	0306060200	50-334 G	STAROSTECKI, R	0306230075	50-271
SMITH, W G	0306160384	50-316 R	STAROSTECKI, R	0306060205	50-423 G	STAROSTECKI, R	0306230114	70-820
SMITH, W G	0306210030	50-315 S	STAROSTECKI, R	0306060210	50-322 G	STAROSTECKI, R	0306230195	50-244
SMITH, W G	0306210120	50-315 S	STAROSTECKI, R	0306060217	50-219 G	STAROSTECKI, R	0306230203	50-247
SMITH, W G	0306210257	50-315 S	STAROSTECKI, R	0306060223	50-220 G	STAROSTECKI, R	0306230317	50-244
SMITH, W G	0306270150	50-316 S	STAROSTECKI, R	0306060230	50-333 G	STAROSTECKI, R	0306230399	50-443
SMITH, W G	0306270161	50-316 S	STAROSTECKI, R	0306060257	50-309 G	STAROSTECKI, R	0306230415	50-412
SMITH, W G	0306270437	50-315 S	STAROSTECKI, R	0306060260	50-320 G	STAROSTECKI, R	0306280164	50-271
SMITH, W G	0306270444*	50-315 S	STAROSTECKI, R	0306060265	50-322 G	STAROSTECKI, R	0306280170	50-271
SMITH, W G	0306300035	50-315 G	STAROSTECKI, R	0306070046	50-286 G	STAROSTECKI, R	0306280347	50-77
SMITH, W P	0306080316*	50-148 P	STAROSTECKI, R	0306070223	50-277 G	STAROSTECKI, R	0306280492*	50-334
SNELL, W	0306130412*	50-254 G	STAROSTECKI, R	0306070344	50-271 G	STAROSTECKI, R	0306280586	50-354
SNOW, B A	0306020274	50-244 H	STAROSTECKI, R	0306090067	50-322 G	STECKEL, A	0306080250	FOIA
SNOW, B A	0306160485	50-244 H	STAROSTECKI, R	0306090140	50-332 G	STEED, L S	0306030021	50-334
SNYDER, B J	0306030490	50-320 P	STAROSTECKI, R	0306090230	50-245 G	STEFANO, J J	0306080437	50-440
SNYDER, B J	0306130460	50-320 H	STAROSTECKI, R	0306090358	50-271 G	STEIN, M H	0306060005*	FOIA
SNYDER, B J	0306220161	50-320 P	STAROSTECKI, R	0306140017	50-307 V	STEIN, M H	0306060025*	FOIA
SNYDER, B J	0306280074	50-320 P	STAROSTECKI, R	0306140032	50-271 V	STELLO, V	0306060303	REVIEW OR
SNYDER, H L	0306060415	40-8584	STAROSTECKI, R	0306140044	50-412 V	STELLO, V	0306080207	REVIEW OR
SNYDER, H L	0306140687	40-8584	STAROSTECKI, R	0306140055	50-293 V	STELLO, V	0306130385	REVIEW OR
SOKOLSKI, H D	0306160148*	FOIA	STAROSTECKI, R	0306140062	50-334 V	STELLO, V	0306280370	REVIEW OR
SOMEVILLE, K G	0306210353	40-8783	STAROSTECKI, R	0306140074	50-322 V	STEPLE, P J	0306030256*	CONTRACT
SOONG, A	0306140046*	40-8794	STAROSTECKI, R	0306140090	50-193 V	STEPHENSON, T R	0306210038	50-315
SOONG, A L	0306030175	70-142	STAROSTECKI, R	0306140104	50-213 V	STEPHENSON, C J	0306010353	50-289
SOONG, A L	0306170435	70-820	STAROSTECKI, R	0306140147	50-333 G	STEPHENSON, C J	0306200127	50-289
SOUSA, H	0306300217	PR	STAROSTECKI, R	0306140148	50-354 V	STEPHENSON, C J	0306210254*	50-289
SOUTHERN, R L	0306160647	71-86	STAROSTECKI, R	0306140152	50-184 V	STEPHENSON, C J	0306210258*	50-289
SPAINMAN, H H	0306280133*	CONTRACT	STAROSTECKI, R	0306140158	50-333 G	STEPHENSON, C J	0306280365	50-289
SPANG, J R	0306280532	50-209 G	STAROSTECKI, R	0306140170	50-289 V	STERN, P	0306100191	50-309
SPECTOR, R	0306280035	FOIA	STAROSTECKI, R	0306140224	50-320 V	STERN, P	0306100193*	50-309
SPEER, H	0306160455	50-206 R	STAROSTECKI, R	0306140231	50-336 V	STERN, P	0306100204	50-309
SPICIS, T P	0112030545*	50-498 A	STAROSTECKI, R	0306140243	50-244 V	STERN, P	0306100205*	50-309
SPICIS, T P	0306010166	NUH G	STAROSTECKI, R	0306140248	50-77 G	STERNBERG, D M	0306020097	50-397
SPILL, W H	0306130336	State Prop	STAROSTECKI, R	0306140255	50-225 V	STERNBERG, D M	0306070005	50-328
SPILLMAN, H J	0306080293	40-2061	STAROSTECKI, R	0306140256	50-272 G	STERNBERG, D M	0306070015	50-344
SPILLMAN, H J	0306200042	40-2061	STAROSTECKI, R	0306140278	50-184 V	STERNBERG, D M	0306070057	50-312
SPENCER, D A	0306280017	50-373 G	STAROSTECKI, R	0306140291	50-286 V	STERNBERG, D M	0306070075	50-344
SPENCER, D A	0306210045	50-373 G	STAROSTECKI, R	0306140322	50-410 V	STERNBERG, D M	0306070252	50-328
SPENCER, M	0306080215	50-358 G	STAROSTECKI, R	0306140332	50-322 G	STERNBERG, D M	0306070254	50-508
SPENCER, M	0306080250	50-358 G	STAROSTECKI, R	0306140371	50-219 V	STERNBERG, D M	0306070364	50-312
SPENCER, W C	0306300036	50-404 A	STAROSTECKI, R	0306140378	50-247 V	STERNBERG, D M	0306100032*	50-312
SPESSARD, R L	0306060208	50-284 G	STAROSTECKI, R	0306140403	50-272 V	STERNBERG, D M	0306100036*	50-206
SPESSARD, R L	0306070137	50-483 G	STAROSTECKI, R	0306140441	50-410 G	STERNBERG, D M	0306100047*	50-312
SPESSARD, R L	0306070139	50-546 G	STAROSTECKI, R	0306140443	50-77 V	STERNBERG, D M	0306170216	50-308
SPESSARD, R L	0306070388	50-454 G	STAROSTECKI, R	0306140447	50-332 V	STERNBERG, D M	0306170425	50-308
SPESSARD, R L	0306160391	50-373 G	STAROSTECKI, R	0306140453	50-245 V	STERNBERG, D M	0306210240	50-397
SPESSARD, R L	0306210187	50-403 G	STAROSTECKI, R	0306140467	50-5 V	STERNBERG, D M	0306280209	50-397
SPESSARD, R L	0306220014	50-341 G	STAROSTECKI, R	0306140494	50-322 G	STERNBERG, D M	0306280210	50-312
SPESSARD, R L	0306230285	50-454 G	STAROSTECKI, R	0306140510	50-443 V	STERNBERG, D M	0306280333	50-344
SPESSARD, R L	0306230290*	50-454 G	STAROSTECKI, R	0306140523	50-29 V	STERNBERG, D M	0306280334	50-397
SPESSARD, R L	0306270112	50-440 G	STAROSTECKI, R	0306140531	50-28 V	STERNBERG, D M	0306280371	50-397
SPICELLES, P R	0306160327	40-8677	STAROSTECKI, R	0306140536	50-277 V	STERNBERG, D M	0306280405	50-508
SPICELLES, P R	0306160567	40-8380	STAROSTECKI, R	0306140551	50-87 V	STERNBERG, D M	0306280450	50-528
SPINDOSA, E	0306230084*	FOIA	STAROSTECKI, R	0306140553	50-87 V	STERNBERG, D M	0306280515	50-528
SPINDOSA, I	0306230085*	FOIA	STAROSTECKI, R	0306140554	50-410 G	STERNBERG, D M	0306280516	50-397

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
BIERNBERG, D. H.	8306300007	50-312 Q	STOLZ, J. F.	8306220318	50-289 P	TAYLOR, J. H.	8306210295	TOPREP
STETKA, T. F.	8306140469*	50-302 Q	STOLZ, J. F.	8306220469	50-313 P	TAYLOR, J. H.	8306220007	50-387 S
STEVENS, D. L.	8306020134	NUREQ	STOLZ, J. F.	8306220476	50-278 P	TAYLOR, J. H.	8306220337	TOPREP
STEVENS, J. L.	8306020425	50-309 S	STOLZ, J. F.	8306220036	50-289 P	TAYLOR, J. H.	8306300157	50-438 S
STEVENS, J. L.	8306030341	50-309 S	STOLZ, J. F.	8306220103	50-277 P	TAYLOR, J. H.	8306300220	50-269 S
STEVENSON, M. G.	8306020173	NUREQ	STOLZ, J. F.	8306220156	50-277 P	TAYLOR, J. J.	8306170333	NUREQ
STEVENSON, R. L.	8306140394	XPDRYLIC	STRAUBE, M.	8306220042	50-289 G	TAYLOR, J. M.	8305110450	50-3 Q
STEWART, E. C.	8306240207*	0A999	STREET, J. J.	8306070155	50-346 G	TAYLOR, J. M.	8306240059	50-478 A
STEWART, J. P.	8306220511*	50-361 Q	STREET, J. J.	8306100162	50-483 G	TAYLOR, J. M.	8306270295	50-309 S
STEWART, P.	8306220561*	50-361 Q	STREET, J. J.	8306100172	50-373 G	TAYLOR, P. A.	8306140171*	50-389 Q
STEWART, W. L.	8306020072	50-338 R	STREET, J. J.	8306100174*	50-373 G	TAYLOR, P. A.	8306270404*	50-417 Q
STEWART, W. L.	8306020159	50-280 R	STREET, J. F.	8306100244	50-454 G	TEDESCO, R. L.	8304070019*	50-508 A
STEWART, W. L.	8306020424	PR	STREET, J. F.	8306100245	50-373 G	TELFORD, C. F.	8306210432*	CONTRACT
STEWART, W. L.	8306070148	50-339 S	STREET, J. F.	8306100247*	50-454 G	TEKIN, J. V.	8306080256	FOIA
STEWART, W. L.	8306080225	50-339 P	STREET, J. F.	8306130258	50-315 Q	TEMPLE, G.	8306220507*	50-397 Q
STEWART, W. L.	8306100170	50-280 P	STREET, J. F.	8306130263*	50-315 Q	TEMPLE, G. H.	8306070337*	50-204 Q
STEWART, W. L.	8306140208	50-338 P	STREET, J. F.	8306220274	50-266 Q	TERC, N. H.	8306020387*	50-266 Q
STEWART, W. L.	8306160247	50-338 P	STREET, J. F.	8306220418	50-374 Q	TERMIN, A.	8306270501	50-322 H
STEWART, W. L.	8306160375	50-280 R	STREET, J. F.	8306300060	50-346 Q	TERRELL, C. W.	8306220569	50-112 P
STEWART, W. L.	8306160399	50-338 F	STREUTKER, G. H.	8306070453	71-9102	TETZLAFF, A. I.	8306160367*	50-315 H
STEWART, W. L.	8306160405	50-338 P	STROHM, W. E.	8306010266	NUREQ	TETZLAFF, A. I.	8306160384	50-316 H
STEWART, W. L.	8306170130	50-281 Q	STRONG, A. D.	8306010266	NUREQ	THADANI, M.	8306080066	50-460 A
STEWART, W. L.	8306170281	50-280 P	STRUCKMAYER, R.	8306220048*	50-293 Q	THEENAN, D. A.	8306030094*	CONTRACT
STEWART, W. L.	8306170327	50-280 P	STUCKY, G. H.	8306060307	70-25	THIES, A. C.	8306150177	50-369 P
STEWART, W. L.	8306200219	50-280 Q	STUNKEL, C. B.	8306010081	NUREQ	THOM, T.	8306160482	50-259 H
STEWART, W. L.	8306220033	50-280 P	STURKEY, J. J.	8306220351*	50-331 P	THOMAS, C. D.	8306020612	50-128 P
STEWART, W. L.	8306270214	50-338 P	SUDIN, R.	8306200274	40-8380	THOMAS, C. D.	8306020616	50-248 P
STEWART, W. L.	8306290331	50-280 Q	SUERHANN, J. J.	8306200185	50-269 P	THOMAS, C. D.	8306020700	50-197 P
STEWART, W. L.	8306290387*	50-338 Q	SUGARMAN, R. J.	8306220051	50-352 G	THOMAS, C. D.	8306070466	MISC
STEWART, W. L.	8306290387*	71-5450	SUGARMAN, R. J.	8306220051	50-352 G	THOMAS, C. D.	8306070466*	MISC
STEWART, W. L.	8306300094	50-338 P	SUGARMAN, R. J.	8306220103	50-352 G	THOMAS, C. D.	8306090457	TOPREP
STEWART, W. L.	8306300149	50-280 K	SULLIVAN, J. M.	8306270230*	50-324 P	THOMAS, C. D.	8306140282	MIX
STEWART, W. L.	8306300240	50-338 P	SULLIVAN, P. J.	8306140671	NUREQ	THOMAS, C. D.	8306150121	TOPREP
STICKLEY, T. H.	8306030080*	50-397 A	SUMMERS, R. J.	8306230334	50-311 G	THOMAS, C. D.	8306200067	50-456 A
STIEDE, W. L.	8306240252	50-374 A	SUMMERS, R. J.	8306160144*	50-272 G	THOMAS, C. D.	8306200070	50-470 P
STIEDE, W. L.	8306300032	50-374 A	SUMNER, L.	8306150141*	50-321 F	THOMAS, C. D.	8306200154*	50-177 P
STIMKROTH, T. J.	8306270288	50-322 H	SUNDHL, J. A.	8306200036	40-8714	THOMAS, C. D.	8306210328	50-166 P
STOETZEL, G. A.	8306020053	NUREQ	SUNDIN, R. E.	8306200160	40-8697	THOMAS, C. D.	8306210333	50-294 P
STOHR, J.	8306220433	70-1151	SURNER, J. J.	8306130303	50-410 F	THOMAS, C. D.	8306220216	50-121 P
STOHR, J. P.	8306060114	70-1151	SUTHI, R. N.	8306130273*	50-315 G	THOMAS, C. D.	8306220220	50-42 P
STOHR, J. P.	8306060124*	70-1151	SUTTON, J. W.	8306270454*	0A999	THOMAS, C. D.	8306220240	50-89 P
STOHR, J. P.	8306140107	TOPREP	SVENSSON, B. A.	8306020186	50-316 R	THOMAS, C. D.	8306220296	50-224 P
STOHR, J. P.	8306140317	70-1113	SWAN, W.	8306140434*	50-390 G	THOMAS, C. D.	8306270007	50-14 P
STOHR, J. P.	8306140342*	70-1113	SWAN, W.	8306140508*	50-390 G	THOMAS, C. D.	8306270250	50-116 P
STOHR, J. P.	8306140527	70-1201	SWANSON, C. A.	8306020233	40-8610	THOMAS, C. D.	8306270403	50-192 P
STOHR, J. P.	8306140568	70-1113	SWANSON, C. A.	8306020243*	40-8610	THOMAS, D. C.	8306020437	50-454 Q
STOHR, J. P.	8306140576	70-1113	SWARTZ, E. D.	8306030225	50-454 G	THOMAS, D. C.	8306150400	50-454 Q
STOHR, J. P.	8306140607	70-624	SWARTZ, E. D.	8306030227	50-454 G	THOMAS, D. C.	8306150400	50-454 Q
STOHR, J. P.	8306140700	70-143	SWARTZ, E. D.	8306100246	50-454 G	THOMAS, D. C.	8306200020	50-454 Q
STOHR, J. P.	8306150264	70-143	SWARTZ, E. D.	8306170045	50-454 G	THOMAS, D. C.	8306200320	50-454 Q
STOLBA, F. B.	8306100203	50-528 S	SWARTZ, E. D.	8306230294	50-456 A	THOMAS, D. C.	8306200327*	50-454 Q
STOLZ, J.	8306060080*	50-287 P	SWARTZ, E. D.	8306280502	50-373 P	THOMAS, D. C.	8306200331*	50-454 Q
STOLZ, J. F.	8306010056	50-366 P	SWARTZ, L. L.	8306170394	50-322 Q	THOMAS, D. C.	8306200327*	50-454 Q
STOLZ, J. F.	8306020103	50-269 P	SWARTZ, L. L.	8306170394	50-322 Q	THOMAS, D. C.	8306200327*	50-454 Q
STOLZ, J. F.	8306020188	50-302 P	SWARTZ, L. L.	8306220088	50-322 G	THOMAS, D. C.	8306200331*	50-454 Q
STOLZ, J. F.	8306020317	50-312 P	SWARTZ, L. L.	8306270280	50-322 Q	THOMAS, D. C.	8306200331*	50-454 Q
STOLZ, J. F.	8306020325	50-277 Q	SWARTZ, L. L.	8306270280	50-322 Q	THOMAS, D. C.	8306200331*	50-454 Q
STOLZ, J. F.	8306020343	50-302 P	SWARTZ, L. L.	8306270505	50-322 Q	THOMAS, D. C.	8306200331*	50-454 Q
STOLZ, J. F.	8306030073	50-313 F	SWARTZMAN, G. I.	8306140691	NUREQ	THOMAS, D. C.	8306200215	50-454 Q
STOLZ, J. F.	8306030096	50-277 F	SWYLER, K. J.	8306010088	NUREQ	THOMAS, D. C.	8306300215	50-454 Q
STOLZ, J. F.	8306030110	50-277 P	SWYLER, K. J.	8306020066	NUREQ	THOMAS, D. H.	8306210342	FOIA
STOLZ, J. F.	8306030127	50-321 P	SWYLER, K. J.	8306060395*	CONTRACT	THOMAS, H. J.	8306170205*	RES
STOLZ, J. F.	8306030132	50-302 P	TAFT, E. P.	8306070427	50-317 P	THOMAS, J.	8306060220*	50-219 Q
STOLZ, J. F.	8306030239	50-366 P	TAFT, E. P.	8306080290*	50-410 A	THOMAS, J.	8306140362*	50-390 Q
STOLZ, J. F.	8306030253	50-302 P	TAFT, E. P.	8306080303*	50-410 A	THOMAS, M.	8306270311*	50-390 Q
STOLZ, J. F.	8306080234	50-346 P	TAFT, E. P.	8306080306*	50-410 A	THOMAS, M.	8306270311*	50-369 Q
STOLZ, J. F.	8306080375	50-287 P	TAFT, E. P.	8306080320*	50-410 A	THOMAS, M.	8306280458*	70-113
STOLZ, J. F.	8306080402	50-269 Q	TAFT, E. P.	8306080343*	50-410 A	THOMAS, W. V.	8306100075	50-263 Q
STOLZ, J. F.	8306090393	50-312 P	TAFT, E. P.	8306080351*	50-410 A	THOMAS, W. V.	8306240373	NUREQ
STOLZ, J. F.	8306140703	50-346 P	TAFT, E. P.	8306080360*	50-410 A	THOMAS, W. V.	8306130337	50-290 S
STOLZ, J. F.	8306140751	50-312 P	TAM, P. B.	8306090190	50-334 P	THOMAS, P. V.	8306160477	50-290 R
STOLZ, J. F.	8306150286*	50-302 P	TANG, HEE, D.	8306060282	50-237 S	THOMAS, P. V.	8306160488	50-290 R
STOLZ, J. F.	8306150297	50-289 P	TANG, R. C.	8306240109*	FOIA	THOMAS, P. V.	8306160494	50-298 Q
STOLZ, J. F.	8306150324	50-289 Q	TAUBER, H.	8306030171	50-341 A	THOMAS, P. V.	8306270163	50-298 S
STOLZ, J. F.	8306150484*	50-366 P	TAUBER, H.	8306160357	50-341 A	THOMAS, P. V.	8306270163	NUREQ
STOLZ, J. F.	8306150499	50-313 P	TAUBER, H.	8306280430	50-341 A	THOMAS, P. V.	8306270163	NUREQ
STOLZ, J. F.	8306150504	50-287 P	TAUBER, H.	8306280585	50-341 A	THOMAS, P. V.	8306240057*	CONTRACT
STOLZ, J. F.	8306150508	50-346 P	TAYLOR, D. C.	8306090165	50-302 S	THOMAS, P. V.	8306060030*	FOIA
STOLZ, J. F.	8306150519	50-313 P	TAYLOR, D. J.	8306020142	50-375 R	THOMAS, P. V.	8306270546	50-142 Q
STOLZ, J. F.	8306150621	50-302 P	TAYLOR, D. J.	8306160570	50-375 R	THOMAS, P. V.	8306270546	50-142 Q
STOLZ, J. F.	8306170471	50-277 P	TAYLOR, J. H.	8306070280*	50-269 P	THOMAS, P. V.	8306060266*	50-320 Q
STOLZ, J. F.	8306200059	50-313 P	TAYLOR, J. H.	8306070280*	50-269 P	THOMAS, P. V.	8306150008*	50-287 Q
STOLZ, J. F.	8306220219	50-321 P	TAYLOR, J. H.	8306100090	50-312 S	THORNBERY, R. C.	8306020214	50-275 R
STOLZ, J. F.	8306220224	50-289 P	TAYLOR, J. H.	8306140377	50-269 P	THORNBERY, R. C.	8306140535	50-275 R
STOLZ, J. F.	8306220275	50-269 P	TAYLOR, J. H.	8306170192	RES	THORNBERY, R. C.	8306070277*	50-298 Q

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
THORNTON, P	8306220105	50-155 0	TRAMM, T R	8306230257	50-454 F	TUCKER, H B	8306240183	50-413
THORNTON, P	8306220105	50-155 0	TRAMM, T R	8306230385	50-454 F	TUCKER, H B	8306270094	50-369
THORPE, D	8306270371	50-296 0	TRAMM, T R	8306230412	50-454 F	TUCKER, H B	8306270118	50-413
THORSEN, E O	8306200098	50-247 H	TRAMM, T R	8306270322	50-454 A	TUCKER, H B	8306270124	50-369
THULL, T S	8306010434	50-245 B	TRAMM, T R	8306270373	50-454 A	TUCKER, H B	8306270189	50-369
THULL, T S	8306030319	50-245 B	TRAMM, T R	8306270431	50-454 E	TUCKER, H B	8306270227	50-369
THULL, T S	8306030326	50-245 B	TRAPP, D	8306140210	PROJ	TUCKER, H B	8306270301	50-369
THULL, T S	8306170046	50-245 C	TRAPP, D	8306240370	PROJ	TUCKER, H B	8306270384	50-413
THULL, T S	8306270129	50-245 B	TRAVIS, W H	8306200033	71-5595	TUCKER, H B	8306280427	50-369
THURMOND, P	8306240349	FOIA	TRAVIS, W H	8306240044	71-5595	TUCKER, H B	8306290245	50-269
TIETZ, G	8306130329	50-254 G	TREAT, R L	8306140402	NUREQ	TUCKER, H B	8306290282	50-369
TIFFANY, J A	8306200215	50-344 I	TREBY, S A	8306080210	50-445 C	TUCKER, H B	8306300002	50-369
TILLMAN, A	8306170307	50-269 Q	TREBY, S A	8306080230	50-445 C	TUCKER, H B	8306300015	50-287
TIMO, D P	8306290220	50-440 Q	TREBY, S A	8306100118	50-445 C	TUCKER, H B	8306300114	50-370
TIMO, D P	8306290220	50-440 Q	TREBY, S A	8306150390	50-445 C	TUCKER, H B	8306300171	50-370
TINOLE, A	8306280044	NUREQ	TREBY, S A	8306300056	50-445 C	TUCKER, H B	8306300174	50-287
TIPPS, S B	8306070080	50-321 B	TRENER, B E	8306290131	NUREQ	TUCKER, H B	8306300189	50-370
TIPPS, S B	8306070257	50-366 B	TRIMBLE, D C	8306010324	50-317 Q	TUCKER, H B	8306300191	50-369
TIPPS, S B	8306070347	50-321 B	TRIPP, L E	8306060021	50-354 Q	TUCKER, H B	8306300232	50-370
TIPPS, S B	8306130264	50-366 B	TRIPP, L E	8306060214	50-334 Q	TUCKER, H K	8306160642	WABTE I
TIPPS, S B	8306200004	50-366 B	TRIPP, L E	8306070226	50-277 Q	TUCKER, M K	8306210307	40-134
TIPPS, S B	8306200202	50-321 B	TRIPP, L E	8306160054	50-277 Q	TUCKER, M K	8306210428	40-134
TIPPS, S B	8306200205	50-366 B	TRIPP, L E	8306160144	50-272 Q	UTITE, P T	8306030476	WABTE I
TIPPS, S B	8306200261	50-321 B	TRIPP, L C	8306230424	50-412 Q	TULODIESKI, D	8306270069	50-329
TIPPS, S B	8306200374	50-321 B	TROBOSKEL, W H	8306060214	50-334 Q	TURK, E J	8306290240	50-440
TIPPS, S B	8306270328	50-366 B	TROSTEN, L H	8306240158	FOIA	TURK, S E	8306070037	50-337
TIPPS, S B	8306280361	50-321 B	TROTT, E	8306220282	CONTRACT	TURK, S E	8306100043	50-337
TIPPS, S B	8306290460	50-366 B	TRUITT, M O	8306200273	FOIA	TURK, S E	8306150311	50-337
TISCHLER, L F	8306220227	CONTRACT	TSAT, Y J	8306080294	50-410 A	TURK, S E	8306150315	50-337
TKACHYK, J W	8306270157	NUREQ	TSAT, Y J	8306080338	50-410 A	TURK, S E	8306150317	50-337
TOBIAS, M L	8306270146	NUREQ	TUCKER, H B	8306010015	50-370 B	TURKETT, J	8306010357	50-395
TOBIN, W	8306070061	50-250 Q	TUCKER, H B	8306010098	50-369 B	TURKETT, J	8306010374	50-395
TOBIN, W J	8306170162	50-369 Q	TUCKER, H B	8306010104	50-370 B	TURNER, D	8306200097	50-346
TODD, J T	8306010068	50-387 B	TUCKER, H B	8306010123	50-369 B	TURNQUEST, L	8306130348	50-237
TODD, J T	8306010099	50-387 B	TUCKER, H B	8306010236	50-369 B	UDALL, M K	8306220268	50-289
TOLSON, R G	8306080241	50-445 Q	TUCKER, H B	8306010401	50-369 B	UDERITZ, R A	8306030141	50-272
TOMAN, G J	8306220381	50-336 P	TUCKER, H B	8306020638	70-2985	UDERITZ, R A	8306030349	50-272
TOMECEK, M	8306230091	FOIA	TUCKER, H B	8306030122	50-269 P	UDERITZ, R A	8306070177	50-272
TOMECEK, P	8306230094	FOIA	TUCKER, H B	8306030300	50-413 A	UDERITZ, R A	8306140261	50-272
TOMLINSON, D P	8306060122	50-498 Q	TUCKER, H B	8306030315	50-369 P	UDERITZ, R A	8306160448	50-272
TOMPKINS, B A	8306180357	50-443 Q	TUCKER, H B	8306060076	50-269 P	UEBBING, R	8306210262	50-346
TOMPKINS, B A	8306220032	50-289 Q	TUCKER, H B	8306070031	50-269 P	UHRIG, R E	8306030074	50-369
TOMPKINS, B A	8306220097	50-443 Q	TUCKER, H B	8306070131	50-369 P	UHRIG, R E	8306060082	50-369
TOMPKINS, B A	8306220099	50-443 Q	TUCKER, H B	8306070143	50-369 S	UHRIG, R E	8306080004	50-250
TONER, K A	8306010281	50-155 P	TUCKER, H B	8306070206	50-413 E	UHRIG, R E	8306090352	50-250
TONER, K A	8306030362	50-255 P	TUCKER, H B	8306070268	50-369 P	UHRIG, R E	8306100087	50-335
TONER, K A	8306060119	50-155 P	TUCKER, H B	8306070269	50-369 P	UHRIG, R E	8306100140	50-369
TONER, K A	8306060145	50-255 P	TUCKER, H B	8306070272	50-269 P	UHRIG, R E	8306130156	50-369
TONER, K A	8306080045	50-155 P	TUCKER, H B	8306070283	50-369 P	UHRIG, R E	8306130268	50-369
TONER, K A	8306100055	50-155 F	TUCKER, H B	8306070314	50-413 E	UHRIG, R E	8306130291	50-369
TONER, K A	8306100222	50-155 P	TUCKER, H B	8306070349	50-413 F	UHRIG, R E	8306130435	50-250
TONER, K A	8306130051	50-155 P	TUCKER, H B	8306090015	50-370 B	UHRIG, R E	8306140009	50-369
TONER, K A	8306130334	50-250 P	TUCKER, H B	8306090040	50-370 B	UHRIG, R E	8306140011	50-369
TONER, K A	8306200230	50-155 P	TUCKER, H B	8306090147	50-369 B	UHRIG, R E	8306140097	50-369
TONER, K A	8306200367	50-155 P	TUCKER, H B	8306090361	50-269 F	UHRIG, R E	8306140111	50-369
TONER, K A	8306220020	50-255 P	TUCKER, H B	8306100138	50-370 B	UHRIG, R E	8306140510	50-369
TONER, K A	8306220270	50-155 P	TUCKER, H B	8306100164	50-370 B	UHRIG, R E	8306140572	50-335
TONER, K A	8306240139	50-155 P	TUCKER, H B	8306100185	50-370 B	UHRIG, R E	8306140581	50-369
TONER, K A	8306270076	50-155 P	TUCKER, H B	8306100216	50-370 B	UHRIG, R E	8306140638	50-369
TONER, K A	8306270107	50-155 P	TUCKER, H B	8306100243	50-370 B	UHRIG, R E	8306140745	50-335
TONER, K A	8306270391	50-155 P	TUCKER, H B	8306130312	50-370 B	UHRIG, R E	8306160335	50-250
TONER, K A	8306290412	50-155 P	TUCKER, H B	8306130314	50-370 B	UHRIG, R E	8306170319	50-335
TONQUE, T	8306270277	50-237 S	TUCKER, H B	8306130342	50-369 B	UHRIG, R E	8306200146	50-369
TOOLE, R	8306150030	50-289 F	TUCKER, H B	8306130448	50-369 B	UHRIG, R E	8306200194	50-369
TOOLE, R J	8306210040	50-289 S	TUCKER, H B	8306140018	50-413 E	UHRIG, R E	8306200310	50-369
TOBACANI, K	8306090350	50-247 T	TUCKER, H B	8306140119	50-413 Q	UHRIG, R E	8306210071	50-250
TOTH, A D	8306280341	50-377 Q	TUCKER, H B	8306140123	50-413 Q	UHRIG, R E	8306210160	50-369
TOURIGNY, E O	8306160691	50-285 P	TUCKER, H B	8306140129	50-413 Q	UHRIG, R E	8306210261	50-369
TOURIGNY, E O	8306280073	50-285 P	TUCKER, H B	8306140502	50-413 Q	UHRIG, R E	8306280250	50-335
TOURTELLOTTE, J	8306160680	REVIEW GRP	TUCKER, H B	8306140580	50-370 P	UHRIG, R E	8306280356	50-335
TOUBLEY, D R	8306240003	FOIA	TUCKER, H B	8306140738	50-269 P	UHRIG, R E	8306290338	50-335
TOWNLEY, E L	8306210074	50-316 B	TUCKER, H B	8306170297	50-269 P	UHRIG, R E	8306290345	50-250
TOWNLEY, E L	8306210325	50-316 S	TUCKER, H B	8306170311	50-369 E	UHRIG, R E	8306290351	50-335
TOWNSEND, B L	8306230041	CONTRACT	TUCKER, H B	8306170316	50-413 E	UHRIG, R E	8306290398	50-250
TOWNSEND, B L	8306290268	CONTRACT	TUCKER, H B	8306200212	50-369 S	ULIE, J M	8306300067	50-341
TOY, H L	8306230137	70-8	TUCKER, H B	8306200237	50-369 S	UNKLE, T J	8306210108	50-317
TRAINOR, A F	8306270002	50-373 B	TUCKER, H B	8306200238	50-370 S	UPPULUR, V. R.	8306010086	NUREQ
TRAMM, T R	8306030272	50-454 K	TUCKER, H B	8306200245	50-369 S	UPRIGHT, C M	8306140172	50-438
TRAMM, T R	8306090221	50-454 F	TUCKER, H B	8306200264	50-369 S	UPRIGHT, C M	8306140471	50-395
TRAMM, T R	8306100178	50-454 B	TUCKER, H B	8306200321	50-370 B	UPRIGHT, C M	8306140512	50-400
TRAMM, T R	8306100207	50-454 B	TUCKER, H B	8306200352	50-369 P	UPRIGHT, C M	8306290233	50-537
TRAMM, T R	8306100234	50-454 K	TUCKER, H B	8306210092	50-287 S	UTLEY, E E	8306010311	50-324
TRAMM, T R	8306210211	50-454 E	TUCKER, H B	8306210190	50-413 F	UTLEY, E E	8306060112	50-400
TRAMM, T R	8306220001	50-454 A	TUCKER, H B	8306220295	50-413 E	UTLEY, E E	8306140708	50-261
TRAMM, T R	8306230237	50-454 A	TUCKER, H B	8306240123	50-413 E			

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
UTLEY, E E	8306290553*	50-261 Q	VASSALLO, D B	8306020290*	50-324 Q	VOIGT, H H	8306280527	50-289 Q
VAETH, M	8306240078	50-389 S	VASSALLO, D B	8306020568	50-298 Q	VOIGT, H H	8306280530*	50-289 Q
VALDES, S A	8306010009	50-389 S	VASSALLO, D B	8306020587*	50-298 Q	VOLGENAU, F	8306060035*	FOIA
VALDES, S A	8306010252	50-389 S	VASSALLO, D B	8306020699	50-325 P	VORDERBRUEGGEN	8306070253*	50-528 Q
VALDES, S A	8306200094	50-389 S	VASSALLO, D B	8306030032	50-333 P	VORDERBRUEGGEN	8306070256*	50-528 Q
VAN BRUNT, E E	8306010055	50-528 S	VASSALLO, D B	8306030119	50-293 Q	VOSBURY, F	8306090388*	50-298 P
VAN BRUNT, E E	8306010072	50-528 S	VASSALLO, D B	8306030134*	50-293 Q	VOSBURY, F W	8306200714*	50-305 P
VAN BRUNT, E F	8306010076	50-528 S	VASSALLO, D B	8306090386*	50-298 P	VOSBURY, F W	8306230021*	50-282 P
VAN BRUNT, E E	8306010119	50-528 S	VASSALLO, D B	8306090430	50-220 P	VOSBURY, F W	8306020196*	50-302 P
VAN BRUNT, E E	8306010137	50-528 S	VASSALLO, D B	8306130481	50-333 Q	VOSBURY, F W	8306030070*	50-338 P
VAN BRUNT, E E	8306010272	50-528 S	VASSALLO, D B	8306130495	50-271 P	VOSBURY, F W	8306030299*	50-315 P
VAN BRUNT, E E	8306010289	50-528 S	VASSALLO, D B	8306130224	50-133 F	VOSBURY, F W	8306030446*	50-280 P
VAN BRUNT, E E	8306010341	50-529 S	VASSALLO, D B	8306130260	50-259 P	VOSBURY, F W	8306090397*	50-312 P
VAN BRUNT, E E	8306010375	50-528 S	VASSALLO, D B	8306130464	50-324 P	VOTH, M H	8306030064	70-687
VAN BRUNT, E E	8306030337	50-528 F	VASSALLO, D B	8306130466	50-263 P	WADE, L	8306170152*	FOIA
VAN BRUNT, E E	8306070078	50-528 S	VASSALLO, D B	8306150576	50-253 P	WAGNER, G H	8306230090*	FOIA
VAN BRUNT, E E	8306070091	50-528 A	VASSALLO, D B	8306150629	50-269 Q	WAGNER, G P	8306130454	50-10 R
VAN BRUNT, E E	8306070104	50-529 S	VASSALLO, D B	8306150626	50-220 F	WAGNER, G P	8306130457*	50-10 R
VAN BRUNT, E E	8306070178	50-528 S	VASSALLO, D B	8306150631	50-220 P	WAGNER, H E	8306020412	50-460 Q
VAN BRUNT, E E	8306070221	50-528 S	VASSALLO, D B	8306220196	50-293 P	WAGNER, M E	8306150245	50-289 Q
VAN BRUNT, E E	8306070225	50-528 S	VASSALLO, D B	8306060410	NUREG	WAGNER, M E	8306160008	50-289 Q
VAN BRUNT, E E	8306090275*	50-528 F	VASSALLO, D B	8306140122	70-1113	WAGNER, M E	8306170411	50-460 Q
VAN BRUNT, E E	8306130432	50-528 E	VASSALLO, D B	8306140328*	70-1113	WAGNER, M E	8306240286	50-460 Q
VAN BRUNT, E E	8306160500	50-528 E	VASSALLO, D B	8306300165	PR	WAGNER, M C	8306290550	50-289 Q
VAN BRUNT, E E	8306170180	50-528 S	VASSALLO, D B	8306060241*	50-445 Q	WAGNER, R M	8306230105*	FOIA
VAN BRUNT, E E	8306170240	50-528 S	VASSALLO, D B	8306010275	50-293 S	WAGNER, W J	8306070065*	50-312 Q
VAN BRUNT, E E	8306170244	50-528 S	VASSALLO, D B	8306010386	50-293 S	WAGNER, W J	8306280339*	50-344 Q
VAN BRUNT, E E	8306170265	50-528 A	VASSALLO, D B	8306020486	50-293 S	WALKER, R D	8306060251*	50-263 Q
VAN BRUNT, E E	8306170302	50-528 A	VASSALLO, D B	8306010332	50-348 Q	WALKER, R D	8306270222*	50-373 Q
VAN BRUNT, E E	8306170326	50-528 E	VASSALLO, D B	8306140102	50-416 V	WALKER, R D	8306300141*	50-373 Q
VAN BRUNT, E E	8306170341	50-529 S	VASSALLO, D B	8306140114	50-438 Q	WALL, G F	8306270164	50-317 F
VAN BRUNT, E E	8306170342	50-528 B	VASSALLO, D B	8306140131*	50-438 Q	WALLACE, C G	8306010314	50-313 P
VAN BRUNT, E E	8306170351	50-528 A	VASSALLO, D B	8306140132	50-400 V	WALLACE, E G	8306010314	50-313 P
VAN BRUNT, E E	8306170366	50-528 S	VASSALLO, D B	8306140141	50-324 V	WALLACE, W T	8306270372	State Prop
VAN BRUNT, E E	8306170367	50-528 S	VASSALLO, D B	8306140143	50-438 Q	WALLER, N K	8306030105	71-6649
VAN BRUNT, E E	8306170393	50-528 S	VASSALLO, D B	8306140157*	50-438 Q	WALLING, G E	8306300153	50-389 S
VAN BRUNT, E E	8306200337	50-528 F	VASSALLO, D B	8306140235	50-416 Q	WALSKE, C	8306230328	PR
VAN BRUNT, E E	8306210287	50-528 S	VASSALLO, D B	8306140355	50-390 Q	WALSKE, C	8306270303	50-289 H
VAN BRUNT, E E	8306230245	50-528 S	VASSALLO, D B	8306140368	50-400 Q	WALTON, G A	8306230424*	50-412 Q
VAN BRUNT, E E	8306230270	50-528 S	VASSALLO, D B	8306140386	50-327 Q	WAMBACH, T	8306290323	50-255 P
VAN BRUNT, E E	8306230318	50-528 S	VASSALLO, D B	8306140396	50-324 Q	WAMBACH, T V	8306070062	50-255 P
VAN BRUNT, E E	8306230377	50-529 S	VASSALLO, D B	8306140413*	50-324 Q	WAMBACH, T V	8306070247	50-255 P
VAN BRUNT, E E	8306230408	50-528 S	VASSALLO, D B	8306140450	50-416 Q	WAMBACH, T V	8306160396	50-255 P
VAN BRUNT, E E	8306270143	50-528 A	VASSALLO, D B	8306140463*	50-416 Q	WAMBACH, T V	8306280439	50-255 P
VAN BRUNT, E E	8306270368	50-528 E	VASSALLO, D B	8306140473	50-348 Q	WANG, C H	8306070044	50-243 S
VAN BRUNT, E E	8306270447	50-528 F	VASSALLO, D B	8306140483	50-400 Q	WARD, E C	8306090257*	50-282 F
VAN BRUNT, E E	8306280317	50-528 E	VASSALLO, D B	8306140492*	50-395 Q	WARD, E C	8306230079*	50-282 F
VAN BRUNT, E E	8306280436	50-528 A	VASSALLO, D B	8306140535	50-327 Q	WARD, K D	8306030105*	50-403 Q
VAN VLIET, J	8306210361	50-289 P	VASSALLO, D B	8306140562	50-390 Q	WARD, K D	8306230271*	50-440 Q
VANDEL, T. E	8306230423*	50-374 Q	VASSALLO, D B	8306140626	50-259 V	WARD, K D	8306230440*	50-155 Q
VANDERBER, J J	8306240191	50-397 S	VASSALLO, D B	8306140645	50-348 Q	WARD, K D	8306300218*	50-358 Q
VANDEWALLE, D J	8306030223	50-155 P	VASSALLO, D B	8306140653	50-324 Q	WARD, T	8306220091*	CONTRACT
VANDEWALLE, D J	8306150409*	50-155 Q	VASSALLO, D B	8306140677	50-324 Q	WAREMBOURG, D	8306060130	50-267 P
VANDEWALLE, D J	8306170210	50-155 F	VASSALLO, D B	8306140685	50-259 Q	WAREMBOURG, D	8306060134	50-267 S
VANDEWALLE, D J	8306210102*	50-155 Q	VASSALLO, D B	8306140687	50-259 V	WAREMBOURG, D	8306160434	50-267 R
VANDEWALLE, D J	8306230010*	50-155 Q	VASSALLO, D B	8306140693*	50-324 Q	WAREMBOURG, D	8306280217	50-267 S
VANDEWALLE, D J	8306240285	50-155 F	VASSALLO, D B	8306140757	50-438 Q	WAREMBOURG, D	8306300098	50-267 S
VANDEWALD, P K	8306290305*	50-413 Q	VASSALLO, D B	8306140794	50-260 S	WAREMBOURG, D	8306300187	50-267 S
VARELA, A A	8306090131*	50-322 Q	VASSALLO, D B	8306210184	50-293 S	WAREMBOURG, D W	8306070199	50-267 Q
VARGA, S A	8306010065	50-305 P	VASSALLO, D B	8306230248	50-339 S	WAREMBOURG, D W	8306140733	50-267 P
VARGA, S A	8306020036	50-348 P	VASSALLO, D B	8306290231	50-438 Q	WAREMBOURG, D W	8306210253	50-267 Q
VARGA, S A	8306020562	50-272 P	VASSALLO, D B	8306290236	50-416 Q	WAREMBOURG, D W	8306210373*	50-267 F
VARGA, S A	8306020570	50-348 F	VASSALLO, D B	8306290237	50-438 Q	WAREMBOURG, D W	8306300059	50-267 F
VARGA, S A	8306020676	50-334 P	VASSALLO, D B	8306290308	50-390 Q	WARNICK, R F	8306060048	50-329 Q
VARGA, S A	8306030243	50-334 P	VASSALLO, D B	8306290309	50-438 Q	WARNICK, R F	8306060071	50-358 A
VARGA, S A	8306030247	50-334 P	VASSALLO, D B	8306290318*	50-390 Q	WARNICK, R F	8306070042*	50-358 Q
VARGA, S A	8306030290	50-315 P	VASSALLO, D B	8306290325*	50-438 Q	WARNICK, R F	8306090243	50-329 Q
VARGA, S A	8306030441	50-280 P	VASSALLO, D B	8306290365	50-416 Q	WARNICK, R F	8306090244*	50-329 Q
VARGA, S A	8306030508	50-295 P	VASSALLO, D B	8306290420	50-261 Q	WARNICK, R F	8306210123	50-358 S
VARGA, S A	8306080073	50-334 P	VASSALLO, D B	8306290420	50-390 Q	WARNICK, R F	8306230353	50-358 Q
VARGA, S A	8306090052	50-311 F	VASSALLO, D B	8306090299	50-247 F	WARNICK, R F	8306230357*	50-358 Q
VARGA, S A	8306150627	50-286 P	VASSALLO, D B	8306090317	50-247 F	WARNICK, R F	8306270150	50-329 A
VARGA, S A	8306150630*	50-286 P	VASSALLO, D B	8306300146	NUREG	WARNICK, R F	8306270374	50-358 A
VARGA, S A	8306150638*	50-286 P	VASSALLO, D B	8306090388*	50-298 P	WARNICK, R F	8306280208	50-358 A
VARGA, S A	8306170481	50-272 F	VASSALLO, D B	8306020037*	50-309 P	WARNICK, R F	8306280539	50-329 A
VARGA, S A	8306220243	50-286 F	VASSALLO, D B	8306030512*	50-295 P	WARNICK, R F	8306300101	50-329 A
VARGA, S A	8306230371	50-250 F	VASSALLO, D B	8306090397*	50-312 P	WATKINS, S L	8306210431	40-8084
VARGA, S A	8306240470	50-261 Q	VASSALLO, D B	8306020420	RC600	WATKINS, J R	8306060202*	50-295 Q
VARNADO, G. B.	8306240301*	50-247 Q	VASSALLO, D B	8306080214	50-361 Q	WATKINS, L B	8306220117	50-458 Q
VARNER, D H	8306210206	50-293 S	VASSALLO, D B	8306130366	50-352 Q	WAYNE, L	8306170379*	50-142 T
VASSALLO, D B	8306010179	50-254 Q	VASSALLO, D B	8306230127	50-445 H	WAYNE, L	8306170426*	50-142 T
VASSALLO, D B	8306020020	50-324 P	VASSALLO, D B	8306090488*	CONTRACT	WEBB, D	8306220272*	CONTRACT
VASSALLO, D B	8306020107	50-324 Q	VASSALLO, D B	8306290225*	50-389 Q	WEBB, D F	8306270410	50-358 Q
VASSALLO, D B	8306030180	50-259 P	VASSALLO, D B	8306070127*	50-321 I	WEBER, M F	8306140203	WASTE MGT
VASSALLO, D B	8306030205	50-331 P	VASSALLO, D B	8306280537	50-289 Q	WEEKS, E D	8306020309	50-133 R

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUB CAT
WEEKS, E. D.	8306160461	50-133 R	WESTERMAN, T. F.	8306160362*	50-298 Q	WILCOX, J. D.	8306290334*	50-4
WEGST, W. F.	8306280895	50-142 R	WESTERMAN, T. F.	8306210012*	50-298 Q	WILCOUS, W. S.	8306070300	50-3
WEINFURTER, E.	8306170314	50-294 R	WESTERMAN, T. F.	8306210129*	50-298 Q	WILCOUS, W. S.	8306140437	50-3
WEINKAM, E.	8306070205	50-410 A	WESTERMAN, T. F.	8306240148*	50-274 Q	WILLETT, D. J.	8306070083*	50-3
WEINKAM, E. J.	8306130462	50-458 A	WESTERMAN, T. F.	8306270237*	50-298 Q	WILLETT, D. J.	8306280380*	50-3
WEINKAM, E. J.	8306140417	50-458 A	WETHY, C. M.	8306140033*	50-335 F	WILLHOITE, B.	8306300128	NURC
WEINKAM, E. J.	8306220254	50-458 A	WETHY, C. M.	8306160662*	50-359 F	WILLIAMS, C. C.	8306030143*	50-2
WEINMAN, G.	8306140467	PR	WETHY, C. M.	8306170287	50-359 F	WILLIAMS, C. C.	8306030147*	50-4
WEIR, B. A.	8306010094	NURC	WETHY, C. M.	8306210388*	50-359 F	WILLIAMS, C. C.	8306030148*	50-5
WEIR, P. J.	8306020374	50-318 S	WETHY, C. M.	8306220230*	50-335 F	WILLIAMS, C. C.	8306030202*	50-5
WEIR, P. J.	8306020430	50-318 S	WETTERHANN, H. J.	8306070295	50-352 C	WILLIAMS, C. C.	8306070190*	50-2
WEIR, P. J.	8306020433	50-317 S	WETTERHANN, H. J.	8306070295	50-352 C	WILLIAMS, C. C.	8306100105*	50-2
WEIR, P. J.	8306020438	50-318 S	WETTERHANN, H. J.	8306070299*	50-352 C	WILLIAMS, C. C.	8306100266*	50-3
WEIR, P. J.	8306280172	50-318 S	WETTERHANN, H. J.	8306070299*	50-352 C	WILLIAMS, C. C.	8306130345*	50-4
WEIR, S. H.	8306020423	50-317 S	WETTERHANN, H. J.	8306070301*	50-352 C	WILLIAMS, C. C.	8306230355*	50-3
WEISS, D.	8306130493	70-1257	WETTERHANN, H. J.	8306070301*	50-352 C	WILLIAMS, C. C.	8306230420*	50-4
WEISS, C.	8306140297	50-289 Q	WETTERHANN, H. J.	8306080107*	ADVCM	WILLIAMS, C. C.	8306300292*	50-3
WEISS, E. R.	8306030007	50-320 Q	WETTERHANN, H. J.	8306090212	50-352 Q	WILLIAMS, C. C.	8306160667*	71-9
WEISS, E. R.	8306070410	50-289 Q	WETTERHANN, H. J.	8306090212	50-352 Q	WILLIAMS, J.	8306010151	50-3
WEISS, E. R.	8306130389	50-247 Q	WETTERHANN, H. J.	8306090240	50-352 Q	WILLIAMS, J.	8306060074*	50-3
WEISS, E. R.	8306130389	50-247 Q	WETTERHANN, H. J.	8306140740*	ADVCM	WILLIAMS, J.	8306060099	50-3
WEISS, E. R.	8306140604	50-289 Q	WETTERHANN, H. J.	8306150393	50-352 Q	WILLIAMS, J.	8306060197	50-3
WEISS, E. R.	8306140604	50-289 Q	WETTERHANN, H. J.	8306150393	50-352 Q	WILLIAMS, J.	8306060254	50-3
WEISS, E. R.	8306220146	50-337 Q	WETTERHANN, H. J.	8306160603	50-352 Q	WILLIAMS, J.	8306070135	50-3
WEISS, E. R.	8306220146	50-337 Q	WETTERHANN, H. J.	8306160603	50-352 Q	WILLIAMS, J.	8306070232	50-3
WEISS, E. R.	8306220153*	50-337 Q	WETTERHANN, H. J.	8306220031	50-358 Q	WILLIAMS, J.	8306070267	50-3
WEISS, E. R.	8306220153*	50-337 Q	WETTERHANN, H. J.	8306220031	50-358 Q	WILLIAMS, J.	8306070267	50-3
WEISS, E. R.	8306220153*	50-337 Q	WETTERHANN, H. J.	8306220036*	50-358 Q	WILLIAMS, J.	8306080137	50-3
WEISS, E. R.	8306230330	50-247 Q	WETTERHANN, H. J.	8306220036*	50-358 Q	WILLIAMS, J.	8306080213	50-3
WEISS, E. R.	8306230330	50-247 Q	WETTERHANN, H. J.	8306270122	50-410 Q	WILLIAMS, J.	8306090084	50-3
WEISS, E. R.	8306270139	50-247 Q	WETTERHANN, H. J.	8306270122	50-410 Q	WILLIAMS, J.	8306090127	50-3
WEISS, E. R.	8306300037	50-289 Q	WETTERHANN, H. J.	8306270122	50-392 Q	WILLIAMS, J.	8306130381	50-3
WELLS, D. A.	8306060187	50-341 S	WETTERHANN, H. J.	8306270143	50-392 Q	WILLIAMS, J.	8306170321	50-3
WELLS, D. A.	8306060245	50-341 S	WHALEN, R. J.	8306270083	50-249 S	WILLIAMS, J.	8306210054	50-3
WELLS, D. A.	8306070085*	50-341 Q	WHICHER, L.	8306240462	50-443 A	WILLIAMS, J.	8306210058	50-3
WELLS, D. A.	8306130292*	50-341 Q	WHICHER, J. M.	8306100201	50-454 Q	WILLIAMS, J.	8306210294	50-3
WELLS, D. A.	8306170233	50-341 S	WHICHER, J. M.	8306100201	50-454 Q	WILLIAMS, J.	8306230081	50-3
WELLS, D. A.	8306170419	50-341 S	WHICHER, J. M.	8306100201	50-454 Q	WILLIAMS, J.	8306230089	50-3
WELLS, D. A.	8306220024*	50-341 Q	WHICHER, J. M.	8306100201	50-454 Q	WILLIAMS, J.	8306230196	50-3
WELLS, D. A.	8306220030*	50-341 Q	WHICHER, J. M.	8306170371	50-454 Q	WILLIAMS, J.	8306230268	50-3
WELLS, R.	8306010329	50-320 S	WHICHER, J. M.	8306170371	50-454 Q	WILLIAMS, J.	8306230395	50-3
WELLS, R.	8306170025	50-320 S	WHICHER, J. M.	8306170371	50-454 Q	WILLIAMS, J.	8306230442	50-3
WENDERLICH, R. I.	8306020374	50-318 S	WHICHER, J. M.	8306170371	50-454 Q	WILLIAMS, J.	8306230472	50-3
WENDERLICH, R. I.	8306020430	50-318 S	WHICHER, J. M.	8306170384*	50-454 Q	WILLIAMS, J.	8306270180	50-3
WENDERLICH, R. I.	8306020467	50-317 S	WHICHER, J. M.	8306170389*	50-454 Q	WILLIAMS, J.	8306270331	50-3
WENDERLICH, R. L.	8306170072	50-318 S	WHICHER, J. M.	8306230370*	50-367 Q	WILLIAMS, J.	8306270332	50-3
WENDERLICH, R. I.	8306280447	50-317 S	WHITE, A. F.	8306160446	REGCD	WILLIAMS, J.	8306270378*	50-3
WENBLAWSKI, I.	8306070011*	50-344 Q	WHITE, A. F.	8306160575	50-410 Q	WILLIAMS, J.	8306280213*	50-3
WENBLAWSKI, I.	8306070287*	50-243 Q	WHITE, A. F.	8306160582*	50-410 Q	WILLIAMS, J.	8306280359*	50-3
WENBLAWSKI, I.	8306070337*	50-206 Q	WHITE, A. F.	8306160582*	50-410 Q	WILLIAMS, J.	8306300160	50-35
WENBLAWSKI, I.	8306090174	50-275 S	WHITE, J. R.	8306020416*	50-293 Q	WILLIAMS, J. G.	8306060142	50-28
WENBLAWSKI, I.	8306280310*	50-528 Q	WHITE, J. R.	8306020447*	50-219 Q	WILLIAMS, J. H.	8306030312*	50-27
WENBLAWSKI, I.	8306280507*	50-377 Q	WHITE, W.	8306230339	PR	WILLIAMS, J. H.	8306070224*	50-27
WENBLAWSKI, I. A.	8306070197*	50-312 Q	WHITEMAN, D. C.	8306280013	NURC	WILLIAMS, J. W.	8306010009	50-38
WENBLAWSKI, I. A.	8306070176*	50-312 Q	WHITENER, H. L.	8306140196*	50-335 Q	WILLIAMS, J. W.	8306010116	50-38
WENBLAWSKI, I. A.	8306280145*	50-528 Q	WHITENER, H. L.	8306140537*	50-349 Q	WILLIAMS, J. W.	8306010252	50-38
WENBLAWSKI, I. A.	8306280177*	50-57 Q	WHITNEY, O. Q.	8306280358	50-293 S	WILLIAMS, J. W.	8306020216	50-25
WENBLAWSKI, I. A.	8306280185*	50-57 Q	WHITNEY, O. Q.	8306010060	50-293 S	WILLIAMS, J. W.	8306070058	50-38
WENBLAWSKI, I. A.	8306280632*	50-244 Q	WHITNEY, O. Q.	8306010157	50-293 S	WILLIAMS, J. W.	8306070181	50-38
WERNER, T. A.	8306160210	NURC	WHITNEY, O. Q.	8306010293	50-293 S	WILLIAMS, J. W.	8306160638	50-25
WESCOTT, H. M.	8306210298*	50-341 Q	WHITNEY, O. Q.	8306020154	50-293 S	WILLIAMS, J. W.	8306200094	50-38
WCBT, D.	8306200180	50-309 S	WHITNEY, O. Q.	8306020419	50-293 S	WILLIAMS, J. W.	8306200180	50-38
WCBT, D.	8306300025	50-309 S	WHITNEY, O. Q.	8306280072	50-293 S	WILLIAMS, J. W.	8306210081	50-38
WCBT, D. K.	8306060370	FOIA	WHITNEY, J. W.	8306010077*	CONTRACT	WILLIAMS, J. W.	8306210197	50-25
WCBT, D. K.	8306080820	FOIA	WHITNEY, J. W.	8306290653*	CONTRACT	WILLIAMS, J. W.	8306220014	50-38
WCBTAFER, Q. R.	8306030320	50-302 J	WIDMAYER, D. A.	8306210437	27-47	WILLIAMS, J. W.	8306270200	50-25
WCBTAFER, Q. R.	8306070273	50-302 S	WIEBE, J. B.	8306060266*	50-380 Q	WILLIAMS, J. W.	8306280168	50-25
WCBTAFER, Q. R.	8306090165	50-302 S	WIEDER, A. V.	8306200410*	70-1257	WILLIAMS, J. W.	8306280476	50-38
WCBTAFER, Q. R.	8306140451*	50-302 Q	WIEDER, A. V.	8306200383*	70-724	WILLIAMS, J. W.	8306300023	50-38
WCBTAFER, Q. R.	8306170221	50-302 R	WIEBEMANN, R. A.	8306070210*	50-413 E	WILLIAMS, J. W.	8306300153	50-38
WCBTAFER, Q. R.	8306200033	50-302 P	WIEBEMANN, R. A.	8306150172*	PROJ	WILLIAMS, R.	8306220297*	CONTR
WCBTAFER, Q. R.	8306220049	50-302 P	WIEBEMANN, R. A.	8306240314	TOPREP	WILLIAMS, R. E.	8306020263	40-22
WCBTAFER, Q. R.	8306230427	50-302 P	WIEBEMANN, R. A.	8306270434	PROJ	WILLIAMS, R. E.	8306020269*	40-29
WCBTAFER, Q. R.	8306230447	50-302 R	WIGGINS, E.	8306230218	CONTRACT	WILLIAMS, R. E.	8306140438*	CONTR
WCBTAFER, Q. R.	8306230465	50-302 P	WIGGINS, J. T.	8306070353*	50-271 Q	WILLIAMS, R. E.	8306150570*	CONTR
WCBTAFER, Q. R.	8306240259	50-302 P	WIGGINS, J. T.	8306090366*	50-271 Q	WILLIAMS, R. E.	8306200111	40-65
WCBTAFER, Q. R.	8306300225	50-302 P	WIGGINS, J. T.	8306160606*	50-271 Q	WILLIAMS, R. A.	8306060309*	70-25
WESTERMAN, T.	8306140374*	50-445 Q	WIGGINTON, D.	8306020009	50-315 P	WILLIAMS, V. B.	8306100064	50-29
WESTERMAN, T. I.	8306010141*	50-267 Q	WIGGINTON, D.	8306210343	50-315 F	WILLIAMS, V. B.	8306130307	50-29
WESTERMAN, T. I.	8306010262	50-298 S	WILBORN, L.	8306080211*	50-285 Q	WILLIAMSON, B.	8306210270	50-25
WESTERMAN, T. I.	8306060126*	50-267 Q	WILBORN, L.	8306080338	50-313 Q	WILSON, B.	8306030083	XPORIT
WESTERMAN, T. I.	8306060130*	50-112 Q	WILBORN, L.	8306270237*	50-298 Q	WILSON, B. D.	8306150348	XPORIT
WESTERMAN, T. I.	8306080221*	50-445 Q	WILCOVE, H. N.	8306150220	50-329 Q	WILSON, B. D.	8306160648	XPORIT
WESTERMAN, T. I.	8306130261*	50-445 Q	WILCOVE, H. N.	8306150274	50-329 Q	WILSON, C. L.	8306240052	NURC

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
WILSON, J F	8306020336*	CONTRACT	WORTHAM, T R	8306280436*	50-397 E	ZIMMERMAN, J V	8306030219	XPORLTIC
WILSON, J H	8306020641	50-392 A	WOZNIAK, D R	8306150343	XPORLTIC	ZIMMERMAN, J V	8306030226	XPORLTIC
WILSON, J L	8306070220	50-280 S	WRAY, J R	8306170345	70-143	ZIMMERMAN, J V	8306030249	XPORLTIC
WILSON, J L	8306070238	50-281 S	WRAY, R	8306080060	50-275 P	ZIMMERMAN, J V	8306030474	XPORLTIC
WILSON, J L	8306070243*	50-281 S	WRIGHT, D J	8306060226	PR	ZIMMERMAN, J V	8306030478*	XPORLTIC
WILSON, J L	8306070245*	50-281 S	WRIGHT, E O	8111040442*	XPORLTIC	ZIMMERMAN, J V	8306090008	XPORLTIC
WILSON, J L	8306100186	50-281 S	WRIGHT, N A	8306140660	50-329 G	ZIMMERMAN, J V	8306090009	XPORLTIC
WILSON, J L	8306210285	50-280 S	WRIGHT, N A	8306140727	50-329 G	ZIMMERMAN, J V	8306090181	XPORLTIC
WILSON, J L	8306270005	50-280 S	WRIGHT, N A	8306270154	50-329 G	ZIMMERMAN, J V	8306140267	XPORLTIC
WILSON, J L	8306270351	50-281 S	WRIGHT, R W	8306140172*	50-438 G	ZIMMERMAN, J V	8306140271	XPORLTIC
WILSON, J L	8306270357*	50-281 S	WRIGHT, S V	8306020222	27-4B	ZIMMERMAN, J V	8306140274	XPORLTIC
WILSON, J L	8306270364*	50-281 S	WRIGHT, S V	8306240487	27-4B	ZIMMERMAN, J V	8306140309	XPORLTIC
WILSON, J L	8306300199	50-281 S	WULLER, O E	8306020203	70-2947	ZIMMERMAN, J V	8306150271	XPORLTIC
WILSON, J L	8306130375	50-322 Q	WULLER, O E	8306100097	50-461 F	ZIMMERMAN, J V	8306150457	XPORLTIC
WILSON, J L	8306200151	50-27 F	WULLER, O E	8306200409	50-461 F	ZIMMERMAN, J V	8306160205	XPORLTIC
WILSON, W H	8306140225	50-528 A	WULLER, O E	8306210231	50 461 A	ZIMMERMAN, J V	8306160290	XPORLTIC
WINEGARDNER, W	8306070471	NUREG	WUSTERBARTH, A	8306240078	NUREG	ZIMMERMAN, J V	8306200063	XPORLTIC
WINGO, M D	8306280375	50-260 S	WYATT, J H	8306060120*	50-382 I	ZIMMERMAN, J V	8306200362	XPORLTIC
WINSECK, S	8306230109*	FOIA	YARLO, W R	8306300142	PR	ZIMMERMAN, J V	8306280027	XPORLTIC
WINTON, M L	8306210324	NUREG	YEAGER, B B	8306300142	PR	ZIMMERMAN, R	8306240214*	GA999
WIRE, K R	8306270163	50-298 S	YIN, I T	8306060130*	50-358 G	ZIMMERMAN, R	8306240219*	GA999
WISE, J A	8306140315	NUREG	YIN, I T	8306300029*	50-346 G	ZIMMERMAN, R	8306240224*	GA999
WISE, R	8306080046*	50-267 G	YIN, I T	8306300246*	50-237 G	ZIMMERMAN, R	8306150271	GA999
WISENBURG, M R	8306300077	50-498 K	YORK, J W	8306140139*	50-438 G	ZIMMERMAN, R	8306160372*	50-244 G
WISENBURG, M R	8306300173	NUREG	YORK, J W	8306140439*	50-424 G	ZIMMERMAN, R	8306230322*	50-244 G
WISNER, C E	8306140636*	50-382 G	YORK, J W	8306140511*	50-413 G	ZIMMERMAN, R	8306070035	50-324 P
WISSINK, R O	8306230340	PR	YORK, J W	8306270235*	50-438 G	ZIMMERMAN, R	8306070151	50-400 E
WITHERS, B D	8306010316	50-344 P	YOSHIDA, D K	8306160366*	50-341 A	ZIMMERMAN, R	8306070153	50-261 P
WITHERS, B D	8306070209	50-344 F	YOUNG, F	8306150008*	50-289 G	ZIMMERMAN, R	8306070172	50-261 G
WITHERS, B D	8306130415	50-344 F	YOUNG, M A	8306210276	50-460 G	ZIMMERMAN, R	8306080080	50-324 P
WITHERS, B D	8306170303	50-344 P	YOUNG, M A	8306210301	50-460 G	ZIMMERMAN, R	8306090394*	50-261 F
WITHERS, B D	8306170400	50-344 F	YOUNG, M A	8306210347	50-460 G	ZIMMERMAN, R	8306100260	50-261 P
WITHERS, B D	8306200191	50-344 I	YOUNG, M C	8306080284	50-528 A	ZIMMERMAN, R	8306220005	50-261 P
WITHERS, B D	8306200207	50-344 I	YOUNG, T	8306070007*	50-528 G	ZIMMERMAN, R	8306270225	50-324 P
WITHERS, B D	8306230323	PR	YOUNG, T	8306070256*	50-528 G	ZUCKER, C C	8306010089*	71-6400
WITHERS, B D	8306230445	PR	YOUNG, T	8306070378*	50-312 G	ZUDANS, Z	8306210446	ACRS
WITHERS, B D	8306240354	50-344 F	YOUNG, T	8306070385*	50-312 G	ZUDANS, Z	8306210446	ACRS
WITHERS, B D	8306240316	50-344 G	YOUNG, T	8306280452*	50-528 G	ZUPKO, J M	8306070132	50-311 S
WITHERS, B D	8306270242	PR	YOUNG, T	8306280317*	50-528 G	ZUPKO, J M	8306080406	50-311 S
WIDEX, D J	8306170459	40-8714	YOUNG, T E	8306080161	50-333 P	ZUPKO, J M	8306070180	50-311 S
WOHAM, N A	8306090357	WASTE MGT	YOUNG, Y	8306090495*	40-8585	ZUPKO, J M	8306030301	50-311 S
WOLF, J F	8306060285	50-522 G	YOUNG, Y	8306240373	NUREG	ZUPKO, J M	8306030344	50-311 S
WOLFBEIN, S L	8306200289*	CONTRACT	YOUNGBLOOD, B J	8306010042	50-335 A	ZUPKO, J M	8306170021	50-311 S
WOLFE, R	8306100124	50-346 S	YOUNGBLOOD, B J	8306030066	50-436 A	ZUPKO, J M	8306170144	50-272 S
WOLFE, S J	8306150422	50-338 G	YOUNGBLOOD, B J	8306030232	50-436 C	ZUPKO, J M	8306170153	50-311 S
WOLFE, S J	8306280536	50-382 Q	YOUNGBLOOD, B J	8306030232	50-436 C	ZUPKO, J M	8306170207	50-311 S
WOLLETT, S	8306040708	CONTRACT	YOUNGBLOOD, B J	8306030232	50-436 A	ZUPKO, J M	8306170338	50-272 S
WOLLETT, S	8306040117	CONTRACT	YOUNGBLOOD, B J	8306030417	50-454 A	ZUPKO, J M	8306170362	50-311 S
WOLLETT, S	8306040240	CONTRACT	YOUNGBLOOD, B J	8306060373	50-440 A	ZUPKO, J M	8306170381	50-272 S
WOLLETT, S	8306030252	CONTRACT	YOUNGBLOOD, B J	8306060383	50-482 A	ZUPKO, J M	8306200132	50-311 R
WOLLETT, S	8306030254	CONTRACT	YOUNGBLOOD, B J	8306070459	50-423 A	ZUPKO, J M	8306200226	50-272 R
WOLLETT, S	8306070464	CONTRACT	YOUNGBLOOD, B J	8306080051	50-482 A	ZUPKO, J M	8306210187	50-272 R
WOLLETT, S	8306080419	CONTRACT	YOUNGBLOOD, B J	8306170470	50-546 D	ZUPKO, J M	8306270188	50-311 S
WOLLETT, S	8306220229	CONTRACT	YOUNGBLOOD, B J	8306210403	50-445 A	ZUPKO, J M	8306270267	50-272 S
WOLLETT, S	8306280152	CONTRACT	YOUNGBLOOD, B J	8306220090	50-482 F	ZUPKO, J M	8306270343	50-272 G
WOLLETT, S	8306290597	CONTRACT	YOUNGBLOOD, B J	8306220101	50-546 A	ZUPKO, J M	8306280256	50-272 S
WOLLETT, S A	8306220324	CONTRACT	YOUNGBLOOD, B J	8306220106	50-341 A	ZUPKO, J M	8306280480	50-272 S
WOLLIN, J	8306060309*	70-25	YOUNGBLOOD, B J	8306240064	50-440 E	ZURAKOWSKI, F R	8306280136*	50-344 G
WOLTER, E	8306170245*	70-371	YOUNGBLOOD, B J	8306240070	50-454 E	ZWETZIG, G B	8306070049*	50-312 G
WONO, T	8306020314	40-299	YOUNGBLOOD, B J	8306240288	50-440 C	ZWETZIG, G B	8306070369*	50-275 G
WONO, T	8306020320*	40-299	YOUNGBLOOD, B J	8306240390	50-440 A	ZWETZIG, G B	8306280226*	50-312 G
WOOD, E C	8306010408	50-309 S	YOUNGBLOOD, B J	8306270137	50-440 C	ZWETZIG, G B	8306280337*	50-344 G
WOODFIN, R L	8306020080	NUREG	YOUNGBLOOD, B J	8306290142	50-341 A	ZWETZIG, G B	8306070369*	50-275 G
WOODHEAD, C P	8306020161	50-142 T	YOUNGBLOOD, B J	8306080182*	50-322 G	ZWETZIG, G B	8306280226*	50-312 G
WOODHEAD, C P	8306130371	50-142 G	YOUNGBLOOD, B J	8306170334	NUREG	ZWETZIG, G B	8306280337*	50-344 G
WOODHEAD, C P	8306140009	50-142 T	YUHAS, G P	8306280185*	50-89 G			
WOODHEAD, C P	8306210275	50-142 G	YUNDT, C P	8306010070	50-344 S			
WOODHEAD, C P	8306210280	50-142 G	YUNDT, C P	8306020119	50-344 R			
WOODHEAD, C P	8306230301	50-142 G	YUNDT, C P	8306070071	50-344 S			
WOODHEAD, C P	8306230302	50-142 G	YUNDT, C P	8306070212	50-344 S			
			YUNDT, C P	8306160392	50-344 R			
			YUNDT, C P	8306170173	50-344 R			
			YUNDT, C P	8306170317	50-344 R			
			YUNDT, C P	8306200152	50-344 R			
			ZETTLER, Z	8306060309*	70-25			
			ZIBULSKY, H	8306010183*	70-371			
			ZIBULSKY, H	8306010339*	70-687			
			ZIBULSKY, H	8306030324*	70-371			
			ZIMMERMAN, J V	8306020593	XPORLTIC			
			ZIMMERMAN, J V	8306020597	XPORLTIC			
			ZIMMERMAN, J V	8306020623	XPORLTIC			
			ZIMMERMAN, J V	8306020628	XPORLTIC			
			ZIMMERMAN, J V	8306020653	XPORLTIC			
			ZIMMERMAN, J V	8306020663	XPORLTIC			
			ZIMMERMAN, J V	8306030174	XPORLTIC			

CORPORATE SOURCE INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
3M Co., Minnesota Mining & Mfg. Co.	8306230340	PR
ATC Medical Technology, Inc.	8306020468	71-5796
Aamodts, The	8306060190	50-289 Q
	8306070420	50-289 Q
	8306090297	50-289 Q
	8306150427	50-289 Q
	8306220068	50-289 Q
	8306220142	50-289 Q
	8306220147	50-289 Q
Abington Memorial Hosp. Abington, PA	8306280433*	70-1402
Advisory Council on Historic Preservation	8306020308*	40-8681
Aerospace Corp.	8306150584	NUREG
Agriculture, Dept. of	8306070458*	71-9182
	8306210127	50-546 A
	8306280269	50-400 D
Air and Water Pollution Patrol	8306010464	50-352 Q
	8306080261	50-320 Q
	8306290364	50-352 Q
	8306290364	50-352 Q
	8306290509	50-352 Q
Alabama Power Co.	8306290509	50-352 Q
	8306010331	50-348 P
	8306010426	50-364 P
	8306010429*	50-364 P
	8306030307	50-348 P
	8306030311*	50-348 P
	8306060115	50-364 P
	8306060201	50-348 P
	8306060201	50-348 P
	8306070326	50-364 P
	8306090208*	50-348 F
	8306090332*	50-348 Q
	8306100270	50-348 S
	8306130429	50-348 P
	8306130429	50-348 P
	8306130442*	50-348 P
	8306130442*	50-348 P
	8306140071	50-348 Q
	8306140071	50-348 Q
	8306140993	50-348 P
	8306140993	50-348 P
	8306140610	50-348 P
	8306140610	50-348 P
	8306160032*	50-348 F
	8306160119	50-364 R
	8306160278	50-348 P
	8306160278	50-348 P
	8306160327	50-348 R
	8306170357	50-348 Q
	8306170357	50-348 Q
	8306200216	50-348 S
	8306200216	50-348 S
	8306200220*	50-348 S
	8306200227*	50-348 S
	8306200233*	50-348 S

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8306200336	50-348
	8306210193	50-348
	8306210201*	50-348
	8306210365*	50-348
	8306220378	50-348
	8306220378	50-348
	8306230382*	50-348
	8306230382*	50-348
	8306240040	50-348
	8306240040	50-348
	8306270229	50-348
	8306270232*	50-348
	8306270369*	50-348
	8306290207*	50-348
Alabama, State of	8306280159*	CONTRACT
Alden Research Laboratory	8306080303*	50-410
Alderson Reporting	8306070023	FOIA
	8306210318	FOIA
Allied Chemical Corp.	8306080406	40-3392
Alpha-Omega Services, Inc.	8306160649	71-86
	8306160652*	71-86
American Group Co.	8306060142	50-289
American Mining Congress	8306300135	PR
American Nuclear Insurers	8306230161*	FOIA
American Nuclear Society	8306160451	REQD
	8306220245	NUREG
American Resources Group, Ltd.	8306100132*	50-483
American Society for Testing & Materials	8306160446	REQD
American Society of Mechanical Engineers	8306160467	PR
American Society of Utility Investors	8306280532	50-289
Anaconda Co. (subs. of Atlantic-Richfield Co.)	8306230404*	GA999
Analysis & Technology, Inc.	8306240356*	FOIA
Anchor/Darling Valve (subs. Anchor/Darling Industries)	8306160356*	GA999
Anthony, R. L.	8306160378*	GA999
	8306270038	50-332
Antioch School of Law, Washington, DC	8306240423*	50-135
Applied Risk Technology Corp.	8306020448*	50-247
	8306020448*	50-247
	8306020452*	50-247
	8306020452*	50-247
Aptech Engineering Services	8306080048*	50-440
	8306290496*	50-329
Argonne National Laboratory	8305240612*	COMMITTEE
	8305240624*	COMMITTEE
	8306270146	NUREG
	8306270308*	50-322
	8306280085	NUREG
	8306280096	NUREG
Arizona Public Service Co.	8306010055	50-528
	8306010072	50-528
	8306010076	50-528
	8306010076	50-528

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8306010119	50-528 S		8306070034	50-368 P
	8306010119	50-528 S		8306070193	50-313 P
	8306010119	50-528 S		8306070298	50-313 Q
	8306010137	50-528 S		8306070384*	50-313 Q
	8306010272	50-528 S		8306070384*	50-313 Q
	8306010272	50-528 S		8306080012	50-313 F
	8306010272	50-528 S		8306080012	50-313 F
	8306010289	50-528 S		8306090248	50-313 F
	8306010289	50-528 S		8306090248	50-313 F
	8306010341	50-529 S		8306090313	50-313 P
	8306010341	50-529 S		8306130037	50-313 R
	8306010363	50-528 G		8306130037	50-313 R
	8306010375	50-528 S		8306130222	50-313 Q
	8306030357	50-528 F		8306130222	50-313 Q
	8306030357	50-528 F		8306130270	50-368 S
	8306070078	50-528 S		8306130409	50-313 S
	8306070078	50-528 S		8306130421	50-368 S
	8306070078	50-528 S		8306140050	50-313 Q
	8306070091	50-528 A		8306140050	50-313 Q
	8306070104	50-529 S		8306140155	50-313 F
	8306070178	50-528 S		8306140155	50-313 F
	8306070221	50-528 S		8306140155	50-313 F
	8306070225	50-528 S		8306140034*	50-313 F
	8306070432	70-2984		8306160324	50-313 P
	8306090275*	50-528 F		8306160355	50-368 S
	8306090276*	50-528 F		8306160469	50-313 S
	8306130432	50-528 E		8306160474	50-368 R
	8306160064*	50-528 F		8306160479	50-368 S
	8306160500	50-528 E		8306160493	50-313 P
	8306160500	50-528 E		8306160493	50-368 S
	8306160500	50-528 E		8306160537	50-313 Q
	8306170180	50-528 S		8306160561	50-313 R
	8306170240	50-528 S		8306160577	50-368 S
	8306170246	50-528 S		8306160614	50-313 S
	8306170265	50-528 A		8306170275	50-313 P
	8306170302	50-528 A		8306170275	50-313 P
	8306170302	50-528 A		8306170408	50-313 P
	8306170302	50-528 A		8306200060*	50-313 F
	8306170326	50-528 E		8306210003	50-313 S
	8306170326	50-528 E		8306210093	TOPREP
	8306170326	50-528 E		8306210125	50-313 R
	8306170341	50-529 G		8306210125	50-313 R
	8306170342	50-528 S		8306210181	50-368 S
	8306170351	50-528 A		8306210229	50-368 P
	8306170351	50-528 A		8306220062	50-313 V
	8306170351	50-528 A		8306230474	50-313 F
	8306170356	50-528 F		8306230474	50-313 F
	8306170356	50-528 F		8306230487	50-368 P
	8306170356	50-528 F		8306270192	50-368 S
	8306170360*	50-528 F		8306300079*	50-313 Q
	8306170360*	50-528 F	Arkansas, State of	8306030284*	CONTRACT
	8306170366	50-528 S	Army, Dept of	8306220272*	CONTRACT
	8306170366	50-528 S	Army, Dept of, Army Engineer Waterways	8306010266	NUREG
	8306170367	50-528 S	Experiment Station		
	8306170393	50-528 S	Army, Dept of, Corps of Engineers	8306240034*	CONTRACT
	8306200371	50-528 F	Associated Piping & Engineering Corp	8306020585	71-302
	8306200371	50-528 F	(subs of Johnson Controls, Inc)		
	8306210287	50-528 E	Atlas Minerals	8306200107	40-3453
	8306230245	50-528 S	Atomic Industrial Forum	8306160224	NUREG
	8306230252	50-528 G		8306160334	PR
	8306230270	50-528 S		8306230328	PR
	8306230318	50-528 S		8306270303	50-289 H
	8306230318	50-528 S			
	8306230379	50-529 S	Australia	8305040713*	CONTRACT
	8306230408	50-528 S	Automated Correspondence Systems, Inc	8306280133*	CONTRACT
	8306270143	50-528 A	Automation Industries, Inc	8306240441*	71-9006
	8306270368	50-528 E		8306240443*	71-9006
	8306270368	50-528 E	BWR Owners Group	8306210146	TOPREP
	8306270368	50-528 E		8306230324	TOPREP
	8306270447	50-528 F		8306070280*	50-269 P
	8306280317	50-528 E	Dabcock & Wilcox Co	8306070286*	50-269 P
	8306280436	50-528 A		8306100090	50-312 S
	8306010024	50-313 P		8306140377	50-269 P
Arkansas Power & Light Co	8306010028*	50-313 P		8306140674	70-1201
	8306010267	50-313 P		8306140746*	50-269 P
	8306020081	50-313 R		8306140752*	50-269 P
	8306020135	50-313 P		8306160497*	50-313 P
	8306020150	50-368 R		8306200020	70-135
	8306020466	50-368 P		8306210295	TOPREP
	8306030294	50-313 J		8306220007	50-287 S
	8306060067*	50-313 Q		8306220131	70-824
	8306060067*	50-313 Q		8306270121	70-1201
	8306060253	50-313 R		8306280337	TOPREP
				8306300159	50-438 S
				8306300220	50-269 S
			Dabcock & Wilcox Operating Plants Owners Group	8306010314	50-313 P

CORPORATE SOURCE INDEX

49

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Bachus, Shea & Meyer	8306070280*	50-269 P		8306200423	40-85B4
	8306210093	TOPREP		8306200444	ACRB
	8306200291	FOIA		8306230137*	70-B
	8306200293*	FOIA		8306240052	NUREG
	8306290521	50-443 G		8306240058	NUREG
Baltimore Gas & Electric Co	8306290532	50-443 G	Battelle New England Marine Research Laboratory	8306240073	NUREG
	8306010264	50-317 S		8306240078	NUREG
	8306010270	50-318 S		8306240373	NUREG
	8306010273	50-318 S		8306270324	50-254
	8306010277	50-317 S		8306060252	50-219
	8306010299	50-318 S	Bechtel Corp	8306090235	50-219
	8306010300	50-317 S		8306070107*	50-229
	8306010307	50-317 S		8306130372*	50-329
	8306020374	50-318 S		8306140225	50-328
	8306020423	50-317 S		8306210220	50-322
	8306020430	50-318 S	Behrand, Aramson & Morris	8306070018	FOIA
	8306020433	50-317 S		8306280230	FOIA
	8306020436	50-317 S		8306070471	NUREG
	8306020438	50-318 S	Benton City Technology Darle, Buttel, Mass & Case Berlin, K	8306210384*	CONTRACT
	8306020467	50-317 S		8306150398	50-329
	8306060105	50-317 P	Binder, Elster, Mendelson & Wheeler, Inc	8306170466*	CONTRACT
	8306060109	50-317 P		8306080009*	50-290
	8306060109*	50-317 P		8306030266*	CONTRACT
	8306070047	50-317 P		8306200280*	FOIA
	8306070047	50-317 P		8306200282*	FOIA
	8306070077	50-317 S	Boeing Computer Services, Inc (subs of Boeing Co)	Book Mart International, Inc	
	8306070156	50-317 P			
	8306070156	50-317 P			
	8306070229	50-317 F			
	8306130001	50-317 Q			
	8306130001	50-317 Q	Boston Edison Co	8306240436	50-293
	8306150086*	50-317 F		8306010060	50-293
	8306160330*	50-317 Q		8306010157	50-293
	8306170011	50-317 S		8306010275	50-293
	8306170011	50-317 S		8306010322	50-293
	8306170018	50-317 R		8306010334	50-293
	8306170031	50-317 S		8306010386	50-293
	8306170072	50-318 S		8306010393	50-293
	8306170420	50-318 S		8306020154	50-293
	8306200089	50-317 S		8306020419	50-293
	8306200118	50-318 S		8306020456	50-293
	8306200208	50-317 S		8306070045	50-293
	8306200268	50-317 S		8306070167	50-293
	8306210046	50-318 S		8306070170*	50-293
	8306210086	50-317 S		8306070348	50-293
	8306210099	50-318 S		8306140613	50-293
	8306210101	50-317 S		8306140662*	50-293
	8306210108	50-317 S		8306150011	50-293
	8306210121	50-317 Q		8306210184	50-293
	8306210159	50-318 S		8306210206	50-293
	8306210246	50-318 S		8306220003	50-293
	8306270164	50-317 F		8306220009*	50-293
	8306270195	50-317 F		8306240172	50-293
	8306280172	50-318 S		8306280072	50-293
	8306280352	50-318 S		8306280331	50-293
	8306280447	50-317 S	Braunkohl's Transport & Storage, Inc Brookhaven National Laboratory	8306280358	50-293
	8306280462	50-318 S		8306060354	XPORTRIC
	8306280463*	50-317 Q		8303220403*	TOPREP
	8306030351*	50-272 S		8306010088	NUREG
	8306150185*	50-289 H		8306010478	RES
Basic Energy Technology Associates	8306280447	50-317 S		8306020048	RES
	8306280462	50-318 S		8306020066	NUREG
	8306280463*	50-317 Q		8306020072	NUREG
	8306030351*	50-272 S		8306030435	RES
	8306150185*	50-289 H		8306130379*	50-142
Battelle Human Affairs Research Centers	8306030009	NUREG		8306140407	NUREG
	8306140315	NUREG		8306170192	RES
	8306010129*	CONTRACT		8306170205*	RES
	8306170482*	CONTRACT		8306240413	50-286
	8306230505*	CONTRACT		8306280044	NUREG
Battelle Memorial Institute, Columbus Laboratories	8306240241	RES	Brush Wellman, Inc Burns & Roe Co	8306130243	40-8722
	8303220042*	50-309 G		8306100122	50-397
	8306010039	NUREG		8306230339	PR
	8306010067	NUREG		8306230437	TOPREP
	8306010071	NUREG		8306230443*	TOPREP
	8306010478	RES	Burstain, C H Businessmen for the Public Interest	8306240191	50-397
	8306020053	NUREG		8306280541*	50-382
	8306020131	NUREG		8306170371	50-434
	8306020134	NUREG		8306170384*	50-434
	8306020217	WASTE MGT		8306170389*	50-434
	8306030009	NUREG	California, State of	8306230370*	50-367
	8306030485	NUREG		8306220045	50-275
	8306070471	NUREG		8306220052*	50-275
	8306090357	WASTE MGT		8306220246*	CONTRACT
	8306100095	50-263 G		8306220290	ACRB
	8306140315	NUREG	California, Univ of, Berkeley	8306210186	50-326
	8306140402	NUREG		8306070399	50-142
	8306160010*	50-142 T		8306070416	50-142

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
California, Univ of, San Diego Capitol Steel Corp	8306140774	NUREG
	8306280325	50-142 Q
	8306280395	50-142 R
	8306160043*	CONTRACT
	8306030038	71-9133
Caroline Environmental Study Group	8306100196	50-413 Q
	8306150385	50-413 Q
	8306270284	50-413 Q
	8306010105	50-324 S
	8306010109	50-324 S
Carolina Power & Light Co	8306010118	50-325 S
	8306010128	50-400 S
	8306010311	50-324 Q
	8306010311	50-324 Q
	8306010388	50-324 S
	8306010390	50-400 Q
	8306010390	50-400 Q
	8306010395*	50-400 Q
	8306010395*	50-400 Q
	8306010422	50-400 S
	8306030336	50-400 Q
	8306030336	50-400 Q
	8306060112	50-400 F
	8306060132	50-400 E
	8306060132	50-400 E
	8306060202	50-400 E
	8306060202	50-400 E
	8306070035	50-324 P
	8306070053	50-325 S
	8306070081	50-325 S
	8306070097	50-324 S
	8306070101	50-261 P
	8306070102	50-324 S
	8306070122	50-400 E
	8306070122	50-400 E
	8306070141	50-324 S
	8306070151	50-400 E
	8306070151	50-400 E
	8306070153	50-261 P
	8306070161	50-261 S
	8306070172	50-261 Q
	8306070182	50-261 S
	8306070217	50-400 S
	8306070231	50-400 S
	8306070231	50-400 S
	8306070235	50-324 S
	8306070291	50-400 Q
	8306070291	50-400 Q
	8306070342	50-324 S
	8306070342	50-324 S
	8306070366	50-400 S
	8306070389	50-400 S
	8306070400	50-400 S
	8306080032	50-400 E
	8306080032	50-400 E
	8306080080	50-324 P
	8306080080	50-324 P
	8306080083*	50-324 P
	8306080122	50-261 F
	8306080149	50-400 Q
	8306080149	50-400 Q
	8306080160	50-400 Q
	8306080160	50-400 Q
	8306090046	50-400 S
	8306090046	50-400 S
	8306090136	50-325 S
	8306090180	50-400 S
	8306090180	50-400 S
	8306090191	50-400 S
	8306090191	50-400 S
	8306090242	50-400 S
	8306090251	50-400 S
	8306090394*	50-261 F
	8306100091	50-400 Q
	8306100091	50-400 Q
	8306100127	50-325 S
	8306100177	50-324 S
	8306100188	50-400 E
	8306100188	50-400 E
	8306100238	50-400 S
	8306100254	50-400 S
	8306100254	50-400 S
	8306100260	50-261 P
	8306140214	50-324 R
	8306140264	50-261 Q

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8306140404*	50-324 Q
	8306140404*	50-324 Q
	8306140405	50-261 R
	8306140490*	50-400 Q
	8306140547	50-324 Q
	8306140682*	50-324 Q
	8306140682*	50-324 Q
	8306140688*	50-324 Q
	8306140688*	50-324 Q
	8306140708*	50-261 Q
	8306160116	50-400 E
	8306160284	TOPREP
	8306160420	50-261 R
	8306170224	50-400 E
	8306170224	50-400 E
	8306200002	50-261 S
	8306200003	50-324 S
	8306200083	50-400 E
	8306200083	50-400 E
	8306200109	50-261 S
	8306200116	50-400 S
	8306200116	50-400 S
	8306200188	50-261 S
	8306200200	50-400 S
	8306200309	50-400 E
	8306200309	50-400 E
	8306210002	50-400 A
	8306210002	50-400 A
	8306210082	50-324 J
	8306210082	50-324 J
	8306210096	50-324 S
	8306210109	50-324 J
	8306210109	50-324 J
	8306210174	50-325 S
	8306210204	50-400 E
	8306210204	50-400 E
	8306220003	50-261 P
	8306220087	TOPREP
	8306220108	50-400 Q
	8306220108	50-400 Q
	8306220111*	50-400 Q
	8306220111*	50-400 Q
	8306220125	50-400 Q
	8306220125	50-400 Q
	8306220273	50-261 F
	8306220273	50-261 F
	8306220273	50-261 F
	8306230345	50-400 Q
	8306230345	50-400 Q
	8306240008	50-324 P
	8306240145	50-325 P
	8306240149*	50-325 P
	8306240246	50-324 P
	8306240246	50-324 P
	8306270061	50-324 S
	8306270098	50-325 S
	8306270100	50-400 E
	8306270100	50-400 E
	8306270113	50-400 A
	8306270113	50-400 A
	8306270119	50-324 S
	8306270196	50-324 S
	8306270199	50-324 S
	8306270217	50-400 E
	8306270217	50-400 E
	8306270223	50-400 S
	8306270223	50-400 S
	8306270225	50-324 P
	8306270225	50-324 P
	8306270241	50-400 E
	8306270241	50-400 E
	8306270243	50-324 S
	8306270277	50-324 S
	8306270291	50-325 S
	8306270292	50-400 E
	8306270292	50-400 E
	8306270448	50-400 E
	8306270448	50-400 E
	8306280088	50-400 S
	8306280463	50-400 S
	8306280463	50-400 S
	8306280489	50-325 Q
	8306280524	50-324 P
	8306280524	50-324 P
	8306280544*	50-324 P
	8306280544*	50-324 P

CORPORATE SOURCE INDEX

501

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8306280544*	50-324 P		8306270378*	50-338 A
	8306280359	50-155 P		8306280213*	50-338 A
	8306290247	50-261 Q		8306280339	50-338 A
	8306290395	50-400 Q		8306300160	50-338 B
	8306290402	50-324 Q	Citizens Association for Sound Energy	8306070304	50-445 Q
	8306290353*	50-261 Q		8306070304	50-445 Q
	8306290353*	50-261 Q		8306070306*	50-445 Q
	8306290353*	50-261 Q		8306070306*	50-445 Q
	8306290353*	50-261 Q		8306070382	50-445 Q
	8306290353*	50-261 Q		8306070382	50-445 Q
	8306290353*	50-261 Q		8306070394*	50-445 Q
	8306290355*	50-261 Q		8306070394*	50-445 Q
	8306300012	50-324 S		8306100223	50-445 Q
	8306300031	50-324 S		8306100223	50-445 Q
	8306300192	50-400 S		8306100227*	50-445 Q
	8306300193	50-324 S		8306100227*	50-445 Q
	8306300193	50-324 S		8306100230*	50-445 Q
	8306300203	50-323 S		8306150310	50-445 Q
	8306300242	50-324 S		8306150310	50-445 Q
Carpenter Technology Corp	8306150343	XPORTLIC		8306150380	50-445 Q
Carrier Corp	8306160454	50-518 S		8306150380	50-445 Q
Catholic Univ of America, Washington, DC	8306280351*	50-77 Q		8306150406	50-445 Q
Center for Law in the Public Interest	8306010336	50-275 H		8306150406	50-445 Q
	8306060182	50-275 Q		8306150414	50-445 Q
	8306150314	50-275 Q		8306150414	50-445 Q
	8306150435	50-275 Q		8306150415*	50-445 Q
	8306220038	50-275 Q		8306150415*	50-445 Q
	8306280563	50-275 P		8306080150	50-498 Q
	8306290535	50-275 Q	Citizens Concerned About Nuclear Power, Inc	8306080150	50-498 Q
Charlotte-Mecklenberg Environmental Coalition	8306130437	50-413 Q		8306080153*	50-498 Q
	8306290461*	50-413 Q		8306080159*	50-498 Q
	8306290461*	50-413 Q		8306080159*	50-498 Q
	8306290464*	50-413 Q		8306220057	50-498 Q
Charnoff, G	8306170476	ADVCH	Citizens for Energy & Employment	8306270218	50-341 Q
	8306200048*	ADVCH	Citizens for Nuclear Reactor Safety, Inc	8306060316	50-170 Q
Chem-Nuclear Systems, Inc	8306080345	71-9176		8306010058	50-440 E
	8306090202	71-9094	Cleveland Electric Illuminating Co	8306080044	50-440 A
	8306210250	71-9108		8306080044	50-440 A
	8306210256*	71-9108		8306100119	50-440 B
	8306240394	27-47		8306100119	50-440 B
Cherna Contracting Corp	8306240381	71-9135		8306100180	50-440 A
Chicago Bridge & Iron Co	8306160639	71-9141		8306130305*	50-440 Q
Christa-Maria	8306010450	50-155 Q		8306130305*	50-440 Q
	8306080232	50-155 Q		8306140661	50-440 A
	8306080235*	50-155 Q		8306160611	50-440 Q
	8306240423*	50-155 Q		8306160611	50-440 Q
	8306010151	50-388 K		8306200085	50-440 E
Cincinnati Gas & Electric Co	8306010156*	50-358 K		8306200120	50-440 B
	8306020312	70-2892		8306200120*	50-440 B
	8306060074*	50-358 A		8306220015	50-440 B
	8306060099	50-358 E		8306220039	50-440 B
	8306060101*	50-358 E		8306220039	50-440 B
	8306060197	50-358 B		8306220058	50-440 B
	8306060254	50-358 A		8306220058	50-440 B
	8306070135	50-358 B		8306240186	50-440 A
	8306070232	50-358 B		8306240186	50-440 A
	8306070267	50-358 B		8306240269	50-440 E
	8306070267	50-358 B		8306240344	70-2968
	8306070373	50-358 Q		8306270115*	50-440 Q
	8306080137	50-358 E		8306270287*	50-440 Q
	8306080140*	50-358 E		8306280161	50-440 A
	8306080213	50-358 F		8306280161	50-440 A
	8306090084	50-358 B		8306290214	50-440 Q
	8306090127	50-358 B		8306290214	50-440 Q
	8306130381	50-358 K		8306290240*	50-440 Q
	8306170321	50-358 R		8306300169	50-440 B
	8306210054	50-358 B		8306300169	50-440 B
	8306210058	50-358 B	Cleveland-Cliffs Iron Co	8306170459	40-8714
	8306210269	50-358 H	Coalition for Nuclear Power Plant Postponement	8306300195	PR
	8306210294	50-358 B		8306010364	50-460 Q
	8306220031	50-358 Q	Coalition for Safe Power	8306060308	50-460 Q
	8306220036*	50-358 Q		8306150302	50-460 Q
	8306230081	50-358 B		8306150306	50-460 Q
	8306230089	50-358 B		8306160078	FOIA
	8306230196	50-358 B		8306220129	50-308 Q
	8306230268	50-358 B		8306290370	50-460 Q
	8306230395	50-358 B		8306290375*	50-460 Q
	8306230435	50-358 H		8306300219	PR
	8306230442	50-358 B	Colorado, State of	8306300110	PR
	8306230472	50-358 B	Colt Industries, Inc		
	8306270180	50-358 B		8306240358*	CONTRACT
	8306270331	50-358 B	Columbia Univ.	8306010078*	50-528
	8306270332	50-358 A	Combustion Engineering, Inc	8306010059*	50-528

CORPORATE SOURCE INDEX

50

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8306160233	50-237 P		8306270041	50-454
	8306160233	50-237 P		8306270041	50-454
	8306160233	50-237 P		8306270071*	50-456
	8306160233	50-237 P		8306270108	50-254
	8306160233	50-237 P		8306270111	50-249
	8306160435*	50-373 Q		8306270168	50-295
	8306160596	50-440 Q		8306270221	50-304
	8306170045	50-454 S		8306270247	50-237
	8306170045	50-454 S		8306270252	50-254
	8306170283	50-373 J		8306270302	50-373
	8306170314	50-254 R		8306270322	50-454
	8306170314	50-254 R		8306270322	50-454
	8306170344	50-265 S		8306270322	50-454
	8306170380	50-237 Q		8306270322	50-454
	8306170380	50-237 Q		8306270322	50-454
	8306170380	50-237 Q		8306270345	50-454
	8306170380	50-237 Q		8306270345	50-454
	8306170380	50-237 Q		8306270373	50-454
	8306170380	50-237 Q		8306270373	50-454
	8306170380	50-237 Q		8306270373	50-454
	8306170409	50-249 S		8306270373	50-454
	8306200265	50-237 P		8306270383	50-454
	8306200300	50-454 Q		8306270383	50-454
	8306200300	50-454 Q		8306270387	50-237
	8306200304	50-454 Q		8306270392*	50-237
	8306200304	50-454 Q		8306270393	50-454
	8306200350	50-454 Q		8306270431	50-454
	8306200350	50-454 Q		8306270431	50-454
	8306210045	50-373 S		8306270431	50-454
	8306210073	50-295 P		8306270431	50-454
	8306210089	50-373 S		8306280323	50-373
	8306210192	50-373 S		8306280377	50-304
	8306210205	50-373 F		8306280502	50-373
	8306210211	50-454 K		8306280528	50-454
	8306210211	50-454 K		8306280535	50-454
	8306210211	50-454 K		8306300032	50-374
	8306210234	50-304 S		8306300032	50-374
	8306210263	50-373 S		8306300032	50-374
	8306210277	50-373 S		8306300032	50-374
	8306210308	50-373 S		8306300043	50-254
	8306210357*	50-10 F		8306300073*	50-373
	8306220001	50-454 E		8306300216*	50-295
	8306220019	50-373 S		8306300216*	50-295
	8306220034*	50-254 Q		8306300237	50-254
	8306220034*	50-254 Q		8306090379*	FDIA
	8306220064	50-373 S	Computer Data Systems, Inc	8306170336*	50-390
	8306220067	50-254 Q	Conax Corp	8306150251*	CONTRACT
	8306220086	50-237 R	Conference of Radiation Control Program		
	8306230037*	50-373 A	Directors, Inc	8306010340	50-213
	8306230039*	50-373 A	Connecticut Yankee Atomic Power Co	8306020268	50-213
	8306230219	50-295 P		8306060090	50-213
	8306230219	50-295 P		8306060090	50-213
	8306230237	50-454 A		8306060090	50-213
	8306230237	50-454 A		8306060090	50-213
	8306230237	50-454 A		8306060207	50-213
	8306230237	50-454 A		8306060243	50-213
	8306230257	50-454 F		8306100114	50-213
	8306230257	50-454 F		8306150338*	50-213
	8306230257	50-454 F		8306150341*	50-213
	8306230257	50-454 F		8306160053	50-213
	8306230257	50-454 F		8306160459	50-213
	8306230294	50-456 A		8306170051	50-213
	8306230294	50-456 A		8306170231	50-213
	8306230385	50-454 Q		8306170301	50-213
	8306230385	50-454 Q		8306170347	50-213
	8306230412	50-454 F		8306170391	50-213
	8306230412	50-454 F		8306170391	50-213
	8306230412	50-454 F		8306170391	50-213
	8306230412	50-454 F		8306200391*	50-213
	8306230412	50-454 F		8306230100*	50-213
	8306230425	REQD		8306230102*	50-213
	8306240030	50-237 P		8306230426	50-213
	8306240030	50-237 P		8306240200	50-213
	8306240035*	50-237 P		8306240200	50-213
	8306240035*	50-237 P		8306270001	50-213
	8306240035*	50-237 P		8306270004*	50-213
	8306240252	50-374 A		8306270361	50-213
	8306240252	50-374 A		8306020032*	70-2953
	8306240252	50-374 A		8306060322	50-352
	8306240252	50-374 A		8306070295	50-352
	8306270002	50-373 S		8306070295	50-352
	8306270016	50-454 Q		8306070299*	50-352
	8306270016	50-454 Q		8306070299*	50-352
	8306270020*	50-454 Q		8306070301*	50-352
	8306270020*	50-454 Q			
			Connecticut Univ of		
			Conner & Wetterhahn		

AUTHOR	ACCESSION	SUBJECT	AUTHOR	ACCESSION	SUBJECT	
AFFILIATION	NUMBER	CATEGORY	AFFILIATION	NUMBER	CATEGORY	
Consolidated Edison Co of New York, Inc	8306070301*	50-352		8306070248	50-233	
	8306070373	50-358		8306070282	50-233	
	8306080107*	ADVCM		8306080045	50-135	
	8306090212	50-352		8306090203*	50-233	
	8306090212	50-352		8306090287*	50-233	
	8306090240	50-352				
	8306090240	50-352		8306090321	50-329	
	8306100206	50-458		8306100055	50-135	
	8306140740*	ADVCM		8306100179	50-233	
	8306150393	50-352		8306100181*	50-233	
				8306100222	50-135	
				8306100268	50-329	
				8306100268	50-329	
				8306100269*	50-329	
				8306100269*	50-329	
				8306100272*	50-329	
		8306270413	50-352		8306130051	50-135
		8306010126*	50-247		8306130281	50-329
		8306020276	50-247		8306130281	50-329
		8306070343	50-247		8306130310	50-233
		8306070414	50-247		8306130334	50-233
		8306090299	50-247		8306130335*	50-233
		8306090299	50-247		8306130368	50-329
		8306090317	50-247		8306130394	50-233
		8306090317	50-247		8306140223*	50-135
		8306090325	50-247		8306140227*	50-135
		8306090325	50-247		8306140524	50-329
		8306090340	50-247		8306140524	50-329
		8306090340	50-247		8306140831*	50-233
		8306090359	50-247		8306180003	50-135
		8306150429	50-247		8306150346*	50-329
		8306160462	50-247		8306150346*	50-329
		8306170044	50-247		8306150351*	50-329
		8306170189	50-247		8306150351*	50-329
		8306170197	50-247		8306150405	50-135
		8306170200	50-247		8306150409*	50-135
		8306170230*	50-247		8306150413*	50-135
		8306170271	50-247		8306160235	50-329
		8306170323	50-247		8306160380	50-135
		8306170397	50-247		8306160443	REG00
		8306170405	50-247		8306160468	REG00
		8306170410	50-247		8306160566	50-135
		8306170415	50-247		8306170218	50-135
		8306200257	50-247		8306170355	50-135
		8306200342	50-247		8306200015*	50-135
		8306200342	50-247		8306200230	50-135
		8306200346*	50-247		8306200367	50-135
		8306200346*	50-247		8306210102*	50-135
		8306230376	50-247		8306210151	50-233
		8306240225	50-247		8306210173	50-135
		8306240372	71-6601		8306210302	50-329
		8306270083	50-249		8306210302	50-329
		8306270160	50-247		8306220013	50-233
		8306270171	50-3		8306220020	50-233
		8306270171	50-3		8306220023	50-135
		8306270179*	50-3		8306220029	50-233
		8306270179*	50-3		8306220065	50-135
		8306270184*	50-3		8306220102	50-135
		8306270184*	50-3		8306220105	50-135
		8306290329	50-295		8306220256	50-233
		8306290329	50-295		8306230010*	50-135
		8306290335*	50-295		8306230241	50-135
		8306290335*	50-295		8306230250	50-329
		811209561	50-235		8306230250	50-329
		8305260226	50-135		8306230278	50-135
		8305260265	50-135		8306230287	50-233
		8306010281	50-135		8306230374	50-233
		8306010362	50-135		8306230413	50-233
		8306020283	50-135		8306240004	50-135
		8306020337	50-135		8306240139	50-135
		8306030172	50-329		8306240285	50-135
		8306030172	50-329		8306240285	50-135
		8306030223	50-135		8306240285	50-135
		8306030230*	50-135		8306240401	71-9033
		8306030362	50-233		8306270063	50-233
		8306060055*	50-329		8306270076	50-135
		8306060095	50-135		8306270079*	50-135
		8306060119	50-135		8306270107	50-135
		8306060144	50-135		8306270109*	50-135
		8306060145	50-235		8306270125	50-135
		8306060149*	50-235		8306270173	50-135
		8306060192*	50-329		8306270242	50-329
		8306060192*	50-329		8306270242	50-329
		8306070068	50-235		8306270349*	50-329
		8306070236	50-235		8306270349*	50-329
	8306070242	50-329		8306270376	50-135	

CORPORATE SOURCE INDEX

505

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	B306270432	50-255 S		B306100199*	50-413 Q
	B306270435	50-255 S		B306100199*	50-413 Q
	B306270439	50-155 P		B306130501	ADVCM
	B306270412	50-155 P		B306150354	50-508 Q
	B306270493	50-329 A		B306150366	50-445 Q
	B306300065	50-329 A		B306150376	50-445 Q
	B306300103*	50-329 A		B306150423	50-445 Q
	B306300103*	50-329 A		B306160069	FDIA
	B306300109*	50-329 A		B306170334	NUREG
	B306300109*	50-329 A		B306170406	50-445 Q
	B306300112*	50-329 A		B306230364	50-460 Q
	B306300112*	50-329 A		B306300047	50-460 Q
Continuum Dynamics, Inc	B306270226*	50-324 P	Del-Aware Unlimited, Inc	B306010369	50-392 Q
Converse, Ward, Davis, Dixon, Inc	B306270230*	50-324 P		B306220051	50-392 Q
	B306230059*	CONTRACT	Detroit Edison Co	B306010168	50-341 K
Cooper Industries, Inc	B306100203	50-528 S		B306010174*	50-341 K
Cornell Univ	B306140253*	50-97 Q		B306010178*	50-341 K
	B306160138*	FOIA		B306030171	50-341 A
	B306230238	50-97 F		B306060187	50-341 S
Council on Economic Priorities	B306210322	FOIA		B306060245	50-341 S
	B306210330	FOIA		B306070085*	50-341 Q
	B306230006	FOIA		B306130292*	50-341 Q
Covington & Burling	B306070163*	QA999		B306140614	50-341 A
Custom Alloy Corp	B306020291	50-409 R		B306160357	50-341 A
Dairyland Power Cooperative	B306070040	50-409 S		B306170233	50-341 S
	B306070079	50-409 P		B306170419	50-341 S
	B306070311	50-409 F		B306220024*	50-341 Q
	B306070332	50-409 Q		B306220030*	50-341 Q
	B306100184	50-409 P		B306280438	50-341 A
	B306130314*	50-409 Q		B306280585	50-341 F
	B306140707	50-409 P	Dolan & Dolan	B306060002	FOIA
	B306150277	50-409 P	Dorsey, J A	B306030280	50-392 Q
	B306150283*	50-409 P		B306150362	50-392 Q
	B306160279*	50-409 F		B306270297	50-392 Q
	B306160378	50-409 R	Dover General Hosp Dover, NJ	B306020405*	70-2348
	B306170376	50-409 S		B306010015	50-370 S
	B306210066	50-409 P	Duke Power Co	B306010098	50-369 S
	B306210122*	50-409 P		B306010104	50-370 S
	B306210132	50-409 P		B306010123	50-369 S
	B306270337	50-409 S		B306010256	50-369 S
	B306270382	50-409 Q		B306010401	50-369 S
	B306300006	50-409 S		B306020638	70-2985
Damans & Associates	B306080072*	CONTRACT		B306020646*	70-2985
Data Consultants, Inc	B306220288*	CONTRACT		B306030122	50-269 P
Data Stor, Inc	B306210297	FOIA		B306030122	50-269 P
	B306230048*	CONTRACT		B306030122	50-269 P
DataFlow Systems, Inc	B306160600	50-289 Q		B306030300	50-413 A
Dauphin County, PA	B306280538	50-289 Q		B306030300	50-413 A
David W Taylor Naval Research & Development Center	B306060410	NUREG		B306030315	50-369 P
DeGraff, Foy, Conway & Holt-Harris	B306160575	50-410 Q		B306030315	50-369 P
	B306160582*	50-410 Q		B306060076*	50-269 P
	B306080143	50-434 Q		B306060301	50-413 Q
DeKalb Area Alliance for Responsible Energy	B306080143	50-454 Q		B306070051	50-269 P
	B306080143*	50-454 Q		B306070131	50-369 P
	B306080143*	50-454 Q		B306070131	50-369 P
	B306100201	50-434 Q		B306070134*	50-369 P
	B306150436*	50-434 Q		B306070143	50-369 S
	B306150436*	50-434 Q		B306070206	50-413 E
	B306150442*	50-434 Q		B306070210*	50-413 E
	B306150442*	50-434 Q		B306070268	50-369 P
	B306170371	50-454 Q		B306070269	50-369 F
	B306200327*	50-454 Q		B306070269	50-369 F
	B306200327*	50-454 Q		B306070272	50-269 P
	B306200331*	50-454 Q		B306070272	50-269 P
	B306200331*	50-454 Q		B306070272	50-269 P
	B306270082	50-454 Q		B306070283	50-369 P
Debevoise & Liberman	B306020365	50-460 Q		B306070283	50-369 P
	B306020431	50-508 Q		B306070314	50-413 E
	B306030330	50-445 Q		B306070314	50-413 E
	B306030347	50-460 Q		B306070349	50-413 F
	B306030353	50-460 Q		B306080170	50-413 Q
	B306060301	50-413 Q		B306080170	50-413 Q
	B306060313	PRM		B306090015	50-370 S
	B306080170	50-413 Q		B306090040	50-370 S
	B306080239	50-445 Q		B306090147	50-369 S
	B306080239	50-445 Q		B306090361	50-269 F
	B306080243*	50-445 Q		B306100138	50-370 S
	B306080243*	50-445 Q		B306100164	50-370 S
	B306090337	50-460 Q		B306100185	50-370 S
	B306100006	ADVCM		B306100197	50-413 Q
	B306100190	50-460 Q		B306100197	50-413 Q
	B306100197	50-413 Q		B306100199*	50-413 Q
	B306100197	50-413 Q		B306100199*	50-413 Q
	B306100197	50-413 Q		B306100216	50-370 S

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8306100243	50-370 S		8306070264	50-334 F
	8306130312	50-370 S		8306070189	50-334 F
	8306130316	50-370 S		8306070368	50-334 P
	8306130342	50-369 S		8306100104	50-334 Q
	8306130448	50-369 S		8306140620	50-334 Q
	8306140018	50-413 E		8306140639	50-334 P
	8306140018	50-413 E		8306140643*	50-334 P
	8306140119	50-413 Q		8306140672*	50-412 Q
	8306140123	50-413 Q		8306130359*	50-412 Q
	8306140129	50-413 Q		8306160476	50-334 R
	8306140502*	50-413 Q		8306170030	50-334 S
	8306140680	50-370 P		8306200334	50-334 P
	8306140686*	50-370 P		8306200382	50-334 S
	8306140738	50-269 P		8306210141	50-412 S
	8306150177	50-369 P		8306280139	50-334 S
	8306150177	50-369 P		8306280435	50-334 Q
	8306160460	REGD		8306280475*	50-334 Q
	8306170297	50-269 R		8306300209	PR
	8306170311	50-369 R		8306300210	50-334 R
	8306170311	50-369 R		8306220091*	CONTRACT
	8306170316	50-413 E	Dybell/Hare & Associates, Inc	8306230031*	50-373 A
	8306170316	50-413 E	E C Rodabaugh Associates, Inc	8306170029*	CONTRACT
	8306200212	50-369 S	E K Fox & Associates, Ltd	8306210033*	QA799
	8306200237	50-369 S	E L Manufacturing Pebbles, Inc	8306170320*	TOPREP
	8306200238	50-370 S	EDS Nuclear, Inc	830620011	NUREG
	8306200245	50-369 S	EG&G, Inc	8306030088*	50-397 A
	8306200264	50-369 S		8306080161	50-335 P
	8306200321	50-370 S		8306080229	RES
	8306200352	50-369 I		8306160641*	50-389 P
	8306200352	50-369 I		8306160670*	71-9134
	8306200352	50-369 I	ENSA, Inc	8306060366	NUREG
	8306200352	50-369 I		8306170081	NUREG
	8306210092	50-369 P		8306170263	NUREG
	8306210097*	50-369 P		8306240062	NUREG
	8306210190	50-287 S		8306020513*	CONTRACT
	8306220092	50-413 Q	Ebasco Services, Inc (subs of Enverch Corp)	8306140115*	50-389 P
	8306220092	50-413 Q		8306010355	50-400 Q
	8306220295*	50-413 F		8306010359	50-400 Q
	8306220295*	50-413 F	Eddleman, W	8306030337	50-400 Q
	8306240123	50-413 E		8306090222	50-400 Q
	8306240183	50-413 E		8306270307	50-400 Q
	8306270094	50-369 S		8306270307	50-400 Q
	8306270094	50-369 S		8306270313*	50-400 Q
	8306270118	50-413 S		8306270313*	50-400 Q
	8306270124	50-369 S		8306270402	50-400 Q
	8306270189	50-369 F		8306290361	50-400 Q
	8306270227	50-369 S		8306290381	50-400 Q
	8306270301	50-369 S		8306300124	PR
	8306270384	50-413 E	Ederer, Inc	8306020364	TOPREP
	8306280427	50-369 S	Edison Electric Institute	8306060229	PR
	8306290245	50-269 Q		8306160149	FOIA
	8306290282	50-369 Q		8306300223	PR
	8306290459	50-413 Q	Edlow International Co	8306030169	XPORTLIC
	8306290459	50-413 Q		8306150447	XPORTLIC
	8306290461*	50-413 Q	Elcen Metal Products Co	8306270282	50-10 S
	8306290461*	50-413 Q		8306170333	NUREG
	8306290464*	50-413 Q	Electric Power Research Institute	8306230027	40-8681
	8306290464*	50-413 Q	Energy Fuels Nuclear, Inc	8306240267*	TOPREP
	8306290540	50-413 Q	Energy Incorporated	8306290413*	50-245 P
	8306290540	50-413 Q		8306060188*	50-322 Q
	8306300002	50-369 P	Energy Research Group, Inc	8306070386*	50-322 Q
	8306300015	50-287 S		8306220241*	CONTRACT
	8306300114	50-370 S	Energy Resources Co, Inc	8306010001	71-6400
	8306300171	50-370 S	Energy, Dept of	8306010085*	71-6400
	8306300174	50-287 P		8306010103	40-86
	8306300189	50-370 S		8306020192	WASTE HOT
	8306300191	50-369 S		8306020194	WASTE HOT
	8306300191	50-369 S		8306020228	WASTE HOT
	8306300198*	50-369 S		8306020231	WASTE HOT
	8306300206*	50-369 S		8306020235	WASTE HOT
Duquesne Light Co	8306300232	50-370 S		8306060203	50-537 A
	8304110818	50-334 S		8306060417	WASTE HOT
	8304110827*	50-334 S		8306080148	WASTE HOT
	8306010092	50-412 S		8306080153*	WASTE HOT
	8306010295	50-334 S		8306090393	WASTE HOT
	8306010302	50-334 S		8306130403	50-537 A
	8306020218	50-334 R		8306130407*	50-537 A
	8306020324	50-334 S		8306140695	WASTE HOT
	8306020383	50-334 S		8306150229	WASTE HOT
	8306020428	50-412 S		8306160210	NUREG
	8306020440	50-334 S		8306160642	WASTE HOT
	8306030303*	50-334 Q		8306160664	71-9134
	8306060293*	50-412 Q		8306160667*	71-9134
	8306070076	50-334 R		8306170462	71-9132
	8306070120	50-334 R			

CORPORATE SOURCE INDEX

50

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8306200012	WASTE MGT		8306130291	50-389
	8306200022	71-4960		8306130435	50-250
	8306200032	50-537 G		8306130441*	50-250
	8306200035	50-537 E		8306140009	50-389
	8306210307	40-1341		8306140011	50-389
	83062210428	40-1341		8306140033*	50-335
	8306220048	50-537 A		8306140038*	50-335
	8306220169	WASTE MGT		8306140097	50-389
	8306220173*	WASTE MGT		8306140111	50-389
	8306220208	WASTE MGT		8306140310*	50-389
	8306220211	WASTE MGT		8306140572	50-335
	8306240033	71-5595		8306140581	50-389
	8306240044*	71-5595		8306140638	50-389
	8306240179	WASTE MGT		8306140745	50-335
	8306240277	WASTE MGT		8306160335	50-250
	8306240482	WASTE MGT		8306160638	50-250
	8306270317	50-537 G		8306160662*	50-389
	8306290566	50-201 P		8306160666*	50-389
	8306290620	50-201 P		8306170287	50-389
	8306290626*	50-201 P		8306170292*	50-389
	8306300119	50-373 F		8306170299*	50-389
	8306300223	PR		8306170304*	50-389
Energy, Dept. of, Clinch River Breeder Reactor Plant	8306240233	50-537 A		8306170319	50-335
Engineering Science	8306220227*	CONTRACT		8306200094	50-389
Environmental Policy Institute	8306060246	PRM		8306200146	50-389
	8306060248*	PRM		8306200180	50-389
	8306300137	PR		8306200194	50-389
	8306300142	PR		8306200195*	50-389
Environmental Surveillance Laboratory	8306210432*	CONTRACT		8306200310	50-389
Envirosphere Co	8306220246*	CONTRACT		8306210071	50-250
	8306200215*	50-344 I		8306210081	50-389
Eugene Water & Electricity Board	8306150340	XPORTLIC		8306210160	50-389
European Communities, Commission of	8306160628	XPORTLIC		8306210169*	50-389
	8306160716	XPORTLIC		8306210197	50-251
	8306160720	XPORTLIC		8306210261	50-389
	8306300146	NUREG		8306210388*	50-389
Exxon Corp	8306060318	40-8064		8306210392*	50-389
	8306070456	40-8064		8306220014	50-389
	8306200421	40-8064		8306220230*	50-335
Exxon Nuclear Co., Inc. (subs. of Exxon Corp.)	8306020454	PR		8306220236*	50-335
	8306020659*	XPORTLIC		8306270200	50-251
	8306030051	XPORTLIC		8306280168	50-250
	8306030060*	XPORTLIC		8306280250	50-335
	8306090043	TOPREP		8306280356	50-335
	8306090134	TOPREP		8306280476	50-389
	8306130500*	70-1257		8306290338*	50-335
	8306140288	XPORTLIC		8306290345*	50-250
	8306170294	REGOD		8306290351*	50-335
	8306240376	70-1257		8306290398	50-250
	8306200240	TOPREP		8306300025	50-389
	8306070441	FOIA	Florida Power Corp	8306300153	50-389
Fairness Committee Against Tax-Funded Politics	8306160015	FOIA		8306300154	PR
Falkenhainer, D	8306220117	50-458 G		8306030320	50-302
Fearer & Nye	8306060302	50-454 G		8306030322*	50-302
Federal American Partners	8306200067	40-4492		8306070273	50-302
Federal Emergency Management Agency	8306010241	50-397 F		8306070300	50-302
	8306090114	50-329 F		8306090165	50-302
	8306090118	70-155 F		8306140437	50-302
	8306100006	50-247 G		8306140451*	50-302
	8306240308	50-344 F		8306170221	50-302
	8306240310*	50-344 F		8306200033	50-302
	8306270305	50-322 F		8306220049	50-302
	8306040415	50-275 G		8306230429	50-302
Fleischaker, D. S.	8306080195	50-361 G		8306230449	50-302
Fleming, Anderson, McClung & Finch	8306010009	50-389 S		8306230465	50-302
Florida Power & Light Co	8306010116	50-389 S		8306240259	50-302
	8306010272	50-389 S		8306300062*	50-302
	8306020216	50-250 R		8306300225	50-302
	8306030074	50-389 P		8306300229*	50-302
	8306060082	50-389 P	Floridians United For Safe Energy	8306300157	PR
	8306070059	50-389 S		8306300161	PR
	8306070184	50-389 S		8306300227	PR
	8306080004*	50-250 G		8306200168	ACRB
	8306090352	50-250 P	Foundation for National Progress	8306160024	FOIA
	8306090352	50-250 P	Franklin Institute/Franklin Research Center	8306220381*	50-336
	8306090355*	50-250 P		8305200714*	50-305
	8306090355*	50-250 P		8305230021*	50-282
	8306100087	50-335 P		8306020037*	50-309
	8306100140	50-389 P		8306020196*	50-302
	8306100144*	50-389 P		8306030070*	50-338
	8306130156	50-389 F		8306030299*	50-315
	8306130268	50-389 P		8306030310*	50-317
				8306030446*	50-280
				8306030512*	50-295

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8306060329*	50-277 P		8306010407	50-289 R
	8306080232*	50-333 P		8306020090	50-219 R
	8306090388*	50-298 P		8306020096	50-320 P
	8306090397*	50-312 P		8306020341	50-219 Q
	8306140424*	50-219 P		8306020353	50-219 S
	8306150266*	50-239 P		8306020398	50-219 S
	8306210446	ACRS		8306060181	50-289 P
	8306220192*	CONTRACT		8306070215	50-289 R
	8306160024	50-247 Q		8306070215	50-289 R
	8306200324	50-247 Q		8306090027*	50-219 F
	8306270038	50-352 Q		8306090031*	50-219 F
	8306020670	XPORTLIC		8306090235	50-219 R
	8306070294*	QA999		8306090271*	50-289 F
	8306090430	ADVCH		8306100120	50-289 F
	8306100005	70-734		8306130137	50-320 Q
	8306160545*	50-267 P		8306130384	50-219 P
	8306160560*	50-267 P		8306130395*	50-289 Q
	8306160564*	50-267 P		8306140014	50-289 P
	8306170334	NUREG		8306140480	50-289 P
	8306210408	71-6346		8306140986	50-289 P
	8306210415*	71-6346		8306140600	50-320 Q
	8306300202	50-389 S		8306140623	50-289 P
	8306170077	70-498		8306140732	50-289 F
	8306060226	PR		8306150030*	50-289 F
	8306020234	70-754		8306160258*	50-219 Q
	8306020303*	50-277 P		8306170025	50-320 S
	8306020379*	50-277 P		8306170256	50-289 P
	8306030083	XPORTLIC		8306170282	50-320 P
	8306070105	50-447 K		8306200127	50-289 S
	8306070111*	50-447 K		8306200246	50-289 P
	8306070114*	50-447 K		8306200340	50-219 F
	8306070171*	QA999		8306200357	50-320 P
	8306070174*	50-293 P		8306210040	50-289 S
	8306070201	50-447 K		8306210005	50-219 Q
	8306080105	TOPREP		8306210247	50-289 S
	8306090236	50-447 A		8306210254*	50-289 S
	8306100092	50-352 S		8306210258*	50-289 S
	8306100121	PT21		8306220035	50-320 P
	8306100125	50-482 S		8306220054	50-320 P
	8306130328*	50-322 E		8306220298*	50-289 F
	8306130331*	50-322 E		8306240319	50-289 F
	8306130332*	50-322 E		8306270231	50-289 P
	8306140122	70-1113		8306270233*	50-289 P
	8306140238*	CONTRACT		8306270234*	50-289 P
	8306140338*	70-1113		8306280365	50-289 S
	8306150348	XPORTLIC		8306280366	50-289 Q
	8306150453	XPORTLIC		8306280406	50-219 P
	8306150402	NUREG		8306300078	50-289 Q
	8306160470	50-70 S		8306300148	50-438 S
	8306160516	PT21		8306300162	50-289 R
	8306160668	XPORTLIC	General Research Corp	8306140426*	CONTRACT
	8306170214	50-447 A	Georgia Power Co	8306310144	50-321 S
	8306170318	TOPREP		8306010367	50-366 P
	8306170320*	TOPREP		8306010371*	50-366 P
	8306200247*	50-397 E		8306030042	71-9176
	8306200253*	50-397 E		8306030233	50-321 F
	8306200255	TOPREP		8306070080	50-321 S
	8306210028*	QA999		8306070123	50-321 I
	8306210153*	TOPREP		8306070123	50-321 I
	8306240232*	50-322 E		8306070125	50-366 Q
	8306280456*	50-397 E		8306070129	50-321 P
	8306270220*	50-440 Q		8306070129	50-321 P
	8306290481	50-447 K		8306070130*	50-321 I
	8306290495	50-447 K		8306070224	50-321 P
	8306290500*	50-447 K		8306070259	50-366 S
	8306290504*	50-447 K		8306070347	50-321 S
	8306290507	50-447 K		8306070351	50-321 P
	8306290512*	50-447 K		8306070351	50-321 P
	8306290513*	50-447 K		8306070357*	50-321 P
	8306290623*	CONTRACT		8306070357*	50-321 P
	8306300131	NUREG		8306070357*	50-321 P
	8306300165	PR		8306100132	50-366 S
	8306030426	70-130B		8306100221	50-424 S
	8306010077*	CONTRACT		8306100221	50-424 S
	8306080265	FOIA		8306100231	50-424 S
	8306240012*	50-324 P		8306100231	50-424 S
	8306290633*	CONTRACT		8306100259	50-424 S
	8306020461	50-219 I		8306100259	50-424 S
	8306060487	50-289 P		8306100264	50-424 A
	8306010314	50-313 P		8306100264	50-424 A
	8306010329	50-320 S		8306100265*	50-424 A
	8306010351	50-289 Q		8306100267*	50-424 A
	8306010353	50-289 S		8306100267*	50-424 A
	8306010404	50-219 P		8306100274	50-424 S

CORPORATE SOURCE INDEX

509

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8306100274	50-424 S		8306100206	50-458
	8306130264	50-366 S		8306130317	50-458
	8306140075	50-321 P		8306130376	50-458
	8306140075	50-321 P		8306160353	50-458
	8306140246*	50-321 F		8306160439	50-458
	8306140246*	50-321 F		8306160520	50-458
	8306140254*	50-321 F		8306160521	50-458
	8306140254*	50-321 F		8306160531	50-458
	8306140493*	50-321 V		8306170395	50-458
	8306140563	50-366 Q		8306270095	50-458
	8306140743*	50-321 Q		8306270130	50-458
	8306150041*	50-321 F		8306270156	50-458
	8306150044*	50-321 F		8306270391	50-458
	8306150137*	50-321 F		8306280328	50-458
	8306150141*	50-321 F		8306280355	50-458
	8306150228	50-366 P		8306300121	50-458
	8306150232*	50-366 P	H&R Technical Associates, Inc	8306220320*	CONTRACT
	8306160267	50-321 P	HHS, Dept of, US Public Health Service	8306060402*	FOIA
	8306160267	50-321 P		8306220138*	CONTRACT
	8306160397	50-366 P	Hall, N	8306200134*	CONTRACT
	8306170202	50-321 F		8306280186	FOIA
	8306170382	50-321 R	Hamel, Park, McCabe & Saunders	8306010382	50-443
	8306200004	50-366 S	Harmon & Weiss	8306010446	50-443
	8306200202	50-321 S		8306150369	50-247
	8306200205	50-366 S		8306160337	PR
	8306200261	50-321 S		8306160604	50-289
	8306200374	50-321 S		8306220153*	50-537
	8306220002	50-321 P		8306230350	50-247
	8306220002	50-321 P		8306240003	FOIA
	8306220010*	50-321 P		8306290556	50-443
	8306220010*	50-321 P		8306300142	PR
	8306220310*	50-321 F	Harold J Spelman & Associates	8306080293	40-2061
	8306220313*	50-321 F		8306200042	40-2061
	8306240274	50-424 A	Harvard Univ	8009030104*	FOIA
	8306270120	50-366 P		8306170291*	FOIA
	8306270166	50-424 S		8306170295*	FOIA
	8306270170	50-366 P		8306170298*	FOIA
	8306270173*	50-366 P		8306280190	NUREG
	8306270328	50-366 S	Hepford, Swartz, Menaker & Morgan	8306280387	50-320
	8306280361	50-321 S	Heritage Foundation	8306160148*	FOIA
	8306280468	50-366 S		8306020333*	71-9080
	8306290264	50-321 Q	Hittman Nuclear & Development Corp		
	8306290264	50-321 Q	(subs Hittman Corp)	8306020340*	71-9080
	8306290265*	50-321 Q		8306020572*	71-9080
	8306290265*	50-321 Q		8306080340*	71-9017
	8306290303*	50-321 Q		8306080342*	71-9017
	8306290455	50-321 Q		8306130185*	71-9089
	8306290455	50-321 Q		8306130198*	71-9089
	8306300085	50-321 Q		8306130212*	71-9089
Geotechnical Engineers, Inc	8306170259*	CONTRACT	Hoke, Inc	8306030160	XPORTLI
				8306150345	XPORTLI
Gibbs & Hill, Inc (subs of Dravo Corp)	8306220305*	CONTRACT			
Gilbert/Commonwealth Cos	8306020420	REQD	House of Rep	8306020248*	50-322
	8306060059*	50-244 P		8306140323*	50-322
	8306140737*	50-289 F		8306300074	50-289
	8306200316*	50-244 P	House of Rep, Energy & Commerce	8306030158*	50-247
	8306220055*	50-302 P		8306060380*	COMMITTEE
	8306240312*	50-244 P			
Gilby Associates	8306300172	NUREG	House of Rep, Interior & Insular Affairs	8306060392*	50-272
Godfrey & Sundahl	8306200036	40-8714		8306220268*	50-289
Good, R P	8306200335	50-358 Q	Houston Lighting & Power Co	8306070112	50-498
				8306070204	50-498
Government Accountability Project	8306090284	50-528 A		8306100200	50-498
	8306160035	50-329 A			
	8306160192	FOIA		8306130350	50-498
	8306200345*	50-358 Q		8306170388	50-498
	8306200359*	50-358 Q		8306200122	50-498
				8306200122	50-498
	8306290498	50-329 Q		8306200126*	50-498
	8306290498	50-329 Q		8306200126*	50-498
	8306290330	50-329 Q		8306230460	50-498
	8306290530	50-329 Q		8306300077	50-498
	8306290551*	50-329 Q		8306300173	NUREG
Greater New York Council on Energy	8306200290	50-247 Q			
Greenblatt, D	8306090225	50-400 Q	Hovis, Cockrill, Weaver & Bjur	8306240128*	FOIA
Greeneville Metal Manufacturing, Inc	8306070308*	QA999	Human Design Group	8306230301*	50-320
	8306070312*	QA999	Hunton & Williams	8306010437	50-443
Guild, R	8306150385	50-413 Q		8306010443*	50-443
				8306030355	50-443
Gulf Nuclear, Inc	8306060394	71-210		8306030355	50-443
	8306010305	71-9163		8306030359*	50-443
Gulf States Utilities Co	8306010394	50-458 S		8306030359*	50-443
	8306010423	50-458 S		8306070405	50-321
	8306070195	50-458 S		8306080171	50-321
	8306070196	50-458 S			
	8306070265	50-458 S		8306080177*	50-321
	8306090038	50-458 S		8306090295	50-321
	8306090365	50-458 S		8306130404	50-321
	8306100206	50-458 Q		8306130411	50-321

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8306130446	50-322 Q			
	8306150370	50-322 Q	International Brotherhood of Electrical Workers	8306080095	ADVCM
	8306160287	50-322 Q	International Energy Associates, Ltd	8306160134*	FOIA
	8306220017	50-322 Q	International Generation & Transmission Co , Inc	8306210375*	CONTRACT
	8306300147	50-322 Q	Interstate Court Reporters, Inc	8306210323*	FOIA
IIT Research Inst	8306070465*	CONTRACT		8306210326*	FOIA
Ichthyological Associates, Inc	8306070219*	50-289 R			
	8306300164*	50-289 R			
Idaho National Engineering Laboratory	8306270157	NUREG	Iowa Electric Light & Power Co	8306060207	50-331 S
Illinois Institute of Technology	8306020437	50-434 G		8306090326*	50-331 Q
				8306100103	50-331 S
				8306130375	50-331 S
Illinois Power Co	8306130408	50-434 G		8306130378*	50-331 S
	8306020203	70-2947			
	8306070289	50-461 S			
	8306070338	50-461 S			
	8306070376	50-461 K		8306140590	50-331 Q
				8306160389	50-331 P
	8306070401*	50-461 K		8306160460	REGGD
	8306100060	50-461 S		8306170337	50-331 S
	8306100097	50-461 F		8306200223	50-331 R
	8306100141	50-461 B			
	8306170370	50-461 S		8306220348	50-331 P
				8306270089	50-331 Q
	8306170383	50-461 B		8306270290	50-331 B
	8306200407	50-461 F		8306270420	50-331 P
	8306200414*	50-461 F		8306270426*	50-331 P
	8306210231	50-461 A	Iowa State Univ		
	8306270117	50-461 Q	Isham, Lincoln & Beale	8306100275	50-116 Q
				8306010457	50-454 Q
	8306270321*	50-461 Q		8306020339	50-155 Q
	8306270334	50-461 S		8306060193	50-454 Q
Illinois, State of	8306090247	50-10 F		8306060193	50-454 Q
	8306140214	50-10 F			
Illinois, State of, Dept Nuc Safety (formerly Dept. Public Health)	8306240391	27-39		8306060196*	50-454 Q
				8306060315	50-329 Q
	8306090023	50-313 Q		8306080385	ADVCM
Illinois, Univ. of, Urbana-Champaign	8306020109	50-313 R		8306130445	50-454 Q
Indiana & Michigan Electric Co	8306020111*	50-313 R		8306130445	50-454 Q
	8306020118*	50-313 R			
	8306020186	50-316 R		8306130452*	50-454 Q
				8306130452*	50-454 Q
	8306020281	50-313 P		8306130402	50-454 G
	8306020281	50-313 P		8306130402	50-454 Q
	8306060183	50-313 S		8306130405	50-155 Q
	8306060183	50-313 S			
	8306060183*	50-313 S		8306130420	50-454 Q
				8306130420	50-454 Q
	8306060186*	50-313 B		8306200300	50-454 Q
	8306060269	50-316 S		8306200300	50-454 Q
	8306060271*	50-316 B		8306200300	50-454 Q
	8306060273*	50-316 S		8306200304	50-454 Q
	8306070208	50-315 P			
				8306220006	50-329 Q
	8306160343	50-315 R		8306220006	50-329 Q
	8306160358*	50-315 R			
	8306160367*	50-315 R		8306220023	50-155 Q
	8306160384	50-316 R		8306220065	50-155 Q
	8306170129	50-315 Q		8306220069	50-329 Q
				8306220069	50-329 Q
	8306210058	50-313 S		8306220102	50-155 Q
	8306210065*	50-313 Q			
	8306210065*	50-313 Q		8306220105	50-155 Q
	8306210074	50-316 S		8306270016	50-454 Q
	8306210128	50-313 S		8306270016	50-454 Q
				8306270020*	50-454 Q
	8306210134*	50-313 S		8306270020*	50-454 Q
	8306210142*	50-313 S			
	8306210167	50-313 P		8306270041	50-454 Q
	8306210259	50-313 S		8306270173	50-155 Q
	8306210267*	50-313 S		8306270383	50-454 Q
				8306270393	50-454 Q
	8306210273*	50-313 S		8306280528	50-454 Q
	8306210279*	50-313 S			
	8306210284*	50-313 S		8306280535	50-454 Q
	8306210325	50-316 S	Jacobs Engineering Group, Inc	8306200013*	WASTE MGT
	8306230333	50-313 F	Japan, Govt of	8306150468	XPQRTLIC
			Jersey Central Power & Light Co	8306030269	50-219 S
	8306270158	50-316 S	John A Blume & Associates, Engineers (subs URS Corp)	8306130238*	REVIEW GRP
	8306270161	50-316 S			
	8306270312	50-313 P			
	8306270433	50-313 S	Joint Applicants-Palo Verde	8306100078*	50-329 Q
	8306270436*	50-313 S		8306130304	50-329 Q
				8306130398	50-329 Q
	8306270444*	50-313 S	Joint Applicants-Bouth Texas Project	83062800308	50-498 Q
	8306270449*	50-313 S	Joint Intervenor-Diablo Canyon	8306010336	50-279 H
	8306300035	50-313 B			
Indiana, State of	8306200097	50-546 A		8306060182	50-275 Q
	8306280382	50-546 D		8306060182	50-275 Q
				8306070406	50-275 Q
	8306170461	71-9156		8306070406	50-275 Q
Industrial Nuclear Co	8306280122*	CONTRACT		8306150435	50-275 Q
Information Handling Services	8306070233	50-295 R		8306220038	50-275 Q
Institute of Nuclear Power Operations	8306020329*	CONTRACT		8306280565	50-275 P
Interior, Dept of	8306020336*	CONTRACT		8306290535	50-275 Q
				8306150368	50-382 Q
Interior, Dept. of, Fish & Wildlife Service	8306140161	50-456 A	Joint Intervenor-Waterford		
International Atomic Energy Agency (Austria)	8306140365	50-412 C		8306280541*	50-382 Q
	8306160186*	FOIA	Justice, Dept of, Attorney General, Office of	8306090501	ADVCM

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
KLM Engineering, Inc	8306140681	ADVCM		8306130442*	50-43*
Kaman Tempo	8306060008	FOIA		8306170371	50-43*
Kansas Gas & Electric Co	8306220253*	CONTRACT		8306200320	50-43*
	8306060191	50-482 K		8306200320	50-43*
	8306060194*	50-482 K		8306200327*	50-43*
	8306060195*	50-482 F		8306200327*	50-43*
	8306070194	50-482 S		8306200331*	50-43*
	8306070262	50-482 S		8306200331*	50-43*
	8306080175	50-482 A		8306270022	50-43*
	8306080178*	50-482 A		8306270023	50-43*
	8306080188*	50-482 Q	Ledoux & Co, Inc	8306140394	XPORTL
	8306090231	50-482 S	Leeds, Hill & Jewett, Inc	8306230198*	CONTRA
	8306130043	50-482 S	Leesburg, FL	8306030328*	50-30*
	8306130138	50-482 S	Lewis, M	8306020380	50-35*
	8306130393	50-482 Q		8306220043	50-35*
	8306140230	50-482 A		8306300130	PR
	8306140234*	50-482 A	Liberty Lines Transit, Inc	8306090323	50-24*
	8306150487*	50-482 F	Limerick Ecology Action	8306030280	50-35*
	8306160415	50-482 S		8306150362	50-35*
	8306160339	50-482 A		8306270300*	50-35*
	8306160365	50-482 S	Literature Research Corp	8306030271*	CONTRA
	8306160593	50-482 Q	Lodge, T J	8306030288	50-44*
	8306170386	50-482 S	Long Island Lighting Co	8306010011	50-32*
	8306200312	50-482 Q		8306010432	50-32*
	8306200318	50-482 Q		8306200455	50-32*
	8306220082	50-482 Q		8306060231	PR
	8306220358	50-482 Q		8306060352*	50-32*
	8306270088	50-482 Q		8306070013	50-32*
	8306270352	50-482 S		8306070038	50-32*
	8306280335	50-482 S		8306070321	50-32*
	8306300100	REQD		8306080171	50-32*
Kansas State Univ	8306160229	50-188 H		8306080177*	50-32*
Kansas, Univ of	8306080316*	50-148 P		8306080182*	50-32*
Karr & Lyons	8306290498	50-329 Q		8306090295	50-32*
	8306290498	50-329 Q		8306130236	50-32*
	8306290530	50-329 Q		8306130326	50-32*
	8306290530	50-329 Q		8306130404	50-32*
Kentucky, Univ of	8306030402*	CONTRACT		8306130411	50-32*
Kerr-McGee Chemical Corp (subs of	8306080399	40-2061		8306130446	50-32*
Kerr-McGee Corp)	8306130344	40-8027		8306140358*	50-32*
	8306300155	PR		8306140498*	50-32*
Kerr-McGee Corp	8306220140	40-8768		8306140607	50-32*
	8306240343	40-8027		8306140613*	50-32*
	8306300103	PR		8306140739	50-32*
Keyboard Communications, Inc	8306080417*	CONTRACT		8306150214*	50-32*
	8306200438	50-289 Q		8306150370	50-32*
Kilcoyne, J J	8306060184	50-322 Q		8306150373*	50-32*
Kirkpatrick, Lockhart, Hill, Christopher	8306060292	50-322 Q		8306150381*	50-32*
& Phillips	8306070381	50-322 Q		8306160087*	50-32*
	8306080169	50-322 Q		8306160089*	50-32*
	8306090216	50-322 Q		8306160091*	50-32*
	8306130423	50-322 Q		8306160100*	50-32*
	8306130395	50-322 Q		8306160104*	50-32*
	8306130397	50-322 Q		8306160108*	50-32*
	8306150401*	50-322 Q		8306160287	50-32*
	8306200337	50-322 Q		8306220017	50-32*
	8306220134	50-322 Q		8306220094	50-32*
	8306230337	50-312 Q		8306240230	50-32*
	8306280601	50-322 Q		8306240250	50-32*
	8306290480	50-322 Q		8306280042*	50-32*
	8306290483*	50-322 Q		8306280046*	50-32*
	8306290533	50-322 Q		8306280265	50-32*
	8306300081	50-322 Q		8306280445	50-32*
	8306300094	50-322 Q		8306280547	50-32*
	8306030327*	50-302 I		8306290393	50-32*
Kissimmee, FL	8306210433	XPORTLIC	Los Alamos Scientific Laboratory	8306290526	50-32*
Korea, Republic of (South Korea)	8306030449	FOIA		8306300147	50-32*
Laboratory of Clinical Medicine, Sioux	8306080274*	50-410 A		8306020193	NUREQ
Falls, SD	8304070100*	50-277 P		8306070422	REB
Lawler, Matuskay & Skelly Engineers	8306100135*	50-237 P		8306190377*	50-14*
Lawrence Livermore Laboratory	8306150064	50-272 P		8306280013	NUREQ
	8306150619	NUREQ		8306220117	50-45*
	8306290413*	50-245 P	Louisiana Consumer's League, Inc	8306010084	50-38*
	8306010168	50-341 K	Louisiana Power & Light Co	8306010223	50-38*
LeBoeuf, Lamb, Leiby & MacRae	8306160183	FOIA		8306010297	50-38*
	8306240158*	FOIA		8306060117	50-38*
	8306280527	50-289 Q		8306060120*	50-38*
League of Women Voters	8306300128	NUREQ		8306070133	50-38*
League of Women Voters of Rockford, IL	8306100201	50-454 Q		8306070169	50-38*
	8306150436*	50-454 Q		8306070274	50-38*
	8306150436*	50-454 Q		8306070307	50-38*
	8306150442*	50-454 Q		8306070317	50-38*
				8306070419	50-38*
				8306090411*	50-38*
				8306090416*	50-38*

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8306130204	50-382		8306140987*	50-329 A
	8306130280	50-382 E		8306140992*	50-329 A
	8306140002	50-382 S		8306140992*	50-329 A
	8306170268*	50-382 S		8306140997*	50-329 A
	8306170349*	50-382 G		8306140997*	50-329 A
	8306210124	50-382 A		8306140605*	50-329 A
	8306270052	50-382 S		8306140605*	50-329 A
	8306270127	50-382 S		8306010398	50-250 J
	8306270206	50-382 A	Marsh & McLennan, Inc	8306020128	50-244 J
	8306270213	50-382 S		8306020318	50-247 J
	8306270310	50-382 S		8306030338	TOPREP
	8306270330	50-382 S		8306030339*	TOPREP
	8306280342	50-382 R		8306230125	50-250 J
	8306300099	50-382 S		8306230283	50-29 J
	8306300166	50-382 A	Marubeni America Corp (subs of Marubeni Corp)	8306150463	XPORTLIC
Louisiana, State of	8306300188	50-382 S		8306150465*	XPORTLIC
	8306070090	50-382 A		8306160684	XPORTLIC
	8306130336	State Prog		8306160685*	XPORTLIC
Louisianians for Safe Energy, Inc	8306150488*	CONTRACT		8306090280*	CONTRACT
	8306220117	50-458 G	Maryland, State of	8306220168*	CONTRACT
Lowenstein, Neuman, Reis, Axelrad & Toll	8306030167	50-331 J			
	8306100200	50-478 G			
	8306160201	PR	Massachusetts Institute of Technology	8306030363*	50-443 G
	8306200308	50-478 G	Massachusetts, Commonwealth of,	8306070411	50-443 G
MPR Associates, Inc	8306020482*	CONTRACT	Materials Engineering Associates, Inc	8306060366	NUREG
				8306150081	NUREG
Maine Yankee Atomic Power Co	8306010408	50-309 S		8306170263	NUREG
	8306020146	50-309 P			
	8306020152	50-309 R		8306240062	NUREG
	8306020352	50-309 R	Maxima Corp	8306090284*	CONTRACT
	8306020425	50-309 S	Mayer, Brown & Platt	8306270239*	40-8610
			McGraw-Hill Publications Co	8306280193	FOIA
			Memphis State Univ	8306160273*	CONTRACT
	8306020524	50-309 P			
	8306030341	50-309 S	Mentor, KY	8306270410	50-358 G
	8306060305	50-309 G	Metal Hollows Corp	8306230277	50-482 S
	8306060310	50-309 P	Metropolitan Edison Co	8306010434	50-289 G
	8306060332	50-309 G		8306090211	50-289 G
				8306150410	50-289 G
	8306070290	50-309 G			
	8306070296	50-309 G		8306220071	50-289 G
	8306100276	50-309 G		8306290399*	50-289 G
	8306140273*	50-309 F		8306300050	50-289 G
	8306150263	50-309 F		8306300087	50-289 G
				8306060075	50-358 G
	8306160444	50-309 R	Miami Valley Power Project		
	8306170166	50-309 F			
	8306170177*	50-309 F	Michigan, Univ of	8306030256*	CONTRACT
	8306170186	50-309 S		8306090470*	CONTRACT
	8306170430	50-309 S		8306210453	ACRS
			Middle South Services, Inc	8306240262	TOPREP
	8306210175	50-309 G	Middle South Utilities, Inc - Middle	8306060225*	50-382 I
	8306230361	50-309 F	South Energy, Inc		
	8306230366*	50-309 F			
	8306270295	50-309 S	Minnesota Project	8306030379	FOIA
	8306280009	50-309 P	Minock, J	8306270218	50-341 G
			Mississippi Power & Light Co	8306010074	50-416 P
				8306010244	50-416 S
				8306010261	50-416 S
Maine, State of	8306290486	50-309 G			
	8306090218	50-309 G		8306020286	50-416 P
	8306100191	50-309 G		8306060038*	50-416 A
	8306100193*	50-309 G		8306060079	50-416 F
	8306100204	50-309 G		8306060079	50-416 F
				8306060236	50-416 P
Manhattan College	8306100205*	50-309 G			
Mapleton Intervenor	8306280389	50-199 H		8306070084	50-416 S
Mark G Jones Engineering Consultants, Inc.	8306080206	50-329 G		8306070142	50-416 S
	8306140532*	50-329 A		8306070228	50-416 S
				8306070230	50-416 S
	8306140534*	50-329 A			
				8306070237	50-416 S
	8306140539*	50-329 A		8306070410	50-416 S
	8306140540*	50-329 A		8306090134	50-416 S
	8306140540*	50-329 A		8306100219	50-416 S
	8306140544*	50-329 A		8306100235	50-416 S
	8306140546*	50-329 A		8306100235	50-416 S
	8306140546*	50-329 A		8306100251	50-416 S
	8306140548*	50-329 A		8306140046	50-416 S
	8306140548*	50-329 A		8306140084	50-416 S
	8306140552*	50-329 A		8306140259	50-416 S
	8306140552*	50-329 A		8306140259	50-416 S
	8306140555*	50-329 A		8306140384	50-416 S
	8306140555*	50-329 A		8306140434*	50-416 G
	8306140557*	50-329 A		8306140567*	50-416 G
	8306140557*	50-329 A		8306140611	50-416 S
	8306140560*	50-329 A		8306140669	50-416 S
	8306140560*	50-329 A		8306140724	50-416 P
	8306140566*	50-329 A		8306140729*	50-416 P
	8306140566*	50-329 A		8306160271	50-416 P
	8306140573*	50-329 A		8306160274*	50-416 P
	8306140573*	50-329 A			
	8306140579*	50-329 A		8306200121	50-416 S
	8306140579*	50-329 A		8306200133	50-416 S
	8306140587*	50-329 A		8306200133	50-416 S

CORPORATE SOURCE INDEX

51

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8306200142	50-416 S		8306160494	50-298
	8306200186	50-416 K		8306200106	50-298
	8306200186	50-416 K		8306270163	50-298
	8306200189*	50-416 K		8306280386	50-298
	8306200204	50-416 P		8306280444	50-298
	8306200250	50-416 S	Nebraska, State of	8306020463*	CONTRACT
	8306200412	50-416 R		8306230494*	CONTRACT
	8306210140	50-416 F	Neutron Products, Inc	8306240341	71-5364
	8306210140	50-416 F	New England Coalition on Nuclear	8306010382	50-443
	8306230167	50-416 P	Pollution		
	8306230167	50-416 P		8306030355	50-443
	8306270077	50-416 P		8306030355	50-443
	8306270080*	50-416 P		8306030359*	50-443
	8306270116	50-416 G		8306030359*	50-443
	8306270126	50-416 G		8306290363*	50-443
	8306270132	50-416 S		8306290356	50-443
	8306270165	50-416 S	New Hampshire, State of	8306010342	50-443
	8306270285	50-416 P		8306010342	50-443
	8306270346	50-416 S		8306010384	50-443
	8306270439	50-416 S		8306010384	50-443
	8306270439	50-416 S		8306270372	State Pr
	8306280188	50-416 S	New Jersey, State of	8306020047*	50-320
	8306280287	50-416 S	New York City Audubon Society	8306200324	50-247
	8306280329	50-416 S	New York, State Univ. of, Buffalo	8306170052*	50-57
	8306280471	50-416 S	New York, State of	8306010094	50-201
	8306280505	50-416 P		8306030176*	50-322
	8306280555	50-416 S		8306060231	PR
	8306290211	50-416 G		8306060233	PR
	8306290211	50-416 G		8306300158	PR
	8306300163	50-416 S		8306300176	PR
	8306300175	50-416 S	New York, State of, Energy Office	8306220123	50-410
Missouri, State of	8306160322*	50-483 G		8306290393	50-322
Missouri, Univ of, Columbia	8306150165	50-186 F	Newbury, MA	8306280312	50-443
Mitsubishi International Corp (subs of	8306240019	XPORTLIC	Niagara Mohawk Power Corp	8306010063	50-220
Mitsubishi Corp)	8306030165	XPORTLIC		8306010258	50-220
Mitsui & Co (USA), Inc (subs of Mitsui				8306010360	50-220
& Co, Ltd)				8306010412*	50-220
	8306160624	XPORTLIC		8306010453	50-410
	8306160724*	XPORTLIC		8306020094	50-220
Mitsui & Co, Ltd	8306140260	XPORTLIC		8306020158	50-220
	8306150458	XPORTLIC		8306020189	50-220
	8306150459	XPORTLIC		8306030352	50-220
	8306020230	40-8794		8306060199	50-220
Molycorp, Inc	8306070026*	FOIA		8306070034	50-220
Monick Reporting Co	8306070027*	FOIA		8306080273	50-410
	8306010095	40-6500		8306100143	50-220
Monsanto Co	8306020677	XPORTLIC		8306130303	50-410
Monsanto Research Corp				8306140440	50-410
	8306030194	40-6500		8306140443*	50-410
	8306030506	40-6500		8306140558*	50-410
Montgomery County, MD	8306220056	50-170 G		8306140564*	50-410
Morgan Associates	8306070414	50-247 G		8306200214	50-220
	8306150429	50-247 G		8306200258	50-410
	8306200342	50-247 T		8306200262	50-410
	8306230376	50-247 G		8306210182	50-410
	8306270160	50-247 G		8306210195	50-410
Motor Oils Refining Co	8306060302	50-454 G		8306210200	50-410
NUS Corp	8306160030	50-146 P		8306220096	50-410
	8306240349	FOIA		8306220104*	50-410
	8306280258	XPORTLIC		8306220107*	50-410
	8306280261*	XPORTLIC		8306270122	50-410
NUBAC, Inc	8306210344*	CONTRACT		8306270294	50-410
NUTECH Engineers, Inc	8306100136*	50-366 P		8306280255	50-410
	8306140549*	50-324 G		8306280422	50-220
	8306160366*	50-341 A		8306280424*	50-220
	8306170354*	50-263 P		8306280509	50-220
	8306230351*	50-331 P		8306280513*	50-220
National Lawyers Guild, Houston Chapter	8306160594	50-289 G		8306280550	50-410
				8306280597	50-410
Natural Resources Defense Council	8306090234	50-522 G		8306280605	50-410
	8306220146	50-537 G		8306300241	50-220
	8306220153*	50-537 G		8306200356*	50-367
	8306220157*	50-537 G	North Carolina Municipal Power Agencies	8306210410	ACRS
	8306270370	50-289 H	North Carolina State Univ	8306150378	50-322
	8306080326	71-9017	North Shore Committee Against Nuclear &		
Navy, Dept of	8306220158*	CONTRACT	Thermal Pollution		
	8306020148	50-298 R	Northeast Nuclear Energy Co. (subs of	8306010340	50-213
Nebraska Public Power District	8306060261	50-298 J	Northeast Utilities)		
	8306080061	50-298 F		8306010434	50-245
	8306080219*	50-298 G		8306020077	50-336
	8306100133	50-298 P		8306020084	50-245
	8306130339	50-298 S		8306020397	50-245
	8306140716	50-298 G		8306030317	50-245
	8306160464	50-298 P		8306030326	50-245
	8306160466	50-298 P		8306040090	50-213
	8306160477	50-298 R		8306040090	50-213
	8306160488	50-298 R			

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Northeast Utilities	8306060090	50-213 H	Northeast Utilities Service Co Northern States Power Co	8306280430	50-236 S
	8306060098	50-336 P		8306280478	50-245 P
	8306060143	50-423 A		8306280482	50-423 S
	8306060154	50-336 F		8306280534	50-245 P
	8306060207	50-213 P		8306300140	50-245 P
	8306060263	50-245 R		8306300140	50-245 P
	8306070136	50-245 F		8306160412	50-213 P
	8306080038	50-245 P		8305060453	50-263 Q
	8306090232	50-245 P		8306010349	50-282 P
	8306140361*	50-336 P		8306010441	50-263 P
Northeast Utilities	8306160388	50-245 R	Northeast Utilities Service Co Northern States Power Co	8306020088	50-263 R
	8306170042	50-336 S		8306020167	50-282 R
	8306170046	50-245 S		8306060084	50-263 Q
	8306170300	50-245 S		8306090230	50-282 P
	8306170391	50-213 Q		8306090230	50-282 P
	8306170391	50-213 Q		8306090237	50-282 F
	8306170391	50-213 Q		8306090237	50-282 F
	8306200104	50-336 S		8306090239*	50-282 F
	8306200313*	50-245 Q		8306090239*	50-282 F
	8306200322*	50-245 Q		8306090239*	50-282 F
Northeast Utilities	8306230289	50-245 P	Northeast Utilities Service Co Northern States Power Co	8306090261*	50-282 F
	8306240200	50-213 P		8306090263	50-282 F
	8306270129	50-245 S		8306100039	50-282 F
	8306270228	50-213 S		8306100057	50-282 F
	8306270255	50-336 P		8306130438	50-263 S
	8306280231	50-336 S		8306140002	50-282 R
	8306280321	50-245 P		8306140002	50-282 R
	8306280346	50-423 S		8306160430	50-263 F
	8306280353	50-336 S		8306170134	50-263 Q
	8306280412	50-245 P		8306170232	50-282 Q
Northeast Utilities	8306280414	50-336 Q	Northeast Utilities Service Co Northern States Power Co	8306170353	50-263 P
	8306280430	50-336 S		8306200109	50-263 R
	8306280478	50-245 P		8306200108	50-263 F
	8306280482	50-423 S		8306200390	50-282 P
	8306280534	50-245 P		8306200390	50-282 P
	8306300140	50-245 P		8306210094	50-263 F
	8306300140	50-245 P		8306230079*	50-282 F
	8306110936	50-245 I		8306230087*	50-282 F
	8306010340	50-213 P		8306280340	50-282 Q
	8306010434	50-245 S		8306280340	50-282 Q
Northeast Utilities	8306020077	50-336 R	Norton, Burke, Berry & French	8306280345*	50-282 Q
	8306020084	50-245 R		8306280345*	50-282 Q
	8306020397	50-245 S		8306280459	50-263 F
	8306020449	PR		8306060275	50-275 Q
	8306030319	50-245 S		8306160579	50-275 Q
	8306030326	50-245 S		8306160579	50-275 Q
	8306060090	50-213 H		8306160584*	50-275 Q
	8306060090	50-213 H		8306160584*	50-275 Q
	8306060090	50-213 H		8306160595*	50-275 Q
	8306060098	50-336 P		8306160595*	50-275 Q
Northeast Utilities	8306060143	50-423 A	Nuclear Assurance Corp	8306280520	50-275 Q
	8306060154	50-336 F		8306020199	50-266 F
	8306060207	50-213 P		8306100018	50-266 P
	8306060263	50-245 R		8306230166*	FOIA
	8306070136	50-245 F		8306230220*	CONTRACT
	8306080038	50-245 P		8306240457	71-9010
	8306090232	50-245 P		8306060034	FOIA
	8306130233	REVIEW ORP		8306160143*	FOIA
	8306140361*	50-336 P		8306080077	MISC
	8306160388	50-245 R		8306030338	TOPREP
Northeast Utilities	8306160412	50-213 P	Nuclear Club, Inc., The	8306030339*	TOPREP
	8306160412	50-213 P		8306300113	50-280 J
	8306160412	50-213 P		8306300116	TOPREP
	8306160424*	50-213 P		8304290092*	50-409 P
	8306160424*	50-213 P		8306020178*	50-271 P
	8306160424*	50-213 P		8306020184*	50-271 P
	8306170042	50-336 S		8306030283	70-143
	8306170046	50-245 S		8306080381	70-143
	8306170300	50-245 S		8306190269*	70-143
	8306170391	50-213 Q		8306160658	70-143
Northeast Utilities	8306170391	50-213 Q	Nuclear Fuel Services, Inc (subs of Getty Oil Co)	8306290572	70-143
	8306200104	50-336 S		8306290588	71-6357
	8306200313*	50-245 Q		8306290546	50-142 Q
	8306200322*	50-245 Q		8306030135	71-9159
	8306240200	50-213 P		8306070453	71-9182
	8306270129	50-245 S		8306070455*	71-9182
	8306270255	50-336 P		8306160098	FOIA
	8306270258*	50-336 S		8306160174	FOIA
	8306280231	50-336 S		8306030373	FOIA
	8306280321	50-245 P		8306060043*	50-546 A
Northeast Utilities	8306280346	50-423 S	Nuclear Law Center Nuclear Packaging, Inc	8306070372	50-135 Q
	8306280353	50-336 S		8306070375*	50-135 Q
	8306280412	50-245 P		8306070424	50-135 Q
	8306280414	50-336 Q			
	8306280321	50-245 P			
	8306280346	50-423 S			
	8306280353	50-336 S			
	8306280412	50-245 P			
	8306280414	50-336 Q			
	8306280414	50-336 Q			

CORPORATE SOURCE INDEX

5

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
Oak Ridge National Laboratory	8306010086	NUREG		8306210171*	50-275	
	8306020122	NUREG		8306230365	50-275	
	8306080041*	FOIA		8306230422	50-275	
	8306160631*	50-135	P	8306240318*	50-275	
	8306210324	NUREG		8306240398	70-2375	
Ocala, FL	8306210350	NUREG		8306280332	50-275	
	8306280080	50-259	P	8306280388	50-275	
	8306280089	NUREG		8306280394*	50-275	
	8306280093	NUREG		8306280396*	50-275	
	8306300325*	50-302	I	8306280421	50-275	
Office of Management & Budget Offshore Power Systems (subs of Westinghouse Electric Corp.)	8306070475	ORG		8306280451	50-275	
	8306230169*	50-416	P	8306280520	50-275	
	8306130367	40-8745		8306280520	50-275	
	8306060381	50-440	A	8306280522	50-275	
	8306270014	50-440	G	8306280523	50-275	
Ogle Petroleum, Inc	8306270014	50-440	G	8306280526	50-275	
	8306270017*	50-440	G	8306300041	50-275	
	8306270017*	50-440	G	8306300089*	50-275	
	8306290536	50-440	G	8306300093*	50-275	
	8306290536	50-440	G	8306300211	50-275	
Ohio Citizens for Responsible Energy	8306290549*	50-440	G	8306300217*	50-275	
	8306270549*	50-440	G	8306170374	50-322	
	8306010081	NUREG		8306220088	50-322	
	8306280569	50-112	P	8306270280	50-322	
	8306280581*	50-112	P	8306290505	50-322	
Oklahoma, Univ of	8306280594*	50-112	P	Pacific Legal Foundation		
	8306060153	50-285	P			
	8306060299	50-285	S			
	8306080236*	50-285	G			
	8306090032*	50-285	F			
Omaha Public Power District	8306100102	50-285	P	Pacific Power & Light Co	8306200213*	50-344
	8306100106*	50-285	P	Palmetto Alliance	8306060297	50-413
	8306130130*	50-285	G		8306100196	50-413
	8306130260	50-285	P		8306150385	50-413
	8306130364	50-285	G	Parameter, Inc	8306240050	NUREG
Orange County Alliance for Survival	8306160354*	50-285	F	Parents Concerned About Indian Point	8306060180	50-247
	8306200358	50-285	R		8306090300	50-247
	8306210360*	50-285	F		8306090300	50-247
	8306270105	50-285	P		8306090347	50-247
	8306280233	50-285	P		8306090347	50-247
Oregon, State of	8306280464	50-285	P		8306090350	50-247
	8306280487	50-285	P		8306090350	50-247
	8306300069	50-285	P	Pathfinder Mines Corp	8306140168	40-6622
	8306160046	50-206	G		8306160234	40-2259
	8306070044	50-243	S		8306160656	40-2259
Oregon, State of	8306230509*	CONTRACT		Paul, Weiss, Ripkind, Wharton & Garrison	8306210293	FOIA
	8306220084	50-361	G	Peabody International Corp	8306240443*	50-293
	8306210342	FOIA		Pennsylvania Power & Light Co	8306010061	50-387
	8306030348	MISC			8306010068	50-387
	8306240293*	QA999			8306010070	50-387
Overseas Packing, Inc	8306010347	50-275	R		8306010099	50-387
	8306020214	50-275	R		8306010150	50-387
	8306020309	50-133	R		8306010177*	50-387
	8306030162	50-275	P		8306010218	50-387
	8306030162	50-275	P		8306010278	50-387
Pacific Air Products Co	8306060155	50-275	F		8306010309	50-387
	8306060275	50-275	G		8306010313	50-387
	8306060275	50-275	G		8306010323	50-387
	8306070036	50-133	H		8306010330	50-387
	8306070270	50-275	P		8306010330	50-387
Pacific Gas & Electric Co	8306070275*	50-275	P		8306020223	50-387
	8306070278*	50-275	P		8306020369	50-387
	8306070292	50-275	R		8306020382	50-387
	8306070297*	50-275	R		8306020394	50-387
	8306100067	50-275	S		8306020401	50-387
Pacific Gas & Electric Co	8306100082	50-275	S		8306020429	50-387
	8306140031	50-275	P		8306020429	50-387
	8306140031	50-275	P		8306020444*	50-387
	8306160461	50-133	R		8306070214	50-387
	8306160526	50-275	R		8306090021*	50-387
Pacific Gas & Electric Co	8306160529*	50-275	R		8306090021*	50-387
	8306160535	50-275	R		830609026*	50-387
	8306160579	50-275	G		8306090246	50-387
	8306160579	50-275	G		8306140482	50-387
	8306160584*	50-275	G		8306140482	50-387
Pacific Gas & Electric Co	8306160584*	50-275	G		8306140648	50-387
	8306160595*	50-275	G		8306140648	50-387
	8306160595*	50-275	G		8306160472	50-387
	8306210044	50-275	S		8306170015	50-387
	8306210078	50-275	S		8306170037	50-387
Pacific Gas & Electric Co	8306210080	50-133	G		8306170188	50-387
	8306210111	50-275	P		8306170191*	50-387
	8306210162	50-275	R		8306170217	50-387
	8306210164	50-275	S		8306170250	50-388
					8306170413	50-387
				8306210050	50-387	
				8306210079	50-388	
				8306210143	50-387	
				8306210212	50-387	
				8306230297	50-387	

CORPORATE SOURCE INDEX

51

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8306300016	50-352 E		8306180429	50-247 Q
	8306300016	50-352 E		8306160385	50-286 R
	8306300024	50-352 A		8306160450	50-286 Q
	8306300024	50-352 A		8306170249	50-286 P
	8306300133	50-352 A		8306200139	50-333 B
	8306300133	50-352 A		8306200342	50-247 T
	8306300200	50-352 E		8306200342	50-247 T
	8306300200	50-352 E		8306200344*	50-333 Q
	8306300221	50-352 A		8306200346*	50-247 T
	8306300221	50-352 A		8306200346*	50-247 T
Philbrick, S S	8306240112*	FOIA		8306200375	50-333 S
Pickard, Lowe & Garrick, Inc	8306210336*	FOIA		8306200401	50-286 P
Plano Archaeological Consultants	8306230030*	40-8681		8306200403	50-286 F
Plateau Resources, Ltd	8306130347	40-7869		8306200411*	50-286 F
	8306140356	40-8698		8306210068	50-286 Q
	8306140367*	40-8698		8306210138	50-286 F
	8306220311	40-8674		8306210144	50-286 P
Porter Consultants, Inc.	8306240384	NUREG		8306210156	50-333 Q
Portland General Electric Co	8306010073	50-344 S		8306210178	50-286 P
	8306010316	50-344 P		8306210188*	50-286 P
	8306020119	50-344 R		8306220170	50-333 P
	8306030293	50-344 J		8306230174*	50-333 P
	8306070071	50-344 S		8306230376	50-247 Q
	8306070207	50-344 P		8306270160	50-247 Q
	8306070209	50-344 P		8306280486	50-333 S
	8306070211*	50-344 P		8306280508	50-333 P
	8306070212	50-344 S		8306300142	PR
	8306070213*	50-344 P	Power Engineering Society	8306160468	REGD
	8306130415	50-344 F	Professional Reactor Operator Society	8306080070	FOIA
	8306160392	50-344 R	Project Management Corp	8306270317	50-337 Q
	8306170193	50-344 S	Public Interest Research Group, New York	8306070421	50-247 Q
	8306170303	50-344 P		8306090300	50-247 Q
	8306170317	50-344 S		8306090300	50-247 Q
	8306170400	50-344 Q		8306090308	50-247 Q
	8306200152	50-344 R		8306090308	50-247 Q
	8306200191	50-344 F		8306090350	50-247 T
	8306200207	50-344 I		8306090350	50-247 T
	8306200210*	50-344 I		8306150389	50-247 Q
	8306230323	PR		8306230346	50-247 Q
	8306230414	REGD	Public Service Co of Colorado	8306010335	50-267 F
	8306230445	PR		8306010343	50-267 F
	8306240256	50-344 F		8306010344*	50-267 P
	8306240316	50-344 Q		8306010345*	50-267 P
	8306270394	50-344 H		8306010411	50-267 P
	8306280613	50-344 P		8306010416*	50-267 P
	8306280617*	50-344 P		8306010419*	50-267 P
	8306290242	PR		8306060130	50-267 P
Potter & Carmine	8306060010	50-354 Q		8306060134	50-267 S
Power Authority of the State of New York	8306010112	50-333 S		8306070103	50-267 P
	8306010312	50-333 S		8306070106*	50-267 P
	8306010346	50-286 S		8306070199	50-267 Q
	8306020450	50-286 S		8306140733	50-267 Q
	8306030224	50-286 P		8306160286	50-267 Q
	8306030345*	50-286 Q		8306160434	50-267 R
	8306060121	50-333 P		8306160541	50-267 P
	8306070185	50-286 P		8306210011	50-267 Q
	8306070197*	50-286 P		8306210253	50-267 Q
	8306070303	50-333 P		8306210373*	50-267 F
	8306070414	50-247 Q		8306280217	50-267 S
	8306080034	50-286 P		8306280228*	50-267 S
	8306090299	50-247 F		8306280236*	50-267 S
	8306090299	50-247 F		8306280246*	50-267 S
	8306090302	50-286 P		8306280260*	50-267 S
	8306090304*	50-286 P		8306280262*	50-267 S
	8306090307*	50-286 P		8306280264*	50-267 S
	8306090317	50-247 F		8306280272*	50-267 S
	8306090317	50-247 F		8306280278*	50-267 S
	8306090325	50-247 F		8306280283*	50-267 S
	8306090325	50-247 F		8306280288*	50-267 S
	8306090340	50-247 F		8306280293*	50-267 S
	8306090340	50-247 F		8306280298*	50-267 S
	8306090359	50-247 Q		8306280302*	50-267 S
	8306100017	50-333 R		8306280307*	50-267 S
	8306100100	50-333 P		8306280313*	50-267 S
	8306100113	50-286 P		8306280343	50-267 P
	8306100253	50-286 P		8306280354	50-267 P
	8306100256*	50-286 P		8306300039	50-267 F
	8306130111	50-286 I		8306300098	50-267 S
	8306130111	50-286 I		8306300104	50-267 Q
	8306130111	50-286 I		8306300107*	50-267 Q
	8306140153*	50-333 Q		8306300111*	50-267 Q
	8306140169*	50-333 Q	Public Service Co. of Indiana, Inc.	8306300187	50-267 Q
	8306140277	50-286 P		8306060039	50-346
	8306140318	50-333 P		8306060039	50-346
	8306140398	50-286 P		8306070144*	50-346

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Public Service Co of New Hampshire	8306070147*	50-546 Q	Public Service Co of New Hampshire	8306270304*	50-272 F
	8306070377	50-546 S		8306270343	50-272 S
	8306140596	50-546 A		8306280256	50-272 S
	8306140596	50-546 A		8306280488	50-272 S
	8306170182	50-546 S		8306280542	50-272 R
	8306270138	50-546 K		8306280542	50-272 R
	8306270138	50-546 K		8306280590*	50-354 Q
	8306270149*	50-546 C		8306290313	50-272 P
	8306270149*	50-546 C		8306290409	50-354 K
	8306270152*	50-546 K		8306290431*	50-354 K
	8306270152*	50-546 K		8306290432*	50-354 A
	8306270219	50-546 A		8306290435*	50-354 C
	8306270219	50-546 A		8306290444*	50-354 K
	8306270375	50-546 S		8306290448*	50-354 K
	8306010448	50-443 A		8306290449*	50-354 K
	8306010449*	50-443 Q		8306290451*	50-354 K
	8306030177	50-443 E		8306290454*	50-354 K
	8306030177	50-443 E		8306290456*	50-354 K
	8306080125	50-443 E		8306290457*	50-354 K
	8306080125	50-443 E		8306290458*	50-354 K
	8306150387	50-443 Q		8306290460*	50-354 K
	8306150387	50-443 Q		8306290465*	50-354 K
	8306150388	50-443 Q		8306290468*	50-354 K
	8306150388	50-443 Q		8306290469*	50-354 K
	8306170169	50-443 S		8306290471*	50-354 K
	8306200236	50-443 E		8306290473*	50-354 K
	8306200236	50-443 E		8306290474*	50-354 K
	8306200230	50-443 E		8306290477*	50-354 K
	8306200397	50-443 E		8306290478*	50-354 K
	8306200397	50-443 E		8306290479*	50-354 K
	8306230452	50-443 A		8306290482*	50-354 K
	8306280543	50-443 Q		8306290484*	50-354 K
	8306280545	50-443 S		8306290487*	50-354 K
	8306010328	50-311 S		8306290489*	50-354 K
Public Service Electric & Gas Co of New Jersey	8306020232	50-272 F		8306290491*	50-354 K
	8306020240*	50-272 F	Purdue Univ	8306290494*	50-354 K
	8306020240*	50-272 F		8306290497*	50-354 K
	8306020406	50-311 S		8306300190	50-272 P
	8306030141	50-272 P		8306300194*	50-272 P
	8306030141	50-272 P	R E Williams & Associates, Inc	8306080168	NUREG
	8306030188	50-311 S		8306230282	50-182 S
	8306030301	50-311 S		8306020263	40-2259
	8306030344	50-311 S		8306020269*	40-259
	8306030349	50-272 S	RBA Corp	8306200111	40-8584
	8306070150	50-272 F		8306060004*	FOIA
	8306070154	50-272 F		8306060005*	FOIA
	8306070177	50-272 Q		8306060012*	FOIA
	8306070177	50-272 Q	Radiac Research	8306060025*	FOIA
	8306090049	50-272 F		8306060033*	FOIA
	8306090049	50-272 F		8306080256	FOIA
	8306140036	50-272 V	Radiation Management Corp	8306270251*	50-387 R
	8306140036	50-272 V		8306010069	

CORPORATE SOURCE INDEX

51

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8306150309	50-244 Q	Science Applications, Inc	8209030325*	50-346
	8306160485	50-244 R		8209200365*	50-254
	8306170032	50-244 P		8209200370*	50-293
	8306170201	50-244 S		8211220337*	50-245
	8306200314	50-244 P		8306020583*	50-298
	8306210015	50-244 Q		8306090452*	CONTRACT
	8306210034	50-244 S		8306130328*	50-322
	8306220022	50-244 Q		8306160631*	50-155
	8306240177	50-244 P		8306220233*	CONTRACT
	8306240298	50-244 P		8306220276*	CONTRACT
	8306240302*	50-244 P		8306280057*	CONTRACT
	8306240311	50-244 P		8306280118*	CONTRACT
	8306270257	50-244 P		8306280147*	CONTRACT
	8306270360	50-244 P	Science Management Corp	8306090373	FOIA
Rochester, Univ of	8306030456	70-2982	Scripps-Howard Newspapers	8306210314	50-10
Rockland County, NY	8306200098	50-247 H	Seacoast Anti-Pollution League	8306010444	50-443
Rocky Mountain Energy Co	8306070450	40-8697		8306290521	50-443
	8306160329	40-8697		8306290532	50-443
	8306160567	40-8380	Senat#	8211160565*	50-204
	8306160576*	40-8380		8306150543*	50-272
	8306200425	40-8380		8306160131*	FOIA
Rondout Associates	8306200440	ACRS	Senate, Labor & Human Resources	8306140505*	CONTRACT
Ropes & Gray	8306060305	50-309 Q	Sensible Maine Power	8306020358	50-309
	8306060332	50-309 Q	Shaw, Pittman, Potts & Trowbridge	8306010390	50-400
	8306070290	50-309 Q		8306010390	50-400
	8306070296	50-309 Q		8306010395*	50-400
	8306150387	50-443 Q		8306010395*	50-400
	8306150387	50-443 Q		8306010434	50-289
	8306150388	50-443 Q		8306030329	50-289
	8306150388	50-443 Q		8306030336	50-400
	8306280543	50-443 Q		8306070291	50-400
Rothschild, D E	8306220117	50-458 G		8306070419	50-382
Roy F Weston, Inc	8306240057*	CONTRACT		8306090211	50-289
SEP Owners Group	8306130233	REVIEW GRP		8306100091	50-400
SPS Technologies	8306230028*	50-373 A		8306130390	50-289
Sacramento Municipal Utility District	8306010399	50-312 P		8306150410	50-289
	8306030029	71-5971		8306160314	50-483
	8306070067	50-312 S		8306160593	50-482
	8306070069	50-312 S		8306160596	50-440
	8306090233	50-312 P		8306160611	50-440
	8306090306	50-312 S		8306200312	50-482
	8306140126	50-312 P		8306200318	50-482
	8306140591	50-312 F		8306220071	50-289
	8306170223	50-312 S		8306220082	50-482
	8306170290	50-312 S		8306220108	50-400
	8306170358	50-312 S		8306220108	50-400
	8306170402	50-312 P		8306220111*	50-400
	8306170407*	50-312 P		8306220111*	50-400
	8306210048	50-312 P		8306220132	50-483
	8306210056	50-312 R		8306230345	50-400
	8306220040	50-312 P		8306230358	50-482
	8306220075	50-312 P		8306280514	50-482
	8306220150	50-312 P		8306290214	50-440
	8306230372	50-312 S		8306290395	50-400
	8306230393	50-312 F		8306290399	50-289
	8306230396	50-312 S		8306300087	50-289
	8306230410	50-312 S	Sheffield, Univ of	8306290281*	CONTRACT
	8306230447	50-312 P	Shorham Opponents Coalition	8306150379	50-322
	8306270133	50-312 P	Sierra Club	8306150384	50-358
	8306270260	50-312 P		8306200335	50-358
	8306270325	50-312 J		8306200341*	50-358
	8306300011*	50-312 Q		8306200372*	50-358
San Diego Gas & Electric Co	8306150002	50-361 K		8306220146	50-337
Sandia Laboratories	8303310226	50-245 P		8306220153*	50-337
	8306010041	NUREG		8306300142	PR
	8306010052	NUREG		8306300155	PR
	8306010081	NUREG	Simons, Li & Associates, Inc	8306210386*	CONTRACT
	8306010144	NUREG	Simpson, J M	8306290522	50-482
	8306020007	NUREG	Sinnissippi Alliance for the Environment	8306080143	50-454
	8306020016	NUREG	(SAFE)	8306080143	50-454
	8306020080	NUREG		8306080143*	50-454
	8306210020*	QA799		8306080143*	50-454
	8306240301*	50-247 Q		8306100201	50-454
	8306270141	NUREG		8306150436*	50-454
	8306270151	NUREG		8306150436*	50-454
	8306280033	NUREG		8306150442*	50-454
	8306280049	NUREG		8306150442*	50-454
	8306280190	NUREG		8306170371	50-454
Sandvik Special Metals Corp	8306160646	XPORTLIC		8306200327*	50-454
	8306160653	XPORTLIC		8306200327*	50-454
	8306160659	XPORTLIC		8306200331*	50-454
	8306160661	XPORTLIC		8306200331*	50-454
Sargent & Lundy, Inc	8305190373*	50-373 P		8306270022	50-454
Schwalb, Donnenfeld, Bray & Silbert	8306140789	ADVCM	Small Business Administration	8306090284*	CONTRACT
	8306200045	ADVCM			

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Snake River Alliance	8306300152	PR		8306220084	50-361 C
Snell & Wilmer	8306100078*	50-529 Q		8306220095	50-206 P
	8306150304	50-529 Q		8306220127	50-361 Q
	8306150398	50-529 Q		8306220127	50-361 Q
Source Production & Equipment Co., Inc.	8306030057*	71-9056		8306230211	50-361 Q
South Carolina Electric & Gas Co.	8306010325	50-395 Q		8306230266	50-361 S
	8306010357*	50-395 Q		8306230369	50-362 S
	8306010366*	50-395 Q		8306230467	50-362 S
	8306010374*	50-395 Q		8306240002	50-362 Q
	8306020142	50-395 R		8306240203	50-206 P
	8306020385	50-395 P		8306240208*	50-206 P
	8306070128	50-395 S		8306270172	50-206 J
	8306070202	50-395 S		8306270172	50-206 J
	8306070402	50-395 P		8306270362	50-361 P
	8306100142	50-395 S		8306280252	50-361 S
	8306100163	50-395 S		8306280267	50-361 S
	8306100208	50-395 S		8306280273	50-361 S
	8306100213	50-395 S		8306280350	50-361 S
	8306100261	50-395 S		8306280410	50-361 S
	8306130417	50-395 P		8306280466	50-206 P
	8306140088	50-395 S		8306290415	50-206 P
	8306140388*	50-395 Q		8306300057	50-361 P
	8306140457*	50-395 Q		8306300144*	50-361 P
	8306140670	50-395 S		8306240274	50-424 A
	8306160370	50-395 R	Southern Co. Services, Inc.	8306270166	50-424 S
	8306210021	50-395 S		8306240448*	50-293 P
	8306210209	50-395 S	Southwest Research Institute	8306240455*	50-293 P
	8306230086	50-395 P		8306240461*	50-293 P
	8306270136	50-395 S		8306202683	RES
	8306270289	50-395 S		8306270003*	50-237 P
	8306270356	50-395 P		8306160465	PRM
	8306280067	50-395 S	Southwest Research and Information Center	8306300219	PR
	8306280504	50-395 S		8306070189*	MISC
	8306290088	50-395 Q	Special-T-Metals Co., Inc.	8306160155	FOIA
	8306300018	50-395 S	Spiegel & McDiarmid	8305170121	NUREG
	8306300049	50-395 S	St. Louis Univ., St. Louis, MO		
	8306300122	50-395 S	Standardized Nuclear Unit Power Plant	8306030220	50-482 S
	8306300156	50-395 S	System		
	8306300196	50-395 S		8306070345	50-482 S
South Carolina, State of	8306220299*	50-413 F		8306100183	50-482 S
	8306300142	PR		8306140240*	50-482 A
Southampton, NY	8306280608*	50-322 Q		8306220018	50-482 A
Southern California Edison Co.	8306010142	50-206 F	State, Dept. of	8306020615	XPORTRIC
	8306010164*	50-361 Q		8306020645	XPORTRIC
	8306070029	50-361 Q	State, Dept. of, Bureau of Oceans & Intl	8306030011	XPORTRIC
	8306070029	50-361 Q	Environ. & Scientific Affairs		
	8306070313	50-361 P	Stepan Chemical Co.	8306020238	40-8610
	8306070313	50-361 P		8306020243*	40-8610
	8306080020	50-361 P		8306270239*	40-8610
	8306080020	50-361 P		8306060359*	50-322 A
	8306080210*	50-206 P	Stone & Webster Engineering Corp.	8306080294*	50-410 A
	8306090196	50-361 P		8306080298*	50-410 A
	8306090164*	50-361 P		8306080303*	50-410 A
	8306100034	50-361 S		8306080306*	50-410 A
	8306100069	50-361 S		8306080312*	50-410 A
	8306100072	50-361 S		8306080328*	50-410 A
	8306100098	50-361 S		8306080338*	50-410 A
	8306100111	50-206 Q		8306080343*	50-410 A
	8306100115	50-361 S		8306080351*	50-410 A
	8306130386	50-206 P		8306080360*	50-410 A
	8306130386	50-206 P		8306130308	50-329 A
	8306130386	50-206 P		8306160347	NUREG
	8306130392*	50-206 P		8306170350	50-275 R
	8306140007	50-361 S		8306290397	50-275 R
	8306140019	50-206 P		8306290401*	50-275 R
	8306140039	50-361 S		8306290545*	50-275 R
	8306140178	50-361 P	Stone & Webster, Inc.	8306100168	50-275 R
	8306140239	50-362 S		8306100171*	50-275 R
	8306140250	50-361 S		8306130444	TOPREP
	8306140444	50-361 P		8306230121	50-329 A
	8306140644	50-361 P		8306270262	50-329 A
	8306140644	50-361 P		8306270262	50-329 A
	8306140684	50-361 S		8306270271	50-329 V
	8306150002	50-361 K		8306270271	50-329 V
	8306150002	50-361 K		8306270309	50-329 A
	8306150303	50-206 P		8306060184	50-322 Q
	8306160275	50-361 K	Buffalo County, NY	8306060188*	50-322 Q
	8306160275	50-361 K		8306060292	50-322 Q
	8306160455	50-206 R		8306070381	50-322 Q
	8306160489	50-361 R		8306070386*	50-322 Q
	8306200156	50-206 P		8306080169	50-322 Q
	8306200381*	50-361 Q		8306090216	50-322 Q
	8306210113	50-361 S		8306090258	50-322 Q
	8306210352	50-361 S		8306130423	50-322 Q
	8306220004	50-206 P		8306150214*	50-322 Q
	8306220084	50-361 Q			

CORPORATE SOURCE INDEX

521

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8306150395	50-322 G		8306060102	50-259 X
	8306150401*	50-322 G		8306060102	50-259 X
	8306220134	50-322 G		8306070039	50-327 S
	8306220141*	50-322 G		8306070048	50-390 S
	8306280601	50-322 G		8306070059	50-296 S
	8306290480	50-322 G		8306070064	50-390 S
	8306290485*	50-322 G		8306070064	50-390 S
	8306290492*	50-322 G		8306070072	50-390 S
	8306300081	50-322 G		8306070072	50-390 S
	8306300094	50-322 G		8306070072	50-390 S
Sugarman, R J	8306220051	50-352 G		8306070072	50-390 S
	8306220051	50-352 G		8306070074	50-390 S
	8306220103	50-352 G		8306070074	50-390 S
Sunflower Alliance	8306220103	50-352 G		8306070074	50-390 S
	8306220080	50-440 G		8306070074	50-390 S
System Safety Society	8306160401	NUREG		8306070084	50-260 S
Stawlewicki, S A	8306060395*	CONTRACT		8306070087	50-259 S
TERA Corp	8306270067	50-329 R		8306070092	50-259 S
	8306270067	50-329 R		8306070099	50-260 S
	8306270069*	50-329 R		8306070121	50-438 S
	8306270069*	50-329 R		8306070132	50-327 F
Tallahassee, FL	8306030323*	50-302 I		8306070132	50-327 F
Target Rock Corp	8306130150	50-528 S		8306070138	50-390 S
Technical Operations, Inc	8306030489	71-9165		8306070138	50-390 S
	8306240440	71-6613		8306070138	50-390 S
Technical Specialties, Inc	8306270446*	CONTRACT		8306070138	50-390 S
Teknekron Research, Inc	8306090488*	CONTRACT		8306070160	50-438 S
Teledyne Engineering Services	8306010317	50-275 R		8306070160	50-438 S
	8306010319*	50-275 R		8306070188	50-438 S
	8306080068	50-275 P		8306070218	50-328 S
	8306100130	50-275 R		8306070241	50-259 S
	8306100134*	50-275 R		8306070266	50-296 S
	8306140616*	50-293 P		8306070284	50-327 S
	8306150615*	50-322 F		8306080006	50-390 A
	8306170270	50-275 R		8306080071	50-390 A
	8306170293	50-275 R		8306080071	50-390 A
	8306170312	50-275 R		8306080208	50-327 P
	8306170313	50-275 P		8306080208	50-327 P
	8306170315*	50-275 R		8306080212	50-327 P
	8306170328	50-275 P		8306080212	50-327 P
	8306200249	50-275 R		8306090135	50-390 S
	8306200252*	50-275 R		8306090135	50-390 S
	8306220053*	50-271 P		8306090135	50-390 S
	8306230326*	TOPREP		8306090135	50-390 S
	8306270416	50-275 R		8306090142	50-390 S
	8306270477*	50-275 R		8306090142	50-390 S
	8306280469	50-275 R		8306090159	50-259 S
	8306280470*	50-275 R		8306090310	50-438 S
	8306280483	50-275 R		8306090322	50-390 S
Teledyne Isotopes	8306020019	70-124		8306090331	50-259 S
	8306160689	XPORTLIC		8306090331	50-259 S
Teleflex, Inc	8306020415*	70-1224		8306090331	50-259 S
Tennessee Valley Authority	8306010014	50-328 S		8306100123	50-438 A
	8306010020	50-327 S		8306100173	50-328 S
	8306010113	50-390 S		8306100192	50-296 S
	8306010113	50-390 S		8306100239	50-390 S
	8306010136	50-390 S		8306130163	50-296 S
	8306010136	50-390 S		8306130242	50-328 S
	8306010143	50-390 S		8306130340	50-438 A
	8306010143	50-390 S		8306130340	50-438 A
	8306010169	50-328 S		8306130362	50-390 A
	8306010237	50-260 S		8306130362	50-390 A
	8306010251	50-438 S		8306140041	50-260 Q
	8306010251	50-438 S		8306140125*	50-438 Q
	8306010269	50-259 S		8306140142*	50-327 Q
	8306010269	50-259 S		8306140150*	50-438 Q
	8306010269	50-259 S		8306140266*	50-259 Q
	8306010274	50-390 S		8306140420*	50-390 Q
	8306010274	50-390 S		8306140427	50-390 S
	8306010274	50-390 S		8306140435	50-390 S
	8306010274	50-390 S		8306140466	50-390 S
	8306010274	50-390 S		8306140466	50-390 S
	8306010283	50-390 S		8306140526	50-327 R
	8306010283	50-390 S		8306140656	50-259 P
	8306010396	50-327 S		8306150094*	50-327 F
	8306010405	50-438 S		8306150098*	50-327 F
	8306010431	50-390 S		8306150243	50-259 P
	8306010431	50-390 S		8306150243	50-259 P
	8306010431	50-390 S		8306150243	50-259 P
	8306010431	50-390 S		8306150248*	50-259 P
	8306010431	50-390 S		8306150248*	50-259 P
	8306020197	50-327 R		8306150248*	50-259 P
	8306030504	70-2910		8306160453	50-260 P
	8306060102	50-259 X		8306160453	50-260 P
	8306060102	50-259 X		8306160456*	50-260 P

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8306160456*	50-260 P		8306210218	50-327 S
	8306160482	50-259 R		8306210226	50-260 S
	8306160507	50-259 P		8306210252	50-438 S
	8306160507	50-259 P		8306210270	50-259 S
	8306160507	50-259 P		8306210290	50-328 S
	8306160523*	50-259 P		8306220011	50-390 E
	8306160523*	50-259 P		8306220011	50-390 E
	8306160523*	50-259 P		8306230178	50-390 F
	8306160533	50-390 A		8306230178	50-390 F
	8306160533	50-390 A		8306230272	50-328 P
	8306170334	NUREG		8306230444	50-328 P
	8306170335	50-390 A		8306230453*	50-328 P
	8306170335	50-390 A		8306270007	50-259 F
	8306170423	50-296 S		8306270007	50-259 F
	8306200141	50-438 S		8306270007	50-259 F
	8306200141	50-438 S		8306270090	50-260 S
	8306200143	50-438 S		8306270250	50-327 S
	8306200143	50-438 S		8306270274	50-296 S
	8306200143	50-390 S		8306270327	50-260 S
	8306200145	50-390 S		8306270354	50-390 S
	8306200145	50-390 S		8306270354	50-390 S
	8306200155	40-1341		8306270371	50-296 S
	8306200167	50-327 S		8306270386	50-390 S
	8306200169	50-390 S		8306280092	50-438 S
	8306200169	50-390 S		8306280178	50-327 P
	8306200332	50-327 S		8306280192	50-327 S
	8306210004	50-438 S		8306280222	50-439 S
	8306210005	50-438 S		8306280369	50-438 S
	8306210005	50-438 S		8306280369	50-438 S
	8306210010	50-259 F		8306280375	50-260 S
	8306210010	50-259 F		8306280415	50-259 P
	8306210010	50-259 F		8306280415	50-259 P
	8306210010	50-259 F		8306280415	50-259 P
	8306210010	50-259 F		8306280425	50-438 S
	8306210010	50-259 F		8306280425	50-438 S
	8306210010	50-259 F		8306280426	50-390 S
	8306210010	50-259 F		8306280426	50-390 S
	8306210010	50-259 F		8306280479	50-438 S
	8306210014	50-259 P		8306280479	50-438 S
	8306210014	50-259 P		8306280567	50-259 P
	8306210016*	50-259 F		8306280567	50-259 P
	8306210016*	50-259 F		8306280573	50-390 S
	8306210016*	50-259 F		8306280578	50-390 S
	8306210016*	50-259 F		8306280578	50-390 S
	8306210016*	50-259 F		8306280578	50-390 S
	8306210016*	50-259 F		8306280578	50-390 S
	8306210016*	50-259 F		8306280578	50-390 S
	8306210016*	50-259 F		8306280612	50-390 R
	8306210016*	50-259 F		8306280612	50-390 R
	8306210016*	50-259 F		8306280619	50-438 S
	8306210018	50-438 S		8306280619	50-438 S
	8306210018	50-438 S		8306290203*	50-259 Q
	8306210027	50-327 P		8306290246*	50-438 Q
	8306210027	50-327 P		8306290246*	50-438 Q
	8306210032*	50-327 P		8306290250	50-259 Q
	8306210039	50-390 S		8306290275*	50-259 Q
	8306210039	50-390 S		8306290283*	50-259 Q
	8306210042	50-438 S		8306290283*	50-259 Q
	8306210051	50-390 S		8306290283*	50-259 Q
	8306210051	50-390 S		8306290316*	50-390 Q
	8306210051	50-390 S		8306290316*	50-390 Q
	8306210051	50-390 S		8306290319*	50-438 Q
	8306210051	50-390 S		8306290319*	50-438 Q
	8306210087	50-390 S		8306290388	50-327 Q
	8306210087	50-390 S		8306290400	50-259 P
	8306210088	50-390 S		8306290400	50-259 P
	8306210088	50-390 S		8306290400*	50-259 P
	8306210090	50-328 S		8306290408*	50-259 P
	8306210106	50-328 S		8306290408*	50-259 P
	8306210115	50-327 P		8306290408*	50-259 P
	8306210115	50-327 P		8306290510*	50-259 Q
	8306210116	50-390 S		8306300008	50-438 S
	8306210116	50-390 S		8306300008	50-438 S
	8306210117*	50-327 P		8306300013	50-390 S
	8306210117*	50-327 P		8306300013	50-390 S
	8306210136	50-260 S		8306300033	50-390 S
	8306210150	50-390 S		8306300033	50-390 S
	8306210165	TOPREP		8306300038	50-390 S
	8306210180	50-327 P		8306300038	50-390 S
	8306210180	50-327 P		8306300051	50-390 S
	8306210203*	50-259 Q		8306300051	50-390 S
	8306210203*	50-259 Q		8306300054	50-390 S
	8306210203*	50-259 Q		8306300054	50-390 S
	8306210217	50-390 E		8306300066	50-259 S
	8306210217	50-390 E		8306300082	50-390 S

CORPORATE SOURCE INDEX

52

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8306300082	50-390 S		8306090283*	50-346
	8306300139	50-259 S		8306090373*	50-346
	8306300177	50-259 P		8306100124	50-346
	8306300181	50-260 S		8306140448	50-346
	8306300205	50-390 S		8306140500	50-346
	8306300205	50-390 S		8306160540	50-346
	8306300208	50-259 S		8306160679*	50-346
	8306300214	50-390 S		8306160690*	50-346
	8306300214	50-390 S		8306170027	50-346
	8306300214	50-390 S		8306170075	50-346
	8306300214	50-390 S		8306170142	50-346
	8306300224	50-260 S		8306170276	50-346
	8306300228	50-390 S		8306170414	50-346
	8306300228	50-390 S		8306170429	50-346
	8306300245	50-438 S		8306200393	50-346
	8306300245	50-438 S		8306200394*	50-346
	8306300254	50-438 S		8306210026	50-346
Tennessee, State of	8306220222*	CONTRACT		8306210084	50-346
Texas A&M Univ., College Station, TX	8306010298*	50-128 H		8306210170*	50-346
	8306010350	50-128 P		8306210262	50-346
	8306010361*	50-128 P		8306220257*	50-346
	8306010389	50-128 R		8306220260*	50-346
	8306030045	71-5977		8306220263*	50-346
	8306060213	50-128 P		8306230259	50-346
	8306060216*	50-128 P		8306230262*	50-346
Texas Utilities Generating Co	8306010279	50-445 F		8306270204	50-346
	8306010392	50-445 A	Torrey Pines Technology	8306270379	50-346
	8306030330	50-445 Q		8306070354	50-358
	8306080239	50-445 G		8306070359	50-358
	8306080239	50-445 G		8306220078	50-358
	8306080241*	50-445 G		8306230131	50-358
	8306080241*	50-445 G		8306230133*	50-358
	8306080243*	50-445 G	Transnuclear, Inc	8306020580	XPOR TLIC
	8306080243*	50-445 G		8306150337	XPOR TLIC
	8306080248*	50-445 G		8306150426	XPOR TLIC
	8306090043	50-445 S		8306240375	71-9015
	8306090312	50-445 V	Transportation, Dept of	8306080341	71-4909
	8306090312	50-445 V	Trends Publishing, Inc	8306160041	FOIA
	8306090315*	50-445 V	Tri-State Motor Transit Co	8306200115	70-1739
	8306130440	50-445 S	Twomey, Latham & Shea	8306280608*	50-322 Q
	8306150366	50-445 G	URS Corp	8306130238*	REVIEW ORP
	8306150376	50-445 G	US Ecology, Inc (Formerly Nuclear Engineering)	8306020222	27-48
	8306150425	50-445 G		8306030105	71-6679
	8306170406	50-445 G		8306210435	27-48
	8306300055	50-445 S		8306240487	27-48
	8306300055	50-445 S		8306210313	FOIA
	8306300074	50-445 S	Underhill Range Committee	8306070109*	QA999
	8306300074	50-445 S	Unibraze Corp	8306070110*	QA999
	8306300088	50-445 S		8306080500	40-8584
	8306300088	50-445 S	Union 76 Minerals Exploration Co	8306140689	40-8584
	8306300167	50-445 S		8306270177	40-8584
	8306300167	50-445 S		8306020198	40-299
Texas Utilities Services, Inc	8306090162	50-445 A	Union Carbide Corp	8306020201*	40-299
	8306100153	50-445 A		8306020314	40-299
	8306100153	50-445 A		8306020320*	40-299
	8306130176	50-445 A		8306030064	70-687
	8306130193	50-445 A		8306070467	40-299
	8306130193	50-445 A		8306070470*	40-299
	8306130279	50-445 A		8306080348*	71-4909
	8306130279	50-445 A		8306080358*	71-4909
	8306130293	50-445 A		8306090364	50-54 P
	8306130293	50-445 A		8306010110	70-2945
	8306150102*	50-445 F	Union Electric Co	8306070145*	50-483 Q
	8306160503	50-445 Q		8306100147	50-483 A
	8306160506*	50-445 Q		8306100148*	50-483 A
	8306280400*	50-445 A		8306150455*	50-483 F
Texas, State of	8306150307	50-445 Q		8306160314	50-483 Q
	8306230491*	CONTRACT		8306160322*	50-483 Q
	8306280553	50-443 G		8306170279	50-483 B
The Southern Co	8306070127*	50-321 I		8306210198*	50-483 Q
	8306030054*	CONTRACT		8306220132	50-483 Q
Therman, B A	8306200320	50-454 G		8306220137*	50-483 Q
Thomas, D C	8306300213	50-454 G		8306230481*	50-483 Q
Three Mile Island Alert	8306020355	50-289 Q		8306270235	50-483 B
	8306020454	PR		8306290585	70-2945
	8306060279	50-289 G		8306300090*	50-483 Q
	8306270388	50-289 Q	Union Minerals	8306060415	40-8584
	8306280202	50-320 P	Union of Concerned Scientists	8306030007	50-320 Q
	8306300095	50-289 G		8306070418	50-289 Q
	8306300097*	50-289 Q		8306080028	FOIA
	8306020129	50-346 R		8306080238	FOIA
Toledo Edison Co	8306060137	50-346 S		8306150389	50-247 Q
	8306070166*	50-346 Q		8306160297	50-289 Q
	8306070397	50-346 Q		8306160604	50-289 Q
	8306090060*	50-346 F			

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
United Engineers & Constructors, Inc (subs of Raytheon Co.)	8306230350	50-247 G		8306140222*	50-338 P
	8306270159	50-247 G		8306160249	50-338 P
	8306300039	50-289 G		8306160249	50-338 P
	8306200242*	50-443 E		8306160266*	50-338 P
United Nuclear Corp	8306210112	50-443 S		8306160266*	50-338 P
	8306230458*	50-443 A		8306160375	50-280 R
	8306240243*	QA999		8306160399	50-338 F
	8306240245*	QA999		8306160405	50-338 P
	8306030502	70-371		8306160532	50-338 R
Uranerz USA, Inc Uranium Resources, Inc	8306080022	71-5641		8306170138	50-281 Q
	8306130450	70-820		8306170281	50-280 P
	8306290577	70-820		8306170281	50-280 P
	8306210353	40-8783		8306170327	50-280 P
Utah, Univ of	8306090028	40-8786		8306170327	50-280 P
	8306090035*	40-8786		8306170331*	50-280 P
	8306210425	40-8786		8306200114	50-339 S
	8306210451	40-8786		8306200207	50-339 S
	8306220130	40-8786		8306200219	50-280 Q
Vermont Yankee Decommissioning Alliance Vermont Yankee Nuclear Power Corp	8306060226	PR		8306200232	50-338 S
	8306160194*	50-72 F		8306210285	50-280 S
	8306210029	50-271 H		8306220033	50-280 P
	8306010246	50-271 P		8306220033	50-280 P
	8306010248*	50-271 P		8306220047*	50-280 P
Versar, Inc Victoreen, Inc (subs of Sheller-Globe Corp)	8306010379	50-271 P		8306220047*	50-280 P
	8306010383*	50-271 P		8306270005	50-280 S
	8306010435	50-271 P		8306270104	50-338 S
	8306010436*	50-271 P		8306270142	50-339 S
	8306020174	50-271 P		8306270183	50-339 S
Virginia Electric & Power Co	8306030112	50-271 P		8306270214	50-338 P
	8306080076	50-271 Q		8306270316	50-339 S
	8306090303	50-271 P		8306270351	50-281 S
	8306140283	50-271 P		8306270357*	50-281 S
	8306140489	50-271 Q		8306270364*	50-281 S
Virginia, Univ of, Charlottesville, VA Vollen, R J & Whicker, J M Washington Public Power Supply System	8306150161	50-271 P		8306270366	50-339 S
	8306170039	50-271 S		8306270430	50-338 S
	8306170068	50-271 R		8306280568	50-338 S
	8306170264	50-271 S		8306290331	50-280 Q
	8306200073	50-271 I		8306290387*	50-338 Q
Versar, Inc Victoreen, Inc (subs of Sheller-Globe Corp)	8306200388	50-271 Q		8306290387*	50-338 Q
	8306210118	50-271 Q		8306290561	71-5490
	8306210223	50-271 Q		8306300020	50-338 S
	8306220044	50-271 P		8306300036	50-404 A
	8306240170	50-271 P		8306300096	50-338 P
Virginia Electric & Power Co	8306280112	50-271 F		8306300149	50-280 K
	8306280173*	50-271 Q		8306300149	50-280 K
	8306170485*	CONTRACT		8306300151*	50-280 K
	8306240201*	QA999		8306300199	50-281 S
	8306240207*	QA999		8306300240	50-338 P
Virginia Electric & Power Co	8306240214*	QA999		8306140005	50-452 S
	8306240219*	QA999		8306100201	50-454 G
	8306240224*	QA999		8306010106	50-513 S
	8306240227*	QA999		8306010220	50-397 S
	8306020092	50-338 R		8306010236	50-397 A
Virginia Electric & Power Co	8306020159	50-280 R		8306010249	50-397 A
	8306020159	50-280 R		8306010368	50-397 Q
	8306020162*	50-280 R		8306010376	50-508 Q
	8306020168*	50-280 R		8306010400	50-397 F
	8306020168*	50-280 R		8306010413	50-397 A
Virginia Electric & Power Co	8306020173*	50-280 R		8306020104*	50-397 Q
	8306020173*	50-280 R		8306020365	50-460 Q
	8306020424	PR		8306030347	50-460 Q
	8306070148	50-339 S		8306030353	50-460 Q
	8306070173	50-338 S		8306070095	50-397 S
Virginia Electric & Power Co	8306070220	50-280 S		8306070113	50-460 S
	8306070238	50-281 S		8306080026	70-2990
	8306070243*	50-281 S		8306080039	50-397 A
	8306070245*	50-281 S		8306090207	50-508 C
	8306070249	50-339 S		8306090262	50-460 A
Virginia Electric & Power Co	8306070276	50-339 S		8306090337	50-460 Q
	8306070281	50-338 S		8306100117	50-508 A
	8306080225	50-338 P		8306100190	50-460 Q
	8306080225	50-338 P		8306130004	50-397 A
	8306080228*	50-338 P		8306140612	50-460 A
Virginia Electric & Power Co	8306080228*	50-338 P		8306150354	50-508 Q
	8306090137	50-338 S		8306160048*	50-305 F
	8306090158	50-338 S		8306160147	50-397 K
	8306090314	50-339 S		8306170184	50-508 A
	8306090318	50-338 S		8306170215	50-397 R
Virginia Electric & Power Co	8306100170	50-280 P		8306170222*	50-508 Q
	8306100186	50-281 S		8306170296	50-508 S
	8306140208	50-338 P		8306170426*	50-508 Q
	8306140208	50-338 P		8306200243	50-397 E
	8306140222*	50-338 P		8306200251*	50-397 E

525

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	B306210120	50-397 A		B306200267	50-266
	B306210154	50-308 A		B306210091	50-266
	B306230364	50-460 G		B306210091	50-266
	B306230373	50-308 A		B306210100	50-266
	B306240339	70-2990		B306210100	50-266
	B306240460	70-2990		B306210207	50-301
	B306270347	50-397 S		B306230261*	50-266
	B306270353*	50-397 S		B306230261*	50-266
	B306280453	50-397 E		B306230356	50-266
	B306280596	50-397 A		B306230356	50-266
	B306300047	50-460 G		B306270275	50-266
Washington State Univ	B306200131	50-27 F		B306270275	50-266
Washington, Univ of, Seattle, WA	B306140691	NUREG		B306280397	50-266
Waste Management Group, Inc	B306030476	WASTE MGT		B306280443	50-266
Water, Waste & Land, Inc	B306080350	40-299		B306300038	50-266
West Branch Conservation Association	B306080200	50-247 G	Wisconsin Public Service Corp	B306020395	50-305
West Newbury, MA	B306270256	50-443 G		B306070070	50-305
West Valley Agricultural Protection	B306030333	50-529 G		B306100189	50-305
Council, Inc	B306030333	50-529 G		B306140001	50-305
	B306030334*	50-529 G		B306140048	50-305
	B306030334*	50-529 G		B306160619	50-305
	B306030335*	50-529 G		B306170056	50-305
	B306030335*	50-529 G		B306200102	50-305
	B306100075	50-529 G		B306210041*	50-305
	B306100075	50-529 G		B306270110	50-305
	B306100078*	50-529 G		B306280373	50-305
	B306100078*	50-529 G		B306280378*	50-305
	B306150398	50-529 G	Wisconsin, Univ of, Madison	B306060272*	50-156
	B306150398	50-529 G		B306150321*	CONTRACT
Westchester County, NY	B306290550	50-247 G		B306210398	ACRB
Western Nuclear, Inc (subs of Phelps Dodge Corp)	B306200074	40-1162	Wolfbein, S L	B306200289*	CONTRACT
	B306230032	40-8684	Wyoming Mineral Corp	B306130245	40-8502
	B306060118*	70-1131		B306160215	40-8502
Westinghouse Electric Corp	B306080021	70-1131		B306200182	40-8502
	B306080021*	70-1131		B306240436	40-8502
	B306080327	71-4909	Wyoming, State of	B306060294	40-8064
	B306090012	XPORTLIC		B306200160	40-8697
	B306150167	PROJ		B306200179	40-8584
	B306150172*	PROJ		B306200276	40-8380
	B306160224	NUREG		B306210454	40-8064
	B306160433	PT21		B306220113	40-8584
	B306160672	XPORTLIC		B306220116	40-299
	B306170254	REG00		B306220118	40-299
	B306200402*	50-286 P		B306220121	40-2259
	B306230386	TOPREP		B306220126	40-8728
	B306230391*	TOPREP		B306220136	40-1162
	B306240205	50-369 P		B306230331	PR
	B306240313	TOPREP		B306240444	40-8768
	B306240314*	TOPREP	Yakima Indian Nation	B306280106	40-8348
	B306240315*	TOPREP		B306020225	27-48
	B306270355	PROJ		B306240096*	FOIA
	B306270434	PROJ		B306240101*	FOIA
	B306280392	50-445 A	Yankee Atomic Electric Co	B306240131*	FOIA
	B306280392	50-445 A		B306010165*	50-29
	B306280449	TOPREP		B306010448	50-443
	B306300120	50-445 A		B306010449*	50-443
	B306300120	50-445 A		B306020139	50-29
Westinghouse Operating Plants Owners Group	B306160284	TOPREP		B306020337	50-29
	B306160291*	TOPREP		B306030177	50-443
	B306160300*	TOPREP		B306030177	50-443
	B306160303*	TOPREP		B306070302	50-29
Williams-Robinette & Associates, Inc	B306220087	TOPREP		B306080125	50-443
	B306140438*	CONTRACT		B306080125	50-443
	B306150570*	CONTRACT		B306090291*	50-29
	B306220259*	CONTRACT		B306140067	50-29
	B306200273	FOIA		B306150293*	50-271
Wilner, Cutler & Pickering	B305020208	50-266 S		B306150299*	50-271
Wisconsin Electric Power Co	B305020231*	50-266 S		B306160382	50-29
	B306010428	50-266 P		B306170033	50-29
	B306010428	50-266 P		B306170169	50-443
	B306060078	50-266 S		B306170339	50-29
	B306060156	50-266 F		B306170398	50-29
	B306070086	50-266 P		B306170418	50-29
	B306070404	50-266 J		B306200236	50-443
	B306090183*	50-266 Q		B306200330	50-443
	B306130146	50-266 G		B306200330	50-443
	B306130146	50-266 G		B306200365*	50-29
	B306160460	REG00		B306200369*	50-29
	B306200137	50-266 R		B306200397	50-443
	B306200137	50-266 R		B306200397	50-443
	B306200260	50-266 P		B306210017	50-29
	B306200260	50-266 P		B306210024*	50-29
				B306230452	50-443
				B306280009	50-309
				B306280011*	50-309

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8306280107	50-29 S

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8306280144	50-29 S
	8306280545	50-443 S

REPORT NUMBER INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER	REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER
029-0A-80-PA R02	8306130328*	50-322 E		NUREG-0580 V12 N05	8306240048	NUREG	
0383-03 FA	8306070107*	50-329 S		NUREG-0606 V03 N02	8306210383	NUREG	
15183	8306090235	50-219 R		NUREG-0748 V03 N04	8306070016	NUREG	
186-02B-04	8306020383*	50-298 Q		NUREG-0800 FC	8306070437	NUREG	
22A7007	8306070114*	50-447 K		NUREG-0800 R04 ERR	8306010138	NUREG	
246B R00	8306140737*	50-269 F		NUREG-0831 S04	8306210331	50-416 E	
3572	8306240312*	50-244 P	04-4824-035	NUREG-0843 S02	8306010037	50-389 E	
77-1140895-00	8306140732*	50-269 P		NUREG-0843 S04	8306240036	50-389 E	
77-1141256-00	8306140746*	50-269 P		NUREG-0853 S02	8306060412	50-461 E	
77-1143707-00	8306160197*	50-313 P		NUREG-0856	8306240060	NUREG	
82-31 R00	8306270230*	50-324 P		NUREG-0869 FC ERR	8306010166	NUREG	
83-0002	8306010078*	50-528 S	DER 82-61	NUREG-0880 R01 FC	8306080158	NUREG	
8306010478	8306010478	RES	BNL-NUREG-32876	NUREG-0882 S01	8306210378	50-170 E	
8306020048	8306020048	RES	BNL-NUREG-32748	NUREG-0892 S03	8306010043	50-397 E	
8306020683	8306020683	RES		NUREG-0904	8306080146	40-206 I	
8306030435	8306030435	RES	BNL-NUREG-32824	NUREG-0910 R01	8306150588	NUREG	
8306070422	8306070422	RES		NUREG-0927 FC	8306060413	NUREG	
8306080229	8306080229	RES		NUREG-0936 V02 N01	8306010046	NUREG	
8306170192	8306170205*	RES		NUREG-0939	8306210362	NUREG	
8306240241	8306240241	RES	GMI-NUREG-1991	NUREG-0948 S02	8306150616	50-537 E	
906505	8306160545*	50-267 P	PED-81-2200	NUREG-0982	8306210317	50-57 E	
906577	8306160560*	50-267 P	PED-81-2200	NUREG-0986	8306240063	NUREG	
906624	8306070106*	50-267 P		NUREG-0987	8306020112	70-1201	
9763 006-S-N-5	8306230458*	50-413 A		NUREG-0992	8306210334	NUREG	
AEDD/N301	8306160057*	FOIA		NUREG-0993 FC	8306060419	NUREG	
ARTECH-83-001	8306020452*	50-247 Q		NUREG-0999	8306010018	NUREG	
8&RDE-COM4-1 NP R03	8306230443*	TOPREP		NUREG/BR-0015	8306010138	NUREG	
B31-F031 R23	8306130332*	50-322 E		NUREG/BR-0025 V09 N5	8306150574	NUREG	
BAW-1784	8306070286*	50-269 P		NUREG/BR-0031 V04 N7	8306290131	NUREG	
CEN-239	8306300125*	50-361 P		NUREG/CP-0043 ERR	8306220243	NUREG	
CEN-239 R01	8306300136*	50-361 P		NUREG/CP-0044 V01	8306170263	NUREG	MEA-2014
CPL-09-102 R00	8306140349*	50-324 Q		NUREG/CP-0044 V02	8306150081	NUREG	MEA-2014
DET-19-076-6 R00	8306160366*	50-341 A		NUREG/CR-1579	8306270157	NUREG	ENI CO-1049
EA-83-BR0-005	8306060149*	50-253 P		NUREG/CR-2006	8306020072	NUREG	BNL-NUREG-51341
EQO-HS-6263 DRFT	8306160641*	50-389 P	TAC 47015	NUREG/CR-2044	8306210324	NUREG	ORNL/NSIC-194
EQO-PHYS-6241	8306080161	50-335 P		NUREG/CR-2607	8306280033	NUREG	SAND82-0431
EPRI NP-1850-CCM V04	8306240263*	TOPREP		NUREG/CR-2640	8306240052	NUREG	PNL-4232
GA-A16829	8306160564*	50-267 P	UC-77	NUREG/CR-2766	8306140315	NUREG	
GP-R-74002	8306240012*	50-324 P		NUREG/CR-2767 ERR	8306010144	NUREG	SAND82-1292
GPC-07-102 R00	8306100136*	50-366 P		NUREG/CR-2785	8306010088	NUREG	BNL-NUREG-51551
IPB-701	8306170336*	50-390 A		NUREG/CR-2786	8306150602	NUREG	EPRI NP-2542
K/D-9400 R01	8306080358*	71-4909	22335	NUREG/CR-2789	8306280089	NUREG	ORNL/NSIC-210
K/TL/88-B8	8306080348*	71-4909	22335	NUREG/CR-2800 B01	8306020131	NUREG	PNL-4297
M1-LR-83-01	8306170320*	TOPREP		NUREG/CR-2809 V04	8306270146	NUREG	ORNL/TH-8397
MK1-03-008	8306230351*	50-331 P	N0-83-2093	NUREG/CR-2814 V03	8306020193	NUREG	LA-9649-PR
NEDO-22198	8306070174*	50-293 P	82NED084	NUREG/CR-2837 B01	8306020134	NUREG	PNL-4327
NF-1583 04 (NP)	8306080083*	50-324 P	NF-83-139	NUREG/CR-2839	8306010086	NUREG	ORNL/CSD-TH-190
NSP-48-1103 R01	8306170354*	50-263 P	ES2N400	NUREG/CR-2841	8306020007	NUREG	SAND82-1572
NUREG 0750 V16 N01	8306230317	NUREG		NUREG/CR-2843 V02	8306010041	NUREG	SAND82-1788
NUREG-0020 V07 N02	8306210401	NUREG		NUREG/CR-2874 V03	8306280093	NUREG	ORNL/TH-8443/V3
NUREG-0090 V09 N04	8306140324	NUREG		NUREG/CR-2906	8306280044	NUREG	BNL-NUREG-51580
NUREG-0304 V08 N01	8306030488	NUREG		NUREG/CR-2954	8306240373	NUREG	PNL-4264
NUREG-0422 S07	8306160665	50-369 F		NUREG/CR-2962	8306270141	NUREG	SAND82-2164
NUREG-0483 V05 N04	8306020144	NUREG		NUREG/CR-2965	8306150066	50-272 P	UCRL-93325
NUREG-0540 V05 N02	8306060419	NUREG		NUREG/CR-2969	8306020066	NUREG	BNL-NUREG-51590

REPORT NUMBER INDEX

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER	REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER
NUREQ/CR-2973	8306290080	50-259	P ORNL/TM-8332	RMC-TR-83-02	8306270251*	50-387	R
NUREQ/CR-3011	8306020053	NUREG	PNL-4491	RMC-TR-83-03	8306150270*	50-212	R
NUREQ/CR-3012 V01	8306010039	NUREG	PNL-4510	SAI-186-028-30	8209200365*	50-234	Q
NUREQ/CR-3012 V02	8306010067	NUREG	PNL-4510	SAI-186-028-33	8209200370*	50-293	Q
NUREQ/CR-3012 V03	8306010071	NUREG	PNL-4510	SAI-186-029-28	8209030325*	50-346	P
NUREQ/CR-3027 ERR	8306030485	NUREG	PNL-4523	SANDB2-2429	8211220337*	50-245	P
NUREQ/CR-3047	8306240050	NUREG	PARAMETER IE-12	SCE-1-A A06	8306130392*	50-206	P
NUREQ/CR-3085 V01	8306310226	50-245	P SANDB2-7212	SECY-82-025	8306160193*	FOIA	
NUREQ/CR-3087	8306140402	NUREG	PNL-4563	SECY-82-046	8306160198*	FOIA	
NUREQ/CR-3089	8306060410	NUREG		SECY-82-127	8204070018*	FOIA	
NUREQ/CR-3119 V02	8306150384	NUREG	ATR-83(3818)-1N	SECY-82-162A	8306060108*	FOIA	
NUREQ/CR-3131 V01	8306020080	NUREG	SANDB3-0417	SECY-82-210	8306160208*	FOIA	
NUREQ/CR-3156	8306270151	NUREG	SANDB2-2559	SECY-82-313	8306160216*	FOIA	
NUREQ/CR-3163	8306280049	NUREG	SANDB3-0245	SECY-82-475	8306030370*	FOIA	
NUREQ/CR-3164	8306010266	NUREG		SECY-83-219	8306240403	SLCY	
NUREQ/CR-3173	8305170121	NUREG		STD-R-02-011 R00	8306020392*	71-9080	22226
NUREQ/CR-3174 V01	8306080168	NUREG		STD-R-02-012 R00	8306130212*	71-9089	22286
NUREQ/CR-3183	8306240073	NUREG	PNL-7650	SWR-6901-002	8306270003*	50-237	P
NUREQ/CR-3185	8306280190	NUREG	SANDB2-7081	TER-C5257-388 DRFT	8306090397*	50-312	P TAC 08079
NUREQ/CR-3189	8306020016	NUREG	SANDB3-0356	TER-C5257-467	8306220196*	50-336	P TAC 42493
NUREQ/CR-3191	8306010081	NUREG	SANDB3-7012	TER-C5506-337/338/33	8306150266*	50-259	P TAC 07974
NUREQ/CR-3194	8306240078	NUREG	PNL-4653	TER-C5506-342	8306030310*	50-317	P TAC 07978
NUREQ/CR-3207	8306010094	50-201	P	TER-C5506-344/345 DR	8306030299*	50-315	P TAC 07980
NUREQ/CR-3210	8306020011	NUREG	EGG-2247	TER-C5506-346 DRFT	8306090388*	50-298	P TAC 07982
NUREQ/CR-3217	8306030009	NUREG	PNL-4662	TER-C5506-347 DRFT	8306020196*	50-302	P
NUREQ/CR-3219 V02	8306140407	NUREG	BNL-NUREG-51658	TER-C5506-363 DRFT	8305200714*	50-305	P TAC 16747
NUREQ/CR-3225	8306150619	NUREG	UCRL-53049	TER-C5506-365 DRFT	8306020037*	50-309	P TAC-08059
NUREQ/CR-3226	8306010052	NUREG	SANDB2-2450	TER-C5506-372/373 DR	8306030070*	50-338	P TAC 47112
NUREQ/CR-3228 V01	8306060766	NUREG	MEA-2012	TER-C5506-377	8306140424*	50-219	P TAC 47128
NUREQ/CR-3239	8306140774	NUREG	UCLA-ENG-8257	TER-C5506-379/380	8306060329*	50-277	P TAC 08070
NUREQ/CR-3245	8306020122	NUREG	ORNL/TM-8630	TER-C5506-384/385	8305230021*	50-282	P TAC 08075
NUREQ/CR-3248	8306070471	NUREG	PNL-4691	TER-C5506-394 DRFT	8306080252*	50-335	P TAC 08083
NUREQ/CR-3254	8306240058	NUREG	PNL-4683	TER-C5506-395/396 DR	8306030446*	50-280	P TAC 08084
NUREQ/CR-3263	8306280013	NUREG	LA-9729-MS	TER-C5506-403/404 DR	8306030512*	50-295	P TAC 08092
NUREQ/CR-3267	8306280085	NUREG	ANL-83-32	TF-382/0823A	8306290413*	50-245	P TAC 44384
NUREQ/CR-3281	8306240413	50-286	P BNL/NUREG-51670	TR-3310-1 R01	8306140616*	50-293	P
NUREQ/CR-3287	8306210350	NUREG	ORNL/TM-8763	TR-3709-1	8306230326*	TQPREP	
NUREQ/CR-3290	8306070452	NUREG		TR-MCM-112	8306010083*	50-520	S
NUREQ/CR-3291	8306070473	NUREG		TR-V-MCM-003	8306010087*	50-528	S
NUREQ/CR-3292	8306280096	NUREG	ANL-83-27	UCID-19115 R01	8304070100*	50-277	P
NUREQ/CR-3294	8306240062	NUREG	MEA-2016	UCID-19705	8306100135*	50-237	P
NUREQ/CR-3296	8306240384	NUREG	PCI-TR-224	UMTRA-DDE/AL-140 DR	8306080153*	WASTE MGT	
NUREQ/CR-3308 V01	8306140691	NUREG		URS/JAB 8050	8306130238*	REVIEW GRP	
OPS-39AB2 RA	8306230169*	50-416	P	UTEC ME 82-100	8306160194*	50-72	F
ORNL/NSIC-202	8306160631*	50-159	P	WAPD-LP(FE)-220 R03	8306010085*	71-6400	22304
ORNL/TM-8275	8306080041*	FOIA		WASH-1250	8306200040*	FOIA	
ORD-4207-13	8306010389	50-128	R	WCAP-10170 APP E	8306230391*	TQPREP	42320
PLC-0207 DRFT	8306210336*	FOIA		WDP-100	8306290626*	50-201	P
PR-T-79-012 R01	8306160670*	71-9134		YAEC-1336	8306280011*	50-309	P
PROAB3-0014A-GL07 R1	8306100272*	50-329	A	YAEC-1361	8306210024*	50-29	P

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

Items listed as enclosures are those indicated by an asterisk following the accession number in the indexes. The second column gives the accession number of the principal document under which the enclosure is listed. Knowing the accession number of the principal document, the date issued, and the category enables locating the title listing of the enclosure.

The subject category column in this index gives the docl number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8006200486	8306060003	83/03/21	FOIA
8007160084	8306060003	83/03/21	FOIA
8009030104	8306170089	83/04/14	FOIA
8010070140	8306170089	83/04/14	FOIA
8109210318	8306060051	83/04/07	50-287 P
8111040442	8306140394	83/05/24	XPORTLIC
8112030545	8306020024	83/05/12	50-498 A
8203090638	8306160081	83/04/19	FOIA
8204070018	8306030383	83/04/01	FOIA
8204090019	8306080388	83/05/24	50-508 A
8204120488	8306060051	83/04/07	50-416 A
8205170474	8306070019	83/04/05	50-206 P
8207280024	8306060051	83/04/07	50-313 P
8208050024	8306070019	83/04/05	50-206 P
8209030325	8306030503	83/05/13	50-346 P
8209200365	8306010179	83/05/19	50-254 Q
8209200370	8306030119	83/05/19	50-293 Q
8209210553	8306160186	83/04/28	FOIA
8210290150	8306280125	83/06/17	MISC
8211160565	8306160052	83/04/14	50-206 U
8211220332	8306060051	83/04/07	50-245 P
8211220337	8306060051	83/04/07	50-245 P
8212020236	8306200045	83/03/07	ADVCH
8302250381	8306140352	83/06/03	50-336 P
8303220042	8306170469	83/06/08	50-309 Q
8303220403	8306150121	83/05/31	TOPREP
8304070100	8306280156	83/06/14	50-277 P
8304110827	8304110818	83/03/10	50-334 S
8304190510	8305040657	83/04/28	CONTRACT
8304290092	8306210066	83/06/13	50-409 P
8305020231	8305020208	83/04/19	50-266 S
8305020555	8306010091	83/05/20	PR
8305040713	8305040708	83/04/20	CONTRACT
8305190373	8305190370	83/05/13	50-373 P
8305200714	8306010065	83/05/16	50-305 P
8305230021	8306170053	83/06/06	50-282 P
8305230135	8305110471	83/06/10	50-275 P
8305230345	8305110471	83/06/10	50-275 P
8305240443	8305240436	83/05/20	50-293 P
8305240448	8305240436	83/05/20	50-293 P
8305240455	8305240436	83/05/20	50-293 P
8305240461	8305240436	83/05/20	50-293 P
8305240612	8305240605	83/05/09	COMMIBBION
8305240624	8305240605	83/05/09	COMMIBBION
8306010028	8306010024	83/05/12	50-313 P
8306010077	8306010022	83/05/09	CONTRACT
8306010078	8306010072	83/05/18	50-528 S
8306010083	8306010072	83/05/18	50-528 S
8306010085	8306010001	83/04/22	71-6400
8306010087	8306010072	83/05/18	50-528 S

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8306010100	8306010096	83/05/17	50-29 Q
8306010107	8306010101	83/05/12	50-313 Q
8306010124	8306010121	83/05/16	50-387 Q
8306010126	8306010115	83/05/25	50-247 Q
8306010129	8306010117	83/05/11	CONTRACT
8306010134	8306010121	83/05/16	50-387 Q
8306010135	8306010132	83/05/14	50-267 Q
8306010141	8306010132	83/05/14	50-267 Q
8306010153	8306010148	83/05/17	70-371
8306010156	8306010151	83/05/31	50-358 K
8306010164	8306010159	83/05/25	50-361 Q
8306010165	8306010160	83/05/25	50-29 Q
8306010174	8306010168	83/05/27	50-341 K
8306010177	8306010171	83/05/26	50-387 Q
8306010178	8306010168	83/05/27	50-341 K
8306010182	8306010179	83/05/19	50-254 Q
8306010208	8306150490	83/06/08	50-213 Q
8306010229	8306010227	83/05/16	50-333 Q
8306010231	8306010227	83/05/16	50-333 Q
8306010239	8306010233	83/05/31	50-352 A
8306010240	8306010233	83/05/31	50-352 K
8306010243	8306010233	83/05/31	50-352 C
8306010248	8306010246	83/05/26	50-271 P
8306010298	8306010296	83/05/27	50-188 H
8306010304	8306010301	83/05/17	50-271 Q
8306010306	8306010303	83/05/17	50-213 Q
8306010319	8306010317	83/05/27	50-275 R
8306010320	8306010318	83/05/16	50-317 Q
8306010324	8306010318	83/05/16	50-317 Q
8306010327	8306010326	83/05/17	50-334 Q
8306010333	8306010332	83/05/26	50-348 Q
8306010339	8306010338	83/05/17	70-687
8306010344	8306010343	83/05/20	50-267 P
8306010345	8306010343	83/05/20	50-267 P
8306010356	8306010350	83/05/25	50-478 Q
8306010357	8306010325	83/05/23	50-395 Q
8306010361	8306010358	83/04/29	50-128 P
8306010366	8306010325	83/05/23	50-395 Q
8306010370	8306010365	83/05/16	50-247 Q
8306010371	8306010367	83/05/26	50-366 P
8306010374	8306010325	83/05/23	50-395 Q
8306010378	8306010365	83/05/16	50-247 Q
8306010380	8306010372	83/05/26	50-352 C
8306010383	8306010379	83/05/26	50-271 P
8306010395	8306010390	83/05/27	50-400 Q
8306010412	8306010402	83/05/25	50-220 Q
8306010416	8306010411	83/05/20	50-267 P
8306010419	8306010411	83/05/20	50-267 P
8306010429	8306010426	83/05/27	50-364 P
8306010436	8306010435	83/05/26	50-271 P

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

530

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8306010443	8306010437	83/05/27	50-443 O	8306030144	8306030142	83/05/16	50-461 O
8306010445	8306010438	83/05/09	50-278 S	8306030147	8306030142	83/03/16	50-461 G
8306010449	8306010442	83/05/25	50-443 G	8306030148	8306030146	83/05/17	50-546 G
8306020012	8306020009	83/05/13	50-315 P	8306030151	8306030149	83/05/16	50-440 G
8306020032	8306020025	83/05/18	70-2953	8306030158	8306030156	83/05/12	50-247 U
8306020037	8306020015	83/05/24	50-309 P	8306030176	8306030170	83/05/10	50-322 U
8306020047	8306020043	83/05/24	50-320 H	8306030179	8306030152	83/05/27	70-1201
8306020104	8306020099	83/05/27	50-397 G	8306030185	8306030180	83/05/20	50-483 G
8306020111	8306020109	83/04/12	50-315 R	8306030202	8306030198	83/05/18	50-546 G
8306020116	8306020107	83/05/19	50-324 G	8306030213	8306030209	83/05/19	50-374 G
8306020118	8306020109	83/04/12	50-315 R	8306030230	8306030223	83/05/27	50-155 P
8306020162	8306020159	83/04/14	50-280 R	8306030235	8306030231	83/05/20	50-309 P
8306020168	8306020159	83/04/14	50-280 R	8306030246	8306030242	83/05/24	50-329 M
8306020173	8306020159	83/04/14	50-280 R	8306030256	8306030252	83/04/06	CONTRACT
8306020178	8306020174	83/05/26	50-271 P	8306030266	8306030263	83/05/25	CONTRACT
8306020184	8306020174	83/05/26	50-271 P	8306030271	8306030268	83/05/19	CONTRACT
8306020187	8306020180	83/05/19	50-259 P	8306030281	8306030272	83/05/31	50-454 K
8306020196	8306020188	83/05/19	50-302 P	8306030284	8306030277	83/05/20	CONTRACT
8306020201	8306020198	83/05/09	40-299	8306030299	8306030290	83/05/16	50-315 P
8306020209	8306020205	83/05/20	50-331 P	8306030303	8306030298	83/05/26	50-334 G
8306020240	8306020232	83/05/20	50-272 F	8306030310	8306090426	83/05/27	50-317 P
8306020242	8306020229	83/05/09	50-322 U	8306030311	8306030307	83/05/20	50-348 P
8306020243	8306020238	83/03/16	40-8610	8306030312	8306030291	83/05/20	50-277 G
8306020248	8306020229	83/05/09	50-322 U	8306030316	8306030282	83/05/27	50-309 G
8306020264	8306020258	83/05/20	71-250	8306030317	8306030314	83/05/20	70-371
8306020269	8306020259	83/05/10	40-299	8306030322	8306030320	83/05/26	50-302 I
8306020290	8306020107	83/05/19	50-324 G	8306030323	8306030320	83/05/26	50-302 I
8306020303	8306020299	83/05/23	50-277 P	8306030324	8306030328	83/05/20	70-371
8306020308	8306020305	83/05/03	40-8681	8306030325	8306030320	83/05/26	50-302 I
8306020320	8306020314	83/04/27	40-299	8306030327	8306030320	83/05/26	50-302 I
8306020328	8306020326	83/05/11	40-8681	8306030328	8306030320	83/05/26	50-302 I
8306020329	8306020327	83/05/26	CONTRACT	8306030334	8306030333	83/06/01	50-529 G
8306020334	8306020331	83/04/29	40-8686	8306030335	8306030333	83/06/01	50-529 G
8306020336	8306020333	83/05/26	CONTRACT	8306030339	8306030338	83/04/21	TOPREP
8306020376	8306020378	83/05/20	50-354 G	8306030345	8306030343	83/05/23	50-286 G
8306020379	8306020378	83/05/26	50-277 P	8306030351	8306030349	83/05/31	50-272 S
8306020389	8306020381	83/05/20	50-244 G	8306030359	8306030355	83/06/01	50-443 G
8306020391	8306020387	83/05/20	70-698	8306030363	8306030355	83/06/01	50-443 G
8306020392	8306020387	83/05/20	70-698	8306030370	8306030366	83/04/01	FOIA
8306020403	8306020400	83/05/20	50-244 G	8306030371	8306030369	83/05/11	COMMISSION
8306020404	8306020402	83/05/20	50-317 G	8306030375	8306030369	83/05/11	COMMISSION
8306020405	8306020399	83/05/31	70-2948	8306030388	8306030383	83/04/01	FOIA
8306020407	8306020402	83/05/20	50-317 G	8306030390	8306030383	83/04/01	FOIA
8306020413	8306020409	83/05/18	50-293 G	8306030395	8306030383	83/04/01	FOIA
8306020415	8306020408	83/05/31	70-1224	8306030402	8306030400	83/05/27	CONTRACT
8306020416	8306020409	83/05/18	50-293 G	8306030446	8306030441	83/05/16	50-280 P
8306020434	8306020427	83/05/20	50-244 G	8306030453	8306030454	83/04/19	FOIA
8306020444	8306020442	83/05/20	50-387 G	8306030478	8306030474	83/05/23	XPORTRIC
8306020447	8306020443	83/05/20	50-219 G	8306030492	8306030489	83/05/12	71-9165
8306020448	8306020443	83/05/31	50-247 G	8306030500	8306030498	83/05/19	50-320 P
8306020452	8306020443	83/05/31	50-247 G	8306030512	8306030508	83/05/19	50-295 P
8306020460	8306020458	83/05/20	50-244 G	8306060004	8306060003	83/03/21	FOIA
8306020463	8306020459	83/05/16	CONTRACT	8306060005	8306060003	83/03/21	FOIA
8306020482	8306020460	83/05/20	CONTRACT	8306060006	8306060003	83/03/21	FOIA
8306020498	8306210463	83/06/07	NUREG	8306060007	8306060003	83/03/21	FOIA
8306020509	8306020503	83/04/06	40-1341	8306060009	8306060003	83/03/21	FOIA
8306020511	8306020503	83/05/25	50-309 P	8306060012	8306060003	83/03/21	FOIA
8306020513	8306020506	83/05/20	CONTRACT	8306060014	8306060011	83/04/19	FOIA
8306020533	8306020528	82/05/13	71-9080	8306060015	8306060003	83/03/21	FOIA
8306020540	8306020528	82/05/13	71-9080	8306060016	8306060013	83/04/15	50-354 G
8306020572	8306020560	83/05/19	50-278 P	8306060017	8306060003	83/03/21	FOIA
8306020574	8306020568	83/05/19	50-298 G	8306060018	8306060013	83/04/15	50-354 G
8306020583	8306020568	83/05/19	50-298 G	8306060019	8306060003	83/03/21	FOIA
8306020587	8306020568	83/05/19	50-298 G	8306060020	8306060003	83/03/21	FOIA
8306020592	8306020528	82/05/13	71-9080	8306060021	8306060013	83/04/15	50-354 G
8306020646	8306020638	83/05/17	70-2985	8306060022	8306060003	83/03/21	FOIA
8306020659	8306020653	83/05/19	XPORTRIC	8306060023	8306060013	83/04/15	50-354 G
8306020676	8306020692	83/05/20	TOPREP	8306060024	8306060003	83/03/21	FOIA
8306030016	8306030012	83/05/18	50-336 P	8306060025	8306060003	83/03/21	FOIA
8306030027	8306030022	83/05/25	71-6142	8306060026	8306060003	83/03/21	FOIA
8306030054	8306030048	83/05/17	CONTRACT	8306060027	8306060013	83/04/15	FOIA
8306030057	8306030053	83/05/05	71-9086	8306060028	8306060003	83/03/21	FOIA
8306030060	8306030061	83/05/06	XPORTRIC	8306060030	8306060003	83/03/21	FOIA
8306030070	8306030067	83/05/17	50-338 P	8306060031	8306060003	83/03/21	FOIA
8306030078	8306030073	83/05/13	50-313 F	8306060033	8306060003	83/03/21	FOIA
8306030088	8306030020	83/05/24	50-397 A	8306060035	8306060003	83/03/21	FOIA
8306030090	8306030067	83/05/25	71-6003	8306060038	8306060003	83/03/21	FOIA
8306030130	8306030119	83/05/19	50-293 G	8306060041	8306060003	83/03/21	FOIA
8306030134	8306030119	83/05/19	50-293 G	8306060043	8306060039	83/05/31	50-546 A
8306030143	8306030159	83/05/17	50-254 G	8306060047	8306060044	83/05/31	50-255 P

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

53

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8306060053	8306060003	83/03/21	FOIA	8306060395	8306060391	83/04/28	CONTRACT
8306060055	8306060048	83/05/31	50-329 Q	8306060396	8306060393	83/04/05	FOIA
8306060058	8306060051	83/04/07	50-416 A	8306060399	8306060391	83/04/28	CONTRACT
8306060059	8306060057	83/05/27	50-244 P	8306060402	8306060400	83/04/06	FOIA
8306060060	8306060056	83/05/18	50-498 Q	8306070007	8306070005	83/05/24	50-528 Q
8306060061	8306060051	83/04/07	50-245 P	8306070011	8306070009	83/05/20	50-344 Q
8306060066	8306060051	83/04/07	FOIA	8306070017	8306070015	83/05/23	50-344 Q
8306060067	8306060063	83/05/31	50-313 Q	8306070021	8306070019	83/04/05	50-206 P
8306060073	8306060069	83/05/17	50-498 Q	8306070026	8306070025	83/03/03	FOIA
8306060074	8306060071	83/05/31	50-358 A	8306070027	8306070025	83/05/03	FOIA
8306060076	8306060051	83/04/07	50-269 P	8306070028	8306070019	83/04/05	50-206 P
8306060080	8306060051	83/04/07	50-287 P	8306070042	8306070033	83/06/01	50-358 Q
8306060085	8306060051	83/04/07	50-269 P	8306070052	8306070044	83/03/24	50-286 Q
8306060101	8306060099	83/06/01	50-358 E	8306070061	8306070050	83/06/01	50-250 Q
8306060108	8306060104	83/03/29	FOIA	8306070063	8306070062	83/05/31	50-255 P
8306060109	8306060105	83/05/27	50-317 P	8306070065	8306070057	83/05/12	50-312 Q
8306060116	8306060111	83/05/18	50-498 Q	8306070068	8306070075	83/03/11	50-344 Q
8306060118	8306060114	83/04/06	70-1151	8306070085	8306070082	83/06/03	50-341 Q
8306060120	8306060117	83/05/30	50-382 I	8306070098	8306070093	83/03/11	50-275 Q
8306060122	8306060111	83/05/18	50-498 Q	8306070106	8306070103	83/03/19	50-267 P
8306060124	8306060114	83/04/06	70-1151	8306070107	8306070104	83/05/24	50-529 B
8306060126	8306060125	83/05/20	50-267 Q	8306070109	8306070108	83/06/02	GA997
8306060131	8306060128	83/05/17	50-112 Q	8306070110	8306070108	83/06/02	GA997
8306060132	8306060129	83/05/23	50-388 Q	8306070111	8306070105	83/06/02	50-447 K
8306060133	8306060128	83/05/17	50-112 Q	8306070114	8306070105	83/05/24	50-447 K
8306060138	8306060129	83/05/23	50-358 Q	8306070127	8306070123	83/06/02	50-321 I
8306060149	8306060145	83/05/27	50-255 P	8306070130	8306070123	83/06/02	50-321 I
8306060150	8306060157	83/05/27	50-277 F	8306070134	8306070131	83/06/02	50-369 P
8306060165	8306060160	83/05/23	50-245 Q	8306070144	8306070139	83/06/01	50-546 Q
8306060166	8306060162	83/05/23	50-277 Q	8306070145	8306070137	83/06/01	50-483 Q
8306060169	8306060167	83/05/23	40-672	8306070146	8306070140	83/05/24	50-317 Q
8306060170	8306060162	83/05/23	50-277 Q	8306070147	8306070139	83/06/01	50-546 Q
8306060171	8306060160	83/05/23	50-245 Q	8306070157	8306070152	83/05/17	50-312 Q
8306060172	8306060167	83/05/23	40-672	8306070159	8306070156	83/05/25	50-317 P
8306060173	8306060163	83/05/23	70-364	8306070163	8306070158	83/06/02	GA997
8306060176	8306060163	83/05/23	70-364	8306070166	8306070155	83/06/01	50-346 Q
8306060177	8306060167	83/05/23	40-672	8306070170	8306070167	83/05/31	50-293 P
8306060179	8306060167	83/05/23	40-672	8306070171	8306070168	83/06/02	GA997
8306060185	8306060183	83/05/27	50-315 B	8306070174	8306070167	83/05/31	50-293 P
8306060186	8306060183	83/05/27	50-315 B	8306070176	8306070152	83/05/17	50-312 Q
8306060188	8306060184	83/05/31	50-322 Q	8306070189	8306070186	83/06/02	HISC
8306060192	8306060189	83/05/27	50-329 A	8306070190	8306070175	83/06/03	50-254 Q
8306060194	8306060191	83/05/31	50-402 K	8306070197	8306070185	83/06/01	50-286 P
8306060195	8306060191	83/05/31	50-402 F	8306070210	8306070206	83/05/27	50-415 E
8306060196	8306060193	83/05/31	50-454 Q	8306070211	8306070207	83/06/03	50-344 P
8306060204	8306060200	83/05/23	50-334 Q	8306070213	8306070207	83/06/03	50-344 P
8306060211	8306060205	83/05/23	50-423 Q	8306070219	8306070215	83/06/01	50-289 R
8306060212	8306060208	83/05/31	50-254 Q	8306070226	8306070223	83/05/24	50-277 Q
8306060214	8306060200	83/05/23	50-334 Q	8306070243	8306070238	83/05/27	50-281 B
8306060215	8306060210	83/05/23	50-322 Q	8306070244	8306070240	83/05/13	50-206 Q
8306060216	8306060213	83/05/30	50-128 P	8306070245	8306070238	83/05/27	50-281 B
8306060217	8306060218	83/05/19	50-295 Q	8306070250	8306070247	83/06/03	50-255 P
8306060220	8306060217	83/05/23	50-219 Q	8306070253	8306070252	83/05/25	50-528 Q
8306060221	8306060218	83/05/19	50-295 Q	8306070259	8306070251	83/05/16	50-206 Q
8306060224	8306060223	83/05/23	50-220 Q	8306070256	8306070252	83/05/25	50-528 Q
8306060225	8306060117	83/05/30	50-382 I	8306070261	8306070251	83/05/16	50-206 Q
8306060227	8306060223	83/05/23	50-220 Q	8306070279	8306070270	83/05/27	50-275 P
8306060234	8306060230	83/05/23	50-333 Q	8306070277	8306070271	83/06/02	50-209 Q
8306060237	8306060230	83/05/23	50-333 Q	8306070278	8306070270	83/05/27	50-275 P
8306060242	8306060241	83/05/20	50-483 Q	8306070280	8306070272	83/05/31	50-269 P
8306060244	8306060241	83/05/20	50-483 Q	8306070286	8306070272	83/05/31	50-269 P
8306060248	8306060246	83/04/27	PRM	8306070287	8306070285	83/05/20	50-243 Q
8306060251	8306060247	83/05/19	50-263 Q	8306070294	8306070288	83/06/02	GA997
8306060258	8306060257	83/05/23	50-309 Q	8306070297	8306070292	83/05/27	50-275 R
8306060262	8306060260	83/05/23	50-320 Q	8306070299	8306070295	83/06/03	50-352 Q
8306060266	8306060260	83/05/23	50-320 Q	8306070301	8306070295	83/06/03	50-352 Q
8306060267	8306060264	83/05/23	50-286 Q	8306070306	8306070304	83/06/04	50-445 Q
8306060268	8306060265	83/05/25	50-327 Q	8306070308	8306070305	83/06/02	GA997
8306060271	8306060269	83/05/27	50-316 B	8306070312	8306070305	83/06/02	GA997
8306060272	8306060270	83/06/01	50-156 Q	8306070336	8306070331	83/06/02	GA997
8306060273	8306060269	83/05/27	50-316 B	8306070339	8306070333	83/05/13	50-206 Q
8306060293	8306060289	83/05/26	50-412 Q	8306070346	8306070344	83/05/24	50-271 Q
8306060309	8306060307	83/06/03	70-25	8306070352	8306070349	83/05/31	50-413 F
8306060329	8306280138	83/06/14	50-277 P	8306070353	8306070344	83/05/24	50-271 Q
8306060352	8306060349	83/05/19	50-322 A	8306070357	8306070351	83/05/31	50-321 P
8306060359	8306060349	83/05/19	50-322 A	8306070368	8306070361	83/05/13	50-361 Q
8306060367	8306060362	83/05/27	40-2061	8306070369	8306070360	83/05/03	50-275 Q
8306060374	8306060369	83/05/16	COMMISSION	8306070374	8306070363	83/06/02	50-277 P
8306060380	8306060369	83/05/16	COMMISSION	8306070375	8306070372	83/05/30	50-155 Q
8306060392	8306060388	83/05/16	50-272 U	8306070376	8306070363	83/06/02	50-277 P

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

532

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8306070378	8306070364	83/03/09	50-312 Q	8306080267	8306080259	83/04/06	FOIA
8306070379	8306070363	83/06/02	50-277 P	8306080269	8306080259	83/04/06	50-443 Q
8306070383	8306070363	83/06/02	50-277 P	8306080270	8306080268	83/04/11	FOIA
8306070384	8306070380	83/06/02	50-313 Q	8306080274	8306080273	83/06/06	50-410 A
8306070385	8306070364	83/05/09	50-312 Q	8306080294	8306080273	83/06/06	50-410 A
8306070386	8306070381	83/06/03	50-322 Q	8306080298	8306080273	83/06/06	50-410 A
8306070387	8306070363	83/06/02	50-277 P	8306080302	8306080297	83/04/06	40-2061
8306070391	8306070363	83/06/02	50-277 P	8306080303	8306080273	83/06/06	50-410 A
8306070392	8306070388	83/06/01	50-454 Q	8306080304	8306080277	83/04/12	50-478 Q
8306070394	8306070382	83/06/04	50-445 Q	8306080306	8306080273	83/06/06	50-410 A
8306070395	8306070363	83/06/02	50-277 P	8306080308	8306080277	83/04/12	50-498 Q
8306070398	8306070363	83/06/02	50-277 P	8306080310	8306080277	83/04/12	50-478 Q
8306070401	8306070396	83/05/31	50-461 K	8306080312	8306080273	83/06/06	50-410 A
8306070403	8306070363	83/06/02	50-277 P	8306080316	8306080313	83/04/06	50-148 P
8306070407	8306070271	83/06/02	50-289 Q	8306080328	8306080273	83/06/06	50-410 A
8306070431	8306070428	83/05/27	50-370 P	8306080334	8306080326	83/05/03	71-9017
8306070434	8306070428	83/05/27	50-370 P	8306080336	8306080326	83/03/03	71-9017
8306070442	8306070435	83/06/02	40-2061	8306080338	8306080273	83/06/06	50-410 A
8306070446	8306070444	83/05/31	50-461 E	8306080339	8306080326	83/03/03	71-9017
8306070447	8306070444	83/05/31	50-461 E	8306080340	8306080326	83/05/03	71-9017
8306070451	8306070444	83/05/31	50-461 E	8306080342	8306080326	83/05/03	71-9017
8306070455	8306070453	83/05/16	71-9182	8306080343	8306080273	83/06/06	50-410 A
8306070458	8306070453	83/05/16	71-9182	8306080348	8306080341	83/05/12	71-4709
8306070465	8306070464	83/05/18	CONTRACT	8306080351	8306080273	83/06/06	50-410 A
8306070468	8306070466	83/05/25	MISC	8306080358	8306080341	83/05/12	71-4709
8306070470	8306070467	83/03/28	40-299	8306080360	8306080273	83/06/06	50-410 A
8306080004	8306080003	83/06/03	50-250 Q	8306080376	8306080373	83/05/31	70-2838
8306080007	8306080006	83/05/11	50-390 A	8306080411	8306080408	83/06/03	71-9016
8306080023	8306080021	83/04/29	70-1151	8306080417	8306080413	83/06/01	CONTRACT
8306080041	8306080031	83/03/25	FOIA	8306080427	8306080419	83/05/24	CONTRACT
8306080046	8306080042	83/03/21	50-267 Q	8306080442	8306080439	83/05/18	50-322 T
8306080048	8306080044	83/05/31	50-440 A	8306090002	8306090001	83/03/31	71-9111
8306080056	8306080052	83/06/01	70-2910	8306090006	8306090004	83/05/31	71-6601
8306080057	8306080053	83/06/06	50-443 Q	8306090017	8306090014	83/05/31	71-9026
8306080072	8306080067	83/06/02	CONTRACT	8306090021	8306090018	83/06/06	50-387 F
8306080074	8306080069	83/04/04	50-382 Q	8306090026	8306090018	83/06/06	50-387 F
8306080077	8306080078	83/04/20	50-382 Q	8306090027	8306090024	83/06/06	50-219 F
8306080083	8306080080	83/05/31	50-324 P	8306090031	8306090024	83/06/06	50-219 F
8306080107	8306080101	83/03/01	ADVCH	8306090032	8306090029	83/06/01	50-205 F
8306080124	8306080119	83/03/01	40-8722	8306090035	8306090028	83/04/28	40-8786
8306080127	8306080123	83/05/27	50-312 F	8306090036	8306090030	83/05/25	71-2
8306080129	8306080109	83/04/13	50-285 Q	8306090037	8306090034	83/05/27	71-9010
8306080133	8306080128	83/04/04	50-498 Q	8306090044	8306090041	83/05/26	50-219 Q
8306080134	8306080109	83/04/13	50-285 Q	8306090060	8306090057	83/06/01	50-346 F
8306080140	8306080137	83/06/02	50-358 E	8306090069	8306090067	83/05/27	50-322 Q
8306080145	8306080143	83/05/31	50-454 Q	8306090074	8306090070	83/05/31	71-6244
8306080153	8306080148	83/05/26	WASTE MGT	8306090076	8306090067	83/05/27	50-322 Q
8306080155	8306080150	83/06/02	50-498 Q	8306090131	8306090128	83/05/27	50-322 Q
8306080156	8306080152	83/04/04	40-8027	8306090132	8306090129	83/03/07	40-8698
8306080159	8306080150	83/06/02	50-498 Q	8306090138	8306090129	83/03/07	40-8698
8306080165	8306080152	83/04/06	40-8027	8306090143	8306090140	83/05/26	50-352 Q
8306080177	8306080171	83/06/03	50-322 Q	8306090151	8306090140	83/05/26	50-352 Q
8306080178	8306080175	83/06/06	50-482 A	8306090164	8306090156	83/06/07	50-361 P
8306080182	8306080171	83/06/03	50-322 Q	8306090167	8306090163	83/02/02	40-8084
8306080188	8306080184	83/06/06	50-482 Q	8306090175	8306090163	83/02/02	40-8084
8306080190	8306080181	83/03/07	40-8681	8306090179	8306090172	83/04/15	40-8663
8306080193	8306080181	83/03/07	40-8681	8306090185	8306090177	83/06/06	50-266 Q
8306080197	8306080192	83/03/04	50-313 Q	8306090193	8306090190	83/05/25	50-334 P
8306080201	8306080199	83/06/03	50-275 P	8306090203	8306090201	83/06/01	50-255 F
8306080205	8306080203	83/06/06	50-358 Q	8306090208	8306090204	83/06/01	50-348 F
8306080210	8306080209	83/06/03	50-206 P	8306090223	8306090221	83/06/02	50-454 F
8306080211	8306080109	83/04/13	50-285 Q	8306090226	8306090219	83/06/02	50-277 P
8306080216	8306080214	83/06/06	50-361 Q	8306090228	8306090224	83/05/18	40-8452
8306080219	8306080217	83/05/19	50-298 Q	8306090239	8306090237	83/05/31	50-282 F
8306080221	8306080220	83/04/14	50-445 Q	8306090241	8306090238	83/05/27	50-245 Q
8306080222	8306080218	83/06/06	50-445 Q	8306090244	8306090243	83/05/27	50-329 Q
8306080224	8306080218	83/06/06	50-445 Q	8306090245	8306090243	83/05/27	50-329 Q
8306080227	8306080218	83/06/06	50-445 Q	8306090257	8306090254	83/06/01	50-282 F
8306080228	8306080225	82/11/22	50-338 P	8306090259	8306090255	83/06/01	70-2910
8306080235	8306080232	83/06/02	50-155 Q	8306090261	8306090254	83/06/01	50-282 F
8306080236	8306080231	83/03/29	50-285 Q	8306090269	8306090265	83/05/31	70-2926
8306080237	8306080234	83/05/31	50-346 P	8306090271	8306090268	83/06/01	50-289 F
8306080238	8306080192	83/03/04	50-313 Q	8306090272	8306090267	83/06/08	50-245 P
8306080241	8306080239	83/06/06	50-445 Q	8306090274	8306090265	83/05/31	70-2926
8306080243	8306080239	83/06/06	50-445 Q	8306090275	8306090273	83/06/03	50-528 F
8306080248	8306080239	83/06/06	50-445 Q	8306090276	8306090273	83/06/03	50-528 F
8306080252	8306080251	83/05/24	50-335 P	8306090279	8306090278	83/06/03	71-9015
8306080263	8306080259	83/04/06	50-443 Q	8306090280	8306090277	83/05/09	CONTRACT
8306080264	8306080259	83/04/06	50-443 Q	8306090283	8306090281	83/06/01	50-346 F
8306080266	8306080259	83/04/06	50-443 Q	8306090284	8306090282	83/06/02	CONTRACT

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8306090287	8306090285	83/06/01	50-255 F	8306130230	8306130226	83/06/07	50-249 P
8306090291	8306090289	83/06/01	50-27 F	8306130238	8306130233	83/04/29	REVIEW QRP
8306090304	8306090302	83/06/03	50-286 P	8306130261	8306130255	83/03/25	50-445 Q
8306090307	8306090302	83/06/03	50-286 P	8306130263	8306130258	83/06/01	50-315 Q
8306090315	8306090312	83/06/06	50-445 V	8306130273	8306130258	83/06/01	50-315 Q
8306090324	8306090319	83/03/23	50-348 Q	8306130292	8306130285	83/06/10	50-341 Q
8306090326	8306090316	83/06/03	50-331 Q	8306130305	8306130299	83/06/08	50-440 Q
8306090332	8306090329	83/06/06	50-348 Q	8306130314	8306130311	83/06/10	50-409 Q
8306090354	8306090349	83/04/13	50-285 Q	8306130319	8306130298	83/06/10	50-346 Q
8306090355	8306090352	83/06/03	50-250 P	8306130328	8306130326	83/06/06	50-322 E
8306090360	8306090358	83/05/26	50-271 Q	8306130331	8306130326	83/06/06	50-322 E
8306090366	8306090358	83/05/26	50-271 Q	8306130332	8306130326	83/06/06	50-322 E
8306090375	8306090370	83/06/06	50-346 F	8306130333	8306130330	83/03/27	50-305 Q
8306090379	8306090376	83/04/13	FOIA	8306130335	8306130334	83/06/07	50-255 F
8306090380	8306090377	83/05/21	50-309 P	8306130343	8306130341	83/03/31	50-454 Q
8306090388	8306090386	83/05/26	50-298 P	8306130345	8306130341	83/03/31	50-454 Q
8306090394	8306090391	83/06/01	50-261 F	8306130356	8306130356	83/06/09	50-245 P
8306090397	8306090393	83/03/31	50-312 F	8306130372	8306130368	83/06/02	50-329 A
8306090411	8306090406	83/06/06	50-388 F	8306130377	8306130371	83/06/09	50-142 T
8306090416	8306090406	83/06/06	50-382 F	8306130378	8306130375	83/06/08	50-331 B
8306090432	8306090430	83/05/27	50-220 P	8306130379	8306130371	83/06/09	50-142 T
8306090452	8306090447	83/05/27	CONTRACT	8306130391	8306130387	83/06/09	50-322 E
8306090470	8306090467	83/05/25	CONTRACT	8306130392	8306130386	83/06/09	50-206 P
8306090488	8306090484	83/05/25	CONTRACT	8306130395	8306130390	83/06/10	50-289 Q
8306090492	8306090426	83/05/27	50-317 P	8306130402	8306130397	83/05/23	0A999
8306100014	8306100009	83/04/11	50-275 Q	8306130407	8306130403	83/05/27	50-537 A
8306100032	8306100009	83/04/11	50-312 Q	8306130410	8306130397	83/05/23	0A999
8306100036	8306100009	83/04/11	50-206 Q	8306130412	8306130405	83/05/27	50-254 Q
8306100038	8306100009	83/04/11	50-312 Q	8306130416	8306130413	83/05/23	0A999
8306100039	8306100009	83/04/11	50-312 Q	8306130418	8306130414	83/06/10	50-322 Q
8306100040	8306100009	83/04/11	50-312 Q	8306130422	8306130413	83/05/23	0A999
8306100044	8306100009	83/04/11	50-312 Q	8306130441	8306130435	83/06/06	50-250 F
8306100047	8306100009	83/04/11	50-312 Q	8306130442	8306130429	83/06/06	50-348 P
8306100078	8306100075	83/06/09	50-529 Q	8306130452	8306130445	83/06/07	50-454 Q
8306100093	8306100088	83/06/06	50-155 Q	8306130457	8306130454	83/06/07	50-10 R
8306100105	8306100101	83/05/27	50-237 Q	8306130460	8306130454	83/06/07	50-10 R
8306100106	8306100102	83/06/06	50-285 P	8306130500	8306130493	83/02/28	70-1257
8306100131	8306100128	83/06/09	50-237 P	8306140033	8306140023	83/06/06	50-335 F
8306100134	8306100130	83/03/21	50-275 R	8306140038	8306140023	83/06/06	50-335 F
8306100135	8306100128	83/06/09	50-237 P	8306140063	8306140059	83/06/07	50-272 P
8306100136	8306100132	83/06/08	50-366 P	8306140115	8306140111	83/05/26	50-389 P
8306100144	8306100140	83/06/06	50-389 P	8306140125	8306140114	83/05/27	50-438 Q
8306100148	8306100147	83/06/03	50-483 A	8306140131	8306140114	83/05/27	50-438 Q
8306100152	8306100147	83/06/03	50-483 A	8306140134	8306140114	83/05/27	50-438 Q
8306100156	8306100149	83/06/06	50-237 Q	8306140139	8306140114	83/05/27	50-438 Q
8306100167	8306100165	83/05/25	50-483 Q	8306140142	8306140137	83/05/26	50-327 Q
8306100169	8306100162	83/03/23	50-483 Q	8306140145	8306140137	83/05/26	50-327 Q
8306100171	8306100168	83/06/02	50-275 R	8306140149	8306140137	83/05/26	50-327 Q
8306100174	8306100172	83/03/24	50-373 Q	8306140150	8306140143	83/05/26	50-438 Q
8306100175	8306100172	83/05/24	50-373 Q	8306140153	8306140147	83/05/31	50-323 Q
8306100181	8306100179	83/05/18	50-235 R	8306140157	8306140143	83/05/26	50-438 Q
8306100193	8306100191	83/06/07	50-309 Q	8306140162	8306140137	83/05/26	50-327 Q
8306100199	8306100197	83/06/08	50-413 Q	8306140164	8306140143	83/05/26	50-438 Q
8306100205	8306100204	83/06/07	50-309 Q	8306140169	8306140158	83/06/09	50-333 Q
8306100212	8306100210	83/03/20	50-341 Q	8306140172	8306140143	83/05/26	50-438 Q
8306100220	8306100217	83/05/25	50-151 Q	8306140180	8306140174	83/05/16	50-389 Q
8306100227	8306100223	83/06/06	50-445 Q	8306140191	8306140186	83/05/16	50-389 Q
8306100229	8306100226	83/05/26	50-155 Q	8306140196	8306140190	83/05/19	50-335 Q
8306100230	8306100223	83/06/06	50-445 Q	8306140197	8306140188	83/05/11	50-407 Q
8306100242	8306100240	83/06/08	50-322 Q	8306140201	8306140194	83/05/25	50-324 Q
8306100247	8306100244	83/05/24	50-454 Q	8306140212	8306140207	83/05/20	50-482 Q
8306100249	8306100244	83/05/24	50-454 Q	8306140220	8306140207	83/05/20	50-482 Q
8306100250	8306100245	83/06/06	50-373 Q	8306140222	8306140208	83/06/03	50-338 P
8306100255	8306100252	83/05/20	50-373 Q	8306140223	8306140217	83/06/06	50-155 F
8306100256	8306100253	83/06/06	50-286 P	8306140227	8306140217	83/06/06	50-155 F
8306100258	8306100252	83/05/20	50-373 Q	8306140232	8306140226	83/05/11	50-72 Q
8306100265	8306100264	83/06/10	50-424 A	8306140234	8306140230	83/06/10	50-482 A
8306100266	8306100263	83/03/27	50-374 Q	8306140236	8306140226	83/05/11	50-72 Q
8306100267	8306100264	83/06/10	50-424 A	8306140238	8306140228	83/05/18	CONTRACT
8306100269	8306100268	83/06/03	50-329 A	8306140240	8306140230	83/06/10	50-482 A
8306100272	8306100268	83/06/03	50-329 A	8306140244	8306140235	83/05/17	50-416 Q
8306100273	8306100271	83/06/07	50-315 Q	8306140246	8306140237	83/06/06	50-321 F
8306100311	8306100237	83/06/08	50-389 H	8306140249	8306140245	83/05/13	50-482 Q
8306130129	8306130118	83/03/25	50-382 Q	8306140253	8306140248	83/06/06	50-97 Q
8306130130	8306130117	83/06/06	50-285 Q	8306140254	8306140237	83/06/06	50-321 F
8306130185	8306130177	83/06/03	71-9089	8306140261	8306140256	83/05/31	50-272 Q
8306130198	8306130177	83/06/03	71-9089	8306140262	8306140258	83/06/09	50-277 Q
8306130212	8306130177	83/06/03	71-9089	8306140266	8306140251	83/06/02	50-259 Q
8306130216	8306130194	83/03/23	0A999	8306140273	8306140265	83/06/06	50-309 F
8306130224	8306130194	83/03/23	0A999	8306140276	8306140251	83/06/02	50-259 Q

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8306140284	8306140251	83/06/02	50-259 Q	8306140546	8306140524	83/06/07	50-329 A
8306140297	8306140251	83/06/02	50-259 Q	8306140548	8306140524	83/06/07	50-329 A
8306140310	8306140302	83/05/23	50-335 Q	8306140549	8306140547	83/05/16	50-324 Q
8306140323	8306140316	83/05/23	50-322 H	8306140552	8306140524	83/06/07	50-329 A
8306140337	8306140329	83/06/07	ADVCM	8306140555	8306140524	83/06/07	50-329 A
8306140338	8306140317	83/05/26	70-1113	8306140557	8306140524	83/06/07	50-329 A
8306140342	8306140317	83/05/26	70-1113	8306140558	8306140534	83/06/02	50-410 Q
8306140348	8306140317	83/05/26	70-1113	8306140560	8306140524	83/06/07	50-329 A
8306140349	8306140343	83/05/17	50-335 Q	8306140564	8306140554	83/06/02	50-410 Q
8306140350	8306140345	83/05/24	50-329 H	8306140566	8306140524	83/06/07	50-329 A
8306140357	8306140317	83/05/26	70-1113	8306140567	8306140559	83/06/07	50-416 Q
8306140358	8306140332	83/05/31	50-322 Q	8306140569	8306140559	83/06/07	50-416 Q
8306140361	8306140352	83/06/03	50-336 P	8306140571	8306140559	83/06/07	50-416 Q
8306140362	8306140355	83/05/13	50-390 Q	8306140573	8306140524	83/06/07	50-329 A
8306140363	8306140359	83/05/18	50-313 Q	8306140574	8306140559	83/06/07	50-416 Q
8306140367	8306140356	83/04/11	40-8698	8306140575	8306140568	83/06/02	70-1113
8306140374	8306140370	83/05/27	50-445 Q	8306140579	8306140524	83/06/07	50-329 A
8306140375	8306140368	83/05/24	50-400 Q	8306140580	8306140562	83/05/20	50-390 Q
8306140388	8306140382	83/06/01	50-395 Q	8306140582	8306140576	83/06/01	70-1113
8306140390	8306140386	83/05/17	50-327 Q	8306140583	8306140559	83/06/07	50-416 Q
8306140391	8306140381	83/06/06	50-277 F	8306140587	8306140524	83/06/07	50-329 A
8306140398	8306140381	83/06/06	50-277 F	8306140592	8306140524	83/06/07	50-329 A
8306140400	8306140397	83/05/17	50-380 Q	8306140597	8306140524	83/06/07	50-329 A
8306140404	8306140396	83/05/24	50-324 Q	8306140605	8306140524	83/06/07	50-329 A
8306140413	8306140396	83/05/24	50-324 Q	8306140615	8306140607	83/06/08	50-322 Q
8306140420	8306140415	83/05/27	50-390 Q	8306140616	8306140613	83/06/07	50-293 P
8306140423	8306140396	83/05/24	50-324 Q	8306140617	8306140609	83/05/18	70-824
8306140424	8306220074	83/06/21	50-219 P	8306140627	8306140621	83/03/25	50-280 Q
8306140425	8306140415	83/05/27	50-390 Q	8306140636	8306140631	83/05/27	50-302 Q
8306140426	8306140421	83/06/03	CONTRACT	8306140643	8306140639	83/05/31	50-334 P
8306140428	8306140415	83/05/27	50-390 Q	8306140647	8306140608	83/05/17	50-338 Q
8306140434	8306140415	83/05/27	50-390 Q	8306140652	8306140641	83/05/17	50-338 Q
8306140438	8306140433	83/06/03	CONTRACT	8306140655	8306140643	83/05/26	50-348 Q
8306140439	8306140432	83/05/19	50-424 Q	8306140662	8306140637	83/06/09	50-293 Q
8306140445	8306140441	83/05/31	50-410 Q	8306140663	8306140658	83/06/08	50-412 Q
8306140446	8306140442	83/06/06	40-8794	8306140667	8306140658	83/06/08	50-412 Q
8306140451	8306140447	83/05/27	50-302 Q	8306140671	8306140664	83/05/24	50-413 Q
8306140454	8306140450	83/06/07	50-416 Q	8306140672	8306140658	83/06/08	50-412 Q
8306140455	8306140447	83/05/27	50-302 Q	8306140675	8306140668	83/04/08	MISC
8306140457	8306140452	83/05/25	50-395 Q	8306140682	8306140677	83/06/07	50-324 Q
8306140461	8306140452	83/05/25	50-395 Q	8306140686	8306140680	83/06/09	50-370 P
8306140462	8306140447	83/05/27	50-302 Q	8306140688	8306140677	83/06/07	50-324 Q
8306140463	8306140430	83/06/07	50-416 Q	8306140692	8306140685	83/05/25	50-259 Q
8306140465	8306140452	83/05/25	50-395 Q	8306140693	8306140677	83/06/07	50-324 Q
8306140468	8306140430	83/06/07	50-416 Q	8306140699	8306140677	83/06/07	50-324 Q
8306140469	8306140447	83/05/27	50-302 Q	8306140705	8306140677	83/06/07	50-324 Q
8306140471	8306140452	83/05/25	50-395 Q	8306140708	8306140698	83/03/31	50-261 Q
8306140474	8306140450	83/06/07	50-416 Q	8306140713	8306140700	83/06/02	70-143
8306140477	8306140473	83/05/16	50-348 Q	8306140718	8306140712	83/06/01	PR
8306140490	8306140483	83/06/02	50-400 Q	8306140719	8306140711	83/06/01	50-321 Q
8306140492	8306140487	83/06/09	50-395 Q	8306140729	8306140724	83/06/09	50-416 P
8306140493	8306140486	83/03/24	50-321 V	8306140730	8306140711	83/06/01	50-321 Q
8306140495	8306140483	83/06/02	50-400 Q	8306140734	8306140726	83/03/03	ADVCM
8306140498	8306140494	83/06/03	50-322 Q	8306140737	8306140732	83/06/09	50-289 F
8306140499	8306140483	83/06/02	50-400 Q	8306140740	8306140726	83/03/03	ADVCM
8306140502	8306140497	83/05/27	50-413 Q	8306140743	8306140711	83/06/01	50-321 Q
8306140503	8306140483	83/06/02	50-400 Q	8306140746	8306140738	83/06/06	50-269 P
8306140505	8306140501	83/05/18	COMMISSION	8306140750	8306140744	83/06/03	71-6553
8306140506	8306140497	83/05/27	50-413 Q	8306140752	8306140738	83/06/06	50-269 P
8306140507	8306140483	83/06/02	50-400 Q	8306140831	8306140828	83/06/01	50-255 F
8306140508	8306140497	83/05/27	50-413 Q	8306150008	8306150005	83/06/02	50-289 Q
8306140510	8306140504	83/05/25	50-389 Q	8306150014	8306150013	83/06/13	50-244 Q
8306140511	8306140497	83/05/27	50-413 Q	8306150030	8306150025	83/06/07	50-289 F
8306140512	8306140483	83/06/02	50-400 Q	8306150034	8306150032	83/06/07	50-313 F
8306140513	8306140509	83/02/28	ADVCM	8306150041	8306150037	83/06/07	50-321 F
8306140514	8306140504	83/05/25	50-389 Q	8306150044	8306150037	83/06/07	50-321 F
8306140516	8306140504	83/05/25	50-389 Q	8306150086	8306150082	83/06/01	50-317 F
8306140517	8306140509	83/02/28	ADVCM	8306150094	8306150091	83/06/06	50-327 F
8306140520	8306140504	83/05/25	50-389 Q	8306150098	8306150091	83/06/06	50-327 F
8306140521	8306140509	83/02/28	ADVCM	8306150102	8306150101	83/06/06	50-445 F
8306140522	8306140515	83/05/25	50-321 Q	8306150124	8306150121	83/05/31	TDPREP
8306140529	8306140527	83/05/25	70-1201	8306150137	8306150133	83/06/01	50-321 F
8306140532	8306140524	83/06/07	50-329 A	8306150141	8306150133	83/06/01	50-321 F
8306140534	8306140524	83/06/07	50-329 A	8306150150	8306150149	83/05/19	50-412 A
8306140537	8306140530	83/05/17	50-369 Q	8306150163	8306150156	83/06/08	70-2669
8306140539	8306140524	83/06/07	50-329 A	8306150166	8306150156	83/06/08	70-2669
8306140540	8306140524	83/06/07	50-329 A	8306150169	8306150156	83/06/08	70-2669
8306140541	8306140538	83/05/18	50-335 Q	8306150172	8306150167	83/06/13	PRDJ
8306140542	8306140535	83/05/23	50-327 Q	8306150179	8306150174	83/06/13	50-289 H
8306140544	8306140524	83/06/07	50-329 A	8306150185	8306150174	83/06/13	50-289 H

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

53

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8306150214	8306150211	83/03/20	50-322 Q	8306160125	8306160093	83/04/01	FOIA
8306150222	8306150218	83/06/10	50-195 Q	8306160131	8306160093	83/04/01	FOIA
8306150232	8306150228	83/06/09	50-366 P	8306160132	8306160110	83/04/14	FOIA
8306150240	8306150239	83/06/03	71-9017	8306160134	8306160093	83/04/01	FOIA
8306150247	8306150237	83/06/02	50-35P Q	8306160137	8306160130	83/05/31	50-272 Q
8306150248	8306150243	83/06/03	50-259 P	8306160138	8306160093	83/04/01	FOIA
8306150251	8306150246	83/06/07	CONTRACT	8306160139	8306160110	83/04/14	FOIA
8306150257	8306150253	83/06/10	50-29 J	8306160143	8306160093	83/04/01	FOIA
8306150259	8306150256	83/03/11	50-443 Q	8306160144	8306160130	83/03/31	50-272 Q
8306150262	8306150256	83/03/11	50-443 Q	8306160148	8306160093	83/04/01	FOIA
8306150266	8306150260	83/03/26	50-259 P	8306160153	8306160093	83/04/01	FOIA
8306150269	8306150264	83/06/02	70-143	8306160156	8306160093	83/04/01	FOIA
8306150270	8306150267	83/06/02	50-272 R	8306160162	8306160093	83/04/01	FOIA
8306150272	8306150260	83/03/26	50-259 P	8306160164	8306160159	83/06/01	50-285 P
8306150276	8306150271	83/06/10	50-275 P	8306160166	8306160093	83/04/01	FOIA
8306150281	8306150277	83/06/10	50-275 P	8306160173	8306160171	83/04/27	FOIA
8306150283	8306150282	83/03/27	50-302 P	8306160175	8306160093	83/04/01	FOIA
8306150286	8306150290	83/06/06	50-271 F	8306160178	8306160093	83/04/01	FOIA
8306150293	8306150290	83/06/06	50-271 F	8306160179	8306160177	83/04/25	FOIA
8306150299	8306150290	83/06/06	50-271 F	8306160182	8306160093	83/04/01	FOIA
8306150335	8306150332	83/06/07	70-1257	8306160185	8306160093	83/04/01	FOIA
8306150338	8306150334	83/06/06	50-213 F	8306160190	8306160093	83/04/01	FOIA
8306150341	8306150334	83/06/06	50-213 F	8306160193	8306160093	83/04/01	FOIA
8306150346	8306150344	83/06/06	50-329 F	8306160194	8306160189	83/06/06	50-72 F
8306150351	8306150344	83/06/06	50-329 F	8306160198	8306160093	83/04/01	FOIA
8306150355	8306150349	83/06/03	50-412 Q	8306160200	8306160197	83/04/25	50-206 Q
8306150373	8306150370	83/06/10	50-322 Q	8306160200	8306160197	83/04/25	50-206 Q
8306150381	8306150370	83/06/10	50-322 Q	8306160203	8306160093	83/04/01	FOIA
8306150386	8306150384	83/06/10	50-358 Q	8306160204	8306160197	83/04/25	FOIA
8306150400	8306150396	83/06/10	50-445 Q	8306160208	8306160093	83/04/01	FOIA
8306150401	8306150395	83/06/09	50-322 Q	8306160209	8306160197	83/04/25	50-206 Q
8306150403	8306150396	83/06/10	50-445 Q	8306160211	8306160093	83/04/01	FOIA
8306150409	8306150405	83/06/09	50-155 Q	8306160216	8306160093	83/04/01	FOIA
8306150413	8306150405	83/06/09	50-155 Q	8306160218	8306160197	83/04/25	50-206 Q
8306150415	8306150414	83/06/09	50-445 Q	8306160222	8306160093	83/04/01	FOIA
8306150431	8306150238	83/05/24	50-443 Q	8306160223	8306160197	83/04/25	50-206 Q
8306150436	8306150420	83/06/07	50-454 Q	8306160230	8306160197	83/04/25	50-206 Q
8306150437	8306150238	83/05/24	50-443 Q	8306160239	8306160238	83/05/27	50-193 Q
8306150442	8306150420	83/06/07	50-454 Q	8306160243	8306160197	83/04/25	50-206 Q
8306150455	8306150454	83/06/06	50-483 F	8306160246	8306160238	83/05/27	50-193 Q
8306150461	8306150460	83/06/07	50-320 H	8306160247	8306160242	83/06/03	50-440 Q
8306150465	8306150463	83/06/03	XPORTLTIC	8306160253	8306160197	83/04/25	50-206 Q
8306150475	8306150470	83/06/08	XPORTLTIC	8306160254	8306160242	83/06/03	50-440 Q
8306150484	8306150478	83/05/12	50-366 P	8306160258	8306160250	83/06/08	50-219 Q
8306150487	8306150482	83/06/06	50-482 F	8306160263	8306160197	83/04/25	50-206 Q
8306150488	8306150485	83/06/01	CONTRACT	8306160266	8306160249	83/06/09	50-338 P
8306150501	8306150499	83/03/24	50-313 P	8306160273	8306160259	83/03/27	CONTRACT
8306150515	8306150508	83/03/24	50-346 P	8306160274	8306160271	83/06/14	50-416 P
8306150521	8306150506	83/06/01	CONTRACT	8306160276	8306160197	83/04/25	50-206 Q
8306150543	8306150533	83/06/02	50-272 U	8306160279	8306160289	83/06/06	50-409 F
8306150570	8306150560	83/06/03	CONTRACT	8306160281	8306160197	83/04/25	50-206 Q
8306150615	8306150609	83/06/07	50-322 F	8306160291	8306160384	83/03/16	TOPREP
8306150628	8306150626	83/05/27	50-220 F	8306160292	8306160197	83/04/25	FOIA
8306150630	8306150627	83/05/27	50-286 P	8306160300	8306160384	83/03/16	TOPREP
8306150634	8306150627	83/05/27	50-286 P	8306160301	8306160197	83/04/25	50-206 Q
8306150636	8306150632	83/06/07	50-373 F	8306160303	8306160284	83/03/16	TOPREP
8306150637	8306150627	83/03/27	50-206 P	8306160321	8306160313	83/06/01	70-1207
8306150638	8306150627	83/05/27	50-206 P	8306160322	8306160314	83/06/13	50-483 Q
8306160005	8306160003	83/06/01	50-271 Q	8306160330	8306160323	83/06/14	50-317 Q
8306160006	8306160003	83/06/01	50-271 Q	8306160344	8306160341	83/06/01	50-220 Q
8306160010	8306160009	83/06/14	50-142 T	8306160348	8306160341	83/06/01	50-220 Q
8306160017	8306160009	83/06/14	50-142 T	8306160354	8306160346	83/06/06	50-285 F
8306160032	8306160027	83/06/06	50-348 F	8306160358	8306160343	83/03/11	50-315 R
8306160045	8306160040	83/06/06	CONTRACT	8306160362	8306160351	83/06/10	50-298 Q
8306160048	8306160043	83/06/06	50-305 F	8306160365	8306160361	83/03/31	50-244 Q
8306160057	8306160050	83/04/21	FOIA	8306160366	8306160357	83/06/10	50-341 A
8306160064	8306160058	83/06/07	50-254 F	8306160367	8306160343	83/03/11	50-315 R
8306160077	8306160071	83/06/07	50-254 F	8306160372	8306160361	83/03/31	50-244 Q
8306160083	8306160081	83/04/19	50-317 S	8306160424	8306160412	83/06/09	50-213 P
8306160087	8306160072	83/06/09	50-322 F	8306160435	8306160391	83/06/10	50-371 Q
8306160089	8306160072	83/06/09	50-322 F	8306160448	8306160440	83/06/07	50-272 Q
8306160091	8306160072	83/06/09	50-322 F	8306160456	8306160453	83/06/02	50-260 P
8306160100	8306160096	83/06/09	50-322 F	8306160486	8306160483	83/06/10	50-277 Q
8306160104	8306160096	83/06/09	50-322 F	8306160497	8306160493	83/06/08	50-313 P
8306160107	8306160093	83/04/01	FOIA	8306160506	8306160503	83/06/13	50-445 Q
8306160108	8306160096	83/06/09	50-322 F	8306160523	8306160507	83/06/13	50-259 P
8306160112	8306160093	83/04/01	FOIA	8306160529	8306160526	83/06/10	50-275 R
8306160115	8306160093	83/04/01	FOIA	8306160545	8306160541	83/06/02	50-267 P
8306160118	8306160093	83/04/01	FOIA	8306160556	8306160548	83/06/13	0A999
8306160124	8306160110	83/04/14	FOIA	8306160560	8306160541	83/06/02	50-267 P

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8306160564	8306160541	83/06/02	50-267 P	8306170349	8306170346	83/06/15	50-389 Q
8306160576	8306160567	83/04/30	40-8280	8306170354	8306170353	83/06/13	50-263 P
8306160578	8306160548	83/06/13	04999	8306170360	8306170356	83/03/02	50-328 F
8306160582	8306160575	83/06/10	50-410 Q	8306170361	8306170359	83/05/26	50-454 Q
8306160584	8306160579	83/06/10	50-275 Q	8306170364	8306170359	83/05/26	50-454 Q
8306160595	8306160579	83/06/10	50-275 Q	8306170379	8306170373	83/06/14	50-142 T
8306160609	8306160603	83/06/13	50-352 Q	8306170384	8306170378	83/06/14	50-454 G
8306160631	8306160625	83/06/02	50-155 P	8306170389	8306170378	83/06/14	50-454 G
8306160641	8306160630	83/05/31	50-389 P	8306170390	8306170373	83/06/14	50-142 T
8306160652	8306160649	83/05/25	71-86	8306170392	8306170378	83/06/14	50-454 G
8306160662	8306160660	83/06/06	50-389 F	8306170407	8306170402	83/06/06	50-312 P
8306160666	8306160660	83/06/06	50-389 F	8306170417	8306170373	83/06/14	50-142 T
8306160667	8306160664	83/06/02	71-9134	8306170426	8306170373	83/06/14	50-142 T
8306160670	8306160664	83/06/02	71-9134	8306170428	8306170425	83/06/13	50-508 Q
8306160679	8306160676	83/06/01	50-346 F	8306170451	8306170449	83/06/02	COMMISSION
8306160685	8306160684	83/06/03	XPORL1C	8306170456	8306170455	83/06/09	71-9110
8306160690	8306160686	83/06/06	50-346 F	8306170466	8306170463	83/06/15	CONTRACT
8306160724	8306160723	83/06/13	XPORL1C	8306170472	8306170469	83/06/08	50-309 Q
8306170016	8306170013	83/06/01	50-301 Q	8306170474	8306170469	83/06/08	50-309 Q
8306170019	8306170013	83/06/01	50-301 Q	8306170482	8306170480	83/05/27	CONTRACT
8306170023	8306170020	83/05/27	50-454 Q	8306170483	8306170481	83/05/31	50-270 F
8306170029	8306170026	83/04/08	CONTRACT	8306170485	8306170484	83/06/03	CONTRACT
8306170052	8306170050	83/06/01	50-57 Q	8306200013	8306200012	83/06/08	WASTE MGR
8306170055	8306170049	83/05/27	50-341 Q	8306200015	8306200014	83/06/06	50-155 F
8306170058	8306170053	83/06/06	50-282 P	8306200040	8306200037	83/05/18	FOIA
8306170097	8306170089	83/04/14	FOIA	8306200041	8306200037	83/05/18	FOIA
8306170099	8306170089	83/04/14	FOIA	8306200048	8306200045	83/03/07	ADVM
8306170152	8306170089	83/04/14	FOIA	8306200060	8306200056	83/06/07	50-313 F
8306170155	8306170089	83/04/14	FOIA	8306200086	8306200082	83/06/06	50-423 Q
8306170157	8306170089	83/04/14	FOIA	8306200126	8306200122	83/05/18	50-498 A
8306170160	8306170089	83/04/14	FOIA	8306200130	8306200125	83/06/06	50-277 Q
8306170162	8306170151	83/06/14	50-369 Q	8306200134	8306200128	83/06/07	CONTRACT
8306170167	8306170089	83/04/14	FOIA	8306200136	8306200135	83/06/06	50-387 Q
8306170170	8306170089	83/04/14	FOIA	8306200154	8306200151	83/06/14	50-27 F
8306170174	8306170089	83/04/14	FOIA	8306200161	8306200158	83/06/06	50-293 Q
8306170177	8306170166	83/06/02	50-309 F	8306200162	8306200158	83/06/06	50-293 Q
8306170178	8306170089	83/04/14	FOIA	8306200165	8306200159	83/06/14	50-277 Q
8306170185	8306170089	83/04/14	FOIA	8306200166	8306200158	83/06/06	50-293 Q
8306170190	8306170089	83/04/14	FOIA	8306200175	8306200171	83/05/04	40-8084
8306170191	8306170188	83/06/10	50-387 P	8306200177	8306200174	83/06/06	50-271 Q
8306170194	8306170089	83/04/14	FOIA	8306200181	8306200174	83/06/06	50-271 Q
8306170198	8306170089	83/04/14	FOIA	8306200189	8306200186	83/06/17	50-416 K
8306170203	8306170089	83/04/14	FOIA	8306200195	8306200194	83/06/16	50-389 P
8306170205	8306170192	83/05/31	RES	8306200197	8306200192	83/06/14	50-155 P
8306170208	8306170089	83/04/14	FOIA	8306200210	8306200207	83/06/07	50-344 I
8306170212	8306170089	83/04/14	FOIA	8306200213	8306200207	83/06/07	50-344 I
8306170220	8306170089	83/04/14	FOIA	8306200215	8306200207	83/06/07	50-344 I
8306170222	8306170216	83/06/13	50-308 Q	8306200220	8306200216	83/06/10	50-348 S
8306170225	8306170089	83/04/14	FOIA	8306200222	8306200221	83/06/06	70-1143
8306170229	8306170089	83/04/14	FOIA	8306200225	8306200221	83/06/06	70-1143
8306170230	8306170226	83/06/10	50-247 Q	8306200227	8306200216	83/06/10	50-348 S
8306170235	8306170089	83/04/14	FOIA	8306200233	8306200216	83/06/10	50-348 S
8306170238	8306170089	83/04/14	FOIA	8306200242	8306200236	83/06/07	50-443 E
8306170242	8306170089	83/04/14	FOIA	8306200247	8306200243	83/06/10	50-397 E
8306170244	8306170089	83/04/14	FOIA	8306200251	8306200243	83/06/10	50-397 E
8306170245	8306170241	83/06/01	70-371	8306200252	8306200249	83/06/15	50-275 R
8306170248	8306170089	83/04/14	FOIA	8306200253	8306200243	83/06/10	50-397 E
8306170252	8306170089	83/04/14	FOIA	8306200280	8306200277	83/04/28	FOIA
8306170258	8306170089	83/04/14	FOIA	8306200282	8306200277	83/04/28	FOIA
8306170259	8306170253	83/05/27	CONTRACT	8306200283	8306200281	83/06/03	50-282 P
8306170262	8306170089	83/04/14	FOIA	8306200284	8306200277	83/04/28	FOIA
8306170267	8306170089	83/04/14	FOIA	8306200285	8306200171	83/05/04	40-8084
8306170268	8306170266	83/06/15	50-382 Q	8306200286	8306200277	83/04/28	FOIA
8306170269	8306170089	83/04/14	FOIA	8306200287	8306200277	83/04/28	FOIA
8306170272	8306170089	83/04/14	FOIA	8306200289	8306200284	83/06/06	CONTRACT
8306170274	8306170089	83/04/14	FOIA	8306200293	8306200291	83/05/06	FOIA
8306170280	8306170089	83/04/14	FOIA	8306200313	8306200307	83/06/15	50-245 Q
8306170284	8306170089	83/04/14	FOIA	8306200316	8306200314	83/06/13	50-244 P
8306170288	8306170089	83/04/14	FOIA	8306200322	8306200307	83/06/15	50-245 Q
8306170291	8306170089	83/04/14	FOIA	8306200327	8306200320	83/06/14	50-454 Q
8306170292	8306170287	83/06/08	50-389 P	8306200331	8306200320	83/06/14	50-454 Q
8306170295	8306170089	83/04/14	FOIA	8306200341	8306200333	83/06/14	50-358 Q
8306170298	8306170089	83/04/14	FOIA	8306200344	8306200338	83/06/14	50-333 Q
8306170299	8306170287	83/06/08	50-389 P	8306200345	8306200335	83/06/16	50-358 Q
8306170304	8306170287	83/06/08	50-389 P	8306200346	8306200342	83/06/19	50-247 T
8306170307	8306170285	83/06/15	50-269 Q	8306200347	8306200343	83/06/06	50-77 Q
8306170315	8306170312	83/06/10	50-275 R	8306200348	8306200335	83/06/16	50-358 Q
8306170320	8306170318	83/06/08	TOPREP	8306200351	8306200335	83/06/16	50-77 Q
8306170331	8306170327	83/06/14	50-280 P	8306200353	8306200343	83/06/06	50-77 Q
8306170336	8306170335	83/06/10	50-390 A	8306200356	8306200352	83/06/19	50-349 I

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

537

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8306200359	8306200335	83/06/16	50-358 Q	8306210373	8306210368	83/06/06	50-267 F
8306200365	8306200361	83/06/14	50-29 Q	8306210375	8306210370	83/06/03	CONTRACT
8306200369	8306200361	83/06/14	50-29 Q	8306210384	8306210376	83/06/16	CONTRACT
8306200372	8306200335	83/06/16	50-358 Q	8306210386	8306210381	83/05/27	CONTRACT
8306200381	8306200378	83/06/17	50-361 Q	8306210388	8306210382	83/06/06	50-389 F
8306200383	8306200379	83/06/15	70-734	8306210392	8306210382	83/06/06	50-389 F
8306200391	8306200387	83/06/15	50-213 Q	8306210397	8306210391	83/06/10	CONTRACT
8306200394	8306200393	83/06/15	50-346 P	8306210415	8306210408	83/05/18	71-6346
8306200402	8306200401	83/06/15	50-286 P	8306210426	8306210424	83/06/13	50-111 P
8306200410	8306200406	83/06/15	70-125/	8306210427	8306210406	83/06/09	50-369 P
8306200411	8306200403	83/03/17	50-286 F	8306210430	8306210424	83/06/13	50-111 P
8306200414	8306200409	83/06/16	50-441 F	8306210432	8306210421	83/06/16	CONTRACT
8306200419	8306200415	83/05/25	WASTE MGT	8306210440	8306210436	83/06/10	70-143
8306200430	8306200429	83/06/13	50-416 E	8306220009	8306220003	83/06/16	50-293 P
8306200431	8306200429	83/06/13	50-416 E	8306220010	8306220002	83/06/15	50-321 P
8306200432	8306200429	83/06/13	50-416 E	8306220024	8306220016	83/06/15	50-341 Q
8306210012	8306210009	83/05/31	50-278 Q	8306220030	8306220016	83/06/15	50-341 Q
8306210016	8306210010	83/06/09	50-259 F	8306220034	8306220028	83/06/17	50-284 Q
8306210020	8306210013	83/05/27	0A999	8306220036	8306220031	83/06/20	50-358 Q
8306210024	8306210017	83/06/10	50-29 P	8306220041	8306220037	83/06/07	50-346 Q
8306210028	8306210023	83/06/03	0A999	8306220047	8306220033	83/06/16	50-280 P
8306210031	8306210025	83/05/27	0A999	8306220050	8306220037	83/06/07	50-346 Q
8306210032	8306210027	83/06/15	50-327 P	8306220052	8306220045	83/06/17	50-275 Q
8306210033	8306210030	83/06/17	0A999	8306220053	8306220044	83/06/17	50-271 P
8306210041	8306210037	83/06/14	50-305 Q	8306220055	8306220049	83/06/15	50-302 P
8306210064	8306210061	83/06/06	50-382 Q	8306220063	8306220056	83/06/14	50-170 Q
8306210065	8306210057	83/06/14	50-315 Q	8306220076	8306220066	83/06/06	50-461 Q
8306210070	8306210061	83/06/06	50-382 Q	8306220083	8306220074	83/06/21	50-219 P
8306210075	8306210072	83/06/15	50-263 Q	8306220091	8306220073	83/06/02	CONTRACT
8306210097	8306210092	83/06/15	50-369 P	8306220093	8306220088	83/06/16	50-322 Q
8306210102	8306210095	83/06/14	50-155 Q	8306220104	8306220096	83/06/06	50-410 X
8306210103	8306210098	83/06/07	50-213 Q	8306220107	8306220096	83/06/06	50-410 C
8306210107	8306210104	83/06/07	50-327 Q	8306220111	8306220108	83/06/17	50-400 Q
8306210110	8306210105	83/05/31	50-445 Q	8306220137	8306220132	83/06/20	50-483 Q
8306210117	8306210115	83/06/15	50-327 P	8306220138	8306220133	83/06/06	CONTRACT
8306210122	8306210066	83/06/13	50-409 P	8306220141	8306220134	83/06/20	50-322 Q
8306210129	8306210114	83/05/31	50-278 Q	8306220148	8306220143	83/06/30	REPOD
8306210134	8306210128	83/06/06	50-315 S	8306220153	8306220146	83/06/21	50-337 Q
8306210142	8306210128	83/06/06	50-315 S	8306220154	8306220149	83/04/26	50-410 Q
8306210149	8306210145	83/06/01	50-219 Q	8306220157	8306220146	83/06/21	50-537 Q
8306210153	8306210146	83/06/17	TOPREP	8306220159	8306220151	83/06/10	CONTRACT
8306210163	8306210157	83/06/17	50-244 P	8306220155	8306220155	83/04/22	50-387 Q
8306210166	8306210158	83/06/17	50-219 P	8306220160	8306220166	83/06/16	CONTRACT
8306210168	8306210157	83/06/17	50-244 P	8306220173	8306220164	83/06/13	WASTE MGT
8306210169	8306210160	83/06/17	50-389 P	8306220175	8306220171	83/06/02	50-269 Q
8306210170	8306210161	83/06/15	50-346 Q	8306220176	8306220164	83/06/13	WASTE MGT
8306210171	8306210162	83/06/13	50-275 R	8306220178	8306220172	83/06/13	71-498
8306210188	8306210170	83/06/17	50-286 P	8306220190	8306220184	83/06/09	71-5828
8306210198	8306210187	83/06/14	50-483 Q	8306220191	8306220181	83/03/29	50-277 Q
8306210201	8306210193	83/06/17	50-348 P	8306220192	8306220186	83/06/15	CONTRACT
8306210203	8306210194	83/06/17	50-259 Q	8306220222	8306220217	83/05/31	CONTRACT
8306210213	8306210194	83/06/17	50-259 Q	8306220226	8306220223	83/06/08	50-309 P
8306210224	8306210194	83/06/17	50-259 Q	8306220227	8306220220	83/06/10	CONTRACT
8306210233	8306210230	83/05/27	0A999	8306220230	8306220225	83/06/06	50-335 F
8306210238	8306210230	83/05/27	0A999	8306220233	8306220229	83/06/10	CONTRACT
8306210243	8306210236	83/06/13	50-416 Q	8306220236	8306220225	83/06/06	50-335 F
8306210245	8306210240	83/06/17	50-397 Q	8306220241	8306220238	83/06/15	CONTRACT
8306210254	8306210247	83/06/06	50-209 S	8306220246	8306220244	83/06/10	CONTRACT
8306210256	8306210250	83/05/31	71-9108	8306220251	8306220243	83/03/27	50-286 F
8306210258	8306210247	83/06/06	50-209 S	8306220255	8306220249	83/06/10	CONTRACT
8306210267	8306210259	83/06/08	50-315 S	8306220257	8306220252	83/06/07	50-346 F
8306210271	8306210266	83/06/17	50-483 Q	8306220259	8306220253	83/06/03	CONTRACT
8306210273	8306210259	83/06/08	50-315 S	8306220260	8306220252	83/06/07	50-346 F
8306210274	8306210272	83/06/01	0A999	8306220261	8306220243	83/03/27	50-286 F
8306210279	8306210259	83/06/08	50-315 S	8306220263	8306220252	83/06/07	50-346 F
8306210282	8306210272	83/06/01	0A999	8306220264	8306220198	83/06/02	50-320 P
8306210284	8306210259	83/06/08	50-315 S	8306220266	8306220262	83/06/10	CONTRACT
8306210286	8306210272	83/06/01	0A999	8306220268	8306220198	83/06/02	50-289 P
8306210298	8306210291	83/05/23	50-341 Q	8306220272	8306220267	83/06/03	CONTRACT
8306210299	8306210292	83/06/20	50-409 F	8306220276	8306220269	83/06/10	CONTRACT
8306210303	8306210300	83/04/11	FOIA	8306220282	8306220277	83/06/06	CONTRACT
8306210323	8306210320	83/04/07	FOIA	8306220288	8306220284	83/05/31	CONTRACT
8306210326	8306210320	83/04/07	FOIA	8306220295	8306220289	83/06/17	50-413 F
8306210332	8306210327	83/04/22	FOIA	8306220298	8306220293	83/06/06	50-289 F
8306210336	8306210327	83/04/22	FOIA	8306220299	8306220289	83/06/17	50-413 F
8306210344	8306210339	83/06/03	CONTRACT	8306220303	8306220300	83/06/09	TOPREP
8306210357	8306210355	83/06/06	50-10 F	8306220305	8306220302	83/06/03	CONTRACT
8306210360	8306210359	83/06/06	50-286 F	8306220310	8306220307	83/06/07	50-321 F
8306210365	8306210363	83/06/06	50-348 F	8306220313	8306220307	83/06/07	50-321 F
8306210371	8306210364	83/05/31	CONTRACT	8306220320	8306220316	83/06/03	CONTRACT

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8306220327	8306220324	83/05/27	CONTRACT	83062230359	83062230353	83/06/10	50-358 Q
83062203010	83062203007	83/06/20	50-155 Q	83062230366	83062230361	83/06/21	50-309 F
83062203012	83062203005	83/03/25	50-373 Q	83062230370	83062230368	83/06/22	50-367 G
83062203015	83062203005	83/03/25	50-373 Q	83062230382	83062230378	83/06/20	50-348 P
83062230016	83062230009	83/05/06	FOIA	83062230388	83062230383	83/06/09	50-317 Q
83062230018	83062230009	83/05/06	FOIA	83062230391	83062230386	83/06/08	TOPREF
83062230019	83062230005	83/03/25	50-373 Q	83062230392	83062230389	83/06/08	50-293 Q
83062230020	83062230009	83/05/06	FOIA	83062230397	83062230389	83/06/08	50-273 Q
83062230022	83062230005	83/03/25	50-373 Q	83062230404	83062230401	83/06/08	0A999
83062230024	83062230005	83/03/25	FOIA	83062230405	83062230399	83/06/08	50-443 Q
83062230025	83062230009	83/05/06	FOIA	83062230417	83062230415	83/06/10	50-412 Q
83062230028	83062230005	83/03/25	50-373 A	83062230420	83062230411	83/06/08	50-409 Q
83062230030	83062230027	83/06/01	40-8681	83062230423	83062230418	83/06/10	50-374 Q
83062230031	83062230005	83/03/25	50-373 A	83062230424	83062230415	83/06/10	50-412 Q
83062230035	83062230009	83/05/06	FOIA	83062230440	83062230431	83/06/08	50-155 Q
83062230037	83062230005	83/03/25	50-373 A	83062230443	83062230437	83/06/09	TOPREF
83062230038	83062230009	83/05/06	FOIA	83062230453	83062230444	83/06/21	50-328 P
83062230039	83062230005	83/03/25	50-373 A	83062230458	83062230452	83/06/20	50-443 A
83062230042	83062230009	83/05/06	FOIA	83062230459	83062230456	83/06/20	50-333 Q
83062230043	83062230005	83/03/25	50-373 Q	83062230463	83062230456	83/06/20	50-333 Q
83062230048	8306220041	83/06/07	CONTRACT	83062230469	83062230456	83/06/20	50-333 Q
83062230051	83062230005	83/03/25	50-373 A	83062230475	83062230471	83/06/08	50-272 Q
83062230052	83062230047	83/06/01	TOPREF	83062230477	83062230476	83/06/20	50-483 Q
83062230053	83062230009	83/05/06	FOIA	83062230479	83062230476	83/06/20	50-483 Q
83062230056	83062230005	83/03/25	50-373 Q	83062230481	83062230476	83/06/20	50-483 Q
83062230058	83062230009	83/05/06	FOIA	83062230491	83062230485	83/06/14	CONTRACT
83062230059	83062230054	83/05/27	CONTRACT	83062230496	83062230494	83/06/15	CONTRACT
83062230060	83062230009	83/05/06	FOIA	83062230501	83062230497	83/05/13	50-320 P
83062230061	83062230005	83/03/25	50-373 Q	83062230505	83062230503	83/06/15	CONTRACT
83062230063	83062230009	83/05/06	FOIA	83062230509	83062230507	83/06/15	CONTRACT
83062230064	83062230009	83/05/06	FOIA	83062240011	83062240007	83/04/25	FOIA
83062230065	83062230005	83/03/25	50-373 Q	83062240012	83062240008	83/06/21	50-324 P
83062230066	83062230009	83/05/06	FOIA	83062240014	83062240006	83/06/02	50-321 Q
83062230067	83062230009	83/05/06	FOIA	83062240016	83062240007	83/04/25	FOIA
83062230069	83062230009	83/05/06	FOIA	83062240020	83062240007	83/04/25	FOIA
83062230071	83062230009	83/05/06	FOIA	83062240024	83062240007	83/04/25	FOIA
83062230072	83062230009	83/05/06	FOIA	83062240025	83062240017	83/06/16	50-460 A
83062230076	83062230009	83/05/06	FOIA	83062240027	83062240017	83/06/16	50-460 A
83062230077	83062230009	83/05/06	FOIA	83062240028	83062240007	83/04/25	FOIA
83062230078	83062230009	83/05/06	FOIA	83062240034	83062240031	83/06/15	CONTRACT
83062230079	83062230073	83/06/06	50-282 F	83062240035	83062240030	83/06/13	50-237 P
83062230080	83062230009	83/05/06	FOIA	83062240036	83062240007	83/04/25	FOIA
83062230084	83062230009	83/05/06	FOIA	83062240039	83062240007	83/04/25	FOIA
83062230085	83062230009	83/05/06	FOIA	83062240043	83062240007	83/04/25	FOIA
83062230087	83062230073	83/06/06	50-282 F	83062240044	83062240033	83/06/10	71-5595
83062230091	83062230009	83/05/06	FOIA	83062240047	83062240007	83/04/25	FOIA
83062230094	83062230009	83/05/06	FOIA	83062240049	83062240046	83/05/05	50-277 Q
83062230098	83062230009	83/05/06	FOIA	83062240051	83062240007	83/04/25	FOIA
83062230100	83062230092	83/06/06	50-213 F	83062240053	83062240007	83/04/25	FOIA
83062230102	83062230092	83/06/06	50-213 F	83062240057	83062240055	83/06/15	CONTRACT
83062230105	83062230009	83/05/06	FOIA	83062240084	83062240007	83/04/25	FOIA
83062230109	83062230009	83/05/06	FOIA	83062240094	83062240007	83/04/25	FOIA
83062230118	83062230114	83/06/09	70-820	83062240096	83062240007	83/04/25	FOIA
83062230133	83062230131	83/06/10	50-358 R	83062240101	83062240007	83/04/25	FOIA
83062230137	83062230129	83/04/13	70-8	83062240106	83062240007	83/04/25	FOIA
83062230139	83062230129	83/04/13	70-8	83062240109	83062240007	83/04/25	FOIA
83062230144	83062230129	83/04/13	70-8	83062240112	83062240007	83/04/25	FOIA
83062230149	83062230129	83/04/13	50-6	83062240116	83062240007	83/04/25	FOIA
83062230153	83062230129	83/04/13	70-8	83062240118	83062240115	83/06/30	REGED
83062230157	83062230129	83/04/13	FOIA	83062240119	83062240007	83/04/25	FOIA
83062230161	83062230129	83/04/13	FOIA	83062240128	83062240007	83/04/25	FOIA
83062230166	83062230129	83/04/13	FOIA	83062240131	83062240007	83/04/25	FOIA
83062230169	83062230167	83/06/16	50-416 P	83062240148	83062240140	83/06/20	50-274 Q
83062230174	83062230170	83/06/21	50-333 P	83062240149	83062240145	83/06/20	50-325 P
83062230198	83062230192	83/06/14	CONTRACT	83062240151	83062240007	83/04/25	FOIA
83062230199	83062230195	83/06/08	50-244 Q	83062240155	83062240007	83/04/25	FOIA
83062230212	83062230203	83/06/10	50-247 Q	83062240158	83062240007	83/04/25	FOIA
83062230216	83062230215	83/06/10	50-336 Q	83062240160	83062240007	83/04/25	FOIA
83062230220	83062230218	83/03/31	CONTRACT	83062240163	83062240007	83/04/25	FOIA
83062230255	83062230253	83/06/10	50-346 Q	83062240168	83062240007	83/04/25	FOIA
83062230261	83062230260	83/06/20	50-266 Q	83062240201	83062240196	83/06/17	0A999
83062230262	83062230259	83/06/15	50-346 P	83062240204	83062240196	83/06/17	0A999
83062230271	83062230267	83/06/08	50-440 Q	83062240207	83062240196	83/06/17	0A999
83062230279	83062230274	83/06/10	50-266 Q	83062240208	83062240203	83/06/17	50-206 P
83062230290	83062230285	83/06/10	50-454 Q	83062240209	83062240196	83/06/17	0A999
83062230305	83062230303	83/06/20	50-142 Q	83062240214	83062240196	83/06/17	0A999
83062230322	83062230317	83/06/21	50-244 Q	83062240219	83062240196	83/06/17	0A999
83062230326	83062230324	83/06/02	TOPREF	83062240224	83062240196	83/06/17	0A999
83062230351	83062230348	83/06/20	50-331 P	83062240229	83062240196	83/06/17	0A999
83062230357	83062230353	83/06/10	50-358 Q	83062240232	83062240230	83/06/20	50-322 E

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

539

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8306240243	8306240237	83/05/26	0A997	8306270342	8306110492	83/06/24	50-275 Q
8306240245	8306240237	83/05/26	0A997	8306270344	8306110492	83/06/24	50-275 Q
8306240263	8306240262	83/06/09	TOPREP	8306270349	8306270339	83/06/23	50-329 A
8306240281	8306240279	83/06/22	50-204 Q	8306270350	8306110492	83/06/24	50-275 Q
8306240293	8306240289	83/06/03	0A997	8306270353	8306270347	83/06/22	50-397 S
8306240375	8306240290	83/06/20	50-247 Q	8306270357	8306270351	83/06/13	50-281 S
8306240301	8306240290	83/06/20	50-247 Q	8306270364	8306270351	83/06/13	50-281 S
8306240303	8306240298	83/06/20	50-244 P	8306270369	8306270229	83/06/16	50-348 S
8306240305	8306240290	83/06/20	50-247 Q	8306270378	8306270374	83/06/22	50-358 A
8306240310	8306240308	83/05/18	50-344 F	8306270385	8306270381	83/06/17	50-409 Q
8306240312	8306240311	83/06/16	50-244 P	8306270389	8306270381	83/06/17	50-409 Q
8306240314	8306240313	83/06/02	TOPREP	8306270392	8306270387	83/06/08	50-237 Q
8306240315	8306240313	83/06/02	TOPREP	8306270426	8306270420	83/06/24	50-331 P
8306240318	8306110486	83/06/20	50-275 S	8306270436	8306270433	83/06/16	50-315 B
8306240330	8306240328	83/06/13	COMMISSION	8306270444	8306270433	83/06/16	50-315 S
8306240331	8306240328	83/06/13	COMMISSION	8306270446	8306270441	83/06/03	CONTRACT
8306240336	8306240335	83/06/13	COMMISSION	8306270449	8306270433	83/06/16	50-315 S
8306240337	8306240335	83/06/13	COMMISSION	8306270453	8306270452	83/06/01	0A997
8306240356	8306240352	83/05/06	FOIA	8306270456	8306270452	83/06/01	0A997
8306240358	8306240353	83/06/15	CONTRACT	8306270477	8306270416	83/06/22	50-275 R
8306240380	8306240369	83/06/15	PROJ	8306280011	8306280009	83/06/24	50-309 P
8306240410	8306240405	83/06/16	50-155 Q	8306280042	8306280034	83/06/23	50-322 F
8306240415	8306240405	83/06/16	50-155 Q	8306280046	8306280034	83/06/23	50-322 F
8306240419	8306240405	83/06/16	50-155 Q	8306280056	8306280047	83/06/17	PR
8306240421	8306240405	83/06/16	50-155 Q	8306280057	8306280050	83/06/27	CONTRACT
8306240422	8306240405	83/06/16	50-155 Q	8306280075	8306280073	83/06/20	50-285 P
8306240423	8306240405	83/06/16	50-155 Q	8306280078	8306280073	83/06/20	50-285 P
8306240441	8306240438	83/06/07	71-9006	8306280081	8306280076	83/06/07	50-206 Q
8306240445	8306240438	83/06/07	71-9006	8306280118	8306280113	83/06/03	CONTRACT
8306240446	8306240443	83/06/03	PROJ	8306280122	8306280115	83/06/13	CONTRACT
8306240450	8306240443	83/06/03	PROJ	8306280133	8306280127	83/05/06	CONTRACT
8306240479	8306240477	83/06/10	50-361 P	8306280136	8306280131	83/06/03	50-344 Q
8306240489	8306240488	83/06/16	71-86	8306280145	8306280137	83/06/03	50-528 Q
8306270003	8306200265	83/06/10	50-237 P	8306280147	8306280141	83/06/03	CONTRACT
8306270004	8306270001	83/06/17	50-213 Q	8306280159	8306280152	83/05/16	CONTRACT
8306270017	8306270014	83/06/21	50-440 Q	8306280162	8306280156	83/06/14	50-277 P
8306270020	8306270016	83/06/21	50-454 Q	8306280166	8306280164	83/06/21	50-271 Q
8306270069	8306270067	83/05/21	50-329 R	8306280167	8306280156	83/06/14	50-277 P
8306270071	8306270066	83/06/20	50-456 Q	8306280173	8306280170	83/06/21	50-271 Q
8306270079	8306270076	83/06/22	50-155 P	8306280177	8306280171	83/05/27	50-69 Q
8306270080	8306270077	83/06/23	50-416 P	8306280181	8306280176	83/06/24	50-219 P
8306270109	8306270107	83/06/22	50-155 P	8306280183	8306280175	83/05/27	50-312 Q
8306270115	8306270112	83/04/22	50-440 Q	8306280185	8306280171	83/05/27	50-69 Q
8306270149	8306270138	83/06/24	50-546 C	8306280194	8306280189	83/05/26	50-275 Q
8306270152	8306270138	83/06/24	50-546 K	8306280210	8306280204	83/06/13	50-213 Q
8306270167	8306270162	83/06/08	50-156 Q	8306280211	8306280206	83/05/06	50-320 P
8306270174	8306270169	83/06/10	50-155 Q	8306280213	8306280208	83/06/24	50-358 A
8306270175	8306270170	83/06/20	50-366 P	8306280215	8306280209	83/06/02	50-397 Q
8306270177	8306270171	83/06/16	50-3 R	8306280216	8306280206	83/05/06	50-320 P
8306270184	8306270171	83/06/16	50-3 R	8306280220	8306280206	83/05/06	50-320 P
8306270187	8306270185	83/06/10	50-2 Q	8306280226	8306280218	83/06/10	50-312 Q
8306270205	8306270201	83/06/08	50-546 Q	8306280228	8306280217	83/06/06	50-267 S
8306270220	8306270215	83/06/23	50-371 Q	8306280236	8306280217	83/06/06	50-267 S
8306270222	8306270215	83/06/23	50-374 Q	8306280246	8306280217	83/06/06	50-267 S
8306270226	8306270223	83/06/23	50-374 P	8306280260	8306280217	83/06/06	50-267 S
8306270230	8306270225	83/06/23	50-324 P	8306280261	8306280258	83/06/10	XPORTRIC
8306270232	8306270229	83/06/16	50-348 S	8306280262	8306280217	83/06/06	50-267 S
8306270233	8306270231	83/06/20	50-289 P	8306280266	8306280217	83/06/06	50-267 S
8306270234	8306270231	83/06/20	50-289 P	8306280272	8306280217	83/06/06	50-267 S
8306270237	8306270236	83/05/03	50-278 Q	8306280278	8306280217	83/06/06	50-267 S
8306270239	8306270238	83/06/16	40-8610	8306280283	8306280217	83/06/06	50-267 S
8306270251	8306270248	83/04/28	50-387 R	8306280288	8306280217	83/06/06	50-267 S
8306270253	8306270248	83/04/28	50-387 R	8306280291	8306280280	83/05/26	WASTE MOT
8306270258	8306270255	83/06/03	50-336 P	8306280293	8306280217	83/06/06	50-267 S
8306270264	8306270261	83/06/22	50-277 P	8306280298	8306280217	83/06/06	50-267 S
8306270268	8306270261	83/06/22	50-277 P	8306280302	8306280217	83/06/06	50-267 S
8306270270	8306270265	83/06/23	50-289 Q	8306280309	8306280217	83/06/06	50-267 S
8306270278	8306270273	83/06/23	50-209 Q	8306280310	8306280303	83/06/16	50-528 Q
8306270281	8306270273	83/06/23	50-209 Q	8306280313	8306280217	83/06/06	50-267 S
8306270287	8306270283	83/06/23	50-440 Q	8306280339	8306280333	83/06/02	50-344 Q
8306270298	8306270293	83/06/21	50-254 Q	8306280341	8306280334	83/06/03	50-397 Q
8306270300	8306270297	83/06/17	50-352 Q	8306280345	8306280340	83/06/24	50-282 Q
8306270304	8306270299	83/06/17	50-272 P	8306280351	8306280347	83/06/23	50-77 Q
8306270308	8306270305	83/06/23	50-322 P	8306280363	8306280357	83/06/13	50-293 Q
8306270313	8306270307	83/06/20	50-400 Q	8306280378	8306280373	83/06/24	50-305 P
8306270314	8306270311	83/06/22	50-461 Q	8306280380	8306280371	83/06/15	50-397 Q
8306270321	8306270311	83/06/22	50-461 Q	8306280394	8306280368	83/06/23	50-275 P
8306270323	8306270320	83/06/21	50-289 Q	8306280396	8306280368	83/06/23	50-275 P
8306270335	8306270329	83/06/17	50-305 Q	8306280400	8306280392	83/06/21	50-445 A
8306270341	8306270329	83/06/17	50-305 Q	8306280409	8306280405	83/06/13	50-508 Q

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

540

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8306280424	8306280422	83/06/24	50-220 Q	8306290345	8306290341	83/06/16	50-250 Q
8306280433	8306280429	83/06/22	70-1402	8306290349	8306290341	83/06/16	50-250 Q
8306280452	8306280450	83/06/09	50-528 Q	8306290351	8306290327	83/06/17	50-335 Q
8306280456	8306280453	83/06/21	50-397 E	8306290354	8306290341	83/06/16	50-250 Q
8306280458	8306280455	83/06/07	70-115	8306290357	8306290341	83/06/16	50-250 Q
8306280465	8306280461	83/06/22	50-317 Q	8306290359	8306290327	83/06/17	50-335 Q
8306280470	8306280469	83/06/24	50-275 R	8306290368	8306290327	83/06/17	50-335 Q
8306280474	8306280472	83/06/13	50-271 Q	8306290371	8306290365	83/06/03	50-416 Q
8306280480	8306280477	83/06/14	50-206 Q	8306290375	8306290370	83/06/22	50-460 Q
8306280484	8306280357	83/06/13	50-293 Q	8306290379	8306290327	83/06/17	50-335 Q
8306280492	8306280490	83/06/23	50-334 Q	8306290380	8306290377	83/05/27	50-302 Q
8306280495	8306280490	83/06/23	50-334 Q	8306290387	8306290383	83/06/17	50-338 Q
8306280497	8306280490	83/06/23	50-334 Q	8306290401	8306290397	83/06/24	50-275 R
8306280507	8306280503	83/05/27	50-397 Q	8306290404	8306290396	83/06/03	50-412 Q
8306280511	8306280498	83/06/15	50-361 Q	8306290408	8306290400	83/06/20	50-259 P
8306280513	8306280509	83/06/24	50-220 P	8306290413	8306290406	83/06/27	50-245 P
8306280519	8306280515	83/06/24	50-529 Q	8306290424	8306290421	83/06/01	50-389 Q
8306280521	8306280516	83/06/06	50-397 Q	8306290426	8306290420	83/06/08	50-261 Q
8306280530	8306280527	83/06/23	50-289 Q	8306290431	8306290409	83/06/28	50-354 K
8306280541	8306280536	83/06/27	50-382 Q	8306290432	8306290409	83/06/28	50-354 A
8306280544	8306280524	83/06/23	50-324 P	8306290435	8306290409	83/06/28	50-354 C
8306280551	8306280546	83/06/17	50-361 Q	8306290436	8306290433	83/06/22	70-1151
8306280561	8306280546	83/06/17	50-361 Q	8306290444	8306290409	83/06/28	50-354 K
8306280570	8306280564	83/06/24	50-237 P	8306290448	8306290409	83/06/28	50-354 K
8306280575	8306280564	83/06/24	50-237 P	8306290449	8306290409	83/06/28	50-354 K
8306280581	8306280569	83/06/20	50-117 P	8306290451	8306290409	83/06/28	50-354 K
8306280590	8306280586	83/06/20	50-354 Q	8306290454	8306290409	83/06/28	50-354 K
8306280594	8306280569	83/06/20	50-112 P	8306290456	8306290409	83/06/28	50-354 K
8306280608	8306280601	83/06/23	50-322 Q	8306290457	8306290409	83/06/28	50-354 K
8306280617	8306280613	83/06/21	50-344 P	8306290458	8306290409	83/06/28	50-354 K
8306280632	8306280620	83/06/10	50-344 Q	8306290460	8306290409	83/06/28	50-354 K
8306290018	8306200154	83/06/10	50-27 F	8306290461	8306290459	83/06/23	50-413 Q
8306290073	8306290068	83/06/21	50-141 W	8306290464	8306290459	83/06/23	50-413 Q
8306290077	8306290068	83/06/21	50-141 W	8306290465	8306290409	83/06/28	50-354 K
8306290080	8306290068	83/06/21	50-141 W	8306290468	8306290409	83/06/28	50-354 K
8306290083	8306290082	83/06/21	70-734	8306290469	8306290409	83/06/28	50-354 K
8306290122	8306290089	83/06/23	50-447 D	8306290470	8305110499	83/06/27	50-275 T
8306290135	8306290128	83/06/22	50-556 A	8306290471	8306290409	83/06/28	50-354 K
8306290192	8306290186	83/06/03	50-413 Q	8306290473	8306290409	83/06/28	50-354 K
8306290202	8306290194	83/06/07	50-317 P	8306290474	8306290409	83/06/28	50-354 K
8306290203	8306290195	83/06/09	50-259 Q	8306290476	8305110499	83/06/27	50-275 T
8306290207	8306290198	83/06/16	50-348 Q	8306290477	8306290409	83/06/28	50-354 K
8306290212	8306290204	83/05/31	50-250 Q	8306290478	8306290409	83/06/28	50-354 K
8306290213	8306290198	83/06/16	50-348 Q	8306290479	8306290409	83/06/28	50-354 K
8306290216	8306290198	83/06/16	50-348 Q	8306290482	8306290409	83/06/28	50-354 K
8306290220	8306290214	83/06/27	50-440 Q	8306290484	8306290409	83/06/28	50-354 K
8306290221	8306290209	83/06/01	50-335 Q	8306290485	8306290480	83/06/27	50-322 Q
8306290222	8306290198	83/06/16	50-348 Q	8306290487	8306290409	83/06/28	50-354 K
8306290224	8306290218	83/03/21	50-259 Q	8306290489	8306290409	83/06/28	50-354 K
8306290225	8306290217	83/06/08	50-389 Q	8306290490	8306290483	83/06/17	50-259 Q
8306290228	8306290218	83/03/21	50-259 Q	8306290491	8306290409	83/06/28	50-354 K
8306290233	8306290227	83/06/07	50-537 Q	8306290492	8306290480	83/06/27	50-322 Q
8306290235	8306290231	83/06/09	50-438 Q	8306290494	8306290409	83/06/28	50-354 K
8306290240	8306290214	83/06/27	50-440 Q	8306290496	8306290493	83/06/23	50-329 A
8306290244	8306290236	83/06/03	50-416 Q	8306290497	8306290409	83/06/28	50-354 K
8306290246	8306290239	83/06/20	50-438 Q	8306290500	8306290495	83/06/15	50-447 K
8306290255	8306290254	83/06/16	50-321 Q	8306290503	8306290483	83/06/17	50-259 Q
8306290275	8306290272	83/06/16	50-259 Q	8306290504	8306290495	83/06/15	50-447 K
8306290278	8306290254	83/06/16	50-321 Q	8306290510	8306290483	83/06/17	50-259 Q
8306290281	8306290268	83/06/20	CONTRACT	8306290511	8306290428	83/06/06	50-390 Q
8306290283	8306290277	83/06/14	50-259 Q	8306290512	8306290507	83/06/15	50-447 K
8306290284	8306290254	83/06/16	50-321 Q	8306290515	8306290507	83/06/15	50-447 K
8306290288	8306290277	83/06/14	50-259 Q	8306290519	8306290517	83/06/08	50-369 Q
8306290292	8306290277	83/06/14	50-259 Q	8306290531	8306290524	83/06/14	50-261 Q
8306290293	8306290254	83/06/14	50-321 Q	8306290537	8306290524	83/06/14	50-261 Q
8306290297	8306290277	83/06/14	50-259 Q	8306290545	8306290397	83/06/24	50-275 R
8306290303	8306290298	83/06/16	50-321 Q	8306290549	8306290536	83/06/23	50-440 Q
8306290305	8306290308	83/06/07	50-413 Q	8306290551	8306290530	83/06/27	50-329 Q
8306290312	8306290298	83/06/16	50-321 Q	8306290552	8306290536	83/06/23	50-142 Q
8306290316	8306290308	83/06/15	50-390 Q	8306290553	8306290524	83/06/14	50-261 Q
8306290317	8306290298	83/06/16	50-321 Q	8306290555	8306290524	83/06/14	50-261 Q
8306290318	8306290308	83/06/15	50-390 Q	8306290567	8306290564	83/06/07	REVIEW ORP
8306290319	8306290308	83/06/15	50-438 Q	8306290625	8306290597	83/06/15	CONTRACT
8306290324	8306290308	83/06/15	50-390 Q	8306290626	8306290620	83/06/14	50-201 P
8306290325	8306290309	83/06/15	50-438 Q	8306290633	8306290385	83/06/15	CONTRACT
8306290328	8306290308	83/06/15	50-390 Q	8306290687	8306290682	83/06/16	70-2375
8306290332	8306290298	83/06/16	50-321 Q	8306300011	8306300007	83/06/24	50-312 Q
8306290334	8306290309	83/06/15	50-438 Q	8306300021	8306300014	83/06/16	50-255 Q
8306290335	8306290329	83/06/27	50-295 Q	8306300029	8306300022	83/06/17	50-346 Q
8306290338	8306290327	83/06/17	50-335 Q	8306300034	8306300027	83/06/28	50-155 P

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

541

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
B306300061	B306300053	83/06/16	50-341 Q	B306300141	B306300129	83/06/11	50-371 Q
B306300062	B306300033	83/06/14	50-302 P	B306300144	B306300057	83/06/21	50-361 P
B306300063	B306300060	83/06/14	50-346 Q	B306300151	B306300149	83/06/22	50-280 K
B306300067	B306300053	83/06/16	50-341 Q	B306300164	B306300162	83/06/21	50-289 R
B306300073	B306300068	83/06/27	50-373 Q	B306300162	B306300170	83/06/20	50-401 Q
B306300079	B306300075	83/06/27	50-313 Q	B306300183	B306300179	83/06/15	50-440 Q
B306300089	B306300083	83/06/24	50-275 Q	B306300184	B306300178	83/06/16	50-454 Q
B306300090	B306300084	83/06/27	50-403 Q	B306300186	B306300170	83/06/20	50-463 Q
B306300073	B306300083	83/06/24	50-275 Q	B306300194	B306300190	83/06/21	50-271 P
B306300077	B306300095	83/06/23	50-289 Q	B306300190	B306300191	83/06/23	50-369 S
B306300105	B306300101	83/06/27	50-314 A	B306300204	B306300191	83/06/23	50-369 S
B306300107	B306300104	82/11/17	50-261 Q	B306300207	B306300201	83/06/14	50-440 Q
B306300108	B306300102	83/06/28	50-324 Q	B306300216	B306300197	83/06/23	50-291 Q
B306300109	B306300101	83/06/27	50-329 A	B306300217	B306300211	83/06/24	50-271 P
B306300111	B306300104	82/11/17	50-267 Q	B306300218	B306300212	83/06/15	50-358 Q
B306300112	B306300101	83/06/27	50-329 A	B306300229	B306300225	83/06/24	50-301 P
B306300125	B306300057	83/06/22	50-361 P	B306300231	B306300226	83/06/14	50-409 Q
B306300132	B306300126	83/06/17	50-440 Q	B306300238	B306300235	83/06/16	50-231 Q
B306300135	B306300129	83/06/11	50-373 Q	B306300246	B306300239	83/06/16	50-231 Q
B306300136	B306300057	83/06/23	50-361 P	B306300252	B306300251	83/06/17	50-346 Q

APPENDIX A

DEFINITIONS OF DOCKET 50 CATEGORIES

A APPLICATION/CONSTRUCTION STAGE DOCUMENTS AND CORRESPONDENCE

This category follows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are

- 1 Application for construction permit
2. General Information submitted with construction permit application
- 3 Amendments and changes to items 1 and 2.
4. NRC questions, requests for additional information, and applicant responses.
5. Correspondence and documents relating to unresolved design and construction issues.
6. Meeting announcements and summaries of meeting discussions on issues of item 5.
7. Correspondence regarding the Preliminary Safety Analysis Report (PSAR).
8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
9. Construction Permit, amendments, and correspondence relating to the construction permit
10. Scheduling of license application submission or review.
11. Environmental review information.
12. Application for operating license.
13. General Information submitted with operating license application.
14. Amendments and changes to items 12 and 13.
15. Correspondence regarding the Final Safety Analysis Report (FSAR).
16. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 17 Reports of site visits.
18. Backup technical documents (e.g., topical reports) submitted in support of the application.

B. UTILITY PRELIMINARY SAFETY ANALYSIS REPORT (PSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence is filed in Category A.

1. Preliminary Safety Analysis Report (PSAR) submitted by utility (formerly called Hazards Summary Report or Safety Analysis Report).
2. Amendments and changes to the PSAR.

3. Transmittal and acknowledgement letters
4. Certificates of service to the PSAR

C UTILITY ENVIRONMENTAL REPORT (ER), AMENDMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are filed in Categories A, D, M, P or R.

1. Environmental Report (ER) submitted by the utility
2. Amendments and supplements to the ER
3. Transmittal and acknowledgement letters
4. Information on scheduling of submittal or review of ER.
5. NRC questions, requests for additional information, and applicant responses
6. Federal register notices citing the availability of items 1 and 2
7. Correspondence relating to the review of ER
8. Meeting announcements or reports of meetings where the primary subject of discussion is the ER.

D. NRC DRAFT AND FINAL ENVIRONMENTAL (IMPACT) STATEMENTS (DES AND FES), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are in categories A, C, M, P or R.

1. Draft and Final Environmental (Impact) Statements (DES and FES) prepared by the NRC.
2. Supplements to the DES and FES.
3. Correspondence relating to the DES and FES.
4. Comments from other federal, state and local government agencies.
5. Transmittal and acknowledgement letters
6. Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements.
7. Backup technical documents submitted in connection with above.
8. Federal register notice citing availability of items 1 and 2.
9. Site visits to obtain information for DES or FES.
10. Meeting announcements or reports of meetings where the primary subject of discussion is the DES or FES.

E. NRC SAFETY EVALUATION REPORT (SER), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other documents dealing with safety related issues are filed in categories A, P or W, depending on the phase of the licensing process.

1. Safety Evaluation Report (SER) prepared by the NRC (formerly called NRC-AEC Hazard Analysis Report)
2. Supplements to SER
3. Correspondence relating to SER
4. Federal register notices citing availability of items 1 and 2.
5. Information on scheduling of SER submittals and review.
6. Requests for additional information for use in preparing SER; responses to such requests.
7. Meeting announcements or reports of meetings where the primary subject of discussion is the SER
8. Transmittal and acknowledgement letters.

F. SECURITY, MEDICAL, EMERGENCY AND FIRE PROTECTION PLANS

All plans in this category are individual submissions. Information submitted as part of the PSAR or FSAR is excluded.

1. Fire Hazard Protection Plan and surveys.
2. Plant evacuation correspondence.
3. Safeguards Contingency Plans.
4. Review of Health Physics Program
5. Correspondence relating to aforementioned plans.
6. Supplements, changes and revisions to plans.

G. LEGAL AND ADJUDICATORY CORRESPONDENCE

This category contains all non-antitrust legal and adjudicatory documentation, except for transcripts, briefings and testimony, which are filed in category T.

1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) hearing related documents.
2. Federal register notices regarding hearings.
3. Requests to make appearances at hearings.
4. Motions, briefs, arguments, statements and related correspondence filed by participants for hearings.
5. Transmittal of supporting documents (e.g., SER, FES) to the boards.
6. Correspondence to and from intervenors.
7. Board orders and decisions.
8. Petitions for Commission action.
9. Legal filings and Commission orders and decisions resulting from item 8

H. GENERAL CORRESPONDENCE

This category includes documents with little or no bearing on the status of the application or license. Items that have no substantive technical content or meaning for the status of the license or application are included.

1. Change of address notifications.
2. Changes in structure of organization.
3. Changes in service lists.
4. NRC requests to applicant for additional copies of documents.
5. Correspondence from the public requesting information about the facility and NRC responses.
6. Correspondence on strictly administrative matters.
7. Letters of support, concern or opposition to the facility.
8. Correspondence regarding the Local Public Document Rooms (LPDRs).
9. Professional qualification statements not pertaining to the hearing process.

I. FINANCIAL INFORMATION

This category contains all financial information except that submitted as part of the application or its amendments or relating to the imposition of civil penalties.

1. Company annual reports.
2. Separately submitted financial information and related correspondence.

J. INSURANCE AND INDEMNITY INFORMATION

1. Indemnity agreements and amendments.
2. Endorsements insurance policies.
3. Other correspondence regarding indemnity and insurance matters.

K. UTILITY FINAL SAFETY ANALYSIS REPORT (FSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence falls in category A or P.

1. Final Safety Analysis Report (FSAR) (formerly called Final Hazards Summary Report).
2. Amendments and changes to the FSAR.
3. Federal register notices citing availability of items 1 and 2.
4. Transmittal and acknowledgement letters.
5. Certificates of service to the FSAR.

L. LIMITED WORK AUTHORIZATION (LWA) AND RELATED CORRESPONDENCE

This category is limited to documents pertaining to Limited Work Authorizations (LWA) whereby applicants can carry out limited site preparation and construction prior to the granting of a construction permit

- 1 Limited Work Authorizations (LWA) and amendments.
- 2 Correspondence pertaining to work performed under LWA's

M. ANTITRUST REVIEW AND ANTITRUST CORRESPONDENCE

- 1 Document submitted as part of the applications for a construction permit and operating license entitled "Information Requested by the Attorney General for Antitrust Review"
- 2 Correspondence where the primary topic of discussion is antitrust matters.
- 3 All antitrust proceeding related documents except for hearing transcripts, testimony and briefings, which are filed in category N.

N. ANTITRUST HEARING TRANSCRIPTS, TESTIMONY AND BRIEFINGS

This category contains word-for-word transcripts of hearings, testimony and briefings in antitrust matters. Related correspondence falls in category M.

O. ADVISORY COMMITTEE ON REACTOR SAFEGUARDS (ACRS) REPORTS AND CORRESPONDENCE

1. Correspondence and letter reports relating to Advisory Committee on Reactor Safeguards (ACRS) reviews.
2. Correspondence from ACRS
3. Announcement of ACRS meetings.
4. Transmittal and acknowledgement letters.
5. ACRS reports.
6. Statements and written testimony by ACRS members or presented by individuals at ACRS proceedings.
7. Minutes at ACRS Subcommittee Meetings.

P OPERATING LICENSE STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Application/Construction Stage (category A) file for general technical items dated from the issuance of the operating license to the application for termination of the license.

1. Operating license, amendments, proposed amendments, changes and related correspondence.
2. Technical specifications and changes.

- 3 Backup technical documents (e.g., topical reports) submitted in support of items 1 and 2.
- 4 Federal register notices citing availability of items 1 and 2
5. Correspondence regarding the Final Safety Analysis Report (FSAR)
6. All general technical correspondence, meeting announcements or meeting summaries relating to technical specifications, the operating license or technical issues arising after the issuance of the operating license.
7. Correspondence regarding codes (e.g., ASME), regulations, laws or changes in policy that may affect plant operation or bear on the operating license
- 8 Information on the Standard Review Plan (STP)
- 9 Results of surveys or tests conducted in accordance with the technical specifications (not periodic reports, which fall in category R).
- 10 Correspondence relating to NRC's Systematic Evaluation Program (SEP).
11. Owner's group meeting announcements and reports.
- 12 Quality assurance information.
13. Environmental matters (technical).
14. Emergency core cooling system documents.
15. Radioactive waste information.
16. Correspondence regarding expansion of spent fuel storage pool.
17. Start-up test reports
- 18 Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 19 Reports of site visits.

Q. INSPECTION REPORTS; IE BULLETINS, CIRCULARS AND INFORMATION NOTICES; CIVIL PENALTIES AND RELATED CORRESPONDENCE

1. Inspection reports.
2. IE Bulletins (formerly called Regulatory Operations (RO) Bulletins), Circulars and Information Notices.
3. Responses by applicant to IE correspondence.
4. Applicant's determination of proprietary nature of inspection reports.
5. Letters concerning areas of noncompliance.
6. Pre-service and in-service inspections and procedures.
7. Correspondence and orders relating to imposition and payment of civil penalties, including Notification of Significant Enforcement Actions (ENs).
8. Any correspondence relating to inspection and enforcements that does not specifically relate to incidents or events as defined in category S.

R. PERIODIC OPERATING REPORTS AND RELATED CORRESPONDENCE

This category includes periodic reports of a routine nature

- 1 Monthly, semiannual, or annual operating reports (other than financial).
- 2 Periodic environmental monitoring, effluent testing, or similar reports
3. Periodic personnel exposure reports.
- 4 Operational Logbooks.
Logbooks on Environmental Data
Logbooks on Radiological Data
Operations Log on Plant Systems Core
Plant Status Summary Sheets
- 5 Correspondence or other documents relating to the above listed items

S. REPORTABLE OCCURRENCES, PNOs, PNSs AND RELATED CORRESPONDENCE

This category contains all materials relating to abnormal, unusual, reportable or nonroutine occurrences or events. This includes:

1. All 24-hour, 10-day, 30-day, interim and final Licensee Event Reports (LERs) and follow-up correspondence (also called incident reports, abnormal occurrence reports and reportable occurrences).
2. Potential or possible reportable deficiency reports and related correspondence.
3. Personnel exposure reports.
- 4 Construction deficiency reports submitted under 10 CFR 50.55e.
5. Preliminary Notification of Occurrence (PNOs) and Preliminary Notification of Safeguards Events (PNSs).
6. Environmental Technical Specifications violation reports and Environmental Event reports.
- 7 Part 21 Reports of defects and noncompliance.
8. Correspondence or other documents relating to items 1-7.

T. TRANSCRIPTS, TESTIMONY AND BRIEFINGS ON NON-ANTITRUST MATTERS

This category contains all word-for-word transcripts, except for antitrust matters (category N), testimony and briefings, and congressional matters (category U).

- 1 Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) transcripts.
- 2 Testimony and statements submitted to ASLB and ASLAB.
3. Commission meeting transcripts.
4. NRC staff briefings to the Commission.
5. Statements and written testimony submitted at Commission meeting or hearings.
6. Transcripts of utility briefs to NRC staff.
7. Advisory Committee on Reactor Safeguards (ACRS) meeting transcripts.
8. Corrections to above items.

U. CONGRESSIONAL/EXECUTIVE CORRESPONDENCE

This category contains correspondence on substantive matters. Routine responses to constituent inquiries are filed in category H

1. Statements and testimony before Congress or before bodies/committees appointed by the Executive or Legislative Branches.
2. Preparatory and backup documents for item 1.
3. Correspondence to and from NRC Office of Congressional Affairs, Congress and the Executive Branch on other than constituent response matters

V. LICENSING OPERATORS AND RELATED CORRESPONDENCE

1. Operator licenses or administrative information bearing on licensing of operators.
2. NRC examination results
3. Power plant examination summary sheet.

W. DECOMMISSIONING STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Operating License Stage (category P) file for general technical items from the application for termination of the operating license onward

1. Application for authority to voluntarily surrender license.
2. Application to dismantle the facility and dispose of component parts.
3. Technical documents submitted in support of items 1 and 2, such as: Decommissioning Plan, Dismantling Plan, Environmental Report on Dismantling, Safety Analysis Report on Decommissioning.
4. Documents relating to disposal of radioactive material and decontamination of the site.
5. Other correspondence relating to above items.
6. All documentation relating to the ongoing operation of the plan, formerly filed in category P.

X. ONSITE LOW-LEVEL WASTES STORAGE

This category contains items related to the onsite storage of low-level radioactive wastes generated onsite.

Y. INDEPENDENT SPENT FUEL STORAGE INSTALLATIONS (ISFSI)

This category contains documents with an NMSS license and/or a Docket-72 number. For installations on a reactor site, the associated Docket-50 number will also be identified.

1. License applications, licenses, amendments and proposed amendments to possess power reactor spent fuel and other radioactive materials associated with spent storage in an independent spent fuel storage installation. (Such spent fuel storage installations may be on a reactor site or at a separate site.)
2. All related correspondence and reports to the above.

APPENDIX B

DEFINITIONS OF NONDOCKETED CATEGORIES

10CFR – Commission Meeting Records

This category contains documentation pertaining to open and closed Commission meetings. It includes

1. Sunshine Act Federal Register notices.
2. Full, written explanation of closed meetings.
3. Certification of General Counsel on closed meetings.
4. Commission Determination Statements regarding the public disclosure of transcripts of Commission meetings.
5. Verbatim unofficial and official transcripts or portions of transcripts of open and closed Commission meetings made publicly available in accordance with provisions of 10CFR Part 9, the Sunshine Act, and Commission policies.
6. Enclosures to released transcripts, including applicable viewgraphs, staff papers, and staff correspondence.
7. Staff requirements memoranda for open meetings; memoranda to record; record of votes of Commissioners on items under consideration at meetings.

ACRS – Advisory Committee on Reactor Safeguards

This category contains documentation pertaining to the responsibilities of the Advisory Committee on Reactor Safeguards. ACRS serves as an independent advisory committee to the Commission in safety-related areas. The committee provides advice with respect to the hazards of new or existing nuclear facilities and the adequacy of related safety standards. The documents in this category are

1. Verbatim transcripts of ACRS subcommittee and full committee meetings relating to facility license applications and safety-related matters.
2. ACRS meeting announcements; description of meeting agendas.
3. ACRS-generated reports, memoranda and correspondence that are publicly available.
4. ACRS consultant reports, comments and related correspondence.
5. ACRS and NRC technical correspondence pertaining to safety matters under review by the Advisory Committee on Reactor Safeguards.

ADVCM – NRC Advisory Committees

This category contains documentation pertaining to the responsibilities of all NRC advisory committees, other than the Advisory Committee on Reactor Safeguards. The documents in this category are:

1. Charters of each advisory committee.
2. Verbatim transcripts of committee meetings.

3. Meeting announcements; description of meeting agendas.
4. Committee generated reports, memoranda, and correspondence that are publicly available.
5. Committee related correspondence.

COMMISSION – NRC Commissioners

This category contains documentation pertaining to the daily conduct of Commission business in the Office of the Commissioners, including

1. Incoming and outgoing correspondence to and from the Commissioners relating to official NRC business, including reports and other enclosures.
2. Travel vouchers, telephone logs and official appointment calendars of individual Commissioners.
3. Weekly Information Reports (SECY series number) prepared by the Executive Director for Operations (EDO) for the Commissioners, providing a summary of key events and items of interest undertaken by individual staff and program offices.

NOTE: For transcripts of Commission meetings, see 10CFR category. For all other staff papers with a SECY series designation prepared for Commission review, see SECY category.

CONTRACT – NRC Contracts and Modifications

This category contains documentation pertaining to AEC and NRC contracts and Interagency Agreements, including

1. Notifications of issuance of request for proposal (RFP) and invitations for bid (IFB).
2. Solicitations (RFP or IFB) issued by the NRC.
3. Notifications of contract execution, specifying contract number, project title, contractor name, contract type, funding, and period of performance.
4. Contractual documents and contract modifications, if any.

DISCLOSURE – Financial Disclosure Information

This category contains financial disclosure information in accordance with the Ethics in Government Act of 1978.

FOIA – Freedom of Information Act Requests and Releases

This category contains requests for agency records and records released in accordance with the provisions of the Freedom of Information Act (FOIA). Documents in this category include:

1. Requests made by any member of the public (assigned an identifying number YY-NNN for last two digits of the year numerical sequence) for NRC records made in accordance with the provisions of the Freedom of Information Act.
2. Correspondence between the NRC and the requester relevant to the processing, appeal, denial or granting of an FOIA request.
3. Records or portions of records released in response to specific requests made under FOIA.

GEN TECH IS – Generic Technical Issues

This category contains records pertaining to unresolved safety issues of a generic nature that are being analyzed by the Division of Nuclear Reactor Regulation.

1. Draft reports of action plans to accomplish generic tasks in the regulatory program.
2. Correspondence with industry and internal correspondence regarding the methodologies, analyses, and programmatic and technical aspects of issues.
3. Meeting notifications and minutes.
4. Interim findings and status reports on generic tasks addressing related aspects of generic technical issues.

I&E – Inspection and Enforcement

This category contains bulletins, circulars and information notices that are issued by the Office of Inspection and Enforcement. These issuances describe particular events that occur at a facility that may require some follow-up action on the part of licensees. Also included in this category are preliminary notifications of events (PNOs).

1. I&E Circulars, which describe an event at a licensed facility and are informational in nature.
2. I&E Information Notices, which are similar to circulars but are preliminary in nature and issued shortly after an event has occurred.
3. I&E Bulletins, which describe an event at a licensed facility and request all recipients to perform certain actions as a result of this event.
4. Preliminary Notifications of Events (PNOs), which provide updated information of an event of safety or public interest significance.

NOTE: For letters forwarding the above issuances, utility responses to such issuances, and related correspondence, see Category Q of individual docket categories.

MISC – Public Document Room Miscellaneous

This category contains documents that do not fall into the scope of the other nondocketed categories.

NUREG – NUREG Reports and Related Correspondence

These documents are formal reports issued by the U.S. Nuclear Regulatory Commission which carry the NUREG series code and correspondence pertaining to those reports. NUREG reports are accounts of work performed either by the NRC staff or by NRC contractors.

1. These reports are normally final work products and are characterized by the following criteria:
 - a. They are predecisional documents which present information to be considered in Commission licensing and policy decisions.
 - b. They present the results of Commission licensing and policy decisions.
 - c. They present the results of technical research conducted for the Commission.
2. Correspondence from industry, government and interested members of the public commenting on reports or requesting clarification or interpretation.
3. Internal NRC memoranda summarizing meetings or discussions pertaining to the content of the reports.

ORG -- Correspondence with Other Organizations

This category contains correspondence with professional organizations and associations; records other than Regulatory Guides that pertain to the activities of NRC's Office of Standards Development, and emergency petitions not assigned Petition for Rulemaking (PRM) numbers that request the Commission to take immediate action on some issue. Included are:

1. Meeting summaries and technical correspondence between NRC and professional associations and international bodies, such as the Atomic Industrial Forum and the International Atomic Energy Agency.
2. Correspondence between NRC's Office of Standards Development and other government agencies in which both parties have joint regulatory responsibility, e.g., EPA has authority to control all radioactive pollutants emitted into the air.
3. Internal memoranda, correspondence between NRC and Congress, and other technical correspondence dealing with the role and activities of the Office of Standards Development.
4. Statements, motions, orders and correspondence dealing with emergency petitions filed by parties on such topics as fire protection and re-analysis of the capacity of operating U.S. plants to withstand earthquakes.

NOTE For Regulatory Guides and comments to Regulatory Guides issued by the NRC Office of Standards Development, see the REGGD category.

For petitions for rule makings filed by the public to amend, rescind or change an NRC regulation, see the PRM category.

PR -- Proposed Rule

This category contains records dealing with NRC staff proposals to adopt, amend or repeal a Commission regulation. Proposed Rules (PRs) are normally the result of a Commission determination that sufficient grounds exist for it to proceed with a petition for change in an NRC regulation (PRM) filed by an outside party or person. The documents in this category are:

1. Federal Register notices stating the terms or substance of the proposed rule or a specification of the subject and issues involved.
2. Text of the Proposed Rule (PR).
3. Comments, statements, information, opinions or arguments on the proposed change to a part of the Code of Federal Regulations, Title 10.
4. Requests from the nuclear industry, organizations and other parties for written interpretations of the PR.

PRM -- Petition for Rulemaking

This category contains records dealing with petitions filed with the Commission by an outside party to issue, amend or rescind an NRC regulation. Included are:

1. Petitions filed by any interested person or party to issue, amend or rescind an NRC regulation.
2. Federal Register cause notices of the filing of the petition.

3. Correspondence between NRC and the petitioner regarding the status and substance of the petition.
4. Comments from the nuclear industry, professional associations, public interest groups and others in favor of or in opposition to the PRM.

NOTE: For staff recommendations to the Commissioners on whether the PRM should be denied or issued as a Proposed Rule, see the SECY category.

For Commission review of staff recommendations, see the 10CFR category.

PROJ – Projects–Predocket Licensing

This category contains records pertaining to two classes of projects (1) commercial nuclear power plants for which NRC has full licensing responsibilities, and (2) government-owned reactors for which NRC provides technical expertise and occasional review. Both classes are identified with a “P” prefix, followed by a series of numbers.

1. “Pre-docketed” commercial nuclear power plants

This category contains all documentation up until the time that the NRC considers the application and the Preliminary Safety Analysis Report (PSAR) is submitted by the utility for staff review. The unit is then assigned a docket number, and transferred to the Docket 50 category.

These documents are grouped together in categories, designated by alphabetic characters. These are the same categories as those used for the Docket 50 series.

A. Application/Construction Stage

1. Application submitted by the utility.
2. Meeting notices, summaries and correspondence discussing the completeness and adequacy of the PSAR.
3. Applicant’s Quality Assurance Manual.
4. Early site review information.
5. Backup technical documents submitted in support of the application.
6. Early site visits.

B. Utility PSAR and Amendments

1. PSARs submitted by the utility.
2. Amendments and changes to the PSAR.
3. Transmittal letters.
4. Letters acknowledging receipt of the PSAR.

G. Adjudicatory Correspondence

1. Motions, briefs, orders, *et al.* pertaining to pre-hearing conferences, if any.

M. Antitrust Correspondence

1. Submittals and related material pertaining to the antitrust review.

Q. Inspection Reports

1. Inspection reports of the applicant's quality assurance program.
2. Notices of deviations.
3. Follow-up correspondence resolving deviations cited.

2. Government-owned reactors

Meeting summaries and technical correspondence between NRC and other government technical personnel related to test reactors, critical experiments, and DOD reactors on navy ships and other sites.

PT21 – Noncompliance Reports and Related Correspondence

Deficiency reports are performed in compliance with Part 21 of Title 10 of the Code of Federal Regulations and include:

1. Reports by firms involved in the nuclear industry concerning noncompliance with NRC regulations or the existence of defects which could create a substantial safety hazard.
2. Correspondence pertaining to the NRC review of reports to assess the possibility of generic defects.
3. NRC inspection reports of defects cited.
4. Correspondence specifying appropriate follow-up actions taken by the Agency.

QA999 – Quality Assurance Inspections

This category contains inspection reports of vendors' quality assurance programs and follow-up correspondence. Each vendor facility is assigned a docket number and is part of the QA999 series.

Vendors are defined here as companies, both U.S. and foreign, that are engaged in the design or the manufacture of nuclear components for plants licensed by NRC. QA comprises all those planned and systematic actions necessary to provide adequate confidence that a structure, system or component being manufactured will perform satisfactorily once it is put in service. The controlling criteria are 10 CFR Part 50, Appendix B, vendor QA topical reports, and the PSAR and FSAR submitted by utilities for specific facilities. Documents in this category include:

1. NRC inspection reports, conducted on a quarterly or semi-annual basis, of vendor sites. Inspections may cover the design, fabrication, construction and testing of structural systems and components.
2. Notices of deviations.
3. Vendor corrective actions and other follow-up correspondence associated with the resolution of inspection findings.

REGGD – Regulatory Guides

This category contains new and revised regulatory guides issued by the Commission and related correspondence. These guides describe for the industry and the public methods acceptable to the NRC

staff for implementing specific parts of the NRC's regulations. They also delineate techniques used by the staff in evaluating specific problems or postulated accidents, or provide guidance to applicants. Included are:

1. Federal Register notices announcing the issuance and availability of a proposed regulatory guide.
2. Revised or newly issued Regulatory Guides.
3. NRC value/impact assessment and industry codes, when applicable, that pertain to the issuance of a specific Regulatory Guide.
4. Comments submitted by the nuclear industry and interested members of the public regarding a proposed Regulatory Guide.
5. Summary of meetings held in the NRC to discuss proposed Regulatory Guides.

NOTE: For documentation pertaining to other work products and activities of the NRC Office of Standards Development, see the Organization category.

RES – Research and Technical Assistance Reports

This category contains reports, generally of an interim nature, submitted by NRC contractors providing research and technical assistance to the Commission. It also includes documentation pertaining to research activities of the Commission. Included are:

1. Project description documents.
2. Letter reports of accomplishments and data reports; for example,
 - a. model documentation reports
 - b. code documentation reports
 - c. code verification reports
3. Pre-test prediction reports.
4. "Quick look" reports.
5. Informal experimental data reports and post-irradiation examination analyses.
6. Conceptual design descriptions.
7. Letter reports of foreign travel and site visits by contractors.
8. Letter, monthly, quarterly, interim or annual status or progress reports on other research projects contracted for by the NRC.
9. Meeting summaries and correspondence dealing with technical matters relating to research and technical assistance contracts.
10. Staff Research Information Letters (RILs) transmitting the documented results from completed research programs.

NOTE: For final reports of research conducted by contractors, see also NUREG reports.

REVIEW GRP – NRC Research Review Groups

This category contains records pertaining to the activities of NRC Research Review Groups. Such groups provide a broad base of technical expertise to aid management in reviewing research in

defined technical areas. They review and comment on research plans and predicted results of major experiments, the validity and applicability of research results, the possible redirection of research projects, new research projects, and priorities within the technical areas covered by the research review group. Documents in this category are:

1. Agendas for quarterly review group meetings.
2. Summary minutes of review group meetings representing views expressed, including dissenting views.
3. Research plans and predicted results of major experiments; presentations by research contractors.
4. Comments on meetings from attendees, including representatives from contractors, universities, vendors and other agencies.
5. Internal memoranda relating to topics under discussion.

RM – Rulemakings

This category contains records pertaining to public hearings held on proposed changes (PRs) to the Commission's regulations. Hearings are instituted at the discretion of the Commission based on the importance and the magnitude of the subject under consideration. Documents in this category include:

1. Designations of the presiding officer and any special directions for the conduct of the hearing.
2. Notifications of hearing board meetings.
3. Petitions, motions, testimony and statements submitted by parties to the hearings.
4. Hearing board orders and rulings.
5. Technical reports submitted as evidence in the proceeding.
6. Reports, if any, of the special board to the Commission regarding a rulemaking proceeding.

SECY – Position Papers Before the Commission

This category consists of staff papers prepared for the information or approval of the Commissioners which are assigned a SECY report series code. Included are:

1. Commission Action papers, which normally include alternatives and recommendations by the staff on a given issue and require Commission action.
2. Consent Calendar items and Policy Session items.

NOTE: For Weekly Information Reports prepared by EDO to the Commissioners providing a summary of key events and items of interest undertaken by staff and program offices, see the NRC Commissioners category.

STATE PROG – State Programs

This category contains records that pertain to the Commission's activities and interaction with State governments. Areas covered include: (1) the State Agreements Program, whereby States may assume certain of the NRC's regulatory authority over nuclear materials; (2) the Agency's role in assisting

State and local governments in planning responses to radiological emergencies; and (3) a wide range of liaison and cooperative activities regarding such functions as licensing and siting. It includes:

1. Correspondence between and among NRC Office of State Programs and State officials, mostly State liaison officers, regarding:
 - a. cooperative programs in such technical areas as radiation control, emergency response planning to radiological incidents, water quality and transportation surveillance.
 - b. technical assistance to Agreement States in reviewing applications, compliance actions, developing regulations, and other areas.
2. Agendas, reports and transcripts of regional workshops and training programs on current matters of policy and regulations; i.e. decommissioning and facility siting.
3. State Legislative Reports.
4. Agreement State Licensing Statistics Reports.

NOTE: For specific uranium milling and mining projects in which the Agency is providing technical assistance to States, see the Projects category.

TOPREP – Vendor Reports and Related Correspondence

This category contains topical reports, generally of a technical generic nature, submitted by vendors, and correspondence pertaining to the NRC review of these reports. General vendor related correspondence that is not docket specific is also included in this category.

1. Topical reports, dealing with such technical matters as specifications, testing and safety submitted by architect, engineers and other vendors.
2. Revisions, modifications and amendments to topical reports.
3. Correspondence between NRC and vendors pertaining to the review of submittals.
4. Meeting agendas, summaries, minutes and correspondence pertinent to vendor activities, programs, methodologies and design criteria.

NOTE: For reports submitted by utilities that are written by vendors on their behalf and that relate to docketed cases, see the categories for the Docket 50 series.

WASTE MGT – Nuclear Waste Management

This category is topical in nature and contains records dealing with the activities of the NRC Division of Waste Management. Each topic has been assigned a number, with the series designated by a WM prefix. These documents deal primarily with NRC's interaction with DOE and its future role in licensing and regulating DOE facilities designed for the disposal of high-level waste in geologic repositories. This category will be enlarged later to include records dealing with low-level waste issues and tasks. The documents in this category are:

1. Meeting agenda and minutes of DOE/NRC meetings in which DOE presents information on their geological exploration program to identify sites for nuclear waste repositories.
2. Briefings by DOE on research being conducted on spent fuel storage and nuclear waste management.

3. Correspondence pertaining to NRC's advisory role in providing DOE with technical assistance in the Waste Isolation Pilot Plan (WIPP) for burial of defense wastes.
4. NRC draft staff guides for developing positions on the content and format of environmental reports for geological repositories.

XPORTLIC – Export and Import Licenses

This category contains records relating to the issuance of licenses to export or import nuclear facilities and materials. Included are:

1. License applications and amendments to export or import special nuclear material, source material, byproduct material, reactors, nuclear facility components or reactor materials.
2. Correspondence between NRC and applicant or licensee pertaining to the review or status of a pending application or license amendment.
3. Commission letters requesting Executive Branch views.
4. Review and findings of the Executive Branch on whether issuance of a license would be inimical to U.S. common defense and security.
5. Correspondence from foreign governments, international organizations, and members of the public.
6. Staff position papers (SECY series code) prepared for Commissioners review of import or export licenses.
7. Filings pursuant to hearing requests or intervention petitions, if any.
8. Hearing records and decisions.
9. Memoranda from the Office of the Secretary to the Executive Director for Operations regarding the Commission decision on issuance of a proposed license.
10. Licenses, license amendments and license renewals for types specified in item 1

NOTE. For transcripts of Commission meetings and papers submitted for Commissioner consideration or information, see 10CFR category.

U.S. NUCLEAR REGULATORY COMMISSION
BIBLIOGRAPHIC DATA SHEET1 REPORT NUMBER (Assigned by DDC)
NUREG-0540
Vol. 5, No. 6

4 TITLE AND SUBTITLE (Add Volume No., if appropriate)

Title List of Documents Made Publicly Available
June 1-30, 1983

2 (Leave blank)

3 RECIPIENT'S ACCESSION NO

7. AUTHOR(S)

5 DATE REPORT COMPLETED

MONTH

YEAR

9. PERFORMING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code)

Division of Technical Information and Document Control
Office of Administration
U.S. Nuclear Regulatory Commission
Washington, DC 20555

DATE REPORT ISSUED

MONTH

YEAR

August

1983

6 (Leave blank)

8 (Leave blank)

12. SPONSORING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code)

Same as 9, above.

10 PROJECT/TASK/WORK UNIT NO

11 FIN NO

13. TYPE OF REPORT

Monthly

PERIOD COVERED (Inclusive dates)

June 1-30, 1983

15. SUPPLEMENTARY NOTES

14. (Leave blank)

16. ABSTRACT (200 words or less)

This document is a monthly publication containing descriptions of information received and generated by the U.S. NRC. This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials, and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. The following indexes are included: Personal Author Index, Corporate Source Index, Report Number Index, and Cross Reference to Principal Documents Index.

17. KEY WORDS AND DOCUMENT ANALYSIS

17a DESCRIPTORS

17b. IDENTIFIERS/OPEN-ENDED TERMS

18 AVAILABILITY STATEMENT

Unlimited

19 SECURITY CLASS (This report)

Unclassified

21 NO OF PAGES

20 SECURITY CLASS (This page)

Unclassified

22 PRICE

S